



Sep 10, 2024

BROWN R

12607 S UNION AVE, Chicago IL 60628.

Dear **BROWN R** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit www.cdc.gov/lead.

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



Sep 10, 2024

BROWN R

12607 S UNION AVE, Chicago IL 60628.

Estimadas familias de **BROWN R**:

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer
Director de Salud y Seguridad Ambientales
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51512	51512-1-HAL-F13	Across From Boys Toilets, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F13	Across From Boys Toilets, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F13	Across From Boys Toilets, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F13	Across From Boys Toilets, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F13	Across From Boys Toilets, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F13	Across From Boys Toilets, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F13	Across From Boys Toilets, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F13	Across From Boys Toilets, Fountain 1	Initial	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F13	Across From Boys Toilets, Fountain 1	Initial	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F14	Across From Boys Toilets, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F14	Across From Boys Toilets, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F14	Across From Boys Toilets, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F14	Across From Boys Toilets, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F14	Across From Boys Toilets, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F14	Across From Boys Toilets, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F14	Across From Boys Toilets, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F14	Across From Boys Toilets, Fountain 2	Initial	10-JUN-16	0.168	ppb
51512	51512-1-HAL-F14	Across From Boys Toilets, Fountain 2	Initial	10-JUN-16	0.168	ppb
51512	51512-1-HAL-F04	Across From Kitchen, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F04	Across From Kitchen, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F04	Across From Kitchen, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F04	Across From Kitchen, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F04	Across From Kitchen, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F04	Across From Kitchen, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F04	Across From Kitchen, Fountain 1	Initial	10-JUN-16	0.201	ppb
51512	51512-1-HAL-F04	Across From Kitchen, Fountain 1	Initial	10-JUN-16	0.201	ppb
51512	51512-1-HAL-F05	Across From Kitchen, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F05	Across From Kitchen, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F05	Across From Kitchen, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F05	Across From Kitchen, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F05	Across From Kitchen, Fountain 2	Flush180	10-JUN-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51512	51512-1-HAL-F05	Across From Kitchen, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F05	Across From Kitchen, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F05	Across From Kitchen, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F05	Across From Kitchen, Fountain 2	Initial	10-JUN-16	0.132	ppb
51512	51512-1-HAL-F05	Across From Kitchen, Fountain 2	Initial	10-JUN-16	0.132	ppb
51512	51512-1-HAL-F06	Across From Kitchen, Fountain 3	Flush180	10-JUN-16	0.127	ppb
51512	51512-1-HAL-F06	Across From Kitchen, Fountain 3	Flush180	10-JUN-16	0.127	ppb
51512	51512-1-HAL-F06	Across From Kitchen, Fountain 3	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F06	Across From Kitchen, Fountain 3	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F06	Across From Kitchen, Fountain 3	Flush180	10-JUN-16	0.138	ppb
51512	51512-1-HAL-F06	Across From Kitchen, Fountain 3	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F06	Across From Kitchen, Fountain 3	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F06	Across From Kitchen, Fountain 3	Flush180	10-JUN-16	0.138	ppb
51512	51512-1-HAL-F06	Across From Kitchen, Fountain 3	Initial	10-JUN-16	0.322	ppb
51512	51512-1-HAL-F06	Across From Kitchen, Fountain 3	Initial	10-JUN-16	0.322	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	10-JUN-16	0.344	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	10-JUN-16	0.344	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F01-0051512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Flush180	19-AUG-20	1.000	ug/L
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Initial	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Initial	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F01	Across from Room 119, Fountain 1	Initial	19-AUG-20	1.000	ug/L
51512	51512-1-HAL-F02	Across from Room 119, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F02	Across from Room 119, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F02	Across from Room 119, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F02	Across from Room 119, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F02	Across from Room 119, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F02	Across from Room 119, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F02	Across from Room 119, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F02	Across from Room 119, Fountain 2	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F02	Across from Room 119, Fountain 2	Initial	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F02	Across from Room 119, Fountain 2	Initial	10-JUN-16	1.000	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F02					
51512	51512-1-102-S08	Inside Kindergarten Room 102, Sink	Flush180	10-JUN-16	1.670	ppb
51512	51512-1-102-S08	Inside Kindergarten Room 102, Sink	Flush180	10-JUN-16	0.826	ppb
51512	51512-1-102-S08	Inside Kindergarten Room 102, Sink	Flush180	10-JUN-16	1.670	ppb
51512	51512-1-102-S08	Inside Kindergarten Room 102, Sink	Flush180	10-JUN-16	0.826	ppb
51512	51512-1-102-S08	Inside Kindergarten Room 102, Sink	Flush180	10-JUN-16	1.110	ppb
51512	51512-1-102-S08	Inside Kindergarten Room 102, Sink	Flush180	10-JUN-16	1.110	ppb
51512	51512-1-102-S08	Inside Kindergarten Room 102, Sink	Flush180	10-JUN-16	0.856	ppb
51512	51512-1-102-S08	Inside Kindergarten Room 102, Sink	Flush180	10-JUN-16	0.856	ppb
51512	51512-1-102-S08	Inside Kindergarten Room 102, Sink	Initial	10-JUN-16	2.490	ppb
51512	51512-1-102-S08	Inside Kindergarten Room 102, Sink	Initial	10-JUN-16	2.490	ppb
51512	51512-1-104-BF01	Inside Pre-K Room 104, Bottle Filler	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-BF01	Inside Pre-K Room 104, Bottle Filler	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-BF01	Inside Pre-K Room 104, Bottle Filler	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-BF01	Inside Pre-K Room 104, Bottle Filler	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-BF01	Inside Pre-K Room 104, Bottle Filler	Initial	23-NOV-22	1.000	ug/L
51512	51512-1-104-F10	Inside Pre-K Room 104, Fountain	Flush180	10-JUN-16	0.467	ppb
51512	51512-1-104-F10	Inside Pre-K Room 104, Fountain	Flush180	10-JUN-16	0.399	ppb
51512	51512-1-104-F10	Inside Pre-K Room 104, Fountain	Flush180	10-JUN-16	0.339	ppb
51512	51512-1-104-F10	Inside Pre-K Room 104, Fountain	Flush180	10-JUN-16	0.399	ppb
51512	51512-1-104-F10	Inside Pre-K Room 104, Fountain	Flush180	10-JUN-16	0.339	ppb
51512	51512-1-104-F10	Inside Pre-K Room 104, Fountain	Flush180	10-JUN-16	0.580	ppb
51512	51512-1-104-F10	Inside Pre-K Room 104, Fountain	Flush180	10-JUN-16	0.580	ppb
51512	51512-1-104-F10	Inside Pre-K Room 104, Fountain	Flush180	10-JUN-16	0.467	ppb
51512	51512-1-104-F10	Inside Pre-K Room 104, Fountain	Initial	10-JUN-16	2.000	ppb
51512	51512-1-104-F10	Inside Pre-K Room 104, Fountain	Initial	10-JUN-16	2.000	ppb
51512	51512-1-104-F01	Inside Pre-K Room 104, Fountain	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-F01	Inside Pre-K Room 104, Fountain	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-F01	Inside Pre-K Room 104, Fountain	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-F01	Inside Pre-K Room 104, Fountain	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-F01	Inside Pre-K Room 104, Fountain	Initial	23-NOV-22	1.000	ug/L
51512	51512-1-104-S01	Inside Pre-K Room 104, Left Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-S01	Inside Pre-K Room 104, Left Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-S01	Inside Pre-K Room 104, Left Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-S01	Inside Pre-K Room 104, Left Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-S01	Inside Pre-K Room 104, Left Sink	Initial	23-NOV-22	1.000	ug/L
51512	51512-1-104-S02	Inside Pre-K Room 104, Right Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-S02	Inside Pre-K Room 104, Right Sink	Flush180	23-NOV-22	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51512	51512-1-104-S02	Inside Pre-K Room 104, Right Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-S02	Inside Pre-K Room 104, Right Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-104-S02	Inside Pre-K Room 104, Right Sink	Initial	23-NOV-22	1.000	ug/L
51512	51512-1-104-S09	Inside Pre-K Room 104, Sink	Flush180	10-JUN-16	1.300	ppb
51512	51512-1-104-S09	Inside Pre-K Room 104, Sink	Flush180	10-JUN-16	0.993	ppb
51512	51512-1-104-S09	Inside Pre-K Room 104, Sink	Flush180	10-JUN-16	0.739	ppb
51512	51512-1-104-S09	Inside Pre-K Room 104, Sink	Flush180	10-JUN-16	0.810	ppb
51512	51512-1-104-S09	Inside Pre-K Room 104, Sink	Flush180	10-JUN-16	0.993	ppb
51512	51512-1-104-S09	Inside Pre-K Room 104, Sink	Flush180	10-JUN-16	1.300	ppb
51512	51512-1-104-S09	Inside Pre-K Room 104, Sink	Flush180	10-JUN-16	0.810	ppb
51512	51512-1-104-S09	Inside Pre-K Room 104, Sink	Flush180	10-JUN-16	0.739	ppb
51512	51512-1-104-S09	Inside Pre-K Room 104, Sink	Initial	10-JUN-16	2.960	ppb
51512	51512-1-104-S09	Inside Pre-K Room 104, Sink	Initial	10-JUN-16	2.960	ppb
51512	51512-1-106-BF01	Inside Pre-K Room 106, Bottle Filler	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-BF01	Inside Pre-K Room 106, Bottle Filler	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-BF01	Inside Pre-K Room 106, Bottle Filler	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-BF01	Inside Pre-K Room 106, Bottle Filler	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-BF01	Inside Pre-K Room 106, Bottle Filler	Initial	23-NOV-22	1.000	ug/L
51512	51512-1-106-F12	Inside Pre-K Room 106, Fountain	Flush180	10-JUN-16	0.405	ppb
51512	51512-1-106-F12	Inside Pre-K Room 106, Fountain	Flush180	10-JUN-16	0.359	ppb
51512	51512-1-106-F12	Inside Pre-K Room 106, Fountain	Flush180	10-JUN-16	0.273	ppb
51512	51512-1-106-F12	Inside Pre-K Room 106, Fountain	Flush180	10-JUN-16	0.273	ppb
51512	51512-1-106-F12	Inside Pre-K Room 106, Fountain	Flush180	10-JUN-16	0.359	ppb
51512	51512-1-106-F12	Inside Pre-K Room 106, Fountain	Flush180	10-JUN-16	0.424	ppb
51512	51512-1-106-F12	Inside Pre-K Room 106, Fountain	Flush180	10-JUN-16	0.405	ppb
51512	51512-1-106-F12	Inside Pre-K Room 106, Fountain	Flush180	10-JUN-16	0.424	ppb
51512	51512-1-106-F12	Inside Pre-K Room 106, Fountain	Initial	10-JUN-16	1.060	ppb
51512	51512-1-106-F12	Inside Pre-K Room 106, Fountain	Initial	10-JUN-16	1.060	ppb
51512	51512-1-106-F01	Inside Pre-K Room 106, Fountain	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-F01	Inside Pre-K Room 106, Fountain	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-F01	Inside Pre-K Room 106, Fountain	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-F01	Inside Pre-K Room 106, Fountain	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-F01	Inside Pre-K Room 106, Fountain	Initial	23-NOV-22	1.000	ug/L
51512	51512-1-106-S01	Inside Pre-K Room 106, Left Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-S01	Inside Pre-K Room 106, Left Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-S01	Inside Pre-K Room 106, Left Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-S01	Inside Pre-K Room 106, Left Sink	Flush180	23-NOV-22	1.000	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51512	51512-1-106-S01	Inside Pre-K Room 106, Left Sink	Initial	23-NOV-22	1.000	ug/L
51512	51512-1-106-S02	Inside Pre-K Room 106, Right Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-S02	Inside Pre-K Room 106, Right Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-S02	Inside Pre-K Room 106, Right Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-S02	Inside Pre-K Room 106, Right Sink	Flush180	23-NOV-22	1.000	ug/L
51512	51512-1-106-S02	Inside Pre-K Room 106, Right Sink	Initial	23-NOV-22	1.000	ug/L
51512	51512-1-106-S11	Inside Pre-K Room 106, Sink	Flush180	10-JUN-16	0.781	ppb
51512	51512-1-106-S11	Inside Pre-K Room 106, Sink	Flush180	10-JUN-16	0.398	ppb
51512	51512-1-106-S11	Inside Pre-K Room 106, Sink	Flush180	10-JUN-16	0.711	ppb
51512	51512-1-106-S11	Inside Pre-K Room 106, Sink	Flush180	10-JUN-16	0.781	ppb
51512	51512-1-106-S11	Inside Pre-K Room 106, Sink	Flush180	10-JUN-16	0.711	ppb
51512	51512-1-106-S11	Inside Pre-K Room 106, Sink	Flush180	10-JUN-16	0.361	ppb
51512	51512-1-106-S11	Inside Pre-K Room 106, Sink	Flush180	10-JUN-16	0.361	ppb
51512	51512-1-106-S11	Inside Pre-K Room 106, Sink	Flush180	10-JUN-16	0.398	ppb
51512	51512-1-106-S11	Inside Pre-K Room 106, Sink	Initial	10-JUN-16	1.120	ppb
51512	51512-1-106-S11	Inside Pre-K Room 106, Sink	Initial	10-JUN-16	1.120	ppb
51512	51512-1-KIT-KS03	Kitchen, Sink	Flush180	10-JUN-16	0.209	ppb
51512	51512-1-KIT-KS03	Kitchen, Sink	Flush180	10-JUN-16	0.209	ppb
51512	51512-1-KIT-KS03	Kitchen, Sink	Flush180	10-JUN-16	0.308	ppb
51512	51512-1-KIT-KS03	Kitchen, Sink	Flush180	10-JUN-16	0.346	ppb
51512	51512-1-KIT-KS03	Kitchen, Sink	Flush180	10-JUN-16	0.207	ppb
51512	51512-1-KIT-KS03	Kitchen, Sink	Flush180	10-JUN-16	0.207	ppb
51512	51512-1-KIT-KS03	Kitchen, Sink	Flush180	10-JUN-16	0.346	ppb
51512	51512-1-KIT-KS03	Kitchen, Sink	Flush180	10-JUN-16	0.308	ppb
51512	51512-1-KIT-KS03	Kitchen, Sink	Initial	10-JUN-16	1.680	ppb
51512	51512-1-KIT-KS03	Kitchen, Sink	Initial	10-JUN-16	1.680	ppb
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	29-JAN-21	1.000	ug/L
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	29-JAN-21	1.000	ug/L
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	29-JAN-21	1.000	ug/L
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	29-JAN-21	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F07					
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Flush180	19-AUG-20	1.000	ug/L
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Initial	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Initial	10-JUN-16	1.000	ppb
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Initial	29-JAN-21	1.000	ug/L
51512	51512-1-HAL-F07	Next to Main Office, Fountain	Initial	19-AUG-20	1.000	ug/L