



Sep 10, 2024

CURIE HS

4959 S ARCHER AVE, Chicago IL 60632.

Dear **CURIE HS** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit www.cdc.gov/lead.

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



Sep 10, 2024

CURIE HS

4959 S ARCHER AVE, Chicago IL 60632.

Estimadas familias de **CURIE HS**:

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer
Director de Salud y Seguridad Ambientales
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
50951	50951-1-HAL-F07	Addition- 1st Floor By Door 12 Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F07	Addition- 1st Floor By Door 12 Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F07	Addition- 1st Floor By Door 12 Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F07	Addition- 1st Floor By Door 12 Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F07	Addition- 1st Floor By Door 12 Left	Flush180	13-OCT-16	0.214	ppb
50951	50951-1-HAL-F07	Addition- 1st Floor By Door 12 Left	Flush180	13-OCT-16	0.343	ppb
50951	50951-1-HAL-F07	Addition- 1st Floor By Door 12 Left	Flush180	13-OCT-16	0.289	ppb
50951	50951-1-HAL-F07	Addition- 1st Floor By Door 12 Left	Flush180	13-OCT-16	0.402	ppb
50951	50951-1-HAL-F07	Addition- 1st Floor By Door 12 Left	Initial	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F07	Addition- 1st Floor By Door 12 Left	Initial	13-OCT-16	0.547	ppb
50951	50951-1-HAL-F08	Addition- 1st Floor By Door 12 Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F08	Addition- 1st Floor By Door 12 Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F08	Addition- 1st Floor By Door 12 Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F08	Addition- 1st Floor By Door 12 Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F08	Addition- 1st Floor By Door 12 Right	Flush180	13-OCT-16	0.694	ppb
50951	50951-1-HAL-F08	Addition- 1st Floor By Door 12 Right	Flush180	13-OCT-16	0.664	ppb
50951	50951-1-HAL-F08	Addition- 1st Floor By Door 12 Right	Flush180	13-OCT-16	0.627	ppb
50951	50951-1-HAL-F08	Addition- 1st Floor By Door 12 Right	Flush180	13-OCT-16	0.570	ppb
50951	50951-1-HAL-F08	Addition- 1st Floor By Door 12 Right	Initial	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F08	Addition- 1st Floor By Door 12 Right	Initial	13-OCT-16	0.664	ppb
50951	50951-1-POOL-F09	Addition- 1st Floor Inside Pool Area East Wall Lef	Flush180	13-OCT-16	0.210	ppb
50951	50951-1-POOL-F09	Addition- 1st Floor Inside Pool Area East Wall Lef	Flush180	13-OCT-16	0.241	ppb
50951	50951-1-POOL-F09	Addition- 1st Floor Inside Pool Area East Wall Lef	Flush180	13-OCT-16	0.245	ppb
50951	50951-1-POOL-F09	Addition- 1st Floor Inside Pool Area East Wall Lef	Flush180	13-OCT-16	0.237	ppb
50951	50951-1-POOL-F09	Addition- 1st Floor Inside Pool Area East Wall Lef	Initial	13-OCT-16	0.334	ppb
50951	50951-1-POOL-F10	Addition- 1st Floor Inside Pool Area East Wall Rig	Flush180	13-OCT-16	0.243	ppb
50951	50951-1-POOL-F10	Addition- 1st Floor Inside Pool Area East Wall Rig	Flush180	13-OCT-16	0.229	ppb
50951	50951-1-POOL-F10	Addition- 1st Floor Inside Pool Area East Wall Rig	Flush180	13-OCT-16	0.268	ppb
50951	50951-1-POOL-F10	Addition- 1st Floor Inside Pool Area East Wall Rig	Flush180	13-OCT-16	0.232	ppb
50951	50951-1-POOL-F10	Addition- 1st Floor Inside Pool Area East Wall Rig	Initial	13-OCT-16	0.238	ppb
50951	50951-1-HAL-F01	Addition- 1st Floor Near Room 531A Left Side	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F01	Addition- 1st Floor Near Room 531A Left Side	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F01	Addition- 1st Floor Near Room 531A Left Side	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F01	Addition- 1st Floor Near Room 531A Left Side	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F01	Addition- 1st Floor Near Room 531A Left Side	Flush180	13-OCT-16	0.468	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
50951	50951-1-HAL-F01	Addition- 1st Floor Near Room 531A Left Side	Flush180	13-OCT-16	0.503	ppb
50951	50951-1-HAL-F01	Addition- 1st Floor Near Room 531A Left Side	Flush180	13-OCT-16	0.442	ppb
50951	50951-1-HAL-F01	Addition- 1st Floor Near Room 531A Left Side	Flush180	13-OCT-16	0.481	ppb
50951	50951-1-HAL-F01	Addition- 1st Floor Near Room 531A Left Side	Initial	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F01	Addition- 1st Floor Near Room 531A Left Side	Initial	13-OCT-16	0.574	ppb
50951	50951-1-HAL-F02	Addition- 1st Floor Near Room 531A Right Side	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F02	Addition- 1st Floor Near Room 531A Right Side	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F02	Addition- 1st Floor Near Room 531A Right Side	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F02	Addition- 1st Floor Near Room 531A Right Side	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F02	Addition- 1st Floor Near Room 531A Right Side	Flush180	13-OCT-16	0.412	ppb
50951	50951-1-HAL-F02	Addition- 1st Floor Near Room 531A Right Side	Flush180	13-OCT-16	0.434	ppb
50951	50951-1-HAL-F02	Addition- 1st Floor Near Room 531A Right Side	Flush180	13-OCT-16	0.398	ppb
50951	50951-1-HAL-F02	Addition- 1st Floor Near Room 531A Right Side	Flush180	13-OCT-16	0.388	ppb
50951	50951-1-HAL-F02	Addition- 1st Floor Near Room 531A Right Side	Initial	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F02	Addition- 1st Floor Near Room 531A Right Side	Initial	13-OCT-16	0.452	ppb
50951	50951-1-HAL-F04	Addition- 1st Floor Outside Dance Room Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F04	Addition- 1st Floor Outside Dance Room Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F04	Addition- 1st Floor Outside Dance Room Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F04	Addition- 1st Floor Outside Dance Room Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F04	Addition- 1st Floor Outside Dance Room Left	Flush180	13-OCT-16	0.298	ppb
50951	50951-1-HAL-F04	Addition- 1st Floor Outside Dance Room Left	Flush180	13-OCT-16	0.346	ppb
50951	50951-1-HAL-F04	Addition- 1st Floor Outside Dance Room Left	Flush180	13-OCT-16	0.276	ppb
50951	50951-1-HAL-F04	Addition- 1st Floor Outside Dance Room Left	Flush180	13-OCT-16	0.397	ppb
50951	50951-1-HAL-F04	Addition- 1st Floor Outside Dance Room Left	Initial	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F04	Addition- 1st Floor Outside Dance Room Left	Initial	13-OCT-16	0.761	ppb
50951	50951-1-HAL-F05	Addition- 1st Floor Outside Dance Room Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F05	Addition- 1st Floor Outside Dance Room Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F05	Addition- 1st Floor Outside Dance Room Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F05	Addition- 1st Floor Outside Dance Room Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F05	Addition- 1st Floor Outside Dance Room Right	Flush180	13-OCT-16	0.340	ppb
50951	50951-1-HAL-F05	Addition- 1st Floor Outside Dance Room Right	Flush180	13-OCT-16	0.305	ppb
50951	50951-1-HAL-F05	Addition- 1st Floor Outside Dance Room Right	Flush180	13-OCT-16	0.424	ppb
50951	50951-1-HAL-F05	Addition- 1st Floor Outside Dance Room Right	Flush180	13-OCT-16	0.318	ppb
50951	50951-1-HAL-F05	Addition- 1st Floor Outside Dance Room Right	Initial	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F05	Addition- 1st Floor Outside Dance Room Right	Initial	13-OCT-16	0.558	ppb
50951	50951-1-HAL-F03	Addition- 1st Floor Outside Room 508	Flush180	13-OCT-16	0.737	ppb
50951	50951-1-HAL-F03	Addition- 1st Floor Outside Room 508	Flush180	13-OCT-16	1.100	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
50951	50951-1-HAL-F03	Addition- 1st Floor Outside Room 508	Flush180	13-OCT-16	0.742	ppb
50951	50951-1-HAL-F03	Addition- 1st Floor Outside Room 508	Flush180	13-OCT-16	0.715	ppb
50951	50951-1-HAL-F03	Addition- 1st Floor Outside Room 508	Initial	13-OCT-16	0.879	ppb
50951	50951-1-HAL-RBF01	Addition- 1st Floor Outside Room 508 Retrofitted Bottle Filler	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-RBF01	Addition- 1st Floor Outside Room 508 Retrofitted Bottle Filler	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-RBF01	Addition- 1st Floor Outside Room 508 Retrofitted Bottle Filler	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-RBF01	Addition- 1st Floor Outside Room 508 Retrofitted Bottle Filler	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-RBF01	Addition- 1st Floor Outside Room 508 Retrofitted Bottle Filler	Initial	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F06	Addition- 1st Floor Outside Room 544	Flush180	28-JUL-23	1.260	ug/L
50951	50951-1-HAL-F06	Addition- 1st Floor Outside Room 544	Flush180	28-JUL-23	1.330	ug/L
50951	50951-1-HAL-F06	Addition- 1st Floor Outside Room 544	Flush180	28-JUL-23	1.210	ug/L
50951	50951-1-HAL-F06	Addition- 1st Floor Outside Room 544	Flush180	28-JUL-23	1.000	ug/L
50951	50951-1-HAL-F06	Addition- 1st Floor Outside Room 544	Flush180	13-OCT-16	1.050	ppb
50951	50951-1-HAL-F06	Addition- 1st Floor Outside Room 544	Flush180	13-OCT-16	1.290	ppb
50951	50951-1-HAL-F06	Addition- 1st Floor Outside Room 544	Flush180	13-OCT-16	1.310	ppb
50951	50951-1-HAL-F06	Addition- 1st Floor Outside Room 544	Flush180	13-OCT-16	1.140	ppb
50951	50951-1-HAL-F06	Addition- 1st Floor Outside Room 544	Initial	28-JUL-23	1.580	ug/L
50951	50951-1-HAL-F06	Addition- 1st Floor Outside Room 544	Initial	13-OCT-16	2.640	ppb
50951	50951-2-HAL-F02	Addition- 2nd Floor Outisde Room 630 Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-2-HAL-F02	Addition- 2nd Floor Outisde Room 630 Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-2-HAL-F02	Addition- 2nd Floor Outisde Room 630 Left	Flush180	28-JUL-23	1.000	ug/L
50951	50951-2-HAL-F02	Addition- 2nd Floor Outisde Room 630 Left	Flush180	13-OCT-16	1.740	ppb
50951	50951-2-HAL-F02	Addition- 2nd Floor Outisde Room 630 Left	Flush180	13-OCT-16	1.330	ppb
50951	50951-2-HAL-F02	Addition- 2nd Floor Outisde Room 630 Left	Flush180	13-OCT-16	1.270	ppb
50951	50951-2-HAL-F02	Addition- 2nd Floor Outisde Room 630 Left	Flush180	13-OCT-16	2.360	ppb
50951	50951-2-HAL-F02	Addition- 2nd Floor Outisde Room 630 Left	Initial	28-JUL-23	1.000	ug/L
50951	50951-2-HAL-F02	Addition- 2nd Floor Outisde Room 630 Left	Initial	13-OCT-16	4.810	ppb
50951	50951-2-HAL-F03	Addition- 2nd Floor Outisde Room 630 Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-2-HAL-F03	Addition- 2nd Floor Outisde Room 630 Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-2-HAL-F03	Addition- 2nd Floor Outisde Room 630 Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-2-HAL-F03	Addition- 2nd Floor Outisde Room 630 Right	Flush180	28-JUL-23	1.000	ug/L
50951	50951-2-HAL-F03	Addition- 2nd Floor Outisde Room 630 Right	Flush180	13-OCT-16	0.460	ppb
50951	50951-2-HAL-F03	Addition- 2nd Floor Outisde Room 630 Right	Flush180	13-OCT-16	0.374	ppb
50951	50951-2-HAL-F03	Addition- 2nd Floor Outisde Room 630 Right	Flush180	13-OCT-16	0.365	ppb
50951	50951-2-HAL-F03	Addition- 2nd Floor Outisde Room 630 Right	Flush180	13-OCT-16	0.404	ppb
50951	50951-2-HAL-F03	Addition- 2nd Floor Outisde Room 630 Right	Initial	28-JUL-23	1.000	ug/L
50951	50951-2-HAL-F03	Addition- 2nd Floor Outisde Room 630 Right	Initial	13-OCT-16	0.568	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F03	630 Right				
51590	51590-1-CAF-WC09	1st Floor Cafeteria Fountain Across From Room 127	Flush180	13-OCT-16	0.615	ppb
51590	51590-1-CAF-WC09	1st Floor Cafeteria Fountain Across From Room 127	Flush180	13-OCT-16	0.618	ppb
51590	51590-1-CAF-WC09	1st Floor Cafeteria Fountain Across From Room 127	Flush180	13-OCT-16	0.656	ppb
51590	51590-1-CAF-WC09	1st Floor Cafeteria Fountain Across From Room 127	Flush180	13-OCT-16	0.612	ppb
51590	51590-1-CAF-WC09	1st Floor Cafeteria Fountain Across From Room 127	Initial	13-OCT-16	0.586	ppb
51590	51590-1-HAL-F01	1st Floor Fountain Left Side Across From Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F01	1st Floor Fountain Left Side Across From Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F01	1st Floor Fountain Left Side Across From Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F01	1st Floor Fountain Left Side Across From Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F01	1st Floor Fountain Left Side Across From Room 159	Flush180	13-OCT-16	0.198	ppb
51590	51590-1-HAL-F01	1st Floor Fountain Left Side Across From Room 159	Flush180	13-OCT-16	0.197	ppb
51590	51590-1-HAL-F01	1st Floor Fountain Left Side Across From Room 159	Flush180	13-OCT-16	0.271	ppb
51590	51590-1-HAL-F01	1st Floor Fountain Left Side Across From Room 159	Flush180	13-OCT-16	0.246	ppb
51590	51590-1-HAL-F01	1st Floor Fountain Left Side Across From Room 159	Initial	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F01	1st Floor Fountain Left Side Across From Room 159	Initial	13-OCT-16	0.393	ppb
51590	51590-1-HAL-F04	1st Floor Fountain Left Side Across From Room 165	Flush180	13-OCT-16	0.447	ppb
51590	51590-1-HAL-F04	1st Floor Fountain Left Side Across From Room 165	Flush180	13-OCT-16	0.901	ppb
51590	51590-1-HAL-F04	1st Floor Fountain Left Side Across From Room 165	Flush180	13-OCT-16	0.371	ppb
51590	51590-1-HAL-F04	1st Floor Fountain Left Side Across From Room 165	Flush180	13-OCT-16	0.368	ppb
51590	51590-1-HAL-F04	1st Floor Fountain Left Side Across From Room 165	Initial	13-OCT-16	0.698	ppb
51590	51590-1-HAL-F06	1st Floor Fountain Left Side Across From Room 166	Flush180	13-OCT-16	1.080	ppb
51590	51590-1-HAL-F06	1st Floor Fountain Left Side Across From Room 166	Flush180	13-OCT-16	1.140	ppb
51590	51590-1-HAL-F06	1st Floor Fountain Left Side Across From Room 166	Flush180	13-OCT-16	1.630	ppb
51590	51590-1-HAL-F06	1st Floor Fountain Left Side Across From Room 166	Flush180	13-OCT-16	1.440	ppb
51590	51590-1-HAL-F06	1st Floor Fountain Left Side Across From Room 166	Initial	13-OCT-16	4.300	ppb
51590	51590-1-HAL-F07	1st Floor Fountain Left Side Across From Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F07	1st Floor Fountain Left Side Across From Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F07	1st Floor Fountain Left Side Across From Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F07	1st Floor Fountain Left Side Across From Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F07	1st Floor Fountain Left Side Across From Room 184	Flush180	13-OCT-16	1.000	ppb
51590	51590-1-HAL-F07	1st Floor Fountain Left Side Across From Room 184	Flush180	13-OCT-16	1.000	ppb
51590	51590-1-HAL-F07	1st Floor Fountain Left Side Across From Room 184	Flush180	13-OCT-16	1.000	ppb
51590	51590-1-HAL-F07	1st Floor Fountain Left Side Across From Room 184	Initial	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F07	1st Floor Fountain Left Side Across From Room 184	Initial	13-OCT-16	1.000	ppb
51590	51590-1-HAL-F07	1st Floor Fountain Left Side Across From Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F02	1st Floor Fountain Right Side Across From Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-	1st Floor Fountain Right Side	Flush180	28-JUL-23	1.000	ug/L

Water Quality Assessment
Marie Sklodowska Curie Metropolitan High School

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F02	Across From Room 159				
51590	51590-1-HAL-F02	1st Floor Fountain Right Side Across From Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F02	1st Floor Fountain Right Side Across From Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F02	1st Floor Fountain Right Side Across From Room 159	Flush180	13-OCT-16	0.121	ppb
51590	51590-1-HAL-F02	1st Floor Fountain Right Side Across From Room 159	Flush180	13-OCT-16	0.166	ppb
51590	51590-1-HAL-F02	1st Floor Fountain Right Side Across From Room 159	Flush180	13-OCT-16	0.207	ppb
51590	51590-1-HAL-F02	1st Floor Fountain Right Side Across From Room 159	Flush180	13-OCT-16	1.000	ppb
51590	51590-1-HAL-F02	1st Floor Fountain Right Side Across From Room 159	Initial	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F02	1st Floor Fountain Right Side Across From Room 159	Initial	13-OCT-16	0.273	ppb
51590	51590-1-HAL-F03	1st Floor Fountain Right Side Across From Room 165	Flush180	28-JUL-23	1.020	ug/L
51590	51590-1-HAL-F03	1st Floor Fountain Right Side Across From Room 165	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F03	1st Floor Fountain Right Side Across From Room 165	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F03	1st Floor Fountain Right Side Across From Room 165	Flush180	13-OCT-16	0.669	ppb
51590	51590-1-HAL-F03	1st Floor Fountain Right Side Across From Room 165	Flush180	13-OCT-16	0.433	ppb
51590	51590-1-HAL-F03	1st Floor Fountain Right Side Across From Room 165	Flush180	13-OCT-16	0.489	ppb
51590	51590-1-HAL-F03	1st Floor Fountain Right Side Across From Room 165	Flush180	13-OCT-16	0.399	ppb
51590	51590-1-HAL-F03	1st Floor Fountain Right Side Across From Room 165	Initial	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F03	1st Floor Fountain Right Side Across From Room 165	Initial	13-OCT-16	0.939	ppb
51590	51590-1-HAL-F05	1st Floor Fountain Right Side Across From Room 166	Flush180	13-OCT-16	0.955	ppb
51590	51590-1-HAL-F05	1st Floor Fountain Right Side Across From Room 166	Flush180	13-OCT-16	1.050	ppb
51590	51590-1-HAL-F05	1st Floor Fountain Right Side Across From Room 166	Flush180	13-OCT-16	1.630	ppb
51590	51590-1-HAL-F05	1st Floor Fountain Right Side Across From Room 166	Flush180	13-OCT-16	1.970	ppb
51590	51590-1-HAL-F05	1st Floor Fountain Right Side Across From Room 166	Initial	13-OCT-16	2.010	ppb
51590	51590-1-HAL-F08	1st Floor Fountain Right Side Across From Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F08	1st Floor Fountain Right Side Across From Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F08	1st Floor Fountain Right Side Across From Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F08	1st Floor Fountain Right Side Across From Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F08	1st Floor Fountain Right Side Across From Room 184	Flush180	13-OCT-16	1.000	ppb
51590	51590-1-HAL-F08	1st Floor Fountain Right Side Across From Room 184	Flush180	13-OCT-16	1.000	ppb
51590	51590-1-HAL-F08	1st Floor Fountain Right Side Across From Room 184	Flush180	13-OCT-16	1.000	ppb
51590	51590-1-HAL-F08	1st Floor Fountain Right Side Across From Room 184	Initial	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-F08	1st Floor Fountain Right Side Across From Room 184	Initial	13-OCT-16	1.000	ppb
51590	51590-1-159-F11	1st Floor Pre K Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-159-F11	1st Floor Pre K Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-159-F11	1st Floor Pre K Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-159-F11	1st Floor Pre K Room 159	Flush180	28-JUL-23	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51590	51590-1-159-S12	1st Floor Pre K Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-159-S12	1st Floor Pre K Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-159-S12	1st Floor Pre K Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-159-S12	1st Floor Pre K Room 159	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-159-S12	1st Floor Pre K Room 159	Flush180	13-OCT-16	0.636	ppb
51590	51590-1-159-S12	1st Floor Pre K Room 159	Flush180	13-OCT-16	0.429	ppb
51590	51590-1-159-S12	1st Floor Pre K Room 159	Flush180	13-OCT-16	0.330	ppb
51590	51590-1-159-F11	1st Floor Pre K Room 159	Flush180	13-OCT-16	0.575	ppb
51590	51590-1-159-F11	1st Floor Pre K Room 159	Flush180	13-OCT-16	0.359	ppb
51590	51590-1-159-F11	1st Floor Pre K Room 159	Flush180	13-OCT-16	0.460	ppb
51590	51590-1-159-F11	1st Floor Pre K Room 159	Flush180	13-OCT-16	0.264	ppb
51590	51590-1-159-S12	1st Floor Pre K Room 159	Flush180	13-OCT-16	0.633	ppb
51590	51590-1-159-F11	1st Floor Pre K Room 159	Initial	28-JUL-23	1.000	ug/L
51590	51590-1-159-S12	1st Floor Pre K Room 159	Initial	28-JUL-23	1.000	ug/L
51590	51590-1-159-F11	1st Floor Pre K Room 159	Initial	13-OCT-16	0.354	ppb
51590	51590-1-159-S12	1st Floor Pre K Room 159	Initial	13-OCT-16	0.154	ppb
51590	51590-2-CAF-WC09	2nd Floor Fountain Across From Room 227	Flush180	28-JUL-23	1.420	ug/L
51590	51590-2-CAF-WC09	2nd Floor Fountain Across From Room 227	Flush180	28-JUL-23	2.170	ug/L
51590	51590-2-CAF-WC09	2nd Floor Fountain Across From Room 227	Flush180	28-JUL-23	2.930	ug/L
51590	51590-2-CAF-WC09	2nd Floor Fountain Across From Room 227	Flush180	28-JUL-23	3.170	ug/L
51590	51590-2-CAF-WC09	2nd Floor Fountain Across From Room 227	Flush180	13-OCT-16	0.488	ppb
51590	51590-2-CAF-WC09	2nd Floor Fountain Across From Room 227	Flush180	13-OCT-16	0.560	ppb
51590	51590-2-CAF-WC09	2nd Floor Fountain Across From Room 227	Flush180	13-OCT-16	0.538	ppb
51590	51590-2-CAF-WC09	2nd Floor Fountain Across From Room 227	Flush180	13-OCT-16	0.577	ppb
51590	51590-2-CAF-WC09	2nd Floor Fountain Across From Room 227	Initial	28-JUL-23	1.000	ug/L
51590	51590-2-CAF-WC09	2nd Floor Fountain Across From Room 227	Initial	13-OCT-16	0.531	ppb
51590	51590-2-HAL-F01	2nd Floor Fountain Left Side Across From Room 246	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F01	2nd Floor Fountain Left Side Across From Room 246	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F01	2nd Floor Fountain Left Side Across From Room 246	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F01	2nd Floor Fountain Left Side Across From Room 246	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F01	2nd Floor Fountain Left Side Across From Room 246	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F01	2nd Floor Fountain Left Side Across From Room 246	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F01	2nd Floor Fountain Left Side Across From Room 246	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F01	2nd Floor Fountain Left Side Across From Room 246	Initial	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F01	2nd Floor Fountain Left Side Across From Room 246	Initial	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F03	2nd Floor Fountain Left Side Across From Room 262	Flush180	13-OCT-16	0.724	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51590	51590-2-HAL-F03	2nd Floor Fountain Left Side Across From Room 262	Flush180	13-OCT-16	0.813	ppb
51590	51590-2-HAL-F03	2nd Floor Fountain Left Side Across From Room 262	Flush180	13-OCT-16	0.738	ppb
51590	51590-2-HAL-F03	2nd Floor Fountain Left Side Across From Room 262	Flush180	13-OCT-16	0.736	ppb
51590	51590-2-HAL-F03	2nd Floor Fountain Left Side Across From Room 262	Initial	13-OCT-16	0.841	ppb
51590	51590-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 272	Flush180	28-JUL-23	1.110	ug/L
51590	51590-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 272	Flush180	28-JUL-23	1.020	ug/L
51590	51590-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 272	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 272	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 272	Flush180	13-OCT-16	0.338	ppb
51590	51590-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 272	Flush180	13-OCT-16	0.328	ppb
51590	51590-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 272	Flush180	13-OCT-16	0.322	ppb
51590	51590-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 272	Flush180	13-OCT-16	0.330	ppb
51590	51590-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 272	Initial	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F05	2nd Floor Fountain Left Side Across From Room 272	Initial	13-OCT-16	0.241	ppb
51590	51590-2-HAL-F07	2nd Floor Fountain Left Side Across From Room 287	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F07	2nd Floor Fountain Left Side Across From Room 287	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F07	2nd Floor Fountain Left Side Across From Room 287	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F07	2nd Floor Fountain Left Side Across From Room 287	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F07	2nd Floor Fountain Left Side Across From Room 287	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F07	2nd Floor Fountain Left Side Across From Room 287	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F07	2nd Floor Fountain Left Side Across From Room 287	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F07	2nd Floor Fountain Left Side Across From Room 287	Initial	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F07	2nd Floor Fountain Left Side Across From Room 287	Initial	13-OCT-16	0.144	ppb
51590	51590-2-HAL-F02	2nd Floor Fountain Right Side Across From Room 246	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F02	2nd Floor Fountain Right Side Across From Room 246	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F02	2nd Floor Fountain Right Side Across From Room 246	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F02	2nd Floor Fountain Right Side Across From Room 246	Initial	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 262	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 262	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 262	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 262	Flush180	13-OCT-16	0.758	ppb
51590	51590-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 262	Flush180	13-OCT-16	0.704	ppb
51590	51590-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 262	Flush180	13-OCT-16	0.729	ppb
51590	51590-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 262	Flush180	13-OCT-16	0.659	ppb
51590	51590-2-HAL-	2nd Floor Fountain Right Side	Initial	28-JUL-23	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F04	Across From Room 262				
51590	51590-2-HAL-F04	2nd Floor Fountain Right Side Across From Room 262	Initial	13-OCT-16	0.716	ppb
51590	51590-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 272	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 272	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 272	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 272	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 272	Flush180	13-OCT-16	0.358	ppb
51590	51590-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 272	Flush180	13-OCT-16	0.360	ppb
51590	51590-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 272	Flush180	13-OCT-16	0.384	ppb
51590	51590-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 272	Flush180	13-OCT-16	0.436	ppb
51590	51590-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 272	Initial	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-F06	2nd Floor Fountain Right Side Across From Room 272	Initial	13-OCT-16	0.281	ppb
51590	51590-2-HAL-F08	2nd Floor Fountain Right Side Across From Room 287	Flush180	13-OCT-16	0.186	ppb
51590	51590-2-HAL-F08	2nd Floor Fountain Right Side Across From Room 287	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F08	2nd Floor Fountain Right Side Across From Room 287	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F08	2nd Floor Fountain Right Side Across From Room 287	Flush180	13-OCT-16	1.000	ppb
51590	51590-2-HAL-F08	2nd Floor Fountain Right Side Across From Room 287	Initial	13-OCT-16	1.000	ppb
51590	51590-3-CAF-WC08	3rd Floor Fountain Across From Room 333	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-CAF-WC08	3rd Floor Fountain Across From Room 333	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-CAF-WC08	3rd Floor Fountain Across From Room 333	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-CAF-WC08	3rd Floor Fountain Across From Room 333	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-CAF-WC08	3rd Floor Fountain Across From Room 333	Flush180	13-OCT-16	0.499	ppb
51590	51590-3-CAF-WC08	3rd Floor Fountain Across From Room 333	Flush180	13-OCT-16	0.537	ppb
51590	51590-3-CAF-WC08	3rd Floor Fountain Across From Room 333	Flush180	13-OCT-16	0.396	ppb
51590	51590-3-CAF-WC08	3rd Floor Fountain Across From Room 333	Flush180	13-OCT-16	0.509	ppb
51590	51590-3-CAF-WC08	3rd Floor Fountain Across From Room 333	Initial	28-JUL-23	1.000	ug/L
51590	51590-3-CAF-WC08	3rd Floor Fountain Across From Room 333	Initial	13-OCT-16	0.491	ppb
51590	51590-3-HAL-F01	3rd Floor Fountain Left Side Across From Room 248	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F01	3rd Floor Fountain Left Side Across From Room 248	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F01	3rd Floor Fountain Left Side Across From Room 248	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F01	3rd Floor Fountain Left Side Across From Room 248	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F01	3rd Floor Fountain Left Side Across From Room 248	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F01	3rd Floor Fountain Left Side Across From Room 248	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F01	3rd Floor Fountain Left Side Across From Room 248	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F01	3rd Floor Fountain Left Side Across From Room 248	Initial	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F01	3rd Floor Fountain Left Side Across From Room 248	Initial	13-OCT-16	0.148	ppb
51590	51590-3-HAL-F01	3rd Floor Fountain Left Side	Flush180	28-JUL-23	1.660	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F04	Across From Room 371				
51590	51590-3-HAL-F04	3rd Floor Fountain Left Side Across From Room 371	Flush180	28-JUL-23	1.650	ug/L
51590	51590-3-HAL-F04	3rd Floor Fountain Left Side Across From Room 371	Flush180	28-JUL-23	1.670	ug/L
51590	51590-3-HAL-F04	3rd Floor Fountain Left Side Across From Room 371	Flush180	28-JUL-23	1.620	ug/L
51590	51590-3-HAL-F04	3rd Floor Fountain Left Side Across From Room 371	Flush180	13-OCT-16	0.837	ppb
51590	51590-3-HAL-F04	3rd Floor Fountain Left Side Across From Room 371	Flush180	13-OCT-16	0.656	ppb
51590	51590-3-HAL-F04	3rd Floor Fountain Left Side Across From Room 371	Flush180	13-OCT-16	0.666	ppb
51590	51590-3-HAL-F04	3rd Floor Fountain Left Side Across From Room 371	Flush180	13-OCT-16	0.680	ppb
51590	51590-3-HAL-F04	3rd Floor Fountain Left Side Across From Room 371	Initial	28-JUL-23	1.190	ug/L
51590	51590-3-HAL-F04	3rd Floor Fountain Left Side Across From Room 371	Initial	13-OCT-16	0.371	ppb
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Flush	13-OCT-2023	1.000	ug/L
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Flush	13-OCT-2023	1.000	ug/L
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Flush	13-OCT-2023	1.000	ug/L
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Flush180	28-JUL-23	5.690	ug/L
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Flush180	28-JUL-23	4.310	ug/L
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Flush180	28-JUL-23	3.890	ug/L
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Flush180	28-JUL-23	2.640	ug/L
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Initial	28-JUL-23	13.100	ug/L
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Initial	13-OCT-16	0.228	ppb
51590	51590-3-HAL-F06	3rd Floor Fountain Left Side Across From Room 381	Initial	13-OCT-2023	1.000	ug/L
51590	51590-3-HAL-F02	3rd Floor Fountain Right Side Across From Room 248	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F02	3rd Floor Fountain Right Side Across From Room 248	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F02	3rd Floor Fountain Right Side Across From Room 248	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F02	3rd Floor Fountain Right Side Across From Room 248	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F02	3rd Floor Fountain Right Side Across From Room 248	Flush180	13-OCT-16	0.495	ppb
51590	51590-3-HAL-F02	3rd Floor Fountain Right Side Across From Room 248	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F02	3rd Floor Fountain Right Side Across From Room 248	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F02	3rd Floor Fountain Right Side Across From Room 248	Initial	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F02	3rd Floor Fountain Right Side Across From Room 248	Initial	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F03	3rd Floor Fountain Right Side Across From Room 360	Flush180	13-OCT-16	0.859	ppb
51590	51590-3-HAL-F03	3rd Floor Fountain Right Side Across From Room 360	Flush180	13-OCT-16	0.675	ppb
51590	51590-3-HAL-F03	3rd Floor Fountain Right Side Across From Room 360	Flush180	13-OCT-16	0.882	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51590	51590-3-HAL-F03	3rd Floor Fountain Right Side Across From Room 360	Flush180	13-OCT-16	0.827	ppb
51590	51590-3-HAL-F03	3rd Floor Fountain Right Side Across From Room 360	Initial	13-OCT-16	1.160	ppb
51590	51590-3-HAL-F05	3rd Floor Fountain Right Side Across From Room 371	Flush180	28-JUL-23	1.610	ug/L
51590	51590-3-HAL-F05	3rd Floor Fountain Right Side Across From Room 371	Flush180	28-JUL-23	1.640	ug/L
51590	51590-3-HAL-F05	3rd Floor Fountain Right Side Across From Room 371	Flush180	28-JUL-23	1.640	ug/L
51590	51590-3-HAL-F05	3rd Floor Fountain Right Side Across From Room 371	Flush180	28-JUL-23	1.650	ug/L
51590	51590-3-HAL-F05	3rd Floor Fountain Right Side Across From Room 371	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F05	3rd Floor Fountain Right Side Across From Room 371	Flush180	13-OCT-16	0.570	ppb
51590	51590-3-HAL-F05	3rd Floor Fountain Right Side Across From Room 371	Flush180	13-OCT-16	0.511	ppb
51590	51590-3-HAL-F05	3rd Floor Fountain Right Side Across From Room 371	Flush180	13-OCT-16	0.522	ppb
51590	51590-3-HAL-F05	3rd Floor Fountain Right Side Across From Room 371	Initial	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F05	3rd Floor Fountain Right Side Across From Room 371	Initial	13-OCT-16	0.458	ppb
51590	51590-3-HAL-F07	3rd Floor Fountain Right Side Across From Room 381	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F07	3rd Floor Fountain Right Side Across From Room 381	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F07	3rd Floor Fountain Right Side Across From Room 381	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F07	3rd Floor Fountain Right Side Across From Room 381	Flush180	28-JUL-23	1.000	ug/L
51590	51590-3-HAL-F07	3rd Floor Fountain Right Side Across From Room 381	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F07	3rd Floor Fountain Right Side Across From Room 381	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F07	3rd Floor Fountain Right Side Across From Room 381	Flush180	13-OCT-16	1.000	ppb
51590	51590-3-HAL-F07	3rd Floor Fountain Right Side Across From Room 381	Initial	28-JUL-23	1.540	ug/L
51590	51590-3-HAL-F07	3rd Floor Fountain Right Side Across From Room 381	Initial	13-OCT-16	0.167	ppb
51590	51590-1-HAL-BF01	Across Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-BF01	Across Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-BF01	Across Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-BF01	Across Room 184	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-HAL-BF01	Across Room 184	Initial	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-BF01	Across from Room 287	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-BF01	Across from Room 287	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-BF01	Across from Room 287	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-BF01	Across from Room 287	Flush180	28-JUL-23	1.000	ug/L
51590	51590-2-HAL-BF01	Across from Room 287	Initial	28-JUL-23	1.000	ug/L
51590	51590-B-HAL-WC08	Basement By Boiler Room / Washroom Water Cooler	Flush180	28-JUL-23	1.110	ug/L
51590	51590-B-HAL-WC08	Basement By Boiler Room / Washroom Water Cooler	Flush180	28-JUL-23	1.080	ug/L
51590	51590-B-HAL-WC08	Basement By Boiler Room / Washroom Water Cooler	Flush180	28-JUL-23	1.000	ug/L
51590	51590-B-HAL-WC08	Basement By Boiler Room / Washroom Water Cooler	Flush180	28-JUL-23	1.000	ug/L
51590	51590-B-HAL-WC08	Basement By Boiler Room / Washroom Water Cooler	Flush180	13-OCT-16	0.296	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51590	51590-B-HAL-WC08	Basement By Boiler Room / Washroom Water Cooler	Flush180	13-OCT-16	0.273	ppb
51590	51590-B-HAL-WC08	Basement By Boiler Room / Washroom Water Cooler	Flush180	13-OCT-16	0.302	ppb
51590	51590-B-HAL-WC08	Basement By Boiler Room / Washroom Water Cooler	Flush180	13-OCT-16	0.255	ppb
51590	51590-B-HAL-WC08	Basement By Boiler Room / Washroom Water Cooler	Initial	28-JUL-23	1.000	ug/L
51590	51590-B-HAL-WC08	Basement By Boiler Room / Washroom Water Cooler	Initial	13-OCT-16	0.217	ppb
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush	03-NOV-2023	1.000	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush	03-NOV-2023	1.000	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush	03-NOV-2023	1.000	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush	03-NOV-2023	1.000	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush	13-OCT-2023	1.240	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush	13-OCT-2023	1.000	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush	13-OCT-2023	1.000	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush	13-OCT-2023	1.000	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush180	28-JUL-23	3.980	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush180	28-JUL-23	3.940	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush180	28-JUL-23	14.900	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush180	28-JUL-23	41.900	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush180	13-OCT-16	0.663	ppb
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush180	13-OCT-16	0.652	ppb
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush180	13-OCT-16	0.983	ppb
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Flush180	13-OCT-16	0.791	ppb
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Initial	28-JUL-23	9.410	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Initial	13-OCT-16	1.810	ppb
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Initial	03-NOV-2023	4.360	ug/L
51590	51590-B-KIT-KS05	Basement Kitchen Center Kettle Left Side	Initial	13-OCT-2023	11.300	ug/L
51590	51590-B-KIT-KS06	Basement Kitchen North Sink Left Side	Flush180	28-JUL-23	1.000	ug/L
51590	51590-B-KIT-KS06	Basement Kitchen North Sink Left Side	Flush180	28-JUL-23	1.000	ug/L
51590	51590-B-KIT-KS06	Basement Kitchen North Sink Left Side	Flush180	28-JUL-23	1.000	ug/L
51590	51590-B-KIT-KS06	Basement Kitchen North Sink Left Side	Flush180	28-JUL-23	1.000	ug/L
51590	51590-B-KIT-KS06	Basement Kitchen North Sink Left Side	Flush180	13-OCT-16	0.280	ppb
51590	51590-B-KIT-KS06	Basement Kitchen North Sink Left Side	Flush180	13-OCT-16	0.194	ppb
51590	51590-B-KIT-KS06	Basement Kitchen North Sink Left Side	Flush180	13-OCT-16	0.233	ppb
51590	51590-B-KIT-KS06	Basement Kitchen North Sink Left Side	Flush180	13-OCT-16	0.210	ppb
51590	51590-B-KIT-KS06	Basement Kitchen North Sink Left Side	Initial	28-JUL-23	1.000	ug/L
51590	51590-B-KIT-KS06	Basement Kitchen North Sink Left Side	Initial	13-OCT-16	0.480	ppb
51590	51590-B-KIT-KS07	Basement Kitchen North Sink Right Side	Flush180	28-JUL-23	1.000	ug/L
51590	51590-B-KIT-KS07	Basement Kitchen North Sink Right Side	Flush180	28-JUL-23	1.000	ug/L
51590	51590-B-KIT-	Basement Kitchen North Sink	Flush180	28-JUL-23	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	KS07	Right Side				
51590	51590-B-KIT-KS07	Basement Kitchen North Sink Right Side	Flush180	28-JUL-23	1.000	ug/L
51590	51590-B-KIT-KS07	Basement Kitchen North Sink Right Side	Flush180	13-OCT-16	0.375	ppb
51590	51590-B-KIT-KS07	Basement Kitchen North Sink Right Side	Flush180	13-OCT-16	0.210	ppb
51590	51590-B-KIT-KS07	Basement Kitchen North Sink Right Side	Flush180	13-OCT-16	0.218	ppb
51590	51590-B-KIT-KS07	Basement Kitchen North Sink Right Side	Flush180	13-OCT-16	0.216	ppb
51590	51590-B-KIT-KS07	Basement Kitchen North Sink Right Side	Initial	28-JUL-23	1.170	ug/L
51590	51590-B-KIT-KS07	Basement Kitchen North Sink Right Side	Initial	13-OCT-16	0.267	ppb
51590	51590-B-KIT-KS01	Basement Kitchen South Sink Left Side	Flush180	28-JUL-23	1.170	ug/L
51590	51590-B-KIT-KS01	Basement Kitchen South Sink Left Side	Flush180	28-JUL-23	2.030	ug/L
51590	51590-B-KIT-KS01	Basement Kitchen South Sink Left Side	Flush180	28-JUL-23	1.060	ug/L
51590	51590-B-KIT-KS01	Basement Kitchen South Sink Left Side	Flush180	28-JUL-23	1.090	ug/L
51590	51590-B-KIT-KS01	Basement Kitchen South Sink Left Side	Flush180	13-OCT-16	0.298	ppb
51590	51590-B-KIT-KS01	Basement Kitchen South Sink Left Side	Flush180	13-OCT-16	0.360	ppb
51590	51590-B-KIT-KS01	Basement Kitchen South Sink Left Side	Flush180	13-OCT-16	0.370	ppb
51590	51590-B-KIT-KS01	Basement Kitchen South Sink Left Side	Flush180	13-OCT-16	0.329	ppb
51590	51590-B-KIT-KS01	Basement Kitchen South Sink Left Side	Initial	28-JUL-23	1.490	ug/L
51590	51590-B-KIT-KS01	Basement Kitchen South Sink Left Side	Initial	13-OCT-16	0.918	ppb
51590	51590-B-KIT-KS02	Basement Kitchen South Sink Right Side	Flush180	28-JUL-23	1.000	ug/L
51590	51590-B-KIT-KS02	Basement Kitchen South Sink Right Side	Flush180	28-JUL-23	2.150	ug/L
51590	51590-B-KIT-KS02	Basement Kitchen South Sink Right Side	Flush180	28-JUL-23	1.830	ug/L
51590	51590-B-KIT-KS02	Basement Kitchen South Sink Right Side	Flush180	28-JUL-23	1.480	ug/L
51590	51590-B-KIT-KS02	Basement Kitchen South Sink Right Side	Flush180	13-OCT-16	0.225	ppb
51590	51590-B-KIT-KS02	Basement Kitchen South Sink Right Side	Flush180	13-OCT-16	0.221	ppb
51590	51590-B-KIT-KS02	Basement Kitchen South Sink Right Side	Flush180	13-OCT-16	0.210	ppb
51590	51590-B-KIT-KS02	Basement Kitchen South Sink Right Side	Flush180	13-OCT-16	0.736	ppb
51590	51590-B-KIT-KS02	Basement Kitchen South Sink Right Side	Initial	28-JUL-23	1.490	ug/L
51590	51590-B-KIT-KS02	Basement Kitchen South Sink Right Side	Initial	13-OCT-16	0.235	ppb
51590	51590-1-CAF-F01	Room 116 Lunchroom	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-CAF-F01	Room 116 Lunchroom	Flush180	28-JUL-23	1.050	ug/L
51590	51590-1-CAF-F01	Room 116 Lunchroom	Flush180	28-JUL-23	1.000	ug/L
51590	51590-1-CAF-F01	Room 116 Lunchroom	Flush180	28-JUL-23	1.100	ug/L
51590	51590-1-CAF-F01	Room 116 Lunchroom	Initial	28-JUL-23	1.000	ug/L