



**Sep 10, 2024**

**FIELD**

**7019 N ASHLAND AVE, Chicago IL 60626.**

Dear **FIELD** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit [www.cdc.gov/lead](http://www.cdc.gov/lead).

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



**Sep 10, 2024**

**FIELD**

**7019 N ASHLAND AVE, Chicago IL 60626.**

Estimadas familias de **FIELD**:

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer  
Director de Salud y Seguridad Ambientales  
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51057	51507-1-W-HAL-F03	1st FI Outside room 104, Left fountain	Flush	24-JAN-2024	1.000	ug/L
51057	51507-1-W-HAL-F03	1st FI Outside room 104, Left fountain	Flush	24-JAN-2024	1.000	ug/L
51057	51507-1-W-HAL-F03	1st FI Outside room 104, Left fountain	Flush	24-JAN-2024	1.000	ug/L
51057	51507-1-W-HAL-F03	1st FI Outside room 104, Left fountain	Flush	24-JAN-2024	1.000	ug/L
51057	51507-1-W-HAL-F03	1st FI Outside room 104, Left fountain	Initial	24-JAN-2024	1.000	ug/L
51057	51507-1-W-HAL-F04	1st FI Outside room 104, Right fountain	Flush	24-JAN-2024	1.000	ug/L
51057	51507-1-W-HAL-F04	1st FI Outside room 104, Right fountain	Flush	24-JAN-2024	1.000	ug/L
51057	51507-1-W-HAL-F04	1st FI Outside room 104, Right fountain	Flush	24-JAN-2024	1.000	ug/L
51057	51507-1-W-HAL-F04	1st FI Outside room 104, Right fountain	Flush	24-JAN-2024	1.000	ug/L
51057	51507-1-W-HAL-F04	1st FI Outside room 104, Right fountain	Initial	24-JAN-2024	1.000	ug/L
51057	51507-2-W-HAL-F03	2nd FI outside room 204, Left fountain	Flush	24-JAN-2024	1.510	ug/L
51057	51507-2-W-HAL-F03	2nd FI outside room 204, Left fountain	Flush	24-JAN-2024	1.470	ug/L
51057	51507-2-W-HAL-F03	2nd FI outside room 204, Left fountain	Flush	24-JAN-2024	1.380	ug/L
51057	51507-2-W-HAL-F03	2nd FI outside room 204, Left fountain	Flush	24-JAN-2024	1.870	ug/L
51057	51507-2-W-HAL-F03	2nd FI outside room 204, Left fountain	Initial	24-JAN-2024	1.560	ug/L
51057	51507-2-W-HAL-F04	2nd FI outside room 204, Right fountain	Flush	24-JAN-2024	1.240	ug/L
51057	51507-2-W-HAL-F04	2nd FI outside room 204, Right fountain	Flush	24-JAN-2024	1.140	ug/L
51057	51507-2-W-HAL-F04	2nd FI outside room 204, Right fountain	Flush	24-JAN-2024	1.040	ug/L
51057	51507-2-W-HAL-F04	2nd FI outside room 204, Right fountain	Flush	24-JAN-2024	1.010	ug/L
51057	51507-2-W-HAL-F04	2nd FI outside room 204, Right fountain	Initial	24-JAN-2024	1.610	ug/L
51057	51057-B-N-HAL-F03	Basement, Across from room 504, Left fountain	Flush	24-JAN-2024	14.600	ug/L
51057	51057-B-N-HAL-F03	Basement, Across from room 504, Left fountain	Flush	24-JAN-2024	19.400	ug/L
51057	51057-B-N-HAL-F03	Basement, Across from room 504, Left fountain	Flush	24-JAN-2024	13.200	ug/L
51057	51057-B-N-HAL-F03	Basement, Across from room 504, Left fountain	Flush	24-JAN-2024	11.800	ug/L
51057	51057-B-N-HAL-F03	Basement, Across from room 504, Left fountain	Initial	24-JAN-2024	9.590	ug/L
51057	51057-B-N-HAL-F04	Basement, Across from room 504, Right fountain	Flush	24-JAN-2024	16.100	ug/L
51057	51057-B-N-HAL-F04	Basement, Across from room 504, Right fountain	Flush	24-JAN-2024	9.460	ug/L
51057	51057-B-N-HAL-F04	Basement, Across from room 504, Right fountain	Flush	24-JAN-2024	10.400	ug/L
51057	51057-B-N-HAL-F04	Basement, Across from room 504, Right fountain	Flush	24-JAN-2024	4.270	ug/L
51057	51057-B-N-HAL-F04	Basement, Across from room 504, Right fountain	Initial	24-JAN-2024	13.900	ug/L
51057	51057-B-E-HAL-RBF01	Basement, Outside Assembly Hall, Left fountain	Flush	24-JAN-2024	4.260	ug/L
51057	51057-B-E-HAL-RBF01	Basement, Outside Assembly Hall, Left fountain	Flush	24-JAN-2024	3.110	ug/L
51057	51057-B-E-HAL-RBF01	Basement, Outside Assembly Hall, Left fountain	Flush	24-JAN-2024	2.300	ug/L
51057	51057-B-E-HAL-RBF01	Basement, Outside Assembly Hall, Left fountain	Flush	24-JAN-2024	1.970	ug/L
51057	51057-B-E-HAL-RBF01	Basement, Outside Assembly Hall, Left fountain	Initial	24-JAN-2024	3.090	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51057	51507-B-E-HAL-F02	Basement, Outside Assembly Hall, Right fountain	Flush	24-JAN-2024	3.640	ug/L
51057	51507-B-E-HAL-F02	Basement, Outside Assembly Hall, Right fountain	Flush	24-JAN-2024	2.930	ug/L
51057	51507-B-E-HAL-F02	Basement, Outside Assembly Hall, Right fountain	Flush	24-JAN-2024	2.830	ug/L
51057	51507-B-E-HAL-F02	Basement, Outside Assembly Hall, Right fountain	Flush	24-JAN-2024	2.600	ug/L
51057	51507-B-E-HAL-F02	Basement, Outside Assembly Hall, Right fountain	Initial	24-JAN-2024	4.610	ug/L
51057	51057-1-E-HAL-F01	Main- 1st Floor Outside Main Office, Left Fountain	Flush180	22-SEP-16	1.000	ppb
51057	51057-1-E-HAL-F01	Main- 1st Floor Outside Main Office, Left Fountain	Flush180	22-SEP-16	1.000	ppb
51057	51057-1-E-HAL-F01	Main- 1st Floor Outside Main Office, Left Fountain	Flush180	22-SEP-16	1.000	ppb
51057	51057-1-E-HAL-F01	Main- 1st Floor Outside Main Office, Left Fountain	Flush180	22-SEP-16	1.000	ppb
51057	51057-1-E-HAL-F01	Main- 1st Floor Outside Main Office, Left Fountain	Flush180	27-MAR-19	2.000	ug/L
51057	51057-1-E-HAL-F01	Main- 1st Floor Outside Main Office, Left Fountain	Flush180	27-MAR-19	1.120	ug/L
51057	51057-1-E-HAL-F01	Main- 1st Floor Outside Main Office, Left Fountain	Flush180	27-MAR-19	1.000	ug/L
51057	51057-1-E-HAL-F01	Main- 1st Floor Outside Main Office, Left Fountain	Flush180	27-MAR-19	1.000	ug/L
51057	51057-1-E-HAL-F01	Main- 1st Floor Outside Main Office, Left Fountain	Initial	22-SEP-16	1.000	ppb
51057	51057-1-E-HAL-F01	Main- 1st Floor Outside Main Office, Left Fountain	Initial	27-MAR-19	1.830	ug/L
51057	51057-1-E-HAL-F02	Main- 1st Floor Outside Main Office, Right Fountain	Flush180	22-SEP-16	2.200	ppb
51057	51057-1-E-HAL-F02	Main- 1st Floor Outside Main Office, Right Fountain	Flush180	22-SEP-16	2.800	ppb
51057	51057-1-E-HAL-F02	Main- 1st Floor Outside Main Office, Right Fountain	Flush180	22-SEP-16	1.000	ppb
51057	51057-1-E-HAL-F02	Main- 1st Floor Outside Main Office, Right Fountain	Flush180	22-SEP-16	2.200	ppb
51057	51057-1-E-HAL-F02	Main- 1st Floor Outside Main Office, Right Fountain	Initial	22-SEP-16	4.500	ppb
51057	51057-1-W-HAL-F03	Main- 1st Floor Outside Room 104, Left Fountain	Flush180	22-SEP-16	1.000	ppb
51057	51057-1-W-HAL-F03	Main- 1st Floor Outside Room 104, Left Fountain	Flush180	22-SEP-16	1.000	ppb
51057	51057-1-W-HAL-F03	Main- 1st Floor Outside Room 104, Left Fountain	Flush180	22-SEP-16	2.400	ppb
51057	51057-1-W-HAL-F03	Main- 1st Floor Outside Room 104, Left Fountain	Flush180	22-SEP-16	1.000	ppb
51057	51057-1-W-HAL-F03	Main- 1st Floor Outside Room 104, Left Fountain	Flush180	27-MAR-19	1.240	ug/L
51057	51057-1-W-HAL-F03	Main- 1st Floor Outside Room 104, Left Fountain	Flush180	27-MAR-19	1.540	ug/L
51057	51057-1-W-HAL-F03	Main- 1st Floor Outside Room 104, Left Fountain	Flush180	27-MAR-19	1.090	ug/L
51057	51057-1-W-HAL-F03	Main- 1st Floor Outside Room 104, Left Fountain	Flush180	27-MAR-19	1.000	ug/L
51057	51057-1-W-HAL-F03	Main- 1st Floor Outside Room 104, Left Fountain	Initial	22-SEP-16	3.400	ppb
51057	51057-1-W-HAL-F03	Main- 1st Floor Outside Room 104, Left Fountain	Initial	27-MAR-19	2.640	ug/L
51057	51057-1-W-HAL-F04	Main- 1st Floor Outside Room 104, Right Fountain	Flush180	22-SEP-16	240.000	ppb
51057	51057-1-W-HAL-F04	Main- 1st Floor Outside Room 104, Right Fountain	Flush180	22-SEP-16	3.800	ppb
51057	51057-1-W-HAL-F04	Main- 1st Floor Outside Room 104, Right Fountain	Flush180	22-SEP-16	2.400	ppb
51057	51057-1-W-HAL-F04	Main- 1st Floor Outside Room 104, Right Fountain	Flush180	22-SEP-16	5.100	ppb
51057	51057-1-W-HAL-F04	Main- 1st Floor Outside Room 104, Right Fountain	Flush180	27-MAR-19	1.690	ug/L
51057	51057-1-W-HAL-F04	Main- 1st Floor Outside Room 104, Right Fountain	Flush180	27-MAR-19	1.000	ug/L
51057	51057-1-W-HAL-F04	Main- 1st Floor Outside Room 104, Right Fountain	Flush180	27-MAR-19	1.000	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51057	51057-1-W-HAL-F04	Main- 1st Floor Outside Room 104, Right Fountain	Flush180	27-MAR-19	1.000	ug/L
51057	51057-1-W-HAL-F04	Main- 1st Floor Outside Room 104, Right Fountain	Initial	22-SEP-16	38.000	ppb
51057	51057-1-W-HAL-F04	Main- 1st Floor Outside Room 104, Right Fountain	Initial	27-MAR-19	2.020	ug/L
51057	51057-2-E-HAL-F01	Main- 2nd Floor Outside Restrooms, North Fountain	Flush180	10-AUG-17	6.540	ppb
51057	51057-2-E-HAL-F01	Main- 2nd Floor Outside Restrooms, North Fountain	Flush180	10-AUG-17	11.200	ppb
51057	51057-2-E-HAL-F01	Main- 2nd Floor Outside Restrooms, North Fountain	Flush180	10-AUG-17	24.500	ppb
51057	51057-2-E-HAL-F01	Main- 2nd Floor Outside Restrooms, North Fountain	Flush180	10-AUG-17	12.700	ppb
51057	51057-2-E-HAL-F01	Main- 2nd Floor Outside Restrooms, North Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-2-E-HAL-F01	Main- 2nd Floor Outside Restrooms, North Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-2-E-HAL-F01	Main- 2nd Floor Outside Restrooms, North Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-2-E-HAL-F01	Main- 2nd Floor Outside Restrooms, North Fountain	Initial	21-SEP-16	1.000	ppb
51057	51057-2-E-HAL-F01	Main- 2nd Floor Outside Restrooms, North Fountain	Initial	10-AUG-17	12.000	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	10-AUG-17	22.400	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	10-AUG-17	15.200	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	10-AUG-17	13.900	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	10-AUG-17	15.400	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	24-APR-20	1.880	ug/L
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	24-APR-20	2.210	ug/L
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	24-APR-20	2.510	ug/L
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Flush180	24-APR-20	4.730	ug/L
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Initial	10-AUG-17	14.100	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Initial	21-SEP-16	1.000	ppb
51057	51057-2-E-HAL-F02	Main- 2nd Floor Outside Restrooms, South Fountain	Initial	24-APR-20	3.980	ug/L
51057	51057-2-W-HAL-F03	Main- 2nd Floor Outside Room 204, Left Fountain	Flush180	22-SEP-16	2.500	ppb
51057	51057-2-W-HAL-F03	Main- 2nd Floor Outside Room 204, Left Fountain	Flush180	22-SEP-16	2.000	ppb
51057	51057-2-W-HAL-F03	Main- 2nd Floor Outside Room 204, Left Fountain	Flush180	22-SEP-16	5.500	ppb
51057	51057-2-W-HAL-F03	Main- 2nd Floor Outside Room 204, Left Fountain	Flush180	22-SEP-16	4.200	ppb
51057	51057-2-W-HAL-F03	Main- 2nd Floor Outside Room 204, Left Fountain	Flush180	27-MAR-19	3.320	ug/L
51057	51057-2-W-HAL-F03	Main- 2nd Floor Outside Room 204, Left Fountain	Flush180	27-MAR-19	2.370	ug/L
51057	51057-2-W-HAL-F03	Main- 2nd Floor Outside Room 204, Left Fountain	Flush180	27-MAR-19	2.030	ug/L
51057	51057-2-W-HAL-F03	Main- 2nd Floor Outside Room 204, Left Fountain	Flush180	27-MAR-19	1.430	ug/L
51057	51057-2-W-HAL-F03	Main- 2nd Floor Outside Room 204, Left Fountain	Initial	22-SEP-16	7.500	ppb
51057	51057-2-W-	Main- 2nd Floor Outside Room	Initial	27-MAR-19	4.040	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	HAL-F03	204, Left Fountain				
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush	03-OCT-2023	1.000	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush	03-OCT-2023	1.000	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush	03-OCT-2023	1.080	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush	03-OCT-2023	1.000	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	10-AUG-17	2.780	ppb
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	10-AUG-17	2.710	ppb
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	10-AUG-17	2.550	ppb
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	10-AUG-17	2.600	ppb
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	22-SEP-16	4.400	ppb
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	22-SEP-16	4.600	ppb
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	22-SEP-16	5.100	ppb
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	22-SEP-16	4.800	ppb
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	27-MAR-19	1.000	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	27-MAR-19	1.000	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	27-MAR-19	1.000	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	05-AUG-20	8.540	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	08-JAN-21	5.680	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	08-JAN-21	7.110	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	08-JAN-21	6.490	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	08-JAN-21	7.900	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	04-FEB-21	2.460	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	04-FEB-21	2.130	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	04-FEB-21	2.030	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	04-FEB-21	2.230	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	10-DEC-20	4.500	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	10-DEC-20	5.120	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	10-DEC-20	6.810	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	10-DEC-20	9.970	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	13-NOV-20	7.720	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	13-NOV-20	6.030	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	13-NOV-20	4.750	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Flush180	13-NOV-20	5.870	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Initial	10-AUG-17	2.790	ppb
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Initial	22-SEP-16	20.000	ppb
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Initial	27-MAR-19	1.550	ug/L
51057	51057-2-W-	Main- 2nd Floor Outside Room	Initial	05-AUG-20	33.400	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	HAL-F04	204, Right Fountain				
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Initial	08-JAN-21	9.610	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Initial	04-FEB-21	8.400	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Initial	10-DEC-20	61.800	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Initial	13-NOV-20	58.000	ug/L
51057	51057-2-W-HAL-F04	Main- 2nd Floor Outside Room 204, Right Fountain	Initial	03-OCT-2023	1.000	ug/L
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	22-SEP-16	6.400	ppb
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	22-SEP-16	4.900	ppb
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	22-SEP-16	6.800	ppb
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	22-SEP-16	3.700	ppb
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	27-MAR-19	5.120	ug/L
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	27-MAR-19	5.430	ug/L
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	27-MAR-19	4.720	ug/L
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	27-MAR-19	4.550	ug/L
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	24-APR-20	2.250	ug/L
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	24-APR-20	2.810	ug/L
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	24-APR-20	2.200	ug/L
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Flush180	24-APR-20	2.200	ug/L
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Initial	22-SEP-16	11.000	ppb
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Initial	27-MAR-19	6.480	ug/L
51057	51057-B-N-HAL-F03	Main- Basement, Across From Room 504, Left Fountai	Initial	24-APR-20	2.510	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	22-SEP-16	7.100	ppb
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	22-SEP-16	5.500	ppb
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	22-SEP-16	11.000	ppb
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	22-SEP-16	12.000	ppb
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	27-MAR-19	4.710	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	27-MAR-19	3.370	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	27-MAR-19	2.640	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	27-MAR-19	2.280	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	05-AUG-20	1.000	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	24-APR-20	3.990	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	24-APR-20	3.080	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	24-APR-20	3.780	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Flush180	24-APR-20	4.670	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Initial	22-SEP-16	9.100	ppb
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Initial	27-MAR-19	5.910	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Initial	05-AUG-20	1.000	ug/L
51057	51057-B-N-HAL-F04	Main- Basement, Across From Room 504, Right Founta	Initial	24-APR-20	3.460	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51057	51057-B-E-HAL-F01	Main- Basement, Outside Assembly Hall, Left Founta	Flush180	22-SEP-16	1.000	ppb
51057	51057-B-E-HAL-F01	Main- Basement, Outside Assembly Hall, Left Founta	Flush180	22-SEP-16	1.000	ppb
51057	51057-B-E-HAL-F01	Main- Basement, Outside Assembly Hall, Left Founta	Flush180	22-SEP-16	1.000	ppb
51057	51057-B-E-HAL-F01	Main- Basement, Outside Assembly Hall, Left Founta	Flush180	22-SEP-16	1.000	ppb
51057	51057-B-E-HAL-F01	Main- Basement, Outside Assembly Hall, Left Founta	Flush180	27-MAR-19	1.050	ug/L
51057	51057-B-E-HAL-F01	Main- Basement, Outside Assembly Hall, Left Founta	Flush180	27-MAR-19	1.130	ug/L
51057	51057-B-E-HAL-F01	Main- Basement, Outside Assembly Hall, Left Founta	Flush180	27-MAR-19	1.450	ug/L
51057	51057-B-E-HAL-F01	Main- Basement, Outside Assembly Hall, Left Founta	Flush180	27-MAR-19	1.350	ug/L
51057	51057-B-E-HAL-F01	Main- Basement, Outside Assembly Hall, Left Founta	Initial	22-SEP-16	2.800	ppb
51057	51057-B-E-HAL-F01	Main- Basement, Outside Assembly Hall, Left Founta	Initial	27-MAR-19	2.350	ug/L
51057	51057-B-E-HAL-F02	Main- Basement, Outside Assembly Hall, Right Fount	Flush180	22-SEP-16	1.000	ppb
51057	51057-B-E-HAL-F02	Main- Basement, Outside Assembly Hall, Right Fount	Flush180	22-SEP-16	2.500	ppb
51057	51057-B-E-HAL-F02	Main- Basement, Outside Assembly Hall, Right Fount	Flush180	22-SEP-16	2.900	ppb
51057	51057-B-E-HAL-F02	Main- Basement, Outside Assembly Hall, Right Fount	Flush180	22-SEP-16	2.100	ppb
51057	51057-B-E-HAL-F02	Main- Basement, Outside Assembly Hall, Right Fount	Flush180	27-MAR-19	1.380	ug/L
51057	51057-B-E-HAL-F02	Main- Basement, Outside Assembly Hall, Right Fount	Flush180	27-MAR-19	1.330	ug/L
51057	51057-B-E-HAL-F02	Main- Basement, Outside Assembly Hall, Right Fount	Flush180	27-MAR-19	1.120	ug/L
51057	51057-B-E-HAL-F02	Main- Basement, Outside Assembly Hall, Right Fount	Flush180	27-MAR-19	1.090	ug/L
51057	51057-B-E-HAL-F02	Main- Basement, Outside Assembly Hall, Right Fount	Initial	22-SEP-16	2.800	ppb
51057	51057-B-E-HAL-F02	Main- Basement, Outside Assembly Hall, Right Fount	Initial	27-MAR-19	1.370	ug/L
51057	51057-1-100-S12	Main- Inside Room 100, Sink	Flush180	21-SEP-16	2.800	ppb
51057	51057-1-100-S12	Main- Inside Room 100, Sink	Flush180	21-SEP-16	6.000	ppb
51057	51057-1-100-S12	Main- Inside Room 100, Sink	Flush180	21-SEP-16	3.600	ppb
51057	51057-1-100-S12	Main- Inside Room 100, Sink	Flush180	21-SEP-16	5.300	ppb
51057	51057-1-100-S12	Main- Inside Room 100, Sink	Initial	21-SEP-16	11.000	ppb
51057	51057-1-102-F11	Main- Inside Room 102, Fountain	Flush180	21-SEP-16	2.200	ppb
51057	51057-1-102-F11	Main- Inside Room 102, Fountain	Flush180	21-SEP-16	2.100	ppb
51057	51057-1-102-F11	Main- Inside Room 102, Fountain	Flush180	21-SEP-16	2.700	ppb
51057	51057-1-102-F11	Main- Inside Room 102, Fountain	Flush180	21-SEP-16	3.000	ppb
51057	51057-1-102-F11	Main- Inside Room 102, Fountain	Initial	21-SEP-16	8.800	ppb
51057	51057-1-102-S10	Main- Inside Room 102, Sink	Flush180	21-SEP-16	19.000	ppb
51057	51057-1-102-S10	Main- Inside Room 102, Sink	Flush180	21-SEP-16	23.000	ppb
51057	51057-1-102-S10	Main- Inside Room 102, Sink	Flush180	21-SEP-16	18.000	ppb
51057	51057-1-102-S10	Main- Inside Room 102, Sink	Flush180	21-SEP-16	6.500	ppb
51057	51057-1-102-S10	Main- Inside Room 102, Sink	Initial	21-SEP-16	21.000	ppb
51057	51057-1-KIT-KS02	Main- Kitchen, Center Sink	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-KIT-KS02	Main- Kitchen, Center Sink	Flush180	21-SEP-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51057	51057-1-KIT-KS02	Main- Kitchen, Center Sink	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-KIT-KS02	Main- Kitchen, Center Sink	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-KIT-KS02	Main- Kitchen, Center Sink	Initial	21-SEP-16	1.000	ppb
51057	51057-B-KIT-KS01	Main- Kitchen, Left Sink	Flush180	30-SEP-16	1.000	ppb
51057	51057-B-KIT-KS01	Main- Kitchen, Left Sink	Flush180	30-SEP-16	1.000	ppb
51057	51057-B-KIT-KS01	Main- Kitchen, Left Sink	Flush180	30-SEP-16	1.000	ppb
51057	51057-B-KIT-KS01	Main- Kitchen, Left Sink	Flush180	30-SEP-16	1.000	ppb
51057	51057-B-KIT-KS01	Main- Kitchen, Left Sink	Initial	30-SEP-16	2.100	ppb
51057	51057-B-S-KIT-KS01	Main- Kitchen, NorMain- Kitchen, North Sink	Flush180	21-SEP-16	1.000	ppb
51057	51057-B-S-KIT-KS01	Main- Kitchen, NorMain- Kitchen, North Sink	Flush180	21-SEP-16	1.000	ppb
51057	51057-B-S-KIT-KS01	Main- Kitchen, NorMain- Kitchen, North Sink	Flush180	21-SEP-16	1.000	ppb
51057	51057-B-S-KIT-KS01	Main- Kitchen, NorMain- Kitchen, North Sink	Flush180	21-SEP-16	1.000	ppb
51057	51057-B-S-KIT-KS01	Main- Kitchen, NorMain- Kitchen, North Sink	Flush180	27-MAR-19	1.000	ug/L
51057	51057-B-S-KIT-KS01	Main- Kitchen, NorMain- Kitchen, North Sink	Flush180	27-MAR-19	1.000	ug/L
51057	51057-B-S-KIT-KS01	Main- Kitchen, NorMain- Kitchen, North Sink	Flush180	27-MAR-19	1.000	ug/L
51057	51057-B-S-KIT-KS01	Main- Kitchen, NorMain- Kitchen, North Sink	Flush180	27-MAR-19	1.000	ug/L
51057	51057-B-S-KIT-KS01	Main- Kitchen, NorMain- Kitchen, North Sink	Initial	21-SEP-16	1.000	ppb
51057	51057-B-S-KIT-KS01	Main- Kitchen, NorMain- Kitchen, North Sink	Initial	27-MAR-19	1.040	ug/L
51057	51057-B-KIT-KS02	Main- Kitchen, Right Sink	Flush180	30-SEP-16	1.000	ppb
51057	51057-B-KIT-KS02	Main- Kitchen, Right Sink	Flush180	30-SEP-16	1.000	ppb
51057	51057-B-KIT-KS02	Main- Kitchen, Right Sink	Flush180	30-SEP-16	1.000	ppb
51057	51057-B-KIT-KS02	Main- Kitchen, Right Sink	Initial	30-SEP-16	1.000	ppb
51057	51057-1-KIT-KS03	Main- Kitchen, South Sink	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-KIT-KS03	Main- Kitchen, South Sink	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-KIT-KS03	Main- Kitchen, South Sink	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-KIT-KS03	Main- Kitchen, South Sink	Initial	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F06	Main- Outside Girls Toilets, East Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F06	Main- Outside Girls Toilets, East Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F06	Main- Outside Girls Toilets, East Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F06	Main- Outside Girls Toilets, East Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F06	Main- Outside Girls Toilets, East Fountain	Initial	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F07	Main- Outside Girls Toilets, West Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F07	Main- Outside Girls Toilets, West Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F07	Main- Outside Girls Toilets, West Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F07	Main- Outside Girls Toilets, West Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F07	Main- Outside Girls Toilets, West Fountain	Initial	21-SEP-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F07	Fountain				
51057	51057-1-HAL-F08	Main- Outside Lunchroom, East Fountain	Flush180	21-SEP-16	110.00 0	ppb
51057	51057-1-HAL-F08	Main- Outside Lunchroom, East Fountain	Flush180	21-SEP-16	230.00 0	ppb
51057	51057-1-HAL-F08	Main- Outside Lunchroom, East Fountain	Flush180	21-SEP-16	280.00 0	ppb
51057	51057-1-HAL-F08	Main- Outside Lunchroom, East Fountain	Flush180	21-SEP-16	130.00 0	ppb
51057	51057-1-HAL-F08	Main- Outside Lunchroom, East Fountain	Initial	21-SEP-16	310.00 0	ppb
51057	51057-1-HAL-F09	Main- Outside Lunchroom, West Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F09	Main- Outside Lunchroom, West Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F09	Main- Outside Lunchroom, West Fountain	Flush180	21-SEP-16	2.500	ppb
51057	51057-1-HAL-F09	Main- Outside Lunchroom, West Fountain	Flush180	21-SEP-16	2.700	ppb
51057	51057-1-HAL-F09	Main- Outside Lunchroom, West Fountain	Initial	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F04	Main- Outside Restrooms, North Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F04	Main- Outside Restrooms, North Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F04	Main- Outside Restrooms, North Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F04	Main- Outside Restrooms, North Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F04	Main- Outside Restrooms, North Fountain	Flush180	10-AUG-17	1.000	ppb
51057	51057-1-HAL-F04	Main- Outside Restrooms, North Fountain	Flush180	10-AUG-17	1.000	ppb
51057	51057-1-HAL-F04	Main- Outside Restrooms, North Fountain	Flush180	10-AUG-17	2.200	ppb
51057	51057-1-HAL-F04	Main- Outside Restrooms, North Fountain	Flush180	10-AUG-17	1.000	ppb
51057	51057-1-HAL-F04	Main- Outside Restrooms, North Fountain	Initial	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F04	Main- Outside Restrooms, North Fountain	Initial	10-AUG-17	2.690	ppb
51057	51057-1-HAL-F05	Main- Outside Restrooms, South Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F05	Main- Outside Restrooms, South Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F05	Main- Outside Restrooms, South Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F05	Main- Outside Restrooms, South Fountain	Flush180	21-SEP-16	1.000	ppb
51057	51057-1-HAL-F05	Main- Outside Restrooms, South Fountain	Initial	21-SEP-16	1.000	ppb
53804	53804-1-HAL-F01	Modular- Hallway Fountain	Flush180	22-SEP-16	18.000	ppb
53804	53804-1-HAL-F01	Modular- Hallway Fountain	Flush180	22-SEP-16	22.000	ppb
53804	53804-1-HAL-F01	Modular- Hallway Fountain	Flush180	22-SEP-16	34.000	ppb
53804	53804-1-HAL-F01	Modular- Hallway Fountain	Flush180	22-SEP-16	37.000	ppb
53804	53804-1-HAL-F01	Modular- Hallway Fountain	Initial	22-SEP-16	40.000	ppb