



Sep 10, 2024

HERNANDEZ

3510 W 55TH ST, Chicago IL 60632.

Dear **HERNANDEZ** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit www.cdc.gov/lead.

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



Sep 10, 2024

HERNANDEZ

3510 W 55TH ST, Chicago IL 60632.

Estimadas familias de **HERNANDEZ:**

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer
Director de Salud y Seguridad Ambientales
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
54697	54697-3-HAL-RBF01		Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-RBF01		Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-RBF01		Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-RBF01		Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-RBF01		Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-RBF01		Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-RBF01		Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-RBF01		Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-RBF01		Initial	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-RBF01		Initial	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F08	1st Floor Fountain Center Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F08	1st Floor Fountain Center Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F08	1st Floor Fountain Center Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F08	1st Floor Fountain Center Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F08	1st Floor Fountain Center Across From Room 108	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F08	1st Floor Fountain Center Across From Room 108	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F08	1st Floor Fountain Center Across From Room 108	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F08	1st Floor Fountain Center Across From Room 108	Initial	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F08	1st Floor Fountain Center Across From Room 108	Initial	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F05	1st Floor Fountain Center Across From Room 130	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F05	1st Floor Fountain Center Across From Room 130	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F05	1st Floor Fountain Center Across From Room 130	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F05	1st Floor Fountain Center Across From Room 130	Initial	03-NOV-16	1.000	ppb
54697	54697-1-GYM-F12	1st Floor Fountain Gym South Side	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-GYM-F12	1st Floor Fountain Gym South Side	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-GYM-F12	1st Floor Fountain Gym South Side	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-GYM-F12	1st Floor Fountain Gym South Side	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-GYM-F12	1st Floor Fountain Gym South Side	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-GYM-F12	1st Floor Fountain Gym South Side	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-GYM-F12	1st Floor Fountain Gym South Side	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-GYM-F12	1st Floor Fountain Gym South Side	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-GYM-F12	1st Floor Fountain Gym South Side	Initial	03-NOV-16	1.000	ppb
54697	54697-1-GYM-F12	1st Floor Fountain Gym South Side	Initial	01-JUN-23	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
54697	54697-1-HAL-F04	1st Floor Fountain Left Side Across From Room 130	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F04	1st Floor Fountain Left Side Across From Room 130	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F04	1st Floor Fountain Left Side Across From Room 130	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F04	1st Floor Fountain Left Side Across From Room 130	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F04	1st Floor Fountain Left Side Across From Room 130	Initial	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F09	1st Floor Fountain Right Side Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F09	1st Floor Fountain Right Side Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F09	1st Floor Fountain Right Side Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F09	1st Floor Fountain Right Side Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F09	1st Floor Fountain Right Side Across From Room 108	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F09	1st Floor Fountain Right Side Across From Room 108	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F09	1st Floor Fountain Right Side Across From Room 108	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F09	1st Floor Fountain Right Side Across From Room 108	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F09	1st Floor Fountain Right Side Across From Room 108	Initial	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F09	1st Floor Fountain Right Side Across From Room 108	Initial	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F06	1st Floor Fountain Right Side Across From Room 130	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F06	1st Floor Fountain Right Side Across From Room 130	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F06	1st Floor Fountain Right Side Across From Room 130	Flush180	03-NOV-16	0.123	ppb
54697	54697-1-HAL-F06	1st Floor Fountain Right Side Across From Room 130	Flush180	03-NOV-16	0.127	ppb
54697	54697-1-HAL-F06	1st Floor Fountain Right Side Across From Room 130	Initial	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F07	1st Floor Fountain left Side Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F07	1st Floor Fountain left Side Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F07	1st Floor Fountain left Side Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F07	1st Floor Fountain left Side Across From Room 108	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F07	1st Floor Fountain left Side Across From Room 108	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F07	1st Floor Fountain left Side Across From Room 108	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F07	1st Floor Fountain left Side Across From Room 108	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-HAL-F07	1st Floor Fountain left Side Across From Room 108	Initial	03-NOV-16	1.000	ppb
54697	54697-1-HAL-F07	1st Floor Fountain left Side Across From Room 108	Initial	01-JUN-23	1.000	ug/L
54697	54697-1-KIT-KS03	1st Floor Kitchen Dish Washing Sink East of Triple	Flush180	03-NOV-16	0.360	ppb
54697	54697-1-KIT-KS03	1st Floor Kitchen Dish Washing Sink East of Triple	Flush180	03-NOV-16	0.163	ppb
54697	54697-1-KIT-KS03	1st Floor Kitchen Dish Washing Sink East of Triple	Flush180	03-NOV-16	0.313	ppb
54697	54697-1-KIT-KS03	1st Floor Kitchen Dish Washing Sink East of Triple	Flush180	03-NOV-16	0.584	ppb
54697	54697-1-KIT-KS03	1st Floor Kitchen Dish Washing Sink East of Triple	Initial	03-NOV-16	0.243	ppb
54697	54697-1-KIT-KS01	1st Floor Kitchen Sink Left Side Triple Sink North	Flush180	03-NOV-16	0.153	ppb
54697	54697-1-KIT-KS01	1st Floor Kitchen Sink Left Side Triple Sink North	Flush180	03-NOV-16	0.545	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
54697	54697-1-KIT-KS01	1st Floor Kitchen Sink Left Side Triple Sink North	Flush180	03-NOV-16	0.379	ppb
54697	54697-1-KIT-KS01	1st Floor Kitchen Sink Left Side Triple Sink North	Flush180	03-NOV-16	0.175	ppb
54697	54697-1-KIT-KS01	1st Floor Kitchen Sink Left Side Triple Sink North	Initial	03-NOV-16	0.526	ppb
54697	54697-1-KIT-KS02	1st Floor Kitchen Sink Right Side Triple Sink Nort	Flush180	03-NOV-16	0.237	ppb
54697	54697-1-KIT-KS02	1st Floor Kitchen Sink Right Side Triple Sink Nort	Flush180	03-NOV-16	0.124	ppb
54697	54697-1-KIT-KS02	1st Floor Kitchen Sink Right Side Triple Sink Nort	Flush180	03-NOV-16	0.146	ppb
54697	54697-1-KIT-KS02	1st Floor Kitchen Sink Right Side Triple Sink Nort	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-KIT-KS02	1st Floor Kitchen Sink Right Side Triple Sink Nort	Initial	03-NOV-16	0.418	ppb
54697	54697-1-100E-S11	1st Floor Main Office Room 100E	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-100E-S11	1st Floor Main Office Room 100E	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-100E-S11	1st Floor Main Office Room 100E	Flush180	03-NOV-16	1.440	ppb
54697	54697-1-100E-S11	1st Floor Main Office Room 100E	Flush180	03-NOV-16	0.492	ppb
54697	54697-1-100E-S11	1st Floor Main Office Room 100E	Flush180	03-NOV-16	1.000	ppb
54697	54697-1-100E-S11	1st Floor Main Office Room 100E	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-100E-S11	1st Floor Main Office Room 100E	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-100E-S11	1st Floor Main Office Room 100E	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-100E-S11	1st Floor Main Office Room 100E	Initial	01-JUN-23	1.000	ug/L
54697	54697-1-100E-S11	1st Floor Main Office Room 100E	Initial	03-NOV-16	0.157	ppb
54697	54697-1-112-S10	1st Floor Sink Nurses Office Room 112	Flush180	03-NOV-16	4.560	ppb
54697	54697-1-112-S10	1st Floor Sink Nurses Office Room 112	Flush180	03-NOV-16	1.990	ppb
54697	54697-1-112-S10	1st Floor Sink Nurses Office Room 112	Flush180	03-NOV-16	9.770	ppb
54697	54697-1-112-S10	1st Floor Sink Nurses Office Room 112	Flush180	03-NOV-16	1.090	ppb
54697	54697-1-112-S10	1st Floor Sink Nurses Office Room 112	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-112-S10	1st Floor Sink Nurses Office Room 112	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-112-S10	1st Floor Sink Nurses Office Room 112	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-112-S10	1st Floor Sink Nurses Office Room 112	Flush180	01-JUN-23	1.000	ug/L
54697	54697-1-112-S10	1st Floor Sink Nurses Office Room 112	Initial	03-NOV-16	1.470	ppb
54697	54697-1-112-S10	1st Floor Sink Nurses Office Room 112	Initial	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F05	2nd Floor Fountain Center Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F05	2nd Floor Fountain Center Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F05	2nd Floor Fountain Center Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F05	2nd Floor Fountain Center Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F05	2nd Floor Fountain Center Across Room 210	Initial	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F02	2nd Floor Fountain Center Side Across Room 228	Flush180	03-NOV-16	0.166	ppb
54697	54697-2-HAL-F02	2nd Floor Fountain Center Side Across Room 228	Flush180	03-NOV-16	0.194	ppb
54697	54697-2-HAL-F02	2nd Floor Fountain Center Side Across Room 228	Flush180	03-NOV-16	0.175	ppb
54697	54697-2-HAL-F02	2nd Floor Fountain Center Side Across Room 228	Flush180	03-NOV-16	0.200	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
54697	54697-2-HAL-F02	2nd Floor Fountain Center Side Across Room 228	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F02	2nd Floor Fountain Center Side Across Room 228	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F02	2nd Floor Fountain Center Side Across Room 228	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F02	2nd Floor Fountain Center Side Across Room 228	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F02	2nd Floor Fountain Center Side Across Room 228	Initial	03-NOV-16	0.142	ppb
54697	54697-2-HAL-F02	2nd Floor Fountain Center Side Across Room 228	Initial	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F04	2nd Floor Fountain Left Side Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F04	2nd Floor Fountain Left Side Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F04	2nd Floor Fountain Left Side Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F04	2nd Floor Fountain Left Side Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F04	2nd Floor Fountain Left Side Across Room 210	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F04	2nd Floor Fountain Left Side Across Room 210	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F04	2nd Floor Fountain Left Side Across Room 210	Initial	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F04	2nd Floor Fountain Left Side Across Room 210	Initial	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F01	2nd Floor Fountain Left Side Across Room 228	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F01	2nd Floor Fountain Left Side Across Room 228	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F01	2nd Floor Fountain Left Side Across Room 228	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F01	2nd Floor Fountain Left Side Across Room 228	Initial	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F06	2nd Floor Fountain Right Side Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F06	2nd Floor Fountain Right Side Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F06	2nd Floor Fountain Right Side Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F06	2nd Floor Fountain Right Side Across Room 210	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F06	2nd Floor Fountain Right Side Across Room 210	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F06	2nd Floor Fountain Right Side Across Room 210	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F06	2nd Floor Fountain Right Side Across Room 210	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F06	2nd Floor Fountain Right Side Across Room 210	Initial	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F06	2nd Floor Fountain Right Side Across Room 210	Initial	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F03	2nd Floor Fountain Right Side Across Room 228	Flush180	03-NOV-16	0.204	ppb
54697	54697-2-HAL-F03	2nd Floor Fountain Right Side Across Room 228	Flush180	03-NOV-16	0.188	ppb
54697	54697-2-HAL-F03	2nd Floor Fountain Right Side Across Room 228	Flush180	03-NOV-16	0.127	ppb
54697	54697-2-HAL-F03	2nd Floor Fountain Right Side Across Room 228	Flush180	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F03	2nd Floor Fountain Right Side Across Room 228	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F03	2nd Floor Fountain Right Side Across Room 228	Flush180	01-JUN-23	1.000	ug/L

Water Quality Assessment
Irene C. Hernandez Middle School for the Advancement of
Science

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
54697	54697-2-HAL-F03	2nd Floor Fountain Right Side Across Room 228	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F03	2nd Floor Fountain Right Side Across Room 228	Flush180	01-JUN-23	1.000	ug/L
54697	54697-2-HAL-F03	2nd Floor Fountain Right Side Across Room 228	Initial	03-NOV-16	1.000	ppb
54697	54697-2-HAL-F03	2nd Floor Fountain Right Side Across Room 228	Initial	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F05	3rd Floor Fountain Center Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F05	3rd Floor Fountain Center Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F05	3rd Floor Fountain Center Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F05	3rd Floor Fountain Center Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F05	3rd Floor Fountain Center Across Room 310	Initial	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F02	3rd Floor Fountain Center Across Room 328	Flush180	03-NOV-16	0.289	ppb
54697	54697-3-HAL-F02	3rd Floor Fountain Center Across Room 328	Flush180	03-NOV-16	0.305	ppb
54697	54697-3-HAL-F02	3rd Floor Fountain Center Across Room 328	Flush180	03-NOV-16	0.299	ppb
54697	54697-3-HAL-F02	3rd Floor Fountain Center Across Room 328	Flush180	03-NOV-16	0.311	ppb
54697	54697-3-HAL-F02	3rd Floor Fountain Center Across Room 328	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F02	3rd Floor Fountain Center Across Room 328	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F02	3rd Floor Fountain Center Across Room 328	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F02	3rd Floor Fountain Center Across Room 328	Initial	03-NOV-16	0.253	ppb
54697	54697-3-HAL-F02	3rd Floor Fountain Center Across Room 328	Initial	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F04	3rd Floor Fountain Left Side Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F04	3rd Floor Fountain Left Side Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F04	3rd Floor Fountain Left Side Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F04	3rd Floor Fountain Left Side Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F04	3rd Floor Fountain Left Side Across Room 310	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F04	3rd Floor Fountain Left Side Across Room 310	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F04	3rd Floor Fountain Left Side Across Room 310	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F04	3rd Floor Fountain Left Side Across Room 310	Initial	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F04	3rd Floor Fountain Left Side Across Room 310	Initial	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F01	3rd Floor Fountain Left Side Across Room 328	Flush180	03-NOV-16	0.171	ppb
54697	54697-3-HAL-F01	3rd Floor Fountain Left Side Across Room 328	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F01	3rd Floor Fountain Left Side Across Room 328	Flush180	03-NOV-16	0.238	ppb
54697	54697-3-HAL-F01	3rd Floor Fountain Left Side Across Room 328	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F01	3rd Floor Fountain Left Side Across Room 328	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F01	3rd Floor Fountain Left Side Across Room 328	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F01	3rd Floor Fountain Left Side Across Room 328	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F01	3rd Floor Fountain Left Side Across Room 328	Flush180	01-JUN-23	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
54697	54697-3-HAL-F01	3rd Floor Fountain Left Side Across Room 328	Initial	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F01	3rd Floor Fountain Left Side Across Room 328	Initial	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F06	3rd Floor Fountain Right Side Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F06	3rd Floor Fountain Right Side Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F06	3rd Floor Fountain Right Side Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F06	3rd Floor Fountain Right Side Across Room 310	Flush180	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F06	3rd Floor Fountain Right Side Across Room 310	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F06	3rd Floor Fountain Right Side Across Room 310	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F06	3rd Floor Fountain Right Side Across Room 310	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F06	3rd Floor Fountain Right Side Across Room 310	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F06	3rd Floor Fountain Right Side Across Room 310	Initial	03-NOV-16	1.000	ppb
54697	54697-3-HAL-F06	3rd Floor Fountain Right Side Across Room 310	Initial	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F03	3rd Floor Fountain Right Side Across Room 328	Flush180	03-NOV-16	0.317	ppb
54697	54697-3-HAL-F03	3rd Floor Fountain Right Side Across Room 328	Flush180	03-NOV-16	0.262	ppb
54697	54697-3-HAL-F03	3rd Floor Fountain Right Side Across Room 328	Flush180	03-NOV-16	0.240	ppb
54697	54697-3-HAL-F03	3rd Floor Fountain Right Side Across Room 328	Flush180	03-NOV-16	0.309	ppb
54697	54697-3-HAL-F03	3rd Floor Fountain Right Side Across Room 328	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F03	3rd Floor Fountain Right Side Across Room 328	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F03	3rd Floor Fountain Right Side Across Room 328	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F03	3rd Floor Fountain Right Side Across Room 328	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-HAL-F03	3rd Floor Fountain Right Side Across Room 328	Initial	03-NOV-16	0.149	ppb
54697	54697-3-HAL-F03	3rd Floor Fountain Right Side Across Room 328	Initial	01-JUN-23	1.000	ug/L
54697	54697-3-305-S07	3rd Floor Sink Teachers Lounge Room 305	Flush180	03-NOV-16	0.282	ppb
54697	54697-3-305-S07	3rd Floor Sink Teachers Lounge Room 305	Flush180	03-NOV-16	0.291	ppb
54697	54697-3-305-S07	3rd Floor Sink Teachers Lounge Room 305	Flush180	03-NOV-16	0.269	ppb
54697	54697-3-305-S07	3rd Floor Sink Teachers Lounge Room 305	Flush180	03-NOV-16	0.268	ppb
54697	54697-3-305-S07	3rd Floor Sink Teachers Lounge Room 305	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-305-S07	3rd Floor Sink Teachers Lounge Room 305	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-305-S07	3rd Floor Sink Teachers Lounge Room 305	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-305-S07	3rd Floor Sink Teachers Lounge Room 305	Flush180	01-JUN-23	1.000	ug/L
54697	54697-3-305-S07	3rd Floor Sink Teachers Lounge Room 305	Initial	03-NOV-16	0.393	ppb
54697	54697-3-305-S07	3rd Floor Sink Teachers Lounge Room 305	Initial	01-JUN-23	1.000	ug/L