



Sep 10, 2024

MOOS

1711 N CALIFORNIA AVE, Chicago IL 60647.

Dear **MOOS** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit www.cdc.gov/lead.

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



Sep 10, 2024

MOOS

1711 N CALIFORNIA AVE, Chicago IL 60647.

Estimadas familias de **MOOS**:

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer
Director de Salud y Seguridad Ambientales
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51122	51122-ADD-2-HAL-F01	Addition- 2nd Floor Outside Restrooms, East Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F01	Addition- 2nd Floor Outside Restrooms, East Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F01	Addition- 2nd Floor Outside Restrooms, East Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F01	Addition- 2nd Floor Outside Restrooms, East Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F01	Addition- 2nd Floor Outside Restrooms, East Founta	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F02	Addition- 2nd Floor Outside Restrooms, West Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F02	Addition- 2nd Floor Outside Restrooms, West Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F02	Addition- 2nd Floor Outside Restrooms, West Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F02	Addition- 2nd Floor Outside Restrooms, West Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F02	Addition- 2nd Floor Outside Restrooms, West Founta	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F03	Addition- 2nd Floor Outside Room 111, North Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F03	Addition- 2nd Floor Outside Room 111, North Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F03	Addition- 2nd Floor Outside Room 111, North Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F03	Addition- 2nd Floor Outside Room 111, North Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-2-HAL-F03	Addition- 2nd Floor Outside Room 111, North Founta	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F02	Addition- 3rd FIAddition- 3rd Floor Outside Restro	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F02	Addition- 3rd FIAddition- 3rd Floor Outside Restro	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F02	Addition- 3rd FIAddition- 3rd Floor Outside Restro	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F02	Addition- 3rd FIAddition- 3rd Floor Outside Restro	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F02	Addition- 3rd FIAddition- 3rd Floor Outside Restro	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F01	Addition- 3rd Floor Outside Restrooms, East Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F01	Addition- 3rd Floor Outside Restrooms, East Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F01	Addition- 3rd Floor Outside Restrooms, East Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F01	Addition- 3rd Floor Outside Restrooms, East Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F01	Addition- 3rd Floor Outside Restrooms, East Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F01	Addition- 3rd Floor Outside Restrooms, East Founta	Flush180	30-JUL-20	1.000	ug/L
51122	51122-ADD-3-HAL-F01	Addition- 3rd Floor Outside Restrooms, East Founta	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F01	Addition- 3rd Floor Outside Restrooms, East Founta	Initial	30-JUL-20	1.000	ug/L
51122	51122-ADD-3-HAL-F03	Addition- 3rd Floor Outside Room 211, North Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F03	Addition- 3rd Floor Outside Room 211, North Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F03	Addition- 3rd Floor Outside Room 211, North Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F03	Addition- 3rd Floor Outside Room 211, North Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F03	Addition- 3rd Floor Outside Room 211, North Founta	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F04	Addition- 3rd Floor Outside Room 211, South Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F04	Addition- 3rd Floor Outside Room 211, South Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F04	Addition- 3rd Floor Outside Room 211, South Founta	Flush180	09-JUN-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51122	51122-ADD-3-HAL-F04	Addition- 3rd Floor Outside Room 211, South Founta	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-3-HAL-F04	Addition- 3rd Floor Outside Room 211, South Founta	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-1-001-F13	Addition- Inside Room 001, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-001-F13	Addition- Inside Room 001, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-001-F13	Addition- Inside Room 001, Fountain	Flush180	09-JUN-16	0.132	ppb
51122	51122-ADD-1-001-F13	Addition- Inside Room 001, Fountain	Flush180	09-JUN-16	0.138	ppb
51122	51122-ADD-1-001-F13	Addition- Inside Room 001, Fountain	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-1-001-S12	Addition- Inside Room 001, Sink	Flush180	09-JUN-16	0.212	ppb
51122	51122-ADD-1-001-S12	Addition- Inside Room 001, Sink	Flush180	09-JUN-16	0.202	ppb
51122	51122-ADD-1-001-S12	Addition- Inside Room 001, Sink	Flush180	09-JUN-16	0.258	ppb
51122	51122-ADD-1-001-S12	Addition- Inside Room 001, Sink	Flush180	09-JUN-16	0.454	ppb
51122	51122-ADD-1-001-S12	Addition- Inside Room 001, Sink	Initial	09-JUN-16	0.361	ppb
51122	51122-ADD-1-003-F11	Addition- Inside Room 003, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-003-F11	Addition- Inside Room 003, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-003-F11	Addition- Inside Room 003, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-003-F11	Addition- Inside Room 003, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-003-F11	Addition- Inside Room 003, Fountain	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-1-003-S10	Addition- Inside Room 003, Sink	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-003-S10	Addition- Inside Room 003, Sink	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-003-S10	Addition- Inside Room 003, Sink	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-003-S10	Addition- Inside Room 003, Sink	Initial	09-JUN-16	0.200	ppb
51122	51122-ADD-1-005-F07	Addition- Inside Room 005, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-005-F07	Addition- Inside Room 005, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-005-F07	Addition- Inside Room 005, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-005-F07	Addition- Inside Room 005, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-005-F07	Addition- Inside Room 005, Fountain	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-1-005-S06	Addition- Inside Room 005, Sink	Flush180	09-JUN-16	0.143	ppb
51122	51122-ADD-1-005-S06	Addition- Inside Room 005, Sink	Flush180	09-JUN-16	0.146	ppb
51122	51122-ADD-1-005-S06	Addition- Inside Room 005, Sink	Flush180	09-JUN-16	0.214	ppb
51122	51122-ADD-1-005-S06	Addition- Inside Room 005, Sink	Flush180	09-JUN-16	0.132	ppb
51122	51122-ADD-1-005-S06	Addition- Inside Room 005, Sink	Initial	09-JUN-16	0.824	ppb
51122	51122-ADD-1-006-F09	Addition- Inside Room 006, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-006-F09	Addition- Inside Room 006, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-006-F09	Addition- Inside Room 006, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-006-F09	Addition- Inside Room 006, Fountain	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-006-F09	Addition- Inside Room 006, Fountain	Initial	09-JUN-16	1.000	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51122	51122-ADD-1-006-S08	Addition- Inside Room 006, Sink	Flush180	09-JUN-16	0.826	ppb
51122	51122-ADD-1-006-S08	Addition- Inside Room 006, Sink	Flush180	09-JUN-16	0.521	ppb
51122	51122-ADD-1-006-S08	Addition- Inside Room 006, Sink	Flush180	09-JUN-16	0.620	ppb
51122	51122-ADD-1-006-S08	Addition- Inside Room 006, Sink	Flush180	09-JUN-16	0.519	ppb
51122	51122-ADD-1-006-S08	Addition- Inside Room 006, Sink	Initial	09-JUN-16	1.080	ppb
51122	51122-ADD-1-KIT-KS02	Addition- Kitchen, Island Sink	Flush180	09-JUN-16	0.198	ppb
51122	51122-ADD-1-KIT-KS02	Addition- Kitchen, Island Sink	Flush180	09-JUN-16	0.315	ppb
51122	51122-ADD-1-KIT-KS02	Addition- Kitchen, Island Sink	Flush180	09-JUN-16	0.184	ppb
51122	51122-ADD-1-KIT-KS02	Addition- Kitchen, Island Sink	Flush180	09-JUN-16	0.125	ppb
51122	51122-ADD-1-KIT-KS02	Addition- Kitchen, Island Sink	Initial	09-JUN-16	0.271	ppb
51122	51122-ADD-1-KIT-KS01	Addition- Kitchen, Wall Sink	Flush180	09-JUN-16	0.227	ppb
51122	51122-ADD-1-KIT-KS01	Addition- Kitchen, Wall Sink	Flush180	09-JUN-16	0.417	ppb
51122	51122-ADD-1-KIT-KS01	Addition- Kitchen, Wall Sink	Flush180	09-JUN-16	0.236	ppb
51122	51122-ADD-1-KIT-KS01	Addition- Kitchen, Wall Sink	Flush180	09-JUN-16	0.307	ppb
51122	51122-ADD-1-KIT-KS01	Addition- Kitchen, Wall Sink	Initial	09-JUN-16	0.186	ppb
51122	51122-ADD-1-HAL-F14	Addition- Outside Exit 8, East Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F14	Addition- Outside Exit 8, East Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F14	Addition- Outside Exit 8, East Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F14	Addition- Outside Exit 8, East Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F14	Addition- Outside Exit 8, East Fountain 1	Flush180	30-JUL-20	1.000	ug/L
51122	51122-ADD-1-HAL-F14	Addition- Outside Exit 8, East Fountain 1	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F14	Addition- Outside Exit 8, East Fountain 1	Initial	30-JUL-20	1.000	ug/L
51122	51122-ADD-1-HAL-F15	Addition- Outside Exit 8, West Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F15	Addition- Outside Exit 8, West Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F15	Addition- Outside Exit 8, West Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F15	Addition- Outside Exit 8, West Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F15	Addition- Outside Exit 8, West Fountain 2	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F04	Addition- Outside Restrooms, Center Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F04	Addition- Outside Restrooms, Center Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F04	Addition- Outside Restrooms, Center Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F04	Addition- Outside Restrooms, Center Fountain 2	Flush180	09-JUN-16	0.124	ppb
51122	51122-ADD-1-HAL-F04	Addition- Outside Restrooms, Center Fountain 2	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F03	Addition- Outside Restrooms, East Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F03	Addition- Outside Restrooms, East Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F03	Addition- Outside Restrooms, East Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F03	Addition- Outside Restrooms, East Fountain 1	Initial	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F03	Addition- Outside Restrooms, East Fountain 1	Flush180	09-JUN-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	HAL-F05	West Fountain 3				
51122	51122-ADD-1-HAL-F05	Addition- Outside Restrooms, West Fountain 3	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F05	Addition- Outside Restrooms, West Fountain 3	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F05	Addition- Outside Restrooms, West Fountain 3	Flush180	09-JUN-16	1.000	ppb
51122	51122-ADD-1-HAL-F05	Addition- Outside Restrooms, West Fountain 3	Initial	09-JUN-16	0.122	ppb
51122	51122-1-HAL-F03	Main- Across From Room 102, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-1-HAL-F03	Main- Across From Room 102, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-1-HAL-F03	Main- Across From Room 102, North Fountain 1	Flush180	09-JUN-16	0.833	ppb
51122	51122-1-HAL-F03	Main- Across From Room 102, North Fountain 1	Flush180	09-JUN-16	0.122	ppb
51122	51122-1-HAL-F03	Main- Across From Room 102, North Fountain 1	Initial	09-JUN-16	0.143	ppb
51122	51122-B-TL-F02	Main- Basement Teachers Lounge, Fountain	Flush180	09-JUN-16	2.540	ppb
51122	51122-B-TL-F02	Main- Basement Teachers Lounge, Fountain	Flush180	09-JUN-16	2.140	ppb
51122	51122-B-TL-F02	Main- Basement Teachers Lounge, Fountain	Flush180	09-JUN-16	3.850	ppb
51122	51122-B-TL-F02	Main- Basement Teachers Lounge, Fountain	Flush180	09-JUN-16	4.120	ppb
51122	51122-B-TL-F02	Main- Basement Teachers Lounge, Fountain	Initial	09-JUN-16	3.000	ppb
51122	51122-B-TL-S01	Main- Basement Teachers Lounge, Sink	Flush180	09-JUN-16	0.766	ppb
51122	51122-B-TL-S01	Main- Basement Teachers Lounge, Sink	Flush180	09-JUN-16	1.160	ppb
51122	51122-B-TL-S01	Main- Basement Teachers Lounge, Sink	Flush180	09-JUN-16	0.720	ppb
51122	51122-B-TL-S01	Main- Basement Teachers Lounge, Sink	Flush180	09-JUN-16	1.160	ppb
51122	51122-B-TL-S01	Main- Basement Teachers Lounge, Sink	Initial	09-JUN-16	1.710	ppb
51122	51122-1-HAL-F01	Main- Outside Room 107, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-1-HAL-F01	Main- Outside Room 107, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-1-HAL-F01	Main- Outside Room 107, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-1-HAL-F01	Main- Outside Room 107, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-1-HAL-F01	Main- Outside Room 107, North Fountain 1	Flush180	30-JUL-20	1.000	ug/L
51122	51122-1-HAL-F01	Main- Outside Room 107, North Fountain 1	Initial	09-JUN-16	0.352	ppb
51122	51122-1-HAL-F01	Main- Outside Room 107, North Fountain 1	Initial	30-JUL-20	1.000	ug/L
51122	51122-1-HAL-F02	Main- Outside Room 107, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-1-HAL-F02	Main- Outside Room 107, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-1-HAL-F02	Main- Outside Room 107, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-1-HAL-F02	Main- Outside Room 107, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-1-HAL-F02	Main- Outside Room 107, South Fountain 2	Initial	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F03	Main- Outside Room 203, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F03	Main- Outside Room 203, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F03	Main- Outside Room 203, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F03	Main- Outside Room 203, North Fountain 1	Initial	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F03	Main- Outside Room 203, North Fountain 1	Flush180	09-JUN-16	0.127	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F04	Fountain 2				
51122	51122-2-HAL-F04	Main- Outside Room 203, South Fountain 2	Flush180	09-JUN-16	0.158	ppb
51122	51122-2-HAL-F04	Main- Outside Room 203, South Fountain 2	Flush180	09-JUN-16	0.163	ppb
51122	51122-2-HAL-F04	Main- Outside Room 203, South Fountain 2	Flush180	09-JUN-16	0.132	ppb
51122	51122-2-HAL-F04	Main- Outside Room 203, South Fountain 2	Initial	09-JUN-16	0.410	ppb
51122	51122-2-HAL-F01	Main- Outside Room 207, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F01	Main- Outside Room 207, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F01	Main- Outside Room 207, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F01	Main- Outside Room 207, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F01	Main- Outside Room 207, North Fountain 1	Flush180	30-JUL-20	1.000	ug/L
51122	51122-2-HAL-F01	Main- Outside Room 207, North Fountain 1	Initial	09-JUN-16	0.314	ppb
51122	51122-2-HAL-F01	Main- Outside Room 207, North Fountain 1	Initial	30-JUL-20	1.000	ug/L
51122	51122-2-HAL-F02	Main- Outside Room 207, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F02	Main- Outside Room 207, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F02	Main- Outside Room 207, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F02	Main- Outside Room 207, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-2-HAL-F02	Main- Outside Room 207, South Fountain 2	Initial	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F03	Main- Outside Room 303, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F03	Main- Outside Room 303, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F03	Main- Outside Room 303, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F03	Main- Outside Room 303, North Fountain 1	Initial	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F04	Main- Outside Room 303, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F04	Main- Outside Room 303, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F04	Main- Outside Room 303, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F04	Main- Outside Room 303, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F04	Main- Outside Room 303, South Fountain 2	Initial	09-JUN-16	0.283	ppb
51122	51122-3-HAL-F01	Main- Outside Room 307, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F01	Main- Outside Room 307, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F01	Main- Outside Room 307, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F01	Main- Outside Room 307, North Fountain 1	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F01	Main- Outside Room 307, North Fountain 1	Initial	09-JUN-16	0.191	ppb
51122	51122-3-HAL-F02	Main- Outside Room 307, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F02	Main- Outside Room 307, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F02	Main- Outside Room 307, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F02	Main- Outside Room 307, South Fountain 2	Flush180	09-JUN-16	1.000	ppb
51122	51122-3-HAL-F02	Main- Outside Room 307, South Fountain 2	Initial	09-JUN-16	0.120	ppb

