



Sep 10, 2024

SCHURZ HS

3601 N MILWAUKEE AVE, Chicago IL 60641.

Dear **SCHURZ HS** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit www.cdc.gov/lead.

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



Sep 10, 2024

SCHURZ HS

3601 N MILWAUKEE AVE, Chicago IL 60641.

Estimadas familias de **SCHURZ HS**:

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer
Director de Salud y Seguridad Ambientales
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	11-JUL-23	1.470	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	11-JUL-23	1.540	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	11-JUL-23	2.910	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	11-JUL-23	2.270	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	05-APR-23	6.920	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	05-APR-23	2.850	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	05-APR-23	1.690	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	05-APR-23	1.290	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	25-APR-23	9.130	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	25-APR-23	5.140	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	25-APR-23	3.480	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Flush180	25-APR-23	3.790	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Initial	11-JUL-23	19.500	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Initial	05-APR-23	7.900	ug/L
51537	51537-4-HAL-RBF01	Main - Near Room 416, Retrofit Bottle Filler	Initial	25-APR-23	5.160	ug/L
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Flush180	21-OCT-16	0.587	ppb
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Flush180	21-OCT-16	0.627	ppb
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Flush180	21-OCT-16	0.461	ppb
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Flush180	21-OCT-16	0.379	ppb
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Flush180	16-DEC-20	1.000	ug/L
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Flush180	05-APR-23	1.480	ug/L
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Flush180	05-APR-23	2.380	ug/L
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Flush180	05-APR-23	1.770	ug/L
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Flush180	05-APR-23	1.350	ug/L
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Initial	21-OCT-16	0.279	ppb
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Initial	16-DEC-20	1.000	ug/L
51537	51537-3-HAL-F13	Main- Across From 329, Fountain	Initial	05-APR-23	2.130	ug/L
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Flush180	21-OCT-16	0.522	ppb
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Flush180	21-OCT-16	0.464	ppb
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Flush180	21-OCT-16	1.080	ppb
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Flush180	21-OCT-16	0.606	ppb
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Flush180	16-DEC-20	1.000	ug/L
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Flush180	05-APR-23	1.040	ug/L
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Flush180	05-APR-23	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Initial	21-OCT-16	1.680	ppb
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Initial	16-DEC-20	1.000	ug/L
51537	51537-1-HAL-RBF02	Main- Across From Gym 165 North Entrance Fountain	Initial	05-APR-23	1.550	ug/L
51537	51537-3-HAL-F05	Main- Across From Main- Across From Room 377, Left	Flush180	21-OCT-16	2.500	ppb
51537	51537-3-HAL-F05	Main- Across From Main- Across From Room 377, Left	Flush180	21-OCT-16	1.310	ppb
51537	51537-3-HAL-F05	Main- Across From Main- Across From Room 377, Left	Flush180	21-OCT-16	1.710	ppb
51537	51537-3-HAL-F05	Main- Across From Main- Across From Room 377, Left	Flush180	21-OCT-16	1.750	ppb
51537	51537-3-HAL-F05	Main- Across From Main- Across From Room 377, Left	Initial	21-OCT-16	1.850	ppb
51537	51537-1-HAL-RBF01	Main- Across From Room 109, Retrofit Bottle Filler	Flush180	21-OCT-16	0.846	ppb
51537	51537-1-HAL-RBF01	Main- Across From Room 109, Retrofit Bottle Filler	Flush180	21-OCT-16	0.825	ppb
51537	51537-1-HAL-RBF01	Main- Across From Room 109, Retrofit Bottle Filler	Flush180	21-OCT-16	0.884	ppb
51537	51537-1-HAL-RBF01	Main- Across From Room 109, Retrofit Bottle Filler	Flush180	21-OCT-16	0.884	ppb
51537	51537-1-HAL-RBF01	Main- Across From Room 109, Retrofit Bottle Filler	Flush180	05-APR-23	1.690	ug/L
51537	51537-1-HAL-RBF01	Main- Across From Room 109, Retrofit Bottle Filler	Flush180	05-APR-23	1.380	ug/L
51537	51537-1-HAL-RBF01	Main- Across From Room 109, Retrofit Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-RBF01	Main- Across From Room 109, Retrofit Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-RBF01	Main- Across From Room 109, Retrofit Bottle Filler	Initial	21-OCT-16	0.587	ppb
51537	51537-1-HAL-RBF01	Main- Across From Room 109, Retrofit Bottle Filler	Initial	05-APR-23	1.550	ug/L
51537	51537-1-HAL-F09	Main- Across From Room 129, Fountain	Flush180	21-OCT-16	1.080	ppb
51537	51537-1-HAL-F09	Main- Across From Room 129, Fountain	Flush180	21-OCT-16	0.740	ppb
51537	51537-1-HAL-F09	Main- Across From Room 129, Fountain	Flush180	21-OCT-16	0.709	ppb
51537	51537-1-HAL-F09	Main- Across From Room 129, Fountain	Flush180	21-OCT-16	0.717	ppb
51537	51537-1-HAL-F09	Main- Across From Room 129, Fountain	Initial	21-OCT-16	2.500	ppb
51537	51537-2-HAL-F06	Main- Across From Room 201, Fountain	Flush180	21-OCT-16	1.350	ppb
51537	51537-2-HAL-F06	Main- Across From Room 201, Fountain	Flush180	21-OCT-16	2.780	ppb
51537	51537-2-HAL-F06	Main- Across From Room 201, Fountain	Flush180	21-OCT-16	1.530	ppb
51537	51537-2-HAL-F06	Main- Across From Room 201, Fountain	Flush180	21-OCT-16	1.940	ppb
51537	51537-2-HAL-F06	Main- Across From Room 201, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F06	Main- Across From Room 201, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F06	Main- Across From Room 201, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F06	Main- Across From Room 201, Fountain	Initial	21-OCT-16	1.790	ppb
51537	51537-2-HAL-F06	Main- Across From Room 201, Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F07	Main- Across From Room 210, Left Fountain	Flush180	21-OCT-16	0.263	ppb
51537	51537-2-HAL-F07	Main- Across From Room 210, Left Fountain	Flush180	21-OCT-16	0.360	ppb
51537	51537-2-HAL-F07	Main- Across From Room 210, Left Fountain	Flush180	21-OCT-16	0.480	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51537	51537-2-HAL-F07	Main- Across From Room 210, Left Fountain	Flush180	21-OCT-16	0.530	ppb
51537	51537-2-HAL-F07	Main- Across From Room 210, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F07	Main- Across From Room 210, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F07	Main- Across From Room 210, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F07	Main- Across From Room 210, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F07	Main- Across From Room 210, Left Fountain	Initial	21-OCT-16	0.631	ppb
51537	51537-2-HAL-F07	Main- Across From Room 210, Left Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F08	Main- Across From Room 210, Right Fountain	Flush180	21-OCT-16	0.236	ppb
51537	51537-2-HAL-F08	Main- Across From Room 210, Right Fountain	Flush180	21-OCT-16	0.433	ppb
51537	51537-2-HAL-F08	Main- Across From Room 210, Right Fountain	Flush180	21-OCT-16	0.275	ppb
51537	51537-2-HAL-F08	Main- Across From Room 210, Right Fountain	Flush180	21-OCT-16	0.213	ppb
51537	51537-2-HAL-F08	Main- Across From Room 210, Right Fountain	Initial	21-OCT-16	0.257	ppb
51537	51537-2-HAL-BF02	Main- Across From Room 219A, Left Fountain	Flush180	21-OCT-16	0.971	ppb
51537	51537-2-HAL-BF02	Main- Across From Room 219A, Left Fountain	Flush180	21-OCT-16	0.644	ppb
51537	51537-2-HAL-BF02	Main- Across From Room 219A, Left Fountain	Flush180	21-OCT-16	0.583	ppb
51537	51537-2-HAL-BF02	Main- Across From Room 219A, Left Fountain	Flush180	21-OCT-16	0.713	ppb
51537	51537-2-HAL-BF02	Main- Across From Room 219A, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-BF02	Main- Across From Room 219A, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-BF02	Main- Across From Room 219A, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-BF02	Main- Across From Room 219A, Left Fountain	Initial	21-OCT-16	0.618	ppb
51537	51537-2-HAL-BF02	Main- Across From Room 219A, Left Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F10	Main- Across From Room 219A, Right Fountain	Flush180	21-OCT-16	0.637	ppb
51537	51537-2-HAL-F10	Main- Across From Room 219A, Right Fountain	Flush180	21-OCT-16	0.536	ppb
51537	51537-2-HAL-F10	Main- Across From Room 219A, Right Fountain	Flush180	21-OCT-16	0.513	ppb
51537	51537-2-HAL-F10	Main- Across From Room 219A, Right Fountain	Flush180	21-OCT-16	0.658	ppb
51537	51537-2-HAL-F10	Main- Across From Room 219A, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F10	Main- Across From Room 219A, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F10	Main- Across From Room 219A, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F10	Main- Across From Room 219A, Right Fountain	Initial	21-OCT-16	1.000	ppb
51537	51537-2-HAL-F10	Main- Across From Room 219A, Right Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F14	Main- Across From Room 231, Fountain	Flush180	21-OCT-16	0.413	ppb
51537	51537-2-HAL-F14	Main- Across From Room 231, Fountain	Flush180	21-OCT-16	0.591	ppb
51537	51537-2-HAL-F14	Main- Across From Room 231, Fountain	Flush180	21-OCT-16	0.458	ppb
51537	51537-2-HAL-F14	Main- Across From Room 231, Fountain	Flush180	21-OCT-16	0.534	ppb
51537	51537-2-HAL-F14	Main- Across From Room 231, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F14	Main- Across From Room 231, Fountain	Flush180	05-APR-23	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F14	Fountain				
51537	51537-2-HAL-F14	Main- Across From Room 231, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F14	Main- Across From Room 231, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F14	Main- Across From Room 231, Fountain	Initial	21-OCT-16	0.800	ppb
51537	51537-2-HAL-F14	Main- Across From Room 231, Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F12	Main- Across From Room 234, Left Fountain	Flush180	21-OCT-16	0.664	ppb
51537	51537-2-HAL-F12	Main- Across From Room 234, Left Fountain	Flush180	21-OCT-16	0.438	ppb
51537	51537-2-HAL-F12	Main- Across From Room 234, Left Fountain	Flush180	21-OCT-16	0.322	ppb
51537	51537-2-HAL-F12	Main- Across From Room 234, Left Fountain	Flush180	21-OCT-16	0.515	ppb
51537	51537-2-HAL-F12	Main- Across From Room 234, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F12	Main- Across From Room 234, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F12	Main- Across From Room 234, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F12	Main- Across From Room 234, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F12	Main- Across From Room 234, Left Fountain	Initial	21-OCT-16	0.377	ppb
51537	51537-2-HAL-F12	Main- Across From Room 234, Left Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-2-HAL-BF01	Main- Across From Room 234, Right Fountain	Flush180	21-OCT-16	0.172	ppb
51537	51537-2-HAL-BF01	Main- Across From Room 234, Right Fountain	Flush180	21-OCT-16	0.188	ppb
51537	51537-2-HAL-BF01	Main- Across From Room 234, Right Fountain	Flush180	21-OCT-16	0.165	ppb
51537	51537-2-HAL-BF01	Main- Across From Room 234, Right Fountain	Flush180	21-OCT-16	0.192	ppb
51537	51537-2-HAL-BF01	Main- Across From Room 234, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-BF01	Main- Across From Room 234, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-BF01	Main- Across From Room 234, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-BF01	Main- Across From Room 234, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-BF01	Main- Across From Room 234, Right Fountain	Initial	21-OCT-16	0.202	ppb
51537	51537-2-HAL-BF01	Main- Across From Room 234, Right Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F16	Main- Across From Room 265A Gym Balcony, Left Foun	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-HAL-F16	Main- Across From Room 265A Gym Balcony, Left Foun	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-HAL-F16	Main- Across From Room 265A Gym Balcony, Left Foun	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-HAL-F16	Main- Across From Room 265A Gym Balcony, Left Foun	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-HAL-F16	Main- Across From Room 265A Gym Balcony, Left Foun	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F16	Main- Across From Room 265A Gym Balcony, Left Foun	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F16	Main- Across From Room 265A Gym Balcony, Left Foun	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F16	Main- Across From Room 265A Gym Balcony, Left Foun	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F16	Main- Across From Room 265A Gym Balcony, Left Foun	Initial	21-OCT-16	1.000	ppb
51537	51537-2-HAL-F16	Main- Across From Room 265A Gym Balcony, Left Foun	Initial	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F15	Main- Across From Room 265A Gym Balcony, Right Fou	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-HAL-F15	Main- Across From Room 265A Gym Balcony, Right Fou	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-HAL-	Main- Across From Room 265A	Flush180	21-OCT-16	1.000	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F15	Gym Balcony, Right Fou				
51537	51537-2-HAL-F15	Main- Across From Room 265A Gym Balcony, Right Fou	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-HAL-F15	Main- Across From Room 265A Gym Balcony, Right Fou	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F15	Main- Across From Room 265A Gym Balcony, Right Fou	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F15	Main- Across From Room 265A Gym Balcony, Right Fou	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-F15	Main- Across From Room 265A Gym Balcony, Right Fou	Initial	21-OCT-16	0.133	ppb
51537	51537-2-HAL-F15	Main- Across From Room 265A Gym Balcony, Right Fou	Initial	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F07	Main- Across From Room 302, Fountain	Flush180	21-OCT-16	3.330	ppb
51537	51537-3-HAL-F07	Main- Across From Room 302, Fountain	Flush180	21-OCT-16	3.210	ppb
51537	51537-3-HAL-F07	Main- Across From Room 302, Fountain	Flush180	21-OCT-16	3.330	ppb
51537	51537-3-HAL-F07	Main- Across From Room 302, Fountain	Flush180	21-OCT-16	3.590	ppb
51537	51537-3-HAL-F07	Main- Across From Room 302, Fountain	Flush180	05-APR-23	1.330	ug/L
51537	51537-3-HAL-F07	Main- Across From Room 302, Fountain	Flush180	05-APR-23	1.320	ug/L
51537	51537-3-HAL-F07	Main- Across From Room 302, Fountain	Flush180	05-APR-23	1.180	ug/L
51537	51537-3-HAL-F07	Main- Across From Room 302, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F07	Main- Across From Room 302, Fountain	Initial	21-OCT-16	3.740	ppb
51537	51537-3-HAL-F07	Main- Across From Room 302, Fountain	Initial	05-APR-23	1.640	ug/L
51537	51537-3-HAL-F06	Main- Across From Room 310, Fountain	Flush180	21-OCT-16	2.620	ppb
51537	51537-3-HAL-F06	Main- Across From Room 310, Fountain	Flush180	21-OCT-16	5.080	ppb
51537	51537-3-HAL-F06	Main- Across From Room 310, Fountain	Flush180	21-OCT-16	4.110	ppb
51537	51537-3-HAL-F06	Main- Across From Room 310, Fountain	Flush180	21-OCT-16	3.180	ppb
51537	51537-3-HAL-F06	Main- Across From Room 310, Fountain	Initial	21-OCT-16	3.220	ppb
51537	51537-3-HAL-RBF01	Main- Across From Room 310, Fountain	Flush180	05-APR-23	1.700	ug/L
51537	51537-3-HAL-RBF01	Main- Across From Room 310, Fountain	Flush180	05-APR-23	1.650	ug/L
51537	51537-3-HAL-RBF01	Main- Across From Room 310, Fountain	Flush180	05-APR-23	1.770	ug/L
51537	51537-3-HAL-RBF01	Main- Across From Room 310, Fountain	Flush180	05-APR-23	2.000	ug/L
51537	51537-3-HAL-RBF01	Main- Across From Room 310, Fountain	Initial	05-APR-23	2.570	ug/L
51537	51537-3-HAL-F11	Main- Across From Room 334, Left Fountain	Flush180	21-OCT-16	0.714	ppb
51537	51537-3-HAL-F11	Main- Across From Room 334, Left Fountain	Flush180	21-OCT-16	0.558	ppb
51537	51537-3-HAL-F11	Main- Across From Room 334, Left Fountain	Flush180	21-OCT-16	1.010	ppb
51537	51537-3-HAL-F11	Main- Across From Room 334, Left Fountain	Flush180	21-OCT-16	0.923	ppb
51537	51537-3-HAL-F11	Main- Across From Room 334, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F11	Main- Across From Room 334, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F11	Main- Across From Room 334, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F11	Main- Across From Room 334, Left Fountain	Initial	21-OCT-16	1.020	ppb
51537	51537-3-HAL-F11	Main- Across From Room 334, Left Fountain	Initial	05-APR-23	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51537	51537-3-HAL-F12	Main- Across From Room 334, Right Fountain	Flush180	21-OCT-16	0.403	ppb
51537	51537-3-HAL-F12	Main- Across From Room 334, Right Fountain	Flush180	21-OCT-16	0.502	ppb
51537	51537-3-HAL-F12	Main- Across From Room 334, Right Fountain	Flush180	21-OCT-16	0.558	ppb
51537	51537-3-HAL-F12	Main- Across From Room 334, Right Fountain	Flush180	21-OCT-16	0.554	ppb
51537	51537-3-HAL-F12	Main- Across From Room 334, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F12	Main- Across From Room 334, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F12	Main- Across From Room 334, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F12	Main- Across From Room 334, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F12	Main- Across From Room 334, Right Fountain	Initial	21-OCT-16	0.770	ppb
51537	51537-3-HAL-F12	Main- Across From Room 334, Right Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-3-HAL-BF02	Main- Across From Room 351, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-BF02	Main- Across From Room 351, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-BF02	Main- Across From Room 351, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-BF02	Main- Across From Room 351, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-BF02	Main- Across From Room 351, Bottle Filler	Initial	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F10	Main- Across From Room 351, Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-3-HAL-F10	Main- Across From Room 351, Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-3-HAL-F10	Main- Across From Room 351, Fountain	Flush180	21-OCT-16	0.133	ppb
51537	51537-3-HAL-F10	Main- Across From Room 351, Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-3-HAL-F10	Main- Across From Room 351, Fountain	Initial	21-OCT-16	0.322	ppb
51537	51537-3-HAL-BF01	Main- Across From Room 377, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-BF01	Main- Across From Room 377, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-BF01	Main- Across From Room 377, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-BF01	Main- Across From Room 377, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-BF01	Main- Across From Room 377, Bottle Filler	Initial	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F04	Main- Across From Room 377, Right Fountain	Flush180	21-OCT-16	1.760	ppb
51537	51537-3-HAL-F04	Main- Across From Room 377, Right Fountain	Flush180	21-OCT-16	1.580	ppb
51537	51537-3-HAL-F04	Main- Across From Room 377, Right Fountain	Flush180	21-OCT-16	2.750	ppb
51537	51537-3-HAL-F04	Main- Across From Room 377, Right Fountain	Flush180	21-OCT-16	1.250	ppb
51537	51537-3-HAL-F04	Main- Across From Room 377, Right Fountain	Initial	21-OCT-16	1.370	ppb
51537	51537-4-HAL-F03	Main- Across From Room 425, Left Fountain	Flush180	21-OCT-16	0.201	ppb
51537	51537-4-HAL-F03	Main- Across From Room 425, Left Fountain	Flush180	21-OCT-16	0.334	ppb
51537	51537-4-HAL-F03	Main- Across From Room 425, Left Fountain	Flush180	21-OCT-16	0.380	ppb
51537	51537-4-HAL-F03	Main- Across From Room 425, Left Fountain	Flush180	21-OCT-16	0.279	ppb
51537	51537-4-HAL-F03	Main- Across From Room 425, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-4-HAL-F03	Main- Across From Room 425, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-4-HAL-F03	Main- Across From Room 425, Left Fountain	Flush180	05-APR-23	1.000	ug/L

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51537	51537-4-HAL-F03	Main- Across From Room 425, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-4-HAL-F03	Main- Across From Room 425, Left Fountain	Initial	21-OCT-16	0.420	ppb
51537	51537-4-HAL-F03	Main- Across From Room 425, Left Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-4-HAL-F02	Main- Across From Room 425, Right Fountain	Flush180	21-OCT-16	1.820	ppb
51537	51537-4-HAL-F02	Main- Across From Room 425, Right Fountain	Flush180	21-OCT-16	0.952	ppb
51537	51537-4-HAL-F02	Main- Across From Room 425, Right Fountain	Flush180	21-OCT-16	0.527	ppb
51537	51537-4-HAL-F02	Main- Across From Room 425, Right Fountain	Flush180	21-OCT-16	0.658	ppb
51537	51537-4-HAL-F02	Main- Across From Room 425, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-4-HAL-F02	Main- Across From Room 425, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-4-HAL-F02	Main- Across From Room 425, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-4-HAL-F02	Main- Across From Room 425, Right Fountain	Initial	21-OCT-16	0.493	ppb
51537	51537-4-HAL-F02	Main- Across From Room 425, Right Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F03	Main- Across Stairway #05, Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F03	Main- Across Stairway #05, Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F03	Main- Across Stairway #05, Fountain	Flush180	21-OCT-16	0.817	ppb
51537	51537-1-HAL-F03	Main- Across Stairway #05, Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F03	Main- Across Stairway #05, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F03	Main- Across Stairway #05, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F03	Main- Across Stairway #05, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F03	Main- Across Stairway #05, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F03	Main- Across Stairway #05, Fountain	Initial	21-OCT-16	0.260	ppb
51537	51537-1-HAL-F03	Main- Across Stairway #05, Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F07	Main- By Stairway 12, Left Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F07	Main- By Stairway 12, Left Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F07	Main- By Stairway 12, Left Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F07	Main- By Stairway 12, Left Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F07	Main- By Stairway 12, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F07	Main- By Stairway 12, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F07	Main- By Stairway 12, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F07	Main- By Stairway 12, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F07	Main- By Stairway 12, Left Fountain	Initial	21-OCT-16	0.144	ppb
51537	51537-1-HAL-F07	Main- By Stairway 12, Left Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F08	Main- By Stairway 12, Right Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F08	Main- By Stairway 12, Right Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F08	Main- By Stairway 12, Right Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F08	Main- By Stairway 12, Right Fountain	Flush180	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F08	Main- By Stairway 12, Right Fountain	Flush180	05-APR-23	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F08	Fountain				
51537	51537-1-HAL-F08	Main- By Stairway 12, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F08	Main- By Stairway 12, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F08	Main- By Stairway 12, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F08	Main- By Stairway 12, Right Fountain	Initial	21-OCT-16	1.000	ppb
51537	51537-1-HAL-F08	Main- By Stairway 12, Right Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-2-CAF-F05	Main- Cafeteria, Left Fountain	Flush180	21-OCT-16	0.650	ppb
51537	51537-2-CAF-F05	Main- Cafeteria, Left Fountain	Flush180	21-OCT-16	1.360	ppb
51537	51537-2-CAF-F05	Main- Cafeteria, Left Fountain	Flush180	21-OCT-16	0.873	ppb
51537	51537-2-CAF-F05	Main- Cafeteria, Left Fountain	Flush180	21-OCT-16	0.939	ppb
51537	51537-2-CAF-F05	Main- Cafeteria, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-CAF-F05	Main- Cafeteria, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-CAF-F05	Main- Cafeteria, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-CAF-F05	Main- Cafeteria, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-CAF-F05	Main- Cafeteria, Left Fountain	Initial	21-OCT-16	0.655	ppb
51537	51537-2-CAF-F05	Main- Cafeteria, Left Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-2-CAF-F04	Main- Cafeteria, Right Fountain	Flush180	21-OCT-16	0.743	ppb
51537	51537-2-CAF-F04	Main- Cafeteria, Right Fountain	Flush180	21-OCT-16	0.801	ppb
51537	51537-2-CAF-F04	Main- Cafeteria, Right Fountain	Flush180	21-OCT-16	0.397	ppb
51537	51537-2-CAF-F04	Main- Cafeteria, Right Fountain	Flush180	21-OCT-16	0.635	ppb
51537	51537-2-CAF-F04	Main- Cafeteria, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-CAF-F04	Main- Cafeteria, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-CAF-F04	Main- Cafeteria, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-CAF-F04	Main- Cafeteria, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-CAF-F04	Main- Cafeteria, Right Fountain	Initial	21-OCT-16	1.370	ppb
51537	51537-2-CAF-F04	Main- Cafeteria, Right Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-1-GYM-F12	Main- Inside Gym Room 165, Mens locker, Left Fount	Flush180	21-OCT-16	0.275	ppb
51537	51537-1-GYM-F12	Main- Inside Gym Room 165, Mens locker, Left Fount	Flush180	21-OCT-16	0.191	ppb
51537	51537-1-GYM-F12	Main- Inside Gym Room 165, Mens locker, Left Fount	Flush180	21-OCT-16	0.215	ppb
51537	51537-1-GYM-F12	Main- Inside Gym Room 165, Mens locker, Left Fount	Flush180	21-OCT-16	0.185	ppb
51537	51537-1-GYM-F12	Main- Inside Gym Room 165, Mens locker, Left Fount	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-GYM-F12	Main- Inside Gym Room 165, Mens locker, Left Fount	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-GYM-F12	Main- Inside Gym Room 165, Mens locker, Left Fount	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-GYM-F12	Main- Inside Gym Room 165, Mens locker, Left Fount	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-GYM-F12	Main- Inside Gym Room 165, Mens locker, Left Fount	Initial	21-OCT-16	0.942	ppb
51537	51537-1-GYM-F12	Main- Inside Gym Room 165, Mens locker, Left Fount	Initial	05-APR-23	1.000	ug/L
51537	51537-1-GYM-F13	Main- Inside Gym Room 165, Mens locker, Right Foun	Flush180	21-OCT-16	0.244	ppb
51537	51537-1-	Main- Inside Gym Room 165,	Flush180	21-OCT-16	0.264	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	GYM-F13	Mens locker, Right Foun				
51537	51537-1-GYM-F13	Main- Inside Gym Room 165, Mens locker, Right Foun	Flush180	21-OCT-16	0.347	ppb
51537	51537-1-GYM-F13	Main- Inside Gym Room 165, Mens locker, Right Foun	Flush180	21-OCT-16	0.245	ppb
51537	51537-1-GYM-F13	Main- Inside Gym Room 165, Mens locker, Right Foun	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-GYM-F13	Main- Inside Gym Room 165, Mens locker, Right Foun	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-GYM-F13	Main- Inside Gym Room 165, Mens locker, Right Foun	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-GYM-F13	Main- Inside Gym Room 165, Mens locker, Right Foun	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-GYM-F13	Main- Inside Gym Room 165, Mens locker, Right Foun	Initial	21-OCT-16	0.389	ppb
51537	51537-1-GYM-F13	Main- Inside Gym Room 165, Mens locker, Right Foun	Initial	05-APR-23	1.000	ug/L
51537	51537-1-POOL-F15	Main- Inside Pool Area, Left Fountain	Flush180	21-OCT-16	3.560	ppb
51537	51537-1-POOL-F15	Main- Inside Pool Area, Left Fountain	Flush180	21-OCT-16	3.430	ppb
51537	51537-1-POOL-F15	Main- Inside Pool Area, Left Fountain	Flush180	21-OCT-16	3.510	ppb
51537	51537-1-POOL-F15	Main- Inside Pool Area, Left Fountain	Flush180	21-OCT-16	2.900	ppb
51537	51537-1-POOL-F15	Main- Inside Pool Area, Left Fountain	Flush180	05-APR-23	1.870	ug/L
51537	51537-1-POOL-F15	Main- Inside Pool Area, Left Fountain	Flush180	05-APR-23	3.950	ug/L
51537	51537-1-POOL-F15	Main- Inside Pool Area, Left Fountain	Flush180	05-APR-23	2.470	ug/L
51537	51537-1-POOL-F15	Main- Inside Pool Area, Left Fountain	Flush180	05-APR-23	2.090	ug/L
51537	51537-1-POOL-F15	Main- Inside Pool Area, Left Fountain	Initial	21-OCT-16	2.850	ppb
51537	51537-1-POOL-F15	Main- Inside Pool Area, Left Fountain	Initial	05-APR-23	2.510	ug/L
51537	51537-1-POOL-F16	Main- Inside Pool Area, Right Fountain	Flush180	21-OCT-16	3.570	ppb
51537	51537-1-POOL-F16	Main- Inside Pool Area, Right Fountain	Flush180	21-OCT-16	3.520	ppb
51537	51537-1-POOL-F16	Main- Inside Pool Area, Right Fountain	Flush180	21-OCT-16	3.550	ppb
51537	51537-1-POOL-F16	Main- Inside Pool Area, Right Fountain	Flush180	21-OCT-16	3.520	ppb
51537	51537-1-POOL-F16	Main- Inside Pool Area, Right Fountain	Flush180	05-APR-23	3.250	ug/L
51537	51537-1-POOL-F16	Main- Inside Pool Area, Right Fountain	Flush180	05-APR-23	3.210	ug/L
51537	51537-1-POOL-F16	Main- Inside Pool Area, Right Fountain	Flush180	05-APR-23	3.250	ug/L
51537	51537-1-POOL-F16	Main- Inside Pool Area, Right Fountain	Flush180	05-APR-23	2.620	ug/L
51537	51537-1-POOL-F16	Main- Inside Pool Area, Right Fountain	Initial	21-OCT-16	3.500	ppb
51537	51537-1-POOL-F16	Main- Inside Pool Area, Right Fountain	Initial	05-APR-23	4.120	ug/L
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Flush180	21-OCT-16	0.120	ppb
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Initial	21-OCT-16	0.266	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51537	51537-2-KIT-KS01	Main- Kitchen South Wall, Sink	Initial	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS03	Main- Kitchen, Center Island Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS03	Main- Kitchen, Center Island Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS03	Main- Kitchen, Center Island Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS03	Main- Kitchen, Center Island Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS03	Main- Kitchen, Center Island Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS03	Main- Kitchen, Center Island Sink	Flush180	05-APR-23	1.730	ug/L
51537	51537-2-KIT-KS03	Main- Kitchen, Center Island Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS03	Main- Kitchen, Center Island Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS03	Main- Kitchen, Center Island Sink	Initial	21-OCT-16	0.254	ppb
51537	51537-2-KIT-KS03	Main- Kitchen, Center Island Sink	Initial	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS02	Main- Kitchen, Northwest Corner, Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS02	Main- Kitchen, Northwest Corner, Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS02	Main- Kitchen, Northwest Corner, Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS02	Main- Kitchen, Northwest Corner, Sink	Flush180	21-OCT-16	1.000	ppb
51537	51537-2-KIT-KS02	Main- Kitchen, Northwest Corner, Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS02	Main- Kitchen, Northwest Corner, Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS02	Main- Kitchen, Northwest Corner, Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS02	Main- Kitchen, Northwest Corner, Sink	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS02	Main- Kitchen, Northwest Corner, Sink	Initial	21-OCT-16	0.225	ppb
51537	51537-2-KIT-KS02	Main- Kitchen, Northwest Corner, Sink	Initial	05-APR-23	1.000	ug/L
51537	51537-4-HAL-F01	Main- Near Room 416, Fountain	Flush180	21-OCT-16	0.741	ppb
51537	51537-4-HAL-F01	Main- Near Room 416, Fountain	Flush180	21-OCT-16	0.609	ppb
51537	51537-4-HAL-F01	Main- Near Room 416, Fountain	Flush180	21-OCT-16	0.557	ppb
51537	51537-4-HAL-F01	Main- Near Room 416, Fountain	Flush180	21-OCT-16	0.994	ppb
51537	51537-4-HAL-F01	Main- Near Room 416, Fountain	Initial	21-OCT-16	1.700	ppb
51537	51537-2-HAL-RBF01	Main- Next to Room 212, Fountain	Flush180	21-OCT-16	0.688	ppb
51537	51537-2-HAL-RBF01	Main- Next to Room 212, Fountain	Flush180	21-OCT-16	0.513	ppb
51537	51537-2-HAL-RBF01	Main- Next to Room 212, Fountain	Flush180	21-OCT-16	0.417	ppb
51537	51537-2-HAL-RBF01	Main- Next to Room 212, Fountain	Flush180	21-OCT-16	0.436	ppb
51537	51537-2-HAL-RBF01	Main- Next to Room 212, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-RBF01	Main- Next to Room 212, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-RBF01	Main- Next to Room 212, Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-HAL-RBF01	Main- Next to Room 212, Fountain	Initial	21-OCT-16	0.873	ppb
51537	51537-2-HAL-RBF01	Main- Next to Room 212, Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F09	Main- Next to Room 318, Left Fountain	Flush180	21-OCT-16	1.070	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51537	51537-3-HAL-F09	Main- Next to Room 318, Left Fountain	Flush180	21-OCT-16	0.815	ppb
51537	51537-3-HAL-F09	Main- Next to Room 318, Left Fountain	Flush180	21-OCT-16	1.320	ppb
51537	51537-3-HAL-F09	Main- Next to Room 318, Left Fountain	Flush180	21-OCT-16	1.890	ppb
51537	51537-3-HAL-F09	Main- Next to Room 318, Left Fountain	Initial	21-OCT-16	0.651	ppb
51537	51537-3-HAL-F08	Main- Next to Room 318, Right Fountain	Flush180	21-OCT-16	1.410	ppb
51537	51537-3-HAL-F08	Main- Next to Room 318, Right Fountain	Flush180	21-OCT-16	1.380	ppb
51537	51537-3-HAL-F08	Main- Next to Room 318, Right Fountain	Flush180	21-OCT-16	1.410	ppb
51537	51537-3-HAL-F08	Main- Next to Room 318, Right Fountain	Flush180	21-OCT-16	1.470	ppb
51537	51537-3-HAL-F08	Main- Next to Room 318, Right Fountain	Flush180	05-APR-23	1.020	ug/L
51537	51537-3-HAL-F08	Main- Next to Room 318, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F08	Main- Next to Room 318, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F08	Main- Next to Room 318, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F08	Main- Next to Room 318, Right Fountain	Initial	21-OCT-16	0.829	ppb
51537	51537-3-HAL-F08	Main- Next to Room 318, Right Fountain	Initial	05-APR-23	1.890	ug/L
51537	51537-3-HAL-F02	Main- Next to Room 356, Left Fountain	Flush180	21-OCT-16	3.090	ppb
51537	51537-3-HAL-F02	Main- Next to Room 356, Left Fountain	Flush180	21-OCT-16	1.150	ppb
51537	51537-3-HAL-F02	Main- Next to Room 356, Left Fountain	Flush180	21-OCT-16	0.355	ppb
51537	51537-3-HAL-F02	Main- Next to Room 356, Left Fountain	Flush180	21-OCT-16	0.774	ppb
51537	51537-3-HAL-F02	Main- Next to Room 356, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F02	Main- Next to Room 356, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F02	Main- Next to Room 356, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F02	Main- Next to Room 356, Left Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F02	Main- Next to Room 356, Left Fountain	Initial	21-OCT-16	3.600	ppb
51537	51537-3-HAL-F02	Main- Next to Room 356, Left Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F01	Main- Next to Room 356, Right Fountain	Flush180	21-OCT-16	1.900	ppb
51537	51537-3-HAL-F01	Main- Next to Room 356, Right Fountain	Flush180	21-OCT-16	1.010	ppb
51537	51537-3-HAL-F01	Main- Next to Room 356, Right Fountain	Flush180	21-OCT-16	0.880	ppb
51537	51537-3-HAL-F01	Main- Next to Room 356, Right Fountain	Flush180	21-OCT-16	6.610	ppb
51537	51537-3-HAL-F01	Main- Next to Room 356, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F01	Main- Next to Room 356, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F01	Main- Next to Room 356, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F01	Main- Next to Room 356, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F01	Main- Next to Room 356, Right Fountain	Initial	21-OCT-16	1.070	ppb
51537	51537-3-HAL-F01	Main- Next to Room 356, Right Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-3-HAL-F03	Main- Next to Room 369, Fountain	Flush180	21-OCT-16	2.240	ppb
51537	51537-3-HAL-F03	Main- Next to Room 369, Fountain	Flush180	21-OCT-16	2.320	ppb
51537	51537-3-HAL-F03	Main- Next to Room 369, Fountain	Flush180	21-OCT-16	4.310	ppb
51537	51537-3-HAL-	Main- Next to Room 369, Fountain	Flush180	21-OCT-16	2.800	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F03					
51537	51537-3-HAL-F03	Main- Next to Room 369, Fountain	Initial	21-OCT-16	2.710	ppb
51537	51537-3-HAL-RBF02	Main- Next to Room 369, Retrofit Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-RBF02	Main- Next to Room 369, Retrofit Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-RBF02	Main- Next to Room 369, Retrofit Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-RBF02	Main- Next to Room 369, Retrofit Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-3-HAL-RBF02	Main- Next to Room 369, Retrofit Bottle Filler	Initial	05-APR-23	1.440	ug/L
51537	51537-1-HAL-BF01	Main- Outside Gym Room 126, Bottle Filler	Flush180	21-OCT-16	0.176	ppb
51537	51537-1-HAL-BF01	Main- Outside Gym Room 126, Bottle Filler	Flush180	21-OCT-16	0.161	ppb
51537	51537-1-HAL-BF01	Main- Outside Gym Room 126, Bottle Filler	Flush180	21-OCT-16	0.174	ppb
51537	51537-1-HAL-BF01	Main- Outside Gym Room 126, Bottle Filler	Flush180	21-OCT-16	0.146	ppb
51537	51537-1-HAL-BF01	Main- Outside Gym Room 126, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-BF01	Main- Outside Gym Room 126, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-BF01	Main- Outside Gym Room 126, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-BF01	Main- Outside Gym Room 126, Bottle Filler	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-BF01	Main- Outside Gym Room 126, Bottle Filler	Initial	21-OCT-16	0.204	ppb
51537	51537-1-HAL-BF01	Main- Outside Gym Room 126, Bottle Filler	Initial	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F05	Main- Outside Gym Room 126, Right Fountain	Flush180	21-OCT-16	0.137	ppb
51537	51537-1-HAL-F05	Main- Outside Gym Room 126, Right Fountain	Flush180	21-OCT-16	0.150	ppb
51537	51537-1-HAL-F05	Main- Outside Gym Room 126, Right Fountain	Flush180	21-OCT-16	0.218	ppb
51537	51537-1-HAL-F05	Main- Outside Gym Room 126, Right Fountain	Flush180	21-OCT-16	0.479	ppb
51537	51537-1-HAL-F05	Main- Outside Gym Room 126, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F05	Main- Outside Gym Room 126, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F05	Main- Outside Gym Room 126, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F05	Main- Outside Gym Room 126, Right Fountain	Flush180	05-APR-23	1.000	ug/L
51537	51537-1-HAL-F05	Main- Outside Gym Room 126, Right Fountain	Initial	21-OCT-16	0.290	ppb
51537	51537-1-HAL-F05	Main- Outside Gym Room 126, Right Fountain	Initial	05-APR-23	1.000	ug/L
51537	51537-1-HAL-RBF01	Main- Outside Gym, Right Bottle Filler	Flush180	11-MAY-23	1.000	ug/L
51537	51537-1-HAL-RBF01	Main- Outside Gym, Right Bottle Filler	Flush180	11-MAY-23	1.000	ug/L
51537	51537-1-HAL-RBF01	Main- Outside Gym, Right Bottle Filler	Flush180	11-MAY-23	1.000	ug/L
51537	51537-1-HAL-RBF01	Main- Outside Gym, Right Bottle Filler	Initial	11-MAY-23	1.000	ug/L
51537	51537-1-HAL-F02	Main- Outside Room 100, Left Fountain	Flush180	21-OCT-16	5.830	ppb
51537	51537-1-HAL-F02	Main- Outside Room 100, Left Fountain	Flush180	21-OCT-16	5.970	ppb
51537	51537-1-HAL-F02	Main- Outside Room 100, Left Fountain	Flush180	21-OCT-16	5.320	ppb
51537	51537-1-HAL-F02	Main- Outside Room 100, Left Fountain	Flush180	21-OCT-16	6.880	ppb
51537	51537-1-HAL-F02	Main- Outside Room 100, Left Fountain	Initial	21-OCT-16	5.650	ppb
51537	51537-1-HAL-	Main- Outside Room 100, Right	Flush180	21-OCT-16	2.910	ppb

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	F01	Fountain				
51537	51537-1-HAL-F01	Main- Outside Room 100, Right Fountain	Flush180	21-OCT-16	6.610	ppb
51537	51537-1-HAL-F01	Main- Outside Room 100, Right Fountain	Flush180	21-OCT-16	4.760	ppb
51537	51537-1-HAL-F01	Main- Outside Room 100, Right Fountain	Flush180	21-OCT-16	5.950	ppb
51537	51537-1-HAL-F01	Main- Outside Room 100, Right Fountain	Initial	21-OCT-16	4.830	ppb
51537	51537-1-HAL-F10	Main- Outside Room 138 (Assembly Hall), East Wall	Flush180	21-OCT-16	1.280	ppb
51537	51537-1-HAL-F10	Main- Outside Room 138 (Assembly Hall), East Wall	Flush180	21-OCT-16	1.360	ppb
51537	51537-1-HAL-F10	Main- Outside Room 138 (Assembly Hall), East Wall	Flush180	21-OCT-16	1.130	ppb
51537	51537-1-HAL-F10	Main- Outside Room 138 (Assembly Hall), East Wall	Flush180	21-OCT-16	1.110	ppb
51537	51537-1-HAL-F10	Main- Outside Room 138 (Assembly Hall), East Wall	Flush180	05-APR-23	3.490	ug/L
51537	51537-1-HAL-F10	Main- Outside Room 138 (Assembly Hall), East Wall	Flush180	05-APR-23	3.490	ug/L
51537	51537-1-HAL-F10	Main- Outside Room 138 (Assembly Hall), East Wall	Flush180	05-APR-23	3.160	ug/L
51537	51537-1-HAL-F10	Main- Outside Room 138 (Assembly Hall), East Wall	Flush180	05-APR-23	3.530	ug/L
51537	51537-1-HAL-F10	Main- Outside Room 138 (Assembly Hall), East Wall	Initial	21-OCT-16	1.100	ppb
51537	51537-1-HAL-F10	Main- Outside Room 138 (Assembly Hall), East Wall	Initial	05-APR-23	4.320	ug/L
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	21-OCT-16	19.000	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	21-OCT-16	18.200	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	21-OCT-16	58.800	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	21-OCT-16	50.900	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	09-DEC-16	2.500	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	09-DEC-16	3.900	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	09-DEC-16	2.800	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	09-DEC-16	2.600	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	09-DEC-16	2.500	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	09-DEC-16	3.900	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	09-DEC-16	2.800	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Flush180	09-DEC-16	2.600	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Initial	21-OCT-16	66.800	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Initial	09-DEC-16	4.000	ppb
51537	51537-1-HAL-F11	Main- Outside Room 138 (Assembly Hall), West Wall	Initial	09-DEC-16	4.000	ppb
51537	51537-2-KIT-KS05	NE Corner Double Basin	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS05	NE Corner Double Basin	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS05	NE Corner Double Basin	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS05	NE Corner Double Basin	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS05	NE Corner Double Basin	Initial	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS04	NW Corner Single Basin	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS04	NW Corner Single Basin	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS04	NW Corner Single Basin	Flush180	05-APR-23	1.000	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51537	51537-2-KIT-KS04	NW Corner Single Basin	Flush180	05-APR-23	1.000	ug/L
51537	51537-2-KIT-KS04	NW Corner Single Basin	Initial	05-APR-23	1.000	ug/L