



Sep 10, 2024

STOWE

3444 W WABANSIA AVE, Chicago IL 60647.

Dear **STOWE** families,

In 2016, Chicago Public Schools (CPS) began sampling for lead in drinking water from all schools across the district. Our top priority is the health and safety of our students and staff, and this testing was initiated out of an abundance of caution to ensure the water in our schools is safe.

Per the Environmental Protection Agency's (EPA) guidance on lead in drinking water, lead concentrations in drinking water should not exceed 15 parts per billion (ppb). Per the Illinois Department of Public Health (IDPH) guidance, lead concentrations in drinking water shall not exceed 5 ppb. For fixtures that have sample results equal to or above the Illinois Department of Public Health's standard of 5 ppb, these fixtures have been taken out of service until the issue is addressed and the fixture has been retested. No fixture will be returned to service until the Illinois Department of Public Health standard for lead in drinking water is met. Chicago's water supply is free of lead when it leaves the treatment plant. However, lead can be found in some interior plumbing fixtures and materials, and lead found in tap water usually comes from the corrosion of these items. This explains why some fixtures return with elevated results. The issue is not system-wide, but it is specific to the fixtures or pipes that will be addressed through the remediation plan.

Federal guidance indicates that children under the age of six are at the highest risk for harmful lead exposure, and they can be exposed to lead from a variety of sources, including paint, soil and even some consumer products. If you are concerned about your child's possible lead exposure risks, the Chicago Department of Public Health (CDPH) recommends going to your pediatrician or one of the local health care providers listed in the attachment for testing. Additionally, CDPH's lead hotline can address any health-related questions you may have or help you in deciding whether to have your child tested; for questions or more information, please call 312-747-5323. For additional information about lead and children, visit www.cdc.gov/lead.

The safety of your children is our highest priority, and we are doing everything in our power to address this situation in a quick and thorough manner. We will continue to keep you and your family informed throughout this process.

Sincerely,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer

Director of Environmental Health and Safety

Chicago Public Schools



Sep 10, 2024

STOWE

3444 W WABANSIA AVE, Chicago IL 60647.

Estimadas familias de **STOWE**:

En 2016, las Escuelas Públicas de Chicago (CPS) comenzaron a inspeccionar el agua potable de las escuelas del distrito en búsqueda de plomo. Nuestra primera prioridad es la salud y la seguridad de nuestros estudiantes y personal, y estas pruebas se iniciaron para ser precavidos y confirmar que el agua en nuestras escuelas estuviera segura.

Según las directrices de la Agencia de Protección Ambiental (EPA, según sus siglas en inglés) en cuanto al plomo en el agua potable la concentración de plomo en el agua potable no debe exceder 15 partes por mil millones (ppb, según sus siglas en inglés). Según las directrices del Departamento de Salud Pública de Illinois (IDPH, según sus siglas en inglés), las concentraciones de plomo en el agua potable no deben exceder 5 ppb.

Las instalaciones que al ser examinadas demostraron resultados que igualen o sobrepasaran el estándar del IDPH de 5 ppb han sido removidas de servicio hasta que el asunto sea resuelto y la instalación haya sido reexaminada. Ninguna instalación será regresada al servicio hasta que cumpla con los estándares de plomo en el agua del IDPH.

El agua de Chicago no contiene plomo al salir de la planta de tratamiento. Sin embargo, se puede encontrar plomo en algunas instalaciones y materiales de plomería interiores, y el plomo encontrado en el agua de pluma normalmente surge de la corrosión en estos artículos. Esto explica por qué algunas instalaciones regresan con resultados elevados. El asunto no está generalizado en el sistema, sino que es específico para instalaciones o tuberías que serán trabajadas por el plan de remediación.

Las directrices federales indican que los niños de menos de seis años sufren el mayor riesgo de exposición dañina al plomo, y pueden ser expuestos al plomo de una variedad de fuentes, que incluyen la pintura, el terreno y hasta algunos productos para el consumidor. Si está preocupado sobre los riesgos posibles de ser expuesto al plomo, el Departamento de Salud Pública de Chicago (CDPH) recomienda ir a su pediatra o uno de los proveedores de atención médica locales incluidos en el anexo para que sea examinado. Adicionalmente, la línea directa sobre el plomo del CDPH puede responder a cualquier pregunta de salud que tenga o ayudarlo y a decidir si hacerle una prueba a su niño; para preguntas o más información sobre el plomo y los niños, visite <https://www.cdc.gov/nceh/lead/>.

La seguridad de sus niños es nuestra primera prioridad, y estamos haciendo todo lo posible para responder a esta situación lo más rápida y rigurosamente posible. Continuaremos a mantenerlos a ustedes y sus familias informadas durante este proceso.

Sinceramente,

A handwritten signature in black ink that reads "Richard J. Schleyer".

Richard J. Schleyer
Director de Salud y Seguridad Ambientales
Escuelas Públicas de Chicago

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51129	51129-1-S-103-S01	1st Floor, South End, Room 103	Flush180	31-OCT-19	1.000	ug/L
51129	51129-1-S-103-S01	1st Floor, South End, Room 103	Flush180	31-OCT-19	4.180	ug/L
51129	51129-1-S-103-S01	1st Floor, South End, Room 103	Flush180	31-OCT-19	1.890	ug/L
51129	51129-1-S-103-S01	1st Floor, South End, Room 103	Flush180	31-OCT-19	1.000	ug/L
51129	51129-1-S-103-S01	1st Floor, South End, Room 103	Initial	31-OCT-19	1.550	ug/L
51129	51129-3-HAL-F06	Hallway 3rd floor	Flush180	05-AUG-20	1.920	ug/L
51129	51129-3-HAL-F06	Hallway 3rd floor	Initial	05-AUG-20	2.200	ug/L
51129	51129-1-101-S01	Main- Inside Room 101, Sink	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-101-S01	Main- Inside Room 101, Sink	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-101-S01	Main- Inside Room 101, Sink	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-101-S01	Main- Inside Room 101, Sink	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-101-S01	Main- Inside Room 101, Sink	Initial	03-JUN-16	1.000	ppb
51129	51129-1-102-S02	Main- Inside Room 102, Sink	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-102-S02	Main- Inside Room 102, Sink	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-102-S02	Main- Inside Room 102, Sink	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-102-S02	Main- Inside Room 102, Sink	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-102-S02	Main- Inside Room 102, Sink	Initial	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS04	Main- Kitchen Sink 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS04	Main- Kitchen Sink 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS04	Main- Kitchen Sink 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS04	Main- Kitchen Sink 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS04	Main- Kitchen Sink 1	Initial	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS05	Main- Kitchen Sink 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS05	Main- Kitchen Sink 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS05	Main- Kitchen Sink 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS05	Main- Kitchen Sink 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS05	Main- Kitchen Sink 2	Initial	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS06	Main- Kitchen Sink 3	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS06	Main- Kitchen Sink 3	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS06	Main- Kitchen Sink 3	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS06	Main- Kitchen Sink 3	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-KIT-KS06	Main- Kitchen Sink 3	Initial	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F01	Main- Outside Room 010, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F01	Main- Outside Room 010, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F01	Main- Outside Room 010, Fountain 1	Flush180	03-JUN-16	1.000	ppb



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51129	51129-B-HAL-F01	Main- Outside Room 010, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F01	Main- Outside Room 010, Fountain 1	Initial	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F02	Main- Outside Room 010, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F02	Main- Outside Room 010, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F02	Main- Outside Room 010, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F02	Main- Outside Room 010, Fountain 2	Initial	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F03	Main- Outside Room 010, Fountain 3	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F03	Main- Outside Room 010, Fountain 3	Flush180	03-JUN-16	1.000	ppb
51129	51129-B-HAL-F03	Main- Outside Room 010, Fountain 3	Initial	03-JUN-16	1.000	ppb
51129	51129-1-HAL-F03	Main- Outside Room 104, Sink 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-HAL-F03	Main- Outside Room 104, Sink 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-HAL-F03	Main- Outside Room 104, Sink 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-HAL-F03	Main- Outside Room 104, Sink 1	Initial	03-JUN-16	1.000	ppb
51129	51129-1-HAL-F04	Main- Outside Room 104, Sink 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-HAL-F04	Main- Outside Room 104, Sink 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-HAL-F04	Main- Outside Room 104, Sink 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-1-HAL-F04	Main- Outside Room 104, Sink 2	Flush180	05-AUG-20	1.000	ug/L
51129	51129-1-HAL-F04	Main- Outside Room 104, Sink 2	Initial	03-JUN-16	1.000	ppb
51129	51129-1-HAL-F04	Main- Outside Room 104, Sink 2	Initial	05-AUG-20	1.000	ug/L
51129	51129-2-HAL-F03	Main- Outside Room 204, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F03	Main- Outside Room 204, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F03	Main- Outside Room 204, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F03	Main- Outside Room 204, Fountain 1	Initial	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F04	Main- Outside Room 204, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F04	Main- Outside Room 204, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F04	Main- Outside Room 204, Fountain 2	Initial	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F01	Main- Outside Room 210, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F01	Main- Outside Room 210, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F01	Main- Outside Room 210, Fountain 1	Flush180	03-JUN-16	1.000	ppb

Water Quality Assessment Harriet Beecher Stowe Elementary School

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
51129	51129-2-HAL-F01	Main- Outside Room 210, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F01	Main- Outside Room 210, Fountain 1	Initial	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F02	Main- Outside Room 210, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F02	Main- Outside Room 210, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F02	Main- Outside Room 210, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F02	Main- Outside Room 210, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-2-HAL-F02	Main- Outside Room 210, Fountain 2	Initial	03-JUN-16	1.000	ppb
51129	51129-3-HAL-F04	Main- Outside Room 303, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-3-HAL-F04	Main- Outside Room 303, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-3-HAL-F04	Main- Outside Room 303, Fountain 1	Flush180	03-JUN-16	1.000	ppb
51129	51129-3-HAL-F04	Main- Outside Room 303, Fountain 1	Initial	03-JUN-16	1.000	ppb
51129	51129-3-HAL-F05	Main- Outside Room 303, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-3-HAL-F05	Main- Outside Room 303, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-3-HAL-F05	Main- Outside Room 303, Fountain 2	Flush180	03-JUN-16	1.000	ppb
51129	51129-3-HAL-F05	Main- Outside Room 303, Fountain 2	Initial	03-JUN-16	1.000	ppb
52576	52576-2-S-HAL-F01	Annex- 2nd Floor Outside washroom, Fountain 1	Flush180	14-MAR-19	1.120	ug/L
52576	52576-2-S-HAL-F01	Annex- 2nd Floor Outside washroom, Fountain 1	Flush180	14-MAR-19	1.000	ug/L
52576	52576-2-S-HAL-F01	Annex- 2nd Floor Outside washroom, Fountain 1	Flush180	14-MAR-19	1.000	ug/L
52576	52576-2-S-HAL-F01	Annex- 2nd Floor Outside washroom, Fountain 1	Flush180	14-MAR-19	1.000	ug/L
52576	52576-2-S-HAL-F01	Annex- 2nd Floor Outside washroom, Fountain 1	Initial	14-MAR-19	2.320	ug/L
52576	52576-2-S-HAL-F02	Annex- 2nd Floor Outside washroom, Fountain 2	Flush180	14-MAR-19	1.000	ug/L
52576	52576-2-S-HAL-F02	Annex- 2nd Floor Outside washroom, Fountain 2	Flush180	14-MAR-19	1.000	ug/L
52576	52576-2-S-HAL-F02	Annex- 2nd Floor Outside washroom, Fountain 2	Flush180	14-MAR-19	1.000	ug/L
52576	52576-2-S-HAL-F02	Annex- 2nd Floor Outside washroom, Fountain 2	Flush180	14-MAR-19	1.000	ug/L
52576	52576-2-S-HAL-F02	Annex- 2nd Floor Outside washroom, Fountain 2	Flush180	05-AUG-20	1.000	ug/L
52576	52576-2-S-HAL-F02	Annex- 2nd Floor Outside washroom, Fountain 2	Initial	14-MAR-19	1.000	ug/L
52576	52576-2-S-HAL-F02	Annex- 2nd Floor Outside washroom, Fountain 2	Initial	05-AUG-20	1.270	ug/L
52576	52576-1-W-401-S01	Annex- Inside Room 401, Sink	Flush180	14-MAR-19	6.300	ug/L
52576	52576-1-W-401-S01	Annex- Inside Room 401, Sink	Flush180	14-MAR-19	2.230	ug/L
52576	52576-1-W-401-S01	Annex- Inside Room 401, Sink	Flush180	14-MAR-19	1.790	ug/L
52576	52576-1-W-401-S01	Annex- Inside Room 401, Sink	Flush180	14-MAR-19	2.240	ug/L
52576	52576-1-W-401-S01	Annex- Inside Room 401, Sink	Flush180	21-NOV-19	4.530	ug/L
52576	52576-1-W-401-S01	Annex- Inside Room 401, Sink	Flush180	21-NOV-19	3.980	ug/L
52576	52576-1-W-401-S01	Annex- Inside Room 401, Sink	Flush180	21-NOV-19	1.650	ug/L
52576	52576-1-W-401-S01	Annex- Inside Room 401, Sink	Flush180	21-NOV-19	1.730	ug/L
52576	52576-1-W-	Annex- Inside Room 401, Sink	Initial	14-MAR-19	4.440	ug/L



Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	401-S01					
52576	52576-1-W-401-S01	Annex- Inside Room 401, Sink	Initial	21-NOV-19	1.100	ug/L
52576	52576-1-E-402-S01	Annex- Inside Room 402, Sink	Flush180	14-MAR-19	3.570	ug/L
52576	52576-1-E-402-S01	Annex- Inside Room 402, Sink	Flush180	14-MAR-19	1.190	ug/L
52576	52576-1-E-402-S01	Annex- Inside Room 402, Sink	Flush180	14-MAR-19	1.300	ug/L
52576	52576-1-E-402-S01	Annex- Inside Room 402, Sink	Flush180	14-MAR-19	1.530	ug/L
52576	52576-1-E-402-S01	Annex- Inside Room 402, Sink	Initial	14-MAR-19	2.260	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush	29-NOV-2023	1.400	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush	29-NOV-2023	1.110	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush	29-NOV-2023	1.610	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush	29-NOV-2023	1.500	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush	02-NOV-2023	4.810	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush	02-NOV-2023	1.840	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush	02-NOV-2023	2.670	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush	02-NOV-2023	1.950	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	12-JUL-23	5.450	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	12-JUL-23	7.220	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	12-JUL-23	3.810	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	12-JUL-23	2.310	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	27-JUL-23	5.250	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	27-JUL-23	2.950	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	27-JUL-23	3.070	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	27-JUL-23	8.720	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	14-MAR-19	15.900	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	14-MAR-19	5.990	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	14-MAR-19	5.740	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	14-MAR-19	5.850	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	21-NOV-19	2.710	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	21-NOV-19	2.150	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	19-FEB-20	1.970	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	21-NOV-19	8.550	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	21-NOV-19	43.300	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	19-FEB-20	1.840	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	19-FEB-20	1.670	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	19-FEB-20	2.530	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	11-AUG-23	6.430	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	11-AUG-23	3.430	ug/L
52576	52576-1-E-	Annex- Inside Room 414, Sink	Flush180	11-AUG-23	2.040	ug/L

Water Quality Assessment Harriet Beecher Stowe Elementary School

Facility ID	Fixture Code	Fixture Location	Draw Type	Collected On	Result	UOM
	414-S01					
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Flush180	11-AUG-23	2.310	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Initial	12-JUL-23	2.870	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Initial	27-JUL-23	2.410	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Initial	14-MAR-19	6.770	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Initial	21-NOV-19	19.000	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Initial	19-FEB-20	68.400	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Initial	11-AUG-23	2.200	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Initial	29-NOV-2023	2.240	ug/L
52576	52576-1-E-414-S01	Annex- Inside Room 414, Sink	Initial	02-NOV-2023	9.840	ug/L
52576	52576-1-S-HAL-F01	Annex- Outside Washroom 405, Fountain	Flush180	14-MAR-19	1.000	ug/L
52576	52576-1-S-HAL-F01	Annex- Outside Washroom 405, Fountain	Flush180	14-MAR-19	1.000	ug/L
52576	52576-1-S-HAL-F01	Annex- Outside Washroom 405, Fountain	Flush180	14-MAR-19	1.000	ug/L
52576	52576-1-S-HAL-F01	Annex- Outside Washroom 405, Fountain	Flush180	14-MAR-19	1.000	ug/L
52576	52576-1-S-HAL-F01	Annex- Outside Washroom 405, Fountain	Flush180	05-AUG-20	1.000	ug/L
52576	52576-1-S-HAL-F01	Annex- Outside Washroom 405, Fountain	Initial	14-MAR-19	1.430	ug/L
52576	52576-1-S-HAL-F01	Annex- Outside Washroom 405, Fountain	Initial	05-AUG-20	3.940	ug/L
52576	52576-1-S-HAL-F02	Annex- Outside Washroom 408, Fountain	Flush180	14-MAR-19	1.000	ug/L
52576	52576-1-S-HAL-F02	Annex- Outside Washroom 408, Fountain	Flush180	14-MAR-19	1.000	ug/L
52576	52576-1-S-HAL-F02	Annex- Outside Washroom 408, Fountain	Flush180	14-MAR-19	1.000	ug/L
52576	52576-1-S-HAL-F02	Annex- Outside Washroom 408, Fountain	Initial	14-MAR-19	2.490	ug/L