Chicago Public Schools

6 Month Asbestos Surveillance

2015 - Fall

		Y Scammon enderson Sti					acle Unit:	2524 01	1	Buildir Mail Ro	•	
	HERE IF NO CHA	NGE TO) ASBE	STOS Surve	stos Surveyor: ey Date: I Address:	11/5/2015	5					
	A copy of the 2013/201		Notice	d staff regarding the printed in school's n				was distributed ool's calendar		ther		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
04	9"x9" Tan w/ Brown Streaks VFT	115	SF	Engineer's Office & Bo Toilet, 1925 Building	iler	Miscellaneous	No	None	0		YES	XNO
2013 - Fall: N Comments: 2014- Spring Comments: 2014 - Fall: N Comments: 2015- Spring Comments: 2015 - Fall: N Comments:	: No Change No Change : No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
05	12"x12" Light Blue w/ Beige & Gray Flecks VFT	2100	SF	Room 107, Gymnasium Office, 1925 Building		Miscellaneous	No	None			YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
06	12"x12" Gray w/ Brown, White, & Orange Flecks VFT	640	SF	Room 220, 1925 Building		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
07	12"x12" Orange w/ Brown & White Specks VFT	4000	SF	1ES, 2ES, 1WS, 2WS, 1st and 2nd Floor Corridor, 2nd Floor Teachers Toilet, 1925 Building		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change

Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA	No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
09		9"x9" Tan w/ Brown Streaks VFT Mastic	115	SF	Engineer's Office & Boiler Toilet, 1925 Building		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
10	12"x12" Lt Blue w/ Beige & Gray Flecks VFT Mastic	2100	SF	Room 107, Gymnasium Office, 1925 Building, engineers office		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
11	12"x12" Gray w/Brn,White,&Orange Flks VFT Mastic	640	SF	Room 220, 1925 Building		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
12	12"x12" Orange w/ Brown & White Specks VFT Mastic	4000	SF	1ES, 2ES, 1WS, 2WS, 1st and 2nd Floor Corridor, 2nd Floor Teachers Toilet, 1925 Building		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change

Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13	12"x12" Beige w/ Brown & White Flecks VFT	600	SF	1WL, 204, 216, 2EL, 1925 Building		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
14	12"x12" Beige w/ Brown & White Flecks VFT Mastic	600	SF	1WL, 204, 216, 2EL, 1925 Building		Miscellaneous	No	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor
15	12"x12" Tan w/ Brown & White Specks VFT	2000	SF	Lunchroom/Auditorium, 106 Main Office, 1925 Building		Miscellaneous	No	None			YES X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

	2014 - Fall: No Change	
Comments:	Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
16	12"x12" Tan w/ Brown & White Specks VFT Mastic	200	SF	Lunchroom/Auditorium, 106 Main Office, 1925 Building		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
17	12"x12" Blue w/ Dark Blue & White Specks VFT	600	SF	Room 101, 1925 Building		Miscellaneous	No	None			YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
18	12"x12" Blue w/ Dk Blue & White Specks VFT Mastic	600	SF	Room 101, 1925 Building		Miscellaneous	No	None			YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x 9" Brown w/ White Specks VFT	115	SF	Boiler Toilet Under HA#4, & Engineer's Office, 1925 Building		Miscellaneous	No	None	0		YES X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
20	9"x9" Brown w/ White Specks VFT Mastic	115	SF	Boiler Toilet Under HA#4, & Engineer's Office, 1925 Building		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
21	12" x 12" Gray VFT	0	SF	Throughout, 1998 Annex Building		Miscellaneous		None			YES X NO	

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
22	12" x 12" Gray VFT Mastic	0	SF	Throughout, 1998 Annex Building		Miscellaneous		None			YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
23	Gray Vinyl Baseboard	0	LF	Throughout, 1998 Annex Building		Miscellaneous		None			YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
24	Gray Vinyl Baseboard Mastic	0		Throughout, 1998 Annex Building		Miscellaneous		None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

Commonts:	2015 - Fall: No Change
Comments.	Comments:

HA N	10	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
25		2' x 4' Ceiling Tile	0	SF	Throughout, 1998 Annex Building		Miscellaneous	Yes	None			YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
26	Drywall	0	SF	Throughout, 1998 Annex Building		Surface	Yes	None			YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
26A	Drywall Joint Compound	0	SF	Throughout, 1998 Annex Building		Surface	Yes	None			YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
27	12" x 12" White w/ Grey Streaks VFT	0	SF	Room 005, Room 006, Foyer, Men's and Women's Toilet, Pump Room, West Mobile Unit 1998		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2015- Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
28	12" x 12" White w/ Grey Streaks VFT Mastic	0	SF	Room 005, Room 006, Foyer, Men's and Women's Toilet, Pump Room, West Mobile Unit 1998		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change
Comments:

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
29	12" x 12" White w/ Grey Streaks VFT	0	SF	Room 005, Room 006, Foyer, Men's and Women's Toilet, Pump Room, East Mobile Unit 1998		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	
	-

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change
Comments:

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
30	12" x 12" White w/ Grey Streaks VFT Mastic	0	SF	Room 005, Room 006, Foyer, Men's and Women's Toilet, Pump Room, East Mobile Unit 1998		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change
Comments:

2015- Spring: No Change	
Comments:	

2015 - Fall: No	o Change
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
31	Cream Vinyl Baseboard	0	LF	Room 005, Room 006, Foyer, Men's and Women's Toilet, Pump Room, West Mobile Unit 1998		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2015- Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
32	Cream Vinyl Baseboard Mastic	0	SF	Room 005, Room 006, Foyer, Men's and Women's Toilet, Pump Room, West Mobile Unit 1998		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
33	Cream Vinyl Baseboard	0	LF	Room 005, Room 006, Foyer, Men's and Women's Toilet, Pump Room, East Mobile Unit 1998		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2015- Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34	Cream Vinyl Baseboard Mastic	0	LF	Room 005, Room 006, Foyer, Men's and Women's Toilet, Pump Room, East Mobile Unit 1998		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
35	12" x 12" Sand VFT	1400	SF	Room 001, Room 002, East Mobile Unit 1992		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
36	12" x 12" Sand VFT Mastic	1400	SF	Room 001, Room 002, East Mobile Unit 1992		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessmen	Category
37	Carpet Mastic	700	SF	Room 113		Miscellaneous	No	None	0		YES	NO

Comments:	2013 - Fall: No Change
Comments.	Comments:

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

Comments:	2015- Spring: No Change	
	Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
38	Terrazo	1800	SF	Room 201, 1st & 2nd floor corridors, all stairwells, entry vestibules, stairs to balcony, stage side stairs		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change
Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
39	12"x12" off white with tan & gray specks VFT	200	SF	Assembly hall toilets		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change Comments:

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
39 A	12"x12" off white with tan & gray specks (MASTIC)	200	SF	Assembly Hall toilets		Miscellaneous	No	None	0		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	
	· · ·

F	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	egory
2	41	12x12 Light Blue w/ Beige & Gray Flecks VFT	210	SF	Rooms 112 & 111		Miscellaneous	No	None			YES X NO)

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
41A	12x12 Light Blue w/ Beige & Gray Flecks Mastic	210	SF	rooms 112, 111		Miscellaneous	No	None			YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

Н	IA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
4	2	12x12 White w/ Tan Streaks	1800	SF	Main office waiting area & store room, 2nd fl library (207 & 211), room 106, 101, 107, 112, 111, 207		Miscellaneous	No	None			YES X NO	

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change Comments:

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
42A	12x12 White w/ Tan Streaks Mastic	1800	SF	Main office waiting area and store room, 2nd fl library (207 & 211), room 106, 101, 107, 112, 111, & 207		Miscellaneous	No	None			YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change

Comments:

2015- Spring: No Change Comments:

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
D	Cardboard Pipe Insulation	1000	LF	East and West Air Tunnels, & Pipe Chases - 1925 Building		TSI	Yes	Dist	50		YES XNO	

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change Comments:

2014- Spring: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categor	
E	MJP E/F/V on Cardboard Pipe Insulation	150	LF	East and West Air Tunnels, & Pipe Chases 1925 Building		TSI	Yes	Dist	25		YES	XNO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
F	Aircell Pipe Insulation	1500	LF	East and West Air Tunnels		TSI	Yes	Dist	50		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
G	MJP E/F/V on Aircell Pipe Insulation	275	LF	East and West Air Tunnels		TSI	Yes	Dist	15		YES	X NO

2013 - Fall: No Change	
Comments:	

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
н	Aircell Duct Insulation	200	SF	Crawl Space Under Auditorium Stage, 1925 Building		TSI	Yes	None	0		YES	X NO

2013 - Fall: No Change	
Comments:	

2014- Spring: No Change	
Comments:	

2014 - Fall: No Change	
Comments:	

2015 - Fall: No Change	
Comments:	

2015- Spring: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Syn & Crwill

Lynn A.Crivello

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Jonathan Y Scammon School
Date:	12/5/2015

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.


Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013.

Asbestos surveillances are conducted every six months.

CHECK ONE

A copy of this notice was sent home in each child's backpack.

A copy of this notice was printed in the school's newsletter and sent home with each child



Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.