Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7: The item/system is new or in good condition and no work is required.
- Rank 6: The item/system requires general cleaning and/or routine maintenance.
- Rank 5: The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4: The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3: The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2: The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1: The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.1

Definitions

Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.

Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.

For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.

Total Campus Need also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main

Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|-------------|-----------|---|--|------|----------|------|---------------|
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | NW- Rebuilt top section and Bottom | 6 | 70 | LF | \$35,035 |
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | NW- Middle portion right beneath rebuild | 5 | 10 | LF | \$17,875 |
| Cornice | | Cornice - Metal Projecting | Entire Building | 6 | 619 | LF | \$55,500 |
| Doors | | Exterior FRP Door | doors 1-3, 7-10 | 6 | 9 | EΑ | \$5,012 |
| Doors | | Exterior Steel Door | fire escape doors | 6 | 2 | EΑ | \$661 |
| Doors | | Side Lite | door 10 | 6 | 1 | EΑ | \$227 |
| Doors | | Transom Lite | door 1, 2, fire escape doors | 6 | 6 | EΑ | \$1,699 |
| Entrance | | Concrete Exterior Stairs | door 1 | 7 | 9 | LF | \$0 |
| Entrance | | Entrance Controls - Audio | door 1 | 6 | 1 | EΑ | \$429 |
| Entrance | | Stone Stairs | door 10 | 6 | 5 | LF | \$894 cracked |
| Fire Escape | | Fire Escapes | North Façade | 6 | 4 | LF | \$408 |
| Foundation | | Masonry Foundation | Entire Building | 7 | 439 | SF | \$0 |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Roof | 7 | 3 | EA | \$0 |



Building: Main Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|---|---|------|----------|------|-----------|--|
| Lintels | | Lintels - Brick | above doors and 3rd story windows | 6 | 21 | LF | \$0 | |
| Lintels | | Lintels - Stone | Entire Building | 6 | 520 | LF | \$0 | |
| Parapet | | Coping - Metal | N lower roof | 7 | 27 | LF | \$0 | |
| Parapet | | Coping - Stone | S lower roof | 6 | 33 | LF | \$0 | |
| Parapet | | Coping - Terra Cotta | S upper roof | 5 | 5 | LF | \$894 | cracked |
| Parapet | | Coping - Terra Cotta | Entire Building | 6 | 673 | LF | \$0 | open joints |
| Parapet | | Parapet < 16" Height | N lower roof | 6 | 27 | LF | \$4,205 | |
| Parapet | | Parapet 16" to 30" Height | Entire Building | 6 | 524 | LF | \$108,801 | |
| Roof System | | EPDM/ Synthetic Rubber Roof | upper W roof | 5 | 3,060 | SF | \$26,255 | bubbles throughout, ponding in SE corner |
| Roof System | | Exterior Downspouts | Entire Building | 6 | 164 | LF | \$3,049 | |
| Roof System | | Modified Bitumen Roof | Roof | 7 | 11,734 | SF | \$0 | |
| Roof System | | Modified Bitumen Roof | Upper central roof and lower roof- N near windows | 6 | 100 | SF | \$708 | |
| Roof System | | Roof Structure: Heavy Timber | Roof | 7 | 11,438 | SF | \$0 | |
| Roof System | | Roof Structure: Steel/Metal Deck/Concrete Topping | N boilerhouse | 7 | 3,456 | SF | \$0 | |
| Superstructure | | Heavy Timber | Entire Building | 7 | 45,208 | SF | \$0 | |
| Superstructure | | Steel with Clay Tile Arch | N- boilerhouse | 7 | 3,456 | SF | \$0 | |
| Walls | | Brick | Entire Building | 6 | 15,518 | SF | \$102,521 | efflorescence under windows, staining throughout |
| Walls | | Brick | upper roof, E and W face at roof level | 5 | 913 | SF | \$20,681 | spalling common brick |
| Walls | | Brick | East Façade | 5 | 250 | SF | \$5,663 | ivy |
| Walls | | Stone - Cut | Entire Building | 6 | 2,088 | SF | \$29,858 | |
| Windows | | Skylite - Glass Single-Pane | N, lower roof | 5 | 120 | SF | \$7,248 | chipped paint, putty cracking |
| Windows | | Window - Guards perforated | Entire Building | 6 | 997 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 5 | 1,899 | SF | \$65,581 | per engineer: balance issues, windows difficult to open throughout |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 6 | 2,849 | SF | \$24,444 | |
| | | | EXTERIOR Sub Total | | | | \$517,646 | |

Building: Main

Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank (| Quantity | Unit | Cost | Reason |
|------------------|-----------|--|-----------------|--------|----------|------|------|--------|
| Emergency System | | Automatic Transfer switch | Boiler Room | 7 | 1 | EA | \$0 | |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Entire Building | 7 | 6,629 | SF | \$0 | |



Building: Main

Category: ELECTRICAL

| Group | Sub Group | ltem | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------|-----------|--|-----------------|------|----------|------|-----------|--------------------|
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Entire Building | 7 | 5,382 | SF | \$0 | |
| Emergency System | | Emergency A/C power - Students Toilets | Entire Building | 7 | 1,748 | SF | \$0 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | 2nd Floor | 7 | 1 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | 1st Floor | 7 | 1 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | 3rd Floor | 7 | 1 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Lunchroom and Gym | 1st Floor | 7 | 4 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Toilets | 2nd Floor | 7 | 2 | EA | \$0 | |
| mergency System | | Exit Signs - Corridors and Stairs | 1st Floor | 7 | 3 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | 2nd Floor | 7 | 4 | EA | \$0 | |
| mergency System | | Exit Signs - Corridors and Stairs | Basement | 7 | 15 | EA | \$0 | |
| mergency System | | Exit Signs - Corridors and Stairs | 3rd Floor | 7 | 3 | EA | \$0 | |
| mergency System | | Exit Signs - Lunchroom - Gym - multipurpose room | s 1st Floor | 7 | 5 | EA | \$0 | |
| mergency System | | Public Announcement System | Main Office | 6 | 71,910 | SF | \$43,189 | |
| mergency System | | Security System - CCTV | Main Office | 6 | 71,910 | SF | \$102,831 | |
| mergency System | | Security System - Intrusion detection | Main Office | 6 | 71,910 | SF | \$66,840 | |
| mergency System | | UPS 30 KW and below | Boiler Room | 2 | 1 | EA | \$50,050 | Batteries removed. |
| ower Distribution | | Lighting and power panels | 3rd Floor | 6 | 1 | EA | \$715 | |
| ower Distribution | | Lighting and power panels | 1st Floor | 6 | 2 | EA | \$1,430 | |
| ower Distribution | | Lighting and power panels | Basement | 7 | 1 | EA | \$0 | |
| ower Distribution | | Lighting and power panels | Basement | 4 | 1 | EA | \$5,434 | |
| ower Distribution | | Lighting and power panels | 2nd Floor | 6 | 1 | EA | \$715 | |
| ower Distribution | | Lighting and power panels | 3rd Floor | 7 | 1 | EA | \$0 | |
| ower Distribution | | Lighting and power panels | Basement | 6 | 1 | EA | \$715 | |
| ower Distribution | | Lighting and power panels | 2nd Floor | 7 | 4 | EA | \$0 | |
| Power Distribution | | Main distribution panels 400-600 amp | 2nd Floor | 7 | 1 | EA | \$0 | |

ELECTRICAL Sub Total

\$271,920

Building: Main

Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------|-----------|--------------------------|---------------------------|------|----------|------|-----------|--------|
| Fire Alarm | | Fire Alarm System | Boiler Room | 4 | 47,449 | SF | \$167,595 | |
| Fire Alarm | | Fire Pump Controller | Sprinkler Room | 4 | 1 | EA | \$18,590 | |
| Pump Room Assembly | | Fire Pump less than 25hp | Sprinkler Room | 6 | 1 | EA | \$3,160 | |
| Sprinkler System | | Dry Sprinkler System | Sprinkler Room | 7 | 48,664 | SF | \$0 | |
| Sprinkler System | | Sprinkler Heads | Entire Building | 4 | 48,664 | SF | \$24,356 | |
| | | | FIRE PROTECTION Sub Total | | | | \$213,701 | |





Building: Main

Category: MECHANICAL

Group Sub Group Item Location Rank Quantity Unit Cost Reason

Building: Main

Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|----------------------|-----------|--|----------------------|------|----------|------|-------------|
| Air Conditioning | | Window A/C Unit | Basement | 7 | 3 | EA | \$0 |
| Air Conditioning | | Window A/C Unit | 2nd Floor | 7 | 12 | EA | \$0 |
| Air Conditioning | | Window A/C Unit | 1st Floor | 7 | 8 | EA | \$0 |
| Air Conditioning | | Window A/C Unit | 3rd Floor | 7 | 15 | EA | \$0 |
| Air Handling Systems | | Air Intake - Built Up Air Handling Unit | South Side Area Well | 6 | 1 | EA | \$1,430 |
| Air Handling Systems | | Multi Zone Double Delivery Built Up Air Handling Unit - Steam 45,000 to 60,000 cfm | Basement | 5 | 1 | EA | \$82,940 |
| Air Handling Systems | | Multi Zone Double Delivery Built Up Air Handling Unit Auxiliaries - Steam 30,001 to 45,000 cfm | Basement | 5 | 1 | EA | \$22,880 |
| Air Handling Systems | | Return Duct Work - Indoor - Vertical Shaft and Ducts | Entire Building | 7 | 100 | LF | \$0 |
| Boiler Systems | | Boiler Assembly - Steam - Low Pressure Scotch Marine Boiler 76-100 HP | Boiler Room | 5 | 2 | EA | \$114,400 |
| Boiler Systems | | Boiler Auxiliary - Steam Boiler 76-100 HP | Boiler Room | 6 | 2 | EA | \$4,004 |
| Boiler Systems | | Chemical Feed System (Steam Boilers) | Boiler Room | 4 | 1 | EA | \$10,296 |
| Boiler Systems | | Combustion Dampers | Boiler Room | 6 | 3 | EA | \$858 |
| Boiler Systems | | Feed Water Pumps and Tank - Steam Boilers | Pump Room | 6 | 1 | EA | \$8,437 |
| Boiler Systems | | Gas Boosters | Boiler Room | 7 | 2 | EA | \$0 |
| Heating Devices | | Unit Heater - Gas | Boiler Room | 5 | 1 | EA | \$4,290 |
| Heating Devices | | Wall Heater - Electric | Basement | 4 | 5 | EA | \$5,148 |
| Heating Devices | | Wall Heater - Electric | Basement | 7 | 3 | EA | \$0 |
| Heating Devices | | Wall Heater - Electric | Sprinkler Room | 4 | 1 | EA | \$1,030 |
| Heating Devices | | Wall Heater - Electric | 2nd Floor | 7 | 2 | EA | \$0 |
| Mechanical Plumbing | | Condensate Assembly - Pumps and Tank | Boiler Room | 5 | 1 | EA | \$9,438 |
| Mechanical Plumbing | | Piping - Condensate - Steel or Galvanized | Entire Building | 4 | 100 | LF | \$9,796 |
| Mechanical Plumbing | | Piping - Steam - Steel or Galvanized | Entire Building | 5 | 100 | LF | \$4,948 |
| Temperature Control | | Pneumatic System | Pump Room | 5 | 71,910 | SF | \$308,494 |
| Temperature Control | | Thermostats - Pneumatic | 3rd Floor | 7 | 8 | EA | \$0 |
| Temperature Control | | Thermostats - Pneumatic | Basement | 7 | 2 | EA | \$0 |
| Temperature Control | | Thermostats - Pneumatic | 1st Floor | 7 | 5 | EA | \$0 |
| Temperature Control | | Thermostats - Pneumatic | 2nd Floor | 7 | 7 | EA | \$0 |
| Temperature Control | | Zone Dampers | Basement | 6 | 36 | EA | \$5,148 |
| Ventilation | | Exhaust Fan - Indoor | 1st Floor | 6 | 2 | EA | \$1,001 |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 6 | 1 | EA | \$429 |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 7 | 2 | EA | \$0 |
| | | | | | | | |





Building: Main

Category: MECHANICAL

Group Sub Group Item Location Rank Quantity Unit Cost Reason

MECHANICAL Sub Total

\$594,966

Building: Main

Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason | |
|-----------|-----------|--|-----------------|------|----------|------|-------------|--|
| Hot Water | | Hot Water Heater - Gas 150,000 -300,000 BTU/HR | Boiler Room | 7 | 1 | EA | \$0 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 5 | 48,664 | SF | \$8,351 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 5 | 48,664 | SF | \$16,006 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 5 | 48,664 | SF | \$55,672 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 5 | 48,664 | SF | \$10,438 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 5 | 48,664 | SF | \$12,526 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 5 | 48,664 | SF | \$43,146 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 5 | 48,664 | SF | \$25,748 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 5 | 48,664 | SF | \$26,444 | |
| Piping | | Sanitary Piping | Entire Building | 5 | 48,664 | SF | \$29,923 | |
| Piping | | Storm Piping | Entire Building | 7 | 48,664 | SF | \$ 0 | |
| Piping | | Vent Piping | Entire Building | 7 | 48,664 | SF | \$ 0 | |
| Pumps | | Domestic Booster Pump duplex | Boiler Room | 7 | 1 | EA | \$0 | |

PLUMBING Sub Total

\$228,254

Building: Main Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason | |
|-----------------------|----------------------------------|---------------------------|------------------------------|------|----------|------|-------------|--|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | 1st Floor Main Office | 6 | 562 | SF | \$1,205 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Principal's Office 1st Floor | 5 | 489 | SF | \$2,769 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 2nd Fl. teachers Lounge | 6 | 402 | SF | \$1,138 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Basement Engineer's Office | 5 | 288 | SF | \$1,631 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Basement Office 2 | 6 | 307 | SF | \$869 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Basement Office | 6 | 363 | SF | \$1,028 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | 1st Floor Main Office | 6 | 361 | SF | \$516 | |



Building: Main Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|-----------------------|----------------------------------|------------------------------|--|------|----------|------|-------------|
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement Engineer's Office | 5 | 288 | SF | \$1,631 |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Assistant Principal 1st Floor in Main Office | 6 | 150 | SF | \$215 |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 1st Floor Main Office | 6 | 201 | SF | \$287 |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement Office | 6 | 363 | SF | \$519 |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement Office 2 | 6 | 307 | SF | \$439 |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 2nd Fl. teachers Lounge | 6 | 402 | SF | \$575 |
| Administrative Suites | Administrative Suites/Offices | Flooring - Wood | Principal's Office 1st Floor | 6 | 489 | SF | \$3,692 |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 2nd Fl. teachers Lounge | 7 | 6 | SF | \$0 |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Basement Engineer's Office | 6 | 4 | SF | \$3 |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Basement Office 2 | 6 | 7 | SF | \$5 |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Basement Office | 6 | 8 | SF | \$6 |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 1st Floor Main Office | 6 | 10 | SF | \$7 |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Principal's Office 1st Floor | 6 | 9 | SF | \$6 |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Basement Office 2 | 7 | 441 | SF | \$0 |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Basement Office | 6 | 353 | SF | \$1,010 |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement Engineer's Office | 6 | 375 | SF | \$885 |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement Office | 6 | 336 | SF | \$793 |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 1st Floor Main Office | 6 | 83 | SF | \$196 |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Principal's Office 1st Floor | 6 | 883 | SF | \$2,083 |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Assistant Principal 1st Floor in Main Office | 5 | 112 | SF | \$529 |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 2nd Fl. teachers Lounge | 6 | 877 | SF | \$2,069 |
| Doors | | Interior Steel Doors incl hw | Entire Building | 6 | 24 | EA | \$6,795 |
| Doors | | Interior Wood Doors incl hw | Entire Building | 5 | 26 | EA | \$12,269 |





Building: Main Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------------|---|-----------------------------|---------------------------|------|----------|------|----------|--------|
| Doors | | Interior Wood Doors incl hw | Entire Building | 6 | 45 | EA | \$12,741 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 7 | 6 | EA | \$0 | |
| Doors | | Transom Window | Entire Building | 7 | 396 | SF | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Bleacher Seating | 3rd Floor | | | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Ceiling - Plaster/Drywall | 3rd Floor | 6 | 4,560 | SF | \$38,994 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Flooring - Tile/Sheet | 3rd Floor | 6 | 3,680 | SF | \$5,262 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Flooring - Wood | 3rd Floor | 6 | 887 | SF | \$6,697 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Lighting - Pendant/Surface | 3rd Floor | 6 | 32 | EA | \$3,890 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Scoreboards | 3rd Floor | | | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Sound System | 3rd Floor | | | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Stage Curtain | 3rd Floor | 6 | 2 | EA | \$18,876 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Walls - Plaster/Drywall | 3rd Floor | 6 | 3,030 | SF | \$25,997 | |
| Locker/Shower Room | Children's Standard Student Restroom | Benches | Basement Girls East | | | LF | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Benches | 2nd Floor Boys | | | LF | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Benches | 2nd Floor Girls | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | 2nd Floor | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Benches | Basement Girls West | | | LF | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Benches | Basement PreK East | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | Men's Basement Staff | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Benches | Basement Boys | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | 2nd Floor Teachers Lounge | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | Basement Girls East | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Lockers | Basement PreK East | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | 2nd Floor Teachers Lounge | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | 2nd Floor | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Lockers | 2nd Floor Girls | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | Basement Girls West | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Lockers | 2nd Floor Boys | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | Men's Basement Staff | | | EA | \$0 | |



Building: Main Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|---|-------------------------|--------------------------------|------|----------|------|----------|--------|
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | Basement Boys | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Showers | Basement PreK East | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | Basement Boys | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Showers | 2nd Floor Boys | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Showers | 2nd Floor Girls | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 2nd Floor Teachers Lounge | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | Basement Girls East | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | Basement Girls West | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | Men's Basement Staff | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 2nd Floor | | | EA | \$0 | |
| Lunchroom | Lunchroom | Ceiling - Lay-In | Basement | 6 | 822 | SF | \$1,763 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Basement | 5 | 822 | SF | \$4,655 | |
| Lunchroom | Lunchroom | Lighting - Lay-In | Basement | 6 | 14 | SF | \$10 | |
| Lunchroom | Lunchroom | Serving Line | Basement | | | LF | \$0 | |
| Lunchroom | Lunchroom | Wall - Concrete Block | Basement | 6 | 1,870 | SF | \$5,348 | |
| MDF/IDF | | Finishes | Entire Building | 7 | 147 | SF | \$0 | |
| MDF/IDF | | Ventilation and Cooling | Entire Building | 7 | 1 | EA | \$0 | |
| Mechanical/Service Rooms | | Boiler Room | Basement | 5 | 2,453 | SF | \$27,782 | |
| Mechanical/Service Rooms | | Storage Room | Basement Supply Room | 6 | 314 | SF | \$1,482 | |
| Mechanical/Service Rooms | | Storage Room | Basement | 6 | 850 | SF | \$4,011 | |
| Mechanical/Service Rooms | | Storage Room | Class Room Wardrobe/Storage | 6 | 2,520 | SF | \$11,892 | |
| Mechanical/Service Rooms | | Storage Room | Fieldhouse- Music room storage | 6 | 510 | SF | \$2,407 | |
| Mechanical/Service Rooms | | Storage Room | Storage at Pre-K | 6 | 56 | SF | \$264 | |
| Mechanical/Service Rooms | | Storage Room | Basement Storage at Boiler | 5 | 341 | SF | \$3,862 | |
| Mechanical/Service Rooms | | Storage Room | Main Office Storage | 6 | 77 | SF | \$363 | |
| Mechanical/Service Rooms | | Storage Room | Basement Storage at Tank | 5 | 216 | SF | \$2,446 | |
| Mechanical/Service Rooms | | Storage Room | Storage at Engineer's Office | 5 | 216 | SF | \$2,446 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd Floor Teachers Lounge | 7 | 57 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | Men's Basement Staff | 6 | 28 | SF | \$216 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Basement Boys | 6 | 217 | SF | \$1,676 | |



Building: Main Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|---|---------------------------|---------------------------|------|----------|------|---------|--------|
| Staff Restroom | Adult Standard Student Restroom | Accessories | 2nd Floor Girls | 7 | 340 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | Basement PreK East | 6 | 65 | SF | \$502 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd Floor | 7 | 45 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | 2nd Floor Boys | 6 | 340 | SF | \$2,625 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Basement Girls West | 6 | 288 | SF | \$2,224 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Basement Girls East | 6 | 498 | SF | \$3,846 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | 2nd Floor Teachers Lounge | 7 | 57 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Men's Basement Staff | 5 | 28 | SF | \$159 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Girls | 7 | 340 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Basement Girls East | 5 | 498 | SF | \$2,820 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Basement Girls West | 6 | 288 | SF | \$815 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | Basement PreK East | 6 | 65 | SF | \$184 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd Floor | 7 | 45 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Basement Boys | 6 | 217 | SF | \$614 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Boys | 7 | 340 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 2nd Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | Men's Basement Staff | | | EΑ | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Basement Girls East | 5 | 2 | EA | \$3,003 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Basement Boys | 5 | 1 | EA | \$1,502 | |
| Staff Restroom | Staff Restroom | Floor Drain | 2nd Floor Teachers Lounge | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Basement Girls West | 6 | 1 | EA | \$300 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | 2nd Floor Girls | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | 2nd Floor Boys | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | Basement PreK East | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Concrete | Basement PreK East | 6 | 65 | SF | \$307 | |





Building: Main Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|----------------|---|-----------------------------------|---------------------------|------|----------|------|-------------|
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement Girls East | 6 | 498 | SF | \$1,268 |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement Girls West | 6 | 288 | SF | \$733 |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Men's Basement Staff | 5 | 28 | SF | \$440 |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor Teachers Lounge | 7 | 57 | SF | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement Boys | 6 | 217 | SF | \$552 |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor Girls | 7 | 340 | SF | \$0 |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor Boys | 7 | 340 | SF | \$0 |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor | 7 | 45 | SF | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Basement Girls West | 6 | 2 | EA | \$434 |
| Staff Restroom | Staff Restroom | Hand Dryer | Men's Basement Staff | | | EA | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Basement Girls East | 6 | 2 | EA | \$434 |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | Basement PreK East | | | EA | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Basement Boys | 6 | 2 | EA | \$434 |
| Staff Restroom | Staff Restroom | Hand Dryer | 2nd Floor | | | EA | \$0 |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | 2nd Floor Boys | 7 | 1 | EA | \$0 |
| Staff Restroom | Staff Restroom | Hand Dryer | 2nd Floor Teachers Lounge | | | EA | \$0 |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | 2nd Floor Girls | 7 | 1 | EA | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Basement Girls West | 6 | 2 | EA | \$744 |
| Staff Restroom | Staff Restroom | Lavatory | Men's Basement Staff | 6 | 1 | EA | \$372 |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Basement Girls East | | | EA | \$0 |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | Basement PreK East | 6 | 1 | EA | \$372 |
| Staff Restroom | Staff Restroom | Lavatory | 2nd Floor Teachers Lounge | 6 | 1 | EA | \$372 |
| Staff Restroom | Staff Restroom | Lavatory | 2nd Floor | 7 | 1 | EA | \$0 |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | 2nd Floor Girls | 7 | 2 | EA | \$0 |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | 2nd Floor Boys | 7 | 2 | EA | \$0 |





Building: Main Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|----------------|---|-----------------------------|---------------------------|------|----------|------|-------------|
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Basement Boys | 6 | 2 | EA | \$744 |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Pendant/ Surface | Basement PreK East | 6 | 1 | SF | \$1 |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Girls | 7 | 4 | SF | \$0 |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 2nd Floor Teachers Lounge | 7 | 1 | SF | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Basement Girls East | 6 | 9 | SF | \$6 |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Basement Girls West | 6 | 4 | SF | \$3 |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Men's Basement Staff | 6 | 1 | SF | \$1 |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 2nd Floor | 7 | 1 | SF | \$0 |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Boys | 7 | 4 | SF | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Basement Boys | 6 | 4 | SF | \$3 |
| Staff Restroom | Adult Standard Student Restroom | Partitions | Basement PreK East | | | EA | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Basement Boys | 6 | 3 | EA | \$538 |
| Staff Restroom | Staff Restroom | Partitions | Men's Basement Staff | | | EA | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Basement Girls East | 6 | 16 | EA | \$2,869 |
| Staff Restroom | Staff Restroom | Partitions | 2nd Floor Teachers Lounge | 7 | 2 | EA | \$0 |
| Staff Restroom | Staff Restroom | Partitions | 2nd Floor | | | EA | \$0 |
| Staff Restroom | Adult Standard Student Restroom | Partitions | 2nd Floor Boys | 7 | 2 | EA | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Basement Girls West | 6 | 5 | EA | \$897 |
| Staff Restroom | Adult Standard Student Restroom | Partitions | 2nd Floor Girls | 7 | 5 | EA | \$0 |
| Staff Restroom | Staff Restroom | Urinals | 2nd Floor | | | EA | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Basement Boys | 6 | 10 | EA | \$3,718 |
| Staff Restroom | Staff Restroom | Urinals | Men's Basement Staff | | | EA | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Basement Girls West | | | EA | \$0 |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Basement Girls East | | | EA | \$0 |
| Staff Restroom | Staff Restroom | Urinals | 2nd Floor Teachers Lounge | | | EA | \$0 |



Building: Main Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|---|--------------------------------|---------------------------|------|----------|------|----------|----------|
| • | • | | | | | | | 11000011 |
| Staff Restroom | Adult Standard Student Restroom | Urinals | 2nd Floor Girls | 7 | 3 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | 2nd Floor Boys | 7 | 3 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | Basement PreK East | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | Basement Girls West | 6 | 147 | SF | \$420 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | Basement Girls East | 6 | 184 | SF | \$526 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Plaster/Drywall | Basement PreK East | 6 | 126 | SF | \$297 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 2nd Floor Teachers Lounge | 7 | 152 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 2nd Floor | 6 | 112 | SF | \$264 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Plaster/Drywall | 2nd Floor Girls | 6 | 243 | SF | \$573 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Plaster/Drywall | 2nd Floor Boys | 6 | 243 | SF | \$573 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Basement Girls West | 6 | 589 | SF | \$4,211 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Boys | 6 | 472 | SF | \$3,375 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Basement Girls East | 5 | 735 | SF | \$34,685 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | Men's Basement Staff | 6 | 178 | SF | \$1,273 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Basement Boys | 6 | 607 | SF | \$4,340 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 2nd Floor Teachers Lounge | 7 | 105 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Girls | 6 | 472 | SF | \$3,375 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | 2nd Floor | 6 | 176 | SF | \$448 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Basement Girls West | 6 | 5 | EA | \$1,859 | |
| Staff Restroom | Staff Restroom | Water Closet | Men's Basement Staff | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Basement Girls East | 6 | 16 | EA | \$5,949 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | Basement PreK East | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | 2nd Floor Girls | 7 | 5 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | 2nd Floor Boys | 7 | 2 | EA | \$0 | |





Building: Main Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------|---|--------------|---------------------------|--------|----------|------|-----------|--------|
| Staff Restroom | Staff Restroom | Water Closet | 2nd Floor Teachers Lounge | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Basement Boys | 6 | 3 | EA | \$1,115 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| | | | INTERIOR | Sub To | tal | | \$324 888 | |

Building: Main Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|---------------|-------------------------------|--------------------------------|--|------|----------|------|-------------|
| ADMIN_CEILING | Administrative Suites/Offices | Administrative Office Ceiling | Assistant Principal 1st Floor in Main Office | | 150 | SF | \$0 |
| ADMIN_LIGHT | Administrative Suites/Offices | Administrative Office Lighting | Assistant Principal 1st Floor in Main Office | | | EA | \$0 |
| ADMIN_WALL | Administrative Suites/Offices | Administrative Office Walls | 1st Floor Main Office | 6 | 301 | SF | \$710 |
| ADMIN_WALL | Administrative Suites/Offices | Administrative Office Walls | Assistant Principal 1st Floor in Main Office | 6 | 168 | SF | \$396 |
| ADMIN_WALL | Administrative Suites/Offices | Administrative Office Walls | Principal's Office 1st Floor | 6 | 278 | SF | \$656 |
| ADMIN_WALL | Administrative Suites/Offices | Administrative Office Walls | Assistant Principal 1st Floor in Main Office | 6 | 28 | SF | \$66 |
| ADMIN_WALL | Administrative Suites/Offices | Administrative Office Walls | Basement Engineer's Office | 5 | 375 | SF | \$1,770 |
| Casework | Classroom | Casework | | 7 | 4 | LF | \$0 |
| Casework | Classroom | Casework | | 6 | 17 | LF | \$608 |
| Casework | Classroom | Casework | | 6 | 4 | LF | \$143 |
| Casework | Classroom | Casework | | | | LF | \$0 |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 |
| Casework | Classroom | Casework | | 6 | 40 | LF | \$1,430 |
| Casework | Classroom | Casework | | | | LF | \$0 |
| Casework | Classroom | Casework | | 7 | 4 | LF | \$0 |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 |
| Casework | Classroom | Casework | | 6 | 40 | LF | \$1,430 |
| Casework | Classroom | Casework | | | | LF | \$0 |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 |
| Casework | Classroom | Casework | | 7 | 4 | LF | \$0 |





Building: Main Category: ROOM

| Group | Sub Group | Item | Location | Rank C | Quantity | Unit | Cost Reason |
|-------------|-----------|-----------------|----------|--------|----------|------|-------------|
| Casework | Classroom | Casework | | 6 | 57 | LF | \$2,038 |
| Casework | Classroom | Casework | | 7 | 4 | LF | \$0 |
| Casework | Classroom | Casework | | | | LF | \$0 |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 827 | SF | \$0 |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 911 | SF | \$0 |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 860 | SF | \$1,845 |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 827 | SF | \$0 |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 911 | SF | \$0 |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 860 | SF | \$0 |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 860 | SF | \$0 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 852 | SF | \$2,412 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 860 | SF | \$2,435 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 860 | SF | \$2,435 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 860 | SF | \$2,435 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 860 | SF | \$2,435 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 860 | SF | \$2,435 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 700 | SF | \$1,982 |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 860 | SF | \$0 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 720 | SF | \$2,039 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 860 | SF | \$2,435 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 860 | SF | \$2,435 |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Lunchroom | Chalk Board | Basement | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 |



Building: Main Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|-------------|-----------|------------------------|---------------------------|------|----------|------|-------------|
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Corridors | Corridors | Concrete Block | Basement Toilet Vestibule | 7 | 329 | SF | \$0 |
| Corridors | Corridors | Concrete Block | Men's Lounge Vestibule | 6 | 344 | SF | \$984 |
| Corridors | Corridors | Concrete Block | Basement | 6 | 214 | SF | \$612 |
| Corridors | Corridors | Concrete Epoxy/Painted | East Stair | 6 | 687 | SF | \$3,242 |
| Corridors | Corridors | Concrete Epoxy/Painted | Basement | 6 | 2,309 | SF | \$10,896 |
| Corridors | Corridors | Concrete Epoxy/Painted | Men's Lounge Vestibule | 6 | 19 | SF | \$90 |
| Corridors | Corridors | Drinking Fountains | Men's Lounge Vestibule | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | 3rd Floor | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | East Stair | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | East vestibule | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | Basement Toilet Vestibule | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | Basement | | | EA | \$0 |
| Corridors | Corridors | Drop/Lay-In | East Stair | 6 | 435 | SF | \$933 |
| Corridors | Corridors | Floors | 1st Floor | 6 | 1,615 | SF | \$12,194 |
| Corridors | Corridors | Floors | 2nd Floor | 6 | 1,615 | SF | \$12,194 |
| Corridors | Corridors | Floors | 3rd Floor | 6 | 634 | SF | \$4,787 |
| Corridors | Corridors | Pendant/Surface | 3rd Floor | 7 | 634 | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | Basement | 6 | 2,309 | EA | \$1,651 |
| Corridors | Corridors | Pendant/Surface | 1st Floor | 7 | 1,615 | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 7 | 1,615 | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | East Stair | 7 | 6 | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | Men's Lounge Vestibule | 6 | 2 | EA | \$1 |
| Corridors | Corridors | Pendant/Surface | East vestibule | 7 | 2 | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | Basement Toilet Vestibule | 6 | 2 | EA | \$1 |
| Corridors | Corridors | Plaster/Drywall | East Stair | 6 | 3,605 | SF | \$8,506 |
| Corridors | Corridors | Plaster/Drywall | East vestibule | 6 | 320 | SF | \$755 |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 6 | 2,298 | SF | \$5,422 |
| Corridors | Corridors | Plaster/Drywall | 3rd Floor | 6 | 824 | SF | \$1,944 |
| Corridors | Corridors | Plaster/Drywall | Basement | 6 | 1,237 | SF | \$2,919 |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 6 | 2,298 | SF | \$5,422 |
| Corridors | Corridors | Single Water Cooler | 2nd Floor | 7 | 1 | EA | \$0 |
| Corridors | Corridors | Single Water Cooler | 1st Floor | 7 | 1 | EA | \$0 |
| Corridors | Corridors | Stair Handrails | 2nd Floor | | | LF | \$0 |
| | Corridors | Stair Handrails | Basement Toilet Vestibule | | | LF | \$0 |



Building: Main Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|-------------------|-----------|------------------------|---------------------------|------|----------|------|-------------|
| Corridors | Corridors | Stair Handrails | Men's Lounge Vestibule | 6 | 6 | LF | \$0 |
| Corridors | Corridors | Stair Handrails | East Stair | 6 | 156 | LF | \$ 0 |
| Corridors | Corridors | Stair Handrails | Basement | | | LF | \$0 |
| Corridors | Corridors | Stair Handrails | 1st Floor | | | LF | \$0 |
| Corridors | Corridors | Stair Handrails | 3rd Floor | | | LF | \$0 |
| Corridors | Corridors | Stair Handrails | East vestibule | | | LF | \$0 |
| Corridors | Corridors | Stairs | Basement | | | EA | \$ 0 |
| Corridors | Corridors | Stairs | Men's Lounge Vestibule | 6 | 3 | EA | \$21 |
| Corridors | Corridors | Stairs | Basement Toilet Vestibule | | | EA | \$0 |
| Corridors | Corridors | Stairs | 2nd Floor | | | EA | \$0 |
| Corridors | Corridors | Stairs | 3rd Floor | | | EA | \$ 0 |
| Corridors | Corridors | Stairs | 1st Floor | | | EA | \$0 |
| Corridors | Corridors | Stairs | East vestibule | | | EA | \$0 |
| Corridors | Corridors | Stairs | East Stair | 6 | 83 | EA | \$593 |
| Corridors | Corridors | Structural Glazed Tile | Men's Lounge Vestibule | 6 | 230 | SF | \$1,645 |
| Corridors | Corridors | Student Lockers | Basement | | | EA | \$ 0 |
| Corridors | Corridors | Student Lockers | 2nd Floor | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | Basement Toilet Vestibule | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | 1st Floor | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | East vestibule | | | EA | \$ 0 |
| Corridors | Corridors | Student Lockers | Men's Lounge Vestibule | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | East Stair | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | 3rd Floor | | | EA | \$0 |
| Corridors | Corridors | Tile Ceramic/Porcelain | Men's Lounge Vestibule | 6 | 139 | SF | \$354 |
| Corridors | Corridors | Tile Ceramic/Porcelain | East vestibule | 6 | 113 | SF | \$288 |
| Corridors | Corridors | Tile Ceramic/Porcelain | Basement Toilet Vestibule | 6 | 179 | SF | \$456 |
| Corridors | Corridors | Walls | Basement | 6 | 1,855 | SF | \$4,377 |
| Corridors | Corridors | Walls | Basement | 6 | 94 | SF | \$222 |
| Corridors | Corridors | Walls | Basement | 6 | 497 | SF | \$1,173 |
| Corridors | Corridors | Walls | Basement Toilet Vestibule | 6 | 110 | SF | \$260 |
| Corridors Ceiling | Corridors | Plaster/Drywall | East vestibule | 6 | 113 | SF | \$320 |
| Corridors Ceiling | Corridors | Plaster/Drywall | Basement Toilet Vestibule | 6 | 179 | SF | \$507 |
| Corridors Ceiling | Corridors | Plaster/Drywall | Men's Lounge Vestibule | 6 | 164 | SF | \$464 |
| Corridors Ceiling | Corridors | Plaster/Drywall | 3rd Floor | 5 | 634 | SF | \$3,590 |
| Corridors Ceiling | Corridors | Plaster/Drywall | 1st Floor | 6 | 1,615 | SF | \$4,573 |
| Corridors Ceiling | Corridors | Plaster/Drywall | Basement | 6 | 2,309 | SF | \$6,538 |
| Corridors Ceiling | Corridors | Plaster/Drywall | 2nd Floor | 6 | 1,615 | SF | \$4,573 |





Building: Main Category: ROOM

| Group | Sub Group | Item | Location | Rank Qu | ıantity | Unit | Cost | Reason |
|----------|----------------------|-----------------|-----------|---------|---------|------|----------|--------|
| Floor | Classroom | Concrete | | 6 | 720 | SF | \$3,398 | |
| Floor | Classroom | Tile/Sheet | | 6 | 911 | SF | \$1,303 | |
| Floor | Classroom | Tile/Sheet | | 6 | 700 | SF | \$1,001 | |
| Floor | Classroom | Wood | | 5 | 860 | SF | \$12,175 | |
| Floor | Classroom | Wood | | 6 | 911 | SF | \$6,878 | |
| Floor | Classroom | Wood | | 6 | 852 | SF | \$6,433 | |
| Floor | Classroom | Wood | | 6 | 860 | SF | \$6,493 | |
| Floor | Classroom | Wood | | 6 | 860 | SF | \$6,493 | |
| Floor | Classroom | Wood | | 6 | 860 | SF | \$6,493 | |
| Floor | Classroom | Wood | | 6 | 860 | SF | \$6,493 | |
| Floor | Classroom | Wood | | 6 | 860 | SF | \$6,493 | |
| Floor | Classroom | Wood | | 6 | 860 | SF | \$6,493 | |
| Floor | Classroom | Wood | | 6 | 827 | SF | \$6,244 | |
| Floor | Classroom | Wood | | 6 | 827 | SF | \$6,244 | |
| Floor | Classroom | Wood | | 6 | 860 | SF | \$6,493 | |
| Floor | Classroom | Wood | | 6 | 860 | SF | \$6,493 | |
| Floor | Classroom | Wood | | 6 | 860 | SF | \$6,493 | |
| Floor | Classroom | Wood | | 6 | 860 | SF | \$6,493 | |
| GYM_WALL | Gymnasium.Auditorium | Gymnasia Walls | 3rd Floor | 6 | 1,010 | SF | \$8,666 | |
| Lighting | Classroom | Lay-In | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 6 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 20 | EA | \$1,430 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 12 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |



Building: Main Category: ROOM

| Group S | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|-----------------|---------------------------------|-----------------|----------------------|--------|----------|------|-------------|
| | unchroom | Lunchroom Walls | Basement | 6 | 354 | SF | \$1,012 |
| | unchroom | Lunchroom Walls | Basement | 6 | 327 | SF | \$935 |
| | Classroom | Marker Board | Dasement | 7 | 42 | LF | \$0 |
| | unchroom | Marker Board | Basement | , | 42 | LF | \$0 |
| | Classroom | Marker Board | Dasement | 6 | 14 | LF | \$400 |
| | Classroom | Marker Board | | 7 | 42 | LF | \$0 |
| | Classroom | Marker Board | | , | 72 | LF | \$0 |
| | Classroom | Marker Board | | 7 | 26 | LF | \$0 |
| | Classroom | Marker Board | | 7 | 42 | LF | \$0 |
| | Classroom | Marker Board | | 7 | 42 | LF | \$0 |
| | Classroom | Marker Board | | 7 | 42 | LF | \$0 |
| | Classroom | Marker Board | | 7 | 20 | LF | \$0 |
| | Classroom | Marker Board | | , 7 | 8 | LF | \$0 |
| | Classroom | Marker Board | | 7 | 42 | LF | \$0 |
| | Classroom | Marker Board | | 7 | 42 | LF | \$0 |
| | Classroom | Marker Board | | · | | LF | \$0 |
| | Classroom | Marker Board | | 7 | 42 | LF | \$0 |
| | Classroom | Marker Board | | 7 | 26 | LF | \$0 |
| | Classroom | Marker Board | | 7 | 42 | LF | \$0 |
| | Classroom | Marker Board | | | | LF | \$0 |
| | Classroom | Marker Board | | 7 | 42 | LF | \$0 |
| <u> </u> | Adult Standard Student Restroom | Restroom Walls | Basement PreK East | 6 | 191 | SF | \$486 |
| RESTROOM_WALL S | Staff Restroom | Restroom Walls | Men's Basement Staff | 5 | 39 | SF | \$613 |
| Wall | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 |
| Wall | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 |
| Wall C | Classroom | Plaster/Drywall | | 6 | 776 | SF | \$1,831 |
| Wall C | Classroom | Plaster/Drywall | | 6 | 885 | SF | \$2,088 |
| Wall C | Classroom | Plaster/Drywall | | 6 | 776 | SF | \$1,831 |
| Wall C | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 |
| Wall | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 |
| Wall | Classroom | Plaster/Drywall | | 6 | 820 | SF | \$1,935 |
| Wall | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 |
| Wall | Classroom | Plaster/Drywall | | 6 | 670 | SF | \$1,581 |
| Wall | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 |
| Wall | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 |
| Wall | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 |
| Wall | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 |



Building: Main Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|-----------------|----------|---------|----------|------|-----------|--------|
| Wall | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 820 | SF | \$1,935 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 788 | SF | \$1,859 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 951 | SF | \$2,244 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| Wall | Classroom | Wall | | 6 | 364 | SF | \$859 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| Wall | Classroom | Wall | | 6 | 390 | SF | \$920 | |
| Wall | Classroom | Wall | | 6 | 390 | SF | \$920 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| Wall | Classroom | Wall | | 6 | 330 | SF | \$779 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| Wall | Classroom | Wall | | 6 | 364 | SF | \$859 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| Wall | Classroom | Wall | | 6 | 377 | SF | \$890 | |
| | | | ROOM | Sub Tot | tal | | \$315,683 | |

Building Main Sub Total

\$2,467,058

Building: Addition Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------|-----------|---|-------------------|------|----------|------|----------|------------------------------|
| Cornice | | Cornice - Masonry Projecting/Limestone | S and W entrances | 6 | 73 | LF | \$2,239 | |
| Cornice | | Cornice - Metal Projecting | Entire Building | 6 | 478 | LF | \$42,858 | |
| Doors | | Exterior FRP Door | doors 4-6 | 6 | 8 | EA | \$4,455 | |
| Doors | | Transom Lite | doors 4-6 | 6 | 6 | EA | \$1,699 | |
| Entrance | | Concrete Exterior Stairs | doors 4 and 5 | 7 | 33 | LF | \$0 | |
| Entrance | | Concrete Exterior Stairs | door 4 | 6 | 3 | LF | \$322 | |
| Foundation | | Masonry Foundation | Entire Building | 7 | 408 | SF | \$0 | |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Roof | 7 | 6 | EA | \$0 | |
| Lintels | | Lintels - Steel | 2nd story windows | 6 | 53 | LF | \$2,001 | minor corrosion, needs paint |



Building: Addition Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|--|---|--------|----------|------|-----------|---|
| Lintels | | Lintels - Stone | Entire Building | 6 | 255 | LF | \$0 | |
| Parapet | | Coping - Stone | S and W entrances | 6 | 73 | LF | \$0 | |
| Parapet | | Coping - Terra Cotta | Entire Building | 6 | 320 | LF | \$0 | open/ poor joints throughout |
| Parapet | | Parapet < 16" Height | S and W entrances, upper story | 6 | 137 | LF | \$21,335 | |
| Parapet | | Parapet > 30" Height | upper roof | 6 | 88 | LF | \$22,840 | |
| Parapet | | Parapet 16" to 30" Height | upper roof separating main and addition | 5 | 72 | LF | \$23,104 | |
| Parapet | | Parapet 16" to 30" Height | Upper roof | 6 | 96 | LF | \$19,933 | |
| Roof System | | EPDM/ Synthetic Rubber Roof | Roof | 6 | 5,712 | SF | \$28,589 | |
| Roof System | | Exterior Downspouts | S roof | 6 | 53 | LF | \$985 | |
| Roof System | | Modified Bitumen Roof | S and W roof | 6 | 398 | SF | \$2,817 | |
| Roof System | | Roof Structure: Steel/Metal Deck/Concrete Toppin | g Roof | 7 | 6,110 | SF | \$0 | |
| Superstructure | | Steel with Clay Tile Arch | Entire Building | 7 | 23,246 | SF | \$0 | |
| Walls | | Brick | Entire Building | 6 | 8,931 | SF | \$59,004 | efflorescence staining under sills throughout |
| Walls | | Stone - Cut | Entire Building | 6 | 1,261 | SF | \$18,032 | |
| Windows | | Skylite - Glass Single-Pane | Upper Roof | 5 | 15 | SF | \$906 | cracked glass, putty cracking, corroding |
| Windows | | Window - Guards perforated | Entire Building | 6 | 402 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 5 | 975 | SF | \$33,671 | per engineer: balance issues, windows are difficult to open |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 6 | 1,464 | SF | \$12,561 | |
| - | | | EXTERIOR | Sub To | tal | | \$297.350 | |

EXTERIOR Sub Total \$297,350

Building: Addition Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason | |
|------------------|-----------|--|-----------------|------|----------|------|-------------|--|
| Emergency System | | Emergency A/C power - Corridors and Stairs | Entire Building | 7 | 2,864 | SF | \$0 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | 1st Floor | 7 | 2 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | 2nd Floor | 7 | 2 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | 3rd Floor | 7 | 2 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | 2nd Floor | 7 | 2 | EA | \$ 0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | 1st Floor | 7 | 2 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | 3rd Floor | 7 | 2 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Basement | 7 | 11 | EA | \$ 0 | |
| Main Service | | Main Electrical service 1600 A 120/208/3PH | Electrical Room | 7 | 1 | EA | \$ 0 | |





Building: Addition Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank Qu | uantity | Unit | Cost Reason | |
|--------------------|-----------|--|-----------------|---------------|---------|------|-------------|--|
| Power Distribution | | Main distribution panels above 600 amp | Electrical Room | 7 | 2 | EA | \$0 | |
| | | | ELECTRI | CAL Sub Total | | | \$0 | |

Building: Addition Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason | |
|---------------------|-----------|-------------------------|-----------|--------------|----------|------|-------------|--|
| Air Conditioning | | Window A/C Unit | 3rd Floor | 7 | 6 | EA | \$0 | |
| Air Conditioning | | Window A/C Unit | 2nd Floor | 7 | 6 | EA | \$0 | |
| Air Conditioning | | Window A/C Unit | 1st Floor | 7 | 6 | EA | \$0 | |
| Air Conditioning | | Window A/C Unit | Basement | 7 | 3 | EA | \$0 | |
| Heating Devices | | Wall Heater - Electric | Basement | 4 | 1 | EA | \$1,030 | |
| Temperature Control | | Thermostats - Pneumatic | 2nd Floor | 7 | 3 | EA | \$0 | |
| Temperature Control | | Thermostats - Pneumatic | 3rd Floor | 7 | 3 | EA | \$0 | |
| Temperature Control | | Thermostats - Pneumatic | 1st Floor | 7 | 3 | EA | \$0 | |
| Temperature Control | | Thermostats - Pneumatic | Basement | 7 | 1 | EA | \$0 | |
| Ventilation | | Exhaust Fan - Indoor | Basement | 6 | 1 | EA | \$501 | |
| | | | MECHANI | ICAL Sub Tot | al | | \$1,530 | |

Building: Addition Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------|-----------|--|----------|-----------------|----------|------|-----------|--------|
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Kitchen | 5 | 23,246 | SF | \$3,989 | |
| Piping | | Domestic Piping - Cold Water Risers | Kitchen | 5 | 23,246 | SF | \$7,646 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Kitchen | 5 | 23,246 | SF | \$26,593 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Kitchen | 5 | 23,246 | SF | \$4,986 | |
| Piping | | Domestic Piping - Hot Water Risers | Kitchen | 5 | 23,246 | SF | \$5,984 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Kitchen | 5 | 23,246 | SF | \$20,610 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Kitchen | 5 | 23,246 | SF | \$12,299 | |
| Piping | | Domestic Piping Hot Water Return Lines | Kitchen | 5 | 23,246 | SF | \$12,632 | |
| Piping | | Sanitary Piping | Kitchen | 5 | 23,246 | SF | \$14,294 | |
| Piping | | Storm Piping | Kitchen | 7 | 23,246 | SF | \$0 | |
| Piping | | Vent Piping | Kitchen | 7 | 23,246 | SF | \$0 | |
| | | | | PLUMBING Sub To | tal | | \$109,033 | |





Building: Addition Category: INTERIOR

Group Sub Group Item Location Rank Quantity Unit Cost Reason

Building: Addition Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|--------------------------|-----------------|-----------------------------------|-------------------------------------|---------|----------|------|-------------|
| Doors | | Interior Steel Doors incl hw | Entire Building | 6 | 12 | EA | \$3,398 |
| Doors | | Interior Wood Doors incl hw | Entire Building | 6 | 6 | EA | \$1,699 |
| Doors | | Interior Wood Doors incl hw | Entire Building | 5 | 9 | EA | \$4,247 |
| Doors | | Transom Window | Entire Building | 7 | 81 | SF | \$0 |
| Kitchen | Warming Kitchen | Ceiling - Lay-In | Basement Serving Area | 6 | 420 | SF | \$1,201 |
| Kitchen | Warming Kitchen | Ceiling - Plaster/Drywall | Basement | 6 | 586 | SF | \$2,212 |
| Kitchen | Warming Kitchen | Flooring - Tile Ceramic/Porcelain | Basement | 6 | 586 | SF | \$1,492 |
| Kitchen | Warming Kitchen | Flooring - Tile/Sheet | Basement Serving Area | 5 | 420 | SF | \$2,378 |
| Kitchen | Warming Kitchen | Lighting - Lay-In | Basement Serving Area | 6 | 10 | SF | \$7 |
| Kitchen | Warming Kitchen | Lighting - Pendant/Surface | Basement | 7 | 13 | SF | \$0 |
| Kitchen | Warming Kitchen | Wall - Concrete Block | Basement Serving Area | 7 | 167 | SF | \$0 |
| Lunchroom | Lunchroom | Ceiling - Lay-In | Basement | 6 | 906 | SF | \$1,943 |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Basement | 5 | 906 | SF | \$5,130 |
| Lunchroom | Lunchroom | Lighting - Lay-In | Basement | 6 | 15 | SF | \$11 |
| Lunchroom | Warming Kitchen | Serving Line | Basement | | | LF | \$0 |
| Lunchroom | Warming Kitchen | Serving Line | Basement Serving Area | | | LF | \$0 |
| Lunchroom | Lunchroom | Serving Line | Basement | | | LF | \$0 |
| Lunchroom | Lunchroom | Wall - Concrete Block | Basement | 7 | 120 | SF | \$0 |
| Mechanical/Service Rooms | | Storage Room | 101,102,201,202,203,301,30 2,303 | 6 | 840 | SF | \$3,964 |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 |
| | | | INTERIOR | Sub Tot | al | | \$28,455 |

Building: Addition Category: ROOM

| Group | Sub Group | Item | Location | Rank Q | uantity | Unit | Cost Reason | |
|----------|-----------|----------|----------|--------|---------|------|-------------|--|
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 4 | LF | \$143 | |
| Casework | Classroom | Casework | | 6 | 58 | LF | \$2,074 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| | | | | | | | | |



Building: Addition Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|-------------|-----------|------------------------|------------------------|------|----------|------|-------------|
| Casework | Classroom | Casework | | | | LF | \$0 |
| Casework | Classroom | Casework | | | | LF | \$0 |
| Casework | Classroom | Casework | | | | LF | \$0 |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 845 | SF | \$0 |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 845 | SF | \$0 |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 845 | SF | \$0 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 845 | SF | \$2,393 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 845 | SF | \$2,393 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 845 | SF | \$2,393 |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 845 | SF | \$0 |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 845 | SF | \$0 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 845 | SF | \$2,393 |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 845 | SF | \$2,393 |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Lunchroom | Chalk Board | Basement | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | |
| Corridors | Corridors | Concrete Block | Basement at Lunch Room | 7 | 140 | SF | \$0 |
| Corridors | Corridors | Concrete Epoxy/Painted | Basement at Lunch Room | 6 | 66 | SF | \$311 |
| Corridors | Corridors | Concrete Epoxy/Painted | South Stair | 6 | 687 | SF | \$3,242 |
| Corridors | Corridors | Concrete Epoxy/Painted | West Stair | 6 | 687 | SF | \$3,242 |
| Corridors | Corridors | Drinking Fountains | West Stair | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | South Stair Vestibule | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | South Stair | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | West stair vestibule | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | Basement at Lunch Room | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | 3rd Floor | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | 1st Floor | | | EA | \$0 |
| Corridors | Corridors | Drinking Fountains | 2nd Floor | | | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | West stair vestibule | 7 | 2 | EA | \$0 |



Building: Addition Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|-----------|-----------|------------------------|------------------------|------|----------|------|-------------|
| Corridors | Corridors | Pendant/Surface | Basement at Lunch Room | 6 | 2 | EA | \$1 |
| Corridors | Corridors | Pendant/Surface | West Stair | 7 | 6 | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 7 | 846 | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | South Stair | 7 | 6 | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | South Stair Vestibule | 7 | 2 | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | 1st Floor | 7 | 846 | EA | \$0 |
| Corridors | Corridors | Pendant/Surface | 3rd Floor | 7 | 846 | EA | \$0 |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 6 | 1,543 | SF | \$3,641 |
| Corridors | Corridors | Plaster/Drywall | South Stair | 6 | 3,805 | SF | \$8,978 |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 6 | 1,543 | SF | \$3,641 |
| Corridors | Corridors | Plaster/Drywall | 3rd Floor | 6 | 1,543 | SF | \$3,641 |
| Corridors | Corridors | Plaster/Drywall | West Stair | 6 | 3,605 | SF | \$8,506 |
| Corridors | Corridors | Plaster/Drywall | South Stair Vestibule | 6 | 360 | SF | \$849 |
| Corridors | Corridors | Stair Handrails | West Stair | 6 | 156 | LF | \$0 |
| Corridors | Corridors | Stair Handrails | 3rd Floor | | | LF | \$0 |
| Corridors | Corridors | Stair Handrails | 2nd Floor | | | LF | \$0 |
| Corridors | Corridors | Stair Handrails | 1st Floor | | | LF | \$0 |
| Corridors | Corridors | Stair Handrails | West stair vestibule | | | LF | \$0 |
| Corridors | Corridors | Stair Handrails | Basement at Lunch Room | 6 | 10 | LF | \$0 |
| Corridors | Corridors | Stair Handrails | South Stair Vestibule | | | LF | \$0 |
| Corridors | Corridors | Stair Handrails | South Stair | 6 | 156 | LF | \$0 |
| Corridors | Corridors | Stairs | South Stair Vestibule | | | EA | \$0 |
| Corridors | Corridors | Stairs | 2nd Floor | | | EA | \$0 |
| Corridors | Corridors | Stairs | 3rd Floor | | | EA | \$0 |
| Corridors | Corridors | Stairs | West stair vestibule | | | EA | \$0 |
| Corridors | Corridors | Stairs | Basement at Lunch Room | 5 | 3 | EA | \$150 |
| Corridors | Corridors | Stairs | 1st Floor | | | EA | \$0 |
| Corridors | Corridors | Structural Glazed Tile | Basement at Lunch Room | 5 | 140 | SF | \$6,607 |
| Corridors | Corridors | Structural Glazed Tile | West stair vestibule | 6 | 320 | SF | \$2,288 |
| Corridors | Corridors | Student Lockers | West stair vestibule | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | South Stair Vestibule | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | West Stair | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | 3rd Floor | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | 1st Floor | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | 2nd Floor | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | Basement at Lunch Room | | | EA | \$0 |
| Corridors | Corridors | Student Lockers | South Stair | | | EA | \$0 |



Building: Addition Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost Reason |
|-------------------|-----------------|------------------------|------------------------|------|----------|------|-------------|
| Corridors | Corridors | Tile Ceramic/Porcelain | West stair vestibule | 6 | 113 | SF | \$288 |
| Corridors | Corridors | Tile Ceramic/Porcelain | South Stair Vestibule | 6 | 134 | SF | \$341 |
| Corridors | Corridors | Tile/Sheet Flooring | 2nd Floor | 6 | 846 | SF | \$1,210 |
| Corridors | Corridors | Tile/Sheet Flooring | 1st Floor | 6 | 846 | SF | \$1,210 |
| Corridors | Corridors | Tile/Sheet Flooring | 3rd Floor | 6 | 846 | SF | \$1,210 |
| Corridors Ceiling | Corridors | Plaster/Drywall | 3rd Floor | 6 | 846 | SF | \$2,395 |
| Corridors Ceiling | Corridors | Plaster/Drywall | 1st Floor | 6 | 846 | SF | \$2,395 |
| Corridors Ceiling | Corridors | Plaster/Drywall | West Stair | 7 | 435 | SF | \$0 |
| Corridors Ceiling | Corridors | Plaster/Drywall | South Stair Vestibule | 6 | 134 | SF | \$379 |
| Corridors Ceiling | Corridors | Plaster/Drywall | South Stair | 7 | 551 | SF | \$0 |
| Corridors Ceiling | Corridors | Plaster/Drywall | West stair vestibule | 6 | 113 | SF | \$320 |
| Corridors Ceiling | Corridors | Plaster/Drywall | Basement at Lunch Room | 5 | 79 | SF | \$447 |
| Corridors Ceiling | Corridors | Plaster/Drywall | 2nd Floor | 6 | 846 | SF | \$2,395 |
| Stairs | Corridors | Asphalt | West Stair | 6 | 83 | SF | \$593 |
| Stairs | Corridors | Asphalt | South Stair | 6 | 83 | SF | \$593 |
| Floor | Classroom | Tile/Sheet | | 6 | 845 | SF | \$1,208 |
| Floor | Classroom | Tile/Sheet | | 6 | 845 | SF | \$1,208 |
| Floor | Classroom | Wood | | 6 | 845 | SF | \$6,380 |
| Floor | Classroom | Wood | | 6 | 845 | SF | \$6,380 |
| Floor | Classroom | Wood | | 6 | 845 | SF | \$6,380 |
| Floor | Classroom | Wood | | 6 | 845 | SF | \$6,380 |
| Floor | Classroom | Wood | | 6 | 845 | SF | \$6,380 |
| Floor | Classroom | Wood | | 6 | 845 | SF | \$6,380 |
| Floor | Classroom | Wood | | 6 | 845 | SF | \$6,380 |
| Floor | Classroom | Wood | | 6 | 845 | SF | \$6,380 |
| KITCHEN_WALL | Warming Kitchen | Kitchen Walls | Basement Serving Area | 6 | 271 | SF | \$690 |
| KITCHEN_WALL | Warming Kitchen | Kitchen Walls | Basement Serving Area | 6 | 271 | SF | \$690 |
| KITCHEN_WALL | Warming Kitchen | Kitchen Walls | Basement | 6 | 950 | SF | \$2,418 |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 |
| Lighting | Classroom | Pendant/Surface | | 7 | 20 | EA | \$0 |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 |



Building: Addition Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|-----------------|----------|-------------|----------|------|-----------|--------|
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| LUNCH_WALL | Lunchroom | Lunchroom Walls | Basement | 6 | 462 | SF | \$1,321 | |
| LUNCH_WALL | Lunchroom | Lunchroom Walls | Basement | 6 | 191 | SF | \$546 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Lunchroom | Marker Board | Basement | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 50 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 50 | LF | \$0 | |
| Wall | Classroom | Masonry | | 6 | 1,358 | SF | \$17,477 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,358 | SF | \$3,204 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,358 | SF | \$3,204 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,358 | SF | \$3,204 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,358 | SF | \$3,204 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,358 | SF | \$3,204 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,358 | SF | \$3,204 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,358 | SF | \$3,204 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,358 | SF | \$3,204 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,358 | SF | \$3,204 | |
| | | | RO | OOM Sub Tot | al | | \$178,492 | |

Building Addition Sub Total \$614,860

Building: SITE Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|--------------|------------------------------|------|----------|------|---------|--|
| Civil/Drainage | | Catch Basin | Entire Site | 7 | 4 | EA | \$0 | |
| Civil/Drainage | | Catch Basin | N playground and parking lot | 5 | 2 | EA | \$2,431 | per engineer: these areas flood during heavy downpours |
| Civil/Drainage | | Site Manhole | Entire Site | 7 | 5 | EA | \$0 | |
| Fencing | | Chain Link | Site ¿ North | 6 | 128 | LF | \$1,836 | |





Building: SITE Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|---|--------------|-------------|----------|------|-----------|-------------------------------------|
| Fencing | | Ornamental Iron | Entire Site | 6 | 1,023 | LF | \$19,310 | |
| Fencing | | Wood Fencing w/ Steel Frame | Site ¿ North | 6 | 265 | LF | \$3,251 | |
| Field House | | Wood Frame Fieldhouse | site NW | 5 | 1,221 | SF | | rotted wood |
| Field House | | Wood Frame Fieldhouse | Site ¿ North | 6 | 1,775 | SF | | minor deterioration |
| Landscape | | Asphalt Play Area/Hardscape | Site ¿ North | 5 | 11,718 | SF | \$33,178 | cracking throughout, uneven surface |
| Landscape | | Benches | site N and S | 6 | 7 | EA | \$1,652 | |
| Landscape | | Grass | Entire Site | 7 | 16,052 | SF | \$0 | |
| Landscape | | Hardscape - Concrete | Entire Site | 6 | 2,838 | SF | \$5,357 | |
| Landscape | | Parkway trees | Entire Site | 7 | 24 | EA | \$0 | |
| Parking Lot | | Asphalt | site NW | 6 | 11,265 | SF | \$9,665 | |
| Parking Lot | | Trash Enclosure | Site ¿ North | 6 | 783 | SF | \$8,398 | |
| Playground | | Playground Equipment - School Age 5-12 | Site ¿ North | 6 | 1 | EA | \$0 | |
| Playground | | Playground Surfacing - Square Rubber Mats | Site ¿ North | 4 | 2,600 | SF | \$57,629 | |
| Sidewalks | | Perimeter Sidewalks | Entire Site | 6 | 15,147 | SF | \$28,591 | |
| Signage | | Flag Pole | Site - East | 6 | 1 | EA | \$0 | paint chipping, some corrosion |
| Signage | | Marquee - Free Standing Back Lighted | Site - East | 6 | 1 | EA | \$0 | |
| | | | | SITE Sub To | tal | | \$171,299 | |
| | | | | SITE Sub To | al | | \$171,299 | |

Total Campus Need ^{2 3} \$3,253,217

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.



John J Audubon Elementary School

3500 N Hoyne Ave Chicago, IL 60618

| Room | Room | Voice | Data | Elect | Noise | Glaze | Operable | No. of | Window | Smart | Power | Room Type | Room Sub Type | Location |
|---------------------|------|--------|------|--------|-------|--------|----------|--------|--------|-------|-------|-------------------------------|--------------------------------------|----------------------------------|
| Number | Size | Outlet | | Outlet | | Window | Window | Window | Stop | Board | Strip | rtoom rypo | rtoom oub Type | Loodiion |
| | | | | | | Area | Area | AC | | | | | | |
| Building: | Main | | | | | | | | | | | | | |
| 04 | 860 | 1 | 4 | 18 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 05 | 860 | 1 | 4 | 18 | 40 | 126 | 51 | 2 | N | N | N | Classroom | | |
| 06 | 911 | 1 | 4 | 16 | 40 | 116 | 41 | 2 | N | Υ | N | Classroom | | |
| 07 | 827 | 0 | 0 | 10 | 40 | 145 | 41 | 2 | N | N | N | Classroom | | |
| 08 | 860 | 1 | 4 | 18 | 40 | 116 | 41 | | N | Υ | N | Classroom | | |
| 09 | 860 | 1 | 4 | 18 | 40 | 126 | 51 | 2 | N | N | N | Classroom | | |
| 04 | 860 | 1 | 4 | 18 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 06 | 911 | 1 | 4 | 16 | 40 | 116 | 41 | | N | N | N | Classroom | | |
| 206A | 700 | 0 | 0 | 6 | 40 | 57 | | 1 | N | N | N | Classroom | | |
| 207 | 827 | 0 | 0 | 10 | 40 | 96 | 31 | 2 | N | N | Ν | Classroom | | |
| 208 | 860 | 1 | 4 | 18 | 40 | 116 | 41 | | N | Υ | Ν | Classroom | | |
| 09 | 860 | 1 | 4 | 18 | 40 | 126 | 51 | 2 | N | Z | Z | Classroom | | |
| 04 | 860 | 1 | 4 | 18 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 05 | 860 | 1 | 4 | 18 | 40 | 126 | 51 | 2 | N | N | N | Classroom | | |
| 08 | 860 | 1 | 4 | 18 | 40 | 126 | 51 | 2 | N | Y | Ν | Classroom | | |
| 809 | 860 | 1 | 4 | 18 | 40 | 126 | 51 | 2 | N | N | Ν | Classroom | | |
| Basement | 852 | | | 16 | 40 | 59 | 18 | 1 | N | N | Υ | Classroom | | |
| Pre-K FieldHouse | 720 | | | 4 | 40 | 70 | 35 | | N | N | Υ | Classroom | | |
| Other | 217 | | | - | 40 | 70 | 33 | | N | N | N | Restroom | Children's Standard Student Restroom | Basement Boys |
| Other | 288 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Basement Girls West |
| Other | 28 | | | | | | | | N | N | N | Restroom | Staff Restroom | Men's Basement Staff |
| Other | 340 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | 2nd Floor Boys |
| Other | 562 | | | 17 | | | | | N | N | Y | Administrative Suites/Offices | Addit Standard Stadent Nestroom | 1st Floor Main Office |
| Other | 150 | | | 8 | | | | | N | N | N | Administrative Suites/Offices | | Assistant Principal 1st Floor in |
| | 100 | | | 3 | | | | | .,, | ., | ., | | | Main Office |
| Other | 634 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | 113 | | | | | | | | N | N | N | Corridors | | East vestibule |
| Other | | | | | | | | | N | N | N | Corridors | | East Stair |
| Other | 1615 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 489 | | | 8 | | | | | N | N | Υ | Administrative Suites/Offices | | Principal's Office 1st Floor |
| Other | 822 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Basement |
| Other | 4560 | | | | | | | | N | N | N | Gymnasia | Gymnasium.Auditorium | 3rd Floor |
| ther | 2309 | | | | | | | | N | N | N | Corridors | | Basement |
| Other | 307 | | | 12 | | | | | N | N | N | Administrative Suites/Offices | | Basement Office 2 |
| Other | 363 | | | 22 | | | | | N | N | N | Administrative Suites/Offices | | Basement Office |
| Other | 340 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | 2nd Floor Girls |



John J Audubon Elementary School

3500 N Hoyne Ave Chicago, IL 60618

| Room Su | Room Summary | | | | | | | | | | | | | |
|---------|--------------|--------|--------|--------|-------|-------|----------------|--------|--------|-------|-------|-------------------------------|--------------------------------------|----------------------------|
| Room | Room | | | Elect | Noise | Glaze | Operable | No. of | Window | | | Room Type | Room Sub Type | Location |
| Number | Size | Outlet | Outlet | Outlet | Level | Area | Window Area | AC | Stop | Board | Strip | | | |
| Other | 288 | | | 10 | | | | | N | N | Υ | Administrative Suites/Offices | | Basement Engineer's Office |
| Other | 179 | | | | | | | | N | N | N | Corridors | | Basement Toilet Vestibule |
| Other | 65 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | Basement PreK East |
| Other | 498 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Basement Girls East |
| Other | 1615 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 402 | | | 10 | | | | | N | N | N | Administrative Suites/Offices | | 2nd Fl. teachers Lounge |
| Other | 57 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd Floor Teachers Lounge |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd Floor |
| Other | 164 | | | | | | | | N | N | N | Corridors | | Men's Lounge Vestibule |

| Building: Addition | | | | | | | | | | | | | | |
|--------------------|-----|---|---|----|----|-----|----|---|---|---|---|---------------------------|-----------------|------------------------|
| 001 | 845 | 1 | 8 | 60 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 101 | 845 | 1 | 8 | 60 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 102 | 845 | 1 | 8 | 60 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 103 | 845 | 0 | 0 | 10 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 201 | 845 | 1 | 8 | 60 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 202 | 845 | 0 | 0 | 10 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 203 | 845 | 0 | 0 | 10 | 40 | 116 | 41 | 2 | N | Υ | N | Classroom | | |
| 301 | 845 | 1 | 8 | 60 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 302 | 845 | 1 | 8 | 60 | 40 | 116 | 41 | 2 | N | N | N | Classroom | | |
| 303 | 845 | 0 | 0 | 10 | 40 | 116 | 41 | 2 | N | Υ | N | Classroom | | |
| Other | 420 | | | | | | | | N | N | N | Kitchen | Warming Kitchen | Basement Serving Area |
| Other | 846 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 846 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | | | | | | | | | N | N | N | Corridors | | West Stair |
| Other | 134 | | | | | | | | N | N | N | Corridors | | South Stair Vestibule |
| Other | | | | | | | | | N | N | N | Corridors | | South Stair |
| Other | 113 | | | | | | | | N | N | N | Corridors | | West stair vestibule |
| Other | 79 | | | | | | | | N | N | N | Corridors | | Basement at Lunch Room |
| Other | 586 | | | | | | | | N | N | N | Kitchen | Warming Kitchen | Basement |
| Other | 846 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 906 | · | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Basement |