

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.

Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.

For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.

Total Campus Need also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|--|-------------------------------|------|----------|------|----------|-----------------------------------|
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Southeast corner of courtyard | 6 | 43 | LF | \$21,522 | |
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Southeast corner of courtyard | 5 | 8 | LF | \$14,300 | Bottom 8 feet requires repointing |
| Doors | | Exterior Steel Door | Entire Building | 6 | 5 | EA | \$1,652 | |
| Entrance | | Concrete Exterior Stairs | Main Entrance | 6 | 7 | LF | \$751 | |
| Foundation | | Masonry Foundation | Entire Building | 7 | 14,290 | SF | \$0 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 4 | EA | \$858 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 3 | EA | \$644 | |
| Lintels | | Lintels - Brick | Entire Building | 6 | 248 | LF | \$0 | |
| Lintels | | Lintels - Steel | Entire Building | 7 | 47 | LF | \$0 | |
| Lintels | | Lintels - Stone | Entire Building | 6 | 296 | LF | \$0 | |
| Parapet | | Coping - Metal | Roof | 6 | 730 | LF | \$0 | |
| Parapet | | Coping - Stone | Air intake north exterior | 6 | 27 | LF | \$0 | |
| Roof System | | Asphalt Shingle Roof | Roof | 6 | 18,960 | SF | \$75,102 | |

Building: Main
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|-------------------------------------|---------------------|------|----------|------|-----------|--------|
| Roof System | | Exterior Downspouts | Roof | 6 | 372 | LF | \$6,915 | |
| Roof System | | Interior Downspouts | Roof | 6 | 319 | LF | \$0 | |
| Roof System | | Metal Roof | Flat center section | 6 | 883 | SF | \$6,667 | |
| Roof System | | Roof Structure: Heavy Timber | Roof | 7 | 19,483 | SF | \$0 | |
| Superstructure | | Heavy Timber | Entire Building | 7 | 48,585 | SF | \$0 | |
| Walls | | Brick | Entire Building | 6 | 20,695 | SF | \$136,724 | |
| Walls | | Stone - Cast | Entire Building | 6 | 2,630 | SF | \$37,609 | |
| Windows | | Window - Guards perforated | 1st Floor | 6 | 513 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 6 | 5,202 | SF | \$44,633 | |

EXTERIOR Sub Total \$347,376

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------|-----------|---|----------------------|------|----------|------|----------|---|
| Emergency System | | Automatic Transfer switch | Electrical Room | 6 | 2 | EA | \$2,860 | |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Corridors and Stairs | 7 | 7,363 | SF | \$0 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | Corridors and Stairs | 6 | 58 | EA | \$6,221 | Batteries |
| Emergency System | | Emergency generator 60 to 100 KW natural gas - Outdoor | Electrical Room | 6 | 1 | EA | \$10,511 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Corridors and Stairs | 6 | 30 | EA | \$6,993 | Batteries |
| Emergency System | | Public Announcement System | Main Office | 6 | 48,585 | SF | \$29,180 | |
| Emergency System | | Security System - Intrusion detection | Electrical Room | 6 | 48,585 | SF | \$45,160 | |
| Main Service | | Main Electrical service - Live Front - 2000 to 3000 A 277/480/3PH | Electrical Room | 6 | 1 | EA | \$30,388 | |
| Power Distribution | | Lighting and power panels | Electrical Room | 6 | 19 | EA | \$13,585 | Labeling is an issue typical for all Panels |
| Power Distribution | | Lighting and power panels | Electrical Room | 4 | 2 | EA | \$10,868 | Fuses |
| Power Distribution | | Main distribution panels 400-600 amp | Electrical Room | 6 | 4 | EA | \$5,720 | |
| Power Distribution | | Main distribution panels 400-600 amp | Electrical | 6 | 4 | EA | \$5,720 | |
| Power Distribution | | Main distribution panels above 600 amp | Electrical Room | 6 | 7 | EA | \$15,015 | |
| Power Distribution | | Transformers 277/480-120/208 | Electrical Room | 6 | 4 | EA | \$4,576 | |

ELECTRICAL Sub Total \$186,795

Building: Main
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------|-----------|--------------------------|-----------------|------|----------|------|----------|--------|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 6 | 48,585 | SF | \$17,369 | |
| Fire Alarm | | Fire Alarm System | Electrical Room | 7 | 48,585 | SF | \$0 | |

Building: Main
Category: FIRE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|--|-----------------|------|----------|------|-----------------|--------|
| Fire Alarm | | Fire Pump Controller | Mechanical Room | 7 | 1 | EA | \$0 | |
| Pump Room Assembly | | Fire Pump 50-75hp | Mechanical Room | 6 | 1 | EA | \$4,648 | |
| Pump Room Assembly | | Jockey Pump | Mechanical Room | 6 | 1 | EA | \$744 | |
| Sprinkler System | | Combination Wet and Dry Sprinkler System | Entire Building | 7 | 48,585 | SF | \$0 | |
| Sprinkler System | | Sprinkler Heads | Entire Building | 7 | 48,585 | SF | \$0 | |
| FIRE PROTECTION Sub Total | | | | | | | \$22,760 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|-----------------|------|----------|------|-----------|---|
| Air Handling Systems | | Air intake for all Air Handling Units except built up AHU | north Areawell | 3 | 1 | EA | \$7,436 | Intake has been capped with a shingled roof - Limited area for air intake - System Starved for air |
| Air Handling Systems | | Fan Coil Unit - Hot Water and Chilled Water | Entire Building | 6 | 32 | EA | \$45,760 | No Communications with BAS system |
| Air Handling Systems | | Make Up Air Unit - Indoor Mounted - Hot Water 10,001 to 20,000 cfm | Mechanical Room | 3 | 1 | EA | \$47,190 | dampers are not properly function, controls do not work, 100% OA H/C unit Dampers disconnected and operating manually |
| Heating Devices | | Cabinet Heaters With Hot Water Coils | Entire Building | 6 | 2 | EA | \$1,001 | No Communications with BAS system |
| Heating Devices | | Fin Tube Hot Water | Entire Building | 6 | 80 | LF | \$1,373 | No Communications with BAS system |
| Heating Devices | | Unit Heater - Electric | Electrical Room | 6 | 2 | EA | \$2,860 | |
| Mechanical Plumbing | | Piping - Hydronic Supply and Return - Steel or Galvanized | Entire Building | 7 | 300 | LF | \$0 | |
| Temperature Control | | Direct Digital Control (DDC) System | Entire Building | 3 | 48,585 | SF | \$486,336 | Controls 12 Yrs Old but only few of the controls work (most damper and valve actuators are not working, not all sensors are responding, most dampers and valves are operating in manual mode, temperatures are not maintained). |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | Entire Building | 4 | 32 | EA | \$29,744 | System is not communicating for any Terminals, AHU or MUA's. |
| Ventilation | | Exhaust Fan - Indoor | Entire Building | 6 | 2 | EA | \$1,001 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|----------|------|----------|------|------------------|-------------------------------|
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 5 | 6 | EA | \$9,009 | Requires Boom lift to service |
| Ventilation | | Exhaust Fans - Roof mounted less than 500 CFM | Roof | 5 | 1 | EA | \$1,030 | Requires Boom lift to service |
| MECHANICAL Sub Total | | | | | | | \$632,739 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|--|-----------------|------|----------|------|------------------|--------|
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 6 | 48,585 | SF | \$5,558 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 6 | 48,585 | SF | \$7,642 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 6 | 48,585 | SF | \$7,642 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 6 | 48,585 | SF | \$7,642 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 6 | 48,585 | SF | \$7,642 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 6 | 48,585 | SF | \$11,116 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 6 | 48,585 | SF | \$9,727 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 6 | 48,585 | SF | \$7,642 | |
| Piping | | Sanitary Piping | Entire Building | 4 | 48,585 | SF | \$46,549 | |
| Piping | | Vent Piping | Entire Building | 4 | 48,585 | SF | \$27,791 | |
| Pumps | | Domestic Booster Pump simplex | Mechanical Room | 7 | 1 | EA | \$0 | |
| PLUMBING Sub Total | | | | | | | \$138,953 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|---------------------------|--|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Basement to south of room with plan number 23 | 6 | 729 | SF | \$1,564 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Basement SW corner east of sprinkler room | 6 | 397 | SF | \$852 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Basement at east end | 6 | 788 | SF | \$1,690 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Basement across hallway from fan room staff lounge | 6 | 548 | SF | \$1,552 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Basement next to staff lounge | 6 | 240 | SF | \$680 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Basement across hallway from fan room staff lounge | 5 | 548 | SF | \$1,959 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Basement SW corner east of sprinkler room | 5 | 397 | SF | \$1,419 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|-------------------------------|------------------------------|--|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement at east end | 6 | 788 | SF | \$1,127 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement next to staff lounge | 6 | 240 | SF | \$343 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement to south of room with plan number 23 | 6 | 729 | SF | \$1,042 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Basement at east end | 6 | 16 | SF | \$11 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Basement across hallway from fan room staff lounge | 6 | 9 | SF | \$6 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Basement to south of room with plan number 23 | 6 | 12 | SF | \$9 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Basement SW corner east of sprinkler room | 6 | 7 | SF | \$5 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Basement across hallway from fan room staff lounge | 6 | 3 | SF | \$2 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Basement next to staff lounge | 6 | 3 | SF | \$2 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Basement across hallway from fan room staff lounge | 6 | 420 | SF | \$1,201 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Basement next to staff lounge | 6 | 376 | SF | \$1,075 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement next to staff lounge | 6 | 376 | SF | \$887 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement to south of room with plan number 23 | 6 | 972 | SF | \$2,293 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement across hallway from fan room staff lounge | 6 | 420 | SF | \$991 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement at east end | 6 | 894 | SF | \$2,109 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement SW corner east of sprinkler room | 6 | 651 | SF | \$1,536 | |
| Doors | | Interior Steel Doors incl hw | 3rd Floor | 6 | 10 | EA | \$2,831 | |
| Doors | | Interior Steel Doors incl hw | Basement | 6 | 26 | EA | \$7,362 | |
| Doors | | Interior Steel Doors incl hw | 2nd Floor | 6 | 22 | EA | \$6,229 | |
| Doors | | Interior Steel Doors incl hw | 1st Floor | 6 | 21 | EA | \$5,946 | |
| Drinking Fountains | Corridors | Double Fountain | 2nd Floor | 7 | 1 | EA | \$0 | |
| Drinking Fountains | Corridors | Double Fountain | 1st Floor | 7 | 1 | EA | \$0 | |
| Library | Library | Casework | 3rd Floor | 6 | 73 | LF | \$2,239 | |
| Library | Library | Flooring Carpet | 3rd Floor | 6 | 6,129 | SF | \$8,764 | |
| Library | Library | Lighting - Pendant/ Surface | 3rd Floor | 6 | 75 | SF | \$54 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | First floor, east end | 6 | 74 | SF | \$349 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|----------------------------------|-----------------------------------|-----------------------------------|------|----------|------|---------|--------|
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement | 6 | 2,051 | SF | \$9,679 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement elevator machine room | 6 | 109 | SF | \$514 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement SW corner sprinkler room | 6 | 433 | SF | \$2,043 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Second floor, east end | 6 | 74 | SF | \$349 | |
| Mechanical/Service Rooms | | Storage Room | 2nd floor next to room A208 | 6 | 102 | SF | \$481 | |
| Mechanical/Service Rooms | | Storage Room | 2nd floor next to room A207 | 6 | 102 | SF | \$481 | |
| Mechanical/Service Rooms | | Storage Room | 2nd floor inside room A204 | 6 | 175 | SF | \$826 | |
| Mechanical/Service Rooms | | Storage Room | 2nd floor next to room A203 | 6 | 175 | SF | \$826 | |
| Mechanical/Service Rooms | | Storage Room | First floor, Inside room 104 | 6 | 113 | SF | \$533 | |
| Mechanical/Service Rooms | | Storage Room | 2nd floor next to room A202 | 6 | 175 | SF | \$826 | |
| Mechanical/Service Rooms | | Storage Room | Basement next to staff lounge | 6 | 240 | SF | \$1,133 | |
| Mechanical/Service Rooms | | Storage Room | A101 | 6 | 830 | SF | \$3,917 | |
| Mechanical/Service Rooms | | Storage Room | 2nd floor next to room A201 | 6 | 175 | SF | \$826 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | A101 | 6 | 46 | SF | \$355 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | A103 | 6 | 43 | SF | \$332 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | A105 | 6 | 43 | SF | \$332 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | A102 | 6 | 43 | SF | \$332 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Plaster/Drywall | A102 | 6 | 43 | SF | \$122 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Plaster/Drywall | A105 | 6 | 56 | SF | \$159 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Plaster/Drywall | A103 | 6 | 43 | SF | \$122 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Plaster/Drywall | A101 | 6 | 46 | SF | \$130 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | A101 | 6 | 1 | EA | \$300 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | A105 | 6 | 1 | EA | \$300 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | A103 | 6 | 1 | EA | \$300 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | A102 | 6 | 1 | EA | \$300 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | A103 | 7 | 43 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------|----------------------------------|-------------------------------------|-----------------|------|----------|------|----------|--------|
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | A105 | 7 | 56 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | A101 | 7 | 46 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | A102 | 7 | 43 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Pendant/ Surface | A101 | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Pendant/ Surface | A102 | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Pendant/ Surface | A105 | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Pendant/ Surface | A103 | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | A101 | 6 | 252 | SF | \$595 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | A105 | 6 | 297 | SF | \$701 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | A102 | 6 | 342 | SF | \$807 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | A103 | 6 | 243 | SF | \$573 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Tile Ceramic/ Porcelain | A103 | 7 | 104 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Tile Ceramic/ Porcelain | A105 | 7 | 132 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Tile Ceramic/ Porcelain | A102 | 7 | 152 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Tile Ceramic/ Porcelain | A101 | 7 | 112 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | A103 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | A105 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | A102 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | A101 | 6 | 1 | EA | \$372 | |
| Vertical Conveyance | | Elevator - Roped Holeless Hydraulic | Entire Building | 6 | 1 | EA | \$17,160 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 2 | EA | \$772 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 2 | EA | \$772 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 2 | EA | \$772 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 2 | EA | \$772 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|------|----------|------|----------|------|------------------|--------|
| INTERIOR Sub Total | | | | | | | \$106,062 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 6 | 36 | LF | \$1,287 | |
| Casework | Classroom | Casework | | 6 | 32 | LF | \$1,144 | |
| Casework | Classroom | Casework | | 6 | 24 | LF | \$858 | |
| Casework | Classroom | Casework | | 6 | 36 | LF | \$1,287 | |
| Casework | Classroom | Casework | | 6 | 24 | LF | \$858 | |
| Casework | Classroom | Casework | | 6 | 32 | LF | \$1,144 | |
| Casework | Classroom | Casework | | 6 | 26 | LF | \$930 | |
| Casework | Classroom | Casework | | 6 | 17 | LF | \$608 | |
| Casework | Classroom | Casework | | 6 | 36 | LF | \$1,287 | |
| Casework | Classroom | Casework | | 6 | 32 | LF | \$1,144 | |
| Casework | Classroom | Casework | | 6 | 32 | LF | \$1,144 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 60 | LF | \$2,145 | |
| Casework | Classroom | Casework | | 6 | 53 | LF | \$1,895 | |
| Casework | Classroom | Casework | | 6 | 60 | LF | \$2,145 | |
| Ceiling | Classroom | Lay-In/Drop | | 5 | 824 | SF | \$4,666 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 851 | SF | \$2,410 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,017 | SF | \$2,880 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 853 | SF | \$2,415 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 883 | SF | \$2,500 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 875 | SF | \$2,477 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 903 | SF | \$2,557 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 846 | SF | \$2,395 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 903 | SF | \$2,557 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 986 | SF | \$2,792 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 866 | SF | \$2,452 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 866 | SF | \$2,452 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 866 | SF | \$2,452 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 853 | SF | \$2,415 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 875 | SF | \$2,477 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 16 | LF | \$1,945 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|---------------------|-----------------------------|------|----------|------|----------|--------|
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Corridors | Corridors | Double Water Cooler | Basement | 7 | 1 | EA | \$0 | |
| Corridors | Corridors | Drop/Lay-In | 3rd Floor | 6 | 698 | SF | \$1,497 | |
| Corridors | Corridors | Drop/Lay-In | Basement | 6 | 1,925 | SF | \$4,129 | |
| Corridors | Corridors | Lay-In | 3rd Floor | 6 | 698 | EA | \$499 | |
| Corridors | Corridors | Lay-In | Basement | 6 | 1,925 | EA | \$1,376 | |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 6 | 1,919 | EA | \$1,372 | |
| Corridors | Corridors | Pendant/Surface | 1st Floor | 6 | 1,919 | EA | \$1,372 | |
| Corridors | Corridors | Pendant/Surface | Entire building stair wells | 6 | 3,608 | EA | \$2,580 | |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 6 | 4,949 | SF | \$11,677 | |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 6 | 4,949 | SF | \$11,677 | |
| Corridors | Corridors | Plaster/Drywall | Entire building stair wells | 6 | 10,756 | SF | \$25,379 | |
| Corridors | Corridors | Plaster/Drywall | Basement | 6 | 4,441 | SF | \$10,479 | |
| Corridors | Corridors | Plaster/Drywall | 3rd Floor | 6 | 1,170 | SF | \$2,761 | |
| Corridors | Corridors | Stair Handrails | Entire building stair wells | 6 | 440 | LF | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | Basement | 6 | 1,925 | SF | \$2,753 | |
| Corridors | Corridors | Tile/Sheet Flooring | 3rd Floor | 6 | 698 | SF | \$998 | |
| Corridors | Corridors | Tile/Sheet Flooring | 2nd Floor | 6 | 1,919 | SF | \$2,744 | |
| Corridors | Corridors | Tile/Sheet Flooring | 1st Floor | 6 | 1,919 | SF | \$2,744 | |
| Corridors | Corridors | Tile/Sheet Flooring | Entire building stair wells | 6 | 902 | SF | \$1,290 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 2nd Floor | 6 | 1,919 | SF | \$5,433 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 1st Floor | 6 | 1,919 | SF | \$5,433 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Entire building stair wells | 6 | 3,608 | SF | \$10,216 | |
| Stairs | Corridors | Tile | Entire building stair wells | 6 | 216 | SF | \$1,631 | |
| Floor | Classroom | Concrete | | 6 | 903 | SF | \$4,261 | |
| Floor | Classroom | Tile/Sheet | | 6 | 866 | SF | \$1,238 | |
| Floor | Classroom | Tile/Sheet | | 6 | 824 | SF | \$1,178 | |
| Floor | Classroom | Tile/Sheet | | 6 | 875 | SF | \$1,251 | |
| Floor | Classroom | Tile/Sheet | | 6 | 883 | SF | \$1,263 | |
| Floor | Classroom | Tile/Sheet | | 6 | 853 | SF | \$1,220 | |
| Floor | Classroom | Tile/Sheet | | 6 | 866 | SF | \$1,238 | |
| Floor | Classroom | Tile/Sheet | | 6 | 851 | SF | \$1,217 | |
| Floor | Classroom | Tile/Sheet | | 6 | 875 | SF | \$1,251 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,017 | SF | \$1,454 | |
| Floor | Classroom | Tile/Sheet | | 6 | 846 | SF | \$1,210 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------|-----------|-----------------|-----------|------|----------|------|----------|--------------------------------|
| Floor | Classroom | Tile/Sheet | | 6 | 903 | SF | \$1,291 | |
| Floor | Classroom | Tile/Sheet | | 6 | 853 | SF | \$1,220 | |
| Floor | Classroom | Tile/Sheet | | 6 | 986 | SF | \$1,410 | |
| Floor | Classroom | Tile/Sheet | | 6 | 866 | SF | \$1,238 | |
| LIBRARY_CEILING | Library | Exposed | 3rd Floor | 6 | 6,129 | SF | \$11,569 | |
| LIBRARY_WALL | Library | Plaster/Drywall | 3rd Floor | 6 | 4,765 | | \$11,243 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 17 | EA | \$1,216 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 17 | EA | \$1,216 | 1 bad ballast southeast corner |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 15 | EA | \$1,073 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |
| Marker Board | Classroom | Marker Board | | 6 | 8 | LF | \$229 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |
| Marker Board | Classroom | Marker Board | | 6 | 10 | LF | \$286 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,356 | SF | \$3,199 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,356 | SF | \$3,199 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 2,457 | SF | \$5,797 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------------|-----------|-----------------|----------|------|----------|------|--------------------|--------|
| Wall | Classroom | Plaster/Drywall | | 6 | 1,376 | SF | \$3,247 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,444 | SF | \$3,407 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,356 | SF | \$3,199 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 847 | SF | \$1,998 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,356 | SF | \$3,199 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,420 | SF | \$3,350 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,356 | SF | \$3,199 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 2,278 | SF | \$5,375 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,377 | SF | \$3,249 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,392 | SF | \$3,284 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,385 | SF | \$3,268 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,356 | SF | \$3,199 | |
| ROOM Sub Total | | | | | | | \$291,454 | |
| Building Main Sub Total | | | | | | | \$1,726,140 | |

Building: Addition 1
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------|-----------|---|------------------|------|----------|------|-----------|--------|
| Chimney | | Brick Chimney - Stainless Steel Liner | Roof | 6 | 51 | LF | \$25,526 | |
| Chimney | | Metal Flue | Roof | 6 | 10 | LF | \$644 | |
| Cornice | | Cornice - Cast Stone | Entire Building | 6 | 352 | LF | \$18,936 | |
| Doors | | Exterior Steel Door | Entire Building | 6 | 18 | EA | \$5,946 | |
| Entrance | | Concrete Exterior Stairs | Entire Building | 6 | 120 | LF | \$12,870 | |
| Entrance | | Concrete Ramp | East Entrances | 6 | 14 | LF | \$1,952 | |
| Entrance | | Ramp Handrails | East Entrances | 6 | 32 | LF | \$0 | |
| Entrance | | Stair Handrails | Entire Building | 6 | 39 | LF | \$0 | |
| Foundation | | Concrete Foundation | Entire Building | 7 | 499 | LF | \$0 | |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Southwest corner | 6 | 1 | EA | \$501 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 5 | EA | \$1,073 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 7 | EA | \$1,502 | |
| Lintels | | Lintels - Steel | Entire Building | 7 | 628 | LF | \$0 | |
| Lintels | | Lintels - Stone | North Façade | 4 | 14 | LF | \$9,409 | |
| Parapet | | Coping - Stone | Roof | 6 | 803 | LF | \$0 | |
| Parapet | | Parapet < 16" Height | Roof | 6 | 50 | LF | \$7,786 | |
| Parapet | | Parapet > 30" Height | Roof | 6 | 513 | LF | \$133,147 | |

Building: Addition 1
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|---|-----------------|------|----------|------|------------------|--------|
| Parapet | | Parapet 16" to 30" Height | Roof | 6 | 240 | LF | \$49,833 | |
| Roof System | | Interior Downspouts | Roof | 6 | 319 | LF | \$0 | |
| Roof System | | Modified Bitumen Roof | Roof | 6 | 18,450 | SF | \$130,598 | |
| Roof System | | Roof Structure: Steel with Clay Tile Arch | Roof | 7 | 18,450 | SF | \$0 | |
| Superstructure | | Steel with Clay Tile Arch | Entire Building | 7 | 59,963 | SF | \$0 | |
| Walls | | Brick | Entire Building | 6 | 25,558 | SF | \$168,851 | |
| Walls | | Brick | Boiler Room | 5 | 588 | SF | \$13,319 | |
| Walls | | Stone - Cast | Entire Building | 6 | 2,417 | SF | \$34,563 | |
| Windows | | Window - Guards perforated | 1st Floor | 6 | 848 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 6 | 5,421 | SF | \$46,512 | |
| EXTERIOR Sub Total | | | | | | | \$662,967 | |

Building: Addition 1
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|----------------------|------|----------|------|------------------|--|
| Emergency System | | Emergency A/C power - Auditorium and aisle lighting | Auditorium | 3 | 4,825 | SF | \$33,464 | A number of the emergency lights do not work and/or lights are not provided in all areas |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Corridors and Stairs | 6 | 9,233 | SF | \$3,961 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Lunch Room | 6 | 2,992 | SF | \$1,583 | |
| Emergency System | | Emergency A/C power - Students Toilets | Student Toilets | 6 | 2,938 | SF | \$1,260 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | Corridors and stairs | 6 | 28 | EA | \$3,003 | Batteries |
| Emergency System | | Emergency Battery Packs - Lunchroom and Gym | Lunch Room | 6 | 4 | EA | \$429 | Batteries |
| Emergency System | | Exit Signs - Auditorium | Auditorium | 6 | 12 | EA | \$2,797 | Batteries |
| Emergency System | | Exit Signs - Corridors and Stairs | Corridors and Stairs | 6 | 9 | EA | \$2,098 | Batteries |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | Lunch Room | 2 | 1 | EA | \$930 | not provided in all areas |
| Emergency System | | Public Announcement System | Entire Building | 7 | 59,963 | SF | \$0 | |
| Emergency System | | Security System - Intrusion detection | Entire Building | 6 | 59,963 | SF | \$55,736 | |
| Power Distribution | | Main distribution panels 400-600 amp | Boiler Room | 6 | 6 | EA | \$8,580 | |
| ELECTRICAL Sub Total | | | | | | | \$113,840 | |

Building: Addition 1
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------|-----------|--------------------------|-----------------|------|----------|------|----------|--------|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 6 | 59,963 | SF | \$21,437 | |
| Sprinkler System | | Wet Sprinkler System | Entire Building | 7 | 59,963 | SF | \$0 | |

Building: Addition 1
Category: FIRE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|------|----------|------|----------|------|-----------------|--------|
| FIRE PROTECTION Sub Total | | | | | | | \$21,437 | |

Building: Addition 1
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|-------------------------|------|----------|------|-----------|--|
| Air Conditioning | | Chillers - Air Cooled - Screw Type - Ground Mounted greater than 200 tons | Courtyard | 5 | 2 | EA | \$572,000 | Extensive Fin Damage - Hail or Vandilism |
| Air Conditioning | | Condensing Unit - Ground Mounted less than 5 tons | South Façade | 7 | 1 | EA | \$0 | |
| Air Handling Systems | | Air Handling Unit Package - Single Zone - Hot Water 12,001 to 20,000 cfm | Mechanical Room | 6 | 1 | EA | \$7,579 | |
| Air Handling Systems | | Air intake for all Air Handling Units except built up AHU | South Courtyard Façades | 6 | 2 | EA | \$2,860 | |
| Air Handling Systems | | Air intake for all Air Handling Units except built up AHU | Exterior Facade | 6 | 3 | EA | \$4,290 | |
| Air Handling Systems | | Fan Coil Unit - Hot Water and Chilled Water | Entire Building | 6 | 29 | EA | \$41,470 | No Communications with BAS system |
| Air Handling Systems | | Make Up Air Unit - Indoor Mounted - Hot Water 10,001 to 20,000 cfm | Mechanical Room | 3 | 1 | EA | \$47,190 | dampers are not properly function, controls do not work,100% OA Air. Dampers disconnected - Controlled manually |
| Air Handling Systems | | Make Up Air Unit - Indoor Mounted - Hot Water less than 6000 cfm | Kitchen | 6 | 1 | EA | \$2,002 | Heating Only |
| Boiler Systems | | Boiler Assembly - Non-Condensing Scotch Marine Hot Water Boiler 3,001MBH-4,000 MBH | Boiler Room | 6 | 2 | EA | \$37,180 | |
| Boiler Systems | | Boiler Auxiliary Non-Condensing Hot Water Boiler 3,001MBH-4,000 MBH | Boiler Room | 7 | 2 | EA | \$0 | |
| Boiler Systems | | Chemical Pot Feeder - Hot Water | Boiler Room | 7 | 2 | EA | \$0 | |
| Boiler Systems | | Combustion Dampers | Boiler Room | 2 | 3 | EA | \$16,731 | Boiler cannot be properly fired due to lack of combustion air (combustion is provided by a make-up air unit and the unit is inoperable, combustion dampers are closed) |
| Boiler Systems | | Glycol Feed System | Boiler Room | 6 | 1 | EA | \$1,087 | |
| Heating Devices | | Cabinet Heaters With Hot Water Coils | Entire Building | 6 | 5 | EA | \$2,503 | |
| Heating Devices | | Fin Tube Hot Water | Entire Building | 6 | 55 | LF | \$944 | No Communications with BAS system |
| Heating Devices | | Unit Heater - Electric | Boiler Room | 7 | 7 | EA | \$0 | |

Building: Addition 1
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------|-----------|---|-----------------|------|----------|------|-----------|---|
| Mechanical Plumbing | | Piping - Hydronic Supply and Return - Steel or Galvanized | Entire Building | 7 | 600 | LF | \$0 | |
| Mechanical Plumbing | | Pumps - Chilled Water 10 to 20 HP | Boiler Room | 6 | 2 | EA | \$5,148 | Insulation is damaged and missing at pumps |
| Mechanical Plumbing | | Pumps - Dual Temperature Water 21 - 50 HP | Boiler Room | 6 | 2 | EA | \$11,440 | Insulation damaged and missing at pumps |
| Mechanical Plumbing | | Pumps - Hot Water 11 to 20 HP | Boiler Room | 6 | 4 | EA | \$10,296 | |
| Temperature Control | | Direct Digital Control (DDC) System | Entire Building | 3 | 59,963 | SF | \$600,230 | Controls 12 Yrs Old but only few of the controls work (most damper and valve actuators are not working, not all sensors are responding, most dampers and valves are operating in manual mode, temperatures are not maintained). |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | Entire Building | 4 | 29 | EA | \$26,956 | System is not communicating for any Terminals, AHU or MUA's. |
| Ventilation | | Exhaust Fan - Indoor | Lower Roof | 2 | 1 | EA | \$5,577 | Fans were inoperative during boiler and Water Heater operation. |
| Ventilation | | Exhaust Fan - Indoor | Entire Building | 6 | 3 | EA | \$1,502 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 6 | 4 | EA | \$1,716 | |
| Ventilation | | Exhaust Fans - Roof mounted less than 500 CFM | Roof | 6 | 2 | EA | \$315 | |
| Ventilation | | Type I Exhaust Hood - Kitchen or Culinary Arts | Kitchen | 2 | 1 | EA | \$26,884 | Kitchen equipment are located outside the hood. Equipment protrude from the Front of the hood - Elec Equip is outside of the hood but a non issue. |
| Ventilation | | Type II Exhaust Hood - Warming Kitchen | Kitchen | 7 | 1 | EA | \$0 | |

MECHANICAL Sub Total \$1,425,897

Building: Addition 1
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------|-----------|--|-----------------|------|----------|------|---------|--------|
| Hot Water | | Hot Water Heater - Gas 150,000 -300,000 BTU/HR | Boiler Room | 6 | 2 | EA | \$8,294 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 6 | 59,963 | SF | \$6,860 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 6 | 59,963 | SF | \$9,432 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 6 | 59,963 | SF | \$9,432 | |

Building: Addition 1
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|---|-----------------|------|----------|------|------------------|--------|
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 6 | 59,963 | SF | \$9,432 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 6 | 59,963 | SF | \$9,432 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 6 | 59,963 | SF | \$13,720 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 6 | 59,963 | SF | \$12,005 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 6 | 59,963 | SF | \$9,432 | |
| Piping | | Sanitary Piping | Entire Building | 5 | 59,963 | SF | \$36,871 | |
| Piping | | Storm Piping | Entire Building | 5 | 59,963 | SF | \$28,297 | |
| Piping | | Vent Piping | Entire Building | 5 | 59,963 | SF | \$21,437 | |
| PLUMBING Sub Total | | | | | | | \$174,643 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------------|-------------------------------|-----------------------------------|--|------|----------|------|-----------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Basement at west end | 6 | 285 | SF | \$611 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, Health office room B106 | 6 | 437 | SF | \$937 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile Ceramic/Porcelain | First floor, Health office room B106 | 6 | 437 | SF | \$1,112 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement at west end | 6 | 285 | SF | \$408 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, Health office room B106 | 6 | 6 | SF | \$4 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Basement at west end | 6 | 6 | SF | \$4 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Basement at west end | 6 | 147 | SF | \$420 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement at west end | 6 | 440 | SF | \$1,038 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, Health office room B106 | 6 | 856 | SF | \$2,020 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Balcony Seating | 1st Floor | 6 | 297 | EA | \$10,932 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Main Floor Seating | 1st Floor | 6 | 408 | EA | \$15,018 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Sound System | 1st Floor | 6 | 1 | EA | \$35,750 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Stage Curtains | 1st Floor | 6 | 2 | EA | \$22,651 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Stage Lighting System | 1st Floor | 6 | 1 | EA | \$114,400 | |
| Corridor | | Stair Handrails | Basement inside vestibule for auditorium | 6 | 28 | LF | \$0 | |
| Corridor | | Stairs - Terrazzo | Basement inside vestibule for auditorium | 6 | 24 | LF | \$272 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------------------------|------------------------------|--|------|----------|------|----------|--------|
| Doors | | Interior Steel Doors incl hw | Basement | 6 | 36 | EA | \$10,193 | |
| Doors | | Interior Steel Doors incl hw | 1st Floor | 6 | 23 | EA | \$6,512 | |
| Doors | | Interior Steel Doors incl hw | 3rd Floor | 6 | 13 | EA | \$3,681 | |
| Doors | | Interior Steel Doors incl hw | 2nd Floor | 6 | 19 | EA | \$5,380 | |
| Kitchen | Cooking Kitchen | Ceiling - Lay-In | Basement east of boiler room | 6 | 1,119 | SF | \$3,200 | |
| Kitchen | Cooking Kitchen | Flooring - Tile/Sheet | Basement east of boiler room | 6 | 1,119 | SF | \$1,600 | |
| Kitchen | Cooking Kitchen | Lighting - Lay-In | Basement east of boiler room | 6 | 11 | SF | \$8 | |
| Kitchen | Cooking Kitchen | Wall - Plaster/Drywall | Basement east of boiler room | 6 | 1,135 | SF | \$2,678 | |
| Lunchroom | Lunchroom | Ceiling - Lay-In | Basement | 6 | 2,150 | SF | \$4,612 | |
| Lunchroom | Lunchroom | Ceiling - Lay-In | Basement small lunchroom east of kitchen | 6 | 842 | SF | \$1,806 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Basement | 6 | 2,150 | SF | \$3,075 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Basement small lunchroom east of kitchen | 6 | 842 | SF | \$1,204 | |
| Lunchroom | Lunchroom | Lighting - Lay-In | Basement small lunchroom east of kitchen | 6 | 9 | SF | \$6 | |
| Lunchroom | Lunchroom | Lighting - Lay-In | Basement | 6 | 30 | SF | \$21 | |
| Lunchroom | Lunchroom | Serving Line | Basement | 6 | 6 | LF | \$257 | |
| Lunchroom | Lunchroom | Wall - Plaster/Drywall | Basement small lunchroom east of kitchen | 6 | 1,090 | SF | \$2,572 | |
| Lunchroom | Lunchroom | Wall - Plaster/Drywall | Basement | 6 | 1,733 | SF | \$4,089 | |
| MDF/IDF | | Finishes | First floor, inside room B104 | 6 | 155 | SF | \$528 | |
| MDF/IDF | | Ventilation and Cooling | First floor, inside room B104 | 7 | 1 | EA | \$0 | |
| Mechanical/Service Rooms | | Boiler Room | Basement | 6 | 1,788 | SF | \$8,438 | |
| Mechanical/Service Rooms | | Janitor's Closet | 1st Floor | 6 | 1 | SF | \$5 | |
| Mechanical/Service Rooms | | Janitor's Closet | 3rd Floor | 6 | 10 | SF | \$47 | |
| Mechanical/Service Rooms | | Janitor's Closet | Basement | 6 | 10 | SF | \$47 | |
| Mechanical/Service Rooms | | Janitor's Closet | 2nd Floor | 6 | 1 | SF | \$5 | |
| Mechanical/Service Rooms | | Storage Room | First floor, west end storage room | 6 | 185 | SF | \$873 | |
| Mechanical/Service Rooms | | Storage Room | A205, storage | 6 | 56 | SF | \$264 | |
| Mechanical/Service Rooms | | Storage Room | 1st floor next to auditorium | 6 | 272 | SF | \$1,284 | |
| Mechanical/Service Rooms | | Storage Room | Second Floor, storage room, west end | 6 | 185 | SF | \$873 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Second Floor, Girls | 6 | 365 | SF | \$2,819 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|------------------|--|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Accessories | First Floor, Girls | 6 | 365 | SF | \$2,819 | |
| Staff Restroom | Staff Restroom | Accessories | Second floor,East end, Women's Staff | 7 | 48 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | Second Floor, East end, Men's Staff | 7 | 48 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Basement, Boys | 6 | 343 | SF | \$2,649 | |
| Staff Restroom | Staff Restroom | Accessories | Basement women's between lunch room & auditorium | 6 | 50 | SF | \$386 | |
| Staff Restroom | Staff Restroom | Accessories | Second floor, West end, Women's Staff | 7 | 33 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | Second floor, West end, Men's Staff | 7 | 33 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | First floor, West end, Women's Staff | 7 | 33 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | First floor,East end, Women's Staff | 7 | 48 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | First Floor, Boys | 6 | 359 | SF | \$2,772 | |
| Staff Restroom | Staff Restroom | Accessories | First Floor, East end, Men's Staff | 7 | 48 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Basement, Girls | 6 | 343 | SF | \$2,649 | |
| Staff Restroom | Staff Restroom | Accessories | Basement men's between lunch room & auditorium | 6 | 50 | SF | \$386 | |
| Staff Restroom | Staff Restroom | Accessories | First floor, health office | 7 | 146 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | First floor, West end, Men's Staff | 7 | 33 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 3rd floor, Boys | 6 | 404 | SF | \$3,120 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Second Floor, Boys | 6 | 359 | SF | \$2,772 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 3rd floor, Girls | 6 | 400 | SF | \$3,089 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 3rd floor, Girls | 6 | 400 | SF | \$858 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | Second Floor, East end, Men's Staff | 7 | 48 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | Basement men's between lunch room & auditorium | 7 | 50 | SF | \$0 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|------------------|--|------|----------|------|-------|--------|
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | Basement women's between lunch room & auditorium | 7 | 50 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Basement, Girls | 6 | 343 | SF | \$736 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | First floor, health office | 7 | 146 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 3rd floor, Boys | 6 | 404 | SF | \$867 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Second Floor, Boys | 6 | 359 | SF | \$770 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | Second floor,East end, Women's Staff | 7 | 48 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | First Floor, Boys | 6 | 359 | SF | \$770 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | First floor, West end, Men's Staff | 7 | 33 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | First floor, West end, Women's Staff | 7 | 33 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | First Floor, Girls | 6 | 365 | SF | \$783 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | Second floor, West end, Women's Staff | 7 | 33 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Basement, Boys | 6 | 343 | SF | \$736 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | First Floor, East end, Men's Staff | 7 | 48 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Second Floor, Girls | 6 | 365 | SF | \$783 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | First floor,East end, Women's Staff | 7 | 48 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | Second floor, West end, Men's Staff | 7 | 33 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | Second floor,East end, Women's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | Second Floor, East end, Men's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Second Floor, Girls | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | First Floor, Girls | 6 | 1 | EA | \$300 | |
| Staff Restroom | Staff Restroom | Floor Drain | Second floor, West end, Women's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | First floor, West end, Women's Staff | 7 | 1 | EA | \$0 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|--|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Second Floor, Boys | 6 | 1 | EA | \$300 | |
| Staff Restroom | Staff Restroom | Floor Drain | First floor, West end, Men's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | First Floor, East end, Men's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | Second floor, West end, Men's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | First floor, health office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | Basement women's between lunch room & auditorium | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | Basement men's between lunch room & auditorium | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Basement, Girls | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Basement, Boys | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 3rd floor, Boys | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 3rd floor, Girls | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | First Floor, Boys | 6 | 1 | EA | \$300 | |
| Staff Restroom | Staff Restroom | Floor Drain | First floor, East end, Women's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Second floor, West end, Women's Staff | 6 | 33 | SF | \$84 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Second floor, East end, Women's Staff | 6 | 48 | SF | \$122 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Second Floor, Boys | 6 | 359 | SF | \$914 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Second Floor, Girls | 6 | 365 | SF | \$929 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Second floor, West end, Men's Staff | 6 | 33 | SF | \$84 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, West end, Women's Staff | 6 | 33 | SF | \$84 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First Floor, East end, Men's Staff | 6 | 48 | SF | \$122 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | First Floor, Boys | 6 | 359 | SF | \$914 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 3rd floor, Girls | 6 | 400 | SF | \$1,018 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|--|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 3rd floor, Boys | 6 | 404 | SF | \$1,028 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement, Boys | 6 | 343 | SF | \$873 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | First Floor, Girls | 6 | 365 | SF | \$929 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Second Floor, East end, Men's Staff | 6 | 48 | SF | \$122 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, health office | 6 | 146 | SF | \$372 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, West end, Men's Staff | 6 | 33 | SF | \$84 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, East end, Women's Staff | 6 | 48 | SF | \$122 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement, Girls | 6 | 343 | SF | \$873 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Basement men's between lunch room & auditorium | 6 | 50 | SF | \$127 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Basement women's between lunch room & auditorium | 6 | 50 | SF | \$127 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Second Floor, Boys | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | First Floor, Boys | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Basement men's between lunch room & auditorium | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Basement women's between lunch room & auditorium | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Basement, Boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 3rd floor, Boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 3rd floor, Girls | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Basement, Girls | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Second Floor, Boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Staff Restroom | Lavatory | Second Floor, East end, Men's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Second floor, East end, Women's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, health office | 7 | 1 | EA | \$0 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------------|--|------|----------|------|-------|--------|
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Second Floor, Girls | 6 | 2 | EA | \$744 | |
| Staff Restroom | Staff Restroom | Lavatory | Second floor, West end, Men's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Second floor, West end, Women's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | First Floor, Girls | 6 | 2 | EA | \$744 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, West end, Men's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | First Floor, Boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, West end, Women's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | First Floor, East end, Men's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, East end, Women's Staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 3rd floor, Boys | 6 | 6 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Basement, Boys | 6 | 6 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Basement, Girls | 6 | 6 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Basement women's between lunch room & auditorium | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Basement men's between lunch room & auditorium | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | First floor, health office | 7 | 2 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | First floor, East end, Women's Staff | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | First Floor, East end, Men's Staff | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 3rd floor, Girls | 6 | 6 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | First floor, West end, Men's Staff | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | First Floor, Girls | 6 | 6 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | First floor, West end, Women's Staff | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Second floor, West end, Women's Staff | 7 | 1 | SF | \$0 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|------------------------|--------------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Second floor, West end, Men's Staff | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Second Floor, Girls | 6 | 6 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Second Floor, Boys | 6 | 6 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Second floor,East end, Women's Staff | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Second Floor, East end, Men's Staff | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | First Floor, Boys | 6 | 6 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Second Floor, Girls | 6 | 4 | EA | \$717 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | First Floor, Boys | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Basement, Girls | 6 | 4 | EA | \$717 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Second Floor, Boys | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 3rd floor, Girls | 6 | 4 | EA | \$717 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | First Floor, Girls | 6 | 4 | EA | \$717 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 3rd floor, Boys | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Basement, Boys | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Second Floor, Boys | 6 | 3 | EA | \$1,115 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 3rd floor, Boys | 6 | 3 | EA | \$1,115 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | First Floor, Boys | 6 | 3 | EA | \$1,115 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Basement, Boys | 6 | 3 | EA | \$1,115 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | First Floor, Boys | 6 | 326 | SF | \$769 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | 3rd floor, Boys | 6 | 290 | SF | \$684 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Basement, Boys | 6 | 163 | SF | \$385 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | 3rd floor, Girls | 6 | 290 | SF | \$684 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|--------------------------------|--|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Basement, Girls | 6 | 163 | SF | \$385 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Basement women's between lunch room & auditorium | 6 | 109 | SF | \$257 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Basement men's between lunch room & auditorium | 6 | 109 | SF | \$257 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Second Floor, East end, Men's Staff | 6 | 158 | SF | \$373 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | First floor, East end, Women's Staff | 6 | 158 | SF | \$373 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Second floor, East end, Women's Staff | 6 | 158 | SF | \$373 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Second Floor, Boys | 6 | 326 | SF | \$769 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Second floor, West end, Men's Staff | 6 | 134 | SF | \$316 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Second floor, West end, Women's Staff | 6 | 134 | SF | \$316 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | First floor, West end, Women's Staff | 6 | 134 | SF | \$316 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | First floor, West end, Men's Staff | 6 | 134 | SF | \$316 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | First Floor, East end, Men's Staff | 6 | 158 | SF | \$373 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | First floor, health office | 6 | 282 | SF | \$665 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | Basement men's between lunch room & auditorium | 6 | 109 | SF | \$277 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | Basement women's between lunch room & auditorium | 6 | 109 | SF | \$277 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Basement, Girls | 6 | 488 | SF | \$1,242 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | Second Floor, East end, Men's Staff | 7 | 116 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | 3rd floor, Boys | 6 | 580 | SF | \$1,476 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | First Floor, Boys | 6 | 526 | SF | \$1,339 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | 3rd floor, Girls | 6 | 580 | SF | \$1,476 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Basement, Boys | 6 | 488 | SF | \$1,242 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|--------------------------------|---------------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | Second floor,East end, Women's Staff | 7 | 116 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Second Floor, Boys | 6 | 526 | SF | \$1,339 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Second Floor, Girls | 6 | 290 | SF | \$738 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Second Floor, Girls | 6 | 526 | SF | \$1,339 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | Second floor, West end, Men's Staff | 7 | 98 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | Second floor, West end, Women's Staff | 7 | 98 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | First floor, West end, Men's Staff | 7 | 98 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | First Floor, Girls | 6 | 290 | SF | \$738 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | First floor, health office | 7 | 208 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | First Floor, Girls | 6 | 526 | SF | \$1,339 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | First floor,East end, Women's Staff | 7 | 116 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | First Floor, East end, Men's Staff | 7 | 116 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | First floor, West end, Women's Staff | 7 | 98 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 3rd floor, Girls | 6 | 4 | EA | \$1,487 | |
| Staff Restroom | Staff Restroom | Water Closet | First floor, West end, Men's Staff | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | Second Floor, East end, Men's Staff | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Second Floor, Boys | 3 | 1 | EA | \$3,718 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Second Floor, Boys | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Second Floor, Girls | 6 | 4 | EA | \$1,487 | |
| Staff Restroom | Staff Restroom | Water Closet | Second floor, West end, Men's Staff | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | Second floor,East end, Women's Staff | 3 | 1 | EA | \$3,718 | |
| Staff Restroom | Staff Restroom | Water Closet | First floor, West end, Women's Staff | 6 | 1 | EA | \$372 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|--------------------------------------|---------------------------|--|------|----------|------|------------------|--------|
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 3rd floor, Boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | First Floor, Boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Basement, Girls | 6 | 4 | EA | \$1,487 | |
| Staff Restroom | Staff Restroom | Water Closet | Second floor, West end, Women's Staff | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Basement, Boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | First Floor, Girls | 6 | 4 | EA | \$1,487 | |
| Staff Restroom | Staff Restroom | Water Closet | Basement women's between lunch room & auditorium | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | Basement men's between lunch room & auditorium | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | First floor, health office | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | First floor, East end, Women's Staff | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | First Floor, East end, Men's Staff | 6 | 1 | EA | \$372 | |
| Theater | Auditorium - Dedicated | Ceiling - Plaster/Drywall | 1st Floor | 6 | 4,825 | SF | \$41,261 | |
| Theater | Auditorium - Dedicated | Flooring - Concrete | 1st Floor | 6 | 2,412 | SF | \$11,382 | |
| Theater | Auditorium - Dedicated | Flooring - Tile/Sheet | 1st Floor | 6 | 2,412 | SF | \$3,449 | |
| Theater | Auditorium - Dedicated | Lighting - Lay-In | 1st Floor | 6 | 35 | SF | \$40 | |
| Theater | Auditorium - Dedicated | Stage | 1st Floor | 6 | 875 | SF | \$3,716 | |
| Theater | Auditorium - Dedicated | Wall - Plaster/Drywall | 1st Floor | 6 | 5,720 | SF | \$49,078 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 4 | EA | \$1,544 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 3 | EA | \$1,158 | |
| INTERIOR Sub Total | | | | | | | \$476,447 | |

Building: Addition 1
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|----------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 6 | 32 | LF | \$1,144 | |
| Casework | Classroom | Casework | | 6 | 28 | LF | \$1,001 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |

Building: Addition 1
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|----------------------|----------|------|----------|------|----------|---------------|
| Casework | Classroom | Casework | | 6 | 28 | LF | \$1,001 | |
| Casework | Classroom | Casework | | 6 | 28 | LF | \$1,001 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 28 | LF | \$1,001 | |
| Casework | Classroom | Casework | | 6 | 28 | LF | \$1,001 | |
| Casework | Classroom | Casework | | 6 | 28 | LF | \$1,001 | |
| Casework | Classroom | Casework | | 6 | 28 | LF | \$1,001 | |
| Casework | Classroom | Casework | | 6 | 28 | LF | \$1,001 | |
| Casework | Classroom | Casework | | 6 | 28 | LF | \$1,001 | |
| Ceiling | Classroom | Ceiling | | 5 | 902 | SF | \$5,108 | |
| Ceiling | Classroom | Ceiling | | 5 | 902 | SF | \$5,108 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 816 | SF | \$1,750 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 927 | SF | \$1,988 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 919 | SF | \$1,971 | |
| Ceiling | Classroom | Lay-In/Drop | | 5 | 902 | SF | \$5,108 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 1,127 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 902 | SF | \$1,935 | |
| Ceiling | Classroom | Lay-In/Drop | | 5 | 902 | SF | \$5,108 | |
| Ceiling | Classroom | Lay-In/Drop | | 5 | 902 | SF | \$5,108 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 1,059 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 890 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 887 | SF | \$1,903 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 874 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 927 | SF | \$1,988 | Stained tiles |
| Chalk Board | Classroom | Chalk Board | | 4 | 14 | LF | \$1,702 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 14 | LF | \$1,702 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 14 | LF | \$1,702 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 14 | LF | \$1,702 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 14 | LF | \$1,702 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 14 | LF | \$1,702 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| CLASSROOM | Classroom | Eye Wash Station | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Eye Wash Station | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Science Lab Elements | | 6 | 1,127 | SF | \$25,786 | |

Building: Addition 1

Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|----------------------|-----------------------------|------|----------|------|----------|--------|
| CLASSROOM | Classroom | Science Lab Elements | | 6 | 1,059 | SF | \$24,230 | |
| CLASSROOM | Classroom | Science Lab Shower | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Science Lab Shower | | 7 | 1 | EA | \$0 | |
| Corridors | Corridors | Double Water Cooler | 1st Floor | 6 | 1 | EA | \$844 | |
| Corridors | Corridors | Double Water Cooler | 2nd Floor | 6 | 1 | EA | \$844 | |
| Corridors | Corridors | Double Water Cooler | Basement | 6 | 1 | EA | \$844 | |
| Corridors | Corridors | Double Water Cooler | 3rd Floor | 6 | 1 | EA | \$844 | |
| Corridors | Corridors | Drop/Lay-In | 1st Floor | 6 | 1,917 | SF | \$4,112 | |
| Corridors | Corridors | Drop/Lay-In | Basement | 6 | 2,365 | SF | \$5,073 | |
| Corridors | Corridors | Drop/Lay-In | 3rd Floor | 6 | 1,917 | SF | \$4,112 | |
| Corridors | Corridors | Drop/Lay-In | 2nd Floor | 6 | 1,917 | SF | \$4,112 | |
| Corridors | Corridors | Lay-In | 1st Floor | 6 | 1,917 | EA | \$1,371 | |
| Corridors | Corridors | Lay-In | 2nd Floor | 6 | 1,917 | EA | \$1,371 | |
| Corridors | Corridors | Lay-In | Basement | 6 | 1,920 | EA | \$1,373 | |
| Corridors | Corridors | Lay-In | 3rd Floor | 6 | 1,917 | EA | \$1,371 | |
| Corridors | Corridors | Pendant/Surface | Basement | 6 | 445 | EA | \$318 | |
| Corridors | Corridors | Pendant/Surface | Entire building stair wells | 6 | 4,468 | EA | \$3,195 | |
| Corridors | Corridors | Plaster/Drywall | 3rd Floor | 6 | 3,008 | SF | \$7,097 | |
| Corridors | Corridors | Plaster/Drywall | Entire building stair wells | 6 | 7,680 | SF | \$18,121 | |
| Corridors | Corridors | Plaster/Drywall | Basement | 6 | 3,623 | SF | \$8,548 | |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 6 | 3,008 | SF | \$7,097 | |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 6 | 3,008 | SF | \$7,097 | |
| Corridors | Corridors | Stair Handrails | Entire building stair wells | 6 | 300 | LF | \$0 | |
| Corridors | Corridors | Student Lockers | 3rd Floor | 6 | 104 | EA | \$14,872 | |
| Corridors | Corridors | Student Lockers | 1st Floor | 6 | 97 | EA | \$13,871 | |
| Corridors | Corridors | Student Lockers | 2nd Floor | 6 | 109 | EA | \$15,587 | |
| Corridors | Corridors | Terrazzo | 3rd Floor | 6 | 896 | SF | \$5,074 | |
| Corridors | Corridors | Terrazzo | Entire building stair wells | 6 | 4,468 | SF | \$25,301 | |
| Corridors | Corridors | Terrazzo | Basement | 6 | 445 | SF | \$2,520 | |
| Corridors | Corridors | Terrazzo | 1st Floor | 6 | 896 | SF | \$5,074 | |
| Corridors | Corridors | Terrazzo | 2nd Floor | 6 | 896 | SF | \$5,074 | |
| Corridors | Corridors | Tile/Sheet Flooring | 3rd Floor | 6 | 1,021 | SF | \$1,460 | |
| Corridors | Corridors | Tile/Sheet Flooring | 2nd Floor | 6 | 1,021 | SF | \$1,460 | |
| Corridors | Corridors | Tile/Sheet Flooring | 1st Floor | 6 | 1,021 | SF | \$1,460 | |
| Corridors | Corridors | Tile/Sheet Flooring | Basement | 6 | 2,365 | SF | \$3,382 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Basement | 6 | 445 | SF | \$1,260 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Entire building stair wells | 6 | 1,117 | SF | \$3,163 | |

Building: Addition 1
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|--------------|-----------------------------|------|----------|------|---------|--------|
| Stairs | Corridors | Terrazzo | Entire building stair wells | 6 | 144 | SF | \$1,631 | |
| Floor | Classroom | Tile/Sheet | | 6 | 902 | SF | \$1,290 | |
| Floor | Classroom | Tile/Sheet | | 6 | 927 | SF | \$1,326 | |
| Floor | Classroom | Tile/Sheet | | 6 | 927 | SF | \$1,326 | |
| Floor | Classroom | Tile/Sheet | | 6 | 816 | SF | \$1,167 | |
| Floor | Classroom | Tile/Sheet | | 6 | 919 | SF | \$1,314 | |
| Floor | Classroom | Tile/Sheet | | 5 | 1,059 | SF | \$5,997 | |
| Floor | Classroom | Tile/Sheet | | 6 | 874 | SF | \$1,250 | |
| Floor | Classroom | Tile/Sheet | | 6 | 887 | SF | \$1,268 | |
| Floor | Classroom | Tile/Sheet | | 6 | 902 | SF | \$1,290 | |
| Floor | Classroom | Tile/Sheet | | 6 | 890 | SF | \$1,273 | |
| Floor | Classroom | Tile/Sheet | | 6 | 902 | SF | \$1,290 | |
| Floor | Classroom | Tile/Sheet | | 6 | 902 | SF | \$1,290 | |
| Floor | Classroom | Tile/Sheet | | 6 | 902 | SF | \$1,290 | |
| Floor | Classroom | Tile/Sheet | | 5 | 1,127 | SF | \$6,382 | |
| Floor | Classroom | Tile/Sheet | | 6 | 902 | SF | \$1,290 | |
| Lighting | Classroom | Lay-In | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Lay-In | | 6 | 17 | EA | \$1,216 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Lay-In | | 6 | 12 | EA | \$858 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Lay-In | | 6 | 12 | EA | \$858 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |

Building: Addition 1
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 6 | 8 | LF | \$229 | |
| Marker Board | Classroom | Marker Board | | 5 | 12 | LF | \$686 | |
| Marker Board | Classroom | Marker Board | | 6 | 8 | LF | \$229 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,082 | SF | \$2,553 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 867 | SF | \$2,046 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 867 | SF | \$2,046 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 855 | SF | \$2,017 | |
| Wall | Classroom | Plaster/Drywall | | 5 | 1,017 | SF | \$4,799 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,017 | SF | \$2,400 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,017 | SF | \$2,400 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,087 | SF | \$2,565 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,057 | SF | \$2,494 | |
| Wall | Classroom | Plaster/Drywall | | 5 | 1,017 | SF | \$4,799 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,017 | SF | \$2,400 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,030 | SF | \$2,430 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,125 | SF | \$2,654 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,125 | SF | \$2,654 | |
| Wall | Classroom | Plaster/Drywall | | 5 | 1,017 | SF | \$4,799 | |

ROOM Sub Total \$387,640

Building Addition 1 Sub Total \$3,262,871

Building: Addition 2
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------|-----------|---|-----------------|------|----------|------|----------|--------|
| Doors | | Exterior Steel Door | Entire Building | 6 | 7 | EA | \$2,312 | |
| Foundation | | Concrete Foundation | Entire Building | 7 | 446 | LF | \$0 | |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Roof | 6 | 7 | EA | \$3,504 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 5 | EA | \$1,073 | |
| Lintels | | Lintels - Steel | Entire Building | 6 | 667 | LF | \$25,181 | |
| Parapet | | Coping - Stone | Roof | 6 | 497 | LF | \$0 | |

Building: Addition 2
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|---|-----------------|------|----------|------|------------------|--------|
| Parapet | | Parapet < 16" Height | Roof | 6 | 497 | LF | \$77,396 | |
| Roof System | | Interior Downspouts | Roof | 6 | 173 | LF | \$0 | |
| Roof System | | Modified Bitumen Roof | Roof | 6 | 15,637 | SF | \$110,687 | |
| Roof System | | Roof Structure: Steel/Metal Deck/Concrete Topping | Roof | 7 | 15,637 | SF | \$0 | |
| Superstructure | | Concrete | Entire Building | 7 | 38,561 | SF | \$0 | |
| Walls | | Brick | Entire Building | 6 | 20,273 | SF | \$133,936 | |
| Walls | | Stone - Cast | Entire Building | 6 | 1,100 | SF | \$15,730 | |
| Windows | | Window - Guards perforated | 1st Floor | 6 | 1,810 | SF | \$0 | |
| Windows | | Window - Guards wire guard | Gym | 6 | 621 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 6 | 5,319 | SF | \$45,637 | |
| EXTERIOR Sub Total | | | | | | | \$415,454 | |

Building: Addition 2
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|----------------------|------|----------|------|-----------------|--------------------------------------|
| Emergency System | | Emergency A/C power - Corridors and Stairs | Corridors and Stairs | 6 | 6,487 | SF | \$2,783 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Gym | 3 | 2,400 | SF | \$4,290 | lights are not provided in all areas |
| Emergency System | | Emergency A/C power - Students Toilets | Student Toilets | 6 | 1,118 | SF | \$480 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | Corridors and Stairs | 6 | 33 | EA | \$3,539 | Batteries |
| Emergency System | | Emergency Battery Packs - Lunchroom and Gym | Gym | 6 | 3 | EA | \$322 | Batteries |
| Emergency System | | Emergency Battery Packs - Toilets | Student Toilets | 6 | 6 | EA | \$644 | Batteries |
| Emergency System | | Exit Signs - Corridors and Stairs | Corridors and Stairs | 6 | 13 | EA | \$3,030 | Batteries |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | Gym | 2 | 2 | EA | \$1,859 | not provided in all areas |
| Emergency System | | Public Announcement System | Entire Building | 7 | 38,561 | SF | \$0 | |
| Emergency System | | Security System - Intrusion detection | Electrical Room | 6 | 38,561 | SF | \$35,842 | |
| Power Distribution | | Lighting and power panels | Electrical Room | 4 | 1 | EA | \$5,434 | Fuses |
| Power Distribution | | Lighting and power panels | Electrical Room | 6 | 12 | EA | \$8,580 | labeling |
| Power Distribution | | Main distribution panels 400-600 amp | Electrical Room | 6 | 4 | EA | \$5,720 | |
| ELECTRICAL Sub Total | | | | | | | \$72,523 | |

Building: Addition 2
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------|-----------|--------------------------|-----------------|------|----------|------|----------|--------|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 6 | 38,561 | SF | \$13,786 | |
| Sprinkler System | | Wet Sprinkler System | Entire Building | 7 | 38,561 | SF | \$0 | |

Building: Addition 2

Category: FIRE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|------|----------|------|----------|------|-----------------|--------|
| FIRE PROTECTION Sub Total | | | | | | | \$13,786 | |

Building: Addition 2

Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|---------------------|------|----------|------|------------------|---|
| Air Handling Systems | | Air intake for all Air Handling Units except built up AHU | West Courtyard | 6 | 1 | EA | \$1,430 | |
| Air Handling Systems | | Fan Coil Unit - Hot Water and Chilled Water | Entire Building | 6 | 22 | EA | \$31,460 | No Communications with BAS system |
| Air Handling Systems | | Make Up Air Unit - Indoor Mounted - Hot Water 10,001 to 20,000 cfm | Mechanical Room | 6 | 1 | EA | \$4,719 | Controls are functional on this unit |
| Heating Devices | | Cabinet Heaters With Hot Water Coils | Entire Building | 6 | 3 | EA | \$1,502 | No Communications with BAS system |
| Heating Devices | | Fin Tube Hot Water | Entire Building | 6 | 80 | LF | \$1,373 | No Communications with BAS system |
| Heating Devices | | Wall Heater - Electric | West Receiving Door | 7 | 1 | EA | \$0 | |
| Mechanical Plumbing | | Piping - Hydronic Supply and Return - Steel or Galvanized | Entire Building | 7 | 300 | LF | \$0 | |
| Temperature Control | | Direct Digital Control (DDC) System | Entire Building | 3 | 38,561 | SF | \$385,996 | Controls 12 Yrs Old but only few of the controls work (most damper and valve actuators are not working, not all sensors are responding, most dampers and valves are operating in manual mode, temperatures are not maintained). MUA Unit seems to be controllin |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | Entire Building | 4 | 22 | EA | \$20,449 | System is not communicating for any Terminals, AHU or MUA's. |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 6 | 5 | EA | \$2,145 | |
| MECHANICAL Sub Total | | | | | | | \$449,073 | |

Building: Addition 2

Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------|-----------|--|-----------------|------|----------|------|---------|--------|
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 6 | 38,561 | SF | \$4,411 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 6 | 38,561 | SF | \$6,066 | |

Building: Addition 2
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------|-----------|--|-----------------|------|----------|------|----------|--------|
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 6 | 38,561 | SF | \$6,066 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 6 | 38,561 | SF | \$6,066 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 6 | 38,561 | SF | \$6,066 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 6 | 38,561 | SF | \$8,823 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 6 | 38,561 | SF | \$7,720 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 6 | 38,561 | SF | \$6,066 | |
| Piping | | Sanitary Piping | Entire Building | 5 | 38,561 | SF | \$23,711 | |
| Piping | | Storm Piping | Entire Building | 5 | 38,561 | SF | \$18,197 | |
| Piping | | Vent Piping | Entire Building | 5 | 38,561 | SF | \$13,786 | |

PLUMBING Sub Total \$106,976

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|-----------------------|-------------------------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, room 105 | 7 | 365 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Second floor, room 205 | 7 | 365 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Basement east of fan room | 6 | 354 | SF | \$759 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Second floor, office on southwest | 5 | 207 | SF | \$1,172 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Basement Rm across hallway from gym | 6 | 705 | SF | \$1,512 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement Rm across hallway from gym | 6 | 705 | SF | \$1,008 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Second floor, room 205 | 7 | 365 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, room 105 | 7 | 365 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement east of fan room | 6 | 354 | SF | \$506 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Second floor, office on southwest | 6 | 207 | SF | \$296 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, room 105 | 7 | 6 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Second floor, office on southwest | 6 | 6 | SF | \$4 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Basement east of fan room | 6 | 6 | SF | \$4 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|-------------------------------|--------------------------------|-------------------------------------|------|----------|------|----------|--------|
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Basement Rm across hallway from gym | 6 | 10 | SF | \$7 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Second floor, room 205 | 7 | 6 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement Rm across hallway from gym | 6 | 864 | SF | \$2,039 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Second floor, office on southwest | 6 | 670 | SF | \$1,581 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, room 105 | 6 | 784 | SF | \$1,850 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement east of fan room | 6 | 655 | SF | \$1,545 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Second floor, room 205 | 6 | 784 | SF | \$1,850 | |
| Corridor | | Stair Handrails | Basement | 6 | 12 | LF | \$0 | |
| Corridor | | Stairs - Tile | Basement | 6 | 7 | LF | \$53 | |
| Doors | | Interior Steel Doors incl hw | Basement | 6 | 32 | EA | \$9,060 | |
| Doors | | Interior Steel Doors incl hw | 2nd Floor | 6 | 19 | EA | \$5,380 | |
| Doors | | Interior Steel Doors incl hw | 1st Floor | 6 | 20 | EA | \$5,663 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Ceiling - Exposed | Basement | 6 | 2,400 | SF | \$18,258 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Flooring - Tile/Sheet | Basement | 6 | 2,400 | SF | \$3,432 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Lighting - Pendant/Surface | Basement | 6 | 20 | EA | \$2,431 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Sound System | Basement | 6 | 1 | EA | \$5,005 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Walls - Concrete Block | Basement | 6 | 2,780 | SF | \$23,852 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Walls - Structural Glazed Tile | Basement | 6 | 1,853 | SF | \$13,249 | |
| Mechanical/Service Rooms | | Janitor's Closet | 2nd Floor | 6 | 1 | SF | \$5 | |
| Mechanical/Service Rooms | | Janitor's Closet | 1st Floor | 5 | 1 | SF | \$11 | |
| Mechanical/Service Rooms | | Janitor's Closet | Basement 2 janitor's | 6 | 20 | SF | \$94 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 2nd Floor | 6 | 126 | SF | \$595 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 1st Floor | 6 | 126 | SF | \$595 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement elevator machine room | 6 | 240 | SF | \$1,133 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement fan room | 6 | 769 | SF | \$3,629 | |
| Mechanical/Service Rooms | | Storage Room | Southwest, storage room | 6 | 250 | SF | \$1,180 | |
| Mechanical/Service Rooms | | Storage Room | Storage room in southwest office | 6 | 47 | SF | \$222 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|------------------|-----------------------------|------|----------|------|---------|--------|
| Staff Restroom | Staff Restroom | Accessories | Second floor, men's staff | 6 | 38 | SF | \$293 | |
| Staff Restroom | Staff Restroom | Accessories | Second floor, women's staff | 6 | 38 | SF | \$293 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Basement, Girls | 6 | 224 | SF | \$1,730 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Basement, boys | 6 | 223 | SF | \$1,722 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | First floor, Girls | 6 | 224 | SF | \$1,730 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | First floor, boys | 6 | 223 | SF | \$1,722 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Second floor, Girls | 6 | 224 | SF | \$1,730 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Second floor, boys | 6 | 223 | SF | \$1,722 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | 1st floor inside room C-5 | 6 | 26 | SF | \$201 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | 1st floor inside room C-7 | 6 | 26 | SF | \$201 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | First floor, Girls | 6 | 224 | SF | \$480 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Lay-In | 1st floor inside room C-5 | 6 | 26 | SF | \$56 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Basement, boys | 6 | 223 | SF | \$478 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Lay-In | 1st floor inside room C-7 | 6 | 26 | SF | \$56 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | First floor, boys | 6 | 223 | SF | \$478 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Second floor, Girls | 6 | 224 | SF | \$480 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Basement, Girls | 6 | 224 | SF | \$480 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | Second floor, women's staff | 7 | 38 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Second floor, boys | 6 | 223 | SF | \$478 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | Second floor, men's staff | 7 | 38 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | First floor, Girls | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Second floor, boys | 6 | 1 | EA | \$300 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | 1st floor inside room C-5 | 6 | 1 | EA | \$300 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|-----------------------------|------|----------|------|-------|--------|
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | 1st floor inside room C-7 | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Second floor, Girls | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | First floor, boys | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Basement, Girls | 6 | 1 | EA | \$300 | |
| Staff Restroom | Staff Restroom | Floor Drain | Second floor, men's staff | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Basement, boys | 6 | 1 | EA | \$300 | |
| Staff Restroom | Staff Restroom | Floor Drain | Second floor, women's staff | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement, Girls | 6 | 224 | SF | \$570 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | 1st floor inside room C-7 | 6 | 26 | SF | \$66 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Second floor, boys | 6 | 223 | SF | \$568 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Second floor, women's staff | 6 | 38 | SF | \$97 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Second floor, Girls | 6 | 224 | SF | \$570 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | First floor, boys | 6 | 223 | SF | \$568 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | First floor, Girls | 6 | 224 | SF | \$570 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement, boys | 6 | 223 | SF | \$568 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | 1st floor inside room C-5 | 6 | 26 | SF | \$66 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Second floor, men's staff | 6 | 38 | SF | \$97 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Second floor, boys | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Second floor, Girls | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | First floor, boys | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | First floor, Girls | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Basement, boys | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Basement, Girls | 7 | 1 | EA | \$0 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------------|-----------------------------|------|----------|------|-------|--------|
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Second floor, boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | 1st floor inside room C-5 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | First floor, boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Staff Restroom | Lavatory | Second floor, women's staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Second floor, Girls | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | First floor, Girls | 6 | 2 | EA | \$744 | |
| Staff Restroom | Staff Restroom | Lavatory | Second floor, men's staff | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Basement, boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Basement, Girls | 6 | 2 | EA | \$744 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | 1st floor inside room C-7 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Lay-In | 1st floor inside room C-7 | 6 | 1 | SF | \$1 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | First floor, boys | 6 | 5 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | First floor, Girls | 6 | 5 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Second floor, Girls | 6 | 5 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Second floor, men's staff | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Second floor, women's staff | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Second floor, boys | 6 | 5 | SF | \$4 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Lay-In | 1st floor inside room C-5 | 6 | 1 | SF | \$1 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Basement, Girls | 6 | 5 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Basement, boys | 6 | 5 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | First floor, Girls | 6 | 3 | EA | \$538 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | First floor, boys | 6 | 1 | EA | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Second floor, Girls | 6 | 3 | EA | \$538 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|--------------------------------|-----------------------------|------|----------|------|---------|-------------------------|
| Staff Restroom | Children's Standard Student Restroom | Partitions | Second floor, boys | 6 | 1 | EA | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Basement, Girls | 6 | 3 | EA | \$538 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Basement, boys | 6 | 1 | EA | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Second floor, boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Second floor, boys | 3 | 1 | EA | \$3,718 | One urinal out of order |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Basement, boys | 6 | 3 | EA | \$1,115 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | First floor, boys | 3 | 1 | EA | \$3,718 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | First floor, boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Second floor, women's staff | 6 | 116 | SF | \$274 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | First floor, boys | 6 | 210 | SF | \$495 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Second floor, boys | 6 | 210 | SF | \$495 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | 1st floor inside room C-5 | 6 | 102 | SF | \$241 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | 1st floor inside room C-7 | 6 | 102 | SF | \$241 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Second floor, Girls | 6 | 260 | SF | \$613 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Second floor, men's staff | 6 | 116 | SF | \$274 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Basement, boys | 6 | 210 | SF | \$495 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Basement, Girls | 6 | 260 | SF | \$613 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | First floor, Girls | 6 | 260 | SF | \$613 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Basement, boys | 7 | 426 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | Second floor, men's staff | 7 | 106 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | First floor, Girls | 7 | 416 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | First floor, boys | 7 | 426 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Second floor, Girls | 7 | 416 | SF | \$0 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------|--------------------------------------|-------------------------------------|-----------------------------|------|----------|------|----------|--------|
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Second floor, boys | 7 | 426 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Basement, Girls | 7 | 416 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Tile Ceramic/ Porcelain | 1st floor inside room C-5 | 6 | 102 | SF | \$260 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Tile Ceramic/ Porcelain | 1st floor inside room C-7 | 6 | 102 | SF | \$260 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | Second floor, women's staff | 7 | 106 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Basement, Girls | 6 | 3 | EA | \$1,115 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Basement, boys | 6 | 1 | EA | \$372 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | 1st floor inside room C-7 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | 1st floor inside room C-5 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Second floor, boys | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | Second floor, men's staff | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | First floor, boys | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | First floor, Girls | 6 | 3 | EA | \$1,115 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Second floor, Girls | 6 | 3 | EA | \$1,115 | |
| Staff Restroom | Staff Restroom | Water Closet | Second floor, women's staff | 6 | 1 | EA | \$372 | |
| Vertical Conveyance | | Elevator - Roped Holeless Hydraulic | Entire Building | 6 | 1 | EA | \$17,160 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 2 | EA | \$772 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 2 | EA | \$772 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 2 | EA | \$772 | |

INTERIOR Sub Total \$176,773

Building: Addition 2
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|----------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 6 | 49 | LF | \$1,752 | |
| Casework | Classroom | Casework | | 6 | 16 | LF | \$572 | |
| Casework | Classroom | Casework | | 6 | 38 | LF | \$1,359 | |
| Casework | Classroom | Casework | | 6 | 49 | LF | \$1,752 | |
| Casework | Classroom | Casework | | 6 | 29 | LF | \$1,037 | |

Building: Addition 2
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|-------------|----------|------|----------|------|---------|---------------------------|
| Casework | Classroom | Casework | | 6 | 42 | LF | \$1,502 | |
| Casework | Classroom | Casework | | 6 | 49 | LF | \$1,752 | |
| Casework | Classroom | Casework | | 6 | 29 | LF | \$1,037 | |
| Casework | Classroom | Casework | | 6 | 64 | LF | \$2,288 | |
| Casework | Classroom | Casework | | 6 | 49 | LF | \$1,752 | |
| Casework | Classroom | Casework | | 6 | 49 | LF | \$1,752 | |
| Casework | Classroom | Casework | | 6 | 49 | LF | \$1,752 | |
| Casework | Classroom | Casework | | 6 | 35 | LF | \$1,251 | |
| Casework | Classroom | Casework | | 6 | 49 | LF | \$1,752 | |
| Casework | Classroom | Casework | | 6 | 38 | LF | \$1,359 | |
| Casework | Classroom | Casework | | 6 | 49 | LF | \$1,752 | |
| Casework | Classroom | Casework | | 6 | 49 | LF | \$1,752 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 1,069 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 1,070 | SF | \$2,295 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 1,068 | SF | \$2,291 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 738 | SF | \$1,583 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 478 | SF | \$1,025 | Stained tiles |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 1,105 | SF | \$2,370 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 1,068 | SF | \$2,291 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 700 | SF | \$1,502 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 1,070 | SF | \$2,295 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 1,070 | SF | \$2,295 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 1,069 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 719 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 981 | SF | \$2,104 | water damage missing tile |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 1,076 | SF | \$2,308 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 702 | SF | \$1,506 | water staining |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 695 | SF | \$1,491 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 5 | LF | \$608 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 14 | LF | \$1,702 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |

Building: Addition 2
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|-------------------------|-----------------------------|------|----------|------|----------|--|
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 6 | 1 | EA | \$1,359 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 6 | 1 | EA | \$1,359 | |
| Corridors | Corridors | Double Water Cooler | 2nd Floor | 6 | 1 | EA | \$844 | |
| Corridors | Corridors | Double Water Cooler | 1st Floor | 6 | 1 | EA | \$844 | |
| Corridors | Corridors | Double Water Cooler | Basement | 6 | 1 | EA | \$844 | |
| Corridors | Corridors | Drop/Lay-In | 1st Floor | 6 | 1,971 | SF | \$4,228 | Several areas with stained tiles from water damage |
| Corridors | Corridors | Drop/Lay-In | Basement | 6 | 1,971 | SF | \$4,228 | Several areas with stained tiles from water damage |
| Corridors | Corridors | Drop/Lay-In | 2nd Floor | 6 | 1,971 | SF | \$4,228 | Several areas with stained tiles from water damage |
| Corridors | Corridors | Lay-In | Entire building stair wells | 6 | 1,618 | EA | \$1,157 | |
| Corridors | Corridors | Lay-In | 2nd Floor | 6 | 1,971 | EA | \$1,409 | |
| Corridors | Corridors | Lay-In | 1st Floor | 6 | 1,971 | EA | \$1,409 | |
| Corridors | Corridors | Lay-In | Basement | 6 | 1,971 | EA | \$1,409 | |
| Corridors | Corridors | Plaster/Drywall | Basement | 6 | 3,210 | SF | \$7,574 | |
| Corridors | Corridors | Plaster/Drywall | Entire building stair wells | 6 | 5,400 | SF | \$12,741 | |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 6 | 4,012 | SF | \$9,466 | |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 6 | 4,012 | SF | \$9,466 | |
| Corridors | Corridors | Stair Handrails | Entire building stair wells | 6 | 104 | LF | \$0 | |
| Corridors | Corridors | Student Lockers | 1st Floor | 6 | 126 | EA | \$18,018 | |
| Corridors | Corridors | Student Lockers | Basement | 6 | 90 | EA | \$12,870 | |
| Corridors | Corridors | Student Lockers | 2nd Floor | 6 | 140 | EA | \$20,020 | |
| Corridors | Corridors | Terrazzo | Entire building stair wells | 7 | 1,722 | SF | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | 2nd Floor | 6 | 1,971 | SF | \$2,819 | |
| Corridors | Corridors | Tile/Sheet Flooring | 1st Floor | 6 | 1,971 | SF | \$2,819 | |
| Corridors | Corridors | Tile/Sheet Flooring | Basement | 6 | 1,971 | SF | \$2,819 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Entire building stair wells | 6 | 1,722 | SF | \$4,876 | |
| Stairs | Corridors | Terrazzo | Entire building stair wells | 6 | 96 | SF | \$1,087 | |
| Floor | Classroom | Carpet | | 6 | 1,076 | SF | \$1,539 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,069 | SF | \$0 | |

Building: Addition 2

Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|--------------|----------|------|----------|------|---------|--------|
| Floor | Classroom | Tile/Sheet | | 6 | 1,428 | SF | \$2,042 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,070 | SF | \$1,530 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,070 | SF | \$1,530 | |
| Floor | Classroom | Tile/Sheet | | 6 | 695 | SF | \$994 | |
| Floor | Classroom | Tile/Sheet | | 6 | 719 | SF | \$1,028 | |
| Floor | Classroom | Tile/Sheet | | 6 | 738 | SF | \$1,055 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,068 | SF | \$1,527 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,068 | SF | \$1,527 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,105 | SF | \$1,580 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,069 | SF | \$1,529 | |
| Floor | Classroom | Tile/Sheet | | 6 | 702 | SF | \$1,004 | |
| Floor | Classroom | Tile/Sheet | | 6 | 700 | SF | \$1,001 | |
| Floor | Classroom | Tile/Sheet | | 6 | 478 | SF | \$684 | |
| Floor | Classroom | Tile/Sheet | | 6 | 981 | SF | \$1,403 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Lay-In | | 6 | 19 | EA | \$1,359 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Lay-In | | 6 | 24 | EA | \$1,716 | |
| Lighting | Classroom | Lay-In | | 6 | 12 | EA | \$858 | |
| Lighting | Classroom | Lay-In | | 6 | 12 | EA | \$858 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Lay-In | | 6 | 10 | EA | \$715 | |
| Lighting | Classroom | Lay-In | | 6 | 15 | EA | \$1,073 | |
| Lighting | Classroom | Lay-In | | 6 | 18 | EA | \$1,287 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |

Building: Addition 2
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Wall | Classroom | Plaster/Drywall | | 5 | 1,087 | SF | \$5,130 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 921 | SF | \$2,173 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,443 | SF | \$3,405 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 973 | SF | \$2,296 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,087 | SF | \$2,565 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,098 | SF | \$2,591 | |
| Wall | Classroom | Plaster/Drywall | | 5 | 1,087 | SF | \$5,130 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,114 | SF | \$2,628 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,114 | SF | \$2,628 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 942 | SF | \$2,223 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,224 | SF | \$2,888 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,226 | SF | \$2,893 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 947 | SF | \$2,234 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 995 | SF | \$2,348 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,224 | SF | \$2,888 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 973 | SF | \$2,296 | |

ROOM Sub Total \$289,390

Building Addition 2 Sub Total \$1,523,974

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|-----------------|-----------------|------|----------|------|----------|--------|
| Civil/Drainage | | Catch Basin | Entire Site | 6 | 6 | EA | \$3,260 | |
| Civil/Drainage | | Site Drain | Entire Site | 6 | 1 | EA | \$112 | |
| Civil/Drainage | | Site Manhole | Entire Site | 7 | 15 | EA | \$0 | |
| Fencing | | Chain Link | Entire Building | 5 | 896 | LF | \$32,032 | |
| Fencing | | Ornamental Iron | Entire Site | 6 | 361 | LF | \$6,814 | |
| Fencing | | Ornamental Iron | Parking Lot | 6 | 27 | LF | \$510 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|---------------------------------------|--------------------------------|------|----------|------|------------------|--|
| Landscape | | Asphalt Play Area/Hardscape | Playground | 6 | 3,460 | SF | \$2,969 | |
| Landscape | | Benches | Garden (west) | 6 | 2 | EA | \$472 | |
| Landscape | | Grass | West playground field | 5 | 5,610 | SF | \$7,300 | |
| Landscape | | Grass | South of main building | 4 | 2,050 | SF | \$8,120 | Grass completely missing |
| Landscape | | Grass | Entire Site | 6 | 10,110 | SF | \$4,048 | |
| Landscape | | Hardscape - Concrete | Entire Site | 6 | 17,099 | SF | \$32,276 | |
| Landscape | | Parkway trees | North and West Perimeter | 6 | 18 | EA | \$5,148 | |
| Landscape | | Planting Beds/ Areas | Entire Site | 6 | 3,020 | SF | \$0 | |
| Landscape | | Retaining Wall - Masonry | Playground | 6 | 408 | SF | \$5,776 | |
| Parking Lot | | Asphalt | East lot | 5 | 1,149 | SF | \$3,253 | |
| Parking Lot | | Asphalt | Main lot | 6 | 24,280 | SF | \$20,832 | |
| Parking Lot | | Concrete | Main lot - chiller pad | 7 | 2,008 | SF | \$0 | |
| Parking Lot | | Concrete Curbs | Main lot | 6 | 553 | LF | \$3,337 | |
| Parking Lot | | Lighting | Parking Lot | 6 | 7 | EA | \$100,100 | |
| Parking Lot | | Trash Compactor | Parking Lot | 6 | 1 | EA | \$3,575 | |
| Parking Lot | | Vehicular Screening | Parking Lot | 4 | 426 | LF | \$60,309 | Approximately 75% of the bushes are dead |
| Playground | | Playground Equipment - Combo 3-12 | Playground | 7 | 1 | EA | \$0 | |
| Playground | | Playground Surfacing - Poured Surface | Playground | 6 | 2,571 | SF | \$6,802 | |
| Sidewalks | | Internal Walks | Entire Site | 6 | 288 | LF | \$2,718 | |
| Sidewalks | | Perimeter Sidewalks | North, East and West perimeter | 6 | 10,345 | SF | \$19,527 | |
| Signage | | Flag Pole | Northwest corner | 6 | 1 | EA | \$0 | |
| Signage | | Marquee - Free Standing Back Lighted | Northwest corner | 6 | 1 | EA | \$0 | |
| SITE Sub Total | | | | | | | \$329,291 | |
| SITE Sub Total | | | | | | | \$329,291 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---|-----------|------|----------|------|----------|------|--------------------|--------|
| Total Campus Need ^{2 3} | | | | | | | \$6,842,276 | |

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-----------------------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|----------------------------------|--|
| Building: Main | | | | | | | | | | | | | | |
| A101 | 875 | 1 | 8 | 18 | 40 | 178 | 85 | 0 | Y | Y | Y | Classroom | | |
| A102 | 846 | 0 | 3 | 14 | 40 | 178 | 85 | 0 | Y | N | Y | Classroom | | |
| A103 | 903 | 0 | 5 | 14 | 40 | 178 | 85 | 0 | Y | N | Y | Classroom | | |
| A104 | 840 | 1 | 5 | 16 | 40 | 119 | 57 | 0 | Y | Y | Y | Classroom | | |
| A105 | 986 | 1 | 9 | 22 | 40 | 149 | 71 | 0 | Y | Y | Y | Classroom | | |
| A107 | 883 | 1 | 11 | 22 | 40 | 116 | 58 | 0 | Y | Y | Y | Classroom | | |
| A108 | 1017 | 0 | 11 | 26 | 40 | 178 | 85 | 0 | Y | Y | Y | Classroom | | |
| A201 | 866 | 2 | 10 | 20 | 40 | 150 | 75 | | Y | Y | Y | Classroom | | |
| A202 | 866 | 2 | 10 | 20 | 40 | 150 | 75 | | Y | Y | Y | Classroom | | |
| A203 | 875 | 2 | 10 | 20 | 40 | 195 | 98 | | Y | Y | Y | Classroom | | |
| A204 | 866 | 2 | 10 | 20 | 40 | 130 | 65 | | Y | Y | Y | Classroom | | |
| A205 | 851 | 1 | 9 | 20 | 40 | 130 | 65 | | Y | Y | N | Classroom | | |
| A207 | 853 | 2 | 10 | 20 | 40 | 130 | 65 | | Y | Y | Y | Classroom | | |
| A208 | 853 | 2 | 10 | 20 | 40 | 150 | 75 | | Y | Y | Y | Classroom | | |
| A4 | 824 | 2 | 4 | 10 | 40 | 80 | 40 | | Y | N | Y | Classroom | | |
| Other | 729 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Basement to south of room with plan number 23 |
| Other | 43 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | A103 |
| Other | 698 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | 1925 | | | | | | | | N | N | N | Corridors | | Basement |
| Other | 902 | | | | | | | | N | N | N | Corridors | | Entire building stair wells |
| Other | 788 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Basement at east end |
| Other | 6129 | | | | | | | | N | N | N | Library | | 3rd Floor |
| Other | 548 | | | 8 | | | | | N | N | Y | Administrative Suites/Offices | | Basement across hallway from fan room staff lounge |
| Other | 46 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | A101 |
| Other | 56 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | A105 |
| Other | 240 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Basement next to staff lounge |
| Other | 1919 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 1919 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 43 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | A102 |
| Other | 397 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Basement SW corner east of sprinkler room |
| Building: Addition 1 | | | | | | | | | | | | | | |
| B102 | 919 | 1 | 6 | 22 | 40 | 142 | 71 | 0 | Y | Y | Y | Classroom | | |
| B103 | 927 | 0 | 3 | 18 | 40 | 116 | 58 | 0 | Y | Y | Y | Classroom | | |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|--|
| B104 | 927 | 0 | 3 | 18 | 40 | 116 | 58 | 0 | Y | Y | Y | Classroom | | |
| B202 | 1059 | 1 | 9 | 26 | 40 | 154 | 78 | | Y | Y | N | Classroom | | |
| B203 | 874 | 1 | 9 | 28 | 40 | 132 | 67 | | Y | Y | N | Classroom | | |
| B204 | 1127 | 1 | 9 | 26 | 40 | 176 | 89 | | Y | Y | N | Classroom | | |
| B205 | 887 | 1 | 9 | 28 | 40 | 132 | 67 | | Y | Y | N | Classroom | | |
| B206 | 890 | 3 | 6 | 28 | 40 | 132 | 67 | | Y | Y | N | Classroom | | |
| B301 | 902 | 2 | 8 | 16 | 40 | 144 | 72 | | Y | Y | Y | Classroom | | |
| B302 | 902 | 2 | 8 | 16 | 40 | 144 | 72 | | Y | Y | Y | Classroom | | |
| B303 | 902 | 2 | 8 | 16 | 40 | 144 | 72 | | Y | Y | Y | Classroom | | |
| B304 | 902 | 2 | 8 | 16 | 40 | 144 | 72 | | Y | Y | Y | Classroom | | |
| B305 | 902 | 2 | 8 | 16 | 40 | 144 | 72 | | Y | Y | Y | Classroom | | |
| B306 | 902 | 2 | 8 | 16 | 40 | 144 | 72 | | Y | Y | Y | Classroom | | |
| Other | 33 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, West end, Women's Staff |
| Other | 146 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, health office |
| Other | 437 | | | 12 | | | | | N | N | N | Administrative Suites/Offices | | First floor, Health office room B106 |
| Other | 48 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, East end, Women's Staff |
| Other | 48 | | | | | | | | N | N | N | Restroom | Staff Restroom | First Floor, East end, Men's Staff |
| Other | 365 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | First Floor, Girls |
| Other | 33 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, West end, Men's Staff |
| Other | 48 | | | | | | | | N | N | N | Restroom | Staff Restroom | Second floor, East end, Women's Staff |
| Other | 1917 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 33 | | | | | | | | N | N | N | Restroom | Staff Restroom | Second floor, West end, Women's Staff |
| Other | 33 | | | | | | | | N | N | N | Restroom | Staff Restroom | Second floor, West end, Men's Staff |
| Other | 365 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Second Floor, Girls |
| Other | 359 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Second Floor, Boys |
| Other | 343 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Basement, Boys |
| Other | 48 | | | | | | | | N | N | N | Restroom | Staff Restroom | Second Floor, East end, Men's Staff |
| Other | 359 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | First Floor, Boys |
| Other | 50 | | | | | | | | N | N | N | Restroom | Staff Restroom | Basement men's between lunch room & auditorium |
| Other | 343 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Basement, Girls |
| Other | 285 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Basement at west end |
| Other | 842 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Basement small lunchroom east of kitchen |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-----------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|---------------------------|--------------------------------------|--|
| Other | 1117 | | | | | | | | N | N | N | Corridors | | Entire building stair wells |
| Other | 1119 | | | | | | | | N | N | N | Kitchen | Cooking Kitchen | Basement east of boiler room |
| Other | 2365 | | | | | | | | N | N | N | Corridors | | Basement |
| Other | 50 | | | | | | | | N | N | N | Restroom | Staff Restroom | Basement women's between lunch room & auditorium |
| Other | 2150 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Basement |
| Other | 404 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 3rd floor, Boys |
| Other | 400 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 3rd floor, Girls |
| Other | 1917 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | 1917 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 4825 | | | | | | | | N | N | N | Auditorium & Theater | Auditorium - Dedicated | 1st Floor |
| Special Educati | 816 | 0 | 2 | 14 | 40 | 142 | 71 | 0 | Y | Y | Y | Classroom | | |

Building: Addition 2

| | | | | | | | | | | | | | | |
|-----------|------|---|----|----|----|-----|-----|---|---|---|---|-------------------------------|--------------------------------------|-----------------------------------|
| C-10 | 700 | 1 | 6 | 16 | 40 | 100 | 50 | 0 | Y | Y | Y | Classroom | | |
| C104 | 695 | 1 | 9 | 20 | 40 | 116 | 58 | 0 | Y | Y | Y | Classroom | | |
| C105 | 1068 | 1 | 8 | 24 | 40 | 173 | 88 | 0 | Y | Y | Y | Classroom | | |
| C106 | 1105 | 1 | 7 | 28 | 40 | 173 | 88 | 0 | Y | Y | Y | Classroom | | |
| C108 | 478 | 3 | 1 | 8 | 40 | 0 | 0 | 0 | Y | N | Y | Classroom | | |
| C109 | 1068 | 1 | 10 | 32 | 40 | 173 | 88 | 0 | Y | Y | Y | Classroom | | |
| C110 | 738 | 4 | 5 | 14 | 40 | 93 | 39 | 0 | Y | Y | Y | Classroom | | |
| c-202 | 702 | 2 | 10 | 22 | 40 | 107 | 55 | | Y | Y | N | Classroom | | |
| c-203 | 1069 | 1 | 9 | 36 | 40 | 161 | 82 | | Y | Y | N | Classroom | | |
| c-204 | 1076 | 1 | 9 | 36 | 40 | 161 | 82 | | Y | N | N | Classroom | | |
| c-206 | 981 | 1 | 8 | 34 | 40 | 161 | 82 | | Y | Y | N | Classroom | | |
| C-207 | 1069 | 1 | 9 | 36 | 40 | 161 | 82 | | Y | Y | N | Classroom | | |
| c-208 | 719 | 2 | 6 | 20 | 40 | 107 | 55 | | Y | N | N | Classroom | | |
| C-5 | 1070 | 1 | 7 | 28 | 40 | 180 | 90 | 0 | Y | Y | Y | Classroom | | |
| C-7 | 1070 | 1 | 7 | 28 | 40 | 180 | 90 | 0 | Y | Y | Y | Classroom | | |
| C-8 & C-9 | 1428 | 1 | 12 | 36 | 40 | 240 | 120 | 0 | Y | Y | Y | Classroom | | |
| Other | 574 | | | | | | | | N | N | N | Corridors | | Entire building stair wells |
| Other | 1971 | | | | | | | | N | N | N | Corridors | | Basement |
| Other | 207 | | | 6 | | | | | N | N | N | Administrative Suites/Offices | | Second floor, office on southwest |
| Other | 1971 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 354 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Basement east of fan room |
| Other | 38 | | | | | | | | N | N | N | Restroom | Staff Restroom | Second floor, men's staff |
| Other | 223 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Basement, boys |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|-------------------------------------|
| Other | 365 | | | 12 | | | | | N | N | N | Administrative Suites/Offices | | Second floor, room 205 |
| Other | 224 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Basement, Girls |
| Other | 705 | | | 8 | | | | | N | N | Y | Administrative Suites/Offices | | Basement Rm across hallway from gym |
| Other | 224 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | First floor, Girls |
| Other | 223 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | First floor, boys |
| Other | 365 | | | 10 | | | | | N | N | N | Administrative Suites/Offices | | First floor, room 105 |
| Other | 1971 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 224 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Second floor, Girls |
| Other | 223 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Second floor, boys |
| Other | 26 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | 1st floor inside room C-5 |
| Other | 26 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | 1st floor inside room C-7 |
| Other | 2400 | | | | | | | | N | N | N | Gymnasia | Standard Dedicated Gymnasium | Basement |
| Other | 38 | | | | | | | | N | N | N | Restroom | Staff Restroom | Second floor, women's staff |