

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

- Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- Total Campus Need** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Chimney		Brick Chimney - Concrete/ Mortar Liner	East elevation	7	54	LF	\$0	
Chimney		Brick Chimney - Concrete/ Mortar Liner	East elevation	5	1	LF	\$1,788	mortar
Cornice		Cornice - Masonry Projecting/Limestone	Entire Building	7	426	LF	\$0	
Doors		Exterior Steel Door	throughout	7	9	EA	\$0	
Doors		Exterior Steel Door	North Entrances	7	2	EA	\$0	
Doors		Exterior Steel Door	Main Entrance	7	2	EA	\$0	
Doors		Transom Lite	West Entrances	7	1	EA	\$0	
Entrance		Concrete Exterior Stairs	West Entrances	6	40	LF	\$4,290	
Entrance		Concrete Exterior Stairs	East Entrances	6	40	LF	\$4,290	
Entrance		Entrance Controls - Audio and Video	Main Entrance	7	1	EA	\$0	
Entrance		Stair Handrails	West Entrances	6	10	LF	\$0	
Fire Escape		Fire Escapes	North Façade	6	62	LF	\$6,320	paint
Foundation		Masonry Foundation	Entire Building	7	11,719	SF	\$0	
Foundation		Masonry Foundation	S & SE foundation walls	5	50	SF	\$16,351	efflorescence and water intrusion

Building: Main
Category: EXTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Lintels		Lintels - Steel	Entire Building	7	51	LF	\$0	
Lintels		Lintels - Stone	isolated areas throughout	5	36	LF	\$7,722	spalling and deterioration
Lintels		Lintels - Stone	Entire Building	7	415	LF	\$0	
Parapet		Coping - Metal	Main Roof	7	406	LF	\$0	
Parapet		Coping - Stone	Lower Roof	7	54	LF	\$0	
Parapet		Parapet < 16" Height	Lower Roof	5	15	LF	\$3,610	mortar
Parapet		Parapet < 16" Height	Lower Roof	7	39	LF	\$0	
Parapet		Parapet > 30" Height	South Façade	5	15	LF	\$6,017	modified bitumen flashing has openings in joint sealant at entire interior perimeter
Parapet		Parapet 16" to 30" Height	Main Roof	5	391	LF	\$125,469	modified bitumen flashing has openings in joint sealant at entire interior perimeter
Roof System		Asphalt Gravel Ballast Roof	Lower Roof	6	1,701	SF	\$10,849	remove debris and redistribute displaced gravel
Roof System		Exterior Downspouts	Roofs	7	260	LF	\$0	
Roof System		Modified Bitumen Roof	Main Roof	6	10,068	SF	\$71,266	15 years old
Roof System		Roof Structure: Concrete	Lower Roof	7	1,701	SF	\$0	
Roof System		Roof Structure: Heavy Timber	Main Roof	7	10,060	SF	\$0	
Roof System		Roof Structure: Heavy Timber	Main Roof	2	8	SF	\$574	large cracks in 2 vertical wood supports (north & west)
Superstructure		Steel with Clay Tile Arch	Entire Building	7	41,853	SF	\$0	
Superstructure		Steel with Clay Tile Arch	SE stairwell, floors 1-3	6	120	SF	\$1,133	
Walls		Brick	Entire Building	5	20	SF	\$453	mortar - isolated areas throughout
Walls		Brick	Entire Building	7	22,873	SF	\$0	
Walls		Brick	Entire Building	4	50	SF	\$3,775	cracks and deteriorated face in isolated areas throughout
Walls		Stone - Cut	Entire Building	5	552	SF	\$59,202	cracks, spalling, mortar throughout isolated areas
Walls		Stone - Cut	Entire Building	7	2,208	SF	\$0	
Windows		Skylite - Glass Single-Pane	Lower Roof	7	16	SF	\$0	
Windows		Window - Guards perforated	1st and 2nd floors	7	1,570	SF	\$0	
Windows		Window - Guards perforated	North Façade	6	120	SF	\$0	paint
Windows		Window - Guards wire guard	North Façade	6	165	SF	\$0	paint
Windows		Windows - Decorative	South Façade	7	30	SF	\$0	

Building: Main
Category: EXTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Windows		Windows - Decorative	North Façade	7	198	SF	\$0	
Windows		Windows - Sash Aluminum	North Façade	7	506	SF	\$0	
Windows		Windows - Sash Aluminum Double-pane	Entire Building	7	7,486	SF	\$0	missing stops
EXTERIOR Sub Total							\$323,108	

Building: Main
Category: ELECTRICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Emergency System		Automatic Transfer switch	Mechanical Room	4	1	EA	\$8,866	
Emergency System		Emergency A/C power - Corridors and Stairs	Entire Building	4	5,398	SF	\$16,596	
Emergency System		Emergency A/C power - Gym and Lunch rooms	Lunchroom/Kitchen	4	972	SF	\$1,737	
Emergency System		Emergency A/C power - Students Toilets	Entire Building	4	1,244	SF	\$4,447	
Emergency System		Exit Signs - Corridors and Stairs	Entire Building	5	8	EA	\$3,718	
Emergency System		Exit Signs - Lunchroom - Gym - multipurpose rooms	Lunchroom/Kitchen	4	8	EA	\$7,436	
Emergency System		Independent Electrical Service for emergency power	Mechanical Room	5	1	EA	\$5,005	
Emergency System		Public Announcement System	Entire Building	6	41,973	SF	\$25,209	
Emergency System		Security System - Intrusion detection	Entire Building	6	41,973	SF	\$39,014	
Main Service		Main Electrical service 1200 A 120/208/3PH	Mechanical Room	6	1	EA	\$7,150	
Power Distribution		Lighting and power panels	Entire Building	6	8	EA	\$5,720	
Power Distribution		Main distribution panels 400-600 amp	Mechanical Room	6	1	EA	\$1,430	
Power Distribution		Main distribution panels above 600 amp	Mechanical Room	6	1	EA	\$2,145	
ELECTRICAL Sub Total							\$128,474	

Building: Main
Category: FIRE PROTECTION

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Fire Alarm		Fire Alarm Strobe Lights	Entire Building	6	41,973	SF	\$15,005	
Fire Alarm		Fire Alarm System	Entire Building	6	41,973	SF	\$51,018	
Fire Alarm		Fire Pump Controller	Pump Room	3	1	EA	\$18,590	
Pump Room Assembly		Fire Pump 25-50hp	Entire Building	4	1	EA	\$34,034	
Sprinkler System		Dry Sprinkler System	Entire Building	4	41,973	SF	\$300,107	
FIRE PROTECTION Sub Total							\$418,754	

Building: Main
Category: MECHANICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
-------	-----------	------	----------	------	----------	------	------	--------

Building: Main
Category: MECHANICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Air Conditioning		Window A/C Unit	Entire Building	5	23	EA	\$24,668	
Air Handling Systems		Air Intake - Built Up Air Handling Unit	Basement	5	1	EA	\$16,016	
Air Handling Systems		Fan Coil Unit - Electric	Boiler Room	7	1	EA	\$0	
Air Handling Systems		Multi Zone Built Up Air Handling Unit - Steam 15,001 to 25,000 cfm	Engine Room	5	1	EA	\$35,750	
Air Handling Systems		Multi Zone Built Up Air Handling Unit Auxiliaries - Steam 15,001 to 25,000 cfm	AHU	4	1	EA	\$32,890	
Air Handling Systems		Return Duct Work - Masonry and Ducts - Existing or Missing Exterior Shaft	Roof thru Basement	4	41	LF	\$108,466	
Boiler Systems		Boiler Assembly - Steam - Low Pressure Scotch Marine Boiler 76-100 HP	Boiler Room	4	1	EA	\$118,690	
Boiler Systems		Boiler Assembly - Steam - Low Pressure Scotch Marine Boiler 76-100 HP	Boiler Room	4	1	EA	\$118,690	
Boiler Systems		Boiler Auxiliary - Steam Boiler 76-100 HP	Boiler Room	4	2	EA	\$40,040	
Boiler Systems		Chemical Feed System (Steam Boilers)	Boiler Room	6	1	EA	\$2,145	
Boiler Systems		Combustion Dampers	Boiler Room	6	1	EA	\$286	
Boiler Systems		Feed Water Pumps and Tank - Steam Boilers	Boiler Room	4	1	EA	\$31,460	
Heating Devices		Radiators - Steam	Entire Building	6	5	EA	\$701	
Heating Devices		Wall Heater - Electric	Basement	4	8	EA	\$8,237	
Mechanical Plumbing		Piping - Condensate - Steel or Galvanized	Entire Building	4	220	LF	\$21,550	
Mechanical Plumbing		Piping - Steam - Steel or Galvanized	Entire Building	5	220	LF	\$10,885	
Mechanical Plumbing		Pumps - Vacuum	Engine Room	5	1	EA	\$14,300	
Temperature Control		Pneumatic System	Entire Building	6	41,973	SF	\$15,005	
Temperature Control		Thermostats - Pneumatic	Entire Building	6	26	EA	\$3,718	
Temperature Control		Zone Dampers	AHU	5	23	EA	\$8,551	

MECHANICAL Sub Total \$612,048

Building: Main
Category: PLUMBING

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Hot Water		Hot Water Heater - Gas 150,000 -300,000 BTU/HR	Boiler Room	6	1	EA	\$4,147	
Hot Water		Storage Tank less than 500 gallons	Boiler Room	4	1	EA	\$14,872	
Piping		Domestic Piping - Cold Water from Risers to Fixtures	Entire Building	5	41,973	SF	\$7,203	
Piping		Domestic Piping - Cold Water Risers	Entire Building	5	41,973	SF	\$13,805	
Piping		Domestic Piping - Hot Water from Riser to fixtures	Entire Building	5	41,973	SF	\$48,017	
Piping		Domestic Piping - Hot Water Return Risers	Entire Building	5	41,973	SF	\$9,003	
Piping		Domestic Piping - Hot Water Risers	Entire Building	5	41,973	SF	\$10,804	
Piping		Domestic Piping Cold Water Horizontal lines	Entire Building	5	41,973	SF	\$37,213	

Building: Main
Category: PLUMBING

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Piping		Domestic Piping Hot Water Horizontal lines	Entire Building	5	41,973	SF	\$22,208	
Piping		Domestic Piping Hot Water Return Lines	Entire Building	5	41,973	SF	\$22,808	
Piping		Sanitary Piping	Entire Building	5	41,973	SF	\$25,809	
Piping		Storm Piping	Entire Building	5	41,973	SF	\$19,807	
Piping		Vent Piping	Entire Building	5	41,973	SF	\$15,005	
Pumps		Domestic Booster Pump simplex	Pump Room	2	1	EA	\$17,160	
Pumps		Sump Pump	Boiler Room	5	1	EA	\$5,148	

PLUMBING Sub Total \$273,010

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	Teacher's Lounge in Basement	7	364	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	Basement Lunch Room Manager's Office	7	248	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	Basement - Building Engineer's Office	7	232	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	Basement - Counselor's Office near Pump Room	7	285	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	PE Teacher's Office in Basement by Library	7	55	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	3rd Floor Faculty Lounge	7	150	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	2nd Floor Faculty Lounge	7	150	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	3rd Floor Office near Room 305	7	223	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	2nd Floor Office near Room 205	7	223	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	1st Floor Office near Room 105	7	223	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Plaster/Drywall	Reception-1st Floor	7	250	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Concrete	Basement - Building Engineer's Office	7	232	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Concrete	Teacher's Lounge in Basement	7	364	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Concrete	Basement - Counselor's Office near Pump Room	7	285	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Concrete	PE Teacher's Office in Basement by Library	7	55	SF	\$0	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Flooring - Concrete	Basement Lunch Room Manager's Office	7	248	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	2nd Floor Faculty Lounge	7	150	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	3rd Floor Faculty Lounge	7	150	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Wood	Reception-1st Floor	7	250	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Wood	1st Floor Office near Room 105	6	223	SF	\$1,684	
Administrative Suites	Administrative Suites/Offices	Flooring - Wood	2nd Floor Office near Room 205	6	223	SF	\$1,684	
Administrative Suites	Administrative Suites/Offices	Flooring - Wood	3rd Floor Office near Room 305	6	223	SF	\$1,684	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	PE Teacher's Office in Basement by Library	4	1	SF	\$7	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	104A (Book Storage)	4	4	SF	\$26	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Main Office (Principal)	4	15	SF	\$99	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Reception-1st Floor	4	3	SF	\$20	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	1st Floor Office near Room 105	4	2	SF	\$13	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	3rd Floor Faculty Lounge	4	2	SF	\$13	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	3rd Floor Office near Room 305	4	2	SF	\$13	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	2nd Floor Office near Room 205	4	2	SF	\$13	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Basement Lunch Room Manager's Office	4	1	SF	\$7	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	2nd Floor Faculty Lounge	4	2	SF	\$13	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Basement - Building Engineer's Office	4	2	SF	\$13	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Teacher's Lounge in Basement	4	2	SF	\$13	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Basement - Counselor's Office near Pump Room	4	4	SF	\$26	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Basement - Building Engineer's Office	7	350	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	PE Teacher's Office in Basement by Library	7	50	SF	\$0	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Teacher's Lounge in Basement	7	400	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Basement Lunch Room Manager's Office	7	300	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Basement - Counselor's Office near Pump Room	7	365	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	Reception-1st Floor	6	500	SF	\$1,180	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	3rd Floor Office near Room 305	7	290	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	2nd Floor Faculty Lounge	7	225	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	3rd Floor Faculty Lounge	7	225	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	1st Floor Office near Room 105	7	290	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	2nd Floor Office near Room 205	7	290	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Plaster/Drywall	104A (Book Storage)	6	900	SF	\$2,124	
Classrooms		Work Sink	Room 102	7	2	EA	\$0	
Classrooms		Work Sink	Room 106 Wardrobe	7	3	EA	\$0	
Corridor		Ceiling - Plaster/Drywall	Entire Building	6	5,423	SF	\$15,355	
Corridor		Flooring Asphalt	Stair landings	7	1,918	SF	\$0	
Corridor		Flooring Tile/ Sheet	Basement/1st floor stair landings	7	340	SF	\$0	
Corridor		Flooring Wood	Entire Building	7	3,140	SF	\$0	
Corridor		Lighting - Pendant/ Surface	Entire Building	4	5,423	SF	\$52,733	T12 should be replaced by T8
Corridor		Stair Handrails	Entire Building	6	490	LF	\$0	Paint required
Corridor		Stairs - Asphalt	Entire Building	7	158	LF	\$0	
Corridor		Student Lockers	3rd Floor	7	70	EA	\$0	
Corridor		Walls - Masonry	Basement	6	897	SF	\$11,544	
Corridor		Walls - Plaster/Drywall	Entire Building	6	12,365	SF	\$29,175	
Doors		Interior Steel Doors incl hw	throughout	7	2	EA	\$0	
Doors		Interior Wood Doors incl hw	North Entrances	7	3	EA	\$0	
Doors		Interior Wood Doors incl hw	Main Entrance	7	2	EA	\$0	
Doors		Interior Wood Doors incl hw	throughout	7	65	EA	\$0	
Doors		Side-lite	North Entrances	7	2	SF	\$0	
Doors		Side-lite	Main Entrance	7	2	SF	\$0	
Doors		Transom Window	throughout	7	39	SF	\$0	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Drinking Fountains		Single Water Cooler	Entire Building	7	3	EA	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Bleacher Seating				EA	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Scoreboards				EA	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Sound System				EA	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Stage Curtain				EA	\$0	
Library		Casework	Basement	7	27	LF	\$0	
Library	Library	Casework	Basement			LF	\$0	
Library		Ceiling - Splined	Basement	6	550	SF	\$1,180	
Library		Flooring Tile/ Sheet	Basement	7	550	SF	\$0	
Library		Lighting - Pendant/ Surface	Basement	4	20	SF	\$132	
Library		Walls - Plaster/Drywall	Basement	7	500	SF	\$0	
Locker/Shower Room	Staff Restroom	Benches	basement storage room near stairs			LF	\$0	
Locker/Shower Room	Staff Restroom	Benches	Principal's office			LF	\$0	
Locker/Shower Room	Staff Restroom	Lockers	Principal's office			EA	\$0	
Locker/Shower Room	Staff Restroom	Lockers	basement storage room near stairs			EA	\$0	
Locker/Shower Room		Lockers	Basement	7	13	EA	\$0	
Locker/Shower Room	Staff Restroom	Showers	basement storage room near stairs			EA	\$0	
Locker/Shower Room	Staff Restroom	Showers	Principal's office			EA	\$0	
Lunchroom	Lunchroom	Ceiling - Plaster/Drywall	Basement	7	972	SF	\$0	
Lunchroom	Lunchroom	Flooring - Tile/Sheet	Basement	7	972	SF	\$0	
Lunchroom	Lunchroom	Lighting - Pendant/Surface	Basement	4	14	SF	\$92	
Lunchroom	Lunchroom	Serving Line	Basement	7	16	LF	\$0	
Lunchroom	Lunchroom	Wall - Plaster/Drywall	Basement	7	976	SF	\$0	
MDF/IDF		Finishes	3rd Floor	7	133	SF	\$0	
MDF/IDF		Ventilation and Cooling	3rd Floor	7	1	EA	\$0	
Mechanical/Service Rooms		Air Tunnels	Basement	7	260	SF	\$0	
Mechanical/Service Rooms		Boiler Room	Basement	7	1,804	SF	\$0	
Mechanical/Service Rooms		Janitor's Closet	Next to Room 106	6	1	SF	\$5	
Mechanical/Service Rooms		Janitor's Closet	Between Rooms 304 & 306	5	1	SF	\$11	
Mechanical/Service Rooms		Janitor's Closet	Between Rooms 206 & 205	6	1	SF	\$5	
Mechanical/Service Rooms		Mechanical/Service Rooms	Basement	7	260	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Basement	7	34	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Basement	7	136	SF	\$0	
Mechanical/Service Rooms		Storage Room	Room 302	6	60	SF	\$283	
Mechanical/Service Rooms		Storage Room	Room 306	6	113	SF	\$533	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Mechanical/Service Rooms		Storage Room	Basement	7	135	SF	\$0	
Mechanical/Service Rooms		Storage Room	Basement	7	124	SF	\$0	
Mechanical/Service Rooms		Storage Room	Room 206	6	113	SF	\$533	
Mechanical/Service Rooms		Storage Room	Room 202	6	76	SF	\$359	
Mechanical/Service Rooms		Storage Room	Basement	7	697	SF	\$0	
Mechanical/Service Rooms		Storage Room	Basement	7	195	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	Principal's office	7	40	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	2nd Floor	7	57	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	3rd Floor	7	57	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	basement storage room near stairs	6	114	SF	\$880	
Staff Restroom	Children's Standard Student Restroom	Accessories	Boy's Room in the Basement	7	554	SF	\$0	
Staff Restroom	Adult Standard Student Restroom	Accessories	Room 106	7	48	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	Basment Inside the Girl's Restroom	7	52	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	Girl's Room in Basement	7	642	SF	\$0	
Staff Restroom	Adult Standard Student Restroom	Ceiling - Lay-In	Room 106	7	48	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	Principal's office	7	40	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	basement storage room near stairs	6	114	SF	\$323	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	2nd Floor	7	57	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Plaster/Drywall	3rd Floor	7	57	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Splined	Basment Inside the Girl's Restroom	6	52	SF	\$112	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Splined	Boy's Room in the Basement	7	554	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Splined	Girl's Room in Basement	7	642	SF	\$0	
Staff Restroom	Staff Restroom	Floor Drain	Principal's office			EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	Girl's Room in Basement	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	basement storage room near stairs			EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	Boy's Room in the Basement	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Flooring - Concrete	Basment Inside the Girl's Restroom	7	52	SF	\$0	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Staff Restroom	Flooring - Concrete	basement storage room near stairs	7	114	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile Ceramic/Porcelain	3rd Floor	7	57	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile Ceramic/Porcelain	2nd Floor	7	57	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	Girl's Room in Basement	7	642	SF	\$0	
Staff Restroom	Adult Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	Room 106	7	48	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	Boy's Room in the Basement	7	554	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile/Sheet	Principal's office	6	40	SF	\$57	
Staff Restroom	Staff Restroom	Hand Dryer	Principal's office			EA	\$0	
Staff Restroom	Staff Restroom	Hand Dryer	3rd Floor	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Hand Dryer	2nd Floor	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	Girl's Room in Basement	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Hand Dryer	basement storage room near stairs			EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	Boy's Room in the Basement	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	3rd Floor	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	Girl's Room in Basement	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	Basment Inside the Girl's Restroom	7	1	EA	\$0	
Staff Restroom	Adult Standard Student Restroom	Lavatory	Room 106	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	Boy's Room in the Basement	7	4	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	basement storage room near stairs	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	Principal's office	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	2nd Floor	7	1	EA	\$0	
Staff Restroom	Adult Standard Student Restroom	Lighting - Lay-In	Room 106	4	1	SF	\$4	
Staff Restroom	Staff Restroom	Lighting - Pendant/ Surface	basement storage room near stairs	7	1	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	Boy's Room in the Basement	4	4	SF	\$17	
Staff Restroom	Staff Restroom	Lighting - Pendant/ Surface	Basment Inside the Girl's Restroom	4	1	SF	\$4	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	Girl's Room in Basement	4	5	SF	\$21	
Staff Restroom	Staff Restroom	Lighting - Pendant/ Surface	2nd Floor	4	1	SF	\$4	
Staff Restroom	Staff Restroom	Lighting - Pendant/ Surface	Principal's office	7	1	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Pendant/ Surface	3rd Floor	7	1	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	Boy's Room in the Basement	7	4	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	Girl's Room in Basement	7	8	EA	\$0	
Staff Restroom	Staff Restroom	Partitions	2nd Floor	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Partitions	basement storage room near stairs	6	1	EA	\$179	
Staff Restroom	Staff Restroom	Partitions	3rd Floor	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Partitions	Principal's office			EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Urinals	Boy's Room in the Basement	7	8	EA	\$0	
Staff Restroom	Staff Restroom	Urinals	2nd Floor	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Urinals	basement storage room near stairs			EA	\$0	
Staff Restroom	Staff Restroom	Urinals	Principal's office			EA	\$0	
Staff Restroom	Staff Restroom	Urinals	3rd Floor	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	basement storage room near stairs	6	112	SF	\$320	
Staff Restroom	Staff Restroom	Wall - Plaster/Drywall	3rd Floor	7	75	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Plaster/Drywall	Principal's office	7	260	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Plaster/Drywall	basement storage room near stairs	6	112	SF	\$264	
Staff Restroom	Adult Standard Student Restroom	Wall - Plaster/Drywall	Room 106	6	300	SF	\$708	
Staff Restroom	Staff Restroom	Wall - Plaster/Drywall	Basment Inside the Girl's Restroom	7	50	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	Girl's Room in Basement	7	600	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	Boy's Room in the Basement	7	650	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	Boy's Room in the Basement	7	4	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	2nd Floor	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	Girl's Room in Basement	7	10	EA	\$0	
Staff Restroom	Adult Standard Student Restroom	Water Closet	Room 106	7	1	EA	\$0	

Building: Main
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Staff Restroom	Water Closet	basement storage room near stairs	6	1	EA	\$372	
Staff Restroom	Staff Restroom	Water Closet	Principal's office	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	Basment Inside the Girl's Restroom	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	3rd Floor	7	1	EA	\$0	
INTERIOR Sub Total							\$123,837	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
ADMIN_CEILING	Administrative Suites/Offices	Administrative Office Ceiling	Main Office (Principal)	6	430	SF	\$1,218	
ADMIN_CEILING	Administrative Suites/Offices	Administrative Office Ceiling	104A (Book Storage)	6	227	SF	\$643	
ADMIN_FLOOR	Administrative Suites/Offices	Administrative Office Floor	Main Office (Principal)	6	430	SF	\$615	
ADMIN_FLOOR	Administrative Suites/Offices	Administrative Office Floor	104A (Book Storage)	6	227	SF	\$325	
ADMIN_FLOOR	Administrative Suites/Offices	Administrative Office Floor	3rd Floor Faculty Lounge	7	150	SF	\$0	
ADMIN_WALL	Administrative Suites/Offices	Administrative Office Walls	Main Office (Principal)	6	650	SF	\$1,534	
Casework	Classroom	Casework		6	3	LF	\$107	
Casework	Classroom	Casework		7	12	LF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	875	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	1,050	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	943	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	960	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		6	1,050	SF	\$2,973	
Ceiling	Classroom	Plaster/Drywall		6	960	SF	\$2,718	
Ceiling	Classroom	Plaster/Drywall		7	965	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	1,036	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	947	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	929	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	1,004	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	926	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	1,168	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	947	SF	\$0	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Ceiling	Classroom	Plaster/Drywall		7	960	SF	\$0	
Ceiling	Classroom	Plaster/Drywall		7	956	SF	\$0	
Ceiling	Classroom	Splined Ceiling		6	965	SF	\$2,070	
Chalk Board	Classroom	Chalk Board		4	45	LF	\$5,470	
Chalk Board	Classroom	Chalk Board		4	25	LF	\$3,039	
Chalk Board	Classroom	Chalk Board		4	45	LF	\$5,470	
Chalk Board	Classroom	Chalk Board		4	50	LF	\$6,078	
Chalk Board	Classroom	Chalk Board		4	50	LF	\$6,078	
Chalk Board	Classroom	Chalk Board		4	65	LF	\$7,901	
Chalk Board	Classroom	Chalk Board		4	10	LF	\$1,216	
Chalk Board	Classroom	Chalk Board		4	12	LF	\$1,459	
Chalk Board	Classroom	Chalk Board		4	20	LF	\$2,431	
Chalk Board	Classroom	Chalk Board		4	8	LF	\$972	
Chalk Board	Classroom	Chalk Board		4	8	LF	\$972	
Chalk Board	Classroom	Chalk Board		4		LF		
Chalk Board	Classroom	Chalk Board		4	45	LF	\$5,470	
Floor	Classroom	Wood		7	875	SF	\$0	
Floor	Classroom	Wood		6	947	SF	\$7,150	
Floor	Classroom	Wood		6	960	SF	\$7,248	
Floor	Classroom	Wood		6	1,050	SF	\$7,928	
Floor	Classroom	Wood		6	960	SF	\$7,248	
Floor	Classroom	Wood		6	965	SF	\$7,286	
Floor	Classroom	Wood		6	1,036	SF	\$7,822	
Floor	Classroom	Wood		6	943	SF	\$7,120	
Floor	Classroom	Wood		6	929	SF	\$7,014	
Floor	Classroom	Wood		6	1,004	SF	\$7,581	
Floor	Classroom	Wood		6	956	SF	\$7,218	
Floor	Classroom	Wood		6	926	SF	\$6,992	
Floor	Classroom	Wood		6	1,168	SF	\$8,819	
Floor	Classroom	Wood		6	965	SF	\$7,286	
Floor	Classroom	Wood		6	947	SF	\$7,150	
Floor	Classroom	Wood		6	960	SF	\$7,248	
Floor	Classroom	Wood		6	1,050	SF	\$7,928	
GYM_CEILING	Gymnasium.Auditorium	Gymnasia Ceiling				SF	\$0	
GYM_FLOOR	Gymnasium.Auditorium	Gymnasia Floor				SF	\$0	
GYM_LIGHT	Gymnasium.Auditorium	Gymnasia Lighting				EA	\$0	
GYM_WALL	Gymnasium.Auditorium	Gymnasia Walls				SF	\$0	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
LIBRARY_CEILING	Library	Library Ceiling	Basement		550	SF	\$0	
LIBRARY_FLOOR	Library	Library Floor	Basement		550	SF	\$0	
LIBRARY_LIGHTING	Library	Library Lighting	Basement			EA	\$0	
LIBRARY_WALL	Library	Library Walls	Basement			SF	\$0	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	15	EA	\$5,899	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	T-12
Lighting	Classroom	Pendant/Surface		7	12	EA	\$0	
Lighting	Classroom	Pendant/Surface		4	12	EA	\$4,719	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		7	12	EA	\$0	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		7	12	EA	\$0	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Lighting	Classroom	Pendant/Surface		4	13	EA	\$5,112	
Lighting	Classroom	Pendant/Surface		4	14	EA	\$5,506	
Marker Board	Classroom	Marker Board		7	10	LF	\$0	
Marker Board	Classroom	Marker Board		7	4	LF	\$0	
Marker Board	Classroom	Marker Board		7	4	LF	\$0	
Marker Board	Classroom	Marker Board		7	4	LF	\$0	
Marker Board	Classroom	Marker Board		7	4	LF	\$0	
Marker Board	Classroom	Marker Board		7	4	LF	\$0	
Marker Board	Classroom	Marker Board		7	14	LF	\$0	
Marker Board	Classroom	Marker Board		7	8	LF	\$0	
Marker Board	Classroom	Marker Board		7	4	LF	\$0	
Marker Board	Classroom	Marker Board		7	8	LF	\$0	
Marker Board	Classroom	Marker Board		7	6	LF	\$0	
Marker Board	Classroom	Marker Board		7	4	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
RESTROOM_WALL	Staff Restroom	Restroom Walls	2nd Floor	7	75	SF	\$0	
Wall	Classroom	Masonry		6	300	SF	\$3,861	
Wall	Classroom	Masonry		6	275	SF	\$3,539	
Wall	Classroom	Masonry		6	375	SF	\$4,826	

Building: Main
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Wall	Classroom	Masonry		6	275	SF	\$3,539	
Wall	Classroom	Masonry		6	375	SF	\$4,826	
Wall	Classroom	Masonry		6	275	SF	\$3,539	
Wall	Classroom	Masonry		6	275	SF	\$3,539	
Wall	Classroom	Plaster/Drywall		7	690	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	675	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	896	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	850	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	769	SF	\$0	
Wall	Classroom	Plaster/Drywall		6	1,275	SF	\$3,008	
Wall	Classroom	Plaster/Drywall		7	754	SF	\$0	
Wall	Classroom	Plaster/Drywall		6	1,000	SF	\$2,360	
Wall	Classroom	Plaster/Drywall		6	1,000	SF	\$2,360	
Wall	Classroom	Plaster/Drywall		6	1,250	SF	\$2,949	
Wall	Classroom	Plaster/Drywall		6	900	SF	\$2,124	
Wall	Classroom	Plaster/Drywall		6	1,000	SF	\$2,360	
Wall	Classroom	Plaster/Drywall		6	1,250	SF	\$2,949	
Wall	Classroom	Plaster/Drywall		6	1,000	SF	\$2,360	
Wall	Classroom	Plaster/Drywall		7	535	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	595	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	861	SF	\$0	

ROOM Sub Total \$307,730

Building Main Sub Total \$2,186,960

Building: SITE
Category: SITE

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Civil/Drainage		Site Manhole	Entire site	7	4	EA	\$0	
Fencing		Chain Link	North Entrances	6	39	LF	\$559	Painting required
Fencing		Iron and Concrete Post	North Entrances	5	12	LF	\$601	Major deterioration
Fencing		Ornamental Iron	Entire site	5	391	LF	\$24,356	Bent posts, rust, deterioration throughout
Landscape		Benches	West Entrances	7	1	EA	\$0	
Landscape		Grass	West Entrances	5	1,897	SF	\$2,469	Seeding and watering required
Landscape		Hardscape - Concrete	North Courtyard	6	1,626	SF	\$3,069	

Building: SITE
Category: SITE

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Landscape		Hardscape - Concrete	North Courtyard	5	250	SF	\$1,559	Replace damaged slabs, repair large cracks
Landscape		Parkway trees	West side	7	2	EA	\$0	
Landscape		Retaining Wall - Masonry	Entire site	5	198	SF	\$9,250	Repoint, replace missing stones
Landscape		Trash Receptacles	North Entrances	6	1	EA	\$208	
Parking Lot		Asphalt	East Entrances	5	232	SF	\$657	Patch large holes
Parking Lot		Asphalt	East Entrances	6	3,050	SF	\$2,617	Grind, coat, seal, and restripe
Playground		Playground Equipment - School Age 5-12	West Entrances	7	1	EA	\$0	
Playground		Playground Surfacing - Square Rubber Mats	West Entrances	4	1,604	SF	\$35,553	Replace with poured surface
Sidewalks		Internal Walks	Entire site	5	115	LF	\$3,582	
Sidewalks		Perimeter Sidewalks	Entire site	6	4,264	SF	\$8,049	
SITE Sub Total							\$92,527	
SITE Sub Total							\$92,527	

Total Campus Need ^{2 3} \$2,279,487

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Room Summary

Room Number	Room Size	Voice Outlet	Data Outlet	Elect Outlet	Noise Level	Glaze Window Area	Operable Window Area	No. of Window AC	Window Stop	Smart Board	Power Strip	Room Type	Room Sub Type	Location
Building: Main														
101	965	2	2	6	53	414	126	1	N	N	Y	Classroom		
102	947	2	1	20	53	414	104	1	N	N	Y	Classroom		
103	1168	2	2	18	53	414	126	1	N	N	Y	Classroom		
105	926	2	2	12	53	414	126	1	N	N	Y	Classroom		
106	960	1	0	12	53	414	104	1	N	N	Y	Classroom		
201	956	2	2	12	53	414	126	1	N	N	Y	Classroom		
202	875	1	0	12	53	414	104	1	N	N	Y	Classroom		
203	1004	2	2	12	53	414	126	1	N	N	Y	Classroom		
204	929	2	2	15	53	414	126	1	N	N	Y	Classroom		
205	1050	1	1	20	53	184	52	1	N	N	Y	Classroom		
206	960	0	1	12	53	414	104	1	N	N	Y	Classroom		
300	1050	2	2	8	53	230	65	1	N	N	Y	Classroom		
301	943	2	36	40	53	368	112	2	N	N	Y	Classroom		
303	1036	2	2	12	53	184	56	1	N	N	Y	Classroom		
304	947	2	1	20	53	414	104	1	N	N	Y	Classroom		
305	965	2	2	4	53	414	126	1	N	N	Y	Classroom		
306	960	1	2	8	53	414	104	1	N	N	Y	Classroom		
Other	232			4					N	N	Y	Administrative Suites/Offices		Basement - Building Engineer's Office
Other	554								N	N	N	Restroom	Children's Standard Student Restroom	Boy's Room in the Basement
Other	364			6					N	N	Y	Administrative Suites/Offices		Teacher's Lounge in Basement
Other	285			4					N	N	Y	Administrative Suites/Offices		Basement - Counselor's Office near Pump Room
Other	550								N	N	N	Library		Basement
Other	250			4					N	N	Y	Administrative Suites/Offices		Reception-1st Floor
Other	430			8					N	N	Y	Administrative Suites/Offices		Main Office (Principal)
Other	227			6					N	N	Y	Administrative Suites/Offices		104A (Book Storage)
Other	55			2					N	N	Y	Administrative Suites/Offices		PE Teacher's Office in Basement by Library
Other	48								N	N	N	Restroom	Adult Standard Student Restroom	Room 106
Other	642								N	N	N	Restroom	Children's Standard Student Restroom	Girl's Room in Basement
Other	223			2					N	N	Y	Administrative Suites/Offices		3rd Floor Office near Room 305
Other	248			6					N	N	Y	Administrative Suites/Offices		Basement Lunch Room Manager's Office
Other	972								N	N	N	Lunch & Multipurpose Room	Lunchroom	Basement
Other	223			2					N	N	Y	Administrative Suites/Offices		1st Floor Office near Room 105
Other	57								N	N	N	Restroom	Staff Restroom	3rd Floor
Other	223			2					N	N	Y	Administrative Suites/Offices		2nd Floor Office near Room 205

Room Summary

Room Number	Room Size	Voice Outlet	Data Outlet	Elect Outlet	Noise Level	Glaze Window Area	Operable Window Area	No. of Window AC	Window Stop	Smart Board	Power Strip	Room Type	Room Sub Type	Location
Other	114								N	N	N	Restroom	Staff Restroom	basement storage room near stairs
Other	40								N	N	N	Restroom	Staff Restroom	Principal's office
Other									N	N	N	Gymnasia	Gymnasium.Auditorium	
Other	57								N	N	N	Restroom	Staff Restroom	2nd Floor
Other	150			2					N	N	Y	Administrative Suites/Offices		3rd Floor Faculty Lounge
Other	150			2					N	N	Y	Administrative Suites/Offices		2nd Floor Faculty Lounge
Other	52								N	N	N	Restroom	Staff Restroom	Basment Inside the Girl's Restroom