

6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Kennedy | 1965 | 3 | 233,791 | \$8,414,916 |
| Kinzie | 1954 | 2 | 111,615 | \$4,403,405 |
| SITE | | | | \$395,598 |
| Campus Total | | | 345,406 | \$13,213,919 |

Building: Kennedy

| _ | ory: Dananig Extorior | | | | | _ | _ |
|--------|--|--------------|----------|------|------|---------|----------|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Entran | e | | | | | | |
| | Entrance Control - Audio and Video | 1- Main | 1 | EA | 7 | \$0 | |
| | Entrance Control - Audio and Video | 12 | 1 | EA | 7 | \$0 | |
| | Entrance Control - Audio and Video | 9 | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior FRP Door | 10 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior FRP Door | 14 | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | 2 | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | 7 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior FRP Door | 8 | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior FRP Door | 9 | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior Steel Door | 11 | 1 | EΑ | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 13 | 1 | EΑ | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 3 | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 4 | 2 | EA | 5 | \$2,683 | |
| | Exterior Doors - Exterior Steel Door | 5 | 1 | EA | 4 | \$3,823 | corroded |
| | Exterior Doors - Exterior Steel Door | 6 | 1 | EA | 5 | \$1,341 | |
| | Exterior Doors - Exterior Steel Door | Roof | 4 | EA | 5 | \$5,365 | corroded |
| | Exterior Doors - Overhead Rolling/ Garage Door | Loading Dock | 1 | EA | 5 | \$3,942 | |
| | Exterior Doors - Side lite | 14 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Side lite | 2 | 2 | EA | 7 | \$0 | |
| | | | | | | | |



Co-locating on this campus are KENNEDY HS and KINZIE

6325 W 56th St Chicago, IL 60638

Building: Kennedy

| C== | Man Time | l costia : | O. and the | l les!d | Danis | 0 | Comments |
|--------|---------------------------------------|------------|------------|---------|-------|------------|----------|
| • | Item - Type | Location | Quantity | Unit | Kank | Cost | Comments |
| Entran | | 4 Main | | Ε. | 7 | <u>ф</u> о | |
| | Exterior Doors - Store Front | 1- Main | 6 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | 12 | 8 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | 14 | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 1- Main | 6 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 10 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 12 | 8 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 14 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 2 | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 9 | 2 | EA | 6 | \$627 | |
| | Exterior Stairs - Concrete | 1- Main | 2 | LF | 4 | \$327 | broken |
| | Exterior Stairs - Concrete | 1- Main | 138 | LF | 7 | \$0 | |
| | Exterior Stairs - Concrete | 10 | 25 | LF | 7 | \$0 | |
| | Exterior Stairs - Concrete | 11 | 16 | LF | 6 | \$1,308 | |
| | Exterior Stairs - Concrete | 12 | 144 | LF | 7 | \$0 | |
| | Exterior Stairs - Concrete | 13 | 36 | LF | 6 | \$2,944 | |
| | Exterior Stairs - Concrete | 14 | 105 | LF | 7 | \$0 | |
| | Exterior Stairs - Concrete | 2 | 105 | LF | 6 | \$8,586 | |
| | Exterior Stairs - Concrete | 3 | 25 | LF | 6 | \$2,044 | |
| | Exterior Stairs - Concrete | 7 | 15 | LF | 7 | \$0 | |
| | Power Door Operator and Controls | 1- Main | 1 | EΑ | 7 | \$0 | |
| | Power Door Operator and Controls | 12 | 1 | EA | 7 | \$0 | |
| | Power Door Operator and Controls | 9 | 1 | EA | 7 | \$0 | |
| | Ramp Handrail - Steel_Ramp Handrail | 1- Main | 320 | LF | 6 | \$2,773 | |
| | Ramp Handrail - Steel_Ramp Handrail | 12 | 30 | LF | 6 | \$260 | |
| | Ramp Handrail - Steel_Ramp Handrail | 14 | 120 | LF | 5 | \$1,272 | corroded |
| | Ramp Handrail - Steel_Ramp Handrail | 6 | 120 | LF | 6 | \$1,040 | |
| | Ramp Handrail - Steel_Ramp Handrail | 9 | 96 | LF | 7 | \$0 | |
| | Ramps - Concrete | 1- Main | 157 | LF | 7 | \$0 | |
| | Ramps - Concrete | 12 | 15 | LF | 7 | \$0 | |
| | Ramps - Concrete | 14 | 57 | LF | 6 | \$8,563 | |
| | Ramps - Concrete | 6 | 57 | LF | 6 | \$8,563 | |
| | Ramps - Concrete | 9 | 48 | LF | 7 | \$0 | |
| | Stair Handrail - Steel_Stair Handrail | 1- Main | 40 | LF | 6 | \$347 | |
| | Stair Handrail - Steel_Stair Handrail | 10 | 16 | LF | 6 | \$139 | |
| | Stair Handrail - Steel_Stair Handrail | 11 | 5 | LF | 5 | \$57 | corroded |
| | Stair Handrail - Steel_Stair Handrail | 12 | 42 | LF | 7 | \$0 | |
| | Stair Handrail - Steel_Stair Handrail | 13 | 5 | LF | 5 | \$57 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Strain-Paramote | _ | Item - Tyne | Location | Quantity | Unit | Rank | Cost | Comments |
|--|----------|--|-----------------|----------|-------|--------|----------|------------------------|
| Stair Handrala Stael, Stair Handrala 14 | • | •• | Location | Quantity | Offic | Italik | COSI | Comments |
| Stair Handrail - Steel, Stair Handrail 2 40 LF 6 S347 Stair Handrail - Steel, Stair Handrail 2 16 5 557 coroded Foundation - Steel, Stair Handrail 7 1615 LF 7 500 coroded Foundation - Concrete Entire Building 3,400 SF 7 500 coroded Superstructure - Concrete Entire Building 3,400 SF 7 500 coroded Superstructure - Concrete Entire Building 1,9 E 7 500 coroded Exterior Lighting - Parapet or Roaf Mounted Entire Building 1,9 E 4 51,000 missing light Exterior Lighting - Wall Mounted Entire Building 1,9 E 6 \$3,17 500 coroded 500 500 500 600 500 600 500 600 500 600 500 600 50,17 7 500 7 7 500 <td>Littiano</td> <td></td> <td>14</td> <td>40</td> <td>IF</td> <td>6</td> <td>\$347</td> <td></td> | Littiano | | 14 | 40 | IF | 6 | \$347 | |
| Stair Handral - Steel Stair Handrall 3 5 LF 5 S67 Foundation - Concrete Entire Building 1.615 LF 7 500 Equation - Concrete Entire Building 1.615 LF 7 500 Superstructure - Concrete Entire Building 3,400 SF 7 500 Superstructure - Concrete Entire Building 1.615 LF 7 500 Exterior Lighting - Perapet or Roof Mounted Entire Building 11 EA 7 500 missing light Exterior Lighting - Wall Mounted Entire Building 11 EA 4 \$1,000 missing light Exterior Lighting - Wall Mounted Entire Building 11 EA 4 \$1,000 missing light Exterior Lighting - Wall Mounted Entire Building 11 EA 5 \$3,700 missing light Coping - Wall Mounted Entire Building 11 EA 6 \$4,712 missing light Exterior Lighting - Wall Mounted <td< td=""><td></td><td>_</td><td></td><td></td><td></td><td></td><td></td><td></td></td<> | | _ | | | | | | |
| Stair Handrail - Steel _ Stair Handrail - Stair Hand | | | | | | | | |
| Foundation - Concrete Entire Building 3,40 SF 7 \$0 \$0 \$0 \$0 \$0 \$0 \$0 | | _ | | | | | | corroded |
| Foundation - Concrete Entire Building 1,815 LF 7 \$0 Superstructure - Concrete Entire Building 3,400 SF 7 \$0 Superstructure - Concrete Entire Building 233,71 SF 7 \$0 Superstructure - Concrete Entire Building 233,71 SF 7 \$0 Superstructure - Concrete Entire Building SF 7 \$0 Superstructure - Concrete SF SF SF SF SF SF SF S | | Stall Hallurali - Stea_Stall Hallurali | , | 10 | LI | 3 | ψΠΟ | Corroded |
| Superstructure - Concrete Entire Building 3,400 SF 7 \$0 \$0 \$1 \$1 \$1 \$1 \$1 \$1 | Founda | tion | | | | | | |
| Lighting | | Foundation - Concrete | Entire Building | 1,615 | LF | 7 | \$0 | |
| Exterior Lighting - Parapet or Roof Mounted Entire Building 19 EA 7 \$0 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$3.176 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$3.176 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$3.176 Exterior Lighting - Wall Mounted Entire Building Exterior Lighting - Wall Mounted Entire Building Exterior Lighting - Wall Mounted Entire Building Exterior Lighting - Wall Mounted Exterior Lighti | | Superstructure - Concrete | Entire Building | 3,400 | SF | 7 | \$0 | |
| Exterior Lighting - Parapet or Roof Mounted Entire Building 19 EA 7 \$ \$0 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$ \$3.176 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$ \$3.176 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$ \$3.176 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$ \$3.176 Exterior Lighting - Wall Mounted Entire Building Entire Building Exterior Lighting - Wall Mounted Entire Building Entire Building Exterior Lighting - Wall Mounted Exterior Lighting - W | | Superstructure - Concrete | Entire Building | 233,791 | SF | 7 | \$0 | |
| Exterior Lighting - Parapet or Roof Mounted Entire Building 19 EA 7 \$ \$0 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$ \$3.176 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$ \$3.176 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$ \$3.176 Exterior Lighting - Wall Mounted Entire Building 11 EA 6 \$ \$3.176 Exterior Lighting - Wall Mounted Entire Building Entire Building Exterior Lighting - Wall Mounted Entire Building Entire Building Exterior Lighting - Wall Mounted Exterior Lighting - W | Lighting | 1 | | | | | | |
| Exterior Lighting - Wall Mounted Entire Bullding 1 | Lighting | | Entire Building | 19 | FΔ | 7 | \$0 | |
| Exterior Lighting - Wall Mounted Entire Building 11 | | | · · | | | | | missing light |
| Exterior Lighting - Wall Mounted Entire Building 2 | | | ŭ | | | | | This sing light |
| Chimney - Brick Chimney- Concrete/ Mortar Liner | | | | | | | | |
| Chimney - Brick Chimney- Concrete/ Mortar Liner | | | g | _ | _, . | • | Ψ. | |
| Coping - Metal C 178 LF 6 \$5,717 gravel stop Coping - Metal D 482 LF 6 \$15,481 gravel stop Coping - Metal F 1,261 LF 6 \$40,501 Coping - Metal I 278 LF 6 \$8,929 gravel stop Coping - Metal J 50 LF 7 \$0 gravel stop Coping - Metal J 50 LF 7 \$0 gravel stop Coping - Metal J 50 LF 7 \$0 gravel stop Coping - Metal J 50 LF 7 \$0 gravel stop Downspouts - Interior Downspouts E 22 LF 7 \$0 gravel stop Downspouts - Interior Downspouts F 766 LF 7 \$0 gravel stop Roof Structure - Concrete C 1,598 SF 7 \$0 gravel stop Roof Structure - Co | Roof Sy | | | | | | | |
| Coping - Metal D 482 LF 6 \$15,481 gravel stop Coping - Metal F 1,261 LF 6 \$40,501 Coping - Metal H 190 LF 6 \$61,02 gravel stop Coping - Metal J 278 LF 6 \$8,929 gravel stop Coping - Metal J 50 LF 7 \$0 gravel stop Downspouts - Interior Downspouts D 60 LF 7 \$0 Downspouts - Interior Downspouts E 22 LF 7 \$0 Downspouts - Interior Downspouts F 766 LF 7 \$0 Downspouts - Interior Downspouts H 120 LF 7 \$0 Downspouts - Interior Downspouts I 22 LF 6 \$731 Roof Structure - Concrete D 9,512 SF 7 \$0 Roof Structure - Concrete E 1,612 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete H 8,349 SF 7 | | | | | | 6 | | |
| Coping - Metal F 1,261 LF 6 \$40,501 Coping - Metal H 190 LF 6 \$8,102 gravel stop Coping - Metal I 278 LF 6 \$8,929 gravel stop Coping - Metal J 50 LF 7 \$0 gravel stop Downspouts - Interior Downspouts D 60 LF 7 \$0 Downspouts - Interior Downspouts F 766 LF 7 \$0 Downspouts - Interior Downspouts F 766 LF 7 \$0 Downspouts - Interior Downspouts H 120 LF 7 \$0 Downspouts - Interior Downspouts I 22 LF 6 \$731 Roof Structure - Concrete D 9,512 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete H 8,349 SF 7 \$0 | | | | | | 6 | | gravel stop |
| Coping - Metal H 190 LF 6 \$6,102 gravel stop Coping - Metal I 278 LF 6 \$8,929 gravel stop Coping - Metal J 50 LF 7 \$0 gravel stop Downspouts - Interior Downspouts D 60 LF 7 \$0 gravel stop Downspouts - Interior Downspouts E 22 LF 7 \$0 | | | | | | | | gravel stop |
| Coping - Metal I 278 LF 6 \$8,929 gravel stop Coping - Metal J 50 LF 7 \$0 gravel stop Downspouts - Interior Downspouts D 60 LF 7 \$0 Downspouts - Interior Downspouts E 22 LF 7 \$0 Downspouts - Interior Downspouts H 120 LF 7 \$0 Downspouts - Interior Downspouts H 120 LF 7 \$0 Downspouts - Interior Downspouts H 120 LF 7 \$0 Roof Structure - Concrete C 1,596 SF 7 \$0 Roof Structure - Concrete D 9,512 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete G 3,400 SF 7 \$0 Roof Structure - Concrete H 8,349 SF 7 \$0 Roof Str | | | • | 1,261 | | 6 | | |
| Coping - Metal J S B LF 7 S Gravel stop Downspouts - Interior Downspouts B E 22 LF 7 S S D Downspouts - Interior Downspouts B E 22 LF 7 S S D Downspouts - Interior Downspouts F F F F F F F F F F F F F F F F F F F | | | Н | 190 | | 6 | | |
| Downspouts - Interior Downspouts D 60 LF 7 \$0 Downspouts - Interior Downspouts E 22 LF 7 \$0 Downspouts - Interior Downspouts F 766 LF 7 \$0 Downspouts - Interior Downspouts H 120 LF 7 \$0 Downspouts - Interior Downspouts I 22 LF 6 \$731 Roof Structure - Concrete C 1,596 SF 7 \$0 Roof Structure - Concrete D 9,512 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete H 8,349 SF 7 \$0 Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete < | | | I | | | | | |
| Downspouts - Interior Downspouts E 22 LF 7 \$0 Downspouts - Interior Downspouts F 766 LF 7 \$0 Downspouts - Interior Downspouts H 120 LF 7 \$0 Downspouts - Interior Downspouts I 22 LF 6 \$731 Roof Structure - Concrete C 1,596 SF 7 \$0 Roof Structure - Concrete D 9,512 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete G 3,400 SF 7 \$0 Roof Structure - Concrete H 8,349 SF 7 \$0 Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof Structure - Concrete J 9,512 SF 6 \$96,711 | | · - | J | 50 | LF | 7 | \$0 | gravel stop |
| Downspouts - Interior Downspouts F 766 LF 7 \$0 Downspouts - Interior Downspouts H 120 LF 7 \$0 Downspouts - Interior Downspouts I 22 LF 6 \$731 Roof Structure - Concrete C 1,596 SF 7 \$0 Roof Structure - Concrete D 9,512 SF 7 \$0 Roof Structure - Concrete E 1,612 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete H 8,349 SF 7 \$0 Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof Structure - Concrete J 55 7 \$0 Roof Structure - Concrete J 55 7 \$0 Roof - Asphalt Gravel Ballast D 9,512 SF | | Downspouts - Interior Downspouts | D | 60 | | 7 | \$0 | |
| Downspouts - Interior Downspouts H 120 LF 7 \$0 Downspouts - Interior Downspouts I 22 LF 6 \$731 Roof Structure - Concrete C 1,596 SF 7 \$0 Roof Structure - Concrete D 9,512 SF 7 \$0 Roof Structure - Concrete E 1,612 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete H 8,349 SF 7 \$0 Roof Structure - Concrete H 8,349 SF 7 \$0 Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof Structure - Concrete J 9,512 SF 6 \$96,711 | | | | 22 | | 7 | | |
| Downspouts - Interior Downspouts | | | F | 766 | LF | 7 | | |
| Roof Structure - Concrete C 1,596 SF 7 \$0 Roof Structure - Concrete D 9,512 SF 7 \$0 Roof Structure - Concrete E 1,612 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete G 3,400 SF 7 \$0 cracked edges; sundeck Roof Structure - Concrete H 8,349 SF 7 \$0 Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof - Asphalt Gravel Ballast D 9,512 SF 6 \$96,711 | | Downspouts - Interior Downspouts | Н | 120 | | 7 | | |
| Roof Structure - Concrete D 9,512 SF 7 \$0 Roof Structure - Concrete E 1,612 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete G 3,400 SF 7 \$0 cracked edges; sundeck Roof Structure - Concrete H 8,349 SF 7 \$0 \$0 Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof - Asphalt Gravel Ballast D 9,512 SF 6 \$96,711 | | Downspouts - Interior Downspouts | I | 22 | LF | 6 | | |
| Roof Structure - Concrete E 1,612 SF 7 \$0 Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete G 3,400 SF 7 \$0 cracked edges; sundeck Roof Structure - Concrete H 8,349 SF 7 \$0 so Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof - Asphalt Gravel Ballast D 9,512 SF 6 \$96,711 | | Roof Structure - Concrete | С | 1,596 | SF | 7 | \$0 | |
| Roof Structure - Concrete F 51,045 SF 7 \$0 Roof Structure - Concrete G 3,400 SF 7 \$0 cracked edges; sundeck Roof Structure - Concrete H 8,349 SF 7 \$0 Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof - Asphalt Gravel Ballast D 9,512 SF 6 \$96,711 | | Roof Structure - Concrete | = | , | SF | 7 | | |
| Roof Structure - Concrete G 3,400 SF 7 \$0 cracked edges; sundeck Roof Structure - Concrete H 8,349 SF 7 \$0 Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof - Asphalt Gravel Ballast D 9,512 SF 6 \$96,711 | | Roof Structure - Concrete | | 1,612 | SF | 7 | | |
| Roof Structure - Concrete H 8,349 SF 7 \$0 Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof - Asphalt Gravel Ballast D 9,512 SF 6 \$96,711 | | Roof Structure - Concrete | F | 51,045 | SF | 7 | \$0 | |
| Roof Structure - Concrete I 7,732 SF 7 \$0 Roof Structure - Concrete J 150 SF 7 \$0 Roof - Asphalt Gravel Ballast D 9,512 SF 6 \$96,711 | | Roof Structure - Concrete | G | 3,400 | SF | 7 | | cracked edges; sundeck |
| Roof Structure - Concrete J 150 SF 7 \$0 Roof - Asphalt Gravel Ballast D 9,512 SF 6 \$96,711 | | Roof Structure - Concrete | Н | 8,349 | SF | 7 | \$0 | |
| Roof - Asphalt Gravel Ballast D 9,512 SF 6 \$96,711 | | Roof Structure - Concrete | 1 | 7,732 | SF | 7 | \$0 | |
| | | | J | | | 7 | | |
| Roof - Asphalt Gravel Ballast E 1,612 SF 6 \$16,390 | | | | | | 6 | | |
| | | Roof - Asphalt Gravel Ballast | Е | 1,612 | SF | 6 | \$16,390 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|-----------------|----------|------|------|-----------|------------------------------------|
| Roof S | ystem | | | | | | |
| | Roof - Asphalt Gravel Ballast | F | 50,895 | SF | 6 | \$517,465 | |
| | Roof - Asphalt Gravel Ballast | F | 120 | SF | 5 | \$3,719 | ponding |
| | Roof - Asphalt Gravel Ballast | Н | 8,349 | SF | 6 | \$84,887 | |
| | Roof - Asphalt Gravel Ballast | I | 7,732 | SF | 6 | \$78,614 | |
| | Roof - EPDM/ Synthetic Rubber | G | 3,400 | SF | 6 | \$28,783 | epoxy; sundeck |
| | Roof - Modified Bitumen | С | 1,596 | SF | 6 | \$15,017 | ponding |
| | Roof - Modified Bitumen | J | 150 | SF | 7 | \$0 | |
| Walls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building | 300 | SF | 5 | \$30,223 | cracks |
| | Canopy - Concrete/ Stucco | Entire Building | 222 | SF | 6 | \$8,136 | |
| | Canopy - Metal | Entire Building | 692 | SF | 7 | \$0 | |
| | Canopy - Metal | Entire Building | 320 | SF | 6 | \$7,871 | corroded |
| | Canopy - Metal | Entire Building | 24 | SF | 5 | \$1,763 | corroded, holes |
| | Cheek-Wall - Concrete | Entire Building | 500 | SF | 7 | \$0 | |
| | Cheek-Wall - Concrete | Entire Building | 94 | SF | 6 | \$964 | cracks |
| | Exterior Walls - Brick | Entire Building | 520 | SF | 7 | \$0 | ceramic tile |
| | Exterior Walls - Brick | Entire Building | 2,385 | SF | 5 | \$56,786 | open joints |
| | Exterior Walls - Brick | Entire Building | 40 | SF | 4 | \$6,586 | cracks at lintels |
| | Exterior Walls - Brick | Entire Building | 21,440 | SF | 6 | \$144,098 | deteriorated |
| | Exterior Walls - Brick | Entire Building | 20 | SF | 5 | \$476 | cracked at jambs of tiled area |
| | Exterior Walls - Prefabricated Metal Panel Wall | Entire Building | 2,700 | SF | 7 | \$0 | |
| | Exterior Walls - Stone-Cut | Entire Building | 5,250 | SF | 6 | \$35,285 | deteriorated joints |
| Windov | vs | | | | | | |
| | Guard - Guards perforated | Entire Building | 588 | SF | 7 | \$0 | |
| | Guard - Guards wire guard | Entire Building | 200 | SF | 6 | \$2,554 | |
| | Lintels - Concrete | Entire Building | 45 | LF | 7 | \$0 | |
| | Lintels - Steel | Entire Building | 700 | LF | 5 | \$236,576 | corrosion |
| | Lintels - Steel | Entire Building | 6 | LF | 4 | \$2,717 | corroded, sagging |
| | Lintels - Steel | Entire Building | 21 | LF | 7 | \$0 | |
| | Lintels - Steel | Entire Building | 21 | LF | 5 | \$7,097 | corroded |
| | Lintels - Stone | Entire Building | 128 | LF | 7 | \$0 | |
| | Windows - Insulated Panel | Entire Building | 10,000 | SF | 6 | \$74,646 | |
| | Windows - Insulated Panel | Entire Building | 1,185 | SF | 5 | \$37,348 | corroded |
| | Windows - Sash Aluminum Double-pane | Entire Building | 17,335 | SF | 7 | \$0 | interior storms for sound-proofing |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

Category: Building Exterior

Group Item - Type Location Quantity Unit Rank Cost Comments

Building Exterior Subtotal: \$1,686,269

Building: Kennedy

Category: Electrical System

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---|----------------------------|----------|------|------|----------|--------------------------------------|
| nerge | ency System | | | | | | |
| | Automatic Transfer Switch | Entire Building | 2 | EA | 7 | \$0 | |
| | Emergency A/C Power - Auditoium and Aisle Lighting | Entire Building | 7,260 | SF | 6 | \$3,841 | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 31,543 | SF | 6 | \$9,472 | |
| | Emergency A/C Power - Gym | Entire Building | 13,083 | SF | 6 | \$4,864 | |
| | Emergency A/C Power - Students Toilets | Entire Building | 4,341 | SF | 6 | \$1,614 | |
| | Emergency Battery Packs - Lunchrooms | Entire Building | 1 | EA | 4 | \$579 | Greater than 20 years old |
| | Emergency Generator- Outdoor- Diesel - 101 - 150 KW | South Courtyard | 1 | EA | 6 | \$11,529 | |
| | Exit Signs - Auditoium | Entire Building | 12 | EA | 6 | \$1,797 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 64 | EA | 6 | \$9,584 | |
| | Exit Signs - Gym | Entire Building | 5 | EA | 6 | \$787 | |
| | Exit Signs - Gym | Entire Building | 1 | EA | 2 | \$578 | broken |
| | Exit Signs - Lunchroom | Entire Building | 4 | EA | 6 | \$599 | |
| | Exit Signs - Pool | Entire Building | 4 | EA | 6 | \$620 | |
| | Security System - CCTV | Entire Building | 233,791 | SF | 6 | \$70,207 | |
| | Security System - Intrusion Detection | Entire Building | 233,791 | SF | 6 | \$60,178 | |
| in Se | ervice | | | | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 7 | \$0 | |
| | Main Electrical Service - 2001 to 3000 A 277/480/3PH | Basement / Electrical Room | 1 | EA | 7 | \$0 | |
| | Main Electrical Service - Greater than 3000 A 120/208/3PH | Basement / Electrical Room | 1 | EA | 6 | \$16,381 | |
| | PA System | Entire Building | 233,791 | SF | 6 | \$76,894 | |
| wer D | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 4 | EA | 6 | \$1,196 | |
| | Lighting and Power Panels - 100 A | Entire Building | 6 | EA | 4 | \$29,096 | Panels are old and in poor condition |
| | Lighting and Power Panels - 100 A | Entire Building | 28 | EA | 7 | \$0 | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 2 | EA | 4 | \$42,209 | Panels are old and in poor condition |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 2 | EA | 7 | \$0 | • |
| | Transformers - 277/480 - 120/208 | Entire Building | 3 | EA | 7 | \$0 | |

Electrical System Subtotal:

\$342,027



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

Category: Safty System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost (| Comments |
|--------------------------|-----------------|----------|------|------|-----------|----------|
| Fire Alarm | | | | | | |
| Fire Alarm Panel | Entire Building | 1 | EA | 7 | \$0 | |
| Fire Alarm Strobe Lights | Entire Building | 233,791 | SF | 6 | \$83,580 | |
| Fire Alarm_System | Entire Building | 233,791 | SF | 6 | \$113,669 | |
| | | | | | | |

Safty System Subtotal: \$197,249

Building: Kennedy

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|----------------------------|----------|------|------|-----------|---|
| Air Con | ditioning | | | | | | |
| | Chemical Pot Feeder | Roof / Boiler Room | 1 | EA | 6 | \$606 | |
| | Chiller-Air Cooled-Screw Type-Roof Mounted - 201 - 300 tons | Roof | 2 | EA | 6 | \$8,628 | |
| | Condensing Unit- Ground Mounted - Less than 5 tons | Basement / Entire Building | 3 | EA | 7 | \$0 | |
| Air Han | dling Systems | | | | | | |
| | Air Handling Unit- Built Up- Single Zone- Steam Coils and Chilled Water Coils - 8001 - 15000 cfm | Basement | 1 | EA | 6 | \$4,341 | Serves auditorium |
| | Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils and Chilled Water Coils - 25001 - 35000 cfm | Basement | 2 | EA | 6 | \$13,022 | 2 supply fans with shared return, heating coil, coiling coil, and OA intake |
| | Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils and Chilled Water Coils - Less than 8000 cfm | Basement | 1 | EA | 6 | \$3,321 | |
| | Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 8001- 12000 cfm | Basement | 4 | EA | 5 | \$136,700 | |
| | Air Intake | Basement | 1 | EA | 6 | \$5,765 | AHU's #1, 2, 3, and 4 share OA intake and RA plenum |
| | Air Intake | Basement / Roof | 1 | EA | 7 | \$0 | |
| | Air Intake | Basement / Roof | 1 | EA | 7 | \$0 | |
| | Air Intake | Basement / Roof | 1 | EA | 6 | \$5,765 | |
| | Auxiliaries - 25001 - 35000 cfm | Basement | 2 | EA | 6 | \$13,022 | |
| | Auxiliaries - 8001 - 15000 cfm | Basement | 1 | EA | 7 | \$0 | |
| | Auxiliaries - 8001-12000 cfm | Basement | 4 | EA | 5 | \$0 | |
| | Auxiliaries - Less than 8000 cfm | Basement | 1 | EA | 6 | \$3,321 | |
| | Fan Coil Unit- Celing Mounted - Hot Water and Chilled Water | Entire Building | 11 | EA | 6 | \$17,645 | |
| | Fan Coil Unit- Celing Mounted - Steam | Basement / Plenum | 2 | EA | 7 | \$0 | Located in tunnel of multi-zone built up units |
| | Fan Coil Unit- Floor Mounted - Steam | Entire Building | 38 | EΑ | 6 | \$58,169 | |
| | Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM | Mechanical Room | 1 | EΑ | 6 | \$2,433 | |
| | Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM | Roof | 3 | EA | 6 | \$4,772 | |
| | Reheat Boxes | Basement | 6 | EA | 7 | \$0 | |
| | Reheat Boxes - Reheat Boxes with Steam Coil | Basement | 13 | EA | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|-----------------------------------|----------|------|------|-----------|--|
| Air Han | dling Systems | | | | | | |
| | Return Duct Work | Basement | 200 | LF | 6 | \$0 | |
| | Return Duct Work | Basement | 100 | LF | 6 | \$0 | |
| | Zone Dampers | Basement | 47 | EA | 7 | \$0 | |
| Boiler S | Systems | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 201 - 300 HP | Mechanical Room | 3 | EA | 5 | \$83,390 | |
| | Chemical Feed System | Mechanical Room | 1 | EA | 6 | \$1,078 | |
| | Combustion Dampers | Mechanical Room | 3 | EA | 3 | \$19,660 | Indoor inline supply fan feeds boilers |
| | Condensate Pump | Mechanical Room | 2 | EA | 5 | \$36,392 | |
| | Condensate Pump | Mechanical Room | 1 | EA | 4 | \$44,329 | Pump is in poor condition |
| | Feed Water Pumps and Tank | Mechanical Room | 1 | EΑ | 6 | \$2,545 | |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP | Mechanical Room | 3 | EA | 5 | \$83,390 | |
| | Piping - Steam Pipe- Steel | Mechanical Room | 1,000 | LF | 4 | \$294,208 | |
| | Steam Traps | Mechanical Room / Entire Building | 70 | EA | 5 | \$92,043 | |
| Heat Ex | cchangers | | | | | | |
| | Heat Exchanger - Steam to Hot Water Shell Type | Basement | 2 | EA | 7 | \$0 | |
| Heating | Devices | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 3 | EA | 5 | \$5,264 | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 3 | EΑ | 4 | \$11,516 | Heater is old and in poor condition |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 4 | EΑ | 6 | \$1,417 | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 9 | EΑ | 7 | \$0 | |
| | Fin Tube - Steam | 1st Floor | 255 | LF | 6 | \$2,407 | |
| | Unit Heater - Electric | Entire Building | 2 | EΑ | 6 | \$556 | |
| | Unit Heater - Steam | Entire Building / 1st Floor | 1 | EΑ | 4 | \$1,755 | 50 years old |
| | Wall Heater - Electric | Entire Building | 1 | EΑ | 6 | \$139 | |
| | Wall Heater - Electric | Entire Building | 2 | EA | 7 | \$0 | |
| Mechar | nical Plumbing | | | | | | |
| | Chilled Water Pump - 10 - 20 HP | Boiler Room | 5 | EA | 6 | \$6,212 | 2 primary pumps, 3 secondary pumps |
| | Condensate-Steel or Galvanized | Entire Building | 1,800 | LF | 4 | \$586,949 | |
| | Hot Water Pump - Less than 10 | Mechanical Room | 2 | EΑ | 6 | \$2,222 | |
| | Hydronic Supply and Return - Steel | Entire Building | 1,800 | LF | 6 | \$138,198 | |
| Temper | rature Control | | | | | | |
| | DDC System | Entire Building | 251,526 | SF | 6 | \$143,873 | |
| | Electric Thermostat | Entire Building | 13 | EA | 6 | \$0 | |
| | | Č | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------------------|----------|------|------|----------|-------------------|
| Tempe | rature Control | | | | | | |
| | Thermostats - DDC | Entire Building | 65 | EA | 6 | \$0 | |
| Ventila | tion | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Basement | 1 | EA | 3 | \$6,392 | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building / 2nd Floor | 1 | EΑ | 7 | \$0 | |
| | Exhaust Fans- Indoor - Greater than 8000 CFM | Basement | 5 | EA | 4 | \$56,951 | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 4 | EΑ | 3 | \$25,568 | Fan does not work |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 5 | EA | 7 | \$0 | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 1 | EΑ | 6 | \$592 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 1 | EA | 3 | \$4,245 | Fan does not work |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 2 | EΑ | 7 | \$0 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 3 | EA | 6 | \$1,777 | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building | 1 | EΑ | 3 | \$1,942 | Fan does not work |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building | 1 | EΑ | 7 | \$0 | |
| | Lab Exhaust Hood | Entire Building | 1 | EA | 7 | \$0 | |
| | Type I Exhaust Hood- Kitchen | Entire Building | 3 | EA | 7 | \$0 | |
| | | | | | | | |

Mechanical System Subtotal:

\$1,932,520

Building: Kennedy

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------|----------|------|------|-----------|---|
| Hot Wat | ter | | | | | | |
| | Gas Heater - Greater than 600000 BTU/HR | Boiler Room | 1 | EA | 7 | \$0 | Summer Use |
| | Hot Water Storage Tank_Gas - 201 - 500 Gallons | Boiler Room | 2 | EA | 4 | \$26,540 | |
| | Steam Heat Exchanger | Boiler Room | 2 | EA | 7 | \$0 | |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 233,791 | SF | 4 | \$167,161 | 50 years old with numerous clamps installed |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 233,791 | SF | 4 | \$337,664 | 50 years old with numerous clamps installed |
| | Domestic Piping-Cold Water Risers | Entire Building | 233,791 | SF | 4 | \$187,220 | 50 years old with numerous clamps installed |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 233,791 | SF | 4 | \$127,042 | 50 years old with numerous clamps installed |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 233,791 | SF | 4 | \$300,889 | 50 years old with numerous clamps installed |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 233,791 | SF | 4 | \$200,593 | 50 years old with numerous clamps installed |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 233,791 | SF | 4 | \$113,669 | 50 years old with numerous clamps installed |
| | Sanitary Piping | Entire Building | 233,791 | SF | 6 | \$213,966 | |
| | Storm Piping | Entire Building | 233,791 | SF | 6 | \$203,936 | |
| | Vent Piping | Entire Building | 233,791 | SF | 6 | \$157,131 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost Comments | |
|---------|---------------------------------------|-------------------------------------|----------|------|------|---------------|--|
| Piping | | | | | | | |
| Pool Sy | vstems | | | | | | |
| | Pool Drain Piping | Pool Equipment area off Boiler Room | 50 | LF | 7 | \$0 | |
| | Pool Filtration System including Pump | Pool Equipment area off Boiler Room | 1 | EA | 7 | \$0 | |
| | Pool Hot Water Heater - Gas Fired | Pool Equipment area off Boiler Room | 1 | EA | 7 | \$0 | |
| | Pool Supply and Return Piping | Pool Equipment area off Boiler Room | 400 | LF | 7 | \$0 | |
| Pumps | | | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | Mechanical Room | 1 | EΑ | 7 | \$0 | |
| | Pumps - Ejector-Duplex | Mechanical Room | 2 | EΑ | 6 | \$2,774 | |
| | Pumps - Sump-Simplex | Mechanical Room / Basement | 1 | EA | 4 | \$11,443 | |

Plumbing System Subtotal:

\$2,050,028

Building: Kennedy

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|-------------------------------|
| Classro | oom #108 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 1st Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | Lighting retrofit in progress |
| | Marker Board | 1st Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 888 | SF | 6 | \$2,603 | |
| Classro | oom #109 (Science Classroom) | | | | | | |
| | Casework | 1st Floor | 151 | LF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 1,004 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 1,004 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 28 | EA | 6 | \$3,469 | |
| | Lighting - Wall Mounted | 1st Floor | 2 | EA | 6 | \$248 | |
| | Marker Board | 1st Floor | 9 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 741 | SF | 6 | \$2,172 | |
| | Walls - Plaster/Drywall | 1st Floor | 303 | SF | 7 | \$0 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| | Work Sink | 1st Floor | 1 | EA | 5 | \$1,508 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|--|
| Classro | oom #110 (Art Room) | | | | | | |
| | Casework | 1st Floor | 61 | LF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 909 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 909 | SF | 6 | \$910 | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 7 | \$0 | Lighting retrofit in progress |
| | Lighting - Wall Mounted | 1st Floor | 3 | EA | 5 | \$508 | |
| | Marker Board | 1st Floor | 8 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 984 | SF | 6 | \$2,885 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #111 (Music Room) | | | | | | |
| | Casework | 1st Floor | 8 | LF | 6 | \$202 | |
| | Ceiling - Splined | 1st Floor | 1,387 | SF | 7 | \$0 | |
| | Chalk Board | 1st Floor | 16 | LF | 4 | \$1,469 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | \$0 | |
| | Floor - Carpet | 1st Floor | 1,387 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 32 | EA | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 208 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 1,500 | SF | 7 | \$0 | Upper 3 feet of wall covered in spline tiles |
| Classro | oom #111A (Special Program) | | | | | | |
| | Casework | 1st Floor | 46 | LF | 6 | \$1,162 | |
| | Ceiling - Splined | 1st Floor | 493 | SF | 6 | \$402 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 493 | SF | 6 | \$493 | |
| | Lighting - Pendent/Surface | 1st Floor | 8 | EA | 6 | \$991 | No lights in room to see clearly. Lighting retrofit in progress. |
| | Marker Board | 1st Floor | 5 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 116 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 726 | SF | 6 | \$2,128 | |
| | Walls - Plaster/Drywall | 1st Floor | 184 | SF | 6 | \$508 | |
| Classro | oom #112 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 1st Floor | 729 | SF | 6 | \$594 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | Lighting retrofit in progress |
| | Marker Board | 1st Floor | 20 | LF | 7 | \$0 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|--|
| Classro | oom #112 (Regular Classroom) | | | | | | |
| | Walls - Concrete Block | 1st Floor | 888 | SF | 7 | \$0 | |
| Classro | oom #113 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 12 | LF | 6 | \$303 | |
| | Ceiling - Splined | 1st Floor | 545 | SF | 6 | \$444 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 545 | SF | 6 | \$546 | |
| | Lighting - Pendent/Surface | 1st Floor | 9 | EA | 6 | \$1,115 | |
| | Marker Board | 1st Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 543 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 240 | SF | 5 | \$1,819 | |
| Classro | oom #114 (Regular Classroom) | | | | | | |
| | Ceiling - Splined | 1st Floor | 545 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 545 | SF | 6 | \$546 | |
| | Lighting - Pendent/Surface | 1st Floor | 9 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 543 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 240 | SF | 5 | \$1,819 | Half of wall covered in plastic paneling. Behind is plaster/drywall. |
| Classro | oom #115 (Regular Classroom) | | | | | | plactor all y wall. |
| Olubbic | Casework | 1st Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 1st Floor | 729 | SF | 6 | \$594 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | Lighting construction in progress - retrofit |
| | Marker Board | 1st Floor | 20 | LF | 6 | \$428 | |
| | Walls - Concrete Block | 1st Floor | 888 | SF | 7 | \$0 | |
| Classro | oom #116 (Regular Classroom) | | | | | | |
| | Ceiling - Splined | 1st Floor | 545 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 545 | SF | 6 | \$546 | |
| | Lighting - Pendent/Surface | 1st Floor | 9 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 543 | SF | 6 | \$1,592 | |
| | | | | SF | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| | bear Time | Lasatian | 0 | Heli | Davis | 0 | Comments |
|---------|------------------------------|-----------|----------|------|-------|----------|-------------------------------------|
| • | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | pom #117 (Regular Classroom) | | | | | | |
| | Ceiling - Splined | 1st Floor | 545 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 545 | SF | 6 | \$546 | |
| | Lighting - Pendent/Surface | 1st Floor | 9 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 543 | SF | 6 | \$1,592 | |
| | Walls - Plaster/Drywall | 1st Floor | 240 | SF | 5 | \$1,819 | |
| Classro | oom #118 (Art Room) | | | | | | |
| | Casework | | 24 | LF | 5 | \$5,018 | |
| | Ceiling - Lay-in | | 1,569 | SF | 7 | \$0 | |
| | Chalk Board | | 10 | LF | 4 | \$918 | obsolete material |
| | Doors - Steel Doors incl hw | | 1 | EA | 7 | \$0 | FRP finish |
| | Doors - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| | Floor - Concrete | | 1,569 | SF | 6 | \$830 | |
| | Lighting - Pendent/Surface | | 38 | EA | 6 | \$4,708 | |
| | Walls - Concrete Block | | 1,444 | SF | 6 | \$4,233 | peeling paint at windows |
| | Work Sink | | 2 | EA | 6 | \$758 | |
| Classro | oom #201 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 4 | \$10,813 | t-12 |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 7 | \$0 | |
| Classro | oom #202 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 5 | \$5,192 | Ceiling tiles beginning to fall off |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 4 | \$10,813 | t-12 |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 7 | \$0 | |
| Classro | oom #203 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|----------|----------|
| Classro | oom #203 (Regular Classroom) | | | | | | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 4 | \$10,813 | t-12 |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 7 | \$0 | |
| Classro | oom #204 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 4 | \$10,813 | t-12 |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 7 | \$0 | |
| lassro | oom #205 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 6 | \$730 | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EA | 4 | \$10,813 | t-12 |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 7 | \$0 | |
| assro | oom #206 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 6 | \$730 | |
| | Lighting - Pendent/Surface | 2nd Floor | 20 | EΑ | 4 | \$10,813 | t-12 |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 7 | \$0 | |
| lassro | oom #207 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 6 | \$594 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 7 | \$0 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|-----------|----------|------|------|---------|-------------------------------|
| lassro | om #207 (Regular Classroom) | | | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | lighting retrofit in progress |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 6 | \$2,603 | |
| lassro | om #208 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | Lighting retrofit in progress |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 7 | \$0 | |
| lassro | om #209 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | Lighting retrofit in progress |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 6 | \$2,603 | |
| assro | om #210 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | Lighting retrofit in progress |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 7 | \$0 | |
| assro | om #211 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | Lighting retrofit in progress |
| | Marker Board | 2nd Floor | 30 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 7 | \$0 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| | - | | | | | | |
|---------|------------------------------|-----------|----------|------|------|----------|--|
| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | oom #212 (Music Room) | | | | | | |
| | Casework | 2nd Floor | 8 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 1,303 | SF | 7 | \$0 | |
| | Chalk Board | 2nd Floor | 24 | LF | 4 | \$2,203 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 3 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 2nd Floor | 775 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 528 | SF | 6 | \$529 | |
| | Instrument Storage Casework | 2nd Floor | 28 | LF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 6 | \$1,785 | |
| | Risers | 2nd Floor | 89 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 247 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 1,264 | SF | 7 | \$0 | Upper 2 feet of wall covered in spline tiles |
| Classro | oom #213 (Regular Classroom) | | | | | | |
| | Ceiling - Splined | 2nd Floor | 714 | SF | 7 | \$0 | |
| | Chalk Board | 2nd Floor | 8 | LF | 4 | \$734 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 714 | SF | 6 | \$715 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 4 | \$8,110 | t-12 |
| | Marker Board | 2nd Floor | 21 | LF | 6 | \$450 | |
| | Walls - Concrete Block | 2nd Floor | 622 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 300 | SF | 6 | \$828 | |
| | Work Sink | 2nd Floor | 3 | EA | 5 | \$4,523 | 1 sink with 3 separate controls |
| Classro | oom #214 (Regular Classroom) | | | | | | |
| | Ceiling - Splined | 2nd Floor | 814 | SF | 6 | \$663 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 814 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 25 | EA | 4 | \$13,516 | t-12 |
| | Marker Board | 2nd Floor | 8 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 829 | SF | 7 | \$0 | |
| | Walls - Metal Panel | 2nd Floor | 160 | SF | 6 | \$1,194 | |
| | Walls - Plaster/Drywall | 2nd Floor | 236 | SF | 6 | \$651 | |
| Classro | oom #215 (Science Classroom) | | | | | | |
| | Casework | | 191 | LF | 6 | \$4,823 | |
| | Ceiling - Lay-in | | 1,425 | SF | 6 | \$4,279 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | | 1,425 | SF | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-----------|----------|------|------|---------|---|
| Classro | oom #215 (Science Classroom) | | | | | | |
| | Lighting - Lay-in | | 26 | EA | 7 | \$0 | |
| | Marker Board | | 9 | LF | 7 | \$0 | |
| | Storage/ Closet | | 60 | SF | 7 | \$0 | |
| | Walls - Concrete Block | | 848 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 204 | SF | 7 | \$0 | |
| | Work Sink | | 2 | EA | 6 | \$758 | |
| Classro | oom #216 (Science Classroom) | | | | | | |
| | Casework | 2nd Floor | 191 | LF | 6 | \$4,823 | |
| | Ceiling - Lay-in | 2nd Floor | 1,425 | SF | 6 | \$4,279 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 1,425 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 26 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 9 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 60 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 848 | SF | 7 | \$0 | |
| | Work Sink | 2nd Floor | 2 | EA | 6 | \$758 | Also had a separate eyewash station but no fume hood or gas lines |
| Classro | oom #217 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 2nd Floor | 729 | SF | 6 | \$594 | Some tiles loose |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | Lighting retrofit in progress |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 888 | SF | 7 | \$0 | |
| Classro | oom #220A (Regular Classroom) | | | | | | |
| | Ceiling - Plaster/Drywall | | 56 | SF | 5 | \$700 | dirty, damaged patches |
| | Ceiling - Plaster/Drywall | | 685 | SF | 6 | \$2,371 | |
| | Chalk Board | | 16 | LF | 4 | \$1,469 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 741 | SF | 6 | \$1,621 | |
| | Lighting - Pendent/Surface | | 10 | EA | 6 | \$1,239 | |
| | Marker Board | | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 501 | SF | 6 | \$1,383 | |
| | Walls - Structural Glazed Tile | | 945 | SF | 6 | \$2,973 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-----------|----------|------|------|---------|---|
| Classro | oom #220B (Regular Classroom) | | | | | | |
| | Ceiling - Plaster/Drywall | | 776 | SF | 6 | \$2,685 | |
| | Ceiling - Plaster/Drywall | | 60 | SF | 5 | \$750 | spray texture popcorn finish is stained, dirty, and badly patched |
| | Doors - Wood Doors inclu hw | | 1 | EΑ | 6 | \$301 | • |
| | Floor - Tile | | 836 | SF | 6 | \$1,829 | |
| | Lighting - Pendent/Surface | | 10 | EΑ | 6 | \$1,239 | |
| | Marker Board | | 20 | LF | 6 | \$428 | |
| | Marker Board | | 8 | LF | 4 | \$714 | damaged surface |
| | Walls - Concrete Block | | 36 | SF | 6 | \$106 | peeling paint at columns |
| | Walls - Plaster/Drywall | | 555 | SF | 6 | \$1,532 | |
| | Walls - Structural Glazed Tile | | 192 | SF | 6 | \$604 | |
| Classro | oom #222 (Regular Classroom) | | | | | | |
| | Casework | | 12 | LF | 6 | \$303 | |
| | Ceiling - Splined | | 400 | SF | 6 | \$326 | |
| | Ceiling - Splined | | 42 | SF | 4 | \$590 | damaged and missing tiles; water damage |
| | Doors - Steel Doors incl hw | | 2 | EΑ | 6 | \$602 | |
| | Floor - Tile | | 442 | SF | 6 | \$967 | |
| | Lighting - Pendent/Surface | | 8 | EΑ | 5 | \$1,461 | missing fixtures |
| | Marker Board | | 12 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 248 | SF | 6 | \$727 | |
| | Walls - Metal Panel | | 342 | SF | 6 | \$2,553 | |
| Classro | oom #300 (Computer Lab) | | | | | | |
| | Casework | 3rd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Splined | 3rd Floor | 369 | SF | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 369 | SF | 6 | \$369 | |
| | Lighting - Pendent/Surface | 3rd Floor | 8 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 444 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 216 | SF | 7 | \$0 | |
| | Work Sink | 3rd Floor | 1 | EA | 6 | \$379 | 2 sinks, but one is connected to the other. |
| Classro | oom #301 (Special Education) | | | | | | |
| | Casework | 3rd Floor | 7 | LF | 7 | \$0 | |
| | Ceiling - Splined | 3rd Floor | 388 | SF | 5 | \$2,763 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 388 | SF | 6 | \$388 | |
| | Lighting - Pendent/Surface | 3rd Floor | 9 | EA | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| | . – | | | | | | _ |
|---------|------------------------------|-----------|----------|------|------|---------|---|
| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | oom #301 (Special Education) | | | | | | |
| | Marker Board | 3rd Floor | 6 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 500 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 26 | SF | 6 | \$72 | |
| Classro | oom #302 (Computer Lab) | | | | | | |
| | Casework | 3rd Floor | 27 | LF | 6 | \$682 | |
| | Ceiling - Splined | 3rd Floor | 729 | SF | 7 | \$0 | |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | \$1,102 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 729 | SF | 6 | \$730 | |
| | Lighting - Pendent/Surface | 3rd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 6 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 648 | SF | 7 | \$0 | Data outlets and electrical outlets need repairs |
| | Walls - Plaster/Drywall | 3rd Floor | 216 | SF | 7 | \$0 | |
| | Wireless System | 3rd Floor | 1 | EA | 7 | \$0 | |
| Classro | oom #304 (Computer Lab) | | | | | | |
| | Casework | 3rd Floor | 42 | LF | 6 | \$1,061 | |
| | Ceiling - Splined | 3rd Floor | 1,110 | SF | 7 | \$0 | |
| | Chalk Board | 3rd Floor | 5 | LF | 4 | \$459 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EΑ | 7 | \$0 | |
| | Floor - Carpet | 3rd Floor | 1,110 | SF | 6 | \$2,365 | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 20 | LF | 6 | \$428 | |
| | Walls - Concrete Block | 3rd Floor | 1,102 | SF | 7 | \$0 | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | \$0 | |
| Classro | oom #306 (Computer Lab) | | | | | | |
| | Casework | 3rd Floor | 22 | LF | 7 | \$0 | |
| | Ceiling - Splined | 3rd Floor | 729 | SF | 7 | \$0 | |
| | Chalk Board | 3rd Floor | 25 | LF | 4 | \$2,295 | |
| | Doors - Side-lite | 3rd Floor | 24 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Floor - Carpet | 3rd Floor | 729 | SF | 6 | \$1,553 | |
| | Lighting - Pendent/Surface | 3rd Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 648 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 216 | SF | 7 | \$0 | Spline ceiling tiles and wood paneling over plaster/drywall |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|-----------|----------|------|------|---------|--|
| Classro | oom #306A (Special Program) | | | | | | |
| | Casework | 3rd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Splined | 3rd Floor | 369 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 3rd Floor | 369 | SF | 6 | \$786 | |
| | Lighting - Pendent/Surface | 3rd Floor | 8 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 444 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 216 | SF | 7 | \$0 | Spline ceiling tiles and wood paneling on plaster/drywall wall |
| | Work Sink | 3rd Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #307 (Special Program) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 4 | \$6,086 | |
| | Ceiling - Splined | 3rd Floor | 400 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 400 | SF | 4 | \$3,867 | Flooring is missing in large areas |
| | Lighting - Pendent/Surface | 3rd Floor | 3 | EA | 4 | \$1,622 | t-12 |
| | Marker Board | 3rd Floor | 18 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 758 | SF | 6 | \$2,222 | |
| Classro | oom #308 (Computer Lab) | | | | | | |
| | Casework | 3rd Floor | 42 | LF | 6 | \$1,061 | |
| | Ceiling - Splined | 3rd Floor | 1,110 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Floor - Carpet | 3rd Floor | 1,110 | SF | 6 | \$2,365 | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EΑ | 7 | \$0 | |
| | Marker Board | 3rd Floor | 12 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 1,102 | SF | 7 | \$0 | |
| | Wireless System | 3rd Floor | 1 | EΑ | 7 | \$0 | |
| | Work Sink | 3rd Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #309A (Special Program) | | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 417 | SF | 6 | \$1,443 | |
| | Chalk Board | 3rd Floor | 6 | LF | 5 | \$314 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 417 | SF | 6 | \$417 | |
| | Lighting - Pendent/Surface | 3rd Floor | 8 | EA | 6 | \$991 | |
| | Marker Board | 3rd Floor | 6 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 555 | SF | 7 | \$0 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| iroup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|------------------------------------|-----------|----------|------|------|----------|---|
| lassro | oom #309A (Special Program) | | | | | | |
| | Walls - Plaster/Drywall | 3rd Floor | 246 | SF | 6 | \$679 | |
| lassro | oom #309B (Regular Classroom) | | | | | | |
| | Ceiling - Plaster/Drywall | | 697 | SF | 6 | \$2,412 | |
| | Chalk Board | | 13 | LF | 4 | \$1,193 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | | 697 | SF | 6 | \$698 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 12 | LF | 6 | \$257 | |
| | Walls - Concrete Block | | 522 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 246 | SF | 6 | \$679 | |
| lassro | oom #310 (Other Instructional Use) | | | | | | |
| | Casework | 3rd Floor | 35 | LF | 6 | \$884 | |
| | Ceiling - Splined | 3rd Floor | 1,110 | SF | 7 | \$0 | Room is encased in plastic in preparation for asbestos abatement work |
| | Chalk Board | 3rd Floor | 8 | LF | 4 | \$734 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Floor - Carpet | 3rd Floor | 1,110 | SF | 6 | \$2,365 | |
| | Lighting - Pendent/Surface | 3rd Floor | 24 | EA | 4 | \$12,975 | t-12 |
| | Marker Board | 3rd Floor | 3 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 1,102 | SF | 6 | \$3,231 | |
| | Work Sink | 3rd Floor | 1 | EA | 5 | \$1,508 | |
| lassro | oom #311 (Computer Lab) | | | | | | |
| | Casework | 3rd Floor | 27 | LF | 7 | \$0 | |
| | Ceiling - Splined | 3rd Floor | 1,110 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 1,110 | SF | 5 | \$4,984 | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 1,102 | SF | 7 | \$0 | Data outlets and electrical outlets need repairs |
| | Wireless System | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Work Sink | 3rd Floor | 1 | EA | 6 | \$379 | |
| lassro | oom #312A (Special Program) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 6 | \$404 | |
| | Ceiling - Splined | 3rd Floor | 369 | SF | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-------------------------------|-----------|----------|------|------|---------|----------|
| Classro | oom #312A (Special Program) | | • | | | | |
| | Floor - Tile/Sheet | 3rd Floor | 369 | SF | 6 | \$369 | |
| | Lighting - Pendent/Surface | 3rd Floor | 8 | EΑ | 4 | \$4,325 | t-12 |
| | Marker Board | 3rd Floor | 12 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 404 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 280 | SF | 6 | \$773 | |
| Classro | oom #312B (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 37 | LF | 6 | \$934 | |
| | Ceiling - Splined | 3rd Floor | 759 | SF | 6 | \$619 | |
| | Chalk Board | 3rd Floor | 20 | LF | 4 | \$1,836 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 759 | SF | 6 | \$760 | |
| | Lighting - Pendent/Surface | 3rd Floor | 16 | EA | 4 | \$8,650 | t-12 |
| | Walls - Concrete Block | 3rd Floor | 556 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 312 | SF | 6 | \$861 | |
| | Work Sink | 3rd Floor | 2 | EA | 6 | \$758 | |
| Classro | oom #313A (Special Program) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Splined | 3rd Floor | 369 | SF | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 369 | SF | 6 | \$369 | |
| | Lighting - Pendent/Surface | 3rd Floor | 8 | EA | 4 | \$4,325 | t-12 |
| | Marker Board | 3rd Floor | 6 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 404 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 280 | SF | 6 | \$773 | |
| Classro | oom #313B (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 37 | LF | 6 | \$934 | |
| | Ceiling - Splined | 3rd Floor | 759 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 759 | SF | 6 | \$760 | |
| | Lighting - Pendent/Surface | 3rd Floor | 16 | EA | 4 | \$8,650 | t-12 |
| | Marker Board | 3rd Floor | 6 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 556 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 312 | SF | 6 | \$861 | |
| | Work Sink | 3rd Floor | 2 | EA | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-----------|----------|------|------|---------|--|
| Classro | oom #314 (Science Lab Level 1) | | | | | | |
| | Casework | 3rd Floor | 157 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 1,402 | SF | 6 | \$4,210 | Some water infiltration evident on ceiling |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 1,402 | SF | 7 | \$0 | |
| | Fume Hood | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Gas Line | 3rd Floor | 8 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 3rd Floor | 23 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 9 | LF | 7 | \$0 | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 792 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 298 | SF | 7 | \$0 | |
| | Work Sink | 3rd Floor | 1 | EA | 6 | \$379 | |
| | Work Sink | 3rd Floor | 10 | EA | 7 | \$0 | |
| Classro | oom #315 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 37 | LF | 6 | \$934 | |
| | Ceiling - Splined | 3rd Floor | 668 | SF | 5 | | Water damage on ceiling |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | 3 0 |
| | Floor - Tile/Sheet | 3rd Floor | 668 | SF | 6 | \$669 | |
| | Lighting - Pendent/Surface | 3rd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 542 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 338 | SF | 6 | \$933 | |
| | Work Sink | 3rd Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #317 (Regular Classroom) | | | | | | |
| | Casework | | 38 | LF | 6 | \$960 | |
| | Ceiling - Splined | | 878 | SF | 5 | \$6,253 | Water damage on ceiling |
| | Doors - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | | 878 | SF | 6 | \$879 | |
| | Lighting - Pendent/Surface | | 18 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 630 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 348 | SF | 7 | \$0 | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classro | oom #318 (Science Lab Level 2) | | | | | | |
| | Casework | 3rd Floor | 89 | LF | 7 | \$0 | Tables are not fixed casework. |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-----------|----------|------|------|---------|-----------------|
| Classro | oom #318 (Science Lab Level 2) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 1,242 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 1,242 | SF | 7 | \$0 | |
| | Gas Line | 3rd Floor | 7 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 3rd Floor | 24 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 12 | LF | 6 | \$257 | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 1,007 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 178 | SF | 7 | \$0 | |
| | Work Sink | 3rd Floor | 7 | EA | 7 | \$0 | |
| Classro | oom #319A (Regular Classroom) | | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 557 | SF | 6 | \$1,928 | |
| | Chalk Board | 3rd Floor | 9 | LF | 4 | \$826 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 557 | SF | 5 | \$2,501 | |
| | Lighting - Pendent/Surface | 3rd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 6 | LF | 4 | \$536 | Has damage |
| | Marker Board | 3rd Floor | 12 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 416 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 246 | SF | 5 | \$1,864 | |
| Classro | oom #319B (Regular Classroom) | | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 557 | SF | 6 | \$1,928 | |
| | Chalk Board | 3rd Floor | 10 | LF | 4 | \$918 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 557 | SF | 6 | \$558 | |
| | Lighting - Pendent/Surface | 3rd Floor | 8 | EA | 6 | \$991 | |
| | Marker Board | 3rd Floor | 6 | LF | 4 | \$536 | Has some damage |
| | Marker Board | 3rd Floor | 8 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 685 | SF | 6 | \$2,008 | |
| | Walls - Plaster/Drywall | 3rd Floor | 246 | SF | 6 | \$679 | |
| Classro | oom #320 (Science Classroom) | | | | | | |
| | Casework | 3rd Floor | 173 | LF | 7 | \$0 | |
| | Ceiling - Splined | 3rd Floor | 1,184 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 1,184 | SF | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|-----------|----------|------|------|----------|--|
| Classr | oom #320 (Science Classroom) | | | | | | |
| | Lighting - Pendent/Surface | 3rd Floor | 28 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 9 | LF | 7 | \$0 | |
| | Storage/ Closet | 3rd Floor | 120 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 882 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 255 | SF | 7 | \$0 | |
| | Work Sink | 3rd Floor | 2 | EA | 6 | \$758 | |
| Classr | oom #321 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 13 | LF | 6 | \$328 | |
| | Ceiling - Splined | 3rd Floor | 729 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 3rd Floor | 729 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 3rd Floor | 20 | EA | 4 | \$10,813 | t-12 |
| | Marker Board | 3rd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Floor | 888 | SF | 7 | \$0 | |
| Classr | oom #Bsmt Wrestling (Fitness Room) | | | | | | |
| | Ceiling - Exposed | Basement | 1,086 | SF | 6 | \$1,615 | Leaks. |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 7 | \$0 | |
| | Floor - Weight/ Fitness Room Floor Matting | Basement | 1,060 | SF | 7 | \$0 | |
| | Floor - Weight/ Fitness Room Floor Matting | Basement | 26 | SF | 6 | \$183 | puddle and paint from ceiling on floor |
| | Lighting - Pendent/Surface | Basement | 20 | EA | 7 | \$0 | |
| | Storage/ Closet | Basement | 200 | SF | 6 | \$1,450 | |
| | Walls - Concrete Block | Basement | 1,670 | SF | 7 | \$0 | Wall padding on top. 12 SF of padding is missing on a corner and needs to be replaced. |
| | | | | | | * | |

Classrooms Subtotal: \$381,422

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|---------------------|----------|------|------|----------|--------------------------------|
| Admini | strative Suites/Offices | | | | | | |
| | Ceiling - Plaster/Drywall | 101 Conference Room | 672 | SF | 6 | \$2,326 | |
| | Ceiling - Plaster/Drywall | 101 Conference Room | 50 | SF | 5 | \$625 | popcorn finish, dirty, stained |
| | Doors - Wood Doors inclu hw | 101 Conference Room | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 101 Conference Room | 722 | SF | 6 | \$1,538 | some stains throughout |
| | Lighting - Pendent/Surface | 101 Conference Room | 4 | EA | 7 | \$0 | |
| | Power Distribution | 101 Conference Room | 8 | EA | 6 | \$16,999 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Adminis | | Location | Quantity | • | · · · · · · · · · · · · · · · · · · · | 0031 | Comments |
|---------|-----------------------------|---|----------|----|---------------------------------------|---------|-----------------------|
| | strative Suites/Offices | | | | | | |
| | Storage/ Closet | 101 Conference Room | 24 | SF | 6 | \$174 | |
| | Walls - Plaster/Drywall | 101 Conference Room | 828 | SF | 6 | \$2,285 | paneling |
| | Ceiling - Plaster/Drywall | 103 Attendance Office | 300 | SF | 6 | \$1,038 | |
| | Ceiling - Plaster/Drywall | 103 Attendance Office | 66 | SF | 5 | \$710 | |
| | Doors - Wood Doors inclu hw | 103 Attendance Office | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 103 Attendance Office | 366 | SF | 6 | \$801 | |
| | Lighting - Pendent/Surface | 103 Attendance Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | 103 Attendance Office | 6 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 103 Attendance Office | 612 | SF | 6 | \$1,689 | |
| | Ceiling - Plaster/Drywall | 103A Office | 136 | SF | 6 | \$471 | |
| | Ceiling - Plaster/Drywall | 103A Office | 30 | SF | 5 | \$323 | Patches/peeling paint |
| | Doors - Wood Doors inclu hw | 103A Office | 2 | EA | 7 | \$0 | |
| | Floor - Tile | 103A Office | 166 | SF | 6 | \$363 | |
| | Lighting - Pendent/Surface | 103A Office | 1 | EA | 7 | \$0 | |
| | Power Distribution | 103A Office | 4 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 103A Office | 155 | SF | 5 | \$685 | |
| | Walls - Plaster/Drywall | 103A Office | 218 | SF | 4 | \$2,195 | water damage @ column |
| | Ceiling - Plaster/Drywall | 104 Counselor (open office & internal corridor) | 265 | SF | 6 | \$917 | |
| | Doors - Store Front | 104 Counselor (open office & internal corridor) | 1 | EA | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 104 Counselor (open office & internal corridor) | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 104 Counselor (open office & internal corridor) | 265 | SF | 6 | \$580 | vct |
| | Lighting - Pendent/Surface | 104 Counselor (open office & internal corridor) | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 104 Counselor (open office & internal corridor) | 256 | SF | 6 | \$750 | |
| | Walls - Metal Panel | 104 Counselor (open office & internal corridor) | 340 | SF | 6 | \$2,538 | |
| | Walls - Plaster/Drywall | 104 Counselor (open office & internal corridor) | 50 | SF | 6 | \$138 | |
| | Ceiling - Plaster/Drywall | 104A Counselor Office | 115 | SF | 6 | \$398 | |
| | Doors - Wood Doors inclu hw | 104A Counselor Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 104A Counselor Office | 115 | SF | 6 | \$252 | vct |
| | Lighting - Pendent/Surface | 104A Counselor Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | 104A Counselor Office | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 104A Counselor Office | 130 | SF | 6 | \$381 | |
| | Ceiling - Plaster/Drywall | 104B Counselor Office | 90 | SF | 6 | \$311 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------------------|----------|------|------|---------|----------|
| - | strative Suites/Offices | | | • | | 000. | |
| | Doors - Wood Doors inclu hw | 104B Counselor Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 104B Counselor Office | 90 | SF | 6 | \$197 | |
| | Lighting - Pendent/Surface | 104B Counselor Office | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 104B Counselor Office | 30 | SF | 6 | \$88 | |
| | Ceiling - Plaster/Drywall | 104C Personnel Room | 110 | SF | 6 | \$381 | |
| | Doors - Wood Doors inclu hw | 104C Personnel Room | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 104C Personnel Room | 110 | SF | 6 | \$241 | |
| | Lighting - Pendent/Surface | 104C Personnel Room | 4 | EA | 7 | \$0 | |
| | Power Distribution | 104C Personnel Room | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 104C Personnel Room | 130 | SF | 6 | \$381 | |
| | Ceiling - Plaster/Drywall | 104D Counselor Office | 58 | SF | 6 | \$201 | |
| | Doors - Steel Doors incl hw | 104D Counselor Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 104D Counselor Office | 58 | SF | 6 | \$127 | |
| | Lighting - Lay-in | 104D Counselor Office | 2 | EA | 6 | \$238 | |
| | Power Distribution | 104D Counselor Office | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 104D Counselor Office | 56 | SF | 6 | \$164 | |
| | Walls - Metal Panel | 104D Counselor Office | 176 | SF | 6 | \$1,314 | |
| | Ceiling - Plaster/Drywall | 104E Counselor Office | 58 | SF | 6 | \$201 | |
| | Doors - Steel Doors incl hw | 104E Counselor Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 104E Counselor Office | 58 | SF | 6 | \$127 | |
| | Lighting - Pendent/Surface | 104E Counselor Office | 2 | EA | 6 | \$248 | |
| | Power Distribution | 104E Counselor Office | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 104E Counselor Office | 56 | SF | 6 | \$164 | |
| | Walls - Metal Panel | 104E Counselor Office | 176 | SF | 6 | \$1,314 | |
| | Ceiling - Plaster/Drywall | 104F Counselor Office | 34 | SF | 6 | \$118 | |
| | Doors - Steel Doors incl hw | 104F Counselor Office | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile | 104F Counselor Office | 34 | SF | 6 | \$74 | |
| | Lighting - Lay-in | 104F Counselor Office | 1 | EA | 6 | \$119 | |
| | Walls - Concrete Block | 104F Counselor Office | 56 | SF | 6 | \$164 | |
| | Walls - Metal Panel | 104F Counselor Office | 123 | SF | 6 | \$918 | |
| | Ceiling - Plaster/Drywall | 106 "Counselor" | 77 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 106 "Counselor" | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 106 "Counselor" | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 106 "Counselor" | 77 | SF | 5 | \$346 | |
| | Lighting - Pendent/Surface | 106 "Counselor" | 2 | EA | 7 | \$0 | |
| | Power Distribution | 106 "Counselor" | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 106 "Counselor" | 123 | SF | 7 | \$0 | |
| | | | | | | * - | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------------------|-----------------------|----------|------|------|---------|----------------------------------|
| Administrative Suites/Offices | | | | | | |
| Walls - Metal Panel | 106 "Counselor" | 56 | SF | 6 | \$418 | |
| Walls - Plaster/Drywall | 106 "Counselor" | 69 | SF | 6 | \$190 | |
| Ceiling - Plaster/Drywall | 106A Office | 100 | SF | 6 | \$346 | |
| Ceiling - Plaster/Drywall | 106A Office | 23 | SF | 6 | \$94 | |
| Doors - Steel Doors incl hw | 106A Office | 1 | EA | 6 | \$301 | |
| Floor - Tile | 106A Office | 123 | SF | 6 | \$269 | |
| Lighting - Pendent/Surface | 106A Office | 4 | EA | 7 | \$0 | |
| Power Distribution | 106A Office | 4 | EA | 7 | \$0 | |
| Storage/ Closet | 106A Office | 9 | SF | 6 | \$65 | |
| Walls - Concrete Block | 106A Office | 136 | SF | 6 | \$399 | |
| Walls - Metal Panel | 106A Office | 220 | SF | 6 | \$1,642 | |
| Ceiling - Plaster/Drywall | 106B Counselor Office | 110 | SF | 6 | \$381 | |
| Doors - Steel Doors incl hw | 106B Counselor Office | 1 | EA | 6 | \$301 | |
| Floor - Tile | 106B Counselor Office | 110 | SF | 6 | \$241 | |
| Lighting - Pendent/Surface | 106B Counselor Office | 4 | EA | 7 | \$0 | |
| Power Distribution | 106B Counselor Office | 2 | EA | 7 | \$0 | |
| Storage/ Closet | 106B Counselor Office | 6 | SF | 6 | \$44 | |
| Walls - Concrete Block | 106B Counselor Office | 30 | SF | 6 | \$88 | |
| Walls - Metal Panel | 106B Counselor Office | 310 | SF | 6 | \$2,314 | |
| Ceiling - Plaster/Drywall | 106C Office | 110 | SF | 6 | \$381 | popcorn finish is failing; dirty |
| Doors - Steel Doors incl hw | 106C Office | 1 | EA | 6 | \$301 | |
| Floor - Tile | 106C Office | 110 | SF | 5 | \$494 | |
| Lighting - Pendent/Surface | 106C Office | 4 | EA | 7 | \$0 | |
| Storage/ Closet | 106C Office | 6 | SF | 6 | \$44 | |
| Walls - Concrete Block | 106C Office | 130 | SF | 6 | \$381 | |
| Walls - Metal Panel | 106C Office | 210 | SF | 6 | \$1,568 | |
| Doors - Steel Doors incl hw | 106D Main Office | 1 | EA | 6 | \$301 | |
| Floor - Tile | 106D Main Office | 66 | SF | 5 | \$296 | |
| Lighting - Pendent/Surface | 106D Main Office | 2 | EA | 7 | \$0 | |
| Power Distribution | 106D Main Office | 4 | EA | 7 | \$0 | |
| Walls - Concrete Block | 106D Main Office | 528 | SF | 6 | \$1,548 | |
| Walls - Metal Panel | 106D Main Office | 115 | SF | 6 | \$858 | |
| Walls - Plaster/Drywall | 106D Main Office | 55 | SF | 6 | \$152 | |
| Ceiling - Plaster/Drywall | 106E Counselor Office | 106 | SF | 6 | \$367 | |
| Doors - Steel Doors incl hw | 106E Counselor Office | 1 | EA | 6 | \$301 | |
| Floor - Tile | 106E Counselor Office | 106 | SF | 6 | \$232 | vct |
| Lighting - Lay-in | 106E Counselor Office | 4 | EA | 6 | \$476 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| | Item - Tyne | Location | Quantity | Linit | Pank | Cost | Comments |
|--------|--|--|----------|-------|-------|---------|-------------------------------|
| • | Item - Type strative Suites/Offices | Location | Quantity | Uilit | Railk | Cost | Comments |
| Aumini | | 106E Councelor Office | | E^ | 7 | Ф.С | |
| | Power Distribution | 106E Counselor Office 106E Counselor Office | 100 | EA | 7 | \$0 | |
| | Walls - Concrete Block | | 100 | SF | 6 | \$293 | |
| | Walls - Metal Panel | 106E Counselor Office | 248 | SF | 6 | \$1,851 | |
| | Ceiling - Plaster/Drywall | 107 Main Office Reception | 672 | SF | 6 | \$2,326 | |
| | Doors - Wood Doors inclu hw | 107 Main Office Reception | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 107 Main Office Reception | 672 | SF | 6 | \$1,470 | |
| | Lighting - Pendent/Surface | 107 Main Office Reception | 8 | EA | 7 | \$0 | lighting retrofit in process |
| | Power Distribution | 107 Main Office Reception | 18 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 107 Main Office Reception | 593 | SF | 6 | \$1,738 | |
| | Ceiling - Plaster/Drywall | 107A Office (Main office & reception) | 633 | SF | 6 | \$2,191 | |
| | Doors - Wood Doors inclu hw | 107A Office (Main office & reception) | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 107A Office (Main office & reception) | 633 | SF | 5 | \$2,842 | |
| | Lighting - Pendent/Surface | 107A Office (Main office & reception) | 8 | EA | 7 | \$0 | lighting retrofit in progress |
| | Power Distribution | 107A Office (Main office & reception) | 18 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 107A Office (Main office & reception) | 743 | SF | 6 | \$2,178 | |
| | Ceiling - Plaster/Drywall | 107B Principal's Office | 216 | SF | 6 | \$747 | |
| | Doors - Wood Doors inclu hw | 107B Principal's Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 107B Principal's Office | 216 | SF | 6 | \$473 | |
| | Lighting - Pendent/Surface | 107B Principal's Office | 4 | EA | 6 | \$496 | |
| | Power Distribution | 107B Principal's Office | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 107B Principal's Office | 470 | SF | 6 | \$1,378 | |
| | Ceiling - Plaster/Drywall | 107C Asst Principal's Office | 125 | SF | 6 | \$433 | |
| | Doors - Wood Doors inclu hw | 107C Asst Principal's Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 107C Asst Principal's Office | 125 | SF | 6 | \$273 | vct |
| | Lighting - Pendent/Surface | 107C Asst Principal's Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | 107C Asst Principal's Office | 6 | EA | 7 | \$0 | |
| | Storage/ Closet | 107C Asst Principal's Office | 10 | SF | 6 | \$73 | |
| | Walls - Concrete Block | 107C Asst Principal's Office | 370 | SF | 7 | \$0 | |
| | Walls - Metal Panel | 107C Asst Principal's Office | 349 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 107D Social Worker Office (west of the Principal's office) | 121 | SF | 6 | \$419 | |
| | Doors - Wood Doors inclu hw | 107D Social Worker Office (west of the Principal's office) | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 107D Social Worker Office (west of the Principal's office) | 121 | SF | 5 | \$543 | |
| | Lighting - Pendent/Surface | 107D Social Worker Office (west of the Principal's office) | 4 | EA | 7 | \$0 | |
| | Power Distribution | 107D Social Worker Office (west of the Principal's office) | 6 | EA | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|--|----------|------|------|----------|--------------|
| Adminis | strative Suites/Offices | | | | | | |
| | Walls - Concrete Block | 107D Social Worker Office (west of the Principal's office) | 338 | SF | 7 | \$0 | |
| | Ceiling - Splined | 109A Office in Science Lab | 110 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 109A Office in Science Lab | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 109A Office in Science Lab | 110 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 109A Office in Science Lab | 1 | EA | 6 | \$124 | |
| | Power Distribution | 109A Office in Science Lab | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 109A Office in Science Lab | 140 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 109A Office in Science Lab | 202 | SF | 7 | \$0 | |
| | Work SInk | 109A Office in Science Lab | 1 | EΑ | 6 | \$508 | |
| | Ceiling - Plaster/Drywall | 111B - Library Office | 243 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 111B - Library Office | 2 | EΑ | 7 | \$0 | |
| | Floor - Tile/Sheet | 111B - Library Office | 243 | SF | 6 | \$243 | |
| | Lighting - Pendent/Surface | 111B - Library Office | 6 | EA | 7 | \$0 | |
| | Power Distribution | 111B - Library Office | 6 | EΑ | 6 | \$12,749 | |
| | Storage/ Closet | 111B - Library Office | 12 | SF | 6 | \$87 | |
| | Walls - Concrete Block | 111B - Library Office | 544 | SF | 7 | \$0 | |
| | Work SInk | 111B - Library Office | 1 | EA | 6 | \$508 | |
| | Ceiling - Splined | 1st FIr - Admissions Office - North Corridor | 185 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st FIr - Admissions Office - North Corridor | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 1st FIr - Admissions Office - North Corridor | 185 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st FIr - Admissions Office - North Corridor | 2 | EA | 7 | \$0 | |
| | Power Distribution | 1st Flr - Admissions Office - North Corridor | 2 | EA | 6 | \$4,250 | |
| | Walls - Concrete Block | 1st FIr - Admissions Office - North Corridor | 459 | SF | 7 | \$0 | |
| | Ceiling - Splined | 1st Flr - East Staff Resource Rm - North Corridor | 49 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Flr - East Staff Resource Rm - North Corridor | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Flr - East Staff Resource Rm - North Corridor | 289 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st Flr - East Staff Resource Rm - North Corridor | 1 | EA | 6 | \$119 | Incandescent |
| | Lighting - Pendent/Surface | 1st Flr - East Staff Resource Rm - North Corridor | 4 | EA | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group It | em - Tyne | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|-----------------------------|---|----------|-------|--------|---------|--------------------------|
| • | ative Suites/Offices | Location | Quantity | Oilit | rtuint | 0031 | Comments |
| | ower Distribution | 1st Flr - East Staff Resource Rm - North | 4 | EA | 7 | \$0 | |
| | | Corridor | | | | | |
| W | Valls - Concrete Block | 1st FIr - East Staff Resource Rm - North Corridor | 702 | SF | 7 | \$0 | |
| W | Valls - Plaster/Drywall | 1st Flr - East Staff Resource Rm - North Corridor | 240 | SF | 6 | \$662 | |
| С | eiling - Plaster/Drywall | 1st Flr - Nurses Office | 182 | SF | 6 | \$630 | |
| D | Doors - Wood Doors inclu hw | 1st Flr - Nurses Office | 2 | EA | 7 | \$0 | |
| F | loor - Tile | 1st Flr - Nurses Office | 182 | SF | 6 | \$398 | |
| Li | ighting - Pendent/Surface | 1st Flr - Nurses Office | 1 | EA | 7 | \$0 | |
| Р | lower Distribution | 1st Flr - Nurses Office | 6 | EA | 7 | \$0 | |
| S | torage/ Closet | 1st Flr - Nurses Office | 16 | SF | 6 | \$116 | |
| V | Valls - Concrete Block | 1st Flr - Nurses Office | 207 | SF | 6 | \$607 | |
| V | Valls - Plaster/Drywall | 1st Flr - Nurses Office | 249 | SF | 6 | \$687 | |
| С | eiling - Lay-in | 1st Flr - Office in Music Room | 94 | SF | 7 | \$0 | |
| D | Poors - Side-lite | 1st Flr - Office in Music Room | 12 | SF | 7 | \$0 | |
| D | Poors - Wood Doors inclu hw | 1st Flr - Office in Music Room | 1 | EA | 7 | \$0 | |
| F | loor - Carpet | 1st Flr - Office in Music Room | 94 | SF | 7 | \$0 | |
| Li | ighting - Lay-in | 1st Flr - Office in Music Room | 2 | EA | 7 | \$0 | |
| Р | lower Distribution | 1st Flr - Office in Music Room | 2 | EA | 6 | \$4,250 | |
| V | Valls - Concrete Block | 1st Flr - Office in Music Room | 68 | SF | 7 | \$0 | |
| V | Valls - Plaster/Drywall | 1st Flr - Office in Music Room | 232 | SF | 7 | \$0 | |
| V | Vork SInk | 1st Flr - Office in Music Room | 1 | EA | 6 | \$508 | |
| С | ceiling - Plaster/Drywall | 1st Flr - Registration Office in Admission Office - North Corridor | 190 | SF | 6 | \$658 | |
| D | oors - Wood Doors inclu hw | 1st Flr - Registration Office in Admission Office - North Corridor | 1 | EA | 7 | \$0 | |
| F | loor - Carpet | 1st Flr - Registration Office in Admission Office - North Corridor | 190 | SF | 7 | \$0 | |
| Li | ighting - Lay-in | 1st Flr - Registration Office in Admission Office - North Corridor | 1 | EA | 6 | \$119 | Incandescent |
| Li | ighting - Pendent/Surface | 1st FIr - Registration Office in Admission Office - North Corridor | 4 | EA | 7 | \$0 | |
| Р | ower Distribution | 1st FIr - Registration Office in Admission Office - North Corridor | 10 | EA | 7 | \$0 | |
| W | Valls - Concrete Block | 1st Flr - Registration Office in Admission Office - North Corridor | 530 | SF | 6 | \$1,554 | Covered with wood panel. |
| W | Valls - Concrete Block | 1st Flr - Registration Office in Admission Office - North Corridor | 88 | SF | 7 | \$0 | |
| С | eiling - Plaster/Drywall | 1st Flr - Scheduling Office in Admission Office - North Corridor | 190 | SF | 6 | \$658 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|---|----------|------|------|---------|-------------------------|
| Adminis | strative Suites/Offices | | | | | | |
| | Doors - Wood Doors inclu hw | 1st Flr - Scheduling Office in Admission Office - North Corridor | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Flr - Scheduling Office in Admission Office - North Corridor | 190 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st Flr - Scheduling Office in Admission Office - North Corridor | 1 | EA | 6 | \$119 | Incandescent |
| | Lighting - Pendent/Surface | 1st Flr - Scheduling Office in Admission Office - North Corridor | 4 | EA | 7 | \$0 | |
| | Power Distribution | 1st Flr - Scheduling Office in Admission Office - North Corridor | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st FIr - Scheduling Office in Admission Office - North Corridor | 618 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st FIr - School Clerk Office in Admission Office - North Corridor | 55 | SF | 6 | \$190 | |
| | Doors - Wood Doors inclu hw | 1st FIr - School Clerk Office in Admission Office - North Corridor | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st FIr - School Clerk Office in Admission Office - North Corridor | 55 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Flr - School Clerk Office in Admission Office - North Corridor | 2 | EA | 7 | \$0 | |
| | Power Distribution | 1st Flr - School Clerk Office in Admission Office - North Corridor | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Flr - School Clerk Office in Admission Office - North Corridor | 417 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st FIr - West Staff Resource Rm - North Corridor | 240 | SF | 6 | \$831 | |
| | Doors - Wood Doors inclu hw | 1st FIr - West Staff Resource Rm - North Corridor | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st FIr - West Staff Resource Rm - North Corridor | 289 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st FIr - West Staff Resource Rm - North Corridor | 1 | EA | 6 | \$119 | Incandescent |
| | Lighting - Pendent/Surface | 1st FIr - West Staff Resource Rm - North Corridor | 4 | EA | 7 | \$0 | |
| | Power Distribution | 1st FIr - West Staff Resource Rm - North Corridor | 4 | EA | 7 | \$0 | |
| | Storage/ Closet | 1st Flr - West Staff Resource Rm - North Corridor | 49 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Flr - West Staff Resource Rm - North Corridor | 702 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Flr Discipline Office | 400 | SF | 6 | \$1,384 | |
| | Ceiling - Plaster/Drywall | 1st Flr Discipline Office | 43 | SF | 4 | \$936 | stained, damaged, dirty |
| | Doors - Wood Doors inclu hw | 1st Flr Discipline Office | 1 | EA | 6 | \$301 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| | tem - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|--------------------------------|--|----------|------|------|---------|----------|
| - | rative Suites/Offices | | | | | | |
| F | Floor - Tile | 1st FIr Discipline Office | 443 | SF | 6 | \$969 | vct |
| L | Lighting - Pendent/Surface | 1st FIr Discipline Office | 8 | EA | 7 | \$0 | |
| F | Power Distribution | 1st Flr Discipline Office | 9 | EA | 7 | \$0 | |
| ٧ | Walls - Concrete Block | 1st Flr Discipline Office | 486 | SF | 6 | \$1,425 | |
| V | Walls - Plaster/Drywall | 1st Flr Discipline Office | 162 | SF | 7 | \$0 | |
| | Ceiling - Splined | 1st FIr- ID Room | 163 | SF | 6 | \$133 | |
| | Doors - Wood Doors inclu hw | 1st FIr- ID Room | 1 | EA | 7 | \$0 | |
| F | Floor - Tile/Sheet | 1st FIr- ID Room | 163 | SF | 7 | \$0 | |
| L | Lighting - Pendent/Surface | 1st FIr- ID Room | 4 | EA | 7 | \$0 | |
| L | Lighting - Wall Mounted | 1st FIr- ID Room | 2 | EA | 7 | \$0 | |
| F | Power Distribution | 1st FIr- ID Room | 12 | EA | 7 | \$0 | |
| ٧ | Walls - Plaster/Drywall | 1st FIr- ID Room | 210 | SF | 7 | \$0 | |
| ٧ | Walls - Plaster/Drywall | 1st FIr- ID Room | 210 | SF | 7 | \$0 | |
| (| Ceiling - Splined | 1st Flr Kitchen Office | 80 | SF | 6 | \$65 | |
| | Doors - Wood Doors inclu hw | 1st Flr Kitchen Office | 1 | EA | 6 | \$301 | |
| F | Floor - Tile Quarry | 1st Flr Kitchen Office | 80 | SF | 6 | \$169 | |
| L | Lighting - Pendent/Surface | 1st Flr Kitchen Office | 1 | EA | 6 | \$124 | |
| F | Power Distribution | 1st Flr Kitchen Office | 4 | EA | 7 | \$0 | |
| ٧ | Walls - Structural Glazed Tile | 1st Flr Kitchen Office | 279 | SF | 7 | \$0 | |
| (| Ceiling - Plaster/Drywall | 1st Flr Office A in Discipline Office | 98 | SF | 5 | \$898 | |
| | Doors - Wood Doors inclu hw | 1st Flr Office A in Discipline Office | 1 | EA | 7 | \$0 | |
| F | Floor - Tile | 1st Flr Office A in Discipline Office | 98 | SF | 6 | \$214 | vct |
| L | Lighting - Pendent/Surface | 1st Flr Office A in Discipline Office | 2 | EA | 7 | \$0 | |
| F | Power Distribution | 1st FIr Office A in Discipline Office | 2 | EA | 7 | \$0 | |
| ٧ | Walls - Concrete Block | 1st FIr Office A in Discipline Office | 99 | SF | 6 | \$290 | |
| V | Walls - Plaster/Drywall | 1st FIr Office A in Discipline Office | 100 | SF | 6 | \$276 | |
| (| Ceiling - Plaster/Drywall | 1st FIr Office B in Discipline Office | 98 | SF | 5 | \$898 | |
| | Doors - Wood Doors inclu hw | 1st FIr Office B in Discipline Office | 1 | EA | 7 | \$0 | |
| F | Floor - Tile | 1st FIr Office B in Discipline Office | 98 | SF | 6 | \$214 | vct |
| L | Lighting - Pendent/Surface | 1st FIr Office B in Discipline Office | 2 | EA | 7 | \$0 | |
| F | Power Distribution | 1st FIr Office B in Discipline Office | 2 | EA | 7 | \$0 | |
| V | Walls - Concrete Block | 1st Flr Office B in Discipline Office | 99 | SF | 6 | \$290 | |
| V | Walls - Plaster/Drywall | 1st Flr Office B in Discipline Office | 100 | SF | 6 | \$276 | |
| C | Ceiling - Splined | 1st FIr- Office/Cafe in Center of Main Corridor "JFK Copy Cat Cafe" | 96 | SF | 6 | \$78 | |
| | Doors - Wood Doors inclu hw | 1st FIr- Office/Cafe in Center of Main Corridor "JFK Copy Cat Cafe" | 1 | EA | 7 | \$0 | |



Co-locating on this campus are KENNEDY HS and KINZIE

6325 W 56th St Chicago, IL 60638

Building: Kennedy

| o Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------------|--|----------|------|------|---------|----------------|
| nistrative Suites/Offices | | | | | | |
| Floor - Wood | 1st FIr- Office/Cafe in Center of Main Corridor "JFK Copy Cat Cafe" | 96 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | 1st FIr- Office/Cafe in Center of Main Corridor "JFK Copy Cat Cafe" | 2 | EA | 7 | \$0 | |
| Power Distribution | 1st FIr- Office/Cafe in Center of Main Corridor "JFK Copy Cat Cafe" | 10 | EA | 7 | \$0 | |
| Walls - Concrete Block | 1st FIr- Office/Cafe in Center of Main Corridor "JFK Copy Cat Cafe" | 269 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | 1st Flr Police Office in Discipline Office | 98 | SF | 6 | \$339 | popcorn finish |
| Doors - Wood Doors inclu hw | 1st Flr Police Office in Discipline Office | 1 | EΑ | 7 | \$0 | |
| Floor - Tile | 1st Flr Police Office in Discipline Office | 98 | SF | 6 | \$214 | |
| Lighting - Pendent/Surface | 1st Flr Police Office in Discipline Office | 2 | EA | 7 | \$0 | |
| Power Distribution | 1st Flr Police Office in Discipline Office | 2 | EA | 7 | \$0 | |
| Walls - Concrete Block | 1st Flr Police Office in Discipline Office | 99 | SF | 6 | \$290 | |
| Walls - Plaster/Drywall | 1st Flr Police Office in Discipline Office | 100 | SF | 6 | \$276 | |
| Ceiling - Plaster/Drywall | 1st Flr Pool Office | 122 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw | 1st Flr Pool Office | 1 | EΑ | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain | 1st Flr Pool Office | 122 | SF | 6 | \$258 | |
| Lighting - Lay-in | 1st Flr Pool Office | 2 | EΑ | 6 | \$238 | |
| Power Distribution | 1st Flr Pool Office | 4 | EΑ | 6 | \$8,500 | |
| Walls - Structural Glazed Tile | 1st Flr Pool Office | 306 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | 1st Flr- Resource Rm - in Library | 140 | SF | 6 | \$484 | |
| Doors - Side-lite | 1st FIr- Resource Rm - in Library | 12 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 1st FIr- Resource Rm - in Library | 1 | EA | 7 | \$0 | |
| Floor - Tile/Sheet | 1st FIr- Resource Rm - in Library | 140 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | 1st FIr- Resource Rm - in Library | 3 | EA | 7 | \$0 | |
| Power Distribution | 1st Flr- Resource Rm - in Library | 4 | EA | 7 | \$0 | |
| Walls - Concrete Block | 1st Flr- Resource Rm - in Library | 405 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | 207A Case Manager Office - North Corridor | 289 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 207A Case Manager Office - North Corridor | 2 | EA | 7 | \$0 | |
| Floor - Tile/Sheet | 207A Case Manager Office - North Corridor | 289 | SF | 7 | \$0 | |
| Lighting - Lay-in | 207A Case Manager Office - North Corridor | 1 | EA | 6 | \$119 | Incandescent |
| Lighting - Pendent/Surface | 207A Case Manager Office - North Corridor | 4 | EA | 7 | \$0 | |
| Power Distribution | 207A Case Manager Office - North Corridor | 4 | EA | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Walls - Concrete Block | roup Item - Type | | Location | Quantity | Unit | Rank | Cost | Comments |
|--|------------------------------|--------|-------------------------------------|----------|------|------|---------|----------|
| Colling - Splined 212A - Music Room Office 94 SF 7 \$0 | dministrative Suites/Offices | | | | | | | |
| Doors - Wood Doors inclu hw | Walls - Concrete Block | | 3 | 702 | SF | 7 | \$0 | |
| Floor - Carpet | Ceiling - Splined | | 212A - Music Room Office | 94 | SF | 7 | \$0 | |
| Lighting - Lay-in 212A - Music Room Office 2 EA 7 | Doors - Wood Doors in | clu hw | 212A - Music Room Office | 1 | EA | 7 | \$0 | |
| Power Distribution 212A - Music Room Office 2 EA 7 \$0 | Floor - Carpet | | 212A - Music Room Office | 94 | SF | 7 | \$0 | |
| Walls - Plaster/Drywall 212A - Music Room Office 300 SF 6 \$828 Celling - Splined 212B - Practice Room in Music Room 1 EA 7 \$0 Doors - Wood Doors inclu hw 212B - Practice Room in Music Room 1 EA 7 \$0 Floor - Carpet 212B - Practice Room in Music Room 50 SF 7 \$0 Lighting - Pendent/Surface 212B - Practice Room in Music Room 1 EA 7 \$0 Power Distribution 212B - Practice Room in Music Room 2 EA 7 \$0 Walls - Concrete Block 212B - Practice Room in Music Room 51 SF 7 \$0 Walls - Plaster/Drywall 212C - Practice Room in Music Room 50 SF 7 \$0 Celling - Splined 212C - Practice Room in Music Room 15 SF 7 \$0 Doors - Wood Doors inclu hw 212C - Practice Room in Music Room 1 EA 7 \$0 Floor - Carpet 212C - Practice Room in Music Room 1 EA 7 <td< td=""><td>Lighting - Lay-in</td><td></td><td>212A - Music Room Office</td><td>2</td><td>EA</td><td>7</td><td>\$0</td><td></td></td<> | Lighting - Lay-in | | 212A - Music Room Office | 2 | EA | 7 | \$0 | |
| Ceiling - Splined | Power Distribution | | 212A - Music Room Office | 2 | EΑ | 7 | \$0 | |
| Doors - Wood Doors inclu hw 212B - Practice Room in Music Room 50 SF 7 S0 | Walls - Plaster/Drywall | | 212A - Music Room Office | 300 | SF | 6 | \$828 | |
| Floor - Carpet | Ceiling - Splined | | 212B - Practice Room in Music Room | 50 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface 212B - Practice Room in Music Room 2 EA 7 \$0 | Doors - Wood Doors in | clu hw | 212B - Practice Room in Music Room | 1 | EΑ | 7 | \$0 | |
| Power Distribution | Floor - Carpet | | 212B - Practice Room in Music Room | 50 | SF | 7 | \$0 | |
| Walls - Concrete Block 212B - Practice Room in Music Room 51 SF 7 \$0 Walls - Plaster/Drywall 212B - Practice Room in Music Room 195 SF 7 \$0 Ceiling - Splined 212C - Practice Room in Music Room 50 SF 7 \$0 Doors - Wood Doors inclu hw 212C - Practice Room in Music Room 1 EA 7 \$0 Floor - Carpet 212C - Practice Room in Music Room 50 SF 7 \$0 Lighting - Pendent/Surface 212C - Practice Room in Music Room 1 EA 6 \$124 Power Distribution 212C - Practice Room in Music Room 1 EA 6 \$124 Power Distribution 212C - Practice Room in Music Room 123 SF 7 \$0 Walls - Concrete Block 212C - Practice Room in Music Room 123 SF 7 \$0 Walls - Plaster/Drywall 212C - Practice Room in Music Room 123 SF 7 \$0 Ceiling - Lay-in 214A - Dark Room/Office 89 SF 5 | Lighting - Pendent/Surf | face | 212B - Practice Room in Music Room | 1 | EΑ | 7 | \$0 | |
| Walls - Plaster/Drywall 212B - Practice Room in Music Room 195 SF 7 \$0 Ceiling - Splined 212C - Practice Room in Music Room 50 SF 7 \$0 Doors - Wood Doors inclu hw 212C - Practice Room in Music Room 1 EA 7 \$0 Floor - Carpet 212C - Practice Room in Music Room 50 SF 7 \$0 Lighting - Pendent/Surface 212C - Practice Room in Music Room 1 EA 6 \$124 Power Distribution 212C - Practice Room in Music Room 1 EA 7 \$0 Walls - Concrete Block 212C - Practice Room in Music Room 123 SF 7 \$0 Walls - Plaster/Drywall 212C - Practice Room in Music Room 123 SF 7 \$0 Celling - Lay-in 214A - Dark Room/Office 89 SF 5 \$529 Doors - Wood Doors inclu hw 214A - Dark Room/Office 89 SF 7 \$0 Lighting - Lay-in 214A - Dark Room/Office 89 SF 7 \$0 < | Power Distribution | | 212B - Practice Room in Music Room | 2 | EΑ | 7 | \$0 | |
| Ceiling - Splined 212C - Practice Room in Music Room 50 SF 7 \$0 Doors - Wood Doors inclu hw 212C - Practice Room in Music Room 1 EA 7 \$0 Floor - Carpet 212C - Practice Room in Music Room 50 SF 7 \$0 Lighting - Pendent/Surface 212C - Practice Room in Music Room 1 EA 6 \$124 Power Distribution 212C - Practice Room in Music Room 1 EA 6 \$124 Power Distribution 212C - Practice Room in Music Room 123 SF 7 \$0 Walls - Concrete Block 212C - Practice Room in Music Room 123 SF 7 \$0 Walls - Plaster/Drywall 212C - Practice Room in Music Room 123 SF 7 \$0 Ceiling - Lay-in 214A - Dark Room/Office 89 SF 5 \$529 Doors - Wood Doors inclu hw 214A - Dark Room/Office 1 EA 6 \$301 Lighting - Lay-in 214A - Dark Room/Office 89 SF 7 \$0 <td>Walls - Concrete Block</td> <td></td> <td>212B - Practice Room in Music Room</td> <td>51</td> <td>SF</td> <td>7</td> <td>\$0</td> <td></td> | Walls - Concrete Block | | 212B - Practice Room in Music Room | 51 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw 212C - Practice Room in Music Room 1 EA 7 \$0 Floor - Carpet 212C - Practice Room in Music Room 50 SF 7 \$0 Lighting - Pendent/Surface 212C - Practice Room in Music Room 1 EA 6 \$124 Power Distribution 212C - Practice Room in Music Room 2 EA 7 \$0 Walls - Concrete Block 212C - Practice Room in Music Room 123 SF 7 \$0 Walls - Plaster/Drywall 212C - Practice Room in Music Room 123 SF 7 \$0 Ceiling - Lay-in 214A - Dark Room/Office 89 SF 5 \$529 Doors - Wood Doors inclu hw 214A - Dark Room/Office 89 SF 7 \$0 Floor - Tile/Sheet 214A - Dark Room/Office 89 SF 7 \$0 Lighting - Lay-in 214A - Dark Room/Office 89 SF 7 \$0 Lighting - Lay-in 214A - Dark Room/Office 89 SF 7 \$0 Wa | Walls - Plaster/Drywall | | 212B - Practice Room in Music Room | 195 | SF | 7 | \$0 | |
| Floor - Carpet | Ceiling - Splined | | 212C - Practice Room in Music Room | 50 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface 212C - Practice Room in Music Room 1 EA 6 \$124 Power Distribution 212C - Practice Room in Music Room 2 EA 7 \$0 Walls - Concrete Block 212C - Practice Room in Music Room 123 SF 7 \$0 Walls - Plaster/Drywall 212C - Practice Room in Music Room 123 SF 7 \$0 Ceiling - Lay-in 214A - Dark Room/Office 89 SF 5 \$529 Doors - Wood Doors inclu hw 214A - Dark Room/Office 1 EA 6 \$301 Floor - Tile/Sheet 214A - Dark Room/Office 89 SF 7 \$0 Lighting - Lay-in 214A - Dark Room/Office 89 SF 7 \$0 Floor - Tile/Sheet 214A - Dark Room/Office 89 SF 7 \$0 Walls - Governore Distribution 214A - Dark Room/Office 4 EA 7 \$0 Walls - Metal Panel 214A - Dark Room/Office 18 SF 6 \$1,463 Work Slnk< | Doors - Wood Doors in | clu hw | 212C - Practice Room in Music Room | 1 | EΑ | 7 | \$0 | |
| Power Distribution 212C - Practice Room in Music Room 2 EA 7 \$0 Walls - Concrete Block 212C - Practice Room in Music Room 123 SF 7 \$0 Walls - Plaster/Drywall 212C - Practice Room in Music Room 123 SF 7 \$0 Ceiling - Lay-in 214A - Dark Room/Office 89 SF 5 \$529 Doors - Wood Doors inclu hw 214A - Dark Room/Office 1 EA 6 \$301 Floor - Tile/Sheet 214A - Dark Room/Office 89 SF 7 \$0 Lighting - Lay-in 214A - Dark Room/Office 1 EA 6 \$119 Power Distribution 214A - Dark Room/Office 1 EA 6 \$119 Power Distribution 214A - Dark Room/Office 4 EA 7 \$0 Walls - Metal Panel 214A - Dark Room/Office 68 SF 7 \$0 Work Slnk 214A - Dark Room/Office 1 EA 5 \$1,463 Work Slnk 214B Gym Office (formerly Storage) | Floor - Carpet | | 212C - Practice Room in Music Room | 50 | SF | 7 | \$0 | |
| Walls - Concrete Block 212C - Practice Room in Music Room 123 SF 7 \$0 Walls - Plaster/Drywall 212C - Practice Room in Music Room 123 SF 7 \$0 Ceiling - Lay-in 214A - Dark Room/Office 89 SF 5 \$529 Doors - Wood Doors inclu hw 214A - Dark Room/Office 1 EA 6 \$301 Floor - Tile/Sheet 214A - Dark Room/Office 89 SF 7 \$0 Lighting - Lay-in 214A - Dark Room/Office 1 EA 6 \$119 Power Distribution 214A - Dark Room/Office 4 EA 7 \$0 Walls - Concrete Block 214A - Dark Room/Office 68 SF 7 \$0 Walls - Metal Panel 214A - Dark Room/Office 196 SF 6 \$1,463 Work Slnk 214A - Dark Room/Office 1 EA 5 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 18 SF 5 \$194 Ceiling - Plaster/Drywall | Lighting - Pendent/Surf | face | 212C - Practice Room in Music Room | 1 | EΑ | 6 | \$124 | |
| Walls - Plaster/Drywall 212C - Practice Room in Music Room 123 SF 7 \$0 Ceiling - Lay-in 214A - Dark Room/Office 89 SF 5 \$529 Doors - Wood Doors inclu hw 214A - Dark Room/Office 1 EA 6 \$301 Floor - Tile/Sheet 214A - Dark Room/Office 89 SF 7 \$0 Lighting - Lay-in 214A - Dark Room/Office 1 EA 6 \$119 Power Distribution 214A - Dark Room/Office 4 EA 7 \$0 Walls - Concrete Block 214A - Dark Room/Office 68 SF 7 \$0 Walls - Metal Panel 214A - Dark Room/Office 196 SF 6 \$1,463 Work SInk 214A - Dark Room/Office 196 SF 6 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 18 SF 5 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 90 SF 6 \$311 Doors - Steel Doors incl hw 218 B Gym Office (formerly Storage) 1 EA 5 | Power Distribution | | 212C - Practice Room in Music Room | 2 | EΑ | 7 | \$0 | |
| Ceiling - Lay-in 214A - Dark Room/Office 89 SF 5 \$529 Doors - Wood Doors inclu hw 214A - Dark Room/Office 1 EA 6 \$301 Floor - Tile/Sheet 214A - Dark Room/Office 89 SF 7 \$0 Lighting - Lay-in 214A - Dark Room/Office 1 EA 6 \$119 Power Distribution 214A - Dark Room/Office 4 EA 7 \$0 Walls - Concrete Block 214A - Dark Room/Office 68 SF 7 \$0 Walls - Metal Panel 214A - Dark Room/Office 196 SF 6 \$1,463 Work Slnk 214A - Dark Room/Office 1 EA 5 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 18 SF 5 \$194 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 90 SF 6 \$311 Doors - Steel Doors incl hw 218 B Gym Office (formerly Storage) 1 EA 5 \$2,348 Floor - Tile 218 B Gym Office (formerly Storage) 1 EA 7 \$0 | Walls - Concrete Block | | 212C - Practice Room in Music Room | 123 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw 214A - Dark Room/Office 1 EA 6 \$301 Floor - Tile/Sheet 214A - Dark Room/Office 89 SF 7 \$0 Lighting - Lay-in 214A - Dark Room/Office 1 EA 6 \$119 Power Distribution 214A - Dark Room/Office 4 EA 7 \$0 Walls - Concrete Block 214A - Dark Room/Office 68 SF 7 \$0 Walls - Metal Panel 214A - Dark Room/Office 196 SF 6 \$1,463 Work SInk 214A - Dark Room/Office 1 EA 5 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 18 SF 5 \$194 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 90 SF 6 \$311 Doors - Steel Doors incl hw 218 B Gym Office (formerly Storage) 2 EA 5 \$2,348 Floor - Tile 218 B Gym Office (formerly Storage) 108 SF 6 \$236 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 7 \$0 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 6 \$124 Power Distribution 218 B Gym Office (formerly | Walls - Plaster/Drywall | | 212C - Practice Room in Music Room | 123 | SF | 7 | \$0 | |
| Floor - Tile/Sheet 214A - Dark Room/Office 89 SF 7 \$0 Lighting - Lay-in 214A - Dark Room/Office 1 EA 6 \$119 Power Distribution 214A - Dark Room/Office 4 EA 7 \$0 Walls - Concrete Block 214A - Dark Room/Office 68 SF 7 \$0 Walls - Metal Panel 214A - Dark Room/Office 196 SF 6 \$1,463 Work Slnk 214A - Dark Room/Office 1 EA 5 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 18 SF 5 \$194 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 90 SF 6 \$311 Doors - Steel Doors incl hw 218 B Gym Office (formerly Storage) 2 EA 5 \$2,348 Floor - Tile 218 B Gym Office (formerly Storage) 1 EA 7 \$0 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 6 \$124 Pow | Ceiling - Lay-in | | 214A - Dark Room/Office | 89 | SF | 5 | \$529 | |
| Lighting - Lay-in 214A - Dark Room/Office 1 EA 6 \$119 Power Distribution 214A - Dark Room/Office 4 EA 7 \$0 Walls - Concrete Block 214A - Dark Room/Office 68 SF 7 \$0 Walls - Metal Panel 214A - Dark Room/Office 196 SF 6 \$1,463 Work Slnk 214A - Dark Room/Office 1 EA 5 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 18 SF 5 \$194 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 90 SF 6 \$311 Doors - Steel Doors incl hw 218 B Gym Office (formerly Storage) 2 EA 5 \$2,348 Floor - Tile 218 B Gym Office (formerly Storage) 108 SF 6 \$236 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 7 \$0 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 6 \$124 Power Distribution 218 B Gym Office (formerly Storage) 4 EA 7 \$0 | Doors - Wood Doors in | clu hw | 214A - Dark Room/Office | 1 | EA | 6 | \$301 | |
| Power Distribution 214A - Dark Room/Office 4 EA 7 \$0 Walls - Concrete Block 214A - Dark Room/Office 68 SF 7 \$0 Walls - Metal Panel 214A - Dark Room/Office 196 SF 6 \$1,463 Work SInk 214A - Dark Room/Office 1 EA 5 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 18 SF 5 \$194 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 90 SF 6 \$311 Doors - Steel Doors incl hw 218 B Gym Office (formerly Storage) 2 EA 5 \$2,348 Floor - Tile 218 B Gym Office (formerly Storage) 108 SF 6 \$236 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 7 \$0 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 6 \$124 Power Distribution 218 B Gym Office (formerly Storage) 4 EA 7 \$0 | Floor - Tile/Sheet | | 214A - Dark Room/Office | 89 | SF | 7 | \$0 | |
| Walls - Concrete Block 214A - Dark Room/Office 68 SF 7 \$0 Walls - Metal Panel 214A - Dark Room/Office 196 SF 6 \$1,463 Work SInk 214A - Dark Room/Office 1 EA 5 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 18 SF 5 \$194 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 90 SF 6 \$311 Doors - Steel Doors incl hw 218 B Gym Office (formerly Storage) 2 EA 5 \$2,348 Floor - Tile 218 B Gym Office (formerly Storage) 108 SF 6 \$236 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 7 \$0 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 6 \$124 Power Distribution 218 B Gym Office (formerly Storage) 4 EA 7 \$0 | Lighting - Lay-in | | 214A - Dark Room/Office | 1 | EA | 6 | \$119 | |
| Walls - Metal Panel 214A - Dark Room/Office 196 SF 6 \$1,463 Work SInk 214A - Dark Room/Office 1 EA 5 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 18 SF 5 \$194 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 90 SF 6 \$311 Doors - Steel Doors incl hw 218 B Gym Office (formerly Storage) 2 EA 5 \$2,348 Floor - Tile 218 B Gym Office (formerly Storage) 108 SF 6 \$236 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 7 \$0 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 6 \$124 Power Distribution 218 B Gym Office (formerly Storage) 4 EA 7 \$0 | Power Distribution | | 214A - Dark Room/Office | 4 | EA | 7 | \$0 | |
| Work SInk 214A - Dark Room/Office 1 EA 5 \$1,508 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 18 SF 5 \$194 Ceiling - Plaster/Drywall 218 B Gym Office (formerly Storage) 90 SF 6 \$311 Doors - Steel Doors incl hw 218 B Gym Office (formerly Storage) 2 EA 5 \$2,348 Floor - Tile 218 B Gym Office (formerly Storage) 108 SF 6 \$236 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 7 \$0 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 6 \$124 Power Distribution 218 B Gym Office (formerly Storage) 4 EA 7 \$0 | Walls - Concrete Block | | 214A - Dark Room/Office | 68 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall218 B Gym Office (formerly Storage)18SF5\$194Ceiling - Plaster/Drywall218 B Gym Office (formerly Storage)90SF6\$311Doors - Steel Doors incl hw218 B Gym Office (formerly Storage)2EA5\$2,348Floor - Tile218 B Gym Office (formerly Storage)108SF6\$236Lighting - Pendent/Surface218 B Gym Office (formerly Storage)1EA7\$0Lighting - Pendent/Surface218 B Gym Office (formerly Storage)1EA6\$124Power Distribution218 B Gym Office (formerly Storage)4EA7\$0 | Walls - Metal Panel | | 214A - Dark Room/Office | 196 | SF | 6 | \$1,463 | |
| Ceiling - Plaster/Drywall218 B Gym Office (formerly Storage)90 SF6\$311Doors - Steel Doors incl hw218 B Gym Office (formerly Storage)2 EA5\$2,348Floor - Tile218 B Gym Office (formerly Storage)108 SF6\$236Lighting - Pendent/Surface218 B Gym Office (formerly Storage)1 EA7\$0Lighting - Pendent/Surface218 B Gym Office (formerly Storage)1 EA6\$124Power Distribution218 B Gym Office (formerly Storage)4 EA7\$0 | Work SInk | | 214A - Dark Room/Office | 1 | EA | 5 | \$1,508 | |
| Doors - Steel Doors incl hw218 B Gym Office (formerly Storage)2 EA5\$2,348Floor - Tile218 B Gym Office (formerly Storage)108 SF6\$236Lighting - Pendent/Surface218 B Gym Office (formerly Storage)1 EA7\$0Lighting - Pendent/Surface218 B Gym Office (formerly Storage)1 EA6\$124Power Distribution218 B Gym Office (formerly Storage)4 EA7\$0 | Ceiling - Plaster/Drywa | Ш | 218 B Gym Office (formerly Storage) | 18 | SF | 5 | \$194 | |
| Floor - Tile 218 B Gym Office (formerly Storage) 108 SF 6 \$236 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 7 \$0 Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 6 \$124 Power Distribution 218 B Gym Office (formerly Storage) 4 EA 7 \$0 | Ceiling - Plaster/Drywa | ll . | 218 B Gym Office (formerly Storage) | 90 | SF | 6 | \$311 | |
| Lighting - Pendent/Surface218 B Gym Office (formerly Storage)1 EA 7\$0Lighting - Pendent/Surface218 B Gym Office (formerly Storage)1 EA 6\$124Power Distribution218 B Gym Office (formerly Storage)4 EA 7\$0 | Doors - Steel Doors inc | l hw | 218 B Gym Office (formerly Storage) | 2 | EA | 5 | \$2,348 | |
| Lighting - Pendent/Surface 218 B Gym Office (formerly Storage) 1 EA 6 \$124 Power Distribution 218 B Gym Office (formerly Storage) 4 EA 7 \$0 | Floor - Tile | | 218 B Gym Office (formerly Storage) | 108 | SF | 6 | \$236 | |
| Power Distribution 218 B Gym Office (formerly Storage) 4 EA 7 \$0 | Lighting - Pendent/Surf | face | 218 B Gym Office (formerly Storage) | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surf | face | 218 B Gym Office (formerly Storage) | 1 | EA | 6 | \$124 | |
| Walls - Concrete Block 218 B Gym Office (formerly Storage) 300 SF 7 \$0 | Power Distribution | | 218 B Gym Office (formerly Storage) | 4 | | | | |
| | Walls - Concrete Block | | 218 B Gym Office (formerly Storage) | 300 | SF | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Administrative Suites/Offices Ceiling - Splined 218A - Gym Office 92 SF 5 \$655 Doors - Steel Doors incl hw 218A - Gym Office 1 EA 6 \$301 Doors - Wood Doors inclu hw 218A - Gym Office 1 EA 6 \$301 | |
|---|--|
| Doors - Steel Doors incl hw 218A - Gym Office 1 EA 6 \$301 Doors - Wood Doors inclu hw 218A - Gym Office 1 EA 6 \$301 | |
| Doors - Wood Doors inclu hw 218A - Gym Office 1 EA 6 \$301 | |
| Doors - Wood Doors inclu hw 218A - Gym Office 1 EA 6 \$301 | |
| | |
| Floor - Tile 218A - Gym Office 92 SF 5 \$413 | |
| Lighting - Lay-in 218A - Gym Office 1 EA 5 \$162 | |
| Power Distribution 218A - Gym Office 4 EA 7 \$0 | |
| Storage/ Closet 218A - Gym Office 8 SF 6 \$58 | |
| Walls - Concrete Block 218A - Gym Office 300 SF 6 \$879 | |
| Ceiling - Splined 219A Main Gym Office 150 SF 6 \$122 | |
| Ceiling - Splined 219A Main Gym Office 80 SF 5 \$667 | |
| Doors - Steel Doors incl hw 219A Main Gym Office 1 EA 5 \$1,174 | |
| Doors - Wood Doors inclu hw 219A Main Gym Office 1 EA 6 \$301 | |
| Floor - Tile/Sheet 219A Main Gym Office 230 SF 6 \$230 | |
| Lighting - Lay-in 219A Main Gym Office 4 EA 7 \$0 | |
| Power Distribution 219A Main Gym Office 6 EA 7 \$0 | |
| Storage/ Closet 219A Main Gym Office 16 SF 6 \$116 | |
| Walls - Concrete Block 219A Main Gym Office 410 SF 6 \$1,202 | |
| Walls - Plaster/Drywall 219A Main Gym Office 68 SF 6 \$188 | |
| Ceiling - Splined 221 - Resource Room 208 SF 6 \$170 | |
| Doors - Steel Doors incl hw 221 - Resource Room 1 EA 7 \$0 | |
| Floor - Tile Ceramic/ Porcelain 221 - Resource Room 208 SF 6 \$440 | |
| Lighting - Lay-in 221 - Resource Room 2 EA 5 \$324 missing lights | |
| Power Distribution 221 - Resource Room 4 EA 7 \$0 | |
| Walls - Concrete Block 221 - Resource Room 82 SF 6 \$240 | |
| Walls - Metal Panel 221 - Resource Room 198 SF 6 \$1,478 | |
| Walls - Structural Glazed Tile 221 - Resource Room 88 SF 7 \$0 | |
| Ceiling - Plaster/Drywall 224 - Office 60 SF 6 \$208 | |
| Doors - Steel Doors incl hw 224 - Office 1 EA 6 \$301 | |
| Floor - Tile 224 - Office 60 SF 6 \$131 | |
| Lighting - Pendent/Surface 224 - Office 2 EA 6 \$248 | |
| Power Distribution 224 - Office 4 EA 6 \$8,500 | |
| Walls - Metal Panel 224 - Office 225 SF 6 \$1,680 | |
| Ceiling - Plaster/Drywall 225 - Office 137 SF 7 \$0 | |
| Doors - Steel Doors incl hw 225 - Office 1 EA 6 \$301 | |
| Floor - Tile 225 - Office 137 SF 6 \$300 | |
| Lighting - Pendent/Surface 225 - Office 1 EA 7 \$0 | |
| Power Distribution 225 - Office 4 EA 7 \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------|---|----------|------|------|---------|---|
| Administrative Suites/Offices | | | | | | |
| Walls - Concrete Block | 225 - Office | 28 | SF | 6 | \$82 | |
| Walls - Metal Panel | 225 - Office | 168 | SF | 6 | \$1,254 | |
| Walls - Structural Glazed Tile | 225 - Office | 102 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | 226 - Office | 80 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw | 226 - Office | 1 | EA | 6 | \$301 | |
| Floor - Tile | 226 - Office | 80 | SF | 5 | \$359 | |
| Lighting - Lay-in | 226 - Office | 2 | EΑ | 7 | \$0 | |
| Power Distribution | 226 - Office | 2 | EΑ | 6 | \$4,250 | |
| Walls - Metal Panel | 226 - Office | 219 | SF | 6 | \$1,635 | |
| Ceiling - Plaster/Drywall | 227 - Office | 170 | SF | 7 | \$0 | spray texture finish |
| Doors - Steel Doors incl hw | 227 - Office | 1 | EA | 6 | \$301 | |
| Floor - Tile | 227 - Office | 170 | SF | 5 | \$763 | |
| Lighting - Lay-in | 227 - Office | 2 | EΑ | 6 | \$238 | |
| Power Distribution | 227 - Office | 2 | EΑ | 7 | \$0 | |
| Walls - Metal Panel | 227 - Office | 301 | SF | 6 | \$2,247 | |
| Ceiling - Plaster/Drywall | 2nd Flr - Staff Resource Rm - North Corridor | 289 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 2nd Flr - Staff Resource Rm - North Corridor | 1 | EA | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 2nd Flr - Staff Resource Rm - North Corridor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 2nd Flr - Staff Resource Rm - North Corridor | 289 | SF | 7 | \$0 | |
| Lighting - Lay-in | 2nd FIr - Staff Resource Rm - North Corridor | 1 | EA | 6 | \$119 | Recessed Incandescent |
| Lighting - Pendent/Surface | 2nd Flr - Staff Resource Rm - North Corridor | 4 | EA | 7 | \$0 | |
| Power Distribution | 2nd Flr - Staff Resource Rm - North Corridor | 4 | EA | 7 | \$0 | |
| Walls - Concrete Block | 2nd FIr - Staff Resource Rm - North Corridor | 702 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | 301A - Office (In room 301) | 73 | SF | 6 | \$253 | |
| Doors - Side-lite | 301A - Office (In room 301) | 18 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 301A - Office (In room 301) | 1 | EA | 7 | \$0 | |
| Floor - Tile/Sheet | 301A - Office (In room 301) | 73 | SF | 6 | \$73 | |
| Lighting - Pendent/Surface | 301A - Office (In room 301) | 1 | EA | 6 | \$124 | |
| Power Distribution | 301A - Office (In room 301) | 2 | EA | 7 | \$0 | |
| Walls - Concrete Block | 301A - Office (In room 301) | 271 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | Basement Engineers Kitchentte | 60 | SF | 4 | \$903 | large hole in ceiling and remaining surfaces are cracked. |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-------------------------------|----------|------|------|-----------|--|
| Admini | strative Suites/Offices | | | | | | |
| | Doors - Wood Doors inclu hw | Basement Engineers Kitchentte | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Basement Engineers Kitchentte | 60 | SF | 6 | \$131 | |
| | Lighting - Pendent/Surface | Basement Engineers Kitchentte | 1 | EA | 5 | \$183 | "A" lamp, no lens |
| | Power Distribution | Basement Engineers Kitchentte | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Basement Engineers Kitchentte | 280 | SF | 6 | \$821 | |
| | Work Sink | Basement Engineers Kitchentte | 1 | EΑ | 6 | \$508 | |
| | Ceiling - Plaster/Drywall | Basement Engineers Office | 160 | SF | 6 | \$554 | |
| | Ceiling - Plaster/Drywall | Basement Engineers Office | 16 | SF | 5 | \$200 | |
| | Doors - Steel Doors incl hw | Basement Engineers Office | 1 | EΑ | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | Basement Engineers Office | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile | Basement Engineers Office | 176 | SF | 5 | \$790 | |
| | Lighting - Pendent/Surface | Basement Engineers Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | Basement Engineers Office | 8 | EA | 7 | \$0 | |
| | Storage/ Closet | Basement Engineers Office | 22 | SF | 5 | \$355 | water damage/infiltration |
| | Walls - Concrete Block | Basement Engineers Office | 400 | SF | 6 | \$1,173 | |
| Auditor | rium & Theater | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,100 | SF | 6 | \$10,791 | @ stage |
| | Ceiling - Plaster/Drywall | 1st Floor | 7,500 | SF | 6 | \$62,527 | textured |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 6 | \$602 | @ stage |
| | Doors - Wood Doors inclu hw | 1st Floor | 8 | EA | 7 | \$0 | |
| | Floor - Carpet | 1st Floor | 3,900 | SF | 7 | \$0 | |
| | Floor - Concrete Epoxy/ Painted | 1st Floor | 3,300 | SF | 6 | \$1,746 | |
| | Floor - Terrazzo | 1st Floor | 60 | SF | 7 | \$0 | @ stair |
| | Lighting - Pendent/Surface | 1st Floor | 78 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 1st Floor | 12 | EA | 5 | \$2,034 | |
| | Main Floor Seating | 1st Floor | 72 | EA | 5 | \$27,399 | |
| | Main Floor Seating | 1st Floor | 646 | EA | 6 | \$112,350 | |
| | Sound System | 1st Floor | 1 | EΑ | 7 | \$0 | |
| | Stage | 1st Floor | 1,430 | SF | 6 | \$8,261 | wood floor |
| | Stage Curtain | 1st Floor | 3 | EΑ | 7 | \$0 | |
| | Stage Lighting System | 1st Floor | 1 | EΑ | 7 | \$0 | |
| | Stage-Stairs - Terrazzo | 1st Floor | 67 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 320 | SF | 5 | \$5,162 | formerly "Coat Check Room" - used as storage |
| | Storage/ Closet | 1st Floor | 44 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,800 | SF | 6 | \$8,571 | |
| | Walls - Sound Panel | 1st Floor | 200 | SF | 6 | \$807 | acoustic tile |
| | | | | SF | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Auditoriu | | | | | | | |
|-----------|---------------------------------|----------------------|--------|------|---|----------|--|
| | um & Theater | | | | | | |
| | Walls - Structural Glazed Tile | 1st Floor | 2,840 | SF | 7 | \$0 | glazed terracotta |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor | 600 | SF | 7 | \$0 | |
| Gymnas | ia | | | | | | |
| - | Ceiling - Lay-in | 218 (Girls) Gym | 5,580 | SF | 6 | \$16,757 | |
| | Doors - Steel Doors incl hw | 218 (Girls) Gym | 10 | EA | 5 | \$11,741 | |
| | Doors - Steel Doors incl hw | 218 (Girls) Gym | 2 | EA | 6 | \$602 | |
| | Floor - Wood | 218 (Girls) Gym | 5,580 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 218 (Girls) Gym | 18 | EA | 7 | \$0 | |
| | Storage/ Closet | 218 (Girls) Gym | 70 | SF | 5 | \$1,129 | |
| | Storage/ Closet | 218 (Girls) Gym | 150 | SF | 7 | \$0 | |
| | Walls - Concrete Block | 218 (Girls) Gym | 335 | SF | 5 | \$4,719 | stepped and vertical cracks in CMU |
| | Walls - Concrete Block | 218 (Girls) Gym | 3,000 | SF | 6 | \$8,795 | otoppod and tortion ordered in Cinic |
| | Walls - Structural Glazed Tile | 218 (Girls) Gym | 1,830 | SF | 7 | \$0 | |
| | Bleacher Seating | 219 Main (Boys) Gym | 119 | EA | 7 | \$0 | calculated at 24" per person (note bleachers are |
| | 2. Sacrific Country | 2.0 maii: (20,0, 0,1 | | _, , | • | 40 | divided into 18" seat sections) |
| | Ceiling - Lay-in | 219 Main (Boys) Gym | 6,080 | SF | 6 | \$18,258 | |
| | Doors - Steel Doors incl hw | 219 Main (Boys) Gym | 4 | EA | 5 | \$4,696 | |
| | Doors - Steel Doors incl hw | 219 Main (Boys) Gym | 4 | EA | 4 | \$14,144 | doors damaged + do not close |
| | Doors - Wood Doors inclu hw | 219 Main (Boys) Gym | 2 | EA | 7 | \$0 | |
| | Floor - Wood | 219 Main (Boys) Gym | 6,080 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 219 Main (Boys) Gym | 18 | EA | 7 | \$0 | |
| | Scoreboards | 219 Main (Boys) Gym | 1 | EΑ | 7 | \$0 | |
| | Storage/ Closet | 219 Main (Boys) Gym | 300 | SF | 4 | \$8,361 | water damage/infiltration to ceiling, lights non- operational, floor damaged. |
| | Storage/ Closet | 219 Main (Boys) Gym | 330 | SF | 4 | \$9,197 | |
| | Walls - Concrete Block | 219 Main (Boys) Gym | 25,300 | SF | 6 | \$74,167 | , |
| | Walls - Concrete Block | 219 Main (Boys) Gym | 500 | SF | 4 | \$26,226 | visible step and vertical cracking in CMU. Special concern is the south wall. |
| | Walls - Structural Glazed Tile | 219 Main (Boys) Gym | 1,900 | SF | 6 | \$5,977 | |
| | Walls - Structural Glazed Tile | 219 Main (Boys) Gym | 70 | SF | 5 | \$4,467 | |
| | Ceiling - Plaster/Drywall | 220C Weight Room | 1,254 | SF | 6 | \$6,922 | popcorn finish |
| | Ceiling - Splined | 220C Weight Room | 169 | SF | 6 | \$138 | |
| | Doors - Steel Doors incl hw | 220C Weight Room | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 220C Weight Room | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 220C Weight Room | 1,254 | SF | 6 | \$2,672 | |
| | Floor - Tile | 220C Weight Room | 169 | SF | 5 | \$759 | |
| | Lighting - Pendent/Surface | 220C Weight Room | 18 | EA | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|--|----------|------|------|----------|-----------------|
| Gymna | • • | | | J | | - 3300 | |
| -, | Walls - Concrete Block | 220C Weight Room | 96 | SF | 6 | \$281 | |
| | Walls - Plaster/Drywall | 220C Weight Room | 468 | SF | 6 | \$1,292 | |
| | Walls - Structural Glazed Tile | 220C Weight Room | 768 | SF | 7 | \$0 | |
| | | • | | • | | ¥.~ | |
| Kitcher | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,534 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 3 | EA | 6 | \$903 | cart damage |
| | Floor - Tile Quarry | 1st Floor | 1,534 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 32 | EA | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 100 | SF | 6 | \$725 | |
| | Walls - Structural Glazed Tile | 1st Floor | 1,240 | SF | 6 | \$3,901 | |
| Library | • | | | | | | |
| | Casework | 1st Floor | 298 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,390 | SF | 7 | \$0 | |
| | Ceiling - Splined | 1st Floor | 2,050 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 5 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor | 4,278 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 98 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 1,424 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,087 | SF | 7 | \$0 | |
| | Casework | 2nd Flr Writing Center (in Library) | 125 | LF | 6 | \$3,157 | Shelves missing |
| | Ceiling - Plaster/Drywall | 2nd Flr Writing Center (in Library) | 2,147 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Flr Writing Center (in Library) | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Flr Writing Center (in Library) | 1,310 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd FIr Writing Center (in Library) | 14 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Flr Writing Center (in Library) | 38 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd FIr Writing Center (in Library) | 200 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Flr Writing Center (in Library) | 1,087 | SF | 7 | \$0 | |
| Locker | /Shower Room | | | | | | |
| | Accessories | 1st Floor Boys Pool Locker Room | 655 | SF | 6 | \$2,566 | |
| | Benches, ped mounted | 1st Floor Boys Pool Locker Room | 19 | LF | 6 | \$2,069 | |
| | Ceiling - Plaster/ Drywall | 1st Floor Boys Pool Locker Room | 665 | SF | 6 | \$2,301 | |
| | Doors - Steel Doors incl hw | 1st Floor Boys Pool Locker Room | 2 | EA | 7 | \$0 | FRP Finish |
| | Doors - Steel Doors incl hw | 1st Floor Boys Pool Locker Room | 2 | EA | 6 | \$602 | |
| | Floor Drain | 1st Floor Boys Pool Locker Room | 11 | EA | 6 | \$11,651 | |
| | Floor - Concrete | 1st Floor Boys Pool Locker Room | 284 | SF | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Boys Pool Locker Room | 381 | SF | 6 | \$806 | |
| | | ., ., ., ., ., ., ., ., ., ., ., ., ., . | | _ | - | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|---------------------------------|----------------------------------|----------|------|------|----------|------------------------------|
| - | /Shower Room | | | | | | |
| | Hand Dryer | 1st Floor Boys Pool Locker Room | 2 | EA | 5 | \$1,181 | not working |
| | Lavatory | 1st Floor Boys Pool Locker Room | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor Boys Pool Locker Room | 11 | EA | 6 | \$1,363 | |
| | Partitions | 1st Floor Boys Pool Locker Room | 1 | EA | 6 | \$297 | |
| | Showers | 1st Floor Boys Pool Locker Room | 7 | EA | 6 | \$2,180 | |
| | Student Lockers - Two Tier | 1st Floor Boys Pool Locker Room | 58 | EA | 5 | \$5,437 | |
| | Urinals | 1st Floor Boys Pool Locker Room | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor Boys Pool Locker Room | 225 | SF | 5 | \$2,716 | stained, peeling paint, mold |
| | Walls - Concrete Block | 1st Floor Boys Pool Locker Room | 696 | SF | 6 | \$2,040 | |
| | Water Closet | 1st Floor Boys Pool Locker Room | 1 | EA | 7 | \$0 | |
| | Accessories | 1st Floor Girls Pool Locker Room | 2,755 | SF | 7 | \$0 | |
| | Benches, ped mounted | 1st Floor Girls Pool Locker Room | 106 | LF | 6 | \$11,541 | |
| | Ceiling - Plaster/ Drywall | 1st Floor Girls Pool Locker Room | 2,755 | SF | 6 | \$9,534 | peeling paint |
| | Doors - Steel Doors incl hw | 1st Floor Girls Pool Locker Room | 2 | EA | 6 | \$602 | |
| | Doors - Steel Doors incl hw | 1st Floor Girls Pool Locker Room | 2 | EA | 6 | \$602 | FRP finish |
| | Floor Drain | 1st Floor Girls Pool Locker Room | 9 | EA | 6 | \$9,532 | |
| | Floor - Concrete | 1st Floor Girls Pool Locker Room | 1,972 | SF | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Girls Pool Locker Room | 783 | SF | 6 | \$1,657 | |
| | Hand Dryer | 1st Floor Girls Pool Locker Room | 7 | EA | 7 | \$0 | |
| | Hand Dryer | 1st Floor Girls Pool Locker Room | 5 | EA | 5 | \$2,952 | |
| | Lavatory | 1st Floor Girls Pool Locker Room | 2 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor Girls Pool Locker Room | 2 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor Girls Pool Locker Room | 7 | EA | 6 | \$833 | |
| | Lighting - Pendent/Surface | 1st Floor Girls Pool Locker Room | 17 | EA | 6 | \$2,106 | |
| | Partitions | 1st Floor Girls Pool Locker Room | 17 | EA | 7 | \$0 | |
| | Showers | 1st Floor Girls Pool Locker Room | 18 | EA | 6 | \$5,605 | |
| | Student Lockers - One Tier | 1st Floor Girls Pool Locker Room | 147 | EA | 6 | \$13,647 | |
| | Walls - Concrete Block | 1st Floor Girls Pool Locker Room | 520 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 1st Floor Girls Pool Locker Room | 2,750 | SF | 7 | \$0 | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor Girls Pool Locker Room | 200 | SF | 7 | \$0 | |
| | Water Closet | 1st Floor Girls Pool Locker Room | 3 | EA | 7 | \$0 | |
| | Accessories | 2nd Floor Boys Gym Locker Room | 386 | SF | 6 | \$1,512 | |
| | Benches, ped mounted | 2nd Floor Boys Gym Locker Room | 32 | LF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | 2nd Floor Boys Gym Locker Room | 956 | SF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | 2nd Floor Boys Gym Locker Room | 320 | SF | 6 | \$1,309 | |
| | Doors - Steel Doors incl hw | 2nd Floor Boys Gym Locker Room | 1 | EA | 5 | \$1,174 | |
| | Doors - Wood Doors inclu hw | 2nd Floor Boys Gym Locker Room | 3 | EA | 7 | \$0 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|--------------------------------|----------|------|------|----------|---|
| Locker | Shower Room | | | | | | |
| | Floor Drain | 2nd Floor Boys Gym Locker Room | 4 | EA | 6 | \$4,237 | |
| | Floor Drain | 2nd Floor Boys Gym Locker Room | 1 | EΑ | 5 | \$2,094 | Not functional because of floor slope. |
| | Floor Drain | 2nd Floor Boys Gym Locker Room | 1 | EΑ | 7 | \$0 | |
| | Floor - Concrete | 2nd Floor Boys Gym Locker Room | 890 | SF | 6 | \$471 | Ероху |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Boys Gym Locker Room | 386 | SF | 6 | \$817 | |
| | Hand Dryer | 2nd Floor Boys Gym Locker Room | 2 | EΑ | 7 | \$0 | |
| | Lavatory | 2nd Floor Boys Gym Locker Room | 1 | EA | 7 | \$0 | |
| | Lavatory | 2nd Floor Boys Gym Locker Room | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 2nd Floor Boys Gym Locker Room | 21 | EA | 7 | \$0 | |
| | Partitions | 2nd Floor Boys Gym Locker Room | 2 | EA | 7 | \$0 | |
| | Showers | 2nd Floor Boys Gym Locker Room | 6 | EA | 5 | \$16,287 | shower heads missing |
| | Showers | 2nd Floor Boys Gym Locker Room | 8 | EA | 6 | \$2,491 | |
| | Storage/ Closet | 2nd Floor Boys Gym Locker Room | 44 | SF | 6 | \$319 | No light |
| | Student Lockers - One Tier | 2nd Floor Boys Gym Locker Room | 7 | EA | 7 | \$0 | |
| | Student Lockers - Two Tier | 2nd Floor Boys Gym Locker Room | 126 | EA | 7 | \$0 | |
| | Urinals | 2nd Floor Boys Gym Locker Room | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor Boys Gym Locker Room | 1,010 | SF | 6 | \$2,961 | |
| | Walls - Structural Glazed Tile | 2nd Floor Boys Gym Locker Room | 1,800 | SF | 7 | \$0 | |
| | Water Closet | 2nd Floor Boys Gym Locker Room | 2 | EA | 7 | \$0 | |
| | Accessories | Basement Boys Locker Room | 373 | SF | 7 | \$0 | |
| | Benches, ped mounted | Basement Boys Locker Room | 16 | LF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | Basement Boys Locker Room | 847 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Basement Boys Locker Room | 1 | EA | 7 | \$0 | |
| | Floor Drain | Basement Boys Locker Room | 2 | EA | 7 | \$0 | |
| | Floor - Concrete | Basement Boys Locker Room | 100 | SF | 7 | \$0 | |
| | Floor - Concrete Epoxy/ Painted | Basement Boys Locker Room | 347 | SF | 6 | \$184 | |
| | Floor - Tile Ceramic/ Porcelain | Basement Boys Locker Room | 373 | SF | 7 | \$0 | |
| | Hand Dryer | Basement Boys Locker Room | 6 | EA | 7 | \$0 | |
| | Lavatory | Basement Boys Locker Room | 2 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Basement Boys Locker Room | 11 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Basement Boys Locker Room | 5 | EA | 7 | \$0 | Smaller dimensions over showers (1' X 1') |
| | Partitions | Basement Boys Locker Room | 2 | EA | 7 | \$0 | |
| | Showers | Basement Boys Locker Room | 10 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | Basement Boys Locker Room | 3 | EA | 7 | \$0 | |
| | Student Lockers - Two Tier | Basement Boys Locker Room | 48 | EA | 7 | \$0 | |
| | Urinals | Basement Boys Locker Room | 1 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Basement Boys Locker Room | 1,810 | SF | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|-----------------------------|----------|------|------|---------|--|
| Locker | Shower Room | | | | | | |
| | Water Closet | Basement Boys Locker Room | 2 | EA | 7 | \$0 | |
| | Accessories | Basement Girls Locker Room | 340 | SF | 6 | \$1,332 | |
| | Benches, ped mounted | Basement Girls Locker Room | 16 | LF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | Basement Girls Locker Room | 700 | SF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | Basement Girls Locker Room | 80 | SF | 5 | \$1,044 | water damage |
| | Doors - Wood Doors inclu hw | Basement Girls Locker Room | 1 | EA | 7 | \$0 | |
| | Floor Drain | Basement Girls Locker Room | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | Basement Girls Locker Room | 1 | EA | 7 | \$0 | |
| | Floor - Concrete Epoxy/ Painted | Basement Girls Locker Room | 440 | SF | 6 | \$233 | Some seepage at wall edges. |
| | Floor - Tile Ceramic/ Porcelain | Basement Girls Locker Room | 340 | SF | 6 | \$720 | |
| | Hand Dryer | Basement Girls Locker Room | 4 | EA | 7 | \$0 | |
| | Hand Dryer | Basement Girls Locker Room | 2 | EA | 5 | \$1,181 | Non-operational |
| | Lavatory | Basement Girls Locker Room | 2 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Basement Girls Locker Room | 9 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Basement Girls Locker Room | 5 | EA | 7 | \$0 | Smaller fixture at shower location (1' x 1') |
| | Partitions | Basement Girls Locker Room | 3 | EA | 7 | \$0 | |
| | Showers | Basement Girls Locker Room | 10 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | Basement Girls Locker Room | 3 | EA | 7 | \$0 | |
| | Student Lockers - Two Tier | Basement Girls Locker Room | 50 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Basement Girls Locker Room | 1,800 | SF | 7 | \$0 | |
| | Water Closet | Basement Girls Locker Room | 3 | EA | 7 | \$0 | |
| | Accessories | Basement Unisex Locker Room | 170 | SF | 6 | \$666 | |
| | Benches, ped mounted | Basement Unisex Locker Room | 4 | LF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | Basement Unisex Locker Room | 170 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Basement Unisex Locker Room | 1 | EA | 5 | \$1,174 | |
| | Floor Drain | Basement Unisex Locker Room | 2 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | Basement Unisex Locker Room | 170 | SF | 7 | \$0 | |
| | Hand Dryer | Basement Unisex Locker Room | 1 | EA | 7 | \$0 | |
| | Lavatory | Basement Unisex Locker Room | 1 | EΑ | 7 | \$0 | |
| | Lighting - Lay-in | Basement Unisex Locker Room | 2 | EA | 7 | \$0 | |
| | Showers | Basement Unisex Locker Room | 1 | EΑ | 7 | \$0 | |
| | Student Lockers - One Tier | Basement Unisex Locker Room | 3 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Basement Unisex Locker Room | 500 | SF | 7 | \$0 | |
| | Water Closet | Basement Unisex Locker Room | 1 | EA | 7 | \$0 | |
| Lunch | & Multipurpose Room | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor Staff Lunchroom | 872 | SF | 6 | \$3,018 | Popcorn finish |
| | Doors - Side-lite | 1st Floor Staff Lunchroom | 7 | SF | 7 | \$0 | • |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--------------------------------|---------------------------|----------|------|------|----------|--|
| Lunch | & Multipurpose Room | | | | | | |
| | Doors - Store Front | 1st Floor Staff Lunchroom | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 1st Floor Staff Lunchroom | 12 | SF | 7 | \$0 | |
| | Floor - Tile | 1st Floor Staff Lunchroom | 872 | SF | 6 | \$1,908 | |
| | Lighting - Pendent/Surface | 1st Floor Staff Lunchroom | 14 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 1st Floor Staff Lunchroom | 1,152 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 5,409 | SF | 6 | \$18,718 | spray texture 'popcorn' ceiling |
| | Ceiling - Plaster/Drywall | 1st Floor | 400 | SF | 4 | \$8,706 | spray texture 'popcorn' ceiling; water damaged and dirty over serving area |
| | Doors - Wood Doors inclu hw | 1st Floor | 5 | EA | 7 | \$0 | |
| | Floor - Tile | 1st Floor | 5,809 | SF | 6 | \$12,710 | |
| | Lighting - Lay-in | 1st Floor | 15 | EA | 6 | \$1,785 | |
| | Lighting - Pendent/Surface | 1st Floor | 62 | EA | 7 | \$0 | |
| | Serving Line | 1st Floor | 98 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 200 | SF | 6 | \$586 | |
| | Walls - Structural Glazed Tile | 1st Floor | 2,550 | SF | 7 | \$0 | |
| MDF_IC | DF . | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd flr NE Corridor | 1 | EA | 7 | \$0 | |
| | Finishes | 2nd flr NE Corridor | 794 | SF | 6 | \$5,666 | Room is also used for storage |
| | Ventilation and Cooling | 2nd flr NE Corridor | 1 | EA | 6 | \$1,855 | Room was somewhat warm |
| Mechar | nical/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 50 | SF | 6 | \$358 | east |
| | Janitor's Closet | 1st Floor | 80 | SF | 5 | \$1,290 | west |
| | Mechanical/ Service Rooms | 1st Floor | 50 | SF | 7 | \$0 | elevator machine room (adjacent to Library - south corridor) |
| | Mechanical/ Service Rooms | 1st Floor | 145 | SF | 6 | | Laundry @ North Corridor |
| | Storage Room | 1st Floor | 220 | SF | 5 | \$3,549 | NS corridor (center) - water damage/infiltration. |
| | Storage Room | 1st Floor | 125 | SF | 7 | \$0 | NS corridor (south) - book storage |
| | Storage Room | 1st Floor | 125 | SF | 6 | \$896 | NS corridor (north) |
| | Storage Room | 1st Floor | 26 | SF | 5 | \$419 | 104F File Room |
| | Storage Room | 1st Floor | 70 | SF | 6 | \$502 | 106 File Room |
| | Storage Room | 1st Floor | 18 | SF | 5 | | 107 Admin. Storage Closet |
| | Storage Room | 1st Floor | 72 | SF | 5 | \$1,161 | Toilet room at north corridor being used for as a storage room |
| | Storage Room | 1st Floor | 60 | SF | 6 | \$430 | 105 File Room |
| | Vaults | 1st Floor | 120 | SF | 6 | \$860 | 107 Admin Storage Vault |
| | Janitor's Closet | 2nd Floor | 50 | SF | 5 | \$807 | east |
| | Janitor's Closet | 2nd Floor | 80 | SF | 5 | \$1,290 | west |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------|-----------|----------|------|------|-----------|--|
| Mechar | nical/ Service Rooms | | | | | | |
| | Storage Room | 2nd Floor | 230 | SF | 5 | \$3,710 | book storage room north of Auditorium - crack in CMU @ north wall (east). water damage/infiltration. |
| | Storage Room | 2nd Floor | 230 | SF | 6 | \$1,648 | custodial storage room south of Auditorium |
| | Storage Room | 2nd Floor | 140 | SF | 6 | \$1,003 | NS corridor (north) |
| | Storage Room | 2nd Floor | 250 | SF | 7 | \$0 | NS corridor (center) - gym storage |
| | Storage Room | 2nd Floor | 150 | SF | 6 | \$1,075 | book storage - south of stage (east) |
| | Storage Room | 2nd Floor | 35 | SF | 5 | \$565 | storage south of stage (west) |
| | Storage Room | 2nd Floor | 35 | SF | 6 | \$251 | scaffolding storage - north of stage |
| | Storage Room | 2nd Floor | 100 | SF | 6 | \$716 | NS corridor (south) - gym storage |
| | Janitor's Closet | 3rd Floor | 90 | SF | 6 | \$645 | west |
| | Janitor's Closet | 3rd Floor | 50 | SF | 5 | \$807 | east - "do not enter - out of order" sign posted on door. |
| | Storage Room | 3rd Floor | 145 | SF | 5 | \$2,339 | east corridor - storage 1 - water damage/infiltration |
| | Storage Room | 3rd Floor | 110 | SF | 6 | \$788 | NS corridor (south) (books) |
| | Storage Room | 3rd Floor | 125 | SF | 6 | \$896 | east corridor - storage 3 (books) |
| | Storage Room | 3rd Floor | 125 | SF | 6 | \$896 | east corridor - storage 2 (books) |
| | Storage Room | 3rd Floor | 130 | SF | 5 | \$2,097 | NS corridor (north) (books) - water damage/infiltration |
| | Storage Room | 3rd Floor | 135 | SF | 5 | \$2,178 | east corridor - storage 4 - water damage/infiltration |
| | Air Tunnel | Basement | 3,500 | SF | 5 | \$46,597 | north west tunnel (includes NS area) - water infiltration (standing water present) |
| | Air Tunnel | Basement | 1,500 | SF | 6 | \$9,288 | south air tunnel was not accessible - door was jammed. area is estimated from plan. |
| | Air Tunnel | Basement | 2,300 | SF | 7 | \$0 | north east tunnel |
| | Boiler Room | Basement | 6,500 | SF | 5 | \$104,848 | water infiltration (standing water present) |
| | Crawl Space - Unfinished | Basement | 28,000 | SF | 6 | \$173,373 | |
| | Interior Stairs | Basement | 130 | LF | 6 | \$1,173 | Stair #3 - concrete stair |
| | Interior Stairs | Basement | 110 | LF | 6 | \$993 | Stair #4 - concrete stair |
| | Interior Stairs | Basement | 104 | LF | 6 | \$938 | Stair #5 - concrete stair (to exterior door) |
| | Mechanical/ Service Rooms | Basement | 4,000 | SF | 7 | \$0 | west fan room |
| | Mechanical/ Service Rooms | Basement | 1,500 | SF | 7 | \$0 | north electrical/switch/transformer vault |
| | Mechanical/ Service Rooms | Basement | 320 | SF | 5 | \$5,162 | water service room - note: wood shelving has pulled away from wall and needs to be secured. |
| | Mechanical/ Service Rooms | Basement | 980 | SF | 6 | \$7,021 | central electrical/passage |
| | Mechanical/ Service Rooms | Basement | 3,400 | SF | 6 | \$24,359 | central fan/mechanical room |
| | Mechanical/ Service Rooms | Basement | 7,400 | SF | 5 | \$119,365 | filter room/natatorium - water infiltration (standing water present) |
| | Mechanical/ Service Rooms | Basement | 3,200 | SF | 5 | \$51,617 | center mechanical equipment room - water infiltration (standing water present) |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Storage Room Basement 40 SF 6 \$2.866 yard storage Storage Room Basement 40 SF 6 \$3.652 2 storage rooms by engineer's office Storage Room Storage Room Basement 40 SF 6 \$3.652 2 storage rooms by engineer's office Storage Room Stor | Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|---------|---------------------------------|--------------------|----------|------|------|---------|--------------------------------------|
| Storage Room Basement 100 SF 6 \$7.6 \$ | Mechar | nical/ Service Rooms | | | | | | |
| Storage Room | | Storage Room | Basement | 400 | SF | 6 | \$2,866 | yard storage |
| Pool & Natardrium | | Storage Room | Basement | 100 | SF | 6 | \$716 | 2 storage rooms by engineer's office |
| Bleachers Seating/Plank Seating | | Storage Room | Basement | 500 | SF | 6 | \$3,582 | |
| Celling - Exposed | Pool & | Natatorium | | | | | | |
| Ceiling - Plaster/ Dywall | | Bleachers Seating/Plank Seating | 1st Floor | 72 | EA | 6 | \$2,084 | |
| Doors - Steel Doors incl hw 1st Floor 2 EA 7 \$0 FRP finish Doors - Steel Doors Incl hw 1st Floor 3.962 \$5 7 \$0 \$0 \$0 \$0 \$0 \$0 \$0 | | Ceiling - Exposed | 1st Floor | 3,210 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw 1st Floor 3.95 | | Ceiling - Plaster/ Drywall | 1st Floor | 3,952 | SF | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain | | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 7 | \$0 | FRP finish |
| Lighting - Pendent/Surface 1st Floor 3.00 EA 6 \$3,717 Pool Basin 1st Floor 3.925 SF 7 \$0 Pool Deck 1st Floor 3.925 SF 7 \$0 Pool Deck Drains 1st Floor 2.80 EA 7 \$0 Walls - Structural Glazed Tile 1st Floor 5.880 SF 7 \$0 Walls - Structural Glazed Tile 1st Floor 2.80 EA 7 \$0 Walls - Structural Glazed Tile 1st Floor 2.80 EA 7 \$0 Walls - Structural Glazed Tile 1st Floor 1st Floor 2.80 EA 7 \$0 Walls - Structural Glazed Tile 1st Floor 1st Flo | | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 7 | \$0 | |
| Pool Basin | | Floor - Tile Ceramic/ Porcelain | 1st Floor | 3,952 | SF | 7 | \$0 | |
| Pool Deck 1st Floor 3,952 SF 7 \$0 Pool Deck Drains 1st Floor 28 EA 7 \$0 Pool Deck Drains 1st Floor 5,880 SF 7 \$0 Pool Deck Drains 1st Floor 5,880 SF 7 \$0 Pool Deck Drains 1st Floor 5,880 SF 7 \$0 Pool Deck Drains 1st Floor 5,880 SF 7 \$0 Pool Deck Drains 1st Floor | | Lighting - Pendent/Surface | 1st Floor | 30 | EA | 6 | \$3,717 | |
| Pool Deck Drains 1st Floor 28 EA 7 \$0 Walls - Structural Glazed Tile 1st Floor 1st Floor 5,880 5F 7 \$0 Prep Room | | Pool Basin | 1st Floor | 3,210 | SF | 7 | \$0 | |
| Name | | Pool Deck | 1st Floor | 3,952 | SF | 7 | \$0 | |
| Casework | | Pool Deck Drains | 1st Floor | 28 | EA | 7 | \$0 | |
| Casework 314A - In room 314 50 LF 7 \$0 Ceiling - Lay-in 314A - In room 314 264 SF 5 \$1,570 Doors - Steel Doors inch lw 314A - In room 314 1 EA 6 \$301 Floor - Tile/Sheet 314A - In room 314 264 SF 7 \$0 Lighting - Lay-in 314A - In room 314 327 SF 7 \$0 Walls - Plaster/Drywall 314A - In room 314 210 SF 7 \$0 Work Sink 314A - In room 314 1 EA 6 \$379 Casework 318A - In room 318 30 SF 7 \$0 Ceiling - Lay-in 318A - In room 318 30 SF 7 \$0 Doors - Wood Doors inclu hw 318A - In room 318 1 EA 7 \$0 Floor - Tile/Sheet 318A - In room 318 30 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 6 EA 7 \$0 | | Walls - Structural Glazed Tile | 1st Floor | 5,880 | SF | 7 | \$0 | |
| Ceiling - Lay-in 314A - In room 314 264 SF 5 \$1,570 Doors - Steel Doors incl hw 314A - In room 314 1 EA 6 \$301 Floor - Tile/Sheet 314A - In room 314 264 SF 7 \$0 Lighting - Lay-in 314A - In room 314 6 EA 6 \$714 Walls - Plaster/Drywall 314A - In room 314 210 SF 7 \$0 Work Sink 314A - In room 314 1 EA 6 \$379 Casework 318A - In room 318 48 LF 7 \$0 Caling - Lay-in 318A - In room 318 30 SF 7 \$0 Doors - Wood Doors inclu hw 318A - In room 318 30 SF 7 \$0 Floor - Tile/Sheet 318A - In room 318 330 SF 7 \$0 Lighting - Lay-in 318A - In room 318 6 EA 7 \$0 Walls - Concrete Block 318A - In room 318 330 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 16 EA <t< td=""><td>Prep Ro</td><td>oom</td><td></td><td></td><td></td><td></td><td></td><td></td></t<> | Prep Ro | oom | | | | | | |
| Doors - Steel Doors incl hw 314A - In room 314 1 EA 6 \$301 Floor - Tile/Sheet 314A - In room 314 264 SF 7 \$0 Lighting - Lay-in 314A - In room 314 6 EA 6 \$714 Walls - Concrete Block 314A - In room 314 327 SF 7 \$0 Walls - Plaster/Drywall 314A - In room 314 210 SF 7 \$0 Work Sink 314A - In room 314 1 EA 6 \$379 Casework 318A - In room 318 48 LF 7 \$0 Ceiling - Lay-in 318A - In room 318 30 SF 7 \$0 Doors - Wood Doors inclu hw 318A - In room 318 30 SF 7 \$0 Lighting - Lay-in 318A - In room 318 30 SF 7 \$0 Walls - Concrete Block 318A - In room 318 36 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 | | Casework | 314A - In room 314 | 50 | LF | 7 | \$0 | |
| Floor - Tile/Sheet 314A - In room 314 264 SF 7 \$0 Lighting - Lay-in 314A - In room 314 6 EA 6 \$714 Walls - Concrete Block 314A - In room 314 327 SF 7 \$0 Walls - Plaster/Drywall 314A - In room 314 210 SF 7 \$0 Work Sink 314A - In room 314 1 EA 6 \$379 Casework 318A - In room 318 48 LF 7 \$0 Ceiling - Lay-in 318A - In room 318 330 SF 7 \$0 Floor - Tile/Sheet 318A - In room 318 330 SF 7 \$0 Lighting - Lay-in 318A - In room 318 36 EA 7 \$0 Walls - Plaster/Drywall 318A - In room 318 6 EA 7 \$0 Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 Work Sink 318A - In room 320 24 LF 7 \$0 | | Ceiling - Lay-in | 314A - In room 314 | 264 | SF | 5 | \$1,570 | |
| Lighting - Lay-in 314A - In room 314 6 EA 6 \$714 Walls - Concrete Block 314A - In room 314 327 SF 7 \$0 Walls - Plaster/Drywall 314A - In room 314 210 SF 7 \$0 Work Sink 314A - In room 314 1 EA 6 \$379 Casework 318A - In room 318 48 LF 7 \$0 Ceiling - Lay-in 318A - In room 318 30 SF 7 \$0 Doors - Wood Doors inclu hw 318A - In room 318 1 EA 7 \$0 Floor - Tile/Sheet 318A - In room 318 30 SF 7 \$0 Lighting - Lay-in 318A - In room 318 30 SF 7 \$0 Walls - Poortete Block 318A - In room 318 30 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 36 EA 7 \$0 Walls - Plaster/Drywall 318A - In room 318 1 EA 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Doors - Steel Doors incl hw | 314A - In room 314 | 1 | EA | 6 | \$301 | |
| Walls - Concrete Block 314A - In room 314 327 SF 7 \$0 Walls - Plaster/Drywall 314A - In room 314 210 SF 7 \$0 Work Sink 314A - In room 314 1 EA 6 \$379 Casework 318A - In room 318 48 LF 7 \$0 Ceiling - Lay-in 318A - In room 318 1 EA 7 \$0 Doors - Wood Doors inclu hw 318A - In room 318 30 SF 7 \$0 Floor - Tile/Sheet 318A - In room 318 330 SF 7 \$0 Lighting - Lay-in 318A - In room 318 6 EA 7 \$0 Walls - Concrete Block 318A - In room 318 336 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 36 SF 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 | | Floor - Tile/Sheet | 314A - In room 314 | 264 | SF | 7 | \$0 | |
| Walls - Plaster/Drywall 314A - In room 314 210 SF 7 \$0 Work Sink 314A - In room 314 1 EA 6 \$379 Casework 318A - In room 318 48 LF 7 \$0 Ceiling - Lay-in 318A - In room 318 330 SF 7 \$0 Doors - Wood Doors inclu hw 318A - In room 318 1 EA 7 \$0 Floor - Tile/Sheet 318A - In room 318 330 SF 7 \$0 Lighting - Lay-in 318A - In room 318 6 EA 7 \$0 Walls - Concrete Block 318A - In room 318 336 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 40 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 <td></td> <td>Lighting - Lay-in</td> <td>314A - In room 314</td> <td>6</td> <td>EA</td> <td>6</td> <td>\$714</td> <td></td> | | Lighting - Lay-in | 314A - In room 314 | 6 | EA | 6 | \$714 | |
| Work Sink 314A - In room 314 1 EA 6 \$379 Casework 318A - In room 318 48 LF 7 \$0 Ceiling - Lay-in 318A - In room 318 330 SF 7 \$0 Doors - Wood Doors inclu hw 318A - In room 318 1 EA 7 \$0 Floor - Tile/Sheet 318A - In room 318 330 SF 7 \$0 Lighting - Lay-in 318A - In room 318 6 EA 7 \$0 Walls - Concrete Block 318A - In room 318 336 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Walls - Concrete Block | 314A - In room 314 | 327 | SF | 7 | \$0 | |
| Casework 318A - In room 318 48 LF 7 \$0 Ceiling - Lay-in 318A - In room 318 330 SF 7 \$0 Doors - Wood Doors inclu hw 318A - In room 318 1 EA 7 \$0 Floor - Tile/Sheet 318A - In room 318 330 SF 7 \$0 Lighting - Lay-in 318A - In room 318 6 EA 7 \$0 Walls - Concrete Block 318A - In room 318 336 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Walls - Plaster/Drywall | 314A - In room 314 | 210 | SF | 7 | \$0 | |
| Ceiling - Lay-in 318A - In room 318 330 SF 7 \$0 Doors - Wood Doors inclu hw 318A - In room 318 1 EA 7 \$0 Floor - Tile/Sheet 318A - In room 318 330 SF 7 \$0 Lighting - Lay-in 318A - In room 318 6 EA 7 \$0 Walls - Concrete Block 318A - In room 318 336 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Work Sink | 314A - In room 314 | 1 | EA | 6 | \$379 | |
| Doors - Wood Doors inclu hw 318A - In room 318 1 EA 7 \$0 Floor - Tile/Sheet 318A - In room 318 330 SF 7 \$0 Lighting - Lay-in 318A - In room 318 6 EA 7 \$0 Walls - Concrete Block 318A - In room 318 336 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Casework | 318A - In room 318 | 48 | LF | 7 | \$0 | |
| Floor - Tile/Sheet 318A - In room 318 330 SF 7 \$0 Lighting - Lay-in 318A - In room 318 6 EA 7 \$0 Walls - Concrete Block 318A - In room 318 336 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Ceiling - Lay-in | 318A - In room 318 | 330 | SF | 7 | \$0 | |
| Lighting - Lay-in 318A - In room 318 6 EA 7 \$0 Walls - Concrete Block 318A - In room 318 336 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Doors - Wood Doors inclu hw | 318A - In room 318 | 1 | EA | 7 | \$0 | |
| Walls - Concrete Block 318A - In room 318 336 SF 7 \$0 Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Floor - Tile/Sheet | 318A - In room 318 | 330 | SF | 7 | \$0 | |
| Walls - Plaster/Drywall 318A - In room 318 168 SF 7 \$0 Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Lighting - Lay-in | 318A - In room 318 | 6 | EA | 7 | \$0 | |
| Work Sink 318A - In room 318 1 EA 7 \$0 Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Walls - Concrete Block | 318A - In room 318 | 336 | SF | 7 | \$0 | |
| Casework 320A - In room 320 24 LF 7 \$0 Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Walls - Plaster/Drywall | 318A - In room 318 | 168 | SF | 7 | \$0 | |
| Ceiling - Splined 320A - In room 320 100 SF 7 \$0 Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Work Sink | 318A - In room 318 | 1 | EA | 7 | \$0 | |
| Doors - Side-lite 320A - In room 320 40 SF 7 \$0 | | Casework | 320A - In room 320 | 24 | LF | 7 | \$0 | |
| | | Ceiling - Splined | 320A - In room 320 | 100 | SF | 7 | \$0 | |
| Doors - Transom Window 320A - In room 320 40 SF 7 \$0 | | Doors - Side-lite | 320A - In room 320 | 40 | SF | 7 | \$0 | |
| | | Doors - Transom Window | 320A - In room 320 | 40 | SF | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|--------------------|----------|------|------|---------|-------------------------|
| Prep R | oom | | | | | | |
| | Doors - Wood Doors inclu hw | 320A - In room 320 | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 320A - In room 320 | 100 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 320A - In room 320 | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 320A - In room 320 | 250 | SF | 7 | \$0 | |
| | Work Sink | 320A - In room 320 | 1 | EA | 7 | \$0 | |
| Restro | om | | | | | | |
| | Accessories | 121 Unisex at Pool | 148 | SF | 7 | \$0 | |
| | Benches | 121 Unisex at Pool | 4 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 121 Unisex at Pool | 148 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 121 Unisex at Pool | 2 | EA | 7 | \$0 | 1 door with FRP surface |
| | Floor Drain | 121 Unisex at Pool | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 121 Unisex at Pool | 148 | SF | 6 | \$313 | |
| | Hand Dryer | 121 Unisex at Pool | 1 | EA | 7 | \$0 | |
| | Lavatory | 121 Unisex at Pool | 1 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 121 Unisex at Pool | 2 | EA | 6 | \$238 | |
| | Showers | 121 Unisex at Pool | 1 | EA | 6 | \$311 | |
| | Student Lockers - One Tier | 121 Unisex at Pool | 6 | EA | 7 | \$0 | |
| | Walls - Tile Ceramic/ Porcelain | 121 Unisex at Pool | 326 | SF | 6 | \$737 | |
| | Water Closet | 121 Unisex at Pool | 1 | EA | 6 | \$336 | |
| | Accessories | 1st Floor East | 306 | SF | 6 | \$2,822 | |
| | Accessories | 1st Floor East | 290 | SF | 6 | \$2,675 | |
| | Ceiling - Plaster/Drywall | 1st Floor East | 290 | SF | 6 | \$1,004 | |
| | Ceiling - Plaster/Drywall | 1st Floor East | 306 | SF | 6 | \$1,059 | |
| | Doors - Side-lite | 1st Floor East | 36 | SF | 7 | \$0 | |
| | Doors - Side-lite | 1st Floor East | 36 | SF | 7 | \$0 | |
| | Floor Drain | 1st Floor East | 1 | EA | 7 | \$0 | |
| | Floor Drain | 1st Floor East | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor East | 280 | SF | 6 | \$593 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor East | 290 | SF | 6 | \$614 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor East | 10 | SF | 5 | \$209 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor East | 16 | SF | 5 | \$334 | |
| | Hand Dryer | 1st Floor East | 3 | EA | 5 | \$1,771 | Non-operational |
| | Hand Dryer | 1st Floor East | 3 | EA | 7 | \$0 | |
| | Lavatory | 1st Floor East | 3 | EA | 6 | \$959 | |
| | Lavatory | 1st Floor East | 5 | EA | 6 | \$1,598 | |
| | Lavatory | 1st Floor East | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor East | 4 | EA | 7 | \$0 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|------------------------|----------|------|------|---------|-----------------|
| Restro | ** | | • | | | | |
| | Lighting - Pendent/Surface | 1st Floor East | 5 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor East | 1 | EA | 6 | \$124 | |
| | Partitions | 1st Floor East | 4 | EA | 7 | \$0 | |
| | Partitions | 1st Floor East | 7 | EA | 6 | \$2,078 | |
| | Urinals | 1st Floor East | 3 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor East | 30 | SF | 5 | \$227 | |
| | Walls - Structural Glazed Tile | 1st Floor East | 580 | SF | 6 | \$1,825 | |
| | Walls - Structural Glazed Tile | 1st Floor East | 540 | SF | 6 | \$1,699 | |
| | Water Closet | 1st Floor East | 5 | EA | 7 | \$0 | |
| | Water Closet | 1st Floor East | 4 | EA | 7 | \$0 | |
| | Water Closet | 1st Floor East | 2 | EA | 5 | \$2,688 | |
| | Accessories | 1st Floor Men's West | 235 | SF | 6 | \$2,168 | |
| | Ceiling - Plaster/Drywall | 1st Floor Men's West | 235 | SF | 6 | \$813 | |
| | Doors - Side-lite | 1st Floor Men's West | 36 | SF | 7 | \$0 | |
| | Floor Drain | 1st Floor Men's West | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Men's West | 235 | SF | 6 | \$497 | |
| | Hand Dryer | 1st Floor Men's West | 2 | EA | 7 | \$0 | |
| | Lavatory | 1st Floor Men's West | 2 | EA | 6 | \$639 | |
| | Lavatory | 1st Floor Men's West | 1 | EA | 5 | \$1,590 | Non-operational |
| | Lighting - Pendent/Surface | 1st Floor Men's West | 4 | EA | 7 | \$0 | |
| | Partitions | 1st Floor Men's West | 1 | EA | 7 | \$0 | |
| | Urinals | 1st Floor Men's West | 2 | EA | 6 | \$672 | |
| | Walls - Structural Glazed Tile | 1st Floor Men's West | 626 | SF | 6 | \$1,969 | |
| | Water Closet | 1st Floor Men's West | 1 | EA | 7 | \$0 | |
| | Accessories | 1st Floor Women's West | 258 | SF | 6 | \$2,380 | |
| | Ceiling - Plaster/Drywall | 1st Floor Women's West | 258 | SF | 6 | \$893 | |
| | Doors - Side-lite | 1st Floor Women's West | 36 | SF | 7 | \$0 | |
| | Floor Drain | 1st Floor Women's West | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor Women's West | 258 | SF | 6 | \$546 | |
| | Hand Dryer | 1st Floor Women's West | 1 | EA | 7 | \$0 | |
| | Hand Dryer | 1st Floor Women's West | 1 | EA | 5 | \$590 | |
| | Lavatory | 1st Floor Women's West | 2 | EA | 6 | \$639 | |
| | Lavatory | 1st Floor Women's West | 1 | EA | 5 | \$1,590 | |
| | Lighting - Pendent/Surface | 1st Floor Women's West | 4 | EA | 7 | \$0 | |
| | Partitions | 1st Floor Women's West | 3 | EA | 6 | \$891 | |
| | Walls - Structural Glazed Tile | 1st Floor Women's West | 655 | SF | 7 | \$0 | |
| | Water Closet | 1st Floor Women's West | 3 | EA | 7 | \$0 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|--|----------|------|------|---------|-----------------------|
| Restro | • | | • | | | | |
| | Accessories | 1st Flr - Cafeteria Staff Locker/ Rest Room in North Corridor | 88 | SF | 6 | \$812 | |
| | Ceiling - Plaster/Drywall | 1st Flr - Cafeteria Staff Locker/ Rest Room in North Corridor | 88 | SF | 5 | \$807 | |
| | Doors - Wood Doors inclu hw | 1st Flr - Cafeteria Staff Locker/ Rest Room in North Corridor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Flr - Cafeteria Staff Locker/ Rest Room in North Corridor | 88 | SF | 5 | \$395 | |
| | Lavatory | 1st Flr - Cafeteria Staff Locker/ Rest Room in North Corridor | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 1st Flr - Cafeteria Staff Locker/ Rest Room in North Corridor | 2 | EA | 5 | \$365 | |
| | Lighting - Wall Mounted | 1st Flr - Cafeteria Staff Locker/ Rest Room in North Corridor | 1 | EA | 6 | \$124 | |
| | Partitions | 1st Flr - Cafeteria Staff Locker/ Rest Room in North Corridor | 2 | EA | 5 | \$1,502 | |
| | Walls - Structural Glazed Tile | 1st Flr - Cafeteria Staff Locker/ Rest Room in North Corridor | 251 | SF | 7 | \$0 | |
| | Water Closet | 1st Flr - Cafeteria Staff Locker/ Rest Room in North Corridor | 2 | EA | 5 | \$2,688 | |
| | Accessories | 1st Flr - Men in Main Office | 27 | SF | 6 | \$249 | |
| | Ceiling - Plaster/Drywall | 1st Flr - Men in Main Office | 27 | SF | 7 | \$0 | |
| | Doors - Transom Window | 1st Flr - Men in Main Office | 1 | SF | 6 | \$17 | |
| | Floor - Tile | 1st Flr - Men in Main Office | 27 | SF | 6 | \$59 | |
| | Lavatory | 1st Flr - Men in Main Office | 1 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 1st Flr - Men in Main Office | 1 | EA | 5 | \$162 | not functioning |
| | Lighting - Wall Mounted | 1st Flr - Men in Main Office | 4 | EA | 6 | \$496 | |
| | Walls - Structural Glazed Tile | 1st Flr - Men in Main Office | 187 | SF | 7 | \$0 | |
| | Water Closet | 1st Flr - Men in Main Office | 1 | EA | 6 | \$336 | |
| | Accessories | 1st Flr - Mens Staff Resource Rm - North Corridor | 77 | SF | 7 | \$0 | |
| | Ceiling - Splined | 1st Flr - Mens Staff Resource Rm - North Corridor | 77 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Flr - Mens Staff Resource Rm - North Corridor | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Flr - Mens Staff Resource Rm - North Corridor | 77 | SF | 6 | \$163 | |
| | Lavatory | 1st Flr - Mens Staff Resource Rm - North Corridor | 2 | EA | 6 | \$639 | |
| | Lighting - Lay-in | 1st Flr - Mens Staff Resource Rm - North Corridor | 1 | EA | 6 | \$119 | Recessed Incandescent |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|--|----------|------|------|-------|--|
| Restroc | om | | | | | | |
| | Partitions | 1st Flr - Mens Staff Resource Rm - North Corridor | 1 | EA | 7 | \$0 | |
| | Urinals | 1st Flr - Mens Staff Resource Rm - North Corridor | 1 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 1st Flr - Mens Staff Resource Rm - North Corridor | 283 | SF | 7 | \$0 | |
| | Water Closet | 1st Flr - Mens Staff Resource Rm - North Corridor | 1 | EA | 7 | \$0 | |
| | Accessories | 1st Flr - Unisex in Registration Office (in Admissions Office) | 28 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Flr - Unisex in Registration Office (in Admissions Office) | 28 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Flr - Unisex in Registration Office (in Admissions Office) | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Flr - Unisex in Registration Office (in Admissions Office) | 28 | SF | 7 | \$0 | |
| | Lavatory | 1st Flr - Unisex in Registration Office (in Admissions Office) | 1 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 1st Flr - Unisex in Registration Office (in Admissions Office) | 1 | EA | 7 | \$0 | Incandescent |
| | Walls - Concrete Block | 1st Flr - Unisex in Registration Office (in Admissions Office) | 170 | SF | 7 | \$0 | |
| | Water Closet | 1st Flr - Unisex in Registration Office (in Admissions Office) | 1 | EA | 7 | \$0 | |
| | Accessories | 1st Flr - Unisex in Scheduling Office (in Admissions Office) | 28 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Flr - Unisex in Scheduling Office (in Admissions Office) | 28 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Flr - Unisex in Scheduling Office (in Admissions Office) | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Flr - Unisex in Scheduling Office (in Admissions Office) | 28 | SF | 7 | \$0 | |
| | Lavatory | 1st Flr - Unisex in Scheduling Office (in Admissions Office) | 1 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 1st Flr - Unisex in Scheduling Office (in Admissions Office) | 1 | EA | 7 | \$0 | Incandescent |
| | Lighting - Wall Mounted | 1st FIr - Unisex in Scheduling Office (in Admissions Office) | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st FIr - Unisex in Scheduling Office (in Admissions Office) | 170 | SF | 7 | \$0 | |
| | Water Closet | 1st Flr - Unisex in Scheduling Office (in Admissions Office) | 1 | EA | 7 | \$0 | |
| | Accessories | 1st Flr - Women in Main Office | 30 | SF | 6 | \$277 | toilet paper holder, mirror, paper towel dispenser |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| roup It | tem - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|--|----------|------|------|---------|-----------------------|
| estroom | 1 | | | | | | |
| (| Ceiling - Plaster/Drywall | 1st Flr - Women in Main Office | 30 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Flr - Women in Main Office | 1 | EA | 6 | \$301 | |
| F | Floor - Tile | 1st Flr - Women in Main Office | 30 | SF | 5 | \$135 | |
| L | Lavatory | 1st Flr - Women in Main Office | 1 | EA | 5 | \$1,590 | |
| L | Lighting - Pendent/Surface | 1st Flr - Women in Main Office | 1 | EA | 5 | \$183 | |
| L | Lighting - Wall Mounted | 1st Flr - Women in Main Office | 1 | EA | 5 | \$169 | |
| V | Walls - Structural Glazed Tile | 1st Flr - Women in Main Office | 177 | SF | 7 | \$0 | |
| V | Water Closet | 1st Flr - Women in Main Office | 1 | EA | 6 | \$336 | |
| A | Accessories | 1st Flr - Womens Staff Resource Rm - North Corridor | 77 | SF | 7 | \$0 | |
| (| Ceiling - Splined | 1st Flr - Womens Staff Resource Rm - North Corridor | 77 | SF | 6 | \$63 | |
| [| Doors - Wood Doors inclu hw | 1st Flr - Womens Staff Resource Rm - North Corridor | 1 | EA | 7 | \$0 | |
| F | Floor - Tile/Sheet | 1st FIr - Womens Staff Resource Rm - North Corridor | 77 | SF | 7 | \$0 | |
| L | Lavatory | 1st FIr - Womens Staff Resource Rm - North Corridor | 1 | EA | 7 | \$0 | |
| L | Lighting - Lay-in | 1st FIr - Womens Staff Resource Rm - North Corridor | 1 | EA | 6 | \$119 | Recessed Incandescent |
| F | Partitions | 1st FIr - Womens Staff Resource Rm - North Corridor | 2 | EA | 7 | \$0 | |
| V | Walls - Structural Glazed Tile | 1st FIr - Womens Staff Resource Rm - North Corridor | 283 | SF | 7 | \$0 | |
| V | Water Closet | 1st FIr - Womens Staff Resource Rm - North Corridor | 2 | EA | 7 | \$0 | |
| P | Accessories | 1st Flr Mens in Auditorium Lobby | 124 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Flr Mens in Auditorium Lobby | 124 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Flr Mens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| F | Floor Drain | 1st Flr Mens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| F | Floor - Tile Ceramic/ Porcelain | 1st Flr Mens in Auditorium Lobby | 124 | SF | 7 | \$0 | |
| H | Hand Dryer | 1st Flr Mens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| L | Lavatory | 1st Flr Mens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| L | Lighting - Pendent/Surface | 1st Flr Mens in Auditorium Lobby | 2 | EA | 7 | \$0 | |
| F | Partitions | 1st Flr Mens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| ι | Urinals | 1st Flr Mens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| V | Walls - Structural Glazed Tile | 1st FIr Mens in Auditorium Lobby | 390 | SF | 6 | \$1,227 | |
| V | Water Closet | 1st FIr Mens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| P | Accessories | 1st Flr Womens in Auditorium Lobby | 164 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st FIr Womens in Auditorium Lobby | 164 | SF | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Decar - Wood Doors inclu hw | | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|---|---------------------------------|------------------------------------|----------|------|------|---------|--------------------|
| Doors - Wood Doors inclut hw Ist Fir Womens in Auditorium Lobby 1 EA 7 \$0 Filor - Tile Ceramic Porcelain 1st Fir Womens in Auditorium Lobby 1 EA 7 \$0 Filor - Tile Ceramic Porcelain 1st Fir Womens in Auditorium Lobby 1 EA 7 \$0 Filor - Tile Ceramic Porcelain 1st Fir Womens in Auditorium Lobby 1 EA 7 \$0 Lawstory 1st Fir Womens in Auditorium Lobby 1 EA 7 \$0 Lawstory 1st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Lighting - Pendent/Surface 1st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Lighting - Pendent/Surface 1st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Walls - Structural Glazed Tile 1st Fir Womens in Auditorium Lobby 430 \$F 7 \$0 Walls - Structural Clazed Tile 1st Fir Womens in Auditorium Lobby 430 \$F 7 \$0 Walls - Structural Clazed Tile 1st Fir Womens in Auditorium Lobby 430 \$F 7 \$0 Walls - Structural Clazed Tile 1st Fir Womens in Auditorium Lobby 430 \$F 7 \$0 Walls - Structural Clazed Tile 1st Fir Womens in Auditorium Lobby 430 \$F 7 \$0 Walls - Structural Clazed Tile 1st Fir Womens in Auditorium Lobby 430 \$F 7 \$0 Walls - Structural Clazed Tile 1st Fir Womens in Auditorium Lobby 430 \$F 7 \$0 Walls - Structural Clazed Tile 1st Fir Womens in Auditorium Lobby 430 \$F 6 \$5 \$6 \$5 \$6 Walls - Structural Clazed Tile 2nd Floor East 36 \$F 6 \$5 \$6 \$5 \$6 Accessories 2nd Floor East 36 \$F 6 \$5 \$6 \$5 \$6 Ploor Tile Clared Tile 2nd Floor East 36 \$F 6 \$5 \$6 \$6 \$6 Ploor Tile Clared Tile 2nd Floor East 36 \$F 6 \$6 \$6 \$6 Ploor Tile Clared Tile 2nd Floor East 36 \$F 6 \$6 \$6 \$6 Ploor Tile Clared Tile 2nd Floor East 4 EA 6 \$1 \$2 \$6 Ploor Tile Clared Tile 2nd Floor East 5 EA 7 \$0 Ploor Tile Clared Tile 2nd Floor East 5 EA 7 \$0 Ploor East 5 EA 7 | • | • | | | | | | |
| Floor - Tile Ceramic/ Porcelain | | | 1st Flr Womens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| Hand Dryee | | Floor Drain | 1st Flr Womens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| Lizartory | | Floor - Tile Ceramic/ Porcelain | 1st Flr Womens in Auditorium Lobby | 164 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface 1st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Partitions 1st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Waller - Structural Glazed Tile 1st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 1st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 1st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Water Closet 2st Fir Womens in Auditorium Lobby 2 | | Hand Dryer | 1st Flr Womens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| Partitions | | Lavatory | 1st Flr Womens in Auditorium Lobby | 1 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tile 1st Fir Womens in Auditorium Lobby 430 SF 7 \$0 Water Closet 1st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Accessories 2nd Floor East 290 SF 6 \$2,675 Accessories 2nd Floor East 306 SF 6 \$2,822 Celling - Plaster/Drywall 2nd Floor East 306 SF 6 \$1,049 Celling - Plaster/Drywall 2nd Floor East 30 SF 6 \$1,059 Doors - Side-lite 2nd Floor East 36 SF 6 \$602 Floor Drain 2nd Floor East 36 SF 6 \$602 Floor Trian Ceramic/ Porcelain 2nd Floor East 1 EA 7 \$0 Floor - Tilia Ceramic/ Porcelain 2nd Floor East 29 SF 6 \$648 Hand Dryer 2nd Floor East 10 EA 7 \$0 Hand Dryer 2nd Floor East 1 EA 6 <td< td=""><td></td><td>Lighting - Pendent/Surface</td><td>1st Flr Womens in Auditorium Lobby</td><td>2</td><td>EA</td><td>7</td><td>\$0</td><td></td></td<> | | Lighting - Pendent/Surface | 1st Flr Womens in Auditorium Lobby | 2 | EA | 7 | \$0 | |
| Water Closet 1st Fir Womens in Auditorium Lobby 2 EA 7 \$0 Accessories 2nd Floor East 290 SF 6 \$2,675 Accessories 2nd Floor East 306 SF 6 \$1,059 Ceiling - Plaster/Drywall 2nd Floor East 30 SF 6 \$1,059 Doors - Side-lite 2nd Floor East 36 SF 6 \$602 Ploor Drain 2nd Floor East 1 EA 7 \$0 Floor Drain 2nd Floor East 20 SF 6 \$602 Floor Trilie Ceramic/ Porcelain 2nd Floor East 1 EA 7 \$0 Floor Tille Ceramic/ Porcelain 2nd Floor East 20 SF 6 \$614 Floor Tille Ceramic/ Porcelain 2nd Floor East 20 SF 6 \$614 Floor Tille Ceramic/ Porcelain 2nd Floor East 2 EA 7 \$0 Hand Dryer 2nd Floor East 1 EA 5 \$131 | | Partitions | 1st Flr Womens in Auditorium Lobby | 2 | EA | 7 | \$0 | |
| Accessories 2nd Floor East 290 SF 6 \$2,675 Accessories 2nd Floor East 306 SF 6 \$2,6825 Ceiling - Plaster/Drywall 2nd Floor East 290 SF 6 \$1,004 some peeling paint Ceiling - Plaster/Drywall 2nd Floor East 306 SF 6 \$1,005 Doors - Stide-lite 2nd Floor East 306 SF 6 \$602 Doors - Stide-lite 2nd Floor East 36 SF 6 \$602 Doors - Stide-lite 2nd Floor East 36 SF 6 \$602 Floor Drain 2nd Floor East 36 SF 6 \$602 Floor Drain 2nd Floor East 1 EA 7 \$0 Floor Drain 2nd Floor East 1 EA 7 \$0 Floor Drain 2nd Floor East 1 EA 6 \$1,059 Floor - Tille Ceramic/ Porcelain 2nd Floor East 20 SF 6 \$614 Floor - Tille Ceramic/ Porcelain 2nd Floor East 306 SF 6 \$644 Floor - Tille Ceramic/ Porcelain 2nd Floor East 306 SF 6 \$644 Floor - Tille Ceramic/ Porcelain 2nd Floor East 306 SF 6 \$644 Floor - Tille Ceramic/ Porcelain 2nd Floor East 306 SF 6 \$648 Hand Dryer 2nd Floor East 1 EA 6 \$230 Hand Dryer 2nd Floor East 1 EA 6 \$230 Hand Dryer 2nd Floor East 1 EA 6 \$230 Hand Dryer 2nd Floor East 1 EA 6 \$1,181 Non-operational Lavatory 2nd Floor East 4 EA 6 \$1,181 Non-operational Lavatory 2nd Floor East 5 EA 7 \$0 Lavatory 2nd Floor East 5 EA 7 \$0 Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Lighting - Pendent/Surface 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 4 EA 6 \$1,188 Urinals Plaster/Drywall 2nd Floor East 6 SF 7 \$0 Walls - Plaster/Drywall 2nd Floor East 6 SF 7 \$0 Walls - Plaster/Drywall 2nd Floor East 60 SF 5 \$455 Walls - Plaster/Drywall 2nd Floor East 60 SF 5 \$455 Walls - Structural Glazed Tile 2nd Floor East 60 SF 5 \$455 Walls - Structural Glazed Tile 2nd Floor East 64 EA 6 \$2,078 Walls - Structural Glazed Tile 2nd Floor East 64 EA 6 \$2,073 | | Walls - Structural Glazed Tile | 1st Flr Womens in Auditorium Lobby | 430 | SF | 7 | \$0 | |
| Accessories 2nd Floor East 306 SF 6 \$2,822 Ceiling - Plaster/Drywall 2nd Floor East 306 SF 6 \$1,004 Ceiling - Plaster/Drywall 2nd Floor East 306 SF 6 \$1,004 Ceiling - Plaster/Drywall 2nd Floor East 306 SF 6 \$1,005 Doors - Side-lite 2nd Floor East 36 SF 6 \$6,002 Doors - Side-lite 2nd Floor East 36 SF 6 \$6,002 Floor Drain 2nd Floor East 1 EA 7 \$00 Floor Drain 2nd Floor East 1 EA 6 \$1,059 Floor Trile Ceramic/ Porcelain 2nd Floor East 200 SF 6 \$614 Floor - Tile Ceramic/ Porcelain 2nd Floor East 306 SF 6 \$644 Floor - Tile Ceramic/ Porcelain 2nd Floor East 306 SF 6 \$648 Hand Dryer 2nd Floor East 306 SF 6 \$648 Hand Dryer 2nd Floor East 1 EA 5 \$300 Hand Dryer 2nd Floor East 1 EA 6 \$230 Hand Dryer 2nd Floor East 1 EA 5 \$300 Hand Dryer 2nd Floor East 1 EA 5 \$300 Hand Dryer 2nd Floor East 1 EA 5 \$300 Hand Dryer 2nd Floor East 1 EA 5 \$300 Hand Dryer 2nd Floor East 1 EA 5 \$300 Hand Dryer 2nd Floor East 1 EA 5 \$300 Hand Dryer 2nd Floor East 1 EA 5 \$1,181 Lavatory 2nd Floor East 5 EA 6 \$1,598 Lavatory 2nd Floor East 5 EA 7 \$00 Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$00 Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$00 Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$00 Partitions 2nd Floor East 5 EA 7 \$00 Partitions 2nd Floor East 5 EA 7 \$00 Valls - Plaster/Drywall 2nd Floor East 6 S EA 7 \$00 Walls - Plaster/Drywall 2nd Floor East 6 S EA 7 \$00 Walls - Plaster/Drywall 2nd Floor East 6 S EA 7 \$00 Walls - Plaster/Drywall 2nd Floor East 6 S EA 7 \$00 Walls - Plaster/Drywall 2nd Floor East 6 S EA 7 \$00 Walls - Structural Glazed Tile 2nd Floor East 6 S EA 7 \$00 Walls - Structural Glazed Tile 2nd Floor East 6 S EA 7 \$00 Walls - Structural Glazed Tile 2nd Floor East 6 S EA 7 \$00 Walls - Plaster/Drywall 2nd Floor East 6 S EA 7 \$00 Walls - Plaster/Drywall 2nd Floor East 6 S EA 7 \$00 Walls - Walls - Structural Glazed Tile 2nd Floor East 6 S EA 7 \$00 | | Water Closet | 1st Flr Womens in Auditorium Lobby | 2 | EA | 7 | \$0 | |
| Ceiling - Plaster/Drywall 2nd Floor East 290 SF 6 \$1,004 some peeling paint Ceiling - Plaster/Drywall 2nd Floor East 306 SF 6 \$1,059 Doors - Side-lite 2nd Floor East 36 SF 6 \$602 Floor Drain 2nd Floor East 1 EA 7 \$0 Floor Train 2nd Floor East 1 EA 7 \$0 Floor Train Ceramic/ Porcelain 2nd Floor East 290 SF 6 \$614 Floor Tile Ceramic/ Porcelain 2nd Floor East 290 SF 6 \$614 Floor Tile Ceramic/ Porcelain 2nd Floor East 290 SF 6 \$648 Hand Dryer 2nd Floor East 2 EA 7 \$0 Hand Dryer 2nd Floor East 1 EA 6 \$230 Hand Dryer 2nd Floor East 2 EA 5 \$1,818 Non-operational Lavatory 2nd Floor East 5 EA | | Accessories | 2nd Floor East | 290 | SF | 6 | \$2,675 | |
| Ceiling - Plaster/Drywall 2nd Floor East 306 SF 6 \$10,59 Doors - Side-lite 2nd Floor East 36 SF 6 \$602 Ploor Drain 2nd Floor East 1 EA 7 \$0 Floor Drain 2nd Floor East 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 2nd Floor East 29 SF 6 \$614 Floor - Tile Ceramic/ Porcelain 2nd Floor East 306 SF 6 \$644 Floor - Tile Ceramic/ Porcelain 2nd Floor East 306 SF 6 \$644 Hand Dryer 2nd Floor East 1 EA 7 \$0 Hand Dryer 2nd Floor East 1 EA 5 \$590 Hand Dryer 2nd Floor East 4 EA 5 \$590 Hand Dryer 2nd Floor East 4 EA 5 \$1,181 Non-operational Lavatory 2nd Floor East 5 EA 6 \$1,598 Non- | | Accessories | 2nd Floor East | 306 | SF | 6 | \$2,822 | |
| Doors - Side-lite 2nd Floor East 36 SF 6 \$602 Doors - Side-lite 2nd Floor East 16 \$602 \$600 Floor Drain 2nd Floor East 1 EA 7 \$0 Floor Drain 2nd Floor East 290 SF 6 \$614 Floor - Tile Ceramic/ Porcelain 2nd Floor East 290 SF 6 \$648 Hand Dryer 2nd Floor East 2 EA 7 \$0 Hand Dryer 2nd Floor East 1 EA 6 \$230 Hand Dryer 2nd Floor East 1 EA 6 \$230 Hand Dryer 2nd Floor East 1 EA 5 \$500 Lavatory 2nd Floor East 4 EA 6 \$1,278 Lavatory 2nd Floor East 5 EA 6 \$1,590 Lavatory 2nd Floor East 5 EA 7 \$0 Lighting - Pendent/Surface 2nd Floor East 5 EA | | Ceiling - Plaster/Drywall | 2nd Floor East | 290 | SF | 6 | \$1,004 | some peeling paint |
| Doors - Side-lite | | | 2nd Floor East | 306 | SF | 6 | \$1,059 | |
| Floor Drain 2nd Floor East 1 | | | 2nd Floor East | 36 | SF | 6 | \$602 | |
| Floor Drain 2nd Floor East 1 | | Doors - Side-lite | 2nd Floor East | 36 | SF | 6 | \$602 | |
| Floor - Tile Ceramic/ Porcelain 2nd Floor East 290 | | Floor Drain | 2nd Floor East | 1 | EA | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain 2nd Floor East 306 SF 6 \$648 | | Floor Drain | 2nd Floor East | 1 | EA | 6 | \$1,059 | |
| Hand Dryer 2nd Floor East 2 EA 7 \$0 Hand Dryer 2nd Floor East 1 EA 6 \$230 Hand Dryer 2nd Floor East 1 EA 5 \$590 Hand Dryer 2nd Floor East 2 EA 5 \$1,181 Non-operational Lavatory 2nd Floor East 4 EA 6 \$1,278 Lavatory 2nd Floor East 5 EA 6 \$1,598 Lavatory 2nd Floor East 1 EA 5 \$1,599 Non-operational Lavatory 2nd Floor East 5 EA 7 \$0 Non-operational Lavatory 2nd Floor East 5 EA 7 \$0 Non-operational Lavatory 2nd Floor East 5 EA 7 \$0 Non-operational Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Partitions 2nd Floor East 4 EA 6 | | Floor - Tile Ceramic/ Porcelain | 2nd Floor East | 290 | SF | 6 | \$614 | |
| Hand Dryer 2nd Floor East 1 EA 6 \$230 Hand Dryer 2nd Floor East 1 EA 5 \$590 Hand Dryer 2nd Floor East 2 EA 5 \$1,181 Non-operational Lavatory 2nd Floor East 4 EA 6 \$1,278 Acceptable Lavatory 2nd Floor East 5 EA 6 \$1,598 Non-operational Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Partitions 2nd Floor East 7 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 60 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor East 640 SF 6 <th< td=""><td></td><td>Floor - Tile Ceramic/ Porcelain</td><td>2nd Floor East</td><td>306</td><td>SF</td><td>6</td><td>\$648</td><td></td></th<> | | Floor - Tile Ceramic/ Porcelain | 2nd Floor East | 306 | SF | 6 | \$648 | |
| Hand Dryer 2nd Floor East 1 EA 5 \$590 Hand Dryer 2nd Floor East 2 EA 5 \$1,181 Non-operational Lavatory 2nd Floor East 4 EA 6 \$1,278 Acceptable Lavatory 2nd Floor East 5 EA 6 \$1,598 Non-operational Lighting - Pendent/Surface 2nd Floor East 1 EA 5 \$1,590 Non-operational Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Partitions 2nd Floor East 7 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 60 SF 5 \$455 Walls - Structural Glazed Tile 2nd Floor East 60 SF 6 \$2,013 Walls - Structural Glazed Tile 2nd Floor East < | | Hand Dryer | 2nd Floor East | 2 | EA | 7 | \$0 | |
| Hand Dryer 2nd Floor East 2 EA 5 \$1,181 Non-operational Lavatory 2nd Floor East 4 EA 6 \$1,278 Lavatory 2nd Floor East 5 EA 6 \$1,598 Lavatory 2nd Floor East 1 EA 5 \$1,590 Non-operational Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Partitions 2nd Floor East 7 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 60 SF 5 \$455 Walls - Structural Glazed Tile 2nd Floor East 676 SF 7 \$0 | | Hand Dryer | 2nd Floor East | 1 | EA | 6 | \$230 | |
| Lavatory 2nd Floor East 4 EA 6 \$1,278 Lavatory 2nd Floor East 5 EA 6 \$1,598 Lavatory 2nd Floor East 1 EA 5 \$1,590 Non-operational Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Partitions 2nd Floor East 7 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 60 SF 5 \$455 Walls - Structural Glazed Tile 2nd Floor East 676 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor East 640 SF 6 \$2,013 | | Hand Dryer | 2nd Floor East | 1 | EA | 5 | \$590 | |
| Lavatory 2nd Floor East 5 EA 6 \$1,598 Lavatory 2nd Floor East 1 EA 5 \$1,590 Non-operational Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Partitions 2nd Floor East 7 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 24 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor East 60 SF 5 \$455 Walls - Structural Glazed Tile 2nd Floor East 640 SF 6 \$2,013 Water Closet 2nd Floor East 4 EA 7 \$0 | | Hand Dryer | 2nd Floor East | 2 | EA | 5 | \$1,181 | Non-operational |
| Lavatory 2nd Floor East 1 EA 5 \$1,590 Non-operational Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Partitions 2nd Floor East 7 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 24 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor East 676 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor East 640 SF 6 \$2,013 Water Closet 2nd Floor East 4 EA 7 \$0 | | Lavatory | 2nd Floor East | 4 | EA | 6 | \$1,278 | |
| Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Partitions 2nd Floor East 7 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 24 SF 7 \$0 Walls - Plaster/Drywall 2nd Floor East 60 SF 5 \$455 Walls - Structural Glazed Tile 2nd Floor East 676 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor East 640 SF 6 \$2,013 Water Closet 2nd Floor East 4 EA 7 \$0 | | Lavatory | 2nd Floor East | 5 | EA | 6 | \$1,598 | |
| Lighting - Pendent/Surface 2nd Floor East 5 EA 7 \$0 Partitions 2nd Floor East 7 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 24 SF 7 \$0 Walls - Plaster/Drywall 2nd Floor East 60 SF 5 \$455 Walls - Structural Glazed Tile 2nd Floor East 676 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor East 640 SF 6 \$2,013 Water Closet 2nd Floor East 4 EA 7 \$0 | | Lavatory | 2nd Floor East | 1 | EA | 5 | \$1,590 | Non-operational |
| Partitions 2nd Floor East 7 EA 6 \$2,078 Partitions 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 24 SF 7 \$0 Walls - Plaster/Drywall 2nd Floor East 60 SF 5 \$455 Walls - Structural Glazed Tile 2nd Floor East 676 SF 7 \$0 Water Closet 2nd Floor East 4 EA 7 \$0 | | Lighting - Pendent/Surface | 2nd Floor East | 5 | EA | 7 | \$0 | |
| Partitions 2nd Floor East 4 EA 6 \$1,188 Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 60 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor East 676 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor East 640 SF 6 \$2,013 Water Closet 2nd Floor East 4 EA 7 \$0 | | Lighting - Pendent/Surface | 2nd Floor East | 5 | EA | 7 | \$0 | |
| Urinals 2nd Floor East 3 EA 7 \$0 Walls - Plaster/Drywall 2nd Floor East 24 SF 7 \$0 Walls - Plaster/Drywall 2nd Floor East 60 SF 5 \$455 Walls - Structural Glazed Tile 2nd Floor East 676 SF 7 \$0 Walls - Structural Glazed Tile 2nd Floor East 640 SF 6 \$2,013 Water Closet 2nd Floor East 4 EA 7 \$0 | | Partitions | 2nd Floor East | 7 | EA | 6 | \$2,078 | |
| Walls - Plaster/Drywall2nd Floor East24SF7\$0Walls - Plaster/Drywall2nd Floor East60SF5\$455Walls - Structural Glazed Tile2nd Floor East676SF7\$0Walls - Structural Glazed Tile2nd Floor East640SF6\$2,013Water Closet2nd Floor East4EA7\$0 | | Partitions | 2nd Floor East | 4 | EA | 6 | \$1,188 | |
| Walls - Plaster/Drywall2nd Floor East60SF5\$455Walls - Structural Glazed Tile2nd Floor East676SF7\$0Walls - Structural Glazed Tile2nd Floor East640SF6\$2,013Water Closet2nd Floor East4EA7\$0 | | Urinals | 2nd Floor East | 3 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tile2nd Floor East676SF7\$0Walls - Structural Glazed Tile2nd Floor East640SF6\$2,013Water Closet2nd Floor East4EA7\$0 | | Walls - Plaster/Drywall | 2nd Floor East | 24 | SF | 7 | \$0 | |
| Walls - Structural Glazed Tile 2nd Floor East 640 SF 6 \$2,013 Water Closet 2nd Floor East 4 EA 7 \$0 | | Walls - Plaster/Drywall | 2nd Floor East | 60 | SF | 5 | \$455 | |
| Water Closet 2nd Floor East 4 EA 7 \$0 | | Walls - Structural Glazed Tile | 2nd Floor East | 676 | SF | 7 | \$0 | |
| | | Walls - Structural Glazed Tile | 2nd Floor East | 640 | SF | 6 | \$2,013 | |
| Water Closet 2nd Floor East 7 EA 6 \$2,352 | | Water Closet | 2nd Floor East | 4 | EA | 7 | \$0 | |
| | | Water Closet | 2nd Floor East | 7 | EA | 6 | \$2,352 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|-----------------------------------|----------|------|------|---------|---------------------------|
| Restro | om | | | | | | |
| | Accessories | 2nd Floor Girls Gym Office Toilet | 37 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor Girls Gym Office Toilet | 10 | SF | 5 | \$108 | |
| | Ceiling - Plaster/Drywall | 2nd Floor Girls Gym Office Toilet | 27 | SF | 6 | \$93 | |
| | Doors - Wood Doors inclu hw | 2nd Floor Girls Gym Office Toilet | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor Girls Gym Office Toilet | 4 | SF | 5 | \$20 | |
| | Floor - Tile/Sheet | 2nd Floor Girls Gym Office Toilet | 20 | SF | 7 | \$0 | |
| | Lavatory | 2nd Floor Girls Gym Office Toilet | 1 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor Girls Gym Office Toilet | 1 | EA | 5 | \$162 | |
| | Showers | 2nd Floor Girls Gym Office Toilet | 1 | EA | 5 | \$1,172 | |
| | Walls - Structural Glazed Tile | 2nd Floor Girls Gym Office Toilet | 200 | SF | 7 | \$0 | |
| | Water Closet | 2nd Floor Girls Gym Office Toilet | 1 | EA | 7 | \$0 | |
| | Accessories | 2nd Floor- Main Gym Office Toilet | 58 | SF | 6 | \$535 | |
| | Ceiling - Plaster/Drywall | 2nd Floor- Main Gym Office Toilet | 58 | SF | 5 | \$532 | Water damage |
| | Doors - Wood Doors inclu hw | 2nd Floor- Main Gym Office Toilet | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile/Sheet | 2nd Floor- Main Gym Office Toilet | 46 | SF | 5 | \$207 | |
| | Lavatory | 2nd Floor- Main Gym Office Toilet | 1 | EA | 5 | \$1,590 | |
| | Lighting - Lay-in | 2nd Floor- Main Gym Office Toilet | 1 | EA | 4 | \$336 | water damage |
| | Lighting - Wall Mounted | 2nd Floor- Main Gym Office Toilet | 1 | EA | 4 | \$393 | broken - non operable |
| | Showers | 2nd Floor- Main Gym Office Toilet | 1 | EA | 4 | \$4,720 | Non-operational and leaks |
| | Walls - Structural Glazed Tile | 2nd Floor- Main Gym Office Toilet | 324 | SF | 6 | \$1,019 | |
| | Water Closet | 2nd Floor- Main Gym Office Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 2nd Floor West | 235 | SF | 6 | \$2,168 | |
| | Accessories | 2nd Floor West | 258 | SF | 6 | \$2,380 | |
| | Ceiling - Plaster/Drywall | 2nd Floor West | 44 | SF | 6 | \$180 | |
| | Ceiling - Plaster/Drywall | 2nd Floor West | 44 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor West | 191 | SF | 5 | \$1,751 | water damage |
| | Ceiling - Plaster/Drywall | 2nd Floor West | 214 | SF | 4 | \$3,222 | water damage |
| | Doors - Side-lite | 2nd Floor West | 36 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor West | 36 | SF | 6 | \$602 | |
| | Floor Drain | 2nd Floor West | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 2nd Floor West | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor West | 258 | SF | 6 | \$546 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor West | 235 | SF | 6 | \$497 | |
| | Hand Dryer | 2nd Floor West | 1 | EA | 6 | \$230 | |
| | Hand Dryer | 2nd Floor West | 2 | EA | 7 | \$0 | |
| | Hand Dryer | 2nd Floor West | 1 | EA | 5 | \$590 | |
| | Lavatory | 2nd Floor West | 2 | EΑ | 6 | \$639 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | |
|---------|--------------------------------|--|----------|------|------|---------|-------------------|--|--|
| Restroo | stroom | | | | | | | | |
| | Lavatory | 2nd Floor West | 1 | EA | 6 | \$320 | | | |
| | Lavatory | 2nd Floor West | 2 | EA | 5 | \$3,179 | 1 Non-operational | | |
| | Lavatory | 2nd Floor West | 1 | EA | 5 | \$1,590 | | | |
| | Lighting - Pendent/Surface | 2nd Floor West | 3 | EA | 6 | \$372 | | | |
| | Lighting - Pendent/Surface | 2nd Floor West | 1 | EA | 4 | \$541 | water damage | | |
| | Lighting - Pendent/Surface | 2nd Floor West | 4 | EA | 7 | \$0 | | | |
| | Partitions | 2nd Floor West | 3 | EA | 7 | \$0 | | | |
| | Partitions | 2nd Floor West | 1 | EA | 6 | \$297 | | | |
| | Urinals | 2nd Floor West | 2 | EA | 7 | \$0 | | | |
| | Walls - Structural Glazed Tile | 2nd Floor West | 655 | SF | 6 | \$2,061 | | | |
| | Walls - Structural Glazed Tile | 2nd Floor West | 626 | SF | 6 | \$1,969 | | | |
| | Water Closet | 2nd Floor West | 3 | EA | 7 | \$0 | | | |
| | Water Closet | 2nd Floor West | 1 | EA | 6 | \$336 | | | |
| | Accessories | 2nd Flr - 207B Womens in Case Manager Office - North Corridor | 77 | SF | 7 | \$0 | | | |
| | Ceiling - Plaster/Drywall | 2nd Flr - 207B Womens in Case Manager Office - North Corridor | 77 | SF | 7 | \$0 | | | |
| | Doors - Wood Doors inclu hw | 2nd Flr - 207B Womens in Case Manager Office - North Corridor | 1 | EA | 7 | \$0 | | | |
| | Floor - Tile/Sheet | 2nd Flr - 207B Womens in Case Manager Office - North Corridor | 77 | SF | 6 | \$77 | | | |
| | Lavatory | 2nd Flr - 207B Womens in Case Manager Office - North Corridor | 2 | EA | 7 | \$0 | | | |
| | Lighting - Lay-in | 2nd Flr - 207B Womens in Case Manager Office - North Corridor | 1 | EA | 6 | \$119 | Incandescent | | |
| | Lighting - Wall Mounted | 2nd Flr - 207B Womens in Case Manager Office - North Corridor | 2 | EA | 7 | \$0 | | | |
| | Partitions | 2nd Flr - 207B Womens in Case Manager Office - North Corridor | 2 | EA | 6 | \$594 | | | |
| | Walls - Structural Glazed Tile | 2nd Flr - 207B Womens in Case Manager Office - North Corridor | 283 | SF | 7 | \$0 | | | |
| | Water Closet | 2nd Flr - 207B Womens in Case Manager Office - North Corridor | 2 | EA | 7 | \$0 | | | |
| | Accessories | 2nd Flr - Mens Staff Resource Rm - North Corridor | 77 | SF | 7 | \$0 | | | |
| | Ceiling - Plaster/Drywall | 2nd Flr - Mens Staff Resource Rm - North Corridor | 77 | SF | 7 | \$0 | | | |
| | Doors - Wood Doors inclu hw | 2nd Flr - Mens Staff Resource Rm - North Corridor | 1 | EA | 7 | \$0 | | | |
| | Floor - Tile/Sheet | 2nd Flr - Mens Staff Resource Rm - North Corridor | 77 | SF | 6 | \$77 | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|--|----------|------|------|---------|-----------------|
| Restroo | m | | | | | | |
| | Lavatory | 2nd Flr - Mens Staff Resource Rm - North Corridor | 2 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Flr - Mens Staff Resource Rm - North Corridor | 1 | EA | 6 | \$119 | Incandescent |
| | Lighting - Wall Mounted | 2nd Flr - Mens Staff Resource Rm - North Corridor | 2 | EA | 7 | \$0 | |
| | Partitions | 2nd Flr - Mens Staff Resource Rm - North Corridor | 1 | EA | 7 | \$0 | |
| | Urinals | 2nd Flr - Mens Staff Resource Rm - North Corridor | 1 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Flr - Mens Staff Resource Rm - North Corridor | 283 | SF | 7 | \$0 | |
| | Water Closet | 2nd Flr - Mens Staff Resource Rm - North Corridor | 1 | EA | 7 | \$0 | |
| | Accessories | 3rd Floor East | 290 | SF | 6 | \$2,675 | |
| | Accessories | 3rd Floor East | 306 | SF | 6 | \$2,822 | |
| | Ceiling - Plaster/Drywall | 3rd Floor East | 306 | SF | 6 | \$1,059 | |
| | Ceiling - Plaster/Drywall | 3rd Floor East | 290 | SF | 6 | \$1,004 | |
| | Doors - Side-lite | 3rd Floor East | 36 | SF | 6 | \$602 | |
| | Doors - Side-lite | 3rd Floor East | 36 | SF | 7 | \$0 | |
| | Floor Drain | 3rd Floor East | 1 | EA | 7 | \$0 | |
| | Floor Drain | 3rd Floor East | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor East | 306 | SF | 6 | \$648 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor East | 290 | SF | 6 | \$614 | |
| | Hand Dryer | 3rd Floor East | 3 | EA | 6 | \$690 | |
| | Hand Dryer | 3rd Floor East | 3 | EA | 6 | \$690 | |
| | Lavatory | 3rd Floor East | 3 | EA | 6 | \$959 | |
| | Lavatory | 3rd Floor East | 4 | EA | 6 | \$1,278 | |
| | Lavatory | 3rd Floor East | 1 | EA | 5 | \$1,590 | Non-operational |
| | Lavatory | 3rd Floor East | 2 | EA | 5 | \$3,179 | |
| | Lighting - Pendent/Surface | 3rd Floor East | 3 | EA | 5 | \$548 | |
| | Lighting - Pendent/Surface | 3rd Floor East | 5 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 3rd Floor East | 2 | EA | 7 | \$0 | |
| | Partitions | 3rd Floor East | 4 | EA | 6 | \$1,188 | |
| | Partitions | 3rd Floor East | 7 | EA | 6 | \$2,078 | |
| | Urinals | 3rd Floor East | 3 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 3rd Floor East | 600 | SF | 6 | \$1,888 | |
| | Walls - Structural Glazed Tile | 3rd Floor East | 720 | SF | 6 | \$2,265 | |
| | Water Closet | 3rd Floor East | 7 | EA | 6 | \$2,352 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|---------------------|----------|------|------|---------|-----------------|
| Restro | om | | | | | | |
| | Water Closet | 3rd Floor East | 4 | EA | 6 | \$1,344 | |
| | Accessories | 3rd Floor West | 258 | SF | 6 | \$2,380 | |
| | Accessories | 3rd Floor West | 235 | SF | 6 | \$2,168 | |
| | Ceiling - Plaster/Drywall | 3rd Floor West | 200 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 3rd Floor West | 35 | SF | 5 | \$376 | Water damage |
| | Ceiling - Plaster/Drywall | 3rd Floor West | 258 | SF | 7 | \$0 | |
| | Doors - Side-lite | 3rd Floor West | 36 | SF | 6 | \$602 | |
| | Doors - Side-lite | 3rd Floor West | 36 | SF | 7 | \$0 | |
| | Floor Drain | 3rd Floor West | 1 | EA | 7 | \$0 | |
| | Floor Drain | 3rd Floor West | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor West | 235 | SF | 6 | \$497 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor West | 258 | SF | 7 | \$0 | |
| | Hand Dryer | 3rd Floor West | 1 | EA | 6 | \$230 | |
| | Hand Dryer | 3rd Floor West | 1 | EA | 5 | \$590 | Non-operational |
| | Hand Dryer | 3rd Floor West | 2 | EA | 7 | \$0 | |
| | Lavatory | 3rd Floor West | 1 | EA | 6 | \$320 | |
| | Lavatory | 3rd Floor West | 2 | EA | 5 | \$3,179 | |
| | Lavatory | 3rd Floor West | 3 | EA | 6 | \$959 | |
| | Lighting - Pendent/Surface | 3rd Floor West | 4 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 3rd Floor West | 4 | EA | 7 | \$0 | |
| | Partitions | 3rd Floor West | 1 | EA | 7 | \$0 | |
| | Partitions | 3rd Floor West | 3 | EA | 7 | \$0 | |
| | Urinals | 3rd Floor West | 2 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 3rd Floor West | 626 | SF | 6 | \$1,969 | |
| | Walls - Structural Glazed Tile | 3rd Floor West | 655 | SF | 6 | \$2,061 | |
| | Water Closet | 3rd Floor West | 1 | EA | 6 | \$336 | |
| | Water Closet | 3rd Floor West | 3 | EA | 7 | \$0 | |
| | Accessories | 3rd Flr East Unisex | 85 | SF | 6 | \$784 | |
| | Ceiling - Plaster/Drywall | 3rd Flr East Unisex | 85 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Flr East Unisex | 1 | EA | 7 | \$0 | |
| | Floor Drain | 3rd Flr East Unisex | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Flr East Unisex | 85 | SF | 7 | \$0 | |
| | Hand Dryer | 3rd Flr East Unisex | 1 | EA | 7 | \$0 | |
| | Lavatory | 3rd Flr East Unisex | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 3rd Flr East Unisex | 2 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 3rd Flr East Unisex | 300 | SF | 7 | \$0 | |
| | Water Closet | 3rd Flr East Unisex | 1 | EA | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|---------------------------|----------|------|------|---------|---|
| Restroc | m | | | | | | |
| | Accessories | 3rd FIr East Womens | 154 | SF | 6 | \$1,420 | |
| | Ceiling - Plaster/Drywall | 3rd Flr East Womens | 154 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 3rd Flr East Womens | 1 | EA | 7 | \$0 | |
| | Floor Drain | 3rd Flr East Womens | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Flr East Womens | 154 | SF | 7 | \$0 | |
| | Hand Dryer | 3rd Flr East Womens | 1 | EA | 7 | \$0 | |
| | Lavatory | 3rd Flr East Womens | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 3rd Flr East Womens | 2 | EA | 7 | \$0 | |
| | Partitions | 3rd Flr East Womens | 3 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 3rd Flr East Womens | 64 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 3rd Flr East Womens | 380 | SF | 7 | \$0 | |
| | Water Closet | 3rd FIr East Womens | 3 | EA | 7 | \$0 | |
| | Accessories | Basement Engineers Toilet | 60 | SF | 6 | \$553 | |
| | Ceiling - Plaster/Drywall | Basement Engineers Toilet | 178 | SF | 6 | \$616 | |
| | Doors - Steel Doors incl hw | Basement Engineers Toilet | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | Basement Engineers Toilet | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | Basement Engineers Toilet | 60 | SF | 6 | \$76 | |
| | Floor - Tile/Sheet | Basement Engineers Toilet | 118 | SF | 4 | \$1,141 | surface worn and in need of replacement |
| | Lavatory | Basement Engineers Toilet | 1 | EA | 5 | \$1,590 | |
| | Lighting - Pendent/Surface | Basement Engineers Toilet | 3 | EA | 7 | \$0 | |
| | Showers | Basement Engineers Toilet | 1 | EA | 6 | \$311 | |
| | Walls - Concrete Block | Basement Engineers Toilet | 630 | SF | 6 | \$1,847 | |

Rooms (Other Than Classrooms) Subtotal:

\$1,614,036

Building: Kennedy

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------|---|----------|------|------|---------|---------------|
| Corridor | | | | | | |
| Ceiling - Plaster/Drywall | 106 Counselor Offices Internal Corridor | 138 | SF | 7 | \$0 | |
| Floor - Tile/Sheet | 106 Counselor Offices Internal Corridor | 138 | SF | 6 | \$75 | cracks in VCT |
| Lighting - Lay-in | 106 Counselor Offices Internal Corridor | 4 | EA | 6 | \$476 | |
| Walls - Concrete Block | 106 Counselor Offices Internal Corridor | 40 | SF | 7 | \$0 | |
| Walls - Metal Panel | 106 Counselor Offices Internal Corridor | 512 | SF | 6 | \$3,822 | |
| Ceiling - Plaster/Drywall | 107 Admin. Internal Corridor | 90 | SF | 7 | \$0 | |
| Floor - Tile/Sheet | 107 Admin. Internal Corridor | 90 | SF | 6 | \$49 | cracks in VCT |
| Lighting - Lay-in | 107 Admin. Internal Corridor | 3 | EA | 6 | \$357 | |
| | To 7 tanimi internal contact | · · | _, . | | ψου. | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|------------------------------|----------|------|------|----------|----------|
| Corrido | r | | | | | | |
| | Walls - Concrete Block | 107 Admin. Internal Corridor | 304 | SF | 6 | \$891 | |
| | Walls - Metal Panel | 107 Admin. Internal Corridor | 42 | SF | 6 | \$314 | |
| | Ceiling - Plaster/Drywall | 1st Floor Auditorium - north | 210 | SF | 7 | \$0 | |
| | Doors - Wood Doors include hw | 1st Floor Auditorium - north | 2 | EA | 7 | \$0 | |
| | Floor - Carpet | 1st Floor Auditorium - north | 210 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st Floor Auditorium - north | 5 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor Auditorium - north | 60 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 1st Floor Auditorium - north | 550 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Floor Auditorium - south | 210 | SF | 7 | \$0 | |
| | Doors - Wood Doors include hw | 1st Floor Auditorium - south | 4 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Floor Auditorium - south | 210 | SF | 6 | \$114 | |
| | Lighting - Lay-in | 1st Floor Auditorium - south | 5 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor Auditorium - south | 60 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 1st Floor Auditorium - south | 550 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Flr. Link to Kinzie | 266 | SF | 6 | \$2,317 | |
| | Ceiling - Plaster/Drywall | 2nd Flr. Link to Kinzie | 2,477 | SF | 6 | \$15,337 | |
| | Ceiling - Splined | 2nd Flr. Link to Kinzie | 196 | SF | 6 | \$566 | |
| | Doors - Steel Doors incl hw | 2nd Flr. Link to Kinzie | 8 | EA | 7 | \$0 | |
| | Drinking Fountains - Single Water Cooler | 2nd Flr. Link to Kinzie | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Flr. Link to Kinzie | 2,939 | SF | 6 | \$1,597 | |
| | Lighting - Lay-in | 2nd Flr. Link to Kinzie | 33 | EA | 6 | \$3,926 | |
| | Lighting - Pendent/Surface | 2nd Flr. Link to Kinzie | 6 | EA | 5 | \$1,095 | |
| | Walls - Concrete Block | 2nd Flr. Link to Kinzie | 656 | SF | 6 | \$1,923 | |
| | Walls - Metal Panel | 2nd Flr. Link to Kinzie | 776 | SF | 6 | \$5,793 | |
| | Walls - Plaster/Drywall | 2nd Flr. Link to Kinzie | 632 | SF | 6 | \$2,802 | |
| | Walls - Structural Glazed Tile | 2nd Flr. Link to Kinzie | 1,785 | SF | 6 | \$5,616 | |
| | Ceiling - Plaster/Drywall | Auditorium Lobby | 460 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Auditorium Lobby | 120 | SF | 6 | \$884 | |
| | Doors - Wood Doors include hw | Auditorium Lobby | 8 | EA | 6 | \$2,408 | |
| | Drinking Fountains - Single Fountain | Auditorium Lobby | 1 | EA | 5 | \$1,180 | |
| | Floor - Terrazzo | Auditorium Lobby | 580 | SF | 6 | \$4,869 | |
| | Lighting - Lay-in | Auditorium Lobby | 4 | EA | 5 | \$649 | |
| | Lighting - Pendent/Surface | Auditorium Lobby | 5 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Auditorium Lobby | 590 | SF | 7 | \$0 | |
| | Ceiling - Exposed | Basement corridor @ Stair #7 | 350 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Basement corridor @ Stair #7 | 3 | EA | 7 | \$0 | |
| | Doors - Wood Doors include hw | Basement corridor @ Stair #7 | 1 | EΑ | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|--|------------------------------------|----------|------|------|---------|----------|
| rrido | r | | | | | | |
| | Floor - Concrete Epoxy/ Painted | Basement corridor @ Stair #7 | 350 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Basement corridor @ Stair #7 | 3 | EA | 6 | \$372 | |
| | Lighting - Pendent/Surface | Basement corridor @ Stair #7 | 1 | EA | 5 | \$183 | |
| | Stairs - Concrete Stairs | Basement corridor @ Stair #7 | 86 | LF | 5 | \$8,521 | |
| | Walls - Concrete Block | Basement corridor @ Stair #7 | 1,000 | SF | 7 | \$0 | |
| | Ceiling - Exposed | Basement Locker Room Corridor | 128 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Basement Locker Room Corridor | 142 | SF | 7 | \$0 | |
| | Doors - Wood Doors include hw | Basement Locker Room Corridor | 2 | EA | 7 | \$0 | |
| | Floor - Concrete | Basement Locker Room Corridor | 270 | SF | 6 | \$143 | |
| | Lighting - Lay-in | Basement Locker Room Corridor | 3 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Basement Locker Room Corridor | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Basement Locker Room Corridor | 840 | SF | 6 | \$2,462 | |
| | Ceiling - Lay-in | First Floor Corridor / 1st Floor | 8,817 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | First Floor Corridor / 1st Floor | 2 | EA | 7 | \$0 | |
| | Drinking Fountains - Single Water Cooler | First Floor Corridor / 1st Floor | 4 | EA | 7 | \$0 | |
| | Floor - Terrazzo | First Floor Corridor / 1st Floor | 479 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | First Floor Corridor / 1st Floor | 8,338 | SF | 7 | \$0 | |
| | Lighting - Lay-in | First Floor Corridor / 1st Floor | 128 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | First Floor Corridor / 1st Floor | 427 | EA | 7 | \$0 | |
| | Walls - Concrete Block | First Floor Corridor / 1st Floor | 2,628 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | First Floor Corridor / 1st Floor | 2,186 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | First Floor Corridor / 1st Floor | 4,307 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Second Floor Corridors / 2nd Floor | 8,921 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Second Floor Corridors / 2nd Floor | 2 | EΑ | 7 | \$0 | |
| | Drinking Fountains - Single Water Cooler | Second Floor Corridors / 2nd Floor | 6 | EA | 7 | \$0 | |
| | Floor - Terrazzo | Second Floor Corridors / 2nd Floor | 317 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | Second Floor Corridors / 2nd Floor | 8,694 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Second Floor Corridors / 2nd Floor | 113 | EΑ | 7 | \$0 | |
| | Student Lockers - One Tier | Second Floor Corridors / 2nd Floor | 541 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Second Floor Corridors / 2nd Floor | 2,288 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | Second Floor Corridors / 2nd Floor | 1,694 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Second Floor Corridors / 2nd Floor | 4,876 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Third Floor Corridor / 3rd Floor | 8,292 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Third Floor Corridor / 3rd Floor | 10 | SF | 5 | \$174 | |
| | Drinking Fountains - Single Water Cooler | Third Floor Corridor / 3rd Floor | 4 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | Third Floor Corridor / 3rd Floor | 8,308 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | Third Floor Corridor / 3rd Floor | 4 | SF | 5 | \$23 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-----------------------------------|----------|------|------|---------|----------------------|
| Corrido | r | | • | | | | |
| | Lighting - Lay-in | Third Floor Corridor / 3rd Floor | 119 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | Third Floor Corridor / 3rd Floor | 491 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | Third Floor Corridor / 3rd Floor | 2,174 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | Third Floor Corridor / 3rd Floor | 2,174 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Third Floor Corridor / 3rd Floor | 4,064 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Vestibule @ Stair #3 | 200 | SF | 7 | \$0 | |
| | Doors - Store Front | Vestibule @ Stair #3 | 4 | EΑ | 7 | \$0 | |
| | Doors - Wood Doors include hw | Vestibule @ Stair #3 | 1 | EΑ | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | Vestibule @ Stair #3 | 200 | SF | 6 | \$558 | |
| | Lighting - Pendent/Surface | Vestibule @ Stair #3 | 2 | EΑ | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Vestibule @ Stair #3 | 270 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Vestibule @ Stair #7 | 80 | SF | 7 | \$0 | |
| | Doors - Wood Doors include hw | Vestibule @ Stair #7 | 1 | EΑ | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | Vestibule @ Stair #7 | 8 | SF | 5 | \$167 | |
| | Floor - Tile Ceramic/ Porcelain | Vestibule @ Stair #7 | 72 | SF | 6 | \$201 | |
| | Lighting - Pendent/Surface | Vestibule @ Stair #7 | 1 | EΑ | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Vestibule @ Stair #7 | 200 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Vestibules @ Stairs #2, #4 and #8 | 336 | SF | 7 | \$0 | |
| | Doors - Wood Doors include hw | Vestibules @ Stairs #2, #4 and #8 | 3 | EΑ | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | Vestibules @ Stairs #2, #4 and #8 | 336 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Vestibules @ Stairs #2, #4 and #8 | 3 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Vestibules @ Stairs #2, #4 and #8 | 546 | SF | 7 | \$0 | |
| Safety | | | | | | | |
| | Security Cameras | Entire Building | 15 | EA | 7 | \$0 | Viewing on PC's only |
| | Security Cameras | Entire Building | 1 | EΑ | 4 | \$1,326 | Camera is broken |
| Stairs | | | | | | | |
| | Handrails | In Library and Writing Center | 188 | LF | 7 | \$0 | |
| | Stairs - Terrazzo | In Library and Writing Center | 144 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Stair #3 (north-central) | 1,650 | SF | 7 | \$0 | |
| | Floor - Terrazzo | Stair #3 (north-central) | 1,280 | SF | 7 | \$0 | |
| | Handrails | Stair #3 (north-central) | 4 | LF | 5 | \$46 | |
| | Handrails | Stair #3 (north-central) | 192 | LF | 7 | \$0 | |
| | Lighting - Lay-in | Stair #3 (north-central) | 12 | EΑ | 7 | \$0 | |
| | Lighting - Pendent/Surface | Stair #3 (north-central) | 4 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | Stair #3 (north-central) | 484 | LF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Stair #3 (north-central) | 50 | SF | 5 | \$3,191 | |
| | | , | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-------------------------------------|----------|------|------|-----------|---|
| Stairs | | | | | | |
| Walls - Structural Glazed Tile | Stair #3 (north-central) | 1,700 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | Stair #6 at Cafeteria | 330 | SF | 5 | \$4,851 | dirty and failing popcorn finish; peeling paint |
| Floor - Terrazzo | Stair #6 at Cafeteria | 42 | SF | 6 | \$353 | |
| Floor - Tile | Stair #6 at Cafeteria | 238 | SF | 5 | \$1,069 | |
| Handrails | Stair #6 at Cafeteria | 46 | LF | 6 | \$399 | |
| Lighting - Lay-in | Stair #6 at Cafeteria | 1 | EΑ | 5 | \$162 | |
| Lighting - Pendent/Surface | Stair #6 at Cafeteria | 5 | EΑ | 5 | \$913 | |
| Stairs - Terrazzo | Stair #6 at Cafeteria | 80 | LF | 6 | \$742 | |
| Walls - Structural Glazed Tile | Stair #6 at Cafeteria | 2,409 | SF | 5 | \$122,396 | |
| Ceiling - Plaster/Drywall | Stair #7 (south central) | 576 | SF | 7 | \$0 | |
| Floor - Terrazzo | Stair #7 (south central) | 323 | SF | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain | Stair #7 (south central) | 128 | SF | 6 | \$858 | |
| Handrails | Stair #7 (south central) | 142 | LF | 7 | \$0 | |
| Lighting - Lay-in | Stair #7 (south central) | 4 | EΑ | 7 | \$0 | |
| Lighting - Pendent/Surface | Stair #7 (south central) | 2 | EΑ | 7 | \$0 | |
| Stairs - Terrazzo | Stair #7 (south central) | 180 | LF | 7 | \$0 | |
| Walls - Structural Glazed Tile | Stair #7 (south central) | 1,420 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | Stair #9 (girls gym to locker room) | 150 | SF | 6 | \$1,098 | |
| Floor - Terrazzo | Stair #9 (girls gym to locker room) | 26 | SF | 7 | \$0 | |
| Floor - Tile | Stair #9 (girls gym to locker room) | 50 | SF | 6 | \$27 | |
| Handrails | Stair #9 (girls gym to locker room) | 40 | LF | 6 | \$347 | |
| Lighting - Lay-in | Stair #9 (girls gym to locker room) | 2 | EΑ | 6 | \$238 | |
| Stairs - Terrazzo | Stair #9 (girls gym to locker room) | 92 | LF | 7 | \$0 | |
| Walls - Structural Glazed Tile | Stair #9 (girls gym to locker room) | 800 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | Stairs #2, #4 and #8 | 2,688 | SF | 7 | \$0 | |
| Floor - Terrazzo | Stairs #2, #4 and #8 | 1,816 | SF | 7 | \$0 | |
| Floor - Terrazzo | Stairs #2, #4 and #8 | 200 | SF | 6 | \$2,328 | |
| Handrails | Stairs #2, #4 and #8 | 210 | LF | 7 | \$0 | |
| Lighting - Lay-in | Stairs #2, #4 and #8 | 18 | EA | 7 | \$0 | |
| Lighting - Pendent/Surface | Stairs #2, #4 and #8 | 6 | EΑ | 7 | \$0 | |
| Stairs - Terrazzo | Stairs #2, #4 and #8 | 125 | LF | 6 | \$1,160 | |
| Stairs - Terrazzo | Stairs #2, #4 and #8 | 715 | LF | 7 | \$0 | |
| Walls - Structural Glazed Tile | Stairs #2, #4 and #8 | 5,115 | SF | 7 | \$0 | |
| Vertical Conveyance | | | | | | |
| Elevator - Elevator- Roped Holeless Hydraulic | 1st Floor | 1 | EA | 7 | \$0 | |
| Elevator - Elevator- Roped Holeless Hydraulic | 1st Floor | 1 | EA | 7 | \$0 | |
| | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kennedy

Category: Building Interior

Group Item - Type Location Quantity Unit Rank Cost Comments

Building Interior Subtotal: \$211,366

Total Building Cost \$8,414,916

Building: Kinzie

| oup Item - Type | | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------------------------|----|-----------|----------|------|------|---------|----------|
| trance | | | | | | | |
| Entrance Control - Audio and Vid | eo | 15 - Main | 1 | EA | 7 | \$0 | |
| Exterior Doors - Exterior Steel Do | or | 18 | 1 | EA | 5 | \$1,341 | |
| Exterior Doors - Exterior Steel Do | or | 19 | 1 | EA | 5 | \$1,341 | |
| Exterior Doors - Exterior Steel Do | or | 20 | 1 | EA | 6 | \$481 | |
| Exterior Doors - Exterior Steel Do | or | 21 | 1 | EA | 6 | \$481 | |
| Exterior Doors - Exterior Steel Do | or | 22 | 1 | EA | 6 | \$481 | |
| Exterior Doors - Exterior Steel Do | or | 23 | 1 | EA | 5 | \$1,341 | |
| Exterior Doors - Exterior Steel Do | or | 24 | 1 | EA | 5 | \$1,341 | |
| Exterior Doors - Exterior Steel Do | or | 25 | 1 | EA | 6 | \$481 | |
| Exterior Doors - Exterior Steel Do | or | 26 | 2 | EA | 5 | \$2,683 | |
| Exterior Doors - Exterior Steel Do | or | 27 | 1 | EA | 5 | \$1,341 | |
| Exterior Doors - Side lite | | 16 | 2 | EA | 5 | \$952 | |
| Exterior Doors - Side lite | | 17 | 2 | EA | 5 | \$952 | |
| Exterior Doors - Store Front | | 15 - Main | 2 | EA | 5 | \$3,672 | corroded |
| Exterior Doors - Store Front | | 16 | 2 | EA | 5 | \$3,672 | |
| Exterior Doors - Store Front | | 17 | 2 | EA | 5 | \$3,672 | |
| Exterior Doors - Store Front | | 28 | 4 | EA | 5 | \$7,345 | |
| Exterior Doors - Transom Lite | | 16 | 2 | EA | 5 | \$1,643 | |
| Exterior Doors - Transom Lite | | 17 | 2 | EA | 5 | \$1,643 | |
| Exterior Stairs - Concrete | | 18 | 28 | LF | 6 | \$2,289 | |
| Exterior Stairs - Concrete | | 19 | 80 | LF | 6 | \$6,541 | |
| Exterior Stairs - Concrete | | 20 | 15 | LF | 5 | \$1,644 | |
| Exterior Stairs - Concrete | | 21 | 80 | LF | 6 | \$6,541 | |
| Exterior Stairs - Concrete | | 22 | 25 | LF | 6 | \$2,044 | |
| Exterior Stairs - Concrete | | 23 | 25 | LF | 5 | \$2,740 | |
| Exterior Stairs - Concrete | | 24 | 30 | LF | 5 | \$3,287 | |
| Exterior Stairs - Concrete | | 25 | 70 | LF | 5 | \$7,671 | |
| Exterior Stairs - Concrete | | 26 | 10 | LF | 3 | \$1,636 | broken |
| Exterior Stairs - Concrete | | 26 | 60 | LF | 6 | \$4,906 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| | tom Type | Lagation | Ouenthi | l lmit | Donk | Ca-4 | Comments | | | |
|---------|--|-----------------|----------|--------|------|----------|--|--|--|--|
| - | Item - Type | Location | Quantity | Unit | Kank | Cost | Comments | | | |
| ∟ntran | Entrance Control of the Control of t | | | | | | | | | |
| | Exterior Stairs - Concrete | 27 | 30 | LF | 6 | \$2,453 | | | | |
| | Exterior Stairs - Concrete | 28 | 72 | LF | 6 | \$5,887 | | | | |
| | Exterior Stairs - Stone | 17 | 10 | LF | 6 | \$1,130 | | | | |
| | Power Door Operator and Controls | 15 - Main | 1 | EA | 7 | \$0 | | | | |
| | Ramp Handrail - Steel_Ramp Handrail | 28 | 50 | LF | 5 | \$530 | | | | |
| | Ramps - Concrete | 28 | 25 | LF | 6 | \$3,756 | | | | |
| | Stair Handrail - Steel_Stair Handrail | 18 | 2 | LF | 5 | \$23 | | | | |
| | Stair Handrail - Steel_Stair Handrail | 19 | 36 | LF | 6 | \$312 | | | | |
| | Stair Handrail - Steel_Stair Handrail | 20 | 5 | LF | 5 | \$57 | | | | |
| | Stair Handrail - Steel_Stair Handrail | 21 | 36 | LF | 6 | \$312 | | | | |
| | Stair Handrail - Steel_Stair Handrail | 22 | 9 | LF | 6 | \$78 | | | | |
| | Stair Handrail - Steel_Stair Handrail | 23 | 5 | LF | 6 | \$43 | | | | |
| | Stair Handrail - Steel_Stair Handrail | 24 | 15 | LF | 6 | \$130 | | | | |
| | Stair Handrail - Steel_Stair Handrail | 25 | 30 | LF | 6 | \$260 | | | | |
| | Stair Handrail - Steel_Stair Handrail | 26 | 30 | LF | 6 | \$260 | | | | |
| | Stair Handrail - Steel_Stair Handrail | 27 | 10 | LF | 6 | \$87 | | | | |
| Founda | ation | | | | | | | | | |
| | Foundation - Concrete | Entire Building | 1,635 | LF | 7 | \$0 | | | | |
| | Superstructure - Concrete | Entire Building | 111,615 | SF | 7 | \$0 | | | | |
| Lightin | g | | | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 18 | EA | 7 | \$0 | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 5 | EA | 6 | \$1,444 | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 4 | EA | 4 | \$4,120 | lights missing | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 3 | EA | 7 | \$0 | | | | |
| Roof S | ystem | | | | | | | | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | A / Main Roof | 8 | LF | 4 | \$45,056 | concrete cap- deteriorated and corroded | | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | A / Main Roof | 35 | LF | 6 | \$33,414 | | | | |
| | Coping - Stone | Α | 1,625 | LF | 6 | \$52,191 | | | | |
| | Coping - Stone | A / South | 1 | LF | 4 | \$363 | deteriorated mortar | | | |
| | Coping - Stone | В | 44 | LF | 6 | \$1,413 | | | | |
| | Downspouts - Interior Downspouts | Α | 50 | LF | 5 | \$11,065 | | | | |
| | Downspouts - Interior Downspouts | A | 300 | LF | 6 | \$9,970 | | | | |
| | Downspouts - Interior Downspouts | В | 13 | LF | 4 | \$6,073 | not accessible, clogged, causing substantial | | | |
| | Parapet - 16" - 30" Height | Α | 1,626 | LF | 6 | \$64,966 | ponding | | | |
| | Parapet - Parapet < 16" Height | В | 44 | LF | 6 | \$938 | | | | |
| | | _ | • • | | - | +-00 | | | | |



6325 W 56th St Chicago, IL 60638 Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

Category: Building Exterior

| n | - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----|----------------------------------|-------------------------------|----------|------|------|-----------|----------------------------------|
| n | | | | | | | |
| of | f Structure - Concrete | A | 48,332 | SF | 7 | \$0 | |
| of | f Structure - Concrete | В | 437 | SF | 7 | \$0 | |
| of | f - Asphalt Gravel Ballast | A | 150 | SF | 5 | \$4,648 | |
| of | f - Asphalt Gravel Ballast | A | 48,182 | SF | 6 | \$489,881 | |
| of | f - Asphalt Gravel Ballast | В | 437 | SF | 6 | \$4,443 | |
| | | | | | | | |
| าด | opy - Metal | Entire Building / West Façade | 240 | SF | 5 | \$12,849 | |
| er | rior Walls - Brick | Entire Building | 23,950 | SF | 6 | \$160,968 | |
| er | rior Walls - Stone-Cast | Entire Building | 1,214 | SF | 6 | \$8,159 | |
| er | rior Walls - Stone-Cast | Entire Building / East Façade | 128 | SF | 5 | \$2,255 | |
| er | rior Walls - Stone-Cast | Entire Building / West Façade | 3 | SF | 4 | \$545 | deteriorated |
| | | | | | | | |
| el | els - Steel | Entire Building | 1,639 | LF | 6 | \$47,579 | |
| nd | dows - Decorative | Entire Building | 2 | SF | 4 | \$653 | glass block - cracked |
| nd | dows - Decorative | Entire Building | 238 | SF | 6 | \$1,777 | |
| nd | dows - Louver | Entire Building | 232 | SF | 5 | \$19,866 | |
| nd | dows - Sash Aluminum Double-pane | Entire Building | 7,884 | SF | 6 | \$58,851 | |
| | dows - Sash Aluminum Double-pane | Entire Building | 7,884 | SF | : | | 6 \$58,851 \$1,132,070 |

Building Exterior Subtotal:

\$1,132,970

Building: Kinzie

Category: Electrical System

| Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|---|---|---|--|---|--|
| ncy System | | | | | | |
| Automatic Transfer Switch | Basement | 1 | EA | 6 | \$408 | |
| Emergency A/C Power - Corridors and Stairs | Entire Building | 11,343 | SF | 6 | \$3,406 | |
| Emergency A/C Power - Gym | Entire Building | 19,754 | SF | 6 | \$7,345 | |
| Emergency A/C Power - Students Toilets | Entire Building | 4,341 | SF | 6 | \$1,614 | |
| Emergency Battery Packs - Corridors and Stairs | Basement | 4 | EA | 6 | \$810 | All 4 are located in the basement |
| Exit Signs - Corridors and Stairs | Entire Building | 28 | EA | 2 | \$15,274 | |
| Exit Signs - Gym | Entire Building | 5 | EA | 2 | \$2,891 | |
| Exit Signs - Multipurpose Room | Entire Building | 4 | EA | 2 | \$2,182 | |
| Security System - CCTV | Entire Building | 111,615 | SF | 6 | \$33,518 | |
| Security System - Intrusion Detection | Entire Building | 111,615 | SF | 6 | \$28,730 | |
| | Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Multipurpose Room Security System - CCTV | Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Exit Signs - Multipurpose Room Exit Signs - Multipurpose Room Security System - CCTV Basement Entire Building Entire Building Entire Building Entire Building | Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Entire Building Exit Signs - Multipurpose Room Entire Building Security System - CCTV Entire Building 111,615 | Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Exit Signs - Corridors and Stairs Exit Signs - Gym Entire Building 28 EA Exit Signs - Gym Entire Building 5 EA Exit Signs - Multipurpose Room Entire Building 4 EA Exit Signs - Multipurpose Room Entire Building 5 EA | Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Entire Building 4,341 SF 6 Emergency Battery Packs - Corridors and Stairs Basement 4 EA 6 Exit Signs - Corridors and Stairs Entire Building 28 EA 2 Exit Signs - Gym Entire Building 5 EA 2 Exit Signs - Multipurpose Room Entire Building 4 EA 2 Security System - CCTV Entire Building 111,615 SF 6 | Automatic Transfer Switch Emergency A/C Power - Corridors and Stairs Entire Building Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Corridors and Stairs Exit Signs - Corridors and Stairs Entire Building Exit Signs - Gym Entire Building Exit Signs - Multipurpose Room Entire Building Entire Building |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|-----------------------------------|----------|------|------|----------|----------|
| Main S | ervice | | | | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 7 | \$0 | |
| | Main Electrical Service - 1600 A 277/480/3PH | Mechanical Room | 1 | EA | 7 | \$0 | |
| | PA System | Entire Building | 111,615 | SF | 6 | \$36,710 | |
| Power | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 3 | EA | 4 | \$14,548 | |
| | Lighting and Power Panels - 100 A | Entire Building | 3 | EA | 7 | \$0 | |
| | Lighting and Power Panels - 100 A | Entire Building | 21 | EA | 6 | \$6,281 | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building / Mechanical Room | 1 | EA | 7 | \$0 | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 7 | \$0 | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 7 | \$0 | |
| | | | | | | <u> </u> | |

Electrical System Subtotal:

\$153,717

Building: Kinzie

Category: Safty System

| Group Item - Type | Location | Quantity Unit Rank | Cost Comments | |
|--------------------------|-----------------|--------------------|---------------|--|
| Fire Alarm | | | | |
| Fire Alarm Panel | Entire Building | 1 EA 6 | \$6,406 | |
| Fire Alarm Strobe Lights | Entire Building | 111,615 SF 6 | \$39,902 | |
| Fire Alarm_System | Entire Building | 111,615 SF 6 | \$54,267 | |
| | | | | |

Safty System Subtotal:

\$100,575

Building: Kinzie

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | | | |
|---------|---|--------------------|----------|------|------|-----------|--------------------------|--|--|--|--|
| Air Co | Air Conditioning | | | | | | | | | | |
| | Chemical Pot Feeder | Roof / Boiler Room | 1 | EA | 5 | \$1,685 | | | | | |
| | Chiller-Air Cooled- Recipricating-Roof Mounted - 201 - 300 tons | Roof | 2 | EA | 5 | \$140,540 | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | \$3,334 | | | | | |
| | Glycol Feed | Roof / Boiler Room | 1 | EA | 6 | \$490 | | | | | |
| | Pressure Fill System | Roof / Boiler Room | 1 | EA | 6 | \$1,405 | | | | | |
| Air Haı | ndling Systems | | | | | | | | | | |
| | Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm | Mechanical Room | 1 | EA | 5 | \$26,442 | Serves multipurpose room | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--|-------------------------------|----------|------|------|-----------|---|
| Air Han | dling Systems | | | | | | |
| | Fan Coil Unit- Floor Mounted - Hot Water and Chilled Water | 215 | 1 | EA | 7 | \$0 | |
| | Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM | Mechanical Room / Attic | 1 | EA | 5 | \$9,732 | |
| Boiler S | Systems | | | | | | |
| | Boiler Auxiliary- Steam Boiler - Greater than 200 HP | Boiler Room | 2 | EA | 6 | \$4,093 | |
| | Combustion Dampers | Boiler Room | 2 | EΑ | 6 | \$818 | |
| | Condensate Pump | Boiler Room / Basement | 2 | EA | 6 | \$4,042 | |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 6 | \$2,545 | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Steam Boiler - Greater than 200 HP | Boiler Room | 2 | EA | 6 | \$4,093 | |
| | Piping - Condensate Pipe- Steel | Boiler Room | 100 | LF | 6 | \$189 | |
| | Piping - Steam Pipe- Steel | Boiler Room | 100 | LF | 6 | \$189 | |
| | Steam Traps | Boiler Room / Entire Building | 70 | EA | 6 | \$18,490 | |
| Heat Ex | changers | | | | | | |
| | Heat Exchanger - Steam to Hot Water Shell Type | Boiler Room | 1 | EA | 7 | \$0 | |
| Heating | Devices | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 18 | EA | 6 | \$6,378 | |
| | Fin Tube - Hot Water | Entire Building / Basement | 87 | LF | 6 | \$821 | |
| | Radiators - Hot Water | Entire Building | 4 | EA | 6 | \$1,111 | |
| | Unit Heater - Hot Water | Boiler Room | 1 | EA | 7 | \$0 | |
| | Unit Heater - Steam | Boiler Room / 1st Floor | 3 | EA | 4 | \$5,266 | |
| | Wall Heater - Electric | Entire Building | 4 | EA | 6 | \$556 | |
| Mechar | nical Plumbing | | | | | | |
| | Chilled Water Pump - 21 - 50 HP | Boiler Room | 2 | EA | 6 | \$2,485 | |
| | Hot Water Pump - 21 - 50 HP | Boiler Room | 2 | EA | 6 | \$2,485 | |
| | Hydronic Supply and Return - Steel | Boiler Room | 800 | LF | 6 | \$61,421 | |
| Temper | rature Control | | | | | | |
| | Pneumatic System | Entire Building | 106,838 | SF | 4 | \$556,113 | |
| | Thermostats - Pneumatic | Entire Building | 94 | EA | 4 | \$69,300 | |
| Unit Ve | ntilation | | | | | | |
| | Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water | Entire Building | 59 | EA | 6 | \$73,296 | Most classrooms have 2 unit ventilators |
| Ventilat | ion | | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building / 1st Floor | 1 | EA | 6 | \$592 | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 1 | EA | 7 | \$0 | |
| IZENINIE | | David 05 (1400 | | | | | A D-1- 0/00 |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------------------|----------|------|------|----------|---|
| Ventila | tion | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 4 | EA | 4 | \$25,568 | Greater than 15 years of age and poor condition |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 2 | EA | 6 | \$1,185 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 6 | EA | 4 | \$25,467 | Greater than 15 years of age and poor condition |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 3 | EA | 7 | \$0 | |
| | Type I Exhaust Hood- Kitchen | Entire Building / 1st Floor | 1 | EA | 3 | \$28,265 | |
| | Type I Exhaust Hood- Kitchen | Entire Building / 1st Floor | 1 | EA | 6 | \$1,248 | |

Mechanical System Subtotal: \$1,079,644

Building: Kinzie

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------|----------|------|------|-----------|----------|
| Hot Wat | ter | | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 2 | EA | 7 | \$0 | |
| | Hot Water Storage Tank_Gas - Less than 200 Gallons | Boiler Room | 2 | EA | 7 | \$0 | |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 111,615 | SF | 5 | \$0 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 111,615 | SF | 5 | \$0 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 111,615 | SF | 5 | \$0 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 111,615 | SF | 5 | \$0 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 111,615 | SF | 5 | \$0 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 111,615 | SF | 5 | \$0 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 111,615 | SF | 5 | \$0 | |
| | Sanitary Piping | Entire Building | 111,615 | SF | 6 | \$102,150 | |
| | Storm Piping | Entire Building | 111,615 | SF | 6 | \$97,362 | |
| | Vent Piping | Entire Building | 111,615 | SF | 6 | \$75,016 | |
| Pumps | | | | | | | |
| | Pumps - Sump-Duplex | Mechanical Room | 1 | EA | 5 | \$7,535 | |

Plumbing System Subtotal: \$282,063

Building: Kinzie

Category: Classrooms

Group Item - Type Location Quantity Unit Rank Cost Comments



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------------|----------|----------|------|------|---------|--------------------------|
| _ | oom #102 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 25 | SF | 5 | \$173 | stained and missing tile |
| | Ceiling - Lay-in | | 65 | SF | 6 | \$195 | |
| | Ceiling - Plaster/Drywall | | 635 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EΑ | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | stained and worn |
| | Lighting - Lay-in | | 4 | EΑ | 6 | \$476 | |
| | Lighting - Pendent/Surface | | 12 | EΑ | 6 | \$1,487 | |
| | Marker Board | | 41 | LF | 7 | \$0 | |
| | Work Sink | | 1 | EA | 5 | \$1,508 | |
| Classro | oom #104 (Other Instructional Use) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 90 | SF | 6 | \$270 | |
| | Ceiling - Plaster/Drywall | | 635 | SF | 7 | \$0 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile | | 725 | SF | 7 | \$0 | |
| | Lighting - Lay-in | | 4 | EA | 6 | \$476 | |
| | Lighting - Pendent/Surface | | 12 | EΑ | 6 | \$1,487 | |
| | Marker Board | | 23 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 7 | \$0 | |
| | Work Sink | | 1 | EA | 5 | \$1,508 | |
| Classro | oom #112 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 90 | SF | 6 | \$270 | |
| | Ceiling - Plaster/Drywall | | 635 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 6 | \$1,545 | |
| | Lighting - Lay-in | | 4 | EΑ | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 12 | EΑ | 7 | \$0 | |
| | Marker Board | | 38 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 7 | \$0 | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classro | oom #113 (Regular Classroom) | | | | | | |
| | Casework | | 23 | LF | 6 | \$581 | |
| | Ceiling - Lay-in | | 90 | SF | 6 | \$270 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|----------|----------|------|------|----------|--------------------------|
| _ | oom #113 (Regular Classroom) | | | | | | |
| | Ceiling - Plaster/Drywall | | 650 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 740 | SF | 6 | \$1,577 | |
| | Lighting - Lay-in | | 4 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 12 | EΑ | 7 | \$0 | |
| | Marker Board | | 12 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 629 | SF | 6 | \$1,844 | |
| | Walls - Plaster/Drywall | | 250 | SF | 6 | \$690 | |
| Classro | oom #114 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 90 | SF | 6 | \$270 | |
| | Ceiling - Plaster/Drywall | | 635 | SF | 6 | \$2,197 | some peeling paint |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | | 725 | SF | 6 | \$726 | |
| | Lighting - Lay-in | | 4 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 12 | EΑ | 7 | \$0 | |
| | Marker Board | | 23 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 7 | \$0 | |
| Classro | oom #115 (Science Lab Level 3) | | | | | | |
| | Casework | | 112 | LF | 5 | \$23,417 | |
| | Ceiling - Lay-in | | 135 | SF | 6 | \$405 | |
| | Ceiling - Plaster/Drywall | | 995 | SF | 6 | \$3,443 | |
| | Chalk Board | | 8 | LF | 4 | \$734 | obsolete material |
| | Doors - Wood Doors inclu hw | | 2 | EΑ | 6 | \$602 | |
| | Floor - Tile | | 1,130 | SF | 6 | \$2,472 | |
| | Lighting - Lay-in | | 7 | EΑ | 6 | \$833 | |
| | Lighting - Pendent/Surface | | 18 | EA | 6 | \$2,230 | |
| | Storage/ Closet | | 4 | SF | 6 | \$29 | |
| | Walls - Concrete Block | | 918 | SF | 6 | \$2,691 | peeling paint at windows |
| | Work Sink | | 4 | EA | 6 | \$1,516 | |
| Classro | oom #116 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 90 | SF | 6 | \$270 | |
| | Ceiling - Plaster/Drywall | | 635 | SF | 7 | \$0 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------------|----------|----------|------|------|---------|-----------------------------------|
| _ | Classroom #116 (Regular Classroom) | | | | | | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | zippering seams, stained and worn |
| | Lighting - Lay-in | | 4 | EA | 6 | \$476 | |
| | Lighting - Pendent/Surface | | 12 | EA | 6 | \$1,487 | |
| | Marker Board | | 23 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 6 | \$2,199 | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classro | oom #117 (Faculty Lounge) | | | | | | |
| | Casework | | 70 | LF | 6 | \$1,768 | |
| | Ceiling - Lay-in | | 135 | SF | 6 | \$405 | |
| | Ceiling - Plaster/Drywall | | 1,040 | SF | 6 | \$3,599 | minor peeling paint |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 1,175 | SF | 5 | \$6,032 | |
| | Lighting - Lay-in | | 4 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 18 | EA | 6 | \$2,230 | |
| | Walls - Concrete Block | | 1,054 | SF | 7 | \$0 | |
| | Work Sink | | 2 | EA | 6 | \$758 | |
| Classro | oom #118 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 90 | SF | 6 | \$270 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 6 | \$1,545 | |
| | Lighting - Lay-in | | 4 | EA | 6 | \$476 | |
| | Lighting - Pendent/Surface | | 12 | EA | 6 | \$1,487 | |
| | Marker Board | | 14 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 6 | \$2,199 | peeling paint at windows |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classro | oom #119 (Pre School) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | refinish or replace |
| | Ceiling - Lay-in | | 811 | SF | 6 | \$2,435 | peeling paint near windows |
| | Chalk Board | | 24 | LF | 4 | \$2,203 | obsolete material |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | | 811 | SF | 5 | \$4,163 | zippening, stained |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 10 | LF | 7 | \$0 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|----------|----------|------|------|---------|----------------------------------|
| Classro | oom #119 (Pre School) | | | | | | |
| | Walls - Concrete Block | | 813 | SF | 6 | \$2,383 | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classro | oom #120 (Kindergarten) | | | | | | |
| | Casework | | 37 | LF | 6 | \$934 | |
| | Ceiling - Lay-in | | 135 | SF | 6 | \$405 | |
| | Ceiling - Plaster/Drywall | | 1,080 | SF | 6 | \$3,737 | peeling paint at north window |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile | | 1,215 | SF | 6 | \$2,658 | |
| | Lighting - Lay-in | | 6 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 16 | EA | 6 | \$1,982 | |
| | Marker Board | | 16 | LF | 7 | \$0 | |
| | Storage/ Closet | | 55 | SF | 6 | \$399 | |
| | Walls - Concrete Block | | 924 | SF | 7 | \$0 | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classro | oom #121 (Kindergarten) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 725 | SF | 6 | \$2,177 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| | Walls - Concrete Block | | 50 | SF | 5 | \$704 | heavily peeling paint at windows |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classro | oom #122 (Kindergarten) | | | | | | |
| | Casework | | 37 | LF | 6 | \$934 | |
| | Ceiling - Lay-in | | 1,215 | SF | 6 | \$3,649 | peeling paint at windows |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile | | 1,269 | SF | 6 | \$2,776 | vct |
| | Lighting - Lay-in | | 17 | EA | 6 | \$2,023 | |
| | Marker Board | | 4 | LF | 7 | \$0 | |
| | Storage/ Closet | | 54 | SF | 6 | \$392 | |
| | Walls - Concrete Block | | 924 | SF | 7 | \$0 | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|----------|----------|------|------|---------|---------------------------------------|
| Classro | om #123 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 725 | SF | 6 | \$2,177 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | zippering seams, stained and worn |
| | Lighting - Lay-in | | 12 | EA | 6 | \$1,428 | |
| | Marker Board | | 21 | LF | 6 | \$450 | |
| | Walls - Concrete Block | | 50 | SF | 5 | \$704 | heavily peeling paint at windows |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classro | oom #124 (Regular Classroom) | | | | | | |
| | Casework | | 8 | LF | 6 | \$202 | |
| | Ceiling - Lay-in | | 730 | SF | 6 | \$2,192 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 730 | SF | 5 | \$3,748 | |
| | Lighting - Lay-in | | 6 | EA | 6 | \$714 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 638 | SF | 6 | \$1,870 | |
| Classro | oom #125 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 725 | SF | 6 | \$2,177 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | zippering seams, stained and worn |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 41 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 50 | SF | 5 | \$704 | heavily peeling paint at windows |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | partially covered in splined material |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classro | oom #126 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | | 725 | SF | 6 | \$2,177 | |
| | Doors - Wood Doors inclu hw | | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile | | 725 | SF | 6 | \$1,586 | |
| | Lighting - Lay-in | | 15 | EA | 6 | \$1,785 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 787 | SF | 6 | \$2,307 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | ltem - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|------------------------------|----------|----------|------|------|---------|--|
| Classr | oom #126 (Regular Classroom) | | | | | | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classr | oom #127 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 870 | SF | 6 | \$2,613 | |
| | Ceiling - Lay-in | | 8 | SF | 4 | \$112 | mismatched, broken & warped tiles |
| | Chalk Board | | 8 | LF | 4 | \$734 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 878 | SF | 5 | \$4,507 | stained, zippering |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 787 | SF | 6 | \$2,307 | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classr | oom #129 (Regular Classroom) | | | | | | |
| | Casework | | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | | 617 | SF | 6 | \$1,853 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 617 | SF | 5 | \$3,167 | zippering stained |
| | Lighting - Lay-in | | 9 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 723 | SF | 6 | \$2,119 | |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classr | room #131 (Store Room) | | | | | | |
| | Casework | | 19 | LF | 6 | \$480 | |
| | Ceiling - Lay-in | | 15 | SF | 5 | \$120 | watre damage at windows |
| | Ceiling - Lay-in | | 710 | SF | 6 | \$2,132 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 751 | SF | 6 | \$2,202 | parially covered with splined material |
| | Work Sink | | 1 | EA | 6 | \$379 | |
| Classr | oom #133 (Regular Classroom) | | | | | | |
| | Casework | | 19 | LF | 6 | \$480 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| | Item - Type | Location Quar | ntity | Unit | Rank | Cost | Comments |
|---------|------------------------------|---------------|-------|------|------|---------|---------------------------------------|
| _ | oom #133 (Regular Classroom) | | • | | | | |
| | Ceiling - Lay-in | | 762 | SF | 6 | \$2,288 | chipping paint at windows |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 762 | SF | 6 | \$1,667 | |
| | Lighting - Lay-in | | 12 | EA | 6 | \$1,428 | |
| | Marker Board | | 18 | LF | 7 | \$0 | |
| | Walls - Concrete Block | , | 787 | SF | 6 | \$2,307 | partially covered by splined material |
| | Work Sink | | 1 | EA | 5 | \$1,508 | |
| Classro | oom #200 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 6 | \$2,509 | |
| | Chalk Board | | 22 | LF | 4 | \$2,020 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | |
| | Lighting - Pendent/Surface | | 16 | EA | 6 | \$1,982 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 6 | \$2,199 | |
| Classro | oom #202 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 5 | \$6,646 | |
| | Chalk Board | | 22 | LF | 4 | \$2,020 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 6 | \$1,545 | |
| | Lighting - Pendent/Surface | | 16 | EA | 6 | \$1,982 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | : | 750 | SF | 7 | \$0 | |
| Classro | oom #203 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 6 | \$2,509 | some peeling paint |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 6 | \$1,545 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 25 | SF | 5 | \$352 | cracks |
| | Walls - Concrete Block | | 725 | SF | 6 | \$2,125 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|----------|----------|------|------|---------|------------------------------------|
| Classro | oom #203 (Regular Classroom) | | | | | | |
| Classro | oom #204 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Splined | | 725 | SF | 6 | \$591 | minor staining |
| | Chalk Board | | 10 | LF | 4 | \$918 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | worn and stained |
| | Lighting - Pendent/Surface | | 20 | EA | 6 | \$2,478 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| | Walls - Concrete Block | | 50 | SF | 5 | \$704 | wall crack, damaged sill |
| Classro | oom #205 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 6 | \$1,545 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 23 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| | Walls - Concrete Block | | 50 | SF | 5 | \$704 | cracks |
| Classro | oom #206 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Splined | | 700 | SF | 6 | \$571 | |
| | Ceiling - Splined | | 25 | SF | 4 | \$351 | damaged/missing tiles; |
| | Chalk Board | | 10 | LF | 4 | \$918 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | damaged finish, replace or repaint |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | zippering, damaged |
| | Lighting - Pendent/Surface | | 16 | EA | 6 | \$1,982 | |
| | Marker Board | | 23 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 6 | \$2,199 | |
| Classro | oom #207 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 6 | \$2,509 | peeling paint |
| | Chalk Board | | 22 | LF | 4 | \$2,020 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 6 | \$1,545 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| | tem Type | l anatinu | 0 | l les!4 | Denle | 0 | Comments |
|---------|------------------------------|-----------|----------|---------|-------|---------------|-------------------|
| _ | Item - Type | Location | Quantity | Unit | Kank | Cost | Comments |
| Classro | oom #207 (Regular Classroom) | | 40 | Ε. | 0 | #4.000 | |
| | Lighting - Pendent/Surface | | 16 | EA | 6 | \$1,982 | |
| | Marker Board | | 43 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 50 | SF | 5 | | cracks |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| Classro | oom #209 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 7 | \$0 | |
| | Chalk Board | | 22 | LF | 4 | \$2,020 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile/Sheet | | 725 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 16 | EΑ | 7 | \$0 | |
| | Marker Board | | 23 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 7 | \$0 | |
| Classro | oom #211 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 6 | \$2,509 | peeling paint |
| | Chalk Board | | 22 | LF | 4 | \$2,020 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile | | 725 | SF | 6 | \$1,586 | vct |
| | Lighting - Pendent/Surface | | 16 | EA | 6 | \$1,982 | |
| | Marker Board | | 23 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| | Walls - Concrete Block | | 50 | SF | 5 | \$704 | cracks |
| Classro | oom #212 (Regular Classroom) | | | | | | |
| | Casework | | 26 | LF | 6 | \$657 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 6 | \$2,509 | peeling paint |
| | Chalk Board | | 22 | LF | 4 | \$2,020 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EΑ | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 6 | \$1,545 | |
| | Lighting - Pendent/Surface | | 16 | EA | 6 | \$1,982 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 50 | SF | 5 | \$704 | cracks |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| Classro | oom #213 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|----------|----------|------|------|---------|---|
| Classro | oom #213 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | | 725 | SF | 6 | \$2,177 | |
| | Chalk Board | | 22 | LF | 4 | \$2,020 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | stained, zippering |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 21 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| | Walls - Concrete Block | | 50 | SF | 5 | \$704 | cracks in CMU wall |
| Classro | oom #214 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 6 | \$2,509 | some water damage/peeling paint |
| | Chalk Board | | 21 | LF | 4 | \$1,928 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 725 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 16 | EΑ | 7 | \$0 | |
| | Marker Board | | 23 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| | Walls - Concrete Block | | 50 | SF | 5 | \$704 | cracks in wall and window sill |
| Classro | oom #215 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 725 | SF | 6 | \$2,177 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | |
| | Lighting - Lay-in | | 12 | EΑ | 7 | \$0 | |
| | Marker Board | | 41 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 6 | \$2,199 | partially covered with splined material |
| Classro | oom #216 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 6 | \$2,509 | some peeling paint |
| | Chalk Board | | 21 | LF | 4 | \$1,928 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EΑ | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 6 | \$1,545 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 43 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| | Walls - Concrete Block | | 50 | SF | 4 | \$2,623 | cracks |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|------------------------------|----------|----------|------|------|---------|---|
| - | pom #216 (Regular Classroom) | | | | | | |
| | | | | | | | |
| Classro | oom #217 (Computer Lab) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Splined | | 725 | SF | 6 | \$591 | |
| | Chalk Board | | 41 | LF | 4 | | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 725 | SF | 6 | \$1,586 | |
| | Lighting - Pendent/Surface | | 20 | EA | 6 | \$2,478 | |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | |
| | Walls - Concrete Block | | 50 | SF | 5 | \$704 | cracks |
| Classro | oom #218 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 725 | SF | 6 | \$2,177 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 41 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 700 | SF | 6 | \$2,052 | partially covered in splined material |
| | Walls - Concrete Block | | 50 | SF | 5 | | cracks |
| Classro | oom #219 (Regular Classroom) | | | | | | |
| 0.0.00.0 | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 725 | SF | 6 | \$2,177 | |
| | Chalk Board | | 20 | LF | 4 | | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | ossoloto matoria. |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | zippering, stains |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | ppog, otao |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 6 | \$2,199 | partially covered with splined material |
| Classro | oom #220 (Science) | | | | | | |
| | Casework | | 65 | LF | 6 | \$1,641 | |
| | Ceiling - Plaster/Drywall | | 872 | SF | 6 | \$3,018 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 872 | SF | 6 | \$1,908 | vct |
| | Lighting - Pendent/Surface | | 16 | EA | 6 | | suspended at an angle |
| | Walls - Concrete Block | | 679 | SF | 6 | \$1,990 | |
| | Walls - Plaster/Drywall | | 260 | SF | 7 | \$0 | |
| | · | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|----------|----------|------|------|---------|---------------------------------------|
| Classro | oom #220 (Science) | | | | | | |
| | Work Sink | | 1 | EA | 5 | \$1,508 | damaged instructional sink |
| Classro | oom #221 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 878 | SF | 6 | \$2,637 | |
| | Chalk Board | | 22 | LF | 4 | \$2,020 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 878 | SF | 5 | \$4,507 | zippering, stains |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | | 757 | SF | 6 | \$2,219 | |
| | Walls - Concrete Block | | 30 | SF | 5 | \$423 | cracks |
| Classro | oom #222 (Special Program) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Plaster/Drywall | | 725 | SF | 6 | \$2,509 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 725 | SF | 6 | \$1,586 | |
| | Lighting - Pendent/Surface | | 17 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 6 | \$2,199 | |
| Classro | oom #223 (Regular Classroom) | | | | | | |
| | Casework | | 18 | LF | 5 | \$3,763 | |
| | Ceiling - Lay-in | | 617 | SF | 6 | \$1,853 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 617 | SF | 5 | \$3,167 | |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 723 | SF | 6 | \$2,119 | partially covered in splined material |
| Classro | oom #224 (Art Room) | | | | | | |
| | Casework | | 100 | LF | 6 | \$2,525 | |
| | Ceiling - Plaster/Drywall | | 1,361 | SF | 6 | | minor peeling paint at windows |
| | Chalk Board | | 10 | LF | 4 | \$918 | obsolete material |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile | | 1,361 | SF | 6 | \$2,978 | |
| | Lighting - Pendent/Surface | | 28 | EA | 6 | \$3,469 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|----------|----------|------|------|---------|---------------------------|
| Classro | oom #224 (Art Room) | | | | | | |
| | Walls - Concrete Block | | 1,153 | SF | 6 | \$3,380 | |
| | Work Sink | | 2 | EA | 6 | \$758 | |
| Classro | oom #225 (Regular Classroom) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 725 | SF | 6 | \$2,177 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 5 | \$3,722 | |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 43 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 6 | \$2,199 | |
| Classro | oom #227 (Kindergarten) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 700 | SF | 6 | \$2,102 | |
| | Ceiling - Lay-in | | 25 | SF | 5 | \$199 | tiles broken and warped |
| | Chalk Board | | 21 | LF | 4 | \$1,928 | obsolete material |
| | Doors - Wood Doors inclu hw | | 1 | EΑ | 6 | \$301 | |
| | Floor - Carpet | | 725 | SF | 6 | \$1,545 | |
| | Lighting - Lay-in | | 12 | EΑ | 7 | \$0 | |
| | Marker Board | | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 400 | SF | 6 | \$1,173 | |
| | Walls - Concrete Block | | 61 | SF | 4 | \$2,565 | large cracks in CMU walls |
| Classro | oom #235 (Computer Lab) | | | | | | |
| | Casework | | 20 | LF | 6 | \$505 | |
| | Ceiling - Lay-in | | 725 | SF | 6 | \$2,177 | |
| | Chalk Board | | 20 | LF | 4 | \$1,836 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Tile | | 725 | SF | 6 | \$1,586 | |
| | Lighting - Lay-in | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | | 750 | SF | 6 | \$2,199 | |
| Classro | oom #Bsmt AudioBooth (Special Program) | | | | | | |
| | Ceiling - Plaster/Drywall | Basement | 392 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Basement | 1 | EA | 6 | \$301 | |
| | Floor - Concrete Epoxy/ Painted | Basement | 392 | SF | 6 | \$207 | |
| | Lighting - Pendent/Surface | Basement | 2 | EA | 7 | \$0 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|----------|----------|------|------|---------|-----------------|
| Classro | oom #Bsmt AudioBooth (Special Program) | | | | | | |
| | Storage/ Closet | Basement | 64 | SF | 6 | \$464 | |
| | Walls - Concrete Block | Basement | 678 | SF | 7 | \$0 | |
| | Work Sink | Basement | 5 | EA | 6 | \$1,895 | |
| Classro | oom #Bsmt Speech (Other Instructional Use) | | | | | | |
| | Ceiling - Plaster/Drywall | | 422 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | | 2 | EA | 6 | \$602 | |
| | Floor - Concrete Epoxy/ Painted | | 422 | SF | 6 | \$223 | |
| | Lighting - Pendent/Surface | | 4 | EA | 7 | \$0 | |
| | Storage/ Closet | | 6 | SF | 6 | \$44 | |
| | Walls - Concrete Block | | 392 | SF | 6 | \$1,149 | |
| Classro | oom #In Room 119 (Other Instructional Use) | | | | | | |
| | Casework | | 45 | LF | 6 | \$1,136 | |
| | Ceiling - Lay-in | | 95 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 176 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | | 221 | SF | 5 | \$1,135 | zippering, worn |
| | Lighting - Lay-in | | 3 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | | 3 | EA | 6 | \$372 | |
| | Walls - Concrete Block | | 464 | SF | 6 | \$1,360 | parch holes |

Classrooms Subtotal: \$507,089

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---------------------------------|--|----------|------|------|---------|----------------------|
| Admin | strative Suites/Offices | | | | | | |
| | Ceiling - Plaster/Drywall | 002 - Basement North West Office (across from play room) | 122 | SF | 5 | \$1,118 | severe peeling paint |
| | Doors - Steel Doors incl hw | 002 - Basement North West Office (across from play room) | 2 | EA | 5 | \$2,348 | |
| | Floor - Concrete Epoxy/ Painted | 002 - Basement North West Office (across from play room) | 122 | SF | 6 | \$65 | |
| | Lighting - Pendent/Surface | 002 - Basement North West Office (across from play room) | 2 | EA | 7 | \$0 | |
| | Power Distribution | 002 - Basement North West Office (across from play room) | 4 | EA | 6 | \$8,500 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| p Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|--|----------|------|------|---------|------------------------------|
| inistrative Suites/Offices | | | | | | |
| Walls - Concrete Block | 002 - Basement North West Office (across from play room) | 318 | SF | 6 | \$932 | |
| Ceiling - Plaster/Drywall | 101A - Gym Office | 183 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 101A - Gym Office | 2 | EA | 6 | \$602 | |
| Floor - Tile | 101A - Gym Office | 183 | SF | 6 | \$400 | |
| Lighting - Pendent/Surface | 101A - Gym Office | 2 | EA | 7 | \$0 | |
| Power Distribution | 101A - Gym Office | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | 101A - Gym Office | 681 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | 101B - Gym Office | 77 | SF | 6 | \$266 | peeling paint & water damage |
| Doors - Wood Doors inclu hw | 101B - Gym Office | 1 | EA | 5 | \$1,174 | |
| Floor - Tile | 101B - Gym Office | 77 | SF | 6 | \$168 | |
| Lighting - Pendent/Surface | 101B - Gym Office | 2 | EA | 7 | \$0 | |
| Power Distribution | 101B - Gym Office | 2 | EA | 7 | \$0 | |
| Walls - Concrete Block | 101B - Gym Office | 261 | SF | 5 | \$2,680 | |
| Ceiling - Lay-in | 108 - 1st Flr Main Office | 45 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | 108 - 1st Flr Main Office | 275 | SF | 7 | \$0 | |
| Doors - Side-lite | 108 - 1st Flr Main Office | 22 | SF | 5 | \$1,540 | |
| Doors - Wood Doors inclu hw | 108 - 1st Flr Main Office | 1 | EA | 5 | \$1,174 | |
| Floor - Tile | 108 - 1st Flr Main Office | 320 | SF | 7 | \$0 | |
| Lighting - Lay-in | 108 - 1st Flr Main Office | 2 | EA | 7 | \$0 | |
| Lighting - Pendent/Surface | 108 - 1st Flr Main Office | 6 | EA | 7 | \$0 | |
| Power Distribution | 108 - 1st Flr Main Office | 12 | EA | 7 | \$0 | |
| Walls - Concrete Block | 108 - 1st Flr Main Office | 598 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 110 - Assistant Principal's Office | 66 | SF | 6 | \$198 | |
| Ceiling - Plaster/Drywall | 110 - Assistant Principal's Office | 300 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 110 - Assistant Principal's Office | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 110 - Assistant Principal's Office | 366 | SF | 6 | \$780 | |
| Lighting - Lay-in | 110 - Assistant Principal's Office | 2 | EA | 6 | \$238 | |
| Lighting - Pendent/Surface | 110 - Assistant Principal's Office | 6 | EA | 7 | \$0 | |
| Power Distribution | 110 - Assistant Principal's Office | 6 | EΑ | 7 | \$0 | |
| Walls - Concrete Block | 110 - Assistant Principal's Office | 631 | SF | 7 | \$0 | |
| Ceiling - Lay-in | 111 - Office | 60 | SF | 6 | \$180 | minor water stains |
| Ceiling - Plaster/Drywall | 111 - Office | 360 | SF | 6 | \$1,246 | minor peeling paint |
| Doors - Wood Doors inclu hw | 111 - Office | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 111 - Office | 360 | SF | 6 | \$767 | |
| Lighting - Lay-in | 111 - Office | 2 | EA | 6 | \$238 | |
| Lighting - Pendent/Surface | 111 - Office | 6 | EA | 6 | \$743 | |
| Walls - Concrete Block | 111 - Office | 295 | SF | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|-----------------------------|---|----------|------|------|---------|-------------------------|
| minis | strative Suites/Offices | | | | | | |
| | Walls - Plaster/Drywall | 111 - Office | 216 | SF | 7 | \$0 | |
| | Work SInk | 111 - Office | 1 | EA | 5 | \$1,508 | missing hardware |
| | Ceiling - Lay-in | 1st Floor Nurse's Office | 50 | SF | 6 | \$150 | |
| | Ceiling - Plaster/Drywall | 1st Floor Nurse's Office | 310 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Floor Nurse's Office | 1 | EΑ | 6 | \$301 | |
| | Floor - Carpet | 1st Floor Nurse's Office | 360 | SF | 6 | \$767 | |
| | Lighting - Lay-in | 1st Floor Nurse's Office | 2 | EA | 6 | \$238 | |
| | Lighting - Pendent/Surface | 1st Floor Nurse's Office | 6 | EA | 7 | \$0 | |
| | Power Distribution | 1st Floor Nurse's Office | 5 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor Nurse's Office | 556 | SF | 6 | \$1,630 | |
| | Work SInk | 1st Floor Nurse's Office | 1 | EA | 6 | \$508 | |
| | Ceiling - Plaster/Drywall | 1st Flr - Office in North Corridor | 77 | SF | 5 | \$706 | water damage throughout |
| | Doors - Wood Doors inclu hw | 1st Flr - Office in North Corridor | 1 | EΑ | 5 | \$1,174 | |
| | Floor - Tile | 1st Flr - Office in North Corridor | 77 | SF | 6 | \$168 | |
| | Lighting - Pendent/Surface | 1st Flr - Office in North Corridor | 2 | EΑ | 7 | \$0 | |
| | Power Distribution | 1st Flr - Office in North Corridor | 2 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | 1st Flr - Office in North Corridor | 261 | SF | 5 | \$2,680 | |
| | Ceiling - Lay-in | 1st Flr - Radio Room ("Principal's Office" on plans) | 136 | SF | 6 | \$408 | |
| | Doors - Wood Doors inclu hw | 1st FIr - Radio Room ("Principal's Office" on plans) | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | 1st Flr - Radio Room ("Principal's Office" on plans) | 136 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 1st Flr - Radio Room ("Principal's Office" on plans) | 4 | EA | 6 | \$476 | |
| | Power Distribution | 1st Flr - Radio Room ("Principal's Office" on plans) | 8 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st FIr - Radio Room ("Principal's Office" on plans) | 334 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Flr - Social Worker Office in North Corridor | 172 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Flr - Social Worker Office in North Corridor | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | 1st Flr - Social Worker Office in North Corridor | 172 | SF | 6 | \$376 | |
| | Lighting - Pendent/Surface | 1st Flr - Social Worker Office in North Corridor | 2 | EA | 7 | \$0 | |
| | Power Distribution | 1st Flr - Social Worker Office in North Corridor | 6 | EA | 7 | \$0 | |
| | Storage/ Closet | 1st Flr - Social Worker Office in North Corridor | 48 | SF | 5 | \$774 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|--|----------|------|------|---------|--------------------------|
| Adminis | strative Suites/Offices | | | | | | |
| | Walls - Concrete Block | 1st Flr - Social Worker Office in North Corridor | 200 | SF | 6 | \$586 | |
| | Ceiling - Lay-in | 1st Flr Office (Between Principa'ls office and Nurse's Office - "Teacher Lunch" on plan) | 50 | SF | 6 | \$150 | |
| | Ceiling - Plaster/Drywall | 1st Flr Office (Between Principa'ls office and Nurse's Office - "Teacher Lunch" on plan) | 310 | SF | 6 | \$1,073 | peeling paint at windows |
| | Doors - Wood Doors inclu hw | 1st Flr Office (Between Principa'ls office and Nurse's Office - "Teacher Lunch" on plan) | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Flr Office (Between Principa'ls office and Nurse's Office - "Teacher Lunch" on plan) | 360 | SF | 5 | \$1,616 | |
| | Lighting - Lay-in | 1st Flr Office (Between Principa'ls office and Nurse's Office - "Teacher Lunch" on plan) | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Flr Office (Between Principa'ls office and Nurse's Office - "Teacher Lunch" on plan) | 6 | EA | 6 | \$743 | |
| | Power Distribution | 1st Flr Office (Between Principa'ls office and Nurse's Office - "Teacher Lunch" on plan) | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Flr Office (Between Principa'ls office and Nurse's Office - "Teacher Lunch" on plan) | 581 | SF | 6 | \$1,703 | |
| | Ceiling - Lay-in | 1st Flr Principal's Office ("Asst Principal" on floor plan) | 59 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Flr Principal's Office ("Asst Principal" on floor plan) | 300 | SF | 6 | \$1,038 | cracks in ceiling |
| | Doors - Wood Doors inclu hw | 1st Flr Principal's Office ("Asst Principal" on floor plan) | 2 | EA | 5 | \$2,348 | |
| | Floor - Carpet | 1st Flr Principal's Office ("Asst Principal" on floor plan) | 359 | SF | 6 | \$765 | |
| | Lighting - Lay-in | 1st Flr Principal's Office ("Asst Principal" on floor plan) | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Flr Principal's Office ("Asst Principal" on floor plan) | 6 | EA | 7 | \$0 | |
| | Power Distribution | 1st Flr Principal's Office ("Asst Principal" on floor plan) | 8 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Flr Principal's Office ("Asst Principal" on floor plan) | 556 | SF | 7 | \$0 | |
| | Work Slnk | 1st Flr Principal's Office ("Asst Principal" on floor plan) | 1 | EA | 6 | \$508 | (double faucet) |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---|-------------------------------------|----------|------|------|----------|--|
| Admin | istrative Suites/Offices | | | | | | |
| | Ceiling - Plaster/Drywall | 210A - Media Center/Library Office | 130 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 210A - Media Center/Library Office | 1 | EA | 6 | \$301 | refinish |
| | Floor - Carpet | 210A - Media Center/Library Office | 130 | SF | 6 | \$277 | |
| | Lighting - Pendent/Surface | 210A - Media Center/Library Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | 210A - Media Center/Library Office | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 210A - Media Center/Library Office | 444 | SF | 7 | \$0 | |
| | Work Slnk | 210A - Media Center/Library Office | 1 | EA | 6 | \$508 | |
| | Ceiling - Plaster/Drywall | 210B Library Reading Room | 226 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 210B Library Reading Room | 1 | EA | 6 | \$301 | cart damage |
| | Floor - Carpet | 210B Library Reading Room | 226 | SF | 6 | \$482 | |
| | Lighting - Pendent/Surface | 210B Library Reading Room | 4 | EA | 6 | \$496 | |
| | Power Distribution | 210B Library Reading Room | 2 | EA | 6 | \$4,250 | |
| | Walls - Concrete Block | 210B Library Reading Room | 531 | SF | 6 | \$1,557 | |
| | Ceiling - Lay-in | 223 College Career Center (at Link) | 1,687 | SF | 6 | \$5,066 | minor water stains throughout |
| | Doors - Wood Doors inclu hw | 223 College Career Center (at Link) | 4 | EA | 6 | \$1,204 | |
| | Floor - Tile | 223 College Career Center (at Link) | 1,687 | SF | 6 | \$3,691 | |
| | Lighting - Lay-in | 223 College Career Center (at Link) | 27 | EA | 6 | \$3,212 | |
| | Power Distribution | 223 College Career Center (at Link) | 112 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 223 College Career Center (at Link) | 1,155 | SF | 6 | \$3,386 | partially covered by splined material |
| | Ceiling - Plaster/Drywall | 2nd Floor Teachers' Lounge | 344 | SF | 6 | \$1,190 | |
| | Doors - Wood Doors inclu hw | 2nd Floor Teachers' Lounge | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile | 2nd Floor Teachers' Lounge | 344 | SF | 6 | \$753 | |
| | Lighting - Pendent/Surface | 2nd Floor Teachers' Lounge | 4 | EA | 6 | \$496 | |
| | Power Distribution | 2nd Floor Teachers' Lounge | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor Teachers' Lounge | 633 | SF | 6 | \$1,856 | |
| | Work Slnk | 2nd Floor Teachers' Lounge | 1 | EA | 6 | \$508 | |
| Gymna | asia | | | | | | |
| | Ceiling - Exposed | 101 | 500 | SF | 5 | \$1,938 | water damage |
| | Ceiling - Exposed | 101 | 6,223 | SF | 6 | \$9,255 | |
| | Doors - Steel Doors incl hw | 101 | 6 | EA | 6 | \$1,806 | |
| | Floor - Wood | 101 | 6,723 | SF | 6 | \$47,396 | damaged floor was in the process of being repaired at the time of the assessment |
| | Lighting - Metal Halide/ High Pressure Sodium | 101 | 24 | EA | 6 | \$3,209 | |
| | Storage/ Closet | 101 | 327 | SF | 5 | \$5,275 | |
| | Storage/ Closet | 101 | 404 | SF | 6 | \$2,929 | |
| | Walls - Concrete Block | 101 | 420 | SF | 5 | \$5,069 | cracking, peeling paint |
| | Walls - Concrete Block | 101 | 3,250 | SF | 6 | \$9,527 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| up Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------|-------------------------------|----------|------|------|----------|---------------------------------------|
| nnasia | | | | | | |
| Walls - Structural Glazed Tile | 101 | 1,857 | SF | 6 | \$5,842 | |
| Walls - Structural Glazed Tile | 101 | 250 | SF | 4 | \$26,348 | damaged block |
| hen | | | | | | |
| Ceiling - Lay-in | 1st Floor | 100 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | 1st Floor | 142 | SF | 7 | \$0 | |
| Ceiling - Splined | 1st Floor | 800 | SF | 6 | \$652 | |
| Doors - Wood Doors inclu hw | 1st Floor | 3 | EΑ | 5 | \$3,522 | |
| Floor - Tile | 1st Floor | 1,042 | SF | 6 | \$2,280 | |
| Lighting - Lay-in | 1st Floor | 2 | EA | 6 | \$238 | |
| Lighting - Pendent/Surface | 1st Floor | 13 | EA | 6 | \$1,611 | |
| Serving Line | 1st Floor | 20 | LF | 7 | \$0 | |
| Storage/ Closet | 1st Floor | 60 | SF | 5 | \$968 | |
| Walls - Concrete Block | 1st Floor | 676 | SF | 6 | \$1,982 | |
| Walls - Structural Glazed Tile | 1st Floor | 235 | SF | 7 | \$0 | |
| ary | | | | | | |
| Casework | 210 Media Center/Library | 336 | LF | 7 | \$0 | |
| Ceiling - Splined | 210 Media Center/Library | 1,096 | SF | 6 | \$893 | |
| Doors - Wood Doors inclu hw | 210 Media Center/Library | 2 | EA | 6 | \$602 | |
| Floor - Carpet | 210 Media Center/Library | 1,096 | SF | 6 | \$2,335 | |
| Lighting - Pendent/Surface | 210 Media Center/Library | 30 | EA | 6 | \$3,717 | |
| Walls - Concrete Block | 210 Media Center/Library | 1,286 | SF | 6 | \$3,770 | |
| ker/Shower Room | | | | | | |
| Accessories | Basement NW Girls Locker Room | 2,214 | SF | 6 | \$8,675 | |
| Benches, ped mounted | Basement NW Girls Locker Room | 16 | LF | 5 | \$4,396 | damaged surface |
| Ceiling - Plaster/ Drywall | Basement NW Girls Locker Room | 2,214 | SF | 4 | \$33,338 | peeling paint, damaged surface, |
| Doors - Steel Doors incl hw | Basement NW Girls Locker Room | 2 | EA | 5 | \$2,348 | damaged door and hardware |
| Floor Drain | Basement NW Girls Locker Room | 9 | EA | 5 | \$18,846 | damaged |
| Floor - Concrete | Basement NW Girls Locker Room | 2,214 | SF | 4 | \$7,219 | damaged finish, standing water |
| Hand Dryer | Basement NW Girls Locker Room | 1 | EA | 5 | \$590 | not functioning |
| Lavatory | Basement NW Girls Locker Room | 2 | EA | 6 | \$639 | - |
| Lighting - Lay-in | Basement NW Girls Locker Room | 29 | EA | 4 | \$9,740 | not functioning, broken, insufficient |
| Partitions | Basement NW Girls Locker Room | 9 | EA | 6 | \$2,672 | - |
| Showers | Basement NW Girls Locker Room | 14 | EA | 4 | \$66,086 | damaged finish and piping |
| Walls - Concrete Block | Basement NW Girls Locker Room | 1,650 | SF | 5 | \$16,941 | |
| Walls - Structural Glazed Tile | Basement NW Girls Locker Room | 775 | SF | 6 | \$2,438 | - |
| | | 4 | EΑ | 5 | \$15,576 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | ltem - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---|-----------------------------------|----------|------|------|----------------|---|
| Locke | r/Shower Room | | | | | | |
| | Accessories | Basement South Boiler Locker Room | 2,115 | SF | 5 | \$18,479 | |
| | Ceiling - Lay-In | Basement South Boiler Locker Room | 2,115 | SF | 4 | \$21,504 | damaged finish, holes, peeling paint, evidence of water damage |
| | Doors - Wood Doors inclu hw | Basement South Boiler Locker Room | 2 | EA | 5 | \$2,348 | delaminating veneer; damaged hardware |
| | Floor Drain | Basement South Boiler Locker Room | 5 | EA | 5 | \$10,470 | |
| | Floor - Concrete Epoxy/ Painted | Basement South Boiler Locker Room | 1,715 | SF | 5 | \$2,943 | |
| | Floor - Tile Ceramic/ Porcelain | Basement South Boiler Locker Room | 400 | SF | 5 | \$6,389 | |
| | Lavatory | Basement South Boiler Locker Room | 1 | EA | 5 | \$3,763 | |
| | Lighting - Pendent/Surface | Basement South Boiler Locker Room | 26 | EA | 4 | \$14,057 | not functioning, broken, insufficient illumination |
| | Showers | Basement South Boiler Locker Room | 12 | EA | 5 | \$32,574 | |
| | Urinals | Basement South Boiler Locker Room | 2 | EA | 4 | \$15,339 | damaged, broken |
| | Walls - Concrete Block | Basement South Boiler Locker Room | 1,724 | SF | 6 | \$5,054 | |
| | Walls - Structural Glazed Tile | Basement South Boiler Locker Room | 664 | SF | 5 | \$33,736 | damaged finish |
| | Water Closet | Basement South Boiler Locker Room | 1 | EA | 4 | \$7,669 | damaged, broken |
| Lunch | & Multipurpose Room | | | | | | |
| | Ceiling - Lay-in | 103 | 3,496 | SF | 6 | \$10,498 | |
| | Doors - Steel Doors incl hw | 103 | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 103 | 5 | EA | 5 | \$5,870 | |
| | Floor - Tile | 103 | 3,496 | SF | 5 | \$15,698 | |
| | Lighting - Metal Halide/ High Pressure Sodium | 103 | 15 | EΑ | 6 | \$2,006 | |
| | Stage | 103 | 619 | SF | 6 | \$3,576 | |
| | Walls - Concrete Block | 103 | 2,225 | SF | 6 | \$6,523 | |
| | Walls - Structural Glazed Tile | 103 | 1,120 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Basement North 'Play Room' | 2,000 | SF | 5 | \$18,333 | Peeling paint at ceiling; Ceiling tiles have been removed, leaving exposed grid at ceiling plane; |
| | Chalk Board | Basement North 'Play Room' | 10 | LF | 4 | \$918 | |
| | Doors - Steel Doors incl hw | Basement North 'Play Room' | 2 | EA | 6 | \$602 | Provide illuminated exit signage and verify that egress pathway is code-compliant |
| | Doors - Wood Doors inclu hw | Basement North 'Play Room' | 1 | EA | 6 | \$301 | Provide illuminated exit lights; Verify that egress pathway is code-compliant |
| | Floor - Concrete Epoxy/ Painted | Basement North 'Play Room' | 2,000 | SF | 5 | \$3,432 | |
| | Lighting - Lay-in | Basement North 'Play Room' | 18 | EA | 6 | \$2,142 | |
| | Walls - Concrete Block | Basement North 'Play Room' | 3,750 | SF | 6 | \$10,993 | |
| | Ceiling - Exposed | Bsmt. South 'Play Room' | 447 | SF | 5 | \$1,227 | |
| | Doors - Wood Doors inclu hw | Bsmt. South 'Play Room' | 2 | EA | 6 | \$602 | delaminating finish and damaged hardware |
| | Floor - Concrete | Bsmt. South 'Play Room' | 447 | SF | 5 | \$767 | unfinished surface |
| | Lighting - Pendent/Surface | Bsmt. South 'Play Room' | 9 | EA | 5 | \$1,643 | not functioning |
| | Serving Line | Bsmt. South 'Play Room' | 6 | LF | 5 | \$3 113 | abandoned function |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|-----------------------------|----------|------|------|----------|---|
| Lunch 8 | & Multipurpose Room | | | | | | |
| | Storage/ Closet | Bsmt. South 'Play Room' | 25 | SF | 5 | \$403 | |
| | Walls - Concrete Block | Bsmt. South 'Play Room' | 1,663 | SF | 6 | \$4,875 | |
| MDF_ID | DF . | | | | | | |
| | Doors - Steel Doors incl hw | Room 203 | 1 | EA | 7 | \$0 | |
| | Finishes | Room 203 | 250 | SF | 5 | \$4,036 | |
| | Ventilation and Cooling | Room 203 | 1 | EA | 7 | \$0 | |
| Mechar | nical/ Service Rooms | | | | | | |
| | Auditorium Plenums | 1st & 2nd Floors | 110 | SF | 6 | \$681 | NW Corner |
| | Janitor's Closet | 1st & 2nd Floors | 39 | SF | 6 | \$279 | south |
| | Janitor's Closet | 1st & 2nd Floors | 41 | SF | 5 | \$661 | north |
| | Janitor's Closet | 1st & 2nd Floors | 42 | SF | 6 | \$301 | 2nd Flr JC @ North Toilet Rooms |
| | Mechanical/ Service Rooms | 1st & 2nd Floors | 64 | SF | 6 | \$459 | 1st Flr Elev. Equip. Rm. |
| | Mechanical/ Service Rooms | 1st & 2nd Floors | 127 | SF | 6 | \$910 | Fan Room above stage |
| | Storage Room | 1st & 2nd Floors | 61 | SF | 5 | \$984 | 2nd floor Stg. Room at Link Corridor |
| | Storage Room | 1st & 2nd Floors | 64 | SF | 6 | \$459 | 2nd Flr Storage @ Elev. Corridor |
| | Storage Room | 1st & 2nd Floors | 35 | SF | 6 | \$251 | at 2nd floor North Toilet Rooms |
| | Storage Room | 1st & 2nd Floors | 360 | SF | 6 | \$2,579 | 2nd Floor Book Room adj. to girls North Toilet Room |
| | Storage Room | 1st & 2nd Floors | 35 | SF | 6 | \$251 | 1st Floor storage @ North Toilet Rooms |
| | Vaults | 1st & 2nd Floors | 66 | SF | 6 | \$473 | vault at admin, used for storage |
| | Boiler Room | Basement | 4,011 | SF | 5 | \$64,699 | Boiler Room and Access Corridor to Boiler Room |
| | Janitor's Closet | Basement | 20 | SF | 5 | \$323 | North Janitor Closet |
| | Mechanical/ Service Rooms | Basement | 571 | SF | 6 | \$4,091 | Mech. Room at E/W 'Passage' Corridor |
| | Storage Room | Basement | 56 | SF | 7 | \$0 | |
| Restroc | om | | | | | | |
| | Accessories | 101A Gym Office Toilet Room | 49 | SF | 6 | \$452 | toilet paper holder, soap dispenser |
| | Ceiling - Plaster/Drywall | 101A Gym Office Toilet Room | 49 | SF | 6 | \$170 | |
| | Doors - Wood Doors inclu hw | 101A Gym Office Toilet Room | 1 | EΑ | 5 | \$1,174 | |
| | Floor - Tile | 101A Gym Office Toilet Room | 29 | SF | 6 | \$63 | |
| | Floor - Tile | 101A Gym Office Toilet Room | 20 | SF | 4 | \$204 | cracked and damaged at tile joints |
| | Lavatory | 101A Gym Office Toilet Room | 1 | EΑ | 6 | \$320 | |
| | Lighting - Pendent/Surface | 101A Gym Office Toilet Room | 1 | EA | 7 | \$0 | |
| | Showers | 101A Gym Office Toilet Room | 1 | EA | 5 | \$1,172 | |
| | Walls - Concrete Block | 101A Gym Office Toilet Room | 175 | SF | 7 | \$0 | |
| | Water Closet | 101A Gym Office Toilet Room | 1 | EA | 6 | \$336 | |
| | Accessories | 109A Unisex Toilet | 27 | SF | 6 | \$249 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|--------------------------|----------|------|------|-------|-----------------------------|
| Restro | • • | | | - | | | |
| | Ceiling - Plaster/Drywall | 109A Unisex Toilet | 27 | SF | 5 | \$247 | water damage |
| | Doors - Wood Doors inclu hw | 109A Unisex Toilet | 1 | EA | 6 | \$301 | • |
| | Floor - Tile | 109A Unisex Toilet | 27 | SF | 6 | \$59 | |
| | Lavatory | 109A Unisex Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 109A Unisex Toilet | 1 | EA | 7 | \$0 | |
| | Partitions | 109A Unisex Toilet | 1 | EA | 5 | \$751 | |
| | Walls - Concrete Block | 109A Unisex Toilet | 139 | SF | 6 | \$407 | |
| | Water Closet | 109A Unisex Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 119A Unisex | 80 | SF | 6 | \$738 | |
| | Ceiling - Plaster/Drywall | 119A Unisex | 80 | SF | 6 | \$277 | |
| | Doors - Wood Doors inclu hw | 119A Unisex | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 119A Unisex | 80 | SF | 6 | \$175 | vct |
| | Lavatory | 119A Unisex | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 119A Unisex | 1 | EA | 7 | \$0 | |
| | Partitions | 119A Unisex | 2 | EA | 6 | \$594 | rusty |
| | Walls - Concrete Block | 119A Unisex | 339 | SF | 6 | \$994 | |
| | Water Closet | 119A Unisex | 2 | EA | 6 | \$672 | |
| | Accessories | 120A | 30 | SF | 6 | \$277 | mirror, toilet paper holder |
| | Ceiling - Plaster/Drywall | 120A | 30 | SF | 6 | \$104 | |
| | Doors - Hardware | 120A | 1 | EA | 6 | \$212 | |
| | Floor - Tile | 120A | 30 | SF | 6 | \$66 | vct |
| | Lavatory | 120A | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 120A | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 120A | 176 | SF | 6 | \$516 | wall crack |
| | Water Closet | 120A | 1 | EA | 6 | \$336 | |
| | Accessories | 122A | 43 | SF | 6 | \$397 | |
| | Ceiling - Plaster/Drywall | 122A | 43 | SF | 6 | \$149 | peeling paint |
| | Doors - Steel Doors incl hw | 122A | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 122A | 43 | SF | 6 | \$94 | vct |
| | Lavatory | 122A | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 122A | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 122A | 219 | SF | 6 | \$642 | |
| | Water Closet | 122A | 1 | EA | 6 | \$336 | |
| | Accessories | 1st Flr - Kitchen Unisex | 62 | SF | 6 | \$572 | |
| | Ceiling - Lay-in | 1st Flr - Kitchen Unisex | 62 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Flr - Kitchen Unisex | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Flr - Kitchen Unisex | 62 | SF | 5 | \$278 | cracked and worn |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Laydroy | | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|---|---------------------------------|--------------------------------|----------|------|------|---------|----------------------|
| Lesterby | - | • • | | | | , | - 5.50 | |
| Lighting - Pendent/Surface 1st Fir - Kitchen Unisex 2 | | | 1st Flr - Kitchen Unisex | 1 | EA | 6 | \$320 | |
| Walls - Concrete Block 1st Fir - Kitchen Unisex 264 SF 6 \$774 Water Closet 1st Fir - Kitchen Unisex 1 EA 5 \$1,344 Accessories 1st Fir Admin. Toilet Room 38 SF 6 \$350 Ceiling - Lay-in 1st Fir Admin. Toilet Room 38 SF 7 \$0 Doors - Wood Doors inclu hw 1st Fir Admin. Toilet Room 38 SF 6 \$331 Floor - Tile 1st Fir Admin. Toilet Room 38 SF 6 \$32 Laxetory 1st Fir Admin. Toilet Room 1 EA 6 \$32 Lighting - Pendent/Surface 1st Fir Admin. Toilet Room 1 EA 6 \$297 Walls - Concrete Block 1st Fir Admin. Toilet Room 1 EA 6 \$297 Waller Closet 1st Fir Admin. Toilet Room 1 EA 6 \$336 Accessories 1st Fir Admin. Toilet Room 1 EA 6 \$336 Valler Closet 1st Fir Admin. Toilet Room < | | | | • | | | | missing cover |
| Water Closet | | | 1st Flr - Kitchen Unisex | | SF | 6 | | 3 |
| Accessories 1st Fir Admin. Toilet Room 38 SF 6 S350 Calling - Lay-in 1st Fir Admin. Toilet Room 1 EA 6 S301 Floor - Tile 1st Fir Admin. Toilet Room 1 EA 6 S301 Floor - Tile 1st Fir Admin. Toilet Room 38 SF 6 S83 Laxatory 1st Fir Admin. Toilet Room 38 SF 6 S83 Laxatory 1st Fir Admin. Toilet Room 1 EA 6 S320 Lighting - Pendent/Surface 1st Fir Admin. Toilet Room 1 EA 6 S320 Lighting - Pendent/Surface 1st Fir Admin. Toilet Room 1 EA 7 S0 Partitions 1st Fir Admin. Toilet Room 1 EA 6 S327 Walls - Concrete Block 1st Fir Admin. Toilet Room 1 EA 6 S326 Walls - Concrete Block 1st Fir Admin. Toilet Room 1 EA 6 S326 Accessories 1st Fir Boys (near main entry) 237 SF 7 S0 Ceiling - Lay-in 1st Fir Boys (near main entry) 50 SF 6 S150 Ceiling - Plaster/Drywall 1st Fir Boys (near main entry) 150 SF 6 S150 Ceiling - Lay-in 1st Fir Boys (near main entry) 1 EA 6 S10,099 original to building Floor - Tile Ceramic/Porcelain 1st Fir Boys (near main entry) 237 SF 7 S0 Laxatory 1st Fir Boys (near main entry) 1 EA 6 S10,099 original to building Floor - Tile Ceramic/Porcelain 1st Fir Boys (near main entry) 227 SF 6 S502 Laxatory 1st Fir Boys (near main entry) 1 EA 6 S330 Laxatory 1st Fir Boys (near main entry) 1 EA 6 S330 Laxatory 1st Fir Boys (near main entry) 1 EA 6 S330 Laxatory 1st Fir Boys (near main entry) 1 EA 6 S330 Laxatory 1st Fir Boys (near main entry) 1 EA 6 S330 Laxatory 1st Fir Boys (near main entry) 1 EA 6 S330 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 2 EA 7 S0 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 2 EA 6 S504 Walls - Concrete Block 1st Fir Boys (near main entry) 2 EA 6 S504 Walls - Concrete Block 1st Fir Boys (near main entry) 2 EA 6 S504 Walls - Concrete Block 1st Fir Boys (near main entry) 2 EA 6 S504 Walls - Concrete Block 1st Fir Boys (near main entry) 2 EA 6 S504 Walls - Concrete Block 1st Fir Boys (near main entry) 2 EA 6 S504 Walls - Concrete Block 1st Fir Boys South 17 SF 7 S0 Ceiling - Plaster/Drywall 1st Fir Boys South 17 SF 7 S0 Ceiling - Plaster/Drywall 1st Fir Boys South 17 | | | | | _ | | | |
| Ceiling - Lay-in 1st Fir Admin. Toilet Room 1 | | Accessories | 1st Flr Admin. Toilet Room | 38 | SF | | | |
| Doors - Wood Doors inclut hw | | | | | | | | |
| Lavatory 1st Fir Admin. Toilet Room 1 EA 6 \$320 Lighting - Pendent/Surface 1st Fir Admin. Toilet Room 1 EA 7 \$0 Partitions 1st Fir Admin. Toilet Room 1 EA 6 \$297 Walls - Concrete Block 1st Fir Admin. Toilet Room 11 EA 6 \$297 Walls - Concrete Block 1st Fir Admin. Toilet Room 171 SF 7 \$0 Water Closet 1st Fir Admin. Toilet Room 171 SF 7 \$0 Water Closet 1st Fir Boys (near main entry) 237 SF 7 \$0 Ceiling - Lay-in 1st Fir Boys (near main entry) 237 SF 6 \$150 Ceiling - Plaster/Dywall 1st Fir Boys (near main entry) 187 SF 6 \$4150 Ceiling - Plaster/Dywall 1st Fir Boys (near main entry) 187 SF 6 \$4150 Floor Train 1st Fir Boys (near main entry) 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Fir Boys (near main entry) 27 SF 6 \$502 Lavatory 1st Fir Boys (near main entry) 1 EA 7 \$0 Lavatory 1st Fir Boys (near main entry) 1 EA 7 \$0 Lavatory 1st Fir Boys (near main entry) 2 EA 7 \$0 Lavatory 1st Fir Boys (near main entry) 2 EA 7 \$0 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 48 SF 6 \$62 Accessories 1st Fir Boys (near main entry) 48 SF 6 \$1,409 Urinals 1st Fir Boys (near main entry) 48 SF 7 \$0 Ceiling - Plaster/Dywall 1st Fir Boys (near main entry) 48 SF 7 \$0 Ceiling - Plaster/Dywall 1st Fir Boys (near main entry) 48 SF 7 \$0 Ceiling - Plaster/Dywall 1st Fir Boys South 171 SF 7 \$0 Ceiling - Plaster/Dywall 1st Fir Boys South 171 SF 7 \$0 Ceiling - Plaster/Dywall 1st Fir Boys South 171 SF 6 \$602 Lavatory 1st Fir Boys South 2 EA 6 \$602 Lavatory 1st Fir Boys South 2 EA 7 \$0 Urinals 1st Fir Boys South 2 EA 7 \$0 | | | 1st Flr Admin. Toilet Room | 1 | EA | 6 | | |
| Lavatory 1st Fir Admin. Toilet Room 1 EA 6 \$320 Lighting - Pendent/Surface 1st Fir Admin. Toilet Room 1 EA 7 \$0 Partitions 1st Fir Admin. Toilet Room 1 EA 7 \$0 Walls - Concrete Block 1st Fir Admin. Toilet Room 11 EA 6 \$3297 Walls - Concrete Block 1st Fir Admin. Toilet Room 171 SF 7 \$0 Water Closet 1st Fir Admin. Toilet Room 171 SF 7 \$0 Water Closet 1st Fir Boys (near main entry) 237 SF 7 \$0 Ceiling - Lay-in 1st Fir Boys (near main entry) 237 SF 6 \$150 Ceiling - Plaster/Dywall 1st Fir Boys (near main entry) 187 SF 6 \$647 Ficor Drain 1st Fir Boys (near main entry) 187 SF 6 \$547 Ficor Trile Ceramic/ Porcelain 1st Fir Boys (near main entry) 1 EA 6 \$11,059 Ficor - Title Ceramic/ Porcelain 1st Fir Boys (near main entry) 27 SF 6 \$502 Lavatory 1st Fir Boys (near main entry) 1 EA 7 \$0 Lavatory 1st Fir Boys (near main entry) 1 EA 7 \$0 Lavatory 1st Fir Boys (near main entry) 2 EA 7 \$0 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 48 SF 6 \$1,409 Walls - Structural Clazed Tile 1st Fir Boys (near main entry) 48 SF 6 \$1,409 Urinals 1st Fir Boys (near main entry) 48 SF 7 \$0 Ceiling - Plaster/Dywall 1st Fir Boys (near main entry) 48 SF 7 \$0 Ceiling - Plaster/Dywall 1st Fir Boys (near main entry) 48 SF 7 \$0 Ceiling - Plaster/Dywall 1st Fir Boys South 171 SF 7 \$0 Ceiling - Plaster/Dywall 1st Fir Boys South 171 SF 7 \$0 Ceiling - Plaster/Dywall 1st Fir Boys South 171 SF 7 \$0 Urinals 1st Fir Boys South 2 EA 7 \$0 Urinals 1st Fir Boys South 2 EA 7 \$0 Urinals 1st Fir Boys South 2 EA 7 \$0 | | Floor - Tile | 1st Flr Admin. Toilet Room | 38 | SF | 6 | \$83 | |
| Lighting - Pendent/Surface | | Lavatory | 1st Flr Admin. Toilet Room | 1 | | 6 | | |
| Partitions | | Lighting - Pendent/Surface | 1st Flr Admin. Toilet Room | 1 | EA | 7 | | |
| Water Closet 1st Fir Admin. Toilet Room 1 EA 6 \$336 Accessories 1st Fir Boys (near main entry) 237 SF 7 \$0 Ceiling - Lay-in 1st Fir Boys (near main entry) 50 SF 6 \$150 Ceiling - Plaster/Dywall 1st Fir Boys (near main entry) 187 SF 6 \$647 Floor Drain 1st Fir Boys (near main entry) 1 EA 6 \$1,059 original to building Floor - Tile Ceramic/ Porcelain 1st Fir Boys (near main entry) 27 SF 6 \$502 Hand Dryer 1st Fir Boys (near main entry) 1 EA 6 \$320 Lavatory 1st Fir Boys (near main entry) 1 EA 7 \$0 Lavatory 1st Fir Boys (near main entry) 1 EA 7 \$0 Lavatory 1st Fir Boys (near main entry) 2 EA 7 \$0 Lavatory 1st Fir Boys (near main entry) 2 EA 7 \$0 Urinals 1st | | | 1st Flr Admin. Toilet Room | 1 | EA | 6 | | |
| Accessories 1st Fir Boys (near main entry) 237 SF 7 \$0 Ceiling - Lay-in 1st Fir Boys (near main entry) 50 SF 6 \$150 Ceiling - Plaster/Drywall 1st Fir Boys (near main entry) 187 SF 6 \$547 Floor Drain 1st Fir Boys (near main entry) 1 EA 6 \$1,059 original to building Floor - Tile Ceramic/ Porcelain 1st Fir Boys (near main entry) 27 SF 6 \$502 Hand Dryer 1st Fir Boys (near main entry) 1 EA 6 \$320 Lavatory 1st Fir Boys (near main entry) 1 EA 6 \$320 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 1 EA 7 \$0 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 48 SF 7 \$0 | | Walls - Concrete Block | 1st Flr Admin. Toilet Room | 171 | SF | 7 | \$0 | |
| Ceiling - Lay-in 1st Fir Boys (near main entry) 50 SF 6 \$150 Ceiling - Plaster/Drywall 1st Fir Boys (near main entry) 187 SF 6 \$647 Floor Drain 1st Fir Boys (near main entry) 1 EA 6 \$1,059 original to building Floor - Tile Ceramic/ Porcelain 1st Fir Boys (near main entry) 237 SF 6 \$502 Hand Dryer 1st Fir Boys (near main entry) 1 EA 6 \$502 Lavatory 1st Fir Boys (near main entry) 1 EA 6 \$320 Layatory 1st Fir Boys (near main entry) 1 EA 7 \$0 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 2 EA 7 \$0 Partitions 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$2,016 Walls - Structural Glazed Tile 1st Fir Boys (near main entry) 24 8 6 \$1,409 | | Water Closet | 1st Flr Admin. Toilet Room | 1 | EA | 6 | \$336 | |
| Ceiling - Lay-in 1st Fir Boys (near main entry) 50 SF 6 \$150 Ceiling - Plaster/Drywall 1st Fir Boys (near main entry) 187 SF 6 \$647 Floor Drain 1st Fir Boys (near main entry) 1 EA 6 \$1,059 original to building Floor - Tile Ceramic/ Porcelain 1st Fir Boys (near main entry) 237 SF 6 \$502 Hand Dryer 1st Fir Boys (near main entry) 1 EA 6 \$320 Lavatory 1st Fir Boys (near main entry) 1 EA 6 \$320 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 1 EA 7 \$0 Partitions 1st Fir Boys (near main entry) 2 EA 7 \$0 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$504 Walls - Concrete Block 1st Fir Boys (near main entry) 24 SF 7 \$0 Walls - Structural Glazed Tile 1st Fir Boys South 171 SF 7 \$0 < | | Accessories | 1st Flr Boys (near main entry) | 237 | SF | 7 | | |
| Ceiling - Plaster/Drywall 1st Fir Boys (near main entry) 187 SF 6 \$647 Floor Drain 1st Fir Boys (near main entry) 1 EA 6 \$1,059 original to building Floor - Tile Ceramic/ Porcelain 1st Fir Boys (near main entry) 2 EA 7 \$0 Lavatory 1st Fir Boys (near main entry) 1 EA 6 \$320 Lavatory 1st Fir Boys (near main entry) 1 EA 7 \$0 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 1 EA 7 \$0 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 2 EA 7 \$0 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 48 SF 6 \$1,409 Walls - Structural Glazed Tile 1st Fir Boys (near main entry) 2 EA 6 \$672 <td></td> <td>Ceiling - Lay-in</td> <td></td> <td>50</td> <td>SF</td> <td>6</td> <td>\$150</td> <td></td> | | Ceiling - Lay-in | | 50 | SF | 6 | \$150 | |
| Floor - Tile Ceramic/ Porcelain 1st Fir Boys (near main entry) 237 SF 6 \$502 Hand Dryer 1st Fir Boys (near main entry) 2 EA 7 \$0 Lavatory 1st Fir Boys (near main entry) 1 EA 6 \$320 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 1 EA 7 \$0 Partitions 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 6 EA 6 \$2,016 Walls - Concrete Block 1st Fir Boys (near main entry) 224 SF 7 \$0 Walls - Structural Glazed Tile 1st Fir Boys (near main entry) 448 SF 6 \$1,409 Water Closet 1st Fir Boys (near main entry) 2 EA 6 \$672 Accessories 1st Fir Boys South 171 SF 7 \$0 Ceiling - Plaster/Drywall 1st Fir Boys South 171 SF 7 \$0 Doors - Steel Doors incl hw | | | | 187 | SF | 6 | \$647 | |
| Hand Dryer | | | | 1 | EA | 6 | \$1,059 | original to building |
| Lavatory 1st FIr Boys (near main entry) 1 EA 6 \$320 Lavatory 1st FIr Boys (near main entry) 1 EA 7 \$0 Lighting - Pendent/Surface 1st FIr Boys (near main entry) 2 EA 7 \$0 Partitions 1st FIr Boys (near main entry) 2 EA 6 \$594 Urinals 1st FIr Boys (near main entry) 6 EA 6 \$2,016 Walls - Concrete Block 1st FIr Boys (near main entry) 224 SF 7 \$0 Walls - Structural Glazed Tile 1st FIr Boys (near main entry) 448 SF 6 \$1,409 Water Closet 1st FIr Boys (near main entry) 2 EA 6 \$672 Accessories 1st FIr Boys (near main entry) 2 EA 6 \$672 Accessories 1st FIr Boys South 171 SF 7 \$0 Ceiling - Plaster/Drywall 1st FIr Boys South 171 SF 7 \$0 Doors - Steel Doors incl hw 1st FIr Boys South 1 EA 6 \$1,059 Floor - Tile C | | Floor - Tile Ceramic/ Porcelain | 1st Flr Boys (near main entry) | 237 | SF | 6 | \$502 | |
| Lavatory 1st Fir Boys (near main entry) 1 EA 7 \$0 Lighting - Pendent/Surface 1st Fir Boys (near main entry) 2 EA 7 \$0 Partitions 1st Fir Boys (near main entry) 2 EA 6 \$594 Urinals 1st Fir Boys (near main entry) 6 EA 6 \$2,016 Walls - Concrete Block 1st Fir Boys (near main entry) 224 SF 7 \$0 Walls - Structural Glazed Tile 1st Fir Boys (near main entry) 448 SF 6 \$1,009 Water Closet 1st Fir Boys South 171 SF 7 \$0 Accessories 1st Fir Boys South 171 SF 7 \$0 Ceiling - Plaster/Drywall 1st Fir Boys South 171 SF 7 \$0 Doors - Steel Doors incl hw 1st Fir Boys South 1 EA 6 \$602 rusted Floor - Tile Ceramic/ Porcelain 1st Fir Boys South 1 EA 6 \$363 \$60 \$60 \$60 | | Hand Dryer | 1st Flr Boys (near main entry) | 2 | EA | 7 | \$0 | |
| Lighting - Pendent/Surface 1st Flr Boys (near main entry) 2 EA 7 \$0 Partitions 1st Flr Boys (near main entry) 2 EA 6 \$594 Urinals 1st Flr Boys (near main entry) 6 EA 6 \$2,016 Walls - Concrete Block 1st Flr Boys (near main entry) 224 SF 7 \$0 Walls - Structural Glazed Tile 1st Flr Boys (near main entry) 448 SF 6 \$1,409 Water Closet 1st Flr Boys (near main entry) 2 EA 6 \$672 Accessories 1st Flr Boys South 171 SF 7 \$0 Ceiling - Plaster/Drywall 1st Flr Boys South 171 SF 7 \$0 Doors - Steel Doors incl hw 1st Flr Boys South 1 EA 6 \$602 rusted Floor - Tile Ceramic/ Porcelain 1st Flr Boys South 1 EA 6 \$162 Lavatory 1st Flr Boys South 2 EA 6 \$639 Lighting - Pendent/Surface 1st Flr Boys South 2 EA 7 \$0 | | Lavatory | 1st Flr Boys (near main entry) | 1 | EA | 6 | \$320 | |
| Partitions 1st Flr Boys (near main entry) 2 EA 6 \$594 Urinals 1st Flr Boys (near main entry) 6 EA 6 \$2,016 Walls - Concrete Block 1st Flr Boys (near main entry) 224 SF 7 \$0 Walls - Structural Glazed Tile 1st Flr Boys (near main entry) 448 SF 6 \$1,409 Water Closet 1st Flr Boys (near main entry) 2 EA 6 \$672 Accessories 1st Flr Boys South 171 SF 7 \$0 Ceiling - Plaster/Drywall 1st Flr Boys South 171 SF 7 \$0 Doors - Steel Doors incl hw 1st Flr Boys South 2 EA 6 \$602 rusted Floor Drain 1st Flr Boys South 1 EA 6 \$1,059 \$1 Floor - Tile Ceramic/ Porcelain 1st Flr Boys South 171 SF 6 \$362 \$362 Lavatory 1st Flr Boys South 2 EA 6 \$639 \$1 | | Lavatory | 1st Flr Boys (near main entry) | 1 | EA | 7 | \$0 | |
| Urinals 1st Flr Boys (near main entry) 6 EA 6 \$2,016 Walls - Concrete Block 1st Flr Boys (near main entry) 224 SF 7 \$0 Walls - Structural Glazed Tile 1st Flr Boys (near main entry) 448 SF 6 \$1,409 Water Closet 1st Flr Boys (near main entry) 2 EA 6 \$672 Accessories 1st Flr Boys South 171 SF 7 \$0 Ceiling - Plaster/Drywall 1st Flr Boys South 171 SF 7 \$0 Doors - Steel Doors incl hw 1st Flr Boys South 2 EA 6 \$602 rusted Floor Drain 1st Flr Boys South 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Flr Boys South 171 SF 6 \$362 Lavatory 1st Flr Boys South 2 EA 6 \$639 Lighting - Pendent/Surface 1st Flr Boys South 2 EA 7 \$0 Urinals 1st Flr Boys South | | Lighting - Pendent/Surface | 1st Flr Boys (near main entry) | 2 | EA | 7 | \$0 | |
| Walls - Concrete Block 1st Flr Boys (near main entry) 224 SF 7 \$0 Walls - Structural Glazed Tile 1st Flr Boys (near main entry) 448 SF 6 \$1,409 Water Closet 1st Flr Boys (near main entry) 2 EA 6 \$672 Accessories 1st Flr Boys South 171 SF 7 \$0 Ceiling - Plaster/Drywall 1st Flr Boys South 171 SF 7 \$0 Doors - Steel Doors incl hw 1st Flr Boys South 2 EA 6 \$602 rusted Floor Drain 1st Flr Boys South 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Flr Boys South 171 SF 6 \$362 Lavatory 1st Flr Boys South 2 EA 6 \$639 Lighting - Pendent/Surface 1st Flr Boys South 2 EA 7 \$0 Partitions 1st Flr Boys South 2 EA 7 \$0 Urinals 1st Flr Boys South 4 EA 6 \$1,344 | | Partitions | 1st Flr Boys (near main entry) | 2 | EA | 6 | \$594 | |
| Walls - Structural Glazed Tile 1st FIr Boys (near main entry) 448 SF 6 \$1,409 Water Closet 1st FIr Boys (near main entry) 2 EA 6 \$672 Accessories 1st FIr Boys South 171 SF 7 \$0 Ceiling - Plaster/Drywall 1st FIr Boys South 171 SF 7 \$0 Doors - Steel Doors incl hw 1st FIr Boys South 2 EA 6 \$602 rusted Floor Drain 1st FIr Boys South 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st FIr Boys South 171 SF 6 \$362 Lavatory 1st FIr Boys South 2 EA 6 \$639 Lighting - Pendent/Surface 1st FIr Boys South 2 EA 7 \$0 Partitions 1st FIr Boys South 2 EA 7 \$0 Urinals 1st FIr Boys South 4 EA 6 \$1,344 | | Urinals | 1st Flr Boys (near main entry) | 6 | EA | 6 | \$2,016 | |
| Water Closet 1st FIr Boys (near main entry) 2 EA 6 \$672 Accessories 1st FIr Boys South 171 SF 7 \$0 Ceiling - Plaster/Drywall 1st FIr Boys South 171 SF 7 \$0 Doors - Steel Doors incl hw 1st FIr Boys South 2 EA 6 \$602 rusted Floor Drain 1st FIr Boys South 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st FIr Boys South 171 SF 6 \$362 Lavatory 1st FIr Boys South 2 EA 6 \$639 Lighting - Pendent/Surface 1st FIr Boys South 2 EA 7 \$0 Partitions 1st FIr Boys South 2 EA 7 \$0 Urinals 1st FIr Boys South 4 EA 6 \$1,344 | | Walls - Concrete Block | 1st Flr Boys (near main entry) | 224 | SF | 7 | \$0 | |
| Accessories 1st FIr Boys South 171 SF 7 \$0 Ceiling - Plaster/Drywall 1st FIr Boys South 171 SF 7 \$0 Doors - Steel Doors incl hw 1st FIr Boys South 2 EA 6 \$602 rusted Floor Drain 1st FIr Boys South 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st FIr Boys South 171 SF 6 \$362 Lavatory 1st FIr Boys South 2 EA 6 \$639 Lighting - Pendent/Surface 1st FIr Boys South 2 EA 7 \$0 Partitions 1st FIr Boys South 2 EA 7 \$0 Urinals 1st FIr Boys South 4 EA 6 \$1,344 | | Walls - Structural Glazed Tile | 1st Flr Boys (near main entry) | 448 | SF | 6 | \$1,409 | |
| Ceiling - Plaster/Drywall1st Flr Boys South171SF7\$0Doors - Steel Doors incl hw1st Flr Boys South2EA6\$602rustedFloor Drain1st Flr Boys South1EA6\$1,059Floor - Tile Ceramic/ Porcelain1st Flr Boys South171SF6\$362Lavatory1st Flr Boys South2EA6\$639Lighting - Pendent/Surface1st Flr Boys South2EA7\$0Partitions1st Flr Boys South2EA7\$0Urinals1st Flr Boys South4EA6\$1,344 | | Water Closet | 1st Flr Boys (near main entry) | 2 | EA | 6 | \$672 | |
| Doors - Steel Doors incl hw 1st Flr Boys South 2 EA 6 \$602 rusted Floor Drain 1st Flr Boys South 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Flr Boys South 171 SF 6 \$362 Lavatory 1st Flr Boys South 2 EA 6 \$639 Lighting - Pendent/Surface 1st Flr Boys South 2 EA 7 \$0 Partitions 1st Flr Boys South 2 EA 7 \$0 Urinals | | Accessories | 1st Flr Boys South | 171 | SF | 7 | \$0 | |
| Floor Drain 1st Flr Boys South 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Flr Boys South 171 SF 6 \$362 Lavatory 1st Flr Boys South 2 EA 6 \$639 Lighting - Pendent/Surface 1st Flr Boys South 2 EA 7 \$0 Partitions 1st Flr Boys South 2 EA 7 \$0 Urinals 1st Flr Boys South 4 EA 6 \$1,344 | | Ceiling - Plaster/Drywall | 1st Flr Boys South | 171 | SF | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain 1st Flr Boys South 171 SF 6 \$362 Lavatory 1st Flr Boys South 2 EA 6 \$639 Lighting - Pendent/Surface 1st Flr Boys South 2 EA 7 \$0 Partitions 1st Flr Boys South 2 EA 7 \$0 Urinals 1st Flr Boys South 4 EA 6 \$1,344 | | Doors - Steel Doors incl hw | 1st Flr Boys South | 2 | EA | 6 | \$602 | rusted |
| Lavatory1st FIr Boys South2EA6\$639Lighting - Pendent/Surface1st FIr Boys South2EA7\$0Partitions1st FIr Boys South2EA7\$0Urinals1st FIr Boys South4EA6\$1,344 | | Floor Drain | 1st Flr Boys South | 1 | EA | 6 | \$1,059 | |
| Lighting - Pendent/Surface 1st Flr Boys South 2 EA 7 \$0 Partitions 1st Flr Boys South 2 EA 7 \$0 Urinals 1st Flr Boys South 4 EA 6 \$1,344 | | Floor - Tile Ceramic/ Porcelain | 1st FIr Boys South | 171 | SF | 6 | \$362 | |
| Partitions 1st Flr Boys South 2 EA 7 \$0 Urinals 1st Flr Boys South 4 EA 6 \$1,344 | | Lavatory | 1st Flr Boys South | 2 | EA | 6 | \$639 | |
| Urinals 1st Flr Boys South 4 EA 6 \$1,344 | | Lighting - Pendent/Surface | 1st Flr Boys South | 2 | EA | 7 | \$0 | |
| | | Partitions | 1st Flr Boys South | 2 | EA | 7 | \$0 | |
| Walls - Concrete Block 1st Flr Boys South 162 SF 7 \$0 | | Urinals | 1st Flr Boys South | 4 | EA | 6 | \$1,344 | |
| | | Walls - Concrete Block | 1st Flr Boys South | 162 | SF | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|---|----------|------|------|---------|--|
| Restroc | om | | | | | | |
| | Walls - Structural Glazed Tile | 1st Flr Boys South | 336 | SF | 7 | \$0 | |
| | Water Closet | 1st Flr Boys South | 2 | EA | 6 | \$672 | |
| | Accessories | 1st Flr Girls (near main entry) | 254 | SF | 6 | \$2,343 | |
| | Ceiling - Lay-in | 1st Flr Girls (near main entry) | 54 | SF | 6 | \$162 | |
| | Ceiling - Plaster/Drywall | 1st Flr Girls (near main entry) | 200 | SF | 6 | \$692 | |
| | Floor Drain | 1st Flr Girls (near main entry) | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 1st Flr Girls (near main entry) | 254 | SF | 5 | \$1,141 | |
| | Hand Dryer | 1st Flr Girls (near main entry) | 2 | EA | 7 | \$0 | |
| | Lavatory | 1st Flr Girls (near main entry) | 1 | EA | 6 | \$320 | |
| | Lavatory | 1st Flr Girls (near main entry) | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Flr Girls (near main entry) | 2 | EA | 7 | \$0 | |
| | Partitions | 1st Flr Girls (near main entry) | 7 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | 1st Flr Girls (near main entry) | 231 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 1st Flr Girls (near main entry) | 462 | SF | 6 | \$1,453 | |
| | Water Closet | 1st Flr Girls (near main entry) | 5 | EA | 6 | \$1,680 | |
| | Accessories | 1st Flr Girls South | 171 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Flr Girls South | 171 | SF | 6 | \$592 | |
| | Doors - Wood Doors inclu hw | 1st Flr Girls South | 4 | EA | 6 | \$1,204 | |
| | Floor Drain | 1st Flr Girls South | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Flr Girls South | 171 | SF | 7 | \$0 | |
| | Lavatory | 1st Flr Girls South | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Flr Girls South | 2 | EA | 7 | \$0 | |
| | Partitions | 1st Flr Girls South | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Flr Girls South | 162 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 1st Flr Girls South | 336 | SF | 7 | \$0 | |
| | Water Closet | 1st Flr Girls South | 6 | EA | 6 | \$2,016 | |
| | Accessories | 1st Flr North Corridor Mens (used as Storage) | 145 | SF | 6 | \$1,337 | used as storage, paper towel dispenser, soap dispenser |
| | Ceiling - Plaster/Drywall | 1st Flr North Corridor Mens (used as Storage) | 95 | SF | 6 | \$329 | |
| | Ceiling - Plaster/Drywall | 1st Flr North Corridor Mens (used as Storage) | 50 | SF | 4 | \$879 | water damage |
| | Doors - Wood Doors inclu hw | 1st Flr North Corridor Mens (used as Storage) | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Flr North Corridor Mens (used as Storage) | 145 | SF | 6 | \$307 | |
| | Lighting - Pendent/Surface | 1st Flr North Corridor Mens (used as Storage) | 3 | EA | 6 | \$372 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--------------------------------|---|----------|------|------|---------|--------------------------------|
| Restro | om | | | | | | |
| | Walls - Concrete Block | 1st Flr North Corridor Mens (used as Storage) | 60 | SF | 6 | \$176 | |
| | Walls - Structural Glazed Tile | 1st Flr North Corridor Mens (used as Storage) | 332 | SF | 6 | \$1,044 | |
| | Accessories | 1st Flr North Social Workers Toilet | 18 | SF | 6 | \$166 | |
| | Ceiling - Plaster/Drywall | 1st Flr North Social Workers Toilet | 18 | SF | 6 | \$62 | |
| | Doors - Wood Doors inclu hw | 1st Flr North Social Workers Toilet | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Flr North Social Workers Toilet | 18 | SF | 5 | \$81 | cracked throughout |
| | Lavatory | 1st Flr North Social Workers Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | 1st Flr North Social Workers Toilet | 1 | EA | 5 | \$169 | not functioning |
| | Showers | 1st Flr North Social Workers Toilet | 1 | EA | 5 | \$1,172 | being used as a storage closet |
| | Walls - Concrete Block | 1st Flr North Social Workers Toilet | 177 | SF | 6 | \$519 | |
| | Water Closet | 1st Flr North Social Workers Toilet | 1 | EΑ | 6 | \$336 | |
| | Accessories | 1st Flr North Unisex 105 | 279 | SF | 6 | \$2,573 | |
| | Ceiling - Plaster/Drywall | 1st Flr North Unisex 105 | 279 | SF | 6 | \$966 | |
| | Doors - Wood Doors inclu hw | 1st Flr North Unisex 105 | 3 | EA | 6 | \$903 | |
| | Floor - Tile | 1st Flr North Unisex 105 | 279 | SF | 5 | \$1,253 | |
| | Lavatory | 1st Flr North Unisex 105 | 2 | EΑ | 6 | \$639 | |
| | Lighting - Lay-in | 1st Flr North Unisex 105 | 5 | EΑ | 6 | \$595 | |
| | Lighting - Wall Mounted | 1st Flr North Unisex 105 | 2 | EΑ | 5 | \$339 | Not functioning |
| | Partitions | 1st Flr North Unisex 105 | 2 | EΑ | 6 | \$594 | |
| | Student Lockers | 1st Flr North Unisex 105 | 15 | EΑ | 6 | \$0 | |
| | Walls - Concrete Block | 1st Flr North Unisex 105 | 272 | SF | 6 | \$797 | |
| | Walls - Structural Glazed Tile | 1st Flr North Unisex 105 | 423 | SF | 6 | \$1,331 | |
| | Water Closet | 1st Flr North Unisex 105 | 2 | EΑ | 6 | \$672 | |
| | Accessories | 1st Flr Single User Boys South | 32 | SF | 6 | \$295 | |
| | Ceiling - Lay-in | 1st Flr Single User Boys South | 32 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st Flr Single User Boys South | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile | 1st Flr Single User Boys South | 32 | SF | 6 | \$70 | |
| | Lavatory | 1st Flr Single User Boys South | 1 | EΑ | 6 | \$320 | |
| | Lighting - Pendent/Surface | 1st Flr Single User Boys South | 1 | EA | 7 | \$0 | |
| | Partitions | 1st Flr Single User Boys South | 1 | EΑ | 6 | \$297 | |
| | Walls - Concrete Block | 1st Flr Single User Boys South | 155 | SF | 6 | \$454 | |
| | Water Closet | 1st Flr Single User Boys South | 1 | EA | 6 | \$336 | |
| | Accessories | 201A Unisex Toilet | 30 | SF | 6 | \$277 | |
| | Ceiling - Plaster/Drywall | 201A Unisex Toilet | 30 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 201A Unisex Toilet | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 201A Unisex Toilet | 20 | SF | 6 | \$44 | |
| | 1 1221 1112 | | | ٠. | • | Ψ''' | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|---|----------|------|------|----------|--|
| Restro | om | | | | | | |
| | Floor - Tile | 201A Unisex Toilet | 10 | SF | 5 | \$49 | cracked and warped |
| | Lavatory | 201A Unisex Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 201A Unisex Toilet | 1 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 201A Unisex Toilet | 1 | EA | 6 | \$124 | missing fixtures (bulbs) |
| | Partitions | 201A Unisex Toilet | 1 | EA | 6 | \$297 | rusted |
| | Walls - Concrete Block | 201A Unisex Toilet | 176 | SF | 6 | \$516 | |
| | Water Closet | 201A Unisex Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 208A Unisex @ Teachers' Lounge | 35 | SF | 6 | \$323 | |
| | Ceiling - Plaster/Drywall | 208A Unisex @ Teachers' Lounge | 35 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 208A Unisex @ Teachers' Lounge | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 208A Unisex @ Teachers' Lounge | 15 | SF | 4 | \$153 | damaged/missing tiles |
| | Floor - Tile | 208A Unisex @ Teachers' Lounge | 20 | SF | 6 | \$44 | |
| | Lavatory | 208A Unisex @ Teachers' Lounge | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 208A Unisex @ Teachers' Lounge | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 208A Unisex @ Teachers' Lounge | 177 | SF | 7 | \$0 | |
| | Water Closet | 208A Unisex @ Teachers' Lounge | 1 | EA | 6 | \$336 | |
| | Accessories | 2nd Flr Boys (near central stair tower) | 237 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd FIr Boys (near central stair tower) | 237 | SF | 6 | \$820 | |
| | Doors - Steel Doors incl hw | 2nd Flr Boys (near central stair tower) | 2 | EA | 6 | \$602 | |
| | Floor Drain | 2nd FIr Boys (near central stair tower) | 1 | EA | 6 | \$1,059 | miss cover |
| | Floor - Tile Ceramic/ Porcelain | 2nd Flr Boys (near central stair tower) | 200 | SF | 6 | \$423 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd FIr Boys (near central stair tower) | 37 | SF | 5 | \$681 | missing/broken tile |
| | Hand Dryer | 2nd FIr Boys (near central stair tower) | 2 | EA | 7 | \$0 | |
| | Lavatory | 2nd FIr Boys (near central stair tower) | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 2nd FIr Boys (near central stair tower) | 2 | EA | 7 | \$0 | |
| | Partitions | 2nd FIr Boys (near central stair tower) | 2 | EA | 6 | \$594 | |
| | Urinals | 2nd FIr Boys (near central stair tower) | 1 | EA | 5 | \$1,344 | out of service, covered with garbage bag |
| | Urinals | 2nd FIr Boys (near central stair tower) | 5 | EA | 6 | \$1,680 | |
| | Walls - Concrete Block | 2nd FIr Boys (near central stair tower) | 224 | SF | 6 | \$657 | cracks throughout |
| | Walls - Plaster/Drywall | 2nd FIr Boys (near central stair tower) | 180 | SF | 6 | \$497 | |
| | Walls - Structural Glazed Tile | 2nd FIr Boys (near central stair tower) | 448 | SF | 5 | \$22,762 | cracks throughout |
| | Water Closet | 2nd Flr Boys (near central stair tower) | 2 | EA | 7 | \$0 | |
| | Accessories | 2nd Flr Boys South | 171 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd FIr Boys South | 171 | SF | 6 | \$592 | |
| | Doors - Wood Doors inclu hw | 2nd Flr Boys South | 2 | EA | 6 | \$602 | |
| | Floor Drain | 2nd Flr Boys South | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Flr Boys South | 171 | SF | 7 | \$0 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|--|----------|------|------|---------|---------------------|
| Restroc | om | | | | | | |
| | Lavatory | 2nd Flr Boys South | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 2nd Flr Boys South | 2 | EA | 7 | \$0 | |
| | Partitions | 2nd Flr Boys South | 2 | EA | 7 | \$0 | |
| | Urinals | 2nd Flr Boys South | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Flr Boys South | 162 | SF | 6 | \$475 | peeling paint |
| | Walls - Structural Glazed Tile | 2nd Flr Boys South | 336 | SF | 6 | \$1,057 | |
| | Water Closet | 2nd Flr Boys South | 2 | EA | 6 | \$672 | |
| | Accessories | 2nd Flr Girls (near central stair tower) | 254 | SF | 6 | \$2,343 | |
| | Ceiling - Plaster/Drywall | 2nd Flr Girls (near central stair tower) | 254 | SF | 6 | \$879 | |
| | Doors - Steel Doors incl hw | 2nd Flr Girls (near central stair tower) | 4 | EA | 6 | \$1,204 | |
| | Floor Drain | 2nd Flr Girls (near central stair tower) | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Flr Girls (near central stair tower) | 54 | SF | 5 | \$995 | missing/broken tile |
| | Floor - Tile Ceramic/ Porcelain | 2nd Flr Girls (near central stair tower) | 200 | SF | 6 | \$423 | |
| | Hand Dryer | 2nd Flr Girls (near central stair tower) | 2 | EA | 7 | \$0 | |
| | Lavatory | 2nd Flr Girls (near central stair tower) | 1 | EΑ | 7 | \$0 | |
| | Lavatory | 2nd Flr Girls (near central stair tower) | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 2nd Flr Girls (near central stair tower) | 2 | EΑ | 7 | \$0 | |
| | Partitions | 2nd Flr Girls (near central stair tower) | 7 | EA | 6 | \$2,078 | |
| | Walls - Concrete Block | 2nd Flr Girls (near central stair tower) | 203 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Flr Girls (near central stair tower) | 80 | SF | 6 | \$221 | |
| | Walls - Structural Glazed Tile | 2nd Flr Girls (near central stair tower) | 406 | SF | 7 | \$0 | |
| | Water Closet | 2nd Flr Girls (near central stair tower) | 7 | EΑ | 6 | \$2,352 | |
| | Accessories | 2nd Flr Girls South | 171 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Flr Girls South | 171 | SF | 6 | \$592 | |
| | Doors - Wood Doors inclu hw | 2nd Flr Girls South | 4 | EA | 6 | \$1,204 | |
| | Floor Drain | 2nd Flr Girls South | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Flr Girls South | 171 | SF | 7 | \$0 | |
| | Lavatory | 2nd Flr Girls South | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 2nd Flr Girls South | 2 | EA | 7 | \$0 | |
| | Partitions | 2nd Flr Girls South | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Flr Girls South | 168 | SF | 6 | \$492 | |
| | Walls - Structural Glazed Tile | 2nd Flr Girls South | 336 | SF | 6 | \$1,057 | |
| | Water Closet | 2nd Flr Girls South | 6 | EA | 7 | \$0 | |
| | Accessories | 2nd Flr Mens South | 32 | SF | 6 | \$295 | |
| | Ceiling - Plaster/Drywall | 2nd Flr Mens South | 32 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 2nd Flr Mens South | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Flr Mens South | 32 | SF | 5 | \$144 | Warping |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|------------------------------|----------|------|------|---------|------------------------------------|
| Restro | om | | | | | | |
| | Lavatory | 2nd Flr Mens South | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 2nd Flr Mens South | 1 | EA | 7 | \$0 | |
| | Partitions | 2nd FIr Mens South | 1 | EA | 5 | \$751 | rusted finish |
| | Walls - Concrete Block | 2nd Flr Mens South | 199 | SF | 6 | \$583 | |
| | Water Closet | 2nd FIr Mens South | 1 | EA | 6 | \$336 | |
| | Accessories | Bsmt. Engineer's Toilet Room | 30 | SF | 5 | \$594 | missing and damaged accessories |
| | Ceiling - Plaster/Drywall | Bsmt. Engineer's Toilet Room | 30 | SF | 4 | \$452 | large hole in plaster; rusted lath |
| | Doors - Wood Doors inclu hw | Bsmt. Engineer's Toilet Room | 1 | EA | 5 | \$1,174 | damaged finish |
| | Floor - Concrete | Bsmt. Engineer's Toilet Room | 30 | SF | 5 | \$51 | |
| | Lavatory | Bsmt. Engineer's Toilet Room | 1 | EA | 5 | \$1,590 | badly stained and damaged |
| | Lighting - Pendent/Surface | Bsmt. Engineer's Toilet Room | 1 | EA | 4 | \$541 | missing fixture |
| | Walls - Concrete Block | Bsmt. Engineer's Toilet Room | 175 | SF | 5 | \$1,797 | |
| | Water Closet | Bsmt. Engineer's Toilet Room | 1 | EA | 4 | \$7,669 | badly stained; plumbing issues |

Rooms (Other Than Classrooms) Subtotal:

\$900,667

Building: Kinzie

Category: Building Interior

| Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|--------------------------------|----------|------|------|----------|----------|
| or | | | | | | |
| Ceiling - Splined | 1st FIr - Main Entry | 744 | SF | 6 | \$2,149 | |
| Doors - Steel Doors incl hw | 1st Flr - Main Entry | 2 | EA | 6 | \$602 | |
| Doors - Wood Doors include hw | 1st Flr - Main Entry | 2 | EA | 5 | \$2,348 | |
| Drinking Fountains - Single Fountain | 1st Flr - Main Entry | 2 | EA | 6 | \$551 | |
| Floor - Terrazzo | 1st Flr - Main Entry | 744 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | 1st Flr - Main Entry | 6 | EA | 7 | \$0 | |
| Walls - Structural Glazed Tile | 1st Flr - Main Entry | 834 | SF | 6 | \$2,624 | |
| Ceiling - Plaster/Drywall | 1st Flr - South | 2,112 | SF | 5 | \$26,608 | |
| Doors - Steel Doors incl hw | 1st Flr - South | 2 | EA | 6 | \$602 | |
| Drinking Fountains - Single Water Cooler | 1st Flr - South | 5 | EA | 7 | \$0 | |
| Floor - Tile/Sheet | 1st Flr - South | 2,112 | SF | 6 | \$1,148 | |
| Lighting - Pendent/Surface | 1st Flr - South | 53 | EA | 6 | \$6,566 | |
| Student Lockers - One Tier | 1st Flr - South | 273 | EA | 6 | \$25,344 | |
| Walls - Plaster/Drywall | 1st Flr - South | 1,806 | SF | 7 | \$0 | |
| Walls - Structural Glazed Tile | 1st Flr - South | 2,895 | SF | 6 | \$9,108 | |
| Ceiling - Plaster/Drywall | 1st Flr Admin. office corridor | 59 | SF | 7 | \$0 | |
| Doors - Wood Doors include hw | 1st Flr Admin. office corridor | 1 | EΑ | 6 | \$301 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

Category: Building Interior

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--------------------------------------|--|----------|------|------|---------|----------|
| orrido | r | | | | | | |
| | Floor - Tile/Sheet | 1st Flr Admin. office corridor | 59 | SF | 7 | \$0 | vct |
| | Lighting - Pendent/Surface | 1st Flr Admin. office corridor | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st FIr Admin. office corridor | 219 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Flr North | 1,320 | SF | 7 | \$0 | |
| | Ceiling - Splined | 1st Flr North | 200 | SF | 6 | \$578 | |
| | Doors - Wood Doors include hw | 1st Flr North | 4 | EA | 5 | \$4,696 | |
| | Floor - Tile/Sheet | 1st Flr North | 1,520 | SF | 6 | \$826 | vct |
| | Lighting - Pendent/Surface | 1st Flr North | 23 | EA | 6 | \$2,850 | |
| | Student Lockers - One Tier | 1st Flr North | 75 | EA | 6 | \$6,963 | |
| | Walls - Plaster/Drywall | 1st Flr North | 1,455 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Flr North | 908 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Flr. Elev. Lobby | 140 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 1st Flr. Elev. Lobby | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 1st Flr. Elev. Lobby | 140 | SF | 6 | \$76 | vct |
| | Lighting - Pendent/Surface | 1st Flr. Elev. Lobby | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Flr. Elev. Lobby | 205 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Flr. Elev. Lobby | 205 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 1st Flr. Gym Lobby & 'Passage' Hallway | 119 | SF | 5 | \$1,499 | |
| | Ceiling - Splined | 1st Flr. Gym Lobby & 'Passage' Hallway | 1,062 | SF | 5 | \$7,563 | |
| | Doors - Steel Doors incl hw | 1st Flr. Gym Lobby & 'Passage' Hallway | 5 | EA | 5 | \$6,894 | |
| | Doors - Wood Doors include hw | 1st Flr. Gym Lobby & 'Passage' Hallway | 4 | EA | 6 | \$1,204 | |
| | Drinking Fountains - Double Fountain | 1st Flr. Gym Lobby & 'Passage' Hallway | 1 | EA | 6 | \$336 | |
| | Floor - Terrazzo | 1st Flr. Gym Lobby & 'Passage' Hallway | 859 | SF | 6 | \$7,211 | |
| | Floor - Tile/Sheet | 1st Flr. Gym Lobby & 'Passage' Hallway | 322 | SF | 5 | \$1,446 | vct |
| | Lighting - Pendent/Surface | 1st Flr. Gym Lobby & 'Passage' Hallway | 16 | EA | 6 | \$1,982 | |
| | Walls - Concrete Block | 1st Flr. Gym Lobby & 'Passage' Hallway | 603 | SF | 6 | \$1,768 | |
| | Walls - Plaster/Drywall | 1st Flr. Gym Lobby & 'Passage' Hallway | 232 | SF | 6 | \$1,028 | |
| | Walls - Structural Glazed Tile | 1st Flr. Gym Lobby & 'Passage' Hallway | 1,065 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd FIr Elev. Lobby | 140 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Flr Elev. Lobby | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd FIr Elev. Lobby | 140 | SF | 6 | \$76 | vct |
| | Lighting - Pendent/Surface | 2nd Flr Elev. Lobby | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Flr Elev. Lobby | 205 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Flr Elev. Lobby | 205 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Flr North | 1,520 | SF | 7 | \$0 | |
| | Doors - Wood Doors include hw | 2nd Flr North | 2 | EA | 5 | \$2,348 | |
| | Floor - Tile/Sheet | 2nd Flr North | 1,520 | SF | 6 | \$826 | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------------------|----------|------|------|----------|---------------------------------|
| Corrido | or | | | | | | |
| | Lighting - Pendent/Surface | 2nd Flr North | 23 | EA | 6 | \$2,850 | |
| | Student Lockers - One Tier | 2nd Flr North | 75 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Flr North | 908 | SF | 6 | \$4,025 | |
| | Walls - Structural Glazed Tile | 2nd Flr North | 1,455 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd FIr South & Center | 2,112 | SF | 6 | \$13,077 | |
| | Ceiling - Splined | 2nd Flr South & Center | 744 | SF | 6 | \$2,149 | |
| | Doors - Wood Doors include hw | 2nd Flr South & Center | 2 | EA | 5 | \$2,348 | |
| | Drinking Fountains - Double Fountain | 2nd Flr South & Center | 1 | EA | 6 | \$336 | |
| | Drinking Fountains - Single Water Cooler | 2nd Flr South & Center | 4 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Flr South & Center | 2,856 | SF | 6 | \$1,552 | |
| | Lighting - Pendent/Surface | 2nd Flr South & Center | 59 | EA | 6 | \$7,310 | |
| | Student Lockers - One Tier | 2nd FIr South & Center | 273 | EA | 5 | \$38,262 | damaged doors, missing hardware |
| | Walls - Plaster/Drywall | 2nd Flr South & Center | 1,806 | SF | 6 | \$8,006 | |
| | Walls - Structural Glazed Tile | 2nd FIr South & Center | 3,729 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Bsmt E/W 'Passage' Corridor | 477 | SF | 5 | \$6,009 | water damage |
| | Floor - Concrete Epoxy/ Painted | Bsmt E/W 'Passage' Corridor | 477 | SF | 5 | \$819 | |
| | Lighting - Pendent/Surface | Bsmt E/W 'Passage' Corridor | 6 | EA | 6 | \$743 | |
| | Walls - Concrete Block | Bsmt E/W 'Passage' Corridor | 1,010 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Bsmt N/S Corridor | 600 | SF | 5 | \$7,559 | peeling paint |
| | Doors - Steel Doors incl hw | Bsmt N/S Corridor | 4 | EA | 6 | \$1,204 | |
| | Floor - Concrete Epoxy/ Painted | Bsmt N/S Corridor | 600 | SF | 5 | \$1,030 | |
| | Lighting - Pendent/Surface | Bsmt N/S Corridor | 10 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Bsmt N/S Corridor | 5 | SF | 4 | \$262 | hole |
| | Walls - Concrete Block | Bsmt N/S Corridor | 1,556 | SF | 6 | \$4,561 | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | Central Stair | 635 | SF | 7 | \$0 | |
| | Floor - Terrazzo | Central Stair | 262 | SF | 6 | \$2,199 | |
| | Floor - Tile | Central Stair | 373 | SF | 6 | \$203 | |
| | Handrails | Central Stair | 92 | LF | 6 | \$797 | |
| | Lighting - Pendent/Surface | Central Stair | 7 | EA | 6 | \$867 | |
| | Stairs - Terrazzo | Central Stair | 100 | LF | 6 | \$928 | |
| | Walls - Concrete Block | Central Stair | 216 | SF | 6 | \$633 | |
| | Walls - Structural Glazed Tile | Central Stair | 830 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | South Stair | 255 | SF | 7 | \$0 | |
| | Ceiling - Splined | South Stair | 190 | SF | 5 | \$1,353 | |
| | Floor - Terrazzo | South Stair | 258 | SF | 6 | \$2,166 | |
| | Floor - Tile Ceramic/ Porcelain | South Stair | 74 | SF | 5 | \$1,182 | |
| | | | | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Building: Kinzie

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---------------------------------|---------------------|----------|------|------|---------|--|
| Stairs | | | | | | | |
| | Handrails | South Stair | 52 | LF | 6 | \$451 | |
| | Lighting - Pendent/Surface | South Stair | 2 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | South Stair | 1 | EA | 5 | \$169 | yellowed lens; insufficient illumination |
| | Stairs - Terrazzo | South Stair | 100 | LF | 7 | \$0 | |
| | Walls - Concrete Block | South Stair | 387 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | South Stair | 534 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | South/Central Stair | 318 | SF | 6 | \$955 | |
| | Ceiling - Splined | South/Central Stair | 199 | SF | 5 | \$1,417 | some water damage |
| | Floor - Terrazzo | South/Central Stair | 283 | SF | 6 | \$2,376 | |
| | Floor - Tile | South/Central Stair | 111 | SF | 6 | \$60 | |
| | Floor - Tile Ceramic/ Porcelain | South/Central Stair | 79 | SF | 6 | \$530 | |
| | Handrails | South/Central Stair | 52 | LF | 7 | \$0 | |
| | Lighting - Pendent/Surface | South/Central Stair | 4 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | South/Central Stair | 1 | EA | 5 | \$169 | yellowed lens, insufficient illumination |
| | Stairs - Terrazzo | South/Central Stair | 100 | LF | 7 | \$0 | |
| | Walls - Concrete Block | South/Central Stair | 288 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | South/Central Stair | 418 | SF | 7 | \$0 | |
| Vertical | Conveyance | | | | | | |
| | Elevator - Hydraulic Elevator | | 1 | EA | 7 | \$0 | |

Building Interior Subtotal: \$246,679

Total Building Cost \$4,403,405

SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | | | |
|---------|-----------------------------------|-------------|----------|------------------------------------|------|----------|---|--|--|--|--|
| Civil/E | Civil/Drainage | | | | | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 16 | EA | 7 | \$0 | | | | | |
| | Civil/ Drainage - Site Drain | Entire Site | 4 | sundeck entrances- cracked, uneven | | | | | | | |
| | Civil/ Drainage - Site Manhole | Entire Site | 18 | EA | 7 | \$0 | | | | | |
| Fencir | g | | | | | | | | | | |
| | Fencing - Chain Link | Entire Site | 1,168 | LF | 6 | \$21,930 | NE trash, W parking lot, sundeck perimeter | | | | |
| | Fencing - Guard Rail | Entire Site | 1,075 | LF | 7 | \$0 | W parking lot, along drive between buildings | | | | |
| | Fencing - New Standard Ornamental | Entire Site | 405 | LF | 6 | \$12,921 | NW of auditorium, W of W parking lot - corroded | | | | |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|--------------------|----------|------|------|-----------|--|
| Landsc | ape | | | | | | |
| | Landscape - Grass | Entire Site | 12,332 | SF | 7 | \$0 | |
| | Landscape - Hardscape- Concrete | Entire Site | 15,710 | SF | 7 | \$0 | W and N entry and trash, S of Kennedy |
| | Landscape - Hardscape- Concrete | Entire Site | 2,576 | SF | 5 | \$28,254 | W of sundeck, under connector - cracked, uneve |
| | Parkway trees | Entire Site | 25 | EA | 7 | \$0 | |
| | Planting Beds/ Area | Entire Site | 2,000 | SF | 7 | \$0 | N of Kennedy |
| | Play Area - Asphalt/ Hardscape | Entire Site | 336 | SF | 4 | \$3,560 | E of sundeck - missing areas, uneven |
| | Play Area - Asphalt/ Hardscape | Entire Site | 5,814 | SF | 6 | \$14,051 | W of sundeck |
| | Retaining Wall - Concrete | Entire Site | 900 | SF | 7 | \$0 | N loading dock |
| | Retaining Wall - Concrete | Entire Site | 1,225 | SF | 6 | \$28,711 | E and W sundeck |
| | Trash Receptacles | Entire Site | 7 | EA | 6 | \$2,186 | |
| Parking | g Lot | | | | | | |
| | Surface - Asphalt | Entire Site / East | 9,375 | SF | 6 | \$26,142 | |
| | Surface - Asphalt | Entire Site / West | 45,756 | SF | 5 | \$208,725 | cracked, uneven |
| | Trash Enclosure - Chain Links | Entire Site | 700 | SF | 7 | \$0 | NE of Kennedy |
| Sidewa | lks | | | | | | |
| | Sidewalks - Perimeter Sidewalks | N and W of Kennedy | 14,453 | SF | 7 | \$0 | |
| Signag | e | | | | | | |
| | Flag Pole - Flag Pole | Entire Site | 1 | EA | 7 | \$0 | NW by Kennedy Auditorium |
| | Marquee - Free Standing Back lighted w/ LED | Entire Site | 1 | EA | 4 | \$43,600 | missing components, exposed wiring |
| | Monument - Building Mounted Cut Letter Sign | Entire Site | 2 | EA | 7 | \$0 | NW and N of Kennedy |
| Site S | Subtotal: | | | | | \$395,598 | |
| | | | | | | | |
| Total | Site Cost | · | | | | \$395.598 | |

Total Site Cost \$395,598

Campus Total ^{2 3} \$13,213,919

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Kennedy | | - | | | | | | | | | - | | | + |
| Art Room | Regular Classroom | 1st Floor | 110 | 109 | 909 | 1 | 0 | 6 | 246 | 60 | 40 | N | Υ | N |
| Art Room | Art Room | | 118 | 118 | 1,569 | 1 | 5 | 14 | 315 | 157 | 40 | N | Υ | N |
| Computer Lab | Computer Lab | 3rd Floor | 300 | 301 (partial) | 369 | 0 | 8 | 16 | 96 | 24 | 40 | N | Υ | N |
| Computer Lab | Computer Lab | 3rd Floor | 302 | 301 (partial) | 729 | 0 | 12 | 42 | 192 | 48 | 40 | N | Υ | N |
| Computer Lab | Computer Lab | 3rd Floor | 304 | 303 | 1,110 | 0 | 2 | 78 | 288 | 72 | 40 | N | Υ | N |
| Computer Lab | Computer Lab | 3rd Floor | 306 | 305 (partial) | 729 | 0 | 33 | 68 | 192 | 48 | 40 | N | Υ | N |
| Computer Lab | Computer Lab | 3rd Floor | 308 | 306 | 1,110 | 1 | 2 | 112 | 288 | 72 | 40 | N | Ν | N |
| Computer Lab | Computer Lab | 3rd Floor | 311 | 308 | 1,110 | 1 | 23 | 98 | 288 | 72 | 40 | N | Υ | N |
| Fitness Room | Fitness Room | Basement | Bsmt Wrestling | B100 | 1,086 | 0 | 0 | 12 | 0 | 0 | 40 | N | Ν | N |
| Music Room | Music Room | 1st Floor | 111 | 110 | 1,595 | 0 | 0 | 10 | 0 | 0 | 40 | N | Υ | N |
| Music Room | Choral Room | 2nd Floor | 212 | 212 | 1,550 | 0 | 1 | 8 | 0 | 0 | 40 | N | Ν | N |
| Other Instructional Use | Computer Lab | 3rd Floor | 310 | 307 | 1,110 | 1 | 2 | 98 | 288 | 72 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 108 | 105 | 729 | 1 | 0 | 6 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 112 | 112 | 729 | 0 | 2 | 10 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 113 | 113 (partial) | 545 | 0 | 1 | 8 | 144 | 36 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 114 | 113 (partial) | 545 | 0 | 1 | 4 | 144 | 36 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 115 | 114 | 729 | 0 | 1 | 8 | 192 | 48 | 40 | N | Ν | N |
| Regular Classroom | Regular Classroom | 1st Floor | 116 | 115 (partial) | 545 | 1 | 1 | 6 | 144 | 36 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 117 | 115 (partial) | 545 | 0 | 1 | 6 | 144 | 36 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 729 | 0 | 1 | 6 | 192 | 49 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 729 | 0 | 1 | 4 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 729 | 0 | 1 | 4 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 729 | 0 | 1 | 6 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 729 | 0 | 2 | 10 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 729 | 0 | 1 | 6 | 192 | 48 | 40 | N | Ν | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 729 | 0 | 2 | 8 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 729 | 0 | 1 | 6 | 192 | 48 | 40 | N | Ν | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 729 | 0 | 1 | 6 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 210 | 729 | 0 | 2 | 8 | 192 | 48 | 40 | N | Ν | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 211 | 211 | 729 | 0 | 1 | 6 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Special Program | 2nd Floor | 213 | 213 (partial) | 714 | 2 | 3 | 18 | 148 | 40 | | N | Ν | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 214 | 213 (partial) | 814 | 0 | 1 | 10 | 200 | 56 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 217 | 217 | 729 | 0 | 1 | 6 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 220A | n/a | 741 | 0 | 1 | 4 | 221 | 110 | 40 | Υ | Υ | Υ |
| Regular Classroom | Regular Classroom | | 220B | n/a | 836 | 0 | 1 | 6 | 336 | 168 | 50 | Υ | Z | N |
| Regular Classroom | Office | | 222 | n/a | 442 | 0 | 1 | 4 | 72 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 309B | NA | 697 | 0 | 2 | 6 | 174 | 48 | 40 | N | Υ | N |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------------|-------------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Kennedy | | | | | | | | | | | | | | - |
| Regular Classroom | Regular Classroom | 3rd Floor | 312B | 309 (partial) | 759 | 0 | 2 | 8 | 192 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 313B | 310 (partial) | 759 | 0 | 1 | 6 | 192 | 48 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 315 | 312 (partial) | 668 | 0 | 2 | 18 | 148 | 40 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 317 | 312 (partial) | 878 | 1 | 0 | 8 | 200 | 56 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 319A | NA | 557 | 0 | 0 | 4 | 200 | 56 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 319B | NA | 557 | 0 | 0 | 10 | 0 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 321 | 315 | 729 | 0 | 1 | 6 | 192 | 48 | 40 | N | Υ | N |
| Science Classroom | Science Classroom | 1st Floor | 109 | 108 | 1,004 | 1 | 2 | 82 | 273 | 66 | 40 | N | Υ | N |
| Science Classroom | Science Classroom | | 215 | 214 | 1,485 | 1 | 2 | 34 | 384 | 96 | 40 | N | Υ | N |
| Science Classroom | Science Classroom | 2nd Floor | 216 | 215 | 1,485 | 1 | 2 | 80 | 384 | 96 | 40 | N | Υ | N |
| Science Classroom | Science Lab Level 3 | 3rd Floor | 320 | 314 | 1,304 | 1 | 3 | 78 | 285 | 72 | 40 | N | Υ | N |
| Science Lab Level 1 | Science Lab Level 1 | 3rd Floor | 314 | 311 | 1,402 | 0 | 12 | 72 | 225 | 54 | 40 | N | Υ | N |
| Science Lab Level 2 | Science Lab Level 2 | 3rd Floor | 318 | 313 | 1,242 | 1 | 5 | 36 | 315 | 78 | 40 | N | N | N |
| Special Education | Regular Classroom | 3rd Floor | 301 | 302 (partial) | 388 | 0 | 1 | 2 | 72 | 16 | 40 | N | Υ | N |
| Special Program | Library | 1st Floor | 111A | 111 | 609 | 0 | 1 | 8 | 0 | 0 | 40 | N | Υ | N |
| Special Program | Special Program | 3rd Floor | 306A | 305 (partial) | 369 | 1 | 3 | 32 | 96 | 24 | 40 | N | Υ | N |
| Special Program | Store Room | 3rd Floor | 307 | NA | 400 | 0 | 1 | 30 | 72 | 16 | 40 | N | Υ | N |
| Special Program | Special Program | 3rd Floor | 309A | NA | 417 | 1 | 0 | 16 | 0 | 0 | 40 | N | Υ | N |
| Special Program | Special Program | 3rd Floor | 312A | 309 (partial) | 369 | 1 | 0 | 8 | 96 | 24 | 40 | N | Υ | N |
| Special Program | Special Program | 3rd Floor | 313A | 310 (partial) | 369 | 1 | 0 | 8 | 96 | 24 | 40 | N | N | N |
| Kinzie | | | | | | | | | | | | | | |
| Art Room | Regular Classroom | | 224 | NA | 1,361 | 0 | 0 | 11 | 345 | 172 | 53 | Υ | Υ | Υ |
| Computer Lab | Regular Classroom | | 217 | NA | 725 | 0 | 34 | 101 | 210 | 105 | 53 | N | Υ | Y |
| Computer Lab | Regular Classroom | | 235 | NA | 725 | 1 | 32 | 70 | 168 | 66 | 53 | N | Υ | Υ |
| Faculty Lounge | Other Instructional Use | | 117 | NA | 1,175 | 2 | 7 | 35 | 345 | 99 | 40 | Υ | Υ | N |
| Kindergarten | Kindergarten | | 120 | NA | 1,270 | 0 | 0 | 8 | 345 | 172 | 53 | N | Υ | Υ |
| Kindergarten | Regular Classroom | | 121 | NA | 725 | 0 | 0 | 4 | 210 | 105 | 53 | N | Υ | Υ |
| Kindergarten | Kindergarten | | 122 | NA | 1,269 | 1 | 1 | 4 | 345 | 172 | 53 | Υ | Υ | Υ |
| Kindergarten | Regular Classroom | | 227 | NA | 725 | 0 | 1 | 8 | 200 | 100 | 53 | Υ | Υ | Υ |
| Other Instructional Use | Regular Classroom | | 104 | NA | 725 | 0 | 1 | 4 | 210 | 105 | 53 | N | N | N |
| Other Instructional Use | Other Instructional Use | | Bsmt Speech | | 428 | 0 | 0 | 4 | 0 | 0 | 40 | N | N | N |
| Other Instructional Use | Other Instructional Use | | In Room 119 | NA | 221 | 0 | 0 | 8 | 115 | 33 | 40 | Υ | N | N |
| Pre School | Pre School | | 119 | NA | 811 | 1 | 1 | 10 | 168 | 66 | 40 | Υ | Υ | Υ |
| Regular Classroom | Regular Classroom | | 102 | NA | 725 | 0 | 0 | 6 | 210 | 105 | 53 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 112 | NA | 725 | 0 | 0 | 6 | 210 | 105 | 53 | N | N | Υ |
| Regular Classroom | Regular Classroom | | 113 | NA | 740 | 1 | 2 | 7 | 230 | 66 | 40 | Υ | Υ | Υ |



6325 W 56th St Chicago, IL 60638

Co-locating on this campus are KENNEDY HS and KINZIE

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|---------------------|---------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Kinzie | | | | | | | | - | | • | | | 1 | * |
| Regular Classroom | Regular Classroom | | 114 | NA | 725 | 0 | 0 | 8 | 210 | 105 | 53 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 116 | NA | 725 | 0 | 1 | 4 | 210 | 105 | 53 | N | N | Υ |
| Regular Classroom | Regular Classroom | | 118 | NA | 725 | 0 | 0 | 6 | 210 | 105 | 53 | N | N | Υ |
| Regular Classroom | Regular Classroom | | 123 | NA | 725 | 0 | 0 | 6 | 210 | 105 | 53 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 124 | NA | 730 | 1 | 0 | 6 | 115 | 66 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | | 125 | NA | 725 | 0 | 1 | 8 | 210 | 105 | 53 | Ν | N | Υ |
| Regular Classroom | Regular Classroom | | 126 | NA | 725 | 0 | 0 | 6 | 200 | 100 | 53 | Ν | Υ | N |
| Regular Classroom | Regular Classroom | | 127 | NA | 878 | 0 | 0 | 4 | 210 | 105 | 53 | Υ | N | Υ |
| Regular Classroom | Regular Classroom | | 129 | NA | 617 | 0 | 0 | 6 | 156 | 78 | 40 | Ν | N | Υ |
| Regular Classroom | Regular Classroom | | 133 | NA | 762 | 0 | 1 | 6 | 200 | 100 | 40 | Ν | N | Υ |
| Regular Classroom | Regular Classroom | | 200 | NA | 725 | 0 | 8 | 26 | 168 | 66 | 53 | Ν | N | N |
| Regular Classroom | Regular Classroom | | 202 | NA | 725 | 1 | 8 | 20 | 210 | 105 | 53 | N | N | Υ |
| Regular Classroom | Regular Classroom | | 203 | NA | 725 | 0 | 1 | 12 | 210 | 105 | 53 | Ν | N | N |
| Regular Classroom | Regular Classroom | | 204 | NA | 725 | 1 | 11 | 30 | 210 | 105 | 53 | Ν | Υ | N |
| Regular Classroom | Regular Classroom | | 205 | NA | 725 | 0 | 0 | 14 | 210 | 105 | 53 | Ν | Υ | Υ |
| Regular Classroom | Regular Classroom | | 206 | NA | 725 | 0 | 9 | 10 | 168 | 66 | 53 | Ν | Υ | Υ |
| Regular Classroom | Regular Classroom | | 207 | NA | 725 | 0 | 7 | 20 | 210 | 105 | 53 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 209 | NA | 725 | 0 | 9 | 22 | 210 | | 53 | N | N | N |
| Regular Classroom | Regular Classroom | | 211 | NA | 725 | 0 | 10 | 22 | 210 | 105 | 53 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 212 | NA | 725 | 0 | 7 | 20 | 210 | 105 | 53 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 213 | NA | 725 | 0 | 0 | 6 | 210 | 105 | 53 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 214 | NA | 725 | 0 | 8 | 20 | 210 | 105 | 53 | N | N | N |
| Regular Classroom | Regular Classroom | | 215 | NA | 725 | 0 | 0 | 8 | 210 | 105 | 53 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 216 | NA | 725 | 0 | 8 | 22 | 210 | 105 | 53 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 218 | NA | 725 | 0 | 11 | 22 | 210 | 105 | 53 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 219 | NA | 725 | 1 | 9 | 22 | 210 | 105 | 53 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 221 | NA | 878 | 0 | 4 | 14 | 210 | 105 | 53 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 223 | NA | 617 | 0 | 0 | 6 | 156 | 78 | 53 | Υ | Y | Υ |
| Regular Classroom | Regular Classroom | | 225 | NA | 725 | 0 | 2 | 4 | 210 | 105 | 53 | N | Υ | Υ |
| Science | Science Classroom | | 220 | NA | 872 | 0 | 8 | 16 | 230 | 115 | 40 | Υ | Υ | Υ |
| Science Lab Level 3 | Science Lab Level 3 | | 115 | 103 | 1,134 | 0 | 7 | 36 | 315 | 157 | 53 | N | Υ | Υ |
| Special Program | Regular Classroom | | 222 | 222 | 725 | 0 | 7 | 20 | 210 | 105 | 40 | Ν | Υ | N |
| Special Program | | Basement | smt AudioBootl | | 456 | 0 | 0 | 2 | 0 | 0 | 40 | N | N | N |
| Store Room | Regular Classroom | | 131 | NA | 725 | 0 | 1 | 6 | 200 | 100 | 40 | Υ | N | N |