

## Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition<sup>1</sup>. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at [http://www.cps.edu/About\\_CPS/Policies\\_and\\_guidelines/Pages/facilitystandards.aspx](http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx). Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1934	4	707,164	\$44,537,141
Annex	1975	1	6,771	\$579,645
SITE				\$3,689,925
<b>Campus Total</b>			<b>713,935</b>	<b>\$48,806,711</b>

### Building: Main

#### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Entrance Control - Audio and Video	B- NE	1	EA	6	\$702	
	Entrance Control - Audio and Video	D- NW	1	EA	6	\$702	
	Entrance Control - Audio and Video	J- SW	1	EA	6	\$702	
	Entrance Control - Audio and Video	M- SE	1	EA	6	\$702	
	Entrance Control - Audio and Video	N- SE	1	EA	6	\$702	
	Entrance Control - Audio and Video	T- NE	1	EA	6	\$702	
	Exterior Doors - Exterior Steel Door	#3- SW	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	#3.1- SE	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	#3.3- SW	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	A- NE	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	Boiler Room- SW	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	CT YD 1- NE	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	CT YD 3- NW	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	D- NW	3	EA	6	\$1,442	graffiti
	Exterior Doors - Exterior Steel Door	F- NW	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	G- NW	4	EA	6	\$1,922	
	Exterior Doors - Exterior Steel Door	H- SW	3	EA	6	\$1,442	rust
	Exterior Doors - Exterior Steel Door	M- SE	3	EA	6	\$1,442	
	Exterior Doors - Exterior Steel Door	N.1- SE	1	EA	5	\$1,341	dents

**Building: Main**

**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Exterior Doors - Exterior Steel Door	O- SE	3	EA	6	\$1,442	gaffiti
	Exterior Doors - Exterior Steel Door	Roof access doors	1	EA	5	\$1,341	Rust & flaking paint
	Exterior Doors - Exterior Steel Door	Roof access doors	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Roof access doors / North East	1	EA	5	\$1,341	rust & paint
	Exterior Doors - Exterior Steel Door	Roof access doors / North West	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	Roof access doors / North West	1	EA	4	\$3,823	Deterioration & rust
	Exterior Doors - Exterior Steel Door	Z- SW	3	EA	6	\$1,442	
	Exterior Doors - Exterior Wood Door	C- NW	3	EA	6	\$1,442	
	Exterior Doors - Exterior Wood Door	#3.2- SE	2	EA	6	\$961	
	Exterior Doors - Exterior Wood Door	B- NE	3	EA	5	\$4,024	repair framing
	Exterior Doors - Exterior Wood Door	E- NW	9	EA	4	\$34,403	deterioration
	Exterior Doors - Exterior Wood Door	Eng Entrance- SW CT YD	1	EA	4	\$3,823	deterioration
	Exterior Doors - Exterior Wood Door	I- SW	3	EA	4	\$11,468	deterioration
	Exterior Doors - Exterior Wood Door	J- SW	3	EA	4	\$11,468	deterioration
	Exterior Doors - Exterior Wood Door	K- SW	2	EA	6	\$961	
	Exterior Doors - Exterior Wood Door	Kitchen- SE	1	EA	6	\$481	
	Exterior Doors - Exterior Wood Door	L- SE	2	EA	6	\$961	
	Exterior Doors - Exterior Wood Door	M.1- SE	2	EA	4	\$7,645	deterioration
	Exterior Doors - Exterior Wood Door	N- SE	3	EA	6	\$1,442	
	Exterior Doors - Exterior Wood Door	P- NE	3	EA	4	\$11,468	deterioration
	Exterior Doors - Exterior Wood Door	Q- NE	2	EA	4	\$7,645	deterioration
	Exterior Doors - Exterior Wood Door	R- NE	2	EA	4	\$7,645	deteriorating
	Exterior Doors - Exterior Wood Door	S- NE	2	EA	6	\$961	
	Exterior Doors - Exterior Wood Door	T- NE	9	EA	6	\$4,325	
	Exterior Doors - Exterior Wood Door	U- NE	2	EA	6	\$961	Graffiti
	Exterior Doors - Overhead Rolling/ Garage Door	H.1- SW	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	H.2- SW	1	EA	6	\$1,433	
	Exterior Doors - Overhead Rolling/ Garage Door	H.3- SW	4	EA	6	\$5,734	
	Exterior Doors - Overhead Rolling/ Garage Door	I.1- SW	4	EA	6	\$5,734	
	Exterior Doors - Overhead Rolling/ Garage Door	K.1- SW	2	EA	6	\$2,867	
	Exterior Doors - Overhead Rolling/ Garage Door	P.1- NE	1	EA	5	\$3,942	rusted through in spots
	Exterior Doors - Side lite	CT YD 2- NW	2	EA	6	\$627	
	Exterior Doors - Store Front	CT YD 2- NW	2	EA	6	\$1,092	
	Exterior Doors - Transom Lite	C- NW	6	EA	6	\$1,880	
	Exterior Doors - Transom Lite	#3- SW	3	EA	6	\$940	
	Exterior Doors - Transom Lite	#3.1- SE	3	EA	6	\$940	
	Exterior Doors - Transom Lite	#3.2- SE	2	EA	6	\$627	

**Building: Main**
**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Exterior Doors - Transom Lite	#3.3- SW	2	EA	6	\$627	
	Exterior Doors - Transom Lite	A- NE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	B- NE	6	EA	6	\$1,880	
	Exterior Doors - Transom Lite	Boiler Room- SW	2	EA	6	\$627	
	Exterior Doors - Transom Lite	CT YD 2- NW	4	EA	6	\$1,253	
	Exterior Doors - Transom Lite	D- NW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	E- NW	18	EA	6	\$5,640	
	Exterior Doors - Transom Lite	Eng Entrance- SW CT YD	1	EA	6	\$313	
	Exterior Doors - Transom Lite	F- NW	6	EA	4	\$12,041	deterioration
	Exterior Doors - Transom Lite	G- NW	2	EA	6	\$627	
	Exterior Doors - Transom Lite	H- SW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	H.1- SW	3	EA	6	\$940	
	Exterior Doors - Transom Lite	H.2- SW	3	EA	6	\$940	
	Exterior Doors - Transom Lite	I- SW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	J- SW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	K- SW	2	EA	6	\$627	
	Exterior Doors - Transom Lite	K.1- SW	2	EA	6	\$627	
	Exterior Doors - Transom Lite	Kitchen- SE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	L- SE	2	EA	6	\$627	
	Exterior Doors - Transom Lite	M- SE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	O- SE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	P- NE	6	EA	6	\$1,880	
	Exterior Doors - Transom Lite	Q- NE	3	EA	6	\$940	
	Exterior Doors - Transom Lite	R- NE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	S- NE	3	EA	6	\$940	
	Exterior Doors - Transom Lite	T- NE	18	EA	6	\$5,640	
	Exterior Doors - Transom Lite	U- NE	3	EA	6	\$940	
	Exterior Doors - Transom Lite	Z- SW	3	EA	6	\$940	
	Exterior Stairs - Concrete	C- NW	12	LF	4	\$1,963	Concrete landing is spalling & deteriorating
	Exterior Stairs - Concrete	#3- SW	12	LF	5	\$1,315	cracks
	Exterior Stairs - Concrete	B- NE	50	LF	6	\$4,088	
	Exterior Stairs - Concrete	Boiler Room- SW	6	LF	6	\$491	
	Exterior Stairs - Concrete	CT YD 1- NE	6	LF	6	\$491	
	Exterior Stairs - Concrete	CT YD 2- NW	50	LF	6	\$4,088	
	Exterior Stairs - Concrete	D- NW	50	LF	6	\$4,088	
	Exterior Stairs - Concrete	E- NW	64	LF	5	\$7,013	cracks & spalling
	Exterior Stairs - Concrete	Eng Entrance- SW CT YD	3	LF	6	\$245	

**Building: Main**
**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Exterior Stairs - Concrete	F- NW	12	LF	5	\$1,315	concrete landing has cracks
	Exterior Stairs - Concrete	H- SW	12	LF	5	\$1,315	spalling
	Exterior Stairs - Concrete	J- SW	12	LF	6	\$981	
	Exterior Stairs - Concrete	M- SE	12	LF	6	\$981	
	Exterior Stairs - Concrete	N.1- SE	80	LF	6	\$6,541	has moss on them
	Exterior Stairs - Concrete	P- NE	12	LF	5	\$1,315	section of concrete landing is missing
	Exterior Stairs - Concrete	T- NE	60	LF	6	\$4,906	
	Exterior Stairs - Concrete	T- NE	60	LF	5	\$6,575	cracks
	Exterior Stairs - Steel or Aluminum	T- NE	72	LF	6	\$277	
	Exterior Stairs - Stone	C- NW	72	LF	6	\$8,135	
	Exterior Stairs - Stone	#3- SW	9	LF	6	\$1,017	
	Exterior Stairs - Stone	#3.2- SE	6	LF	6	\$678	
	Exterior Stairs - Stone	#3.3- SW	6	LF	6	\$678	
	Exterior Stairs - Stone	A- NE	60	LF	6	\$6,779	
	Exterior Stairs - Stone	CT YD 1- NE	25	LF	5	\$6,779	Gaps at bricks
	Exterior Stairs - Stone	CT YD 3- NW	25	LF	5	\$6,779	Stone & brick steps. Gaps
	Exterior Stairs - Stone	E- NW	216	LF	5	\$58,573	gaps
	Exterior Stairs - Stone	Eng Entrance- SW CT YD	3	LF	6	\$339	
	Exterior Stairs - Stone	F- NW	70	LF	6	\$7,909	
	Exterior Stairs - Stone	H- SW	24	LF	6	\$2,712	
	Exterior Stairs - Stone	K- SW	6	LF	6	\$678	
	Exterior Stairs - Stone	Kitchen- SE	3	LF	6	\$339	
	Exterior Stairs - Stone	L- SE	6	LF	6	\$678	
	Exterior Stairs - Stone	M.1- SE	6	LF	6	\$678	
	Exterior Stairs - Stone	N- SE	9	LF	6	\$1,017	
	Exterior Stairs - Stone	O- SE	10	LF	6	\$1,130	
	Exterior Stairs - Stone	P- NE	72	LF	5	\$19,524	Gaps & movement
	Exterior Stairs - Stone	Q- NE	6	LF	6	\$678	
	Exterior Stairs - Stone	R- NE	6	LF	6	\$678	
	Exterior Stairs - Stone	S- NE	42	LF	5	\$11,389	open joints
	Exterior Stairs - Stone	T- NE	180	LF	6	\$20,337	
	Exterior Stairs - Stone	U- NE	48	LF	5	\$13,016	gaps
	Exterior Stairs - Stone	Z- SW	9	LF	6	\$1,017	
	Power Door Operator and Controls	B- NE	2	EA	6	\$0	
	Power Door Operator and Controls	D- NW	2	EA	6	\$0	
	Power Door Operator and Controls	J- SW	1	EA	6	\$0	
	Power Door Operator and Controls	M- SE	2	EA	6	\$0	

**Building: Main**
**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Power Door Operator and Controls	T- NE	2	EA	6	\$0	
	Ramp Handrail - Steel_Ramp Handrail	B- NE	100	LF	6	\$867	
	Ramp Handrail - Steel_Ramp Handrail	CT YD 2- NW	122	LF	4	\$18,329	missing handrail for paver ramp
	Ramp Handrail - Steel_Ramp Handrail	CT YD 2- NW	110	LF	6	\$953	
	Ramp Handrail - Steel_Ramp Handrail	CT YD 2- NW	12	LF	4	\$1,803	missing sections
	Ramp Handrail - Steel_Ramp Handrail	D- NW	110	LF	6	\$953	
	Ramp Handrail - Steel_Ramp Handrail	G- NW	35	LF	6	\$303	
	Ramp Handrail - Steel_Ramp Handrail	G- NW	35	LF	4	\$5,258	missing rail
	Ramp Handrail - Steel_Ramp Handrail	I- SW	3	LF	6	\$26	
	Ramp Handrail - Steel_Ramp Handrail	J- SW	30	LF	6	\$260	
	Ramp Handrail - Steel_Ramp Handrail	M- SE	55	LF	6	\$477	
	Ramp Handrail - Steel_Ramp Handrail	T- NE	95	LF	6	\$823	
	Ramps - Concrete	B- NE	50	LF	6	\$7,512	
	Ramps - Concrete	CT YD 2- NW	55	LF	6	\$8,263	
	Ramps - Concrete	CT YD 2- NW	55	LF	6	\$8,263	pavers
	Ramps - Concrete	D- NW	55	LF	6	\$8,263	
	Ramps - Concrete	G- NW	35	LF	6	\$5,258	
	Ramps - Concrete	J- SW	15	LF	6	\$2,254	
	Ramps - Concrete	M- SE	25	LF	6	\$3,756	
	Ramps - Concrete	T- NE	65	LF	6	\$9,765	
	Stair Handrail - Steel_Stair Handrail	C- NW	3	LF	6	\$26	
	Stair Handrail - Steel_Stair Handrail	A- NE	3	LF	6	\$26	
	Stair Handrail - Steel_Stair Handrail	B- NE	18	LF	6	\$156	
	Stair Handrail - Steel_Stair Handrail	CT YD 2- NW	24	LF	6	\$208	
	Stair Handrail - Steel_Stair Handrail	D- NW	25	LF	6	\$217	
	Stair Handrail - Steel_Stair Handrail	E- NW	8	LF	6	\$69	
	Stair Handrail - Steel_Stair Handrail	F- NW	3	LF	6	\$26	
	Stair Handrail - Steel_Stair Handrail	H- SW	3	LF	6	\$26	
	Stair Handrail - Steel_Stair Handrail	J- SW	13	LF	6	\$113	
	Stair Handrail - Steel_Stair Handrail	M- SE	12	LF	6	\$104	
	Stair Handrail - Steel_Stair Handrail	N- SE	3	LF	6	\$26	
	Stair Handrail - Steel_Stair Handrail	N.1- SE	40	LF	4	\$6,009	missing
	Stair Handrail - Steel_Stair Handrail	O- SE	3	LF	6	\$26	
	Stair Handrail - Steel_Stair Handrail	P- NE	3	LF	6	\$26	
	Stair Handrail - Steel_Stair Handrail	T- NE	8	LF	6	\$69	
<b>Foundation</b>							
	Foundation - Concrete	Entire Building	10	LF	5	\$0	seepage and cracks

**Building: Main**
**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Foundation</b>							
	Foundation - Concrete	Entire Building	10	LF	5	\$0	seepage and cracks
	Foundation - Concrete	Entire Building	10	LF	5	\$0	seepage
	Foundation - Concrete	Entire Building	20	LF	5	\$0	seepage
	Foundation - Concrete	Entire Building	3	LF	5	\$0	seepage
	Foundation - Concrete	Entire Building	10	LF	5	\$0	seepage and cracks
	Foundation - Concrete	Entire Building	10	LF	5	\$0	seepage and cracks
	Foundation - Concrete	Entire Building	20	LF	5	\$0	seepage and cracks
	Foundation - Concrete	Entire Building	4,387	LF	7	\$0	
	Foundation - Concrete	Entire Building	10	LF	5	\$0	cracks, spalling, exposed steel
	Foundation - Concrete	Entire Building	15	LF	5	\$0	seepage and cracks
	Superstructure - Concrete	Entire Building	150	SF	5	\$0	stress cracks
	Superstructure - Concrete	Entire Building	10	SF	5	\$0	step cracks
	Superstructure - Concrete	Entire Building	50	SF	5	\$0	stress cracks
	Superstructure - Concrete	Entire Building	706,954	SF	7	\$0	
<b>Lighting</b>							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	\$2,146	
	Exterior Lighting - Wall Mounted	Entire Building	96	EA	6	\$27,720	
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	5	\$2,564	Power may be severed.
<b>Roof System</b>							
	Cell Tower	Roof #7	1	EA	6	\$736	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof #4	60	LF	6	\$57,281	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof #4	60	LF	6	\$57,281	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof #7	45	LF	6	\$42,961	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof #7	120	LF	6	\$114,562	some open joints
	Chimney - Metal Flue	Roof #22	70	LF	6	\$11,070	rust
	Chimney - Metal Flue	Roof #7	80	LF	6	\$12,651	
	Chimney - Metal Flue	Roof #7	55	LF	6	\$8,698	
	Chimney - Metal Flue	Roof #7	80	LF	6	\$12,651	
	Coping - Metal	Roof #1	725	LF	6	\$23,285	
	Coping - Metal	Roof #17	260	LF	6	\$8,351	
	Coping - Metal	Roof #26	376	LF	6	\$12,076	
	Coping - Metal	Roof #3	334	LF	6	\$10,727	
	Coping - Metal	Roof #3	7	LF	5	\$496	flashing is peeled back
	Coping	Roof #11	495	LF	6	\$0	
	Coping - Terra Cotta	Roof #10	318	LF	6	\$10,213	
	Coping - Terra Cotta	Roof #11	94	LF	6	\$3,019	

**Building: Main**

**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Roof System</b>							
	Coping - Terra Cotta	Roof #12	43	LF	6	\$1,381	
	Coping - Terra Cotta	Roof #13	198	LF	6	\$6,359	
	Coping - Terra Cotta	Roof #14	88	LF	6	\$2,826	
	Coping - Terra Cotta	Roof #15	370	LF	6	\$11,884	
	Coping - Terra Cotta	Roof #16	119	LF	6	\$3,822	
	Coping - Terra Cotta	Roof #18	99	LF	6	\$3,180	
	Coping - Terra Cotta	Roof #19	86	LF	6	\$2,762	
	Coping - Terra Cotta	Roof #1 / East	166	LF	6	\$5,332	
	Coping - Terra Cotta	Roof #2	80	LF	5	\$10,611	open joints
	Coping - Terra Cotta	Roof #2	670	LF	6	\$21,519	
	Coping - Terra Cotta	Roof #20	43	LF	6	\$1,381	
	Coping - Terra Cotta	Roof #21	18	LF	6	\$578	
	Coping - Terra Cotta	Roof #22	290	LF	6	\$9,314	
	Coping - Terra Cotta	Roof #23	18	LF	6	\$578	
	Coping - Terra Cotta	Roof #24	192	LF	6	\$6,167	
	Coping - Terra Cotta	Roof #25	62	LF	6	\$1,991	
	Coping - Terra Cotta	Roof #26	140	LF	6	\$4,496	
	Coping - Terra Cotta	Roof #3	165	LF	6	\$5,299	
	Coping - Terra Cotta	Roof #4	1,429	LF	6	\$45,896	some open joints
	Coping - Terra Cotta	Roof #5	469	LF	5	\$78,723	some open joints
	Coping - Terra Cotta	Roof #5 / South	7	LF	5	\$1,072	gaps
	Coping - Terra Cotta	Roof #6	80	LF	6	\$2,569	
	Coping - Terra Cotta	Roof #7	504	LF	5	\$84,598	some open joints
	Coping - Terra Cotta	Roof #9	243	LF	6	\$7,805	
	Downspouts - Exterior Downspouts	Roof #1	15	LF	5	\$1,211	disconnected
	Downspouts - Exterior Downspouts	Roof #1	459	LF	6	\$15,254	
	Downspouts - Exterior Downspouts	Roof #15	15	LF	6	\$498	
	Downspouts - Exterior Downspouts	Roof #2	45	LF	6	\$1,495	
	Downspouts - Exterior Downspouts	Roof #4	18	LF	6	\$598	
	Downspouts - Interior Downspouts	Roof #10	240	LF	6	\$7,976	
	Downspouts - Interior Downspouts	Roof #11	20	LF	6	\$665	
	Downspouts - Interior Downspouts	Roof #12	50	LF	6	\$1,662	
	Downspouts - Interior Downspouts	Roof #13	36	LF	6	\$1,196	
	Downspouts - Interior Downspouts	Roof #14	19	LF	6	\$631	
	Downspouts - Interior Downspouts	Roof #15	200	LF	6	\$6,647	
	Downspouts - Interior Downspouts	Roof #16	19	LF	6	\$631	
	Downspouts - Interior Downspouts	Roof #17	34	LF	6	\$1,130	

**Building: Main**

**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Roof System</b>							
	Downspouts - Interior Downspouts	Roof #18	19	LF	6	\$631	
	Downspouts - Interior Downspouts	Roof #19	19	LF	6	\$631	
	Downspouts - Interior Downspouts	Roof #2	130	LF	6	\$4,320	
	Downspouts - Interior Downspouts	Roof #20	50	LF	6	\$1,662	
	Downspouts - Interior Downspouts	Roof #21	15	LF	6	\$498	
	Downspouts - Interior Downspouts	Roof #22	54	LF	6	\$1,795	
	Downspouts - Interior Downspouts	Roof #23	15	LF	6	\$498	
	Downspouts - Interior Downspouts	Roof #24	36	LF	6	\$1,196	
	Downspouts - Interior Downspouts	Roof #25	51	LF	6	\$1,695	
	Downspouts - Interior Downspouts	Roof #26	240	LF	6	\$7,976	
	Downspouts - Interior Downspouts	Roof #3	204	LF	6	\$6,780	
	Downspouts - Interior Downspouts	Roof #4	840	LF	6	\$27,916	
	Downspouts - Interior Downspouts	Roof #5	100	LF	6	\$3,323	
	Downspouts - Interior Downspouts	Roof #6	69	LF	6	\$2,293	
	Downspouts - Interior Downspouts	Roof #7	111	LF	6	\$3,689	
	Downspouts - Interior Downspouts	Roof #9	36	LF	6	\$1,196	
	Downspouts	Roof #11	198	LF	6	\$0	
	Parapet - 16" - 30" Height	Roof #10	258	LF	6	\$10,308	
	Parapet - 16" - 30" Height	Roof #11	94	LF	6	\$3,756	
	Parapet - 16" - 30" Height	Roof #13	198	LF	6	\$7,911	
	Parapet - 16" - 30" Height	Roof #14	88	LF	6	\$3,516	
	Parapet - 16" - 30" Height	Roof #16	119	LF	6	\$4,755	
	Parapet - 16" - 30" Height	Roof #18	99	LF	6	\$3,955	
	Parapet - 16" - 30" Height	Roof #19	86	LF	6	\$3,436	
	Parapet - 16" - 30" Height	Roof #1 / East	166	LF	6	\$6,632	
	Parapet - 16" - 30" Height	Roof #2	750	LF	6	\$29,966	
	Parapet - 16" - 30" Height	Roof #21	18	LF	6	\$719	
	Parapet - 16" - 30" Height	Roof #22	290	LF	6	\$11,587	
	Parapet - 16" - 30" Height	Roof #23	18	LF	6	\$719	
	Parapet - 16" - 30" Height	Roof #24	192	LF	6	\$7,671	
	Parapet - 16" - 30" Height	Roof #26	140	LF	6	\$5,594	
	Parapet - 16" - 30" Height	Roof #3	165	LF	6	\$6,592	
	Parapet - 16" - 30" Height	Roof #4	1,429	LF	6	\$57,095	
	Parapet - 16" - 30" Height	Roof #5	474	LF	6	\$18,938	
	Parapet - 16" - 30" Height	Roof #5 / South	4	LF	4	\$3,496	vertical gaps, movement
	Parapet - 16" - 30" Height	Roof #7	40	LF	6	\$1,598	
	Parapet - 16" - 30" Height	Roof #9	243	LF	6	\$9,709	



**Building: Main**

**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Roof System</b>							
	Parapet - Parapet < 16" Height	Roof #10	60	LF	6	\$1,278	
	Parapet - Parapet < 16" Height	Roof #17	260	LF	6	\$5,540	
	Parapet - Parapet > 30"	Roof #12	43	LF	6	\$2,749	
	Parapet - Parapet > 30"	Roof #15	370	LF	6	\$23,651	
	Parapet - Parapet > 30"	Roof #20	43	LF	6	\$2,749	
	Parapet - Parapet > 30"	Roof #25	62	LF	6	\$3,963	
	Parapet - Parapet > 30"	Roof #6	80	LF	6	\$5,114	
	Parapet - Parapet > 30"	Roof #7	464	LF	6	\$29,659	
	Parapet	Roof #11	60	LF	6	\$0	
	Parapet	Roof #11	70	LF	6	\$0	some open joints
	Parapet	Roof #11	365	LF	6	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #1	39,965	SF	7	\$0	gaps in clay tiles
	Roof Structure - Steel with Clay Tile Arch	Roof #10	6,448	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #11	1,446	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #11	8,862	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #12	469	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #13	2,996	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #14	1,284	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #15	7,480	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #16	594	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #17	6,810	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #18	1,186	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #19	900	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #2	11,944	SF	7	\$0	gaps in clay tiles
	Roof Structure - Steel with Clay Tile Arch	Roof #20	469	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #21	70	SF	6	\$1,261	
	Roof Structure - Steel with Clay Tile Arch	Roof #22	7,271	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #23	70	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #24	2,762	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #25	1,001	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #26	17,241	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #3	18,921	SF	7	\$0	gaps in clay tiles
	Roof Structure - Steel with Clay Tile Arch	Roof #4	43,678	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #5	12,897	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #6	6,050	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #7	8,830	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof #9	4,331	SF	7	\$0	

**Building: Main**

**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Roof System</b>							
	Roof - Asphalt Gravel Ballast	Roof #1	20	SF	3	\$561	roof leaks
	Roof - Asphalt Gravel Ballast	Roof #10	6,448	SF	4	\$180,725	surface deterioration, water ponding
	Roof - Asphalt Gravel Ballast	Roof #11	8,052	SF	4	\$225,681	surface deterioration, vegetative growth
	Roof - Asphalt Gravel Ballast	Roof #11	1,446	SF	4	\$40,528	surface deterioration, blisters
	Roof - Asphalt Gravel Ballast	Roof #12	469	SF	4	\$13,145	surface deterioration, vegetative growth
	Roof - Asphalt Gravel Ballast	Roof #13	2,996	SF	4	\$83,972	surface deterioration, vegetative growth
	Roof - Asphalt Gravel Ballast	Roof #14	25	SF	3	\$1,325	active roof leaks
	Roof - Asphalt Gravel Ballast	Roof #14	1,259	SF	4	\$35,287	water ponding, surface deterioration
	Roof - Asphalt Gravel Ballast	Roof #15	7,480	SF	4	\$209,649	surface deterioration
	Roof - Asphalt Gravel Ballast	Roof #16	594	SF	4	\$16,649	surface deterioration, water ponding
	Roof - Asphalt Gravel Ballast	Roof #17	6,810	SF	4	\$190,871	water ponding, severe blistering
	Roof - Asphalt Gravel Ballast	Roof #18	1,186	SF	4	\$33,241	water ponding, surface deterioration
	Roof - Asphalt Gravel Ballast	Roof #19	900	SF	4	\$25,225	deterioration, water ponding, vegetative growth
	Roof - Asphalt Gravel Ballast	Roof #20	469	SF	4	\$13,145	surface deterioration, vegetative growth
	Roof - Asphalt Gravel Ballast	Roof #22	7,271	SF	4	\$203,792	surface deterioration, vegetative growth
	Roof - Asphalt Gravel Ballast	Roof #24	2,762	SF	4	\$77,413	worn surface
	Roof - Asphalt Gravel Ballast	Roof #25	1,001	SF	5	\$23,633	vegetative growth
	Roof - Asphalt Gravel Ballast	Roof #26	12,348	SF	4	\$346,090	soft spots, surface deterioration, water ponding
	Roof - Asphalt Gravel Ballast	Roof #26 / North West	150	SF	3	\$7,949	active roof leak over auditorium
	Roof - Asphalt Gravel Ballast	Roof #3	30	SF	3	\$1,590	roof leaks
	Roof - Asphalt Gravel Ballast	Roof #3	10,304	SF	4	\$288,801	water ponding, surface deterioration, vegetative growth
	Roof - Asphalt Gravel Ballast	Roof #4	35,978	SF	4	\$1,008,391	surface deterioration, vegetative growth
	Roof - Asphalt Gravel Ballast	Roof #5	12,897	SF	4	\$361,477	worn surface, vegetation
	Roof - Asphalt Gravel Ballast	Roof #6	6,050	SF	4	\$169,569	surface deterioration, vegetative growth
	Roof - Asphalt Gravel Ballast	Roof #7	8,830	SF	4	\$247,487	blisters, worn surface
	Roof - Asphalt Gravel Ballast	Roof #9	4,331	SF	4	\$121,389	surface deterioration, water ponding, vegetative growth
	Roof - Metal	Roof #21	70	SF	6	\$938	
	Roof - Metal	Roof #23	70	SF	6	\$938	
	Roof - Metal	Roof #26	280	SF	6	\$3,752	
	Roof - Metal	Roof #3	215	SF	6	\$2,881	
	Roof - Modified Bitumen	Roof #1	13,050	SF	6	\$122,793	
	Roof - Modified Bitumen	Roof #11	972	SF	6	\$9,146	
	Roof - Modified Bitumen	Roof #2	9,757	SF	5	\$205,241	poor seams, water ponding
	Roof - Modified Bitumen	Roof #3	6,012	SF	6	\$56,569	
	Roof - Modified Bitumen	Roof #4	2,184	SF	5	\$45,941	poor seams, water ponding
	Roof - Slate Shingle	Roof #1	10,875	SF	6	\$93,930	

**Building: Main**
**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Roof System</b>							
	Roof - Slate Shingle	Roof #2	3,210	SF	5	\$64,586	gaps, movement
	Roof - Slate Shingle	Roof #26	6,516	SF	6	\$56,280	
	Roof - Slate Shingle	Roof #3	5,010	SF	6	\$43,272	
	Roof - Slate Shingle	Roof #4	4,932	SF	5	\$99,232	shifting & loose tiles
<b>Walls</b>							
	Cheek-Wall - Concrete	Entire Building	12	SF	4	\$704	deterioration
	Cheek-Wall - Concrete	Entire Building	12	SF	4	\$704	deterioration
	Cheek-Wall - Stone	Entire Building	64	SF	6	\$656	
	Cheek-Wall - Stone	Entire Building	100	SF	6	\$1,025	
	Cheek-Wall - Stone	Entire Building	48	SF	4	\$9,288	deterioration
	Cheek-Wall - Stone	Entire Building	80	SF	5	\$1,904	cracks
	Cheek-Wall - Stone	Entire Building	80	SF	6	\$820	
	Cheek-Wall - Stone	Entire Building	40	SF	6	\$410	
	Cheek-Wall - Stone	Entire Building	50	SF	5	\$1,190	open joints
	Cheek-Wall - Stone	Entire Building	40	SF	5	\$952	spalling
	Cornice - Terra Cotta	Entire Building	11,462	LF	5	\$1,961,142	some open joints
	Exterior Walls - Brick	Entire Building	30	SF	5	\$714	Efflorescence,open joints
	Exterior Walls - Brick	Entire Building	146,123	SF	6	\$982,093	some open joints, vines are present
	Exterior Walls - Brick	Entire Building	480	SF	4	\$79,032	Vertical Cracks
	Exterior Walls - Brick	Entire Building	80	SF	4	\$13,172	Netting, presumed to be foiling
	Exterior Walls - Brick	Entire Building	40	SF	4	\$6,586	movement, open joints, broken brick
	Exterior Walls - Brick	Entire Building	10	SF	5	\$238	Gaps above windows
	Exterior Walls - Brick	Entire Building	15	SF	4	\$2,470	Vertical Crack
	Exterior Walls - Brick	Entire Building	30	SF	4	\$4,940	Vertical Cracks
	Exterior Walls - Brick	Entire Building	10	SF	4	\$1,647	vertical Cracks
	Exterior Walls - Brick	Entire Building	15	SF	5	\$357	Step Cracks
	Exterior Walls - Brick	Entire Building	80	SF	4	\$13,172	Bulging
	Exterior Walls - Brick	Entire Building	10	SF	4	\$1,647	Vertical cracks
	Exterior Walls - Brick	Entire Building	10	SF	5	\$238	stepcracks
	Exterior Walls - Brick	Entire Building / East Façade	300	SF	5	\$7,143	Efflorescence, open joints, cracks
	Exterior Walls - Brick	Entire Building / North Façade	80	SF	5	\$1,905	Efflorescence, open joints, cracks
	Exterior Walls - Brick	Entire Building / West Façade	80	SF	5	\$1,905	Efflorescence, Open Joints
	Exterior Walls - Concrete Block	Entire Building / Roofs	610	SF	6	\$4,100	
	Exterior Walls - Stone-Cast	Entire Building	30	SF	4	\$5,448	Spalling,shear
	Exterior Walls - Stone-Cast	Entire Building	20	SF	4	\$3,632	spalling, shearing
	Exterior Walls - Stone-Cast	Entire Building	5	SF	4	\$908	spauling,shearing
	Exterior Walls - Stone-Cast	Entire Building	8,924	SF	6	\$59,978	some open joints

**Building: Main**
**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Walls</b>							
	Exterior Walls - Stone-Cast	Entire Building	15	SF	4	\$2,724	spalling,cracks
	Exterior Walls - Stone-Cast	Entire Building	25	SF	4	\$4,540	Spalling Corner Shear
	Exterior Walls - Terra Cotta	Entire Building	4	SF	4	\$2,595	cracked
	Exterior Walls - Terra Cotta	Entire Building	16	SF	4	\$10,378	cracks, spalling, movement
	Exterior Walls - Terra Cotta	Entire Building / East	130	SF	4	\$77,043	Netting on wall
	Exterior Walls - Terra Cotta	Entire Building / North	220	SF	4	\$130,380	Netting on wall
	Exterior Walls - Terra Cotta	Entire Building / South Façade	90	SF	4	\$53,337	netting on wall
	Exterior Walls - Terra Cotta	Entire Building / West	130	SF	4	\$77,043	Netting on Wall
<b>Windows</b>							
	Curtain wall - Insulated Panel	Entire Building	420	SF	6	\$4,709	
	Curtain wall - Louver	Entire Building	120	SF	6	\$1,345	
	Guard - Guards perforated	Entire Building / East Façade	76	SF	6	\$971	
	Guard - Guards wire guard	Entire Building	5,700	SF	6	\$72,788	
	Lintels - Brick	Entire Building / South Courtyard Façades	189	LF	6	\$0	
	Lintels - Steel	Entire Building	4,617	LF	6	\$134,027	
	Lintels - Steel	Entire Building	8	LF	4	\$0	sagging
	Lintels - Terra Cotta	Entire Building	1,590	LF	5	\$302,629	open joints
	Lintels - Terra Cotta	Entire Building / West Courtyard	46	LF	4	\$20,554	loose, cracks
	Skylite - Glass Single-Pane	Entire Building	723	SF	5	\$43,279	broken panes, poor glazing
	Skylite - Glass Single-Pane	Entire Building	221	SF	5	\$13,229	broken panes, poor glazing
	Skylite - Glass Single-Pane	Entire Building	130	SF	5	\$7,782	broken panes
	Skylite - Glass Single-Pane	Entire Building	240	SF	5	\$14,366	broken panes
	Skylite - Glass Single-Pane	Entire Building	1,262	SF	6	\$30,156	
	Windows - Decorative	Entire Building	788	SF	6	\$5,882	
	Windows - Decorative	Entire Building / North West	60	SF	6	\$448	
	Windows - Sash Aluminum Double-pane	Entire Building	57,912	SF	5	\$3,119,609	poor balances, poor insulation, 2% have broken panes
	Windows - Sash Aluminum	Entire Building / East Façade	10,488	SF	5	\$376,596	poor balances, poor insulation

**Building Exterior Subtotal:**
**\$14,049,856**
**Building: Main**
**Category: Electrical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Emergency System</b>							
	Automatic Transfer Switch	Basement	1	EA	6	\$408	(No Other Information Available)

## Building: Main

### Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Emergency System</b>							
	Automatic Transfer Switch	Basement	1	EA	6	\$408	(No Other Information Available)
	Emergency A/C Power - Auditorium and Aisle Lighting	Entire Building / 1st Floor	19,935	SF	6	\$10,548	
	Emergency A/C Power - Corridors and Stairs	Entire Building	151,405	SF	6	\$45,467	
	Emergency A/C Power - Gym	Entire Building	26,036	SF	6	\$9,680	
	Emergency A/C Power - Lunchrooms	Entire Building / 1st Floor	15,743	SF	6	\$5,853	
	Emergency A/C Power - Multipurpose Room	Entire Building	10,595	SF	6	\$3,939	
	Emergency A/C Power - Pool	Entire Building / 1st Floor	7,543	SF	6	\$2,804	
	Emergency A/C Power - Students Toilets	Entire Building	7,608	SF	6	\$2,829	
	Emergency Generator- Outdoor- Natural Gas - Below 60 KW	Outside Next to Boiler Room building	1	EA	7	\$0	Outside Next to Boiler Room building
	Exit Signs - Auditorium	Entire Building / 1st Floor	16	EA	6	\$2,396	
	Exit Signs - Corridors and Stairs	Entire Building	194	EA	6	\$29,051	
	Exit Signs - Gym	Entire Building / 2nd Floor	4	EA	6	\$630	
	Exit Signs - Lunchroom	Entire Building / 1st Floor	4	EA	6	\$599	
	Exit Signs - Multipurpose Room	Entire Building / 2nd Floor	2	EA	6	\$299	
	Exit Signs - Pool	Entire Building / 1st Floor	4	EA	6	\$620	
<b>Main Service</b>							
	Main Electrical Service - 1000 A 120/208/3PH	Electrical Room / Basement	1	EA	6	\$4,540	
	Main Electrical Service - 1000 A 120/208/3PH	Electrical Room	1	EA	6	\$4,540	Room #4
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	\$5,641	Room #1
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	\$10,867	Room #3/5
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	\$10,867	Room #2
	PA System	1st Floor	707,164	SF	6	\$232,586	
<b>Power Distribution</b>							
	Lighting and Power Panels - 100 A	1st Floor	1	EA	6	\$299	Creiger 120/208V 3P 4W 100A (No other Information Available)
	Lighting and Power Panels - 100 A	1st Floor	1	EA	6	\$299	Electrical Panel Guttred, used as a pull box
	Lighting and Power Panels - 100 A	1st Floor	1	EA	6	\$299	Creiger 120/208V 3P 4W 100A (No other Information Available)
	Lighting and Power Panels - 100 A	1st Floor	1	EA	4	\$4,849	Panel: KIT/CE4 120/208v 3P 4W 100A M#: S35275, S#: 14180; Live front
	Lighting and Power Panels - 100 A	1st Floor	1	EA	6	\$299	Panel No: EM-N-2 (No Other Information Available)
	Lighting and Power Panels - 100 A	1st Floor	1	EA	6	\$299	Panel No.: EM-N-1 (No Other Information Available)
	Lighting and Power Panels - 100 A	1st Floor	1	EA	6	\$299	Panel "A" 120/208V 3P 4W, 100A 42CCT, Eaton-Cutler Hammer S# A0007031B, M# 21408006 Feeds Room 134 Wall AC's #1, #2, #3, & #4, Outlets, Reels, projectionunit & wall outlets

**Building: Main**

**Category: Electrical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Power Distribution</b>							
	Lighting and Power Panels - 100 A	4th Floor	1	EA	6	\$299	120/208V 3P 4W 70A (No other Information Available)
	Lighting and Power Panels - 100 A	4th Floor	1	EA	6	\$299	SqD 120/208V 3P 4W 30A (No other Information Available)
	Lighting and Power Panels - 100 A	4th Floor	1	EA	6	\$299	120/208V 3P 4W 70A (No other Information Available)
	Lighting and Power Panels - 100 A	4th Floor	1	EA	6	\$299	120/208V 3P 4W 70A (No other Information Available)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Eaton/Cutler Hammer S#; SC9008554=001 120/208V 3P 4W 200A (No other Information Available)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Eaton/Cutler Hammer S#; SC9008554=001 120/208V 3P 4W 200A (No other Information Available)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Creiger 120/208v 3P 4W 200A S#: E89915461 (Exterior Lighting)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Eaton 120/208v 3P 4W 200A M#: EZB2048R Serves Room 140
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Siemens 120/208v 3P 4W, 225 amp M#BD565243 S#. 26300 (Two Section Panel),
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Panel L-154, Cresier Lighting Panel 120/208V 3P 4W, 225A
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Airport Electrical Pnl, 208V 3P 4W, 220A (No Other Information Available)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Panel No: RP-1CE Eaton/Cutler Hammer 120/208V 3P 4 W 225A, (No other information Available)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Eaton 120/208v 3P 4W 200A M#: EZB2048R (Serves 1st FL: Bathrooms and Bathroom Lighting)
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	\$994	Pnl No's 157A & 157B 120/208V 3P 4 W 225A Elect Pnl (No Other Information Available)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	120/208V 3P 4W 225A Elect Pnl (No Other Information Available)
	Lighting and Power Panels - Above 100 A	1st Floor	2	EA	6	\$994	(2) Creiger Pnls M# 565318, S#: 26200 120/208V 3P 4 W 225A Elect Pnl (No Other Information Available)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Panel No: E-L-R 120/208V 3P 4W 225A (No Other Information Available)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Panel L-1SW, Cresier Lighting Panel 120/208V 3P 4W, 225A,, 42 CCT/section (2 section Panel), Feeds M# BD565243, S# 26200 Feed Corridor Lighting SW
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Airport Electric Panel: PP124A 208v 3P 3W, 200A 30 Fuses, Feeds Room 124A, Wall Outlets

**Building: Main**

**Category: Electrical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Power Distribution</b>							
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Eaton-Cutler Hammer 120/208V 3P 4W, 200A, 42 CCT (No M#, S# or Pnl Sch Present)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Siemens 120/208v 3P 4W, 225 amp panel CCT 24 M#G244263200CU, (No Panel Schedule Present)
	Lighting and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Panel L-155, Cresier Lighting Panel 120/208V 3P 4W, 225A,, 30 Fuses, Feeds locker room lighting & pool office,
	Lighting and Power Panels - Above 100 A	2nd Floor	1	EA	6	\$497	ITE Panel 120/208V 3P 4W 225A (No other Information Available)
	Lighting and Power Panels - Above 100 A	2nd Floor	1	EA	6	\$497	120/208V 3P 4W 225A (No other Information Available)
	Lighting and Power Panels - Above 100 A	2nd Floor	1	EA	6	\$497	120/208V 3P 4W 200A (No other Information Available)
	Lighting and Power Panels - Above 100 A	2nd Floor	1	EA	6	\$497	120/208V 3P 4W 225A (No other Information Available)
	Lighting and Power Panels - Above 100 A	3rd Floor	1	EA	6	\$497	120/208V 3P 4W 225A (No other Information Available)
	Lighting and Power Panels - Above 100 A	3rd Floor	1	EA	6	\$497	Siemens 120/208V 3P 4W 225A (No other Information Available)
	Lighting and Power Panels - Above 100 A	3rd Floor	1	EA	6	\$497	120/208V 3P 4 W 225A Elect Pnl (No Other Information Available)
	Lighting and Power Panels - Above 100 A	3rd Floor	2	EA	6	\$994	(2) 120/208V 3P 4W 225A Elect Pnls (No Other Information)
	Lighting and Power Panels - Above 100 A	3rd Floor	1	EA	6	\$497	120/208V 3P 4W 225A Elect Pnls (No Other Information)
	Lighting and Power Panels - Above 100 A	3rd Floor	1	EA	6	\$497	120/208V 3P 4W 225A Elect Pnls (No Other Information)
	Lighting and Power Panels - Above 100 A	3rd Floor	1	EA	6	\$497	120/208V 3P 4W 225A Elect Pnls (No Other Information)
	Lighting and Power Panels - Above 100 A	3rd Floor	1	EA	6	\$497	120/208V 3P 4 W 225A Elect Pnl (No Other Information Available)
	Lighting and Power Panels - Above 100 A	3rd Floor	2	EA	6	\$994	(2) 120/208V 3P 4W 225A Elect Pnls (No Other Information)
	Lighting and Power Panels - Above 100 A	4th Floor	1	EA	6	\$497	Panel No. L-4CE 120/208V 3P 4W 200A (No other Information Available)
	Lighting and Power Panels - Above 100 A	4th Floor	1	EA	6	\$497	120/208V 3P 4W 225A (No other Information Available)
	Lighting and Power Panels - Above 100 A	4th Floor	1	EA	6	\$497	GE 120/208V 3P 4W 225A (M#: AXTiB4, S#: (No other Information Available)
	Lighting and Power Panels - Above 100 A	4th Floor	1	EA	6	\$497	GE 120/208V 3P 4W 225A (M#: AXTiB4, S#: (No other Information Available)
	Lighting and Power Panels - Above 100 A	4th Floor	1	EA	6	\$497	120/208V 3P 4W 225A (No other Information Available)

**Building: Main**

**Category: Electrical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Power Distribution</b>							
	Lighting and Power Panels - Above 100 A	Basement	1	EA	6	\$497	
	Lighting and Power Panels - Above 100 A	Basement / Electrical Room	1	EA	6	\$497	
	Lighting and Power Panels - Above 100 A	Outside Classroom 122 / 1st Floor	1	EA	6	\$497	Panel: L-122, 120/208V 3P 4W, 200A 36CCT, S# E89915461, No M# Feeds Exterior Lights
	Lighting and Power Panels - Above 100 A	Outside Storage Room 437B / 1st Floor	1	EA	6	\$497	120/208V 3P 4W 225A, 42 CCT, M# AXT1B4, S# AQU3422RCX A-Series II Panel Board, (No Panel Schedule)
	Lighting and Power Panels - Above 100 A	Penthouse	2	EA	6	\$994	
	Main Distribution Panels - 400 - 600 amp	Basement / Boiler Room	1	EA	4	\$13,694	
	Main Distribution Panels - 400 - 600 amp	Basement / Boiler Room	1	EA	4	\$13,694	
	Main Distribution Panels - Greater than 600 amp	Basement / Boiler Room	1	EA	6	\$730	
	Main Distribution Panels - Less than 400 amp	Basement / Boiler Room	1	EA	6	\$503	
	Main Distribution Panels - Less than 400 amp	Basement / Boiler Room	1	EA	6	\$503	
	Transformers - 120/240 - 120/208	1st Floor	3	EA	6	\$9,064	(No Other Information Available)
	Transformers - 120/240 - 120/208	1st Floor	1	EA	6	\$3,021	Square D Feeds 3 100 amp electrical panels
	Transformers - 120/240 - 120/208	Penthouse	2	EA	6	\$6,043	

**Electrical System Subtotal:**

**\$462,530**

**Building: Main**

**Category: Safty System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Fire Alarm</b>							
	Fire Alarm Panel	Entire Building	2	EA	6	\$12,812	Location: Assistant Principles Office (Monitoring Station)
	Fire Alarm Panel	Entire Building	1	EA	6	\$6,406	Location Security (Monitoring Station)
	Fire Alarm Strobe Lights	Entire Building	707,164	SF	6	\$252,811	Strobe Lights located throughout the building
	Fire Alarm_System	Entire Building	707,164	SF	6	\$343,823	Audible alarms located throughout the entire building

**Safty System Subtotal:**

**\$615,852**

**Building: Main**

**Category: Mechanical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Air Conditioning</b>							
	Condensing Unit- Ground Mounted - 11-20 tons	1st Floor / Mechanical Room	1	EA	4	\$19,823	S#: 17811278015, M#: 5100-4-18A, R22, HP = 1/3, 208V 3P FLA = 66



## Building: Main

### Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Air Conditioning</b>							
	Condensing Unit- Roof Mounted - 11-20 tons	Lower Roof	1	EA	6	\$3,727	
	Condensing Unit- Roof Mounted - 5-10 tons	Lower Roof / Lower Roofs	1	EA	6	\$3,334	
	Condensing Unit- Roof Mounted - 5-10 tons	Lower Roof / Lower Roofs	1	EA	6	\$3,334	
<b>Air Handling Systems</b>							
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 10001-15000 cfm	Basement	1	EA	5	\$52,178	(No other Information Available)
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 10001-15000 cfm	Basement	1	EA	5	\$52,178	(No other Information Available)
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 10001-15000 cfm	Basement	1	EA	5	\$52,178	(No other Information Available)
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 10001-15000 cfm	Basement	1	EA	5	\$52,178	(No other Information)
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 10001-15000 cfm	Basement / Mechanical Room	1	EA	5	\$52,178	(No other Information Available)
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 10001-15000 cfm	Basement / Mechanical Room	1	EA	5	\$52,178	(No other Information)
	Air Intake	Basement / Plenum	5	EA	6	\$28,823	
	Make Up Air Unit- Indoor Mounted- Steam Coils - 10,001 - 20,000 cfm	4th Floor	1	EA	6	\$3,334	Fan No. 4 (No other Information Available)
	Make Up Air Unit- Indoor Mounted- Steam Coils - 10,001 - 20,000 cfm	4th Floor	1	EA	6	\$3,334	Fan No. 12 (No other Information Available)
	Make Up Air Unit- Indoor Mounted- Steam Coils - 10,001 - 20,000 cfm	Penthouse	1	EA	5	\$42,077	Leaking Bearings & Motor Housing (No Other Information Available)
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Roof	4	EA	6	\$13,400	
	Zone Dampers	Basement	279	EA	5	\$533,878	
<b>Boiler Systems</b>							
	Boiler Auxiliary- Scotch Marine- Steam High Pressure Boiler - 150 - 300 HP	Boiler Room	4	EA	5	\$86,823	
	Boiler Auxiliary- Scotch Marine- Steam High Pressure Boiler - 150 - 300 HP	Boiler Room	1	EA	5	\$21,706	Tube Leaks
	Combustion Dampers	Boiler Room	3	EA	6	\$1,227	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	\$36,450	Location: Pump Room
	Non Condensing- Fire Tube- Scotch Marine- Steam- High Pressure Boiler - 150 - 300 HP	Boiler Room	1	EA	5	\$21,706	
	Non Condensing- Fire Tube- Scotch Marine- Steam- High Pressure Boiler - 150 - 300 HP	Boiler Room	4	EA	5	\$86,823	
	Piping - Condensate Pipe- Steel	Boiler Room	3,000	LF	5	\$39,296	
	Piping - Steam Pipe- Steel	Boiler Room / Entire Building	3,000	LF	5	\$44,959	Piping, Valve Stems Leaking, and Corrosion Present
	Steam Traps	Boiler Room / Entire Building	100	EA	5	\$131,490	Traps Leaking (Replacement Needed)

## Building: Main

### Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Heat Exchangers</b>							
	Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	3	EA	5	\$34,605	
	Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	1	EA	4	\$32,861	
<b>Heating Devices</b>							
	Cabinet Heaters - With Steam Coil	Entire Building	9	EA	5	\$15,865	
	Fin Tube - Electric	Entire Building	40	LF	6	\$378	
	Fin Tube - Hot Water	Entire Building	6	LF	4	\$965	
	Fin Tube - Hot Water	Entire Building	132	LF	6	\$1,246	
	Radiators - Steam	Entire Building	6	EA	4	\$21,943	
	Radiators - Steam	Entire Building	218	EA	5	\$365,219	
	Radiators - Steam	Entire Building	13	EA	5	\$21,779	
	Unit Heater - Electric	Shipping & Receiving / 1st Floor	2	EA	4	\$4,002	
	Unit Heater - Hot Water	Boiler Room	2	EA	6	\$558	
	Wall Heater - Electric	Entire Building	3	EA	5	\$1,610	
	Wall Heater - Electric	Entire Building	19	EA	6	\$2,639	
<b>Mechanical Plumbing</b>							
	Condensate-Steel or Galvanized	Entire Building	3,000	LF	6	\$230,330	require frequent repairs, Petcocks leak, drain lines leak, steam traps malfunction and in some cases don;t work at all.
	Condenser Pump - Less than 10	Boiler Room	4	EA	6	\$4,445	M#: BC284TT, S#: 732828BBW 2HP 1760 RPM
	Hydronic Supply and Return - Steel	Entire Building	1,000	LF	6	\$76,777	
<b>Temperature Control</b>							
	Pneumatic System	Entire Building	707,164	SF	4	\$3,680,930	Engineer says "none"
	Thermostats - Pneumatic	Entire Building	30	EA	4	\$22,117	
	Thermostats - Pneumatic	Entire Building	195	EA	6	\$0	
<b>Ventilation</b>							
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	1	EA	6	\$592	Location 125 (No Other Information Available)
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	1	EA	6	\$592	Location 119 (No Other Information Available)
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	1	EA	6	\$592	M# 56ABA, S#: 1361811 1/6HP 1725 RPM (No Other Information Available)
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	2	EA	6	\$1,185	(No Other Information Available) Location: Room 123
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	1	EA	6	\$592	(No other Information Available)
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	1	EA	6	\$592	(No other Information Available)
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	1	EA	6	\$592	(No other Information Available)
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	1	EA	6	\$592	(No other Information Available)

**Building: Main**
**Category: Mechanical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Ventilation</b>							
	Exhaust Fans- Indoor - 500 - 1500 CFM	1st Floor	2	EA	6	\$1,185	Location Room 123 GE Motor, M# 5KC35JN10GX S# SEL/ RPM 1725, HP 1/4 208V Single Phase, 6.2A, Belt Driven, Greenheck Fan M#SPF4-30-4, S# 91E02391, Manual Dampers
	Exhaust Fans- Indoor - 500 - 1500 CFM	2nd Floor	1	EA	6	\$592	Location Room 220 (No Other Information Available)
	Exhaust Fans- Indoor - 500 - 1500 CFM	4th Floor	1	EA	6	\$592	
	Exhaust Fans- Indoor - 500 - 1500 CFM	4th Floor	1	EA	6	\$592	
	Exhaust Fans- Indoor - 500 - 1500 CFM	4th Floor	1	EA	6	\$592	
	Exhaust Fans- Indoor - 500 - 1500 CFM	4th Floor	1	EA	6	\$592	
	Exhaust Fans- Indoor - 500 - 1500 CFM	4th Floor	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	1st Floor	2	EA	4	\$8,489	(No Other Information Available)
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	7	\$0	Fan in place, but abandoned
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	4	\$8,489	(No Other Information Available)
	Lab Exhaust Hood	1st Floor	2	EA	6	\$2,495	Kewaunee Scientific Corp. M# Q-2108-00, Dayton Motor M# SC195(No Other Information Available)
	Lab Exhaust Hood	2nd Floor	2	EA	6	\$2,495	(No Other Information Available)
	Roof Mounted Duct Work	Main Roof / Main Roofs	40	LF	6	\$15,161	12"x12" SS Duct is capped off, Location Ctr of Room, approx 12 A.F.F. and should be removed completely. No Longer needed.
	Roof Mounted Duct Work	Roof	50	LF	6	\$18,951	Fan in place, but abandoned & duct capped off inside
	Type I Exhaust Hood- Culinary Arts	1st Floor	3	EA	6	\$3,743	

**Mechanical System Subtotal:**
**\$6,026,777**
**Building: Main**
**Category: Plumbing System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Hot Water</b>							
	Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Basement	1	EA	6	\$678	
<b>Piping</b>							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	707,164	SF	4	\$505,622	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	707,164	SF	4	\$1,021,357	
	Domestic Piping-Cold Water Risers	Entire Building	707,164	SF	6	\$131,462	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	707,164	SF	6	\$111,237	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	707,164	SF	4	\$910,120	
	Domestic Piping-Hot Water Return Lines	Entire Building	707,164	SF	4	\$606,747	

**Building: Main**
**Category: Plumbing System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Piping</b>							
	Domestic Piping-Hot Water Return Risers	Entire Building	707,164	SF	4	\$343,823	
	Sanitary Piping	Entire Building	707,164	SF	4	\$2,457,324	
	Storm Piping	Entire Building	707,164	SF	4	\$2,447,212	
	Vent Piping	Entire Building	707,164	SF	4	\$1,729,228	
<b>Pool Systems</b>							
	Pool Drain Piping	Basement	60	LF	7	\$0	
	Pool Filtration System including Pump	Basement	1	EA	6	\$12,330	
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	6	\$310	
	Pool Supply and Return Piping	Basement	610	LF	7	\$0	
<b>Pumps</b>							
	Pumps - Domestic Booster Pump-Duplex	Auditorium (Wheel Chair Lift) / 1st Floor	1	EA	6	\$1,977	Auditorium
	Pumps - Domestic Booster Pump-Duplex	Basement	1	EA	6	\$1,977	Location: Pump Room
	Pumps - Domestic Booster Pump-Duplex	Entire Building / Boiler Room	1	EA	4	\$46,158	
	Pumps - Domestic Booster Pump-Duplex	Entire Building / Mechanical Room	1	EA	4	\$46,158	
	Pumps - Ejector-Duplex	Basement and Boiler room / Basement	5	EA	4	\$78,746	Pits are full of water, pipes leaking and corroded
	Pumps - Ejector-Simplex	Basement and Boiler room / Boiler Room	2	EA	2	\$22,887	Both pumps were broken and water was 12" from reaching the top of the Boiler Room Floor.
	Pumps - Sump-Simplex	Elevator Room 440B / 4th Floor	1	EA	5	\$5,627	Passenger Elevator (Maintenance & Operational issues due to age)
	Pumps - Sump-Simplex	Freight Elevator (Basement) / Basement	1	EA	6	\$745	
<b>Plumbing System Subtotal:</b>						<b>\$10,481,724</b>	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #104 (Regular Classroom)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	1st Floor	997	SF	6	\$3,450	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	997	SF	6	\$7,029	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,697	SF	6	\$4,684	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #104 (Regular Classroom)</b>							
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #106 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	1st Floor	722	SF	5	\$6,618	peeling
	Chalk Board	1st Floor	18	LF	6	\$402	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	722	SF	6	\$5,090	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	36	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,404	SF	6	\$3,875	
<b>Classroom #107E (Regular Classroom)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	5	\$6,691	peeling
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	720	SF	6	\$5,076	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,427	SF	6	\$3,938	
<b>Classroom #110 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	4	\$6,086	not working
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	1st Floor	735	SF	6	\$2,544	
	Chalk Board	1st Floor	8	LF	4	\$734	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	735	SF	6	\$5,182	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,394	SF	6	\$3,847	
<b>Classroom #111 (Regular Classroom)</b>							
	Casework	1st Floor	16	LF	6	\$404	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #111 (Regular Classroom)</b>							
	Ceiling - Plaster/Drywall	1st Floor	714	SF	5	\$6,545	peeling
	Chalk Board	1st Floor	4	LF	4	\$367	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	714	SF	6	\$5,034	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	36	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	25	SF	5	\$128	peeling
	Walls - Plaster/Drywall	1st Floor	1,373	SF	6	\$3,789	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #112 (Regular Classroom)</b>							
	Casework	1st Floor	14	LF	6	\$354	
	Ceiling - Lay-in	1st Floor	1,054	SF	6	\$3,165	8sf has water stains
	Chalk Board	1st Floor	6	LF	4	\$551	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	1,104	SF	6	\$7,783	
	Lighting - Pendent/Surface	1st Floor	30	EA	7	\$0	
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,306	SF	6	\$3,604	
	Walls - Plaster/Drywall	1st Floor	50	SF	5	\$255	peeling
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #114 (Computer Lab)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	1st Floor	770	SF	6	\$2,665	
	Charging Station	1st Floor	4	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	770	SF	6	\$5,428	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	18	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,450	SF	6	\$4,002	
	Wireless System	1st Floor	1	EA	7	\$0	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #115 (Science)</b>							
	Casework	1st Floor	75	LF	6	\$1,894	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #115 (Science)</b>							
	Ceiling - Lay-in	1st Floor	1,053	SF	6	\$3,162	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Eye Wash Station	1st Floor	1	EA	7	\$0	
	Floor - Tile	1st Floor	1,053	SF	6	\$2,304	
	Fume Hood	1st Floor	1	EA	6	\$816	
	Gas Line	1st Floor	6	EA	6	\$3,055	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	\$0	
	Marker Board	1st Floor	11	LF	7	\$0	
	Science Lab Shower	1st Floor	1	EA	7	\$0	
	Storage/ Closet	1st Floor	284	SF	6	\$2,059	
	Walls - Plaster/Drywall	1st Floor	1,446	SF	6	\$3,991	
	Work Sink	1st Floor	10	EA	6	\$3,790	
<b>Classroom #117 (Science Classroom)</b>							
	Casework	1st Floor	12	LF	6	\$303	
	Ceiling - Lay-in	1st Floor	588	SF	6	\$1,766	
	Chalk Board	1st Floor	6	LF	4	\$551	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	588	SF	6	\$1,286	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	\$0	
	Marker Board	1st Floor	6	LF	7	\$0	
	Storage/ Closet	1st Floor	8	SF	6	\$58	
	Walls - Plaster/Drywall	1st Floor	1,116	SF	6	\$3,080	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #119 (Science)</b>							
	Casework	1st Floor	117	LF	6	\$2,955	
	Ceiling - Lay-in	1st Floor	41	SF	5	\$327	ceiling is leaking. water damaged tiles.
	Ceiling - Lay-in	1st Floor	900	SF	6	\$2,703	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	1 door is missing a handle
	Floor - Tile	1st Floor	941	SF	6	\$2,059	there is standing water on floor, from leaking ceiling
	Gas Line	1st Floor	6	EA	6	\$3,055	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,417	SF	6	\$3,911	
	Work Sink	1st Floor	5	EA	6	\$1,895	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #119 (Science)</b>							
<b>Classroom #120 (Regular Classroom)</b>							
	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	1st Floor	16	SF	5	\$200	peeling
	Ceiling - Plaster/Drywall	1st Floor	954	SF	6	\$3,301	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	970	SF	6	\$6,838	
	Lighting - Pendent/Surface	1st Floor	27	EA	7	\$0	
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,608	SF	6	\$4,438	
	Walls - Plaster/Drywall	1st Floor	50	SF	5	\$255	peeling
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #122 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st Floor	913	SF	7	\$0	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	913	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	\$0	
	Marker Board	1st Floor	18	LF	7	\$0	
	Storage/ Closet	1st Floor	10	SF	6	\$73	
	Walls - Plaster/Drywall	1st Floor	124	SF	7	\$0	Under remodel
<b>Classroom #123 (Science)</b>							
	Casework	1st Floor	148	LF	6	\$3,738	
	Ceiling - Lay-in	1st Floor	1,016	SF	6	\$3,051	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	1,016	SF	6	\$2,223	
	Gas Line	1st Floor	6	EA	6	\$3,055	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	282	SF	6	\$2,045	
	Walls - Plaster/Drywall	1st Floor	1,449	SF	6	\$3,999	
	Work Sink	1st Floor	1	EA	4	\$8,619	sink missing & faucet is broken
	Work Sink	1st Floor	6	EA	6	\$2,274	



**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #124 (Special Program)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	1st Floor	2,800	SF	6	\$9,690	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Carpet	1st Floor	555	SF	6	\$1,183	Mezzanine floor
	Floor - Wood	1st Floor	2,245	SF	6	\$15,827	
	Lighting - Pendent/Surface	1st Floor	3	EA	4	\$1,622	T-12 in closet
	Lighting - Pendent/Surface	1st Floor	54	EA	7	\$0	
	Marker Board	1st Floor	6	LF	7	\$0	
	Storage/ Closet	1st Floor	191	SF	6	\$1,385	
	Walls - Structural Glazed Tile	1st Floor	2,984	SF	6	\$9,388	
<b>Classroom #125 (Science)</b>							
	Casework	1st Floor	96	LF	6	\$2,424	
	Ceiling - Lay-in	1st Floor	950	SF	6	\$2,853	
	Chalk Board	1st Floor	18	LF	4	\$1,653	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	950	SF	6	\$2,079	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	32	SF	6	\$232	
	Walls - Plaster/Drywall	1st Floor	1,460	SF	6	\$4,029	6 sf of wall has a crack
	Work Sink	1st Floor	5	EA	6	\$1,895	
<b>Classroom #128 Aquaponics (Special Program)</b>							
	AC Units		3	EA	6	\$1,487	
	Ceiling - Plaster/Drywall		5	SF	5	\$62	leaking by skylight
	Ceiling - Plaster/Drywall		2,744	SF	6	\$9,496	
	Doors - Side-lite		15	SF	6	\$251	
	Doors - Wood Doors inclu hw		2	EA	6	\$602	
	Floor - Carpet		494	SF	6	\$1,053	mezzanine floor
	Floor - Wood		1,226	SF	6	\$8,643	
	Floor - Wood		1,019	SF	5	\$17,413	wood is buckling from water & humidity
	Lighting - Pendent/Surface		2	EA	4	\$1,081	T12 in closet
	Lighting - Pendent/Surface		45	EA	7	\$0	
	Marker Board		6	LF	7	\$0	
	Storage/ Closet		191	SF	6	\$1,385	
	Walls - Plaster/Drywall		200	SF	6	\$552	
	Walls - Structural Glazed Tile		3,000	SF	6	\$9,438	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #128 Aquaponics (Special Program)</b>							
	Work Sink		2	EA	6	\$758	
<b>Classroom #129 (Special Program)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	1st Floor	2,210	SF	7	\$0	room is under construction, all new
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Exposed	1st Floor	404	SF	7	\$0	mezzanine floor is exposed metal
	Floor - Wood	1st Floor	2,614	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	cover is broken
	Lighting - Pendent/Surface	1st Floor	53	EA	7	\$0	
	Storage/ Closet	1st Floor	155	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	2,961	SF	7	\$0	
<b>Classroom #132 (Computer Lab)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	1st Floor	6	SF	5	\$75	holes and peeling
	Ceiling - Plaster/Drywall	1st Floor	1,561	SF	6	\$5,402	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	1,567	SF	6	\$3,428	
	Lighting - Pendent/Surface	1st Floor	34	EA	7	\$0	
	Marker Board	1st Floor	17	LF	7	\$0	
	Storage/ Closet	1st Floor	180	SF	6	\$1,305	door locked, accessed from outside
	Walls - Plaster/Drywall	1st Floor	110	SF	6	\$304	wood wainscot
	Walls - Structural Glazed Tile	1st Floor	2,255	SF	6	\$7,094	
<b>Classroom #133 (Physical Education Room)</b>							
	AC Units	1st Floor	2	EA	7	\$0	Room is all new construction
	Ceiling - Plaster/Drywall	1st Floor	2,167	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	2,571	SF	7	\$0	Pergo type of laminate wood floor
	Lighting - Pendent/Surface	1st Floor	53	EA	7	\$0	
	Storage/ Closet	1st Floor	155	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	2,932	SF	7	\$0	
<b>Classroom #135 (Multi Purpose Room)</b>							
	Ceiling - Plaster/Drywall	1st Floor	3,259	SF	6	\$11,278	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	3,259	SF	6	\$22,976	
	Lighting - Pendent/Surface	1st Floor	61	EA	7	\$0	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #135 (Multi Purpose Room)</b>							
	Marker Board	1st Floor	8	LF	7	\$0	
	Walls - Structural Glazed Tile	1st Floor	3,304	SF	6	\$10,394	
<b>Classroom #136 (Regular Classroom)</b>							
	Casework	1st Floor	16	LF	6	\$404	
	Ceiling - Plaster/Drywall	1st Floor	757	SF	6	\$2,620	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	757	SF	6	\$1,656	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	34	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	622	SF	6	\$1,717	
	Walls - Structural Glazed Tile	1st Floor	1,013	SF	6	\$3,187	
<b>Classroom #137 (Special Program)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	46	LF	6	\$1,162	
	Ceiling - Plaster/Drywall	1st Floor	1,575	SF	6	\$5,450	
	Chalk Board	1st Floor	17	LF	4	\$1,561	
	Doors - Transom Window	1st Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	5	SF	5	\$99	floor buckling from water drip from A/C unit above
	Floor - Wood	1st Floor	1,570	SF	6	\$11,068	
	Lighting - Pendent/Surface	1st Floor	28	EA	7	\$0	
	Storage/ Closet	1st Floor	3	SF	6	\$22	
	Walls - Structural Glazed Tile	1st Floor	2,260	SF	6	\$7,110	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #138 (Weight)</b>							
	Casework	1st Floor	102	LF	5	\$21,326	built-in bleachers falling apart
	Ceiling - Plaster/Drywall	1st Floor	2,667	SF	6	\$9,229	ceiling flaking / peeling
	Chalk Board	1st Floor	8	LF	4	\$734	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Sport Flooring	1st Floor	2,468	SF	6	\$5,329	
	Lighting - Pendent/Surface	1st Floor	32	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	199	SF	6	\$1,443	SW corner storage locked, not accessed
	Walls - Concrete Block	1st Floor	689	SF	6	\$2,020	cmu interior partitions

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #138 (Weight)</b>							
	Walls - Structural Glazed Tile	1st Floor	2,916	SF	6	\$9,174	
	Work Sink	1st Floor	1	EA	5	\$1,508	not is good condition
<b>Classroom #139 (Special Program)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	1,571	SF	6	\$5,437	
	Chalk Board	1st Floor	8	LF	4	\$734	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	\$903	
	Floor - Wood	1st Floor	1,571	SF	6	\$11,075	
	Lighting - Pendent/Surface	1st Floor	37	EA	7	\$0	
	Storage/ Closet	1st Floor	102	SF	6	\$740	
	Walls - Structural Glazed Tile	1st Floor	2,513	SF	6	\$7,906	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #140 (Multi Purpose Room)</b>							
	Ceiling - Plaster/Drywall	1st Floor	1,580	SF	6	\$5,468	
	Chalk Board	1st Floor	23	LF	4	\$2,112	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,580	SF	6	\$836	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	129	SF	6	\$935	
	Walls - Structural Glazed Tile	1st Floor	2,533	SF	6	\$7,969	
	Work Sink	1st Floor	2	EA	6	\$758	
<b>Classroom #141 (Regular Classroom)</b>							
	Casework	1st Floor	19	LF	6	\$480	
	Ceiling - Plaster/Drywall	1st Floor	689	SF	6	\$2,384	
	Chalk Board	1st Floor	24	LF	4	\$2,203	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	689	SF	6	\$4,857	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	18	LF	7	\$0	
	Storage/ Closet	1st Floor	3	SF	6	\$22	Built-in closet
	Walls - Plaster/Drywall	1st Floor	4	SF	5	\$20	crack in wall
	Walls - Plaster/Drywall	1st Floor	1,436	SF	6	\$3,963	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #141 (Regular Classroom)</b>							
	Work Sink	1st Floor	2	EA	6	\$758	
<b>Classroom #143 (Multi Purpose Room)</b>							
	AC Units	1st Floor	1	EA	4	\$6,086	not on dedicated circuit
	Casework	1st Floor	13	LF	6	\$328	
	Ceiling - Plaster/Drywall	1st Floor	4	SF	5	\$50	plaster peeling
	Ceiling - Plaster/Drywall	1st Floor	1,467	SF	6	\$5,077	
	Doors - Side-lite	1st Floor	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Carpet	1st Floor	324	SF	6	\$690	
	Floor - Tile	1st Floor	1,147	SF	6	\$2,510	
	Lighting - Pendent/Surface	1st Floor	32	EA	7	\$0	
	Marker Board	1st Floor	18	LF	7	\$0	
	Storage/ Closet	1st Floor	82	SF	6	\$595	
	Walls - Structural Glazed Tile	1st Floor	2,018	SF	6	\$6,349	
<b>Classroom #144 (Multi Purpose Room)</b>							
	Ceiling - Plaster/Drywall	1st Floor	1,513	SF	6	\$5,236	
	Doors - Side-lite	1st Floor	10	SF	6	\$167	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	1,513	SF	6	\$3,310	
	Lighting - Pendent/Surface	1st Floor	37	EA	7	\$0	
	Storage/ Closet	1st Floor	45	SF	6	\$326	
	Walls - Structural Glazed Tile	1st Floor	2,242	SF	6	\$7,053	
<b>Classroom #145 (Regular Classroom)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Plaster/Drywall	1st Floor	1,352	SF	6	\$4,679	
	Chalk Board	1st Floor	4	LF	4	\$367	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile	1st Floor	1,352	SF	6	\$2,958	
	Lighting - Pendent/Surface	1st Floor	25	EA	7	\$0	
	Marker Board	1st Floor	22	LF	6	\$471	
	Storage/ Closet	1st Floor	158	SF	6	\$1,146	storage door locked, ranking based on surrounding conditions
	Walls	1st Floor	358		6	\$0	wood wainscot at 4' A.F.F.
	Walls - Structural Glazed Tile	1st Floor	1,965	SF	6	\$6,182	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #146 (Multi Purpose Room)</b>							
	Casework	1st Floor	7	LF	6	\$177	
	Ceiling - Plaster/Drywall	1st Floor	1,578	SF	6	\$5,461	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	1,575	SF	6	\$3,446	
	Lighting - Pendent/Surface	1st Floor	40	EA	7	\$0	
	Marker Board	1st Floor	6	LF	7	\$0	
	Storage/ Closet	1st Floor	100	SF	6	\$725	9 sq.ft. closet assessed, 91 sq.ft. storage room locked, measured from outside
	Walls - Structural Glazed Tile	1st Floor	2,281	SF	6	\$7,176	
	Work Sink	1st Floor	2	EA	6	\$758	
<b>Classroom #147 (Multi Purpose Room)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	1st Floor	1,500	SF	6	\$5,191	
	Doors - Side-lite	1st Floor	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	1,500	SF	6	\$10,575	
	Lighting - Pendent/Surface	1st Floor	32	EA	7	\$0	
	Storage/ Closet	1st Floor	7	SF	6	\$51	
	Walls - Plaster/Drywall	1st Floor	2,203	SF	7	\$0	new renovation work
<b>Classroom #148 (Multi Purpose Room)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	2,237	SF	6	\$7,741	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	2,237	SF	6	\$15,771	
	Lighting - Pendent/Surface	1st Floor	30	EA	7	\$0	
	Marker Board	1st Floor	6	LF	7	\$0	
	Storage/ Closet	1st Floor	75	SF	6	\$544	
	Walls - Structural Glazed Tile	1st Floor	2,497	SF	6	\$7,856	
<b>Classroom #149 (Multi Purpose Room)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	53	LF	6	\$1,338	
	Ceiling - Plaster/Drywall	1st Floor	1,539	SF	6	\$5,326	
	Chalk Board	1st Floor	6	LF	4	\$551	
	Doors - Side-lite	1st Floor	14	SF	6	\$234	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #149 (Multi Purpose Room)</b>							
	Floor - Wood	1st Floor	1,539	SF	6	\$10,850	
	Lighting - Pendent/Surface	1st Floor	28	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	85	SF	6	\$616	
	Walls - Structural Glazed Tile	1st Floor	2,247	SF	6	\$7,069	
<b>Classroom #150 (North) (Multi Purpose Room)</b>							
	Ceiling - Plaster/Drywall	1st Floor	3,170	SF	7	\$0	new renovation
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Concrete	1st Floor	3,170	SF	6	\$1,677	
	Lighting - Pendent/Surface	1st Floor	74	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	4,172	SF	7	\$0	new renovation
	Work Sink	1st Floor	1	EA	7	\$0	new sink
<b>Classroom #150 (South) (Art Room)</b>							
	Ceiling - Exposed	1st Floor	3,170	SF	7	\$0	new renovation
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Concrete	1st Floor	3,170	SF	6	\$1,677	
	Lighting - Pendent/Surface	1st Floor	74	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	4,172	SF	7	\$0	new renovation
	Work Sink	1st Floor	1	EA	7	\$0	new sink
<b>Classroom #151 (Special Education)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	49	LF	6	\$1,237	base cabinetry / lockers / built-ins
	Ceiling - Plaster/Drywall	1st Floor	1,693	SF	6	\$5,859	
	Chalk Board	1st Floor	11	LF	4	\$1,010	
	Doors - Transom Window	1st Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	1,693	SF	6	\$11,935	
	Lighting - Pendent/Surface	1st Floor	28	EA	7	\$0	
	Walls - Structural Glazed Tile	1st Floor	2,790	SF	6	\$8,777	hole in east wall where pigeons come in per teachers comments
	Work Sink	1st Floor	1	EA	6	\$379	kitchen sink
<b>Classroom #153 (Multi Purpose Room)</b>							
	Casework	1st Floor	54	LF	6	\$1,364	
	Ceiling - Plaster/Drywall	1st Floor	1,486	SF	6	\$5,142	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #153 (Multi Purpose Room)</b>							
	Chalk Board	1st Floor	10	LF	6	\$223	
	Doors - Side-lite	1st Floor	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	1,486	SF	6	\$10,476	
	Lighting - Pendent/Surface	1st Floor	32	EA	7	\$0	
	Storage/ Closet	1st Floor	79	SF	6	\$573	
	Walls - Structural Glazed Tile	1st Floor	2,112	SF	6	\$6,644	
<b>Classroom #155 (Regular Classroom)</b>							
	Casework	1st Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	1st Floor	2,055	SF	6	\$7,112	
	Chalk Board	1st Floor	5	LF	4	\$459	
	Doors - Side-lite	1st Floor	13	SF	6	\$217	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	2,055	SF	6	\$14,488	
	Lighting - Pendent/Surface	1st Floor	32	EA	7	\$0	
	Marker Board	1st Floor	18	LF	7	\$0	
	Storage/ Closet	1st Floor	475	SF	6	\$3,444	
	Walls - Structural Glazed Tile	1st Floor	2,206	SF	6	\$6,940	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #157 (Special Education)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	1st Floor	1,539	SF	6	\$5,326	
	Doors - Side-lite	1st Floor	14	SF	6	\$234	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	1,539	SF	6	\$10,850	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	\$0	
	Marker Board	1st Floor	16	LF	6	\$343	
	Walls - Plaster/Drywall	1st Floor	713	SF	6	\$1,968	
	Walls - Structural Glazed Tile	1st Floor	1,601	SF	6	\$5,037	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #157A (Special Education)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	32	LF	6	\$808	base cabinetry at kitchen area
	Ceiling - Plaster/Drywall	1st Floor	1,230	SF	6	\$4,257	



**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #157A (Special Education)</b>							
	Doors - Side-lite	1st Floor	6	SF	6	\$100	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	892	SF	6	\$6,289	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Storage/ Closet	1st Floor	19	SF	6	\$138	laundry closet
	Walls - Plaster/Drywall	1st Floor	713	SF	6	\$1,968	
	Walls - Structural Glazed Tile	1st Floor	1,370	SF	6	\$4,310	
	Work Sink	1st Floor	2	EA	6	\$758	kitchen sinks in base cabinets
<b>Classroom #160 (Weight)</b>							
	Ceiling - Plaster/Drywall	1st Floor	2,173	SF	6	\$7,520	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Floor - Weight/ Fitness Room Floor Matting	1st Floor	2,173	SF	6	\$11,373	
	Lighting - Pendent/Surface	1st Floor	35	EA	7	\$0	
	Storage/ Closet	1st Floor	66	SF	6	\$479	
	Walls - Plaster/Drywall	1st Floor	1,245	SF	6	\$3,436	
	Walls - Structural Glazed Tile	1st Floor	240	SF	5	\$13,848	Glazing part is missing, brick exposed
	Walls - Structural Glazed Tile	1st Floor	1,005	SF	6	\$3,162	
<b>Classroom #161 (Regular Classroom)</b>							
	AC Units	1st Floor	3	EA	6	\$1,487	
	Casework	1st Floor	17	LF	6	\$429	
	Ceiling - Plaster/Drywall	1st Floor	2,361	SF	6	\$8,170	
	Chalk Board	1st Floor	8	LF	4	\$734	
	Doors - Side-lite	1st Floor	14	SF	6	\$234	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	2,361	SF	6	\$16,645	
	Lighting - Pendent/Surface	1st Floor	40	EA	7	\$0	
	Walls - Concrete Block	1st Floor	512	SF	6	\$1,501	
	Walls - Plaster/Drywall	1st Floor	263	SF	6	\$726	
	Walls - Structural Glazed Tile	1st Floor	1,813	SF	6	\$5,704	
<b>Classroom #162 (Physical Education Room)</b>							
	Ceiling - Plaster/Drywall	1st Floor	993	SF	6	\$3,436	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Weight/ Fitness Room Floor Matting	1st Floor	993	SF	6	\$5,197	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	\$0	
	Storage/ Closet	1st Floor	148	SF	6	\$1,073	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #162 (Physical Education Room)</b>							
	Walls - Structural Glazed Tile	1st Floor	1,668	SF	6	\$5,248	
	Walls - Structural Glazed Tile	1st Floor	3	SF	5	\$191	missing bricks
<b>Classroom #202- Drama (Other Instructional Use)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	2nd Floor	1,324	SF	6	\$4,582	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,324	SF	6	\$9,334	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,710	SF	6	\$4,719	
<b>Classroom #207 (Regular Classroom)</b>							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	\$2,526	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	730	SF	6	\$5,146	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	\$10	Holes in wall
	Walls - Plaster/Drywall	2nd Floor	1,203	SF	6	\$3,320	
<b>Classroom #210 (Regular Classroom)</b>							
	AC Units	2nd Floor	3	EA	6	\$1,487	
	Casework	2nd Floor	16	LF	6	\$404	
	Ceiling - Plaster/Drywall	2nd Floor	25	SF	5	\$312	peeling
	Ceiling - Plaster/Drywall	2nd Floor	1,435	SF	6	\$4,966	
	Doors - Transom Window	2nd Floor	36	SF	6	\$610	
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	6	\$1,204	
	Floor - Carpet	2nd Floor	1,460	SF	4	\$13,425	has holes, has come loose & is all stained
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	2,157	SF	6	\$5,953	
	Walls - Plaster/Drywall	2nd Floor	40	SF	5	\$204	peeling
<b>Classroom #211 (Regular Classroom)</b>							
	Casework	2nd Floor	22	LF	6	\$556	
	Ceiling - Plaster/Drywall	2nd Floor	12	SF	5	\$150	Peeling paint

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #211 (Regular Classroom)</b>							
	Ceiling - Plaster/Drywall	2nd Floor	718	SF	6	\$2,485	
	Chalk Board	2nd Floor	6	LF	4	\$551	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	730	SF	6	\$5,146	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	T8
	Marker Board	2nd Floor	18	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,199	SF	6	\$3,309	
	Walls - Plaster/Drywall	2nd Floor	6	SF	5	\$31	Peeling paint
<b>Classroom #214 (Regular Classroom)</b>							
	Casework	2nd Floor	64	LF	6	\$1,616	
	Ceiling - Plaster/Drywall	2nd Floor	957	SF	6	\$3,312	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	957	SF	6	\$6,747	
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Storage/ Closet	2nd Floor	90	SF	6	\$653	
	Walls - Metal Panel	2nd Floor	332	SF	6	\$2,478	Wood Planks
	Walls - Plaster/Drywall	2nd Floor	1,326	SF	6	\$3,660	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #215 (Science Classroom)</b>							
	Casework	2nd Floor	53	LF	6	\$1,338	
	Ceiling - Plaster/Drywall	2nd Floor	930	SF	6	\$3,218	
	Chalk Board	2nd Floor	48	LF	4	\$4,407	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	25	SF	5	\$144	damaged tile
	Floor - Tile	2nd Floor	905	SF	6	\$1,980	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,638	SF	6	\$4,521	
	Work Sink	2nd Floor	2	EA	6	\$758	
<b>Classroom #217 (Regular Classroom)</b>							
	Casework	2nd Floor	34	LF	6	\$859	
	Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	\$2,353	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #217 (Regular Classroom)</b>							
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	13	SF	5	\$75	damaged
	Floor - Tile	2nd Floor	667	SF	6	\$1,459	
	Lighting - Pendent/Surface	2nd Floor	11	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,372	SF	6	\$3,787	
<b>Classroom #218 (Regular Classroom)</b>							
	Casework	2nd Floor	11	LF	6	\$278	
	Ceiling - Plaster/Drywall	2nd Floor	1,070	SF	6	\$3,703	
	Ceiling - Plaster/Drywall	2nd Floor	40	SF	5	\$500	peeling
	Chalk Board	2nd Floor	6	LF	4	\$551	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,110	SF	6	\$7,825	
	Lighting - Pendent/Surface	2nd Floor	30	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	8	SF	5	\$41	cracked
	Walls - Plaster/Drywall	2nd Floor	1,800	SF	6	\$4,968	
<b>Classroom #219 (Science Classroom)</b>							
	Casework	2nd Floor	39	LF	6	\$985	
	Ceiling - Plaster/Drywall	2nd Floor	120	SF	5	\$1,290	water stains
	Ceiling - Plaster/Drywall	2nd Floor	855	SF	6	\$2,959	
	Chalk Board	2nd Floor	27	LF	4	\$2,479	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	100	SF	5	\$576	missing tiles & damaged tiles
	Floor - Tile	2nd Floor	875	SF	6	\$1,914	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	\$0	
	Marker Board	2nd Floor	21	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	18	SF	5	\$92	peeling
	Walls - Plaster/Drywall	2nd Floor	1,614	SF	6	\$4,454	
	Work Sink	2nd Floor	2	EA	6	\$758	
<b>Classroom #220 (Art Room)</b>							
	Casework	2nd Floor	18	LF	6	\$455	
	Ceiling - Plaster/Drywall	2nd Floor	100	SF	5	\$1,250	water damage
	Ceiling - Plaster/Drywall	2nd Floor	1,043	SF	6	\$3,609	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	\$903	
	Floor - Wood	2nd Floor	1,143	SF	6	\$8,058	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #220 (Art Room)</b>							
	Instructional Surface	2nd Floor	8	LF	6	\$269	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Storage/ Closet	2nd Floor	91	SF	6	\$660	
	Walls - Plaster/Drywall	2nd Floor	100	SF	5	\$511	water damage
	Walls - Plaster/Drywall	2nd Floor	1,740	SF	6	\$4,802	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #222 (Regular Classroom)</b>							
	Casework	2nd Floor	7	LF	6	\$177	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	\$2,526	2sf is peeling
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	730	SF	6	\$5,146	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,456	SF	6	\$4,018	
<b>Classroom #223 (Science Classroom)</b>							
	Casework	2nd Floor	54	LF	6	\$1,364	
	Ceiling - Plaster/Drywall	2nd Floor	1,012	SF	6	\$3,502	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	50	SF	5	\$288	damaged floor tile
	Floor - Tile	2nd Floor	962	SF	6	\$2,105	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	\$0	
	Marker Board	2nd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,702	SF	6	\$4,697	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	\$5	hole in wall
	Work Sink	2nd Floor	2	EA	6	\$758	
<b>Classroom #224 (Regular Classroom)</b>							
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	975	SF	6	\$3,374	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	975	SF	6	\$6,874	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #224 (Regular Classroom)</b>							
	Marker Board	2nd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,651	SF	6	\$4,557	
<b>Classroom #225 (Science Classroom)</b>							
	Casework	2nd Floor	49	LF	6	\$1,237	
	Ceiling - Plaster/Drywall	2nd Floor	975	SF	6	\$3,374	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	22	SF	4	\$285	missing
	Floor - Tile	2nd Floor	953	SF	6	\$2,085	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	\$124	cover is broken
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	12	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,658	SF	6	\$4,576	
	Work Sink	2nd Floor	3	EA	6	\$1,137	1 faucet leaking
<b>Classroom #226 (Regular Classroom)</b>							
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	975	SF	6	\$3,374	
	Chalk Board	2nd Floor	40	LF	4	\$3,672	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	975	SF	6	\$6,874	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,657	SF	6	\$4,573	
<b>Classroom #228 (Regular Classroom)</b>							
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	975	SF	6	\$3,374	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	975	SF	6	\$6,874	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	18	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,658	SF	6	\$4,576	
<b>Classroom #229 (Regular Classroom)</b>							
	Casework	2nd Floor	10	LF	6	\$253	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #229 (Regular Classroom)</b>							
	Ceiling - Plaster/Drywall	2nd Floor	975	SF	6	\$3,374	
	Chalk Board	2nd Floor	6	LF	4	\$551	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	975	SF	6	\$6,874	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,638	SF	6	\$4,521	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #230 (Regular Classroom)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	2nd Floor	1,157	SF	6	\$4,004	
	Chalk Board	2nd Floor	7	LF	4	\$643	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,157	SF	6	\$8,157	
	Lighting - Pendent/Surface	2nd Floor	39	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Storage/ Closet	2nd Floor	140	SF	6	\$1,015	
	Walls - Plaster/Drywall	2nd Floor	1,746	SF	6	\$4,819	
<b>Classroom #231 (Regular Classroom)</b>							
	Casework	2nd Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	2nd Floor	975	SF	6	\$3,374	
	Chalk Board	2nd Floor	6	LF	6	\$134	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	975	SF	6	\$6,874	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	6	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,696	SF	6	\$4,681	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #232 (Computer Lab)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	2nd Floor	1,356	SF	6	\$4,693	
	Charging Station	2nd Floor	30	EA	6	\$14,539	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #232 (Computer Lab)</b>							
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,356	SF	6	\$9,560	
	Lighting - Pendent/Surface	2nd Floor	39	EA	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Storage/ Closet	2nd Floor	192	SF	6	\$1,392	3 sq.ft. built-in closet, 189 sq.ft. storage
	Walls - Plaster/Drywall	2nd Floor	1,760	SF	6	\$4,857	
<b>Classroom #233 (Regular Classroom)</b>							
	Casework		12	LF	6	\$303	
	Ceiling - Plaster/Drywall		975	SF	6	\$3,374	
	Chalk Board		30	LF	4	\$2,754	
	Doors - Transom Window		9	SF	6	\$152	
	Doors - Wood Doors inclu hw		1	EA	6	\$301	
	Floor - Wood		975	SF	6	\$6,874	
	Lighting - Pendent/Surface		16	EA	7	\$0	
	Walls - Plaster/Drywall		1,655	SF	6	\$4,568	
	Walls - Plaster/Drywall		15	SF	5	\$77	damaged
	Work Sink		1	EA	6	\$379	
<b>Classroom #234 (Regular Classroom)</b>							
	Casework	2nd Floor	46	LF	6	\$1,162	
	Ceiling - Plaster/Drywall	2nd Floor	1,124	SF	6	\$3,890	
	Chalk Board	2nd Floor	10	LF	4	\$918	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	3	SF	5	\$17	missing / broken tiles
	Floor - Tile	2nd Floor	1,121	SF	6	\$2,453	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	7	EA	6	\$867	spotlights - track lighting
	Marker Board	2nd Floor	20	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	3 sq.ft. built-in closet, door to other storage locked - not assessed
	Walls - Plaster/Drywall	2nd Floor	2,179	SF	6	\$6,014	
<b>Classroom #235 (Computer Lab)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	2nd Floor	1,347	SF	6	\$4,661	



**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #235 (Computer Lab)</b>							
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Carpet	2nd Floor	1,347	SF	6	\$2,870	
	Lighting - Pendent/Surface	2nd Floor	39	EA	7	\$0	
	Marker Board	2nd Floor	30	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	3 sq.ft. built-in closet / storage door locked
	Walls - Plaster/Drywall	2nd Floor	1,756	SF	6	\$4,846	
	Wireless System	2nd Floor	1	EA	6	\$372	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #236 (Regular Classroom)</b>							
	Casework	2nd Floor	23	LF	6	\$581	
	Ceiling - Plaster/Drywall	2nd Floor	1,054	SF	6	\$3,647	
	Chalk Board	2nd Floor	13	LF	4	\$1,193	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	1,054	SF	6	\$2,306	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,496	SF	6	\$4,129	
<b>Classroom #238 (Regular Classroom)</b>							
	Casework	2nd Floor	26	LF	6	\$657	
	Ceiling - Plaster/Drywall	2nd Floor	991	SF	6	\$3,429	
	Chalk Board	2nd Floor	19	LF	4	\$1,744	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	991	SF	6	\$2,168	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Storage/ Closet	2nd Floor	66	SF	6	\$479	built-in closet - 3 sq.ft., caged storage 63 sq.ft.
	Walls - Plaster/Drywall	2nd Floor	1,459	SF	6	\$4,027	
<b>Classroom #239 (Regular Classroom)</b>							
	AC Units	2nd Floor	3	EA	6	\$1,487	
	Casework	2nd Floor	20	LF	6	\$505	
	Ceiling - Plaster/Drywall	2nd Floor	1,455	SF	6	\$5,035	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,455	SF	6	\$10,258	
	Lighting - Pendent/Surface	2nd Floor	38	EA	7	\$0	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #239 (Regular Classroom)</b>							
	Marker Board	2nd Floor	26	LF	7	\$0	
	Storage/ Closet	2nd Floor	95	SF	6	\$689	
	Walls - Plaster/Drywall	2nd Floor	1,886	SF	6	\$5,205	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #240 (Regular Classroom)</b>							
	Casework	2nd Floor	7	LF	6	\$177	
	Ceiling - Plaster/Drywall	2nd Floor	818	SF	6	\$2,831	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	818	SF	6	\$5,767	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet
	Walls - Plaster/Drywall	2nd Floor	1,317	SF	6	\$3,635	
<b>Classroom #241 (Science Classroom)</b>							
	Casework	2nd Floor	93	LF	6	\$2,349	
	Ceiling - Splined	2nd Floor	1,065	SF	6	\$868	
	Chalk Board	2nd Floor	45	LF	4	\$4,131	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	1,065	SF	6	\$2,330	
	Lighting - Pendent/Surface	2nd Floor	27	EA	7	\$0	
	Storage/ Closet	2nd Floor	196	SF	6	\$1,421	
	Walls - Plaster/Drywall	2nd Floor	1,860	SF	6	\$5,133	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #242 (Regular Classroom)</b>							
	Casework	2nd Floor	7	LF	6	\$177	
	Ceiling - Plaster/Drywall	2nd Floor	794	SF	6	\$2,748	
	Chalk Board	2nd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	794	SF	6	\$5,598	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	21	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #242 (Regular Classroom)</b>							
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	\$26	plaster cracking / peeling
	Walls - Plaster/Drywall	2nd Floor	1,292	SF	6	\$3,566	
<b>Classroom #243 (Science Classroom)</b>							
	Casework	2nd Floor	159	LF	6	\$4,015	tables bolted to floor, countertop / backsplash broken apart
	Ceiling - Plaster/Drywall	2nd Floor	694	SF	6	\$2,402	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	15	SF	5	\$86	holes in floor
	Floor - Tile	2nd Floor	679	SF	6	\$1,486	
	Lighting - Pendent/Surface	2nd Floor	27	EA	7	\$0	
	Marker Board	2nd Floor	26	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,304	SF	6	\$3,599	
	Work Sink	2nd Floor	3	EA	6	\$1,137	sinks at built-in base cabinets with countertop
<b>Classroom #244 (Regular Classroom)</b>							
	Casework	2nd Floor	7	LF	6	\$177	
	Ceiling - Plaster/Drywall	2nd Floor	6	SF	5	\$75	ceiling flaking / peeling
	Ceiling - Plaster/Drywall	2nd Floor	812	SF	6	\$2,810	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	818	SF	6	\$5,767	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	21	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet
	Walls - Plaster/Drywall	2nd Floor	6	SF	5	\$31	cracks in walls
	Walls - Plaster/Drywall	2nd Floor	1,312	SF	6	\$3,621	
<b>Classroom #245 (Science Classroom)</b>							
	AC Units	2nd Floor	2	EA	6	\$991	covers missing on both
	Casework	2nd Floor	47	LF	6	\$1,187	base cabinets included
	Ceiling - Plaster/Drywall	2nd Floor	1,342	SF	6	\$4,644	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	covered by plywood
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	1,342	SF	6	\$2,936	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #245 (Science Classroom)</b>							
	Storage/ Closet	2nd Floor	155	SF	6	\$1,124	storage door locked, accessed from outside
	Walls - Plaster/Drywall	2nd Floor	1,952	SF	6	\$5,387	
	Work Sink	2nd Floor	4	EA	6	\$1,516	kitchen sinks in base cabinets
<b>Classroom #246 (Regular Classroom)</b>							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	\$62	plaster flaking / peeling
	Ceiling - Plaster/Drywall	2nd Floor	691	SF	6	\$2,391	
	Chalk Board	2nd Floor	26	LF	4	\$2,387	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	696	SF	6	\$4,907	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	\$26	cracks in walls
	Walls - Plaster/Drywall	2nd Floor	1,404	SF	6	\$3,875	
<b>Classroom #249 (Regular Classroom)</b>							
	Casework	2nd Floor	20	LF	6	\$505	
	Ceiling - Plaster/Drywall	2nd Floor	1,347	SF	6	\$4,661	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,347	SF	6	\$9,496	
	Lighting - Pendent/Surface	2nd Floor	38	EA	7	\$0	
	Storage/ Closet	2nd Floor	118	SF	6	\$856	storage door locked, measured from outside, rank is assumed
	Walls - Plaster/Drywall	2nd Floor	1,925	SF	6	\$5,313	
<b>Classroom #250 (Regular Classroom)</b>							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	2nd Floor	3	SF	5	\$37	plaster flaking and peeling
	Ceiling - Plaster/Drywall	2nd Floor	1,043	SF	6	\$3,609	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	1,046	SF	6	\$7,374	
	Lighting - Pendent/Surface	2nd Floor	30	EA	7	\$0	
	Marker Board	2nd Floor	37	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet
	Walls - Plaster/Drywall	2nd Floor	1,827	SF	6	\$5,042	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #250 (Regular Classroom)</b>							
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	\$15	cracks and holes in walls around sink
	Work Sink	2nd Floor	1	EA	5	\$1,508	doesn't work, backs up when it rains - per teacher
<b>Classroom #251 (Regular Classroom)</b>							
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	2nd Floor	807	SF	6	\$2,793	
	Chalk Board	2nd Floor	11	LF	4	\$1,010	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	807	SF	6	\$5,689	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	17	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet
	Walls - Plaster/Drywall	2nd Floor	1,163	SF	6	\$3,210	
<b>Classroom #252 (Regular Classroom)</b>							
	Casework	2nd Floor	20	LF	6	\$505	
	Ceiling - Lay-in	2nd Floor	984	SF	6	\$2,955	
	Doors - Transom Window	2nd Floor	21	SF	6	\$356	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	(1) double door
	Floor - Carpet	2nd Floor	984	SF	6	\$2,097	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	\$0	
	Marker Board	2nd Floor	39	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet
	Walls - Metal Panel	2nd Floor	274	SF	6	\$2,045	metal panel partition with fabric
	Walls - Plaster/Drywall	2nd Floor	726	SF	6	\$2,004	lower part of walls
	Walls - Tile	2nd Floor	414	SF	6	\$906	lay-in tile (act) used on upper part of walls
<b>Classroom #253 (Regular Classroom)</b>							
	Casework	2nd Floor	7	LF	6	\$177	
	Ceiling - Splined	2nd Floor	810	SF	6	\$660	
	Chalk Board	2nd Floor	12	LF	4	\$1,102	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	810	SF	6	\$5,710	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	23	LF	7	\$0	
	Storage/ Closet	2nd Floor	4	SF	6	\$29	built-in closet
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	\$2,763	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #253 (Regular Classroom)</b>							
<b>Classroom #254 (Regular Classroom)</b>							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	2nd Floor	1,002	SF	6	\$3,468	
	Chalk Board	2nd Floor	6	LF	4	\$551	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,002	SF	6	\$7,064	
	Lighting - Pendent/Surface	2nd Floor	27	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet door locked, rank assumed
	Walls - Plaster/Drywall	2nd Floor	4	SF	5	\$20	cracks / holes in wall
	Walls - Plaster/Drywall	2nd Floor	1,483	SF	6	\$4,093	
<b>Classroom #255 (Computer Lab)</b>							
	AC Units	2nd Floor	3	EA	6	\$1,487	
	Casework	2nd Floor	16	LF	6	\$404	
	Ceiling - Plaster/Drywall	2nd Floor	1,017	SF	6	\$3,519	
	Chalk Board	2nd Floor	13	LF	4	\$1,193	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,017	SF	6	\$7,170	
	Lighting - Pendent/Surface	2nd Floor	27	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	\$15	walls on both sides of lav cracking / peeling
	Walls - Plaster/Drywall	2nd Floor	1,478	SF	6	\$4,079	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #256 (Regular Classroom)</b>							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	2nd Floor	1,008	SF	6	\$3,488	
	Chalk Board	2nd Floor	27	LF	4	\$2,479	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,008	SF	6	\$7,106	
	Lighting - Pendent/Surface	2nd Floor	27	EA	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet
	Walls - Plaster/Drywall	2nd Floor	1,489	SF	6	\$4,109	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #257 (Regular Classroom)</b>							
	Casework	2nd Floor	21	LF	6	\$530	
	Ceiling - Plaster/Drywall	2nd Floor	1,440	SF	6	\$4,983	
	Chalk Board	2nd Floor	15	LF	4	\$1,377	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	24	SF	5	\$138	strip of tile removed
	Floor - Tile	2nd Floor	1,416	SF	6	\$3,098	
	Lighting - Pendent/Surface	2nd Floor	22	EA	7	\$0	
	Marker Board	2nd Floor	18	LF	7	\$0	
	Storage/ Closet	2nd Floor	75	SF	6	\$544	7 sq.ft. of built-in closet
	Walls - Plaster/Drywall	2nd Floor	1,937	SF	6	\$5,346	
<b>Classroom #258 (Regular Classroom)</b>							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	2nd Floor	1,100	SF	6	\$3,807	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,100	SF	6	\$7,755	
	Lighting - Pendent/Surface	2nd Floor	30	EA	7	\$0	
	Marker Board	2nd Floor	27	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet door locked, rank assumed
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	\$26	cracks / holes in walls around removed sink
	Walls - Plaster/Drywall	2nd Floor	1,547	SF	6	\$4,270	
<b>Classroom #259 (Regular Classroom)</b>							
	AC Units	2nd Floor	3	EA	6	\$1,487	
	Casework	2nd Floor	35	LF	6	\$884	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	\$125	ceiling has holes and cracking
	Ceiling - Plaster/Drywall	2nd Floor	1,092	SF	6	\$3,779	
	Chalk Board	2nd Floor	17	LF	4	\$1,561	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	1,102	SF	6	\$7,769	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	3 sq.ft. built-in closet accessed, storage door locked - not accessed
	Walls - Plaster/Drywall	2nd Floor	1,831	SF	6	\$5,053	
	Work Sink	2nd Floor	1	EA	6	\$379	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #259 (Regular Classroom)</b>							
<b>Classroom #260 (Regular Classroom)</b>							
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	2nd Floor	1,106	SF	6	\$3,827	
	Chalk Board	2nd Floor	14	LF	4	\$1,285	
	Doors - Transom Window	2nd Floor	16	SF	6	\$271	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	1,106	SF	6	\$7,797	
	Lighting - Pendent/Surface	2nd Floor	30	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet door locked, rank assumed
	Walls - Plaster/Drywall	2nd Floor	1,562	SF	6	\$4,311	
<b>Classroom #261 (Regular Classroom)</b>							
	Casework	2nd Floor	11	LF	6	\$278	
	Ceiling - Plaster/Drywall	2nd Floor	1,102	SF	6	\$3,814	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	1,102	SF	6	\$7,769	
	Lighting - Pendent/Surface	2nd Floor	30	EA	7	\$0	
	Marker Board	2nd Floor	21	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	built-in closet
	Walls - Plaster/Drywall	2nd Floor	1,546	SF	6	\$4,267	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #302 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	3rd Floor	830	SF	6	\$2,872	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	830	SF	6	\$5,851	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,124	SF	6	\$3,102	
<b>Classroom #303 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	3rd Floor	830	SF	6	\$2,872	
	Chalk Board	3rd Floor	5	LF	4	\$459	



**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #303 (Regular Classroom)</b>							
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	830	SF	6	\$5,851	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,124	SF	6	\$3,102	
<b>Classroom #304 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	970	SF	5	\$8,891	Paint peeling, some water damage
	Chalk Board	3rd Floor	5	LF	4	\$459	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	970	SF	6	\$6,838	
	Lighting - Pendent/Surface	3rd Floor	27	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,148	SF	6	\$3,168	
	Walls - Plaster/Drywall	3rd Floor	296	SF	5	\$1,308	water damage and cracking
<b>Classroom #305 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	4	SF	5	\$37	Water damage
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	910	SF	6	\$6,415	
	Lighting - Pendent/Surface	3rd Floor	27	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,439	SF	6	\$3,971	
	Work Sink	3rd Floor	1	EA	6	\$379	
<b>Classroom #306 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	22	SF	5	\$275	Peeling paint
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	\$2,526	
	Chalk Board	3rd Floor	5	LF	4	\$459	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	730	SF	6	\$5,146	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #306 (Regular Classroom)</b>							
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,177	SF	6	\$3,248	
<b>Classroom #307 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	3rd Floor	685	SF	6	\$2,371	
	Ceiling - Plaster/Drywall	3rd Floor	40	SF	5	\$500	Water damage
	Chalk Board	3rd Floor	5	LF	4	\$459	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	725	SF	6	\$5,111	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,368	SF	6	\$3,776	
	Walls - Plaster/Drywall	3rd Floor	39	SF	5	\$199	Water damage
<b>Classroom #308 (Regular Classroom)</b>							
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	3rd Floor	822	SF	6	\$2,845	
	Ceiling - Plaster/Drywall	3rd Floor	6	SF	5	\$75	Water damage
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	828	SF	6	\$5,837	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,304	SF	6	\$3,599	
<b>Classroom #309 (Regular Classroom)</b>							
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	6	\$2,838	
	Ceiling - Plaster/Drywall	3rd Floor	8	SF	5	\$100	Water damage
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	820	SF	6	\$5,781	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,270	SF	6	\$3,505	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #309 (Regular Classroom)</b>							
	Walls - Plaster/Drywall	3rd Floor	34	SF	5	\$174	Water damage at window wall
<b>Classroom #310 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	\$2,492	
	Chalk Board	3rd Floor	5	LF	4	\$459	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	720	SF	6	\$5,076	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	38	SF	5	\$194	Crack at door, water damage window wall
	Walls - Plaster/Drywall	3rd Floor	1,171	SF	6	\$3,232	
<b>Classroom #311 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	3rd Floor	725	SF	6	\$2,509	
	Chalk Board	3rd Floor	25	LF	4	\$2,295	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	725	SF	6	\$5,111	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,407	SF	6	\$3,883	
<b>Classroom #312 (Regular Classroom)</b>							
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	3rd Floor	728	SF	6	\$2,519	
	Ceiling - Plaster/Drywall	3rd Floor	100	SF	5	\$1,075	Severe water damage
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	828	SF	4	\$23,965	Floor has been removed
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,148	SF	6	\$3,168	
	Walls - Plaster/Drywall	3rd Floor	156	SF	5	\$689	Severe water damage

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #313 (Regular Classroom)</b>							
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	3rd Floor	828	SF	5	\$7,590	damage throughout
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	828	SF	6	\$5,837	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	t8
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	8	SF	5	\$41	Water damage, cracking at door
	Walls - Plaster/Drywall	3rd Floor	1,296	SF	6	\$3,577	
<b>Classroom #314 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	6	\$2,595	
	Chalk Board	3rd Floor	10	LF	4	\$918	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	750	SF	6	\$5,287	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	72	SF	5	\$368	Cracking and peeling paint
	Walls - Plaster/Drywall	3rd Floor	1,152	SF	6	\$3,179	
<b>Classroom #315 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	3rd Floor	744	SF	6	\$2,575	
	Chalk Board	3rd Floor	25	LF	4	\$2,295	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	744	SF	6	\$5,245	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	120	SF	5	\$613	Crack at door, peeling paint
	Walls - Plaster/Drywall	3rd Floor	1,097	SF	6	\$3,028	
<b>Classroom #316 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	840	SF	6	\$2,907	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #316 (Regular Classroom)</b>							
	Floor - Wood	3rd Floor	840	SF	6	\$5,922	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,279	SF	6	\$3,530	
<b>Classroom #317 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	840	SF	6	\$2,907	
	Chalk Board	3rd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	840	SF	6	\$5,922	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,283	SF	6	\$3,541	
	Walls - Plaster/Drywall	3rd Floor	20	SF	5	\$102	Cracked, peeling paint
<b>Classroom #318 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	\$2,526	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	730	SF	6	\$5,146	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,205	SF	6	\$3,326	
<b>Classroom #319 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	3rd Floor	744	SF	6	\$2,575	
	Chalk Board	3rd Floor	25	LF	4	\$2,295	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	744	SF	6	\$5,245	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,217	SF	6	\$3,359	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #320 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	50	SF	5	\$625	Water damaged
	Ceiling - Plaster/Drywall	3rd Floor	700	SF	6	\$2,422	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	750	SF	6	\$5,287	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,157	SF	6	\$3,193	
	Walls - Plaster/Drywall	3rd Floor	56	SF	5	\$286	Water damaged
<b>Classroom #321 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	16	SF	5	\$200	Water damaged
	Ceiling - Plaster/Drywall	3rd Floor	824	SF	6	\$2,852	
	Chalk Board	3rd Floor	25	LF	4	\$2,295	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	16	SF	5	\$316	Water damaged
	Floor - Wood	3rd Floor	824	SF	6	\$5,809	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,281	SF	6	\$3,535	
	Walls - Plaster/Drywall	3rd Floor	16	SF	5	\$82	Water damaged
<b>Classroom #322 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	6	\$2,682	
	Chalk Board	3rd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	8	SF	5	\$46	Missing tiles
	Floor - Tile/Sheet	3rd Floor	767	SF	6	\$768	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,554	SF	6	\$4,289	
	Walls - Plaster/Drywall	3rd Floor	12	SF	5	\$61	Water damaged and cracking at window

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #323 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	3rd Floor	736	SF	6	\$2,547	
	Ceiling - Plaster/Drywall	3rd Floor	8	SF	5	\$100	Water damage at window wall
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	744	SF	6	\$5,245	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	45	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,178	SF	6	\$3,251	
	Walls - Plaster/Drywall	3rd Floor	39	SF	5	\$199	Water damage at window wall
<b>Classroom #324 (Regular Classroom)</b>							
	Casework	3rd Floor	14	LF	6	\$354	
	Ceiling - Plaster/Drywall	3rd Floor	975	SF	6	\$3,374	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Weight/ Fitness Room Floor Matting	3rd Floor	975	SF	6	\$5,103	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,418	SF	6	\$3,914	
<b>Classroom #325 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	840	SF	6	\$2,907	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	840	SF	6	\$5,922	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,315	SF	6	\$3,629	
<b>Classroom #326 (Regular Classroom)</b>							
	Casework	3rd Floor	18	LF	6	\$455	
	Ceiling - Plaster/Drywall	3rd Floor	975	SF	6	\$3,374	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	975	SF	6	\$6,874	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	\$0	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #326 (Regular Classroom)</b>							
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,395	SF	6	\$3,850	
	Work Sink	3rd Floor	1	EA	6	\$379	
<b>Classroom #327 (Regular Classroom)</b>							
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	25	SF	5	\$312	Water damaged
	Ceiling - Plaster/Drywall	3rd Floor	815	SF	6	\$2,820	
	Chalk Board	3rd Floor	24	LF	4	\$2,203	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	840	SF	6	\$5,922	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,315	SF	6	\$3,629	
<b>Classroom #328 (Regular Classroom)</b>							
	Casework	3rd Floor	14	LF	6	\$354	
	Ceiling - Plaster/Drywall	3rd Floor	975	SF	6	\$3,374	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	975	SF	6	\$6,874	
	Lighting - Pendent/Surface	3rd Floor	27	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,408	SF	6	\$3,886	
	Work Sink	3rd Floor	1	EA	6	\$379	
<b>Classroom #329 (Regular Classroom)</b>							
	Casework	3rd Floor	14	LF	6	\$354	
	Ceiling - Plaster/Drywall	3rd Floor	975	SF	6	\$3,374	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	975	SF	6	\$6,874	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	\$2,230	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,418	SF	6	\$3,914	
	Work Sink	3rd Floor	1	EA	6	\$379	



**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #330 (Language Lab)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Ceiling - Lay-in	3rd Floor	1,350	SF	6	\$4,054	
	Chalk Board	3rd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,350	SF	6	\$9,517	
	Lighting - Lay-in	3rd Floor	33	EA	7	\$0	
	Storage/ Closet	3rd Floor	148	SF	6	\$1,073	
	Walls - Plaster/Drywall	3rd Floor	1,465	SF	6	\$4,043	
<b>Classroom #331 (Regular Classroom)</b>							
	Casework	3rd Floor	14	LF	6	\$354	
	Ceiling - Plaster/Drywall	3rd Floor	975	SF	6	\$3,374	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	975	SF	6	\$6,874	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,395	SF	6	\$3,850	
	Work Sink	3rd Floor	1	EA	6	\$379	
<b>Classroom #332 (Science Classroom)</b>							
	Casework	3rd Floor	41	LF	6	\$1,035	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	\$2,526	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	730	SF	6	\$5,146	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,250	SF	6	\$3,450	
<b>Classroom #333 (Regular Classroom)</b>							
	Casework	3rd Floor	14	LF	6	\$354	
	Ceiling - Plaster/Drywall	3rd Floor	975	SF	6	\$3,374	
	Chalk Board	3rd Floor	10	LF	4	\$918	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Weight/ Fitness Room Floor Matting	3rd Floor	975	SF	6	\$5,103	
	Lighting - Pendent/Surface	3rd Floor	27	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,408	SF	6	\$3,886	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #333 (Regular Classroom)</b>							
	Work Sink	3rd Floor	1	EA	6	\$379	
<b>Classroom #334 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	350	SF	5	\$3,764	Water damaged
	Ceiling - Plaster/Drywall	3rd Floor	380	SF	6	\$1,315	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	730	SF	6	\$5,146	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,136	SF	6	\$3,135	
<b>Classroom #335 (Computer Lab)</b>							
	AC Units	3rd Floor	3	EA	6	\$1,487	
	Casework	3rd Floor	25	LF	6	\$631	
	Ceiling - Splined	3rd Floor	1,470	SF	6	\$1,198	
	Doors - Side-lite	3rd Floor	6	SF	6	\$100	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	3rd Floor	1,470	SF	6	\$1,471	
	Lighting - Pendent/Surface	3rd Floor	26	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	25	SF	5	\$189	Water damaged
	Wireless System	3rd Floor	1	EA	7	\$0	
<b>Classroom #336 (Regular Classroom)</b>							
	AC Units	3rd Floor	1	EA	6	\$496	floor portable
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	3rd Floor	60	SF	5	\$750	Peeling paint
	Ceiling - Plaster/Drywall	3rd Floor	670	SF	6	\$2,319	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Transom Window	3rd Floor	1	SF	6	\$17	
	Floor - Tile/Sheet	3rd Floor	730	SF	6	\$731	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,532	SF	6	\$4,228	
	Walls - Plaster/Drywall	3rd Floor	35	SF	5	\$179	Cracking and separating

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #336 (Regular Classroom)</b>							
<b>Classroom #337 (Computer Lab)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	45	LF	6	\$1,136	
	Ceiling - Plaster/Drywall	3rd Floor	910	SF	6	\$3,149	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	910	SF	6	\$6,415	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	\$0	
	Marker Board	3rd Floor	30	LF	7	\$0	
	Storage/ Closet	3rd Floor	110	SF	6	\$798	
	Walls - Plaster/Drywall	3rd Floor	1,606	SF	6	\$4,432	
	Wireless System	3rd Floor	1	EA	6	\$372	
<b>Classroom #338 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	3rd Floor	700	SF	6	\$2,422	
	Chalk Board	3rd Floor	40	LF	4	\$3,672	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	6	SF	5	\$35	Missing tiles
	Floor - Tile/Sheet	3rd Floor	694	SF	6	\$695	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,531	SF	6	\$4,225	
<b>Classroom #339 (Regular Classroom)</b>							
	Casework	3rd Floor	14	LF	6	\$354	
	Ceiling - Plaster/Drywall	3rd Floor	1,050	SF	6	\$3,634	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,050	SF	6	\$7,402	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Storage/ Closet	3rd Floor	70	SF	6	\$508	
	Walls - Plaster/Drywall	3rd Floor	1,356	SF	6	\$3,742	
<b>Classroom #340 (Regular Classroom)</b>							
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	10	LF	6	\$253	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #340 (Regular Classroom)</b>							
	Ceiling - Plaster/Drywall	3rd Floor	4	SF	5	\$50	Water damaged
	Ceiling - Plaster/Drywall	3rd Floor	696	SF	6	\$2,409	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	16	SF	5	\$92	Missing tile
	Floor - Tile/Sheet	3rd Floor	684	SF	6	\$685	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	18	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,490	SF	6	\$4,112	
	Walls - Plaster/Drywall	3rd Floor	40	SF	5	\$204	Walls cracking/ separating at corner
<b>Classroom #341 (Computer Lab)</b>							
	AC Units	3rd Floor	2	EA	6	\$991	
	Casework	3rd Floor	20	LF	6	\$505	
	Ceiling - Plaster/Drywall	3rd Floor	840	SF	6	\$2,907	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	840	SF	6	\$5,922	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,187	SF	6	\$3,276	
	Walls - Plaster/Drywall	3rd Floor	22	SF	5	\$112	Water damaged
	Walls - Vinyl Coated Gypsum Panel	3rd Floor	317	SF	6	\$875	
	Wireless System	3rd Floor	1	EA	7	\$0	
<b>Classroom #342 (Science Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	975	SF	6	\$3,374	
	Chalk Board	3rd Floor	40	LF	4	\$3,672	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	975	SF	6	\$6,874	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,296	SF	6	\$3,577	
<b>Classroom #343 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	\$2,326	
	Ceiling - Plaster/Drywall	3rd Floor	22	SF	5	\$275	Water damage at window wall
	Chalk Board	3rd Floor	25	LF	4	\$2,295	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #343 (Regular Classroom)</b>							
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	694	SF	6	\$4,893	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	12	EA	4	\$5,564	T12
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	84	SF	5	\$429	Water damage, peeling paint, wall damage at chair rail
	Walls - Plaster/Drywall	3rd Floor	1,146	SF	6	\$3,163	
<b>Classroom #344 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	8	SF	5	\$100	Peeling paint
	Ceiling - Plaster/Drywall	3rd Floor	792	SF	6	\$2,741	
	Chalk Board	3rd Floor	40	LF	4	\$3,672	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	800	SF	6	\$5,640	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	50	SF	6	\$193	
	Walls - Plaster/Drywall	3rd Floor	1,246	SF	6	\$3,439	
<b>Classroom #345 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	\$125	Peeling paint
	Ceiling - Plaster/Drywall	3rd Floor	842	SF	6	\$2,914	
	Doors - Transom Window	3rd Floor	63	SF	6	\$1,067	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	852	SF	6	\$6,007	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	\$10	Water damage
	Walls - Plaster/Drywall	3rd Floor	1,368	SF	6	\$3,776	
<b>Classroom #346 (Science Classroom)</b>							
	Casework	3rd Floor	36	LF	6	\$909	
	Ceiling - Plaster/Drywall	3rd Floor	1,080	SF	6	\$3,737	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,080	SF	6	\$7,614	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #346 (Science Classroom)</b>							
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,574	SF	6	\$4,344	
	Work Sink	3rd Floor	2	EA	6	\$758	
<b>Classroom #347 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	675	SF	6	\$2,336	
	Ceiling - Plaster/Drywall	3rd Floor	22	SF	5	\$275	Water damage
	Chalk Board	3rd Floor	25	LF	4	\$2,295	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Weight/ Fitness Room Floor Matting	3rd Floor	697	SF	6	\$3,648	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,170	SF	6	\$3,229	
	Walls - Plaster/Drywall	3rd Floor	60	SF	5	\$306	Water damage
<b>Classroom #349 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	808	SF	6	\$2,796	
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	5	\$250	water damage
	Chalk Board	3rd Floor	25	LF	4	\$2,295	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	828	SF	6	\$5,837	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	72	SF	5	\$546	water damage
<b>Classroom #350 (Science Classroom)</b>							
	AC Units	3rd Floor	1	EA	4	\$6,086	
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	1,050	SF	6	\$3,634	
	Doors - Transom Window	3rd Floor	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile	3rd Floor	1,050	SF	6	\$2,297	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #350 (Science Classroom)</b>							
	Marker Board	3rd Floor	20	LF	7	\$0	
	Storage/ Closet	3rd Floor	81	SF	6	\$587	
	Walls - Plaster/Drywall	3rd Floor	1,481	SF	6	\$4,087	
	Work Sink	3rd Floor	2	EA	6	\$758	
<b>Classroom #351 (Regular Classroom)</b>							
	Casework	3rd Floor	9	LF	5	\$1,882	
	Ceiling - Plaster/Drywall	3rd Floor	667	SF	6	\$2,308	
	Ceiling - Plaster/Drywall	3rd Floor	27	SF	5	\$337	Water damage
	Chalk Board	3rd Floor	25	LF	4	\$2,295	
	Doors - Transom Window	3rd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	694	SF	6	\$4,893	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	1,230	SF	6	\$3,395	
<b>Classroom #353 (Regular Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	5	\$7,516	Cracking and peeling paint throughout
	Chalk Board	3rd Floor	15	LF	4	\$1,377	
	Doors - Transom Window	3rd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	820	SF	6	\$5,781	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	6	SF	5	\$31	Water damage
	Walls - Plaster/Drywall	3rd Floor	1,230	SF	6	\$3,395	
<b>Classroom #354 (Science Classroom)</b>							
	Casework	3rd Floor	32	LF	6	\$808	
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	5	\$250	Peeling paint
	Ceiling - Plaster/Drywall	3rd Floor	985	SF	6	\$3,409	
	Chalk Board	3rd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,005	SF	6	\$7,085	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	\$0	
	Science Lab Elements	3rd Floor	180	SF	7	\$0	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #354 (Science Classroom)</b>							
	Walls - Plaster/Drywall	3rd Floor	1,448	SF	6	\$3,996	
	Walls - Plaster/Drywall	3rd Floor	20	SF	5	\$102	Cracking and peeling paint
	Work Sink	3rd Floor	2	EA	6	\$758	
<b>Classroom #356 (Science Classroom)</b>							
	Casework	3rd Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	3rd Floor	14	SF	5	\$128	Cracking and peeling paint. water damaged
	Chalk Board	3rd Floor	30	LF	4	\$2,754	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Transom Window	3rd Floor	2	SF	6	\$34	
	Floor - Wood	3rd Floor	1,080	SF	6	\$7,614	
	Lighting - Pendent/Surface	3rd Floor	27	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	12	SF	5	\$61	Water damaged
	Walls - Plaster/Drywall	3rd Floor	1,066	SF	6	\$3,491	
	Walls - Plaster/Drywall	3rd Floor	1,479	SF	6	\$4,082	
	Work Sink	3rd Floor	1	EA	6	\$379	
<b>Classroom #358 (Regular Classroom)</b>							
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	3rd Floor	1,400	SF	5	\$12,833	
	Chalk Board	3rd Floor	40	LF	4	\$3,672	
	Doors - Transom Window	3rd Floor	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	1,400	SF	6	\$9,870	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Walls - Plaster/Drywall	3rd Floor	32	SF	5	\$163	Cracking and peeling paint
	Walls - Plaster/Drywall	3rd Floor	1,264	SF	6	\$3,489	
<b>Classroom #360 (Science)</b>							
	Casework	3rd Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	3rd Floor	30	SF	5	\$375	Peeling paint
	Ceiling - Plaster/Drywall	3rd Floor	1,050	SF	6	\$3,634	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	\$602	
	Floor - Wood	3rd Floor	1,080	SF	6	\$7,614	
	Lighting - Pendent/Surface	3rd Floor	30	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	7	\$0	
	Science Lab Elements	3rd Floor	54	SF	7	\$0	



**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #360 (Science)</b>							
	Walls - Plaster/Drywall	3rd Floor	27	SF	5	\$138	Crack
	Walls - Plaster/Drywall	3rd Floor	1,529	SF	6	\$4,220	
	Work Sink	3rd Floor	1	EA	6	\$379	
<b>Classroom #400 (Band Room)</b>							
	AC Units	4th Floor	3	EA	6	\$1,487	
	Ceiling - Plaster/Drywall	4th Floor	3,060	SF	6	\$10,589	
	Ceiling - Splined	4th Floor	1,920	SF	6	\$1,565	
	Chalk Board	4th Floor	72	LF	4	\$6,610	
	Doors - Wood Doors inclu hw	4th Floor	12	EA	6	\$3,612	
	Floor - Wood	4th Floor	3,060	SF	6	\$21,573	
	Instrument Storage Casework	4th Floor	128	LF	6	\$0	
	Lighting - Pendent/Surface	4th Floor	62	EA	7	\$0	
	Sound System	4th Floor	1	EA	6	\$1,442	
	Walls - Plaster/Drywall	4th Floor	3,472	SF	6	\$9,582	
<b>Classroom #400E (Music Room)</b>							
	Ceiling - Plaster/Drywall	4th Floor	360	SF	6	\$1,246	
	Ceiling - Splined	4th Floor	312	SF	6	\$254	
	Doors - Wood Doors inclu hw	4th Floor	7	EA	6	\$2,107	
	Floor - Wood	4th Floor	360	SF	6	\$2,538	
	Lighting - Pendent/Surface	4th Floor	8	EA	7	\$0	
	Walls - Plaster/Drywall	4th Floor	720	SF	6	\$1,987	
<b>Classroom #400W (Music Room)</b>							
	Ceiling - Plaster/Drywall	4th Floor	360	SF	6	\$1,246	
	Ceiling - Splined	4th Floor	312	SF	6	\$254	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	4th Floor	7	EA	6	\$2,107	
	Floor - Wood	4th Floor	360	SF	6	\$2,538	
	Lighting - Pendent/Surface	4th Floor	8	EA	7	\$0	
	Walls - Plaster/Drywall	4th Floor	720	SF	6	\$1,987	
<b>Classroom #402 (Choral Room)</b>							
	Casework	4th Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	4th Floor	5	SF	5	\$62	Location: SW corner
	Ceiling - Plaster/Drywall	4th Floor	1,470	SF	6	\$5,087	
	Ceiling - Splined	4th Floor	900	SF	6	\$734	
	Chalk Board	4th Floor	36	LF	4	\$3,305	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #402 (Choral Room)</b>							
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	1,470	SF	6	\$10,363	
	Instrument Storage Casework	4th Floor	24	LF	6	\$0	
	Lighting - Pendent/Surface	4th Floor	24	EA	7	\$0	
	Risers	4th Floor	16	LF	6	\$360	
	Sound Panels	4th Floor	12	EA	6	\$48	
	Sound System	4th Floor	1	EA	6	\$1,442	
	Walls - Plaster/Drywall	4th Floor	2,210	SF	6	\$6,099	
<b>Classroom #403 (Music Room)</b>							
	Ceiling - Plaster/Drywall	4th Floor	10	SF	5	\$125	Location: NE; peeling
	Ceiling - Plaster/Drywall	4th Floor	775	SF	6	\$2,682	
	Ceiling - Splined	4th Floor	468	SF	6	\$381	
	Ceiling - Splined	4th Floor	15	SF	5	\$145	Location: NE; water damage
	Chalk Board	4th Floor	28	LF	4	\$2,571	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	775	SF	6	\$5,464	
	Lighting - Chandelier, Incandescent	4th Floor	12	EA	7	\$0	
	Sound Panels	4th Floor	6	EA	6	\$24	
	Sound System	4th Floor	1	EA	6	\$1,442	
	Storage/ Closet	4th Floor	120	SF	6	\$870	
	Walls - Plaster/Drywall	4th Floor	1,456	SF	6	\$4,018	
<b>Classroom #427 (Regular Classroom)</b>							
	AC Units	4th Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	4th Floor	741	SF	6	\$2,564	
	Ceiling - Plaster/Drywall	4th Floor	9	SF	5	\$112	Peeling, water damage
	Chalk Board	4th Floor	28	LF	4	\$2,571	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	750	SF	6	\$5,287	
	Lighting - Chandelier, Incandescent	4th Floor	12	EA	7	\$0	T-8 retro fit
	Marker Board	4th Floor	22	LF	7	\$0	
	Storage/ Closet	4th Floor	58	SF	6	\$421	
	Walls - Plaster/Drywall	4th Floor	1,430	SF	6	\$3,947	
<b>Classroom #428 (Regular Classroom)</b>							
	AC Units	4th Floor	1	EA	6	\$496	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #428 (Regular Classroom)</b>							
	Casework	4th Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	4th Floor	744	SF	6	\$2,575	
	Chalk Board	4th Floor	28	LF	4	\$2,571	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	744	SF	6	\$5,245	
	Lighting - Chandelier, Incandescent	4th Floor	12	EA	7	\$0	T-8 retro fit
	Marker Board	4th Floor	22	LF	7	\$0	
	Storage/ Closet	4th Floor	58	SF	6	\$421	
	Walls - Plaster/Drywall	4th Floor	1,410	SF	6	\$3,891	
	Walls - Plaster/Drywall	4th Floor	8	SF	5	\$41	Peeling plaster
<b>Classroom #429 (Regular Classroom)</b>							
	AC Units	4th Floor	1	EA	6	\$496	
	Ceiling - Splined	4th Floor	705	SF	6	\$575	
	Chalk Board	4th Floor	50	LF	4	\$4,590	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	705	SF	6	\$4,970	
	Lighting - Pendent/Surface	4th Floor	12	EA	4	\$6,488	T-12 bulbs
	Storage/ Closet	4th Floor	58	SF	6	\$421	
	Walls - Plaster/Drywall	4th Floor	1,515	SF	6	\$4,181	
<b>Classroom #430 (Science Lab Level 1)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	98	LF	6	\$2,475	
	Ceiling - Plaster/Drywall	4th Floor	1,056	SF	6	\$3,654	
	Chalk Board	4th Floor	108	LF	4	\$9,915	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Eye Wash Station	4th Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	4th Floor	1,056	SF	5	\$4,742	Damaged throughout
	Fume Hood	4th Floor	1	EA	6	\$816	
	Gas Line	4th Floor	10	EA	6	\$5,091	
	Lighting - Pendent/Surface	4th Floor	18	EA	7	\$0	
	Science Lab Elements	4th Floor	25	SF	6	\$169	
	Storage/ Closet	4th Floor	36	SF	6	\$261	
	Walls - Plaster/Drywall	4th Floor	1,632	SF	6	\$4,504	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #430 (Science Lab Level 1)</b>							
	Work Sink	4th Floor	5	EA	6	\$1,895	
<b>Classroom #430/431 Office (Office)</b>							
	Casework	4th Floor	36	LF	6	\$909	
	Ceiling - Plaster/Drywall	4th Floor	196	SF	6	\$678	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Eye Wash Station	4th Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	4th Floor	196	SF	6	\$196	
	Fume Hood	4th Floor	1	EA	6	\$816	
	Gas Line	4th Floor	6	EA	6	\$3,055	
	Lighting - Pendent/Surface	4th Floor	4	EA	6	\$496	
	Science Lab Elements	4th Floor	10	SF	6	\$68	
	Walls - Plaster/Drywall	4th Floor	312	SF	6	\$861	
	Work Sink	4th Floor	1	EA	6	\$379	
<b>Classroom #431 (Science Lab Level 1)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	96	LF	6	\$2,424	
	Ceiling - Plaster/Drywall	4th Floor	924	SF	6	\$3,198	
	Chalk Board	4th Floor	108	LF	4	\$9,915	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	\$301	
	Eye Wash Station	4th Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	4th Floor	924	SF	6	\$925	
	Fume Hood	4th Floor	1	EA	6	\$816	
	Gas Line	4th Floor	10	EA	6	\$5,091	
	Lighting - Pendent/Surface	4th Floor	18	EA	7	\$0	
	Science Lab Elements	4th Floor	25	SF	6	\$169	
	Storage/ Closet	4th Floor	36	SF	6	\$261	
	Walls - Plaster/Drywall	4th Floor	5	SF	5	\$26	Location: SE corner; damaged
	Walls - Plaster/Drywall	4th Floor	1,536	SF	6	\$4,239	
	Work Sink	4th Floor	4	EA	6	\$1,516	
<b>Classroom #432 (Regular Classroom)</b>							
	AC Units	4th Floor	1	EA	6	\$496	
	Casework	4th Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	4th Floor	723	SF	6	\$2,502	
	Chalk Board	4th Floor	44	LF	4	\$4,039	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #432 (Regular Classroom)</b>							
	Floor - Wood	4th Floor	723	SF	6	\$5,097	
	Lighting - Chandelier, Incandescent	4th Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	4th Floor	1,162	SF	6	\$3,207	
<b>Classroom #433 (Regular Classroom)</b>							
	AC Units	4th Floor	1	EA	6	\$496	
	Casework	4th Floor	22	LF	6	\$556	
	Ceiling - Splined	4th Floor	735	SF	6	\$599	
	Chalk Board	4th Floor	6	LF	4	\$551	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	\$301	
	Floor - Wood	4th Floor	735	SF	6	\$5,182	
	Lighting - Pendent/Surface	4th Floor	6	EA	4	\$3,244	T-12 bulbs
	Marker Board	4th Floor	10	LF	7	\$0	
	Storage/ Closet	4th Floor	120	SF	6	\$870	
	Walls - Plaster/Drywall	4th Floor	1,417	SF	6	\$3,911	
<b>Classroom #434 (Science Lab Level 1)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	85	LF	6	\$2,147	
	Ceiling - Plaster/Drywall	4th Floor	1,056	SF	6	\$3,654	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Eye Wash Station	4th Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	4th Floor	1,056	SF	5	\$4,742	Damage throughout
	Fume Hood	4th Floor	1	EA	6	\$816	
	Gas Line	4th Floor	6	EA	6	\$3,055	
	Lighting - Pendent/Surface	4th Floor	18	EA	7	\$0	
	Marker Board	4th Floor	108	LF	7	\$0	
	Science Lab Elements	4th Floor	25	SF	6	\$169	
	Storage/ Closet	4th Floor	36	SF	6	\$261	
	Walls - Plaster/Drywall	4th Floor	1,632	SF	6	\$4,504	
	Work Sink	4th Floor	4	EA	6	\$1,516	
<b>Classroom #434/438 Office (Office)</b>							
	Casework	4th Floor	40	LF	6	\$1,010	
	Ceiling - Plaster/Drywall	4th Floor	196	SF	6	\$678	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Eye Wash Station	4th Floor	1	EA	6	\$336	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #434/438 Office (Office)</b>							
	Floor - Tile/Sheet	4th Floor	196	SF	6	\$196	
	Fume Hood	4th Floor	1	EA	6	\$816	
	Gas Line	4th Floor	6	EA	6	\$3,055	
	Lighting - Pendent/Surface	4th Floor	4	EA	7	\$0	
	Science Lab Elements	4th Floor	16	SF	6	\$108	
	Walls - Plaster/Drywall	4th Floor	312	SF	6	\$861	
	Work Sink	4th Floor	1	EA	6	\$379	
<b>Classroom #435 (Science Lab Level 1)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	40	LF	6	\$1,010	
	Ceiling - Plaster/Drywall	4th Floor	1,104	SF	6	\$3,821	
	Chalk Board	4th Floor	44	LF	4	\$4,039	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Eye Wash Station	4th Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	4th Floor	1,104	SF	5	\$4,957	Damage throughout
	Fume Hood	4th Floor	1	EA	6	\$816	
	Gas Line	4th Floor	6	EA	6	\$3,055	
	Lighting - Pendent/Surface	4th Floor	20	EA	7	\$0	
	Marker Board	4th Floor	22	LF	7	\$0	
	Science Lab Elements	4th Floor	25	SF	6	\$169	
	Storage/ Closet	4th Floor	36	SF	6	\$261	
	Walls - Plaster/Drywall	4th Floor	1,820	SF	6	\$5,023	
	Work Sink	4th Floor	3	EA	6	\$1,137	
<b>Classroom #435/439 Office (Office)</b>							
	Casework	4th Floor	40	LF	6	\$1,010	
	Ceiling - Plaster/Drywall	4th Floor	196	SF	6	\$678	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	4th Floor	196	SF	6	\$196	
	Fume Hood	4th Floor	1	EA	6	\$816	
	Gas Line	4th Floor	6	EA	6	\$3,055	
	Lighting - Chandelier, Incandescent	4th Floor	4	EA	7	\$0	
	Science Lab Elements	4th Floor	16	SF	6	\$108	
	Walls - Plaster/Drywall	4th Floor	312	SF	6	\$861	
	Work Sink	4th Floor	1	EA	6	\$379	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #436 (Regular Classroom)</b>							
	AC Units	4th Floor	1	EA	6	\$496	
	Casework	4th Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	4th Floor	560	SF	6	\$1,938	
	Chalk Board	4th Floor	6	LF	6	\$134	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	560	SF	6	\$3,948	
	Lighting - Pendent/Surface	4th Floor	12	EA	7	\$0	
	Marker Board	4th Floor	44	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	1,152	SF	6	\$3,179	
<b>Classroom #437 (Regular Classroom)</b>							
	AC Units	4th Floor	1	EA	6	\$496	
	Ceiling - Splined	4th Floor	680	SF	6	\$554	
	Ceiling - Splined	4th Floor	20	SF	5	\$193	Water damage
	Doors - Steel Doors incl hw	4th Floor	1	EA	6	\$301	
	Doors - Transom Window	4th Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	\$301	
	Floor - Wood	4th Floor	700	SF	6	\$4,935	
	Lighting - Chandelier, Incandescent	4th Floor	12	EA	4	\$12,680	T-12 bulbs
	Marker Board	4th Floor	21	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	1,383	SF	6	\$3,817	
	Work Sink	4th Floor	1	EA	6	\$379	
<b>Classroom #438 (Science Lab Level 1)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	98	LF	6	\$2,475	
	Ceiling - Plaster/Drywall	4th Floor	1,008	SF	6	\$3,488	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Eye Wash Station	4th Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	4th Floor	1,008	SF	6	\$1,009	
	Fume Hood	4th Floor	1	EA	6	\$816	
	Gas Line	4th Floor	6	EA	6	\$3,055	
	Lighting - Pendent/Surface	4th Floor	18	EA	7	\$0	
	Marker Board	4th Floor	36	LF	7	\$0	
	Science Lab Elements	4th Floor	25	SF	6	\$169	
	Storage/ Closet	4th Floor	36	SF	6	\$261	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #438 (Science Lab Level 1)</b>							
	Walls - Plaster/Drywall	4th Floor	1,584	SF	6	\$4,372	
	Work Sink	4th Floor	4	EA	6	\$1,516	
<b>Classroom #439 (Science Lab Level 1)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	54	LF	6	\$1,364	
	Ceiling - Plaster/Drywall	4th Floor	1,068	SF	6	\$3,696	
	Chalk Board	4th Floor	24	LF	4	\$2,203	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Eye Wash Station	4th Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	4th Floor	1,068	SF	6	\$1,069	
	Fume Hood	4th Floor	1	EA	6	\$816	
	Gas Line	4th Floor	6	EA	6	\$3,055	
	Lighting - Pendent/Surface	4th Floor	20	EA	7	\$0	
	Marker Board	4th Floor	12	LF	7	\$0	
	Science Lab Elements	4th Floor	25	SF	6	\$169	
	Storage/ Closet	4th Floor	36	SF	6	\$261	
	Walls - Plaster/Drywall	4th Floor	1,716	SF	6	\$4,736	
	Work Sink	4th Floor	3	EA	6	\$1,137	
<b>Classroom #440 (Regular Classroom)</b>							
	AC Units	4th Floor	1	EA	6	\$496	
	Casework	4th Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	4th Floor	624	SF	6	\$2,159	
	Chalk Board	4th Floor	6	LF	4	\$551	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	624	SF	6	\$4,399	
	Lighting - Pendent/Surface	4th Floor	12	EA	7	\$0	
	Marker Board	4th Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	1,200	SF	6	\$3,312	
	Work Sink	4th Floor	1	EA	6	\$379	
<b>Classroom #441 (Regular Classroom)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	4th Floor	864	SF	6	\$2,990	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	



**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #441 (Regular Classroom)</b>							
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	864	SF	6	\$6,091	
	Lighting - Pendent/Surface	4th Floor	16	EA	7	\$0	
	Marker Board	4th Floor	58	LF	7	\$0	
	Walls - Plaster/Drywall	4th Floor	10	SF	5	\$51	Location: NE; cracking
	Walls - Plaster/Drywall	4th Floor	16	SF	5	\$82	Location: S; exposed, damaged
	Walls - Plaster/Drywall	4th Floor	2,160	SF	6	\$5,961	
<b>Classroom #442A (Store Room)</b>							
	Casework	4th Floor	12	LF	6	\$303	
	Ceiling - Splined	4th Floor	8	SF	5	\$77	Location: NE corner; water damage
	Ceiling - Splined	4th Floor	864	SF	6	\$704	
	Chalk Board	4th Floor	22	LF	4	\$2,020	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	864	SF	6	\$6,091	
	Lighting - Chandelier, Incandescent	4th Floor	16	EA	6	\$7,641	
	Walls - Plaster/Drywall	4th Floor	10	SF	5	\$51	Location: NE corner; cracking
	Walls - Plaster/Drywall	4th Floor	10	SF	5	\$51	Location: NW corner; cracking
	Walls - Plaster/Drywall	4th Floor	1,508	SF	6	\$4,162	
	Work Sink	4th Floor	1	EA	6	\$379	
<b>Classroom #443 (Art Room)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	64	LF	6	\$1,616	
	Ceiling - Plaster/Drywall	4th Floor	1,089	SF	6	\$3,769	
	Chalk Board	4th Floor	20	LF	4	\$1,836	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	3	EA	6	\$903	
	Floor - Tile/Sheet	4th Floor	5	SF	5	\$29	Location: NE; missing tiles
	Floor - Tile/Sheet	4th Floor	1,089	SF	6	\$1,090	
	Instructional Surface	4th Floor	10	LF	6	\$337	
	Kiln	4th Floor	1	EA	6	\$2,321	
	Lighting - Chandelier, Incandescent	4th Floor	24	EA	7	\$0	
	Walls - Plaster/Drywall	4th Floor	10	SF	5	\$51	Location: W; plaster torn, damaged
	Walls - Plaster/Drywall	4th Floor	2,448	SF	6	\$6,756	
	Work Sink	4th Floor	2	EA	6	\$758	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #444 (Band Room)</b>							
	Casework	4th Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	4th Floor	10	SF	5	\$125	Location: SW corner; water damage
	Ceiling - Plaster/Drywall	4th Floor	3,500	SF	6	\$12,112	
	Ceiling - Splined	4th Floor	2,030	SF	6	\$1,655	
	Chalk Board	4th Floor	30	LF	4	\$2,754	
	Doors - Transom Window	4th Floor	126	SF	6	\$2,133	
	Doors - Wood Doors inclu hw	4th Floor	6	EA	6	\$1,806	
	Floor - Wood	4th Floor	3,500	SF	6	\$24,675	
	Instrument Storage Casework	4th Floor	28	LF	6	\$0	
	Lighting - Chandelier, Incandescent	4th Floor	56	EA	7	\$0	
	Risers	4th Floor	18	LF	6	\$405	
	Sound System	4th Floor	1	EA	6	\$1,442	
	Storage/ Closet	4th Floor	900	SF	6	\$6,525	See 448
	Walls - Plaster/Drywall	4th Floor	3,472	SF	6	\$9,582	
<b>Classroom #445 (Art Room)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	54	LF	6	\$1,364	
	Ceiling - Plaster/Drywall	4th Floor	1,188	SF	6	\$4,111	
	Chalk Board	4th Floor	22	LF	4	\$2,020	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	1,188	SF	5	\$17,379	Damaged throughout
	Lighting - Pendent/Surface	4th Floor	9	EA	7	\$0	
	Lighting - Pendent/Surface	4th Floor	36	EA	7	\$0	
	Storage/ Closet	4th Floor	180	SF	6	\$1,305	
	Walls - Plaster/Drywall	4th Floor	10	SF	5	\$51	Location: E; cracking
	Walls - Plaster/Drywall	4th Floor	1,632	SF	6	\$4,504	
	Work Sink	4th Floor	3	EA	6	\$1,137	
<b>Classroom #445A (Special Program)</b>							
	Ceiling - Plaster/Drywall	4th Floor	648	SF	6	\$2,242	
	Doors - Wood Doors inclu hw	4th Floor	3	EA	6	\$903	
	Floor - Concrete	4th Floor	648	SF	6	\$343	
	Lighting - Pendent/Surface	4th Floor	3	EA	6	\$372	
	Storage/ Closet	4th Floor	30	SF	6	\$218	
	Walls - Plaster/Drywall	4th Floor	1,025	SF	6	\$2,829	
	Walls - Tile	4th Floor	49	SF	6	\$107	
	Work Sink	4th Floor	3	EA	6	\$1,137	

**Building: Main**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #447 (Art Room)</b>							
	AC Units	4th Floor	2	EA	6	\$991	
	Casework	4th Floor	64	LF	6	\$1,616	
	Ceiling - Lay-in	4th Floor	308	SF	6	\$925	
	Ceiling - Plaster/Drywall	4th Floor	1,089	SF	6	\$3,769	
	Chalk Board	4th Floor	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	4th Floor	1,089	SF	5	\$4,890	damaged throughout
	Instructional Surface	4th Floor	10	LF	6	\$337	
	Lighting - Pendent/Surface	4th Floor	24	EA	7	\$0	
	Walls - Plaster/Drywall	4th Floor	2,448	SF	6	\$6,756	
	Work Sink	4th Floor	2	EA	6	\$758	
<b>Classroom #448 (Store Room)</b>							
	Casework	4th Floor	50	LF	6	\$1,263	
	Ceiling - Plaster/Drywall	4th Floor	930	SF	6	\$3,218	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	\$602	
	Floor - Wood	4th Floor	930	SF	6	\$6,556	
	Lighting - Pendent/Surface	4th Floor	20	EA	7	\$0	
	Storage/ Closet	4th Floor	90	SF	6	\$653	
	Student Lockers - One Tier	4th Floor	305	EA	6	\$28,315	
	Walls - Plaster/Drywall	4th Floor	1,360	SF	6	\$3,753	
<b>Classroom #inside 252 (Multi Purpose Room)</b>							
	Ceiling - Lay-in	2nd Floor	139	SF	6	\$417	
	Chalk Board	2nd Floor	11	LF	4	\$1,010	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Carpet	2nd Floor	139	SF	6	\$296	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	\$0	
	Walls - Metal Panel	2nd Floor	267	SF	6	\$1,993	metal panel partition wall with fabric
	Walls - Plaster/Drywall	2nd Floor	112	SF	6	\$309	lower part of walls
	Walls - Tile	2nd Floor	10	SF	6	\$22	lay-in tiles (act) used on upper part of walls

**Classrooms Subtotal:**
**\$3,249,105**
**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Ceiling - Plaster/Drywall	1st- 108E- Football Coach	277	SF	6	\$959	
	Doors - Wood Doors inclu hw	1st- 108E- Football Coach	1	EA	6	\$301	
	Floor - Wood	1st- 108E- Football Coach	277	SF	6	\$1,953	
	Lighting - Pendent/Surface	1st- 108E- Football Coach	4	EA	7	\$0	
	Power Distribution	1st- 108E- Football Coach	9	EA	6	\$19,124	
	Storage/ Closet	1st- 108E- Football Coach	50	SF	6	\$363	
	Walls - Plaster/Drywall	1st- 108E- Football Coach	735	SF	6	\$2,029	
	AC Unit	1st- 114-A Alumni Assoc	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st- 114-A Alumni Assoc	260	SF	6	\$900	
	Doors - Transom Window	1st- 114-A Alumni Assoc	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st- 114-A Alumni Assoc	1	EA	6	\$301	
	Floor - Wood	1st- 114-A Alumni Assoc	260	SF	6	\$1,833	
	Lighting - Pendent/Surface	1st- 114-A Alumni Assoc	4	EA	7	\$0	
	Power Distribution	1st- 114-A Alumni Assoc	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st- 114-A Alumni Assoc	910	SF	6	\$2,512	
	Ceiling - Plaster/Drywall	1st- 118- Admissions	296	SF	6	\$1,024	
	Doors - Wood Doors inclu hw	1st- 118- Admissions	1	EA	6	\$301	
	Floor - Carpet	1st- 118- Admissions	296	SF	6	\$631	
	Lighting - Pendent/Surface	1st- 118- Admissions	8	EA	7	\$0	
	Power Distribution	1st- 118- Admissions	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	1st- 118- Admissions	400	SF	6	\$1,104	
	Walls - Structural Glazed Tile	1st- 118- Admissions	240	SF	6	\$755	
	AC Unit	1st- 118- Budget	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st- 118- Budget	296	SF	6	\$1,024	
	Doors - Wood Doors inclu hw	1st- 118- Budget	1	EA	6	\$301	
	Floor - Carpet	1st- 118- Budget	296	SF	6	\$631	
	Lighting - Pendent/Surface	1st- 118- Budget	8	EA	7	\$0	
	Power Distribution	1st- 118- Budget	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	1st- 118- Budget	240	SF	6	\$662	
	Walls - Structural Glazed Tile	1st- 118- Budget	400	SF	6	\$1,258	
	AC Unit	1st- 118- Building Operations	2	EA	6	\$991	
	Ceiling - Lay-in	1st- 118- Building Operations	336	SF	6	\$1,009	Under Loft
	Ceiling - Plaster/Drywall	1st- 118- Building Operations	1,527	SF	6	\$5,284	
	Doors - Wood Doors inclu hw	1st- 118- Building Operations	2	EA	6	\$602	
	Floor - Wood	1st- 118- Building Operations	1,527	SF	6	\$10,765	vinyl that looks like wood
	Lighting - Lay-in	1st- 118- Building Operations	4	EA	7	\$0	
	Lighting - Pendent/Surface	1st- 118- Building Operations	18	EA	7	\$0	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Power Distribution	1st- 118- Building Operations	12	EA	7	\$0	
	Storage/ Closet	1st- 118- Building Operations	316	SF	6	\$2,291	loft storage area
	Walls - Plaster/Drywall	1st- 118- Building Operations	273	SF	6	\$753	
	Walls - Structural Glazed Tile	1st- 118- Building Operations	2,462	SF	6	\$7,745	
	Ceiling - Plaster/Drywall	1st- 118- LTAC	296	SF	6	\$1,024	
	Doors - Wood Doors inclu hw	1st- 118- LTAC	1	EA	6	\$301	
	Floor - Carpet	1st- 118- LTAC	296	SF	6	\$631	
	Lighting - Pendent/Surface	1st- 118- LTAC	8	EA	7	\$0	
	Power Distribution	1st- 118- LTAC	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	1st- 118- LTAC	400	SF	6	\$1,104	
	Walls - Structural Glazed Tile	1st- 118- LTAC	240	SF	6	\$755	
	AC Unit	1st- 118 Programming	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st- 118 Programming	296	SF	6	\$1,024	
	Doors - Wood Doors inclu hw	1st- 118 Programming	1	EA	6	\$301	
	Floor - Carpet	1st- 118 Programming	296	SF	6	\$631	
	Lighting - Pendent/Surface	1st- 118 Programming	8	EA	7	\$0	
	Power Distribution	1st- 118 Programming	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	1st- 118 Programming	400	SF	6	\$1,104	
	Walls - Structural Glazed Tile	1st- 118 Programming	240	SF	6	\$755	
	AC Unit	1st- 118A	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st- 118A	388	SF	6	\$1,343	
	Doors - Wood Doors inclu hw	1st- 118A	2	EA	6	\$602	
	Floor - Carpet	1st- 118A	388	SF	6	\$827	
	Lighting - Pendent/Surface	1st- 118A	1	EA	6	\$124	Missing a cover
	Lighting - Pendent/Surface	1st- 118A	5	EA	7	\$0	
	Power Distribution	1st- 118A	4	EA	6	\$8,500	
	Storage/ Closet	1st- 118A	7	SF	6	\$51	
	Walls - Structural Glazed Tile	1st- 118A	972	SF	6	\$3,058	
	Work Slnk	1st- 118A	1	EA	6	\$508	
	Ceiling - Splined	1st- Asst Principal 1	156	SF	6	\$127	
	Doors - Wood Doors inclu hw	1st- Asst Principal 1	1	EA	6	\$301	
	Floor - Carpet	1st- Asst Principal 1	156	SF	6	\$332	
	Lighting - Pendent/Surface	1st- Asst Principal 1	2	EA	7	\$0	
	Power Distribution	1st- Asst Principal 1	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st- Asst Principal 1	663	SF	6	\$1,830	
	AC Unit	1st- Asst Principal 2	1	EA	6	\$496	
	Ceiling - Splined	1st- Asst Principal 2	153	SF	6	\$125	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Doors - Wood Doors inclu hw	1st- Asst Principal 2	2	EA	6	\$602	
	Floor - Carpet	1st- Asst Principal 2	153	SF	6	\$326	
	Lighting - Pendent/Surface	1st- Asst Principal 2	1	EA	7	\$0	
	Power Distribution	1st- Asst Principal 2	6	EA	6	\$12,749	
	Storage/ Closet	1st- Asst Principal 2	12	SF	6	\$87	
	Walls - Plaster/Drywall	1st- Asst Principal 2	644	SF	6	\$1,777	
	AC Unit	1st- Asst Principal 3	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st- Asst Principal 3	300	SF	5	\$2,750	peeling & cracks
	Doors - Wood Doors inclu hw	1st- Asst Principal 3	1	EA	6	\$301	
	Floor - Carpet	1st- Asst Principal 3	300	SF	6	\$639	
	Lighting - Pendent/Surface	1st- Asst Principal 3	2	EA	7	\$0	
	Power Distribution	1st- Asst Principal 3	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st- Asst Principal 3	886	SF	6	\$2,445	
	Walls - Plaster/Drywall	1st- Asst Principal 3	18	SF	5	\$92	wall by window cracked & deteriorating
	AC Unit	1st- Asst Principal 4	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st- Asst Principal 4	256	SF	6	\$886	
	Doors - Wood Doors inclu hw	1st- Asst Principal 4	1	EA	6	\$301	
	Floor - Wood	1st- Asst Principal 4	256	SF	6	\$1,805	
	Lighting - Pendent/Surface	1st- Asst Principal 4	4	EA	6	\$496	*Possibility these bulbs are T-12. Fixtures are old & unsure if they were retrofitted with a new ballast.
	Power Distribution	1st- Asst Principal 4	4	EA	6	\$8,500	
	Storage/ Closet	1st- Asst Principal 4	27	SF	6	\$196	
	Walls - Plaster/Drywall	1st- Asst Principal 4	20	SF	5	\$102	wall deterioration
	Walls - Plaster/Drywall	1st- Asst Principal 4	832	SF	6	\$2,296	
	AC Unit	1st- Asst Principal 5	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st- Asst Principal 5	289	SF	6	\$1,000	
	Doors - Wood Doors inclu hw	1st- Asst Principal 5	1	EA	6	\$301	
	Floor - Terrazzo	1st- Asst Principal 5	289	SF	6	\$632	
	Lighting - Pendent/Surface	1st- Asst Principal 5	4	EA	6	\$496	*Possibility these bulbs are T-12. Fixtures are old & unsure if they were retrofitted with a new ballast.
	Power Distribution	1st- Asst Principal 5	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	1st- Asst Principal 5	917	SF	6	\$2,531	
	AC Unit	1st- Asst Principal 6	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st- Asst Principal 6	103	SF	5	\$1,108	Peeling
	Ceiling - Plaster/Drywall	1st- Asst Principal 6	154	SF	6	\$533	
	Doors - Wood Doors inclu hw	1st- Asst Principal 6	1	EA	6	\$301	
	Floor - Terrazzo	1st- Asst Principal 6	257	SF	6	\$562	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Lighting - Pendant/Surface	1st- Asst Principal 6	4	EA	6	\$496	*Possibility these bulbs are T-12. Fixtures are old & unsure if they were retrofitted with a new ballast.
	Power Distribution	1st- Asst Principal 6	6	EA	6	\$12,749	
	Storage/ Closet	1st- Asst Principal 6	27	SF	6	\$196	
	Walls - Plaster/Drywall	1st- Asst Principal 6	852	SF	6	\$2,351	15sf has minor cracking
	Ceiling - Splined	1st- Conference Room in Principal's Suite	670	SF	6	\$546	
	Doors - Wood Doors inclu hw	1st- Conference Room in Principal's Suite	3	EA	6	\$903	
	Floor - Wood	1st- Conference Room in Principal's Suite	670	SF	6	\$4,723	
	Lighting - Pendant/Surface	1st- Conference Room in Principal's Suite	6	EA	7	\$0	
	Power Distribution	1st- Conference Room in Principal's Suite	2	EA	6	\$4,250	
	Storage/ Closet	1st- Conference Room in Principal's Suite	42	SF	6	\$305	
	Walls - Plaster/Drywall	1st- Conference Room in Principal's Suite	1,675	SF	6	\$4,623	
	Ceiling - Plaster/Drywall	1st floor - 130 staff lounge	732	SF	6	\$2,533	
	Doors - Wood Doors inclu hw	1st floor - 130 staff lounge	1	EA	6	\$301	
	Floor - Carpet	1st floor - 130 staff lounge	732	SF	6	\$1,560	
	Lighting - Pendant/Surface	1st floor - 130 staff lounge	16	EA	7	\$0	
	Power Distribution	1st floor - 130 staff lounge	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st floor - 130 staff lounge	727	SF	6	\$2,006	
	Walls - Structural Glazed Tile	1st floor - 130 staff lounge	961	SF	6	\$3,023	
	AC Unit	1st floor - 134 staff dining	4	EA	6	\$1,982	
	Ceiling - Splined	1st floor - 134 staff dining	2,340	SF	7	\$0	new renovation work
	Doors - Wood Doors inclu hw	1st floor - 134 staff dining	1	EA	6	\$301	
	Floor - Wood	1st floor - 134 staff dining	1,884	SF	7	\$0	new renovation work
	Lighting - Pendant/Surface	1st floor - 134 staff dining	37	EA	7	\$0	
	Power Distribution	1st floor - 134 staff dining	36	EA	7	\$0	new renovation work
	Walls - Plaster/Drywall	1st floor - 134 staff dining	3,011	SF	7	\$0	new renovation work
	Work Slnk	1st floor - 134 staff dining	1	EA	7	\$0	new
	Ceiling - Plaster/Drywall	1st floor - back kitchen office	120	SF	6	\$415	entire ceiling peeling / flaking
	Doors - Transom Window	1st floor - back kitchen office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st floor - back kitchen office	1	EA	6	\$301	
	Floor - Tile	1st floor - back kitchen office	120	SF	6	\$263	
	Lighting - Pendant/Surface	1st floor - back kitchen office	1	EA	5	\$183	old ceiling fan with light
	Power Distribution	1st floor - back kitchen office	4	EA	6	\$8,500	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Storage/ Closet	1st floor - back kitchen office	16	SF	6	\$116	
	Walls - Plaster/Drywall	1st floor - back kitchen office	619	SF	6	\$1,708	
	AC Unit	1st floor - bedroom inside 157A	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st floor - bedroom inside 157A	182	SF	6	\$630	
	Doors - Wood Doors inclu hw	1st floor - bedroom inside 157A	1	EA	6	\$301	
	Floor - Wood	1st floor - bedroom inside 157A	182	SF	6	\$1,283	
	Lighting - Pendent/Surface	1st floor - bedroom inside 157A	2	EA	7	\$0	
	Power Distribution	1st floor - bedroom inside 157A	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st floor - bedroom inside 157A	618	SF	6	\$1,706	
	AC Unit	1st floor - food service manager office south side of lunchroom serving room	1	EA	4	\$6,086	not on dedicated circuit, duct tape used to seal
	Ceiling - Plaster/Drywall	1st floor - food service manager office south side of lunchroom serving room	113	SF	6	\$391	
	Ceiling - Plaster/Drywall	1st floor - food service manager office south side of lunchroom serving room	3	SF	5	\$37	ceiling cracking / peeling
	Doors - Transom Window	1st floor - food service manager office south side of lunchroom serving room	32	SF	6	\$542	3 transoms
	Doors - Wood Doors inclu hw	1st floor - food service manager office south side of lunchroom serving room	1	EA	6	\$301	
	Floor - Tile	1st floor - food service manager office south side of lunchroom serving room	110	SF	6	\$241	
	Lighting - Pendent/Surface	1st floor - food service manager office south side of lunchroom serving room	1	EA	7	\$0	
	Power Distribution	1st floor - food service manager office south side of lunchroom serving room	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st floor - food service manager office south side of lunchroom serving room	600	SF	6	\$1,656	
	Ceiling - Exposed	1st floor - inside 130 staff lounge	127	SF	6	\$189	
	Ceiling - Exposed	1st floor - inside 130 staff lounge	88	SF	6	\$131	
	Doors - Wood Doors inclu hw	1st floor - inside 130 staff lounge	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st floor - inside 130 staff lounge	1	EA	6	\$301	
	Floor - Carpet	1st floor - inside 130 staff lounge	127	SF	6	\$271	
	Floor - Carpet	1st floor - inside 130 staff lounge	88	SF	6	\$188	
	Lighting - Pendent/Surface	1st floor - inside 130 staff lounge	2	EA	7	\$0	
	Lighting - Pendent/Surface	1st floor - inside 130 staff lounge	2	EA	7	\$0	
	Power Distribution	1st floor - inside 130 staff lounge	8	EA	6	\$16,999	
	Power Distribution	1st floor - inside 130 staff lounge	2	EA	6	\$4,250	
	Walls - Structural Glazed Tile	1st floor - inside 130 staff lounge	396	SF	6	\$1,246	
	Walls - Structural Glazed Tile	1st floor - inside 130 staff lounge	328	SF	6	\$1,032	
	Ceiling - Exposed	1st floor - inside 135	184	SF	6	\$274	



**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Ceiling - Exposed	1st floor - inside 135	133	SF	6	\$198	
	Doors - Wood Doors inclu hw	1st floor - inside 135	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st floor - inside 135	1	EA	6	\$301	
	Floor - Carpet	1st floor - inside 135	184	SF	6	\$392	
	Floor - Carpet	1st floor - inside 135	133	SF	6	\$283	
	Lighting - Pendent/Surface	1st floor - inside 135	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st floor - inside 135	1	EA	7	\$0	
	Power Distribution	1st floor - inside 135	2	EA	6	\$4,250	
	Power Distribution	1st floor - inside 135	2	EA	6	\$4,250	
	Walls - Structural Glazed Tile	1st floor - inside 135	448	SF	6	\$1,409	
	Walls - Structural Glazed Tile	1st floor - inside 135	404	SF	6	\$1,271	
	Ceiling - Lay-in	1st floor - inside classroom 144	76	SF	6	\$228	
	Doors - Wood Doors inclu hw	1st floor - inside classroom 144	1	EA	6	\$301	
	Floor - Tile	1st floor - inside classroom 144	76	SF	6	\$166	
	Lighting - Lay-in	1st floor - inside classroom 144	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st floor - inside classroom 144	128	SF	6	\$353	
	Walls - Structural Glazed Tile	1st floor - inside classroom 144	128	SF	6	\$403	
	Ceiling - Plaster/Drywall	1st floor - office 153A	432	SF	6	\$1,495	
	Doors - Wood Doors inclu hw	1st floor - office 153A	1	EA	6	\$301	
	Floor - Tile	1st floor - office 153A	432	SF	6	\$945	
	Lighting - Pendent/Surface	1st floor - office 153A	6	EA	7	\$0	
	Power Distribution	1st floor - office 153A	10	EA	6	\$21,249	
	Walls - Structural Glazed Tile	1st floor - office 153A	1,326	SF	6	\$4,172	
	Work Slnk	1st floor - office 153A	1	EA	6	\$508	
	AC Unit	1st- Main Office	3	EA	6	\$1,487	
	Ceiling - Splined	1st- Main Office	20	SF	5	\$193	has water stains/damage
	Ceiling - Splined	1st- Main Office	1,776	SF	6	\$1,448	
	Doors - Wood Doors inclu hw	1st- Main Office	4	EA	6	\$1,204	
	Floor - Carpet	1st- Main Office	898	SF	6	\$1,913	
	Floor - Wood	1st- Main Office	898	SF	6	\$6,331	
	Lighting - Pendent/Surface	1st- Main Office	15	EA	7	\$0	
	Power Distribution	1st- Main Office	10	EA	6	\$21,249	
	Storage/ Closet	1st- Main Office	14	SF	6	\$102	
	Walls - Plaster/Drywall	1st- Main Office	2,242	SF	6	\$6,188	
	Ceiling - Plaster/Drywall	1st- Pool Office	203	SF	6	\$703	
	Doors - Side-lite	1st- Pool Office	2	SF	6	\$33	
	Doors - Transom Window	1st- Pool Office	1	SF	6	\$17	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Doors - Wood Doors inclu hw	1st- Pool Office	1	EA	6	\$301	FRP
	Floor - Tile/Sheet	1st- Pool Office	30	SF	5	\$148	worn off/ missing
	Floor - Tile/Sheet	1st- Pool Office	173	SF	6	\$173	
	Lighting - Pendent/Surface	1st- Pool Office	2	EA	7	\$0	
	Power Distribution	1st- Pool Office	4	EA	6	\$8,500	
	Storage/ Closet	1st- Pool Office	23	SF	6	\$167	
	Walls - Structural Glazed Tile	1st- Pool Office	649	SF	6	\$2,042	
	AC Unit	1st- Principal	1	EA	6	\$496	
	Ceiling - Splined	1st- Principal	25	SF	5	\$242	water damage
	Ceiling - Splined	1st- Principal	290	SF	6	\$236	
	Doors - Transom Window	1st- Principal	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st- Principal	1	EA	6	\$301	
	Floor - Wood	1st- Principal	315	SF	6	\$2,221	
	Lighting - Pendent/Surface	1st- Principal	6	EA	7	\$0	
	Power Distribution	1st- Principal	6	EA	6	\$12,749	
	Storage/ Closet	1st- Principal	31	SF	6	\$225	
	Walls - Plaster/Drywall	1st- Principal	975	SF	6	\$2,691	
	AC Unit	1st- Records Office	1	EA	6	\$496	
	Ceiling - Lay-in	1st- Records Office	164	SF	6	\$492	
	Ceiling - Plaster/Drywall	1st- Records Office	163	SF	6	\$564	
	Doors - Transom Window	1st- Records Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st- Records Office	2	EA	6	\$602	
	Floor - Carpet	1st- Records Office	327	SF	6	\$697	
	Lighting - Pendent/Surface	1st- Records Office	2	EA	7	\$0	
	Power Distribution	1st- Records Office	8	EA	6	\$16,999	
	Storage/ Closet	1st- Records Office	150	SF	6	\$1,088	Records Vault
	Walls - Plaster/Drywall	1st- Records Office	933	SF	6	\$2,575	
	Walls - Plaster/Drywall	1st- Records Office	10	SF	5	\$51	Right of window deteriorating
	AC Unit	1st- Room 127- IT	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st- Room 127- IT	539	SF	6	\$1,865	
	Doors - Transom Window	1st- Room 127- IT	9	SF	6	\$152	
	Floor - Wood	1st- Room 127- IT	539	SF	6	\$3,800	needs refinishing
	Lighting - Pendent/Surface	1st- Room 127- IT	10	EA	7	\$0	
	Power Distribution	1st- Room 127- IT	10	EA	6	\$21,249	
	Storage/ Closet	1st- Room 127- IT	10	SF	6	\$73	
	Walls - Structural Glazed Tile	1st- Room 127- IT	1,202	SF	6	\$3,781	
	Work Sink	1st- Room 127- IT	1	EA	6	\$508	faucet leaking

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	AC Unit	1st- Science teacher office (between 119&125)	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st- Science teacher office (between 119&125)	291	SF	5	\$2,667	peeling
	Doors - Wood Doors inclu hw	1st- Science teacher office (between 119&125)	2	EA	6	\$602	
	Floor - Tile	1st- Science teacher office (between 119&125)	12	SF	5	\$69	buckling & damaged
	Floor - Tile	1st- Science teacher office (between 119&125)	279	SF	6	\$610	
	Lighting - Pendent/Surface	1st- Science teacher office (between 119&125)	4	EA	7	\$0	
	Power Distribution	1st- Science teacher office (between 119&125)	4	EA	6	\$8,500	
	Storage/ Closet	1st- Science teacher office (between 119&125)	8	SF	6	\$58	
	Walls - Plaster/Drywall	1st- Science teacher office (between 119&125)	798	SF	6	\$2,202	
	Work Sink	1st- Science teacher office (between 119&125)	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	1st- Tardy Office (Auditorium Lobby)	168	SF	6	\$581	
	Doors - Wood Doors inclu hw	1st- Tardy Office (Auditorium Lobby)	1	EA	6	\$301	
	Floor - Wood	1st- Tardy Office (Auditorium Lobby)	168	SF	6	\$1,184	
	Lighting - Chandelier, Incandescent	1st- Tardy Office (Auditorium Lobby)	1	EA	7	\$0	
	Lighting - Wall Mounted	1st- Tardy Office (Auditorium Lobby)	1	EA	7	\$0	
	Power Distribution	1st- Tardy Office (Auditorium Lobby)	8	EA	6	\$16,999	
	Storage/ Closet	1st- Tardy Office (Auditorium Lobby)	29	SF	6	\$210	
	Walls - Plaster/Drywall	1st- Tardy Office (Auditorium Lobby)	670	SF	6	\$1,849	
	Ceiling - Plaster/Drywall	1st- Ticket Office for Auditorium	168	SF	6	\$581	
	Doors - Wood Doors inclu hw	1st- Ticket Office for Auditorium	1	EA	6	\$301	
	Floor - Wood	1st- Ticket Office for Auditorium	168	SF	6	\$1,184	
	Lighting - Chandelier, Incandescent	1st- Ticket Office for Auditorium	1	EA	7	\$0	ceiling fan/light
	Lighting - Wall Mounted	1st- Ticket Office for Auditorium	1	EA	7	\$0	
	Power Distribution	1st- Ticket Office for Auditorium	8	EA	6	\$16,999	
	Storage/ Closet	1st- Ticket Office for Auditorium	29	SF	6	\$210	
	Walls - Plaster/Drywall	1st- Ticket Office for Auditorium	670	SF	6	\$1,849	
	Ceiling - Plaster/Drywall	1st- Treasurer Office	139	SF	6	\$481	
	Doors - Transom Window	1st- Treasurer Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st- Treasurer Office	1	EA	6	\$301	
	Floor - Carpet	1st- Treasurer Office	139	SF	6	\$296	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Lighting - Pendent/Surface	1st- Treasurer Office	1	EA	7	\$0	
	Power Distribution	1st- Treasurer Office	4	EA	6	\$8,500	
	Storage/ Closet	1st- Treasurer Office	75	SF	6	\$544	Vault
	Walls - Plaster/Drywall	1st- Treasurer Office	624	SF	6	\$1,722	
	AC Unit	247-Office	1	EA	4	\$6,086	not on dedicated circuit, sealed with duct tape
	Ceiling - Plaster/Drywall	247-Office	470	SF	6	\$1,626	
	Doors - Transom Window	247-Office	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	247-Office	1	EA	6	\$301	
	Floor - Tile	247-Office	5	SF	5	\$29	tiles cracked and holes in floors
	Floor - Tile	247-Office	470	SF	6	\$1,028	
	Lighting - Pendent/Surface	247-Office	8	EA	7	\$0	
	Power Distribution	247-Office	17	EA	6	\$36,123	
	Walls - Plaster/Drywall	247-Office	1,000	SF	6	\$2,760	
	Ceiling - Plaster/Drywall	248-Office	282	SF	6	\$976	
	Doors - Transom Window	248-Office	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	248-Office	1	EA	6	\$301	
	Floor - Carpet	248-Office	282	SF	6	\$601	
	Lighting - Pendent/Surface	248-Office	2	EA	7	\$0	
	Power Distribution	248-Office	11	EA	6	\$23,374	
	Walls - Plaster/Drywall	248-Office	868	SF	6	\$2,396	
	AC Unit	2nd- 205 Attendance Office	1	EA	6	\$496	
	Ceiling - Lay-in	2nd- 205 Attendance Office	664	SF	6	\$1,994	
	Doors - Transom Window	2nd- 205 Attendance Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd- 205 Attendance Office	1	EA	6	\$301	
	Floor - Carpet	2nd- 205 Attendance Office	664	SF	6	\$1,415	
	Lighting - Pendent/Surface	2nd- 205 Attendance Office	12	EA	7	\$0	
	Power Distribution	2nd- 205 Attendance Office	14	EA	6	\$29,748	
	Walls - Plaster/Drywall	2nd- 205 Attendance Office	1,139	SF	6	\$3,144	
	AC Unit	2nd- 208-C Athletic Director	1	EA	6	\$496	free-standing unit vented through door into hallway.
	Ceiling - Plaster/Drywall	2nd- 208-C Athletic Director	650	SF	6	\$2,249	
	Doors - Wood Doors inclu hw	2nd- 208-C Athletic Director	1	EA	6	\$301	
	Floor - Wood	2nd- 208-C Athletic Director	650	SF	6	\$4,582	
	Lighting - Pendent/Surface	2nd- 208-C Athletic Director	10	EA	7	\$0	
	Power Distribution	2nd- 208-C Athletic Director	16	EA	6	\$33,998	
	Walls - Plaster/Drywall	2nd- 208-C Athletic Director	941	SF	6	\$2,597	
	Ceiling - Plaster/Drywall	2nd- 210A PE Office	300	SF	6	\$1,038	
	Doors - Wood Doors inclu hw	2nd- 210A PE Office	1	EA	6	\$301	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Floor - Wood	2nd- 210A PE Office	300	SF	6	\$2,115	
	Lighting - Pendent/Surface	2nd- 210A PE Office	4	EA	7	\$0	
	Power Distribution	2nd- 210A PE Office	4	EA	6	\$8,500	
	Storage/ Closet	2nd- 210A PE Office	50	SF	6	\$363	
	Walls - Plaster/Drywall	2nd- 210A PE Office	914	SF	6	\$2,523	
	AC Unit	2nd- 212 Counseling- A	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- A	105	SF	6	\$363	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- A	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- A	105	SF	6	\$224	
	Lighting - Pendent/Surface	2nd- 212 Counseling- A	3	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- A	4	EA	6	\$8,500	
	Walls - Metal Panel	2nd- 212 Counseling- A	135	SF	6	\$1,008	Fabric dividing wall
	Walls - Plaster/Drywall	2nd- 212 Counseling- A	300	SF	6	\$828	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- B	118	SF	6	\$408	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- B	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- B	118	SF	6	\$251	
	Lighting - Pendent/Surface	2nd- 212 Counseling- B	3	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- B	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	2nd- 212 Counseling- B	398	SF	6	\$1,098	
	AC Unit	2nd- 212 Counseling- C	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- C	112	SF	6	\$388	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- C	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- C	112	SF	6	\$239	
	Lighting - Pendent/Surface	2nd- 212 Counseling- C	3	EA	7	\$0	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- Common area (Lobby/ Reception/ Copy & Hallway)	842	SF	6	\$2,914	
	Doors - Transom Window	2nd- 212 Counseling- Common area (Lobby/ Reception/ Copy & Hallway)	27	SF	6	\$457	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- Common area (Lobby/ Reception/ Copy & Hallway)	4	EA	6	\$1,204	
	Floor - Carpet	2nd- 212 Counseling- Common area (Lobby/ Reception/ Copy & Hallway)	842	SF	5	\$4,323	Carpet appears in good condition, but it repeatedly is being soaked with water from leak in adjoining Conference Room & is musty.
	Lighting - Pendent/Surface	2nd- 212 Counseling- Common area (Lobby/ Reception/ Copy & Hallway)	9	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- Common area (Lobby/ Reception/ Copy & Hallway)	10	EA	6	\$21,249	
	Storage/ Closet	2nd- 212 Counseling- Common area (Lobby/ Reception/ Copy & Hallway)	82	SF	6	\$595	File storage room

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Storage/ Closet	2nd- 212 Counseling- Common area (Lobby/ Reception/ Copy & Hallway)	9	SF	6	\$65	located at far end of office, next to Library. Door was locked, so rank is assumed
	Walls - Metal Panel	2nd- 212 Counseling- Common area (Lobby/ Reception/ Copy & Hallway)	572	SF	6	\$4,270	Fabric panel dividing walls
	Walls - Plaster/Drywall	2nd- 212 Counseling- Common area (Lobby/ Reception/ Copy & Hallway)	3,124	SF	6	\$8,622	
	AC Unit	2nd- 212 Counseling- Conference Room	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- Conference Room	204	SF	6	\$706	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- Conference Room	60	SF	5	\$645	water damage
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- Conference Room	2	EA	6	\$602	1 door is missing door hardware
	Floor - Carpet	2nd- 212 Counseling- Conference Room	264	SF	5	\$1,355	Carpet appears in good condition, but it repeatedly is being soaked with water from leak & is musty.
	Lighting - Pendant/Surface	2nd- 212 Counseling- Conference Room	3	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- Conference Room	8	EA	6	\$16,999	
	Walls - Metal Panel	2nd- 212 Counseling- Conference Room	442	SF	6	\$3,299	Fabric dividing walls
	Walls - Plaster/Drywall	2nd- 212 Counseling- Conference Room	417	SF	6	\$1,151	
	Walls - Plaster/Drywall	2nd- 212 Counseling- Conference Room	25	SF	5	\$128	water damage
	Power Distribution	2nd- 212 Counseling- C	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	2nd- 212 Counseling- C	402	SF	6	\$1,109	
	AC Unit	2nd- 212 Counseling- D	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- D	97	SF	6	\$336	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- D	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- D	97	SF	6	\$207	
	Lighting - Pendant/Surface	2nd- 212 Counseling- D	1	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- D	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	2nd- 212 Counseling- D	399	SF	6	\$1,101	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- E	76	SF	6	\$263	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- E	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- E	76	SF	6	\$162	
	Lighting - Pendant/Surface	2nd- 212 Counseling- E	2	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- E	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	2nd- 212 Counseling- E	315	SF	6	\$869	
	AC Unit	2nd- 212 Counseling- F	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- F	94	SF	6	\$325	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- F	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- F	94	SF	6	\$200	
	Lighting - Pendant/Surface	2nd- 212 Counseling- F	3	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- F	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	2nd- 212 Counseling- F	357	SF	6	\$985	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- H	90	SF	6	\$311	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- H	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- H	90	SF	6	\$192	
	Lighting - Pendent/Surface	2nd- 212 Counseling- H	3	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- H	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	2nd- 212 Counseling- H	348	SF	6	\$960	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- I	93	SF	6	\$322	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- I	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- I	93	SF	6	\$198	
	Lighting - Pendent/Surface	2nd- 212 Counseling- I	3	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- I	3	EA	6	\$6,375	
	Walls - Plaster/Drywall	2nd- 212 Counseling- I	357	SF	6	\$985	2sf area had a minor crack
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- J	93	SF	6	\$322	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- J	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- J	93	SF	6	\$198	
	Lighting - Pendent/Surface	2nd- 212 Counseling- J	2	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- J	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	2nd- 212 Counseling- J	357	SF	6	\$985	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- K.2	194	SF	6	\$671	
	Doors - Transom Window	2nd- 212 Counseling- K.2	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- K.2	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- K.2	194	SF	6	\$413	
	Lighting - Pendent/Surface	2nd- 212 Counseling- K.2	3	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- K.2	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	2nd- 212 Counseling- K.2	790	SF	6	\$2,180	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- K	123	SF	6	\$426	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- K	1	EA	6	\$301	
	Floor - Carpet	2nd- 212 Counseling- K	123	SF	6	\$262	
	Lighting - Pendent/Surface	2nd- 212 Counseling- K	4	EA	7	\$0	
	Power Distribution	2nd- 212 Counseling- K	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	2nd- 212 Counseling- K	439	SF	6	\$1,212	
	AC Unit	2nd- 213 (1) Discipline Office	1	EA	6	\$496	
	Ceiling - Lay-in	2nd- 213 (1) Discipline Office	203	SF	6	\$610	
	Doors - Wood Doors inclu hw	2nd- 213 (1) Discipline Office	1	EA	6	\$301	
	Floor - Carpet	2nd- 213 (1) Discipline Office	203	SF	6	\$433	
	Lighting - Pendent/Surface	2nd- 213 (1) Discipline Office	3	EA	7	\$0	
	Power Distribution	2nd- 213 (1) Discipline Office	4	EA	6	\$8,500	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Walls - Metal Panel	2nd- 213 (1) Discipline Office	319	SF	6	\$2,381	Fabric panel
	Walls - Plaster/Drywall	2nd- 213 (1) Discipline Office	319	SF	6	\$880	
	AC Unit	2nd- 213 (2) Discipline Office	1	EA	6	\$496	
	Ceiling - Lay-in	2nd- 213 (2) Discipline Office	187	SF	6	\$562	
	Doors - Wood Doors inclu hw	2nd- 213 (2) Discipline Office	1	EA	6	\$301	
	Floor - Carpet	2nd- 213 (2) Discipline Office	187	SF	6	\$398	
	Lighting - Pendent/Surface	2nd- 213 (2) Discipline Office	3	EA	7	\$0	
	Power Distribution	2nd- 213 (2) Discipline Office	4	EA	6	\$8,500	
	Walls - Metal Panel	2nd- 213 (2) Discipline Office	440	SF	6	\$3,284	Fabric Panel
	Walls - Plaster/Drywall	2nd- 213 (2) Discipline Office	165	SF	6	\$455	
	AC Unit	2nd- 213 Discipline Main Office	1	EA	6	\$496	
	Ceiling - Lay-in	2nd- 213 Discipline Main Office	715	SF	6	\$2,147	
	Doors - Transom Window	2nd- 213 Discipline Main Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd- 213 Discipline Main Office	1	EA	6	\$301	
	Floor - Carpet	2nd- 213 Discipline Main Office	715	SF	6	\$1,523	
	Lighting - Pendent/Surface	2nd- 213 Discipline Main Office	9	EA	7	\$0	
	Power Distribution	2nd- 213 Discipline Main Office	6	EA	6	\$12,749	
	Walls - Metal Panel	2nd- 213 Discipline Main Office	528	SF	6	\$3,941	Fabric panel
	Walls - Plaster/Drywall	2nd- 213 Discipline Main Office	649	SF	6	\$1,791	
	Ceiling - Plaster/Drywall	2nd- 215-A Project Room	293	SF	6	\$1,014	
	Doors - Transom Window	2nd- 215-A Project Room	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd- 215-A Project Room	1	EA	6	\$301	
	Floor - Tile	2nd- 215-A Project Room	18	SF	5	\$104	damaged
	Floor - Tile	2nd- 215-A Project Room	275	SF	6	\$602	
	Lighting - Pendent/Surface	2nd- 215-A Project Room	6	EA	6	\$743	
	Power Distribution	2nd- 215-A Project Room	4	EA	6	\$8,500	
	Storage/ Closet	2nd- 215-A Project Room	16	SF	6	\$116	
	Walls - Plaster/Drywall	2nd- 215-A Project Room	940	SF	6	\$2,594	
	Ceiling - Plaster/Drywall	2nd- 221 Physics Project room	447	SF	6	\$1,547	
	Doors - Transom Window	2nd- 221 Physics Project room	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd- 221 Physics Project room	1	EA	6	\$301	
	Floor - Wood	2nd- 221 Physics Project room	447	SF	6	\$3,151	
	Lighting - Pendent/Surface	2nd- 221 Physics Project room	6	EA	7	\$0	
	Power Distribution	2nd- 221 Physics Project room	4	EA	6	\$8,500	
	Storage/ Closet	2nd- 221 Physics Project room	76	SF	6	\$551	
	Walls - Plaster/Drywall	2nd- 221 Physics Project room	1,212	SF	6	\$3,345	
	Work Sink	2nd- 221 Physics Project room	1	EA	6	\$508	



**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Ceiling - Plaster/Drywall	2nd- 225A Physics Office	144	SF	6	\$498	
	Doors - Transom Window	2nd- 225A Physics Office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd- 225A Physics Office	1	EA	6	\$301	
	Floor - Wood	2nd- 225A Physics Office	144	SF	6	\$1,015	
	Lighting - Pendent/Surface	2nd- 225A Physics Office	2	EA	7	\$0	
	Power Distribution	2nd- 225A Physics Office	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	2nd- 225A Physics Office	1,080	SF	6	\$2,981	
	Ceiling - Plaster/Drywall	2nd- Basket Ball Coach Office	173	SF	6	\$599	
	Doors - Wood Doors inclu hw	2nd- Basket Ball Coach Office	1	EA	6	\$301	
	Floor - Wood	2nd- Basket Ball Coach Office	173	SF	6	\$1,220	
	Lighting - Pendent/Surface	2nd- Basket Ball Coach Office	1	EA	7	\$0	
	Power Distribution	2nd- Basket Ball Coach Office	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	2nd- Basket Ball Coach Office	3	SF	5	\$15	damaged by sink
	Walls - Plaster/Drywall	2nd- Basket Ball Coach Office	392	SF	6	\$1,082	
	Work SInk	2nd- Basket Ball Coach Office	1	EA	6	\$508	
	AC Unit	2nd floor - back kitchen upper level office 1	1	EA	6	\$496	
	Ceiling - Lay-in	2nd floor - back kitchen upper level office 1	145	SF	6	\$435	
	Doors - Wood Doors inclu hw	2nd floor - back kitchen upper level office 1	1	EA	6	\$301	
	Floor - Carpet	2nd floor - back kitchen upper level office 1	145	SF	6	\$309	
	Lighting - Lay-in	2nd floor - back kitchen upper level office 1	8	EA	7	\$0	
	Power Distribution	2nd floor - back kitchen upper level office 1	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	2nd floor - back kitchen upper level office 1	504	SF	6	\$1,391	
	AC Unit	2nd floor - back kitchen upper level office	2	EA	6	\$991	
	Ceiling - Lay-in	2nd floor - back kitchen upper level office	336	SF	6	\$1,009	
	Doors - Transom Window	2nd floor - back kitchen upper level office	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd floor - back kitchen upper level office	1	EA	6	\$301	
	Floor - Carpet	2nd floor - back kitchen upper level office	336	SF	6	\$716	
	Lighting - Lay-in	2nd floor - back kitchen upper level office	8	EA	7	\$0	
	Power Distribution	2nd floor - back kitchen upper level office	14	EA	6	\$29,748	
	Walls - Plaster/Drywall	2nd floor - back kitchen upper level office	1,196	SF	6	\$3,301	
	AC Unit	2nd floor - back upper kitchen area office 3	1	EA	4	\$6,086	old a/c - need extension cord from a/c to wall outlet

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Ceiling - Plaster/Drywall	2nd floor - back upper kitchen area office 3	342	SF	6	\$1,184	
	Doors - Wood Doors inclu hw	2nd floor - back upper kitchen area office 3	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd floor - back upper kitchen area office 3	132	SF	6	\$132	
	Floor - Wood	2nd floor - back upper kitchen area office 3	210	SF	6	\$1,480	
	Lighting - Pendent/Surface	2nd floor - back upper kitchen area office 3	1	EA	4	\$541	old thicker t-12
	Power Distribution	2nd floor - back upper kitchen area office 3	8	EA	6	\$16,999	
	Walls - Plaster/Drywall	2nd floor - back upper kitchen area office 3	100	SF	6	\$276	interior wood partition with door
	AC Unit	322A	1	EA	4	\$6,086	
	Ceiling - Plaster/Drywall	322A	20	SF	5	\$250	Damaged
	Ceiling - Plaster/Drywall	322A	332	SF	6	\$1,149	
	Doors - Wood Doors inclu hw	322A	1	EA	6	\$301	
	Floor - Tile/Sheet	322A	14	SF	5	\$81	Missing tiles
	Floor - Tile/Sheet	322A	338	SF	6	\$338	
	Lighting - Pendent/Surface	322A	8	EA	7	\$0	
	Power Distribution	322A	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	322A	1,176	SF	6	\$3,246	
	Walls - Plaster/Drywall	322A	49	SF	5	\$250	Crack, peeling paint, water damaged
	Ceiling - Plaster/Drywall	332A	408	SF	6	\$1,412	
	Doors - Transom Window	332A	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	332A	1	EA	6	\$301	
	Floor - Wood	332A	408	SF	6	\$2,876	
	Lighting - Pendent/Surface	332A	4	EA	7	\$0	
	Power Distribution	332A	4	EA	6	\$8,500	
	Storage/ Closet	332A	170	SF	6	\$1,233	
	Walls - Plaster/Drywall	332A	1,088	SF	6	\$3,003	
	Ceiling - Plaster/Drywall	332R	408	SF	6	\$1,412	
	Doors - Transom Window	332R	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	332R	1	EA	6	\$301	
	Floor - Wood	332R	408	SF	6	\$2,876	
	Lighting - Pendent/Surface	332R	4	EA	6	\$496	
	Power Distribution	332R	4	EA	6	\$8,500	
	Storage/ Closet	332R	170	SF	6	\$1,233	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Walls - Plaster/Drywall	332R	1,088	SF	6	\$3,003	
	Ceiling - Plaster/Drywall	341A	520	SF	6	\$1,800	
	Doors - Wood Doors inclu hw	341A	1	EA	6	\$301	
	Floor - Wood	341A	520	SF	6	\$3,666	
	Lighting - Pendent/Surface	341A	8	EA	7	\$0	
	Power Distribution	341A	12	EA	6	\$25,499	
	Storage/ Closet	341A	104	SF	6	\$754	
	Walls - Plaster/Drywall	341A	387	SF	5	\$1,710	Peeling paint
	Walls - Plaster/Drywall	341A	1,045	SF	6	\$2,884	
	AC Unit	341B	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	341B	410	SF	6	\$1,419	
	Doors - Transom Window	341B	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	341B	1	EA	6	\$301	
	Floor - Wood	341B	410	SF	6	\$2,890	
	Lighting - Pendent/Surface	341B	9	EA	7	\$0	
	Power Distribution	341B	4	EA	6	\$8,500	
	Storage/ Closet	341B	147	SF	6	\$1,066	
	Walls - Plaster/Drywall	341B	1,069	SF	6	\$2,950	
	Walls - Vinyl Coated Gypsum Panel	341B	525	SF	6	\$1,449	
	AC Unit	346A	1	EA	4	\$6,086	
	Ceiling - Plaster/Drywall	346A	408	SF	6	\$1,412	
	Doors - Transom Window	346A	6	SF	6	\$102	
	Doors - Wood Doors inclu hw	346A	1	EA	6	\$301	
	Floor - Wood	346A	408	SF	6	\$2,876	
	Lighting - Pendent/Surface	346A	4	EA	7	\$0	
	Power Distribution	346A	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	346A	1,088	SF	6	\$3,003	
	AC Unit	348	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	348	408	SF	6	\$1,412	
	Doors - Wood Doors inclu hw	348	1	EA	6	\$301	
	Floor - Wood	348	408	SF	6	\$2,876	
	Lighting - Pendent/Surface	348	6	EA	7	\$0	
	Power Distribution	348	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	348	1,088	SF	6	\$3,003	
	AC Unit	354A	1	EA	4	\$6,086	
	Ceiling - Plaster/Drywall	354A	300	SF	6	\$1,038	
	Doors - Transom Window	354A	6	SF	6	\$102	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Doors - Wood Doors inclu hw	354A	1	EA	6	\$301	
	Floor - Wood	354A	300	SF	6	\$2,115	
	Lighting - Pendent/Surface	354A	4	EA	7	\$0	
	Power Distribution	354A	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	354A	946	SF	6	\$2,611	
	Work Slnk	354A	1	EA	6	\$508	
	Ceiling - Plaster/Drywall	357 Coach's Office	75	SF	5	\$807	Water damage
	Ceiling - Plaster/Drywall	357 Coach's Office	90	SF	6	\$311	
	Doors - Wood Doors inclu hw	357 Coach's Office	1	EA	6	\$301	
	Floor - Tile	357 Coach's Office	165	SF	6	\$361	
	Lighting - Pendent/Surface	357 Coach's Office	4	EA	4	\$2,163	T12
	Power Distribution	357 Coach's Office	2	EA	6	\$4,250	
	Storage/ Closet	357 Coach's Office	86	SF	6	\$624	
	Walls - Plaster/Drywall	357 Coach's Office	657	SF	6	\$1,813	
	AC Unit	4th Floor	1	EA	6	\$496	
	AC Unit	4th Floor	1	EA	6	\$496	
	AC Unit	4th Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	4th Floor	336	SF	6	\$1,163	
	Ceiling - Splined	4th Floor	300	SF	6	\$245	
	Ceiling - Splined	4th Floor	96	SF	6	\$78	
	Ceiling - Splined	4th Floor	96	SF	6	\$78	
	Doors - Side-lite	4th Floor	30	SF	6	\$502	
	Doors - Side-lite	4th Floor	30	SF	6	\$502	
	Doors - Transom Window	4th Floor	28	SF	6	\$474	
	Doors - Transom Window	4th Floor	28	SF	6	\$474	
	Doors - Transom Window	4th Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	5	\$2,348	Missing hardware
	Floor - Tile/Sheet	4th Floor	336	SF	6	\$336	
	Floor - Wood	4th Floor	96	SF	6	\$677	
	Floor - Wood	4th Floor	300	SF	6	\$2,115	
	Floor - Wood	4th Floor	96	SF	6	\$677	
	Lighting - Chandelier, Incandescent	4th Floor	4	EA	7	\$0	
	Lighting - Chandelier, Incandescent	4th Floor	6	EA	6	\$2,865	
	Lighting - Pendent/Surface	4th Floor	2	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Lighting - Pendent/Surface	4th Floor	2	EA	7	\$0	
	Power Distribution	4th Floor	4	EA	6	\$8,500	
	Power Distribution	4th Floor	7	EA	6	\$14,874	
	Power Distribution	4th Floor	7	EA	6	\$14,874	
	Power Distribution	4th Floor	12	EA	6	\$25,499	
	Walls - Plaster/Drywall	4th Floor	1,064	SF	6	\$2,937	
	Walls - Plaster/Drywall	4th Floor	460	SF	6	\$1,270	
	Walls - Plaster/Drywall	4th Floor	980	SF	6	\$2,705	
	Walls - Plaster/Drywall	4th Floor	460	SF	6	\$1,270	
	Ceiling - Lay-in	Basement Engineer's Office	460	SF	6	\$1,381	
	Doors - Steel Doors incl hw	Basement Engineer's Office	1	EA	6	\$301	
	Floor - Tile	Basement Engineer's Office	460	SF	6	\$1,006	
	Lighting - Lay-in	Basement Engineer's Office	12	EA	7	\$0	
	Power Distribution	Basement Engineer's Office	10	EA	6	\$21,249	
	Walls - Plaster/Drywall	Basement Engineer's Office	1,360	SF	6	\$3,753	
	Ceiling - Plaster/Drywall	Basement- ROTC office	260	SF	6	\$900	Room was assessed through picture window.
	Doors - Steel Doors incl hw	Basement- ROTC office	1	EA	6	\$301	
	Floor - Tile	Basement- ROTC office	260	SF	6	\$569	
	Lighting - Pendent/Surface	Basement- ROTC office	3	EA	7	\$0	
	Power Distribution	Basement- ROTC office	10	EA	6	\$21,249	
	Walls - Plaster/Drywall	Basement- ROTC office	585	SF	6	\$1,615	
<b>Auditorium &amp; Theater</b>							
	Balcony Seating	1st Floor	988	EA	6	\$171,830	
	Ceiling - Exposed	1st Floor	2,412	SF	6	\$3,587	ceiling over back stage
	Ceiling - Plaster/Drywall	1st Floor	5,673	SF	6	\$47,295	
	Ceiling - Plaster/Drywall	1st Floor	50	SF	5	\$1,575	Water damage above balcony seating
	Ceiling - Splined	1st Floor	11,072	SF	6	\$9,025	
	Doors - Wood Doors inclu hw	1st Floor	9	EA	6	\$2,709	
	Floor - Concrete	1st Floor	12,184	SF	6	\$6,447	
	Floor - Terrazzo	1st Floor	1,134	SF	6	\$2,481	
	Floor - Tile	1st Floor	3,685	SF	6	\$8,062	
	Floor - Wood	1st Floor	2,632	SF	6	\$18,555	stage floor
	Lighting - Chandelier, Incandescent	1st Floor	4	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	34	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	5	EA	6	\$619	Stage lights, all missing covers
	Lighting - Wall Mounted	1st Floor	11	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	4	EA	7	\$0	back stage

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Auditorium &amp; Theater</b>							
	Main Floor Seating	1st Floor	2,038	EA	6	\$354,442	
	Sound System	1st Floor	1	EA	6	\$10,721	
	Stage	1st Floor	2,632	SF	6	\$15,206	
	Stage Curtain	1st Floor	2	EA	6	\$0	
	Stage Lift	1st Floor	1	EA	6	\$6,510	
	Stage Lighting System	1st Floor	1	EA	6	\$8,077	
	Stage-Stairs	1st Floor	12		6	\$0	
	Stairs - Asphalt	1st Floor	45	LF	6	\$418	Stairs to above stage lighting catwalk
	Walls - Masonry	1st Floor	8,550	SF	6	\$26,898	backstage
	Walls - Masonry	1st Floor	75	SF	5	\$4,289	efflorescence happening backstage
	Walls - Metal Panel	1st Floor	3,940	SF	6	\$29,411	Wood panel
	Walls - Plaster/Drywall	1st Floor	18,503	SF	6	\$88,109	
	Walls - Plaster/Drywall	1st Floor	100	SF	5	\$1,128	water damage NE section of auditorium in corridor/ stairwell that leads to back stage & up to stage lighting catwalk.
	AC Unit	2nd- 203 Media Center	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd- 203 Media Center	545	SF	6	\$4,544	
	Doors - Wood Doors inclu hw	2nd- 203 Media Center	1	EA	6	\$301	
	Floor - Wood	2nd- 203 Media Center	545	SF	6	\$3,842	Pergo laminate floor
	Lighting - Pendent/Surface	2nd- 203 Media Center	8	EA	7	\$0	
	Sound System	2nd- 203 Media Center	1	EA	6	\$10,721	
	Walls - Plaster/Drywall	2nd- 203 Media Center	1,239	SF	6	\$5,900	
<b>Clinic</b>							
	AC Unit	1st- 116 Nurse	1	EA	4	\$6,086	Not on a dedicated circuit
	Ceiling - Plaster/Drywall	1st- 116 Nurse	300	SF	6	\$1,038	
	Doors - Transom Window	1st- 116 Nurse	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st- 116 Nurse	1	EA	6	\$301	
	Floor - Terrazzo	1st- 116 Nurse	6	SF	6	\$13	At door
	Floor - Tile/Sheet	1st- 116 Nurse	294	SF	6	\$294	
	Lighting - Pendent/Surface	1st- 116 Nurse	3	EA	7	\$0	
	Walls - Plaster/Drywall	1st- 116 Nurse	928	SF	6	\$2,561	
	Walls - Structural Glazed Tile	1st- 116 Nurse	28	SF	6	\$88	
	AC Unit	2nd- Physical Therapy	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	2nd- Physical Therapy	791	SF	5	\$7,251	water damage
	Doors - Wood Doors inclu hw	2nd- Physical Therapy	1	EA	6	\$301	
	Floor - Wood	2nd- Physical Therapy	791	SF	6	\$5,576	
	Lighting - Pendent/Surface	2nd- Physical Therapy	10	EA	7	\$0	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Clinic</b>							
	Walls - Plaster/Drywall	2nd- Physical Therapy	20	SF	5	\$102	water damage
	Walls - Plaster/Drywall	2nd- Physical Therapy	829	SF	6	\$2,288	
	Walls - Structural Glazed Tile	2nd- Physical Therapy	828	SF	6	\$2,605	
<b>Green House</b>							
	Finishes	5th Floor	1,175	SF	6	\$6,435	
	Glazing	5th Floor	1,444	SF	6	\$35,950	
	Mechanical	5th Floor	32	SF	6	\$27	Approx size of 2 ventilation fans
	Plumbing	5th Floor	116	SF	6	\$66	Linear footage of pipes
<b>Gymnasia</b>							
	Bleacher Seating	2nd- GYM 1	662	EA	6	\$19,160	
	Ceiling - Plaster/Drywall	2nd- GYM 1	14,331	SF	6	\$79,104	
	Ceiling - Plaster/Drywall	2nd- GYM 1	500	SF	5	\$10,017	water damage
	Doors - Transom Window	2nd- GYM 1	36	SF	6	\$610	
	Doors - Wood Doors inclu hw	2nd- GYM 1	6	EA	6	\$1,806	
	Floor - Concrete	2nd- GYM 1	6,482	SF	6	\$3,430	bleacher & balcony floor
	Floor - Wood	2nd- GYM 1	8,349	SF	6	\$58,860	
	Lighting - Metal Halide/ High Pressure Sodium	2nd- GYM 1	40	EA	7	\$0	
	Lighting - Wall Mounted	2nd- GYM 1	4	EA	7	\$0	
	Scoreboards	2nd- GYM 1	1	EA	6	\$2,244	
	Sound System	2nd- GYM 1	1	EA	6	\$41,654	
	Storage/ Closet	2nd- GYM 1	183	SF	6	\$1,327	under the balcony seats
	Walls - Structural Glazed Tile	2nd- GYM 1	15,700	SF	6	\$49,392	
	Bleacher Seating	3rd Floor, Gym II	210	EA	6	\$6,078	Concrete
	Ceiling - Plaster/Drywall	3rd Floor, Gym II	5,099	SF	6	\$28,145	
	Ceiling - Plaster/Drywall	3rd Floor, Gym II	1,325	SF	5	\$22,566	Water damage
	Doors - Steel Doors incl hw	3rd Floor, Gym II	2	EA	6	\$602	
	Doors - Transom Window	3rd Floor, Gym II	30	SF	6	\$508	
	Doors - Wood Doors inclu hw	3rd Floor, Gym II	2	EA	6	\$602	
	Floor - Wood	3rd Floor, Gym II	6,424	SF	6	\$45,289	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor, Gym II	12	EA	6	\$1,605	
	Walls - Structural Glazed Tile	3rd Floor, Gym II	7,232	SF	6	\$22,752	
	Ceiling - Plaster/Drywall	Gymnasium #3	4,771	SF	6	\$26,335	
	Doors - Wood Doors inclu hw	Gymnasium #3	2	EA	6	\$602	
	Floor - Wood	Gymnasium #3	4,771	SF	6	\$33,635	
	Lighting - Chandelier, Incandescent	Gymnasium #3	16	EA	6	\$7,641	
	Scoreboards	Gymnasium #3	1	EA	6	\$2,244	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Gymnasia</b>							
	Sound System	Gymnasium #3	1	EA	6	\$41,654	
	Storage/ Closet	Gymnasium #3	369	SF	6	\$2,675	Storage 345D/ uniform locker
	Storage/ Closet	Gymnasium #3	576	SF	6	\$4,176	
	Walls - Metal Panel	Gymnasium #3	634	SF	6	\$4,733	
	Walls - Structural Glazed Tile	Gymnasium #3	5,456	SF	6	\$17,165	
<b>Kitchen</b>							
	Ceiling - Plaster/Drywall	1st floor - south of serving / prep room	1,328	SF	6	\$4,596	
	Doors - Transom Window	1st floor - south of serving / prep room	32	SF	6	\$542	
	Doors - Wood Doors inclu hw	1st floor - south of serving / prep room	2	EA	6	\$602	2 sets of double doors
	Floor - Tile	1st floor - south of serving / prep room	1,328	SF	6	\$2,906	
	Lighting - Pendent/Surface	1st floor - south of serving / prep room	12	EA	7	\$0	
	Walls - Structural Glazed Tile	1st floor - south of serving / prep room	2,145	SF	6	\$6,748	
	Ceiling - Plaster/Drywall	1st- Inside 113- Teachers kitchen	163	SF	6	\$564	
	Doors - Wood Doors inclu hw	1st- Inside 113- Teachers kitchen	1	EA	5	\$1,174	glass window is broken
	Floor - Tile	1st- Inside 113- Teachers kitchen	163	SF	5	\$732	buckling & damaged
	Lighting - Pendent/Surface	1st- Inside 113- Teachers kitchen	1	EA	4	\$541	T12
	Walls - Plaster/Drywall	1st- Inside 113- Teachers kitchen	689	SF	6	\$1,902	
<b>Library</b>							
	Casework	2nd Floor	198	LF	6	\$5,000	
	Ceiling - Plaster/Drywall	2nd Floor	1,233	SF	6	\$4,267	
	Ceiling - Plaster/Drywall	2nd Floor	80	SF	5	\$1,000	water damage NW side
	Ceiling - Splined	2nd Floor	3,895	SF	6	\$3,175	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Tile	2nd Floor	5,205	SF	6	\$11,388	
	Lighting - Chandelier, Incandescent	2nd Floor	16	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	28	EA	7	\$0	
	Walls - Metal Panel	2nd Floor	2,156	SF	6	\$16,094	Wood paneling
	Walls - Plaster/Drywall	2nd Floor	4,581	SF	6	\$12,643	
<b>Locker/Shower Room</b>							
	Accessories	1st Floor	500	SF	6	\$1,959	
	Benches, ped mounted	1st Floor	372	LF	6	\$40,503	
	Ceiling - Plaster/ Drywall	1st Floor	5,979	SF	6	\$20,691	
	Ceiling - Plaster/ Drywall	1st Floor	203	SF	5	\$2,650	ceiling peeling in ADA bathroom
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	1 door has a bent ventilation cover
	Floor Drain	1st Floor	4	EA	6	\$4,237	



**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Locker/Shower Room</b>							
	Floor Drain	1st Floor	6	EA	5	\$12,564	Drains were missing covers &/or had standing water
	Floor - Concrete Epoxy/ Painted	1st Floor	5,148	SF	6	\$2,724	
	Floor - Tile Ceramic/ Porcelain	1st Floor	1	SF	5	\$21	missing
	Floor - Tile Ceramic/ Porcelain	1st Floor	1,033	SF	6	\$2,186	
	Hand Dryer	1st Floor	5	EA	6	\$1,150	
	Lavatory	1st Floor	4	EA	6	\$1,278	
	Lighting - Pendent/Surface	1st Floor	65	EA	7	\$0	
	Partitions	1st Floor	3	EA	6	\$891	
	Showers	1st Floor	2	EA	5	\$5,429	missing shower heads & 1 in ADA bathroom is also missing control handle
	Showers	1st Floor	12	EA	6	\$3,737	
	Storage/ Closet	1st Floor	66	SF	5	\$1,065	NW corner of locker room (right of basket ball room) ceiling has water damage
	Storage/ Closet	1st Floor	171	SF	6	\$1,240	
	Student Lockers - One Tier	1st Floor	567	EA	6	\$52,638	
	Student Lockers - One Tier	1st Floor	4	EA	5	\$561	missing doors & 1 is also missing the side
	Student Lockers - Two Tier	1st Floor	126	EA	6	\$5,849	
	Urinals	1st Floor	8	EA	6	\$2,688	
	Walls - Plaster/Drywall	1st Floor	3,508	SF	6	\$9,682	
	Walls - Structural Glazed Tile	1st Floor	5,546	SF	6	\$17,448	
	Water Closet	1st Floor	4	EA	6	\$1,344	
	Benches, ped mounted	2nd- GYM 1 locker room	12	LF	6	\$1,307	
	Ceiling - Plaster/ Drywall	2nd- GYM 1 locker room	39	SF	5	\$438	Restroom/shower area, ceiling is peeling
	Ceiling - Plaster/ Drywall	2nd- GYM 1 locker room	148	SF	6	\$512	
	Doors - Wood Doors inclu hw	2nd- GYM 1 locker room	1	EA	6	\$301	
	Floor Drain	2nd- GYM 1 locker room	1	EA	6	\$1,059	in shower
	Floor - Tile Ceramic/ Porcelain	2nd- GYM 1 locker room	39	SF	6	\$83	Restroom/shower area
	Floor - Tile/Sheet	2nd- GYM 1 locker room	148	SF	5	\$665	buckling
	Lavatory	2nd- GYM 1 locker room	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd- GYM 1 locker room	3	EA	7	\$0	
	Partitions	2nd- GYM 1 locker room	1	EA	5	\$751	door missing
	Showers	2nd- GYM 1 locker room	1	EA	6	\$311	
	Student Lockers - One Tier	2nd- GYM 1 locker room	15	EA	6	\$1,393	
	Walls - Plaster/Drywall	2nd- GYM 1 locker room	30	SF	5	\$153	Restroom/shower area, walls are peeling
	Walls - Plaster/Drywall	2nd- GYM 1 locker room	388	SF	6	\$1,071	
	Walls - Tile Ceramic/ Porcelain	2nd- GYM 1 locker room	170	SF	6	\$384	Restroom/shower area
	Water Closet	2nd- GYM 1 locker room	1	EA	6	\$336	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Locker/Shower Room</b>							
	Accessories	357	857	SF	6	\$3,358	
	Benches, ped mounted	357	36	LF	6	\$3,920	
	Ceiling - Plaster/ Drywall	357	321	SF	5	\$3,603	peeling paint
	Ceiling - Plaster/ Drywall	357	536	SF	6	\$1,855	
	Doors - Wood Doors inclu hw	357	3	EA	6	\$903	
	Floor Drain	357	6	EA	6	\$6,355	
	Floor - Tile Ceramic/ Porcelain	357	195	SF	6	\$413	
	Floor - Tile/Sheet	357	863	SF	6	\$864	
	Hand Dryer	357	1	EA	6	\$230	
	Lavatory	357	1	EA	6	\$320	
	Lighting - Pendent/Surface	357	10	EA	7	\$0	
	Lighting - Pendent/Surface	357	2	EA	4	\$1,081	
	Partitions	357	2	EA	6	\$594	
	Showers	357	2	EA	6	\$623	
	Storage/ Closet	357	360	SF	6	\$2,610	
	Student Lockers - One Tier	357	100	EA	5	\$14,015	
	Student Lockers - Two Tier	357	12	EA	5	\$1,125	
	Walls - Plaster/Drywall	357	2,349	SF	6	\$6,483	
	Walls - Tile Ceramic/ Porcelain	357	405	SF	6	\$915	
	Walls - Vinyl Coated Gypsum Panel	357	50	SF	6	\$138	
	Water Closet	357	2	EA	6	\$672	
	Ceiling - Plaster/ Drywall	Basketball Locker Room	622	SF	5	\$5,942	water damage
	Doors - Steel Doors incl hw	Basketball Locker Room	2	EA	6	\$602	
	Floor - Carpet	Basketball Locker Room	622	SF	5	\$3,193	water damage
	Lighting - Pendent/Surface	Basketball Locker Room	5	EA	7	\$0	
	Student Lockers - One Tier	Basketball Locker Room	20	EA	6	\$1,857	
	Walls - Structural Glazed Tile	Basketball Locker Room	1,350	SF	6	\$4,247	
	Accessories	Gymnasium #3, 4th Floor	1,484	SF	6	\$5,815	
	Benches, ped mounted	Gymnasium #3, 4th Floor	27	LF	6	\$2,940	
	Ceiling - Plaster/ Drywall	Gymnasium #3, 4th Floor	1,484	SF	6	\$5,136	
	Ceiling - Plaster/ Drywall	Gymnasium #3, 4th Floor	69	SF	5	\$901	Water damaged
	Doors - Wood Doors inclu hw	Gymnasium #3, 4th Floor	2	EA	6	\$602	
	Floor Drain	Gymnasium #3, 4th Floor	3	EA	6	\$3,177	
	Floor - Tile Ceramic/ Porcelain	Gymnasium #3, 4th Floor	358	SF	6	\$758	
	Floor - Tile/Sheet	Gymnasium #3, 4th Floor	899	SF	6	\$900	
	Floor - Tile/Sheet	Gymnasium #3, 4th Floor	227	SF	5	\$1,117	Damaged and missing tiles
	Hand Dryer	Gymnasium #3, 4th Floor	10	EA	6	\$2,300	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Locker/Shower Room</b>							
	Lavatory	Gymnasium #3, 4th Floor	2	EA	6	\$639	
	Lighting - Chandelier, Incandescent	Gymnasium #3, 4th Floor	4	EA	6	\$1,910	
	Lighting - Pendant/Surface	Gymnasium #3, 4th Floor	18	EA	7	\$0	
	Partitions	Gymnasium #3, 4th Floor	20	EA	6	\$5,939	
	Showers	Gymnasium #3, 4th Floor	26	EA	6	\$8,097	
	Student Lockers - Three Tiers	Gymnasium #3, 4th Floor	590	EA	6	\$18,258	3+ tiers of small and large
	Walls - Plaster/Drywall	Gymnasium #3, 4th Floor	16	SF	5	\$121	Water damaged
	Walls - Structural Glazed Tile	Gymnasium #3, 4th Floor	2,274	SF	6	\$7,154	
	Walls - Vinyl Coated Gypsum Panel	Gymnasium #3, 4th Floor	1,924	SF	6	\$5,310	
	Water Closet	Gymnasium #3, 4th Floor	2	EA	6	\$672	
<b>Lunch &amp; Multipurpose Room</b>							
	Ceiling - Exposed	1st floor - school store 130A - west side of corridor to lunchroom	300	SF	6	\$446	steel decking
	Ceiling - Plaster/Drywall	1st floor - school store 130A - west side of corridor to lunchroom	6	SF	5	\$75	holes and stains on ceiling
	Ceiling - Plaster/Drywall	1st floor - school store 130A - west side of corridor to lunchroom	246	SF	6	\$851	
	Doors - Wood Doors inclu hw	1st floor - school store 130A - west side of corridor to lunchroom	1	EA	6	\$301	
	Floor - Carpet	1st floor - school store 130A - west side of corridor to lunchroom	552	SF	6	\$1,176	
	Lighting - Pendant/Surface	1st floor - school store 130A - west side of corridor to lunchroom	12	EA	7	\$0	
	Storage/ Closet	1st floor - school store 130A - west side of corridor to lunchroom	233	SF	6	\$1,689	
	Walls - Plaster/Drywall	1st floor - school store 130A - west side of corridor to lunchroom	898	SF	6	\$2,478	
	Walls - Structural Glazed Tile	1st floor - school store 130A - west side of corridor to lunchroom	894	SF	6	\$2,813	
	Ceiling - Lay-in	1st floor - serving room adjacent south to lunchroom	3,573	SF	6	\$10,730	
	Floor - Tile/Sheet	1st floor - serving room adjacent south to lunchroom	3,573	SF	6	\$3,577	
	Lighting - Lay-in	1st floor - serving room adjacent south to lunchroom	10	EA	7	\$0	
	Lighting - Pendant/Surface	1st floor - serving room adjacent south to lunchroom	8	EA	7	\$0	
	Serving Line	1st floor - serving room adjacent south to lunchroom	202	LF	6	\$12,022	
	Walls - Plaster/Drywall	1st floor - serving room adjacent south to lunchroom	3,014	SF	6	\$8,318	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Lunch &amp; Multipurpose Room</b>							
	Walls - Structural Glazed Tile	1st floor - serving room adjacent south to lunchroom	2,312	SF	6	\$7,274	
	Ceiling - Plaster/Drywall	1st floor - snack shop at north side of lunchroom	234	SF	6	\$810	
	Doors - Wood Doors inclu hw	1st floor - snack shop at north side of lunchroom	1	EA	6	\$301	
	Floor - Tile	1st floor - snack shop at north side of lunchroom	234	SF	6	\$512	
	Lighting - Pendent/Surface	1st floor - snack shop at north side of lunchroom	4	EA	7	\$0	
	Lighting - Wall Mounted	1st floor - snack shop at north side of lunchroom	2	EA	4	\$786	old lights
	Walls - Plaster/Drywall	1st floor - snack shop at north side of lunchroom	510	SF	6	\$1,408	
	Walls - Structural Glazed Tile	1st floor - snack shop at north side of lunchroom	416	SF	6	\$1,309	
	Ceiling - Lay-in	1st Floor	12,180	SF	6	\$36,577	
	Floor - Tile	1st Floor	12,180	SF	6	\$26,649	
	Lighting - Lay-in	1st Floor	52	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	5,601	SF	6	\$15,458	
	Walls - Structural Glazed Tile	1st Floor	3,050	SF	6	\$9,595	
	AC Unit	1st- Rm113- Civics Room	3	EA	6	\$1,487	
	Ceiling - Plaster/Drywall	1st- Rm113- Civics Room	428	SF	6	\$1,481	
	Ceiling - Splined	1st- Rm113- Civics Room	1,285	SF	6	\$1,047	
	Doors - Wood Doors inclu hw	1st- Rm113- Civics Room	2	EA	6	\$602	
	Floor - Wood	1st- Rm113- Civics Room	1,713	SF	6	\$12,076	
	Lighting - Chandelier, Incandescent	1st- Rm113- Civics Room	14	EA	6	\$6,686	track & chandeliers
	Storage/ Closet	1st- Rm113- Civics Room	188	SF	6	\$1,363	
	Walls - Plaster/Drywall	1st- Rm113- Civics Room	2,463	SF	6	\$6,798	
	AC Unit	2nd floor - back upper bakery lab	1	EA	4	\$6,086	need extension cord from a/c to wall outlet
	Ceiling - Plaster/Drywall	2nd floor - back upper bakery lab	392	SF	6	\$1,357	
	Chalk Board	2nd floor - back upper bakery lab	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	2nd floor - back upper bakery lab	2	EA	6	\$602	
	Floor - Tile	2nd floor - back upper bakery lab	392	SF	5	\$1,760	holes / tiles missing and cracked
	Lighting - Pendent/Surface	2nd floor - back upper bakery lab	4	EA	6	\$496	older light fixtures
	Walls - Plaster/Drywall	2nd floor - back upper bakery lab	956	SF	6	\$2,638	
	Ceiling - Plaster/Drywall	2nd floor - back upper kitchen locker room 1	163	SF	6	\$564	
	Doors - Wood Doors inclu hw	2nd floor - back upper kitchen locker room 1	1	EA	6	\$301	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Lunch &amp; Multipurpose Room</b>							
	Floor - Tile	2nd floor - back upper kitchen locker room 1	163	SF	6	\$357	
	Lighting - Pendent/Surface	2nd floor - back upper kitchen locker room 1	3	EA	4	\$1,622	old thicker t-12 bulbs
	Student Lockers - One Tier	2nd floor - back upper kitchen locker room 1	6	EA	6	\$557	
	Walls - Plaster/Drywall	2nd floor - back upper kitchen locker room 1	645	SF	6	\$1,780	unfinished areas
	Ceiling - Plaster/Drywall	2nd floor - back upper kitchen locker room	107	SF	6	\$370	
	Doors - Transom Window	2nd floor - back upper kitchen locker room	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd floor - back upper kitchen locker room	1	EA	6	\$301	
	Floor - Tile	2nd floor - back upper kitchen locker room	107	SF	6	\$234	
	Lighting - Pendent/Surface	2nd floor - back upper kitchen locker room	1	EA	5	\$183	incandescent light with no cover - used as outlet
	Student Lockers - One Tier	2nd floor - back upper kitchen locker room	8	EA	6	\$743	
	Walls - Plaster/Drywall	2nd floor - back upper kitchen locker room	5	SF	5	\$26	holes / cracks / peeling of walls
	Walls - Plaster/Drywall	2nd floor - back upper kitchen locker room	500	SF	6	\$1,380	
	Ceiling - Exposed	Basement- 036 ROTC	2,789	SF	6	\$4,148	Cement
	Doors - Steel Doors incl hw	Basement- 036 ROTC	2	EA	6	\$602	
	Floor - Tile	Basement- 036 ROTC	2,641	SF	6	\$5,778	
	Floor - Tile	Basement- 036 ROTC	148	SF	4	\$1,920	missing floor tiles
	Lighting - Pendent/Surface	Basement- 036 ROTC	11	EA	7	\$0	
	Market Board	Basement- 036 ROTC	6	LF	7	\$0	
	Storage/ Closet	Basement- 036 ROTC	264	SF	6	\$1,914	
	Walls - Concrete Block	Basement- 036 ROTC	2,370	SF	6	\$6,948	
	Walls - Plaster/Drywall	Basement- 036 ROTC	2,040	SF	6	\$5,630	
	Ceiling - Plaster/Drywall	Basement- 038 ROTC	1,114	SF	6	\$3,855	
	Ceiling - Splined	Basement- 038 ROTC	742	SF	6	\$605	Approx 12sf has water stains
	Doors - Steel Doors incl hw	Basement- 038 ROTC	1	EA	6	\$301	
	Floor - Tile	Basement- 038 ROTC	1,800	SF	6	\$3,938	
	Floor - Tile	Basement- 038 ROTC	56	SF	4	\$726	Missing
	Lighting - Pendent/Surface	Basement- 038 ROTC	28	EA	7	\$0	
	Lighting - Wall Mounted	Basement- 038 ROTC	1	EA	7	\$0	
	Walls - Masonry	Basement- 038 ROTC	1,633	SF	6	\$5,137	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Lunch &amp; Multipurpose Room</b>							
	Walls - Plaster/Drywall	Basement- 038 ROTC	211	SF	6	\$582	
<b>MDF_IDF</b>							
	AC Unit	1st Floor	1	EA	4	\$6,086	Not holding temperature
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Finishes	1st Floor	936	SF	5	\$15,111	Ceiling damage, no fire stop at threaded rods at ceiling, carpet water damaged
	Ventilation and Cooling	1st Floor	1	EA	6	\$1,855	
	Doors - Steel Doors incl hw	IDF Basement	1	EA	6	\$301	
	Finishes	IDF Basement	624	SF	5	\$10,074	No fire stop at conduit, peeling paint
<b>Mechanical/ Service Rooms</b>							
	Storage Room	1.5 floor - rear kitchen mid level storage	647	SF	5	\$10,436	old light with no cover hanging from cloth wiring, plaster ceiling cracked
	Janitor's Closet	1st Floor	23	SF	5	\$371	145-B - light fixture uncovered
	Loading Docks	1st Floor	825	SF	6	\$5,911	126 - Receiving - cracks and holes at conc. / tile wall
	Storage Room	1st Floor	57	SF	5	\$919	138-C - light uncovered, extension cords plugged into light fixture
	Storage Room	1st Floor	1,834	SF	6	\$13,139	136A - ceiling flaking
	Storage Room	1st Floor	418	SF	7	\$0	134A - new renovation work
	Storage Room	1st Floor	72	SF	6	\$516	Bakery storage
	Storage Room	1st Floor	50	SF	6	\$358	Bakery Storage 1
	Storage Room	1st Floor	18	SF	6	\$0	has a sink - located behind food service manager office
	Storage Room	1st Floor	168	SF	6	\$1,204	Delivery Storage - west of kitchen
	Storage Room	1st Floor	134	SF	6	\$960	Delivery Storage 1
	Storage Room	1st Floor	250	SF	6	\$1,791	150-A - cracks in wall
	Storage Room	1st Floor	124	SF	5	\$2,000	138-D- cracks in wall, abandoned elect. wires at uncovered light fixture
	Storage Room	1st Floor	45	SF	6	\$322	115-B
	Storage Room	1st Floor	29	SF	5	\$468	114C- walls deteriorating & light not working
	Storage Room	1st Floor	29	SF	6	\$208	120B
	Storage Room	1st Floor	253	SF	6	\$1,813	127-A
	Storage Room	1st Floor	24	SF	6	\$172	123-B
	Storage Room	1st Floor	166	SF	5	\$2,678	109-A - cracks/ceiling in wall & deterioration
	Storage Room	1st Floor	187	SF	6	\$1,340	111-A has 1 crack in wall that runs from ceiling to floor
	Vaults	1st Floor	617	SF	6	\$4,420	ROTC Gun vault & uniform storage
	Janitor's Closet	2nd Floor	15	SF	6	\$107	Located in Men's Staff Bathroom

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Mechanical/ Service Rooms</b>							
	Janitor's Closet	2nd Floor	24	SF	5	\$387	245B - exposed electrical wire, wall has holes / peeling
	Storage Room	2nd Floor	53	SF	5	\$855	242-C- Cracks / holes in walls, light fixture uncovered and hanging by cloth electrical wire
	Storage Room	2nd Floor	180	SF	6	\$1,290	211-A
	Storage Room	2nd Floor	259	SF	6	\$1,856	229-A
	Storage Room	2nd Floor	204	SF	5	\$3,291	213-A Balcony storage for Auditorium. cracks on walls/ceiling
	Storage Room	2nd Floor	44	SF	6	\$315	215-C
	Storage Room	2nd Floor	34	SF	6	\$244	215-C
	Storage Room	2nd Floor	128	SF	6	\$917	215-D
	Storage Room	2nd Floor	22	SF	6	\$158	223-C
	Storage Room	2nd Floor	306	SF	6	\$2,192	224-A
	Storage Room	2nd Floor	27	SF	6	\$193	220-B
	Storage Room	2nd Floor	353	SF	6	\$2,529	Located in between Rm 256 and Storage 242-C, some cracks in wall
	Storage Room	2nd Floor	222	SF	6	\$1,590	255-A - light fixture not covered
	Janitor's Closet	3rd Floor	25	SF	6	\$179	
	Janitor's Closet	3rd Floor	150	SF	6	\$1,075	
	Janitor's Closet	3rd Floor	156	SF	6	\$1,118	
	Storage Room	3rd Floor	380	SF	6	\$2,722	356A
	Storage Room	3rd Floor	44	SF	6	\$315	315B
	Storage Room	3rd Floor	15	SF	6	\$107	323B
	Storage Room	3rd Floor	54	SF	6	\$387	342C
	Storage Room	3rd Floor	350	SF	6	\$2,508	329A
	Storage Room	3rd Floor	25	SF	6	\$179	320A
	Storage Room	3rd Floor	152	SF	6	\$1,089	320B
	Storage Room	3rd Floor	370	SF	6	\$2,651	314B
	Storage Room	3rd Floor	94	SF	6	\$673	314C
	Storage Room	3rd Floor	152	SF	6	\$1,089	324A
	Air Intake Plenums	4th Floor	30	SF	6	\$186	
	Air Tunnel	4th Floor	150	SF	6	\$929	
	Air Tunnel	4th Floor	150	SF	6	\$929	
	Janitor's Closet	4th Floor	15	SF	6	\$107	
	Storage Room	4th Floor	300	SF	6	\$2,149	
	Storage Room	4th Floor	112	SF	6	\$802	
	Storage Room	4th Floor	90	SF	6	\$645	
	Storage Room	4th Floor	360	SF	6	\$2,579	
	Storage Room	5th Floor	272	SF	6	\$1,949	Storage for greenhouse

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Mechanical/ Service Rooms</b>							
	Air Intake Plenums	Basement	775	SF	6	\$4,799	
	Air Tunnel	Basement	20,875	SF	6	\$129,256	
	Auditorium Plenums	Basement	7,500	SF	6	\$46,439	
	Boiler Room	Basement	6,250	SF	5	\$100,815	Boiler room ash pit. Seepage and cracks
	Crawl Space - Unfinished	Basement	44,025	SF	6	\$272,598	
	Interior Stairs	Basement	280	LF	6	\$2,527	
	Janitor's Closet	Basement	2,250	SF	6	\$16,120	
	Mechanical/ Service Rooms	Basement	704	SF	5	\$11,356	Location: Elect. 3, Former Transformer Room. Seepage
	Mechanical/ Service Rooms	Basement	1,300	SF	5	\$20,970	Pool Filtration Room. Efflorescence
	Mechanical/ Service Rooms	Basement	1,400	SF	5	\$22,583	Fan Room 5, Fan Room 3 Sump Pit, Fan Room 7.
	Mechanical/ Service Rooms	Basement	24,910	SF	6	\$178,463	
	Storage Room	Basement	85,070	SF	6	\$609,467	
	Vaults	Basement	2,575	SF	6	\$18,448	
<b>Pool &amp; Natatorium</b>							
	Bleachers Seating/Plank Seating	1st Floor	220	EA	6	\$6,368	
	Ceiling - Plaster/ Drywall	1st Floor	1,159	SF	5	\$20,419	peeling over the bleachers
	Ceiling - Plaster/ Drywall	1st Floor	6,384	SF	6	\$35,238	
	Doors - Transom Window	1st Floor	30	SF	6	\$508	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	6	\$3,010	FRP
	Lighting - Pendent/Surface	1st Floor	49	EA	7	\$0	
	Pool Basin	1st Floor	3,096	SF	6	\$104,749	
	Pool Deck	1st Floor	4,447	SF	6	\$42,225	
	Pool Deck Drains	1st Floor	10	EA	6	\$4,221	
	Walls - Structural Glazed Tile	1st Floor	82,680	SF	6	\$260,111	
<b>Prep Room</b>							
	Ceiling - Plaster/Drywall	1st floor - adjacent to serving room	458	SF	6	\$1,585	
	Floor - Concrete	1st floor - adjacent to serving room	458	SF	6	\$242	
	Lighting - Pendent/Surface	1st floor - adjacent to serving room	3	EA	7	\$0	
	Walls - Structural Glazed Tile	1st floor - adjacent to serving room	1,336	SF	6	\$4,203	
	Work Sink	1st floor - adjacent to serving room	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	1st floor - bakery - adjacent east of kitchen	829	SF	6	\$2,869	
	Floor - Tile	1st floor - bakery - adjacent east of kitchen	829	SF	6	\$1,814	
	Lighting - Pendent/Surface	1st floor - bakery - adjacent east of kitchen	9	EA	7	\$0	



**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Prep Room</b>							
	Walls - Structural Glazed Tile	1st floor - bakery - adjacent east of kitchen	1,706	SF	6	\$5,367	
	Work Sink	1st floor - bakery - adjacent east of kitchen	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	2nd- Projection Rm 209C	4	SF	5	\$50	efflorescence
	Ceiling - Plaster/Drywall	2nd- Projection Rm 209C	164	SF	6	\$568	
	Doors - Wood Doors inclu hw	2nd- Projection Rm 209C	2	EA	6	\$602	
	Floor - Concrete	2nd- Projection Rm 209C	168	SF	6	\$89	
	Lighting - Pendent/Surface	2nd- Projection Rm 209C	2	EA	7	\$0	
	Walls - Plaster/Drywall	2nd- Projection Rm 209C	555	SF	6	\$1,532	
	Walls - Plaster/Drywall	2nd- Projection Rm 209C	28	SF	5	\$143	efflorescence
	Ceiling - Plaster/Drywall	Basement- Theater Dressing Room 1	85	SF	6	\$294	
	Doors - Wood Doors inclu hw	Basement- Theater Dressing Room 1	1	EA	6	\$301	
	Floor - Concrete	Basement- Theater Dressing Room 1	85	SF	6	\$45	
	Lighting - Pendent/Surface	Basement- Theater Dressing Room 1	1	EA	7	\$0	
	Lighting - Wall Mounted	Basement- Theater Dressing Room 1	1	EA	7	\$0	
	Walls - Metal Panel	Basement- Theater Dressing Room 1	289	SF	6	\$2,157	vinyl panel
	Walls - Plaster/Drywall	Basement- Theater Dressing Room 1	192	SF	6	\$530	2 sf of peeling paint behind sink
	Work Sink	Basement- Theater Dressing Room 1	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	Basement- Theater Dressing Room 2	80	SF	6	\$277	
	Doors - Wood Doors inclu hw	Basement- Theater Dressing Room 2	1	EA	6	\$301	
	Floor - Concrete	Basement- Theater Dressing Room 2	80	SF	6	\$42	
	Lighting - Pendent/Surface	Basement- Theater Dressing Room 2	1	EA	7	\$0	
	Lighting - Wall Mounted	Basement- Theater Dressing Room 2	1	EA	7	\$0	
	Walls - Metal Panel	Basement- Theater Dressing Room 2	281	SF	6	\$2,098	vinyl panel
	Walls - Plaster/Drywall	Basement- Theater Dressing Room 2	187	SF	6	\$516	
	Work Sink	Basement- Theater Dressing Room 2	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	Basement- Theater Dressing Room 3	68	SF	6	\$235	
	Doors - Wood Doors inclu hw	Basement- Theater Dressing Room 3	1	EA	6	\$301	
	Floor - Concrete	Basement- Theater Dressing Room 3	68	SF	6	\$36	
	Lighting - Pendent/Surface	Basement- Theater Dressing Room 3	1	EA	7	\$0	
	Walls - Metal Panel	Basement- Theater Dressing Room 3	307	SF	6	\$2,292	vinyl panel
	Walls - Plaster/Drywall	Basement- Theater Dressing Room 3	172	SF	6	\$475	
	Work Sink	Basement- Theater Dressing Room 3	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	Basement- Theater Dressing Room 4	81	SF	6	\$280	
	Doors - Wood Doors inclu hw	Basement- Theater Dressing Room 4	1	EA	6	\$301	
	Floor - Concrete	Basement- Theater Dressing Room 4	81	SF	6	\$43	
	Lighting - Pendent/Surface	Basement- Theater Dressing Room 4	1	EA	7	\$0	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Prep Room</b>							
	Lighting - Wall Mounted	Basement- Theater Dressing Room 4	1	EA	7	\$0	
	Walls - Metal Panel	Basement- Theater Dressing Room 4	281	SF	6	\$2,098	vinyl panel
	Walls - Plaster/Drywall	Basement- Theater Dressing Room 4	187	SF	6	\$516	
	Work Sink	Basement- Theater Dressing Room 4	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	Basement- Theater Dressing Room 6	80	SF	6	\$277	
	Doors - Wood Doors inclu hw	Basement- Theater Dressing Room 6	1	EA	6	\$301	
	Floor - Concrete	Basement- Theater Dressing Room 6	80	SF	6	\$42	
	Lighting - Pendent/Surface	Basement- Theater Dressing Room 6	1	EA	7	\$0	
	Lighting - Wall Mounted	Basement- Theater Dressing Room 6	1	EA	6	\$124	
	Walls - Metal Panel	Basement- Theater Dressing Room 6	280	SF	6	\$2,090	vinyl panel
	Walls - Plaster/Drywall	Basement- Theater Dressing Room 6	188	SF	6	\$519	
	Work Sink	Basement- Theater Dressing Room 6	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	Basement- Theater Dressing Room 7	80	SF	6	\$277	
	Doors - Wood Doors inclu hw	Basement- Theater Dressing Room 7	1	EA	6	\$301	missing inside door knob
	Floor - Concrete	Basement- Theater Dressing Room 7	80	SF	6	\$42	
	Lighting - Pendent/Surface	Basement- Theater Dressing Room 7	1	EA	7	\$0	
	Walls - Metal Panel	Basement- Theater Dressing Room 7	280	SF	6	\$2,090	vinyl panel
	Walls - Plaster/Drywall	Basement- Theater Dressing Room 7	188	SF	6	\$519	
	Work Sink	Basement- Theater Dressing Room 7	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	Basement- Theater Dressing Room 8	80	SF	6	\$277	Room locked- ranking is assumed by surrounding conditions
	Doors - Wood Doors inclu hw	Basement- Theater Dressing Room 8	1	EA	6	\$301	Room locked- ranking is assumed by surrounding conditions
	Floor - Concrete	Basement- Theater Dressing Room 8	80	SF	6	\$42	Room locked- ranking is assumed by surrounding conditions
	Lighting - Pendent/Surface	Basement- Theater Dressing Room 8	1	EA	7	\$0	Room locked- ranking is assumed by surrounding conditions
	Walls - Metal Panel	Basement- Theater Dressing Room 8	280	SF	6	\$2,090	Room locked- ranking is assumed by surrounding conditions
	Walls - Plaster/Drywall	Basement- Theater Dressing Room 8	188	SF	6	\$519	Room locked- ranking is assumed by surrounding conditions - vinyl panel
	Work Sink	Basement- Theater Dressing Room 8	1	EA	6	\$379	Room locked- ranking is assumed by surrounding conditions
	Ceiling - Plaster/Drywall	Basement- Theater Dressing Room 9	108	SF	6	\$374	
	Doors - Wood Doors inclu hw	Basement- Theater Dressing Room 9	1	EA	6	\$301	
	Floor - Concrete	Basement- Theater Dressing Room 9	108	SF	6	\$57	
	Lighting - Pendent/Surface	Basement- Theater Dressing Room 9	1	EA	7	\$0	
	Walls - Metal Panel	Basement- Theater Dressing Room 9	324	SF	6	\$2,419	vinyl panel
	Walls - Plaster/Drywall	Basement- Theater Dressing Room 9	216	SF	6	\$596	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Prep Room</b>							
	Work Sink	Basement- Theater Dressing Room 9	1	EA	6	\$379	
	Ceiling - Plaster/Drywall	Basement- Theater Make-up/Dressing Room 5	80	SF	6	\$277	
	Doors - Wood Doors inclu hw	Basement- Theater Make-up/Dressing Room 5	1	EA	6	\$301	
	Floor - Concrete	Basement- Theater Make-up/Dressing Room 5	80	SF	6	\$42	
	Lighting - Pendent/Surface	Basement- Theater Make-up/Dressing Room 5	1	EA	7	\$0	
	Walls - Metal Panel	Basement- Theater Make-up/Dressing Room 5	281	SF	6	\$2,098	vinyl panel
	Walls - Plaster/Drywall	Basement- Theater Make-up/Dressing Room 5	187	SF	6	\$516	
	Work Sink	Basement- Theater Make-up/Dressing Room 5	1	EA	6	\$379	
<b>Restroom</b>							
	Accessories	near 345 D unlabeled	74	SF	6	\$683	
	Ceiling - Plaster/Drywall	near 345 D unlabeled	74	SF	6	\$256	
	Doors - Wood Doors inclu hw	near 345 D unlabeled	1	EA	6	\$301	
	Floor Drain	near 345 D unlabeled	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	near 345 D unlabeled	74	SF	6	\$157	
	Lavatory	near 345 D unlabeled	1	EA	6	\$320	
	Lighting - Pendent/Surface	near 345 D unlabeled	1	EA	7	\$0	
	Walls - Plaster/Drywall	near 345 D unlabeled	333	SF	6	\$919	
	Water Closet	near 345 D unlabeled	1	EA	6	\$336	
	Accessories	1st- Boys NE (across from 125)	439	SF	6	\$4,049	
	Ceiling - Plaster/Drywall	1st- Boys NE (across from 125)	439	SF	6	\$1,519	
	Doors - Wood Doors inclu hw	1st- Boys NE (across from 125)	1	EA	6	\$301	
	Floor Drain	1st- Boys NE (across from 125)	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st- Boys NE (across from 125)	439	SF	6	\$929	
	Hand Dryer	1st- Boys NE (across from 125)	3	EA	6	\$690	
	Lavatory	1st- Boys NE (across from 125)	4	EA	6	\$1,278	
	Lighting - Lay-in	1st- Boys NE (across from 125)	6	EA	7	\$0	
	Partitions	1st- Boys NE (across from 125)	5	EA	6	\$1,485	
	Urinals	1st- Boys NE (across from 125)	7	EA	6	\$2,352	
	Walls - Plaster/Drywall	1st- Boys NE (across from 125)	357	SF	6	\$985	
	Walls - Structural Glazed Tile	1st- Boys NE (across from 125)	536	SF	6	\$1,686	
	Water Closet	1st- Boys NE (across from 125)	5	EA	6	\$1,680	
	Accessories	1st- Boy's- NW 114-C	390	SF	6	\$3,597	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Ceiling - Plaster/Drywall	1st- Boys- NW 114-C	390	SF	6	\$1,350	
	Doors - Wood Doors inclu hw	1st- Boys- NW 114-C	1	EA	6	\$301	
	Floor Drain	1st- Boys- NW 114-C	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	1st- Boys- NW 114-C	390	SF	6	\$825	
	Lavatory	1st- Boys- NW 114-C	5	EA	6	\$1,598	
	Lighting - Pendent/Surface	1st- Boys- NW 114-C	3	EA	7	\$0	
	Lighting - Pendent/Surface	1st- Boys- NW 114-C	5	EA	6	\$619	missing covers
	Partitions	1st- Boys- NW 114-C	6	EA	6	\$1,782	
	Urinals	1st- Boys- NW 114-C	9	EA	6	\$3,024	
	Walls - Plaster/Drywall	1st- Boys- NW 114-C	6	SF	5	\$31	deterioration below toilet
	Walls - Plaster/Drywall	1st- Boys- NW 114-C	471	SF	6	\$1,300	
	Walls - Structural Glazed Tile	1st- Boys- NW 114-C	477	SF	6	\$1,501	
	Water Closet	1st- Boys- NW 114-C	7	EA	6	\$2,352	
	Accessories	1st floor - across from 144	404	SF	6	\$3,726	
	Ceiling - Lay-in	1st floor - across from 144	404	SF	6	\$1,213	missing a couple tiles
	Floor Drain	1st floor - across from 144	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor - across from 144	404	SF	6	\$855	
	Hand Dryer	1st floor - across from 144	1	EA	6	\$230	
	Lavatory	1st floor - across from 144	2	EA	6	\$639	
	Lighting - Lay-in	1st floor - across from 144	4	EA	7	\$0	
	Partitions	1st floor - across from 144	4	EA	6	\$1,188	
	Urinals	1st floor - across from 144	6	EA	6	\$2,016	
	Walls - Plaster/Drywall	1st floor - across from 144	458	SF	6	\$1,264	
	Walls - Tile Ceramic/ Porcelain	1st floor - across from 144	466	SF	6	\$1,053	
	Water Closet	1st floor - across from 144	5	EA	6	\$1,680	
	Accessories	1st floor - across from classroom 147	505	SF	6	\$4,658	
	Ceiling - Lay-in	1st floor - across from classroom 147	505	SF	6	\$1,517	
	Ceiling - Lay-in	1st floor - across from classroom 147	5	SF	5	\$40	stained ceiling tiles
	Doors - Wood Doors inclu hw	1st floor - across from classroom 147	1	EA	6	\$301	
	Floor Drain	1st floor - across from classroom 147	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	1st floor - across from classroom 147	505	SF	6	\$1,069	
	Hand Dryer	1st floor - across from classroom 147	1	EA	6	\$230	
	Lavatory	1st floor - across from classroom 147	2	EA	6	\$639	
	Lighting - Lay-in	1st floor - across from classroom 147	4	EA	7	\$0	
	Partitions	1st floor - across from classroom 147	6	EA	6	\$1,782	
	Urinals	1st floor - across from classroom 147	12	EA	6	\$4,032	
	Walls - Plaster/Drywall	1st floor - across from classroom 147	489	SF	6	\$1,350	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Walls - Plaster/Drywall	1st floor - across from classroom 147	5	SF	5	\$26	holes and peeling
	Walls - Tile Ceramic/ Porcelain	1st floor - across from classroom 147	387	SF	6	\$874	
	Water Closet	1st floor - across from classroom 147	6	EA	6	\$2,016	
	Accessories	1st floor - across from classroom 149	67	SF	6	\$618	
	Ceiling - Plaster/Drywall	1st floor - across from classroom 149	67	SF	6	\$232	
	Doors - Wood Doors inclu hw	1st floor - across from classroom 149	1	EA	6	\$301	
	Floor Drain	1st floor - across from classroom 149	1	EA	6	\$1,059	
	Floor - Tile	1st floor - across from classroom 149	67	SF	6	\$147	
	Lavatory	1st floor - across from classroom 149	1	EA	6	\$320	
	Lighting - Lay-in	1st floor - across from classroom 149	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st floor - across from classroom 149	318	SF	6	\$878	
	Walls - Plaster/Drywall	1st floor - across from classroom 149	3	SF	5	\$15	holes and peeling next to lav
	Walls - Tile Ceramic/ Porcelain	1st floor - across from classroom 149	12	SF	6	\$27	
	Water Closet	1st floor - across from classroom 149	1	EA	6	\$336	
	Accessories	1st floor - in back kitchen office	30	SF	6	\$277	
	Ceiling - Plaster/Drywall	1st floor - in back kitchen office	30	SF	6	\$104	
	Doors - Wood Doors inclu hw	1st floor - in back kitchen office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st floor - in back kitchen office	30	SF	6	\$63	
	Lavatory	1st floor - in back kitchen office	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st floor - in back kitchen office	1	EA	6	\$124	no cover
	Walls - Plaster/Drywall	1st floor - in back kitchen office	232	SF	6	\$640	
	Walls - Plaster/Drywall	1st floor - in back kitchen office	6	SF	5	\$31	holes / cracks and peeling
	Water Closet	1st floor - in back kitchen office	1	EA	6	\$336	
	Accessories	1st floor - inside bedroom of classroom 157A	73	SF	6	\$673	
	Ceiling - Plaster/Drywall	1st floor - inside bedroom of classroom 157A	73	SF	6	\$253	
	Doors - Wood Doors inclu hw	1st floor - inside bedroom of classroom 157A	1	EA	6	\$301	
	Floor Drain	1st floor - inside bedroom of classroom 157A	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor - inside bedroom of classroom 157A	73	SF	6	\$154	
	Lavatory	1st floor - inside bedroom of classroom 157A	1	EA	6	\$320	
	Lighting - Lay-in	1st floor - inside bedroom of classroom 157A	1	EA	7	\$0	recessed can
	Lighting - Wall Mounted	1st floor - inside bedroom of classroom 157A	1	EA	7	\$0	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Showers	1st floor - inside bedroom of classroom 157A	1	EA	6	\$311	
	Walls - Structural Glazed Tile	1st floor - inside bedroom of classroom 157A	102	SF	6	\$321	
	Walls - Tile Ceramic/ Porcelain	1st floor - inside bedroom of classroom 157A	223	SF	6	\$504	
	Water Closet	1st floor - inside bedroom of classroom 157A	1	EA	6	\$336	
	Accessories	1st floor - inside classroom 157A	83	SF	6	\$766	
	Benches	1st floor - inside classroom 157A	5	LF	6	\$72	
	Ceiling - Plaster/Drywall	1st floor - inside classroom 157A	83	SF	6	\$287	
	Doors - Wood Doors inclu hw	1st floor - inside classroom 157A	1	EA	6	\$301	
	Floor Drain	1st floor - inside classroom 157A	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor - inside classroom 157A	83	SF	6	\$176	
	Lavatory	1st floor - inside classroom 157A	1	EA	6	\$320	
	Lighting - Lay-in	1st floor - inside classroom 157A	2	EA	7	\$0	recessed cans
	Lighting - Pendent/Surface	1st floor - inside classroom 157A	1	EA	7	\$0	
	Showers	1st floor - inside classroom 157A	1	EA	6	\$311	
	Walls - Tile Ceramic/ Porcelain	1st floor - inside classroom 157A	338	SF	6	\$764	
	Water Closet	1st floor - inside classroom 157A	1	EA	6	\$336	
	Accessories	1st floor - Men's 131A	348	SF	6	\$3,210	
	Benches	1st floor - Men's 131A	10	LF	6	\$145	
	Ceiling - Lay-in	1st floor - Men's 131A	348	SF	6	\$1,045	
	Doors - Wood Doors inclu hw	1st floor - Men's 131A	1	EA	6	\$301	
	Floor Drain	1st floor - Men's 131A	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	1st floor - Men's 131A	348	SF	6	\$737	
	Lavatory	1st floor - Men's 131A	2	EA	6	\$639	
	Lighting - Lay-in	1st floor - Men's 131A	5	EA	7	\$0	
	Partitions	1st floor - Men's 131A	2	EA	6	\$594	
	Student Lockers - Two Tiers	1st floor - Men's 131A	2	EA	6	\$93	
	Walls - Plaster/Drywall	1st floor - Men's 131A	519	SF	6	\$1,432	
	Walls - Tile Ceramic/ Porcelain	1st floor - Men's 131A	294	SF	6	\$664	
	Water Closet	1st floor - Men's 131A	2	EA	6	\$672	
	Accessories	1st floor - SW of kitchen	51	SF	6	\$470	
	Ceiling - Plaster/Drywall	1st floor - SW of kitchen	51	SF	6	\$176	
	Doors - Transom Window	1st floor - SW of kitchen	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st floor - SW of kitchen	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st floor - SW of kitchen	51	SF	6	\$108	
	Lavatory	1st floor - SW of kitchen	1	EA	6	\$320	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lighting - Pendent/Surface	1st floor - SW of kitchen	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st floor - SW of kitchen	128	SF	6	\$353	
	Walls - Tile Ceramic/ Porcelain	1st floor - SW of kitchen	180	SF	6	\$407	
	Water Closet	1st floor - SW of kitchen	1	EA	6	\$336	
	Accessories	1st floor - unisex bath in bakery	124	SF	6	\$1,144	
	Ceiling - Plaster/Drywall	1st floor - unisex bath in bakery	124	SF	6	\$429	
	Doors - Wood Doors inclu hw	1st floor - unisex bath in bakery	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st floor - unisex bath in bakery	124	SF	6	\$262	
	Lavatory	1st floor - unisex bath in bakery	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st floor - unisex bath in bakery	2	EA	7	\$0	
	Partitions	1st floor - unisex bath in bakery	1	EA	6	\$297	
	Student Lockers	1st floor - unisex bath in bakery	8	EA	5	\$0	legs are broke, leaning against wall
	Student Lockers - One Tier	1st floor - unisex bath in bakery	7	EA	6	\$650	
	Walls - Plaster/Drywall	1st floor - unisex bath in bakery	562	SF	6	\$1,551	
	Water Closet	1st floor - unisex bath in bakery	1	EA	6	\$336	
	Accessories	1st floor - Women's 131B	287	SF	6	\$2,647	
	Benches	1st floor - Women's 131B	10	LF	6	\$145	
	Ceiling - Lay-in	1st floor - Women's 131B	287	SF	6	\$862	
	Doors - Wood Doors inclu hw	1st floor - Women's 131B	1	EA	6	\$301	
	Floor Drain	1st floor - Women's 131B	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor - Women's 131B	287	SF	6	\$607	
	Lavatory	1st floor - Women's 131B	2	EA	6	\$639	
	Lighting - Lay-in	1st floor - Women's 131B	6	EA	7	\$0	
	Partitions	1st floor - Women's 131B	2	EA	6	\$594	
	Student Lockers - Two Tiers	1st floor - Women's 131B	2	EA	6	\$93	
	Walls - Plaster/Drywall	1st floor - Women's 131B	478	SF	6	\$1,319	
	Walls - Tile Ceramic/ Porcelain	1st floor - Women's 131B	262	SF	6	\$592	
	Water Closet	1st floor - Women's 131B	2	EA	6	\$672	
	Accessories	1st- Girls- NE 115A	604	SF	6	\$5,571	
	Ceiling - Lay-in	1st- Girls- NE 115A	598	SF	6	\$1,796	
	Ceiling - Lay-in	1st- Girls- NE 115A	6	SF	5	\$48	water stained
	Doors - Wood Doors inclu hw	1st- Girls- NE 115A	1	EA	6	\$301	
	Floor Drain	1st- Girls- NE 115A	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st- Girls- NE 115A	604	SF	6	\$1,278	
	Hand Dryer	1st- Girls- NE 115A	1	EA	6	\$230	
	Lavatory	1st- Girls- NE 115A	1	EA	5	\$1,590	replace faucet- running
	Lavatory	1st- Girls- NE 115A	3	EA	6	\$959	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lavatory	1st- Girls- NE 115A	1	EA	4	\$7,342	sink is broken
	Lighting - Lay-in	1st- Girls- NE 115A	4	EA	7	\$0	
	Partitions	1st- Girls- NE 115A	15	EA	6	\$4,454	
	Walls - Plaster/Drywall	1st- Girls- NE 115A	30	SF	5	\$153	peeling
	Walls - Plaster/Drywall	1st- Girls- NE 115A	504	SF	6	\$1,391	
	Walls - Structural Glazed Tile	1st- Girls- NE 115A	133	SF	6	\$418	
	Walls - Tile	1st- Girls- NE 115A	15	SF	5	\$343	Marble- cracked
	Walls - Tile	1st- Girls- NE 115A	785	SF	6	\$1,718	Marble
	Water Closet	1st- Girls- NE 115A	15	EA	6	\$5,040	
	Accessories	1st- Girls- NW 120A	375	SF	6	\$3,459	
	Ceiling - Lay-in	1st- Girls- NW 120A	375	SF	6	\$1,126	
	Doors - Wood Doors inclu hw	1st- Girls- NW 120A	1	EA	6	\$301	
	Floor Drain	1st- Girls- NW 120A	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st- Girls- NW 120A	375	SF	6	\$794	
	Hand Dryer	1st- Girls- NW 120A	2	EA	6	\$460	
	Lavatory	1st- Girls- NW 120A	3	EA	6	\$959	
	Lighting - Lay-in	1st- Girls- NW 120A	6	EA	6	\$714	
	Partitions	1st- Girls- NW 120A	5	EA	6	\$1,485	
	Walls - Plaster/Drywall	1st- Girls- NW 120A	340	SF	6	\$938	
	Walls - Structural Glazed Tile	1st- Girls- NW 120A	510	SF	6	\$1,604	
	Water Closet	1st- Girls- NW 120A	6	EA	6	\$2,016	
	Accessories	1st- Men's- N (across from Main office)	190	SF	6	\$1,752	
	Ceiling - Plaster/Drywall	1st- Men's- N (across from Main office)	190	SF	6	\$658	
	Doors - Side-lite	1st- Men's- N (across from Main office)	14	SF	6	\$234	
	Doors - Transom Window	1st- Men's- N (across from Main office)	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st- Men's- N (across from Main office)	2	EA	6	\$602	
	Floor Drain	1st- Men's- N (across from Main office)	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st- Men's- N (across from Main office)	190	SF	6	\$402	
	Lavatory	1st- Men's- N (across from Main office)	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st- Men's- N (across from Main office)	3	EA	4	\$1,622	T12
	Partitions	1st- Men's- N (across from Main office)	2	EA	6	\$594	
	Urinals	1st- Men's- N (across from Main office)	3	EA	6	\$1,008	
	Walls - Metal Panel	1st- Men's- N (across from Main office)	72	SF	6	\$537	vinyl panel
	Walls - Plaster/Drywall	1st- Men's- N (across from Main office)	578	SF	6	\$1,595	
	Walls - Plaster/Drywall	1st- Men's- N (across from Main office)	16	SF	5	\$82	Cracking /peeling paint
	Water Closet	1st- Men's- N (across from Main office)	2	EA	6	\$672	
	Accessories	1st- Nurse Office Restroom	18	SF	6	\$166	



## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Ceiling - Plaster/Drywall	1st- Nurse Office Restroom	18	SF	6	\$62	
	Doors - Wood Doors inclu hw	1st- Nurse Office Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st- Nurse Office Restroom	18	SF	6	\$38	
	Lighting - Wall Mounted	1st- Nurse Office Restroom	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st- Nurse Office Restroom	8	SF	5	\$41	cracking on wall behind toilet
	Walls - Plaster/Drywall	1st- Nurse Office Restroom	149	SF	6	\$411	some minor paint peeling near ceiling
	Water Closet	1st- Nurse Office Restroom	1	EA	6	\$336	
	Accessories	1st- Pool Office	63	SF	6	\$581	
	Ceiling - Plaster/Drywall	1st- Pool Office	63	SF	6	\$218	
	Doors - Wood Doors inclu hw	1st- Pool Office	1	EA	6	\$301	
	Floor - Tile/Sheet	1st- Pool Office	63	SF	5	\$283	all worn down
	Lavatory	1st- Pool Office	1	EA	6	\$320	
	Lighting - Pendant/Surface	1st- Pool Office	1	EA	5	\$183	fixture missing, hanging bulb only
	Partitions	1st- Pool Office	1	EA	5	\$751	missing door
	Student Lockers - One Tier	1st- Pool Office	4	EA	6	\$371	
	Walls - Plaster/Drywall	1st- Pool Office	315	SF	6	\$869	
	Walls - Tile Ceramic/ Porcelain	1st- Pool Office	100	SF	6	\$226	
	Accessories	1st- Principal's Restroom	42	SF	6	\$387	
	Ceiling - Plaster/Drywall	1st- Principal's Restroom	42	SF	6	\$145	
	Doors - Wood Doors inclu hw	1st- Principal's Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st- Principal's Restroom	42	SF	6	\$89	
	Lavatory	1st- Principal's Restroom	1	EA	6	\$320	
	Lighting - Wall Mounted	1st- Principal's Restroom	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st- Principal's Restroom	211	SF	6	\$582	
	Walls - Plaster/Drywall	1st- Principal's Restroom	5	SF	5	\$26	peeling
	Water Closet	1st- Principal's Restroom	1	EA	6	\$336	
	Accessories	1st- Women's- N (across from Main office)	334	SF	6	\$3,081	
	Ceiling - Plaster/Drywall	1st- Women's- N (across from Main office)	334	SF	6	\$1,156	
	Doors - Side-lite	1st- Women's- N (across from Main office)	14	SF	6	\$234	
	Doors - Transom Window	1st- Women's- N (across from Main office)	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st- Women's- N (across from Main office)	2	EA	6	\$602	
	Floor Drain	1st- Women's- N (across from Main office)	1	EA	6	\$1,059	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Floor - Tile Ceramic/ Porcelain	1st- Women's- N (across from Main office)	148	SF	6	\$313	
	Floor - Wood	1st- Women's- N (across from Main office)	186	SF	6	\$1,311	Pergo type of laminate wood
	Lavatory	1st- Women's- N (across from Main office)	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st- Women's- N (across from Main office)	2	EA	7	\$0	
	Lighting - Wall Mounted	1st- Women's- N (across from Main office)	4	EA	7	\$0	
	Partitions	1st- Women's- N (across from Main office)	2	EA	6	\$594	
	Walls - Plaster/Drywall	1st- Women's- N (across from Main office)	150	SF	5	\$663	cracked by radiator
	Walls - Plaster/Drywall	1st- Women's- N (across from Main office)	949	SF	6	\$2,619	
	Walls - Tile Ceramic/ Porcelain	1st- Women's- N (across from Main office)	125	SF	6	\$282	
	Water Closet	1st- Women's- N (across from Main office)	2	EA	6	\$672	
	Accessories	242-A Men's	520	SF	6	\$4,796	
	Ceiling - Lay-in	242-A Men's	2	SF	6	\$8	water damage from above
	Ceiling - Lay-in	242-A Men's	518	SF	6	\$1,556	
	Doors - Wood Doors inclu hw	242-A Men's	1	EA	6	\$301	
	Floor Drain	242-A Men's	1	EA	6	\$1,059	
	Floor - Tile	242-A Men's	520	SF	6	\$1,138	
	Hand Dryer	242-A Men's	1	EA	6	\$230	
	Lavatory	242-A Men's	2	EA	6	\$639	
	Lighting - Lay-in	242-A Men's	3	EA	7	\$0	
	Partitions	242-A Men's	5	EA	6	\$1,485	
	Urinals	242-A Men's	6	EA	6	\$2,016	
	Walls - Plaster/Drywall	242-A Men's	5	SF	5	\$26	cracks / holes in wall
	Walls - Plaster/Drywall	242-A Men's	269	SF	6	\$742	
	Walls - Tile	242-A Men's	662	SF	6	\$1,448	
	Water Closet	242-A Men's	6	EA	6	\$2,016	
	Accessories	242-B Staff Unisex	83	SF	6	\$766	
	Ceiling - Plaster/Drywall	242-B Staff Unisex	83	SF	6	\$287	
	Doors - Wood Doors inclu hw	242-B Staff Unisex	1	EA	6	\$301	
	Floor Drain	242-B Staff Unisex	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	242-B Staff Unisex	83	SF	6	\$176	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lavatory	242-B Staff Unisex	1	EA	6	\$320	
	Lighting - Lay-in	242-B Staff Unisex	1	EA	7	\$0	
	Walls - Plaster/Drywall	242-B Staff Unisex	4	SF	5	\$20	crack in wall
	Walls - Plaster/Drywall	242-B Staff Unisex	353	SF	6	\$974	
	Walls - Tile Ceramic/ Porcelain	242-B Staff Unisex	12	SF	6	\$27	base trim
	Water Closet	242-B Staff Unisex	1	EA	6	\$336	
	Accessories	2nd- 212 Counseling- access through Rm A or Conference	54	SF	6	\$498	
	Ceiling - Plaster/Drywall	2nd- 212 Counseling- access through Rm A or Conference	54	SF	6	\$187	
	Doors - Wood Doors inclu hw	2nd- 212 Counseling- access through Rm A or Conference	2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain	2nd- 212 Counseling- access through Rm A or Conference	54	SF	6	\$114	
	Lavatory	2nd- 212 Counseling- access through Rm A or Conference	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd- 212 Counseling- access through Rm A or Conference	1	EA	7	\$0	
	Walls - Metal Panel	2nd- 212 Counseling- access through Rm A or Conference	419	SF	6	\$3,128	Fabric dividing walls
	Accessories	2nd- Boy's- NE (left of 223)	439	SF	6	\$4,049	
	Ceiling - Lay-in	2nd- Boy's- NE (left of 223)	439	SF	6	\$1,318	
	Doors - Wood Doors inclu hw	2nd- Boy's- NE (left of 223)	1	EA	6	\$301	
	Floor Drain	2nd- Boy's- NE (left of 223)	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	2nd- Boy's- NE (left of 223)	439	SF	6	\$929	
	Hand Dryer	2nd- Boy's- NE (left of 223)	3	EA	6	\$690	
	Lavatory	2nd- Boy's- NE (left of 223)	4	EA	6	\$1,278	
	Lighting - Lay-in	2nd- Boy's- NE (left of 223)	6	EA	7	\$0	
	Partitions	2nd- Boy's- NE (left of 223)	5	EA	6	\$1,485	
	Urinals	2nd- Boy's- NE (left of 223)	7	EA	6	\$2,352	
	Walls - Plaster/Drywall	2nd- Boy's- NE (left of 223)	357	SF	6	\$985	
	Walls - Structural Glazed Tile	2nd- Boy's- NE (left of 223)	1,070	SF	6	\$3,366	
	Water Closet	2nd- Boy's- NE (left of 223)	5	EA	6	\$1,680	
	Accessories	2nd- Boys- NW 214A	479	SF	6	\$4,418	
	Ceiling - Lay-in	2nd- Boys- NW 214A	479	SF	6	\$1,438	
	Doors - Wood Doors inclu hw	2nd- Boys- NW 214A	1	EA	6	\$301	
	Floor Drain	2nd- Boys- NW 214A	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	2nd- Boys- NW 214A	2	SF	5	\$42	damaged
	Floor - Tile Ceramic/ Porcelain	2nd- Boys- NW 214A	477	SF	6	\$1,010	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Hand Dryer	2nd- Boys- NW 214A	1	EA	6	\$230	
	Lavatory	2nd- Boys- NW 214A	2	EA	5	\$3,179	1 faucet running & other faucet is missing
	Lighting - Lay-in	2nd- Boys- NW 214A	4	EA	7	\$0	
	Partitions	2nd- Boys- NW 214A	1	EA	6	\$297	
	Partitions	2nd- Boys- NW 214A	6	EA	5	\$4,505	missing the doors
	Urinals	2nd- Boys- NW 214A	14	EA	6	\$4,704	
	Walls - Plaster/Drywall	2nd- Boys- NW 214A	440	SF	6	\$1,214	
	Walls - Structural Glazed Tile	2nd- Boys- NW 214A	658	SF	6	\$2,070	
	Water Closet	2nd- Boys- NW 214A	1	EA	5	\$1,344	not flushing
	Water Closet	2nd- Boys- NW 214A	7	EA	6	\$2,352	
	Accessories	2nd floor - 245A - across from office 247	476	SF	6	\$4,390	
	Ceiling - Lay-in	2nd floor - 245A - across from office 247	12	SF	5	\$96	stained tiles
	Ceiling - Lay-in	2nd floor - 245A - across from office 247	464	SF	6	\$1,393	
	Doors - Wood Doors inclu hw	2nd floor - 245A - across from office 247	1	EA	6	\$301	
	Floor Drain	2nd floor - 245A - across from office 247	2	EA	5	\$4,188	1 missing grate cover
	Floor - Tile Ceramic/ Porcelain	2nd floor - 245A - across from office 247	476	SF	6	\$1,007	
	Hand Dryer	2nd floor - 245A - across from office 247	1	EA	6	\$230	
	Lavatory	2nd floor - 245A - across from office 247	2	EA	6	\$639	
	Lighting - Lay-in	2nd floor - 245A - across from office 247	4	EA	7	\$0	
	Partitions	2nd floor - 245A - across from office 247	5	EA	6	\$1,485	
	Urinals	2nd floor - 245A - across from office 247	12	EA	6	\$4,032	
	Walls - Plaster/Drywall	2nd floor - 245A - across from office 247	838	SF	6	\$2,313	
	Walls - Plaster/Drywall	2nd floor - 245A - across from office 247	13	SF	5	\$66	wall beyond all toilets is cracking / peeling
	Walls - Tile Ceramic/ Porcelain	2nd floor - 245A - across from office 247	577	SF	6	\$1,304	
	Water Closet	2nd floor - 245A - across from office 247	6	EA	6	\$2,016	
	Accessories	2nd floor - across from 249	67	SF	6	\$618	
	Ceiling - Plaster/Drywall	2nd floor - across from 249	67	SF	6	\$232	
	Doors - Wood Doors inclu hw	2nd floor - across from 249	1	EA	5	\$1,174	heavy - shuts hard
	Floor Drain	2nd floor - across from 249	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd floor - across from 249	67	SF	6	\$142	
	Lavatory	2nd floor - across from 249	1	EA	6	\$320	
	Lighting - Lay-in	2nd floor - across from 249	1	EA	7	\$0	
	Walls - Plaster/Drywall	2nd floor - across from 249	316	SF	6	\$872	
	Walls - Plaster/Drywall	2nd floor - across from 249	3	SF	5	\$15	holes in wall by lav
	Walls - Tile Ceramic/ Porcelain	2nd floor - across from 249	12	SF	6	\$27	base tile
	Water Closet	2nd floor - across from 249	1	EA	6	\$336	
	Accessories	2nd floor - bath inside back kitchen upper level office	55	SF	6	\$507	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Ceiling - Lay-in	2nd floor - bath inside back kitchen upper level office	55	SF	6	\$165	
	Doors - Wood Doors inclu hw	2nd floor - bath inside back kitchen upper level office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd floor - bath inside back kitchen upper level office	55	SF	6	\$116	
	Lavatory	2nd floor - bath inside back kitchen upper level office	1	EA	6	\$320	
	Lighting - Lay-in	2nd floor - bath inside back kitchen upper level office	1	EA	7	\$0	
	Walls - Plaster/Drywall	2nd floor - bath inside back kitchen upper level office	227	SF	6	\$626	
	Walls - Tile Ceramic/ Porcelain	2nd floor - bath inside back kitchen upper level office	93	SF	6	\$210	
	Water Closet	2nd floor - bath inside back kitchen upper level office	1	EA	6	\$336	
	Accessories	2nd floor - inside back upper kitchen locker room	90	SF	6	\$830	
	Ceiling - Plaster/Drywall	2nd floor - inside back upper kitchen locker room	90	SF	6	\$311	
	Doors - Wood Doors inclu hw	2nd floor - inside back upper kitchen locker room	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd floor - inside back upper kitchen locker room	90	SF	6	\$190	
	Lavatory	2nd floor - inside back upper kitchen locker room	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd floor - inside back upper kitchen locker room	1	EA	5	\$183	incandescent light with no cover hanging from cloth electrical wiring
	Partitions	2nd floor - inside back upper kitchen locker room	1	EA	6	\$297	
	Student Lockers - One Tier	2nd floor - inside back upper kitchen locker room	2	EA	6	\$186	
	Walls - Plaster/Drywall	2nd floor - inside back upper kitchen locker room	336	SF	6	\$927	
	Walls - Tile Ceramic/ Porcelain	2nd floor - inside back upper kitchen locker room	121	SF	6	\$273	
	Water Closet	2nd floor - inside back upper kitchen locker room	2	EA	6	\$672	
	Accessories	2nd- Girl's- NE 215B	789	SF	6	\$7,277	
	Ceiling - Lay-in	2nd- Girl's- NE 215B	16	SF	5	\$128	water damage
	Ceiling - Lay-in	2nd- Girl's- NE 215B	773	SF	6	\$2,321	
	Doors - Wood Doors inclu hw	2nd- Girl's- NE 215B	1	EA	6	\$301	
	Floor Drain	2nd- Girl's- NE 215B	1	EA	5	\$2,094	not working, has standing water in it

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Floor - Tile Ceramic/ Porcelain	2nd- Girl's- NE 215B	784	SF	6	\$1,659	
	Floor - Tile Ceramic/ Porcelain	2nd- Girl's- NE 215B	5	SF	4	\$192	missing
	Lavatory	2nd- Girl's- NE 215B	2	EA	5	\$3,179	1 faucet doesn't work (missing push knobs, ,other is running
	Lighting - Lay-in	2nd- Girl's- NE 215B	4	EA	7	\$0	
	Partitions	2nd- Girl's- NE 215B	15	EA	6	\$4,454	
	Walls - Plaster/Drywall	2nd- Girl's- NE 215B	10	SF	5	\$51	cracked
	Walls - Plaster/Drywall	2nd- Girl's- NE 215B	555	SF	6	\$1,532	
	Walls - Tile	2nd- Girl's- NE 215B	565	SF	6	\$1,236	Marble
	Water Closet	2nd- Girl's- NE 215B	15	EA	6	\$5,040	
	Accessories	2nd- Girl's- NW 220A	375	SF	6	\$3,459	
	Ceiling - Lay-in	2nd- Girl's- NW 220A	375	SF	6	\$1,126	
	Doors - Wood Doors inclu hw	2nd- Girl's- NW 220A	1	EA	6	\$301	
	Floor Drain	2nd- Girl's- NW 220A	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd- Girl's- NW 220A	375	SF	6	\$794	
	Hand Dryer	2nd- Girl's- NW 220A	2	EA	6	\$460	
	Lavatory	2nd- Girl's- NW 220A	3	EA	6	\$959	
	Lighting - Lay-in	2nd- Girl's- NW 220A	6	EA	7	\$0	
	Partitions	2nd- Girl's- NW 220A	5	EA	6	\$1,485	
	Walls - Plaster/Drywall	2nd- Girl's- NW 220A	340	SF	6	\$938	
	Walls - Structural Glazed Tile	2nd- Girl's- NW 220A	510	SF	6	\$1,604	
	Water Closet	2nd- Girl's- NW 220A	6	EA	6	\$2,016	
	Accessories	2nd- Inside Basket Ball Coach Office	30	SF	6	\$277	
	Ceiling - Plaster/Drywall	2nd- Inside Basket Ball Coach Office	30	SF	6	\$104	
	Doors - Wood Doors inclu hw	2nd- Inside Basket Ball Coach Office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd- Inside Basket Ball Coach Office	30	SF	6	\$63	
	Lighting - Pendent/Surface	2nd- Inside Basket Ball Coach Office	1	EA	7	\$0	
	Partitions	2nd- Inside Basket Ball Coach Office	1	EA	6	\$297	
	Walls - Plaster/Drywall	2nd- Inside Basket Ball Coach Office	26	SF	6	\$72	
	Walls - Tile Ceramic/ Porcelain	2nd- Inside Basket Ball Coach Office	150	SF	6	\$339	Marble tile
	Water Closet	2nd- Inside Basket Ball Coach Office	1	EA	6	\$336	
	Accessories	2nd- Men's in 213	33	SF	6	\$304	
	Ceiling - Lay-in	2nd- Men's in 213	33	SF	6	\$99	
	Doors - Wood Doors inclu hw	2nd- Men's in 213	1	EA	6	\$301	
	Floor - Tile	2nd- Men's in 213	33	SF	6	\$72	
	Lavatory	2nd- Men's in 213	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd- Men's in 213	1	EA	7	\$0	
	Walls - Metal Panel	2nd- Men's in 213	253	SF	6	\$1,889	fabric panel

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Water Closet	2nd- Men's in 213	1	EA	6	\$336	
	Accessories	2nd- Men's- Rm 201 (across from Library)	197	SF	6	\$1,817	
	Ceiling - Plaster/Drywall	2nd- Men's- Rm 201 (across from Library)	50	SF	6	\$204	water damaged
	Ceiling - Plaster/Drywall	2nd- Men's- Rm 201 (across from Library)	218	SF	6	\$754	
	Doors - Wood Doors inclu hw	2nd- Men's- Rm 201 (across from Library)	2	EA	5	\$2,348	delaminating
	Floor Drain	2nd- Men's- Rm 201 (across from Library)	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd- Men's- Rm 201 (across from Library)	8	SF	4	\$308	missing
	Floor - Tile Ceramic/ Porcelain	2nd- Men's- Rm 201 (across from Library)	260	SF	6	\$550	
	Lavatory	2nd- Men's- Rm 201 (across from Library)	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd- Men's- Rm 201 (across from Library)	4	EA	7	\$0	
	Lighting - Wall Mounted	2nd- Men's- Rm 201 (across from Library)	1	EA	7	\$0	
	Partitions	2nd- Men's- Rm 201 (across from Library)	2	EA	6	\$594	
	Urinals	2nd- Men's- Rm 201 (across from Library)	3	EA	6	\$1,008	
	Walls - Plaster/Drywall	2nd- Men's- Rm 201 (across from Library)	150	SF	5	\$663	water damaged
	Walls - Plaster/Drywall	2nd- Men's- Rm 201 (across from Library)	1,127	SF	6	\$3,110	
	Accessories	2nd- Women's in 213	33	SF	6	\$304	
	Ceiling - Lay-in	2nd- Women's in 213	33	SF	6	\$99	
	Doors - Wood Doors inclu hw	2nd- Women's in 213	1	EA	6	\$301	
	Floor - Tile	2nd- Women's in 213	33	SF	6	\$72	
	Lavatory	2nd- Women's in 213	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd- Women's in 213	1	EA	7	\$0	
	Walls - Metal Panel	2nd- Women's in 213	253	SF	6	\$1,889	Fabric panel
	Water Closet	2nd- Women's in 213	1	EA	5	\$1,344	not working
	Accessories	2nd- Women's- N (across form Library)	334	SF	6	\$3,081	
	Ceiling - Plaster/Drywall	2nd- Women's- N (across form Library)	334	SF	6	\$1,156	
	Doors - Side-lite	2nd- Women's- N (across form Library)	14	SF	6	\$234	
	Doors - Transom Window	2nd- Women's- N (across form Library)	18	SF	6	\$305	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Doors - Wood Doors inclu hw	2nd- Women's- N (across form Library)	2	EA	6	\$602	
	Floor Drain	2nd- Women's- N (across form Library)	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd- Women's- N (across form Library)	148	SF	6	\$313	
	Floor - Tile/Sheet	2nd- Women's- N (across form Library)	186	SF	6	\$186	
	Lavatory	2nd- Women's- N (across form Library)	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd- Women's- N (across form Library)	2	EA	7	\$0	
	Lighting - Wall Mounted	2nd- Women's- N (across form Library)	1	EA	7	\$0	
	Partitions	2nd- Women's- N (across form Library)	1	EA	6	\$297	
	Walls - Plaster/Drywall	2nd- Women's- N (across form Library)	1,224	SF	6	\$3,378	
	Water Closet	2nd- Women's- N (across form Library)	1	EA	6	\$336	
	Accessories	301A	265	SF	6	\$2,444	
	Ceiling - Plaster/Drywall	301A	265	SF	6	\$917	
	Doors - Transom Window	301A	25	SF	6	\$423	
	Doors - Wood Doors inclu hw	301A	2	EA	6	\$602	
	Floor Drain	301A	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	301A	265	SF	6	\$561	
	Lavatory	301A	2	EA	6	\$639	
	Lighting - Pendent/Surface	301A	4	EA	7	\$0	
	Partitions	301A	1	EA	6	\$297	
	Urinals	301A	3	EA	6	\$1,008	
	Walls - Plaster/Drywall	301A	125	SF	6	\$345	
	Walls - Structural Glazed Tile	301A	1,295	SF	6	\$4,074	
	Water Closet	301A	2	EA	6	\$672	
	Accessories	302A	315	SF	6	\$2,905	
	Accessories	302A	315	SF	6	\$2,905	
	Ceiling - Plaster/Drywall	302A	315	SF	6	\$1,090	
	Doors - Wood Doors inclu hw	302A	2	EA	6	\$602	
	Floor Drain	302A	1	EA	6	\$1,059	
	Floor - Tile/Sheet	302A	310	SF	6	\$310	
	Floor - Tile/Sheet	302A	5	SF	5	\$29	Damaged
	Lavatory	302A	2	EA	6	\$639	
	Lighting - Metal Halide/Sodium Vapor	302A	3	EA	7	\$0	
	Partitions	302A	1	EA	6	\$297	
	Walls - Plaster/Drywall	302A	305	SF	6	\$842	
	Walls - Tile Ceramic/ Porcelain	302A	1,041	SF	6	\$2,352	
	Accessories	315B	638	SF	6	\$5,885	
	Ceiling - Plaster/Drywall	315B	638	SF	6	\$2,208	



**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Doors - Wood Doors inclu hw	315B	1	EA	4	\$3,413	Missing door
	Floor Drain	315B	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	315B	638	SF	6	\$1,350	
	Lavatory	315B	3	EA	6	\$959	
	Lighting - Pendent/Surface	315B	7	EA	7	\$0	
	Partitions	315B	16	EA	6	\$4,751	
	Walls - Plaster/Drywall	315B	803	SF	6	\$2,216	
	Walls - Plaster/Drywall	315B	8	SF	5	\$41	Crack at window
	Walls - Tile Ceramic/ Porcelain	315B	4	SF	5	\$84	Missing tile
	Walls - Tile Ceramic/ Porcelain	315B	763	SF	6	\$1,724	
	Water Closet	315B	15	EA	6	\$5,040	
	Accessories	320A	440	SF	6	\$4,058	
	Ceiling - Lay-in	320A	440	SF	6	\$1,321	
	Doors - Wood Doors inclu hw	320A	1	EA	6	\$301	
	Floor Drain	320A	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	320A	440	SF	6	\$931	
	Hand Dryer	320A	2	EA	6	\$460	
	Lavatory	320A	34	EA	6	\$10,867	
	Lighting - Lay-in	320A	6	EA	7	\$0	
	Partitions	320A	6	EA	6	\$1,782	
	Walls - Plaster/Drywall	320A	446	SF	6	\$1,231	
	Walls - Structural Glazed Tile	320A	727	SF	6	\$2,287	
	Water Closet	320A	6	EA	6	\$2,016	
	Accessories	323C	430	SF	6	\$3,966	
	Ceiling - Lay-in	323C	430	SF	6	\$1,291	
	Doors - Wood Doors inclu hw	323C	1	EA	5	\$1,174	Door missing hardware
	Floor Drain	323C	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	323C	430	SF	6	\$910	
	Hand Dryer	323C	1	EA	6	\$230	
	Lavatory	323C	4	EA	6	\$1,278	
	Lighting - Pendent/Surface	323C	6	EA	7	\$0	
	Partitions	323C	5	EA	6	\$1,485	
	Urinals	323C	7	EA	6	\$2,352	
	Walls - Plaster/Drywall	323C	350	SF	6	\$966	
	Walls - Structural Glazed Tile	323C	612	SF	6	\$1,925	
	Water Closet	323C	4	EA	6	\$1,344	
	Accessories	342A	390	SF	6	\$3,597	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Ceiling - Plaster/Drywall	342A	390	SF	6	\$1,350	
	Doors - Wood Doors inclu hw	342A	1	EA	6	\$301	
	Floor Drain	342A	3	EA	6	\$3,177	
	Floor - Tile Ceramic/ Porcelain	342A	390	SF	6	\$825	
	Hand Dryer	342A	1	EA	6	\$230	
	Lavatory	342A	2	EA	6	\$639	
	Lighting - Pendent/Surface	342A	4	EA	7	\$0	
	Partitions	342A	5	EA	6	\$1,485	
	Urinals	342A	6	EA	6	\$2,016	
	Walls - Plaster/Drywall	342A	340	SF	6	\$938	
	Walls - Structural Glazed Tile	342A	647	SF	6	\$2,035	
	Water Closet	342A	5	EA	6	\$1,680	
	Water Closet	342A	1	EA	5	\$1,344	Broke
	Accessories	342B	86	SF	6	\$793	
	Ceiling - Plaster/Drywall	342B	86	SF	6	\$298	
	Doors - Wood Doors inclu hw	342B	1	EA	6	\$301	
	Floor Drain	342B	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	342B	86	SF	6	\$182	
	Lavatory	342B	1	EA	6	\$320	
	Lighting - Pendent/Surface	342B	1	EA	7	\$0	
	Walls - Plaster/Drywall	342B	393	SF	6	\$1,085	
	Water Closet	342B	1	EA	6	\$336	
	Accessories	345A	485	SF	6	\$4,473	
	Ceiling - Plaster/Drywall	345A	20	SF	5	\$250	Water damaged
	Ceiling - Plaster/Drywall	345A	465	SF	6	\$1,609	
	Doors - Wood Doors inclu hw	345A	1	EA	4	\$3,413	Door missing
	Floor Drain	345A	3	EA	6	\$3,177	
	Floor - Tile Ceramic/ Porcelain	345A	485	SF	6	\$1,026	
	Hand Dryer	345A	2	EA	6	\$460	
	Lavatory	345A	2	EA	6	\$639	
	Lighting - Pendent/Surface	345A	8	EA	7	\$0	
	Partitions	345A	6	EA	6	\$1,782	
	Urinals	345A	12	EA	6	\$4,032	
	Walls - Plaster/Drywall	345A	20	SF	5	\$102	Water damaged
	Walls - Plaster/Drywall	345A	883	SF	6	\$2,437	
	Walls - Structural Glazed Tile	345A	6	SF	5	\$383	cracked or missing tiles
	Walls - Structural Glazed Tile	345A	673	SF	6	\$2,117	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Water Closet	345A	6	EA	6	\$2,016	
	Ceiling - Plaster/Drywall	357A Coach's Office	60	SF	6	\$208	
	Doors - Wood Doors inclu hw	357A Coach's Office	1	EA	6	\$301	
	Floor Drain	357A Coach's Office	1	EA	6	\$1,059	
	Floor - Tile	357A Coach's Office	60	SF	6	\$131	
	Lavatory	357A Coach's Office	1	EA	6	\$320	
	Lighting - Pendent/Surface	357A Coach's Office	1	EA	4	\$541	
	Showers	357A Coach's Office	1	EA	6	\$311	
	Walls - Plaster/Drywall	357A Coach's Office	801	SF	6	\$2,211	
	Water Closet	357A Coach's Office	1	EA	6	\$336	
	Accessories	3rd Floor	440	SF	6	\$4,058	
	Ceiling - Plaster/Drywall	3rd Floor	440	SF	6	\$1,523	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	4	\$3,413	Missing
	Floor Drain	3rd Floor	2	EA	6	\$2,118	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	440	SF	6	\$931	
	Hand Dryer	3rd Floor	1	EA	6	\$230	
	Lavatory	3rd Floor	2	EA	6	\$639	
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	\$0	
	Partitions	3rd Floor	7	EA	6	\$2,078	
	Urinals	3rd Floor	14	EA	6	\$4,704	
	Walls - Plaster/Drywall	3rd Floor	360	SF	6	\$994	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	\$51	Damaged
	Walls - Structural Glazed Tile	3rd Floor	720	SF	6	\$2,265	
	Water Closet	3rd Floor	8	EA	6	\$2,688	
	Accessories	4th Floor	532	SF	6	\$4,907	
	Ceiling - Plaster/Drywall	4th Floor	532	SF	6	\$1,841	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	\$301	
	Floor Drain	4th Floor	1	EA	6	\$1,059	
	Floor - Tile	4th Floor	532	SF	6	\$1,164	
	Hand Dryer	4th Floor	2	EA	6	\$460	
	Lavatory	4th Floor	3	EA	6	\$959	
	Lighting - Pendent/Surface	4th Floor	8	EA	6	\$991	
	Partitions	4th Floor	4	EA	6	\$1,188	
	Urinals	4th Floor	4	EA	6	\$1,344	
	Walls - Plaster/Drywall	4th Floor	439	SF	6	\$1,212	
	Walls - Structural Glazed Tile	4th Floor	1,336	SF	6	\$4,203	
	Water Closet	4th Floor	4	EA	6	\$1,344	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Accessories	Basement- Boys Auditorium Lobby	328	SF	6	\$3,025	
	Ceiling - Plaster/Drywall	Basement- Boys Auditorium Lobby	2	SF	5	\$25	Peeling
	Ceiling - Plaster/Drywall	Basement- Boys Auditorium Lobby	922	SF	6	\$3,191	
	Doors - Wood Doors inclu hw	Basement- Boys Auditorium Lobby	3	EA	6	\$903	
	Floor Drain	Basement- Boys Auditorium Lobby	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Basement- Boys Auditorium Lobby	924	SF	6	\$1,956	
	Hand Dryer	Basement- Boys Auditorium Lobby	1	EA	6	\$230	
	Lavatory	Basement- Boys Auditorium Lobby	2	EA	6	\$639	
	Lighting - Pendent/Surface	Basement- Boys Auditorium Lobby	11	EA	6	\$1,363	
	Partitions	Basement- Boys Auditorium Lobby	2	EA	5	\$1,502	missing doors & 1 marble partition wall is buckling
	Urinals	Basement- Boys Auditorium Lobby	4	EA	6	\$1,344	
	Walls - Plaster/Drywall	Basement- Boys Auditorium Lobby	62	SF	5	\$274	40sqft in bathroom lobby has water damaged & 10sf in resteroom is peeling
	Walls - Plaster/Drywall	Basement- Boys Auditorium Lobby	389	SF	6	\$1,074	
	Walls - Tile	Basement- Boys Auditorium Lobby	1,270	SF	6	\$2,779	marble tile
	Walls - Tile	Basement- Boys Auditorium Lobby	46	SF	5	\$1,053	missing & buckling marble tile
	Water Closet	Basement- Boys Auditorium Lobby	2	EA	6	\$672	
	Accessories	Basement- Boys- NW (by ROTC)	253	SF	6	\$2,334	
	Ceiling - Plaster/Drywall	Basement- Boys- NW (by ROTC)	253	SF	6	\$876	
	Doors - Wood Doors inclu hw	Basement- Boys- NW (by ROTC)	1	EA	6	\$301	
	Floor Drain	Basement- Boys- NW (by ROTC)	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Basement- Boys- NW (by ROTC)	253	SF	6	\$535	
	Lavatory	Basement- Boys- NW (by ROTC)	1	EA	5	\$1,590	broken pedestal leg
	Lavatory	Basement- Boys- NW (by ROTC)	1	EA	6	\$320	
	Lighting - Pendent/Surface	Basement- Boys- NW (by ROTC)	5	EA	7	\$0	
	Partitions	Basement- Boys- NW (by ROTC)	1	EA	6	\$297	
	Urinals	Basement- Boys- NW (by ROTC)	1	EA	4	\$7,669	missing
	Urinals	Basement- Boys- NW (by ROTC)	3	EA	6	\$1,008	1 is running
	Walls - Structural Glazed Tile	Basement- Boys- NW (by ROTC)	900	SF	6	\$2,831	
	Water Closet	Basement- Boys- NW (by ROTC)	2	EA	6	\$672	
	Accessories	Basement- Girls Auditorium Lobby	328	SF	6	\$3,025	
	Ceiling - Plaster/Drywall	Basement- Girls Auditorium Lobby	914	SF	6	\$3,163	
	Ceiling - Plaster/Drywall	Basement- Girls Auditorium Lobby	10	SF	5	\$125	Peeling in restroom lobby
	Doors - Wood Doors inclu hw	Basement- Girls Auditorium Lobby	3	EA	6	\$903	
	Floor Drain	Basement- Girls Auditorium Lobby	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Basement- Girls Auditorium Lobby	924	SF	6	\$1,956	
	Hand Dryer	Basement- Girls Auditorium Lobby	1	EA	6	\$230	
	Lavatory	Basement- Girls Auditorium Lobby	1	EA	6	\$320	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lavatory	Basement- Girls Auditorium Lobby	1	EA	5	\$1,590	1 sink is missing a faucet
	Lighting - Pendent/Surface	Basement- Girls Auditorium Lobby	11	EA	7	\$0	
	Partitions	Basement- Girls Auditorium Lobby	4	EA	6	\$1,188	
	Walls - Plaster/Drywall	Basement- Girls Auditorium Lobby	1,755	SF	6	\$4,844	
	Water Closet	Basement- Girls Auditorium Lobby	4	EA	6	\$1,344	
	Accessories	Basement- Girl's- NE (under Aud. stage)	110	SF	6	\$1,015	
	Ceiling - Plaster/Drywall	Basement- Girl's- NE (under Aud. stage)	110	SF	6	\$381	
	Doors - Wood Doors inclu hw	Basement- Girl's- NE (under Aud. stage)	1	EA	6	\$301	
	Floor Drain	Basement- Girl's- NE (under Aud. stage)	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Basement- Girl's- NE (under Aud. stage)	110	SF	6	\$233	
	Lavatory	Basement- Girl's- NE (under Aud. stage)	2	EA	6	\$639	
	Lighting - Pendent/Surface	Basement- Girl's- NE (under Aud. stage)	1	EA	7	\$0	
	Partitions	Basement- Girl's- NE (under Aud. stage)	1	EA	5	\$751	missing door
	Partitions	Basement- Girl's- NE (under Aud. stage)	1	EA	6	\$297	
	Walls - Plaster/Drywall	Basement- Girl's- NE (under Aud. stage)	559	SF	6	\$1,543	
	Water Closet	Basement- Girl's- NE (under Aud. stage)	3	EA	6	\$1,008	
	Accessories	Basement- Girls- NW by ROTC	309	SF	6	\$2,850	
	Ceiling - Plaster/Drywall	Basement- Girls- NW by ROTC	309	SF	5	\$2,832	lots of water coming through ceiling.
	Doors - Wood Doors inclu hw	Basement- Girls- NW by ROTC	1	EA	5	\$1,174	moldy from water
	Floor Drain	Basement- Girls- NW by ROTC	1	EA	6	\$1,059	appears to be working, no water on floor currently
	Floor - Tile Ceramic/ Porcelain	Basement- Girls- NW by ROTC	309	SF	6	\$654	
	Hand Dryer	Basement- Girls- NW by ROTC	1	EA	4	\$1,079	no longer working
	Lavatory	Basement- Girls- NW by ROTC	2	EA	6	\$639	
	Lighting - Pendent/Surface	Basement- Girls- NW by ROTC	1	EA	6	\$124	
	Lighting - Pendent/Surface	Basement- Girls- NW by ROTC	4	EA	4	\$2,163	not working from water leak
	Partitions	Basement- Girls- NW by ROTC	2	EA	6	\$594	
	Partitions	Basement- Girls- NW by ROTC	1	EA	5	\$751	missing a door
	Walls - Structural Glazed Tile	Basement- Girls- NW by ROTC	888	SF	6	\$2,794	
	Water Closet	Basement- Girls- NW by ROTC	4	EA	6	\$1,344	
	Ceiling - Plaster/Drywall	Basement- Under Auditorium Stage	169	SF	6	\$585	
	Doors - Wood Doors inclu hw	Basement- Under Auditorium Stage	1	EA	6	\$301	
	Floor Drain	Basement- Under Auditorium Stage	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	Basement- Under Auditorium Stage	159	SF	6	\$337	
	Floor - Tile Ceramic/ Porcelain	Basement- Under Auditorium Stage	10	SF	5	\$209	missing
	Lavatory	Basement- Under Auditorium Stage	2	EA	6	\$639	1 pedestal leg is broken slightly at the bottom
	Lighting - Pendent/Surface	Basement- Under Auditorium Stage	1	EA	4	\$541	painted over fixture & bulb
	Lighting - Pendent/Surface	Basement- Under Auditorium Stage	2	EA	7	\$0	

**Building: Main**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Partitions	Basement- Under Auditorium Stage	3	EA	6	\$891	
	Urinals	Basement- Under Auditorium Stage	3	EA	6	\$1,008	
	Walls - Metal Panel	Basement- Under Auditorium Stage	351	SF	6	\$2,620	vinyl panel
	Walls - Plaster/Drywall	Basement- Under Auditorium Stage	351	SF	6	\$969	
	Water Closet	Basement- Under Auditorium Stage	1	EA	4	\$7,669	missing
	Water Closet	Basement- Under Auditorium Stage	2	EA	6	\$672	
	Accessories	Engineer's Office	57	SF	6	\$526	
	Ceiling - Lay-in	Engineer's Office	57	SF	6	\$171	
	Floor - Tile Ceramic/ Porcelain	Engineer's Office	57	SF	6	\$121	
	Lavatory	Engineer's Office	1	EA	6	\$320	
	Lighting - Lay-in	Engineer's Office	1	EA	7	\$0	
	Partitions	Engineer's Office	1	EA	6	\$297	
	Walls - Plaster/Drywall	Engineer's Office	210	SF	6	\$580	
	Walls - Tile Ceramic/ Porcelain	Engineer's Office	96	SF	6	\$217	
	Water Closet	Engineer's Office	1	EA	6	\$336	
	Accessories	unisex bath next to storage 138-C	85	SF	6	\$784	
	Ceiling - Plaster/Drywall	unisex bath next to storage 138-C	85	SF	6	\$294	
	Doors - Wood Doors inclu hw	unisex bath next to storage 138-C	1	EA	6	\$301	
	Floor Drain	unisex bath next to storage 138-C	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	unisex bath next to storage 138-C	85	SF	6	\$180	
	Lavatory	unisex bath next to storage 138-C	1	EA	6	\$320	
	Lighting - Pendent/Surface	unisex bath next to storage 138-C	1	EA	7	\$0	
	Walls - Plaster/Drywall	unisex bath next to storage 138-C	4	SF	5	\$20	cracks in wall
	Walls - Plaster/Drywall	unisex bath next to storage 138-C	357	SF	6	\$985	
	Walls - Tile Ceramic/ Porcelain	unisex bath next to storage 138-C	12	SF	6	\$27	base tile
	Water Closet	unisex bath next to storage 138-C	1	EA	6	\$336	

**Rooms (Other Than Classrooms) Subtotal:**
**\$6,349,262**
**Building: Main**
**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Ceiling - Plaster/Drywall	1st Floor, Auditorium Lobby	671	SF	6	\$4,942	Vestibule
	Ceiling - Plaster/Drywall	1st Floor, Auditorium Lobby	1,162	SF	6	\$7,195	
	Doors - Transom Window	1st Floor, Auditorium Lobby	81	EA	6	\$1,371	
	Doors - Wood Doors include hw	1st Floor, Auditorium Lobby	9	EA	6	\$2,709	

**Building: Main**
**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Floor - Terrazzo	1st Floor, Auditorium Lobby	1,833	SF	6	\$15,386	
	Floor - Terrazzo	1st Floor, Auditorium Lobby	556	SF	6	\$5,518	Vestibule
	Lighting - Pendent/Surface	1st Floor, Auditorium Lobby	7	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor, Auditorium Lobby	3	EA	7	\$0	Vestibule
	Walls - Masonry	1st Floor, Auditorium Lobby	1,664	SF	6	\$5,235	Vestibule
	Walls - Metal Panel	1st Floor, Auditorium Lobby	1,573	SF	6	\$11,742	
	Walls - Plaster/Drywall	1st Floor, Auditorium Lobby	21	SF	5	\$211	Water Damage near exit door NW corner
	Walls - Plaster/Drywall	1st Floor, Auditorium Lobby	1,552	SF	6	\$6,880	
	Ceiling - Plaster/Drywall	1st Floor, E Corridor	6,622	SF	6	\$41,003	
	Doors - Steel Doors incl hw	1st Floor, E Corridor	8	EA	6	\$2,408	
	Doors - Transom Window	1st Floor, E Corridor	108	EA	6	\$1,829	
	Drinking Fountains - Double Fountain	1st Floor, E Corridor	3	EA	6	\$1,008	
	Floor - Terrazzo	1st Floor, E Corridor	662	SF	6	\$5,557	
	Floor - Tile/Sheet	1st Floor, E Corridor	5,960	SF	6	\$3,239	
	Lighting - Pendent/Surface	1st Floor, E Corridor	44	EA	6	\$5,451	
	Student Lockers - One Tier	1st Floor, E Corridor	376	EA	6	\$34,906	
	Walls - Plaster/Drywall	1st Floor, E Corridor	4,318	SF	6	\$19,142	
	Walls - Plaster/Drywall	1st Floor, E Corridor	6	SF	5	\$60	Cracks, peeling
	Walls - Structural Glazed Tile	1st Floor, E Corridor	7,410	SF	6	\$23,312	
	Walls - Tile Ceramic/ Porcelain	1st Floor, E Corridor	39	SF	5	\$819	Cracks, broken
	Walls - Tile Ceramic/ Porcelain	1st Floor, E Corridor	618	SF	6	\$1,944	
	Ceiling	1st Floor, N Corridor	45	SF	5	\$0	Water damaged
	Ceiling - Plaster/Drywall	1st Floor, N Corridor	6,701	SF	6	\$41,492	
	Drinking Fountains - Double Fountain	1st Floor, N Corridor	2	EA	6	\$672	
	Floor - Terrazzo	1st Floor, N Corridor	463	SF	6	\$3,886	
	Floor - Tile/Sheet	1st Floor, N Corridor	4,171	SF	6	\$2,267	
	Lighting - Chandelier, Incandescent	1st Floor, N Corridor	40	EA	6	\$19,103	
	Lighting - Pendent/Surface	1st Floor, N Corridor	32	EA	6	\$3,965	
	Student Lockers - One Tier	1st Floor, N Corridor	311	EA	6	\$28,872	
	Walls - Plaster/Drywall	1st Floor, N Corridor	42,342	SF	6	\$187,702	
	Walls - Plaster/Drywall	1st Floor, N Corridor	132	SF	5	\$1,325	Water damaged
	Walls - Structural Glazed Tile	1st Floor, N Corridor	42,350	SF	6	\$133,233	
	Walls - Tile Ceramic/ Porcelain	1st Floor, N Corridor	8	SF	5	\$168	Cracks, broken
	Walls - Tile Ceramic/ Porcelain	1st Floor, N Corridor	6,701	SF	6	\$21,081	
	Walls - Vinyl Coated Gypsum Panel	1st Floor, N Corridor	21,175	SF	6	\$58,441	
	Ceiling - Plaster/Drywall	1st Floor, S Cafeteria Corridor	425	SF	6	\$2,632	
	Floor - Terrazzo	1st Floor, S Cafeteria Corridor	170	SF	6	\$1,427	

**Building: Main**

**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Floor - Tile/Sheet	1st Floor, S Cafeteria Corridor	255	SF	6	\$139	
	Lighting - Pendent/Surface	1st Floor, S Cafeteria Corridor	10	EA	6	\$1,239	
	Walls - Plaster/Drywall	1st Floor, S Cafeteria Corridor	3,385	SF	6	\$15,006	
	Walls - Structural Glazed Tile	1st Floor, S Cafeteria Corridor	3,358	SF	6	\$10,564	
	Ceiling - Plaster/Drywall	1st Floor, S Corridor	4,634	SF	6	\$28,693	
	Ceiling - Plaster/Drywall	1st Floor, S Corridor	118	SF	5	\$2,059	Water damaged
	Doors - Steel Doors incl hw	1st Floor, S Corridor	8	EA	6	\$2,408	
	Doors - Transom Window	1st Floor, S Corridor	108	EA	6	\$1,829	
	Drinking Fountains - Double Fountain	1st Floor, S Corridor	2	EA	6	\$672	
	Floor - Terrazzo	1st Floor, S Corridor	250	SF	6	\$2,099	
	Floor - Tile/Sheet	1st Floor, S Corridor	2,255	SF	6	\$1,225	
	Lighting - Pendent/Surface	1st Floor, S Corridor	32	EA	6	\$3,965	
	Student Lockers - One Tier	1st Floor, S Corridor	311	EA	6	\$28,872	
	Walls - Plaster/Drywall	1st Floor, S Corridor	4,218	SF	6	\$18,698	
	Walls - Structural Glazed Tile	1st Floor, S Corridor	7,230	SF	6	\$22,746	
	Walls - Tile Ceramic/ Porcelain	1st Floor, S Corridor	25	SF	5	\$525	Cracks, broken
	Walls - Tile Ceramic/ Porcelain	1st Floor, S Corridor	603	SF	6	\$1,897	
	Ceiling - Plaster/Drywall	1st Floor, SW Corridor	1,400	SF	6	\$8,669	
	Floor - Terrazzo	1st Floor, SW Corridor	140	SF	6	\$1,175	
	Floor - Tile/Sheet	1st Floor, SW Corridor	1,260	SF	6	\$685	
	Lighting - Pendent/Surface	1st Floor, SW Corridor	12	EA	6	\$1,487	
	Student Lockers - One Tier	1st Floor, SW Corridor	108	EA	6	\$10,026	
	Walls - Plaster/Drywall	1st Floor, SW Corridor	1,037	SF	6	\$4,597	
	Walls - Plaster/Drywall	1st Floor, SW Corridor	20	SF	5	\$201	Cracks, peeling
	Walls - Structural Glazed Tile	1st Floor, SW Corridor	1,778	SF	6	\$5,594	
	Walls - Tile Ceramic/ Porcelain	1st Floor, SW Corridor	6	SF	5	\$126	Cracks, broken
	Walls - Tile Ceramic/ Porcelain	1st Floor, SW Corridor	148	SF	6	\$466	
	Ceiling - Plaster/Drywall	1st Floor, W Corridor	6,600	SF	6	\$40,867	
	Doors - Steel Doors incl hw	1st Floor, W Corridor	8	EA	6	\$2,408	
	Doors - Transom Window	1st Floor, W Corridor	108	EA	6	\$1,829	
	Drinking Fountains - Double Fountain	1st Floor, W Corridor	3	EA	6	\$1,008	
	Floor - Terrazzo	1st Floor, W Corridor	924	SF	6	\$7,756	
	Floor - Tile/Sheet	1st Floor, W Corridor	8,316	SF	6	\$4,519	
	Lighting - Pendent/Surface	1st Floor, W Corridor	44	EA	6	\$5,451	
	Student Lockers - One Tier	1st Floor, W Corridor	316	EA	6	\$29,336	
	Walls - Plaster/Drywall	1st Floor, W Corridor	4,200	SF	6	\$18,619	
	Walls - Plaster/Drywall	1st Floor, W Corridor	45	SF	6	\$280	Cracks, peeling



**Building: Main**
**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Walls - Structural Glazed Tile	1st Floor, W Corridor	5,544	SF	6	\$17,441	
	Walls - Tile Ceramic/ Porcelain	1st Floor, W Corridor	462	SF	6	\$1,453	
	Walls - Tile Ceramic/ Porcelain	1st Floor, W Corridor	39	SF	5	\$819	Cracks, broken
	Ceiling - Plaster/Drywall	2nd Floor, Auditorium Lobby	2,389	SF	6	\$14,792	
	Drinking Fountains - Single Fountain	2nd Floor, Auditorium Lobby	2	EA	6	\$551	
	Floor - Terrazzo	2nd Floor, Auditorium Lobby	1,630	SF	6	\$13,682	
	Lighting - Pendent/Surface	2nd Floor, Auditorium Lobby	13	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor, Auditorium Lobby	30	SF	5	\$301	peeling/deterioration
	Walls - Plaster/Drywall	2nd Floor, Auditorium Lobby	2,380	SF	6	\$10,551	
	Ceiling - Plaster/Drywall	2nd Floor, E Corridor	6,620	SF	6	\$40,990	
	Ceiling - Plaster/Drywall	2nd Floor, E Corridor	2	SF	5	\$35	Peeling
	Doors - Steel Doors incl hw	2nd Floor, E Corridor	8	EA	6	\$2,408	
	Doors - Transom Window	2nd Floor, E Corridor	108	EA	6	\$1,829	
	Drinking Fountains - Double Fountain	2nd Floor, E Corridor	3	EA	6	\$1,008	
	Floor - Terrazzo	2nd Floor, E Corridor	662	SF	6	\$5,557	
	Floor - Tile/Sheet	2nd Floor, E Corridor	5,960	SF	6	\$3,239	
	Lighting - Pendent/Surface	2nd Floor, E Corridor	44	EA	6	\$5,451	
	Student Lockers - One Tier	2nd Floor, E Corridor	376	EA	6	\$34,906	
	Walls - Plaster/Drywall	2nd Floor, E Corridor	4,322	SF	6	\$19,159	
	Walls - Structural Glazed Tile	2nd Floor, E Corridor	7,410	SF	6	\$23,312	
	Walls - Tile Ceramic/ Porcelain	2nd Floor, E Corridor	39	SF	5	\$819	Cracks, broken
	Walls - Tile Ceramic/ Porcelain	2nd Floor, E Corridor	618	SF	6	\$1,944	
	Ceiling - Plaster/Drywall	2nd Floor, N Corridor	4,620	SF	6	\$28,607	
	Ceiling - Plaster/Drywall	2nd Floor, N Corridor	14	SF	5	\$244	Peeling/water damage
	Drinking Fountains - Double Fountain	2nd Floor, N Corridor	2	EA	6	\$672	
	Floor - Terrazzo	2nd Floor, N Corridor	463	SF	6	\$3,886	
	Floor - Tile/Sheet	2nd Floor, N Corridor	4,171	SF	6	\$2,267	
	Lighting - Pendent/Surface	2nd Floor, N Corridor	32	EA	6	\$3,965	
	Student Lockers - One Tier	2nd Floor, N Corridor	311	EA	6	\$28,872	
	Walls - Plaster/Drywall	2nd Floor, N Corridor	2,196	SF	6	\$9,735	
	Walls - Plaster/Drywall	2nd Floor, N Corridor	6	SF	5	\$60	Cracks, peeling
	Walls - Structural Glazed Tile	2nd Floor, N Corridor	3,744	SF	6	\$11,779	
	Walls - Tile Ceramic/ Porcelain	2nd Floor, N Corridor	25	SF	5	\$525	Cracks, broken
	Walls - Tile Ceramic/ Porcelain	2nd Floor, N Corridor	312	SF	6	\$982	
	Ceiling - Plaster/Drywall	2nd Floor, S Corridor	4,634	SF	6	\$28,693	
	Doors - Steel Doors incl hw	2nd Floor, S Corridor	8	EA	6	\$2,408	
	Doors - Transom Window	2nd Floor, S Corridor	108	EA	6	\$1,829	

**Building: Main**
**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Drinking Fountains - Double Fountain	2nd Floor, S Corridor	2	EA	6	\$672	
	Floor - Terrazzo	2nd Floor, S Corridor	250	SF	6	\$2,099	
	Floor - Tile/Sheet	2nd Floor, S Corridor	2,255	SF	6	\$1,225	
	Lighting - Pendent/Surface	2nd Floor, S Corridor	32	EA	6	\$3,965	
	Student Lockers - One Tier	2nd Floor, S Corridor	311	EA	6	\$28,872	
	Walls - Plaster/Drywall	2nd Floor, S Corridor	6	SF	5	\$60	Cracks
	Walls - Plaster/Drywall	2nd Floor, S Corridor	4,218	SF	6	\$18,698	
	Walls - Structural Glazed Tile	2nd Floor, S Corridor	7,230	SF	6	\$22,746	
	Walls - Tile Ceramic/ Porcelain	2nd Floor, S Corridor	5	SF	5	\$105	Cracks, broken
	Walls - Tile Ceramic/ Porcelain	2nd Floor, S Corridor	623	SF	6	\$1,960	Base board
	Ceiling - Plaster/Drywall	2nd Floor, SE Corridor	425	SF	6	\$2,632	
	Floor - Terrazzo	2nd Floor, SE Corridor	42	SF	6	\$353	
	Floor - Tile/Sheet	2nd Floor, SE Corridor	383	SF	6	\$208	
	Lighting - Pendent/Surface	2nd Floor, SE Corridor	12	EA	6	\$1,487	
	Student Lockers - One Tier	2nd Floor, SE Corridor	116	EA	6	\$10,769	
	Walls - Plaster/Drywall	2nd Floor, SE Corridor	4,029	SF	6	\$17,861	
	Walls - Structural Glazed Tile	2nd Floor, SE Corridor	2,350	SF	6	\$7,393	
	Walls - Tile Ceramic/ Porcelain	2nd Floor, SE Corridor	330	SF	6	\$1,038	
	Walls - Tile Ceramic/ Porcelain	2nd Floor, SE Corridor	6	SF	5	\$126	Cracks, broken
	Ceiling - Plaster/Drywall	2nd Floor, SW Corridor	1,400	SF	6	\$8,669	
	Floor - Terrazzo	2nd Floor, SW Corridor	140	SF	6	\$1,175	
	Floor - Tile/Sheet	2nd Floor, SW Corridor	1,260	SF	6	\$685	
	Lighting - Pendent/Surface	2nd Floor, SW Corridor	12	EA	6	\$1,487	
	Student Lockers - One Tier	2nd Floor, SW Corridor	108	EA	6	\$10,026	
	Walls - Plaster/Drywall	2nd Floor, SW Corridor	4	SF	5	\$40	Cracks, peeling
	Walls - Plaster/Drywall	2nd Floor, SW Corridor	1,053	SF	6	\$4,668	
	Walls - Structural Glazed Tile	2nd Floor, SW Corridor	1,778	SF	6	\$5,594	
	Walls - Tile Ceramic/ Porcelain	2nd Floor, SW Corridor	148	SF	6	\$466	
	Walls - Tile Ceramic/ Porcelain	2nd Floor, SW Corridor	6	SF	5	\$126	Cracks, broken
	Ceiling - Plaster/Drywall	2nd Floor, W Corridor	9,240	SF	6	\$57,213	
	Doors - Steel Doors incl hw	2nd Floor, W Corridor	8	EA	6	\$2,408	
	Doors - Transom Window	2nd Floor, W Corridor	108	EA	6	\$1,829	
	Drinking Fountains - Double Fountain	2nd Floor, W Corridor	3	EA	6	\$1,008	
	Floor - Terrazzo	2nd Floor, W Corridor	8,316	SF	6	\$69,805	
	Floor - Tile/Sheet	2nd Floor, W Corridor	924	SF	6	\$502	
	Lighting - Pendent/Surface	2nd Floor, W Corridor	44	EA	6	\$5,451	
	Student Lockers - One Tier	2nd Floor, W Corridor	316	EA	6	\$29,336	

## Building: Main

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Walls - Plaster/Drywall	2nd Floor, W Corridor	3,225	SF	6	\$14,296	
	Walls - Plaster/Drywall	2nd Floor, W Corridor	20	SF	5	\$201	Cracks, peeling
	Walls - Structural Glazed Tile	2nd Floor, W Corridor	5,544	SF	6	\$17,441	
	Walls - Tile Ceramic/ Porcelain	2nd Floor, W Corridor	39	SF	5	\$819	Cracks, broken
	Walls - Tile Ceramic/ Porcelain	2nd Floor, W Corridor	462	SF	6	\$1,453	
	Ceiling - Plaster/Drywall	3rd Floor, E Corridor	6,622	SF	6	\$41,003	
	Doors - Steel Doors incl hw	3rd Floor, E Corridor	8	EA	6	\$2,408	
	Doors - Transom Window	3rd Floor, E Corridor	108	EA	6	\$1,829	
	Drinking Fountains - Double Fountain	3rd Floor, E Corridor	3	EA	6	\$1,008	
	Floor - Terrazzo	3rd Floor, E Corridor	20	SF	5	\$1,046	Stained
	Floor - Terrazzo	3rd Floor, E Corridor	642	SF	6	\$5,389	
	Floor - Tile/Sheet	3rd Floor, E Corridor	5,960	SF	6	\$3,239	
	Lighting - Pendent/Surface	3rd Floor, E Corridor	44	EA	6	\$5,451	
	Student Lockers - One Tier	3rd Floor, E Corridor	376	EA	6	\$34,906	
	Walls - Plaster/Drywall	3rd Floor, E Corridor	4,322	SF	6	\$19,159	
	Walls - Structural Glazed Tile	3rd Floor, E Corridor	7,410	SF	6	\$23,312	
	Walls - Tile Ceramic/ Porcelain	3rd Floor, E Corridor	618	SF	6	\$1,944	Base board
	Walls - Tile Ceramic/ Porcelain	3rd Floor, E Corridor	39	SF	5	\$819	Cracks, broken
	Ceiling - Plaster/Drywall	3rd Floor, N Corridor	14	SF	5	\$244	Water damage, peeling
	Ceiling - Plaster/Drywall	3rd Floor, N Corridor	4,620	SF	6	\$28,607	
	Drinking Fountains - Double Fountain	3rd Floor, N Corridor	2	EA	6	\$672	
	Floor - Terrazzo	3rd Floor, N Corridor	443	SF	6	\$3,719	
	Floor - Terrazzo	3rd Floor, N Corridor	20	SF	5	\$1,046	Stained
	Floor - Tile/Sheet	3rd Floor, N Corridor	4,171	SF	6	\$2,267	
	Lighting - Pendent/Surface	3rd Floor, N Corridor	32	EA	6	\$3,965	
	Student Lockers - One Tier	3rd Floor, N Corridor	311	EA	6	\$28,872	
	Walls - Plaster/Drywall	3rd Floor, N Corridor	2,184	SF	6	\$9,682	
	Walls - Plaster/Drywall	3rd Floor, N Corridor	18	SF	5	\$181	Cracks, peeling
	Walls - Structural Glazed Tile	3rd Floor, N Corridor	3,744	SF	6	\$11,779	
	Walls - Tile Ceramic/ Porcelain	3rd Floor, N Corridor	25	SF	5	\$525	Cracks, broken
	Walls - Tile Ceramic/ Porcelain	3rd Floor, N Corridor	312	SF	6	\$982	Base board
	Ceiling - Plaster/Drywall	3rd Floor, S Corridor	4,634	SF	6	\$28,693	Some peeling plaster
	Doors - Steel Doors incl hw	3rd Floor, S Corridor	8	EA	6	\$2,408	
	Doors - Transom Window	3rd Floor, S Corridor	108	EA	6	\$1,829	
	Drinking Fountains - Double Fountain	3rd Floor, S Corridor	2	EA	6	\$672	
	Floor - Terrazzo	3rd Floor, S Corridor	250	SF	6	\$2,099	
	Floor - Tile/Sheet	3rd Floor, S Corridor	2,255	SF	6	\$1,225	

## Building: Main

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Lighting - Pendent/Surface	3rd Floor, S Corridor	32	EA	6	\$3,965	
	Student Lockers - One Tier	3rd Floor, S Corridor	311	EA	6	\$28,872	
	Walls - Plaster/Drywall	3rd Floor, S Corridor	4,218	SF	6	\$18,698	
	Walls - Structural Glazed Tile	3rd Floor, S Corridor	7,230	SF	6	\$22,746	
	Walls - Tile Ceramic/ Porcelain	3rd Floor, S Corridor	25	SF	5	\$525	Cracks, broken base board
	Walls - Tile Ceramic/ Porcelain	3rd Floor, S Corridor	603	SF	6	\$1,897	Base board
	Ceiling - Plaster/Drywall	3rd Floor, SE Gym Corridor	14	SF	5	\$244	Peeling
	Ceiling - Plaster/Drywall	3rd Floor, SE Gym Corridor	1,104	SF	6	\$6,836	
	Floor - Terrazzo	3rd Floor, SE Gym Corridor	112	SF	6	\$940	
	Floor - Tile/Sheet	3rd Floor, SE Gym Corridor	1,006	SF	6	\$547	
	Lighting - Pendent/Surface	3rd Floor, SE Gym Corridor	2	EA	6	\$248	
	Student Lockers - One Tier	3rd Floor, SE Gym Corridor	35	EA	6	\$3,249	
	Walls - Plaster/Drywall	3rd Floor, SE Gym Corridor	391	SF	6	\$1,733	
	Walls - Structural Glazed Tile	3rd Floor, SE Gym Corridor	670	SF	6	\$2,108	
	Walls - Tile Ceramic/ Porcelain	3rd Floor, SE Gym Corridor	56	SF	6	\$176	Base board
	Walls - Tile Ceramic/ Porcelain	3rd Floor, SE Gym Corridor	9	SF	5	\$167	Cracks, broken
	Ceiling - Plaster/Drywall	3rd Floor, SW Corridor	1,388	SF	6	\$8,594	
	Ceiling - Plaster/Drywall	3rd Floor, SW Corridor	12	SF	5	\$209	Peeling
	Floor - Terrazzo	3rd Floor, SW Corridor	140	SF	6	\$1,175	
	Floor - Tile/Sheet	3rd Floor, SW Corridor	1,260	SF	6	\$685	
	Lighting - Pendent/Surface	3rd Floor, SW Corridor	12	EA	6	\$1,487	
	Student Lockers - One Tier	3rd Floor, SW Corridor	108	EA	6	\$10,026	
	Walls - Plaster/Drywall	3rd Floor, SW Corridor	1,037	SF	6	\$4,597	
	Walls - Plaster/Drywall	3rd Floor, SW Corridor	20	SF	5	\$201	Cracks
	Walls - Structural Glazed Tile	3rd Floor, SW Corridor	1,778	SF	6	\$5,594	
	Walls - Tile Ceramic/ Porcelain	3rd Floor, SW Corridor	148	SF	6	\$466	
	Walls - Tile Ceramic/ Porcelain	3rd Floor, SW Corridor	6	SF	5	\$126	Cracks, broken
	Ceiling - Plaster/Drywall	3rd Floor, W Corridor	6,566	SF	6	\$40,656	
	Ceiling - Plaster/Drywall	3rd Floor, W Corridor	34	SF	5	\$593	Cracks, peeling, water damage
	Doors - Steel Doors incl hw	3rd Floor, W Corridor	8	EA	6	\$2,408	
	Doors - Transom Window	3rd Floor, W Corridor	108	EA	6	\$1,829	
	Drinking Fountains - Double Fountain	3rd Floor, W Corridor	3	EA	6	\$1,008	
	Floor - Terrazzo	3rd Floor, W Corridor	8,316	SF	6	\$69,805	
	Floor - Tile/Sheet	3rd Floor, W Corridor	924	SF	6	\$502	
	Lighting - Pendent/Surface	3rd Floor, W Corridor	44	EA	6	\$5,451	
	Student Lockers - One Tier	3rd Floor, W Corridor	316	EA	6	\$29,336	
	Walls - Plaster/Drywall	3rd Floor, W Corridor	11	SF	6	\$68	Cracks

**Building: Main**
**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Walls - Plaster/Drywall	3rd Floor, W Corridor	3,234	SF	6	\$14,336	
	Walls - Structural Glazed Tile	3rd Floor, W Corridor	5,544	SF	6	\$17,441	
	Walls - Tile Ceramic/ Porcelain	3rd Floor, W Corridor	39	SF	5	\$819	Cracks, broken
	Walls - Tile Ceramic/ Porcelain	3rd Floor, W Corridor	462	SF	6	\$1,453	
	Ceiling - Lay-in	4th Floor, E Corridor	1,252	SF	6	\$3,760	
	Ceiling - Plaster/Drywall	4th Floor, E Corridor	1,252	SF	6	\$7,752	
	Doors - Transom Window	4th Floor, E Corridor	54	EA	6	\$914	
	Doors - Wood Doors include hw	4th Floor, E Corridor	4	EA	6	\$1,204	
	Floor - Terrazzo	4th Floor, E Corridor	251	SF	6	\$2,107	
	Floor - Tile/Sheet	4th Floor, E Corridor	2,254	SF	6	\$1,225	
	Lighting - Pendent/Surface	4th Floor, E Corridor	22	EA	6	\$2,726	
	Student Lockers - One Tier	4th Floor, E Corridor	21	EA	6	\$1,950	
	Walls - Plaster/Drywall	4th Floor, E Corridor	5,000	SF	6	\$22,165	
	Walls - Plaster/Drywall	4th Floor, E Corridor	20	SF	5	\$201	Peeling, cracking
	Walls - Structural Glazed Tile	4th Floor, E Corridor	12	SF	5	\$766	Missing mortar
	Walls - Structural Glazed Tile	4th Floor, E Corridor	2,916	SF	6	\$9,174	
	Walls - Tile Ceramic/ Porcelain	4th Floor, E Corridor	417	SF	6	\$1,312	Base board
	Walls - Tile Ceramic/ Porcelain	4th Floor, E Corridor	14	SF	5	\$294	Broken, cracks
	Ceiling - Plaster/Drywall	4th Floor, N Corridor	1,624	SF	6	\$10,056	
	Doors - Wood Doors include hw	4th Floor, N Corridor	4	EA	6	\$1,204	
	Drinking Fountains - Single Fountain	4th Floor, N Corridor	2	EA	6	\$551	
	Floor - Terrazzo	4th Floor, N Corridor	162	SF	6	\$1,360	
	Floor - Tile/Sheet	4th Floor, N Corridor	1,462	SF	6	\$794	
	Lighting - Pendent/Surface	4th Floor, N Corridor	14	EA	7	\$0	
	Student Lockers - One Tier	4th Floor, N Corridor	24	EA	6	\$2,228	
	Walls - Masonry	4th Floor, N Corridor	1,560	SF	6	\$4,908	
	Walls - Plaster/Drywall	4th Floor, N Corridor	1,040	SF	6	\$4,610	
	Ceiling - Plaster/Drywall	4th Floor, S Corridor	27	SF	5	\$471	Peeling plaster
	Ceiling - Plaster/Drywall	4th Floor, S Corridor	5,031	SF	6	\$31,151	
	Doors - Steel Doors incl hw	4th Floor, S Corridor	6	EA	6	\$1,806	
	Doors - Transom Window	4th Floor, S Corridor	81	EA	6	\$1,371	
	Drinking Fountains - Double Fountain	4th Floor, S Corridor	2	EA	6	\$672	
	Floor - Terrazzo	4th Floor, S Corridor	506	SF	6	\$4,247	
	Floor - Tile/Sheet	4th Floor, S Corridor	4,553	SF	6	\$2,474	
	Lighting - Chandelier, Incandescent	4th Floor, S Corridor	36	EA	6	\$17,192	
	Student Lockers - One Tier	4th Floor, S Corridor	293	EA	6	\$27,201	
	Walls - Plaster/Drywall	4th Floor, S Corridor	2,938	SF	5	\$21,679	Cracking

**Building: Main**
**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Walls - Structural Glazed Tile	4th Floor, S Corridor	5,037	SF	6	\$15,846	
	Walls - Tile Ceramic/ Porcelain	4th Floor, S Corridor	420	SF	6	\$1,321	Base board
	Walls - Tile Ceramic/ Porcelain	4th Floor, S Corridor	45	SF	5	\$945	Missing, broken
	Ceiling - Plaster/Drywall	4th Floor, W Corridor	1,571	SF	6	\$9,727	
	Doors - Wood Doors include hw	4th Floor, W Corridor	4	EA	6	\$1,204	
	Floor - Terrazzo	4th Floor, W Corridor	157	SF	6	\$1,318	
	Lighting - Pendent/Surface	4th Floor, W Corridor	12	EA	6	\$1,487	
	Student Lockers - Three Tiers	4th Floor, W Corridor	39	EA	6	\$1,207	Instrument Lockers
	Walls - Plaster/Drywall	4th Floor, W Corridor	1,235	SF	6	\$5,475	
	Walls - Structural Glazed Tile	4th Floor, W Corridor	1,950	SF	6	\$6,135	
	Walls - Tile Ceramic/ Porcelain	4th Floor, W Corridor	60	SF	6	\$189	Base board
	Walls - Tile Ceramic/ Porcelain	4th Floor, W Corridor	5	SF	5	\$105	Broken, cracked tiles
<b>Safety</b>							
	Camera Viewing Station	Entire Main building / 1st Floor	1	EA	6	\$683	Room 127
	Security Cameras	Entire Main building / Entire Building	16	EA	6	\$3,105	Interior Cameras
	Security Cameras	Entire Main building	11	EA	6	\$2,134	
<b>Stairs</b>							
	Ceiling - Plaster/Drywall	Stair A	15	SF	5	\$307	Cracks, peeling
	Ceiling - Plaster/Drywall	Stair A	1,068	SF	6	\$7,819	
	Floor - Terrazzo	Stair A	1,005	SF	6	\$8,436	
	Handrails	Stair A	104	LF	6	\$901	
	Lighting - Pendent/Surface	Stair A	8	EA	6	\$991	
	Stairs - Terrazzo	Stair A	56	LF	6	\$520	
	Walls - Plaster/Drywall	Stair A	6,845	SF	6	\$18,892	
	Walls - Plaster/Drywall	Stair A	40	SF	5	\$248	Cracks, peeling
	Walls - Structural Glazed Tile	Stair A	690	SF	5	\$44,036	Efflorescence
	Walls - Structural Glazed Tile	Stair A	6,210	SF	6	\$19,537	
	Ceiling - Plaster/Drywall	Stair B	25	SF	5	\$512	Cracks
	Ceiling - Plaster/Drywall	Stair B	1,364	SF	6	\$9,987	
	Floor - Terrazzo	Stair B	1,126	SF	6	\$9,452	
	Handrails	Stair B	184	LF	6	\$1,595	
	Lighting - Pendent/Surface	Stair B	17	EA	6	\$2,106	
	Stairs - Terrazzo	Stair B	96	LF	6	\$891	
	Walls - Plaster/Drywall	Stair B	13,160	SF	6	\$36,320	
	Walls - Structural Glazed Tile	Stair B	13,160	SF	6	\$41,401	
	Ceiling - Plaster/Drywall	Stair C	25	SF	5	\$512	Cracks

**Building: Main**
**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Stairs</b>							
	Ceiling - Plaster/Drywall	Stair C	2,746	SF	6	\$20,105	
	Floor - Terrazzo	Stair C	1,604	SF	6	\$13,464	
	Handrails	Stair C	214	LF	6	\$1,854	
	Lighting - Pendent/Surface	Stair C	18	EA	6	\$2,230	
	Stairs - Concrete	Stair C	15	LF	6	\$124	Steel
	Stairs - Terrazzo	Stair C	96	LF	6	\$891	
	Walls - Plaster/Drywall	Stair C	36	SF	4	\$529	Water damaged
	Walls - Plaster/Drywall	Stair C	13,672	SF	6	\$37,733	
	Walls - Structural Glazed Tile	Stair C	13,672	SF	6	\$43,012	
	Ceiling - Exposed	Stair D	119	SF	6	\$177	
	Ceiling - Plaster/Drywall	Stair D	1,044	SF	6	\$7,644	
	Ceiling - Plaster/Drywall	Stair D	40	SF	5	\$819	Cracks, peeling
	Floor - Concrete	Stair D	119	SF	6	\$63	
	Floor - Terrazzo	Stair D	1,005	SF	6	\$8,436	
	Handrails	Stair D	144	LF	6	\$1,248	
	Lighting - Pendent/Surface	Stair D	8	EA	6	\$991	
	Stairs - Concrete	Stair D	20	LF	6	\$166	
	Stairs - Terrazzo	Stair D	56	LF	6	\$520	
	Walls - Concrete Block	Stair D	566	SF	6	\$1,659	
	Walls - Plaster/Drywall	Stair D	60	SF	5	\$372	Cracks, peeling
	Walls - Plaster/Drywall	Stair D	6,840	SF	6	\$18,878	
	Walls - Plaster/Drywall	Stair D	92	SF	5	\$571	Water damaged
	Walls - Structural Glazed Tile	Stair D	6,900	SF	6	\$21,707	
	Ceiling - Plaster/Drywall	Stair G	192	SF	6	\$1,406	
	Floor - Tile/Sheet	Stair G	192	SF	6	\$104	
	Handrails	Stair G	112	LF	6	\$971	
	Lighting - Pendent/Surface	Stair G	6	EA	6	\$743	
	Stairs - Terrazzo	Stair G	56	LF	6	\$520	
	Walls - Plaster/Drywall	Stair G	884	SF	5	\$4,033	Cracking
	Walls - Plaster/Drywall	Stair G	736	SF	6	\$2,410	
	Ceiling - Plaster/Drywall	Stair H	1,370	SF	6	\$10,031	
	Ceiling - Plaster/Drywall	Stair H	20	SF	5	\$409	Cracks, peeling
	Floor - Terrazzo	Stair H	1,168	SF	6	\$9,804	
	Handrails	Stair H	117	LF	6	\$1,014	
	Lighting - Pendent/Surface	Stair H	10	EA	6	\$1,239	
	Stairs - Terrazzo	Stair H	70	LF	6	\$650	
	Walls - Plaster/Drywall	Stair H	20	SF	5	\$124	Cracks, peeling

**Building: Main**
**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Stairs</b>							
	Walls - Plaster/Drywall	Stair H	7,015	SF	6	\$19,361	
	Walls - Structural Glazed Tile	Stair H	7,035	SF	6	\$22,132	
	Ceiling - Plaster/Drywall	Stair I	192	SF	6	\$1,406	
	Floor - Tile/Sheet	Stair I	192	SF	6	\$104	
	Handrails	Stair I	112	LF	6	\$971	
	Lighting - Pendant/Surface	Stair I	6	EA	6	\$743	
	Stairs - Terrazzo	Stair I	56	LF	6	\$520	
	Walls - Plaster/Drywall	Stair I	1,486	SF	6	\$4,101	
	Walls - Plaster/Drywall	Stair I	134	SF	5	\$832	Water damaged peeling paint
	Ceiling - Plaster/Drywall	Stair J	1,360	SF	6	\$9,957	
	Floor - Terrazzo	Stair J	1,058	SF	6	\$8,881	
	Handrails	Stair J	251	LF	6	\$2,175	
	Lighting - Pendant/Surface	Stair J	13	EA	6	\$1,611	
	Stairs - Terrazzo	Stair J	106	LF	6	\$984	
	Walls - Plaster/Drywall	Stair J	280	SF	5	\$1,738	Cracking and peeling paint
	Walls - Plaster/Drywall	Stair J	7,880	SF	6	\$21,748	
	Ceiling - Plaster/Drywall	Stair M	1,413	SF	6	\$10,345	
	Floor - Concrete	Stair M	333	SF	6	\$176	
	Floor - Terrazzo	Stair M	1,058	SF	6	\$8,881	
	Handrails	Stair M	251	LF	6	\$2,175	
	Lighting - Pendant/Surface	Stair M	13	EA	6	\$1,611	
	Stairs - Concrete	Stair M	28	LF	6	\$232	
	Stairs - Terrazzo	Stair M	106	LF	6	\$984	
	Walls - Plaster/Drywall	Stair M	7,720	SF	6	\$21,306	
	Walls - Plaster/Drywall	Stair M	440	SF	5	\$2,731	Water damaged
	Ceiling - Plaster/Drywall	Stair N	128	SF	6	\$937	
	Ceiling - Plaster/Drywall	Stair NE Gym	64	SF	6	\$469	
	Floor - Tile/Sheet	Stair NE Gym	35	SF	6	\$19	
	Handrails	Stair NE Gym	28	LF	6	\$243	
	Lighting - Pendant/Surface	Stair NE Gym	1	EA	6	\$124	
	Stairs - Terrazzo	Stair NE Gym	14	LF	6	\$130	
	Walls - Plaster/Drywall	Stair NE Gym	1,088	SF	6	\$3,003	
	Ceiling - Plaster/Drywall	Stair NE Library	64	SF	6	\$469	
	Floor - Tile/Sheet	Stair NE Library	35	SF	6	\$19	
	Handrails	Stair NE Library	28	LF	6	\$243	
	Lighting - Pendant/Surface	Stair NE Library	2	EA	6	\$248	
	Stairs - Terrazzo	Stair NE Library	14	LF	6	\$130	



**Building: Main**
**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Stairs</b>							
	Walls - Plaster/Drywall	Stair NE Library	156	SF	6	\$431	
	Floor - Tile/Sheet	Stair N	128	SF	6	\$70	
	Handrails	Stair N	84	LF	6	\$728	
	Lighting - Pendent/Surface	Stair N	4	EA	6	\$496	
	Stairs - Terrazzo	Stair N	42	LF	6	\$390	
	Ceiling - Plaster/Drywall	Stair NW Library	64	SF	6	\$469	
	Floor - Tile/Sheet	Stair NW Library	35	SF	6	\$19	
	Handrails	Stair NW Library	28	LF	6	\$243	
	Lighting - Pendent/Surface	Stair NW Library	2	EA	6	\$248	
	Stairs - Terrazzo	Stair NW Library	14	LF	6	\$130	
	Walls - Plaster/Drywall	Stair NW Library	156	SF	6	\$431	
	Walls - Plaster/Drywall	Stair N	1,428	SF	6	\$3,941	
	Ceiling - Plaster/Drywall	Stair O	1,370	SF	6	\$10,031	
	Ceiling - Plaster/Drywall	Stair O	20	SF	5	\$409	Cracks, peeling
	Floor - Terrazzo	Stair O	1,168	SF	6	\$9,804	
	Handrails	Stair O	117	LF	6	\$1,014	
	Lighting - Pendent/Surface	Stair O	10	EA	6	\$1,239	
	Stairs - Terrazzo	Stair O	70	LF	6	\$650	
	Walls - Plaster/Drywall	Stair O	212	SF	5	\$1,316	Cracks, peeling
	Walls - Plaster/Drywall	Stair O	6,808	SF	6	\$18,789	
	Walls - Structural Glazed Tile	Stair O	7,035	SF	6	\$22,132	
	Ceiling - Plaster/Drywall	Stair SE Gym	64	SF	6	\$469	
	Floor - Tile/Sheet	Stair SE Gym	35	SF	6	\$19	
	Handrails	Stair SE Gym	28	LF	6	\$243	
	Lighting - Pendent/Surface	Stair SE Gym	1	EA	6	\$124	
	Stairs - Terrazzo	Stair SE Gym	14	LF	6	\$130	
	Walls - Plaster/Drywall	Stair SE Gym	1,088	SF	6	\$3,003	
	Ceiling - Plaster/Drywall	Stair Z	377	SF	6	\$2,760	
	Floor - Tile/Sheet	Stair Z	377	SF	6	\$205	
	Handrails	Stair Z	156	LF	6	\$1,352	
	Lighting - Pendent/Surface	Stair Z	12	EA	6	\$1,487	
	Stairs - Terrazzo	Stair Z	78	LF	6	\$724	
	Walls - Plaster/Drywall	Stair Z	10,556	SF	6	\$29,134	
	Walls - Structural Glazed Tile	Stair Z	10,556	SF	6	\$33,209	

**Vertical Conveyance**

Elevator - Elevator- Machine Roomless	1st Floor	3	EA	6	\$57,714
Elevator - Elevator- Roped Holeless Hydraulic	1st Floor	1	EA	6	\$19,238

**Building: Main**

**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Vertical Conveyance</b>							
	Wheelchair Lift - Chair Lift	1st Floor	1	EA	6	\$5,597	

**Building Interior Subtotal: \$3,302,036**

**Total Building Cost \$44,537,141**

**Building: Annex**

**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Exterior Doors - Exterior Steel Door	#1- Main- SE	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#2- SE	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#3- NW	1	EA	4	\$3,823	Rust & broken panes
	Exterior Doors - Exterior Steel Door	#4- NE	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#6- Main accessible- SE	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#7- SE	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#8- NW	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#9- NW	1	EA	6	\$481	
	Exterior Doors - Exterior Wood Door	#10- NW	1	EA	5	\$1,341	deterioration
	Exterior Doors - Overhead Rolling/ Garage Door	#5- NE	2	EA	6	\$2,867	
	Exterior Doors - Side lite	#9- NW	1	EA	6	\$313	Painted wood
	Exterior Doors - Transom Lite	#1- Main- SE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#2- SE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#4- NE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#6- Main accessible- SE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#7- SE	4	EA	6	\$1,253	
	Exterior Stairs - Concrete	#1- Main- SE	12	LF	6	\$981	
	Exterior Stairs - Concrete	#2- SE	14	LF	6	\$1,145	
	Exterior Stairs - Concrete	#4- NE	4	LF	6	\$327	
	Exterior Stairs - Concrete	#9- NW	3	LF	6	\$245	
	Exterior Stairs - Stone	#10- NW	3	LF	6	\$339	
	Exterior Stairs - Stone	#3- NW	3	LF	6	\$339	
	Exterior Stairs - Stone	#9- NW	3	LF	6	\$339	
	Exterior Stairs - Wood	#9- NW	3	LF	5	\$22	deterioration

**Foundation**

	Foundation - Concrete	Entire Building	633	LF	7	\$0	
--	-----------------------	-----------------	-----	----	---	-----	--

**Building: Annex**
**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Foundation</b>							
	Superstructure - Slab on Grade	Entire Building	6,771	SF	7	\$0	
<b>Lighting</b>							
	Exterior Lighting - Wall Mounted	Entire Building	24	EA	6	\$6,930	
<b>Roof System</b>							
	Chimney - Metal Flue	NE roof	20	LF	6	\$3,163	
	Coping - Metal	S roof	317	LF	6	\$10,181	
	Coping - Metal	Stand alone service garage - SW site	33	LF	6	\$1,060	
	Coping - Terra Cotta	NW roof	160	LF	6	\$5,139	
	Coping - Terra Cotta	Stand alone service garage - SW site	95	LF	6	\$3,051	
	Downspouts - Exterior Downspouts	NW roof / North Façade	18	LF	5	\$1,454	disconnected
	Downspouts - Exterior Downspouts	NW roof / North Façade	18	LF	6	\$598	
	Downspouts - Exterior Downspouts	S roof / East Façade	24	LF	4	\$3,251	disconnected and broken scupper boxes
	Downspouts - Exterior Downspouts	Stand alone service garage - SW site	30	LF	5	\$2,423	clogged
	Downspouts - Interior Downspouts	NE roof	16	LF	6	\$532	
	Parapet - 16" - 30" Height	NW roof	160	LF	6	\$6,393	
	Parapet - 16" - 30" Height	Stand alone service garage - SW site	95	LF	6	\$3,796	
	Parapet - Parapet < 16" Height	NE roof	93	LF	6	\$1,982	
	Roof Structure - Steel with Clay Tile Arch	NE roof	1,021	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	NW roof	1,322	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	S roof	4,428	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Stand alone service garage - SW site	1,066	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	NW roof	1,322	SF	4	\$37,053	severely blistered - not accessible - observed from a higher elevation
	Roof - Asphalt Gravel Ballast	S roof	4,428	SF	3	\$124,108	remove tree overhang, engineer reports active roof leaks - not observed; also roof was not accessible - observed from a higher elevation
	Roof - Asphalt Gravel Ballast	Stand alone service garage - SW site	1,066	SF	4	\$29,878	worn surface, vegetative growth - not accessible - observed from a higher elevation
	Roof - Modified Bitumen	NE roof	1,021	SF	5	\$21,477	remove tree overhang, worn surface and seams; not accessible - observed from a higher elevation
<b>Walls</b>							
	Canopy - Concrete/ Stucco	Entire Building / South West	50	SF	6	\$1,655	
	Exterior Walls - Brick	Entire Building	20	SF	4	\$3,293	open joints, gaps, step cracks
	Exterior Walls - Brick	Entire Building	6,496	SF	6	\$43,660	
	Exterior Walls - Brick	Entire Building / East Façade	20	SF	5	\$476	open joints
	Exterior Walls - Brick	Entire Building / North Façade	10	SF	5	\$238	step cracks
	Exterior Walls - Brick	Entire Building / West Façade	15	SF	4	\$2,470	vertical cracks

**Building: Annex**
**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Walls</b>							
	Exterior Walls - Stone-Cast	Entire Building	150	SF	6	\$1,008	
	Exterior Walls - Terra Cotta	Entire Building	100	SF	6	\$672	
	Exterior Walls - Terra Cotta	Entire Building / North Façade	2	SF	5	\$31	cracks
	Exterior Walls - Vinyl Siding	Entire Building	836	SF	6	\$2,678	
	Exterior Walls - Vinyl Siding	Entire Building	40	SF	5	\$220	buckled siding
	Exterior Walls - Wood Siding	Entire Building / South East	27	SF	4	\$564	deterioration
<b>Windows</b>							
	Curtain wall - Insulated Panel	Entire Building / North Façade	20	SF	5	\$749	hole in panel
	Curtain wall - Louver	Entire Building	120	SF	6	\$1,345	
	Lintels - Steel	Entire Building	102	LF	6	\$2,961	
	Lintels - Steel	Entire Building	24	LF	4	\$10,866	
	Windows - Casement Lexan	Entire Building	480	SF	6	\$3,583	
	Windows - Sash Aluminum Double-pane	Entire Building	140	SF	6	\$1,045	

**Building Exterior Subtotal:**
**\$359,374**
**Building: Annex**
**Category: Electrical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Emergency System</b>							
	Automatic Transfer Switch	Electrical Room	1	EA	4	\$8,200	
	Emergency A/C Power - Corridors and Stairs	Entire Building	385	SF	4	\$754	
	Exit Signs - Corridors and Stairs	Entire Building	3	EA	2	\$1,636	
<b>Main Service</b>							
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	
	Main Electrical Service - 800 A and 120/208/3PH	Electrical Room	1	EA	6	\$3,570	
<b>Power Distribution</b>							
	Lighting and Power Panels - 100 A	Drivers Ed. Building, 1st Floor, Electrical Room	2	EA	7	\$0	Drivers Ed Facility
	Lighting and Power Panels - 100 A	Drivers Ed. Building, 1st Floor, Electrical Room / 1st Floor	1	EA	7	\$0	
	Lighting and Power Panels - 100 A	Drivers Ed. Building, 1st Floor, Electrical Room / 1st Floor	1	EA	7	\$0	
	Lighting and Power Panels - 100 A	Drivers Ed. Building, 1st Floor, Electrical Room / 1st Floor	1	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Drivers Ed. Building, 1st Floor, Electrical Room / Electrical Room	1	EA	7	\$0	

**Building: Annex**
**Category: Electrical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Power Distribution</b>							

**Electrical System Subtotal: \$17,081**

**Building: Annex**
**Category: Safty System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Fire Alarm</b>							
	Fire Alarm Strobe Lights	1st Floor / Entire Building	6,771	SF	4	\$9,198	
	Fire Alarm_System	1st Floor / Entire Building	6,771	SF	4	\$13,459	

**Safty System Subtotal: \$22,657**

**Building: Annex**
**Category: Mechanical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Heating Devices</b>							
	Unit Heater - Electric	1st Floor	1	EA	6	\$278	Bryant Wall Mounted Heater M#: 53122 2,000 watts (No Other Information Available)
	Unit Heater - Gas	1st Floor	1	EA	6	\$278	Sterling Gas Fired Heater (Looks Relatively New) (No Other Information Available)
	Unit Heater - Gas	1st Floor	1	EA	6	\$278	Unit Heater (No Other Information Available)
	Wall Heater - Electric	Entire Building	1	EA	6	\$139	
	Wall Heater - Electric	Entire Building	2	EA	4	\$2,165	
	Wall Heater - Electric	Entire Building	5	EA	5	\$2,683	

**Temperature Control**

	Electric Thermostat	1st Floor	6	EA	4	\$0	
--	---------------------	-----------	---	----	---	-----	--

**Unit Ventilation**

	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	6	EA	5	\$59,285	
--	--	-----------------	---	----	---	----------	--

**Ventilation**

	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	3	EA	6	\$889	

**Mechanical System Subtotal: \$66,586**

**Building: Annex**
**Category: Plumbing System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Hot Water</b>							
	Electric Heater - 20 - 50 KW	1st Floor Janitors Closet	1	EA	6	\$682	Location: 1sr Floor Janitors Closet
<b>Piping</b>							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	6,771	SF	6	\$1,356	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	6,771	SF	6	\$1,646	
	Domestic Piping-Cold Water Risers	Entire Building	6,771	SF	6	\$1,259	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	6,771	SF	6	\$1,065	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	6,771	SF	6	\$1,259	
	Domestic Piping-Hot Water Return Lines	Entire Building	6,771	SF	6	\$968	
	Domestic Piping-Hot Water Return Risers	Entire Building	6,771	SF	6	\$968	
	Sanitary Piping	Entire Building	6,771	SF	6	\$6,197	
	Storm Piping	Entire Building	6,771	SF	6	\$5,906	
	Vent Piping	Entire Building	6,771	SF	6	\$4,551	
<b>Plumbing System Subtotal:</b>						<b>\$25,857</b>	

**Building: Annex**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #x1- classroom (Regular Classroom)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Ceiling - Lay-in	1st Floor	40	SF	5	\$319	water damaged tiles
	Ceiling - Lay-in	1st Floor	1,410	SF	6	\$4,234	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	1,410	SF	6	\$3,085	
	Lighting - Lay-in	1st Floor	24	EA	7	\$0	
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls	1st Floor	1,209		6	\$0	
<b>Classroom #x2- simulator (Regular Classroom)</b>							
	AC Units	1st Floor	2	EA	6	\$991	
	Ceiling - Lay-in	1st Floor	8	SF	5	\$64	Damaged ceiling tiles
	Ceiling - Lay-in	1st Floor	1,402	SF	6	\$4,210	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	80	SF	5	\$461	Damaged/ missing floor tiles
	Floor - Tile	1st Floor	1,330	SF	6	\$2,910	
	Lighting - Lay-in	1st Floor	24	EA	6	\$2,855	
	Walls - Concrete Block	1st Floor	10	SF	5	\$141	Cracking SE wall

**Building: Annex**
**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #x2- simulator (Regular Classroom)</b>							
	Walls - Concrete Block	1st Floor	1,262	SF	6	\$3,700	

**Classrooms Subtotal:**
**\$24,563**
**Building: Annex**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Ceiling - Lay-in	Resource Center Office	126	SF	6	\$378	
	Doors - Wood Doors inclu hw	Resource Center Office	1	EA	6	\$301	
	Floor - Tile	Resource Center Office	126	SF	6	\$276	
	Lighting - Lay-in	Resource Center Office	5	EA	7	\$0	
	Power Distribution	Resource Center Office	6	EA	6	\$12,749	
	Walls - Concrete Block	Resource Center Office	9	SF	5	\$127	Cracking at NE wall
	Walls - Concrete Block	Resource Center Office	356	SF	6	\$1,044	
	Ceiling - Exposed	west of annex - separate building with Driver ed teacher offices	596	SF	6	\$886	wood plank
	Doors - Steel Doors incl hw	west of annex - separate building with Driver ed teacher offices	2	EA	6	\$602	
	Floor - Concrete	west of annex - separate building with Driver ed teacher offices	596	SF	6	\$315	
	Lighting - Pendent/Surface	west of annex - separate building with Driver ed teacher offices	5	EA	7	\$0	
	Power Distribution	west of annex - separate building with Driver ed teacher offices	10	EA	6	\$21,249	
	Walls	west of annex - separate building with Driver ed teacher offices	894		6	\$0	wood plank
	Walls - Masonry	west of annex - separate building with Driver ed teacher offices	730	SF	6	\$2,297	

**Mechanical/ Service Rooms**

	Janitor's Closet	1st Floor	41	SF	6	\$294	light fixture uncovered and hanging from electrical wiring
	Storage Room	1st Floor	121	SF	6	\$867	
	Vaults	1st Floor	91	SF	6	\$652	

**Restroom**

	Accessories	1st Floor	45	SF	6	\$415	
	Accessories	1st Floor	86	SF	6	\$793	
	Accessories	1st Floor	86	SF	6	\$793	

**Building: Annex**
**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Ceiling - Plaster/Drywall	1st Floor	45	SF	6	\$156	
	Ceiling - Plaster/Drywall	1st Floor	86	SF	6	\$298	
	Ceiling - Plaster/Drywall	1st Floor	86	SF	6	\$298	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor	43	SF	6	\$91	
	Floor - Tile Ceramic/ Porcelain	1st Floor	79	SF	6	\$167	
	Floor - Tile Ceramic/ Porcelain	1st Floor	2	SF	5	\$42	tiles and toilet are cracked / stained
	Floor - Tile Ceramic/ Porcelain	1st Floor	82	SF	6	\$174	
	Floor - Tile Ceramic/ Porcelain	1st Floor	7	SF	5	\$146	tiles missing / falling out
	Floor - Tile Ceramic/ Porcelain	1st Floor	4	SF	5	\$84	tiles missing / falling out
	Lavatory	1st Floor	1	EA	6	\$320	
	Lavatory	1st Floor	2	EA	6	\$639	
	Lavatory	1st Floor	1	EA	6	\$320	
	Lighting	1st Floor	2		7	\$0	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	\$124	no cover
	Partitions	1st Floor	1	EA	6	\$297	
	Urinals	1st Floor	2	EA	6	\$672	
	Walls - Concrete Block	1st Floor	214	SF	6	\$627	
	Walls - Concrete Block	1st Floor	346	SF	6	\$1,014	
	Walls - Concrete Block	1st Floor	346	SF	6	\$1,014	
	Walls - Tile Ceramic/ Porcelain	1st Floor	8	SF	6	\$18	base tiles missing
	Walls - Tile Ceramic/ Porcelain	1st Floor	14	SF	6	\$32	
	Walls - Tile Ceramic/ Porcelain	1st Floor	14	SF	6	\$32	some wall tiles missing
	Water Closet	1st Floor	2	EA	6	\$672	
	Water Closet	1st Floor	1	EA	6	\$336	
	Water Closet	1st Floor	1	EA	6	\$336	

**Rooms (Other Than Classrooms) Subtotal:**
**\$54,966**
**Building: Annex**
**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------



## Building: Annex

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Ceiling - Lay-in	1st Floor	385	SF	6	\$1,156	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	6	\$276	
	Floor - Tile/Sheet	1st Floor	385	SF	6	\$209	
	Lighting - Lay-in	1st Floor	9	EA	7	\$0	
	Student Lockers - One Tier	1st Floor	24	EA	6	\$2,228	
	Walls - Concrete Block	1st Floor	1,169	SF	6	\$3,427	
<b>Safety</b>							
	Camera Viewing Station	Entire Building / 1st Floor	1	EA	6	\$683	Location: Main Bldg. Rm 127
	Security Cameras	Entire Building	3	EA	6	\$582	Location: Exterior

**Building Interior Subtotal: \$8,561**

**Total Building Cost \$579,645**

## SITE

### Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Civil/Drainage</b>							
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	5	\$2,570	Location: drivers education parking lot Clogged
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	\$4,120	Location: Dock area - Damaged
	Civil/ Drainage - Catch Basin	Entire Site	16	EA	6	\$17,501	
	Civil/ Drainage - Site Drain	Entire Site / Courtyard	1	EA	6	\$310	
	Civil/ Drainage - Site Manhole	Entire Site	36	EA	6	\$53,739	
<b>Fencing</b>							
	Fencing - Chain Link	Entire Site	1,713	LF	6	\$32,163	
	Fencing - New Standard Ornamental	Entire Site	822	LF	6	\$26,225	
<b>Landscape</b>							
	Benches	Entire Site	47	EA	6	\$20,212	
	Irrigation	Entire Site	378,385	SF	4	\$1,704,435	broken supply piping
	Landscape - Grass	Entire Site	346,094	SF	6	\$287,050	
	Landscape - Hardscape- Asphalt	Entire Site / Site West	2,237	SF	6	\$5,406	
	Landscape - Hardscape- Asphalt	Entire Site / South West	3,618	SF	4	\$28,559	deterioration
	Landscape - Hardscape- Concrete	Entire Site	2,852	SF	6	\$14,723	Location: SE exterior eating area
	Landscape - Hardscape- Concrete	Entire Site / Site West	1,824	SF	6	\$11,085	
	Landscape - Hardscape- Pavers	Entire Site / Courtyard	10,681	SF	6	\$60,484	

**SITE**
**Category: Site**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Landscape</b>							
	Parkway trees	Entire Site	31	EA	6	\$20,461	
	Planting Beds/ Area	Entire Site	32,291	SF	6	\$53,103	
	Retaining Wall - Concrete	Entire Site	2,020	SF	6	\$47,344	
	Retaining Wall - Masonry	Entire Site / Courtyard	424	SF	6	\$6,191	
	Trash Receptacles	Entire Site	32	EA	6	\$9,994	
<b>Parking Lot</b>							
	Lighting - Pole Mounted	SW - parking lot	18	EA	6	\$26,145	
	Surface - Asphalt	SE parking lot	14,213	SF	6	\$44,714	Location: W driveway
	Surface - Asphalt	SE parking lot	156,501	SF	5	\$713,911	potholes and cracks
	Surface - Asphalt	SW - parking lot	30,735	SF	5	\$140,204	cracks
	Surface - Concrete	SE parking lot	11,160	SF	5	\$104,371	Location: S Drive - pitting, cracks
	Surface - Concrete	SE parking lot	200	SF	4	\$4,259	Location: Center of S drive
	Trash Compactor	SE parking lot / Site South	1	EA	6	\$0	
	Trash Enclosure - Chain Links	SE parking lot / Site West	1,307	SF	6	\$22,933	
	Vehicular Screening	SE parking lot	620	LF	6	\$48,816	
<b>Service Garage</b>							
	Service Garage - Built-in	South / South West	5	SF	6	\$46	
	Service Garage - Free-Standing	South / Site South	1	SF	6	\$9	
<b>Sidewalks</b>							
	Sidewalks - Internal Walks	Entire Site	426	LF	4	\$41,400	SE & SW courtyard - deterioration
	Sidewalks - Internal Walks	Entire Site	25	LF	5	\$1,444	Location: Auditorium walkway - cracks, spalling
	Sidewalks - Internal Walks	Entire Site	20	LF	4	\$1,944	Location: S elevation of boiler room
	Sidewalks - Internal Walks	Entire Site	20	LF	4	\$1,944	Location: Door A - movement
	Sidewalks - Internal Walks	Entire Site	3,567	LF	6	\$42,847	
	Sidewalks - Internal Walks	Entire Site / Site - East	563	LF	5	\$28,057	asphalt - cracks
	Sidewalks - Perimeter Sidewalks	Entire Site	24,575	SF	6	\$48,848	
	Sidewalks - Perimeter Sidewalks	Entire Site / North East	20	SF	4	\$322	movement
	Sidewalks - Perimeter Sidewalks	Entire Site / Site North	800	SF	5	\$7,642	cracks, movement, pitting
	Sidewalks - Perimeter Sidewalks	Entire Site / South East	200	SF	5	\$1,910	pitting
<b>Signage</b>							
	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	6	\$828	Location: Entrance C
	Flag Pole - Flag Pole	Entire Site / Courtyard	1	EA	6	\$1,657	
	Marquee - Free Standing Back lighted w/ LED	Entire Site / North East	1	EA	6	\$0	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	\$0	Location: Entrance C
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	\$0	Location: SE Annex

## SITE

### Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	Signage						
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	\$0	Location: Entrance O

### Site Subtotal:

**\$3,689,925**

### Total Site Cost

**\$3,689,925**

## Campus Total <sup>2 3</sup>

**\$48,806,711**

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

<sup>2</sup> As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

<sup>3</sup> The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

## Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- **Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- **For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- **Campus Total** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Main</b>														
Art Room	Laboratory/Shop	1st Floor	150 (South)	152/154	3,170	3	38	86	668	223	40	N	N	N
Art Room	Art Room	2nd Floor	220	220	1,143	1	3	50	378	126	40	N	Y	N
Art Room	Art Room	4th Floor	443	443	1,089	1	2	20	300	96	40	N	Y	N
Art Room	Art Room	4th Floor	445	445	1,188	1	2	72	84	21	40	N	Y	N
Art Room	Art Room	4th Floor	447	447	1,089	1	2	22	300	96	40	N	Y	N
Band Room	Music Room	4th Floor	400	400	3,060	1	1	18	90	9	40	N	Y	N
Band Room	Band Room	4th Floor	444	444	3,570	4	4	20	497	200	40	N	Y	N
Choral Room	Music Room	4th Floor	402	402	1,470	1	2	10	297	127	40	N	Y	N
Computer Lab	Regular Classroom	1st Floor	114	114	770	1	34	88	210	70	49	N	Y	N
Computer Lab	Computer Lab	1st Floor	132	132	1,387	2	33	72	160	53	40	N	N	N
Computer Lab	Laboratory/Shop	2nd Floor	232	232	1,356	1	2	66	370	122	40	N	Y	Y
Computer Lab	Computer Lab	2nd Floor	235	235	1,347	1	34	86	370	122	40	N	Y	Y
Computer Lab	Laboratory/Shop	2nd Floor	255	255	1,017	2	2	90	259	85	40	N	Y	Y
Computer Lab	Computer Lab	3rd Floor	335	335	1,470	2	32	88	350	110	40	Y	Y	N
Computer Lab	Computer Lab	3rd Floor	337	337	910	1	18	40	210	60	40	N	Y	N
Computer Lab	Regular Classroom	3rd Floor	341	341	840	1	35	64	210	66	40	Y	N	Y
Language Lab	Language Lab	3rd Floor	330	330	1,350	1	3	12	315	99	40	Y	N	N
Multi Purpose Room	Multi Purpose Room	1st Floor	135	135	3,259	0	1	42	387	128	40	N	Y	Y
Multi Purpose Room	Laboratory/Shop	1st Floor	140	140	1,451	0	2	10	480	158	40	N	Y	N
Multi Purpose Room	Multi Purpose Room	1st Floor	143	143	1,471	1	2	22	480	158	40	N	Y	N
Multi Purpose Room	Laboratory/Shop	1st Floor	144	144	1,392	2	2	17	240	79	40	N	N	N
Multi Purpose Room	Laboratory/Shop	1st Floor	146	146	1,575	1	1	26	240	80	40	N	N	N
Multi Purpose Room	Multi Purpose Room	1st Floor	147	147	1,493	0	2	10	270	89	40	N	N	N
Multi Purpose Room	Laboratory/Shop	1st Floor	148	158	2,162	1	2	23	480	158	40	N	Y	Y
Multi Purpose Room	Multi Purpose Room	1st Floor	149	149	1,454	1	2	16	252	83	40	N	Y	N
Multi Purpose Room	Multi Purpose Room	1st Floor	150 (North)	150	3,170	0	38	86	571	188	40	N	N	N
Multi Purpose Room	Multi Purpose Room	1st Floor	153	153	1,407	1	0	12	360	119	40	N	Y	N
Multi Purpose Room	Regular Classroom	2nd Floor	inside 252	-	139	0	0	2	74	24	40	N	N	N
Music Room	Music Room	4th Floor	400E	400E	360	0	0	24	22	11	40	N	Y	N
Music Room	Music Room	4th Floor	400W	400W	360	0	0	24	22	11	40	N	Y	N
Music Room	Music Room	4th Floor	403	403	775	1	2	10	162	69	40	N	Y	N
Office	Science	4th Floor	430/431 Office		196	0	0	8	80	40	40	N	Y	N
Office	Science	4th Floor	434/438 Office		196	0	0	8	80	40	40	N	Y	N
Office	Science	4th Floor	435/439 Office		196			8	80	40	40	N	Y	N
Other Instructional Use	Regular Classroom	2nd Floor	202- Drama	202	1,324	1	2	20	336	112	40	N	Y	N
Physical Education Room	Regular Classroom	1st Floor	133	133	2,571	1	2	16	350	117	40	N	N	N
Physical Education Room		1st Floor	162	ROTC	993	0	0	2	88	29		N	N	N

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Main</b>														
Regular Classroom	Office	1st Floor	104	104	997	2	2	24	245	82	40	N	Y	N
Regular Classroom	Office	1st Floor	106	106	722	3	1	16	210	70	40	N	N	N
Regular Classroom	Regular Classroom	1st Floor	107E	107	720	1	2	14	210	70	40	N	Y	N
Regular Classroom	Office	1st Floor	110	110	735	2	3	16	210	63	40	N	N	N
Regular Classroom	Regular Classroom	1st Floor	111	111	714	1	3	12	210	70	40	N	Y	Y
Regular Classroom	Regular Classroom	1st Floor	112	112	1,104	1	2	10	248	124	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	120	120	970	1	2	14	280	93	40	N	Y	Y
Regular Classroom	Special Program	1st Floor	122	122	913	1	2	16	105	35	40	N	Y	N
Regular Classroom	Laboratory/Shop	1st Floor	136	136A	757	1	3	20	118	39	40	N	N	N
Regular Classroom	Regular Classroom	1st Floor	141	141	689	0	2	14	225	74	40	N	N	N
Regular Classroom	Regular Classroom	1st Floor	145	145	1,352	0	2	26	405	134	40	N	Y	N
Regular Classroom	Laboratory/Shop	1st Floor	155	155	1,580	0	0	20	642	212	40	N	Y	N
Regular Classroom	Regular Classroom	1st Floor	161	161	2,361	0	2	34	497	164	40	N	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	730	1	3	8	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210/206	1,460	1	3	50	504	168	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	730	1	3	12	210	66	40	Y	N	N
Regular Classroom		2nd Floor	214	214	957	1	2	34	336	112		N	N	Y
Regular Classroom	Regular Classroom	2nd Floor	217	217	680	1	3	37	210	70	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	1,110	2	4	18	234	78	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	222	222	730	1	3	12	252	84	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	224	224	975	1	3	12	294	98	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	975	1	3	12	240	80	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	228	228	975	1	3	12	240	80	40	N	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	229	229	975	1	3	12	182	60	40	N	Y	Y
Regular Classroom	Laboratory/Shop	2nd Floor	230	230	1,157	1	34	80	333	110	40	N	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	231	231	975	1	3	12	182	60	40	N	Y	Y
Regular Classroom	Regular Classroom		233	233	975	1	3	12	240	80	40	N	Y	Y
Regular Classroom	Laboratory/Shop	2nd Floor	234	234	1,124	1	1	41	296	98	40	N	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	236	236	1,054	1	2	20	296	98	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	238	238	928	1	3	25	259	85	40	N	N	N
Regular Classroom	Laboratory/Shop	2nd Floor	239	239	1,455	2	36	80	360	119	40	N	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	240	240	818	1	2	12	222	73	40	N	N	Y
Regular Classroom	Regular Classroom	2nd Floor	242	242	794	1	2	12	222	73	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	244	244	818	1	2	12	222	74	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	246	246	696	1	2	14	185	61	40	N	N	N
Regular Classroom	Laboratory/Shop	2nd Floor	249	247	1,347	1	1	87	333	110	40	N	Y	N
Regular Classroom	Regular Classroom	2nd Floor	250	258	1,046	1	2	12	444	147	40	N	N	N

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Main</b>														
Regular Classroom	Regular Classroom	2nd Floor	251	259	807	2	2	7	370	122	40	N	Y	Y
Regular Classroom	Laboratory/Shop	2nd Floor	252	256	984	1	3	16	185	61	40	N	N	Y
Regular Classroom	Regular Classroom	2nd Floor	253	257	810	2	2	12	259	85	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	254	254	1,002	1	3	9	259	85	40	N	N	Y
Regular Classroom	Regular Classroom	2nd Floor	256	248	1,008	1	3	13	259	85	40	N	N	N
Regular Classroom	Laboratory/Shop	2nd Floor	257	249	1,440	2	2	65	259	85	40	N	Y	N
Regular Classroom	Laboratory/Shop	2nd Floor	258	252	1,100	1	3	12	296	98	40	N	N	N
Regular Classroom	Laboratory/Shop	2nd Floor	259	253	1,102	2	2	69	296	98	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	260	250	1,106	1	2	13	296	98	40	N	N	Y
Regular Classroom	Regular Classroom	2nd Floor	261	251	1,102	2	2	64	296	98	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	830	1	3	12	210	66	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	830	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	970	1	3	12	245	77	40	N	Y	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	910	1	3	12	245	77	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	306	306	730	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	725	1	3	12	210	66	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	828	1	3	12	210	66	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	309	309	828	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	720	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	725	1	3	12	210	66	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	312	312	828	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	313	313	828	1	3	11	210	66	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	750	1	3	12	210	66	40	Y	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	315	315	744	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	316	316	840	1	3	12	245	77	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	317	317	840	1	3	12	210	66	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	318	318	730	1	3	12	210	66	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	319	319	744	1	3	12	210	66	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	320	320	750	1	3	12	210	66	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	321	321	840	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	322	322	775	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	323	323	744	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	324	324	975	1	3	12	245	66	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	325	325	840	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	326	326	975	1	3	12	280	88	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	327	327	840	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	975	1	3	12	280	88	40	Y	N	Y

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Main</b>														
Regular Classroom	Regular Classroom	3rd Floor	329	329	975	1	3	12	245	77	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	331	331	975	1	3	12	280	88	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	333	333	975	1	3	12	280	88	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	334	334	730	1	3	12	175	55	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	336	339	730	1	3	12	175	55	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	338	342	700	1	4	12	175	55	40	Y	Y	N
Regular Classroom	Regular Classroom	3rd Floor	339	339	1,050	1	3	36	245	77	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	340	339	700	1	4	12	175	55	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	343	343	694	1	3	12	175	55	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	344	342	800	1	3	12	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	345	345	852	1	3	8	210	66	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	347	347	697	1	3	12	175	55	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	349	349	828	1	3	12	210	66	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	351	351	694	1	3	12	175	55	40	Y	N	Y
Regular Classroom	Regular Classroom	3rd Floor	353	359	820	2	3	8	350	110	40	Y	N	N
Regular Classroom	Regular Classroom	3rd Floor	358	352	1,400	2	3	12	210	66	40	Y	N	Y
Regular Classroom	Regular Classroom	4th Floor	427	429	750		3	12	228	76	40	N	Y	Y
Regular Classroom	Regular Classroom	4th Floor	428		744		2	8	228	76	40	N	Y	Y
Regular Classroom	Regular Classroom	4th Floor	429	433	705	0	2	8	228	76	40	N	Y	Y
Regular Classroom	Regular Classroom	4th Floor	432	432	723	1	2	10	162	69	40	N	Y	N
Regular Classroom	Regular Classroom	4th Floor	433	437	735	1	3	14	228	76	40	N	N	Y
Regular Classroom	Regular Classroom	4th Floor	436	436	560	2	2	8	162	69	40	N	Y	N
Regular Classroom	Regular Classroom	4th Floor	437	437	700			2	190	63	40	N	N	N
Regular Classroom	Regular Classroom	4th Floor	440	440	624	1	3	12	162	69	40	N	Y	N
Regular Classroom	Regular Classroom	4th Floor	441	441	864	1	2	12	300	96	40	N	Y	Y
Science	Science	1st Floor	115	115	1,053	1	19	76	280	93	40	N	N	N
Science	Science	1st Floor	119	119	941	1	2	36	245	82	40	N	N	N
Science	Science	1st Floor	123	123	1,016	1	2	36	240	120	40	N	N	N
Science	Science	1st Floor	125	125	950	1	2	66	245	74	40	N	N	N
Science	Regular Classroom	3rd Floor	360	350	1,080	1	3	60	280	88	40	Y	N	N
Science Classroom	Science Classroom	1st Floor	117	117	588	2	2	10	140	47	40	N	Y	N
Science Classroom	Science Lab Level 3	2nd Floor	215	215	930	1	3	50	336	112	40	N	Y	N
Science Classroom	Science Classroom	2nd Floor	219	219	975	1	3	30	294	98	40	N	Y	N
Science Classroom	Science Lab Level 3	2nd Floor	223	223	1,012	1	3	50	240	80	40	N	Y	N
Science Classroom	Science Classroom	2nd Floor	225	225	975	1	3	30	294	98	40	N	Y	N
Science Classroom	Science Classroom	2nd Floor	241	241	1,065	1	1	38	333	110	40	N	N	N
Science Classroom	Science Classroom	2nd Floor	243	243	694	2	3	20	259	85	40	N	Y	N

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Main</b>														
Science Classroom	Laboratory/Shop	2nd Floor	245	245	1,342	2	2	12	333	110	40	N	Y	N
Science Classroom	Science Classroom	3rd Floor	332	332	730	1	3	12	175	55	40	Y	N	N
Science Classroom	Science Classroom	3rd Floor	342	340	975	1	3	12	210	66	40	Y	N	N
Science Classroom	Science Classroom	3rd Floor	346	344	1,080	1	3	50	245	77	40	Y	N	N
Science Classroom	Science Classroom	3rd Floor	350	348	1,050	1	3	34	245	77	40	Y	N	N
Science Classroom	Science Lab Level 3	3rd Floor	354	354	1,005	1	3	12	245	77	40	Y	N	N
Science Classroom	Regular Classroom	3rd Floor	356	358	1,080	1	3	12	245	77	40	Y	Y	N
Science Lab Level 1	Science Lab Level 1	4th Floor	430	430	1,056	1	2	48	180	81	40	N	Y	N
Science Lab Level 1	Science Lab Level 1	4th Floor	431	431	924	2	2	78	180	81	40	N	Y	N
Science Lab Level 1	Science Lab Level 1	4th Floor	434	434	1,056	6	6	48	189	69	40	N	Y	N
Science Lab Level 1	Science Lab Level 1	4th Floor	435	435	1,068	1	2	48	180	81	40	N	Y	N
Science Lab Level 1	Science Lab Level 1	4th Floor	438	438	1,008	1	2	48	162	58	40	N	Y	N
Science Lab Level 1	Science Lab Level 1	4th Floor	439	439	1,068	1	2	52	180	81	40	N	Y	Y
Special Education	Special Education	1st Floor	151	151	1,693	1	1	16	360	119	40	N	Y	Y
Special Education	Special Education	1st Floor	157	157	1,539	1	1	8	210	69	40	N	Y	N
Special Education	Special Education	1st Floor	157A	157A	873	0	0	32	200	66	40	N	Y	N
Special Program	Special Program	1st Floor	124	124	2,800	0	1	94	490	163	40	N	Y	Y
Special Program	Special Program		128 Aquaponics	128	2,749	2	11	62	350	117	40	N	Y	N
Special Program	Special Program	1st Floor	129	129	2,614	1	2	66	429	166	40	N	Y	Y
Special Program	Special Program	1st Floor	137	137	1,575	2	14	56	252	83	40	N	Y	N
Special Program	Special Program	1st Floor	139	139	1,469	0	1	164	270	89	40	N	Y	N
Special Program	Special Program	4th Floor	445A	445	648			24			40	N	Y	N
Store Room	Regular Classroom	4th Floor	442A	442	864	2	2	10	300	96	40	N	N	N
Store Room	Store Room	4th Floor	448	448	930	10	2	2			40	N	Y	N
Weight	Laboratory/Shop	1st Floor	138	138	2,468	2	2	16	210	69	40	N	N	N
Weight		1st Floor	160		2,173	1	0	2	132	44		N	N	N

<b>Annex</b>														
Regular Classroom	Regular Classroom	1st Floor	x1- classroom		1,410	2	13	28	169	33	40	N	Y	N
Regular Classroom	Other Instructional Use	1st Floor	x2- simulator		1,410	1	50	110	169	33	40	N	Y	N