9928 S Crandon Ave Chicago, IL 60617

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1945	2	25,233	\$1,490,675
Addition 1	1948	2	11,526	\$725,758
Addition 2	1950	2	16,169	\$1,025,537
Addition 3	1951	2	29,228	\$1,796,890
Branch	1954	1	15,103	\$1,434,013
SITE				\$811,365
Campus Total			97,259	\$7,284,237

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance	9						
	Entrance Control - Audio and Video	#1 - Main - NE	1	EA	6	\$702	
	Exterior Doors - Exterior Steel Door	#1 - Main - NE	2	EA	5	\$2,683	Repair latch and mullions
	Exterior Doors - Exterior Steel Door	#2 - SE	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#4.2 - Basement Mechanical - W	1	EA	6	\$481	
	Exterior Doors - Transom Lite	#1 - Main - NE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#2 - SE	1	EA	6	\$313	
	Exterior Stairs - Concrete	#1 - Main - NE	84	LF	6	\$6,868	
	Exterior Stairs - Concrete	#2 - SE	60	LF	6	\$4,906	
	Exterior Stairs - Concrete	#4.2 - Basement Mechanical - W	50	LF	5	\$5,479	Spalling
	Exterior Stairs - Stone	#2 - SE	6	LF	6	\$678	
	Power Door Operator and Controls	#1 - Main - NE	1	EA	6	\$0	
	Stair Handrail - Steel_Stair Handrail	#1 - Main - NE	40	LF	6	\$347	
	Stair Handrail - Steel_Stair Handrail	#2 - SE	5	LF	6	\$43	
	Stair Handrail - Steel_Stair Handrail	#4.2 - Basement Mechanical - W	60	LF	6	\$520	



9928 S Crandon Ave Chicago, IL 60617

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Founda	tion						
	Foundation - Concrete	Entire Building	400	LF	7	\$0	
	Superstructure - Concrete	Entire Building	25,233	SF	7	\$0	
Lighting	9						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	6	\$537	
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	\$1,732	
Roof Sy	vstem						
	Coping - Stone	Entire Building	400	LF	6	\$12,847	
	Downspouts - Interior Downspouts	Entire Building	70	LF	6	\$2,326	
	Parapet - 16" - 30" Height	Entire Building	63	LF	6	\$2,517	
	Parapet - Parapet < 16" Height	Entire Building	277	LF	6	\$5,902	
	Parapet - Parapet > 30"	Entire Building	60	LF	6	\$3,835	
	Roof Structure - Steel with Clay Tile Arch	Entire Building	8,460	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Entire Building	8,460	SF	6	\$86,015	
Walls							
	Cheek-Wall - Concrete	Entire Building	5	SF	6	\$51	
	Cheek-Wall - Concrete	Entire Building	5	SF	6	\$51	
	Cheek-Wall - Stone	Entire Building	64	SF	6	\$656	
	Exterior Walls - Brick	Entire Building	585	SF	6	\$3,932	
	Exterior Walls - Brick	Entire Building	15	SF	4	\$2,470	Spalling at basement door
	Exterior Walls - Stone-Cast	Entire Building	240	SF	6	\$1,613	
Window	/s						
	Curtain wall - Insulated Panel	Entire Building	803	SF	6	\$9,003	
	Lintels - Steel	Entire Building	128	LF	7	\$0	
	Lintels - Stone	Entire Building	128	LF	6	\$0	
	Windows - Sash Lexan	Entire Building	1,533	SF	5	\$45,006	Poor latches and balances
D	ng Exterior Subtotal:					\$202 788	

Building Exterior Subtotal:

\$202,788

Building: Main

Category: Electrical System

	• •					
Group	ltem - Type	Location	Quantity	Unit	Rank	Cost Comments
Emer	gency System					
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,762	SF	6	\$1,130
	Emergency Battery Packs - Corridors and Stairs	Entire Building	5	EA	6	\$1,013
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	6	\$898



9928 S Crandon Ave Chicago, IL 60617

Building: Main

Category: Electrical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency System						
Security System - CCTV	Entire Building	25,233	SF	6	\$7,577	Serves all additions
Security System - Intrusion Detection	Entire Building	25,233	SF	6	\$6,495	Serves all additions
Main Service						
PA System	Entire Building	25,233	SF	5	\$17,320	
Power Distribution						
Lighting and Power Panels - Above 100 A	Entire Building / Boiler Room	1	EA	6	\$497	
Main Distribution Panels - 400 - 600 amp	Entire Building / Boiler Room	1	EΑ	4	\$13,694	Fused panel
Main Distribution Panels - 400 - 600 amp	Entire Building / Boiler Room	1	EΑ	6	\$528	
Main Distribution Panels - Greater than 600 amp	Entire Building / Boiler Room	1	EA	6	\$730	
Electrical System Subtotal:					\$49,882	

Building: Main

Category: Safty System

up Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Alarm						
Fire Alarm Panel	MDF Room 1st Floor / 1st Floor	1	EA	6	\$6,406	In MDF room. Also serves all additions
Fire Alarm Strobe Lights	MDF Room 1st Floor / Entire Building	25,233	SF	6	\$9,021	
Fire Alarm_System	MDF Room 1st Floor / Entire Building	25,233	SF	6	\$12,268	

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000	Entire Building / Mechanical Room	1	EA	5	\$66,438	Serves main and part of NE addition
	Air Intake	Entire Building / Roof	1	EA	5	\$7,471	
	Auxiliaries - 15001 - 25000 cfm	Entire Building / Mechanical Room	1	EA	5	\$14,899	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Entire Building	100	LF	5	\$131,341	
	Zone Dampers	Entire Building / Electrical Room	15	EA	6	\$12,495	
Boiler S	Systems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Entire Building / Boiler Room	2	EA	4	\$32,880	
	Chemical Feed System	Entire Building / Boiler Room	1	EA	4	\$6,987	



9928 S Crandon Ave Chicago, IL 60617

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler S	systems						
	Chemical Feeder	Entire Building / Boiler Room	1	EA	4	\$6,987	
	Combustion Dampers	Entire Building / Boiler Room	1	EA	4	\$6,553	
	Condensate Pump	Entire Building / Boiler Room	2	EA	5	\$36,392	One in each AHU room
	Feed Water Pumps and Tank	Entire Building / Boiler Room	1	EA	4	\$92,964	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Entire Building / Boiler Room	2	EA	4	\$106,661	Serves all additions
	Piping - Condensate Pipe- Steel	Entire Building	300	LF	4	\$54,359	Serves all additions
	Piping - Steam Pipe- Steel	Entire Building	300	LF	4	\$86,010	Serves all additions
	Steam Traps	Entire Building	24	EA	5	\$31,558	Serves all additions
Heating	Devices						
	Radiators - Steam	Entire Building / 1st Floor	4	EA	5	\$6,701	Main office
	Wall Heater - Electric	Entire Building	4	EA	5	\$2,146	

Mechanical System Subtotal:

\$702,843

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	25,233	SF	4	\$18,042	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	25,233	SF	4	\$36,444	
	Domestic Piping-Cold Water Risers	Entire Building	25,233	SF	4	\$20,207	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	25,233	SF	4	\$13,712	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	25,233	SF	4	\$32,475	
	Domestic Piping-Hot Water Return Lines	Entire Building	25,233	SF	4	\$21,650	
	Domestic Piping-Hot Water Return Risers	Entire Building	25,233	SF	4	\$12,268	
	Sanitary Piping	Entire Building	25,233	SF	6	\$23,093	
	Storm Piping	Entire Building	25,233	SF	6	\$22,011	
	Vent Piping	Entire Building	25,233	SF	6	\$16,959	
Pumps							
	Pumps - Ejector-Duplex	Boiler Room and Basement / Boiler Room	1	EA	5	\$7,535	
	Pumps - Ejector-Simplex	Boiler Room and Basement / Basement	1	EA	5	\$5,627	

Plumbing System Subtotal:

\$230,021



9928 S Crandon Ave Chicago, IL 60617

Building: Main

Category: Classrooms

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	oom #110 (Regular Classroom)	Location	Quantity	Oille	Ruin	0031	Comments
Olassik	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	\$2,388	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	690	SF	6	\$691	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,148	SF	6	\$3,168	
Classro	oom #112 (Regular Classroom)						
Olubbit	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	5	\$6,325	Peeling paint throughout
	Chalk Board	1st Floor	30	LF	4	\$2,754	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	690	SF	6	\$691	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	Т8
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,148	SF	6	\$3,168	
Classro	oom #114 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	\$2,388	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	690	SF	6	\$691	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	Т8
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,148	SF	6	\$3,168	
Classro	oom #210 (Special Education)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	696	SF	5	\$6,380	Peeling throughout
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	696	SF	6	\$697	
	Lighting - Chandelier, Incandescent	2nd Floor	12	EA	7	\$0	



9928 S Crandon Ave Chicago, IL 60617

Building: Main

Category: Classrooms

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comme
assrc	om #210 (Special Education)						
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444	
acerr	om #211 (Art Room)						
a551 U	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	47	LF	6	\$1,187	
	Ceiling - Plaster/Drywall	2nd Floor	695	SF	6	\$2,405	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	695	SF	6	\$696	
	Lighting - Pendent/Surface	2nd Floor		EA	7	\$0	
		2nd Floor	12	SF			
	Walls - Plaster/Drywall		1,325		6	\$3,657	
	Work Sink	2nd Floor	2	EA	6	\$758	
assrc	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	696	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	\$301	
	Floor - Tile/Sheet	2nd Floor	696	SF	6	\$697	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444	
assrc	om #213 (Science Classroom)						
	Casework	2nd Floor	22	LF	6	\$556	
	Ceiling - Plaster/Drywall	2nd Floor	650	SF	6	\$2,249	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	650	SF	6	\$651	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,275	SF	6	\$3,519	
	Work Sink	2nd Floor	2	EA	6	\$758	
aserr	om #214 (Regular Classroom)					•	
u331 U	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	696	SF	7	\$202	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	696	SF	6	\$697	
	Lighting - Chandelier, Incandescent	2nd Floor	12	EA	7	\$097 \$0	
	Lighting - Chandeller, incandescent	2Πα ΓΙΟΟΙ	12	EA	,	Φ0	



9928 S Crandon Ave Chicago, IL 60617

Building: Main

Category: Classrooms

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #214 (Regular Classroom)						
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444	
Classro	om #215 (Special Education)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	688	SF	6	\$2,381	
	Chalk Board	2nd Floor	30	LF	4	\$2,754	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	688	SF	6	\$689	
	Lighting - Chandelier, Incandescent	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444	

Classrooms Subtotal: \$78,063

Building: Main

ltem - Type	Location	Quantity	Unit	Rank	Cost	Comments
nistrative Suites/Offices						
AC Unit	1st Floor-Counselor's Office 111	1	EA	6	\$496	
Ceiling - Plaster/Drywall	1st Floor-Counselor's Office 111	284	SF	6	\$983	
Doors - Wood Doors inclu hw	1st Floor-Counselor's Office 111	1	EA	6	\$301	
Floor - Carpet	1st Floor-Counselor's Office 111	284	SF	6	\$605	
Lighting - Pendent/Surface	1st Floor-Counselor's Office 111	5	EA	7	\$0	
Power Distribution	1st Floor-Counselor's Office 111	4	EA	7	\$0	
Walls - Plaster/Drywall	1st Floor-Counselor's Office 111	1,152	SF	6	\$3,179	
AC Unit	1st Floor-Main Office	1	EA	6	\$496	
Ceiling - Plaster/Drywall	1st Floor-Main Office	312	SF	6	\$1,080	
Doors - Wood Doors inclu hw	1st Floor-Main Office	1	EA	6	\$301	
Floor - Carpet	1st Floor-Main Office	208	SF	6	\$443	
Floor - Tile/Sheet	1st Floor-Main Office	104	SF	6	\$104	
Lighting - Pendent/Surface	1st Floor-Main Office	6	EA	7	\$0	
Power Distribution	1st Floor-Main Office	16	EA	7	\$0	
Walls - Plaster/Drywall	1st Floor-Main Office	876	SF	6	\$2,418	
Ceiling - Plaster/Drywall	1st Floor-Principal's Office/Main Office	152	SF	6	\$526	
Doors - Wood Doors inclu hw	1st Floor-Principal's Office/Main Office	1	EΑ	6	\$301	



9928 S Crandon Ave Chicago, IL 60617

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Floor - Carpet	1st Floor-Principal's Office/Main Office	152	SF	6	\$324	
	Lighting - Pendent/Surface	1st Floor-Principal's Office/Main Office	2	EA	7	\$0	
	Power Distribution	1st Floor-Principal's Office/Main Office	4	EA	7	\$0	
	Storage/ Closet	1st Floor-Principal's Office/Main Office	53	SF	6	\$384	Vault; no access, so rank is assumed by surrounding conditions
	Walls - Plaster/Drywall	1st Floor-Principal's Office/Main Office	600	SF	6	\$1,656	
	AC Unit	Principal's Office 113A	1	EA	6	\$496	
	Ceiling - Lay-in	Principal's Office 113A	390	SF	6	\$1,171	
	Doors - Wood Doors inclu hw	Principal's Office 113A	1	EA	6	\$301	
	Floor - Carpet	Principal's Office 113A	390	SF	6	\$831	
	Lighting - Pendent/Surface	Principal's Office 113A	6	EA	7	\$0	
	Power Distribution	Principal's Office 113A	4	EA	7	\$0	
	Walls	Principal's Office 113A	790		6	\$0	
MDF_II							
	Doors - Steel Doors incl hw	1st Floor-Within Storage 113	1	EA	6	\$301	
Mecha	nical/ Service Rooms						
	Janitor's Closet	1st Floor	22	SF	6	\$158	
	Storage Room	1st Floor	528	SF	6	\$3,783	
	Janitor's Closet	2nd Floor	9	SF	6	\$64	
	Air Intake Plenums	Basement	213	SF	5	\$2,836	Peeling paint
	Air Intake Plenums	Basement	380	SF	6	\$2,353	
	Interior Stairs	Basement	30	LF	6	\$271	
	Mechanical/ Service Rooms	Basement	905	SF	6	\$6,484	Incinerator room
	Mechanical/ Service Rooms	Basement	380	SF	6	\$2,722	Storage
	Mechanical/ Service Rooms	Basement	294	SF	6	\$2,106	
	Vaults	Basement	175	SF	6	\$1,254	
Restro	om						
	Accessories	1st Floor	225	SF	6	\$2,075	
	Accessories	1st Floor	206	SF	6	\$1,900	
	Ceiling - Plaster/Drywall	1st Floor	225	SF	6	\$779	
	Ceiling - Plaster/Drywall	1st Floor	206	SF	6	\$713	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	Missing door hardware
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor	206	SF	6	\$436	
	Floor - Tile Ceramic/ Porcelain	1st Floor	225	SF	6	\$476	



9928 S Crandon Ave Chicago, IL 60617

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
stroc	om						
	Hand Dryer	1st Floor	2	EA	6	\$460	
	Hand Dryer	1st Floor	2	EA	6	\$460	
	Lavatory	1st Floor	2	EA	6	\$639	
	Lavatory	1st Floor	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	\$0	
	Accessories	1st Floor-Main Office Staff Restroom	34	SF	6	\$314	
	Ceiling - Plaster/Drywall	1st Floor-Main Office Staff Restroom	34	SF	6	\$118	
	Doors - Wood Doors inclu hw	1st Floor-Main Office Staff Restroom	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor-Main Office Staff Restroom	34	SF	6	\$34	
	Lavatory	1st Floor-Main Office Staff Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-Main Office Staff Restroom	2	EΑ	7	\$0	
	Walls - Plaster/Drywall	1st Floor-Main Office Staff Restroom	234	SF	6	\$646	
	Water Closet	1st Floor-Main Office Staff Restroom	1	EΑ	6	\$336	
	Accessories	1st Floor-Office 111 Restroom	27	SF	6	\$249	
	Ceiling - Plaster/Drywall	1st Floor-Office 111 Restroom	27	SF	5	\$247	Peeling
	Doors - Wood Doors inclu hw	1st Floor-Office 111 Restroom	1	EΑ	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Office 111 Restroom	22	SF	6	\$47	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Office 111 Restroom	5	SF	5	\$92	Damaged
	Lavatory	1st Floor-Office 111 Restroom	1	EΑ	6	\$320	
	Lighting - Pendent/Surface	1st Floor-Office 111 Restroom	1	EΑ	7	\$0	
	Partitions	1st Floor-Office 111 Restroom	1	EΑ	6	\$297	
	Walls - Plaster/Drywall	1st Floor-Office 111 Restroom	252	SF	6	\$695	
	Water Closet	1st Floor-Office 111 Restroom	1	EA	6	\$336	
	Partitions	1st Floor	6	EA	6	\$1,782	
	Partitions	1st Floor	2	EA	6	\$594	
	Accessories	1st Floor-Teacher's Restroom	29	SF	6	\$267	
	Ceiling - Plaster/Drywall	1st Floor-Teacher's Restroom	29	SF	6	\$100	
	Doors - Wood Doors inclu hw	1st Floor-Teacher's Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Teacher's Restroom	29	SF	6	\$61	
	Lavatory	1st Floor-Teacher's Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-Teacher's Restroom	1	EA	7	\$0	
	Partitions	1st Floor-Teacher's Restroom	1	EA	6	\$297	
	Walls - Plaster/Drywall	1st Floor-Teacher's Restroom	255	SF	6	\$704	
	Water Closet	1st Floor-Teacher's Restroom	1	EA	6	\$336	
	Urinals	1st Floor	4	EA	6	\$1,344	
	Walls - Plaster/Drywall	1st Floor	70	SF	6	\$193	

9928 S Crandon Ave Chicago, IL 60617

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Walls - Structural Glazed Tile	1st Floor	740	SF	6	\$2,328	
	Walls - Structural Glazed Tile	1st Floor	634	SF	6	\$1,995	
	Water Closet	1st Floor	7	EA	6	\$2,352	
	Water Closet	1st Floor	1	EA	5	\$1,344	Not working
	Water Closet	1st Floor	1	EA	6	\$336	
	Accessories	2nd Floor	225	SF	6	\$2,075	
	Accessories	2nd Floor	206	SF	6	\$1,900	
	Ceiling - Plaster/Drywall	2nd Floor	225	SF	6	\$779	
	Ceiling - Plaster/Drywall	2nd Floor	12	SF	5	\$150	Peeling
	Ceiling - Plaster/Drywall	2nd Floor	194	SF	6	\$671	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	\$602	
	Floor Drain	2nd Floor	1	EΑ	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	225	SF	6	\$476	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	206	SF	6	\$436	
	Hand Dryer	2nd Floor	2	EΑ	6	\$460	
	Hand Dryer	2nd Floor	2	EΑ	6	\$460	
	Lavatory	2nd Floor	2	EΑ	6	\$639	
	Lavatory	2nd Floor	2	EΑ	6	\$639	
	Lighting - Pendent/Surface	2nd Floor	4	EΑ	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	5	EΑ	7	\$0	
	Partitions	2nd Floor	6	EΑ	6	\$1,782	
	Partitions	2nd Floor	2	EΑ	6	\$594	
	Urinals	2nd Floor	4	EA	6	\$1,344	
	Walls - Plaster/Drywall	2nd Floor	70	SF	6	\$193	
	Walls - Structural Glazed Tile	2nd Floor	740	SF	6	\$2,328	
	Walls - Structural Glazed Tile	2nd Floor	634	SF	6	\$1,995	
	Water Closet	2nd Floor	2	EA	6	\$672	
	Water Closet	2nd Floor	7	EA	6	\$2,352	

Rooms (Other Than Classrooms) Subtotal:

\$91,080

Building: Main

Category: Building Interior

Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Corridor			
Ceiling - Plaster/Drywall	1st Floor	2,220 SF 6	\$13,746

9928 S Crandon Ave Chicago, IL 60617

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Floor - Tile Ceramic/ Porcelain	1st Floor	222	SF	6	\$619	
	Floor - Tile/Sheet	1st Floor	1,998	SF	6	\$1,086	
	Lighting - Pendent/Surface	1st Floor	38	EA	7	\$0	
	Student Lockers - One Tier	1st Floor	51	EA	6	\$4,735	
	Walls - Plaster/Drywall	1st Floor	2,616	SF	6	\$11,597	
	Walls - Tile Ceramic/ Porcelain	1st Floor	2,616	SF	6	\$8,230	
	Ceiling - Plaster/Drywall	2nd Floor	1,542	SF	6	\$9,548	
	Floor - Tile/Sheet	2nd Floor	1,542	SF	6	\$838	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	101	EA	6	\$9,376	
	Walls - Plaster/Drywall	2nd Floor	1,330	SF	6	\$5,896	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	1,330	SF	6	\$4,184	
Safety							
	Camera Viewing Station		1	EA	6	\$683	
	Security Cameras		3	EA	6	\$582	
	Security Cameras		2	EA	6	\$388	
Stairs							
	Ceiling - Plaster/Drywall	North East	392	SF	6	\$2,870	
	Floor - Terrazzo	North East	126	SF	6	\$1,058	
	Handrails	North East	52	LF	6	\$451	
	Lighting - Chandelier, Incandescent	North East	2	EΑ	7	\$0	
	Stairs - Terrazzo	North East	26	LF	6	\$241	
	Walls - Plaster/Drywall	North East	1,092	SF	6	\$3,014	
	Walls - Tile Ceramic/ Porcelain	North East	364	SF	6	\$1,145	
	Ceiling - Plaster/Drywall	South East	392	SF	6	\$2,870	
	Floor - Terrazzo	South East	126	SF	6	\$1,058	
	Handrails	South East	52	LF	6	\$451	
	Lighting - Chandelier, Incandescent	South East	2	EA	7	\$0	
	Stairs - Terrazzo	South East	26	LF	6	\$241	
	Walls - Plaster/Drywall	South East	1,092	SF	6	\$3,014	
	Walls - Tile Ceramic/ Porcelain	South East	364	SF	6	\$1,145	
Vertica	I Conveyance						
	Elevator - Hydraulic Elevator	Courtyard	1	EA	6	\$19,238	

Building Interior Subtotal:

\$108,302



9928 S Crandon Ave Chicago, IL 60617

Total Building Cost \$1,490,675

Building: Addition 1

Category: Building Exterior

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	ce		·				
	Exterior Doors - Exterior Wood Door	#7 - NE	2	EA	6	\$961	
	Exterior Doors - Transom Lite	#7 - NE	1	EA	6	\$313	
	Exterior Stairs - Concrete	#7 - NE	120	LF	5	\$13,150	Spalling
	Exterior Stairs - Stone	#7 - NE	6	LF	6	\$678	
	Stair Handrail - Steel_Stair Handrail	#7 - NE	10	LF	6	\$87	
Founda	tion						
	Foundation - Concrete	Entire Building	425	LF	7	\$0	
	Superstructure - Concrete	Entire Building	11,526	SF	7	\$0	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	6	\$1,610	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	4		Bad fixtures
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	\$577	
Roof Sy	vstem						
	Coping - Stone	Lower North Roof	250	LF	6	\$8,029	
	Coping - Stone	Main Roof	290	LF	6	\$9,314	
	Downspouts - Interior Downspouts	Lower North Roof	28	LF	6	\$931	
	Downspouts - Interior Downspouts	Lower North Roof / North East	28	LF	5	\$6,197	Clogged
	Downspouts - Interior Downspouts	Main Roof	70	LF	6	\$2,326	
	Parapet - 16" - 30" Height	Lower North Roof	50	LF	6	\$1,998	
	Parapet - 16" - 30" Height	Main Roof	33	LF	6	\$1,318	
	Parapet - Parapet < 16" Height	Lower North Roof	200	LF	6	\$4,261	
	Parapet - Parapet < 16" Height	Main Roof	257	LF	6	\$5,476	
	Roof Structure - Steel with Clay Tile Arch	Lower North Roof	3,700	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	290	SF	6	\$5,225	
	Roof - Asphalt Gravel Ballast	Lower North Roof	3,700	SF	6	\$37,619	
	Roof - Asphalt Gravel Ballast	Main Roof	5,485	SF	6	\$55,768	
Walls							
	Cheek-Wall - Stone	Entire Building	64	SF	6	\$656	
	Exterior Walls - Brick	Entire Building	8,065	SF	6	\$54,205	
	Exterior Walls - Brick	Entire Building	10	SF	5	\$238	Vertical cracking and some open joints
	Exterior Walls - Brick	Entire Building	150	SF	4	\$24,698	Vertical cracking and some open joints
	Exterior Walls - Stone-Cast	Entire Building	950	SF	6	\$6,385	Some open joints



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 1

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Windo	ws						
	Curtain wall - Insulated Panel	Entire Building	682	SF	6	\$7,646	
	Guard - Guards wire guard	Entire Building	168	SF	6	\$2,145	Rusting
	Lintels - Steel	Entire Building	108	LF	6	\$3,135	
	Lintels - Stone	Entire Building	108	LF	6	\$0	
	Windows - Sash Lexan	Entire Building	1,302	SF	5	\$38,224	Poor latches and balances

Building Exterior Subtotal: \$295,231

Building: Addition 1

Category: Electrical System

Group Item - T	уре	Location	Quantity	Unit	Rank	Cost	Comments
Emergency Syst	tem						
Emerge	ncy A/C Power - Auditoium and Aisle Lighting	Entire Building / 1st Floor	2,396	SF	6	\$1,268	
Emerge	ncy A/C Power - Corridors and Stairs	Entire Building	2,928	SF	6	\$879	
Emerge	ncy Battery Packs - Auditoium and Aisle Lighting	Entire Building / 1st Floor	4	EA	6	\$810	
Emerge	ncy Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	\$405	
Exit Sign	ns - Auditoium	Entire Building / 1st Floor	4	EA	6	\$599	
Exit Sig	ns - Corridors and Stairs	Entire Building	6	EA	6	\$898	
Security	System - CCTV	Entire Building	11,526	SF	6	\$3,461	
Security	System - Intrusion Detection	Entire Building	11,526	SF	6	\$2,967	
Main Service							
PA Syst	tem	Entire Building	11,526	SF	5	\$7,911	
Power Distribution	on						
Lighting	and Power Panels - Above 100 A	1st Floor	1	EA	6	\$497	Auditorium
Electrical Sy	stem Subtotal:					\$10.606	

Electrical System Subtotal: \$19,696

Building: Addition 1

Category: Safty System

Group Item - Type	Location	Quantity Unit	Rank	Cost Comments	
Fire Alarm					
Fire Alarm Strobe Lights	Entire Building	11,526 SF	4	\$15,658 3 strobes	
Fire Alarm_System	Entire Building	11,526 SF	6	\$5,604	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 1
Category: Safty System

Group Item - Type Location Quantity Unit Rank Cost Comments

Safty System Subtotal: \$21,262

Building: Addition 1

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	11,526	SF	4	\$8,241	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	11,526	SF	4	\$16,647	
	Domestic Piping-Cold Water Risers	Entire Building	11,526	SF	4	\$9,230	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	11,526	SF	4	\$6,263	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	11,526	SF	4	\$14,834	
	Domestic Piping-Hot Water Return Lines	Entire Building	11,526	SF	4	\$9,889	
	Domestic Piping-Hot Water Return Risers	Entire Building	11,526	SF	4	\$5,604	
	Sanitary Piping	Entire Building	11,526	SF	6	\$10,549	
	Storm Piping	Entire Building	11,526	SF	6	\$10,054	
	Vent Piping	Entire Building	11,526	SF	6	\$7,747	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	6	\$1,446	

Plumbing System Subtotal: \$100,504

Building: Addition 1

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classr	oom #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	5	\$6,325	peeling paint
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	690	SF	6	\$691	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	Т8
	Marker Board	1st Floor	20	LF	6	\$428	
	Walls - Plaster/Drywall	1st Floor	1,148	SF	6	\$3,168	
Classr	oom #116 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 1 Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #116 (Regular Classroom)						
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	\$2,388	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	690	SF	6	\$691	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	T8
	Marker Board	1st Floor	20	LF	6	\$428	
	Walls - Plaster/Drywall	1st Floor	1,148	SF	6	\$3,168	
Classro	om #117 (Pre School)						
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	906	SF	6	\$3,135	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	906	SF	6	\$907	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	T8
	Marker Board	1st Floor	16	LF	7	\$0	
	Student Lockers - One Tier	1st Floor	12	EA	6	\$1,114	
	Walls - Plaster/Drywall	1st Floor	1,325	SF	6	\$3,657	
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	om #118 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	\$2,388	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	690	SF	6	\$1,510	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	T8
	Marker Board	1st Floor	20	LF	6	\$428	
	Walls - Plaster/Drywall	1st Floor	1,148	SF	6	\$3,168	
Classro	om #217 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	688	SF	6	\$2,381	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	688	SF	6	\$689	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 1
Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #217 (Regular Classroom)						
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	T-8
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444	
Classro	om #218 (Computer Lab)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Ceiling - Lay-in	2nd Floor	1,088	SF	6	\$3,267	
	Charging Station	2nd Floor	3	EΑ	6	\$1,454	
	Doors - Steel Doors incl hw	2nd Floor	2	EΑ	6	\$602	
	Floor - Tile/Sheet	2nd Floor	1,088	SF	6	\$1,089	
	Lighting - Pendent/Surface	2nd Floor	15	EΑ	7	\$0	T-8
	Marker Board	2nd Floor	18	LF	6	\$386	
	Walls - Plaster/Drywall	2nd Floor	1,529	SF	6	\$4,220	
	Work Sink	2nd Floor	1	EA	6	\$379	
Classro	om #219 (Library)						
	AC Units	2nd Floor	1	EA	5	\$1,826	Not working
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	65	LF	6	\$1,641	
	Ceiling - Plaster/Drywall	2nd Floor	1,069	SF	6	\$3,699	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Carpet	2nd Floor	962	SF	6	\$2,050	
	Floor - Tile/Sheet	2nd Floor	107	SF	6	\$107	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0	T-8
	Walls - Plaster/Drywall	2nd Floor	1,725	SF	6	\$4,761	
	Walls - Plaster/Drywall	2nd Floor	1,725	51	ь	\$4,761	

Classrooms Subtotal: \$74,215

Building: Addition 1

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices						
Ceiling - Plaster/Drywall	2nd Floor	340	SF	6	\$1,177	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Tile/Sheet	2nd Floor	340	SF	6	\$340	
Lighting - Pendent/Surface	2nd Floor	2	EA	7	\$0	T8
Power Distribution	2nd Floor	8	EA	6	\$16,999	
Walls - Plaster/Drywall	2nd Floor	938	SF	6	\$2,589	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 1

Category: Rooms (Other Than Classrooms)

ıp Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
inistrative Suites/Offices						
nasia						
Ceiling - Plaster/Drywall	1st Floor-Room 119	2,396	SF	6	\$13,225	
Doors - Transom Window	1st Floor-Room 119	15	SF	6	\$254	
Doors - Wood Doors inclu hw	1st Floor-Room 119	4	EA	6	\$1,204	
Floor - Wood	1st Floor-Room 119	2,396	SF	6	\$16,892	
Lighting - Lay-in	1st Floor-Room 119	12	EA	6	\$1,428	
Lighting - Pendent/Surface	1st Floor-Room 119	10	EA	7	\$0	Т8
Scoreboards	1st Floor-Room 119	1	EA	6	\$2,244	
Stage	1st Floor-Room 119	100	SF	6	\$578	
Stage Lift	1st Floor-Room 119	1	EA	6	\$6,510	
Stage Lighting System	1st Floor-Room 119	1	EA	6	\$12,369	
Stage-Stairs - Tile	1st Floor-Room 119	8	LF	6	\$74	
Storage/ Closet	1st Floor-Room 119	562	SF	6	\$4,075	
Walls - Plaster/Drywall	1st Floor-Room 119	4,528	SF	6	\$12,497	
nanical/ Service Rooms						
Crawl Space - Unfinished	Basement	3,450	SF	6	\$21,362	
room						
Accessories	Room 117 Unisex	67	SF	7	\$0	
Ceiling - Plaster/Drywall	Room 117 Unisex	67	SF	6	\$232	
Doors - Wood Doors inclu hw	Room 117 Unisex	1	EA	6	\$301	
Floor Drain	Room 117 Unisex	1	EA	6	\$1,059	
Floor - Tile	Room 117 Unisex	67	SF	6	\$147	
Lavatory	Room 117 Unisex	1	EA	6	\$320	
Lighting - Pendent/Surface	Room 117 Unisex	1	EA	7	\$0	T8
Walls - Plaster/Drywall	Room 117 Unisex	274	SF	6	\$756	
Walls - Tile Ceramic/ Porcelain	Room 117 Unisex	199	SF	6	\$450	
Water Closet	Room 117 Unisex	1	EA	6	\$336	
(O) TI OI \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\					^	

Rooms (Other Than Classrooms) Subtotal:

\$117,717

Building: Addition 1

Category: Building Interior

Group Item - Type	Location	Quantity Unit Rank	Cost Comments	
Corridor				
Ceiling - Lay-in	1st Floor	1,344 SF 6	\$4,036	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 1

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Ceiling - Plaster/Drywall	1st Floor	1,344	SF	6	\$8,322	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	1st Floor	2,688	SF	6	\$1,461	
	Lighting - Lay-in	1st Floor	3	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	\$0	
	Student Lockers - One Tier	1st Floor	126	EΑ	6	\$11,697	
	Walls - Plaster/Drywall	1st Floor	1,632	SF	6	\$7,235	
	Walls - Tile Ceramic/ Porcelain	1st Floor	1,632	SF	6	\$5,134	
	Ceiling - Plaster/Drywall	2nd Floor	1,584	SF	6	\$9,808	
	Drinking Fountains - Double Fountain	2nd Floor	1	EΑ	6	\$336	
	Floor - Tile/Sheet	2nd Floor	1,584	SF	6	\$861	
	Lighting - Pendent/Surface	2nd Floor	21	EΑ	7	\$0	
	Student Lockers - One Tier	2nd Floor	117	EΑ	6	\$10,862	
	Walls - Plaster/Drywall	2nd Floor	1,560	SF	6	\$6,915	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	1,560	SF	6	\$4,908	
Safety							
	Security Cameras		2	EA	6	\$388	
Vertica	l Conveyance						
	Elevator - Hydraulic Elevator		1	EA	6	\$19,238	
	Wheelchair Lift - Chair Lift		1	EA	6	\$5,597	
Build	ing Interior Subtotal:					\$97,134	

Total Building Cost \$725,758

Building: Addition 2

Category: Building Exterior

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
rance						
Entrance Control - Audio and Video	#5 - E	1	EA	6	\$702	
Exterior Doors - Exterior Steel Door	#5 - E	2	EA	5	\$2,683	Repair latch and loose mullions
Exterior Doors - Exterior Steel Door	#5.5 - Basement Mechanical - S	1	EΑ	6	\$481	
Exterior Doors - Exterior Steel Door	#6.5 - N	1	EΑ	6	\$481	
Exterior Doors - Exterior Wood Door	#6 - W	2	EΑ	6	\$961	
Exterior Doors - Transom Lite	#5 - E	1	EΑ	6	\$313	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 2

Category: Building Exterior

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran	• •	Location	Quantity	Oilit	Italik	0031	Comments
Linuari	Exterior Doors - Transom Lite	#6 - W	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#6.5 - N	1	EA	6	\$313	
	Exterior Stairs - Concrete	#5.5 - N	80	LF	6	\$6,541	
	Exterior Stairs - Concrete	#5.5 - Basement Mechanical - S	50	LF	6	\$4,088	
	Exterior Stairs - Concrete	#6 - W	30	LF	6	\$2,453	
	Exterior Stairs - Stone	#6 - W	6	LF	6	\$678	
	Power Door Operator and Controls	#5 - E	2	EA	6	\$070	
	Ramp Handrail - Steel_Ramp Handrail	#5 - E	200	LF	6	\$1,733	
	Ramps - Concrete	#5 - E	95	LF	6	\$14,272	
	Stair Handrail - Steel_Stair Handrail	#5 - E	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	#5.5 - Basement Mechanical - S	35	LF	6	\$303	
	Stair Handrail - Steel_Stair Handrail	#6 - W	3	LF	6	\$26	
	Stall Hariurali - Steel_Stall Hariurali	#0 - VV	3	LF	O	Φ 20	
Founda	ation						
	Foundation - Concrete	Entire Building	365	LF	7	\$0	
	Superstructure - Concrete	Entire Building	16,169	SF	7	\$0	
Liabtin	a						
Lightin	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	6	\$1,073	
		Entire Building	3	EA	6	\$866	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	O	φουσ	
Roof S	ystem						
	Coping - Stone	Lower SE Roof-Addition 2	14	LF	6	\$450	
	Coping - Stone	Main Roof-Addition 2	365	LF	6	\$11,723	
	Downspouts - Interior Downspouts	Lower SE Roof-Addition 2	12	LF	6	\$399	
	Downspouts - Interior Downspouts	Main Roof-Addition 2	70	LF	6	\$2,326	
	Parapet - 16" - 30" Height	Lower SE Roof-Addition 2	14	LF	6	\$559	
	Parapet - 16" - 30" Height	Main Roof-Addition 2	365	LF	6	\$14,583	
	Roof Structure - Steel with Clay Tile Arch	Lower SE Roof-Addition 2	40	SF	6	\$721	
	Roof Structure - Steel with Clay Tile Arch	Main Roof-Addition 2	5,485	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Lower SE Roof-Addition 2	40	SF	5	\$944	Water ponding
	Roof - Asphalt Gravel Ballast	Main Roof-Addition 2	5,485	SF	6	\$55,768	
Malla							
Walls	Charle Well Chara	Forting Duilding		C.F.		# 000	
	Cheek-Wall - Stone	Entire Building	36	SF	6	\$369 \$300	Capillian
	Exterior Walls - Brick	Entire Building	2	SF	4		Spalling
	Exterior Walls - Brick	Entire Building	8,878	SF	6	\$59,669	Once I are a describe or
	Exterior Walls - Brick	Entire Building	5	SF	4	\$823	Cracks and spalling
	Exterior Walls - Stone-Cast	Entire Building	730	SF	6	\$4,906	

9928 S Crandon Ave Chicago, IL 60617

Building: Addition 2

Category: Building Exterior

Group Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
Walls							
Exterior Wa	alls - Stone-Cast	Entire Building	10	SF	5	\$176	Spalling
Windows							
Curtain wal	I - Insulated Panel	Entire Building	627	SF	6	\$7,029	
Guard - Gu	ards wire guard	Entire Building	42	SF	6	\$536	Rusting
Lintels - St	eel	Entire Building	100	LF	6	\$2,903	
Lintels - St	one	Entire Building	100	LF	6	\$0	
Windows -	Sash Lexan	Entire Building	1,197	SF	5	\$35,141	Poor latches and balances

Building Exterior Subtotal: \$237,811

Building: Addition 2

Category: Electrical System

w System mergency A/C Power - Corridors and Stairs mergency A/C Power - Lunchrooms	Entire Building					
	Entire Building					
mergency A/C Power - Lunchrooms		2,028	SF	6	\$609	
Therefore the second of the se	Entire Building / 1st Floor	2,461	SF	6	\$915	
mergency Battery Packs - Corridors and Stairs	Entire Building	12	EA	6	\$2,430	
mergency Battery Packs - Gym	Entire Building / 1st Floor	3	EA	6	\$608	
xit Signs - Corridors and Stairs	Entire Building	11	EA	6	\$1,647	
xit Signs - Gym	Entire Building / 1st Floor	3	EA	6	\$472	
ecurity System - CCTV	Entire Building	16,169	SF	6	\$4,856	
ecurity System - Intrusion Detection	Entire Building	16,169	SF	6	\$4,162	
ce						
A System	Entire Building	16,169	SF	5	\$11,098	
ribution						
ghting and Power Panels - 100 A	Entire Building / 2nd Floor	1	EA	6	\$299	
ghting and Power Panels - Above 100 A	Entire Building	3	EA	6	\$1,491	
ghting and Power Panels - Above 100 A	Entire Building	1	EA	6	\$497	
	cit Signs - Corridors and Stairs cit Signs - Gym ecurity System - CCTV ecurity System - Intrusion Detection ce A System ribution ghting and Power Panels - 100 A ghting and Power Panels - Above 100 A	Entire Building / 2nd Floor Entire Building	Entire Building 11 dit Signs - Corridors and Stairs Entire Building / 1st Floor 3 ecurity System - CCTV Entire Building 16,169 ecurity System - Intrusion Detection Entire Building 16,169 ecurity System Entire Building 16,169 CCE A System Entire Building 16,169 Tibution System Entire Building 16,169 Thire Building 16,169	Entire Building 11 EA cit Signs - Corridors and Stairs Entire Building / 1st Floor 3 EA cecurity System - CCTV Entire Building 16,169 SF cecurity System - Intrusion Detection Entire Building 16,169 SF cec A System Entire Building 16,169 SF ribution Sphting and Power Panels - 100 A Entire Building 2nd Floor 1 EA ching and Power Panels - Above 100 A Entire Building 3 EA Contribution 1 EA Contribution 1 EA Contribution 1 EA Contribution 2 Entire Building 2nd Floor 1 EA Contribution 3 EA Contribution 2 Entire Building 3 EA Contribution 3 EA Contribution 2 Entire Building 3 EA Contribution 3 EA Contribution 2 Entire Building 3 EA Contribution 3 EA Contribution 2 Entire Building 3 EA Contribution 3 EA Contribution 2 Entire Building 3 EA Contribution 3 EA Contribution 2 Entire Building 3 EA Contribution 3 EA Contrib	Entire Building 11 EA 6 exit Signs - Corridors and Stairs Entire Building / 1st Floor 3 EA 6 excurity System - CCTV Entire Building 16,169 SF 6 excurity System - Intrusion Detection Entire Building 16,169 SF 6 excurity System Entire Building 16,169 SF 5 excurity System Entire Building 16,169 SF 6 excurity System Entire Building	Entire Building 11 EA 6 \$1,647 dit Signs - Corridors and Stairs Entire Building / 1st Floor 3 EA 6 \$472 decurity System - CCTV Entire Building 16,169 SF 6 \$4,856 decurity System - Intrusion Detection Entire Building 16,169 SF 6 \$4,162 decurity System - Intrusion Detection Entire Building 16,169 SF 5 \$11,098 decurity System - Intrusion Detection Entire Building 16,169 SF 5 \$11,098 decurity System - Intrusion Detection Entire Building 16,169 SF 5 \$11,098 decurity System - Intrusion Detection Entire Building / 2nd Floor 1 EA 6 \$299 decurity System - Intrusion Detection Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - Intrusion Detection Entire Building 3 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 1 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 2 Entire Building / 2nd Floor 2 EA 6 \$1,491 decurity System - CCTV Entire Building / 2nd Floor 2 EA 6 EA

Electrical System Subtotal: \$29,084

Building: Addition 2 Category: Safty System

Group Item - Type Location Quantity Unit Rank Cost Comments



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 2 Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Ala	ırm						
	Fire Alarm Strobe Lights	Entire Building	16,169	SF	5	\$12,486	2 strobes
	Fire Alarm_System	Entire Building	16,169	SF	6	\$7,861	

Safty System Subtotal:

\$20,347

Building: Addition 2

Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Heating Devices						
Cabinet Heaters - With Electric Coil	Entire Building	20	EA	4	\$67,197	
Fin Tube - Steam	Entire Building	140	LF	6	\$1,321	
Wall Heater - Electric	Entire Building	2	EA	5	\$1,073	
Unit Ventilation						
Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	17	EA	2	\$339,873	
Ventilation						
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	6	EA	6	\$3,554	

Mechanical System Subtotal:

\$413,018

Building: Addition 2

Category: Plumbing System

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
iping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	16,169	SF	4	\$11,561	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	16,169	SF	4	\$23,353	
	Domestic Piping-Cold Water Risers	Entire Building	16,169	SF	4	\$12,948	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	16,169	SF	4	\$8,786	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	16,169	SF	4	\$20,810	
	Domestic Piping-Hot Water Return Lines	Entire Building	16,169	SF	4	\$13,873	
	Domestic Piping-Hot Water Return Risers	Entire Building	16,169	SF	4	\$7,861	
	Sanitary Piping	Entire Building	16,169	SF	6	\$14,798	
	Storm Piping	Entire Building	16,169	SF	6	\$14,104	
	Vent Piping	Entire Building	16,169	SF	6	\$10,867	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 2

Category: Plumbing System

Group Item - Type Location Quantity Unit Rank **Cost Comments**

Plumbing System Subtotal: \$138,961

Building: Addition 2 Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #220 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	\$2,526	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	730	SF	6	\$731	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	T8
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	\$2,981	
Classro	om #221 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	696	SF	6	\$2,409	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Carpet	2nd Floor	696	SF	6	\$1,483	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	Т8
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	936	SF	6	\$2,583	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	104	SF	6	\$235	
Classro	om #222 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	\$2,526	
	Chalk Board	2nd Floor	30	LF	4	\$2,754	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	730	SF	6	\$731	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	Т8
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	6	\$2,981	
Classro	om #223 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 2
Category: Classrooms

Froup Item - Ty	ре	Location	Quantity	Unit	Rank	Cost	Comments
classroom #223 (Regular Classroom)						
Casework	(2nd Floor	8	LF	6	\$202	
Ceiling -	Plaster/Drywall	2nd Floor	730	SF	6	\$2,526	
Doors - V	ood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Til	e/Sheet	2nd Floor	730	SF	6	\$731	
Lighting -	- Pendent/Surface	2nd Floor	12	EΑ	7	\$0	T-8
Marker Be	oard	2nd Floor	22	LF	7	\$0	
Walls - P	laster/Drywall	2nd Floor	1,080	SF	6	\$2,981	

Classrooms Subtotal: \$32,171

Building: Addition 2

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comment
Adminis	strative Suites/Offices						
	Ceiling - Plaster/Drywall	2nd Floor-Community Learning Center	128	SF	6	\$443	
	Doors - Wood Doors inclu hw	2nd Floor-Community Learning Center	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor-Community Learning Center	128	SF	6	\$128	
	Lighting - Pendent/Surface	2nd Floor-Community Learning Center	3	EA	7	\$0	T8
	Power Distribution	2nd Floor-Community Learning Center	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	2nd Floor-Community Learning Center	625	SF	6	\$1,725	
	AC Unit	2nd flr- 225 Diverse Learners Center	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd flr- 225 Diverse Learners Center	380	SF	6	\$1,315	
	Doors - Wood Doors inclu hw	2nd flr- 225 Diverse Learners Center	1	EA	6	\$301	
	Floor - Carpet	2nd flr- 225 Diverse Learners Center	323	SF	6	\$688	
	Floor - Tile	2nd flr- 225 Diverse Learners Center	45	SF	6	\$98	
	Floor - Tile	2nd flr- 225 Diverse Learners Center	12	SF	5	\$59	missing
	Lighting - Pendent/Surface	2nd flr- 225 Diverse Learners Center	10	EA	6	\$1,239	
	Power Distribution	2nd flr- 225 Diverse Learners Center	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	2nd flr- 225 Diverse Learners Center	975	SF	6	\$2,691	
	Ceiling - Plaster/Drywall	Room 124 ESP	132	SF	6	\$457	
	Doors - Transom Window	Room 124 ESP	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	Room 124 ESP	1	EA	6	\$301	
	Floor - Tile/Sheet	Room 124 ESP	132	SF	6	\$132	
	Lighting - Pendent/Surface	Room 124 ESP	3	EA	7	\$0	T8
	Power Distribution	Room 124 ESP	2	EA	6	\$4,250	
	Walls - Plaster/Drywall	Room 124 ESP	479	SF	6	\$1,322	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 2

	Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Doors - Transon Window Room 123 1	Kitchen							
Doors - Wood Doors inclut hw Room 123 690 \$5 6 \$691 Floor - Tile (Sheet Room 123 690 \$7 \$0 \$699 Lighting - Pandent/Surface Room 123 120 57 \$0 \$589 Serving Line Room 123 120 57 \$0 \$589 Walls - Plaster/Dywall Room 123 120 57 \$0 \$589 Walls - Plaster/Dywall Room 123 120 57 \$0 \$53,312 Celling - Lay-in Room 121 1,081 \$7 \$0 \$500 Doors - Transform Window Room 121 1,081 \$7 \$0 \$500 Doors - Wood Doors inclut hw Room 121 1,081 \$7 \$0 \$500 Doors - Wood Doors inclut hw Room 121 1,081 \$7 \$0 \$500 Hort-Tile Sheet Room 121 1,081 \$7 \$0 \$500 Hort-Tile Sheet Room 121 1,081 \$7 \$0 \$500 Hort-Tile Sheet Room 121 1,081 \$7 \$0 \$500 Walls - Plaster/Dywall Room 121 1,081 \$7 \$0 \$500 Walls - Plaster/Dywall Room 122 1,380 \$7 \$0 \$500 Hort-Tile Sheet Room 122 1,380 \$7 \$0 \$500 Walls - Plaster/Dywall Room 122 1,380 \$7 \$0 \$500 Walls - Plaster/Dywall Room 122 1,380 \$7 \$0 \$500 Walls - Plaster/Dywall Room 122 1,380 \$7 \$0 \$0 \$500 Walls - Plaster/Dywall Room 122 1,380 \$7 \$0 \$0 \$500 Walls - Plaster/Dywall Room 122 1,380 \$7 \$0 \$0 \$0 \$0 Walls - Plaster/Dywall Room 122 1,380 \$7 \$0 \$0 \$0 \$0 \$0 \$0 \$		Ceiling - Plaster/Drywall	Room 123	690	SF	6	\$2,388	
Floor - Tile/Sheet		Doors - Transom Window	Room 123	9	SF	6	\$152	
Lighting - Pendant/Surface Room 123 10 EA 7 80 T8 Serving Line Room 123 100 EF 6 \$5.955 Walls - Plaster/Drywall Room 123 1,200 SF 6 \$3.312 Celling - Layvin Room 121 1,081 SF 6 \$3.36 Doors - Transom Window Room 121 1,081 SF 6 \$3.05 Doors - Wood Doors inclut hw Room 121 2 EA 6 \$5.00 Floor - Tille/Sheet Room 121 1,881 SF 6 \$3.05 Doors - Wood Doors inclut hw Room 121 2 EA 6 \$5.00 Haster/Drywall Room 121 1,881 SF 6 \$3.05 Lighting - Layvin Room 121 1,881 SF 6 \$5.00 Walls - Plaster/Drywall Room 121 1,881 SF 6 \$3.01 Ceiling - Layvin Room 122 1,380 SF 6 \$4.144 Ceiling - Layvin Room 122 1,380 SF 6 \$4.144 Colling - Layvin Room 122 1,380 SF 6 \$4.144 Colling - Layvin Room 122 1,380 SF 6 \$3.312 Floor - Tille/Sheet Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall Room 122 1,380 SF 6 \$3.312 Walls - Plaster/Drywall SF 6 \$3.301 Walls - Plaster/Drywall		Doors - Wood Doors inclu hw	Room 123	1	EA	6	\$301	
Sening Line Walls - Plaster/Drywall Room 123 10 LF 6 \$555 Walls - Plaster/Drywall Room 123 1,20 SF 6 \$33,24 Lunch & Wuldburprose Room Ceiling - Lay-in Room 121 1,88 SF 6 \$30,26 Doors - Transon Window Room 121 18 SF 6 \$30,50 Floor - Tilis/Sheat Lay Room 121 1,88 SF 6 \$30,60 Floor - Tilis/Sheat Lay-In Room 121 1,88 SF 6 \$30,00 Walls - Plaster/Drywall Room 121 1,188 SF 6 \$3,218 Ceiling - Lay-in Room 122 1,380 SF 6 \$3,218 Chalk Board Room 122 1,380 SF 6 \$3,218 Doors - Wood Doors inclu hw Room 122 1,380 SF 6 \$50,22 Planting - Lay-in Room 122 1,380 SF 6 \$50,22 Ughting - Lay-in Room 122 1,380		Floor - Tile/Sheet	Room 123	690	SF	6	\$691	
Lunch & Multipurpose Room Room 121 1.00 SF 6 \$3,312 Celling - Ley-in Room 121 1.081 SF 6 \$30.5 Doors - Transom Window Room 121 18 SF 6 \$30.5 Doors - Wood Doors indu hw Room 121 18 SF 6 \$50.02 Floor - Tille/Sheet Room 121 1.081 SF 6 \$50.02 Ughting - Lay-in Room 121 1.186 SF 6 \$50.02 Walls - Plaster/Drywall Room 122 1.186 SF 6 \$30.218 Celling - Lay-in Room 122 30 LF 4 \$2.754 Cobes - Wood Doors inclu hw Room 122 1.380 SF 6 \$31.381 Lighting - Lay-in Room 122 1.380 SF 6 \$13.381 Walls - Plaster/Dywall Room 122 1.20 SF 6 \$3.312 Mechanical/ Service Rooms Basement 1.9 SF 6 \$3.312		Lighting - Pendent/Surface	Room 123	10	EA	7	\$0	Т8
Caling - Lay-in Room 121 1,081 SF 6 \$3,024 Doors - Transom Window Room 121 1,081 SF 6 \$305 Doors - Wood Doors inclut hw Room 121 1,081 SF 6 \$305 Doors - Wood Doors inclut hw Room 121 1,081 SF 6 \$5,002 Floor - Tille/Sheet Room 121 1,081 SF 6 \$5,002 Lighting - Lay-in Room 121 1,186 SF 6 \$3,218 Caling - Lay-in Room 122 1,380 SF 6 \$3,218 Caling - Lay-in Room 122 1,380 SF 6 \$4,144 Chalk Beard Room 122 30 LF 4 \$2,754 Doors - Wood Doors inclut hw Room 122 30 LF 4 \$2,754 Doors - Wood Doors inclut hw Room 122 1,380 SF 6 \$3602 Floor - Tille/Sheet Room 122 1,380 SF 6 \$3602 Floor - Tille/Sheet Room 122 1,380 SF 6 \$3,381 Walls - Plaster/Dywall Room 122 1,380 SF 6 \$3,381 Walls - Plaster/Dywall Room 122 1,380 SF 6 \$3,381 Walls - Plaster/Dywall Room 122 1,380 SF 6 \$3,381 Walls - Plaster/Dywall Room 122 1,380 SF 6 \$3,381 Walls - Plaster/Dywall Room 122 1,380 SF 6 \$3,381 Walls - Plaster/Dywall Room 122 1,380 SF 6 \$3,381 Walls - Plaster/Dywall Room 122 1,380 SF 6 \$3,381 Walls - Plaster/Dywall Room 122 Room 123 SF 6 \$1,159 Air Intake Plenums Basement 1,418 SF 6 \$1,159 Accessories Sasement 1,418 SF 6 \$1,159 Accessories Sasement 1,418 SF 6 \$1,159 Accessories Sasement 1,418 SF 6 \$3,361 Celling - Plaster/Dywall 1,51		Serving Line	Room 123	10	LF	6	\$595	
Celling - Lay-in Room 121 1,081 SF 6 \$3,246 Doors - Transom Window Room 121 18 SF 6 \$305 Doors - Wood Doors inclu hw Room 121 2 EA 6 \$602 Floor - Tile/Sheet Room 121 1,081 SF 6 \$1,082 Lighting - Lay-in Room 121 1,186 SF 6 \$3,248 Celling - Lay-in Room 121 1,186 SF 6 \$3,248 Celling - Lay-in Room 122 1,380 SF 6 \$3,248 Chalk Board Room 122 30 LF 4 \$2,754 Doors - Wood Doors inclu hw Room 122 2 EA 6 \$602 Floor - Tile/Sheet Room 122 30 LF 4 \$2,754 Doors - Wood Doors inclu hw Room 122 2 EA 6 \$602 Floor - Tile/Sheet Room 122 2 EA 7 \$0 Walls - Plaster/Dnywall Room 122 2 EA 7 \$0 Walls - Plaster/Dnywall Room 122 2 EA 7 \$0 Walls - Plaster/Dnywall Room 122 1,200 SF 6 \$3,312 Mechanical/ Service Rooms Sasement 197 SF 6 \$1,220 Interior Stairs Basement 197 SF 6 \$1,220 Interior Stairs Basement 30 LF 6 \$271 Janitor's Closet Basement 30 LF 6 \$271 Janitor's Closet Basement 1,418 SF 6 \$3,367 Restroom Restroom Basement 1,418 SF 6 \$3,367 Restroom Restroom Rasement 1,418 SF 6 \$3,367 Restroom Restroom 1 EA 6 \$301 Floor Torin 1 EA 6 \$301 Hard Dryer 1 1 EA 6 \$320 Lextory 1 1 1 EA 6 \$320 Lextory 1 1 1 1 1 1 1 1 1		Walls - Plaster/Drywall	Room 123	1,200	SF	6	\$3,312	
Celling - Lay-in Room 121 1,081 SF 6 \$3,246 Doors - Transom Window Room 121 18 SF 6 \$305 Doors - Wood Doors inclu hw Room 121 2 EA 6 \$602 Floor - Tile/Sheet Room 121 1,081 SF 6 \$1,082 Lighting - Lay-in Room 121 1,186 SF 6 \$3,248 Celling - Lay-in Room 121 1,186 SF 6 \$3,248 Celling - Lay-in Room 122 1,380 SF 6 \$3,248 Chalk Board Room 122 30 LF 4 \$2,754 Doors - Wood Doors inclu hw Room 122 2 EA 6 \$602 Floor - Tile/Sheet Room 122 30 LF 4 \$2,754 Doors - Wood Doors inclu hw Room 122 2 EA 6 \$602 Floor - Tile/Sheet Room 122 2 EA 7 \$0 Walls - Plaster/Dnywall Room 122 2 EA 7 \$0 Walls - Plaster/Dnywall Room 122 2 EA 7 \$0 Walls - Plaster/Dnywall Room 122 1,200 SF 6 \$3,312 Mechanical/ Service Rooms Sasement 197 SF 6 \$1,220 Interior Stairs Basement 197 SF 6 \$1,220 Interior Stairs Basement 30 LF 6 \$271 Janitor's Closet Basement 30 LF 6 \$271 Janitor's Closet Basement 1,418 SF 6 \$3,367 Restroom Restroom Basement 1,418 SF 6 \$3,367 Restroom Restroom Rasement 1,418 SF 6 \$3,367 Restroom Restroom 1 EA 6 \$301 Floor Torin 1 EA 6 \$301 Hard Dryer 1 1 EA 6 \$320 Lextory 1 1 1 EA 6 \$320 Lextory 1 1 1 1 1 1 1 1 1	Lunch &	& Multipurpose Room						
Doors - Wood Doors inclu hw Room 121 1,081 SF 6 \$1,082			Room 121	1,081	SF	6	\$3,246	
Floor - Tile/Sheet		Doors - Transom Window	Room 121	18	SF	6	\$305	
Lighting - Lay-in Room 121 18 EA 7 \$0 \$0 \$0 \$0 \$0 \$0 \$0		Doors - Wood Doors inclu hw	Room 121	2	EA	6	\$602	
Walls - Plaster/Drywall Room 121 1,166 SF 6 \$3,218		Floor - Tile/Sheet	Room 121	1,081	SF	6	\$1,082	
Ceiling - Lay-in Room 122 1,380 SF 6		Lighting - Lay-in	Room 121	18	EA	7	\$0	
Chalk Board Room 122 30 LF 4 \$2,754 Doors - Wood Doors inclu hw Room 122 1,80 SF 6 \$602 Floor - Tile/Sheet Room 122 1,80 SF 6 \$1,381 Lighting - Lay-in Room 122 1,20 SF 6 \$1,381 Walls - Plaster/Drywall Room 122 1,20 SF 6 \$3,312 Mechanical/ Service Rooms SF 6 \$3,312 Mechanical/ Service Rooms SF 6 \$9.3 Air Intake Plenums Basement 197 SF 6 \$1,220 Janitor's Closet Basement 30 LF 6 \$271 Janitor's Closet Basement 30 LF 6 \$271 Janitor's Closet Basement 1,418 SF 6 \$1,227 Mechanical/ Service Rooms Basement 1,418 SF 6 \$1,0159 Air Intake Planums Basement 1,418 SF 6 \$1,0159 Accessories Room Basement 1,418 SF 6 \$1,0159 Accessories String Plaster/Drywall 1st Floor 133 SF 6 \$1,227 Ceiling - Plaster/Drywall 1st Floor 133 SF 6 \$1,227 Ceiling - Plaster/Drywall 1st Floor 133 SF 6 \$1,227 Floor Drain 1st Floor 134 EA 6 \$3,01 Floor Drain 1st Floor 1 EA 6 \$3,01 Floor - Tile Ceramic/ Porcelain 1st Floor 1 EA 6 \$281 Hand Dryer 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1st Floor 1 EA 6 \$281 Lavatory 1st Floor 1st Floor 1 EA 6 \$281 Lavatory 1st Floor		Walls - Plaster/Drywall	Room 121	1,166	SF	6	\$3,218	
Doors - Wood Doors inclu hw Room 122 1,380 SF 6 \$1,381 Floor - Tille/Sheet Room 122 1,380 SF 6 \$1,381 Lighting - Lay-in Room 122 1,20 SF 6 \$1,381 Walls - Plaster/Dywall Room 122 1,20 SF 6 \$3,312 Mechanical/ Service Rooms		Ceiling - Lay-in	Room 122	1,380	SF	6	\$4,144	
Floor - Tile/Sheet		Chalk Board	Room 122	30	LF	4	\$2,754	
Lighting - Lay-in Walls - Plaster/Drywall Room 122 21 EA 7 \$0 Mechanical/ Service Rooms Mechanical/ Service Rooms Service Rooms SF 6 \$93 Air Intake Plenums Basement 197 SF 6 \$1,220 Interior Stairs Basement 30 LF 6 \$2,11 Janitor's Closet Basement 30 LF 6 \$2,11 Mechanical/ Service Rooms Basement 1,418 SF 6 \$10,159 Storage Room Basement 1,418 SF 6 \$10,159 Storage Room Basement 1,418 SF 6 \$10,159 Storage Room Basement 1,418 SF 6 \$3,367 Restroom Basement 1,418 SF 6 \$10,159 Ceiling - Plaster/Drywall 1st Floor 133 SF 6 \$460 Doors - Wood Doors inclu hw 1st Floor 1 EA 6 \$231 <td></td> <td>Doors - Wood Doors inclu hw</td> <td>Room 122</td> <td>2</td> <td>EA</td> <td>6</td> <td>\$602</td> <td></td>		Doors - Wood Doors inclu hw	Room 122	2	EA	6	\$602	
Walls - Plaster/Drywall Room 122 1,200 SF 6 \$3,312 Mechanical/ Service Rooms Janitor's Closet 2nd Floor 13 SF 6 \$93 Air Intake Plenums Basement 197 SF 6 \$1,220 Interior Stairs Basement 30 LF 6 \$271 Janitor's Closet Basement 308 SF 5 \$4,968 break room/ office Mechanical/ Service Rooms Basement 1,418 SF 6 \$1,519 storage Room Basement 470 SF 6 \$1,519 storage Room/ office \$1,519 storage Room \$1,519 <td< td=""><td></td><td>Floor - Tile/Sheet</td><td>Room 122</td><td>1,380</td><td>SF</td><td>6</td><td>\$1,381</td><td></td></td<>		Floor - Tile/Sheet	Room 122	1,380	SF	6	\$1,381	
Mechanical/ Service Rooms Janitor's Closet 2nd Floor 13 SF 6 \$93 Air Intake Plenums Basement 197 SF 6 \$1,220 Interior Stairs Basement 30 LF 6 \$271 Janitor's Closet Basement 308 SF 5 \$4,968 break room/ office Mechanical/ Service Rooms Basement 1,418 SF 6 \$10,159 Storage Room Basement 470 SF 6 \$3,367 Restroom Accessories 1st Floor 133 SF 6 \$1,227 Ceiling - Plaster/Drywall 1st Floor 133 SF 6 \$460 Doors - Wood Doors inclu hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 133 SF 6 \$281 Hand Dryer 1st Floor 133 SF 6 \$281 Hand Dryer 1st Floor 1		Lighting - Lay-in	Room 122	21	EΑ	7	\$0	
Janitor's Closet 2nd Floor 13 SF 6 \$93 Air Intake Plenums Basement 197 SF 6 \$1,220 Interior Stairs Basement 30 LF 6 \$271 Janitor's Closet Basement 308 SF 5 \$4,968 break room/ office Mechanical/ Service Rooms Basement 1,418 SF 6 \$10,159 Storage Room Basement 470 SF 6 \$3,367 Restroom Step		Walls - Plaster/Drywall	Room 122	1,200	SF	6	\$3,312	
Air Intake Plenums Basement 197 SF 6 \$1,220 Interior Stairs Basement 30 LF 6 \$271 Janitor's Closet Basement 308 SF 5 \$4,968 break room/ office Mechanical/ Service Rooms Basement 1,418 SF 6 \$10,159 Storage Room Basement 470 SF 6 \$3,367 Restroom Accessories 1st Floor 133 SF 6 \$1,227 Ceiling - Plaster/Drywall 1st Floor 133 SF 6 \$460 Doors - Wood Doors inclu hw 1st Floor 1 EA 6 \$301 Floor - Tile Ceramic/ Porcelain 1st Floor 133 SF 6 \$281 Hand Dryer 1st Floor 1 EA 6 \$230 Lavatory 1st Floor 1 EA 6 \$320	Mechar	nical/ Service Rooms						
Interior Stairs		Janitor's Closet	2nd Floor	13	SF	6	\$93	
Janitor's Closet Basement 308 SF 5 \$4,968 break room/ office Mechanical/ Service Rooms Basement 1,418 SF 6 \$10,159 Storage Room Basement 470 SF 6 \$3,367 Restroom SF 6 \$3,367 Accessories 1st Floor 133 SF 6 \$1,227 Ceiling - Plaster/Drywall 1st Floor 133 SF 6 \$460 Doors - Wood Doors inclu hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 1 EA 6 \$281 Hand Dryer 1st Floor 1 EA 6 \$230 Lavatory 1st Floor 1 EA 6 \$320 Lavatory 1st Floor 1 EA		Air Intake Plenums	Basement	197	SF	6	\$1,220	
Mechanical/ Service Rooms Storage Room Basement Basement 1,418 SF 6 \$10,159 SF 6 \$3,367 Restroom Accessories Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor Ist Fl		Interior Stairs	Basement	30	LF	6	\$271	
Restroom Basement 470 SF 6 \$3,367 Restroom Accessories 1st Floor 133 SF 6 \$1,227 Ceiling - Plaster/Drywall 1st Floor 133 SF 6 \$460 Doors - Wood Doors inclu hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 133 SF 6 \$281 Hand Dryer 1st Floor 1 EA 6 \$230 Lavatory 1st Floor 1 EA 6 \$320		Janitor's Closet	Basement	308	SF	5	\$4,968	break room/ office
Restroom Accessories 1st Floor 133 SF 6 \$1,227 Ceiling - Plaster/Drywall 1st Floor 133 SF 6 \$460 Doors - Wood Doors inclu hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 133 SF 6 \$281 Hand Dryer 1st Floor 1 EA 6 \$230 Lavatory 1st Floor 1 EA 6 \$320		Mechanical/ Service Rooms	Basement	1,418	SF	6	\$10,159	
Accessories 1st Floor 133 SF 6 \$1,227 Ceiling - Plaster/Drywall 1st Floor 133 SF 6 \$460 Doors - Wood Doors inclu hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 133 SF 6 \$281 Hand Dryer 1st Floor 1 EA 6 \$230 Lavatory 1st Floor 1 EA 6 \$320		Storage Room	Basement	470	SF	6	\$3,367	
Ceiling - Plaster/Drywall 1st Floor 133 SF 6 \$460 Doors - Wood Doors inclu hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 133 SF 6 \$281 Hand Dryer 1st Floor 1 EA 6 \$230 Lavatory 1st Floor 1 EA 6 \$320	Restro	om						
Doors - Wood Doors inclu hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 13 SF 6 \$281 Hand Dryer 1st Floor 1 EA 6 \$230 Lavatory 1st Floor 1 EA 6 \$320		Accessories	1st Floor	133	SF	6	\$1,227	
Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 133 SF 6 \$281 Hand Dryer 1st Floor 1 EA 6 \$230 Lavatory 1st Floor 1 EA 6 \$320		Ceiling - Plaster/Drywall	1st Floor	133	SF	6	\$460	
Floor - Tile Ceramic/ Porcelain 1st Floor 133 SF 6 \$281 Hand Dryer 1st Floor 1 EA 6 \$230 Lavatory 1st Floor 1 EA 6 \$320		Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Hand Dryer 1st Floor 1 EA 6 \$230 Lavatory 1st Floor 1 EA 6 \$320		Floor Drain	1st Floor	1	EA	6	\$1,059	
Lavatory 1 st Floor 1 EA 6 \$320		Floor - Tile Ceramic/ Porcelain	1st Floor	133	SF	6	\$281	
·		Hand Dryer	1st Floor	1	EA	6	\$230	
Lighting - Pendent/Surface 1st Floor 3 FA 7 \$0 T8		Lavatory	1st Floor	1	EA	6	\$320	
<u> </u>		Lighting - Pendent/Surface	1st Floor	3	EA	7	\$0	T8



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 2

ıp Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
room						
Partitions	1st Floor	3	EA	6	\$891	
Walls - Plaster/Drywall	1st Floor	58	SF	6	\$160	
Walls - Structural Glazed Tile	1st Floor	518	SF	6	\$1,630	
Water Closet	1st Floor	3	EΑ	6	\$1,008	
Accessories	2nd floor- Boy's	120	SF	6	\$1,107	
Ceiling - Plaster/Drywall	2nd floor- Boy's	120	SF	6	\$415	
Doors - Wood Doors inclu hw	2nd floor- Boy's	1	EΑ	6	\$301	
Floor Drain	2nd floor- Boy's	1	EΑ	6	\$1,059	
Floor - Tile Ceramic/ Porcelain	2nd floor- Boy's	120	SF	6	\$254	
Hand Dryer	2nd floor- Boy's	1	EΑ	6	\$230	
Lavatory	2nd floor- Boy's	1	EΑ	6	\$320	
Lighting - Pendent/Surface	2nd floor- Boy's	3	EΑ	7	\$0	
Partitions	2nd floor- Boy's	1	EA	6	\$297	
Urinals	2nd floor- Boy's	3	EA	6	\$1,008	
Walls - Plaster/Drywall	2nd floor- Boy's	160	SF	6	\$442	
Walls - Structural Glazed Tile	2nd floor- Boy's	490	SF	6	\$1,542	
Water Closet	2nd floor- Boy's	1	EA	6	\$336	
Accessories	2nd Floor	133	SF	6	\$1,227	
Ceiling - Plaster/Drywall	2nd Floor	133	SF	6	\$460	
Accessories	2nd Floor-Community Learning Center Restroom	36	SF	6	\$332	
Ceiling - Plaster/Drywall	2nd Floor-Community Learning Center Restroom	36	SF	6	\$125	
Doors - Wood Doors inclu hw	2nd Floor-Community Learning Center Restroom	1	EA	6	\$301	
Floor - Tile/Sheet	2nd Floor-Community Learning Center Restroom	36	SF	6	\$36	
Lavatory	2nd Floor-Community Learning Center Restroom	1	EA	6	\$320	
Lighting - Pendent/Surface	2nd Floor-Community Learning Center Restroom	1	EA	7	\$0	Т8
Lighting - Wall Mounted	2nd Floor-Community Learning Center Restroom	1	EA	7	\$0	
Partitions	2nd Floor-Community Learning Center Restroom	1	EA	6	\$297	
Walls - Plaster/Drywall	2nd Floor-Community Learning Center Restroom	225	SF	6	\$621	
Water Closet	2nd Floor-Community Learning Center Restroom	1	EA	6	\$336	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 2

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	m						
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	133	SF	6	\$281	
	Hand Dryer	2nd Floor	1	EA	6	\$230	
	Lavatory	2nd Floor	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	\$0	T8
	Partitions	2nd Floor	3	EA	6	\$891	
	Walls - Plaster/Drywall	2nd Floor	58	SF	6	\$160	
	Walls - Structural Glazed Tile	2nd Floor	518	SF	6	\$1,630	
	Water Closet	2nd Floor	3	EA	6	\$1,008	
	Accessories	Room 124	36	SF	6	\$332	
	Ceiling - Plaster/Drywall	Room 124	36	SF	6	\$125	
	Doors - Transom Window	Room 124	1	SF	6	\$17	
	Floor - Tile/Sheet	Room 124	6	SF	6	\$6	
	Lavatory	Room 124	1	EA	6	\$320	
	Lighting - Pendent/Surface	Room 124	1	EA	7	\$0	Т8
	Partitions	Room 124	1	EA	6	\$297	
	Walls - Plaster/Drywall	Room 124	219	SF	6	\$604	
	Water Closet	Room 124	1	EA	6	\$336	
	•		1	_			

Rooms (Other Than Classrooms) Subtotal:

\$108,108

Building: Addition 2

Category: Building Interior

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
rridor						
Ceiling - Lay-in	1st Floor	1,296	SF	6	\$3,892	
Ceiling - Plaster/Drywall	1st Floor	144	SF	6	\$892	
Doors - Wood Doors include hw	1st Floor	2	EA	6	\$602	
Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
Floor - Terrazzo	1st Floor	144	SF	6	\$1,209	
Floor - Tile Ceramic/ Porcelain	1st Floor	129	SF	6	\$360	
Floor - Tile/Sheet	1st Floor	1,167	SF	6	\$634	
Lighting - Lay-in	1st Floor	4	EA	7	\$0	
Lighting - Pendent/Surface	1st Floor	3	EA	7	\$0	
Student Lockers - One Tier	1st Floor	53	EA	6	\$4,920	
Walls - Plaster/Drywall	1st Floor	1,584	SF	6	\$7,022	
Walls - Tile Ceramic/ Porcelain	1st Floor	1,584	SF	6	\$4,983	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 2

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	•						
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	6	\$4,532	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	6	\$336	
	Floor - Tile/Sheet	2nd Floor	732	SF	6	\$398	
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	52	EA	6	\$4,827	
	Walls - Plaster/Drywall	2nd Floor	730	SF	6	\$3,236	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	730	SF	6	\$2,297	
Safety							
	Security Cameras	North West	1	EA	6	\$194	
	Security Cameras	West	1	EA	6	\$194	
Stairs							
	Ceiling - Plaster/Drywall	North West	144	SF	6	\$1,054	
	Floor - Terrazzo	North West	96	SF	6	\$806	
	Handrails	North West	48	LF	6	\$416	
	Lighting - Chandelier, Incandescent	North West	2	EA	7	\$0	
	Stairs - Terrazzo	North West	24	LF	6	\$223	
	Walls - Plaster/Drywall	North West	702	SF	6	\$1,937	
	Walls - Tile Ceramic/ Porcelain	North West	234	SF	6	\$736	
Buildi	ng Interior Subtotal:					\$46,036	

\$1,025,537

Total Building Cost

Building: Addition 3

Category: Building Exterior

Group Item - Type	Location	Quantity U	Jnit	Rank	Cost	Comments
Entrance						
Exterior Doors - Exterior Steel Door	#3.5 - S	1 E	EΑ	6	\$481	
Exterior Doors - Exterior Steel Door	#4.1 - Elevator Mechanical - Central	1 E	EΑ	6	\$481	
Exterior Doors - Exterior Wood Door	#3 - SE	2 E	EΑ	5	\$2,683	Delamaination
Exterior Doors - Exterior Wood Door	#4 - W	2 E	EΑ	6	\$961	
Exterior Doors - Transom Lite	#3 - SE	1 E	EΑ	6	\$313	
Exterior Doors - Transom Lite	#3.5 - S	1 E	EΑ	6	\$313	
Exterior Doors - Transom Lite	#4 - W	1 E	EΑ	6	\$313	
Exterior Stairs - Concrete	#3 - SE	120 L	LF	6	\$9,812	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	**						
	Exterior Stairs - Concrete	#3.5 - S	60	LF	6	\$4,906	
	Exterior Stairs - Concrete	#4 - W	30	LF	6	\$2,453	
	Stair Handrail - Steel_Stair Handrail	#3 - SE	5	LF	6	\$43	
	Stair Handrail - Steel_Stair Handrail	#3.5 - S	40	LF	6	\$347	
	Stair Handrail - Steel_Stair Handrail	#4 - W	3	LF	6	\$26	
Founda	ition						
· oanac	Foundation - Concrete	Entire Building	825	LF	7	\$0	
	Superstructure - Concrete	Entire Building	29,228	SF	7	\$0	
		2. Tuno Ballaning	20,220	O.	•	ΨΟ	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	5	EA	6	\$2,683	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	\$866	
Roof Sy	ystem						
	Chimney - Brick Chimney- Stainless Steel Liner	Main Roof	47	LF	6	\$44,870	
	Coping - Stone	Elevator Roofs	155	LF	6	\$4,978	
	Coping - Stone	Main Roof	600	LF	6	\$19,271	
	Coping - Stone	South Lower Roof	225	LF	6	\$7,227	
	Downspouts - Exterior Downspouts	Elevator Roofs	42	LF	6	\$1,396	
	Downspouts - Interior Downspouts	Main Roof	70	LF	6	\$2,326	
	Downspouts - Interior Downspouts	South Lower Roof	54	LF	6	\$1,795	
	Parapet - 16" - 30" Height	Elevator Roofs	155	LF	6	\$6,193	
	Parapet - 16" - 30" Height	Main Roof	15	LF	6	\$599	
	Parapet - 16" - 30" Height	South Lower Roof	15	LF	6	\$599	
	Parapet - Parapet < 16" Height	Main Roof	585	LF	6	\$12,465	
	Parapet - Parapet < 16" Height	South Lower Roof	210	LF	6	\$4,474	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Elevator Roofs	350	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	10,687	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	South Lower Roof	2,945	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Main Roof	10,687	SF	6	\$108,658	
	Roof - Asphalt Gravel Ballast	South Lower Roof	2,945	SF	5	\$69,529	Water ponding
	Roof - Modified Bitumen	Elevator Roofs	350	SF	5	\$7,362	Water ponding
Walls							
	Cheek-Wall - Stone	Entire Building	36	SF	5	\$857	Spalling
	Cheek-Wall - Stone	Entire Building	36	SF	6	\$369	
	Exterior Walls - Brick	Entire Building	16,960	SF	6	\$113,988	
	Exterior Walls - Brick	Entire Building	10	SF	5		Step cracks
		-					



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Walls							
	Exterior Walls - Brick	Entire Building / South East	200	SF	4	\$32,930	Vertical cracks
	Exterior Walls - Brick	Entire Building / South West	50	SF	4	\$8,233	Vertical cracks
	Exterior Walls - Brick	Entire Building / West	40	SF	4	\$6,586	Vertical cracks and gaps
	Exterior Walls - Stone-Cast	Entire Building	1,650	SF	6	\$11,090	Open joints
	Exterior Walls - Stone-Cast	Entire Building / North West	15	SF	5	\$264	Spalling
	Exterior Walls - Stone-Cast	Entire Building / South	15	SF	5	\$264	Spalling
	Exterior Walls - Stone-Cast	Entire Building / West	25	SF	5	\$440	Spalling
Windov	vs						
	Curtain wall - Insulated Panel	Entire Building	1,210	SF	6	\$13,566	
	Curtain wall - Louver	Entire Building	54	SF	6	\$605	
	Guard - Guards wire guard	Entire Building	126	SF	6	\$1,609	Rusting
	Lintels - Steel	Entire Building	193	LF	6	\$5,603	
	Lintels - Stone	Entire Building	193	LF	6	\$0	
	Windows - Sash Lexan	Entire Building	2,310	SF	5	\$67,817	Poor latches and balances

Building Exterior Subtotal:

\$582,882

Building: Addition 3

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Automatic Transfer Switch	Electrical Room	1	EA	4	\$8,200	
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,500	SF	6	\$1,351	
	Emergency A/C Power - Gym	Entire Building / 1st Floor	2,410	SF	6	\$896	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EΑ	6	\$810	
	Exit Signs - Corridors and Stairs	Entire Building	6	EΑ	6	\$898	
	Exit Signs - Lunchroom	Entire Building / 1st Floor	4	EA	6	\$599	
Main S	ervice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	\$5,641	also Serves the Main, Addition 1 and 2
Power	Distribution						
	Lighting and Power Panels - Above 100 A	1st Floor, Basement and Mechanical Room / 1st Floor	1	EA	6	\$497	
	Lighting and Power Panels - Above 100 A	1st Floor, Basement and Mechanical Room / Basement	1	EA	6	\$497	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3

Category: Electrical System

Group Iter	m - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distr	ribution						
Lig	hting and Power Panels - Above 100 A	1st Floor, Basement and Mechanical Room / Mechanical Room	1	EA	4	\$6,578	Fused panel
Ma	ain Distribution Panels - 400 - 600 amp	1st Floor, Basement and Mechanical Room / Mechanical Room	1	EA	4	\$13,694	Fused panel
Ma	ain Distribution Panels - 400 - 600 amp	1st Floor, Basement and Mechanical Room / Mechanical Room	1	EA	6	\$528	
Electrical	I System Subtotal:					\$43,110	

Building: Addition 3 Category: Safty System

Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Fire Alarm			
Fire Alarm Strobe Lights	Entire Building	29,228 SF 6	\$10,449
Fire Alarm_System	Entire Building	29,228 SF 6	\$14,211

Safty System Subtotal:

\$24,660

Building: Addition 3

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000	Mechanical Room	1	EA	5	\$78,608	Serves NE and NW additions
	Air Intake	Mechanical Room / Roof	1	EA	5	\$7,471	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	\$6,511	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	100	LF	5	\$131,341	
	Zone Dampers	Mechanical Room / Entire Building	31	EA	5	\$59,320	
Heating	Devices						
	Wall Heater - Electric	Entire Building	4	EA	5	\$2,146	
Temper	ature Control						
	Pneumatic System	Entire Building	29,288	SF	4	\$152,450	
	Thermostats - Pneumatic	Entire Building	31	EA	4	\$22,854	
Ventilat	ion						
	Exhaust Fans- Indoor - Less than 500 CFM	1st Floor and Roof / 1st Floor	1	EA	6	\$296	Location: Kitchen
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st Floor and Roof / Roof	1	EA	6	\$592	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3

Category: Mechanical System

Group Item - Type Location Quantity Unit Rank Cost Comments

Mechanical System Subtotal: \$461,590

Building: Addition 3

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	ter						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	6	\$310	Serves Main and also Addition 1 and 2
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	29,228	SF	4	\$20,898	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	29,228	SF	4	\$42,214	
	Domestic Piping-Cold Water Risers	Entire Building	29,228	SF	4	\$23,406	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	29,228	SF	4	\$15,882	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	29,228	SF	4	\$37,616	
	Domestic Piping-Hot Water Return Lines	Entire Building	29,228	SF	4	\$25,078	
	Domestic Piping-Hot Water Return Risers	Entire Building	29,228	SF	4	\$14,211	
	Sanitary Piping	Entire Building	29,228	SF	6	\$26,749	
	Storm Piping	Entire Building	29,228	SF	6	\$25,496	
	Vent Piping	Entire Building	29,228	SF	6	\$19,644	
Pumps							
	Pumps - Ejector-Simplex	Basement	1	EA	6	\$745	

Plumbing System Subtotal: \$252,249

Building: Addition 3

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroo	m #103 (Science Classroom)						
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	53	LF	6	\$1,338	
	Ceiling - Plaster/Drywall	1st Floor	1,078	SF	6	\$3,731	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	1,078	SF	6	\$1,079	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	T-8
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,680	SF	6	\$4,637	
	Work Sink	1st Floor	4	EA	6	\$1,516	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3
Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classi	room #103 (Science Classroom)						
Classi	room #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st Floor	781	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	\$301	
	Floor - Tile/Sheet	1st Floor	781	SF	6	\$782	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	Т8
	Marker Board	1st Floor	23	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,380	SF	7	\$0	
Classi	room #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	\$2,388	
	Chalk Board	1st Floor	20	LF	4	\$1,836	Replace with marker boards
	Doors - Transom Window	1st Floor	1	SF	6	\$17	
	Floor - Tile/Sheet	1st Floor	690	SF	6	\$691	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	T-8
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	\$3,511	
Classi	room #108 (Kindergarten)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	12	LF	6	\$303	
	Ceiling - Plaster/Drywall	1st Floor	68	SF	5	\$850	Peeling at window
	Ceiling - Plaster/Drywall	1st Floor	622	SF	6	\$2,152	
	Chalk Board	1st Floor	20	LF	6	\$446	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	690	SF	6	\$691	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	T8
	Marker Board	1st Floor	20	LF	6	\$428	
	Walls - Plaster/Drywall	1st Floor	1,281	SF	6	\$3,535	
Classi	room #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	\$2,388	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3
Category: Classrooms

						_	_
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #109 (Regular Classroom)						
	Floor - Tile/Sheet	1st Floor	690	SF	6	\$691	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	T8
	Marker Board	1st Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,148	SF	6	\$3,168	
Classro	oom #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	713	SF	6	\$2,467	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	713	SF	6	\$714	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	Т8
	Marker Board	2nd Floor	44	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,296	SF	6	\$3,577	
Classro	oom #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	\$2,526	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	730	SF	6	\$731	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	Т8
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,296	SF	6	\$3,577	
Classro	oom #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	696	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	\$301	
	Floor - Tile/Sheet	2nd Floor	696	SF	6	\$697	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	Т8
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444	
Classro	oom #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	696	SF	7	\$0	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3
Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #205 (Regular Classroom)						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	696	SF	6	\$697	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	\$0	T8
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444	
Classro	oom #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	685	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	685	SF	6	\$686	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	T8
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444	
Classro	oom #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	688	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	688	SF	6	\$689	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444	
Classro	oom #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	685	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	685	SF	6	\$686	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	T8
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3 Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments					
Classro	Classroom #209 (Regular Classroom)											
	AC Units	2nd Floor	1	EA	6	\$496						
	Casework	2nd Floor	8	LF	6	\$202						
	Ceiling - Plaster/Drywall	2nd Floor	688	SF	7	\$0						
	Chalk Board	2nd Floor	22	LF	6	\$491						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301						
	Floor - Tile/Sheet	2nd Floor	688	SF	6	\$689						
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	\$0	Т8					
	Marker Board	2nd Floor	22	LF	7	\$0						
	Walls - Plaster/Drywall	2nd Floor	1,248	SF	6	\$3,444						

Classrooms Subtotal: \$95,911

Building: Addition 3

o Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
nistrative Suites/Offices						
AC Unit	1st Floor-Office 102	1	EA	6	\$496	
Ceiling - Plaster/Drywall	1st Floor-Office 102	693	SF	6	\$2,398	
Doors - Steel Doors incl hw	1st Floor-Office 102	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor-Office 102	693	SF	6	\$694	
Lighting - Pendent/Surface	1st Floor-Office 102	12	EA	7	\$0	T8
Power Distribution	1st Floor-Office 102	3	EA	6	\$6,375	
Walls - Plaster/Drywall	1st Floor-Office 102	1,272	SF	6	\$3,511	
AC Unit	1st Floor-Staff Lounge 101	1	EA	6	\$496	
Ceiling - Plaster/Drywall	1st Floor-Staff Lounge 101	1,075	SF	6	\$3,720	
Doors - Steel Doors incl hw	1st Floor-Staff Lounge 101	2	EA	6	\$602	
Floor - Tile/Sheet	1st Floor-Staff Lounge 101	999	SF	6	\$1,000	
Floor - Tile/Sheet	1st Floor-Staff Lounge 101	76	SF	5	\$438	Missing tiles
Lighting - Pendent/Surface	1st Floor-Staff Lounge 101	18	EA	7	\$0	T8
Power Distribution	1st Floor-Staff Lounge 101	10	EA	6	\$21,249	
Walls - Plaster/Drywall	1st Floor-Staff Lounge 101	1,656	SF	6	\$4,570	
AC Unit	2nd Floor-Assistant Principal Office 207A	1	EA	6	\$496	
Ceiling - Plaster/Drywall	2nd Floor-Assistant Principal Office 207A	320	SF	6	\$1,107	
Doors - Wood Doors inclu hw	2nd Floor-Assistant Principal Office 207A	2	EA	6	\$602	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Floor - Tile/Sheet	2nd Floor-Assistant Principal Office 207A	320	SF	6	\$320	
	Lighting - Pendent/Surface	2nd Floor-Assistant Principal Office 207A	5	EA	7	\$0	Т8
	Power Distribution	2nd Floor-Assistant Principal Office 207A	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	2nd Floor-Assistant Principal Office 207A	1,104	SF	6	\$3,047	
Gymna	sia						
	Ceiling - Exposed	1st Floor	2,410	SF	6	\$3,584	Concrete
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	\$1,204	
	Floor - Wood	1st Floor	2,410	SF	6	\$16,990	
	Lighting - Metal Halide/ High Pressure Sodium	1st Floor	12	EA	7	\$0	
	Walls - Masonry	1st Floor	3,175	SF	6	\$9,989	
	Walls - Structural Glazed Tile	1st Floor	1,586	SF	6	\$4,990	
Mechar	nical/ Service Rooms						
	Janitor's Closet	1st Floor	22	SF	6	\$158	
	Janitor's Closet	2nd Floor	22	SF	6	\$158	
	Boiler Room	Basement	1,300	SF	5	\$20,970	Peeling paint
	Crawl Space - Unfinished	Basement	8,850	SF	6	\$54,798	
	Interior Stairs	Basement	20	LF	6	\$180	
	Janitor's Closet	Basement	160	SF	6	\$1,146	Engineer's room
Restro	om						
	Accessories	1st Floor	263	SF	6	\$2,426	
	Accessories	1st Floor	235	SF	6	\$2,168	
	Accessories	1st Floor	37	SF	6	\$341	
	Ceiling - Plaster/Drywall	1st Floor	27	SF	6	\$93	
	Ceiling - Plaster/Drywall	1st Floor	263	SF	6	\$910	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	\$108	Peeling
	Ceiling - Plaster/Drywall	1st Floor	235	SF	6	\$813	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor Drain	1st Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor	263	SF	6	\$557	
	Floor - Tile Ceramic/ Porcelain	1st Floor	235	SF	6	\$497	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
stro	om						
	Floor - Tile/Sheet	1st Floor	37	SF	6	\$37	
	Accessories	1st Floor-Gymnasium Staff Restroom	57	SF	6	\$526	
	Ceiling - Plaster/Drywall	1st Floor-Gymnasium Staff Restroom	57	SF	6	\$197	
	Doors - Wood Doors inclu hw	1st Floor-Gymnasium Staff Restroom	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor-Gymnasium Staff Restroom	3	SF	5	\$17	Water damage
	Floor - Tile/Sheet	1st Floor-Gymnasium Staff Restroom	54	SF	6	\$54	
	Lavatory	1st Floor-Gymnasium Staff Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-Gymnasium Staff Restroom	1	EA	7	\$0	Т8
	Partitions	1st Floor-Gymnasium Staff Restroom	1	EA	6	\$297	
	Walls - Plaster/Drywall	1st Floor-Gymnasium Staff Restroom	15	SF	5	\$77	Peeling
	Walls - Plaster/Drywall	1st Floor-Gymnasium Staff Restroom	249	SF	6	\$687	
	Water Closet	1st Floor-Gymnasium Staff Restroom	1	EA	6	\$336	
	Accessories	1st Floor-Gymnasium Vestibule	64	SF	6	\$590	
	Accessories	1st Floor-Gymnasium Vestibule	64	SF	6	\$590	
	Ceiling - Plaster/Drywall	1st Floor-Gymnasium Vestibule	54	SF	6	\$187	
	Ceiling - Plaster/Drywall	1st Floor-Gymnasium Vestibule	10	SF	5	\$108	Bubbling and peeling
	Ceiling - Plaster/Drywall	1st Floor-Gymnasium Vestibule	10	SF	5	\$108	Bubbling and peeling
	Ceiling - Plaster/Drywall	1st Floor-Gymnasium Vestibule	54	SF	6	\$187	
	Doors - Wood Doors inclu hw	1st Floor-Gymnasium Vestibule	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor-Gymnasium Vestibule	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Gymnasium Vestibule	64	SF	6	\$135	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Gymnasium Vestibule	64	SF	6	\$135	
	Lavatory	1st Floor-Gymnasium Vestibule	1	EA	6	\$320	
	Lavatory	1st Floor-Gymnasium Vestibule	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-Gymnasium Vestibule	1	EA	7	\$0	Т8
	Lighting - Pendent/Surface	1st Floor-Gymnasium Vestibule	1	EA	7	\$0	Т8
	Partitions	1st Floor-Gymnasium Vestibule	1	EA	6	\$297	
	Partitions	1st Floor-Gymnasium Vestibule	1	EA	6	\$297	
	Urinals	1st Floor-Gymnasium Vestibule	1	EA	6	\$336	
	Walls - Plaster/Drywall	1st Floor-Gymnasium Vestibule	272	SF	5	\$2,061	Holes, peeling, and cracking
	Walls - Plaster/Drywall	1st Floor-Gymnasium Vestibule	272	SF	6	\$751	
	Water Closet	1st Floor-Gymnasium Vestibule	1	EA	6	\$336	
	Water Closet	1st Floor-Gymnasium Vestibule	1	EA	6	\$336	
	Hand Dryer	1st Floor	1	EA	6	\$230	
	Hand Dryer	1st Floor	1	EA	6	\$230	
	Lavatory	1st Floor	2	EA	6	\$639	
	Lavatory	1st Floor	2	EA	6	\$639	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	m						
	Lavatory	1st Floor	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	\$0	Т8
	Lighting - Pendent/Surface	1st Floor	1	EA	7	\$0	T8
	Lighting - Pendent/Surface	1st Floor	8	EA	7	\$0	T8
	Partitions	1st Floor	4	EA	6	\$1,188	
	Partitions	1st Floor	1	EA	6	\$297	
	Partitions	1st Floor	2	EA	6	\$594	
	Urinals	1st Floor	2	EA	6	\$672	
	Walls - Masonry	1st Floor	269	SF	6	\$846	
	Walls - Masonry	1st Floor	110	SF	6	\$346	
	Walls - Plaster/Drywall	1st Floor	115	SF	6	\$317	
	Walls - Plaster/Drywall	1st Floor	257	SF	6	\$709	
	Walls - Plaster/Drywall	1st Floor	200	SF	6	\$552	
	Walls - Plaster/Drywall	1st Floor	10	SF	5	\$51	Peeling
	Walls - Structural Glazed Tile	1st Floor	384	SF	6	\$1,208	
	Walls - Structural Glazed Tile	1st Floor	367	SF	6	\$1,155	
	Water Closet	1st Floor	1	EA	6	\$336	
	Water Closet	1st Floor	4	EA	6	\$1,344	
	Water Closet	1st Floor	2	EA	6	\$672	
	Accessories	2nd Floor	235	SF	6	\$2,168	
	Accessories	2nd Floor	37	SF	6	\$341	
	Accessories	2nd Floor	263	SF	6	\$2,426	
	Accessories	2nd Floor-Assistant Principal's Office Restroom	70	SF	6	\$646	
	Ceiling - Plaster/Drywall	2nd Floor-Assistant Principal's Office Restroom	70	SF	6	\$242	
	Doors - Wood Doors inclu hw	2nd Floor-Assistant Principal's Office Restroom	1	EA	6	\$301	
	Floor Drain	2nd Floor-Assistant Principal's Office Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Assistant Principal's Office Restroom	70	SF	6	\$148	
	Hand Dryer	2nd Floor-Assistant Principal's Office Restroom	1	EA	6	\$230	
	Lavatory	2nd Floor-Assistant Principal's Office Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd Floor-Assistant Principal's Office Restroom	1	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor-Assistant Principal's Office Restroom	140	SF	6	\$386	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom		•				
Walls - Tile Ceramic/ Porcelain	2nd Floor-Assistant Principal's Office Restroom	140	SF	6	\$316	
Water Closet	2nd Floor-Assistant Principal's Office Restroom	1	EA	6	\$336	
Ceiling - Plaster/Drywall	2nd Floor	36	SF	6	\$125	
Ceiling - Plaster/Drywall	2nd Floor	263	SF	6	\$910	
Ceiling - Plaster/Drywall	2nd Floor	235	SF	6	\$813	
Ceiling - Plaster/Drywall	2nd Floor	1	SF	5	\$12	Hole
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor Drain	2nd Floor	1	EA	6	\$1,059	
Floor Drain	2nd Floor	1	EA	6	\$1,059	
Floor - Tile Ceramic/ Porcelain	2nd Floor	235	SF	6	\$497	
Floor - Tile Ceramic/ Porcelain	2nd Floor	263	SF	6	\$557	
Floor - Tile/Sheet	2nd Floor	37	SF	6	\$37	
Hand Dryer	2nd Floor	1	EA	6	\$230	
Hand Dryer	2nd Floor	1	EA	6	\$230	
Lavatory	2nd Floor	1	EA	6	\$320	
Lavatory	2nd Floor	2	EA	6	\$639	
Lavatory	2nd Floor	2	EA	6	\$639	
Lighting - Pendent/Surface	2nd Floor	1	EA	7	\$0	T8
Lighting - Pendent/Surface	2nd Floor	8	EA	7	\$0	T8
Lighting - Pendent/Surface	2nd Floor	8	EA	7	\$0	T8
Partitions	2nd Floor	1	EA	6	\$297	
Partitions	2nd Floor	4	EA	6	\$1,188	
Partitions	2nd Floor	2	EA	6	\$594	
Walls - Masonry	2nd Floor	269	SF	6	\$846	
Walls - Masonry	2nd Floor	110	SF	6	\$346	
Walls - Plaster/Drywall	2nd Floor	210	SF	6	\$580	
Walls - Plaster/Drywall	2nd Floor	115	SF	6	\$317	
Walls - Plaster/Drywall	2nd Floor	257	SF	6	\$709	
Walls - Structural Glazed Tile	2nd Floor	367	SF	6	\$1,155	
Walls - Structural Glazed Tile	2nd Floor	384	SF	6	\$1,208	
Water Closet	2nd Floor	4	EA	6	\$1,344	
Water Closet	2nd Floor	1	EA	6	\$336	
Water Closet	2nd Floor	2	EA	6	\$672	
Accessories	Room 124	36	SF	6	\$332	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3

Category: Rooms (Other Than Classrooms)

	em - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
C	ceiling - Plaster/Drywall	Room 124	36	SF	6	\$125	
D	oors - Wood Doors inclu hw	Room 124	1	EA	6	\$301	
F	loor - Tile/Sheet	Room 124	36	SF	6	\$36	
L	avatory	Room 124	1	EA	6	\$320	
Li	ighting - Pendent/Surface	Room 124	1	EA	7	\$0	T8
V	Valls - Plaster/Drywall	Room 124	219	SF	6	\$604	
V	Vater Closet	Room 124	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$240,755

Building: Addition 3

Category: Building Interior

up Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ridor						
Ceiling - Plaster/Drywall	1st Floor	2,232	SF	6	\$13,820	
Ceiling - Splined	1st Floor	72	SF	5	\$513	water damaged ceiling
Doors - Wood Doors include hw	1st Floor	2	EA	6	\$602	
Drinking Fountains - Double Fountain	1st Floor	1	EΑ	6	\$336	
Floor - Terrazzo	1st Floor	230	SF	6	\$1,931	
Floor - Tile Ceramic/ Porcelain	1st Floor	104	SF	6	\$290	
Floor - Tile/Sheet	1st Floor	2,069	SF	6	\$1,124	
Floor - Tile/Sheet	1st Floor	5	SF	5	\$29	damaged tiles
Lighting - Pendent/Surface	1st Floor	1	EΑ	4	\$541	ruined by water, needs to be replaced
Lighting - Pendent/Surface	1st Floor	27	EΑ	7	\$0	
Student Lockers - One Tier	1st Floor	127	EΑ	6	\$11,790	
Walls - Plaster/Drywall	1st Floor	1,970	SF	6	\$8,733	
Walls - Tile Ceramic/ Porcelain	1st Floor	2,592	SF	6	\$8,154	
Ceiling - Plaster/Drywall	2nd Floor	2,196	SF	6	\$13,597	
Drinking Fountains - Double Fountain	2nd Floor	1	EA	6	\$336	
Floor - Tile/Sheet	2nd Floor	2,196	SF	6	\$1,193	
Lighting - Pendent/Surface	2nd Floor	28	EΑ	7	\$0	
Student Lockers - One Tier	2nd Floor	128	EA	6	\$11,883	
Walls - Plaster/Drywall	2nd Floor	2,070	SF	6	\$9,176	
Walls - Tile Ceramic/ Porcelain	2nd Floor	2,070	SF	6	\$6,512	
rs						
Ceiling - Plaster/Drywall	South West	144	SF	6	\$1,054	



9928 S Crandon Ave Chicago, IL 60617

Building: Addition 3

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
Stairs							
	Floor - Terrazzo	South West	96	SF	6	\$806	
	Handrails	South West	48	LF	6	\$416	
	Lighting - Chandelier, Incandescent	South West	2	EA	7	\$0	
	Stairs - Terrazzo	South West	24	LF	6	\$223	
	Walls - Plaster/Drywall	South West	702	SF	6	\$1,937	
	Walls - Tile Ceramic/ Porcelain	South West	234	SF	6	\$736	
Build	ng Interior Subtotal:					\$95,734	

Total Building Cost \$1,796,890

Building: Branch

Category: Building Exterior

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntrand	ce						
	Entrance Control - Audio	#1-Main-NE	1	EA	6	\$497	
	Exterior Doors - Exterior Steel Door	#2-S	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#3-SE	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#4-SW	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	#5-SW	1	EΑ	6	\$481	
	Exterior Doors - Exterior Steel Door	#6-W	1	EΑ	6	\$481	
	Exterior Doors - Exterior Steel Door	#7-NW	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	#8-N	1	EA	6	\$481	
	Exterior Doors - Side lite	#1-Main-NE	2	EA	6	\$627	
	Exterior Doors - Side lite	#2-S	2	EΑ	6	\$627	
	Exterior Doors - Store Front	#1-Main-NE	3	EΑ	6	\$1,638	
	Exterior Doors - Transom Lite	#1-Main-NE	3	EΑ	6	\$940	
	Exterior Doors - Transom Lite	#2-S	1	EΑ	6	\$313	
	Exterior Doors - Transom Lite	#3-SE	1	EΑ	6	\$313	
	Exterior Doors - Transom Lite	#4-SW	1	EΑ	6	\$313	
	Exterior Stairs - Concrete	#1-Main-NE	20	LF	5	\$2,192	Cracks
	Exterior Stairs - Concrete	#3-SE	8	LF	6	\$654	
	Exterior Stairs - Concrete	#4-SW	8	LF	6	\$654	
	Exterior Stairs - Concrete	#5-SW	15	LF	6	\$1,227	
	Exterior Stairs - Concrete	#6-W	15	LF	6	\$1,227	
	Exterior Stairs - Concrete	#8-N	4	LF	6	\$327	



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

Category: Building Exterior

_	Item - Type	Location	Quantity	l Init	Donk	Coot	Comments
Entran	•	Location	Quantity	Offic	Kalik	COSI	Comments
Entrant	Exterior Stairs - Stone	#1-Main-NE	11	LF	5	¢2.002	Spalling and open joints
				LF		\$2,963	Spaning and open joints
	Ramp Handrail - Steel_Ramp Handrail	#2-S #2-S	30		6	•	
	Ramps - Concrete		20	LF	6	\$3,005 \$35	
	Stair Handrail - Steel_Stair Handrail	#1-Main-NE	4	LF	6	*	
	Stair Handrail - Steel_Stair Handrail	#5-SW	15	LF	6	\$130	
	Stair Handrail - Steel_Stair Handrail	#6-W	20	LF	6	\$173	
Founda	ation						
	Foundation - Concrete	Entire Building	660	LF	7	\$0	Hairline cracks
	Foundation - Concrete	Entire Building / West	25	LF	5	\$13,798	Spalling and cracks
	Superstructure - Concrete	Entire Building	15,103	SF	7	\$0	
Liabtin							
Lightin	Sexterior Lighting - Wall Mounted	Entire Building	20	EA	6	\$5,775	
	Exterior Lighting - Wall Mounted Exterior Lighting - Wall Mounted	Entire Building / South	1	EA	4		Broken fixture
	Exterior Lighting - Wall Mounted Exterior Lighting - Wall Mounted	Entire Building / West	3	EA	4		Broken fixtures
	Exterior Lighting - waii Mounted	Entire Building / West	3	EA	4	φ3,090	DIOREITIIXIUIES
Roof S	ystem						
	Chimney - Brick Chimney- Stainless Steel Liner	Entire Building	10	LF	4	\$53,184	vertical cracks and step cracks
	Chimney - Brick Chimney- Stainless Steel Liner	Entire Building	12	LF	6	\$11,456	
	Coping - Metal	Entire Building	685	LF	6	\$22,001	
	Downspouts - Interior Downspouts	Entire Building	36	LF	6	\$1,196	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Entire Building	15,103	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Entire Building	15,103	SF	4	\$423,307	Roof not accessible - Water ponding and blisters
Walls							
	Canopy - Concrete/ Stucco	Entire Building	40	SF	6	\$1,466	
	Canopy - Concrete/ Stucco	Entire Building	52	SF	5	\$6,103	Exposed steel
	Canopy - Concrete/ Stucco	Entire Building	20	SF	6	\$733	•
	Canopy - Concrete/ Stucco	Entire Building	20	SF	5	\$2,347	Cracks
	Exterior Walls - Brick	Entire Building	8,070	SF	6	\$54,238	Some open joints
	Exterior Walls - Brick	Entire Building / West	5	SF	4	\$823	• •
	Exterior Walls - Stone-Cast	Entire Building	144	SF	5	\$1,936	G
Windov	N/C	•					
villuot	Curtain wall - Louver	Entire Building	9	SF	6	\$101	
	Guard - Guards wire guard	Entire Building	2,025	SF	6	\$25,859	
	Lintels - Steel	Entire Building	2,023	LF	6	\$8,360	
	Windows - Sash Aluminum Double-pane	Entire Building	1,998	SF	6	\$14,914	
	Windows - Sash Aluminum Double-pane Windows - Sash Aluminum Double-pane	Entire Building / South	1,996	SF	5		Broken
	williaows - Sasii Aluminum Double-pane	Entire building / South	21	SF	ວ	φ1, 4 54	DIONEIL



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

Category: Building Exterior

Group Item - Type Location Quantity Unit Rank Cost Comments

Windows

Building Exterior Subtotal: \$675,633

Building: Branch

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Emerge	nergency System									
	Automatic Transfer Switch	Boiler Room	1	EA	6	\$408				
	Emergency A/C Power - Corridors and Stairs	Entire Building	1,670	SF	6	\$502				
	Emergency A/C Power - Lunchrooms	Entire Building	1,381	SF	6	\$513				
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	6	\$749				
	Exit Signs - Lunchroom	Entire Building	2	EA	6	\$299				
	Security System - CCTV	Entire Building	15,103	SF	6	\$4,535				
	Security System - Intrusion Detection	Entire Building	15,103	SF	6	\$3,888	Controller in boiler room			
Main Se	ervice									
	Independent Electrical Service for emergency power	Boiler Room	1	EA	7	\$0				
	Main Electrical Service- Live Front - 800 A and Less than 120/208/3PH	Boiler Room	1	EA	4	\$24,303	Live front w/ exposed fuse holders. no markings on panel			
	PA System	Entire Building	15,103	SF	6	\$4,967				
Power I	Distribution									
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497	Location: Kitchen			
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	4	\$6,578	Fused panel			
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497	Location: Kitchen			
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	\$6,578	Fused panel			
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	\$994				

Electrical System Subtotal:

\$55,308

Building: Branch

Category: Safty System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Panel	Boiler Room	1	EA	4	\$49,477	
Fire Alarm Strobe Lights	Boiler Room / Entire Building	15,103	SF	4	\$20,517	Horns and bells only
Fire Alarm_System	Boiler Room / Entire Building	15,103	SF	4	\$30,020	



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

Category: Safty System

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
prinkler System						
Sprinkler Heads	Entire Building	15,013	SF	6	\$0	Serves kitchen only
Sprinkler Piping	Entire Building	15,103	SF	6	\$2,808	Serves kitchen only
Wet Sprinkler System	Entire Building	15,103	SF	6	\$3,888	Serves kitchen only

Safty System Subtotal: \$106,709

Building: Branch

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Make Up Air Unit- Roof Mounted- Gas Heating and DX Cooling with Self Contained Compressor - Less than 6000 cfm	Roof	2	EA	6	\$6,700	
Boiler S	Systems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - Less than 50 HP	Boiler Room	2	EA	6	\$4,093	
	Chemical Feed System	Boiler Room	1	EA	6	\$1,078	
	Chemical Feeder	Boiler Room	1	EA	6	\$1,078	
	Combustion Dampers	Boiler Room	2	EA	6	\$818	
	Condensate Pump	Boiler Room	1	EA	6	\$2,021	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	\$2,545	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Less than 50 HP	Boiler Room	2	EA	5	\$19,376	
	Piping - Condensate Pipe- Steel	Boiler Room / Entire Building	100	LF	6	\$189	
	Piping - Steam Pipe- Steel	Boiler Room / Entire Building	100	LF	6	\$189	
	Steam Traps	Boiler Room / Entire Building	24	EA	6	\$6,340	
Gas Bo	oster						
	Gas Booster	Boiler Room	2	EA	6	\$998	
Heating	Devices						
	Cabinet Heaters - With Steam Coil	Entire Building	11	EA	6	\$3,923	
	Fin Tube - Steam	Entire Building	28	LF	5	\$2,280	
	Radiators - Steam	Entire Building / 1st Floor	1	EA	5	\$1,675	
Temper	ature Control						
	Hybrid Pneumatic/DDC System	Entire Building	15,103	SF	5	\$52,049	
	Thermostats - DDC	Entire Building	2	EA	6	\$0	MAU for kitchen / lunchroom
	Thermostats - Pneumatic	Entire Building	11	EA	6	\$0	



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Unit Ve	entilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	8	EA	5	\$76,309	
Ventila	tion						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof and 1st floor / Roof	2	EA	4	\$12,784	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof and 1st floor / Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof and 1st floor / Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof and 1st floor / Roof	1	EA	4	\$1,942	
	Roof Mounted Duct Work	Roof and 1st floor / Roof	50	LF	6	\$18,951	
	Type II Exhaust Hood- Warming Kitchen	Roof and 1st floor / 1st Floor	1	EA	6	\$920	Location: Kitchen

Mechanical System Subtotal:

\$217,442

Building: Branch

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wa	ter						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	\$310	
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	15,103	SF	4	\$21,813	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	15,103	SF	4	\$19,438	
	Domestic Piping-Hot Water Return Lines	Entire Building	15,103	SF	4	\$12,958	
	Sanitary Piping	Entire Building	15,103	SF	6	\$13,822	
	Storm Piping	Entire Building	15,103	SF	6	\$13,174	
	Vent Piping	Entire Building	15,103	SF	6	\$10,151	

Plumbing System Subtotal:

\$91,666

Building: Branch

Category: Classrooms

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classroom #109 (Regular Classroom)						
AC Units	1st Floor	1	EA	6	\$496	
Casework	1st Floor	30	LF	6	\$758	
Ceiling - Splined	1st Floor	1,005	SF	6	\$819	
Chalk Board	1st Floor	18	LF	4	\$1,653	Replace with marker boards
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #109 (Regular Classroom)						
	Floor - Tile/Sheet	1st Floor	1,005	SF	6	\$1,006	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Storage/ Closet	1st Floor	20	SF	6	\$145	
	Walls - Concrete Block	1st Floor	1,105	SF	6	\$3,239	
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	oom #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	30	LF	6	\$758	
	Ceiling - Splined	1st Floor	1,005	SF	6	\$819	
	Chalk Board	1st Floor	18	LF	4	\$1,653	Replace with marker boards
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	1,005	SF	6	\$1,006	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Storage/ Closet	1st Floor	20	SF	4	\$557	Broken door
	Walls - Concrete Block	1st Floor	1,105	SF	6	\$3,239	
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	oom #111 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	30	LF	5	\$6,272	De-laminating
	Ceiling - Splined	1st Floor	1,005	SF	6	\$819	
	Chalk Board	1st Floor	18	LF	4	\$1,653	Replace with marker boards
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	1,005	SF	6	\$2,199	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Storage/ Closet	1st Floor	20	SF	6	\$145	
	Walls - Concrete Block	1st Floor	1,105	SF	6	\$3,239	
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	oom #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	30	LF	6	\$758	
	Ceiling - Splined	1st Floor	30	SF	6	\$24	
	Chalk Board	1st Floor	18	LF	4	\$1,653	Replace with marker board
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	1,005	SF	5	\$4,513	Damaged
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Storage/ Closet	1st Floor	20	SF	6	\$145	



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

Category: Classrooms

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #112 (Regular Classroom)						
	Walls - Concrete Block	1st Floor	1,105	SF	6	\$3,239	
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	oom #113 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Splined	1st Floor	774	SF	6	\$631	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	774	SF	6	\$775	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
	Storage/ Closet	1st Floor	40	SF	6	\$290	
	Walls - Concrete Block	1st Floor	809	SF	6	\$2,372	
	Walls - Plaster/Drywall	1st Floor	143	SF	6	\$395	
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	oom #114 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	30	LF	6	\$758	
	Ceiling - Splined	1st Floor	1,005	SF	6	\$819	
	Chalk Board	1st Floor	18	LF	4	\$1,653	Replace with marker board
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	1,005	SF	6	\$1,006	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Storage/ Closet	1st Floor	20	SF	6	\$145	
	Walls - Concrete Block	1st Floor	1,105	SF	6	\$3,239	
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	oom #116 (Kindergarten)						
	AC Units	1st Floor	1	EA	5	\$1,826	Not plugged in or working
	Casework	1st Floor	38	LF	6	\$960	
	Ceiling - Splined	1st Floor	1,246	SF	6	\$1,016	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	1,246	SF	6	\$2,726	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	\$0	
	Storage/ Closet	1st Floor	42	SF	6	\$305	
	Walls - Concrete Block	1st Floor	1,554	SF	6	\$4,556	
	Work Sink	1st Floor	1	EA	6	\$379	



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

Category: Classrooms

Group Item - Type Location Quantity Unit Rank Cost Comments

Classrooms Subtotal: \$72,018

Building: Branch

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Lay-in	1st Floor-Kitchen Office	55	SF	6	\$165	
	Doors - Steel Doors incl hw	1st Floor-Kitchen Office	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor-Kitchen Office	55	SF	5	\$247	Worn and rusted
	Lighting - Lay-in	1st Floor-Kitchen Office	1	EA	7	\$0	
	Power Distribution	1st Floor-Kitchen Office	8	EA	6	\$16,999	
	Walls - Concrete Block	1st Floor-Kitchen Office	246	SF	6	\$721	
	Ceiling - Splined	1st Floor-Main Office	305	SF	6	\$249	
	Doors - Wood Doors inclu hw	1st Floor-Main Office	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor-Main Office	305	SF	6	\$305	
	Lighting - Pendent/Surface	1st Floor-Main Office	4	EA	7	\$0	
	Power Distribution	1st Floor-Main Office	10	EA	6	\$21,249	
	Storage/ Closet	1st Floor-Main Office	45	SF	6	\$326	
	Walls - Concrete Block	1st Floor-Main Office	629	SF	6	\$1,844	
	Ceiling - Splined	1st Floor-Teacher's Lounge	228	SF	6	\$186	
	Doors - Wood Doors inclu hw	1st Floor-Teacher's Lounge	3	EA	6	\$903	
	Floor - Tile/Sheet	1st Floor-Teacher's Lounge	228	SF	6	\$228	
	Lighting - Pendent/Surface	1st Floor-Teacher's Lounge	4	EA	7	\$0	
	Power Distribution	1st Floor-Teacher's Lounge	10	EΑ	7	\$0	
	Walls - Concrete Block	1st Floor-Teacher's Lounge	527	SF	6	\$1,545	
Kitcher	1						
	Ceiling - Lay-in	1st Floor	360	SF	6	\$1,081	
	Doors - Steel Doors incl hw	1st Floor	2	EΑ	6	\$602	
	Floor - Tile/Sheet	1st Floor	360	SF	6	\$360	
	Lighting - Lay-in	1st Floor	6	EΑ	7	\$0	
	Storage/ Closet	1st Floor	104	SF	6	\$754	Dry Storage
	Walls - Metal Panel	1st Floor	663	SF	6	\$4,949	Vinyl Panel
Lunch	& Multipurpose Room						
	Ceiling - Lay-in	1st Floor	1,229	SF	5	\$7,311	Water damage
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Floor - Epoxy/ Painted	1st Floor	1,229	SF	5	\$2,109	Water damage



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

ıp	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
:h &	& Multipurpose Room						
	Lighting - Lay-in	1st Floor	18	EA	7	\$0	
	Ceiling - Lay-in	1st Floor-Serving Area	152	SF	6	\$456	
	Doors - Steel Doors incl hw	1st Floor-Serving Area	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor-Serving Area	152	SF	6	\$152	
	Lighting - Lay-in	1st Floor-Serving Area	3	EA	7	\$0	
	Serving Line	1st Floor-Serving Area	10	LF	6	\$595	
	Walls - Metal Panel	1st Floor-Serving Area	442	SF	6	\$3,299	FRP Panel
	Serving Line	1st Floor	14	LF	6	\$833	
	Walls - Concrete Block	1st Floor	1,275	SF	6	\$3,738	
_IDI	F						
	AC Unit	1st Floor-Within Classroom 113	1	EA	5	\$1,826	Not plugged in or running, room was warm
	Doors - Steel Doors incl hw	1st Floor-Within Classroom 113	1	EA	6	\$301	
hani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	43	SF	5	\$694	Water leakage, missing door hardware
	Storage Room	1st Floor	48	SF	5	\$774	Door is broke, water is on floor-seepage
	Storage Room	1st Floor	53	SF	6	\$380	
	Boiler Room	Basement-Boiler Room	913	SF	6	\$6,541	Door missing hardware
	Crawl Space - Unfinished	Basement-Boiler Room	5,760	SF	6	\$35,665	
	Interior Stairs	Basement-Boiler Room	5	LF	6	\$45	
roo	om						
	Accessories	1st Floor	240	SF	6	\$2,214	
	Accessories	1st Floor	270	SF	6	\$2,490	
	Ceiling - Plaster/Drywall	1st Floor	240	SF	6	\$831	
	Ceiling - Plaster/Drywall	1st Floor	270	SF	6	\$934	
	Accessories	1st Floor-Classroom 110	30	SF	6	\$277	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 110	30	SF	6	\$104	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 110	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor-Classroom 110	30	SF	6	\$30	
	Lavatory	1st Floor-Classroom 110	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-Classroom 110	1	EA	7	\$0	
	Walls - Concrete Block	1st Floor-Classroom 110	187	SF	6	\$548	
	Water Closet	1st Floor-Classroom 110	1	EA	6	\$336	
	Accessories	1st Floor-Classroom 112	30	SF	6	\$277	
	Ceiling - Plaster/Drywall	1st Floor-Classroom 112	30	SF	6	\$104	
	Doors - Wood Doors inclu hw	1st Floor-Classroom 112	1	EA	5	\$1,174	Cracked glass
	2 00.0	.S.T IOOT OIGOOTOOTT TIE			•	Ψ1,17	



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

Lavalary	oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lighting - Pendent/Surface	stroc	m						
Walts- Concrete Block 1st Floor-Classroom 112 187 SF 6 \$548 Water Closet 1st Floor-Classroom 112 1 E.A. 6 \$336 Accessories 1st Floor-Classroom 113 27 SF 6 \$249 Celling - Plaster/Dywell 1st Floor-Classroom 113 27 SF 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 113 1 EA 6 \$27 Lavatory 1st Floor-Classroom 113 1 EA 6 \$22 Lighting - Pendent/Surface 1st Floor-Classroom 113 1 EA 6 \$22 Walis - Concrete Block 1st Floor-Classroom 113 1 EA 6 \$306 Waler Closet 1st Floor-Classroom 114 30 SF 6 \$277 Celling - Plaster/Dywell 1st Floor-Classroom 114 1 EA 6 \$301 Doors - Wood Doors inclu hw 1st Floor-Classroom 114 1 EA 6 \$301 Hoor - Tile/Sheet 1st Floor-Classroom 116		Lavatory	1st Floor-Classroom 112	1	EA	6	\$320	
Water Closes		Lighting - Pendent/Surface	1st Floor-Classroom 112	1	EA	7	\$0	
Accessories		Walls - Concrete Block	1st Floor-Classroom 112	187	SF	6	\$548	
Celling - Plaster/Dywall		Water Closet	1st Floor-Classroom 112	1	EA	6	\$336	
Doors - Wood Doors inclut hw		Accessories	1st Floor-Classroom 113	27	SF	6	\$249	
Floor - Tile/Sheet		Ceiling - Plaster/Drywall	1st Floor-Classroom 113	27	SF	6	\$93	
Lavatory		Doors - Wood Doors inclu hw	1st Floor-Classroom 113	1	EA	6	\$301	
Lighting - Pendent/Surface 1st Floor-Classroom 113 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 113 1 EA 6 \$488 Waler Closet 1st Floor-Classroom 113 1 EA 6 \$336 Accessories 1st Floor-Classroom 114 30 SF 6 \$277 Celling - Plaster/Drywall 1st Floor-Classroom 114 1 EA 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 114 1 EA 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 114 1 EA 6 \$30 Lavatory 1st Floor-Classroom 114 1 EA 6 \$32 Walls - Concrete Block 1st Floor-Classroom 114 187 SF 6 \$548 Water Closet 1st Floor-Classroom 116 18 SF 6 \$548 Water Closet 1st Floor-Classroom 116 18 SF 6 \$62 Doors - Wood Doors inclu hw 1st Floor-Classroom 116 1		Floor - Tile/Sheet	1st Floor-Classroom 113	27	SF	6	\$27	
Walls - Concrete Block 1st Floor-Classroom 113 170 SF 6 \$498 Water Closet 1st Floor-Classroom 114 30 SF 6 \$2277 Ceiling - Plaster/Drywall 1st Floor-Classroom 114 30 SF 6 \$210 Doors - Wood Doors inclu hw 1st Floor-Classroom 114 1 EA 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 114 30 SF 6 \$30 Lavatory 1st Floor-Classroom 114 1 EA 6 \$320 Lighting - Pendent/Surface 1st Floor-Classroom 114 1 EA 6 \$320 Walls - Concrete Block 1st Floor-Classroom 114 187 SF 6 \$548 Water Closet 1st Floor-Classroom 116 18 SF 6 \$166 Cailing - Plaster/Drywall 1st Floor-Classroom 116 18 SF 6 \$166 Cailing - Plaster/Drywall 1st Floor-Classroom 116 1 EA 6 \$301 Doors - Wood Doors inclu hw 1st Floor		Lavatory	1st Floor-Classroom 113	1	EA	6	\$320	
Water Closet 1st Floor-Classroom 113 1 EA 6 \$336 Accessories 1st Floor-Classroom 114 30 SF 6 \$277 Ceiling - Plaster/Drywall 1st Floor-Classroom 114 30 SF 6 \$104 Doors - Wood Doors inclu hw 1st Floor-Classroom 114 1 EA 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 114 1 EA 6 \$300 Lavatory 1st Floor-Classroom 114 1 EA 5 \$30 Lighting - Pendent/Surface 1st Floor-Classroom 114 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 114 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 116 18 SF 6 \$548 Water Closet 1st Floor-Classroom 116 18 SF 6 \$62 Doors - Wood Doors inclu hw 1st Floor-Classroom 116 18 SF 6 \$20 Elighting - Pendent/Surface 1st Floor-Classroom 116		Lighting - Pendent/Surface	1st Floor-Classroom 113	1	EA	7	\$0	
Accessories		Walls - Concrete Block	1st Floor-Classroom 113	170	SF	6	\$498	
Ceiling - Plaster/Drywall 1st Floor-Classroom 114 30 SF 6 \$104 Doors - Wood Doors inclu hw 1st Floor-Classroom 114 1 EA 6 \$301 Floor - Tille/Sheet 1st Floor-Classroom 114 30 SF 6 \$30 Lavatory 1st Floor-Classroom 114 1 EA 6 \$320 Lighting - Pendent/Surface 1st Floor-Classroom 114 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 114 187 SF 6 \$548 Water Closet 1st Floor-Classroom 116 18 SF 6 \$336 Accessories 1st Floor-Classroom 116 18 SF 6 \$166 Ceiling - Plaster/Drywall 1st Floor-Classroom 116 1 EA 6 \$301 Doors - Wood Doors inclu hw 1st Floor-Classroom 116 1 EA 6 \$301 Lighting - Pendent/Surface 1st Floor-Classroom 116 1 EA 7 \$0 Walls - Concrete Block 1st Floor Classr		Water Closet	1st Floor-Classroom 113	1	EA	6	\$336	
Doors		Accessories	1st Floor-Classroom 114	30	SF	6	\$277	
Floor - Tile/Sheet		Ceiling - Plaster/Drywall	1st Floor-Classroom 114	30	SF	6	\$104	
Lavatory 1st Floor-Classroom 114 1 EA 6 \$320 Lighting - Pendent/Surface 1st Floor-Classroom 114 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 114 187 SF 6 \$548 Water Closet 1st Floor-Classroom 114 1 EA 6 \$336 Accessories 1st Floor-Classroom 116 18 SF 6 \$166 Ceiling - Plaster/Drywall 1st Floor-Classroom 116 18 SF 6 \$62 Doors - Wood Doors inclu hw 1st Floor-Classroom 116 1 EA 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 116 18 SF 6 \$18 Lighting - Pendent/Surface 1st Floor-Classroom 116 18 SF 6 \$18 Walls - Concrete Block 1st Floor-Classroom 116 1 EA 7 \$0 Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Water Closet 1st Floor-Classroom 116 1		Doors - Wood Doors inclu hw	1st Floor-Classroom 114	1	EA	6	\$301	
Lighting - Pendent/Surface 1st Floor-Classroom 114 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 114 187 SF 6 \$548 Water Closet 1st Floor-Classroom 114 1 EA 6 \$336 Accessories 1st Floor-Classroom 116 18 SF 6 \$166 Ceiling - Plaster/Drywall 1st Floor-Classroom 116 1 EA 6 \$301 Floor - Wood Doors inclu hw 1st Floor-Classroom 116 1 EA 6 \$301 Floor - Tille/Sheet 1st Floor-Classroom 116 1 EA 6 \$301 Lighting - Pendent/Surface 1st Floor-Classroom 116 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 116 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 116 1 EA 7 \$0 Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Steel Doors incl hw <td></td> <td>Floor - Tile/Sheet</td> <td>1st Floor-Classroom 114</td> <td>30</td> <td>SF</td> <td>6</td> <td>\$30</td> <td></td>		Floor - Tile/Sheet	1st Floor-Classroom 114	30	SF	6	\$30	
Walls - Concrete Block 1st Floor-Classroom 114 187 SF 6 \$548 Water Closet 1st Floor-Classroom 114 1 EA 6 \$336 Accessories 1st Floor-Classroom 116 18 SF 6 \$166 Ceiling - Plaster/Drywall 1st Floor-Classroom 116 18 SF 6 \$62 Doors - Wood Doors inclu hw 1st Floor-Classroom 116 1 EA 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 116 18 SF 6 \$18 Lighting - Pendent/Surface 1st Floor-Classroom 116 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 116 1 EA 7 \$0 Water Closet 1st Floor-Classroom 116 1 EA 6 \$316 Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA		Lavatory	1st Floor-Classroom 114	1	EA	6	\$320	
Water Closet 1st Floor-Classroom 114 1 EA 6 \$336 Accessories 1st Floor-Classroom 116 18 SF 6 \$166 Ceiling - Plaster/Drywall 1st Floor-Classroom 116 18 SF 6 \$62 Doors - Wood Doors inclu hw 1st Floor-Classroom 116 1 EA 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 116 18 SF 6 \$18 Lighting - Pendent/Surface 1st Floor-Classroom 116 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 116 1 EA 7 \$0 Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF		Lighting - Pendent/Surface	1st Floor-Classroom 114	1	EA	7	\$0	
Accessories 1st Floor-Classroom 116 18 SF 6 \$166 Ceiling - Plaster/Drywall 1st Floor-Classroom 116 18 SF 6 \$62 Doors - Wood Doors inclu hw 1st Floor-Classroom 116 1 EA 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 116 18 SF 6 \$18 Lighting - Pendent/Surface 1st Floor-Classroom 116 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 116 176 SF 6 \$516 Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor Tile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2		Walls - Concrete Block	1st Floor-Classroom 114	187	SF	6	\$548	
Ceiling - Plaster/Drywall 1st Floor-Classroom 116 18 SF 6 \$62 Doors - Wood Doors inclu hw 1st Floor-Classroom 116 1 EA 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 116 18 SF 6 \$18 Lighting - Pendent/Surface 1st Floor-Classroom 116 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 116 1 EA 6 \$516 Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 2 EA 6		Water Closet	1st Floor-Classroom 114	1	EA	6	\$336	
Doors - Wood Doors inclu hw 1st Floor-Classroom 116 1 EA 6 \$301 Floor - Tile/Sheet 1st Floor-Classroom 116 18 SF 6 \$18 Lighting - Pendent/Surface 1st Floor-Classroom 116 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 116 1 EA 6 \$516 Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor Trile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Accessories	1st Floor-Classroom 116	18	SF	6	\$166	
Floor - Tile/Sheet 1st Floor-Classroom 116 18 SF 6 \$18 Lighting - Pendent/Surface 1st Floor-Classroom 116 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 116 176 SF 6 \$516 Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Ceiling - Plaster/Drywall	1st Floor-Classroom 116	18	SF	6	\$62	
Lighting - Pendent/Surface 1st Floor-Classroom 116 1 EA 7 \$0 Walls - Concrete Block 1st Floor-Classroom 116 176 \$F 6 \$516 Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 240 \$F 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 270 \$F 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Doors - Wood Doors inclu hw	1st Floor-Classroom 116	1	EA	6	\$301	
Walls - Concrete Block 1st Floor-Classroom 116 176 SF 6 \$516 Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Floor - Tile/Sheet	1st Floor-Classroom 116	18	SF	6	\$18	
Water Closet 1st Floor-Classroom 116 1 EA 6 \$336 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Lighting - Pendent/Surface	1st Floor-Classroom 116	1	EA	7	\$0	
Doors - Steel Doors incl hw 1st Floor EA 6 \$301 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Walls - Concrete Block	1st Floor-Classroom 116	176	SF	6	\$516	
Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Water Closet	1st Floor-Classroom 116	1	EA	6	\$336	
Floor Drain 1st Floor 1 EA 6 \$1,059 Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
Floor Drain 1st Floor 1 EA 6 \$1,059 Floor - Tile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
Floor - Tile Ceramic/ Porcelain 1st Floor 240 SF 6 \$508 Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Floor Drain	1st Floor	1	EA	6	\$1,059	
Floor - Tile Ceramic/ Porcelain 1st Floor 270 SF 6 \$571 Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Floor Drain	1st Floor	1	EA	6	\$1,059	
Lavatory 1st Floor 2 EA 6 \$639 Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Floor - Tile Ceramic/ Porcelain	1st Floor	240	SF	6	\$508	
Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Floor - Tile Ceramic/ Porcelain	1st Floor	270	SF	6	\$571	
Lavatory 1st Floor 2 EA 6 \$639 Lighting - Pendent/Surface 1st Floor 3 EA 7 \$0		Lavatory	1st Floor	2	EA	6	\$639	
			1st Floor	2	EA	6	\$639	
Lighting - Pendent/Surface 1st Floor 3 EA 6 \$372		Lighting - Pendent/Surface	1st Floor	3	EA	7	\$0	
		Lighting - Pendent/Surface	1st Floor	3	EA	6	\$372	



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	m						
	Partitions	1st Floor	2	EA	6	\$594	
	Partitions	1st Floor	4	EA	6	\$1,188	
	Accessories	1st Floor-Staff Restroom	43	SF	6	\$397	
	Ceiling - Plaster/Drywall	1st Floor-Staff Restroom	43	SF	6	\$149	
	Doors - Wood Doors inclu hw	1st Floor-Staff Restroom	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor-Staff Restroom	43	SF	6	\$43	
	Lavatory	1st Floor-Staff Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-Staff Restroom	2	EA	7	\$0	
	Partitions	1st Floor-Staff Restroom	1	EA	6	\$297	
	Walls - Concrete Block	1st Floor-Staff Restroom	238	SF	6	\$698	
	Water Closet	1st Floor-Staff Restroom	1	EA	5	\$1,344	Not working
	Urinals	1st Floor	3	EA	6	\$1,008	
	Walls - Concrete Block	1st Floor	96	SF	6	\$281	
	Walls - Structural Glazed Tile	1st Floor	544	SF	6	\$1,711	
	Walls - Structural Glazed Tile	1st Floor	430	SF	6	\$1,353	
	Water Closet	1st Floor	4	EA	6	\$1,344	
	Water Closet	1st Floor	2	EA	6	\$672	
	Accessories	Basement-Boiler Room	35	SF	6	\$323	
	Ceiling - Plaster/Drywall	Basement-Boiler Room	35	SF	6	\$121	
	Doors - Wood Doors inclu hw	Basement-Boiler Room	1	EA	6	\$301	
	Floor - Tile/Sheet	Basement-Boiler Room	35	SF	6	\$35	
	Lavatory	Basement-Boiler Room	1	EΑ	6	\$320	
	Lighting - Pendent/Surface	Basement-Boiler Room	1	EΑ	7	\$0	
	Walls - Concrete Block	Basement-Boiler Room	205	SF	6	\$601	
	Water Closet	Basement-Boiler Room	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$154,435

Building: Branch

Category: Building Interior

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
orridor						
Ceiling - Lay-in	1st Floor	1,670	SF	5	\$11,009	Water damage
Doors - Store Front	1st Floor	6	EA	6	\$7,249	
Drinking Fountains - Double Fountain	1st Floor	1	EA	6	\$336	
Drinking Fountains - Single Fountain	1st Floor	1	EA	6	\$276	
Floor - Tile Ceramic/ Porcelain	1st Floor	151	SF	5	\$2,412	Cracking



9928 S Crandon Ave Chicago, IL 60617

Building: Branch

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Floor - Tile/Sheet	1st Floor	1,670	SF	5	\$7,499	Water damage, cracking
	Lighting - Lay-in	1st Floor	26	EA	7	\$0	
	Walls - Concrete Block	1st Floor	2,876	SF	5	\$29,529	Water damage, cracking
	Walls - Masonry	1st Floor	159	SF	6	\$500	
	Walls - Tile Ceramic/ Porcelain	1st Floor	354	SF	6	\$1,114	
Safety							
	Camera Viewing Station		1	EA	6	\$683	
	Security Cameras		1	EA	6	\$194	
Buildi	ing Interior Subtotal:					\$60,800	

Total Building Cost \$1,434,013

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Civil/Dr	ainage						
	Civil/ Drainage - Catch Basin	Entire Site-Branch	3	EA	6	\$3,282	
	Civil/ Drainage - Catch Basin	Entire Site-Main	2	EA	5	\$5,140	Clogged-Location: 1 at SW, 1 at NW
	Civil/ Drainage - Catch Basin	Entire Site-Main	8	EA	7	\$0	
	Civil/ Drainage - Site Drain	Entire Site-Main	2	EA	5	\$2,758	Clogged-Location: 1 NW basement walls, 1 W basement walls
	Civil/ Drainage - Site Drain	Entire Site-Main	1	EA	6	\$310	Location: SE
	Civil/ Drainage - Site Manhole	Entire Site-Main	7	EA	6	\$10,449	
Fencing	1						
	Fencing - Chain Link	Entire Site-Branch	736	LF	6	\$13,819	
	Fencing - Chain Link	Entire Site-Branch / East	50	LF	5	\$3,049	Missing post, broken, loose chains
	Fencing - Chain Link	Entire Site-Branch / West	50	LF	5	\$3,049	Missing post, broken, loose chains
	Fencing - Chain Link	Entire Site-Main	30	LF	5	\$1,830	Bent and leaning-Location: SW
	Fencing - Chain Link	Entire Site-Main / Entire Site	1,195	LF	6	\$22,437	
	Fencing - New Standard Ornamental	Entire Site-Main	90	LF	6	\$2,871	Location: Door #1, sloped walk
Landsc	ape						
	Landscape - Grass	Entire Site-Branch	11,588	SF	6	\$9,611	
	Landscape - Grass	Entire Site-Main / East	11,890	SF	6	\$9,862	
	Landscape - Hardscape- Concrete	Entire Site-Main	120	SF	6	\$729	Loading dock



9928 S Crandon Ave Chicago, IL 60617

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Landsc	аре									
	Landscape - Hardscape- Concrete	Entire Site-Main / North	275	SF	5	\$2,572	Cracks and pitting			
	Parkway trees	Entire Site-Branch	18	EA	6	\$11,881				
	Parkway trees	Entire Site-Main / East	1	EA	4	\$2,624	Missing			
	Parkway trees	Entire Site-Main / East	8	EA	6	\$5,280				
	Parkway trees	Entire Site-Main / North	6	EΑ	6	\$3,960				
	Parkway trees	Entire Site-Main / South	8	EA	6	\$5,280				
	Parkway trees	Entire Site-Main / West	14	EA	6	\$9,241				
	Parkway trees	Entire Site-Main / West		2 EA 4		\$5,248	Missing			
	Play Area - Asphalt/ Hardscape	Entire Site-Branch / South	42,280	2,280 SF 6		\$102,178				
	Play Area - Asphalt/ Hardscape	Entire Site-Branch / South	320	SF	4	\$3,391	Cracks and uneven			
	Play Area - Asphalt/ Hardscape	Entire Site-Main / North	24,300 SF		5	\$126,834	Water ponding and cracks			
	Play Area - Asphalt/ Hardscape	Entire Site-Main / South	32,025	SF	5	\$167,154	Cracks			
	Play Area - Asphalt/ Hardscape	Entire Site-Main / West	15,868	SF	5	\$82,823	Cracks			
	Retaining Wall - Concrete	Entire Site-Branch / North Entrances	90	SF	5	\$5,667	Cracks			
	Retaining Wall - Concrete	Entire Site-Branch / South Entrances	90	SF	5	\$5,667	Cracks			
	Retaining Wall - Concrete	Entire Site-Main / North West	150		6	\$4,151	Location: Basement stairs; Some cracks at previous repair			
	Retaining Wall - Concrete	Entire Site-Main / South East	270	SF	6	\$7,471				
	Retaining Wall - Concrete	Entire Site-Main / West	270	SF	5	\$17,000	Location: Basement; horizontal cracks			
	Trash Receptacles	Entire Site-Main	5	EA	6	\$1,561	Location: West of Addition #2			
Parking	J Lot									
	Concrete Curbs	North Lot-Branch	140	LF	6	\$1,798				
	Concrete Curbs	North West Lot-Branch	225	LF	6	\$2,889				
	Surface - Asphalt	North West Lot-Branch	3,695	SF	6	\$8,930				
	Surface - Asphalt	West-Main / West	13,862	SF	5	\$63,234	Cracks			
	Surface - Concrete	North Lot-Branch	1,255	SF	6	\$3,033				
Playgro	ound									
	Equipment - School Age 5-12	North East-Main	1	EA	6	\$3,546				
	Equipment - School Age 5-12	South-Branch	1	EA	6	\$3,546	Graffiti			
	Surface - Poured Surface	North East-Main	2,860	SF	6	\$20,940				
	Surface - Square Rubber Mats	South-Branch	2,294	SF	6	\$12,367				
Sidewa	lks									
	Sidewalks - Internal Walks	Entire Site-Branch	20	LF	5	\$1,155	Location: at Door #7; cracks and pitting			
	Sidewalks - Internal Walks	Entire Site-Branch	325	LF	6	\$3,904				
	Sidewalks - Internal Walks	Entire Site-Branch / North Entrances	90	LF	5	\$4,485	Cracks and pitting			
	Sidewalks - Internal Walks	Entire Site-Main	40	LF	5	\$2,311	Location: Door #4; cracks			
DUDAII		D 50 -1 57					A 7/0/44			



9928 S Crandon Ave Chicago, IL 60617

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Sidewal	dewalks									
	Sidewalks - Internal Walks	Entire Site-Main	20	LF	5	\$1,155	Location: Door #6; cracks			
	Sidewalks - Internal Walks	Entire Site-Main	10	LF	5	\$578	Location: Door #2; cracks and pitting			
	Sidewalks - Internal Walks	Entire Site-Main	10 400	LF	5	\$578	Location: Door #3; cracks			
	Sidewalks - Internal Walks	Entire Site-Main / Entire Site		LF	6	\$4,805				
	Sidewalks - Perimeter Sidewalks	Entire Site-Branch	888	SF	6	\$1,765				
	Sidewalks - Perimeter Sidewalks	Entire Site-Main / East	200	SF	5	\$1,910	Cracks and pitting			
	Sidewalks - Perimeter Sidewalks	Entire Site-Main / Entire Site	3,406	SF	6	\$6,770				
Signage	9									
	Flag Pole - Building Mounted Flag Pole	East-Main / East	1	EA	6	\$828				
	Flag Pole - Flag Pole	North-Branch / North	1	EΑ	6	\$1,657				
	Marquee - Building Mounted Back Lighted	North-Branch / North	1	EΑ	6	\$0	Cut/Etched on Facade			
	Marquee - Free Standing Back Lighted	East-Main / East	1	EA	6	\$0				
	Marquee - Free Standing Back Lighted	East-Main / South East	1	EA	6	\$0				
Site S	ubtotal:				•	\$811,365				
Total	Site Cost				•	\$811,365				

Campus Total ^{2 3}	\$7,284,237
-----------------------------	-------------

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.



9928 S Crandon Ave Chicago, IL 60617

- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Burnham Elementary Inclusive Academy 9928 S Crandon Ave Chicago, IL 60617

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart Board
Main		+		-		-	!					!		1
Art Room	Laboratory/Shop	2nd Floor	211	211	695	0	1	14	84	42	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	110	110	690	1	1	8	159	29	40	N	N	Υ
Regular Classroom	Regular Classroom	1st Floor	112	112	690	1	1	8	156	29	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	114	114	690	1	1	8	156	29	40	N	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	696	1	2	6	84	42	40	N	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	214	214	696	1	2	8	84	42	40	N	Υ	Υ
Science Classroom	Laboratory/Shop	2nd Floor	213	213	650	0	1	24	84	42	40	N	Υ	Υ
Special Education	Regular Classroom	2nd Floor	210	210	696	1	2	4	84	42	40	N	Υ	Υ
Special Education	Regular Classroom	2nd Floor	215	215	688	2	1	8	84	42	40	N	Υ	Υ
Addition 1														
Computer Lab	Other Instructional Use	2nd Floor	218	218	1,088	0	2	20	243	121	40	N	Υ	Υ
Library	Library	2nd Floor	219	219	1,069	0	1	6	243	121	40	N	N	N
Pre School	Pre School	1st Floor	117	117	906	1	1	6	207	39	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	115	115	690	1	0	6	156	29	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	116	116	690	1	0	6	156	29	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	118	118	690	1	0	6	156	29	40	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	688	1	3	8	324	162	40	N	Υ	Υ
Addition 2														
Regular Classroom	Regular Classroom	2nd Floor	220	220	730	2	2	8	324	162	40	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	221	221	696	2	1	32	324	162	40	N	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	222	222	730	2	2	8	324	162	40	N	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	223	223	730	2	1	8	324	162	40	N	Υ	N
Addition 3														
Kindergarten	Regular Classroom	1st Floor	108	108	690	1	1	8	162	81	40	N	N	Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	781	2	1	8	243	117	40	N	N	Υ
Regular Classroom	Regular Classroom	1st Floor	107	107	690	1	1	8	162	81	40	N	N	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	690	1	2	14	156	29	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	713	2	2	8	84	42	40	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	730	2	2	8	84	42	40	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	696	2	2	8	84	42	40	N	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	696	2	2	8	84	42	40	N	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	685	2	2	40	84	42	40	N	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	688	2	2	8	84	42	40	N	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	685	2	2	8	84	42	40	N	Υ	Υ



Regular Classroom

1st Floor

1st Floor

1st Floor

1st Floor

111

112

113

114

Burnham Elementary Inclusive Academy

9928 S Crandon Ave Chicago, IL 60617

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Addition 3				•		•		'			*	•		*
Regular Classroom	Regular Classroom	2nd Floor	209	209	688	2	2	8	84	42	40	N	Υ	Υ
Science Classroom	Science Classroom	1st Floor	103	103	1,078	0	1	12	182	56	40	N	N	N
Branch														
Kindergarten	Regular Classroom	1st Floor	116		1,246	2	1	8	234	117	40	N	N	N
Regular Classroom	Regular Classroom	1st Floor	109		1,005	2	2	6	234	117	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	110		1,005	2	2	6	234	117	40	N	Υ	N

1,005

1,005

774

1,005

2

2

2

2

2

2

13

2

6

6

14

6

234

234

234

234

117

117

117

117

40

40

40

40

Ν

Ν

Ν

Ν

Υ

Υ

Υ

Υ

Ν

Ν

Ν

Ν