2745 W Roosevelt Rd Chicago, IL 60608

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1959 | 2 | 56,732 | \$2,758,778 |
| Addition | 1963 | 2 | 11,452 | \$514,487 |
| SITE | | | | \$343,240 |
| Campus Total | | | 68,184 | \$3,616,504 |

Building: Main

Category: Building Exterior

| | ory. Dunaning Exterior | | | | | | |
|---------|--------------------------------------|--------------------------------|----------|------|------|---------|------------------|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Entrand | e | | | | | | |
| | Entrance Control - Audio and Video | #1- Main Accessible- NE | 1 | EA | 6 | \$702 | |
| | Entrance Control - Audio and Video | #6 - SE | 1 | EA | 6 | \$702 | |
| | Exterior Doors - Exterior Steel Door | #4.1- Boiler Room- SW | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | #4.1- ComEd Vault Entrance- SW | 1 | EA | 4 | \$3,823 | Ripped off frame |
| | Exterior Doors - Exterior Steel Door | #9- NE | 2 | EΑ | 6 | \$961 | |
| | Exterior Doors - Side lite | #1- Main Accessible- NE | 2 | EΑ | 6 | \$627 | |
| | Exterior Doors - Side lite | #10- SW | 1 | EΑ | 6 | \$313 | |
| | Exterior Doors - Side lite | #11- SW | 1 | EΑ | 6 | \$313 | |
| | Exterior Doors - Side lite | #2- NW | 2 | EΑ | 6 | \$627 | |
| | Exterior Doors - Side lite | #3- SW | 2 | EΑ | 6 | \$627 | |
| | Exterior Doors - Side lite | #4- SW | 2 | EΑ | 6 | \$627 | |
| | Exterior Doors - Side lite | #5- SW | 2 | EΑ | 6 | \$627 | |
| | Exterior Doors - Side lite | #6 - SE | 2 | EΑ | 6 | \$627 | |
| | Exterior Doors - Store Front | #1- Main Accessible- NE | 2 | EΑ | 6 | \$1,092 | |
| | Exterior Doors - Store Front | #10- SW | 1 | EA | 6 | \$546 | |
| | Exterior Doors - Store Front | #11- SW | 1 | EA | 6 | \$546 | |
| | Exterior Doors - Store Front | #2- NW | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | #3- SW | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | #4- SW | 2 | EΑ | 6 | \$1,092 | |
| | | | | | | | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

Category: Building Exterior

| | , o. y aag | | | | | | |
|---------|---------------------------------------|---------------------------------|----------|------|------|-----------|--|
| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Entran | ce | | | | | | |
| | Exterior Doors - Store Front | #5- SW | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | #6 - SE | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Transom Lite | #10- SW | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | #11- SW | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | #2- NW | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | #3- SW | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | #4- SW | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | #5- SW | 2 | EA | 6 | \$627 | |
| | Exterior Stairs - Concrete | #4.1- Boiler Room- SW | 80 | LF | 5 | \$8,766 | Spalling |
| | Exterior Stairs - Concrete | #5- SW | 25 | LF | 5 | \$2,740 | Spalling & cracks |
| | Stair Handrail - Steel_Stair Handrail | #4.1- Boiler Room- SW | 27 | LF | 6 | \$234 | |
| | Stair Handrail - Steel_Stair Handrail | #4.1- Boiler Room- SW | 20 | LF | 4 | \$3,005 | missing |
| Founda | ation | | | | | | |
| | Foundation - Concrete | Entire Building | 931 | LF | 7 | \$0 | cracks at surface patches |
| | Foundation - Concrete | Entire Building | 10 | LF | 6 | \$1,942 | exposed steel, spalling, efflorescence |
| | Foundation - Concrete | Entire Building | 5 | LF | 6 | \$971 | seepage |
| | Foundation - Concrete | Entire Building | 5 | LF | 6 | \$971 | seepage |
| | Foundation - Concrete | Entire Building / Boiler Room | 10 | LF | 6 | \$1,942 | seepage |
| | Foundation - Concrete | Entire Building / Façade- SW | 3 | LF | 6 | \$0 | spalling |
| | Superstructure - Concrete | Entire Building | 56,732 | SF | 7 | \$0 | |
| Lightin | g | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 14 | EA | 6 | \$4,042 | repair lenses, change bulbs |
| Roof S | ystem | | | | | | |
| | Chimney - Metal Flue | Main W roof | 42 | LF | 6 | \$6,642 | |
| | Coping - Metal | Main E roof | 234 | LF | 6 | \$7,516 | |
| | Coping - Metal | Main W roof | 626 | LF | 6 | \$20,106 | |
| | Downspouts - Interior Downspouts | Main E roof | 48 | LF | 6 | \$1,595 | |
| | Downspouts - Interior Downspouts | Main W roof | 96 | LF | 6 | \$3,190 | |
| | Roof Structure - Concrete | Main E roof | 9,469 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | Main W roof | 16,737 | SF | 7 | \$0 | |
| | Roof - Asphalt Gravel Ballast | Main E roof | 9,469 | SF | 4 | \$265,397 | water ponding, severe blistering |
| | Roof - Asphalt Gravel Ballast | Main W roof | 16,737 | SF | 4 | \$469,105 | water ponding, severe blistering |
| Walls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building | 224 | SF | 6 | \$8,210 | |
| | Canopy - Concrete/ Stucco | Entire Building / Main Entrance | 224 | SF | 6 | \$8,210 | |
| | | | | | | | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|-------------------------------|----------|------|------|----------|---|
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 7,832 | SF | 6 | \$52,639 | some open joints |
| Windov | vs | | | | | | |
| | Curtain wall - Glazed Double Pane | Entire Building | 7,924 | SF | 6 | \$88,838 | |
| | Curtain wall - Insulated Panel | Entire Building | 3,102 | SF | 6 | \$34,777 | |
| | Curtain wall - Insulated Panel | Entire Building | 866 | SF | 3 | \$86,365 | allows water in during heavy rain - not visible at time of site visit |
| | Curtain wall - Insulated Panel | Entire Building | 5 | SF | 4 | \$0 | missing panel |
| | Curtain wall - Insulated Panel | Entire Building / Façade- SW | 5 | SF | 5 | \$0 | loose metal framing |
| | Guard - Guards perforated | Entire Building | 2,808 | SF | 6 | \$35,858 | |
| | Lintels - Steel | Entire Building / Boiler Room | 6 | LF | 6 | \$174 | rust |
| | Windows - Casement Aluminum Double-pane | Entire Building | 980 | SF | 6 | \$7,315 | |
| | Windows - Casement Aluminum Double-pane | Entire Building | 60 | SF | 5 | \$3,232 | screwed shut due to vandalism damage |

Building Exterior Subtotal:

\$1,146,095

Building: Main

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------------------------|----------|------|------|----------|---|
| Emerge | ency System | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | \$408 | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 10,095 | SF | 6 | \$3,032 | |
| | Emergency A/C Power - Gym | Entire Building / 1st Floor | 3,768 | SF | 6 | \$1,401 | |
| | Emergency A/C Power - Lunchrooms | Entire Building / 1st Floor | 1,599 | SF | 6 | \$595 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 28 | EΑ | 6 | \$4,193 | |
| | Exit Signs - Gym | Entire Building / 1st Floor | 7 | EΑ | 6 | \$1,102 | |
| | Security System - CCTV | Entire Building | 56,732 | SF | 6 | \$17,037 | Also serves addition |
| | Security System - Intrusion Detection | Entire Building | 56,732 | SF | 6 | \$14,603 | Controller in boiler room. Also serves addition |
| Main Se | ervice | | | | | | |
| | Main Electrical Service - 2001 to 3000 A 120/208/3PH | Electrical Room | 1 | EA | 6 | \$10,867 | Also serves addition |
| | PA System | Entire Building | 56,732 | SF | 5 | \$38,941 | Also serves addition |
| Power I | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building / Boiler Room | 1 | EA | 6 | \$299 | Fused EMT panel |
| | Lighting and Power Panels - 100 A | Entire Building / Mechanical Room | 1 | EΑ | 6 | \$299 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 1 | EA | 6 | \$497 | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 9 | EΑ | 6 | \$4,473 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|--|-----------------------------------|----------|------|------|----------|--------------------|
| Power | Distribution | | | | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 6 | \$497 | Location: MDF room |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 6 | \$994 | Location: MDF room |
| | Lighting and Power Panels - Above 100 A | Entire Building / Mechanical Room | 1 | EA | 6 | \$497 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Boiler Room | 1 | EA | 6 | \$528 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Boiler Room | 1 | EA | 4 | \$13,694 | Corroding |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Boiler Room | 1 | EA | 6 | \$528 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Boiler Room | 1 | EA | 4 | \$13,694 | Corroding |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Boiler Room | 2 | EA | 6 | \$1,055 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Boiler Room | 1 | EA | 6 | \$1,265 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Electrical Room | 1 | EA | 6 | \$1,265 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Mechanical Room | 1 | EA | 6 | \$1,265 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Mechanical Room | 1 | EA | 6 | \$1,265 | |
| | | | | | | | |

Electrical System Subtotal:

\$134,293

Building: Main

Category: Safty System

| Group Item - Type | Location | Quantity Unit | Rank | Cost | Comments |
|--------------------------|-------------------------------|---------------|------|----------|--------------------------|
| Fire Alarm | | | | | |
| Fire Alarm Panel | Boiler Room | 1 EA | 6 | \$6,406 | Also serves the addition |
| Fire Alarm Strobe Lights | Boiler Room / Entire Building | 56,732 SF | 6 | \$20,282 | |
| Fire Alarm_System | Boiler Room / Entire Building | 56,732 SF | 6 | \$27,583 | |
| | | | | | |

Safty System Subtotal:

\$54,271

Building: Main

Category: Mechanical System

| oup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|------------------------|----------|------|------|---------|--------------------------|
| Conditioning | | | | | | |
| Chemical Pot Feeder | Roof / Boiler Room | 1 | EA | 6 | \$725 | |
| Chemical Pot Feeder | Roof / Mechanical Room | 1 | EA | 6 | \$725 | |
| Chiller-Air Cooled-Scroll Type-Roof Mounted - 50 - 100 tons | Roof | 2 | EA | 6 | \$7,317 | Also serves addition |
| Chiller-Air Cooled-Scroll Type-Roof Mounted - Less than 50 tons | Roof | 1 | EA | 6 | \$3,659 | Also serves the Addition |
| Glycol Feed | Roof / Boiler Room | 1 | EA | 6 | \$490 | |
| Glycol Feed | Roof / Mechanical Room | 1 | EA | 6 | \$490 | |
| Pipes - Chilled Water Pipe- Copper | Roof / Entire Building | 200 | LF | 6 | \$378 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--|---|----------|------|------|----------|--------------------------|
| Air Cor | ditioning | | | | | | |
| | Pipes - Chilled Water Pipe- Copper | Roof / Entire Building | 200 | LF | 6 | \$378 | |
| Air Han | dling Systems | | | | | | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm | Mechanical Room | 1 | EA | 5 | \$48,592 | Also serves the Addition |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm | Boiler Room | 1 | EA | 5 | \$91,262 | Also serves the Addition |
| | Air Intake | Boiler Room / Roof | 1 | EA | 6 | \$5,765 | |
| | Air Intake | Mechanical Room / Roof | 1 | EA | 6 | \$5,765 | |
| | Auxiliaries - 12001-20000 cfm | Mechanical Room | 1 | EA | 6 | \$0 | |
| | Auxiliaries - Greater than 30,000 cfm | Boiler Room | 1 | EA | 6 | \$0 | |
| | Fan Coil Unit- Celing Mounted - Electric | 2nd floor MDF Room / 2nd Floor | 1 | EA | 5 | \$3,591 | Location: MDF room |
| | Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM | Mechanical Room | 1 | EA | 5 | \$12,218 | Also serves the Addition |
| | Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM | Boiler Room | 1 | EA | 5 | \$16,255 | Also serves the Addition |
| | Zone Dampers | Boiler Room / Entire Building | 30 | EA | 6 | \$24,991 | |
| | Zone Dampers | Mechanical Room / Entire Building | 30 | EA | 6 | \$24,991 | |
| Boiler S | Systems | | | | | | |
| | Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH | Boiler Room | 2 | EA | 6 | \$4,093 | |
| | Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | \$725 | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | \$818 | |
| | Glycol Feed System | Boiler Room | 1 | EA | 6 | \$539 | |
| | Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH | Boiler Room | 2 | EA | 6 | \$1,996 | Also serves addition |
| Heat Ex | changers | | | | | | |
| | Heat Exchanger - Water to Water Plate Type | Mechanical Room | 1 | EA | 6 | \$0 | |
| Heating | Devices | | | | | | |
| | Unit Heater - Hot Water | 2nd Floor | 2 | EA | 5 | \$3,064 | |
| Mechai | nical Plumbing | | | | | | |
| | Chilled Water Pump - Less than 10 | Boiler and Mechancial Rooms / Boiler Room | 2 | EA | 6 | \$2,222 | |
| | Chilled Water Pump - Less than 10 | Boiler and Mechancial Rooms / Mechanical Room | 4 | EA | 6 | \$4,445 | |
| | Hot Water Pump - Less than 10 | Boiler and Mechanical Rooms / Boiler Room | 3 | EA | 6 | \$3,334 | |
| | Hot Water Pump - Less than 10 | Boiler and Mechanical Rooms / Boiler Room | 1 | EA | 5 | \$11,495 | |
| | | | | | | | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

Category: Mechanical System

| Mechanical | I Disposition of | | | | Rank | 0031 | Comments | | | | |
|-------------|--|---|--------|----|------|----------|----------|--|--|--|--|
| | echanical Plumbing | | | | | | | | | | |
| Ho | ot Water Pump - Less than 10 | Boiler and Mechanical Rooms / Mechanical Room | 2 | EA | 6 | \$2,222 | | | | | |
| Hy | dronic Supply and Return - Copper | Entire Building | 400 | LF | 5 | \$57,040 | | | | | |
| Нус | dronic Supply and Return - Galvanized | Entire Building | 400 | LF | 5 | \$83,792 | | | | | |
| Temperatur | emperature Control | | | | | | | | | | |
| DD | DC System | Entire Building | 56,732 | SF | 6 | \$32,451 | | | | | |
| The | nermostats - DDC | Entire Building / 1st Floor | 1 | EΑ | 4 | \$819 | | | | | |
| The | nermostats - DDC | Entire Building | 64 | EA | 6 | \$0 | | | | | |
| Ventilation | | | | | | | | | | | |
| Ext | rhaust Fans- Indoor - 1501 - 8000 CFM | Roof | 1 | EΑ | 6 | \$592 | | | | | |
| Ext | chaust Fans- Roof Mounted - 500 - 1500 CFM | Roof | 2 | EA | 6 | \$1,185 | | | | | |

Mechanical System Subtotal:

\$458,423

Building: Main

Category: Plumbing System

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|---|----------|------|------|----------|--|
| lot Wa | ter | | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 6 | \$310 | Serves also the addition |
| | Hot Water Storage Tank_Gas - 201 - 500 Gallons | Boiler Room | 2 | EA | 6 | \$1,357 | Location: boiler room, mechanical room. Serves also the addiiton |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 56,732 | SF | 6 | \$11,358 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 56,732 | SF | 6 | \$13,792 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 56,732 | SF | 6 | \$10,546 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 56,732 | SF | 6 | \$8,924 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 56,732 | SF | 6 | \$10,546 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 56,732 | SF | 6 | \$8,113 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 56,732 | SF | 6 | \$8,113 | |
| | Sanitary Piping | Entire Building | 56,732 | SF | 6 | \$51,921 | |
| | Storm Piping | Entire Building | 56,732 | SF | 6 | \$49,487 | |
| | Vent Piping | Entire Building | 56,732 | SF | 6 | \$38,130 | |
| Pumps | | | | | | | |
| | Pumps - Ejector-Duplex | Boiler and Mechancial Rooms / Boiler Room | 1 | EA | 4 | \$15,749 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost Comments |
|-------|---------------------|---|----------|------|------|---------------|
| Pumps | | | | | | |
| | Pumps - Sump-Duplex | Boiler and Mechancial Rooms / Mechanical Room | 1 | EA | 5 | \$7,535 |

Plumbing System Subtotal: \$235,881

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|----------|
| Classro | oom #101 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 1st Floor | 858 | SF | 6 | \$1,276 | |
| | Doors - Side-lite | 1st Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 858 | SF | 6 | \$1,877 | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 1st Floor | 1,148 | SF | 6 | \$3,365 | |
| Classro | oom #102 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 1st Floor | 858 | SF | 7 | \$0 | |
| | Doors - Side-lite | 1st Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 858 | SF | 6 | \$1,877 | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 6 | \$2,602 | |
| | Marker Board | 1st Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 40 | SF | 6 | \$290 | |
| Classro | oom #103 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 1st Floor | 858 | SF | 6 | \$1,276 | |
| | Doors - Side-lite | 1st Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 858 | SF | 6 | \$1,877 | |
| | | | | | | | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------------------|---|---|--|------|---------|--|
| oom #103 (Regular Classroom) | | | | | | |
| Lighting - Pendent/Surface | 1st Floor | 21 | EA | 7 | \$0 | |
| Marker Board | 1st Floor | 24 | LF | 7 | \$0 | |
| Storage/ Closet | 1st Floor | 40 | SF | 6 | \$290 | |
| Walls - Concrete Block | 1st Floor | 1,148 | SF | 6 | \$3,365 | |
| oom #104 (Computer Lab) | | | | | | |
| Casework | 1st Floor | 24 | LF | 6 | \$606 | |
| Ceiling - Exposed | 1st Floor | 856 | SF | 6 | \$1,273 | Sound panels glued to bottom of concrete |
| Doors - Side-lite | 1st Floor | 12 | SF | 6 | \$201 | |
| Doors - Transom Window | 1st Floor | 15 | SF | 6 | \$254 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | 1st Floor | 856 | SF | 6 | \$1,873 | |
| Lighting - Pendent/Surface | 1st Floor | 21 | EA | 6 | \$2,602 | |
| Marker Board | 1st Floor | 12 | LF | 6 | \$257 | |
| Storage/ Closet | 1st Floor | 78 | SF | 6 | \$566 | |
| Walls - Concrete Block | 1st Floor | 1,029 | SF | 6 | \$3,017 | |
| Wireless System | 1st Floor | 1 | EA | 6 | \$372 | |
| oom #105 (Regular Classroom) | | | | | | |
| Casework | 1st Floor | 24 | LF | 6 | \$606 | |
| Ceiling - Exposed | 1st Floor | 856 | SF | 6 | \$1,273 | |
| Doors - Side-lite | 1st Floor | 12 | SF | 6 | \$201 | |
| Doors - Transom Window | 1st Floor | 15 | SF | 6 | \$254 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 1st Floor | 856 | SF | 6 | \$857 | |
| Lighting - Pendent/Surface | 1st Floor | 21 | EA | 6 | \$2,602 | |
| Marker Board | 1st Floor | 12 | LF | 6 | \$257 | |
| Storage/ Closet | 1st Floor | 78 | SF | 6 | \$566 | |
| Walls - Concrete Block | 1st Floor | 1,029 | SF | 6 | \$3,017 | |
| oom #106 (Kindergarten) | | | | | | |
| Casework | 1st Floor | 24 | LF | 6 | \$606 | |
| Ceiling - Exposed | 1st Floor | 805 | SF | 6 | \$1,197 | Sound panels glued to bottom of concrete |
| Doors - Side-lite | 1st Floor | 12 | SF | 6 | \$201 | |
| Doors - Transom Window | 1st Floor | 15 | SF | 6 | \$254 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 1st Floor | 805 | SF | 6 | \$806 | |
| Lighting - Pendent/Surface | 1st Floor | 20 | EA | 6 | \$2,478 | |
| | | | LF | | | |
| | Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Concrete Block From #104 (Computer Lab) Casework Ceiling - Exposed Doors - Side-lite Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Concrete Block Wireless System From #105 (Regular Classroom) Casework Ceiling - Exposed Doors - Side-lite Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile/Sheet Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Concrete Block Ceiling - Exposed Doors - Side-lite Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile/Sheet Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Concrete Block From #106 (Kindergarten) Casework Ceiling - Exposed Doors - Side-lite Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile/Sheet | Lighting - Pendent/Surface 1st Floor Marker Board 1st Floor Storage/ Closet 1st Floor Walls - Concrete Block 1st Floor Doors - Side-lite 1st Floor Marker Board 1st Floor Casework 1st Floor Doors - Side-lite 1st Floor Doors - Wood Doors inclu hw 1st Floor Marker Board 1st Floor Wireless System 1st Floor Wireless System 1st Floor Doors - Transom Window 1st Floor Moors + Toor - Tile 1st Floor More #105 (Regular Classroom) Casework 1st Floor Ceiling - Exposed 1st Floor Woors - Transom Window 1st Floor Doors - Side-lite 1st Floor Marker Board 1st Floor Wireless System 1st Floor More #105 (Regular Classroom) Casework 1st Floor Doors - Side-lite 1st Floor Doors - Transom Window 1st Floor Doors - Transom Window 1st Floor Doors - Wood Doors inclu hw 1st Floor Floor - Tile/Sheet 1st Floor Storage/ Closet 1st Floor Marker Board 1st Floor Marker Board 1st Floor Storage/ Closet 1st Floor Toor #106 (Kindergarten) Casework 1st Floor Doors - Transom Window 1st Floor | tom#103 (Regular Classroom) Lighting - Pendent/Surface 1st Floor 21 Marker Board 1st Floor 40 Walls - Concrete Block 1st Floor 1,148 tom#104 (Computer Lab) Casework 1st Floor 24 Ceiling - Exposed 1st Floor 24 Doors - Side-lite 1st Floor 12 Doors - Transom Window 1st Floor 15 Doors - Wood Doors inclu hw 1st Floor 1 Floor - Tile 1st Floor 21 Marker Board 1st Floor 12 Marker Board 1st Floor 12 Storage/ Closet 1st Floor 1 Walls - Concrete Block 1st Floor 1 Wireless System 1st Floor 2 Casework 1st Floor 2 Ceiling - Exposed 1st Floor 24 Ceiling - Exposed 1st Floor 1 Doors - Side-lite 1st Floor 1 Doors - Wood Doors inclu hw | | | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------|-----------------------------|-----------|----------|--------|--------|---------|----------|
| _ | oom #106 (Kindergarten) | 20041011 | Quantity | 01.110 | rtaint | 000. | |
| G iadoi e | Storage/ Closet | 1st Floor | 78 | SF | 6 | \$566 | |
| | Walls - Concrete Block | 1st Floor | 1,029 | SF | 6 | \$3,017 | |
| | | 101 / 100 | .,020 | ٠. | · · | φο,σ | |
| Classro | oom #107 (Kindergarten) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 42 | LF | 6 | \$1,061 | |
| | Ceiling - Exposed | 1st Floor | 1,144 | SF | 7 | \$0 | |
| | Doors - Side-lite | 1st Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 1,144 | SF | 6 | \$2,503 | |
| | Lighting | 1st Floor | 1,144 | | 6 | \$0 | |
| | Marker Board | 1st Floor | 16 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 80 | SF | 6 | \$580 | |
| | Walls - Concrete Block | 1st Floor | 1,450 | SF | 6 | \$4,251 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #109 (Kindergarten) | | | | | | |
| | Casework | 1st Floor | 42 | LF | 6 | \$1,061 | |
| | Ceiling - Exposed | 1st Floor | 1,144 | SF | 7 | \$0 | |
| | Doors - Side-lite | 1st Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 1,144 | SF | 6 | \$2,503 | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 12 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 80 | SF | 6 | \$580 | |
| | Walls - Concrete Block | 1st Floor | 1,450 | SF | 6 | \$4,251 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #110 (Art Room) | | | | | | |
| | Casework | 1st Floor | 24 | LF | 6 | \$606 | |
| | Ceiling - Exposed | 1st Floor | 856 | SF | 6 | \$1,273 | |
| | Doors - Side-lite | 1st Floor | 12 | SF | 6 | \$201 | |
| | Doors - Transom Window | 1st Floor | 15 | SF | 6 | \$254 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 1,029 | SF | 6 | \$1,030 | |
| | Instructional Surface | 1st Floor | 8 | LF | 6 | \$269 | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 6 | \$2,602 | |
| | | | | | | | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|------------------------------|-----------|----------|------|------|---------|--|
| lassro | oom #110 (Art Room) | | | | | | |
| | Marker Board | 1st Floor | 32 | LF | 6 | \$685 | |
| | Storage/ Closet | 1st Floor | 78 | SF | 6 | \$566 | |
| | Walls - Concrete Block | 1st Floor | 1,029 | SF | 6 | \$3,017 | |
| lassro | oom #111 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 24 | LF | 6 | \$606 | |
| | Ceiling - Exposed | 1st Floor | 856 | SF | 6 | \$1,273 | Sound panels glued to bottom of concrete |
| | Doors - Side-lite | 1st Floor | 12 | SF | 6 | \$201 | |
| | Doors - Transom Window | 1st Floor | 15 | SF | 6 | \$254 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 856 | SF | 5 | \$3,844 | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 6 | \$2,602 | |
| | Marker Board | 1st Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 1st Floor | 78 | SF | 6 | \$566 | |
| | Walls - Concrete Block | 1st Floor | 1,029 | SF | 6 | \$3,017 | |
| ssrc | oom #113 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 1st Floor | 910 | SF | 7 | \$0 | |
| | Doors - Side-lite | 1st Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 910 | SF | 6 | \$1,991 | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 1st Floor | 1,160 | SF | 6 | \$3,401 | |
| ssrc | oom #114 (Art Room) | | | | | | |
| | Casework | 1st Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 1st Floor | 910 | SF | 7 | \$0 | |
| | Doors - Side-lite | 1st Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 910 | SF | 6 | \$1,991 | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 1st Floor | 1,160 | SF | 6 | \$3,401 | |
| | | D-111 40 | | | | | A |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|--------|---------|--|
| _ | oom #114 (Art Room) | 2004.1011 | quantity | 0 | rtuint | 000. | Commission |
| Olubbit | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| 01 | | | | | | 40.0 | |
| Classro | oom #201 (Regular Classroom) | Oct Flore | 00 | | | | |
| | Casework | 2nd Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 2nd Floor | 910 | SF | 7 | \$0 | acoustical panels glued to the underside |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 910 | SF | 6 | \$1,991 | |
| | Lighting - Pendent/Surface | 2nd Floor | 21 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 2nd Floor | 1,160 | SF | 6 | \$3,401 | |
| Classro | oom #202 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 2nd Floor | 858 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 858 | SF | 6 | \$1,877 | |
| | Lighting - Pendent/Surface | 2nd Floor | 21 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 2nd Floor | 1,148 | SF | 6 | \$3,365 | |
| Classro | oom #203 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 2nd Floor | 910 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 910 | SF | 6 | \$1,991 | |
| | Lighting - Pendent/Surface | 2nd Floor | 21 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 24 | LF | 6 | \$514 | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 2nd Floor | 1,160 | SF | 6 | \$3,401 | |
| | | | ., | | - | Ţ-,·•. | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|--------|--------|---------|--|
| _ | oom #204 (Regular Classroom) | 20001011 | quantity | O.I.I. | rtaint | 000. | |
| 0.000.0 | Casework | 2nd Floor | 24 | LF | 6 | \$606 | |
| | Ceiling - Exposed | 2nd Floor | 990 | SF | 6 | | Sound panels glued to bottom of concrete |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 6 | \$201 | Country particle grade to solution of control of |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 6 | \$254 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 990 | SF | 6 | \$991 | |
| | Lighting - Pendent/Surface | 2nd Floor | 21 | EA | 6 | \$2,602 | |
| | Marker Board | 2nd Floor | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | 2nd Floor | 12 | SF | 6 | \$87 | |
| | Walls - Concrete Block | 2nd Floor | 1,056 | SF | 6 | \$3,096 | |
| Classro | oom #205 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 24 | LF | 6 | \$606 | |
| | Ceiling - Exposed | 2nd Floor | 856 | SF | 6 | \$1,273 | Sound panels glued to bottom of concrete |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 6 | \$201 | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 6 | \$254 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 856 | SF | 6 | \$857 | |
| | Lighting - Pendent/Surface | 2nd Floor | 21 | EA | 6 | \$2,602 | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 2nd Floor | 78 | SF | 6 | \$566 | |
| | Walls - Concrete Block | 2nd Floor | 1,029 | SF | 6 | \$3,017 | |
| Classro | oom #206 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 24 | LF | 6 | \$606 | |
| | Ceiling - Exposed | 2nd Floor | 990 | SF | 6 | \$1,472 | Sound panels glued to bottom of concrete |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 6 | \$201 | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 6 | \$254 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 990 | SF | 6 | \$991 | |
| | Lighting - Pendent/Surface | 2nd Floor | 21 | EA | 6 | \$2,602 | |
| | Marker Board | 2nd Floor | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | 2nd Floor | 12 | SF | 6 | \$87 | |
| | Walls - Concrete Block | 2nd Floor | 1,056 | SF | 6 | \$3,096 | |
| Classro | oom #207 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 2nd Floor | 1,148 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | | | | | | | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-------------------------------------|------------------------|------------|----------|--------|------------------|-------------------|
| • | oom #207 (Regular Classroom) | 200000 | - audinity | . | | - 0031 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 858 | SF | 6 | \$1,877 | |
| | Lighting - Pendent/Surface | 2nd Floor | 21 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 2nd Floor | 1,148 | SF | 6 | \$3,365 | |
| Classro | oom #208 (Regular Classroom) | | | | | | |
| Olassic | Casework | 2nd Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 2nd Floor | 858 | SF | 6 | \$1,276 | |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 858 | SF | 6 | \$1,877 | |
| | Lighting - Pendent/Surface | 2nd Floor | 21 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 2nd Floor | 1,148 | SF | 6 | \$3,365 | |
| Classes | | | , - | | | , -, | |
| Classic | Casework | 2nd Floor | 26 | LF | - | ФС Б 7 | |
| | | 2nd Floor 2nd Floor | 26 | SF | 6 | \$657 | |
| | Ceiling - Exposed Doors - Side-lite | | 858 | _ | 6 | \$1,276 | |
| | | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA SF | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 858 | | 6 | \$1,877 | |
| | Lighting - Pendent/Surface | 2nd Floor 2nd Floor | 21 | EA LF | 7 | \$0 \$0 | |
| | Marker Board Storage/ Closet | 2nd Floor 2nd Floor | 24 40 | SF | 7 6 | \$0 \$290 | |
| | Walls - Concrete Block | 2nd Floor 2nd Floor | 1,148 | SF | 6 | \$290 \$3,365 | |
| | | ZIIQ FIOOI | 1,140 | ЭF | υ | φ3,303 | |
| Classro | oom #210 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 24 | LF | 6 | \$606 | |
| | Ceiling - Exposed | 2nd Floor | 856 | SF | 6 | \$1,273 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 6 | \$201 | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 6 | \$254 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 856 | SF | 6 | \$857 | |
| OLIAL N | | D 40 (0 | | | | | A 1 D - 1 - F/00/ |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|-------|------|---------|--|
| _ | oom #210 (Regular Classroom) | Location | Quantity | Oilit | Runk | 0031 | Comments |
| Olassic | Lighting - Pendent/Surface | 2nd Floor | 21 | EA | 6 | \$2,602 | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 2nd Floor | 78 | SF | 6 | \$566 | |
| | Walls - Concrete Block | 2nd Floor | 1,029 | SF | 6 | \$3,017 | |
| | | | .,020 | ٥. | Ü | Ψ0,0 | |
| Classro | oom #212 (Computer Lab) | | | | | | |
| | Casework | 2nd Floor | 24 | LF | 6 | \$606 | |
| | Ceiling - Exposed | 2nd Floor | 858 | SF | 6 | \$1,276 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 6 | \$201 | |
| | Doors - Transom Window | 2nd Floor | 15 | SF | 6 | \$254 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 2nd Floor | 858 | SF | 6 | \$1,828 | |
| | Lighting - Pendent/Surface | 2nd Floor | 21 | EA | 6 | \$2,602 | |
| | Marker Board | 2nd Floor | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | 2nd Floor | 78 | SF | 6 | \$566 | |
| | Walls - Concrete Block | 2nd Floor | 1,029 | SF | 6 | \$3,017 | |
| | Wireless System | 2nd Floor | 1 | EA | 6 | \$372 | |
| Classro | oom #213 (Computer Lab) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 4 | \$6,086 | replace unit |
| | AC Units | 2nd Floor | 1 | EΑ | 6 | \$496 | |
| | Casework | 2nd Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Exposed | 2nd Floor | 910 | SF | 7 | \$0 | acoustical panels glued to the underside "7" |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 910 | SF | 6 | \$1,991 | |
| | Lighting - Pendent/Surface | 2nd Floor | 21 | EΑ | 7 | \$0 | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 6 | \$290 | |
| | Walls - Masonry | 2nd Floor | 1,160 | SF | 6 | \$3,649 | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | \$0 | |
| Classro | oom #214 (Music Room) | | | | | | |
| | Casework | 2nd Floor | 36 | LF | 6 | \$909 | |
| | Ceiling - Exposed | 2nd Floor | 910 | SF | 6 | | acoustical panels glued to the underside "7" |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | | | <u> </u> | | | Ψ001 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

Category: Classrooms

| Group It | em - Type | Location | Quantity | Unit | Rank | Cost Comments | |
|-----------|---------------------------|-----------|----------|------------|------|---------------|--|
| Classroon | m #214 (Music Room) | | | | | | |
| F | Floor - Tile | 2nd Floor | 910 | SF | 6 | \$1,991 | |
| L | ighting - Pendent/Surface | 2nd Floor | 21 | EA | 7 | \$0 | |
| N | Narker Board | 2nd Floor | 12 | LF | 7 | \$ 0 | |
| S | Storage/ Closet | 2nd Floor | 40 | SF | 6 | \$290 | |
| ٧ | Valls - Concrete Block | 2nd Floor | 1,160 | SF | 6 | \$3,401 | |
| V | valis - Concrete block | ≥na Floor | 1,160 | 3 F | Ö | Φ3,401 | |

Classrooms Subtotal: \$230,931

Building: Main

| up Item - Type | | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|----|--|----------|------|------|----------|--|
| ninistrative Suites/Offices | | | | | | | |
| Ceiling - Exposed | | 1st flr south of classroom #101, main office suite | 855 | SF | 6 | \$1,272 | Sound panels glued to bottom of concrete |
| Doors - Side-lite | | 1st flr south of classroom #101, main office suite | 40 | SF | 6 | \$669 | |
| Doors - Transom Window | | 1st flr south of classroom #101, main office suite | 12 | SF | 6 | \$203 | |
| Doors - Wood Doors inclu | hw | 1st flr south of classroom #101, main office suite | 5 | EA | 6 | \$1,505 | |
| Floor - Carpet | | 1st flr south of classroom #101, main office suite | 855 | SF | 6 | \$1,822 | |
| Lighting - Pendent/Surface | | 1st flr south of classroom #101, main office suite | 9 | EA | 6 | \$1,115 | |
| Power Distribution | | 1st flr south of classroom #101, main office suite | 12 | EA | 6 | \$25,499 | |
| Storage/ Closet | | 1st flr south of classroom #101, main office suite | 131 | SF | 6 | \$950 | |
| Walls - Concrete Block | | 1st flr south of classroom #101, main office suite | 2,160 | SF | 6 | \$6,332 | |
| Ceiling - Exposed | | 1st flr south of classroom #102 | 942 | SF | 6 | \$1,401 | Sound panels glued to bottom of concrete |
| Doors - Wood Doors inclu | hw | 1st flr south of classroom #102 | 4 | EA | 6 | \$1,204 | |
| Floor - Tile/Sheet | | 1st flr south of classroom #102 | 942 | SF | 6 | \$943 | |
| Lighting - Pendent/Surface | | 1st flr south of classroom #102 | 8 | EA | 6 | \$991 | |
| Power Distribution | | 1st flr south of classroom #102 | 12 | EA | 6 | \$25,499 | |
| Storage/ Closet | | 1st flr south of classroom #102 | 107 | SF | 6 | \$776 | |
| Walls - Concrete Block | | 1st flr south of classroom #102 | 1,620 | SF | 6 | \$4,749 | |
| Ceiling - Exposed | | 2nd flr north of library | 230 | SF | 6 | \$342 | Sound panels glued to bottom of concrete |
| Doors - Wood Doors inclu | hw | 2nd flr north of library | 1 | EA | 6 | \$301 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|----------------------------|----------|------|------|----------|--|
| Admini | strative Suites/Offices | | | | | | |
| | Floor - Tile/Sheet | 2nd flr north of library | 230 | SF | 6 | \$230 | |
| | Lighting - Pendent/Surface | 2nd flr north of library | 4 | EA | 6 | \$496 | |
| | Power Distribution | 2nd flr north of library | 6 | EA | 6 | \$12,749 | |
| | Walls - Concrete Block | 2nd flr north of library | 594 | SF | 6 | \$1,741 | |
| | Ceiling - Exposed | Basement engineer's office | 280 | SF | 6 | \$416 | Sound panels glued to bottom |
| | Doors - Steel Doors incl hw | Basement engineer's office | 1 | EA | 6 | \$301 | |
| | Floor - Concrete Epoxy/ Painted | Basement engineer's office | 280 | SF | 6 | \$148 | |
| | Lighting - Pendent/Surface | Basement engineer's office | 6 | EA | 6 | \$743 | |
| | Power Distribution | Basement engineer's office | 6 | EA | 6 | \$12,749 | |
| | Walls - Concrete Block | Basement engineer's office | 612 | SF | 6 | \$1,794 | |
| Gymna | sia | | | | | | |
| | Ceiling - Exposed | 1st Floor | 3,768 | SF | 6 | \$5,604 | |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 6 | \$1,204 | |
| | Floor - Wood | 1st Floor | 3,768 | SF | 6 | \$26,564 | |
| | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 38 | EA | 6 | \$5,081 | |
| | Sound System | 1st Floor | 1 | EA | 6 | \$41,654 | |
| | Stage | 1st Floor | 504 | SF | 6 | \$2,912 | |
| | Stage Lift | 1st Floor | 1 | EA | 6 | \$6,510 | |
| | Stage Lighting System | 1st Floor | 1 | EA | 6 | \$12,369 | |
| | Walls - Concrete Block | 1st Floor | 5,386 | SF | 6 | \$15,789 | |
| Library | | | | | | | |
| | Casework | 2nd Floor | 67 | LF | 6 | \$1,692 | |
| | Ceiling - Exposed | 2nd Floor | 1,326 | SF | 6 | \$1,972 | Sound panels glued to bottom of concrete |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | 2nd Floor | 1,326 | SF | 6 | \$2,825 | |
| | Lighting - Pendent/Surface | 2nd Floor | 28 | EA | 6 | \$3,469 | |
| | Walls - Concrete Block | 2nd Floor | 1,721 | SF | 6 | \$5,045 | |
| MDF_I | DF . | | | | | | |
| | Doors - Steel Doors incl hw | 2nd flr south of Rm #210 | 1 | EA | 6 | \$301 | |
| | Finishes | 2nd flr south of Rm #210 | 225 | SF | 6 | \$1,606 | |
| | Ventilation and Cooling | 2nd flr south of Rm #210 | 1 | EA | 6 | \$1,855 | |
| Mechar | nical/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 65 | SF | 6 | \$466 | South of boy's restroom |
| | Storage Room | 1st Floor | 140 | SF | 6 | \$1,003 | South of girl's restroom |
| | | 2nd Floor | 85 | SF | 6 | \$609 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------|---------------------------------|-----------------------------------|----------|------|------|----------|--|
| char | nical/ Service Rooms | | | | | | |
| | Boiler Room | Basement | 2,466 | SF | 6 | \$17,667 | |
| | Interior Stairs | Basement | 12 | LF | 6 | \$108 | |
| | Mechanical/ Service Rooms | Basement | 1,691 | SF | 6 | \$12,115 | Air handling room at east |
| | Storage Room | Basement | 455 | SF | 6 | \$3,260 | |
| stro | om | | | | | | |
| | Accessories | 1st flr inside principal's office | 48 | SF | 6 | \$443 | |
| | Ceiling - Exposed | 1st flr inside principal's office | 48 | SF | 6 | \$71 | Sound panels glued to bottom of concrete |
| | Doors - Wood Doors inclu hw | 1st flr inside principal's office | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 1st flr inside principal's office | 48 | SF | 6 | \$102 | |
| | Lavatory | 1st flr inside principal's office | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | 1st flr inside principal's office | 1 | EA | 6 | \$124 | |
| | Partitions | 1st flr inside principal's office | 1 | EA | 6 | \$297 | |
| | Walls - Concrete Block | 1st flr inside principal's office | 103 | SF | 6 | \$302 | |
| | Walls - Structural Glazed Tile | 1st flr inside principal's office | 206 | SF | 6 | \$648 | |
| | Water Closet | 1st flr inside principal's office | 1 | EA | 6 | \$336 | |
| | Accessories | 1st flr next to main office suite | 48 | SF | 6 | \$443 | |
| | Ceiling - Exposed | 1st flr next to main office suite | 48 | SF | 6 | \$71 | Sound panels glued to bottom of concrete |
| | Doors - Wood Doors inclu hw | 1st flr next to main office suite | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 1st flr next to main office suite | 48 | SF | 6 | \$102 | |
| | Lavatory | 1st flr next to main office suite | 1 | EΑ | 6 | \$320 | |
| | Lighting - Wall Mounted | 1st flr next to main office suite | 1 | EΑ | 6 | \$124 | |
| | Partitions | 1st flr next to main office suite | 1 | EΑ | 6 | \$297 | |
| | Walls - Concrete Block | 1st flr next to main office suite | 103 | SF | 6 | \$302 | |
| | Walls - Structural Glazed Tile | 1st flr next to main office suite | 206 | SF | 6 | \$648 | |
| | Water Closet | 1st flr next to main office suite | 1 | EA | 6 | \$336 | |
| | Accessories | 1st flr north of classroom #107 | 382 | SF | 6 | \$3,523 | |
| | Ceiling - Exposed | 1st flr north of classroom #107 | 251 | SF | 6 | \$373 | Sound panels glued to bottom of concrete |
| | Doors - Wood Doors inclu hw | 1st flr north of classroom #107 | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st flr north of classroom #107 | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st flr north of classroom #107 | 251 | SF | 6 | \$531 | |
| | Hand Dryer | 1st flr north of classroom #107 | 2 | EA | 6 | \$460 | |
| | Lavatory | 1st flr north of classroom #107 | 3 | EΑ | 6 | \$959 | |
| | Lighting - Pendent/Surface | 1st flr north of classroom #107 | 3 | EA | 6 | \$372 | |
| | Partitions | 1st flr north of classroom #107 | 5 | EA | 6 | \$1,485 | |
| | Walls - Concrete Block | 1st flr north of classroom #107 | 235 | SF | 6 | \$689 | |
| | Walls - Structural Glazed Tile | 1st flr north of classroom #107 | 469 | SF | 6 | \$1,475 | |
| | Water Closet | 1st flr north of classroom #107 | 5 | EA | 6 | \$1,680 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|------------------------------------|----------|------|------|---------|--|
| Restroc | om | | | | | | |
| | Accessories | 1st flr north of classroom #109 | 251 | SF | 6 | \$2,315 | |
| | Ceiling - Exposed | 1st flr north of classroom #109 | 251 | SF | 6 | \$373 | Sound panels glued to bottom of concrete |
| | Doors - Wood Doors inclu hw | 1st flr north of classroom #109 | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st flr north of classroom #109 | 1 | EΑ | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st flr north of classroom #109 | 251 | SF | 6 | \$531 | |
| | Hand Dryer | 1st flr north of classroom #109 | 2 | EΑ | 6 | \$460 | |
| | Lavatory | 1st flr north of classroom #109 | 3 | EΑ | 6 | \$959 | |
| | Lighting - Pendent/Surface | 1st flr north of classroom #109 | 2 | EΑ | 6 | \$248 | |
| | Partitions | 1st flr north of classroom #109 | 3 | EΑ | 6 | \$891 | |
| | Urinals | 1st flr north of classroom #109 | 4 | EΑ | 6 | \$1,344 | |
| | Walls - Concrete Block | 1st flr north of classroom #109 | 235 | SF | 6 | \$689 | |
| | Walls - Structural Glazed Tile | 1st flr north of classroom #109 | 469 | SF | 6 | \$1,475 | |
| | Water Closet | 1st flr north of classroom #109 | 3 | EΑ | 6 | \$1,008 | |
| | Accessories | 2nd flr female to north of library | 99 | SF | 6 | \$913 | |
| | Ceiling - Exposed | 2nd flr female to north of library | 99 | SF | 6 | \$147 | Sound panels glued to bottom of concrete |
| | Doors - Wood Doors inclu hw | 2nd flr female to north of library | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd flr female to north of library | 99 | SF | 6 | \$210 | |
| | Lavatory | 2nd flr female to north of library | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | 2nd flr female to north of library | 2 | EΑ | 6 | \$248 | |
| | Partitions | 2nd flr female to north of library | 2 | EΑ | 6 | \$594 | |
| | Walls - Concrete Block | 2nd flr female to north of library | 148 | SF | 6 | \$434 | |
| | Walls - Structural Glazed Tile | 2nd flr female to north of library | 296 | SF | 6 | \$931 | |
| | Water Closet | 2nd flr female to north of library | 2 | EΑ | 6 | \$672 | |
| | Accessories | 2nd flr male to north of library | 47 | SF | 6 | \$434 | |
| | Ceiling - Exposed | 2nd flr male to north of library | 47 | SF | 6 | \$70 | Sound panels glued to bottom of concrete |
| | Doors - Wood Doors inclu hw | 2nd flr male to north of library | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd flr male to north of library | 47 | SF | 6 | \$99 | |
| | Lavatory | 2nd flr male to north of library | 1 | EΑ | 6 | \$320 | |
| | Lighting - Pendent/Surface | 2nd flr male to north of library | 1 | EΑ | 6 | \$124 | |
| | Partitions | 2nd flr male to north of library | 1 | EΑ | 6 | \$297 | |
| | Walls - Concrete Block | 2nd flr male to north of library | 105 | SF | 6 | \$308 | |
| | Walls - Structural Glazed Tile | 2nd flr male to north of library | 210 | SF | 6 | \$661 | |
| | Water Closet | 2nd flr male to north of library | 1 | EA | 6 | \$336 | |
| | Accessories | 2nd flr north of classroom #208 | 251 | SF | 6 | \$2,315 | |
| | Accessories | 2nd flr north of classroom #208 | 382 | SF | 6 | \$3,523 | |
| | Ceiling - Exposed | 2nd flr north of classroom #208 | 382 | SF | 6 | \$568 | Sound panels glued to bottom of concrete |
| | | | | | | | = |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---------------------------------|---------------------------------|----------|------|------|---------|----------|
| estro | om | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd flr north of classroom #208 | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 2nd flr north of classroom #208 | 1 | EA | 6 | \$301 | |
| | Floor Drain | 2nd flr north of classroom #208 | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 2nd flr north of classroom #208 | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd flr north of classroom #208 | 382 | SF | 6 | \$808 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd flr north of classroom #208 | 251 | SF | 6 | \$531 | |
| | Hand Dryer | 2nd flr north of classroom #208 | 2 | EΑ | 6 | \$460 | |
| | Hand Dryer | 2nd flr north of classroom #208 | 2 | EΑ | 6 | \$460 | |
| | Lavatory | 2nd flr north of classroom #208 | 3 | EA | 6 | \$959 | |
| | Lavatory | 2nd flr north of classroom #208 | 4 | EA | 6 | \$1,278 | |
| | Lighting - Pendent/Surface | 2nd flr north of classroom #208 | 3 | EA | 6 | \$372 | |
| | Lighting - Pendent/Surface | 2nd flr north of classroom #208 | 2 | EA | 6 | \$248 | |
| | Partitions | 2nd flr north of classroom #208 | 3 | EA | 6 | \$891 | |
| | Partitions | 2nd flr north of classroom #208 | 8 | EA | 6 | \$2,375 | |
| | Urinals | 2nd flr north of classroom #208 | 4 | EA | 6 | \$1,344 | |
| | Walls - Concrete Block | 2nd flr north of classroom #208 | 298 | SF | 6 | \$874 | |
| | Walls - Concrete Block | 2nd flr north of classroom #208 | 235 | SF | 6 | \$689 | |
| | Walls - Structural Glazed Tile | 2nd flr north of classroom #208 | 597 | SF | 6 | \$1,878 | |
| | Walls - Structural Glazed Tile | 2nd flr north of classroom #208 | 469 | SF | 6 | \$1,475 | |
| | Water Closet | 2nd flr north of classroom #208 | 3 | EA | 6 | \$1,008 | |
| | Water Closet | 2nd flr north of classroom #208 | 8 | EΑ | 6 | \$2,688 | |
| | Accessories | Basement | 69 | SF | 6 | \$636 | |
| | Ceiling - Plaster/Drywall | Basement | 69 | SF | 6 | \$239 | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | \$301 | |
| | Floor Drain | Basement | 1 | EA | 6 | \$1,059 | |
| | Floor - Concrete Epoxy/ Painted | Basement | 69 | SF | 6 | \$37 | |
| | Lavatory | Basement | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Basement | 2 | EA | 6 | \$248 | |
| | Partitions | Basement | 1 | EA | 6 | \$297 | |
| | Showers | Basement | 1 | EA | 6 | \$311 | |
| | Urinals | Basement | 1 | EA | 6 | \$336 | |
| | Walls - Concrete Block | Basement | 918 | SF | 6 | \$2,691 | |
| | Water Closet | Basement | 1 | EA | 6 | \$336 | |
| | Accessories | In Room 106 | 42 | SF | 6 | \$387 | |
| | Ceiling - Lay-in | In Room 106 | 42 | SF | 6 | \$126 | |
| | Doors - Wood Doors inclu hw | In Room 106 | 1 | EA | 6 | \$301 | |
| | Floor Drain | In Room 106 | 1 | EA | 6 | \$1,059 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------------|-------------|----------|------|------|-------|--|
| Restro | om | | | | | | |
| | Floor - Tile/Sheet | In Room 106 | 42 | SF | 6 | \$42 | |
| | Lavatory | In Room 106 | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | In Room 106 | 1 | EA | 6 | \$119 | |
| | Walls - Plaster/Drywall | In Room 106 | 212 | SF | 6 | \$585 | FRP panels |
| | Water Closet | In Room 106 | 1 | EA | 6 | \$336 | |
| | Accessories | In Room 107 | 35 | SF | 6 | \$323 | |
| | Ceiling - Exposed | In Room 107 | 35 | SF | 6 | \$52 | |
| | Doors - Wood Doors inclu hw | In Room 107 | 1 | EA | 6 | \$301 | |
| | Floor - Tile | In Room 107 | 35 | SF | 5 | \$157 | stained |
| | Lavatory | In Room 107 | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | In Room 107 | 1 | EΑ | 6 | \$124 | |
| | Walls - Vinyl Coated Gypsum Panel | In Room 107 | 94 | SF | 5 | \$694 | baseboard is missing leaving wall badly stained at |
| | | | | | | | base |
| | Water Closet | In Room 107 | 1 | EA | 6 | \$336 | |
| | Accessories | In Room 109 | 35 | SF | 7 | \$0 | |
| | Ceiling - Exposed | In Room 109 | 35 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | In Room 109 | 1 | EA | 6 | \$301 | |
| | Floor - Tile | In Room 109 | 35 | SF | 6 | \$77 | |
| | Lavatory | In Room 109 | 1 | EΑ | 7 | \$0 | |
| | Lighting - Wall Mounted | In Room 109 | 1 | EΑ | 6 | \$124 | |
| | Walls - Concrete Block | In Room 109 | 94 | SF | 6 | \$276 | |
| | Water Closet | In Room 109 | 1 | EA | 7 | \$0 | |

Rooms (Other Than Classrooms) Subtotal:

\$358,394

Building: Main

Category: Building Interior

| | | | Rank | COSt | Comments |
|-----------|---|--|--|--|---|
| | | | | | |
| 1st Floor | 4,619 | SF | 6 | \$6,869 | |
| 1st Floor | 8 | EA | 6 | \$2,408 | |
| 1st Floor | 3 | EA | 6 | \$1,008 | |
| 1st Floor | 1,297 | SF | 6 | \$3,617 | |
| 1st Floor | 4,179 | SF | 6 | \$2,271 | |
| 1st Floor | 44 | EA | 6 | \$5,451 | |
| 1st Floor | 4,140 | SF | 6 | \$12,136 | |
| 1st Floor | 8,150 | SF | 6 | \$25,640 | |
| | 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor | 1st Floor 8 1st Floor 3 1st Floor 1,297 1st Floor 4,179 1st Floor 44 1st Floor 4,140 | 1st Floor 8 EA 1st Floor 3 EA 1st Floor 1,297 SF 1st Floor 4,179 SF 1st Floor 44 EA 1st Floor 4,140 SF | 1st Floor 8 EA 6 1st Floor 3 EA 6 1st Floor 1,297 SF 6 1st Floor 4,179 SF 6 1st Floor 44 EA 6 1st Floor 4,140 SF 6 | 1st Floor 8 EA 6 \$2,408 1st Floor 3 EA 6 \$1,008 1st Floor 1,297 SF 6 \$3,617 1st Floor 4,179 SF 6 \$2,271 1st Floor 44 EA 6 \$5,451 1st Floor 4,140 SF 6 \$12,136 |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

Category: Building Interior

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|-----------------|----------|------|------|----------|----------|
| Corrido | or | | - | | | | |
| | Ceiling - Exposed | 2nd Floor | 5,476 | SF | 6 | \$8,144 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 6 | EA | 6 | \$1,806 | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 2 | EA | 6 | \$672 | |
| | Floor - Tile/Sheet | 2nd Floor | 4,619 | SF | 6 | \$2,510 | |
| | Lighting - Pendent/Surface | 2nd Floor | 40 | EA | 6 | \$4,956 | |
| | Stairs - Concrete Stairs | 2nd Floor | 30 | LF | 6 | \$249 | |
| | Walls - Concrete Block | 2nd Floor | 3,980 | SF | 6 | \$11,667 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 7,960 | SF | 6 | \$25,042 | |
| | Ceiling - Plaster/Drywall | Basement | 282 | SF | 6 | \$1,746 | |
| | Doors - Steel Doors incl hw | Basement | 2 | EA | 6 | \$602 | |
| | Floor - Concrete Epoxy/ Painted | Basement | 282 | SF | 6 | \$137 | |
| | Lighting - Pendent/Surface | Basement | 4 | EA | 6 | \$496 | |
| | Walls - Concrete Block | Basement | 720 | SF | 6 | \$2,111 | |
| Cofoty | | | | | | | |
| Safety | Carryity Carrage | Entire Duilding | 4 | Ε.Δ | | ¢404 | |
| | Security Cameras | Entire Building | 1 | EA | 6 | \$194 | |
| Stairs | | | | | | | |
| | Ceiling - Exposed | North | 319 | SF | 6 | \$474 | |
| | Floor - Tile/Sheet | North | 260 | SF | 6 | \$141 | |
| | Handrails | North | 64 | LF | 6 | \$555 | |
| | Lighting - Pendent/Surface | North | 1 | EA | 6 | \$124 | |
| | Lighting - Wall Mounted | North | 2 | EA | 6 | \$248 | |
| | Stairs - Concrete | North | 30 | LF | 6 | \$249 | |
| | Walls - Concrete Block | North | 424 | SF | 6 | \$1,243 | |
| | Walls - Structural Glazed Tile | North | 1,272 | SF | 6 | \$4,002 | |
| | Ceiling - Exposed | South | 319 | SF | 6 | \$474 | |
| | Floor - Tile/Sheet | South | 260 | SF | 6 | \$141 | |
| | Handrails | South | 64 | LF | 6 | \$555 | |
| | Lighting - Pendent/Surface | South | 1 | EA | 6 | \$124 | |
| | Lighting - Wall Mounted | South | 2 | EA | 6 | \$248 | |
| | Stairs - Concrete | South | 30 | LF | 6 | \$249 | |
| | Walls - Concrete Block | South | 424 | SF | 6 | \$1,243 | |
| | Walls - Structural Glazed Tile | South | 1,272 | SF | 6 | \$4,002 | |
| Vertica | I Conveyance | | | | | | |
| | Wheelchair Lift - Platform Lift | 1st Floor | 1 | EA | 6 | \$6,690 | At stage |
| | | | | | | | • |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Main

Category: Building Interior

Group Item - Type Location Quantity Unit Rank Cost Comments

Building Interior Subtotal: \$140,492

Total Building Cost \$2,758,778

Building: Addition

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|-------------------------------|----------|------|------|-----------|---|
| Entrand | ce | | | | | | |
| | Entrance Control - Audio and Video | #7- SE | 1 | EA | 6 | \$702 | |
| | Exterior Doors - Side lite | #7- SE | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Side lite | #8- NE | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Store Front | #7- SE | 2 | EA | 5 | \$3,672 | Missing caps on top of door, allowing water to penetrate & broken metal screens |
| | Exterior Doors - Store Front | #8- NE | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Transom Lite | #7- SE | 3 | EA | 6 | \$940 | |
| | Power Door Operator and Controls | #7- SE | 1 | EA | 6 | \$0 | |
| Founda | ation | | | | | | |
| | Foundation - Concrete | Entire Building | 239 | LF | 7 | \$0 | |
| | Foundation - Concrete | Entire Building | 5 | LF | 5 | \$2,760 | seepage |
| | Superstructure - Concrete | Entire Building | 11,452 | SF | 7 | \$0 | |
| Lightin | g | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 2 | EA | 6 | \$577 | replace bulbs |
| | Exterior Lighting - Wall Mounted | Entire Building / East Façade | 2 | EA | 5 | \$855 | replace ballasts |
| Roof S | ystem | | | | | | |
| | Coping - Metal | Elevator tower roof | 77 | LF | 6 | \$2,473 | |
| | Coping - Metal | Main Roof | 198 | LF | 6 | \$6,359 | |
| | Downspouts - Exterior Downspouts | Elevator tower roof | 8 | LF | 4 | \$1,084 | missing drainage system |
| | Downspouts - Interior Downspouts | Main Roof | 48 | LF | 6 | \$1,595 | |
| | Roof Structure - Concrete | Main Roof | 5,351 | SF | 7 | \$0 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Elevator tower roof | 375 | SF | 7 | \$0 | |
| | Roof - Asphalt Gravel Ballast | Main Roof | 5,351 | SF | 4 | \$149,978 | water ponding, severe blistering |
| | Roof - Modified Bitumen | Elevator tower roof | 2 | SF | 6 | \$39 | recently repaired - not water tested; was causing damage at 2nd fl window wall |
| | Roof - Modified Bitumen | Elevator tower roof | 373 | SF | 5 | \$7,846 | water ponding |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Addition

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|--------------------------------|----------|------|------|----------|--|
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 3,591 | SF | 6 | \$24,135 | some open joints & minor spalling |
| Windov | vs | | | | | | |
| | Curtain wall - Glazed Double Pane | Entire Building | 1,110 | SF | 6 | \$12,444 | |
| | Curtain wall - Insulated Panel | Entire Building | 244 | SF | 3 | \$24,334 | allowing water in during heavy rains - no visible damage at time of site visit |
| | Curtain wall - Insulated Panel | Entire Building | 835 | SF | 6 | \$9,361 | |
| | Curtain wall - Insulated Panel | Entire Building / Façade- NW | 5 | SF | 5 | \$0 | loose metal frame |
| | Curtain wall - Insulated Panel | Entire Building / South Façade | 5 | SF | 5 | \$0 | loose metal frame |
| | Curtain wall - Louver | Entire Building / East Façade | 64 | SF | 6 | \$718 | |
| | Guard - Guards perforated | Entire Building | 544 | SF | 6 | \$6,947 | |
| | Lintels - Steel | Entire Building | 6 | LF | 7 | \$0 | |
| | Windows - Casement Aluminum Double-pane | Entire Building | 320 | SF | 6 | \$2,389 | |

Building Exterior Subtotal:

\$261,553

Building: Addition

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|-----------------------------|----------|------|------|---------|---------------------------|
| Emerge | ency System | | | | | | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 2,196 | SF | 6 | \$659 | |
| | Emergency A/C Power - Lunchrooms | Entire Building / 1st Floor | 1,599 | SF | 6 | \$595 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 10 | EΑ | 6 | \$1,497 | |
| | Exit Signs - Lunchroom | Entire Building / 1st Floor | 2 | EΑ | 6 | \$299 | |
| | Security System - CCTV | Entire Building | 11,452 | SF | 6 | \$3,439 | Connects to main building |
| | Security System - Intrusion Detection | Entire Building | 11,452 | SF | 6 | \$2,948 | Connects to main building |
| Main S | ervice | | | | | | |
| | PA System | Entire Building | 11,452 | SF | 5 | \$7,861 | Connects to main building |
| Power | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EΑ | 6 | \$598 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / 1st Floor | 1 | EΑ | 6 | \$497 | Location: Kitchen |
| | Lighting and Power Panels - Above 100 A | Entire Building / 2nd Floor | 1 | EΑ | 6 | \$497 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / 2nd Floor | 1 | EA | 6 | \$497 | |
| | | | | | | | |

Electrical System Subtotal:

\$19,388



2745 W Roosevelt Rd Chicago, IL 60608

Building: Addition

Category: Safty System

| Group Item - Type | Location | Quantity Unit | Rank | Cost Comments | |
|--------------------------|-----------------|---------------|------|---------------|--|
| Fire Alarm | | | | | |
| Fire Alarm Strobe Lights | Entire Building | 11,452 SF | 6 | \$4,094 | |
| Fire Alarm_System | Entire Building | 11,452 SF | 6 | \$5,568 | |
| | | | | | |
| Safty System Subtotal: | | | | \$9,662 | |

Building: Addition

Category: Mechanical System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|---|----------|------|------|----------|---|
| Heating Devices | | | | | | |
| Cabinet Heaters - With Hot Water Coil | Entire Building | 9 | EA | 6 | \$3,189 | Location: Vestibules, corridors |
| Wall Heater - Electric | Elevator equipment room and elect closet on 2nd floor | 2 | EA | 6 | \$278 | Location: Elevator equipment room and elect closet on 2nd floor |
| Temperature Control | | | | | | |
| DDC System | Entire Building | 11,452 | SF | 5 | \$18,833 | Has programming issues. |
| Thermostats - DDC | Entire Building | 10 | EA | 6 | \$0 | |
| Unit Ventilation | | | | | | |
| Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water | Entire Building | 8 | EA | 6 | \$9,939 | |
| Ventilation | | | | | | |
| Exhaust Fans- Indoor - Less than 500 CFM | Kitchen and elevator equipment room and Roof | 2 | EA | 6 | \$592 | Location: Kitchen and elevator equipment room |
| Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Kitchen and elevator equipment room and Roof / Roof | 1 | EA | 6 | \$592 | |
| Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Kitchen and elevator equipment room and Roof / Roof | 2 | EA | 6 | \$1,185 | |
| Mechanical System Subtotal: | | | | | \$34,608 | |

Building: Addition

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|-----------------|----------|------|------|---------|----------|
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 11,452 | SF | 6 | \$2,293 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 11,452 | SF | 6 | \$2,784 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 11,452 | SF | 6 | \$2,129 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 11,452 | SF | 6 | \$1,801 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Addition

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost Comments | |
|--------|--|-----------------|----------|------|------|---------------|--|
| Piping | | | | | | | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 11,452 | SF | 6 | \$2,129 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 11,452 | SF | 6 | \$1,638 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 11,452 | SF | 6 | \$1,638 | |
| | Sanitary Piping | Entire Building | 11,452 | SF | 6 | \$10,481 | |
| | Storm Piping | Entire Building | 11,452 | SF | 6 | \$9,990 | |
| | Vent Piping | Entire Building | 11,452 | SF | 6 | \$7,697 | |

Plumbing System Subtotal: \$42,579

Building: Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|----------|
| Classro | oom #118 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Splined | 1st Floor | 805 | SF | 6 | \$656 | |
| | Doors - Side-lite | 1st Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 805 | SF | 6 | \$1,761 | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 16 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 1st Floor | 1,142 | SF | 6 | \$3,348 | |
| Classro | oom #215 (Store Room) | | | | | | |
| | Casework | 2nd Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Splined | 2nd Floor | 805 | SF | 6 | \$656 | |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 805 | SF | 6 | \$1,761 | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EΑ | 6 | \$1,487 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 8 | SF | 6 | \$58 | |
| | Walls - Concrete Block | 2nd Floor | 1,142 | SF | 6 | \$3,348 | |
| Classro | oom #216 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 26 | LF | 6 | \$657 | |
| | | | | | | | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Addition

| | Ham Time | Lagation | 0 | I Im! | Dank | 01 | Comments |
|---------|------------------------------|-----------|----------|-------|------|---------|---------------------------------|
| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | oom #216 (Regular Classroom) | | | | | | |
| | Ceiling - Splined | 2nd Floor | 805 | SF | 6 | \$656 | |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 805 | SF | 6 | \$1,761 | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 8 | SF | 6 | \$58 | |
| | Walls - Concrete Block | 2nd Floor | 1,142 | SF | 6 | \$3,348 | |
| | Work Sink | 2nd Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #217 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Splined | 2nd Floor | 805 | SF | 6 | \$656 | |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 805 | SF | 6 | \$1,761 | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 2nd Floor | 1,142 | SF | 6 | \$3,348 | |
| | Work Sink | 2nd Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #218 (Office) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 5 | \$1,826 | no cover, not in good condition |
| | Casework | 2nd Floor | 26 | LF | 6 | \$657 | |
| | Ceiling - Splined | 2nd Floor | 805 | SF | 6 | \$656 | |
| | Chalk Board | 2nd Floor | 12 | LF | 4 | \$1,102 | |
| | Doors - Side-lite | 2nd Floor | 18 | SF | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 12 | SF | 6 | \$203 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 805 | SF | 6 | \$1,761 | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 40 | SF | 6 | \$290 | |
| | Walls - Concrete Block | 2nd Floor | 1,142 | SF | 6 | \$3,348 | |
| | | | | | | | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Addition

Category: Classrooms

Group Item - Type Location Quantity Unit Rank Cost Comments

Classrooms Subtotal:

\$42,293

Building: Addition

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|--------------------------|----------|------|------|---------|--------------------------|
| Admini | strative Suites/Offices | | | | | | |
| | Ceiling - Splined | Kitchen Manager's Office | 172 | SF | 6 | \$140 | |
| | Floor - Tile | Kitchen Manager's Office | 172 | SF | 6 | \$376 | |
| | Lighting - Pendent/Surface | Kitchen Manager's Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | Kitchen Manager's Office | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Kitchen Manager's Office | 283 | SF | 6 | \$830 | |
| Kitcher | 1 | | | | | | |
| | Ceiling - Splined | 1st Floor | 690 | SF | 6 | \$562 | |
| | Floor - Tile | 1st Floor | 690 | SF | 6 | \$1,510 | |
| | Lighting - Pendent/Surface | 1st Floor | 10 | EA | 7 | \$0 | |
| | Serving Line | 1st Floor | 8 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 845 | SF | 6 | \$2,477 | |
| Lunch | & Multipurpose Room | | | | | | |
| | Ceiling - Splined | 1st Floor | 1,599 | SF | 6 | \$1,303 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 1st Floor | 1,599 | SF | 6 | \$3,498 | |
| | Lighting - Pendent/Surface | 1st Floor | 24 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 1,630 | SF | 6 | \$4,778 | |
| Mechar | nical/ Service Rooms | | | | | | |
| | Storage Room | 1st Floor | 62 | SF | 6 | \$444 | Formerly Book Store Room |
| | Storage Room | 2nd Floor | 135 | SF | 6 | \$967 | |
| Restro | om | | | | | | |
| | Accessories | 1st Floor | 142 | SF | 6 | \$1,310 | |
| | Accessories | 1st Floor | 137 | SF | 6 | \$1,264 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 137 | SF | 6 | \$474 | |
| | Ceiling - Splined | 1st Floor | 142 | SF | 6 | \$116 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st Floor | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 1st Floor | 1 | EA | 6 | \$1,059 | |
| | | | | | | | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Addition

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|-----------|----------|------|------|---------|----------|
| estroc | om | | | | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 142 | SF | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 137 | SF | 6 | \$290 | |
| | Hand Dryer | 1st Floor | 2 | EΑ | 7 | \$0 | |
| | Hand Dryer | 1st Floor | 2 | EA | 7 | \$0 | |
| | Lavatory | 1st Floor | 2 | EA | 6 | \$639 | |
| | Lavatory | 1st Floor | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 1st Floor | 2 | EΑ | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 2 | EΑ | 7 | \$0 | |
| | Partitions | 1st Floor | 2 | EΑ | 6 | \$594 | |
| | Partitions | 1st Floor | 2 | EΑ | 6 | \$594 | |
| | Urinals | 1st Floor | 2 | EA | 6 | \$672 | |
| | Walls - Structural Glazed Tile | 1st Floor | 210 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 1st Floor | 204 | SF | 7 | \$0 | |
| | Water Closet | 1st Floor | 3 | EΑ | 7 | \$0 | |
| | Water Closet | 1st Floor | 1 | EΑ | 6 | \$336 | |
| | Accessories | 2nd Floor | 137 | SF | 6 | \$1,264 | |
| | Accessories | 2nd Floor | 142 | SF | 6 | \$1,310 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 137 | SF | 6 | \$474 | |
| | Ceiling - Splined | 2nd Floor | 142 | SF | 6 | \$116 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | \$301 | |
| | Floor Drain | 2nd Floor | 1 | EΑ | 6 | \$1,059 | |
| | Floor Drain | 2nd Floor | 1 | EΑ | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 137 | SF | 6 | \$290 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 142 | SF | 6 | \$301 | |
| | Hand Dryer | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Hand Dryer | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Lavatory | 2nd Floor | 2 | EA | 6 | \$639 | |
| | Lavatory | 2nd Floor | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Partitions | 2nd Floor | 2 | EA | 6 | \$594 | |
| | Partitions | 2nd Floor | 2 | EA | 6 | \$594 | |
| | Urinals | 2nd Floor | 2 | EA | 6 | \$672 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 204 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 210 | SF | 7 | \$0 | |
| | Water Closet | 2nd Floor | 3 | EΑ | 7 | \$0 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Addition

Category: Rooms (Other Than Classrooms)

| Group Item - Type | Location | Quantity Unit Rank | Cost Comments |
|-------------------|-----------|--------------------|---------------|
| Restroom | | | |
| Water Closet | 2nd Floor | 1 EA 6 | \$336 |

Rooms (Other Than Classrooms) Subtotal:

\$37,385

Building: Addition

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|-----------|----------|------|------|---------|----------|
| Corrido | or | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 190 | SF | 6 | \$571 | |
| | Ceiling - Splined | 1st Floor | 1,048 | SF | 6 | \$3,027 | |
| | Doors - Store Front | 1st Floor | 4 | EA | 6 | \$4,833 | |
| | Doors - Wood Doors include hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 6 | \$336 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 320 | SF | 6 | \$892 | |
| | Floor - Tile/Sheet | 1st Floor | 918 | SF | 6 | \$499 | |
| | Lighting - Lay-in | 1st Floor | 2 | EA | 6 | \$238 | |
| | Lighting - Pendent/Surface | 1st Floor | 8 | EA | 6 | \$991 | |
| | Walls - Structural Glazed Tile | 1st Floor | 2,338 | SF | 6 | \$7,355 | |
| | Ceiling - Lay-in | 2nd Floor | 190 | SF | 6 | \$571 | |
| | Ceiling - Splined | 2nd Floor | 1,048 | SF | 6 | \$3,027 | |
| | Doors - Store Front | 2nd Floor | 4 | EA | 6 | \$4,833 | |
| | Doors - Wood Doors include hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 1 | EA | 6 | \$336 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 320 | SF | 6 | \$892 | |
| | Floor - Tile/Sheet | 2nd Floor | 918 | SF | 6 | \$499 | |
| | Lighting - Lay-in | 2nd Floor | 2 | EA | 6 | \$238 | |
| | Lighting - Pendent/Surface | 2nd Floor | 8 | EA | 6 | \$991 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 2,338 | SF | 6 | \$7,355 | |
| Stairs | | | | | | | |
| | Ceiling - Splined | North | 113 | SF | 6 | \$326 | |
| | Floor - Tile | North | 50 | SF | 6 | \$27 | |
| | Handrails | North | 64 | LF | 6 | \$555 | |
| | Lighting - Pendent/Surface | North | 2 | EA | 6 | \$248 | |
| | Lighting - Wall Mounted | North | 1 | EA | 6 | \$124 | |
| | Stairs - Tile | North | 30 | LF | 6 | \$278 | |
| | Walls - Structural Glazed Tile | North | 950 | SF | 6 | \$2,989 | |
| | Walls - Structural Glazed Tile | North | 950 | SF | 6 | \$2,989 | |



2745 W Roosevelt Rd Chicago, IL 60608

Building: Addition

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|----------|----------|------|----------|----------|----------|
| Stairs | | | | | | | |
| | Ceiling - Splined | South | 113 | SF | 6 | \$326 | |
| | Floor - Tile | South | 50 | SF | 6 | \$27 | |
| | Handrails | South | 64 | LF | 6 | \$555 | |
| | Lighting - Pendent/Surface | South | 2 | EA | 6 | \$248 | |
| | Lighting - Wall Mounted | South | 1 | EA | 6 | \$124 | |
| | Stairs - Tile | South | 30 | LF | 6 | \$278 | |
| | Walls - Structural Glazed Tile | South | 950 | SF | 6 | \$2,989 | |
| Vertical | Conveyance | | | | | | |
| | Elevator - Elevator- Roped Holeless Hydraulic | | 1 | EA | 6 | \$19,238 | |
| Buildi | ng Interior Subtotal: | | | | \$67,020 | | |

Total Building Cost \$514,487

SITE

Category: Site

| Group Iter | m - Type | Location Quantity U | | | | Cost | Comments |
|--------------|---------------------------------|---------------------------|-------|----|---|----------|---|
| Civil/Draina | nge . | | | | | | |
| Civ | vil/ Drainage - Catch Basin | Entire Site | 3 | EA | 7 | \$0 | |
| Civ | vil/ Drainage - Catch Basin | Entire Site | 1 | EA | 5 | \$2,570 | Location: E play lot - sinking |
| Civ | vil/ Drainage - Site Drain | Entire Site / Boiler Room | 1 | EA | 5 | \$1,379 | clogged |
| Civ | vil/ Drainage - Site Manhole | Entire Site | 2 | EA | 7 | \$0 | |
| Fencing | | | | | | | |
| Fer | ncing - Chain Link | Entire Site | 700 | LF | 6 | \$13,143 | |
| Fer | ncing - New Standard Ornamental | Entire Site / South East | 384 | LF | 6 | \$12,251 | |
| Landscape | | | | | | | |
| Ber | enches | Entire Site / Courtyard | 1 | EA | 6 | \$430 | being stored - not for use in present location |
| Lan | ndscape - Grass | Entire Site | 9,929 | SF | 6 | \$8,235 | |
| Lan | ndscape - Hardscape- Asphalt | Entire Site / Site South | 640 | SF | 6 | \$1,547 | |
| Lan | ndscape - Hardscape- Concrete | Entire Site | 90 | SF | 5 | \$987 | Location: deck above exterior boiler room stairwell & Com Ed vault - exposed steel, spalling, efflorescence |
| Lan | ndscape - Hardscape- Concrete | Entire Site / Site - East | 735 | SF | 6 | \$3,794 | |
| Lan | ndscape - Hardscape- Pavers | Entire Site / Courtyard | 1,000 | SF | 5 | \$10,267 | Uneven surface |
| Par | rkway trees | Entire Site | 7 | EA | 7 | \$0 | |



2745 W Roosevelt Rd Chicago, IL 60608

SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|---------------------------------|----------|------|------|-----------|--|
| Landsc | аре | | | | | | |
| | Parkway trees | Entire Site / Site - East | 2 | EA | 4 | \$5,248 | missing |
| | Planting Beds/ Area | Entire Site | 440 | SF | 6 | \$724 | |
| | Play Area - Asphalt/ Hardscape | Entire Site / South East | 9,018 | SF | 4 | \$71,184 | Excessive cracks, water ponding, uneven surface |
| | Retaining Wall - Concrete | Entire Site / Boiler Room | 250 | SF | 6 | \$5,859 | |
| | Trash Receptacles | Entire Site / North West | 1 | EA | 6 | \$312 | |
| Parking | Lot | | | | | | |
| | Concrete Curbs | Parking Lot- South / South West | 30 | LF | 6 | \$385 | |
| | Surface - Asphalt | Parking Lot- South | 8,800 | SF | 6 | \$21,267 | |
| | Trash Enclosure - Chain Links | Parking Lot- South | 288 | SF | 6 | \$5,053 | |
| | Vehicular Screening | Parking Lot- South | 191 | LF | 6 | \$15,039 | |
| Playgro | und | | | | | | |
| | Equipment - Pre K 3-5 | SW site | 2 | EΑ | 6 | \$7,092 | |
| | Equipment - School Age 5-12 | SE site | 1 | EΑ | 5 | \$66,350 | graffiti |
| | Surface - Poured Surface | SE site | 2,609 | SF | 6 | \$19,102 | |
| | Surface - Poured Surface | SW site | 2,045 | SF | 6 | \$14,973 | |
| Sidewal | ks | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 121 | LF | 6 | \$1,453 | |
| | Sidewalks - Internal Walks | Entire Site | 10 | LF | 5 | \$578 | Location: N at flag pole - cracks |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 11,716 | SF | 6 | \$23,288 | |
| | Sidewalks - Perimeter Sidewalks | Entire Site / Site North | 175 | SF | 5 | \$1,672 | cracks, movement |
| | Sidewalks - Perimeter Sidewalks | Entire Site / Site South | 2,180 | SF | 5 | \$17,987 | pitting, cracks |
| | Sidewalks - Perimeter Sidewalks | Entire Site / South West | 360 | SF | 5 | \$3,439 | footprints & cracks |
| Signage | 9 | | | | | | |
| | Flag Pole - Flag Pole | Entire Site / Site North | 1 | EA | 5 | \$7,630 | leaning |
| | Marquee - Free Standing Back lighted w/ LED | Entire Site / North West | 1 | EA | 6 | \$0 | |
| | Monument - Building Mounted Cut Letter Sign | Entire Site | 2 | EA | 6 | \$0 | Location: Near door #9 - not cut letters, flat signage |
| Site S | ubtotal: | | | | | \$343,240 | |
| Total | Site Cost | | | | | \$343,240 | |

Campus Total ^{2 3} \$3,616,504



2745 W Roosevelt Rd Chicago, IL 60608

- ¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.
- ² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.
- ³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



2745 W Roosevelt Rd Chicago, IL 60608

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | | + | + | ! | | 1 | - | | ! | | | | - |
| Art Room | Art Room | 1st Floor | 110 | 110 | 856 | 1 | 2 | 10 | 219 | 48 | 40 | N | Υ | N |
| Art Room | Regular Classroom | 1st Floor | 114 | 114 | 910 | 0 | 0 | 4 | 219 | 10 | 40 | N | N | N |
| Computer Lab | Computer Lab | 1st Floor | 104 | 104 | 856 | 1 | 35 | 90 | 219 | 48 | 40 | N | Υ | N |
| Computer Lab | Computer Lab | 2nd Floor | 212 | 212 | 858 | 1 | 36 | 52 | 219 | 0 | 40 | N | Υ | N |
| Computer Lab | Computer Lab | 2nd Floor | 213 | 213 | 910 | 0 | 40 | 124 | 219 | 10 | 40 | N | N | Υ |
| Kindergarten | Kindergarten | 1st Floor | 106 | 106 | 805 | 1 | 2 | 12 | 219 | 56 | 40 | N | Υ | N |
| Kindergarten | Kindergarten | 1st Floor | 107 | 107 | 1,144 | | 2 | 4 | 281 | 10 | 40 | N | Υ | N |
| Kindergarten | Kindergarten | 1st Floor | 109 | 109 | 1,144 | | 2 | 4 | 281 | 10 | 40 | N | Υ | N |
| Music Room | Regular Classroom | 2nd Floor | 214 | 214 | 910 | 0 | 3 | 8 | 219 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 101 | 101 | 858 | 0 | 0 | 10 | 219 | 10 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 102 | 858 | 0 | 0 | 10 | 219 | 10 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 103 | 103 | 858 | 0 | 0 | 10 | 219 | 10 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 105 | 105 | 856 | 1 | 2 | 12 | 219 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 111 | 111 | 856 | 1 | 2 | 10 | 219 | 48 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 113 | 113 | 910 | 0 | 0 | 4 | 219 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 858 | 0 | 2 | 10 | 219 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 858 | 0 | 2 | 10 | 219 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 910 | 0 | 2 | 10 | 219 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 990 | 1 | 2 | 10 | 281 | 60 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 856 | 2 | 0 | 10 | 219 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 990 | 1 | 2 | 10 | 281 | 60 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 858 | 0 | 2 | 10 | 219 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 858 | 0 | 2 | 10 | 219 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 210 | 856 | 1 | 2 | 10 | 219 | 48 | 40 | N | Υ | N |
| Science Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 858 | 0 | 2 | 10 | 219 | 10 | 40 | N | N | N |
| Addition | | | | | | | | | | | | | | |
| Office | Regular Classroom | 2nd Floor | 218 | 218 | 805 | 1 | 2 | 10 | 157 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 118 | 118 | 805 | 1 | 2 | 12 | 157 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 216 | 216 | 805 | 1 | 2 | 12 | 157 | 10 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 217 | 217 | 805 | 1 | 2 | 12 | 157 | 10 | 40 | N | N | N |
| Store Room | Regular Classroom | 2nd Floor | 215 | 215 | 805 | 1 | 2 | 12 | 157 | 10 | 40 | N | N | N |