

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1917 | 3 | 96,895 | \$5,609,723 |
| SITE | | | | \$438,386 |
| Campus Total | | | 96,895 | \$6,048,109 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|----------------|----------|------|------|----------|---|
| Entranc | e | | | | | | |
| | Entrance Control - Audio and Video | 1 | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior FRP Door | 1 | 8 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior FRP Door | 2 | 3 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior FRP Door | 5 | 3 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | 3 | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | 4 | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | NE Boiler Room | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Overhead Rolling/ Garage Door | North Garage | 1 | EA | 6 | \$1,433 | |
| | Exterior Doors - Transom Lite | 1 | 8 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 2 | 3 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | 5 | 3 | EA | 7 | \$0 | |
| | Exterior Stairs - Concrete | 1 | 270 | LF | 6 | \$22,077 | |
| | Exterior Stairs - Concrete | 2 | 200 | LF | 5 | \$21,916 | cracks throughout |
| | Exterior Stairs - Concrete | 3 | 80 | LF | 5 | \$8,766 | spalls, cracks |
| | Exterior Stairs - Concrete | 4 | 40 | LF | 6 | \$3,271 | |
| | Exterior Stairs - Concrete | 5 | 200 | LF | 5 | \$21,916 | rebar exposed, spalled, cracks at entry |
| | Ramp Handrail - Steel_Ramp Handrail | 5 | 30 | LF | 6 | \$260 | |
| | Ramps - Concrete | 5 | 15 | LF | 6 | \$2,254 | |
| | Stair Handrail - Steel_Stair Handrail | 1 | 24 | LF | 6 | \$208 | |
| | Stair Handrail - Steel_Stair Handrail | 2 | 12 | LF | 6 | \$104 | |
| | Stair Handrail - Steel_Stair Handrail | 3 | 25 | LF | 6 | \$217 | |



Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|-----------------|----------|------|------|------------|------------|
| Entrand | e e | | | | | | |
| | Stair Handrail - Steel_Stair Handrail | 4 | 35 | LF | 6 | \$303 | |
| | Stair Handrail - Steel_Stair Handrail | 5 | 12 | LF | 6 | \$104 | |
| Founda | tion | | | | | | |
| Founda | Foundation - Masonry | Entire Building | 765 | LF | 7 | \$0 | |
| | Superstructure - Steel with Clay Tile Arch | Entire Building | 96,895 | SF | 7 | \$0 \$0 | |
| | Superstructure - Steel with Glay The Arch | Entire Building | 90,095 | 5 | 1 | φΟ | |
| Lightin | 9 | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 19 | EA | 6 | \$5,486 | |
| Roof S | vstem | | | | | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | D | 53 | LF | 6 | \$50,598 | strapped |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | D | 52 | LF | 6 | \$49,643 | |
| | Coping - Clay Tile | С | 25 | LF | 6 | \$803 | |
| | Coping - Metal | E | 92 | LF | 6 | \$2,955 | |
| | Coping - Stone | A | 241 | LF | 6 | \$7,740 | |
| | Coping - Stone | В | 894 | LF | 6 | \$28,713 | |
| | Coping - Stone | С | 25 | LF | 6 | \$803 | |
| | Coping - Stone | D | 42 | LF | 6 | \$1,349 | |
| | Downspouts - Exterior Downspouts | A | 12 | LF | 6 | \$399 | |
| | Downspouts - Exterior Downspouts | В | 20 | LF | 6 | \$665 | |
| | Downspouts - Exterior Downspouts | E | 30 | LF | 6 | \$997 | |
| | Downspouts - Interior Downspouts | В | 98 | LF | 6 | \$3,257 | |
| | Downspouts - Interior Downspouts | D | 104 | LF | 6 | \$3,456 | |
| | Parapet - 16" - 30" Height | В | 835 | LF | 6 | \$33,362 | |
| | Parapet - 16" - 30" Height | В | 5 | LF | 5 | \$1,218 | step crack |
| | Parapet - 16" - 30" Height | С | 50 | LF | 6 | \$1,998 | |
| | Parapet - Parapet < 16" Height | А | 241 | LF | 6 | \$5,135 | |
| | Parapet - Parapet < 16" Height | D | 42 | LF | 6 | \$895 | |
| | Parapet - Parapet < 16" Height | E | 92 | LF | 6 | \$1,960 | |
| | Parapet - Parapet > 30" | В | 54 | LF | 6 | \$3,452 | |
| | Roof Structure - Steel with Clay Tile Arch | A | 7,215 | SF | 7 | \$0 | |
| | Roof Structure - Steel with Clay Tile Arch | В | 18,656 | SF | 7 | \$0 | |
| | Roof Structure - Steel with Clay Tile Arch | С | 1,625 | SF | 7 | \$0 | |
| | Roof Structure - Steel with Clay Tile Arch | D | 8,526 | SF | 7 | \$0 | |
| | Roof Structure - Steel with Clay Tile Arch | E | 480 | SF | 7 | \$0 | |
| | Roof - Asphalt Gravel Ballast | А | 7,215 | SF | 6 | \$73,357 | |
| | Roof - Asphalt Gravel Ballast | В | 18,631 | SF | 6 | \$189,427 | |
| | Roof - Asphalt Gravel Ballast | С | 1,625 | SF | 6 | \$16,522 | |



Building: Main

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|-------------------------|----------|------|------|-----------|-------------------------------------|
| Roof S | ystem | | | | | | |
| | Roof - Asphalt Gravel Ballast | D | 5,646 | SF | 6 | \$57,405 | |
| | Roof - EPDM/ Synthetic Rubber | D / North | 2,730 | SF | 6 | \$23,111 | |
| | Roof - Metal | В | 25 | SF | 6 | \$335 | air intake |
| | Roof - Metal | D / Courtyard | 150 | SF | 6 | \$2,010 | shed roof |
| | Roof - Modified Bitumen | E | 480 | SF | 6 | \$4,517 | |
| Walls | | | | | | | |
| | Cheek-Wall - Concrete | Entire Building | 80 | SF | 4 | \$4,694 | spalling, cracks, work order placed |
| | Cheek-Wall - Concrete | Entire Building | 40 | SF | 5 | \$943 | spalling, cracks |
| | Cornice - Masonry Projecting Limestone | Entire Building | 490 | LF | 6 | \$16,992 | |
| | Exterior Walls - Brick | Entire Building | 28,567 | SF | 6 | \$191,999 | |
| | Exterior Walls - Prefabricated Metal Panel Wall | Entire Building / Roof | 158 | SF | 7 | \$0 | |
| | Exterior Walls - Prefabricated Metal Panel Wall | Entire Building / Roof | 1,332 | SF | 6 | \$7,562 | |
| | Exterior Walls - Stone-Cut | Entire Building | 4,088 | SF | 6 | \$27,475 | |
| | Exterior Walls - Stone-Cut | Entire Building / West | 10 | SF | 5 | \$176 | cracks |
| Window | vs | | | | | | |
| | Clerestory - Glass Single-Pane | Entire Building / Roof | 45 | SF | 5 | \$1,911 | |
| | Guard - Guards perforated | Entire Building | 2,392 | SF | 6 | \$30,546 | |
| | Guard - Guards wire guard | Entire Building | 249 | SF | 5 | \$3,817 | |
| | Lintels - Steel | Entire Building | 970 | LF | 6 | \$28,158 | |
| | Windows - Decorative | Entire Building | 1,347 | SF | 6 | \$10,055 | fixed |
| | Windows - Louver | Entire Building / North | 8 | SF | 6 | \$60 | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 8,252 | SF | 6 | \$61,598 | |
| | | | | | | | |

Building Exterior Subtotal:

\$1,043,266

Building: Main

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|-----------------------------|----------|------|------|---------|----------|
| Emerge | ncy System | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | \$408 | |
| | Emergency A/C Power - Auditoium and Aisle Lighting | Entire Building / 1st Floor | 10,545 | SF | 6 | \$5,579 | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 21,602 | SF | 6 | \$6,487 | |
| | Emergency A/C Power - Gym | Entire Building / 2nd Floor | 2,763 | SF | 6 | \$1,027 | |
| | Emergency A/C Power - Lunchrooms | Entire Building / 1st Floor | 3,008 | SF | 6 | \$1,118 | |
| | Emergency Battery Packs - Auditoium and Aisle Lighting | Entire Building / 1st Floor | 8 | EA | 6 | \$1,620 | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 19 | EA | 6 | \$3,848 | |



Building: Main

Category: Electrical System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|-------------------------------|----------|------|------|-----------|--|
| Emergency System | | | | | | |
| Emergency Battery Packs - Gym | Entire Building / 2nd Floor | 2 | EA | 4 | \$1,158 | Obsolete. Appears in poor condition |
| Exit Signs - Auditoium | Entire Building / 1st Floor | 12 | EA | 6 | \$1,797 | |
| Exit Signs - Corridors and Stairs | Entire Building | 30 | EA | 6 | \$4,492 | |
| Exit Signs - Gym | Entire Building / 2nd Floor | 2 | EA | 6 | \$315 | |
| Exit Signs - Lunchroom | Entire Building / 1st Floor | 2 | EA | 6 | \$299 | |
| Exit Signs - Lunchroom | Entire Building / 1st Floor | 2 | EA | 2 | \$1,091 | Do not have a battery backup. School has no E generator or UPS installed |
| Security System - CCTV | Entire Building | 96,895 | SF | 6 | \$29,098 | |
| Security System - Intrusion Detection | Entire Building | 96,895 | SF | 6 | \$24,941 | |
| Main Service | | | | | | |
| Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | \$2,921 | |
| Main Electrical Service - 2000 A 120/208/3PH | Electrical Room | 1 | EA | 6 | \$8,232 | |
| PA System | Entire Building / 1st Floor | 96,895 | SF | 4 | \$422,608 | Not currently working. |
| Power Distribution | | | | | | |
| Lighting and Power Panels - 100 A | Entire Building | 3 | EA | 6 | \$897 | |
| Lighting and Power Panels - Above 100 A | Entire Building | 11 | EA | 6 | \$5,467 | |
| Main Distribution Panels - 400 - 600 amp | Entire Building / Boiler Room | 2 | EA | 6 | \$1,055 | |
| Electrical System Subtotal: | | | | | \$524,459 | |
| Building: Main | | | | | | |
| Category: Safty System | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Fire Alarm | | | | | | |
| Fire Alarm Panel | Boiler Room | 1 | EA | 6 | \$6,406 | |
| Fire Alarm_System | Boiler Room / Entire Building | 69,895 | SF | 6 | \$33,983 | |
| Safty System Subtotal: | | | | | \$40,389 | |

Safty System Subtotal:

Building: Main

Category: Mechanical System

| - | | | | | | |
|----------|---|-----------------------------|---------|--------|------|---------------|
| Group | tem - Type | Location | Quantit | / Unit | Rank | Cost Comments |
| Air Hand | ing Systems | | | | | |
| | Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 | Mechanical Room / 1st Floor | 1 | EA | 6 | \$5,788 |
| | xfm | | | | | |



Category: Mechanical System

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|--------------------------------|----------|------|-------|-----------|--|
| | | | Quantity | Unit | Nalik | COST | Comments |
| Air Han | dling Systems | Machanical Deers / Act Elean | 4 | | 0 | ¢44.007 | |
| | Air Handling Unit- Built Up-Multi Zone-Double Delivery- Steam Coils - 45001 - 60000 cfm | Mechanical Room / 1st Floor | 1 | | 6 | \$11,837 | |
| | Air Intake | Mechanical Room / Lower Roof | 2 | EA | 6 | \$11,529 | |
| | Air Intake | Mechanical Room / South Façade | 1 | EA | 6 | \$5,765 | |
| | Auxiliaries - 15001 - 25000 cfm | Mechanical Room / 1st Floor | 1 | EA | 4 | \$36,420 | Dampers are in poor conditions |
| | Auxiliaries - 45001 - 60000 cfm | Mechanical Room / 1st Floor | 1 | EA | 4 | \$58,901 | Dampers are in poor conditions |
| | Zone Dampers | Mechanical Room | 37 | EA | 4 | \$177,329 | Dampers are rusted. Actuators are not working or communicating properly |
| Boiler S | Systems | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 6 | \$5,091 | |
| | Chemical Feed System | Boiler Room | 2 | EA | 6 | \$2,156 | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | \$818 | |
| | Condensate Pump | Boiler Room | 1 | EA | 6 | \$2,021 | |
| | Condensate Pump | Boiler Room / Mechanical Room | 1 | EA | 6 | \$2,021 | |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 6 | \$2,545 | |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 6 | \$5,091 | Forced draft. |
| | Piping - Condensate Pipe- Steel | Boiler Room | 300 | LF | 6 | \$566 | |
| | Piping - Steam Pipe- Steel | Boiler Room | 300 | LF | 6 | \$566 | |
| | Steam Traps | Boiler Room / Mechanical Room | 1 | EA | 6 | \$264 | |
| Heating | Devices | | | | | | |
| | Cabinet Heaters - With Steam Coil | 1st Floor | 1 | EA | 6 | \$357 | |
| | Cabinet Heaters - With Steam Coil | 1st Floor / 2nd Floor | 1 | EA | 4 | \$3,851 | Appears to be in poor condition. Unit has no cove |
| | Unit Heater - Electric | Boiler Room / Electrical Room | 1 | EA | 6 | \$278 | |
| | Unit Heater - Gas | Boiler Room | 1 | EA | 6 | \$278 | |
| | Wall Heater - Electric | Entire Building | 13 | EA | 4 | \$14,073 | Appears to be in poor conditions |
| | Wall Heater - Electric | Entire Building | 7 | EA | 6 | \$972 | |
| Temper | rature Control | | | | | | |
| | Pneumatic System | Entire Building | 96,895 | SF | 4 | \$504,358 | Sensors are not responding |
| | Thermostats - Pneumatic | Entire Building | 40 | EA | 4 | \$29,489 | Thermostats are not working |
| Ventilat | tion | | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Lower Roof / 1st Floor | 2 | EA | 4 | \$8,489 | Appears not to be in good operating condition. |
| | Exhaust Fans- Indoor - Less than 500 CFM | Lower Roof / Boiler Room | 1 | EA | 6 | \$296 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Lower Roof | 3 | EA | 6 | \$1,777 | |
| | Type I Exhaust Hood- Kitchen | Lower Roof / 1st Floor | 1 | EA | 3 | \$28,265 | No fire suppression |
| | | | | | | | |



| Category: | Mechanical | System |
|-----------|------------|--------|
|-----------|------------|--------|

| Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------------|---|---|--|---|--|
| | | | | \$921,192 | |
| | | | | | |
| | | | | | |
| Location | Quantity | Unit | Rank | Cost | Comments |
| | | | | | |
| Boiler Room | 1 | EA | 6 | \$310 | |
| | | | | | |
| Entire Building | 96,895 | SF | 4 | \$69,280 | Galvanized piping and more than 50 yrs old |
| Entire Building | 96,895 | SF | 4 | \$139,945 | Galvanized piping and more than 50 yrs old |
| Entire Building | 96,895 | SF | 4 | \$77,594 | Galvanized piping and more than 50 yrs old |
| Entire Building | 96,895 | SF | 4 | \$52,653 | Galvanized piping and more than 50 yrs old |
| Entire Building | 96,895 | SF | 4 | \$124,704 | Galvanized piping and more than 50 yrs old |
| Entire Building | 96,895 | SF | 4 | \$83,136 | Galvanized piping and more than 50 yrs old |
| Entire Building | 96,895 | SF | 4 | \$47,110 | Galvanized piping and more than 50 yrs old |
| Entire Building | 96,895 | SF | 6 | \$88,678 | |
| Entire Building | 96,895 | SF | 6 | \$84,522 | |
| Entire Building | 96,895 | SF | 6 | \$65,123 | |
| | | | | | |
| Boiler Room | 1 | EA | 4 | \$25,441 | Pump is in poor condition. Not currently in use because city pressure is adequate. |
| Boiler Room / 1st Floor | 4 | EA | 4 | \$11,443 | Pump is in poor condition |
| | Location Boiler Room Entire Building Entire Building | LocationQuantityBoiler Room1Entire Building96,895Entire Building96,895 | LocationQuantityUnitBoiler Room1EAEntire Building96,895SFEntire Building96,895SF | LocationQuantityUnitRankBoiler Room1EA6Entire Building96,895SF4Entire Building96,895SF4Entire Building96,895SF4Entire Building96,895SF4Entire Building96,895SF4Entire Building96,895SF4Entire Building96,895SF4Entire Building96,895SF4Entire Building96,895SF4Entire Building96,895SF6Entire Building96,895SF6Entire Building96,895SF6Entire Building96,895SF6Entire Building96,895SF6Entire Building96,895SF6Entire Building96,895SF6Entire Building96,895SF6 | LocationQuantityUnitRankCostBoiler Room1EA6\$310Entire Building96,895SF4\$69,280Entire Building96,895SF4\$139,945Entire Building96,895SF4\$139,945Entire Building96,895SF4\$124,704Entire Building96,895SF4\$124,704Entire Building96,895SF4\$124,704Entire Building96,895SF4\$83,136Entire Building96,895SF4\$83,136Entire Building96,895SF4\$84,7110Entire Building96,895SF6\$88,678Entire Building96,895SF6\$84,522Entire Building96,895SF6\$84,522Entire Building96,895SF6\$86,123 |

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|----------|----------|------|------|---------|----------|
| Classro | om #101 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 18 | LF | 6 | \$455 | |
| | Ceiling - Plaster/Drywall | | 814 | SF | 6 | \$2,817 | |
| | Doors - Transom Window | | 6 | SF | 6 | \$102 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 814 | SF | 6 | \$5,739 | |
| | Lighting - Pendent/Surface | | 12 | EA | 7 | \$0 | |

Building: Main

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|-----------|----------|------|------|----------|-------------------|
| - | om #101 (Regular Classroom) | | | 2 | | | |
| | Marker Board | | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | | 14 | SF | 6 | \$102 | |
| | Walls - Plaster/Drywall | | 1,319 | SF | 6 | \$3,640 | |
| | | | | | | . , | |
| | om #107 (Counseling Room) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | \$0 | |
| | Casework | 1st Floor | 6 | LF | 6 | \$152 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 765 | SF | 7 | \$0 | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | | obsolete material |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 1st Floor | 765 | SF | 6 | \$5,393 | |
| | Lighting - Pendent/Surface | 1st Floor | 10 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 6 | \$386 | |
| | Storage/ Closet | 1st Floor | 74 | SF | 5 | \$1,194 | |
| | Walls - Plaster/Drywall | 1st Floor | 892 | SF | 5 | \$6,760 | |
| assroo | om #108 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 6 | LF | 6 | \$152 | |
| | Ceiling - Plaster/Drywall | | 754 | SF | 6 | \$2,609 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 754 | SF | 6 | \$5,316 | |
| | Lighting - Pendent/Surface | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | | 93 | SF | 6 | \$674 | |
| | Walls - Plaster/Drywall | | 1,372 | SF | 5 | \$10,398 | |
| assroo | om #109 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 6 | LF | 6 | \$152 | |
| | Ceiling - Plaster/Drywall | | 735 | SF | 6 | \$2,544 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 735 | SF | 6 | \$5,182 | |
| | Lighting - Pendent/Surface | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | | 93 | SF | 6 | \$674 | |
| | Walls - Plaster/Drywall | | 1,353 | SF | 6 | \$3,734 | |



| Classroom 1 | | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|---------|------------------------------|-----------|----------|------|------|----------|----------|
| AC Units 1st Floor 72 SP 6 Calling - Pasker/Dynall 1st Floor 72 SF 6 St52 Doors - Transom Window 1st Floor 72 SF 6 St51 Doors - Wood Doors inclu hw 1st Floor 72 SF 6 St51 Liphting - Pendent/Surface 1st Floor 72 SF 6 St51 Marker Board 1st Floor 12 EA 7 \$0 Marker Board 1st Floor 12 EA 7 \$0 Storage/ Cleet 1st Floor 12 EA 7 \$0 Marker Board 1st Floor 12,42 SF 6 \$53,94 Clears - Transom Window 9 SF 6 \$52,47 Clears - Transom Window 9 SF 6 \$52,47 Doors - Transom Window 9 SF 6 \$53,43 Doors - Transom Window 9 SF 6 \$53,43 Doors - Transom Window 75 SF 6 \$53,43 Doors - Transom Window <th>•</th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> | • | | | | | | | |
| Doors - Transon Window 1st Floor 9 8F 6 \$152 Doors - Wood Doors inclu hw 1st Floor 72 2F 6 \$5301 Lighting - Perdent/Surface 1st Floor 12 EA 7 \$30 Marker Eoord 1st Floor 18 E 6 \$5386 Storagel Closet 1st Floor 18 E 6 \$5386 Valle - Plester/Dywall 1st Floor 18 E 6 \$5386 Valle - Plester/Dywall 1st Floor 18 E 6 \$5386 Casework 9 F 6 \$5386 Casework 9 SF 6 \$5227 Caling - Plaster/Dywall 75 SF 6 \$5393 Doors - Transon Window 1 F 6 \$5393 Doors - Wood Doors inclu hw 1 F 6 \$5391 Doors - Wood Doors inclu hw 18 F 6 \$5471 Marker Boord 18 F 6 \$5491 Queling - Plester/Dywall 773 <td< td=""><td></td><td></td><td>1st Floor</td><td>1</td><td>EA</td><td>7</td><td>\$0</td><td></td></td<> | | | 1st Floor | 1 | EA | 7 | \$0 | |
| Doors Transon Mist Floor 9 FF 6 \$152 Doors Nood Doors inclu hw 1st Floor 732 SF 8 \$55,161 Liphing -Pendert/Surface 1st Floor 12 EA 7 \$30 Maker Board 1st Floor 18 EF 6 \$5386 Storage Closet 1st Floor 18 EF 6 \$5386 Wals - Plaster/Dywall 1st Floor 18 EA 7 \$30 Closer 41 EA 7 \$30 \$31 Closerson 1 EA 7 \$32 Caling -Plaster/Dywall 15 F 6 \$327 Caling -Plaster/Dywall 76 SF 6 \$3301 Floor Vaod Doors inclu hw 1 EA 6 \$3301 Floor Vaod Doors inclu hw 1 EA 6 \$3301 Floor Vaod Doors inclu hw 17 EA | | Ceiling - Plaster/Drywall | 1st Floor | 732 | SF | 6 | \$2,533 | |
| Floor YWood 1st Floor 72 SF 6 \$3,161 Lighting - Pendent/Surface 1st Floor 18 Floor 8 Floor 6 \$336 Storage Closet 1st Floor 18 Floor 8 Floor 6 \$336 Walls - Plaster/Drywall 1st Floor 18 Floor \$5 6 \$5,394 Conservertite Call to this 5 6 \$2,27 Call to this 1 FA 7 \$5 Casework 9 FF 6 \$2,27 Doors - Trenson Window 0 SF 6 \$3,301 Doors - Wood Doors inclu hw 75 SF 6 \$3,301 Lighting - Pendent/Surface 1374 SF 6 \$3,301 Lighting - Pendent/Surface 1374 SF 6 \$3,301 Casework 9 SF 6 \$3,301 Undits SF 6 \$3,301 | | | 1st Floor | 9 | SF | 6 | | |
| Lighting - Pendent/Surface 1st Floor 12 EA 7 \$0 Marker Board 1st Floor 88 5 6 \$3805 Walls - Plaster/Dryvall 1st Floor 88 5 5 \$5 Walls - Plaster/Dryvall 1st Floor 142 5 5 \$5 AC Unis - 5 5 5 5 5 5 Casework 9 F 6 \$22,47 Doors - Transon Window 9 F 6 \$22,647 Doors - Wood Doors inclu hw 1 FA 6 \$3,014 Floor 15 FA 6 \$3,014 Floor 765 SF 6 \$3,014 Floor 765 SF 6 \$3,014 Floor 765 SF 6 \$3,014 Valls - Plaster/Dryvall 75 SF 6 \$3,014 Walls - Plaster/Dryvall 15 S 5 5 5 < | | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Markar Baard 1st Floor 18 LF 6 \$338 Storage/Closet 1st Floor 88 6 \$363 Walle - Plaster/Drywall 1st Floor 1420 \$F 6 \$363 Classcomer - - - \$5 6 \$363 Classcomer - - - \$5 6 \$363 Casework - - - \$5 6 \$22,647 Doors - Transom Window 9 SF 6 \$333 \$5 6 \$5333 Doors - Transom Window 9 SF 6 \$5333 \$5 6 \$547 Doors - Transom Window 765 SF 6 \$5331 \$5 6 \$547 Boor - Wood 765 SF 6 \$5471 \$5 \$6 \$5471 Walls - Plaster/Drywall Storage/Closet 68 SF 6 \$5471 Walls - Plaster/Drywall Storage/Closet 2 | | Floor - Wood | 1st Floor | 732 | SF | 6 | \$5,161 | |
| Storage Close: 1st Floor 88 97 6 \$53.34 Walls - Plaster/Dywall 1st Floor 142 57 6 \$52.34 Closework 9 15 6 \$52.27 Calling 9 15 6 \$52.27 Calling - Plaster/Dywall 97 5 6 \$52.27 Doors - Transon Window 9 55 6 \$53.33 Doors - Wood Doors inclu hw 1 EA 7 \$6 Floor - Wood 9 55 6 \$53.33 Uighting - Pender/Surface 1 EA 6 \$53.33 Uighting - Pender/Surface 1 EA 6 \$53.33 Walls - Plaster/Dywall 1 EA 6 \$53.33 Walls - Plaster/Dywall 1 EA 6 \$53.33 Walls - Plaster/Dywall 2 EA 6 \$53.44 Galage / Doors inclu hw 1 EA 7 50 Caster/Dywall 1 | | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 7 | \$0 | |
| Walls - Plaster/Dywall 1st Floor 1,429 SF 6 \$3,944 Classroom #111 (Regular Classroom I EA 7 \$0 AC Units 1 EA 7 \$0 Casework 1 EA 6 \$2,247 Coling - Plaster/Dywall 765 \$F 6 \$2,2647 Doors - Transom Window 765 \$F 6 \$3,014 Doors - Wood Doors inclu hw 1 EA 6 \$3,014 I. Light in Plaster/Dywall 765 \$F 6 \$3,014 Doors - Wood Doors inclu hw 1 EA 6 \$3,014 Light in Plaster/Dywall 785 \$F 6 \$3,014 Marker Board 18 LF 6 \$3,014 Marker Board 13 SF 6 \$3,014 Walls - Plaster/Dywall 13/14 SF 6 \$2,217 Clutis 2 FA 6 \$2,217 Celling - Plaster/Dywall 13/14 SF 6 \$2,227 Celling - Plaster/Dywall 2 FA 6 \$2,217 Celling - Plaster/Dywall 2 FA 6 \$2,2605 Doors - Transom Window | | Marker Board | 1st Floor | 18 | LF | 6 | \$386 | |
| Classroom #111 (Regular Classroom) 1 EA 7 \$0 AC Units 1 EA 7 \$0 Casework 9 LF 6 \$2,247 Doors - Transon Window 9 SF 6 \$2,647 Doors - Transon Window 9 SF 6 \$3152 Doors - Wood Doors inclu hw 1 EA 6 \$53,393 Lighting - Pendent/Surface 12 EA 6 \$1487 Marker Board 13 LF 6 \$3366 Storage/ Closet 65 SF 6 \$227 Casework 13 LF 6 \$3368 Casework 13/4 SF 6 \$33792 Claseter/Drywall 13/74 SF 6 \$3217 Colinis Casework 9 LF 6 \$3217 Coloris Casework 9 LF 6 \$2206 Doors - Wood Doors inclu hw 1 EA 7 \$0 \$0 Casework 9 LF 6 | | Storage/ Closet | 1st Floor | 88 | SF | 6 | \$638 | |
| AC Units 1 EA 7 \$0 Casework 9 LF 6 \$227 Caling - Plaster/Drywall 765 \$SF 6 \$\$2,647 Doors - Transom Window 9 SF 6 \$\$122 Doors - Transom Window 9 SF 6 \$\$122 Doors - Wood Doors inclu hw 1 EA 6 \$\$101 Floor - Wood 765 SF 6 \$\$12,87 Marker Board 18 LF 6 \$\$3,86 Storage/ Closet 65 SF 6 \$\$3,792 Casework 112 (Kindergarten) Casework 9 LF 6 \$\$227 Caling - Plaster/Drywall 753 SF 6 \$\$23,792 Casework 9 LF 6 \$\$227 Casework 9 LF 6 \$22,606 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood 753 | | Walls - Plaster/Drywall | 1st Floor | 1,429 | SF | 6 | \$3,944 | |
| Casework 9 LF 6 \$\$227 Ceiling - Plater/Dryvall 766 \$\$2 6 \$\$22,47 Doors - Transom Window 19 \$ 6 \$\$301 Doors - Wood Doors inclu hw 1 \$ 6 \$\$5,33 Lighting - Pendent/Surface 12 \$ 6 \$\$4,47 Marker Board 138 LF 6 \$\$4,47 Marker Board 138 LF 6 \$\$4,47 Walls - Plaster/Drywall 137 \$F 6 \$\$4,71 Walls - Plaster/Drywall 137 \$F 6 \$\$4,71 Casework 138 LF 6 \$\$2,87 Casework 765 \$F 6 \$\$2,90 Doors - Transon Window 753 \$F 6 \$\$2,60 Doors - Transon Window 753 \$F 6 \$\$3,03 Doors - Wood Doors inclu hw 1 EA 6 \$\$3,03 Doors - Wood Doors inclu hw 7 \$\$0 \$\$3,03 Lighting - Pendent/Surface 10 EA 6 | Classro | oom #111 (Regular Classroom) | | | | | | |
| Ceiling - Plaster/Drywall 765 SF 6 \$2,647 Doors - Transom Window 9 SF 6 \$152 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood 765 SF 6 \$53,33 Lighting - Pendent/Surface 12 EA 6 \$31,487 Marker Board 18 LF 6 \$386 Storage/ Closet 6 \$31,792 6 \$387 Walls - Plaster/Drywall 1,374 SF 6 \$991 AC Units 2 EA 6 \$991 Casework 9 LF 6 \$991 Ceiling - Plaster/Drywall 753 SF 6 \$227 Ceiling - Plaster/Drywall 753 SF 6 \$5301 Doors - Transom Window 9 SF 6 \$5152 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood SF S 5 5 \$5152 Doors - Wood Doors inclu hw 1 EA < | | AC Units | | 1 | EA | 7 | \$0 | |
| Doors - Trasom Window 9 SF 6 \$152 Doors - Wood Doors inclu hw 1 EA 6 \$331 Floor - Wood T65 SF 6 \$53.93 Lighting - Pendent/Surface 12 EA 6 \$147 Marker Board 18 LF 6 \$336 Storage/ Closet 1.374 SF 6 \$\$379 Classroom/Kindergarten/Dryvall AC Units 2 EA 6 \$\$227 Ceiling - Plaster/Dryvall 73 SF 6 \$\$216 Doors - Trasom Window 9 SF 6 \$\$216 Doors - Wood Doors inclu hw 1 EA 6 \$\$301 Floor - Wood 73 SF 6 \$\$325 Marker Board 22 LF 6 \$335 Mar | | Casework | | 9 | LF | 6 | \$227 | |
| Doors - Wood Doors inclu hw 1 FA 6 \$3301 Floor - Wood 765 SF 6 \$5,333 Lighting - Pendent/Surface 12 EA 6 \$1,487 Marker Board 18 LF 6 \$3366 Storage/ Closet 65 SF 6 \$471 Walls - Plaster/Dryvall 1.74 SF 6 \$491 Classroot #112 (Kindergarten) 2 KA 6 \$991 Casework 9 LF 6 \$227 Celling - Plaster/Drywall 753 SF 6 \$240 Doors - Transom Window 9 LF 6 \$220 Doors - Wood Doors inclu hw 1 EA 6 \$152 Doors - Transom Window 9 SF 6 \$3361 Ploor - Wood 753 SF 6 \$3509 Lighting - Pendent/Surface 1 EA 6 \$351 Marker Board 128 SF 5 \$10,504 Marker Board 1386 SF 5 \$10, | | Ceiling - Plaster/Drywall | | 765 | SF | 6 | \$2,647 | |
| Floor - Wood 765 SF 6 \$\$5,393 Lighting - Pendent/Surface 12 EA 6 \$\$1,437 Marker Board 18 LF 6 \$\$471 Walls - Plaster/Dryvall 1,374 SF 6 \$\$471 Closer AC Units 2 EA 6 \$\$991 Casework 9 LF 6 \$\$227 Casework 9 LF 6 \$\$227 Coling - Plaster/Dryvall 76 \$\$2,806 \$\$161 Doors - Transon Window 9 SF 6 \$\$152 Doors - Wood Doors inclu hw 1 EA \$\$16 \$\$2,006 Ighting - Pendent/Surface 75 SF \$\$6 \$\$152 Doors - Wood Doors inclu hw 1 EA \$\$6 \$\$152 Ighting - Pendent/Surface 12 LF \$\$6 \$\$151 Marker Board 128 SF \$\$6 \$\$471 Storage/ Closet 1,38 SF \$\$5 \$\$10,504 Walls - Plaster/Dryvall 1,3 | | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| Lighting - Pendent/Surface 12 EA 6 \$1,487 Marker Board 18 LF 6 \$336 Storage/Closet 65 SF 6 \$471 Walls - Plaster/Drywall 1,37 SF 6 \$3792 Casework 8 K 6 \$991 Casework 9 LF 6 \$227 Ceiling - Plaster/Drywall 753 SF 6 \$152 Doors - Transon Window 9 SF 6 \$3301 Doors - Transon Window 9 SF 6 \$53.09 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 28 S 6 \$53.09 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 12 K 6 \$3371 Storage/Closet 49 SF 6 \$353 Walls - Plaster/Drywall 1386 SF 5 \$10,504 Walls - Plaster/Drywall Storage/Closet \$379 \$10,504 | | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| Marker Board 18 LF 6 \$3386 Storage/ Closet 66 SF 6 \$441 Walls - Plaster/Drywall 1,374 SF 6 \$3,792 Closet AC Units 8 S 6 \$921 Casework 9 LF 6 \$227 Celling - Plaster/Drywall 753 SF 6 \$243 Doors - Transom Window 9 SF 6 \$315 Doors - Transom Window 1 EA 6 \$331 Floor - Wood 1 EA 6 \$5,309 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 1,386 SF 6 \$343 Marker Board 1,386 SF 6 \$5,309 Marker Board 1,386 SF 6 \$5,309 Marker Board 1,386 SF 6 \$411 Storage/ Closet 49 SF 6 \$335 Walls - Plaster/Drywall 1,386 SF <td< td=""><td></td><td>Floor - Wood</td><td></td><td>765</td><td>SF</td><td>6</td><td>\$5,393</td><td></td></td<> | | Floor - Wood | | 765 | SF | 6 | \$5,393 | |
| Storage/ Closet 66 87 6 \$471 Walls - Plaster/Drywall 1,374 97 6 \$3,792 Classroum#112 (Kindergaren) AC Units 2 EA 6 \$991 Casework 9 LF 6 \$227 Ceiling - Plaster/Drywall 733 SF 6 \$252 Doors - Transom Window 9 LF 6 \$231 Doors - Wood Doors inclu hw 1 EA 6 \$331 Floor - Wood 753 SF 6 \$5309 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 22 LF 6 \$471 Storage/ Closet 49 SF 5 \$10,504 Walls - Plaster/Drywall 18 SF 5 \$10,504 Warker Board 18 SF 5 \$10,504 Wark Sink 1 EA 6 \$3379 | | Lighting - Pendent/Surface | | 12 | EA | 6 | \$1,487 | |
| Walls - Plaster/Drywall 1,374 SF 6 \$3,792 Classroum #112 (Kindergarten) AC Units 2 EA 6 \$991 Casework 9 LF 6 \$227 Ceiling - Plaster/Drywall 753 SF 6 \$2,606 Doors - Transom Window 9 SF 6 \$152 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood 753 SF 6 \$5,309 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 22 LF 6 \$315 Walls - Plaster/Drywall 1386 SF 5 \$10,504 Work Sink 1 EA 7 \$37 AC Units SF 5 \$10,504 Vork Sink 1 EA 6 \$375 Ceiling - Plaster/Drywall 1 EA 6 \$370 Caserout 1 EA 6 \$370 Caserout 1 EA 6 \$370 <td></td> <td>Marker Board</td> <td></td> <td>18</td> <td>LF</td> <td>6</td> <td>\$386</td> <td></td> | | Marker Board | | 18 | LF | 6 | \$386 | |
| Classroom #12 (Kindergaren) 2 EA 6 \$991 AC Units 2 EA 6 \$991 Casework 9 LF 6 \$227 Ceiling - Plaster/Drywall 753 SF 6 \$2152 Doors - Transom Window 9 SF 6 \$301 Floor - Wood 73 SF 6 \$5309 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 22 LF 6 \$411 Storage/ Closet 49 SF 6 \$325 Walls - Plaster/Drywall 1386 SF 5 \$10,504 Work Sink 1 EA 7 \$0 Closet 1386 SF 5 \$10,504 Work Sink 1 EA 7 \$0 Closet 1 EA 7 \$0 Work Sink 1 EA 5 \$10,504 Work Sink 1 EA 7 \$0 Ceiling - Plaster/Drywall ST SF <td></td> <td>Storage/ Closet</td> <td></td> <td>65</td> <td>SF</td> <td>6</td> <td>\$471</td> <td></td> | | Storage/ Closet | | 65 | SF | 6 | \$471 | |
| AC Units 2 EA 6 \$991 Casework 9 LF 6 \$227 Ceiling - Plaster/Drywall 753 SF 6 \$2,606 Doors - Transom Window 9 SF 6 \$152 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood 753 SF 6 \$5,309 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 22 LF 6 \$471 Storage/ Closet 49 SF 6 \$335 Walls - Plaster/Drywall 1,386 SF 5 \$10,504 Work Sink 1 EA 6 \$3379 | | Walls - Plaster/Drywall | | 1,374 | SF | 6 | \$3,792 | |
| Casework 9 LF 6 \$227 Ceiling - Plaster/Drywall 753 SF 6 \$2,606 Doors - Transom Window 9 SF 6 \$152 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood 753 SF 6 \$5,309 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 22 LF 6 \$471 Storage/ Closet 49 SF 6 \$355 Walls - Plaster/Drywall 1,386 SF 5 \$10,504 Work Sink 1 EA 6 \$379 Classrout 13 EA 6 \$379 Classrout 1 EA 6 \$379 Marker Board 2 S \$10,504 \$379 Work Sink 1 EA 6 \$379 Classrout 2 K 5 \$10,504 Marker Doors (Lobst 2 S \$2 \$2 AC Units Coling - Pl | Classro | oom #112 (Kindergarten) | | | | | | |
| Ceiling - Plaster/Drywall 753 SF 6 \$2,606 Doors - Transom Window 9 SF 6 \$152 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood 753 SF 6 \$5,309 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 22 LF 6 \$471 Storage/ Closet 49 SF 6 \$335 Walls - Plaster/Drywall 1,386 SF 5 \$10,504 Work Sink 1 EA 7 \$0 Centister Computer Lab AC Units 2 EA 7 \$0 Celling - Plaster/Drywall 2 SF 6 \$379 | | AC Units | | 2 | EA | 6 | \$991 | |
| Doors - Transom Window 9 SF 6 \$152 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood 753 SF 6 \$5,309 Lighting - Pendent/Surface 10 EA 7 \$00 Marker Board 22 LF 6 \$471 Storage/ Closet 49 SF 6 \$355 Walls - Plaster/Drywall 1,386 SF 5 \$10,504 Work Sink 1 EA 6 \$379 Classroom #203 (Computer Lab) 2 EA 7 \$00 AC Units 2 EA 7 \$00 Ceiling - Plaster/Drywall 752 SF 6 \$2,602 | | Casework | | 9 | LF | 6 | \$227 | |
| Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood 753 SF 6 \$5,309 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 22 LF 6 \$471 Storage/ Closet 49 SF 6 \$355 Walls - Plaster/Drywall 1,386 SF 5 \$10,504 Work Sink 1 EA 6 \$379 Classroom #203 (Computer Lab) AC Units 2 EA 7 \$0 Ceiling - Plaster/Drywall 28 SF 6 \$2,602 | | Ceiling - Plaster/Drywall | | 753 | SF | 6 | \$2,606 | |
| Floor - Wood 753 SF 6 \$5,309 Lighting - Pendent/Surface 10 EA 7 \$0 Marker Board 22 LF 6 \$471 Storage/ Closet 49 SF 6 \$355 Walls - Plaster/Drywall 1,386 SF 5 \$10,504 Work Sink 1 EA 6 \$3379 Classroom #203 (Computer Lab) AC Units 2 EA 7 \$0 Ceiling - Plaster/Drywall 752 SF 6 \$2,602 | | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| Lighting - Pendent/Surface10EA7\$0Marker Board22LF6\$471Storage/ Closet49SF6\$355Walls - Plaster/Drywall1,366SF5\$10,504Work Sink1EA6\$379Classrour #203 (Computer Lab)AC Units2EA7\$0Ceiling - Plaster/Drywall752SF6\$2,602 | | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| Marker Board 22 LF 6 \$471 Storage/ Closet 49 SF 6 \$355 Walls - Plaster/Drywall 1,386 SF 5 \$10,504 Work Sink 1 EA 6 \$379 Classroom #203 (Computer Lab) AC Units 2 EA 7 \$0 Ceiling - Plaster/Drywall 752 SF 6 \$2,602 | | Floor - Wood | | 753 | SF | 6 | \$5,309 | |
| Storage/ Closet 49 SF 6 \$355 Walls - Plaster/Drywall 1,386 SF 5 \$10,504 Work Sink 1 EA 6 \$379 Classroom #203 (Computer Lab) AC Units 2 EA 7 \$0 Ceiling - Plaster/Drywall 752 SF 6 \$2,602 | | Lighting - Pendent/Surface | | 10 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall 1,386 SF 5 \$10,504 Work Sink 1 EA 6 \$379 Classroom #203 (Computer Lab) AC Units 2 EA 7 \$0 Ceiling - Plaster/Drywall 752 SF 6 \$2,602 | | Marker Board | | 22 | LF | 6 | \$471 | |
| Work Sink1EA6\$379Classroom #203 (Computer Lab)AC UnitsCeiling - Plaster/Drywall752SF6\$2,602 | | Storage/ Closet | | 49 | SF | 6 | \$355 | |
| Classroom #203 (Computer Lab)AC UnitsCeiling - Plaster/Drywall752SF6\$2,602 | | Walls - Plaster/Drywall | | 1,386 | SF | 5 | \$10,504 | |
| AC Units 2 EA 7 \$0 Ceiling - Plaster/Drywall 752 SF 6 \$2,602 | | Work Sink | | 1 | EA | 6 | \$379 | |
| Ceiling - Plaster/Drywall 752 SF 6 \$2,602 | Classro | oom #203 (Computer Lab) | | | | | | |
| | | AC Units | | 2 | EA | 7 | \$0 | |
| Doors - Transom Window 9 SF 6 \$152 | | Ceiling - Plaster/Drywall | | 752 | SF | 6 | \$2,602 | |
| | | Doors - Transom Window | | 9 | SF | 6 | \$152 | |

| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|----------|-------------------|
| | bom #203 (Computer Lab) | | | • | | | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 752 | SF | 6 | \$5,302 | |
| | Lighting - Pendent/Surface | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 28 | LF | 6 | \$600 | |
| | Storage/ Closet | | 65 | SF | 6 | \$471 | |
| | Walls - Plaster/Drywall | | 1,361 | SF | 6 | \$3,756 | |
| | Wireless System | | 1 | EA | 7 | \$0 | |
| Classro | oom #204 (Regular Classroom) | | | | | | |
| | AC Units | | 2 | EA | 7 | \$0 | |
| | Casework | | 9 | LF | 6 | \$227 | |
| | Ceiling - Lay-in | | 648 | SF | 7 | \$0 | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 648 | SF | 5 | \$9,480 | |
| | Lighting - Lay-in | | 10 | EA | 7 | \$0 | |
| | Marker Board | | 18 | LF | 6 | \$386 | |
| | Storage/ Closet | | 68 | SF | 6 | \$493 | |
| | Walls - Plaster/Drywall | | 844 | SF | 6 | \$2,329 | |
| Classro | oom #205 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Casework | 2nd Floor | 9 | LF | 5 | \$1,882 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 765 | SF | 6 | \$2,647 | |
| | Chalk Board | 2nd Floor | 7 | LF | 4 | \$643 | obsolete material |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 2nd Floor | 765 | SF | 5 | \$11,191 | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | 2nd Floor | 65 | SF | 6 | \$471 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,374 | SF | 6 | \$3,792 | |
| Classro | oom #206 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 9 | LF | 5 | \$1,882 | |
| | Ceiling - Plaster/Drywall | | 765 | SF | 6 | \$2,647 | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|----------|-------|-------------------------------|----------|
| - | bom #206 (Regular Classroom) | Location | Quantity | Unit | Nullk | COSI | Commenta |
| 0103510 | Floor - Wood | | 765 | SF | 5 | \$11,191 | |
| | Lighting - Pendent/Surface | | 10 | EA | 6 | \$1,239 | |
| | Marker Board | | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | | 56 | SF | 6 | \$406 | |
| | Walls - Plaster/Drywall | | 1,398 | SF | 6 | \$3,858 | |
| Classes | | | .,000 | 0. | Ũ | <i>Q</i> 0 ,000 | |
| Classro | bom #207 (Regular Classroom) | | 2 | | 7 | ¢0 | |
| | AC Units | | 2 | EA | 7 | \$0 | |
| | Casework | | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | | 765 | SF | 6 | \$2,647 | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 \$201 | |
| | Doors - Wood Doors inclu hw | | 1 | EA SF | 6 | \$301 \$5,202 | |
| | Floor - Wood | | 765 | | 6 | \$5,393 | |
| | Lighting - Pendent/Surface | | 10 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 6 | \$471 \$404 | |
| | Storage/ Closet | | 58 | SF | 6 | \$421 | |
| | Walls - Plaster/Drywall | | 1,398 | SF | 6 | \$3,858 | |
| Classro | oom #208 (Regular Classroom) | | | | | | |
| | AC Units | | 2 | EA | 7 | \$0 | |
| | Casework | | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | | 764 | SF | 6 | \$2,644 | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 764 | SF | 6 | \$5,386 | |
| | Lighting - Pendent/Surface | | 12 | EA | 7 | \$0 | |
| | Marker Board | | 20 | LF | 6 | \$428 | |
| | Storage/ Closet | | 68 | SF | 6 | \$493 | |
| | Walls - Plaster/Drywall | | 1,373 | SF | 6 | \$3,789 | |
| Classro | oom #209 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Casework | 2nd Floor | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 752 | SF | 6 | \$2,602 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 2nd Floor | 752 | SF | 6 | \$5,302 | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 6 | \$1,487 | |
| | Marker Board | 2nd Floor | 22 | LF | 6 | \$471 | |

Building: Main

Category: Classrooms Group Item - Type Location Quantity Unit Rank **Cost Comments** Classroom #209 (Regular Classroom) Storage/ Closet 2nd Floor 65 SF 6 \$471 Walls - Plaster/Drvwall 2nd Floor SF 5 1.361 \$10.315 Classroom #210 (Regular Classroom) AC Units \$0 2 ΕA 7 Casework 9 LF 6 \$227 Ceiling - Plaster/Drywall SF 6 765 \$2.647 Doors - Transom Window 9 SF 6 \$152 Doors - Wood Doors inclu hw \$301 1 ΕA 6 Floor - Wood SF 6 \$5,393 765 7 Lighting - Pendent/Surface 12 ΕA \$0 Marker Board 1 F 6 \$643 30 Storage/ Closet 68 SF 6 \$493 Walls - Plaster/Drywall SF 6 \$3,792 1,374 Classroom #211 (Regular Classroom) AC Units ΕA \$0 2 7 LF Casework 9 6 \$227 Ceiling - Plaster/Drywall 757 SF 6 \$2,620 Doors - Transom Window 9 SF 6 \$152 Doors - Wood Doors inclu hw ΕA 6 \$301 1 Floor - Wood 757 SF 6 \$5,337 Lighting - Pendent/Surface ΕA \$0 12 7 Marker Board 30 LF 6 \$643 Storage/ Closet SF 65 6 \$471 Walls - Plaster/Drywall SF 6 \$3,770 1,366 Classroom #212 (Regular Classroom) AC Units 2 EA 7 \$0 9 LF 6 \$227 Casework Ceiling - Plaster/Drywall SF 6 \$2.647 765 Chalk Board 8 LF 4 \$734 obsolete material 9 SF 6 \$152 Doors - Transom Window Doors - Wood Doors inclu hw ΕA 6 \$301 1 Floor - Wood 6 765 SF \$5,393 Lighting - Pendent/Surface 10 ΕA 7 \$0 Marker Board 22 LF 6 \$471 6 Storage/ Closet 65 SF \$471 Walls - Plaster/Drywall SF 6 \$3,858 1.398



Building: Main

| Category: Classrooms | | | | | | |
|-----------------------------------|-----------|----------|------|------|----------|----------|
| roup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| lassroom #212 (Regular Classroom) | | | | | | |
| assroom #213 (Counseling Room) | | | | | | |
| AC Units | 2nd Floor | 1 | EA | 7 | \$0 | |
| Casework | 2nd Floor | 13 | LF | 6 | \$328 | |
| Ceiling - Plaster/Drywall | 2nd Floor | 594 | SF | 6 | \$2,056 | |
| Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| Floor - Wood | 2nd Floor | 594 | SF | 5 | \$8,690 | |
| Lighting - Pendent/Surface | 2nd Floor | 11 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 2nd Floor | 1,214 | SF | 6 | \$3,351 | |
| lassroom #301 (Regular Classroom) | | | | | | |
| AC Units | | 2 | EA | 6 | \$991 | |
| Casework | | 9 | LF | 5 | \$1,882 | |
| Ceiling - Plaster/Drywall | | 765 | SF | 5 | \$7,012 | |
| Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| Floor - Wood | | 765 | SF | 5 | \$11,191 | |
| Lighting - Pendent/Surface | | 14 | EA | 6 | \$1,735 | |
| Marker Board | | 22 | LF | 6 | \$471 | |
| Storage/ Closet | | 63 | SF | 6 | \$457 | |
| Walls - Plaster/Drywall | | 1,319 | SF | 6 | \$3,640 | |
| assroom #302 (Regular Classroom) | | | | | | |
| AC Units | | 2 | EA | 6 | \$991 | |
| Casework | | 9 | LF | 6 | \$227 | |
| Ceiling - Plaster/Drywall | | 763 | SF | 6 | \$2,640 | |
| Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | |
| Floor - Wood | | 763 | SF | 6 | \$5,379 | |
| Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| Marker Board | | 22 | LF | 6 | \$471 | |
| Storage/ Closet | | 65 | SF | 6 | \$471 | |
| Walls - Plaster/Drywall | | 1,319 | SF | 6 | \$3,640 | |
| lassroom #303 (Regular Classroom) | | | | | | |
| AC Units | | 2 | EA | 6 | \$991 | |
| Casework | | 9 | LF | 5 | \$1,882 | |
| Ceiling - Plaster/Drywall | | 756 | SF | 6 | \$2,616 | |
| | | | | | | |

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|----------|----------|------|------|---------|--------------------------|
| Classro | oom #303 (Regular Classroom) | | | | | | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 756 | SF | 6 | \$5,330 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | | 63 | SF | 6 | \$457 | |
| | Walls - Plaster/Drywall | | 1,371 | SF | 6 | \$3,784 | |
| Classro | oom #304 (Regular Classroom) | | | | | | |
| | AC Units | | 2 | EA | 6 | \$991 | |
| | Casework | | 9 | LF | 6 | \$227 | |
| | Ceiling - Lay-in | | 658 | SF | 6 | \$1,976 | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 658 | SF | 6 | \$4,639 | |
| | Lighting - Lay-in | | 10 | EA | 7 | \$0 | |
| | Marker Board | | 6 | LF | 6 | \$129 | |
| | Storage/ Closet | | 73 | SF | 6 | \$529 | |
| | Walls - Plaster/Drywall | | 852 | SF | 6 | \$2,351 | |
| Classro | oom #305 (Regular Classroom) | | | | | | |
| | AC Units | | 2 | EA | 6 | \$991 | |
| | Casework | | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | | 765 | SF | 6 | \$2,647 | |
| | Chalk Board | | 22 | LF | 4 | \$2,020 | obsolete material |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 5 | \$1,174 | Wood is in bad condition |
| | Floor - Wood | | 765 | SF | 6 | \$5,393 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | | 74 | SF | 6 | \$537 | |
| | Walls - Plaster/Drywall | | 1,319 | SF | 6 | \$3,640 | |
| Classro | oom #306 (Regular Classroom) | | | | | | |
| | AC Units | | 2 | EA | 6 | \$991 | |
| | Casework | | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | | 764 | SF | 6 | \$2,644 | |
| | Chalk Board | | 8 | LF | 4 | \$734 | obsolete material |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|----------|----------|------|------|---------|-------------------|
| - | oom #306 (Regular Classroom) | | | | | | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 764 | SF | 6 | \$5,386 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | | 62 | SF | 5 | \$1,000 | |
| | Walls - Plaster/Drywall | | 1,318 | SF | 6 | \$3,638 | |
| Classro | oom #307 (Regular Classroom) | | | | | | |
| | AC Units | | 2 | EA | 6 | \$991 | |
| | Casework | | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | | 765 | SF | 6 | \$2,647 | |
| | Chalk Board | | 18 | LF | 4 | \$1,653 | obsolete material |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 765 | SF | 6 | \$5,393 | |
| | Lighting - Pendent/Surface | | 14 | EA | 6 | \$1,735 | |
| | Marker Board | | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | | 65 | SF | 6 | \$471 | |
| | Walls - Plaster/Drywall | | 1,319 | SF | 6 | \$3,640 | |
| Classro | oom #308 (Science Classroom) | | | | | | |
| | AC Units | | 2 | EA | 6 | \$991 | |
| | Casework | | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | | 765 | SF | 6 | \$2,647 | |
| | Chalk Board | | 16 | LF | 4 | \$1,469 | obsolete material |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 765 | SF | 6 | \$5,393 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | | 65 | SF | 6 | \$471 | |
| | Walls - Plaster/Drywall | | 1,319 | SF | 6 | \$3,640 | |
| Classro | oom #309 (Regular Classroom) | | | | | | |
| | AC Units | | 2 | EA | 6 | \$991 | |
| | Casework | | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | | 765 | SF | 6 | \$2,647 | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |

Building: Main

| | | Leastion | 0 | 11 | Daula | Onst | Commonto |
|---------|-------------------------------|----------|----------|------|-------|---------|-------------------|
| | Item - Type | Location | Quantity | Unit | калк | Cost | Comments |
| Classro | boom #309 (Regular Classroom) | | | - | | Ac | |
| | Floor - Wood | | 765 | SF | 6 | \$5,393 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | | 74 | SF | 6 | \$537 | |
| | Walls - Plaster/Drywall | | 1,319 | SF | 6 | \$3,640 | |
| Classro | oom #310 (Regular Classroom) | | | | | | |
| | AC Units | | 2 | EA | 7 | \$0 | |
| | Casework | | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | | 765 | SF | 6 | \$2,647 | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 765 | SF | 6 | \$5,393 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | | 65 | SF | 6 | \$471 | |
| | Walls - Plaster/Drywall | | 1,319 | SF | 6 | \$3,640 | |
| Classro | oom #311 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 7 | LF | 5 | \$1,464 | |
| | Ceiling - Plaster/Drywall | | 562 | SF | 7 | \$0 | |
| | Chalk Board | | 8 | LF | 4 | \$734 | obsolete material |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 562 | SF | 6 | \$3,962 | |
| | Lighting - Pendent/Surface | | 8 | EA | 7 | \$0 | |
| | Marker Board | | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | | 1,154 | SF | 6 | \$3,185 | |
| Classro | oom #312 (Regular Classroom) | | | | | | |
| | AC Units | | 2 | EA | 7 | \$0 | |
| | Casework | | 9 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | | 1,001 | SF | 6 | \$3,464 | |
| | Chalk Board | | 9 | LF | 4 | \$826 | obsolete material |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 1,001 | SF | 6 | \$7,057 | |
| | Lighting - Pendent/Surface | | 18 | EA | 7 | \$0 | |
| | | | | | | | |

Building: Main

Category: Classrooms

| Jaicge | Jry. Classicollis | | | | | | |
|----------|------------------------------------|-----------|----------|------|------|-----------|--------------------------------------|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classroo | om #312 (Regular Classroom) | | | | | | |
| | Marker Board | | 22 | LF | 6 | \$471 | |
| | Storage/ Closet | | 4 | SF | 6 | \$29 | |
| | Walls - Plaster/Drywall | | 1,510 | SF | 6 | \$4,167 | |
| Classroo | om #313 (Science Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 6 | \$991 | |
| | Casework | 3rd Floor | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 807 | SF | 5 | \$7,397 | |
| | Chalk Board | 3rd Floor | 34 | LF | 4 | \$3,121 | partially covered, obsolete material |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 3rd Floor | 807 | SF | 6 | \$5,689 | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 8 | LF | 6 | \$171 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,231 | SF | 5 | \$9,330 | |
| | Work Sink | 3rd Floor | 1 | EA | 6 | \$379 | |
| lassroo | om #313A (Other Instructional Use) | | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 402 | SF | 5 | \$3,685 | |
| | Chalk Board | 3rd Floor | 16 | LF | 4 | \$1,469 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 3rd Floor | 402 | SF | 6 | \$2,834 | |
| | Lighting - Pendent/Surface | 3rd Floor | 9 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 6 | \$343 | |
| | Walls - Plaster/Drywall | 3rd Floor | 847 | SF | 5 | \$6,419 | |
| Classr | ooms Subtotal: | | | | | \$519,713 | |
| | | | | | | | |
| Buildir | ng: Main | | | | | | |
| - | ory: Rooms (Other Than Classrooms) | | | | | | |
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Adminis | trative Suites/Offices | | | | | | |
| | Ceiling - Plaster/Drywall | 315A | 58 | SF | 6 | \$201 | |
| | Doors - Wood Doors inclu hw | 315A | 1 | EA | 6 | \$301 | |

Floor - Epoxy/ Painted

Walls - Plaster/Drywall

Ceiling - Plaster/Drywall

Power Distribution

Lighting - Pendent/Surface

315A

315A

315A

315A

315B

SF

SF

34 SF

58

1 EA

2 EA

253

6

7

7

6

5

\$31

\$0

\$0

\$698

\$312



| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---------------------------------|--|----------|------|------|----------|----------|
| dmini | strative Suites/Offices | | | | | | |
| | Doors - Wood Doors inclu hw | 315B | 1 | EA | 6 | \$301 | |
| | Floor - Epoxy/ Painted | 315B | 34 | SF | 5 | \$58 | |
| | Lighting - Pendent/Surface | 315B | 1 | EA | 6 | \$124 | |
| | Power Distribution | 315B | 2 | EA | 6 | \$4,250 | |
| | Walls - Plaster/Drywall | 315B | 188 | SF | 5 | \$1,425 | |
| | Ceiling - Plaster/Drywall | 3RD FLOOR NORTH OFFICE | 144 | SF | 6 | \$498 | |
| | Doors - Steel Doors incl hw | 3RD FLOOR NORTH OFFICE | 1 | EA | 6 | \$301 | |
| | Floor - Concrete Epoxy/ Painted | 3RD FLOOR NORTH OFFICE | 144 | SF | 6 | \$76 | |
| | Lighting - Pendent/Surface | 3RD FLOOR NORTH OFFICE | 2 | EA | 7 | \$0 | |
| | Power Distribution | 3RD FLOOR NORTH OFFICE | 2 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3RD FLOOR NORTH OFFICE | 363 | SF | 6 | \$1,002 | |
| | AC Unit | Adjacent Office to Main Office Level 1.5 | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Adjacent Office to Main Office Level 1.5 | 213 | SF | 6 | \$737 | |
| | Doors - Transom Window | Adjacent Office to Main Office Level 1.5 | 63 | SF | 6 | \$1,067 | |
| | Doors - Wood Doors inclu hw | Adjacent Office to Main Office Level 1.5 | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | Adjacent Office to Main Office Level 1.5 | 213 | SF | 6 | \$213 | |
| | Lighting - Pendent/Surface | Adjacent Office to Main Office Level 1.5 | 4 | EA | 7 | \$0 | |
| | Power Distribution | Adjacent Office to Main Office Level 1.5 | 6 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Adjacent Office to Main Office Level 1.5 | 623 | SF | 6 | \$1,719 | |
| | Ceiling - Lay-in | Engineer's Office 1.5 floor | 380 | SF | 6 | \$1,141 | |
| | Doors - Wood Doors inclu hw | Engineer's Office 1.5 floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | Engineer's Office 1.5 floor | 380 | SF | 6 | \$380 | |
| | Lighting - Lay-in | Engineer's Office 1.5 floor | 4 | EA | 6 | \$476 | |
| | Power Distribution | Engineer's Office 1.5 floor | 18 | EA | 6 | \$38,248 | |
| | Storage/ Closet | Engineer's Office 1.5 floor | 165 | SF | 6 | \$1,196 | |
| | Walls - Plaster/Drywall | Engineer's Office 1.5 floor | 514 | SF | 6 | \$1,419 | |
| | Ceiling - Plaster/Drywall | Gymnasium Office 2ND FLR | 144 | SF | 6 | \$498 | |
| | Doors - Wood Doors inclu hw | Gymnasium Office 2ND FLR | 1 | EA | 6 | \$301 | |
| | Floor - Wood | Gymnasium Office 2ND FLR | 144 | SF | 6 | \$1,015 | |
| | Lighting - Pendent/Surface | Gymnasium Office 2ND FLR | 3 | EA | 7 | \$0 | |
| | Power Distribution | Gymnasium Office 2ND FLR | 2 | EA | 6 | \$4,250 | |
| | Walls - Plaster/Drywall | Gymnasium Office 2ND FLR | 651 | SF | 6 | \$1,797 | |
| | AC Unit | Main Office Level 1.5 | 1 | EA | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Main Office Level 1.5 | 480 | SF | 6 | \$1,661 | |
| | Doors - Transom Window | Main Office Level 1.5 | 90 | SF | 6 | \$1,524 | |
| | Doors - Wood Doors inclu hw | Main Office Level 1.5 | 2 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | Main Office Level 1.5 | 480 | SF | 5 | \$2,155 | |



| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Commen |
|-------|-----------------------------|------------------------------|----------|------|------|-----------|--------|
| Imini | strative Suites/Offices | | | | | | |
| | Lighting - Pendent/Surface | Main Office Level 1.5 | 8 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | Main Office Level 1.5 | 6 | EA | 7 | \$0 | |
| | Power Distribution | Main Office Level 1.5 | 12 | EA | 6 | \$25,499 | |
| | Storage/ Closet | Main Office Level 1.5 | 45 | SF | 6 | \$326 | |
| | Walls - Plaster/Drywall | Main Office Level 1.5 | 871 | SF | 5 | \$6,601 | |
| | Work SInk | Main Office Level 1.5 | 1 | EA | 6 | \$508 | |
| | AC Unit | Principal's Office Level 1.5 | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | Principal's Office Level 1.5 | 191 | SF | 6 | \$661 | |
| | Doors - Wood Doors inclu hw | Principal's Office Level 1.5 | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | Principal's Office Level 1.5 | 191 | SF | 6 | \$191 | |
| | Lighting - Pendent/Surface | Principal's Office Level 1.5 | 3 | EA | 7 | \$0 | |
| | Power Distribution | Principal's Office Level 1.5 | 4 | EA | 6 | \$8,500 | |
| | Storage/ Closet | Principal's Office Level 1.5 | 30 | SF | 6 | \$218 | |
| | Walls - Plaster/Drywall | Principal's Office Level 1.5 | 683 | SF | 6 | \$1,885 | |
| | Ceiling - Plaster/Drywall | Teacher's Lounge 2nd Floor | 489 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | Teacher's Lounge 2nd Floor | 2 | EA | 6 | \$602 | |
| | Floor - Wood | Teacher's Lounge 2nd Floor | 489 | SF | 6 | \$3,447 | |
| | Lighting - Pendent/Surface | Teacher's Lounge 2nd Floor | 10 | EA | 7 | \$0 | |
| | Power Distribution | Teacher's Lounge 2nd Floor | 7 | EA | 6 | \$14,874 | |
| | Walls - Plaster/Drywall | Teacher's Lounge 2nd Floor | 1,152 | SF | 6 | \$3,179 | |
| litor | ium & Theater | | | | | | |
| | Balcony Seating | Assembly Hall 1st Floor | 40 | EA | 4 | \$29,898 | broken |
| | Balcony Seating | Assembly Hall 1st Floor | 356 | EA | 6 | \$61,914 | |
| | Ceiling - Plaster/Drywall | Assembly Hall 1st Floor | 10,545 | SF | 6 | \$87,913 | |
| | Doors - Wood Doors inclu hw | Assembly Hall 1st Floor | 18 | EA | 6 | \$5,418 | |
| | Floor - Wood | Assembly Hall 1st Floor | 10,545 | SF | 6 | \$74,341 | |
| | Lighting - Lay-in | Assembly Hall 1st Floor | 42 | EA | 6 | \$4,997 | |
| | Lighting - Pendent/Surface | Assembly Hall 1st Floor | 10 | EA | 6 | \$1,239 | |
| | Lighting - Wall Mounted | Assembly Hall 1st Floor | 4 | EA | 6 | \$496 | |
| | Main Floor Seating | Assembly Hall 1st Floor | 125 | EA | 4 | \$93,433 | broken |
| | Main Floor Seating | Assembly Hall 1st Floor | 740 | EA | 5 | \$281,598 | |
| | Sound System | Assembly Hall 1st Floor | 1 | EA | 5 | \$27,165 | |
| | Stage | Assembly Hall 1st Floor | 1,081 | SF | 6 | \$6,245 | |
| | Stage Curtain | Assembly Hall 1st Floor | 10 | EA | 6 | \$0 | |
| | Stage Lighting System | Assembly Hall 1st Floor | 1 | EA | 6 | \$8,077 | |
| | Stage-Stairs - Wood | Assembly Hall 1st Floor | 30 | LF | 6 | \$352 | |
| | Walls - Plaster/Drywall | Assembly Hall 1st Floor | 9,268 | SF | 6 | \$44,133 | |
| | | | | | | | |



Building: Main

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|-------------------------|----------|------|------|----------|----------|
| | ium & Theater | | | | | | |
| | | | | | | | |
| Symna | | | | | | | |
| | Ceiling - Splined | 2nd Floor | 2,763 | SF | 6 | \$2,252 | |
| | Doors - Transom Window | 2nd Floor | 36 | SF | 6 | \$610 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 4 | EA | 6 | \$1,204 | |
| | Floor - Wood | 2nd Floor | 2,763 | SF | 6 | \$19,479 | |
| | Lighting - Metal Halide/ High Pressure Sodium | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 2,101 | SF | 6 | \$5,799 | |
| | Walls - Vinyl Coated Gypsum Panel | 2nd Floor | 2,101 | SF | 6 | \$5,799 | |
| itchen | | | | | | | |
| | Ceiling - Plaster/Drywall | KITCHEN 106 FIRST FLOOR | 838 | SF | 6 | \$2,900 | |
| | Doors - Wood Doors inclu hw | KITCHEN 106 FIRST FLOOR | 1 | EA | 6 | \$301 | |
| | Floor - Tile Quarry | KITCHEN 106 FIRST FLOOR | 838 | SF | 6 | \$1,774 | |
| | Lighting - Pendent/Surface | KITCHEN 106 FIRST FLOOR | 15 | EA | 7 | \$0 | |
| | Serving Line | KITCHEN 106 FIRST FLOOR | 18 | LF | 6 | \$1,071 | |
| | Walls - Plaster/Drywall | KITCHEN 106 FIRST FLOOR | 1,074 | SF | 6 | \$2,964 | |
| brary | | | | | | | |
| - | AC Unit | 201/202 | 2 | EA | 7 | \$0 | |
| | Casework | 201/202 | 63 | LF | 6 | \$1,591 | |
| | Ceiling - Plaster/Drywall | 201/202 | 1,415 | SF | 7 | \$0 | |
| | Doors - Transom Window | 201/202 | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | 201/202 | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | 201/202 | 1,415 | SF | 6 | \$3,015 | |
| | Lighting - Pendent/Surface | 201/202 | 21 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 201/202 | 1,826 | SF | 6 | \$5,040 | |
| inch a | & Multipurpose Room | | | | | | |
| | Ceiling - Plaster/Drywall | 102/103 | 1,508 | SF | 6 | \$5,219 | |
| | Doors - Transom Window | 102/103 | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | 102/103 | 3 | EA | 6 | \$903 | |
| | Floor - Tile Quarry | 102/103 | 226 | SF | 7 | \$0 | |
| | Floor - Wood | 102/103 | 1,282 | SF | 5 | \$18,754 | |
| | Lighting - Pendent/Surface | 102/103 | 26 | EA | 7 | \$0 | |
| | Storage/ Closet | 102/103 | 164 | SF | 6 | \$1,189 | |
| | Walls - Plaster/Drywall | 102/103 | 1,725 | SF | 6 | \$4,761 | |
| | Ceiling - Plaster/Drywall | 104/105 | 1,500 | SF | 6 | \$5,191 | |
| | Doors - Wood Doors inclu hw | 104/105 | 3 | EA | 5 | \$3,522 | |
| | | | | | | | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-----------|----------|------|------|----------|---|
| unch a | & Multipurpose Room | | | | | | |
| | Floor - Tile/Sheet | 104/105 | 1,500 | SF | 5 | \$6,735 | |
| | Lighting - Pendent/Surface | 104/105 | 24 | EA | 7 | \$0 | |
| | Market Board | 104/105 | 9 | LF | 6 | \$193 | |
| | Storage/ Closet | 104/105 | 36 | SF | 6 | \$261 | |
| | Walls - Plaster/Drywall | 104/105 | 1,738 | SF | 6 | \$4,797 | |
| /IDF_IC |)F | | | | | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Finishes | 2nd Floor | 113 | SF | 6 | \$806 | |
| /lechar | nical/ Service Rooms | | | | | | |
| | Boiler Room | 1st Floor | 1,338 | SF | 5 | \$21,582 | |
| | Coal Room | 1st Floor | 392 | SF | 5 | \$6,323 | |
| | Janitor's Closet | 1st Floor | 22 | SF | 5 | \$355 | South East |
| | Janitor's Closet | 1st Floor | 10 | SF | 6 | \$72 | South West |
| | Mechanical/ Service Rooms | 1st Floor | 1,340 | SF | 6 | \$9,600 | Warm Air Chamber |
| | Mechanical/ Service Rooms | 1st Floor | 517 | SF | 5 | \$8,339 | |
| | Storage Room | 1st Floor | 34 | SF | 5 | | 1st Floor East Closet |
| | Storage Room | 1st Floor | 38 | SF | 5 | \$613 | |
| | Storage Room | 1st Floor | 118 | SF | 6 | \$845 | 1st Floor Storage |
| | Janitor's Closet | 2nd Floor | 9 | SF | 6 | \$64 | East |
| | Janitor's Closet | 2nd Floor | 9 | SF | 6 | \$64 | West |
| | Janitor's Closet | 2nd Floor | 10 | SF | 5 | \$161 | North |
| | Janitor's Closet | 3rd Floor | 9 | SF | 6 | \$64 | West |
| | Janitor's Closet | 3rd Floor | 9 | SF | 5 | \$145 | East |
| estroc | om | | | | | | |
| | Accessories | 101A | 80 | SF | 6 | \$738 | mirror, soap dispenser, toilet paper holder |
| | Ceiling - Plaster/Drywall | 101A | 80 | SF | 7 | \$0 | |
| | Doors - Wood Doors inclu hw | 101A | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 101A | 80 | SF | 6 | \$169 | |
| | Hand Dryer | 101A | 1 | EA | 6 | \$230 | |
| | Lavatory | 101A | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 101A | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 101A | 208 | SF | 7 | \$0 | |
| | Walls - Tile Ceramic/ Porcelain | 101A | 82 | SF | 6 | \$185 | |
| | Water Closet | 101A | 1 | EA | 6 | \$336 | |
| | Accessories | 112A | 44 | SF | 6 | \$406 | soap dispenser, mirror |
| | Ceiling - Lay-in | 112A | 44 | SF | 6 | \$132 | |



| Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------------|-----------------|----------|------|------|---------|---|
| n | | | | | | |
| Doors - Wood Doors inclu hw | 112A | 1 | EA | 6 | \$301 | |
| Floor Drain | 112A | 1 | EA | 6 | \$1,059 | |
| Floor - Tile/Sheet | 112A | 44 | SF | 6 | \$44 | |
| Lavatory | 112A | 1 | EA | 6 | \$320 | |
| Lighting - Pendent/Surface | 112A | 1 | EA | 7 | \$0 | |
| Walls - Vinyl Coated Gypsum Panel | 112A | 191 | SF | 6 | \$527 | |
| Water Closet | 112A | 1 | EA | 6 | \$336 | |
| Accessories | 204A | 89 | SF | 6 | \$821 | mirror, toilet paper holder, soap dispenser |
| Ceiling - Plaster/Drywall | 204A | 89 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 204A | 1 | EA | 7 | \$0 | |
| Floor Drain | 204A | 1 | EA | 6 | \$1,059 | |
| Floor - Tile Ceramic/ Porcelain | 204A | 89 | SF | 6 | \$188 | |
| Hand Dryer | 204A | 1 | EA | 7 | \$0 | |
| Lavatory | 204A | 1 | EA | 6 | \$320 | |
| Lighting - Lay-in | 204A | 1 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 204A | 182 | SF | 7 | \$0 | |
| Walls - Tile Ceramic/ Porcelain | 204A | 87 | SF | 7 | \$0 | |
| Water Closet | 204A | 1 | EA | 6 | \$336 | |
| Accessories | 304 A | 89 | SF | 6 | \$821 | soap dispenser, mirror |
| Ceiling - Plaster/Drywall | 304 A | 89 | SF | 7 | \$0 | |
| Doors - Wood Doors inclu hw | 304 A | 1 | EA | 7 | \$0 | |
| Floor Drain | 304 A | 1 | EA | 6 | \$1,059 | |
| Floor - Tile Ceramic/ Porcelain | 304 A | 89 | SF | 7 | \$0 | |
| Hand Dryer | 304 A | 1 | EA | 7 | \$0 | |
| Lavatory | 304 A | 1 | EA | 7 | \$0 | |
| _ighting - Lay-in | 304 A | 1 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 304 A | 176 | SF | 7 | \$0 | |
| Walls - Tile Ceramic/ Porcelain | 304 A | 104 | SF | 7 | \$0 | |
| Water Closet | 304 A | 1 | EA | 6 | \$336 | |
| Accessories | Boy's 1st Floor | 344 | SF | 6 | \$3,173 | soap dispenser |
| Ceiling - Plaster/Drywall | Boy's 1st Floor | 344 | SF | 6 | \$1,190 | |
| Doors - Wood Doors inclu hw | Boy's 1st Floor | 2 | EA | 6 | \$602 | |
| Floor Drain | Boy's 1st Floor | 1 | EA | 6 | \$1,059 | |
| Floor - Tile Ceramic/ Porcelain | Boy's 1st Floor | 344 | SF | 6 | \$728 | |
| Lavatory | Boy's 1st Floor | 3 | EA | 6 | \$959 | |
| Lighting - Pendent/Surface | Boy's 1st Floor | 5 | EA | 7 | \$0 | |
| Partitions | Boy's 1st Floor | 3 | EA | 6 | \$891 | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|----------------------------|----------|------|------|----------|---|
| Restroc | om | | | | | | |
| | Urinals | Boy's 1st Floor | 7 | EA | 6 | \$2,352 | |
| | Walls - Plaster/Drywall | Boy's 1st Floor | 127 | SF | 6 | \$351 | |
| | Walls - Structural Glazed Tile | Boy's 1st Floor | 498 | SF | 6 | \$1,567 | |
| | Water Closet | Boy's 1st Floor | 3 | EA | 6 | \$1,008 | |
| | Accessories | Boy's 2nd Floor | 357 | SF | 6 | \$3,293 | soap dispenser |
| | Ceiling - Plaster/Drywall | Boy's 2nd Floor | 357 | SF | 6 | \$1,235 | |
| | Doors - Wood Doors inclu hw | Boy's 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor Drain | Boy's 2nd Floor | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Boy's 2nd Floor | 357 | SF | 6 | \$756 | |
| | Lavatory | Boy's 2nd Floor | 3 | EA | 6 | \$959 | |
| | Lighting - Pendent/Surface | Boy's 2nd Floor | 6 | EA | 6 | \$743 | |
| | Partitions | Boy's 2nd Floor | 3 | EA | 6 | \$891 | |
| | Urinals | Boy's 2nd Floor | 7 | EA | 6 | \$2,352 | |
| | Walls - Plaster/Drywall | Boy's 2nd Floor | 497 | SF | 6 | \$1,372 | |
| | Walls - Structural Glazed Tile | Boy's 2nd Floor | 497 | SF | 5 | \$25,252 | |
| | Water Closet | Boy's 2nd Floor | 3 | EA | 6 | \$1,008 | |
| | Accessories | Boy's 3rd Floor | 334 | SF | 6 | \$3,081 | soap dispenser |
| | Ceiling - Plaster/Drywall | Boy's 3rd Floor | 334 | SF | 6 | \$1,156 | |
| | Doors - Wood Doors inclu hw | Boy's 3rd Floor | 2 | EA | 6 | \$602 | |
| | Floor Drain | Boy's 3rd Floor | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Boy's 3rd Floor | 334 | SF | 6 | \$707 | |
| | Lavatory | Boy's 3rd Floor | 3 | EA | 6 | \$959 | |
| | Lighting - Pendent/Surface | Boy's 3rd Floor | 6 | EA | 6 | \$743 | |
| | Partitions | Boy's 3rd Floor | 3 | EA | 6 | \$891 | |
| | Urinals | Boy's 3rd Floor | 6 | EA | 6 | \$2,016 | |
| | Walls - Plaster/Drywall | Boy's 3rd Floor | 490 | SF | 6 | \$1,352 | |
| | Walls - Structural Glazed Tile | Boy's 3rd Floor | 490 | SF | 6 | \$1,542 | |
| | Water Closet | Boy's 3rd Floor | 3 | EA | 6 | \$1,008 | |
| | Accessories | Engineer's Toilet Basement | 32 | SF | 6 | \$295 | mirror, soap dispenser, paper towel dispenser |
| | Ceiling - Plaster/Drywall | Engineer's Toilet Basement | 32 | SF | 6 | \$111 | |
| | Doors - Wood Doors inclu hw | Engineer's Toilet Basement | 1 | EA | 6 | \$301 | |
| | Floor - Concrete | Engineer's Toilet Basement | 32 | SF | 6 | \$17 | |
| | Lavatory | Engineer's Toilet Basement | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Engineer's Toilet Basement | 1 | EA | 7 | \$0 | |
| | Walls - Masonry | Engineer's Toilet Basement | 250 | SF | 6 | \$787 | |
| | Water Closet | Engineer's Toilet Basement | 1 | EA | 6 | \$336 | |
| | Accessories | Girls 1st Floor | 267 | SF | 6 | \$2,463 | mirror, soap dispenser |
| | | | | | | | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-----------------------|----------|------|------|----------|--|
| Restroc | om | | | | | | |
| | Ceiling - Plaster/Drywall | Girls 1st Floor | 267 | SF | 6 | \$924 | |
| | Doors - Wood Doors inclu hw | Girls 1st Floor | 3 | EA | 5 | \$3,522 | |
| | Floor Drain | Girls 1st Floor | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Girls 1st Floor | 267 | SF | 6 | \$565 | |
| | Lavatory | Girls 1st Floor | 3 | EA | 6 | \$959 | |
| | Lighting - Pendent/Surface | Girls 1st Floor | 5 | EA | 7 | \$0 | |
| | Partitions | Girls 1st Floor | 8 | EA | 5 | \$6,007 | |
| | Walls - Plaster/Drywall | Girls 1st Floor | 99 | SF | 6 | \$273 | |
| | Walls - Structural Glazed Tile | Girls 1st Floor | 525 | SF | 5 | \$26,674 | |
| | Water Closet | Girls 1st Floor | 8 | EA | 6 | \$2,688 | |
| | Accessories | Girls 2nd Floor | 374 | SF | 6 | \$3,450 | toilet paper dispenser |
| | Ceiling - Plaster/Drywall | Girls 2nd Floor | 374 | SF | 6 | \$1,294 | |
| | Doors - Wood Doors inclu hw | Girls 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor Drain | Girls 2nd Floor | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Girls 2nd Floor | 374 | SF | 5 | \$5,974 | |
| | Lavatory | Girls 2nd Floor | 3 | EA | 6 | \$959 | |
| | Lighting - Pendent/Surface | Girls 2nd Floor | 6 | EA | 6 | \$743 | |
| | Partitions | Girls 2nd Floor | 8 | EA | 6 | \$2,375 | |
| | Walls - Plaster/Drywall | Girls 2nd Floor | 509 | SF | 5 | \$3,858 | |
| | Walls - Structural Glazed Tile | Girls 2nd Floor | 509 | SF | 5 | \$25,861 | |
| | Water Closet | Girls 2nd Floor | 8 | EA | 6 | \$2,688 | |
| | Accessories | Girls 3rd Floor | 373 | SF | 6 | \$3,440 | toilet paper dispenser, mirror |
| | Ceiling - Plaster/Drywall | Girls 3rd Floor | 373 | SF | 6 | \$1,291 | |
| | Doors - Wood Doors inclu hw | Girls 3rd Floor | 2 | EA | 6 | \$602 | |
| | Floor Drain | Girls 3rd Floor | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Girls 3rd Floor | 373 | SF | 6 | \$789 | |
| | Lavatory | Girls 3rd Floor | 3 | EA | 6 | \$959 | |
| | Lighting - Pendent/Surface | Girls 3rd Floor | 6 | EA | 6 | \$743 | |
| | Partitions | Girls 3rd Floor | 8 | EA | 6 | \$2,375 | |
| | Walls - Plaster/Drywall | Girls 3rd Floor | 517 | SF | 5 | \$3,918 | |
| | Walls - Structural Glazed Tile | Girls 3rd Floor | 517 | SF | 5 | \$26,268 | |
| | Water Closet | Girls 3rd Floor | 8 | EA | 6 | \$2,688 | |
| | Accessories | Men's Staff 1st Floor | 59 | SF | 6 | \$544 | soap dispenser, toilet paper dispenser |
| | Ceiling - Exposed | Men's Staff 1st Floor | 59 | SF | 6 | \$88 | |
| | Doors - Wood Doors inclu hw | Men's Staff 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | Men's Staff 1st Floor | 59 | SF | 5 | \$942 | |
| | Lavatory | Men's Staff 1st Floor | 1 | EA | 6 | \$320 | |
| | | | | | | | |



| Restroo | | | , | Unit | | | Comments |
|---------|---------------------------------|--------------------------------|----------|------|---|---------|---|
| | m | | | | | | |
| | Lighting - Pendent/Surface | Men's Staff 1st Floor | 1 | EA | 7 | \$0 | |
| | Partitions | Men's Staff 1st Floor | 1 | EA | 6 | \$297 | |
| | Walls - Plaster/Drywall | Men's Staff 1st Floor | 286 | SF | 6 | \$789 | |
| | Water Closet | Men's Staff 1st Floor | 1 | EA | 6 | \$336 | |
| | Accessories | Men's Staff Floor Level 1.5 | 38 | SF | 6 | \$350 | toilet paper dispenser, paper towel dispenser, mirror |
| | Ceiling - Plaster/Drywall | Men's Staff Floor Level 1.5 | 38 | SF | 6 | \$132 | |
| | Doors - Wood Doors inclu hw | Men's Staff Floor Level 1.5 | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile Ceramic/ Porcelain | Men's Staff Floor Level 1.5 | 38 | SF | 6 | \$80 | |
| | Lavatory | Men's Staff Floor Level 1.5 | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Men's Staff Floor Level 1.5 | 2 | EA | 7 | \$0 | |
| | Urinals | Men's Staff Floor Level 1.5 | 1 | EA | 6 | \$336 | |
| | Walls - Plaster/Drywall | Men's Staff Floor Level 1.5 | 83 | SF | 6 | \$229 | |
| | Walls - Tile Ceramic/ Porcelain | Men's Staff Floor Level 1.5 | 157 | SF | 5 | \$2,515 | |
| | Water Closet | Men's Staff Floor Level 1.5 | 1 | EA | 6 | \$336 | |
| | Accessories | Men's Staff Floor Level 2.5 | 41 | SF | 6 | \$378 | toilet paper dispenser, soap dispenser, mirror, paper towel dispenser |
| | Ceiling - Plaster/Drywall | Men's Staff Floor Level 2.5 | 41 | SF | 6 | \$142 | |
| | Doors - Wood Doors inclu hw | Men's Staff Floor Level 2.5 | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | Men's Staff Floor Level 2.5 | 41 | SF | 6 | \$87 | |
| | Lavatory | Men's Staff Floor Level 2.5 | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Men's Staff Floor Level 2.5 | 2 | EA | 7 | \$0 | |
| | Urinals | Men's Staff Floor Level 2.5 | 1 | EA | 6 | \$336 | |
| | Walls - Plaster/Drywall | Men's Staff Floor Level 2.5 | 153 | SF | 6 | \$422 | |
| | Walls - Tile Ceramic/ Porcelain | Men's Staff Floor Level 2.5 | 153 | SF | 5 | \$2,450 | |
| | Water Closet | Men's Staff Floor Level 2.5 | 1 | EA | 6 | \$336 | |
| | Accessories | Principal's Restroom Level 1.5 | 49 | SF | 6 | \$452 | mirror, paper towel dispenser, toilet paper holder |
| | Ceiling - Plaster/Drywall | Principal's Restroom Level 1.5 | 49 | SF | 6 | \$170 | |
| | Doors - Wood Doors inclu hw | Principal's Restroom Level 1.5 | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | Principal's Restroom Level 1.5 | 49 | SF | 6 | \$104 | |
| | Lavatory | Principal's Restroom Level 1.5 | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Principal's Restroom Level 1.5 | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Principal's Restroom Level 1.5 | 198 | SF | 5 | \$1,501 | |
| | Walls - Tile Ceramic/ Porcelain | Principal's Restroom Level 1.5 | 142 | SF | 5 | \$2,274 | |
| | Water Closet | Principal's Restroom Level 1.5 | 1 | EA | 6 | \$336 | |
| | Accessories | Women's 1st Floor | 150 | SF | 6 | \$1,384 | mirror, soap dispenser, paper towel dispenser |
| | Ceiling - Exposed | Women's 1st Floor | 150 | SF | 6 | \$223 | |
| | Doors - Wood Doors inclu hw | Women's 1st Floor | 1 | EA | 6 | \$301 | |



Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------------|-------------------------------|----------|------|------|---------|---|
| Restroc | m | | | | | | |
| | Floor - Tile/Sheet | Women's 1st Floor | 150 | SF | 5 | \$674 | |
| | Lavatory | Women's 1st Floor | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Women's 1st Floor | 2 | EA | 7 | \$0 | |
| | Partitions | Women's 1st Floor | 2 | EA | 6 | \$594 | |
| | Walls - Plaster/Drywall | Women's 1st Floor | 185 | SF | 5 | \$1,402 | |
| | Walls - Vinyl Coated Gypsum Panel | Women's 1st Floor | 283 | SF | 6 | \$781 | |
| | Water Closet | Women's 1st Floor | 2 | EA | 6 | \$672 | |
| | Accessories | Women's Staff Floor Level 1.5 | 62 | SF | 6 | \$572 | mirror, soap dispenser, paper towel dispenser |
| | Doors - Wood Doors inclu hw | Women's Staff Floor Level 1.5 | 1 | EA | 5 | \$1,174 | |
| | Floor - Tile Ceramic/ Porcelain | Women's Staff Floor Level 1.5 | 62 | SF | 6 | \$131 | |
| | Lavatory | Women's Staff Floor Level 1.5 | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Women's Staff Floor Level 1.5 | 2 | EA | 7 | \$0 | |
| | Partitions | Women's Staff Floor Level 1.5 | 2 | EA | 5 | \$1,502 | |
| | Walls - Plaster/Drywall | Women's Staff Floor Level 1.5 | 204 | SF | 5 | \$1,546 | |
| | Walls - Tile Ceramic/ Porcelain | Women's Staff Floor Level 1.5 | 110 | SF | 5 | \$1,762 | |
| | Water Closet | Women's Staff Floor Level 1.5 | 2 | EA | 6 | \$672 | |
| | Accessories | Women's Staff Floor Level 2.5 | 69 | SF | 6 | \$636 | mirror, soap dispenser, paper towel dispenser |
| | Ceiling - Plaster/Drywall | Women's Staff Floor Level 2.5 | 69 | SF | 6 | \$239 | |
| | Doors - Wood Doors inclu hw | Women's Staff Floor Level 2.5 | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | Women's Staff Floor Level 2.5 | 69 | SF | 6 | \$146 | |
| | Lavatory | Women's Staff Floor Level 2.5 | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Women's Staff Floor Level 2.5 | 2 | EA | 7 | \$0 | |
| | Partitions | Women's Staff Floor Level 2.5 | 2 | EA | 6 | \$594 | |
| | Walls - Plaster/Drywall | Women's Staff Floor Level 2.5 | 207 | SF | 6 | \$571 | |
| | Walls - Tile Ceramic/ Porcelain | Women's Staff Floor Level 2.5 | 207 | SF | 6 | \$468 | |
| | Water Closet | Women's Staff Floor Level 2.5 | 2 | EA | 6 | \$672 | |

Rooms (Other Than Classrooms) Subtotal:

\$1,277,049

Building: Main

Category: Building Interior

| 5, 5 | | | | | |
|--------------------------------------|-------------------------|----------|------|------|------------|
| Group Item - Type | Location | Quantity | Unit | Rank | Cost Comme |
| Corridor | | | | | |
| Ceiling - Plaster/Drywall | 1st Floor East Corridor | 2,257 | SF | 6 | \$13,975 |
| Doors - Steel Doors incl hw | 1st Floor East Corridor | 8 | EA | 6 | \$2,408 |
| Doors - Wood Doors include hw | 1st Floor East Corridor | 6 | EA | 6 | \$1,806 |
| Drinking Fountains - Single Fountain | 1st Floor East Corridor | 2 | EA | 7 | \$0 |
| | | | | | |



Category: Building Interior

| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|--------------------------|----------|------|------|----------|----------|
| Corrido | | | , | • | | | |
| | Floor - Epoxy/ Painted | 1st Floor East Corridor | 2,257 | SF | 5 | \$3,873 | |
| | Lighting - Pendent/Surface | 1st Floor East Corridor | 20 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor East Corridor | 3,394 | SF | 6 | \$15,046 | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor East Corridor | 20 | SF | 6 | \$63 | |
| | Ceiling - Plaster/Drywall | 1st Floor North Corridor | 583 | SF | 6 | \$3,610 | |
| | Floor - Epoxy/ Painted | 1st Floor North Corridor | 583 | SF | 6 | \$308 | |
| | Lighting - Pendent/Surface | 1st Floor North Corridor | 12 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 1st Floor North Corridor | 1 | EA | 7 | \$0 | |
| | Stairs - Concrete Stairs | 1st Floor North Corridor | 100 | LF | 6 | \$829 | |
| | Walls - Plaster/Drywall | 1st Floor North Corridor | 2,079 | SF | 6 | \$9,216 | |
| | Ceiling - Plaster/Drywall | 1st Floor South Corridor | 1,476 | SF | 6 | \$9,139 | |
| | Doors - Steel Doors incl hw | 1st Floor South Corridor | 8 | EA | 6 | \$2,408 | |
| | Doors - Transom Window | 1st Floor South Corridor | 24 | EA | 6 | \$406 | |
| | Doors - Wood Doors include hw | 1st Floor South Corridor | 8 | EA | 6 | \$2,408 | |
| | Floor - Epoxy/ Painted | 1st Floor South Corridor | 1,476 | SF | 5 | \$2,533 | |
| | Lighting - Pendent/Surface | 1st Floor South Corridor | 23 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor South Corridor | 1,383 | SF | 6 | \$6,131 | |
| | Ceiling - Plaster/Drywall | 1st Floor West Corridor | 2,257 | SF | 5 | \$28,434 | |
| | Doors - Steel Doors incl hw | 1st Floor West Corridor | 7 | EA | 6 | \$2,107 | |
| | Doors - Wood Doors include hw | 1st Floor West Corridor | 6 | EA | 6 | \$1,806 | |
| | Drinking Fountains - Single Fountain | 1st Floor West Corridor | 2 | EA | 7 | \$0 | |
| | Floor - Epoxy/ Painted | 1st Floor West Corridor | 2,257 | SF | 5 | \$3,873 | |
| | Lighting - Pendent/Surface | 1st Floor West Corridor | 25 | EA | 6 | \$3,097 | |
| | Walls - Plaster/Drywall | 1st Floor West Corridor | 3,394 | SF | 6 | \$15,046 | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor West Corridor | 20 | SF | 6 | \$63 | |
| | Ceiling - Plaster/Drywall | 2nd Floor East Corridor | 2,709 | SF | 6 | \$16,774 | |
| | Drinking Fountains - Single Fountain | 2nd Floor East Corridor | 3 | EA | 7 | \$0 | |
| | Floor - Epoxy/ Painted | 2nd Floor East Corridor | 2,709 | SF | 6 | \$1,433 | |
| | Lighting - Pendent/Surface | 2nd Floor East Corridor | 18 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor East Corridor | 4,443 | SF | 6 | \$19,696 | |
| | Ceiling - Plaster/Drywall | 2nd Floor North Corridor | 583 | SF | 6 | \$3,610 | |
| | Floor - Epoxy/ Painted | 2nd Floor North Corridor | 583 | SF | 6 | \$308 | |
| | Lighting - Pendent/Surface | 2nd Floor North Corridor | 8 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor North Corridor | 2,079 | SF | 6 | \$9,216 | |
| | Ceiling - Plaster/Drywall | 2nd Floor South Corridor | 801 | SF | 6 | \$4,960 | |
| | Floor - Epoxy/ Painted | 2nd Floor South Corridor | 801 | SF | 5 | \$1,375 | |
| | Lighting - Pendent/Surface | 2nd Floor South Corridor | 14 | EA | 6 | \$1,735 | |
| | | | | | | | |



Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|--------------------------|----------|------|------|----------|----------|
| Corrido | r | | | | | | |
| | Walls - Plaster/Drywall | 2nd Floor South Corridor | 1,291 | SF | 6 | \$5,723 | |
| | Ceiling - Plaster/Drywall | 2nd Floor West | 2,709 | SF | 6 | \$16,774 | |
| | Drinking Fountains - Single Fountain | 2nd Floor West | 3 | EA | 7 | \$0 | |
| | Floor - Epoxy/ Painted | 2nd Floor West | 2,709 | SF | 6 | \$1,433 | |
| | Lighting - Pendent/Surface | 2nd Floor West | 18 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor West | 4,416 | SF | 6 | \$19,576 | |
| | Walls - Tile Ceramic/ Porcelain | 2nd Floor West | 40 | SF | 6 | \$126 | |
| | Ceiling - Plaster/Drywall | 3rd Floor East Corridor | 2,709 | SF | 6 | \$16,774 | |
| | Drinking Fountains - Single Fountain | 3rd Floor East Corridor | 3 | EA | 7 | \$0 | |
| | Floor - Epoxy/ Painted | 3rd Floor East Corridor | 2,709 | SF | 5 | \$4,649 | |
| | Lighting - Pendent/Surface | 3rd Floor East Corridor | 6 | EA | 6 | \$743 | |
| | Walls - Plaster/Drywall | 3rd Floor East Corridor | 4,416 | SF | 6 | \$19,576 | |
| | Ceiling - Plaster/Drywall | 3rd Floor North Corridor | 583 | SF | 6 | \$3,610 | |
| | Floor - Epoxy/ Painted | 3rd Floor North Corridor | 583 | SF | 6 | \$308 | |
| | Lighting - Pendent/Surface | 3rd Floor North Corridor | 4 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor North Corridor | 1,232 | SF | 6 | \$5,461 | |
| | Ceiling - Plaster/Drywall | 3rd Floor West Corridor | 2,709 | SF | 6 | \$16,774 | |
| | Drinking Fountains - Single Fountain | 3rd Floor West Corridor | 3 | EA | 7 | \$0 | |
| | Floor - Concrete Epoxy/ Painted | 3rd Floor West Corridor | 2,709 | SF | 6 | \$1,317 | |
| | Lighting - Pendent/Surface | 3rd Floor West Corridor | 16 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor West Corridor | 4,416 | SF | 6 | \$19,576 | |
| Safety | | | | | | | |
| | Camera Viewing Station | | 2 | EA | 6 | \$1,365 | |
| | Security Cameras | | 8 | EA | 6 | \$1,552 | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor North Corridor | 977 | SF | 6 | \$7,153 | |
| | Floor - Epoxy/ Painted | 1st Floor North Corridor | 977 | SF | 6 | \$517 | |
| | Handrails | 1st Floor North Corridor | 20 | LF | 6 | \$173 | |
| | Lighting - Pendent/Surface | 1st Floor North Corridor | 12 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 1st Floor North Corridor | 1 | EA | 6 | \$124 | |
| | Stairs - Concrete | 1st Floor North Corridor | 100 | LF | 6 | \$829 | |
| | Walls - Plaster/Drywall | 1st Floor North Corridor | 2,079 | SF | 6 | \$5,738 | |
| | Ceiling - Plaster/Drywall | North East | 398 | SF | 6 | \$2,914 | |
| | Floor - Epoxy/ Painted | North East | 290 | SF | 6 | \$153 | |
| | Floor - Tile/Sheet | North East | 412 | SF | 6 | \$224 | |
| | Handrails | North East | 144 | LF | 6 | \$1,248 | |
| | | | | | | | |



Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|----------------------------|------------|----------|------|------|-----------|----------|
| Stairs | | | | | | | |
| | Lighting - Lay-in | North East | 3 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | North East | 7 | EA | 7 | \$0 | |
| | Stairs - Tile | North East | 485 | LF | 6 | \$4,501 | |
| | Walls - Plaster/Drywall | North East | 2,515 | SF | 6 | \$6,941 | |
| | Ceiling - Plaster/Drywall | North West | 398 | SF | 6 | \$2,914 | |
| | Floor - Epoxy/ Painted | North West | 290 | SF | 6 | \$153 | |
| | Floor - Tile/Sheet | North West | 412 | SF | 6 | \$224 | |
| | Handrails | North West | 144 | LF | 6 | \$1,248 | |
| | Lighting - Lay-in | North West | 3 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | North West | 7 | EA | 7 | \$0 | |
| | Stairs - Tile | North West | 412 | LF | 6 | \$3,824 | |
| | Walls - Plaster/Drywall | North West | 2,515 | SF | 6 | \$6,941 | |
| | Ceiling - Plaster/Drywall | South East | 390 | SF | 6 | \$2,855 | |
| | Floor - Tile/Sheet | South East | 568 | SF | 6 | \$309 | |
| | Handrails | South East | 174 | LF | 6 | \$1,508 | |
| | Lighting - Pendent/Surface | South East | 9 | EA | 7 | \$0 | |
| | Stairs - Tile | South East | 548 | LF | 6 | \$5,086 | |
| | Walls - Plaster/Drywall | South East | 2,533 | SF | 5 | \$11,555 | |
| | Ceiling - Plaster/Drywall | South West | 390 | SF | 6 | \$2,855 | |
| | Floor - Tile/Sheet | South West | 568 | SF | 5 | \$2,550 | |
| | Handrails | South West | 174 | LF | 6 | \$1,508 | |
| | Lighting - Pendent/Surface | South West | 9 | EA | 7 | \$0 | |
| | Stairs - Tile | South West | 548 | LF | 6 | \$5,086 | |
| | Walls - Plaster/Drywall | South West | 2,533 | SF | 5 | \$11,555 | |
| Buildi | ng Interior Subtotal: | | | | | \$413,717 | |

Dunuing interior Subtotal:

Total Building Cost

\$5,609,723

SITE

| Category: | Site |
|-----------|------|
|-----------|------|

| outog | | | | | | |
|-----------|--------------------------------|---------------------------------|----------|------|------|----------|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost Com |
| Civil/Dra | ainage | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site / Parking Lot- East | 1 | EA | 6 | \$1,094 |
| | Civil/ Drainage - Site Manhole | Entire Site | 5 | EA | 6 | \$7,464 |



SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|--------------------------|----------|------|-------|-----------|--------------------------|
| Fencing | | | | | | | |
| | Fencing - Chain Link | Entire Site | 676 | LF | 6 | \$12,693 | |
| | Fencing - Guard Rail | Entire Site / North | 33 | LF | 6 | \$381 | |
| | Fencing - New Standard Ornamental | Entire Site | 1,162 | LF | 6 | \$37,072 | |
| Landsca | ape | | | | | | |
| | Benches | Entire Site / Site West | 2 | EA | 4 | \$5,652 | bent, backs missing |
| | Landscape - Grass | Entire Site | 3,327 | SF | 6 | \$2,759 | |
| | Landscape - Hardscape- Concrete | Entire Site | 11,608 | SF | 6 | \$59,924 | |
| | Landscape - Hardscape- Concrete | Entire Site / Site West | 400 | SF | 5 | \$5,102 | cracks |
| | Parkway trees | Entire Site | 17 | EA | 7 | \$0 | |
| | Play Area - Asphalt/ Hardscape | Entire Site | 35,540 | SF | 6 | \$85,890 | |
| | Play Area - Asphalt/ Hardscape | Entire Site / South East | 12,556 | SF | 4 | \$112,758 | potholes, uneven surface |
| | Trash Receptacles | Entire Site | 6 | EA | 6 | \$1,874 | |
| Parking | Lot | | | | | | |
| | Surface - Asphalt | Northeast | 21,320 | SF | 7 | \$0 | |
| Playgro | und | | | | | | |
| | Equipment - School Age 5-12 | Northwest / North West | 1 | EA | 6 | \$3,546 | Exercise equipment |
| | Equipment - School Age 5-12 | Southwest / South West | 1 | EA | 6 | \$3,546 | |
| | Equipment - Swingset | Southwest / South West | 1 | EA | 4 | \$16,656 | no swings |
| | Surface - Square Rubber Mats | Northwest / North West | 1,160 | SF | 5 | \$11,711 | Gaps, mats missing |
| | Surface - Square Rubber Mats | Southwest / South West | 4,081 | SF | 5 | \$41,201 | gaps, missing mats |
| Sidewal | ks | | | | | | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 13,372 | SF | 6 | \$26,580 | |
| Signage | | | | | | | |
| | Flag Pole - Building Mounted Flag Pole | South | 1 | EA | 6 | \$828 | no flag |
| | Flag Pole - Flag Pole | South | 1 | EA | 6 | \$1,657 | |
| | Marquee - Free Standing Back lighted w/ LED | South | 1 | EA | 7 | \$0 | |
| Site S | ubtotal: | | | | | \$438,386 | |
| Total \$ | Site Cost | | | | | \$438,386 | |
| Camp | ous Total ^{2 3} | | | | \$6,0 | 048,109 | |



¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------------|-------------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | | - | | | | | | | Į. | - | | | + |
| Computer Lab | Regular Classroom | | 203 | 203 | 817 | 1 | 42 | 83 | 144 | 72 | 40 | Y | Ν | Ν |
| Counseling Room | Store Room | 1st Floor | 107 | | 839 | 1 | 1 | 7 | 120 | 45 | 40 | Y | Ν | Ν |
| Counseling Room | Regular Classroom | 2nd Floor | 213 | Movie Rm | 594 | 1 | 1 | 24 | 72 | 36 | 40 | Y | Ν | Ν |
| Kindergarten | Regular Classroom | | 112 | 112 | 802 | 1 | 1 | 7 | 120 | 60 | 40 | Y | Ν | Ν |
| Other Instructional Use | Store Room | 3rd Floor | 313A | 307B | 402 | 1 | 1 | 4 | 54 | 27 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 101 | 101 | 828 | 1 | 1 | 7 | 120 | 60 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | | 108 | 108 | 847 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 109 | 109 | 828 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 110 | 820 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | | 111 | 111 | 830 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | | 204 | 204 | 716 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 830 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 206 | 206 | 821 | 1 | 1 | 7 | 120 | 60 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 207 | 207 | 823 | 1 | 1 | 7 | 120 | 60 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 208 | 208 | 832 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 817 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 210 | 210 | 833 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | | 211 | 211 | 822 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 212 | 212 | 830 | 1 | 1 | 7 | 120 | 60 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 301 | 301 | 828 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 302 | 302 | 828 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | | 303 | 303 | 819 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Ν | Y |
| Regular Classroom | Regular Classroom | | 304 | 304 | 731 | 1 | 1 | 6 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 305 | 305 | 839 | 1 | 2 | 24 | 144 | 72 | 40 | Y | Ν | Ν |
| Regular Classroom | Regular Classroom | | 306 | 306 | 826 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 307 | 307 | 830 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Regular Classroom | | 309 | 309 | 839 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Y |
| Regular Classroom | Regular Classroom | | 310 | 310 | 830 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Regular Classroom | Other Instructional Use | | 311 | 311 | 562 | 1 | 1 | 44 | 96 | 48 | 40 | Y | Ν | Ν |
| Regular Classroom | Other Instructional Use | | 312 | 312 | 1,005 | 1 | 1 | 70 | 168 | 89 | 40 | Y | Ν | Ν |
| Science Classroom | Science Classroom | | 308 | 308 | 830 | 1 | 1 | 7 | 144 | 72 | 40 | Y | Y | Ν |
| Science Classroom | Health | 3rd Floor | 313 | 307A | 807 | 1 | 1 | 6 | 54 | 31 | 40 | Y | Ν | Ν |