6525 N Hiawatha Ave Chicago, IL 60646

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1939	2	18,347	\$1,653,822
Addition 1	1953	2	4,284	\$296,848
Addition 2	1955	2	7,661	\$638,707
Addition 3	2012	2	35,298	\$748,909
SITE				\$131,626
Campus Total			65,590	\$3,469,912

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	e						
	Exterior Doors - Exterior Steel Door	Door 12 - North - areawell	1	EA	6	\$481	
	Exterior Doors - Exterior Wood Door	Door 1 - Southeast	2	EΑ	6	\$961	
	Exterior Doors - Exterior Wood Door	Door 10 - Southwest	2	EΑ	6	\$961	
	Exterior Doors - Transom Lite	Door 1 - Southeast	1	EΑ	6	\$313	
	Exterior Doors - Transom Lite	Door 10 - Southwest	1	EΑ	6	\$313	
	Exterior Stairs - Concrete	Door 12 - North - areawell	48	LF	6	\$3,925	
	Exterior Stairs - Stone	Door 1 - Southeast	55	LF	6	\$6,214	
	Exterior Stairs - Stone	Door 10 - Southwest	55	LF	6	\$6,214	
	Stair Handrail - Steel_Stair Handrail	Door 1 - Southeast	16	LF	6	\$139	
	Stair Handrail - Steel_Stair Handrail	Door 10 - Southwest	16	LF	6	\$139	
	Stair Handrail - Steel_Stair Handrail	Door 12 - North - areawell	20	LF	6	\$173	
Founda	tion						
	Foundation - Concrete	Entire Building	20	LF	5	\$11,039	Seepage
	Foundation - Concrete	Entire Building	358	LF	7	\$0	
	Superstructure - Concrete	Entire Building	50	SF	5	\$2,091	Ceiling deterioration
	Superstructure - Steel with Clay Tile Arch	Entire Building	18,347	SF	7	\$0	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building / Roof	3	EA	6	\$1,610	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	\$866	
Roof Sys	stem						
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	31	LF	7	\$0	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	20	LF	5	\$57,031	Missing mortar, cracks, spalling
	Coping - Stone	Main Roof	352	LF	6	\$11,305	
	Downspouts - Interior Downspouts	Main Roof	60	LF	6	\$1,994	
	Parapet - 16" - 30" Height	Main Roof	288	LF	6	\$11,507	
	Parapet - Parapet > 30"	Main Roof	64	LF	6	\$4,091	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	7,283	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Main Roof	7,283	SF	4	\$204,128	Bubbles, brittle, cracking, leaks
Walls							
	Cheek-Wall - Concrete	Entire Building	120	SF	6	\$1,230	
	Exterior Walls - Brick	Entire Building	30,242	SF	6	\$203,256	
	Exterior Walls - Stone-Cast	Entire Building	920	SF	6	\$6,183	
Windows	s						
	Guard - Guards perforated	Entire Building	86	SF	7	\$0	
	Lintels - Steel	Entire Building	136	LF	6	\$3,948	
	Lintels - Stone	Entire Building	80	LF	6	\$0	
	Windows - Casement Aluminum	Entire Building	9	SF	7	\$0	
	Windows - Decorative	Entire Building / Boiler Room	32	SF	5	\$3,922	
	Windows - Sash Aluminum	Entire Building	1,572	SF	5	\$56,446	
	an Fretanian Crebtatal					¢c00 404	

Building Exterior Subtotal:

\$600,481

Building: Main

Category: Electrical System

ıp Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
rgency System						
Automatic Transfer Switch	Electrical Room	1	EA	6	\$408	
Emergency A/C Power - Corridors and Stairs	Entire Building	6,968	SF	7	\$0	
Emergency A/C Power - Students Toilets	Entire Building	1,092	SF	7	\$0	
Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	\$1,215	
Emergency Battery Packs - Multipurpose Room	Entire Building / 1st Floor	2	EA	6	\$405	
Exit Signs - Corridors and Stairs	Entire Building	7	EA	6	\$1,048	school has AC generator



6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Category: Electrical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
mergency System						
Exit Signs - Multipurpose Room	Entire Building / 1st Floor	6	EA	6	\$898	
Security System - CCTV	Boiler Room / Entire Building	18,347	SF	6	\$5,510	
Security System - Intrusion Detection	Boiler Room / Entire Building	18,347	SF	6	\$4,723	
fain Service						
Independent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	also serves the 2 annex buildings
Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	\$8,232	Also serves addition 1 and addition 2
PA System	Electrical Room / 1st Floor	18,347	SF	6	\$6,034	connected to addition 1, addition 2 and annex
Power Distribution						
Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	6	\$299	fuse panel. emergrncy
Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
Lighting and Power Panels - Above 100 A	Entire Building	8	EA	6	\$3,976	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	\$994	
Main Distribution Panels - 400 - 600 amp	Entire Building / Electrical Room	1	EA	6	\$528	DPT
Main Distribution Panels - Less than 400 amp	Entire Building	2	EA	6	\$1,006	
The state of Occasions Occletes to I					****	

Electrical System Subtotal:

\$38,795

Building: Main

Category: Safty System

Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Fire Alarm			
Fire Alarm Strobe Lights	Entire Building	30,292 SF 6	\$10,829
Fire Alarm_System	Entire Building	30,292 SF 5	\$33,788 connected to Siemens fire alarm panel, in the annex building

Safty System Subtotal:

\$44,617

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Har	ndling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000	Mechanical Room	1	EA	5	\$78,608	serves main and 2 additions.
	Air Intake	Mechanical Room / 1st Floor	1	EA	6	\$5,765	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	\$6,511	
	Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts	Mechanical Room / Entire Building	200	LF	5	\$208,954	
	Return Duct Work - Sheet Metal- Exterior Vertical Shaft and Ducts	Mechanical Room / Entire Building	200	LF	5	\$208,954	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Har	dling Systems						
	Zone Dampers	Mechanical Room	22	EA	5	\$42,098	
Boiler S	Systems						
Boller	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 HF	P Boiler Room	1	EA	6	\$2,046	
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	6	\$2,545	
	Chemical Feeder	Boiler Room	1	EΑ	6	\$1,078	
	Combustion Dampers	Boiler Room	1	EΑ	6	\$409	
	Combustion Dampers	Boiler Room	1	EΑ	6	\$409	
	Condensate Pump	Boiler Room / Mechanical Room	1	EΑ	6	\$2,021	
	Feed Water Pumps and Tank	Boiler Room	1	EΑ	6	\$2,545	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Boiler Room	1	EA	6	\$2,046	serves also addition 1 and addition 2
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	6	\$2,545	serves also addition 1 and addition 2
	Piping - Condensate Pipe- Steel	Boiler Room / Entire Building	100	LF	6	\$189	
	Piping - Condensate Pipe- Steel	Boiler Room / Entire Building	200	LF	6	\$378	
	Piping - Steam Pipe- Steel	Boiler Room / Entire Building	200	LF	6	\$378	
	Piping - Steam Pipe- Steel	Boiler Room / Entire Building	100	LF	6	\$189	
	Steam Traps	Boiler Room / Entire Building	11	EΑ	5	\$14,464	
	Steam Traps	Boiler Room / Entire Building	11	EA	5	\$14,464	
Tempe	rature Control						
	Hybrid Pneumatic/DDC System	Entire Building	18,347	SF	6	\$16,529	valves are DDC controled, thermostats are pneumatic
	Thermostats - Pneumatic	Entire Building	2	EΑ	4	\$1,474	•
	Thermostats - Pneumatic	Entire Building	18	EA	6	\$0	
Ventila	tion						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building / Attic	2	EA	6	\$1,185	need frequent maintenance
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	3	EA	6	\$889	•
	Roof Mounted Duct Work	Entire Building / Attic	100	LF	6	\$37,902	under the roof

Mechanical System Subtotal:

\$445,622

Building: Main

Category: Plumbing System

Group Item - Type Location Quantity Unit Rank Cost Comments



6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	ter						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	5	\$2,249	requires cleaning
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	30,292	SF	6	\$6,064	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	30,292	SF	6	\$7,364	
	Domestic Piping-Cold Water Risers	Entire Building	30,292	SF	6	\$5,631	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	30,292	SF	6	\$4,765	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	30,292	SF	6	\$5,631	
	Domestic Piping-Hot Water Return Lines	Entire Building	30,292	SF	6	\$4,332	
	Domestic Piping-Hot Water Return Risers	Entire Building	30,292	SF	6	\$4,332	
	Sanitary Piping	Entire Building	30,292	SF	6	\$27,723	
	Storm Piping	Entire Building	30,292	SF	6	\$26,424	
	Vent Piping	Entire Building	30,292	SF	6	\$20,359	
Pumps							
	Pumps - Ejector-Simplex	Boiler Room	1	EA	6	\$745	
	Pumps - Sump-Simplex	Boiler Room / Basement	1	EA	6	\$745	

Plumbing System Subtotal:

\$116,365

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st Floor	715	SF	6	\$2,474	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	715	SF	6	\$716	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	25	LF	6	\$536	
	Storage/ Closet	1st Floor	35	SF	5	\$565	
	Walls - Plaster/Drywall	1st Floor	1,160	SF	6	\$3,201	
Classro	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	6	\$2,374	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Category: Classrooms

	Hom Type	Logotion	Quantitu	l lni4	Donk	Cost	Comments
•	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	pom #105 (Regular Classroom)	Ast Floor				#004	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	686	SF	6	\$687	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	18	LF	7	\$0	
	Storage/ Closet	1st Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	1st Floor	1,160	SF	6	\$3,201	
Classro	oom #106 (Other Instructional Use)						
	Ceiling - Plaster/Drywall	1st Floor	820	SF	6	\$2,838	
	Doors - Transom Window	1st Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	166	SF	6	\$166	
	Floor - Wood	1st Floor	661	SF	6	\$4,660	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	5	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,270	SF	6	\$3,505	
Classro	oom #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	686	SF	6	\$2,374	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	686	SF	6	\$687	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	25	LF	6	\$536	
	Storage/ Closet	2nd Floor	30	SF	6	\$218	
	Walls - Plaster/Drywall	2nd Floor	1,160	SF	6	\$3,201	
Classro	oom #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	\$2,474	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	25	LF	6	\$536	
	Storage/ Closet	2nd Floor	35	SF	6	\$254	
	Walls - Plaster/Drywall	2nd Floor	1,160	SF	6	\$3,201	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Classro	oom #204 (Regular Classroom)									
Classro	ssroom #205 (Other Instructional Use)									
	AC Units	2nd Floor	2	EA	6	\$991				
	Casework	2nd Floor	22	LF	6	\$556				
	Ceiling - Plaster/Drywall	2nd Floor	1,062	SF	6	\$3,675				
	Doors - Transom Window	2nd Floor	18	SF	6	\$305				
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602				
	Floor - Carpet	2nd Floor	1,062	SF	6	\$2,263				
	Lighting - Pendent/Surface	2nd Floor	30	EA	7	\$0				
	Walls - Plaster/Drywall	2nd Floor	1,485	SF	6	\$4,098				
Classro	oom #206 (Regular Classroom)									
	AC Units	2nd Floor	1	EA	6	\$496				
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	\$2,474				
	Doors - Transom Window	2nd Floor	9	SF	6	\$152				
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301				
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716				
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0				
	Marker Board	2nd Floor	25	LF	6	\$536				
	Storage/ Closet	2nd Floor	30	SF	6	\$218				
	Walls - Plaster/Drywall	2nd Floor	1,160	SF	6	\$3,201				

Classrooms Subtotal: \$64,414

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Adminis	strative Suites/Offices						
	AC Unit	1st Floor - 110 Main Office	1	EA	4	\$6,086	Not on dedicated circuit and poor support
	Ceiling - Plaster/Drywall	1st Floor - 110 Main Office	350	SF	6	\$1,211	
	Doors - Transom Window	1st Floor - 110 Main Office	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor - 110 Main Office	1	EA	6	\$301	
	Floor - Carpet	1st Floor - 110 Main Office	250	SF	6	\$533	
	Floor - Tile/Sheet	1st Floor - 110 Main Office	100	SF	6	\$100	
	Lighting - Pendent/Surface	1st Floor - 110 Main Office	8	EA	6	\$991	
	Power Distribution	1st Floor - 110 Main Office	12	EA	6	\$25,499	
	Walls - Plaster/Drywall	1st Floor - 110 Main Office	950	SF	6	\$2,622	
	Work SInk	1st Floor - 110 Main Office	1	EA	6	\$508	Pedestal lavatory



6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
minist	rative Suites/Offices						
	AC Unit	1st Floor - Conference Room inside 110 Main Office	1	EA	4	\$6,086	Not on dedicated circuit
	Ceiling - Plaster/Drywall	1st Floor - Conference Room inside 110 Main Office	225	SF	6	\$779	
	Doors - Transom Window	1st Floor - Conference Room inside 110 Main Office	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	1st Floor - Conference Room inside 110 Main Office	3	EA	6	\$903	
	Floor - Carpet	1st Floor - Conference Room inside 110 Main Office	180	SF	6	\$384	
	Floor - Tile/Sheet	1st Floor - Conference Room inside 110 Main Office	45	SF	6	\$45	At entry hallway from corridor
	Lighting - Pendent/Surface	1st Floor - Conference Room inside 110 Main Office	6	EA	4	\$3,244	T-12
	Power Distribution	1st Floor - Conference Room inside 110 Main Office	12	EA	6	\$25,499	
	Storage/ Closet	1st Floor - Conference Room inside 110 Main Office	30	SF	6	\$218	
	Walls - Plaster/Drywall	1st Floor - Conference Room inside 110 Main Office	750	SF	6	\$2,070	
	AC Unit	2nd Floor - 209 Faculty Lounge	1	EA	4	\$6,086	Not on dedicated circuit
	Ceiling - Plaster/Drywall	2nd Floor - 209 Faculty Lounge	288	SF	6	\$997	
	Doors - Transom Window	2nd Floor - 209 Faculty Lounge	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor - 209 Faculty Lounge	1	EA	6	\$301	
	Floor - Tile	2nd Floor - 209 Faculty Lounge	288	SF	6	\$630	
	Lighting - Pendent/Surface	2nd Floor - 209 Faculty Lounge	2	EA	4	\$1,081	T-12
	Power Distribution	2nd Floor - 209 Faculty Lounge	12	EA	6	\$25,499	
	Walls - Plaster/Drywall	2nd Floor - 209 Faculty Lounge	645	SF	6	\$1,780	
	Work SInk	2nd Floor - 209 Faculty Lounge	1	EA	6	\$508	Kitchen sink
	Ceiling - Exposed	Basement - Janitor's Room	100	SF	6	\$149	
	Doors - Wood Doors inclu hw	Basement - Janitor's Room	1	EA	6	\$301	
	Floor - Carpet	Basement - Janitor's Room	100	SF	5	\$513	Worn out throughout
	Lighting - Pendent/Surface	Basement - Janitor's Room	1	EA	4	\$541	T-12
	Power Distribution	Basement - Janitor's Room	6	EA	6	\$12,749	
	Storage/ Closet	Basement - Janitor's Room	32	SF	6	\$232	
	Walls - Concrete Block	Basement - Janitor's Room	400	SF	6	\$1,173	
	Ceiling - Plaster/Drywall	Office Room 103	170	SF	6	\$588	
	Doors - Transom Window	Office Room 103	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	Office Room 103	1	EA	6	\$301	
	Floor - Tile/Sheet	Office Room 103	170	SF	6	\$170	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Mechanical/ Service Rooms Vaults 1st Floor 70 SF 6 \$502 Inside 110 Main Office Janitor's Closet 2nd Floor 17 SF 6 \$122 Next to classroom 206 Air Intake Plenums Basement 755 SF 6 \$4,675 Air Chambers B07/B08 Boiler Room Basement 1,990 SF 6 \$14,257 Boiler Room Basement 15 SF 5 \$242 Areas of concrete ceiling at north side cracked, missing with exposed rebar missing with exposed rebar Boiler Room Basement 500 SF 6 \$3,582 Upper level B06 at south side used as a break room room Crawl Space - Unfinished Basement 3,443 SF 6 \$21,319 Interior Stairs Basement 20 LF 6 \$180 Metal Stairs	Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution	Admini	strative Suites/Offices						
Storage Office Room 103		Lighting - Pendent/Surface	Office Room 103	6	EA	7	\$0	
Walls - Plaster/Drywall		Power Distribution	Office Room 103	4	EA	6	\$8,500	
Caling - Plaster/Dywall Room 106B Lounge 112 SF 6 \$338 Floor - Wood Room 106B Lounge 12 SF 6 \$790		Storage/ Closet	Office Room 103	9	SF	6	\$65	
Floor - Wood Room 106B Lounge 112 SF 6 \$790		Walls - Plaster/Drywall	Office Room 103	530	SF	6	\$1,463	
Lighting - Pendent/Surface Room 1068 Lounge Care Face State		Ceiling - Plaster/Drywall	Room 106B Lounge	112	SF	6	\$388	
Power Distribution		Floor - Wood	Room 106B Lounge	112	SF	6	\$790	
Storage/ Closet Room 106B Lounge 16 SF 6 \$11.40 Walls - Plaster/Dywall Room 106B Lounge 16 SF 6 \$11.42 Work Slink Room 106B Lounge 1 EA 6 \$3.08 MDF - Locate in room 103 1 EA 6 \$3.08 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 MDF - Locate in room 103 1 EA 6 \$3.00 Mechanical/ Service Rooms Basement 750 SF 6 \$4.00 Machanical/ Service Rooms Basement 20 LF 6 \$3.00 Mechanical/ Service Rooms Basement 20 LF 6 \$3.00 Mechanical/ Service Rooms Basement 160 SF 6 \$4.00 Mechanical/ Service Rooms 100 ST 6 \$4.00 Mechanical/ Service Rooms 100 ST 6 \$4.00 Mechanical/ Service Ro		Lighting - Pendent/Surface	Room 106B Lounge	2	EA	7	\$0	
Walls - Plaster/Drywall Room 106B Lounge 450 SF 6 \$1,242		Power Distribution	Room 106B Lounge	6	EA	6	\$12,749	
MOF_IDF		Storage/ Closet	Room 106B Lounge	16	SF	6	\$116	
MDF Locate in room 103		Walls - Plaster/Drywall	Room 106B Lounge	450	SF	6	\$1,242	
Doors - Wood Doors inclu hw Finishes MDF - Locate in room 103 1 EA 6 \$ \$4.01		Work Slnk	Room 106B Lounge	1	EA	6	\$508	
Mochanical/ Service Rooms	MDF_I	DF						
Mechanical/ Service Rooms Usults 1st Floor 70 SF 6 \$502 Inside 110 Main Office Janitor's Closet 2nd Floor 17 SF 6 \$122 Next to classroom 206 4 ir Chambers B07/B08 Air Intake Plenums Basement 1,990 SF 6 \$14,257 Air Chambers B07/B08 Air Chambers B07/B08 Basement 1,990 SF 6 \$14,257 Areas of concrete ceiling at north side cracked, missing with exposed rebar missing with expos		Doors - Wood Doors inclu hw	MDF - Locate in room 103	1	EA	6	\$301	
Vaults 1st Floor 70 SF 6 \$502 Inside 110 Main Office Janifor's Closet 2nd Floor 17 SF 6 \$122 Next to classroom 206 Air Intake Plenums Basement 755 SF 6 \$14,257 Boiler Room Basement 1,990 SF 6 \$14,257 Boiler Room Basement 500 SF 6 \$3,582 Upper level B06 at south side used as a break room Crawl Space - Unfinished Basement 3,443 SF 6 \$21,319 Interior Stairs Basement 20 LF 6 \$180 Metal Stairs Interior Stairs Basement 6 LF 6 \$150 3-concrete steps up to B01 Engineer's office /3 concrete steps up to B01 Engineer's office /3 concrete steps up to B01 Engineer's office Bathroom Mechanical/ Service Rooms Basement 160 SF 6 \$1,146 Electrical room inside B07 Boiler break room Storage Room Storage Room Storeroom 106A - In room 106 60 SF 6		Finishes	MDF - Locate in room 103	562	SF	6	\$4,010	,
Janitor's Closet Air Intake Plenums Basement Bas	Mechar	nical/ Service Rooms						
Air Intake Plenums Basement Total Basement Basement Total Bota Bota Bota Bota Bota Bota Bota Bota		Vaults	1st Floor	70	SF	6	\$502	Inside 110 Main Office
Boiler Room Basement 1,990 SF 6 \$11,257 Boiler Room Basement 15 SF 5 \$242 Areas of concrete ceiling at north side cracked, missing with exposed rebar room missing with exposed rebar room Crawl Space - Unfinished Basement 3,443 SF 6 \$21,319 Interior Stairs Basement 20 LF 6 \$180 Metal Stairs Interior Stairs Basement 6 LF 6 \$180 Metal Stairs Mechanical/ Service Rooms Basement 160 SF 6 \$1,146 Electrical room inside B07 Boiler break room Mechanical/ Service Rooms Storage Room Storage Room 5 Storeroom 106A - In room 106 6 SF 6 \$1,146 Electrical room inside B07 Boiler break room Restroom Restroom Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 106 SF 6 \$1,25 Cork board To Floor - Boys across from classroom 106 SF 6 \$1,25 Cork board To Floor - Boys across from classroom 106 SF 6 \$1,25 Cork board		Janitor's Closet	2nd Floor	17	SF	6	\$122	Next to classroom 206
Boiler Room Basement 15 SF 5 \$242 Areas of concrete ceiling at north side cracked, missing with exposed rebar Boiler Room Basement 500 SF 6 \$3,582 Upper level B06 at south side used as a break room Crawl Space - Unfinished Basement 3,443 SF 6 \$21,319 Interior Stairs Basement 20 LF 6 \$180 Metal Stairs Interior Stairs Basement 6 LF 6 \$180 Metal Stairs Interior Stairs Basement 7 Stairs 8 Basement 7 Stairs 8 Basement 8 Storage Room 8 Basement 8 Storage Room 8 Storeroom 106A - In room 106 6 SF 6 \$1,146 Electrical room inside B07 Boiler break room Storage Room 8 Storeroom 106A - In room 106 6 SF 6 \$430 Restroom Restroom Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 106 SF 6 \$12 Cork board 106 Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 220 SF 6 \$761		Air Intake Plenums	Basement	755	SF	6	\$4,675	Air Chambers B07/B08
Boiler Room Basement 500 SF 6 \$3,582 Upper level B06 at south side used as a break room Crawl Space - Unfinished Basement 3,443 SF 6 \$21,319 Interior Stairs Basement 20 LF 6 \$180 Metal Stairs Interior Stairs Basement 6 LF 6 \$180 Metal Stairs Interior Stairs Basement 7 50 SF 6 \$180 Metal Stairs Interior Stairs Basement 7 50 SF 6 \$180 Metal Stairs Mechanical/ Service Rooms Basement 160 SF 6 \$1,146 Electrical room inside B07 Boiler break room Storage Room Storage Room Storeroom 106A - In room 106 60 SF 6 \$430 Restroom Accessories 1st Floor - Boys across from classroom 106 Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 20 SF 6 \$123 Cork board Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 20 SF 6 \$761		Boiler Room	Basement	1,990	SF	6	\$14,257	
Crawl Space - Unfinished Interior Stairs Interior Stairs Interior Stairs Interior Stairs Basement Bas		Boiler Room	Basement	15	SF	5	\$242	
Interior Stairs Interior Stairs Interior Stairs Interior Stairs Interior Stairs Basement Base		Boiler Room	Basement	500	SF	6	\$3,582	• •
Interior Stairs Basement		Crawl Space - Unfinished	Basement	3,443	SF	6	\$21,319	
Mechanical/ Service Rooms Basement 160 SF 6 \$1,146 Electrical room inside B07 Boiler break room Storage Room Storeroom 106A - In room 106 60 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 60 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 60 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 60 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 SF 6 \$430 Mechanical/ Service Rooms Storeroom 106A - In room 106 Mechanical/ Service Rooms Storeroom 106A - In room 106 Mechanical/ Service Rooms Storeroom 106A - In room 106 Mechanical/ Service Rooms Storeroom 106A - In room 106 Mechanical/ Service Rooms Storeroom 106A - In room 106 Mechanical/ Service Rooms Storeroom 106A - In room 106A Mechanical/ Service Rooms Storeroom 106A - In room 106A Mechanical/		Interior Stairs	Basement	20	LF	6	\$180	Metal Stairs
Storage Room Storeroom 106A - In room 106 60 SF 6 \$430 Restroom Accessories 1st Floor - Boys across from classroom 106 50 SF 6 \$461 Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 106 30 SF 6 \$123 Cork board Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 220 SF 6 \$761		Interior Stairs	Basement	6	LF	6	\$54	concrete steps up to B01 Engineer's Office
RestroomAccessories1st Floor - Boys across from classroom 10650SF6\$461Ceiling - Plaster/Drywall1st Floor - Boys across from classroom 10630SF6\$123Cork boardCeiling - Plaster/Drywall1st Floor - Boys across from classroom220SF6\$761		Mechanical/ Service Rooms	Basement	160	SF	6	\$1,146	Electrical room inside B07 Boiler break room
Accessories 1st Floor - Boys across from classroom 50 SF 6 \$461 Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 30 SF 6 \$123 Cork board Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 220 SF 6 \$761		Storage Room	Storeroom 106A - In room 106	60	SF	6	\$430	
Ceiling - Plaster/Drywall 106 1st Floor - Boys across from classroom 30 SF 6 \$123 Cork board 106 Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 220 SF 6 \$761	Restro	om						
Ceiling - Plaster/Drywall 1st Floor - Boys across from classroom 220 SF 6 \$761		Accessories		50	SF	6	\$461	
		,	•	30	SF	6	\$123	Cork board
		Ceiling - Plaster/Drywall		220	SF	6	\$761	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Doors - Transom Window	1st Floor - Boys across from classroom 106	32	SF	6	\$542	
	Doors - Wood Doors inclu hw	1st Floor - Boys across from classroom 106	2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Boys across from classroom 106	250	SF	6	\$529	
	Hand Dryer	1st Floor - Boys across from classroom 106	2	EA	6	\$460	
	Lavatory	1st Floor - Boys across from classroom 106	2	EA	6	\$639	Pedestals
	Lighting - Pendent/Surface	1st Floor - Boys across from classroom 106	4	EA	4	\$2,163	T-12
	Partitions	1st Floor - Boys across from classroom 106	1	EA	6	\$297	
	Urinals	1st Floor - Boys across from classroom 106	7	EA	6	\$2,352	
	Walls - Plaster/Drywall	1st Floor - Boys across from classroom 106	170	SF	6	\$469	
	Walls - Structural Glazed Tile	1st Floor - Boys across from classroom 106	680	SF	6	\$2,139	
	Water Closet	1st Floor - Boys across from classroom 106	1	EA	6	\$336	
	Water Closet	1st Floor - Boys across from classroom 106	1	EA	5	\$1,344	Under repair
	Accessories	1st Floor - Girls across classroom 104	4	SF	6	\$37	
	Ceiling - Plaster/Drywall	1st Floor - Girls across classroom 104	20	SF	5	\$250	Area stained, bubbling and peeling adjacent to light fixtures
	Ceiling - Plaster/Drywall	1st Floor - Girls across classroom 104	220	SF	6	\$761	
	Doors - Transom Window	1st Floor - Girls across classroom 104	32	SF	6	\$542	
	Doors - Wood Doors inclu hw	1st Floor - Girls across classroom 104	2	EA	6	\$602	
	Floor Drain	1st Floor - Girls across classroom 104	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Girls across classroom 104	240	SF	6	\$508	
	Hand Dryer	1st Floor - Girls across classroom 104	2	EA	6	\$460	
	Lavatory	1st Floor - Girls across classroom 104	2	EΑ	6	\$639	Pedestals
	Lighting - Pendent/Surface	1st Floor - Girls across classroom 104	4	EA	6	\$496	
	Partitions	1st Floor - Girls across classroom 104	6	EΑ	6	\$1,782	
	Walls - Plaster/Drywall	1st Floor - Girls across classroom 104	170	SF	6	\$469	
	Walls - Structural Glazed Tile	1st Floor - Girls across classroom 104	670	SF	6	\$2,108	
	Water Closet	1st Floor - Girls across classroom 104	7	EA	6	\$2,352	
	Accessories	1st Floor - Inside 110 Main Office	16	SF	6	\$148	
	Ceiling - Plaster/Drywall	1st Floor - Inside 110 Main Office	16	SF	6	\$55	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Doors - Wood Doors inclu hw	1st Floor - Inside 110 Main Office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Inside 110 Main Office	16	SF	6	\$34	
	Lighting - Pendent/Surface	1st Floor - Inside 110 Main Office	1	EA	4		T-12
	Walls - Plaster/Drywall	1st Floor - Inside 110 Main Office	160	SF	6	\$442	
	Water Closet	1st Floor - Inside 110 Main Office	1	EA	6	\$336	
	Accessories	2nd Floor - Boys across from classroom 206	250	SF	6	\$2,306	
	Ceiling - Plaster/Drywall	2nd Floor - Boys across from classroom 206	250	SF	6	\$865	
	Doors - Transom Window	2nd Floor - Boys across from classroom 206	32	SF	6	\$542	
	Doors - Wood Doors inclu hw	2nd Floor - Boys across from classroom 206	3	EA	6	\$903	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Boys across from classroom 206	250	SF	6	\$529	
	Hand Dryer	2nd Floor - Boys across from classroom 206	2	EA	6	\$460	
	Lavatory	2nd Floor - Boys across from classroom 206	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor - Boys across from classroom 206	4	EA	7	\$0	
	Partitions	2nd Floor - Boys across from classroom 206	2	EA	6	\$594	
	Urinals	2nd Floor - Boys across from classroom 206	7	EA	6	\$2,352	
	Walls - Plaster/Drywall	2nd Floor - Boys across from classroom 206	180	SF	6	\$497	
	Walls - Structural Glazed Tile	2nd Floor - Boys across from classroom 206	680	SF	6	\$2,139	
	Water Closet	2nd Floor - Boys across from classroom 206	2	EA	6	\$672	
	Accessories	2nd Floor - Girls across from classroom 204	240	SF	6	\$2,214	
	Ceiling - Plaster/Drywall	2nd Floor - Girls across from classroom 204	240	SF	6	\$831	
	Doors - Transom Window	2nd Floor - Girls across from classroom 204	32	SF	6	\$542	
	Doors - Wood Doors inclu hw	2nd Floor - Girls across from classroom 204	2	EA	6	\$602	
	Floor Drain	2nd Floor - Girls across from classroom 204	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Girls across from classroom 204	240	SF	6	\$508	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Hand Dryer	2nd Floor - Girls across from classroom 204	2	EA	6	\$460	
	Lavatory	2nd Floor - Girls across from classroom 204	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor - Girls across from classroom 204	4	EA	7	\$0	
	Partitions	2nd Floor - Girls across from classroom 204	6	EA	6	\$1,782	
	Walls - Plaster/Drywall	2nd Floor - Girls across from classroom 204	170	SF	6	\$469	
	Walls - Structural Glazed Tile	2nd Floor - Girls across from classroom 204	670	SF	6	\$2,108	
	Water Closet	2nd Floor - Girls across from classroom 204	7	EA	6	\$2,352	
	Accessories	2nd Floor - Inside 209 Faculty Lounge	30	SF	6	\$277	
	Ceiling - Plaster/Drywall	2nd Floor - Inside 209 Faculty Lounge	30	SF	6	\$104	
	Doors - Wood Doors inclu hw	2nd Floor - Inside 209 Faculty Lounge	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Inside 209 Faculty Lounge	30	SF	6	\$63	
	Lavatory	2nd Floor - Inside 209 Faculty Lounge	1	EA	6	\$320	Pedestal
	Lighting - Pendent/Surface	2nd Floor - Inside 209 Faculty Lounge	1	EA	4	\$541	T-12 with no cover
	Partitions	2nd Floor - Inside 209 Faculty Lounge	1	EA	6	\$297	Granite slab
	Walls - Plaster/Drywall	2nd Floor - Inside 209 Faculty Lounge	210	SF	6	\$580	
	Walls - Plaster/Drywall	2nd Floor - Inside 209 Faculty Lounge	20	SF	6	\$77	Granite wainscot around toliet
	Water Closet	2nd Floor - Inside 209 Faculty Lounge	1	EA	6	\$336	
	Accessories	Basement - Inside B01 Engineer's Office	23	SF	6	\$212	
	Ceiling - Exposed	Basement - Inside B01 Engineer's Office	23	SF	6	\$34	
	Doors - Wood Doors inclu hw	Basement - Inside B01 Engineer's Office	1	EA	6	\$301	
	Floor - Concrete Epoxy/ Painted	Basement - Inside B01 Engineer's Office	23	SF	6	\$12	
	Lighting - Pendent/Surface	Basement - Inside B01 Engineer's Office	1	EA	6	\$124	No cover
	Walls - Concrete Block	Basement - Inside B01 Engineer's Office	150	SF	6	\$440	
	Water Closet	Basement - Inside B01 Engineer's Office	1	EA	6	\$336	
	Accessories	Toilet 106C - in Room 106	28	SF	6	\$258	
	Ceiling - Plaster/Drywall	Toilet 106C - in Room 106	28	SF	6	\$97	
	Doors - Wood Doors inclu hw	Toilet 106C - in Room 106	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Toilet 106C - in Room 106	28	SF	6	\$59	
	Lighting - Pendent/Surface	Toilet 106C - in Room 106	1	EA	7	\$0	
	Walls - Plaster/Drywall	Toilet 106C - in Room 106	180	SF	6	\$497	
	Water Closet	Toilet 106C - in Room 106	1	EA	6	\$336	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Category: Rooms (Other Than Classrooms)

Group Item - Type Location Quantity Unit Rank Cost Comments

Rooms (Other Than Classrooms) Subtotal: \$267,011

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Ceiling - Exposed	1st Floor	84	SF	6	\$125	
	Ceiling - Plaster/Drywall	1st Floor	1,793	SF	6	\$11,102	
	Doors - Wood Doors include hw	1st Floor	4	EA	6	\$1,204	
	Drinking Fountains - Double Fountain	1st Floor	2	EA	6	\$672	
	Floor - Tile Ceramic/ Porcelain	1st Floor	224	SF	6	\$625	
	Floor - Tile/Sheet	1st Floor	1,641	SF	6	\$892	
	Floor - Tile/Sheet	1st Floor	12	SF	5	\$69	Bulging and cracking at east / west ends of corridor
	Lighting - Pendent/Surface	1st Floor	18	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	2	EA	7	\$0	
	Student Lockers - One Tier	1st Floor	67	EA	6	\$6,220	
	Walls - Plaster/Drywall	1st Floor	1,920	SF	6	\$8,511	
	Walls - Structural Glazed Tile	1st Floor	1,180	SF	6	\$3,712	
	Ceiling - Plaster/Drywall	2nd Floor	1,402	SF	6	\$8,681	
	Doors - Side-lite	2nd Floor	70	EA	6	\$1,170	
	Doors - Transom Window	2nd Floor	32	EA	6	\$542	
	Doors - Wood Doors include hw	2nd Floor	2	EA	6	\$602	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	6	\$672	
	Floor - Terrazzo	2nd Floor	265	SF	6	\$2,224	
	Floor - Tile/Sheet	2nd Floor	1,258	SF	6	\$684	
	Floor - Tile/Sheet	2nd Floor	12	SF	5	\$69	Bulging and cracking at east / west ends of corridor
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	71	EA	6	\$6,591	
	Walls - Plaster/Drywall	2nd Floor	1,140	SF	6	\$5,054	
	Walls - Structural Glazed Tile	2nd Floor	865	SF	6	\$2,721	
Safety							
	Camera Viewing Station	1st Floor	1	EA	6	\$683	Main Office
	Security Cameras	Entire Building	4	EA	6	\$776	
	Security Cameras	Entire Building	5	EA	6	\$970	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Ceiling - Plaster/Drywall	East	255	SF	6	\$1,867	
	Floor - Terrazzo	East	125	SF	6	\$1,049	
	Handrails	East	60	LF	6	\$520	
	Lighting - Pendent/Surface	East	2	EA	7	\$0	
	Stairs - Terrazzo	East	25	LF	6	\$232	
	Walls - Plaster/Drywall	East	510	SF	6	\$1,408	
	Walls - Structural Glazed Tile	East	285	SF	6	\$897	
	Ceiling - Plaster/Drywall	West / 2nd Floor	255	SF	6	\$1,867	
	Floor - Terrazzo	West	125	SF	6	\$1,049	
	Handrails	West	60	LF	6	\$520	
	Lighting - Pendent/Surface	West	2	EA	7	\$0	
	Stairs - Terrazzo	West	25	LF	6	\$232	
	Walls - Plaster/Drywall	West	510	SF	6	\$1,408	
	Walls - Structural Glazed Tile	West	285	SF	6	\$897	
Buildi	ng Interior Subtotal:					\$76,516	

\$1,653,822

Total Building Cost

Building: Addition 1

Category: Building Exterior

_	Jory. Dulluling Exterior						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran	ce						
	Exterior Doors - Exterior Steel Door	Door 11 - Northwest	2	EA	6	\$961	
Founda	ation						
	Foundation - Concrete	Entire Building	130	LF	7	\$0	
	Superstructure - Steel with Clay Tile Arch	Entire Building	4,284	SF	7	\$0	
Lightin	ng						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	\$2,146	
Roof S	System						
	Coping - Stone	Entire Building	130	LF	6	\$4,175	
	Downspouts - Interior Downspouts	Entire Building	30	LF	6	\$997	
	Parapet - 16" - 30" Height	Entire Building	130	LF	6	\$5,194	
	Roof Structure - Steel with Clay Tile Arch	Entire Building	2,142	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Entire Building	2,142	SF	4	\$60,036	Blisters, cracking, leaks



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 1

Category: Building Exterior

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Roof System						
Walls						
Exterior Walls - Brick	Entire Building	3,108	SF	6	\$20,889	
Exterior Walls - Stone-Cast	Entire Building	558	SF	6	\$3,750	
Windows						
Lintels - Steel	Entire Building	90	LF	6	\$2,613	
Windows - Sash Aluminum Double-pane	Entire Building	922	SF	5	\$49,666	Poor balances, hard to lift

Building Exterior Subtotal:

\$150,428

Building: Addition 1

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ncy System						
	Emergency A/C Power - Corridors and Stairs	1st Floor / Entire Building	850	SF	6	\$255	
	Emergency Battery Packs - Corridors and Stairs	Entire Building / Entire Site	3	EΑ	6	\$608	
	Emergency Battery Packs - Multipurpose Room	Entire Building / 1st Floor	2	EΑ	6	\$405	school has generator
	Exit Signs - Corridors and Stairs	Entire Building	3	EΑ	6	\$449	school has a generator
	Exit Signs - Multipurpose Room	Entire Building / 1st Floor	2	EΑ	6	\$299	
	Security System - CCTV	Entire Building	10,100	SF	6	\$3,033	
	Security System - Intrusion Detection	Entire Building	10,100	SF	6	\$2,600	
Main Se	rvice						
	PA System	Entire Building	10,100	SF	6	\$3,322	
Power D	Pistribution						
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	6	\$299	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	\$994	
	Main Distribution Panels - Less than 400 amp	Entire Building / 1st Floor	1	EA	6	\$503	

Electrical System Subtotal:

\$12,767

Building: Addition 1

Category: Safty System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Strobe Lights	Entire Building	10,100	SF	6	\$3,611	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 1

Category: Safty System

Group Item - Type	Location	Quantity Unit Rank	Cost Comments	
Fire Alarm				
Fire Alarm_System	Entire Building	10,100 SF 6	\$4,911 Siemens fire panel is in the annex building	
0-6-0-0-10-1			#0.504	

Safty System Subtotal:

\$8,521

Building: Addition 1

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Tempera	ature Control						
	Pneumatic System	Entire Building	4,284	SF	6	\$2,267	
	Thermostats - Pneumatic	Entire Building	5	EA	6	\$0	
Ventilati	ion						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building / Attic	1	EA	6	\$592	
	Roof Mounted Duct Work	Entire Building / Attic	80	LF	6	\$30,322	under roof for exhaust fan, serves gym

Mechanical System Subtotal:

\$33,181

Building: Addition 1

Category: Plumbing System

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ing						
Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	10,100	SF	6	\$2,022	
Domestic Piping-Cold Water Horizontal Lines	Entire Building	10,100	SF	6	\$2,455	
Domestic Piping-Cold Water Risers	Entire Building	10,100	SF	6	\$1,878	
Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	10,100	SF	6	\$1,589	
Domestic Piping-Hot Water Horizontal Lines	Entire Building	10,100	SF	6	\$1,878	
Domestic Piping-Hot Water Return Lines	Entire Building	10,100	SF	6	\$1,444	
Domestic Piping-Hot Water Return Risers	Entire Building	10,100	SF	6	\$1,444	
Sanitary Piping	Entire Building	10,100	SF	6	\$9,244	
Storm Piping	Entire Building	10,100	SF	6	\$8,810	
Vent Piping	Entire Building / Entire Site	10,100	SF	6	\$6,788	

Plumbing System Subtotal:

\$37,552

Building: Addition 1 Category: Classrooms



Edgebrook Elementary School 6525 N Hiawatha Ave Chicago, IL 60646

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #107 (Office)						
	AC Units	1st Floor	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	325	SF	6	\$1,125	
	Chalk Board	1st Floor	18	LF	4	\$1,653	
	Doors - Transom Window	1st Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	325	SF	6	\$325	
	Lighting - Pendent/Surface	1st Floor	10	EA	6	\$1,239	
	Marker Board	1st Floor	6	LF	6	\$129	
	Storage/ Closet	1st Floor	8	SF	6	\$58	
	Walls - Plaster/Drywall	1st Floor	815	SF	6	\$2,249	
Classro	oom #108 (Music Room)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	\$2,474	
	Doors - Transom Window	2nd Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	25	LF	6	\$536	
	Storage/ Closet	2nd Floor	40	SF	6	\$290	
	Walls - Plaster/Drywall	2nd Floor	1,177	SF	6	\$3,248	
Classro	oom #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	3	LF	6	\$76	
	Ceiling - Plaster/Drywall	2nd Floor	325	SF	6	\$1,125	
	Doors - Side-lite	2nd Floor	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	325	SF	6	\$325	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	\$0	
	Marker Board	2nd Floor	6	LF	7	\$0	
	Storage/ Closet	2nd Floor	3	SF	6	\$22	
	Walls - Plaster/Drywall	2nd Floor	815	SF	6	\$2,249	
	Work Sink	2nd Floor	1	EA	6	\$379	
Classro	oom #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	22	LF	6	\$556	
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	\$2,474	
	Doors - Transom Window	2nd Floor	10	SF	6	\$169	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 1 Category: Classrooms

Group Item - Type	Location	Quantity Unit Rank	Cost Comments	
Classroom #208 (Regular Classroom)				
Floor - Tile/Sheet	2nd Floor	715 SF 6	\$716	
Lighting - Pendent/Surface	2nd Floor	20 EA 7	\$0	
Marker Board	2nd Floor	25 LF 6	\$536	
Storage/ Closet	2nd Floor	15 SF 6	\$109	
Walls - Plaster/Drywall	2nd Floor	1,177 SF 6	\$3,248	
Classrooms Subtotal:			\$29,255	

Classrooms Subtotal:

Building: Addition 1

Category: Rooms (Other Than Classrooms)

Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Mechanical/ Service Rooms			
Crawl Space - Unfinished	Basement	2,142 SF 6	\$13,263

Rooms (Other Than Classrooms) Subtotal:

\$13,263

Building: Addition 1

Category: Building Interior

roup Iter	m - Type	Location	Quantity	Unit	Rank	Cost	Comments
orridor							
Cei	eiling - Plaster/Drywall	1st Floor	225	SF	6	\$1,393	
Flo	oor - Tile/Sheet	1st Floor	225	SF	6	\$122	
Ligl	hting - Pendent/Surface	1st Floor	4	EΑ	7	\$0	
Stu	udent Lockers - One Tier	1st Floor	32	EΑ	6	\$2,971	
Wa	alls - Plaster/Drywall	1st Floor	250	SF	6	\$1,108	
Wa	alls - Structural Glazed Tile	1st Floor	110	SF	6	\$346	
Cei	eiling - Plaster/Drywall	2nd Floor	225	SF	6	\$1,393	
Flo	oor - Tile/Sheet	2nd Floor	225	SF	6	\$122	
Ligl	hting - Pendent/Surface	2nd Floor	4	EΑ	7	\$0	
Stu	udent Lockers - One Tier	2nd Floor	32	EΑ	6	\$2,971	
Wa	alls - Plaster/Drywall	2nd Floor	250	SF	6	\$1,108	
Wa	alls - Structural Glazed Tile	2nd Floor	110	SF	6	\$346	
	Interior Culatotal					¢44.004	

Building Interior Subtotal:

\$11,881



6525 N Hiawatha Ave Chicago, IL 60646

Total Building Cost \$296,848

Building: Addition 2

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	ce						
	Exterior Doors - Exterior Wood Door	Door 2	2	EA	6	\$961	
	Exterior Doors - Transom Lite	Door 2	1	EA	6	\$313	
	Exterior Stairs - Concrete	Door 2	108	LF	6	\$8,831	
	Stair Handrail - Steel_Stair Handrail	Door 2	40	LF	6	\$347	
Founda	ition						
	Foundation - Concrete	Entire Building	214	LF	7	\$0	
	Superstructure - Steel with Clay Tile Arch	Entire Building	7,661	SF	7	\$0	
Lighting	g						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	\$2,146	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	6	\$289	
Roof Sy	ystem						
	Coping - Stone	Roof 1	130	LF	6	\$4,175	
	Coping - Stone	Roof 2	166	LF	6	\$5,332	
	Downspouts - Interior Downspouts	Roof 1	30	LF	6	\$997	
	Downspouts - Interior Downspouts	Roof 2	48	LF	6	\$1,595	
	Parapet - 16" - 30" Height	Roof 1	130	LF	6	\$5,194	
	Parapet - 16" - 30" Height	Roof 2	166	LF	6	\$6,632	
	Roof Structure - Steel with Clay Tile Arch	Roof 1	2,142	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Roof 2	7,283	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	Roof 1	2,142	SF	4	\$60,036	Blisters, cracking, leaks
	Roof - Asphalt Gravel Ballast	Roof 2	7,283	SF	4	\$204,128	Blisters, cracking, leaks
Walls							
	Cheek-Wall - Concrete	Entire Building	60	SF	6	\$615	
	Exterior Walls - Brick	Entire Building	5,150	SF	6	\$34,613	
	Exterior Walls - Brick	Entire Building	50	SF	5	\$1,190	Missing mortar
	Exterior Walls - Stone-Cast	Entire Building	290	SF	6	\$1,949	
Windov	vs						
	Lintels - Steel	Entire Building	30	LF	6	\$871	
	Lintels - Stone	Entire Building	85	LF	6	\$0	
	Windows - Sash Aluminum Double-pane	Entire Building	320	SF	5	\$17,238	Poor balances



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 2

Category: Building Exterior

Group Item - Type Location Quantity Unit Rank Cost Comments

Building Exterior Subtotal: \$357,453

Building: Addition 2

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Emergency A/C Power - Corridors and Stairs	Entire Building	400	SF	6	\$120	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	\$405	
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	6	\$299	school has a generator
	Security System - CCTV	Entire Building	7,661	SF	6	\$2,301	
	Security System - Intrusion Detection	Entire Building	7,661	SF	6	\$1,972	
Main S	ervice						
	PA System	Entire Building	7,661	SF	6	\$2,520	

Electrical System Subtotal: \$7,617

Building: Addition 2

Category: Safty System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Strobe Lights	Entire Building	7,661	SF	6	\$2,739	
Fire Alarm_System	Entire Building	7,661	SF	6	\$3,725	strobes, smoke and heat sensors. Siemens fire alarm panel located in annex

Safty System Subtotal: \$6,464

Building: Addition 2

Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Temperature Control						
Pneumatic System	Entire Building	7,661	SF	6	\$4,053	
Thermostats - Pneumatic	Entire Building	6	EA	6	\$0	
Ventilation						
Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / Attic	1	EA	6	\$592	under roof, in attic
Roof Mounted Duct Work	Entire Building / Attic	50	LF	6	\$18,951	under roof for exhaust fan



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 2

Category: Mechanical System

Group Item - Type Location Quantity Unit Rank Cost Comments

Mechanical System Subtotal: \$23,597

Building: Addition 2

Category: Plumbing System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping						
Storm Piping	Entire Building	7,661	SF	6	\$6,683	

Plumbing System Subtotal: \$6,683

Building: Addition 2 Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	6	\$2,374	
	Doors - Transom Window	1st Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	686	SF	6	\$687	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	30	LF	6	\$643	
	Storage/ Closet	1st Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	1st Floor	1,160	SF	6	\$3,201	
Classro	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	1st Floor	715	SF	6	\$2,474	
	Doors - Transom Window	1st Floor	1	SF	6	\$17	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	715	SF	6	\$716	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	25	LF	6	\$536	
	Storage/ Closet	1st Floor	35	SF	6	\$254	
	Walls - Plaster/Drywall	1st Floor	1,160	SF	6	\$3,201	
Classro	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	30	LF	6	\$758	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 2 Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #201 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	686	SF	6	\$2,374	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	686	SF	6	\$687	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	6	\$428	
	Storage/ Closet	2nd Floor	15	SF	6	\$109	
	Walls - Plaster/Drywall	2nd Floor	1,160	SF	6	\$3,201	
Classro	oom #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	\$2,474	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	5	\$1,174	
	Floor - Tile/Sheet	2nd Floor	715	SF	6	\$716	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	25	LF	7	\$0	
	Storage/ Closet	2nd Floor	45	SF	6	\$326	
	Walls - Plaster/Drywall	2nd Floor	1,160	SF	6	\$3,201	

Classrooms Subtotal: \$33,002

Building: Addition 2

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Administrative Suites/Offices						
Ceiling - Plaster/Drywall	1st Floor - At gym south vestibule used as park district office	70	SF	6	\$242	
Doors - Wood Doors inclu hw	1st Floor - At gym south vestibule used as park district office	1	EA	6	\$301	
Floor - Tile Ceramic/ Porcelain	1st Floor - At gym south vestibule used as park district office	70	SF	6	\$148	
Lighting - Pendent/Surface	1st Floor - At gym south vestibule used as park district office	1	EA	4	\$541	T-12 with no cover
Lighting - Wall Mounted	1st Floor - At gym south vestibule used as park district office	2	EA	5	\$339	Old and abandoned
Power Distribution	1st Floor - At gym south vestibule used as park district office	2	EA	6	\$4,250	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 2

Wa AC Ce Do Flo Lig Wa	tive Suites/Offices alls - Plaster/Drywall C Unit	1st Floor - At gym south vestibule used	050				
AC Ce Do Flc Lig Wa	•		050				
Ce Do Flo Lig Wa	CUnit	as park district office	250	SF	6	\$690	
Do Flo Lig Wa		1st flr Office - next to 101	1	EA	6	\$496	
Flo Lig Wa	eiling - Plaster/Drywall	1st flr Office - next to 101	199	SF	6	\$689	
Lig Wa	oors - Wood Doors inclu hw	1st flr Office - next to 101	1	EA	6	\$301	
Wa	oor - Tile/Sheet	1st flr Office - next to 101	199	SF	6	\$199	
	ghting - Pendent/Surface	1st flr Office - next to 101	2	EA	7	\$0	
	alls - Plaster/Drywall	1st flr Office - next to 101	525	SF	6	\$1,449	
AC	CUnit	2nd flr Office - next to 201	1	EA	6	\$496	
Ce	eiling - Plaster/Drywall	2nd flr Office - next to 201	199	SF	6	\$689	
Do	oors - Wood Doors inclu hw	2nd flr Office - next to 201	1	EA	6	\$301	
Flo	oor - Tile/Sheet	2nd flr Office - next to 201	199	SF	6	\$199	
Lig	ghting - Pendent/Surface	2nd flr Office - next to 201	2	EA	6	\$248	Missing lens
Wa	alls - Plaster/Drywall	2nd flr Office - next to 201	525	SF	6	\$1,449	
Gymnasia							
Ce	eiling - Plaster/Drywall	1st Floor - 109 Gym	2,400	SF	6	\$13,248	
Do	ors - Wood Doors inclu hw	1st Floor - 109 Gym	4	EA	6	\$1,204	2-Double doors
Flo	oor - Wood	1st Floor - 109 Gym	2,400	SF	6	\$16,920	
Lig	ghting - Metal Halide/ High Pressure Sodium	1st Floor - 109 Gym	12	EA	6	\$1,605	
Sc	coreboards	1st Floor - 109 Gym	1	EA	5	\$10,580	Not working
So	ound System	1st Floor - 109 Gym	1	EA	6	\$41,654	
Sta	age	1st Floor - 109 Gym	410	SF	6	\$2,369	
Sta	age Curtain	1st Floor - 109 Gym	1	EA	6	\$0	
Sta	age Lighting System	1st Floor - 109 Gym	1	EA	6	\$12,369	
Sto	orage/ Closet	1st Floor - 109 Gym	155	SF	6	\$1,124	
Wa	alls - Structural Glazed Tile	1st Floor - 109 Gym	3,440	SF	6	\$10,822	
	/ Service Rooms						
	echanical/ Service Rooms	2nd Floor	60	SF	6	\$430	Roof Access Room across from classroom 207
Cra	awl Space - Unfinished	Basement	6,332	SF	6	\$39,207	
Sto	orage Room	Yard Storage - Located outside	84	SF	6	\$602	
Restroom							
Ac	cessories	1st Floor - At south gym vestibule used as storage for park district	70	SF	6	\$646	
Ce	illing - Plaster/Drywall	1st Floor - At south gym vestibule used as storage for park district	70	SF	6	\$242	
Do	oors - Wood Doors inclu hw	1st Floor - At south gym vestibule used as storage for park district	1	EA	6	\$301	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 2

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Floor - Tile Ceramic/ Porcelain	1st Floor - At south gym vestibule used as storage for park district	70	SF	6	\$148	
	Lavatory	1st Floor - At south gym vestibule used as storage for park district	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor - At south gym vestibule used as storage for park district	1	EA	5	\$183	No cover
	Lighting - Wall Mounted	1st Floor - At south gym vestibule used as storage for park district	2	EA	5	\$339	No working
	Partitions	1st Floor - At south gym vestibule used as storage for park district	1	EA	6	\$297	Granite slab
	Walls - Plaster/Drywall	1st Floor - At south gym vestibule used as storage for park district	250	SF	6	\$690	
	Water Closet	1st Floor - At south gym vestibule used as storage for park district	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$168,659

Building: Addition 2

Category: Building Interior

ıp Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
idor						
Ceiling - Plaster/Drywall	1st Floor	20	SF	5	\$349	At corridor east of stage - stained, bubbling, peeling
Ceiling - Plaster/Drywall	1st Floor	805	SF	6	\$4,984	
Floor - Concrete Epoxy/ Painted	1st Floor	200	SF	6	\$97	In between gym and stage
Floor - Tile/Sheet	1st Floor	625	SF	6	\$340	
Lighting - Pendent/Surface	1st Floor	13	EA	6	\$1,611	No cover at corridor light at entrance 2
Stairs - Concrete Stairs	1st Floor	8	LF	6	\$66	At both sides of stage
Student Lockers - One Tier	1st Floor	39	EA	6	\$3,621	
Walls - Plaster/Drywall	1st Floor	30	SF	5	\$301	At corridors east/west of stage - stained, bubbling, peeling
Walls - Plaster/Drywall	1st Floor	1,790	SF	6	\$7,935	
Walls - Structural Glazed Tile	1st Floor	330	SF	6	\$1,038	
Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	\$4,210	
Floor - Tile/Sheet	2nd Floor	680	SF	6	\$370	
Lighting - Pendent/Surface	2nd Floor	9	EA	7	\$0	
Student Lockers - One Tier	2nd Floor	72	EA	6	\$6,684	
Walls - Plaster/Drywall	2nd Floor	540	SF	6	\$2,394	
Walls - Structural Glazed Tile	2nd Floor	330	SF	6	\$1,038	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 2

Category: Building Interior

Duildi	na Interior Cubtatalı				ተ ጋሀ	222	
	Security Cameras		1	EA	6	\$194	
Safety							
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments

Building Interior Subtotal: \$35,232

Total Building Cost \$638,707

Building: Addition 3

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrance	е						
	Entrance Control - Audio and Video	Door 3 - East main	1	EA	7	\$0	
	Entrance Control - Audio and Video	Door 5 - Northwest	1	EA	7	\$0	
	Entrance Control - Audio and Video	Door 9 - Southwest	1	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	Door 4 - Northeast	1	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	Door 5 - Northwest	2	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	Door 6 - Northwest	2	EA	6	\$961	
	Exterior Doors - Overhead Rolling/ Garage Door	Door 4.5 - Northeast	1	EA	6	\$1,433	
	Exterior Doors - Side lite	Door 8 - West center	2	EA	7	\$0	
	Exterior Doors - Side lite	Door 9 - Southwest	2	EA	7	\$0	
	Exterior Doors - Store Front	Door 3 - East main	2	EA	7	\$0	
	Exterior Doors - Store Front	Door 7 - West center	2	EA	7	\$0	
	Exterior Doors - Store Front	Door 8 - West center	2	EA	7	\$0	
	Exterior Doors - Store Front	Door 9 - Southwest	2	EA	7	\$0	
	Exterior Doors - Transom Lite	Door 8 - West center	4	EA	7	\$0	
	Exterior Doors - Transom Lite	Door 9 - Southwest	4	EA	7	\$0	
	Exterior Stairs - Concrete	Door 3 - East main	80	LF	7	\$0	
	Power Door Operator and Controls	Door 3 - East main	1	EA	7	\$0	
	Power Door Operator and Controls	Door 9 - Southwest	1	EA	6	\$0	
	Ramp Handrail - Steel_Ramp Handrail	Door 3 - East main	160	LF	7	\$0	
	Ramps - Concrete	Door 3 - East main	80	LF	7	\$0	
	Stair Handrail - Steel_Stair Handrail	Door 3 - East main	30	LF	7	\$0	
Foundat	ion						
	Foundation - Concrete	Entire Building	612	LF	7	\$0	
	Superstructure - Steel	Entire Building	35,298	SF	7	\$0	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

Category: Building Exterior

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lighting	• •		,				
	Exterior Lighting - Wall Mounted	Entire Building	22	EA	7	\$0	
		Ç					
Roof Sy						•	
	Chimney - Metal Flue	Roof 1	60	LF	7	\$0	
	Chimney - Metal Flue	Roof 1	72	LF	7	\$0	
	Coping - Metal	Roof 1	640	LF	7	\$0	
	Coping - Metal	Roof 2	60	LF	7	\$0	
	Coping - Metal	Roof 4	18	LF	7	\$0	
	Coping - Stone	Roof 3	73	LF	7	\$0	
	Downspouts - Interior Downspouts	Roof 1	240	LF	7	\$0	
	Downspouts - Interior Downspouts	Roof 2	20	LF	6	\$665	
	Downspouts - Interior Downspouts	Roof 3	40	LF	7	\$0	
	Downspouts - Interior Downspouts	Roof 4	50	LF	7	\$0	
	Parapet - 16" - 30" Height	Roof 1	302	LF	7	\$0	
	Parapet - 16" - 30" Height	Roof 3	73	LF	7	\$0	
	Parapet - Parapet < 16" Height	Roof 1	90	LF	7	\$0	
	Parapet - Parapet < 16" Height	Roof 2	60	LF	7	\$0	
	Parapet - Parapet > 30"	Roof 1	248	LF	7	\$0	
	Parapet - Parapet > 30"	Roof 4	18	LF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 1	16,172	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 2	1,030	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 3	1,300	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 4	52	SF	7	\$0	
	Roof - Modified Bitumen	Roof 1	16,172		6		Green roof
	Roof - Modified Bitumen	Roof 2	1,030	SF	7	\$0	
	Roof - Modified Bitumen	Roof 3	1,300	SF	7	\$0	
	Roof - Modified Bitumen	Roof 4	52	SF	7	\$0	
			32	٥.	•	40	
Walls	Conony Motel	Entire Duilding / Main Entress	740	C.	-	₽4	
	Canopy - Metal	Entire Building / Main Entrance	716	SF	6	\$15,379	
	Exterior Walls - Brick	Entire Building	22,063	SF	7	\$0	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building / Main Roof	968	SF	7	\$0 \$0	
	Exterior Walls - Stone-Cast	Entire Building / Main Entrance	813	SF	7	\$0	
Window	vs						
	Curtain wall - Glazed Double Pane	Entire Building	2,922	SF	6	\$32,759	
	Curtain wall - Louver	Entire Building	693	SF	6	\$7,769	
	Guard - Guards perforated	Entire Building	624	SF	6	\$7,968	
	Lintels - Steel	Entire Building	140	LF	7	\$0	
		-				•	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Windo	ws						
	Windows - Casement Aluminum Double-pane	Entire Building	264	SF	6	\$1,971	
	Windows - Sash Aluminum Double-pane	Entire Building	528	SF	6	\$3,941	
	·						

Building Exterior Subtotal: \$225,016

Building: Addition 3

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	7	\$0	
	Emergency A/C Power - Corridors and Stairs	Entire Building	4,650	SF	6	\$1,396	
	Emergency A/C Power - Lunchrooms	Entire Building / 1st Floor	4,434	SF	6	\$1,649	
	Emergency A/C Power - Students Toilets	Entire Building	1,080	SF	6	\$402	has generator
	Emergency Battery Packs - Corridors and Stairs	Entire Building	14	EA	6	\$2,835	
	Emergency Battery Packs - Lunchrooms	Entire Building / 1st Floor	4	EA	6	\$810	
	Emergency Generator- Outdoor- Natural Gas - 60 - 100 KW	Site - East / East Façade	1	EA	7	\$0	
	Exit Signs - Corridors and Stairs	Entire Building	13	EA	6	\$1,947	school has an electric generator
	Exit Signs - Lunchroom	Entire Building / 1st Floor	5	EA	6	\$749	
	Security System - CCTV	Entire Building	35,298	SF	6	\$10,600	
	Security System - Intrusion Detection	Entire Building	35,298	SF	6	\$9,086	
Main Se	ervice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	7	\$0	
	PA System	Entire Building	35,298	SF	6	\$11,610	connected to main building and 2 additions
ower D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EΑ	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	\$0	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building / Electrical Room	2	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building / Mechanical Room	2	EA	7	\$0	
	Main Distribution Panels - Less than 400 amp	Entire Building	2	EA	7	\$0	
	Carl Overtone Oveletatal					\$44.000	

Electrical System Subtotal: \$41,082

Building: Addition 3



6525 N Hiawatha Ave Chicago, IL 60646

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Ala	rm						
	Fire Alarm Panel	Entire Building / Electrical Room	1	EA	7	\$0	also serves main and 2 addition buildings
	Fire Alarm Strobe Lights	Entire Building	35,298	SF	7	\$0	
	Fire Alarm_System	Entire Building	35,298	SF	7	\$0	
	Fire Pump Controller	Entire Building	1	EA	7	\$0	
Pump F	Room Assembly						
	Fire Pump - Less than 25hp	1st Floor	1	EA	6	\$1,558	
	Jockey Pump	1st Floor	1	EA	6	\$758	
Sprinkl	er System						
	Sprinkler Heads	Entire Building	35,298	SF	7	\$0	
	Sprinkler Piping	Entire Building	35,298	SF	7	\$0	
	Wet Sprinkler System	Entire Building	35,298	SF	7	\$0	
Safty	System Subtotal:					\$2,316	

Building: Addition 3

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Con	ditioning						
	Chemical Pot Feeder	Site - East / Mechanical Room	1	EA	7	\$0	
	Chiller-Air Cooled-Scroll Type-Roof Mounted - 50 - 100 tons	Site - East / Roof	1	EA	7	\$0	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	\$0	serves MDF room
	Glycol Feed	Site - East / Mechanical Room	1	EA	7	\$0	
	Pipes - Chilled Water Pipe- Copper	Site - East / Entire Building	500	LF	7	\$0	
	Pressure Fill System	Site - East / Mechanical Room	1	EA	7	\$0	
Air Han	dling Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	7	\$0	serves lunchroom and offices
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Mechanical Room	1	EA	7	\$0	
	Air Intake	Mechanical Room / 2nd Floor	1	EΑ	7	\$0	
	Air Intake	Mechanical Room / 2nd Floor	1	EA	7	\$0	
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EΑ	7	\$0	
	Indoor Return Fans- Centrifugal Inline - Less than 5000 CFM	Mechanical Room	1	EΑ	7	\$0	
	VAV Box	Mechanical Room / Entire Building	6	EA	7	\$0	
	VAV Box	Mechanical Room / Entire Building	22	EA	7	\$0	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler Systems						
Boiler Auxiliary- Condensing Hot Water - 500 - 1000 HP	Boiler Room	2	EA	7	\$0	
Chemical Pot Feeder	Boiler Room	1	EA	7	\$0	
Condensing- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	2	EA	7	\$0	
Water Fill System	Boiler Room	1	EA	7	\$0	
Heating Devices						
Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	\$1,417	
Unit Heater - Electric	Electrical Room	1	EA	7	\$0	
Unit Heater - Hot Water	Mechanical Room	2	EA	6	\$558	
lechanical Plumbing						
Chilled Water Pump - Less than 10	Mechanical Room	2	EA	6	\$2,222	
Hot Water Pump - Less than 10	Mechanical Room	2	EA	6	\$2,222	
Hydronic Supply and Return - Copper	Entire Building	500	LF	6	\$26,233	
emperature Control						
DDC System	Entire Building	35,298	SF	6	\$20,190	also controls main building and additions
Thermostats - DDC	Entire Building	23	EA	6	\$0	
entilation entil a second entil a se						
Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / Electrical Room	2	EA	6	\$592	also in yard storage room
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	2	EA	6	\$1,185	
Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	5	EA	6	\$2,962	
Type II Exhaust Hood- Warming Kitchen	Entire Building / 1st Floor	1	EA	6	\$920	
Machanical Cratem Cristatal					¢E0 E04	

Mechanical System Subtotal:

\$58,504

Building: Addition 3

Category: Plumbing System

Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Hot Water									
Gas Heater - Less than 150000 BTU/HR	Mechanical Room	2	EA	7	\$0				
Hot Water Storage Tank_Gas - 201 - 500 Gallons	Mechanical Room	1	EA	7	\$0				
Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	35,298	SF	7	\$0				
Domestic Piping-Cold Water Horizontal Lines	Entire Building	35,298	SF	7	\$0				
Domestic Piping-Cold Water Risers	Entire Building	35,298	SF	7	\$0				
Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	35,298	SF	7	\$0				
	Gas Heater - Less than 150000 BTU/HR Hot Water Storage Tank_Gas - 201 - 500 Gallons Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers	Gas Heater - Less than 150000 BTU/HR Mechanical Room Hot Water Storage Tank_Gas - 201 - 500 Gallons Mechanical Room Domestic Piping-Cold Water from Risers to Fixtures Entire Building Domestic Piping-Cold Water Horizontal Lines Entire Building Domestic Piping-Cold Water Risers Entire Building	Gas Heater - Less than 150000 BTU/HR Mechanical Room 2 Hot Water Storage Tank_Gas - 201 - 500 Gallons Mechanical Room 1 Domestic Piping-Cold Water from Risers to Fixtures Entire Building 35,298 Domestic Piping-Cold Water Horizontal Lines Entire Building 35,298 Domestic Piping-Cold Water Risers Entire Building 35,298	Gas Heater - Less than 150000 BTU/HR Mechanical Room 2 EA Hot Water Storage Tank_Gas - 201 - 500 Gallons Mechanical Room 1 EA Domestic Piping-Cold Water from Risers to Fixtures Entire Building 35,298 SF Domestic Piping-Cold Water Horizontal Lines Entire Building 35,298 SF Domestic Piping-Cold Water Risers Entire Building 35,298 SF	Gas Heater - Less than 150000 BTU/HR Mechanical Room 2 EA 7 Hot Water Storage Tank_Gas - 201 - 500 Gallons Mechanical Room 1 EA 7 Domestic Piping-Cold Water from Risers to Fixtures Entire Building 35,298 SF 7 Domestic Piping-Cold Water Horizontal Lines Entire Building 35,298 SF 7 Domestic Piping-Cold Water Risers Entire Building 35,298 SF 7	Gas Heater - Less than 150000 BTU/HR Mechanical Room 2 EA 7 \$0 Hot Water Storage Tank_Gas - 201 - 500 Gallons Mechanical Room 1 EA 7 \$0 Domestic Piping-Cold Water from Risers to Fixtures Entire Building 35,298 SF 7 \$0 Domestic Piping-Cold Water Horizontal Lines Entire Building 35,298 SF 7 \$0 Domestic Piping-Cold Water Risers Entire Building 35,298 SF 7 \$0			



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Piping							
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	35,298	SF	7	\$0	
	Domestic Piping-Hot Water Return Lines	Entire Building	35,298	SF	7	\$0	
	Domestic Piping-Hot Water Return Risers	Entire Building	35,298	SF	7	\$0	
	Sanitary Piping	Entire Building	35,298	SF	7	\$0	
	Storm Piping	Entire Building	35,298	SF	7	\$0	
	Vent Piping	Entire Building	35,298	SF	7	\$0	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	1st Floor	1	EA	7	\$0	
	Pumps - Sump-Simplex	1st Floor	1	EA	7	\$0	
Pluml	oing System Subtotal:					\$0	

Building: Addition 3

Category: Classrooms

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #115 (Office)						
	Ceiling - Lay-in	1st Floor	883	SF	6	\$2,652	
	Doors - Side-lite	1st Floor	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	883	SF	6	\$884	
	Lighting - Lay-in	1st Floor	3	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	15	EΑ	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Walls - Concrete Block	1st Floor	1,190	SF	6	\$3,488	
lassro	oom #116 (Kindergarten)						
	Casework	1st Floor	21	LF	6	\$530	
	Ceiling - Lay-in	1st Floor	915	SF	7	\$0	
	Doors - Side-lite	1st Floor	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	\$0	
	Floor - Tile/Sheet	1st Floor	915	SF	6	\$916	
	Lighting - Lay-in	1st Floor	8	EΑ	7	\$0	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Storage/ Closet	1st Floor	48	SF	6	\$348	
	Walls - Concrete Block	1st Floor	655	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	524	SF	7	\$0	
	2001						



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3 Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #116 (Kindergarten)						
Classro	oom #118 (Kindergarten)						
	Casework	1st Floor	21	LF	6	\$530	
	Ceiling - Lay-in	1st Floor	915	SF	7	\$0	
	Doors - Side-lite	1st Floor	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	915	SF	6	\$916	
	Lighting - Lay-in	1st Floor	8	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Storage/ Closet	1st Floor	48	SF	6	\$348	
	Walls - Concrete Block	1st Floor	655	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	524	SF	7	\$0	
Classro	oom #120 (Other Instructional Use)						
	Casework	2nd Floor	21	LF	6	\$530	
	Ceiling - Lay-in	2nd Floor	915	SF	7	\$0	
	Doors - Side-lite	2nd Floor	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	2nd Floor	915	SF	6	\$916	
	Lighting - Lay-in	2nd Floor	8	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	6	\$514	
	Storage/ Closet	2nd Floor	48	SF	6	\$348	
	Walls - Concrete Block	2nd Floor	915	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	264	SF	7	\$0	
Classro	oom #209 (Regular Classroom)						
	Casework	2nd Floor	21	LF	6	\$530	
	Ceiling - Lay-in	2nd Floor	900	SF	7	\$0	
	Doors - Side-lite	2nd Floor	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	900	SF	6	\$901	
	Lighting - Lay-in	2nd Floor	8	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	6	\$514	
	Storage/ Closet	2nd Floor	48	SF	6	\$348	
	Walls - Concrete Block	2nd Floor	1,179	SF	7	\$0	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3 Category: Classrooms

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
	oom #212 (Special Education)	Location	Quantity	J.III	rwiii.	0031	
J.4551 C	Ceiling - Exposed	2nd Floor	276	SF	6	\$410	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	276	SF	6	\$276	
	Lighting	2nd Floor	4	٥.	7	\$0	
	Marker Board	2nd Floor	5	LF	6	\$107	
	Walls - Concrete Block	2nd Floor	276	SF	7	\$0	
Classro	oom #213 (Science Lab Level 3)						
	Ceiling - Lay-in	2nd Floor	1,279	SF	7	\$0	
	Doors - Side-lite	2nd Floor	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	2nd Floor	1,279	SF	6	\$1,280	
	Gas Line	2nd Floor	1	EA	6	\$509	
	Lighting - Lay-in	2nd Floor	11	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	\$1,982	
	Marker Board	2nd Floor	34	LF	6	\$728	
	Science Lab Elements	2nd Floor	1,279	SF	7	\$0	
	Storage/ Closet	2nd Floor	78	SF	6	\$566	
	Walls - Concrete Block	2nd Floor	1,401	SF	7	\$0	
	Work Sink	2nd Floor	3	EA	6	\$1,137	
Classro	oom #214 (Regular Classroom)						
	Casework	2nd Floor	21	LF	6	\$530	
	Ceiling - Lay-in	2nd Floor	915	SF	7	\$0	
	Doors - Side-lite	2nd Floor	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	2nd Floor	915	SF	6	\$916	
	Lighting - Lay-in	2nd Floor	8	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	6	\$514	
	Storage/ Closet	2nd Floor	48	SF	5	\$774	
	Walls - Concrete Block	2nd Floor	915	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	264	SF	7	\$0	
Classro	oom #216 (Regular Classroom)						
	Casework	2nd Floor	21	LF	6	\$530	
	Ceiling - Lay-in	2nd Floor	915	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	915	SF	6	\$916	
FDOFF		Davis 00 - (45					A D - I 0/0/4

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3 Category: Classrooms

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
_	oom #216 (Regular Classroom)						
	Lighting - Lay-in	2nd Floor	8	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	6	\$514	
	Storage/ Closet	2nd Floor	48	SF	6	\$348	
	Walls - Concrete Block	2nd Floor	655	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	524	SF	7	\$0	
Classro	oom #217 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	1,279	SF	7	\$0	
	Doors - Side-lite	2nd Floor	12	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	1,279	SF	6	\$1,280	
	Lighting - Lay-in	2nd Floor	8	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	6	\$514	
	Walls - Concrete Block	2nd Floor	1,160	SF	7	\$0	
	Wireless System	2nd Floor	1	EA	7	\$0	
Classro	oom #218 (Regular Classroom)						
	Casework	2nd Floor	21	LF	6	\$530	
	Ceiling - Lay-in	2nd Floor	915	SF	7	\$0	
	Doors - Side-lite	2nd Floor	12	SF	7	\$0	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	915	SF	6	\$916	
	Lighting - Lay-in	2nd Floor	8	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	6	\$514	
	Storage/ Closet	2nd Floor	48	SF	6	\$348	
	Walls - Concrete Block	2nd Floor	655	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	524	SF	7	\$0	
Classro	oom #220 (Regular Classroom)						
	Casework	2nd Floor	21	LF	6	\$530	
	Ceiling - Lay-in	2nd Floor	915	SF	7	\$0	
	Doors - Side-lite	2nd Floor	12	SF	6	\$201	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	915	SF	6	\$916	
	Lighting - Lay-in	2nd Floor	8	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	\$0	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3
Category: Classrooms

Group Item - Type	Location	Quantity Unit Rank	Cost Comments
Classroom #220 (Regular Classroom)			
Marker Board	2nd Floor	24 LF 6	\$514
Storage/ Closet	2nd Floor	48 SF 6	\$348
Walls - Concrete Block	2nd Floor	915 SF 7	\$0
Walls - Plaster/Drywall	2nd Floor	264 SF 7	\$0

Classrooms Subtotal: \$38,919

Building: Addition 3

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Ceiling - Lay-in	1st Floor - 112 Office	145	SF	6	\$435	
	Doors - Side-lite	1st Floor - 112 Office	4	SF	6	\$67	
	Doors - Wood Doors inclu hw	1st Floor - 112 Office	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor - 112 Office	145	SF	6	\$145	
	Lighting - Lay-in	1st Floor - 112 Office	2	EA	7	\$0	
	Power Distribution	1st Floor - 112 Office	12	EA	6	\$25,499	
	Walls - Concrete Block	1st Floor - 112 Office	400	SF	6	\$1,173	
	Ceiling - Lay-in	1st Floor - 117C-1 - Kitchen Manager's Office	110	SF	6	\$330	
	Doors - Side-lite	1st Floor - 117C-1 - Kitchen Manager's Office	24	SF	6	\$401	Window to serving line included
	Doors - Steel Doors incl hw	1st Floor - 117C-1 - Kitchen Manager's Office	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor - 117C-1 - Kitchen Manager's Office	110	SF	6	\$233	
	Lighting - Lay-in	1st Floor - 117C-1 - Kitchen Manager's Office	1	EA	7	\$0	
	Power Distribution	1st Floor - 117C-1 - Kitchen Manager's Office	6	EA	6	\$12,749	
	Walls - Concrete Block	1st Floor - 117C-1 - Kitchen Manager's Office	220	SF	6	\$645	
	Ceiling - Lay-in	1st Floor - 117C-5 Engineer's Office	115	SF	6	\$345	
	Doors - Side-lite	1st Floor - 117C-5 Engineer's Office	8	SF	6	\$134	
	Doors - Steel Doors incl hw	1st Floor - 117C-5 Engineer's Office	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor - 117C-5 Engineer's Office	115	SF	6	\$115	
	Lighting - Lay-in	1st Floor - 117C-5 Engineer's Office	2	EA	7	\$0	
	Power Distribution	1st Floor - 117C-5 Engineer's Office	6	EA	6	\$12,749	
	Walls - Concrete Block	1st Floor - 117C-5 Engineer's Office	366	SF	6	\$1,073	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
dminis	strative Suites/Offices						
	Ceiling - Lay-in	Room 112	147	SF	6	\$441	
	Doors - Wood Doors inclu hw	Room 112	1	EA	6	\$301	
	Floor - Tile/Sheet	Room 112	147	SF	6	\$147	
	Lighting - Lay-in	Room 112	2	EA	7	\$0	
	Power Distribution	Room 112	8	EA	7	\$0	
	Walls - Concrete Block	Room 112	415	SF	6	\$1,217	
itchen							
	Ceiling - Lay-in	1st Floor - 117C Kitchen	700	SF	6	\$2,102	
	Doors - Steel Doors incl hw	1st Floor - 117C Kitchen	2	EA	6	\$602	1-Double door
	Floor - Tile Ceramic/ Porcelain	1st Floor - 117C Kitchen	700	SF	6	\$1,481	
	Lighting - Lay-in	1st Floor - 117C Kitchen	14	EA	7	\$0	
	Storage/ Closet	1st Floor - 117C Kitchen	145	SF	6	\$1,051	
	Walls - Concrete Block	1st Floor - 117C Kitchen	985	SF	6	\$2,888	
unch 8	Multipurpose Room						
	Ceiling - Exposed	1st Floor - 117 Cafeteria	2,594	SF	6	\$3,858	
	Ceiling - Lay-in	1st Floor - 117 Cafeteria	1,626	SF	6	\$4,883	3-dropped lay-in ceiling areas / Over serving area
	Ceiling - Plaster/Drywall	1st Floor - 117 Cafeteria	147	SF	6	\$509	
	Doors - Wood Doors inclu hw	1st Floor - 117 Cafeteria	6	EA	6	\$1,806	3-Double doors
	Floor - Tile/Sheet	1st Floor - 117 Cafeteria	3,888	SF	6	\$3,892	
	Lighting - Lay-in	1st Floor - 117 Cafeteria	67	EA	7	\$0	36 - recessed cans at dropped lay-in ceiling areas
	Serving Line	1st Floor - 117 Cafeteria	30	LF	6	\$1,785	
	Storage/ Closet	1st Floor - 117 Cafeteria	105	SF	6	\$761	117A - Storage
	Walls - Concrete Block	1st Floor - 117 Cafeteria	2,306	SF	6	\$6,760	
	Walls - Plaster/Drywall	1st Floor - 117 Cafeteria	405	SF	6	\$1,118	
	Walls - Structural Glazed Tile	1st Floor - 117 Cafeteria	750	SF	6	\$2,360	
DF_ID	F						
	Doors - Wood Doors inclu hw	MDF 212A	1	EA	6	\$301	
	Finishes	MDF 212A	1,015	SF	7	\$0	Painted CMU
echan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	45	SF	6	\$322	113B - Janitor's Closet inside boys entry hallway
	Janitor's Closet	1st Floor	55	SF	6	\$394	117B-Janitor's closet at 117 lunchroom
	Mechanical/ Service Rooms	1st Floor	435	SF	6	\$3,116	117C-6 Electrical Room
	Mechanical/ Service Rooms	1st Floor	195	SF	6	\$1,397	111 - Elevator Machine Room
	Mechanical/ Service Rooms	1st Floor	470	SF	6	\$3,367	114 - Pump Room
	Mechanical/ Service Rooms	1st Floor	120	SF	6	0000	117C-6A-A.T.S inside 117C-6 Electrical Room

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	ical/ Service Rooms						
	Storage Room	1st Floor	140	SF	6	\$1,003	117C-7-Recycling
	Storage Room	1st Floor	147	SF	6		109 - Storage
	Storage Room	1st Floor	150	SF	6		110 - Storage
	Janitor's Closet	2nd Floor	45	SF	6	\$322	Room 211B
	Storage Room	2nd Floor	163	SF	6	\$1,168	Room 213A - Locate in room 213
	Storage Room	2nd Floor	70	SF	6	\$502	Room 210
	Mechanical/ Service Rooms	Mechanical Room 219	3,417	SF	6	\$24,480	
	Storage Room	Yard Storage - Locate outside	221	SF	6	\$1,583	
Restroc	om						
	Accessories	1st Floor - Boys across from classroom 116	310	SF	6	\$2,859	
	Ceiling - Plaster/Drywall	1st Floor - Boys across from classroom 116	310	SF	6	\$1,073	
	Floor Drain	1st Floor - Boys across from classroom 116	1	EA	6	\$1,059	
	Floor - Terrazzo	1st Floor - Boys across from classroom 116	65	SF	6	\$142	At entry hallway
	Floor - Tile Ceramic/ Porcelain	1st Floor - Boys across from classroom 116	245	SF	6	\$519	
	Hand Dryer	1st Floor - Boys across from classroom 116	2	EA	6	\$460	
	Lavatory	1st Floor - Boys across from classroom 116	4	EA	6	\$1,278	
	Lighting - Lay-in	1st Floor - Boys across from classroom 116	7	EA	7	\$0	3-recessed cans at entry hallway
	Partitions	1st Floor - Boys across from classroom 116	2	EA	6	\$594	
	Urinals	1st Floor - Boys across from classroom 116	3	EA	6	\$1,008	
	Walls - Concrete Block	1st Floor - Boys across from classroom 116	144	SF	6	\$422	
	Walls - Structural Glazed Tile	1st Floor - Boys across from classroom 116	495	SF	6	\$1,557	
	Water Closet	1st Floor - Boys across from classroom 116	2	EA	6	\$672	
	Accessories	1st Floor - Girls across from classroom 116	310	SF	6	\$2,859	
	Ceiling - Plaster/Drywall	1st Floor - Girls across from classroom 116	310	SF	6	\$1,073	
	Floor - Terrazzo	1st Floor - Girls across from classroom 116	65	SF	6	\$142	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Floor - Tile Ceramic/ Porcelain	1st Floor - Girls across from classroom 116	245	SF	6	\$519	
	Hand Dryer	1st Floor - Girls across from classroom 116	2	EA	6	\$460	
	Lavatory	1st Floor - Girls across from classroom 116	3	EA	6	\$959	
	Lighting - Lay-in	1st Floor - Girls across from classroom 116	7	EA	7	\$0	3-recessed cans at entry hallway
	Partitions	1st Floor - Girls across from classroom 116	4	EA	6	\$1,188	
	Walls - Concrete Block	1st Floor - Girls across from classroom 116	144	SF	6	\$422	At entry hallway
	Walls - Structural Glazed Tile	1st Floor - Girls across from classroom 116	495	SF	6	\$1,557	
	Water Closet	1st Floor - Girls across from classroom 116	5	EA	6	\$1,680	
	Accessories	1st Floor - Men Staff across from 117C-7 Recycling	57	SF	6	\$526	
	Ceiling - Lay-in	1st Floor - Men Staff across from 117C-7 Recycling	57	SF	6	\$171	
	Doors - Steel Doors incl hw	1st Floor - Men Staff across from 117C-7 Recycling	1	EA	6	\$301	
	Floor Drain	1st Floor - Men Staff across from 117C-7 Recycling	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men Staff across from 117C-7 Recycling	57	SF	6	\$121	
	Hand Dryer	1st Floor - Men Staff across from 117C-7 Recycling	1	EA	6	\$230	
	Lavatory	1st Floor - Men Staff across from 117C-7 Recycling	1	EA	5	\$1,590	
	Lighting - Lay-in	1st Floor - Men Staff across from 117C-7 Recycling	1	EA	7	\$0	
	Walls - Concrete Block	1st Floor - Men Staff across from 117C-7 Recycling	275	SF	6	\$806	
	Water Closet	1st Floor - Men Staff across from 117C-7 Recycling	1	EA	6	\$336	
	Accessories	1st Floor - Women Staff across from 117C-7 Recycling	57	SF	6	\$526	
	Ceiling - Lay-in	1st Floor - Women Staff across from 117C-7 Recycling	57	SF	6	\$171	
	Doors - Steel Doors incl hw	1st Floor - Women Staff across from 117C-7 Recycling	1	EA	6	\$301	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

Group	Item - Type	Location Quantity		Unit	Rank	Rank Cost	Comments	
Restroc	om							
	Floor Drain	1st Floor - Women Staff across from 117C-7 Recycling	1	EA	6	\$1,059		
	Floor - Tile Ceramic/ Porcelain	1st Floor - Women Staff across from 117C-7 Recycling	57	SF	6	\$121		
	Hand Dryer	1st Floor - Women Staff across from 117C-7 Recycling	1	EA	6	\$230		
	Lavatory	1st Floor - Women Staff across from 117C-7 Recycling	1	EA	6	\$320		
	Lighting - Lay-in	1st Floor - Women Staff across from 117C-7 Recycling	1	EA	7	\$0		
	Walls - Concrete Block	1st Floor - Women Staff across from 117C-7 Recycling	275	SF	6	\$806		
	Water Closet	1st Floor - Women Staff across from 117C-7 Recycling	1	EA	6	\$336		
	Accessories	1st Floor - Women Staff across from classroom 116	62	SF	6	\$572		
	Ceiling - Lay-in	1st Floor - Women Staff across from classroom 116	62	SF	6	\$186		
	Doors - Wood Doors inclu hw	1st Floor - Women Staff across from classroom 116	1	EA	6	\$301		
	Floor Drain	1st Floor - Women Staff across from classroom 116	1	EA	6	\$1,059		
	Floor - Tile Ceramic/ Porcelain	1st Floor - Women Staff across from classroom 116	62	SF	6	\$131		
	Hand Dryer	1st Floor - Women Staff across from classroom 116	1	EA	6	\$230		
	Lavatory	1st Floor - Women Staff across from classroom 116	1	EA	6	\$320		
	Lighting - Lay-in	1st Floor - Women Staff across from classroom 116	1	EA	7	\$0		
	Walls - Concrete Block	1st Floor - Women Staff across from classroom 116	260	SF	6	\$762		
	Water Closet	1st Floor - Women Staff across from classroom 116	1	EA	6	\$336		
	Accessories	1st Floor Unisex Restroom	80	SF	6	\$738		
	Ceiling - Lay-in	1st Floor Unisex Restroom	80	SF	6	\$240		
	Doors - Wood Doors inclu hw	1st Floor Unisex Restroom	1	EA	6	\$301		
	Floor Drain	1st Floor Unisex Restroom	1	EA	6	\$1,059		
	Floor - Tile Ceramic/ Porcelain	1st Floor Unisex Restroom	80	SF	6	\$169		
	Hand Dryer	1st Floor Unisex Restroom	1	EA	6	\$230		
	Lavatory	1st Floor Unisex Restroom	1	EA	6	\$320		
	Lighting - Lay-in	1st Floor Unisex Restroom	1	EA	7	\$0		

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

	oup Item - Type Location Q					Cost	Comments
Restro	•		Quantity	•			
	Walls - Concrete Block	1st Floor Unisex Restroom	280	SF	6	\$821	
	Water Closet	1st Floor Unisex Restroom	1	EA	6	\$336	
	Accessories	2nd Floor - Boys across from classroom	31	SF	6	\$286	
	A0003301103	214	31	Oi	O	ΨΖΟΟ	
	Ceiling - Plaster/Drywall	2nd Floor - Boys across from classroom 214	310	SF	6	\$1,073	
	Floor Drain	2nd Floor - Boys across from classroom 214	1	EA	6	\$1,059	
	Floor - Terrazzo	2nd Floor - Boys across from classroom 214	65	SF	6	\$142	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Boys across from classroom 214	245	SF	6	\$519	
	Hand Dryer	2nd Floor - Boys across from classroom 214	2	EA	6	\$460	
	Lavatory	2nd Floor - Boys across from classroom 214	4	EA	6	\$1,278	
	Lighting - Lay-in	2nd Floor - Boys across from classroom 214	7	EA	7	\$0	3-recessed cans at entry hallway
	Partitions	2nd Floor - Boys across from classroom 214	2	EA	6	\$594	
	Urinals	2nd Floor - Boys across from classroom 214	3	EA	6	\$1,008	
	Walls - Concrete Block	2nd Floor - Boys across from classroom 214	144	SF	6	\$422	
	Walls - Structural Glazed Tile	2nd Floor - Boys across from classroom 214	495	SF	6	\$1,557	
	Water Closet	2nd Floor - Boys across from classroom 214	2	EA	6	\$672	
	Accessories	2nd Floor - Girls across from classroom 214	310	SF	6	\$2,859	
	Ceiling - Plaster/Drywall	2nd Floor - Girls across from classroom 214	310	SF	6	\$1,073	
	Floor Drain	2nd Floor - Girls across from classroom 214	1	EA	6	\$1,059	
	Floor - Terrazzo	2nd Floor - Girls across from classroom 214	65	SF	6	\$142	At entry hallway
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Girls across from classroom 214	245	SF	6	\$519	
	Hand Dryer	2nd Floor - Girls across from classroom 214	2	EA	6	\$460	
	Lavatory	2nd Floor - Girls across from classroom 214	4	EA	6	\$1,278	

6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	om						
	Lighting - Lay-in	2nd Floor - Girls across from classroom 214	7	EA	7	\$0	3-recessed cans at entry hallway
	Partitions	2nd Floor - Girls across from classroom 214	4	EA	6	\$1,188	
	Walls - Concrete Block	2nd Floor - Girls across from classroom 214	144	SF	6	\$422	
	Walls - Structural Glazed Tile	2nd Floor - Girls across from classroom 214	495	SF	6	\$1,557	
	Water Closet	2nd Floor - Girls across from classroom 214	5	EA	6	\$1,680	
	Accessories	2nd Floor - Men Staff across from classroom 214	61	SF	6	\$563	
	Ceiling - Lay-in	2nd Floor - Men Staff across from classroom 214	61	SF	6	\$183	
	Doors - Wood Doors inclu hw	2nd Floor - Men Staff across from classroom 214	1	EA	6	\$301	
	Floor Drain	2nd Floor - Men Staff across from classroom 214	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Men Staff across from classroom 214	61	SF	6	\$129	
	Hand Dryer	2nd Floor - Men Staff across from classroom 214	1	EA	6	\$230	
	Lavatory	2nd Floor - Men Staff across from classroom 214	1	EA	6	\$320	
	Lighting - Lay-in	2nd Floor - Men Staff across from classroom 214	1	EA	7	\$0	
	Walls - Concrete Block	2nd Floor - Men Staff across from classroom 214	250	SF	6	\$733	
	Water Closet	2nd Floor - Men Staff across from classroom 214	1	EA	6	\$336	
	Accessories	2nd Floor Unisex Restroom	80	SF	6	\$738	
	Ceiling - Lay-in	2nd Floor Unisex Restroom	80	SF	6	\$240	
	Doors - Wood Doors inclu hw	2nd Floor Unisex Restroom	1	EA	6	\$301	
	Floor Drain	2nd Floor Unisex Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Unisex Restroom	80	SF	6	\$169	
	Hand Dryer	2nd Floor Unisex Restroom	1	EA	6	\$230	
	Lavatory	2nd Floor Unisex Restroom	1	EA	6	\$320	
	Lighting - Lay-in	2nd Floor Unisex Restroom	1	EA	7	\$0	
	Walls - Concrete Block	2nd Floor Unisex Restroom	280	SF	6	\$821	
	Water Closet	2nd Floor Unisex Restroom	1	EA	6	\$336	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

Category: Rooms (Other Than Classrooms)

Group Item - Type Location Quantity Unit Rank Cost Comments

Rooms (Other Than Classrooms) Subtotal: \$204,900

Building: Addition 3

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Ceiling - Lay-in	1st Floor	3,979	SF	6	\$11,949	
	Ceiling - Plaster/Drywall	1st Floor	465	SF	6	\$2,879	
	Doors - Side-lite	1st Floor	135	EA	7	\$0	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	\$1,204	
	Doors - Store Front	1st Floor	6	EA	6	\$7,249	
	Doors - Transom Window	1st Floor	24	EA	7	\$0	
	Doors - Wood Doors include hw	1st Floor	6	EA	6	\$1,806	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	6	\$827	
	Floor - Terrazzo	1st Floor	4,052	SF	6	\$34,013	
	Floor - Tile/Sheet	1st Floor	250	SF	6	\$136	
	Lighting - Lay-in	1st Floor	43	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	5	EA	7	\$0	
	Stairs - Terrazzo	1st Floor	16	LF	6	\$148	
	Student Lockers - One Tier	1st Floor	100	EA	6	\$9,284	
	Walls - Concrete Block	1st Floor	6,418	SF	7	\$0	
	Walls - Masonry	1st Floor	120	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	150	SF	6	\$665	At gym stage door
	Walls - Structural Glazed Tile	1st Floor	250	SF	6	\$787	Location: Corridor wall base perimeter
	Ceiling - Exposed	2nd Floor	1,252	SF	6	\$1,862	At open ceiling
	Ceiling - Lay-in	2nd Floor	1,838	SF	6	\$5,520	
	Ceiling - Plaster/Drywall	2nd Floor	150	SF	6	\$929	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	6	\$1,204	
	Doors - Wood Doors include hw	2nd Floor	6	EA	6	\$1,806	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	6	\$827	
	Floor - Terrazzo	2nd Floor	3,240	SF	6	\$27,197	
	Lighting - Lay-in	2nd Floor	32	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	\$0	
	Lighting - Wall Mounted	2nd Floor	5	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	195	EA	6	\$18,103	
	Walls - Concrete Block	2nd Floor	4,851	SF	6	\$14,221	



6525 N Hiawatha Ave Chicago, IL 60646

Building: Addition 3

Category: Building Interior

curity Cameras curity Cameras curity Cameras lling - Lay-in or - Terrazzo ndrails hting - Wall Mounted	2nd Floor Entire Building Entire Building Stair C - SW / 2nd Floor Stair C - SW Stair C - SW	1,050 8 24 230 70	SF EA EA SF SF	6 6 6	\$4,655 \$1,552 \$4,657 \$691	
curity Cameras curity Cameras lling - Lay-in or - Terrazzo ndrails	Entire Building Entire Building Stair C - SW / 2nd Floor Stair C - SW Stair C - SW	230 70	EA EA	6	\$1,552 \$4,657	
curity Cameras ling - Lay-in or - Terrazzo ndrails	Entire Building Stair C - SW / 2nd Floor Stair C - SW Stair C - SW	24 230 70	EA SF	6	\$4,657	
curity Cameras ling - Lay-in or - Terrazzo ndrails	Entire Building Stair C - SW / 2nd Floor Stair C - SW Stair C - SW	24 230 70	EA SF	6	\$4,657	
lling - Lay-in or - Terrazzo ndrails	Stair C - SW / 2nd Floor Stair C - SW Stair C - SW	230 70	SF			
or - Terrazzo ndrails	Stair C - SW Stair C - SW	70	_	6	\$691	
or - Terrazzo ndrails	Stair C - SW Stair C - SW	70	_	6	\$691	
ndrails	Stair C - SW		SF			
		00	•	6	\$588	
hting - Wall Mounted		90	LF	6	\$780	16' of handrails at 1st floor 7-steps included
	Stair C - SW	4	EA	7	\$0	
irs - Terrazzo	Stair C - SW	28	LF	6	\$260	
alls - Concrete Block	Stair C - SW	885	SF	6	\$2,594	
iling - Lay-in	Stair D - NW	300	SF	6	\$901	
or - Terrazzo	Stair D - NW	140	SF	6	\$1,175	
ndrails	Stair D - NW	90	LF	6	\$780	
hting - Wall Mounted	Stair D - NW	4	EA	7	\$0	
irs - Terrazzo	Stair D - NW	36	LF	6	\$334	
alls - Concrete Block	Stair D - NW	1,680	SF	6	\$4,925	
nveyance						
vator - Lula	South East	1	EA	6	\$11,667	
ilir or nc ht irs alls	ng - Lay-in - Terrazzo Irails ing - Wall Mounted s - Terrazzo s - Concrete Block eyance	ng - Lay-in Stair D - NW - Terrazzo Stair D - NW Irails Stair D - NW sing - Wall Mounted Stair D - NW s - Terrazzo Stair D - NW s - Concrete Block Stair D - NW eyance South East	ang - Lay-in Stair D - NW 300 - Terrazzo Stair D - NW 140 Irails Stair D - NW 90 sing - Wall Mounted Stair D - NW 4 s - Terrazzo Stair D - NW 36 s - Concrete Block Stair D - NW 1,680 eyance ator - Lula South East 1	ng - Lay-in Stair D - NW 300 SF - Terrazzo Stair D - NW 140 SF Irails Stair D - NW 90 LF ing - Wall Mounted Stair D - NW 4 EA is - Terrazzo Stair D - NW 36 LF is - Concrete Block Stair D - NW 1,680 SF eyance South East 1 EA	ng - Lay-in Stair D - NW 300 SF 6 - Terrazzo Stair D - NW 140 SF 6 Irails Stair D - NW 90 LF 6 ing - Wall Mounted Stair D - NW 4 EA 7 is - Terrazzo Stair D - NW 36 LF 6 is - Concrete Block Stair D - NW 1,680 SF 6 eyance ator - Lula South East 1 EA 6	ng - Lay-in Stair D - NW 300 SF 6 \$901 - Terrazzo Stair D - NW 140 SF 6 \$1,175 Irails Stair D - NW 90 LF 6 \$780 ing - Wall Mounted Stair D - NW 4 EA 7 \$0 is - Terrazzo Stair D - NW 36 LF 6 \$334 is - Concrete Block Stair D - NW 1,680 SF 6 \$4,925 eyance ator - Lula South East 1 EA 6 \$11,667

Total Building Cost \$748,909

SITE

Category: Site

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Athletic						
Surface - Asphalt	N Basketball Court	2,112	SF	6	\$5,104	
Civil/Drainage						
Civil/ Drainage - Bioswale	Entire Site	13,620	SF	6	\$81,802	Location: N and S Site
Civil/ Drainage - Catch Basin	Entire Site	8	EA	7	\$0	
Civil/ Drainage - Site Manhole	Entire Site	2	EA	7	\$0	

6525 N Hiawatha Ave Chicago, IL 60646

SITE

Category: Site

Campus Total ^{2 3}

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fencing							
	Fencing - New Standard Ornamental	Entire Site	1,236	LF	7	\$0	
Landsc	аре						
	Benches	Entire Site	17	EA	7	\$0	
	Landscape - Grass	Entire Site	12,430	SF	6	\$10,309	
	Landscape - Hardscape- Concrete	Entire Site	6,595	SF	7	\$0	
	Parkway trees	Entire Site	28	EA	7	\$0	
	Planting Beds/ Area	Entire Site	1,764	SF	6	\$2,901	
	Retaining Wall - Concrete	Entire Site	621	SF	7	\$0	
	Trash Receptacles	Entire Site	2	EA	6	\$625	
Parking	Lot						
	Concrete Curbs	E Parking Lot	546	LF	7	\$0	
	Interior Plantings	E Parking Lot	94	LF	7	\$0	
	Lighting - Pole Mounted	E Parking Lot	5	EA	7	\$0	
	Surface - Asphalt	E Parking Lot	12,780	SF	6	\$30,885	
	Trash Compactor	E Parking Lot	1	EA	7	\$0	
	Vehicular Screening	E Parking Lot	213	LF	7	\$0	
Playgro	und						
	Equipment - Pre K 3-5	NE Playground	1	EA	7	\$0	
	Surface - Poured Surface	NE Playground	4,808	SF	7	\$0	
Sidewa	lks						
	Sidewalks - Internal Walks	Entire Site	1,425	LF	7	\$0	
	Sidewalks - Perimeter Sidewalks	Entire Site	6,383	SF	7	\$0	
Signage	•						
	Flag Pole - Flag Pole	Entire Site / South West	1	EA	7	\$0	
	Monument - Building Mounted Cut Letter Sign	Entire Site / South East	1	EA	7	\$0	
Site S	ubtotal:					\$131,626	
Total	Site Cost					\$131,626	

\$3,469,912



6525 N Hiawatha Ave Chicago, IL 60646

- ¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.
- ² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.
- ³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



6525 N Hiawatha Ave Chicago, IL 60646

Classroom Summary

Current Usage	Intended Usage	Room	Room	Floor Plan	Area (SF)	Voice	Data	Elect.	Glazed	Operable	Noise	Window	Power	Smart-
Current Osage	interided Osage	Location	Number	Room Number	Area (SF)	Outlets	Outlets	Outlets	Window Area	Window Area	Level	Stop	Strip	Board
Main						!	-	1				!		1
Other Instructional Use	Regular Classroom	1st Floor	106	106	820	1	5	14	182	56	50	N	Υ	N
Other Instructional Use	Regular Classroom	2nd Floor	205	205	1,062	1	8	24	234	72	50	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	715	1	5	14	156	48	50	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	105	105	686	1	2	8	156	48	40	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	686	1	2	8	156	48	40	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	715	1	5	14	156	48	50	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	715	1	5	14	156	48	50	N	Υ	N
Addition 1														
Music Room	Regular Classroom	2nd Floor	108	108	715	1	5	4	150	48	50	N	N	N
Office	Regular Classroom	1st Floor	107	107	325	1	2	8	75	24	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	325	1	2	4	75	24	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	715	1	5	14	150	48	40	N	Υ	N
Addition 2														-
Regular Classroom	Regular Classroom	1st Floor	101	101	686	1	2	8	156	48	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	102	102	715	1	5	14	156	48	50	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	686	1	2	8	156	48	40	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	715	1	5	14	156	48	50	N	Υ	N
Addition 3														
Computer Lab	Computer Lab	2nd Floor	217	215	1,279	1	30	50	120	27	40	Υ	Υ	N
Kindergarten	Regular Classroom	1st Floor	116	116	915	1	7	20	75	27	50	Υ	Υ	N
Kindergarten	Regular Classroom	1st Floor	118	118	915	1	7	20	75	27	50	Υ	Υ	N
Office	Regular Classroom	1st Floor	115	115	883	1	7	20	75	25	50	Υ	Υ	N
Other Instructional Use	Regular Classroom	2nd Floor	120	NA	915	1	7	20	75	27	50	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	900	1	2	20	120	27	40	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	915	1	7	20	120	27	50	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	915	1	7	20	150	5	50	Υ	Υ	N
Regular Classroom	Science Classroom	2nd Floor	218	218	915	1	7	20	120	27	50	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	220	220	915	1	7	20	120	27	50	Υ	Υ	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	213	NA`	1,279	1	12	26	160	36	40	Υ	Υ	N
Special Education	Store Room	2nd Floor	212	NA	276	0		2			40	N	Υ	N