4540 N Hamlin Ave Chicago, IL 60625

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1911	3	130,162	\$8,301,200
Addition	1993	1	7,809	\$490,539
SITE				\$464,802
Campus Total	·		137,971	\$9,256,541

Building: Main

Category: Building Exterior

Carog	ory. Bunding Exterior						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran	ce						
	Entrance Control - Audio and Video	#1 E	1	EΑ	6	\$702	
	Entrance Control - Audio and Video	#12 W	1	EΑ	6	\$702	
	Entrance Control - Audio and Video	#9 W	1	EΑ	6	\$702	
	Exterior Doors - Exterior FRP Door	#1 E	3	EΑ	6	\$1,894	
	Exterior Doors - Exterior FRP Door	#12 W	4	EΑ	6	\$2,526	
	Exterior Doors - Exterior FRP Door	#14 Exit N	3	EΑ	6	\$1,894	
	Exterior Doors - Exterior FRP Door	#9 W	4	EΑ	6	\$2,526	
	Exterior Doors - Exterior Steel Door	#10 W	1	EΑ	6	\$481	
	Exterior Doors - Exterior Steel Door	#11 W	1	EΑ	5	\$1,341	
	Exterior Doors - Exterior Steel Door	#2 E	4	EΑ	6	\$1,922	
	Exterior Doors - Exterior Steel Door	#6 E	4	EΑ	6	\$1,922	
	Exterior Doors - Exterior Steel Door	#7 Exit E	3	EΑ	6	\$1,442	
	Exterior Doors - Exterior Steel Door	#8 Exit S	3	EΑ	6	\$1,442	
	Exterior Doors - Overhead Rolling/ Garage Door	#11.5 W	1	EA	6	\$1,433	
	Exterior Doors - Transom Lite	#1 E	3	EA	6	\$940	
	Exterior Doors - Transom Lite	#10 W	2	EA	6	\$627	
	Exterior Doors - Transom Lite	#14 Exit N	3	EA	6	\$940	
	Exterior Doors - Transom Lite	#2 E	4	EA	5	\$3,287	
	Exterior Doors - Transom Lite	#6 E	32	EA	6	\$10,026	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entran		Location	Quantity	Oilit	Italik	0031	Commence
Lillian	Exterior Doors - Transom Lite	#7 Exit E	3	EA	6	\$940	
	Exterior Doors - Transom Lite	#8 Exit S	3	EA	6	\$940	
	Exterior Stairs - Concrete	#8 EXIT 3	25	LF	6	\$2,044	
	Exterior Stairs - Concrete	#2 E #7 Exit E	25	LF	5	\$986	
	Exterior Stairs - Concrete	#7 EXILE #8 Exit S	9	LF	6	\$736	
	Exterior Stairs - Concrete	#6 EXIL S #9 W	12	LF	6	\$730 \$981	
	Exterior Stairs - Concrete	#9 **	12	LF	O	φθοι	
Fire Es	scape						
	Fire Escape	Gym at north facade	67	LF	6	\$42,328	
Founda	ation						
	Foundation - Concrete	Entire Building	1,255	LF	7	\$0	
	Superstructure - Steel with Clay Tile Arch	Entire Building	130,162	SF	7	\$0	
Lightin	ng						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building / Roof	12	EA	6	\$6,438	
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	\$2,887	Auditorium entrance
Roof S	system						
	Chimney - Brick Chimney- Concrete/ Mortar Liner	West Low Roof	45	LF	6	\$42,961	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	West Low Roof	15	LF	6	\$14,320	
	Coping - Stone	East Low Roof	342	LF	5	\$37,452	Need tuck pointing
	Coping - Stone	Main Roof	1,302	LF	5	\$142,581	Need tuck pointing
	Coping - Stone	West Low Roof	226	LF	5	\$24,749	Tuck pointing
	Downspouts - Exterior Downspouts	East Low Roof	60	LF	6	\$1,994	
	Downspouts - Exterior Downspouts	Main Roof	320	LF	6	\$10,635	
	Downspouts - Exterior Downspouts	West Low Roof	46	LF	6	\$1,529	
	Parapet - 16" - 30" Height	Main Roof	596	LF	5	\$103,117	Need tuck pointing
	Parapet - 16" - 30" Height	West Low Roof	226	LF	6	\$9,030	
	Parapet - Parapet < 16" Height	East Low Roof	342	LF	5	\$31,637	Need tuck pointing
	Parapet - Parapet < 16" Height	Main Roof	596	LF	5	\$55,134	Need tuck pointing
	Parapet - Parapet > 30"	Main Roof	110	LF	5	\$27,139	Need tuck pointing
	Roof Structure - Steel with Clay Tile Arch	East Low Roof	9,138	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	40,338	SF	7	\$0	
	Roof Structure - Steel with Clay Tile Arch	West Low Roof	3,942	SF	6	\$71,027	
	Roof - Asphalt Gravel Ballast	East Low Roof	8,315	SF	6	\$84,541	
	Roof - Asphalt Gravel Ballast	Main Roof	40,338	SF	6	\$410,129	
	Roof - Asphalt Gravel Ballast	West Low Roof	3,942	SF	5	\$93,068	
	Roof - Metal	East Low Roof	823	SF	5	\$22,679	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Walls							
	Cornice - Cast Stone	Entire Building / Lower Roofs	368	LF	6	\$12,761	
	Cornice - Metal Projecting	Entire Building	1,467	LF	6	\$50,872	
	Exterior Walls - Brick	Entire Building	33,430	SF	6	\$261,493	
	Exterior Walls - Brick	Entire Building	33,430	SF	5	\$706,556	Need tuck pointing
	Exterior Walls - Stone-Cast	Entire Building	5,040	SF	6	\$33,874	
	Exterior Walls - Stone-Cast	Entire Building / 1st Floor	3,915	SF	5	\$62,479	Need tuck pointing
Windov	vs						
	Guard - Guards perforated	Entire Building / 1st Floor	5,259	SF	6	\$67,157	
	Guard - Guards wire guard	Entire Building	362	SF	6	\$4,623	Gym
	Guard - Guards wire guard	Entire Building / Boiler Room	25	SF	4	\$1,958	Damaged
	Lintels - Steel	Entire Building	1,308	LF	6	\$37,970	
	Lintels - Stone	Entire Building / 1st Floor	443	LF	6	\$0	
	Skylite - Glass Single-Pane	Entire Building / Boiler Room	152	SF	6	\$3,632	
	Storefront Windows	Entire Building	128	SF	6	\$1,435	
	Windows - Sash Aluminum Double-pane	Entire Building	1,618	SF	5	\$87,159	Not operating well
	Windows - Sash Aluminum Double-pane	Entire Building	14,566	SF	6	\$108,729	
	Windows - Wood- Single-pane	Entire Building / Boiler Room	25	SF	4	\$3,281	

Building Exterior Subtotal:

\$2,722,729

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Automatic Transfer Switch	Electrical Room	1	EA	4	\$8,200	Transfer switch has over 40 years of service and shows signs of deterioration.
	Emergency A/C Power - Corridors and Stairs	Entire Building	23,976	SF	6	\$7,200	
	Emergency A/C Power - Gym	Entire Building / 3rd Floor	5,378	SF	6	\$2,000	
	Emergency A/C Power - Multipurpose Room	Entire Building / 1st Floor	7,015	SF	6	\$2,608	
	Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	2	EΑ	6	\$405	
	Emergency Battery Packs - Multipurpose Room	Entire Building / 1st Floor	2	EΑ	6	\$405	
	Exit Signs - Corridors and Stairs	Entire Building	38	EA	2	\$20,729	Exit signs have no emergency backup power source.
	Exit Signs - Gym	Entire Building / 3rd Floor	2	EA	2	\$1,157	Exit signs have no emergency backup power source.
	Exit Signs - Multipurpose Room	Entire Building / 1st Floor	8	EA	2	\$4,364	Exit signs have no emergency backup power source.



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ncy System						
	Security System - Intrusion Detection	Entire Building	130,162	SF	5	\$130,292	detectors only
Main S	ervice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	\$2,921	Secondary service from the utility company.
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	\$10,867	
	PA System	Entire Building	130,162	SF	5	\$89,343	Serves main and addition but service from Main to Addition is not working. Control console located in main.
Power I	Distribution						
	Lighting and Power Panels - 100 A	Entire Building / 1st Floor	1	EA	4	\$4,849	Emergency fuse panel has over 40 years of service and is significantly deteriorated.
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	\$0	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	4	\$9,699	Panels have over 40 years of service and are significantly deteriorated.
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	\$598	
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	4	\$6,578	Emergency fuse panel has over 40 years of service and is significantly deteriorated.
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	4	\$65,778	Panels have over 40 years of service and are significantly deteriorated.
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Entire Building / Electrical Room	2	EA	4	\$27,388	Panels have over 40 years of service and are significantly deteriorated.
	Main Distribution Panels - Greater than 600 amp	Entire Building / Electrical Room	3	EA	6	\$2,191	
	Transformers - 120/240 - 120/208	Entire Building / Electrical Room	2	EA	4	\$58,094	Transformers have more than 30 years of service and show signs of substantial deterioration.

Electrical System Subtotal: \$455,664

Building: Main

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire A	arm						
	Fire Alarm Panel	Entire Building / Mechanical Room	1	EA	3	\$49,477	Panel has over 45 years of service. Obsolete technology.
	Fire Alarm Strobe Lights	Entire Building	130,162	SF	4	\$176,825	
	Fire Alarm_System	Entire Building	130,162	SF	4	\$258,723	System has 45 years of service and can not be upgraded to support strobe lights



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Safty System

Group Item - Type Location Quantity Unit Rank Cost Comments

Safty System Subtotal: \$485,025

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	4	\$68,120	AHU-3 Serves Multipurpose Gym/Auditorium only
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	\$55,649	AHU North
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	5	\$55,649	AHU South
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000	Mechanical Room	1	EA	5	\$66,438	AHU-2
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000	Mechanical Room	1	EA	5	\$66,438	AHU-1
	Air Intake	Mechanical Room / East Façade	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / East Façade	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / Roof	1	EA	3	\$17,616	Intake shared between AHU-1, -2 & -3. Intake hood is makeskift and does not provide sufficient outside air flow for all three AHU's combined.
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	4	\$36,420	Housing walls are deteriorated and not sealed. pre- heat coils are leaking. No filter frames installed.
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	4	\$36,420	Housing walls are deteriorated and not sealed. preheat coils are leaking. No filter frames installed.
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	4	\$39,696	Housing walls are deteriorated and not sealed. No filter frames installed.
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	4	\$39,696	Housing walls are deteriorated and not sealed. No filter frames installed.
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	4	\$29,763	Housing walls are deteriorated and not sealed. preheat coils are leaking. No filter frames installed.
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room / Plenum	7	EA	4	\$60,409	Sheet metal and supports are deteriorated. Zone dampers and coils are not working properly. Classroom temperatures cannot be maintained as designed.
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room / Plenum	7	EA	4	\$60,409	Sheet metal and supports are deteriorated. Zone dampers and coils are not working properly. Classroom temperatures cannot be maintained as designed.
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	80	LF	7	\$0	Needs to be sealed
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	20	LF	7	\$0	Return duct work has large holes through plenum walls which allows heated air flow to circulate directly into the outside air intake resulting in overheated service.



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Mechanical System

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	dling Systems	Location	Quantity	Jint	Nank	CUSI	Commence
All Hall	<u> </u>	Mechanical Room / Plenum	100	LF	7	\$0	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	20	LF	7		Deturn duct work has large helps through planum
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Wechanical Room / Pienum	20	LF	/	\$0	Return duct work has large holes through plenum walls which allows heated air flow to circulate directly into the outside air intake resulting in overheated service.
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Plenum	100	LF	7	\$0	
	Zone Dampers	Mechanical Room / Plenum	16	EA	4	\$76,683	Dampers are rusted and partially open. Temperatures in the spaces served cannot be maintained in severe weather conditions. Dampers are not cost effective for repairs.
	Zone Dampers	Mechanical Room / Plenum	15	EA	4	\$71,890	Dampers are rusted and partially open. Temperatures in the spaces served cannot be maintained in severe weather conditions. Dampers are not cost effective for repairs.
	Zone Dampers	Mechanical Room / Plenum	21	EA	4	\$100,646	Dampers are rusted and partially open. Temperatures in the spaces served cannot be maintained in severe weather conditions. Dampers are not cost effective for repairs.
	Zone Dampers	Mechanical Room / Plenum	22	EA	4	\$105,439	Dampers are rusted and partially open. Temperatures in the spaces served cannot be maintained in severe weather conditions. Dampers are not cost effective for repairs.
Boiler S	Systems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	6	\$5,091	
	Chemical Feeder	Boiler Room / Mechanical Room	1	EA	6	\$1,078	
	Combustion Dampers	Boiler Room	2	EA	6	\$818	
	Condensate Pump	Boiler Room / Mechanical Room	4	EA	6	\$8,084	
	Feed Water Pumps and Tank	Boiler Room / Mechanical Room	1	EA	6	\$2,545	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	6	\$5,091	
	Piping - Condensate Pipe- Steel	Boiler Room / Entire Building	700	LF	5	\$9,169	Piping is old, deteriorated and has several clamps installed
	Piping - Steam Pipe- Steel	Boiler Room / Entire Building	700	LF	5	\$10,490	Piping is old, deteriorated and has several clamps installed
	Steam Traps	Boiler Room / Entire Building	119	EA	5	\$156,473	
Heating	Devices						
	Fin Tube - Steam	Entire Building	66	LF	6	\$623	
	Radiators - Steam	Entire Building	22	EA	5	\$36,857	Manual control.
	Unit Heater - Steam	Entire Building	2	EA	6	\$556	
	Wall Heater - Electric	Entire Building	6	EA	5	\$3,220	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Heating	Devices						
	Wall Heater - Electric	Entire Building	9	EA	6	\$1,250	
Tempe	rature Control						
	Pneumatic System	Entire Building	130,162	SF	4	\$677,519	No manufacturer listed on panels. A large number of actuators are not working and are adjusted manually. Sensors are not responding. Controls are in manual mode. Pneumatic lines are leaking.
	Thermostats - Pneumatic	Entire Building	76	EA	4	\$56,030	Thermostats are very old, deteriorated and not working properly.
Ventila	tion						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building / 1st Floor	1	EA	6	\$296	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	4	EA	6	\$2,370	

Mechanical System Subtotal:

\$1,977,063

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wa	ter						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	\$310	
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	130,162	SF	6	\$26,058	Piping is old & deteriorated
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	130,162	SF	6	\$31,642	Piping is old & deteriorated
	Domestic Piping-Cold Water Risers	Entire Building	130,162	SF	6	\$24,197	Piping is old & deteriorated
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	130,162	SF	6	\$20,474	Piping is old & deteriorated
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	130,162	SF	6	\$24,197	Piping is old & deteriorated
	Domestic Piping-Hot Water Return Lines	Entire Building	130,162	SF	6	\$18,613	Piping is old & deteriorated
	Domestic Piping-Hot Water Return Risers	Entire Building	130,162	SF	6	\$18,613	Piping is old & deteriorated
	Sanitary Piping	Entire Building	130,162	SF	6	\$119,124	Piping is old & deteriorated
	Storm Piping	Entire Building	130,162	SF	6	\$113,540	
	Vent Piping	Entire Building	130,162	SF	6	\$87,482	Piping is old & deteriorated
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	6	\$1,446	
	Pumps - Sump-Simplex	Basement / Plenum	2	EA	6	\$1,490	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Plumbing System

Group Item - Type Location Quantity Unit Rank Cost Comments

Plumbing System Subtotal: \$487,188

Building: Main

oup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ssroom #100 (Regular Classroom)						
AC Units	1st Floor	1	EA	6	\$496	
Casework	1st Floor	14	LF	6	\$354	
Ceiling - Plaster/Drywall	1st Floor	1,180	SF	6	\$4,084	
Doors - Transom Window	1st Floor	12	SF	6	\$203	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Wood	1st Floor	1,180	SF	6	\$8,319	
Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
Marker Board	1st Floor	24	LF	6	\$514	
Walls - Plaster/Drywall	1st Floor	1,643	SF	6	\$4,535	
ssroom #101 (Pre School)						
AC Units	1st Floor	1	EA	6	\$496	
Casework	1st Floor	7	LF	6	\$177	
Ceiling - Plaster/Drywall	1st Floor	923	SF	6	\$3,194	
Doors - Transom Window	1st Floor	12	SF	6	\$203	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Wood	1st Floor	923	SF	6	\$6,507	
Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
Walls - Plaster/Drywall	1st Floor	1,440	SF	6	\$3,974	
ssroom #102 (Regular Classroom)						
AC Units	1st Floor	1	EA	6	\$496	
Casework	1st Floor	34	LF	6	\$859	
Ceiling - Plaster/Drywall	1st Floor	985	SF	6	\$3,409	
Chalk Board	1st Floor	8	LF	4	\$734	
Doors - Transom Window	1st Floor	12	SF	6	\$203	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Tile/Sheet	1st Floor	985	SF	6	\$986	
Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
Marker Board	1st Floor	8	LF	6	\$171	
Walls - Plaster/Drywall	1st Floor	1,541	SF	6	\$4,253	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	oom #108 (Regular Classroom)	Location	Quantity	Oilit	Italik	COSI	Comments
Ciassi	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	839	SF	6	\$2,903	
	Doors - Transom Window	1st Floor	12	SF	6	\$2,903	
	Doors - Wood Doors inclu hw			EA		\$203 \$301	
	Floor - Tile/Sheet	1st Floor 1st Floor	1	SF	6		
			839	_	6	\$840	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Walls - Plaster/Drywall	1st Floor	1,434	SF	6	\$3,958	
Classro	oom #112 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	20	LF	6	\$505	
	Ceiling - Plaster/Drywall	1st Floor	923	SF	6	\$3,194	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	923	SF	6	\$924	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	6	\$343	
	Walls - Metal Panel	1st Floor	1,514	SF	6	\$11,301	
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	oom #113 (Regular Classroom)						
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	839	SF	6	\$2,903	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	839	SF	6	\$840	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Walls - Plaster/Drywall	1st Floor	1,434	SF	6	\$3,958	
Classro	oom #114 (Regular Classroom)						
Jidooik	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	28	LF	6	\$707	
	Ceiling - Plaster/Drywall	1st Floor	923	SF	6	\$3,194	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
					-	4001	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

	Nome Time	Lacation	0	Lle-14	Dani	01	Comments
•	Item - Type	Location	Quantity	Unit	Kank	Cost	Comments
Classro	oom #114 (Regular Classroom)	Ast Flores		~-		*	
	Floor - Tile/Sheet	1st Floor	923	SF	6	\$924	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	28	LF	6	\$600	
	Walls - Plaster/Drywall	1st Floor	1,514	SF	6	\$4,178	
Classro	oom #115 (Regular Classroom)						
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	839	SF	6	\$2,903	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	839	SF	6	\$840	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Walls - Plaster/Drywall	1st Floor	1,434	SF	6	\$3,958	
Classro	oom #116 (Regular Classroom)						
	AC Units	1st Floor	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	1st Floor	761	SF	6	\$2,634	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	761	SF	6	\$762	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	\$1,735	
	Marker Board	1st Floor	20	LF	6	\$428	
	Walls - Plaster/Drywall	1st Floor	1,390	SF	6	\$3,836	
Classro	oom #117 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	1st Floor	985	SF	6	\$3,409	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	985	SF	6	\$986	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Walls - Plaster/Drywall	1st Floor	1,541	SF	6	\$4,253	
Classro	oom #118 (Kindergarten)						
	AC Units	1st Floor	1	EA	6	\$496	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
_	oom #118 (Kindergarten)						
	Casework	1st Floor	28	LF	6	\$707	
	Ceiling - Plaster/Drywall	1st Floor	1,180	SF	6	\$4,084	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	1,180	SF	6	\$8,319	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Walls - Plaster/Drywall	1st Floor	1,878	SF	6	\$5,183	
Classro	oom #119 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	1st Floor	923	SF	6	\$3,194	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	923	SF	6	\$924	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	24	LF	6	\$514	
	Walls - Plaster/Drywall	1st Floor	1,440	SF	6	\$3,974	
Classro	oom #120 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	28	LF	6	\$707	
	Ceiling - Plaster/Drywall	1st Floor	823	SF	6	\$2,848	
	Doors - Transom Window	1st Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	823	SF	6	\$5,802	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	\$0	
	Marker Board	1st Floor	20	LF	6	\$428	
	Walls - Plaster/Drywall	1st Floor	1,410	SF	6	\$3,891	
Classro	oom #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	2	SF	5	\$25	Peeling paint
	Ceiling - Plaster/Drywall	2nd Floor	915	SF	6	\$3,166	
	Ceiling - Plaster/Drywall	2nd Floor	2	SF	5	\$25	Peeling paint
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #200 (Regular Classroom)						
	Floor - Tile/Sheet	2nd Floor	917	SF	6	\$918	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	36	LF	6	\$771	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,735	SF	6	\$4,788	
Classro	oom #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	914	SF	6	\$3,163	
	Ceiling - Plaster/Drywall	2nd Floor	3	SF	5	\$37	Peeling paint
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	5	\$1,174	
	Floor - Tile/Sheet	2nd Floor	1	SF	5	\$6	Damaged tiles
	Floor - Tile/Sheet	2nd Floor	916	SF	6	\$917	-
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	36	LF	6	\$771	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,734	SF	6	\$4,786	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	\$15	Peeling paint
Classro	oom #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	\$2,838	
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	\$301	
	Floor - Wood	2nd Floor	820	SF	6	\$5,781	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	25	LF	6	\$536	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,636	SF	6	\$4,515	
Classro	oom #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	\$2,824	
	Ceiling - Plaster/Drywall	2nd Floor	4	SF	5	\$50	Peeling paint
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
1141104		David 40 at					A

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Classroom #203 (Regular Classroom)		ltom - Tuno	Location	Quantity	l leit	Dank	Coct	Commonts
Doors - Wood Doors inclu hw 2nd Floor 2nd Floor 820 SF 6 \$5,781 Floor - Wood 2nd Floor 2nd Floor 14 EA 6 \$1,735 Marker Board 2nd Floor 37 LF 6 \$7,733 Storago Closet 2nd Floor 37 LF 6 \$7,733 Storago Closet 2nd Floor 3,85 SF 6 \$2,39 Walls - Plaster/Drywall 2nd Floor 1,836 SF 6 \$4,515 Classroom #206 (Regular Classroom) Classroom #206 (Regular Classroom)	•	••	Location	Quantity	Unit	Kalik	Cost	Comments
Floor	Ciassic	· · · · · · · · · · · · · · · · · · ·	2nd Floor	1	ΕΛ	6	¢201	
Lighting - Pendent/Surface 2nd Floor 37				-				
Marker Board 2nd Floor 37								
Storage Claset 2nd Floor 33 5F 6 \$229								
Walls - Plaster/Drywall 2nd Floor 1,636 SF 6 \$4,515 Classroom #205 (Regular Classroom) AC Units 2 EA 6 \$3379 Casework 15 LF 6 \$3379 Celling - Plaster/Drywall 17 EF 6 \$3279 Doors - Wood Doors inclu hw 11 EA 6 \$22,751 Floor - Wood 17 EF 6 \$203 Poors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood 79 SF 6 \$5,605 Lighting - Pendent/Surface 2 8 7 \$0 Marker Board 35 LF 6 \$329 Storage/ Closet 31 5 6 \$239 Wills - Plaster/Drywall 2nd Floor 2 EA 6 \$391 Casework 2nd Floor 15 LF 6 \$329 Calling - Pendent/Surface 2nd Floor 12 EA								
AC Units		•			_			
AC Units		walls - Plaster/Drywall	211d F1001	1,030	SF	0	\$4,515	
Casework	Classro	oom #205 (Regular Classroom)						
Ceiling - Plaster/Drywall 795 SF 6 \$2,751 Doors - Transom Window 12 SF 6 \$203 Doors - Wood Doors inclu hw 1 EA 6 \$301 Floor - Wood 796 SF 6 \$5,605 Lighting - Pendent/Surface 28 EA 7 \$0 Marker Board 33 SF 6 \$239 Walls - Plaster/Drywall 1,415 SF 6 \$239 Walls - Plaster/Drywall 2nd Floor 2 EA 6 \$939 AC Units 2nd Floor 2 EA 6 \$939 Casework 2nd Floor 820 SF 6 \$203 Ceiling - Plaster/Drywall 2nd Floor 820 SF 6 \$203 Doors - Transom Window 2nd Floor 12 SF 6 \$203 Doors - Wood Doors inclu hw 2nd Floor 820 SF 6 \$5,781 Lighting - Pendent/Surface 2nd Floor		AC Units		2	EA	6	\$991	
Doors - Transom Window 12		Casework		15	LF	6	\$379	
Doors - Wood Doors inclu hw Floor - Wood 78		Ceiling - Plaster/Drywall		795	SF	6	\$2,751	
Floor - Wood 795 5F 6 \$5,605		Doors - Transom Window		12	SF	6	\$203	
Lighting - Pendent/Surface 28 EA 7 \$0 Marker Board 35 LF 6 \$750 Storage/ Closet 33 SF 6 \$239 Walls - Plaster/Drywall 1,415 SF 6 \$3,905 Classroom #206 (Regular Classroom) AC Units 2nd Floor 2 EA 6 \$991 Casework 2nd Floor 15 LF 6 \$379 Ceiling - Plaster/Drywall 2nd Floor 15 LF 6 \$379 Ceiling - Plaster/Drywall 2nd Floor 820 SF 6 \$238 Doors - Transom Window 2nd Floor 12 SF 6 \$203 Doors - Wood Doors inclu hw 2nd Floor 820 SF 6 \$5,781 Lighting - Pendent/Surface 2nd Floor 35 LF 6 \$5,781 Marker Board 2nd Floor 35 LF 6 \$323 Storage/ Closet 2nd Floor 35		Doors - Wood Doors inclu hw		1	EA	6	\$301	
Marker Board 35 LF 6 \$750 Storage/ Closet 33 SF 6 \$239 Walls - Plaster/Drywall 1,415 SF 6 \$3,905 Classroom #206 (Regular Classroom) AC Units 2nd Floor 2 EA 6 \$991 Casework 2nd Floor 15 LF 6 \$379 Ceiling - Plaster/Drywall 2nd Floor 820 SF 6 \$2,838 Doors - Transom Window 2nd Floor 12 SF 6 \$2,838 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$203 Floor - Wood 2nd Floor 820 SF 6 \$5,781 Lighting - Pendent/Surface 2nd Floor 35 LF 6 \$239 Marker Board 2nd Floor 33 SF 6 \$239 Storage/ Closet 2nd Floor 33 SF 6 \$239 Walls - Plaster/Drywall 2nd Floor <td></td> <td>Floor - Wood</td> <td></td> <td>795</td> <td>SF</td> <td>6</td> <td>\$5,605</td> <td></td>		Floor - Wood		795	SF	6	\$5,605	
Storage Closet Walls - Plaster Drywall Storage Classroom #206 Regular Classroom R206 R206 R207 R20		Lighting - Pendent/Surface		28	EA	7	\$0	
Nalis - Plaster/Drywall 1,415		Marker Board		35	LF	6	\$750	
Classroom #206 (Regular Classroom) AC Units		Storage/ Closet		33	SF	6	\$239	
AC Units 2nd Floor 2 EA 6 \$ \$991 Casework 2nd Floor 15 LF 6 \$ \$379 Ceiling - Plaster/Drywall 2nd Floor 820 SF 6 \$ \$2,838 Doors - Transom Window 2nd Floor 12 SF 6 \$ \$203 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$ \$301 Floor - Wood 2nd Floor 820 SF 6 \$5,781 Lighting - Pendent/Surface 2nd Floor 14 EA 7 \$ \$0 Marker Board 2nd Floor 35 LF 6 \$750 Storage/ Closet 2nd Floor 33 SF 6 \$ \$239 Walls - Plaster/Drywall 2nd Floor 1,636 SF 6 \$4,515 Classroom #207 (Regular Classroom) AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint		Walls - Plaster/Drywall		1,415	SF	6	\$3,905	
Casework 2nd Floor 15 LF 6 \$379 Ceiling - Plaster/Drywall 2nd Floor 820 SF 6 \$2,838 Doors - Transom Window 2nd Floor 12 SF 6 \$203 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Floor - Wood 2nd Floor 820 SF 6 \$5,781 Lighting - Pendent/Surface 2nd Floor 14 EA 7 \$0 Marker Board 2nd Floor 35 LF 6 \$750 Storage/ Closet 2nd Floor 33 SF 6 \$239 Walls - Plaster/Drywall 2nd Floor 1,636 SF 6 \$4,515 Classroom) AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint	Classro	oom #206 (Regular Classroom)						
Ceiling - Plaster/Drywall 2nd Floor 820 SF 6 \$2,838 Doors - Transom Window 2nd Floor 12 SF 6 \$203 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Floor - Wood 2nd Floor 820 SF 6 \$5,781 Lighting - Pendent/Surface 2nd Floor 14 EA 7 \$0 Marker Board 2nd Floor 35 LF 6 \$750 Storage/ Closet 2nd Floor 33 SF 6 \$239 Walls - Plaster/Drywall 2nd Floor 1,636 SF 6 \$4,515 Classroom #207 (Regular Classroom) AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint		AC Units	2nd Floor	2	EA	6	\$991	
Doors - Transom Window 2nd Floor 12 SF 6 \$203 Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Floor - Wood 2nd Floor 820 SF 6 \$5,781 Lighting - Pendent/Surface 2nd Floor 14 EA 7 \$0 Marker Board 2nd Floor 35 LF 6 \$750 Storage/ Closet 2nd Floor 33 SF 6 \$239 Walls - Plaster/Drywall 2nd Floor 1,636 SF 6 \$4,515 Classroom #207 (Regular Classroom) AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint		Casework	2nd Floor	15	LF	6	\$379	
Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 \$301 Floor - Wood 2nd Floor 820 SF 6 \$5,781 Lighting - Pendent/Surface 2nd Floor 14 EA 7 \$0 Marker Board 2nd Floor 35 LF 6 \$750 Storage/ Closet 2nd Floor 33 SF 6 \$239 Walls - Plaster/Drywall 2nd Floor 1,636 SF 6 \$4,515 Classroom #207 (Regular Classroom) AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint		Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	\$2,838	
Floor - Wood 2nd Floor 820 SF 6 \$5,781 Lighting - Pendent/Surface 2nd Floor 14 EA 7 \$0 Marker Board 2nd Floor 35 LF 6 \$750 Storage/ Closet 2nd Floor 33 SF 6 \$239 Walls - Plaster/Drywall 2nd Floor 1,636 SF 6 \$4,515 Classroom #207 (Regular Classroom) AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint		Doors - Transom Window	2nd Floor	12	SF	6	\$203	
Lighting - Pendent/Surface 2nd Floor 14 EA 7 \$0 Marker Board 2nd Floor 35 LF 6 \$750 Storage/ Closet 2nd Floor 33 SF 6 \$239 Walls - Plaster/Drywall 2nd Floor 1,636 SF 6 \$4,515 Classroom #207 (Regular Classroom) AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint		Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Marker Board 2nd Floor 35 LF 6 \$750 Storage/ Closet 2nd Floor 33 SF 6 \$239 Walls - Plaster/Drywall 2nd Floor 1,636 SF 6 \$4,515 Classroom #207 (Regular Classroom) AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint		Floor - Wood	2nd Floor	820	SF	6	\$5,781	
Storage/ Closet Walls - Plaster/Drywall 2nd Floor 2nd Floor 33 1,636 SF 6 6 \$4,515 Classroom #207 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall 2 2 2 4 4 5 5 5 303 EA 4 5 5 5 5 5 7 12 6 4 7 7 8 7 8 7 9 9 9 9 9 9 9 1 8 7 8 8 9 9 9 1 8 9 9 9 1 9 9 1 9 9 1 9 1 9		Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
Walls - Plaster/Drywall 2nd Floor 1,636 SF 6 \$4,515 Classroom #207 (Regular Classroom) AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint		Marker Board	2nd Floor	35	LF	6	\$750	
Classroom #207 (Regular Classroom) AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint				33	SF	6	\$239	
AC Units 2 EA 6 \$991 Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint		Walls - Plaster/Drywall	2nd Floor	1,636	SF	6	\$4,515	
Casework 12 LF 6 \$303 Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint	Classro	oom #207 (Regular Classroom)						
Ceiling - Plaster/Drywall 1 SF 5 \$12 Peeling paint		AC Units		2	EA	6	\$991	
		Casework		12	LF	6	\$303	
0.11 PL 4 PL 11		Ceiling - Plaster/Drywall		1	SF	5	\$12	Peeling paint
Ceiling - Plaster/Drywaii 784 SF 6 \$2,713		Ceiling - Plaster/Drywall		784	SF	6	\$2,713	
Doors - Store Front 1 EA 6 \$1,208		Doors - Store Front		1	EA	6	\$1,208	
Doors - Transom Window 12 SF 6 \$203		Doors - Transom Window		12	SF	6	\$203	
Floor - Tile/Sheet 785 SF 6 \$786		Floor - Tile/Sheet		785	SF	6	\$786	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

	Itom - Type	Location	Ougntitu	l Init	Dank	Cont	Comments
_	Item - Type	Location	Quantity	Unit	Kailk	Cost	Comments
Ciassro	oom #207 (Regular Classroom)		4.4	Г^	7	ФО	
	Lighting - Pendent/Surface		14	EA	7	\$0	
	Marker Board		35	LF	6	\$750 \$239	
	Storage/ Closet		33	SF	6		
	Walls - Plaster/Drywall		1,415	SF	6	\$3,905	
Classro	oom #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	2nd Floor	807	SF	6	\$2,793	
	Ceiling - Plaster/Drywall	2nd Floor	1	SF	5	\$12	Peeling paint
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	808	SF	6	\$5,696	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	\$1,735	
	Marker Board	2nd Floor	26	LF	6	\$557	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,414	SF	6	\$3,902	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	\$5	Peeling paint
Classro	oom #209 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	2nd Floor	862	SF	6	\$2,983	
	Chalk Board	2nd Floor	4	LF	4	\$367	
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	862	SF	6	\$863	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	\$0	
	Marker Board	2nd Floor	25	LF	6	\$536	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,456	SF	6	\$4,018	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	\$15	Peeling paint
Classro	oom #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	9	LF	5	\$1,882	
	Ceiling - Plaster/Drywall	2nd Floor	2	SF	5	\$25	Peeling paint
	Ceiling - Plaster/Drywall	2nd Floor	860	SF	6	\$2,976	
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

	ory: Classrooms						
_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	pom #210 (Regular Classroom)						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	862	SF	6	\$863	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	46	LF	6	\$985	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,459	SF	6	\$4,027	
Classro	oom #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	2nd Floor	862	SF	6	\$2,983	
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Transom Window	2nd Floor	1	SF	6	\$17	
	Floor - Wood	2nd Floor	862	SF	6	\$6,077	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	42	LF	6	\$900	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,455	SF	6	\$4,016	
	Walls - Plaster/Drywall	2nd Floor	4	SF	5	\$20	Peeling paint
Classro	oom #213 (Vacant)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	2nd Floor	862	SF	6	\$2,983	
	Doors - Wood Doors inclu hw	2nd Floor	12	EA	6	\$3,612	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	862	SF	6	\$863	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	42	LF	6	\$900	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,459	SF	6	\$4,027	
Classro	oom #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	2nd Floor	860	SF	6	\$2,976	
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Transom Window	2nd Floor	1	SF	6	\$17	
	Floor - Wood	2nd Floor	862	SF	6	\$6,077	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	om #214 (Regular Classroom)	2300011	Quantity	O.III	r.w/III	0031	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	21	LF	6	\$450	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	4	SF	5	\$20	Peeling paint
	Walls - Plaster/Drywall	2nd Floor	1,454	SF	6	\$4,013	- com 9 hamm
	Walls - Plaster/Drywall	2nd Floor	2	SF	5		Peeling paint
assro	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	2nd Floor	862	SF	6	\$2,983	
	Chalk Board	2nd Floor	2	LF	4	\$184	
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	862	SF	6	\$863	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	24	LF	6	\$514	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	4	SF	5		Peeling paint
	Walls - Plaster/Drywall	2nd Floor	1,455	SF	6	\$4,016	
assro	om #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	6	LF	5	\$1,254	
	Ceiling - Plaster/Drywall	2nd Floor	2	SF	5	\$25	Peeling paint
	Ceiling - Plaster/Drywall	2nd Floor	860	SF	6	\$2,976	
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	862	SF	6	\$6,077	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	25	LF	6	\$536	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,459	SF	6	\$4,027	
assro	om #217 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	15	LF	6	\$379	
		2nd Floor	795	SF	6	\$2,751	
	Ceiling - Plaster/Drywall	2110 F1001	795	OI	O	Ψ2,101	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

	ory: Classrooms						_
-	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #217 (Regular Classroom)						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	795	SF	6	\$796	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	\$1,735	
	Marker Board	2nd Floor	40	LF	6	\$857	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,415	SF	6	\$3,905	
Classro	oom #218 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	\$2,595	
	Ceiling - Plaster/Drywall	2nd Floor	3	SF	5	\$37	Peeling paint
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	753	SF	6	\$5,309	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	25	LF	6	\$536	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,366	SF	6	\$3,770	
Classro	oom #219 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	790	SF	6	\$2,734	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	\$62	Peeling paint
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	795	SF	6	\$796	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	36	LF	6	\$771	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,415	SF	6	\$3,905	
Classro	oom #220 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	6	\$991	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	4	SF	5	\$50	Peeling paint
	Ceiling - Plaster/Drywall	2nd Floor	804	SF	6	\$2,782	
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassroom #220 (Regular Classroom)			J		- 5500	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Wood	2nd Floor	808	SF	6	\$5,696	
Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
Marker Board	2nd Floor	26	LF	6	\$557	
Storage/ Closet	2nd Floor	33	SF	6	\$239	
Walls - Plaster/Drywall	2nd Floor	1,415	SF	6	\$3,905	
lassroom #222 (Regular Classroom)						
AC Units	2nd Floor	1	EA	6	\$496	
Casework	2nd Floor	15	LF	6	\$379	
Ceiling - Lay-in	2nd Floor	816	SF	6	\$2,450	
Ceiling - Plaster/Drywall	2nd Floor	4	SF	5	\$37	Peeling paint
Doors - Transom Window	2nd Floor	1	SF	6	\$17	
Doors - Transom Window	2nd Floor	12	SF	6	\$203	
Floor - Tile/Sheet	2nd Floor	820	SF	6	\$821	
Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
Marker Board	2nd Floor	30	LF	6	\$643	
Storage/ Closet	2nd Floor	33	SF	6	\$239	
Walls - Plaster/Drywall	2nd Floor	1,634	SF	6	\$4,510	
Walls - Plaster/Drywall	2nd Floor	2	SF	5		Peeling paint
assroom #223 (Regular Classroom)						
AC Units	2nd Floor	1	EA	6	\$496	
Casework	2nd Floor	15	LF	6	\$379	
Ceiling - Plaster/Drywall	2nd Floor	2	SF	5	\$25	Peeling paint
Ceiling - Plaster/Drywall	2nd Floor	818	SF	6	\$2,831	
Doors - Transom Window	2nd Floor	12	SF	6	\$203	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Wood	2nd Floor	820	SF	6	\$5,781	
Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
Marker Board	2nd Floor	22	LF	6	\$471	
Storage/ Closet	2nd Floor	33	SF	6	\$239	
Walls - Plaster/Drywall	2nd Floor	1,636	SF	6	\$4,515	
assroom #224 (Regular Classroom)						
AC Units	2nd Floor	1	EA	6	\$496	
Casework	2nd Floor	15	LF	6	\$379	
Ceiling - Plaster/Drywall	2nd Floor	913	SF	6	\$3,160	
Ceiling - Plaster/Drywall	2nd Floor	4	SF	5	\$50	Peeling paint
ALICANI	D 40 -/					Assessment Pate 40

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	oom #224 (Regular Classroom)					- 5561	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	917	SF	6	\$918	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	30	LF	6	\$643	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,734	SF	6	\$4,786	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5		Peeling paint
Classr	oom #225 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	2nd Floor	913	SF	6	\$3,160	
	Ceiling - Plaster/Drywall	2nd Floor	4	SF	5		Peeling paint
	Chalk Board	2nd Floor	15	LF	4	\$1,377	
	Doors - Transom Window	2nd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	917	SF	6	\$6,465	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	26	LF	6	\$557	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,737	SF	6	\$4,794	
Classr	oom #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	15	LF	6	\$379	
	Ceiling - Plaster/Drywall	3rd Floor	890	SF	6	\$3,080	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	\$125	Peeling paint
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	900	SF	6	\$6,345	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	6	\$857	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	1,440	SF	6	\$3,974	
Classr	oom #303 (Science Classroom)						
	AC Units	3rd Floor	2	EA	6	\$991	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
_	oom #303 (Science Classroom)						
	Casework	3rd Floor	16	LF	6	\$404	
	Ceiling - Plaster/Drywall	3rd Floor	839	SF	6	\$2,903	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	839	SF	6	\$840	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	20	LF	6	\$428	
	Storage/ Closet	3rd Floor	440	SF	6	\$3,190	#301 part of room
	Walls - Plaster/Drywall	3rd Floor	1	SF	5	\$5	Peeling paint
	Walls - Plaster/Drywall	3rd Floor	1,433	SF	6	\$3,955	
Classro	oom #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	7	LF	6	\$177	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	\$62	Peeling paint
	Ceiling - Plaster/Drywall	3rd Floor	895	SF	6	\$3,097	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	900	SF	6	\$6,345	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	6	\$857	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	1,440	SF	6	\$3,974	
Classro	oom #305 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	3rd Floor	2	SF	5	\$25	Peeling paint
	Ceiling - Plaster/Drywall	3rd Floor	898	SF	6	\$3,108	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	\$1,174	
	Floor - Wood	3rd Floor	900	SF	6	\$6,345	
	Lighting - Pendent/Surface	3rd Floor	15	EA	6	\$1,858	
	Marker Board	3rd Floor	40	LF	6	\$857	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	\$10	Peeling paint
	Walls - Plaster/Drywall	3rd Floor	1,438	SF	6	\$3,969	
Classro	oom #306 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	oom #306 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	946	SF	6	\$3,274	
	Doors - Transom Window	2nd Floor	8	SF	6	\$135	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	946	SF	6	\$947	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	\$0	
	Marker Board	2nd Floor	18	LF	6	\$386	
	Storage/ Closet	2nd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	2nd Floor	1,456	SF	6	\$4,018	
Classre	oom #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	14	LF	6	\$354	
	Ceiling - Plaster/Drywall	3rd Floor	946	SF	6	\$3,274	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	946	SF	6	\$947	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	\$1,982	
	Marker Board	3rd Floor	36	LF	6	\$771	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	1,453	SF	6	\$4,010	
	Walls - Plaster/Drywall	3rd Floor	3	SF	6	\$12	Peeling paint
Classr	oom #308 (Art Room)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	10	LF	5	\$2,091	
	Ceiling - Plaster/Drywall	3rd Floor	946	SF	6	\$3,274	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	946	SF	6	\$947	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	\$0	
	Marker Board	3rd Floor	24	LF	6	\$514	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	\$10	Peeling paint
	Walls - Plaster/Drywall	3rd Floor	1,454	SF	6	\$4,013	
	Work Sink	3rd Floor	1	EA	6	\$379	
Classr	oom #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	oom #309 (Regular Classroom)	Location	Quantity	Oilit	Kank	0031	Comments
Olassic	Casework	3rd Floor	14	LF	6	\$354	
	Ceiling - Plaster/Drywall	3rd Floor	932	SF	6	\$3,225	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	932	SF	6	\$6,571	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	6	\$857	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	1,440	SF	6	\$3,974	
	·	5.4	.,	٠.	· ·	ψο,σ	
Classro	oom #310 (Computer Lab)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	14	LF	6	\$354	
	Ceiling - Plaster/Drywall	3rd Floor	932	SF	5		Peeling paint
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	Wood panel
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	932	SF	6	\$6,571	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	\$0	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	1,440	SF	6	\$3,974	
Classro	oom #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	7	LF	6	\$177	
	Ceiling - Plaster/Drywall	3rd Floor	946	SF	6	\$3,274	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd Floor	946	SF	6	\$947	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	6	\$857	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	1,456	SF	6	\$4,018	
Classro	oom #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	3rd Floor	838	SF	6	\$2,900	
	Ceiling - Plaster/Drywall	3rd Floor	1	SF	5		Peeling paint
	Doors - Wood Doors inclu hw	3rd Floor	12	EA	6		Wood panel

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

	Item - Type	Location Quanti	ity	Unit	Rank	Cost	Comments
	oom #312 (Regular Classroom)		•				
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor 83	39	SF	6	\$5,915	
	Lighting - Pendent/Surface	3rd Floor	6	EΑ	7	\$0	
	Marker Board	3rd Floor	25	LF	6	\$536	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	2	SF	5	\$10	Peeling paint
	Walls - Plaster/Drywall	3rd Floor 1,43	32	SF	6	\$3,952	
Classro	oom #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	3rd Floor 83	39	SF	6	\$2,903	
	Ceiling - Plaster/Drywall	3rd Floor	1	SF	5		Peeling paint
	Chalk Board	3rd Floor	8	LF	5	\$942	
	Doors - Transom Window	3rd Floor	1	SF	6	\$17	
	Doors - Transom Window	3rd Floor	2	SF	6	\$203	
	Floor - Wood	3rd Floor 83	39	SF	6	\$5,915	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	\$0	
	Marker Board	3rd Floor	25	LF	6	\$536	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor 1,43	34	SF	6	\$3,958	
Classro	oom #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	6	LF	6	\$404	
	Ceiling - Plaster/Drywall	3rd Floor	9	SF	5	\$112	Peeling paint
	Ceiling - Plaster/Drywall	3rd Floor 83	30	SF	6	\$2,872	
	Doors - Transom Window	3rd Floor	2	SF	6	\$203	Wood panel
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	\$1,174	
	Floor - Tile/Sheet	3rd Floor 83	39	SF	6	\$840	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	\$0	
	Marker Board	3rd Floor	10	LF	6	\$857	
	Walls - Plaster/Drywall	3rd Floor 1,43	30	SF	6	\$3,947	
	Walls - Plaster/Drywall	3rd Floor	4	SF	5	\$20	Peeling paint
Classro	oom #315 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	3rd Floor	4	SF	5	\$50	Peeling paint
		David 00 of 47					A 1 D - 1 - 40/07/45

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
_	om #315 (Regular Classroom)	Location	Quantity	O.III	Main	0031	Commonto
Jiu33i U	Ceiling - Plaster/Drywall	3rd Floor	835	SF	6	\$2,890	
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	839	SF	6	\$5,915	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	40	LF	6	\$857	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	1,434	SF	6	\$3,958	
Classro	om #316 (Regular Classroom)		, -			*-/	
Ciassic	AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	14	LF	6	\$354	
	Ceiling - Plaster/Drywall	3rd Floor	4	SF	5	\$50	Peeling paint
	Ceiling - Plaster/Drywall	3rd Floor	835	SF	6	\$2,890	r coming paint
	Doors - Wood Doors inclu hw	3rd Floor	12	EA	6	\$3,612	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	839	SF	6	\$5,915	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	32	LF	6	\$685	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	1,433	SF	6	\$3,955	
	Walls - Structural Glazed Tile	3rd Floor	1	SF	5		Peeling paint
Classes						***	
Classic	om #318 (Regular Classroom) AC Units	3rd Floor	1	EA	6	\$496	
	Casework	3rd Floor	9	LF	6	\$227	
	Ceiling - Plaster/Drywall	3rd Floor	833	SF	5		Peeling paint
	Doors - Transom Window	3rd Floor	12	SF	6	\$203	reening paint
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	\$301	
	Floor - Wood	3rd Floor	833	SF	6	\$5,873	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	\$0	
	Marker Board	3rd Floor	30	LF	6	\$643	
	Storage/ Closet	3rd Floor	33	SF	6	\$239	
	Walls - Plaster/Drywall	3rd Floor	1,636	SF	6	\$4,515	
01		3.3.100	1,000	٠.	•	ψ 1,0 10	
Classro	om #319 (Regular Classroom)	2rd Floor		ΕΛ	6	£400	
	AC Units	3rd Floor 3rd Floor	1	EA	6	\$496	
	Casework		9	LF SF	6	\$227	Pooling point
	Ceiling - Plaster/Drywall	3rd Floor	833	SF.	5	\$7,036	Peeling paint

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Classrooms

Category: Classrool		Location	Ou	l lm!4	Donk	Cont	Comments
Group Item - Type		Location	Quantity	Unit	Kank	Cost	Comments
Classroom #319 (Regular		. =					
Doors - Transom		3rd Floor	12	SF	6	\$203	
Doors - Wood Doo	ors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - Wood		3rd Floor	833	SF	6	\$5,873	
Lighting - Penden	nt/Surface	3rd Floor	14	EA	6	\$1,735	
Marker Board		3rd Floor	25	LF	6	\$536	
Storage/ Closet		3rd Floor	33	SF	6	\$239	
Walls - Plaster/Dr	ywall	3rd Floor	1,636	SF	6	\$4,515	
Classroom #320 (Regular	Classroom)						
AC Units		3rd Floor	1	EA	6	\$496	
Casework		3rd Floor	15	LF	6	\$379	
Ceiling - Plaster/D	Orywall	3rd Floor	2	SF	5	\$25	Peeling paint
Ceiling - Plaster/D	Orywall	3rd Floor	926	SF	6	\$3,205	
Doors - Transom	Window	3rd Floor	12	SF	6	\$203	
Doors - Wood Doo	ors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - Tile/Sheet		3rd Floor	925	SF	6	\$926	
Lighting - Penden	nt/Surface	3rd Floor	16	EΑ	7	\$0	
Marker Board		3rd Floor	40	LF	6	\$857	
Storage/ Closet		3rd Floor	33	SF	6	\$239	
Walls - Plaster/Dr	ywall	3rd Floor	3	SF	5	\$15	Peeling paint
Walls - Plaster/Dr	ywall	3rd Floor	1,733	SF	7	\$0	
Classroom #321 (Regular	Classroom)						
AC Units		3rd Floor	1	EA	6	\$496	
Casework		3rd Floor	15	LF	6	\$379	
Ceiling - Plaster/D	Drywall	3rd Floor	920	SF	6	\$3,184	
Ceiling - Plaster/D	Drywall	3rd Floor	2	SF	5	\$25	Peeling paint
Doors - Transom	Window	3rd Floor	12	SF	6	\$203	
Doors - Wood Doo	ors inclu hw	3rd Floor	1	EA	6	\$301	
Floor - Tile/Sheet		3rd Floor	925	SF	6	\$926	
Lighting - Penden	nt/Surface	3rd Floor	16	EA	7	\$0	
Marker Board		3rd Floor	25	LF	6	\$536	
Storage/ Closet		3rd Floor	33	SF	6	\$239	
Walls - Plaster/Dr	ywall	3rd Floor	5	SF	5	\$26	Peeling paint
Walls - Plaster/Dr	•	3rd Floor	1,735	SF	6	\$4,788	

Classrooms Subtotal: \$767,290

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Co
lminis	strative Suites/Offices						
	AC Unit	105 Offices	1	EΑ	6	\$496	
	Ceiling - Lay-in	105 Offices	184	SF	6	\$553	
	Doors - Transom Window	105 Offices	24	SF	6	\$406	
	Doors - Wood Doors inclu hw	105 Offices	3	EΑ	6	\$903	
	Floor - Tile/Sheet	105 Offices	184	SF	6	\$184	
	Lighting - Lay-in	105 Offices	4	EΑ	7	\$0	
	Walls - Concrete Block	105 Offices	472	SF	6	\$1,384	
	AC Unit	1st floor main office	2	EΑ	6	\$991	
	Ceiling - Plaster/Drywall	1st floor main office	1,239	SF	6	\$4,288	
	Doors - Transom Window	1st floor main office	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st floor main office	2	EΑ	6	\$602	
	Floor - Carpet	1st floor main office	413	SF	6	\$880	
	Floor - Tile/Sheet	1st floor main office	826	SF	6	\$827	
	Lighting - Pendent/Surface	1st floor main office	20	EΑ	7	\$0	
	Power Distribution	1st floor main office	8	EΑ	6	\$16,999	
	Walls - Plaster/Drywall	1st floor main office	2,967	SF	6	\$8,189	
	AC Unit	1st floor north of auditorium	1	EΑ	6	\$496	
	Ceiling - Plaster/Drywall	1st floor north of auditorium	480	SF	6	\$1,661	
	Doors - Transom Window	1st floor north of auditorium	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	1st floor north of auditorium	1	EΑ	6	\$301	
	Floor - Tile/Sheet	1st floor north of auditorium	480	SF	6	\$480	
	Lighting - Pendent/Surface	1st floor north of auditorium	9	EΑ	7	\$0	
	Power Distribution	1st floor north of auditorium	8	EΑ	6	\$16,999	
	Walls - Plaster/Drywall	1st floor north of auditorium	2,070	SF	6	\$5,713	
	Ceiling - Lay-in	1st floor rm # 111 south side of auditorium	352	SF	6	\$1,057	
	Doors - Wood Doors inclu hw	1st floor rm # 111 south side of auditorium	1	EA	6	\$301	
	Floor - Tile/Sheet	1st floor rm # 111 south side of auditorium	352	SF	6	\$352	
	Lighting - Lay-in	1st floor rm # 111 south side of auditorium	8	EA	7	\$0	
	Power Distribution	1st floor rm # 111 south side of auditorium	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	1st floor rm # 111 south side of auditorium	832	SF	6	\$2,296	
	AC Unit	2nd floor staff resource copy room	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd floor staff resource copy room	496	SF	6	\$1,716	
	Doors - Transom Window	2nd floor staff resource copy room	12	SF	6	\$203	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

up I	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ninist	rative Suites/Offices						
[Doors - Wood Doors inclu hw	2nd floor staff resource copy room	1	EA	6	\$301	
F	Floor - Carpet	2nd floor staff resource copy room	496	SF	6	\$1,057	
- 1	Lighting - Pendent/Surface	2nd floor staff resource copy room	5	EA	7	\$0	
ſ	Power Distribution	2nd floor staff resource copy room	12	EA	6	\$25,499	
١	Walls - Plaster/Drywall	2nd floor staff resource copy room	1,442	SF	6	\$3,980	
(Ceiling - Plaster/Drywall	3rd floor gym office	350	SF	6	\$1,211	
ſ	Doors - Transom Window	3rd floor gym office	20	SF	6	\$339	
ſ	Doors - Wood Doors inclu hw	3rd floor gym office	2	EA	6	\$602	
ſ	Floor - Wood	3rd floor gym office	350	SF	6	\$2,467	
1	Lighting - Pendent/Surface	3rd floor gym office	6	EA	7	\$0	
ſ	Power Distribution	3rd floor gym office	2	EA	6	\$4,250	
١	Walls - Plaster/Drywall	3rd floor gym office	1,050	SF	6	\$2,898	
	Ceiling - Plaster/Drywall	3rd floor staff lounge/copyroom next to staff bathroom	283	SF	6	\$979	
Γ	Doors - Transom Window	3rd floor staff lounge/copyroom next to staff bathroom	20	SF	6	\$339	
Γ	Doors - Wood Doors inclu hw	3rd floor staff lounge/copyroom next to staff bathroom	2	EA	6	\$602	
F	Floor - Tile/Sheet	3rd floor staff lounge/copyroom next to staff bathroom	283	SF	6	\$283	
l	Lighting - Pendent/Surface	3rd floor staff lounge/copyroom next to staff bathroom	3	EA	6	\$372	
F	Power Distribution	3rd floor staff lounge/copyroom next to staff bathroom	6	EA	6	\$12,749	
,	Storage/ Closet	3rd floor staff lounge/copyroom next to staff bathroom	10	SF	6	\$73	
١	Walls - Plaster/Drywall	3rd floor staff lounge/copyroom next to staff bathroom	705	SF	6	\$1,946	
	Walls - Plaster/Drywall	3rd floor staff lounge/copyroom next to staff bathroom	1	SF	5	\$5	Peeling paint
/	AC Unit	Principal's Office 104	1	EA	6	\$496	
(Ceiling - Plaster/Drywall	Principal's Office 104	476	SF	6	\$1,647	
Γ	Doors - Transom Window	Principal's Office 104	12	SF	6	\$203	
Γ	Doors - Wood Doors inclu hw	Principal's Office 104	1	EA	6	\$301	
F	Floor - Tile/Sheet	Principal's Office 104	476	SF	6	\$476	
- 1	Lighting - Pendent/Surface	Principal's Office 104	7	EA	7	\$0	
F	Power Distribution	Principal's Office 104	8	EA	6	\$16,999	
١	Walls - Plaster/Drywall	Principal's Office 104	1,925	SF	6	\$5,313	
1	AC Unit	Room 212	1	EA	5	\$1,826	
				SF			

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Sioup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Doors - Transom Window	Room 212	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	Room 212	1	EA	6	\$301	
	Floor - Wood	Room 212	221	SF	6	\$1,558	
	Lighting - Pendent/Surface	Room 212	5	EA	7	\$0	
	Power Distribution	Room 212	6	EA	6	\$12,749	
	Walls - Plaster/Drywall	Room 212	978	SF	6	\$2,699	
	Walls - Plaster/Drywall	Room 212	2	SF	5	\$10	Peeling paint
	AC Unit	Room 221	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	Room 221	238	SF	6	\$824	
	Ceiling - Plaster/Drywall	Room 221	3	SF	5	\$37	Peeling paint
	Doors - Store Front	Room 221	12	EA	6	\$14,498	
	Doors - Wood Doors inclu hw	Room 221	1	EA	5	\$1,174	
	Floor - Wood	Room 221	241	SF	6	\$1,699	
	Lighting - Pendent/Surface	Room 221	2	EA	6	\$248	Missing lenses
	Power Distribution	Room 221	4	EA	6	\$8,500	
	Walls - Plaster/Drywall	Room 221	1	SF	5	\$5	Peeling paint
	Walls - Plaster/Drywall	Room 221	951	SF	6	\$2,625	
	AC Unit	Room 317	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	Room 317	258	SF	6	\$893	
	Ceiling - Plaster/Drywall	Room 317	2	SF	5	\$25	Peeling paint
	Doors - Transom Window	Room 317	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	Room 317	1	EA	6	\$301	
	Floor - Wood	Room 317	260	SF	6	\$1,833	
	Lighting - Pendent/Surface	Room 317	5	EA	7	\$0	
	Power Distribution	Room 317	10	EA	6	\$21,249	
	Walls - Plaster/Drywall	Room 317	1,066	SF	6	\$2,942	
Gymna	sia						
- J	Bleacher Seating	1st Floor	476	EA	6	\$13,777	
	Ceiling - Plaster/Drywall	1st Floor	7,015	SF	6	\$38,721	
	Doors - Wood Doors inclu hw	1st Floor	12	EA	6	\$3,612	
	Floor - Tile/Sheet	1st Floor	5,262	SF	6	\$5,267	
	Floor - Wood	1st Floor	1,754	SF	6	\$12,366	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	\$0	
	Sound System	1st Floor	1	EA	6	\$41,654	
	Stage Curtain	1st Floor	2	EA	6	\$0	
	Walls - Plaster/Drywall	1st Floor	3,737	SF	6	\$10,314	
	Walls - Structural Glazed Tile	1st Floor	3,737	SF	6	\$11,757	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Gymna	sia						
	Ceiling - Plaster/Drywall	300 Gymnasium	5,378	SF	6	\$29,685	
	Doors - Transom Window	300 Gymnasium	40	SF	6	\$677	
	Doors - Wood Doors inclu hw	300 Gymnasium	4	EA	6	\$1,204	
	Floor - Wood	300 Gymnasium	5,378	SF	6	\$37,914	
	Lighting - Pendent/Surface	300 Gymnasium	25	EA	6	\$3,097	
	Scoreboards	300 Gymnasium	1	EA	6	\$2,244	
	Storage/ Closet	300 Gymnasium	355	SF	6	\$2,574	
	Walls - Plaster/Drywall	300 Gymnasium	3,044	SF	6	\$8,401	
	Walls - Structural Glazed Tile	300 Gymnasium	2,182	SF	6	\$6,865	
Library							
	AC Unit	Primary library room 107	2	EA	6	\$991	
	Casework	Primary library room 107	44	LF	6	\$1,111	
	Ceiling - Plaster/Drywall	Primary library room 107	852	SF	6	\$2,948	
	Doors - Wood Doors inclu hw	Primary library room 107	1	EA	6	\$301	
	Floor - Carpet	Primary library room 107	852	SF	6	\$1,815	
	Lighting - Pendent/Surface	Primary library room 107	14	EA	7	\$0	
	Walls - Plaster/Drywall	Primary library room 107	1,641	SF	6	\$4,529	
	AC Unit	Room 106	3	EA	6	\$1,487	
	Casework	Room 106	185	LF	6	\$4,672	
	Ceiling - Plaster/Drywall	Room 106	1,727	SF	6	\$5,976	
	Doors - Transom Window	Room 106	12	SF	6	\$203	
	Doors - Wood Doors inclu hw	Room 106	2	EA	6	\$602	
	Floor - Carpet	Room 106	1,727	SF	6	\$3,680	
	Lighting - Pendent/Surface	Room 106	30	EA	7	\$0	
	Walls - Plaster/Drywall	Room 106	2,581	SF	6	\$7,123	
Locker	Shower Room						
	Accessories	1st floor inside boiler room	233	SF	6	\$913	
	Ceiling - Plaster/ Drywall	1st floor inside boiler room	233	SF	6	\$806	
	Doors - Wood Doors inclu hw	1st floor inside boiler room	1	EA	6	\$301	
	Floor - Concrete	1st floor inside boiler room	233	SF	6	\$123	
	Lighting - Pendent/Surface	1st floor inside boiler room	2	EA	6	\$248	
	Urinals	1st floor inside boiler room	8	EA	6	\$2,688	
	Walls - Plaster/Drywall	1st floor inside boiler room	1,100	SF	6	\$3,036	
MDF_I	DF .						
	AC Unit	Next to room 102	1	EA	6	\$496	
	Doors - Steel Doors incl hw	Next to room 102	1	EA	6	\$301	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
MDF_I)F						
	Finishes	Next to room 102	162	SF	6	\$1,156	
	Ventilation and Cooling	Next to room 102	1	EA	6	\$1,855	
Mechar	nical/ Service Rooms						
	Boiler Room	1st Floor	2,326	SF	6	\$16,664	
	Coal Room	1st Floor	576	SF	6	\$4,127	
	Janitor's Closet	1st Floor	310	SF	6	\$2,221	
	Mechanical/ Service Rooms	1st Floor	4,005	SF	6	\$28,693	7 7 7 11
	Storage Room	1st Floor	214	SF	6	\$1,533	part of engine rooms.
	Storage Room Janitor's Closet	2nd Floor	310	SF	6	\$2,221	
		2nd Floor		SF	6		#204
	Storage Room	3rd Floor	162	SF		\$1,161 \$1,161	#204
	Janitor's Closet Air Tunnel	Basement	155 5,100	SF	6 6	\$1,110 \$31,579	
	All Turiner	Dasement	5,100	SF	O	φ31,379	
Restro	om						
	Accessories	1st floor boiler room	60	SF	6	\$553	
	Ceiling - Plaster/Drywall	1st floor boiler room	60	SF	6	\$208	
	Doors - Wood Doors inclu hw	1st floor boiler room	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st floor boiler room	60	SF	6	\$127	
	Lavatory	1st floor boiler room	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st floor boiler room	1	EA	6	\$124	
	Showers	1st floor boiler room	1	EA	6	\$311	
	Walls - Plaster/Drywall	1st floor boiler room	332	SF	6	\$916	
	Water Closet	1st floor boiler room	1	EA	6	\$336	
	Accessories	1st floor boys' at auditorium vestibule	195	SF	6	\$1,799	
	Ceiling - Plaster/Drywall	1st floor boys' at auditorium vestibule	195	SF	6	\$675	
	Doors - Steel Doors incl hw	1st floor boys' at auditorium vestibule	1	EA	6	\$301	
	Floor Drain	1st floor boys' at auditorium vestibule	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor boys' at auditorium vestibule	195	SF	6	\$413	
	Hand Dryer	1st floor boys' at auditorium vestibule	2	EA	6	\$460	
	Lavatory	1st floor boys' at auditorium vestibule	2	EA	6	\$639	
	Lighting - Lay-in	1st floor boys' at auditorium vestibule	4	EA	7	\$0	
	Partitions	1st floor boys' at auditorium vestibule	2	EA	6	\$594	
	Urinals	1st floor boys' at auditorium vestibule	2	EA	6	\$672	
	Walls - Plaster/Drywall	1st floor boys' at auditorium vestibule	112	SF	6	\$309	
	Walls - Tile Ceramic/ Porcelain	1st floor boys' at auditorium vestibule	336	SF	6	\$759	
	Water Closet	1st floor boys' at auditorium vestibule	2	EA	6	\$672	
	Accessories	1st floor boys center of corridor	276	SF	6	\$2,546	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
stroc	om						
	Ceiling - Plaster/Drywall	1st floor boys center of corridor	6	SF	5	\$75	Peeling paint
	Ceiling - Plaster/Drywall	1st floor boys center of corridor	270	SF	6	\$934	
	Doors - Transom Window	1st floor boys center of corridor	40	SF	6	\$677	
	Doors - Wood Doors inclu hw	1st floor boys center of corridor	1	EA	6	\$301	Fixed
	Floor Drain	1st floor boys center of corridor	1	EA	6	\$1,059	
	Floor - Concrete	1st floor boys center of corridor	276	SF	6	\$146	
	Hand Dryer	1st floor boys center of corridor	2	EA	5	\$1,181	
	Lavatory	1st floor boys center of corridor	2	EΑ	6	\$639	
	Lighting - Pendent/Surface	1st floor boys center of corridor	3	EA	6	\$372	
	Partitions	1st floor boys center of corridor	2	EA	6	\$594	
	Urinals	1st floor boys center of corridor	4	EA	6	\$1,344	
	Urinals	1st floor boys center of corridor	2	EA	5	\$2,688	Does not work
	Walls - Plaster/Drywall	1st floor boys center of corridor	462	SF	6	\$1,275	
	Walls - Structural Glazed Tile	1st floor boys center of corridor	231	SF	6	\$727	
	Water Closet	1st floor boys center of corridor	2	EΑ	6	\$672	
	Accessories	1st floor boys next to 210	276	SF	6	\$2,546	
	Ceiling - Plaster/Drywall	1st floor boys next to 210	270	SF	6	\$934	
	Ceiling - Plaster/Drywall	1st floor boys next to 210	6	SF	5	\$75	Peeling paint
	Doors - Transom Window	1st floor boys next to 210	40	SF	6	\$677	
	Doors - Wood Doors inclu hw	1st floor boys next to 210	1	EA	6	\$301	Fixed
	Floor Drain	1st floor boys next to 210	1	EA	6	\$1,059	
	Floor - Concrete	1st floor boys next to 210	276	SF	6	\$146	
	Hand Dryer	1st floor boys next to 210	2	EA	5	\$1,181	
	Lavatory	1st floor boys next to 210	2	EΑ	6	\$639	
	Lighting - Pendent/Surface	1st floor boys next to 210	3	EA	6	\$372	
	Partitions	1st floor boys next to 210	2	EA	6	\$594	
	Urinals	1st floor boys next to 210	2	EA	5	\$2,688	Does not work
	Urinals	1st floor boys next to 210	4	EA	6	\$1,344	
	Walls - Plaster/Drywall	1st floor boys next to 210	462	SF	6	\$1,275	
	Walls - Structural Glazed Tile	1st floor boys next to 210	231	SF	6	\$727	
	Water Closet	1st floor boys next to 210	2	EA	6	\$672	
	Accessories	1st floor boys north end	336	SF	6	\$3,099	
	Ceiling - Plaster/Drywall	1st floor boys north end	336	SF	6	\$1,163	
	Floor Drain	1st floor boys north end	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor boys north end	336	SF	6	\$711	
	Hand Dryer	1st floor boys north end	2	EA	6	\$460	
	Lavatory	1st floor boys north end	3	EA	6	\$959	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
stro	om						
	Lighting - Pendent/Surface	1st floor boys north end	4	EA	7	\$0	
	Partitions	1st floor boys north end	2	EA	6	\$594	
	Urinals	1st floor boys north end	6	EA	6	\$2,016	
	Walls - Plaster/Drywall	1st floor boys north end	524	SF	6	\$1,446	
	Walls - Structural Glazed Tile	1st floor boys north end	524	SF	6	\$1,649	
	Water Closet	1st floor boys north end	2	EA	6	\$672	
	Accessories	1st floor girls at auditorium vestibule	195	SF	6	\$1,799	
	Ceiling - Plaster/Drywall	1st floor girls at auditorium vestibule	195	SF	6	\$675	
	Doors - Wood Doors inclu hw	1st floor girls at auditorium vestibule	1	EΑ	6	\$301	
	Floor Drain	1st floor girls at auditorium vestibule	1	EΑ	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor girls at auditorium vestibule	195	SF	6	\$413	
	Hand Dryer	1st floor girls at auditorium vestibule	2	EΑ	6	\$460	
	Lavatory	1st floor girls at auditorium vestibule	2	EΑ	6	\$639	
	Lighting - Lay-in	1st floor girls at auditorium vestibule	4	EΑ	7	\$0	
	Partitions	1st floor girls at auditorium vestibule	4	EΑ	6	\$1,188	
	Walls - Plaster/Drywall	1st floor girls at auditorium vestibule	112	SF	6	\$309	
	Walls - Tile Ceramic/ Porcelain	1st floor girls at auditorium vestibule	336	SF	6	\$759	
	Water Closet	1st floor girls at auditorium vestibule	4	EΑ	6	\$1,344	
	Accessories	1st floor girls bathroom center of corridor	436	SF	6	\$4,021	
	Ceiling - Plaster/Drywall	1st floor girls bathroom center of corridor	436	SF	6	\$1,509	
	Doors - Wood Doors inclu hw	1st floor girls bathroom center of corridor	1	EΑ	6	\$301	
	Floor Drain	1st floor girls bathroom center of corridor	1	EΑ	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor girls bathroom center of corridor	436	SF	6	\$923	
	Hand Dryer	1st floor girls bathroom center of corridor	2	EΑ	6	\$460	
	Lavatory	1st floor girls bathroom center of corridor	2	EΑ	6	\$639	
	Lighting - Pendent/Surface	1st floor girls bathroom center of corridor	4	EΑ	7	\$0	
	Partitions	1st floor girls bathroom center of corridor	6	EΑ	6	\$1,782	
	Walls - Concrete Block	1st floor girls bathroom center of corridor	272	SF	6	\$797	
	Walls - Plaster/Drywall	1st floor girls bathroom center of corridor	714	SF	6	\$1,971	
	Walls - Structural Glazed Tile	1st floor girls bathroom center of corridor	141	SF	6	\$444	
	Water Closet	1st floor girls bathroom center of corridor	6	EA	6	\$2,016	
	Accessories	1st floor girls south end	336	SF	6	\$3,099	
	Ceiling - Plaster/Drywall	1st floor girls south end	336	SF	6	\$1,163	
	Doors - Wood Doors inclu hw	1st floor girls south end	1	EA	6	\$301	
	Floor Drain	1st floor girls south end	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st floor girls south end	336	SF	6	\$711	
	Hand Dryer	1st floor girls south end	2	EΑ	6	\$460	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
stroc	om						
	Lavatory	1st floor girls south end	3	EA	6	\$959	
	Lighting - Pendent/Surface	1st floor girls south end	4	EΑ	7	\$0	
	Partitions	1st floor girls south end	6	EΑ	6	\$1,782	
	Walls - Plaster/Drywall	1st floor girls south end	524	SF	6	\$1,446	
	Walls - Structural Glazed Tile	1st floor girls south end	524	SF	6	\$1,649	
	Water Closet	1st floor girls south end	6	EA	6	\$2,016	
	Accessories	1st floor inside office at north side of auditorium	38	SF	6	\$350	
	Ceiling - Plaster/Drywall	1st floor inside office at north side of auditorium	38	SF	6	\$132	
	Doors - Wood Doors inclu hw	1st floor inside office at north side of auditorium	1	EA	6	\$301	
	Floor - Tile/Sheet	1st floor inside office at north side of auditorium	38	SF	6	\$38	
	Lavatory	1st floor inside office at north side of auditorium	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st floor inside office at north side of auditorium	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st floor inside office at north side of auditorium	380	SF	6	\$1,049	
	Water Closet	1st floor inside office at north side of auditorium	1	EA	6	\$336	
	Accessories	1st floor inside room #118	136	SF	6	\$1,254	
	Ceiling - Plaster/Drywall	1st floor inside room #118	136	SF	6	\$471	
	Doors - Wood Doors inclu hw	1st floor inside room #118	1	EA	6	\$301	
	Floor Drain	1st floor inside room #118	1	EA	6	\$1,059	
	Floor - Tile/Sheet	1st floor inside room #118	136	SF	6	\$136	
	Lavatory	1st floor inside room #118	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st floor inside room #118	2	EA	6	\$248	
	Partitions	1st floor inside room #118	2	EA	6	\$594	
	Walls - Plaster/Drywall	1st floor inside room #118	661	SF	6	\$1,824	
	Water Closet	1st floor inside room #118	2	EA	6	\$672	
	Accessories	1st floor womens' middle of corridor	294	SF	6	\$2,712	
	Ceiling - Plaster/Drywall	1st floor womens' middle of corridor	294	SF	6	\$1,017	
	Doors - Wood Doors inclu hw	1st floor womens' middle of corridor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st floor womens' middle of corridor	294	SF	6	\$294	
	Lavatory	1st floor womens' middle of corridor	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st floor womens' middle of corridor	4	EA	7	\$0	
	Partitions	1st floor womens' middle of corridor	2	EA	6	\$594	
	Walls - Plaster/Drywall	1st floor womens' middle of corridor	798	SF	6	\$2,202	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Group Item -	Туре	Location	Quantity	Unit	Rank	Cost	Comments
Restroom							
Walls -	- Structural Glazed Tile	1st floor womens' middle of corridor	266	SF	6	\$837	
Water	Closet	1st floor womens' middle of corridor	2	EA	6	\$672	
Access	sories	2nd boys next to 222	334	SF	6	\$3,081	
Ceiling	- Plaster/Drywall	2nd boys next to 222	2	SF	5	\$25	Peeling paint
Ceiling	- Plaster/Drywall	2nd boys next to 222	332	SF	5	\$3,043	
Doors	- Wood Doors inclu hw	2nd boys next to 222	20	EA	5	\$23,481	
Doors	- Wood Doors inclu hw	2nd boys next to 222	1	EA	6	\$301	Fixed
Floor D	Drain	2nd boys next to 222	1	EA	5	\$2,094	
Floor -	Tile Ceramic/ Porcelain	2nd boys next to 222	332	SF	5	\$5,303	
Floor -	Tile Ceramic/ Porcelain	2nd boys next to 222	2	SF	5	\$42	Damaged tiles
Hand [Dryer	2nd boys next to 222	2	EA	5	\$1,181	
Lavato	ry	2nd boys next to 222	2	EA	6	\$639	
Lightin	g - Pendent/Surface	2nd boys next to 222	4	EA	5	\$730	
Partitio	ons	2nd boys next to 222	2	EA	6	\$594	
Urinals	8	2nd boys next to 222	6	EA	5	\$8,064	
Walls -	- Concrete Block	2nd boys next to 222	272	SF	6	\$797	
Walls -	- Plaster/Drywall	2nd boys next to 222	714	SF	6	\$1,971	
Walls -	- Structural Glazed Tile	2nd boys next to 222	141	SF	5	\$7,164	
Water	Closet	2nd boys next to 222	2	EA	6	\$672	
Access	sories	2nd floor girls next to 202	336	SF	6	\$3,099	
Ceiling	- Plaster/Drywall	2nd floor girls next to 202	3	SF	5	\$37	Peeling paint
Ceiling	- Plaster/Drywall	2nd floor girls next to 202	333	SF	6	\$1,152	
Doors	- Transom Window	2nd floor girls next to 202	20	SF	6	\$339	
Doors	- Wood Doors inclu hw	2nd floor girls next to 202	1	EA	6	\$301	Fixed
Floor D	Drain	2nd floor girls next to 202	1	EA	5	\$2,094	
Floor -	Tile/Sheet	2nd floor girls next to 202	2	SF	5	\$12	Damaged tiles
	Tile/Sheet	2nd floor girls next to 202	334	SF	6	\$334	
Hand [Oryer	2nd floor girls next to 202	2	EA	6	\$460	
Lavato	ry	2nd floor girls next to 202	2	EA	6	\$639	
Lightin	g - Pendent/Surface	2nd floor girls next to 202	4	EA	6	\$496	
Partitio	ons	2nd floor girls next to 202	6	EA	6	\$1,782	
Walls -	- Concrete Block	2nd floor girls next to 202	377	SF	6	\$1,105	
Walls -	- Plaster/Drywall	2nd floor girls next to 202	430	SF	6	\$1,187	
Walls -	- Structural Glazed Tile	2nd floor girls next to 202	108	SF	6	\$340	
Water	Closet	2nd floor girls next to 202	6	EA	6	\$2,016	
Access	sories	2nd floor girl's next to 214	459	SF	6	\$4,234	
Ceiling	g - Plaster/Drywall	2nd floor girl's next to 214	459	SF	6	\$1,588	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
stro	om						
	Doors - Transom Window	2nd floor girl's next to 214	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	2nd floor girl's next to 214	1	EA	6	\$301	Fixed
	Floor Drain	2nd floor girl's next to 214	1	EA	6	\$1,059	
	Floor - Tile/Sheet	2nd floor girl's next to 214	5	SF	5	\$29	Missing tiles
	Floor - Tile/Sheet	2nd floor girl's next to 214	454	SF	6	\$454	
	Hand Dryer	2nd floor girl's next to 214	2	EA	6	\$460	
	Lavatory	2nd floor girl's next to 214	3	EA	6	\$959	
	Lighting - Pendent/Surface	2nd floor girl's next to 214	4	EA	6	\$496	
	Partitions	2nd floor girl's next to 214	8	EA	6	\$2,375	
	Walls - Concrete Block	2nd floor girl's next to 214	381	SF	6	\$1,117	
	Walls - Plaster/Drywall	2nd floor girl's next to 214	1	SF	5	\$5	Peeling paint
	Walls - Plaster/Drywall	2nd floor girl's next to 214	597	SF	6	\$1,648	
	Walls - Structural Glazed Tile	2nd floor girl's next to 214	169	SF	6	\$532	
	Water Closet	2nd floor girl's next to 214	8	EA	6	\$2,688	
	Accessories	2nd floor staff restroom	159	SF	6	\$1,467	
	Ceiling - Plaster/Drywall	2nd floor staff restroom	159	SF	6	\$550	
	Doors - Wood Doors inclu hw	2nd floor staff restroom	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd floor staff restroom	158	SF	6	\$158	
	Floor - Weight/ Fitness Room Floor Matting	2nd floor staff restroom	1	SF	5	\$11	Damaged tiles
	Lavatory	2nd floor staff restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	2nd floor staff restroom	2	EA	6	\$248	
	Partitions	2nd floor staff restroom	4	EA	6	\$1,188	
	Walls - Plaster/Drywall	2nd floor staff restroom	746	SF	6	\$2,059	
	Water Closet	2nd floor staff restroom	4	EA	6	\$1,344	
	Accessories	3rd floor boys next to 318	336	SF	6	\$3,099	
	Ceiling - Plaster/Drywall	3rd floor boys next to 318	3	SF	5	\$37	Peeling paint
	Ceiling - Plaster/Drywall	3rd floor boys next to 318	333	SF	6	\$1,152	
	Doors - Transom Window	3rd floor boys next to 318	20	SF	6	\$339	
	Doors - Transom Window	3rd floor boys next to 318	1	SF	6	\$17	Fixed
	Floor Drain	3rd floor boys next to 318	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys next to 318	336	SF	6	\$711	
	Hand Dryer	3rd floor boys next to 318	2	EA	6	\$460	
	Lavatory	3rd floor boys next to 318	3	EA	5	\$4,769	
	Lighting - Pendent/Surface	3rd floor boys next to 318	4	EA	6	\$496	
	Partitions	3rd floor boys next to 318	2	EA	6	\$594	
	Urinals	3rd floor boys next to 318	6	EA	6	\$2,016	
	Walls - Concrete Block	3rd floor boys next to 318	377	SF	6	\$1,105	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroo	m						
	Walls - Plaster/Drywall	3rd floor boys next to 318	2	SF	5	\$10	Peeling paint
	Walls - Plaster/Drywall	3rd floor boys next to 318	428	SF	6	\$1,181	
	Walls - Structural Glazed Tile	3rd floor boys next to 318	108	SF	6	\$340	
	Water Closet	3rd floor boys next to 318	2	EA	6	\$672	
	Accessories	3rd floor girls next to 310	470	SF	6	\$4,335	
	Ceiling - Plaster/Drywall	3rd floor girls next to 310	2	SF	5	\$25	Peeling paint
	Ceiling - Plaster/Drywall	3rd floor girls next to 310	468	SF	5	\$4,290	
	Doors - Transom Window	3rd floor girls next to 310	20	SF	6	\$339	
	Doors - Wood Doors inclu hw	3rd floor girls next to 310	1	EA	5	\$1,174	
	Floor Drain	3rd floor girls next to 310	1	EA	6	\$1,059	
	Floor - Tile/Sheet	3rd floor girls next to 310	470	SF	6	\$470	
	Hand Dryer	3rd floor girls next to 310	2	EA	6	\$460	
	Lavatory	3rd floor girls next to 310	3	EA	5	\$4,769	
	Lighting - Pendent/Surface	3rd floor girls next to 310	4	EA	5	\$730	
	Partitions	3rd floor girls next to 310	9	EA	6	\$2,672	
	Walls - Concrete Block	3rd floor girls next to 310	221	SF	6	\$648	
	Walls - Plaster/Drywall	3rd floor girls next to 310	748	SF	6	\$2,064	
	Walls - Structural Glazed Tile	3rd floor girls next to 310	213	SF	5	\$10,822	
	Water Closet	3rd floor girls next to 310	10	EA	6	\$3,360	
	Accessories	3rd floor staff restroom	74	SF	6	\$683	
	Ceiling - Plaster/Drywall	3rd floor staff restroom	74	SF	6	\$256	
	Doors - Wood Doors inclu hw	3rd floor staff restroom	1	EA	6	\$301	
	Floor - Tile/Sheet	3rd floor staff restroom	74	SF	6	\$74	
	Lavatory	3rd floor staff restroom	2	EA	6	\$639	
	Lighting - Pendent/Surface	3rd floor staff restroom	1	EA	6	\$124	
	Partitions	3rd floor staff restroom	2	EA	6	\$594	
	Walls - Plaster/Drywall	3rd floor staff restroom	486	SF	6	\$1,341	
	Water Closet	3rd floor staff restroom	2	EA	6	\$672	

Rooms (Other Than Classrooms) Subtotal:

\$887,071

Building: Main

Category: Building Interior

Group Item - Type		Location	Quantity	Unit	Rank	Cost	Comments
Corridor							
Ceiling - Plaster/Dry	all	1st Floor	20	SF	5	\$349	Peeling paint
Ceiling - Plaster/Dry	all	1st Floor	8,511	SF	6	\$52,699	
Celling - Flaster/Dry	all	151 1001	0,511	31	O	φ52,099	

4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Building Interior

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido		2004.1011	quantity	01111	rtariit	0001	
Joine	Drinking Fountains - Double Fountain	1st Floor	4	EA	6	\$1,344	
	Floor - Terrazzo	1st Floor	3,516	SF	6	\$29,514	
	Floor - Tile/Sheet	1st Floor	5,015	SF	6	\$2,725	
	Lighting - Pendent/Surface	1st Floor	55	EA	6	\$6,814	
	Walls - Plaster/Drywall	1st Floor	15,846	SF	6	\$70,245	
	Walls - Structural Glazed Tile	1st Floor	277	SF	6	\$871	
	Ceiling - Plaster/Drywall	2nd Floor	6	SF	5	\$105	Peeling paint
	Ceiling - Plaster/Drywall	2nd Floor	6,710	SF	6	\$41,548	
	Drinking Fountains - Double Fountain	2nd Floor	4	EΑ	6	\$1,344	
	Floor - Terrazzo	2nd Floor	2,251	SF	6	\$18,895	
	Floor - Tile/Sheet	2nd Floor	5	SF	5		Damaged tiles
	Floor - Tile/Sheet	2nd Floor	4,460	SF	6	\$2,424	3
	Lighting - Pendent/Surface	2nd Floor	38	EA	6	\$4,708	
	Walls - Plaster/Drywall	2nd Floor	13,028	SF	6	\$57,753	
	Ceiling - Plaster/Drywall	3rd Floor	5,984	SF	6	\$37,052	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	\$174	Peeling paint
	Drinking Fountains - Double Fountain	3rd Floor	3	EA	6	\$1,008	.
	Floor - Terrazzo	3rd Floor	1,646	SF	6	\$13,817	
	Floor - Tile/Sheet	3rd Floor	4,348	SF	6	\$2,363	
	Lighting - Pendent/Surface	3rd Floor	32	EΑ	6	\$3,965	
	Walls - Plaster/Drywall	3rd Floor	10,776	SF	6	\$47,770	
Ctaina							
Stairs	Ceiling - Lay-in	Ctain by 400	572	SF		£4.740	
	Floor - Terrazzo	Stair by 109 Stair by 109	572 572	SF	6 6	\$1,718 \$4,801	
	Handrails	Stair by 109 Stair by 109	120	LF	6	\$1,040	
	Lighting - Pendent/Surface	Stair by 109	2	EA	7	\$1,040	
	Stairs - Terrazzo	Stair by 109 Stair by 109	60	LF	6	\$557	
	Walls - Plaster/Drywall	Stair by 109 Stair by 109	6,164	SF	6	\$17,012	
	Ceiling - Plaster/Drywall	stair by 103	572	SF	6	\$4,188	
	Floor - Terrazzo	stair by 111	572	SF	6	\$4,801	
	Handrails	stair by 111	120	LF	6	\$1,040	
	Lighting - Pendent/Surface	stair by 111	2	EA	7	\$0	
	Stairs - Terrazzo	stair by 111	60	LF	6	\$557	
	Walls - Plaster/Drywall	stair by 111	6,164	SF	6	\$17,012	
	Ceiling - Plaster/Drywall	Stair by ITT	476	SF	6	\$3,485	
	Floor - Terrazzo	Stair by library	476	SF	6	\$3,996	
	Handrails	Stair by library	120	LF	6	\$1,040	
	. 101.101.0110	Stall by library	120		•	Ψ1,0-10	



4540 N Hamlin Ave Chicago, IL 60625

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Stairs							
	Lighting - Pendent/Surface	Stair by library	6	EA	7	\$0	
	Stairs - Terrazzo	Stair by library	60	LF	6	\$557	
	Walls - Plaster/Drywall	Stair by library	5,224	SF	6	\$14,418	
	Ceiling - Plaster/Drywall	Stairs by 100	322	SF	6	\$2,358	
	Floor - Terrazzo	Stairs by 100	322	SF	6	\$2,703	
	Handrails	Stairs by 100	60	LF	6	\$520	
	Lighting - Pendent/Surface	Stairs by 100	3	EA	7	\$0	
	Stairs - Terrazzo	Stairs by 100	30	LF	6	\$278	
	Walls - Plaster/Drywall	Stairs by 100	1,856	SF	6	\$5,122	
	Ceiling - Plaster/Drywall	Stairs by 116	476	SF	6	\$3,485	
	Floor - Terrazzo	Stairs by 116	476	SF	6	\$3,996	
	Handrails	Stairs by 116	120	LF	6	\$1,040	
	Lighting - Pendent/Surface	Stairs by 116	6	EA	7	\$0	
	Stairs - Terrazzo	Stairs by 116	60	LF	6	\$557	
	Walls - Plaster/Drywall	Stairs by 116	5,244	SF	6	\$14,473	
	Ceiling - Plaster/Drywall	Stairs by 120	317	SF	6	\$2,321	
	Floor - Terrazzo	Stairs by 120	317	SF	6	\$2,661	
	Handrails	Stairs by 120	60	LF	6	\$520	
	Lighting - Pendent/Surface	Stairs by 120	5	EA	7	\$0	
	Stairs - Terrazzo	Stairs by 120	30	LF	6	\$278	
	Walls - Plaster/Drywall	Stairs by 120	1,856	SF	6	\$5,122	
Duildi	ing Interior Subtotal:					¢510 171	

Building Interior Subtotal:

\$519,171

Total Building Cost

\$8,301,200

Building: Addition

Category: Building Exterior

roup Item - Type L	ocation	Quantity	Unit	Rank	Cost	Comments
ntrance						
Exterior Doors - Exterior Steel Door #	[‡] 3 Exit N	2	EA	6	\$961	
Exterior Doors - Exterior Steel Door #	44 Exit E	2	EA	6	\$961	
Exterior Doors - Exterior Steel Door #	±5 E	1	EA	6	\$481	
Exterior Doors - Side lite #	t3 Exit N	2	EA	6	\$627	
Exterior Doors - Side lite #	44 Exit E	2	EA	6	\$627	
Exterior Doors - Transom Lite #	t3 Exit N	20	EA	6	\$6,266	



4540 N Hamlin Ave Chicago, IL 60625

Building: Addition

Category: Building Exterior

roup Item - Type	Locat	tion Quantit	/ Unit	Rank	Cost	Comments
intrance						
Exterior Doors - Transom Lite	#4 Ex	it E 20	EA	6	\$6,266	
oundation						
Foundation - Concrete	Entire	Building 322	LF	7	\$0	
Superstructure - Steel	Entire	Building 7,809	SF	7	\$0	
ighting						
Exterior Lighting - Wall Mounted	Entire	Building 2	EA	6	\$577	
coof System						
Chimney - Metal Flue	Main I	Roof 18	LF	6	\$2,847	
Coping - Stone	Main I	Roof 332	LF	6	\$10,663	
Downspouts - Exterior Downspouts	Main I	Roof 60	LF	6	\$1,994	
Parapet - 16" - 30" Height	Main I	Roof 332	LF	6	\$13,265	
Roof Structure - Steel with Clay Tile	Arch Main I	Roof 8,195	SF	7	\$0	
Roof - Asphalt Gravel Ballast	Main I	Roof 8,195	SF	5	\$193,478	Worn
/alls						
Exterior Walls - Brick	Entire	Building 7,122	SF	6	\$47,867	
Exterior Walls - Stone-Cast	Entire	Building 354	SF	6	\$2,379	
/indows						
Guard - Guards perforated	Entire	Building 599	SF	6	\$7,649	
Lintels - Steel	Entire	Building 78	LF	6	\$2,264	
Storefront Windows	Entire	Building 120	SF	6	\$1,345	
Windows - Sash Aluminum Double-	pane Entire	Building 60	SF	5	\$3,232	Not working well
Windows - Sash Aluminum Double-	pane Entire	Building 539	SF	6	\$4,023	
Building Exterior Subtotal:					\$307 773	

Building Exterior Subtotal:

\$307,773

Building: Addition

Category: Electrical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emergency System						
Emergency A/C Power - Corridors and Stairs	Entire Building	673	SF	6	\$202	
Emergency A/C Power - Lunchrooms	Entire Building	4,900	SF	6	\$1,822	
Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	\$405	
Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	6	\$203	



4540 N Hamlin Ave Chicago, IL 60625

Building: Addition

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	2	\$1,091	Exit signs have no emergency backup power source.
	Exit Signs - Lunchroom	Entire Building	7	EA	2	\$3,818	Exit signs have no emergency backup power source.
	Security System - Intrusion Detection	Entire Building	7,809	SF	6	\$2,010	detectors only
Main Se	ervice						
	PA System	Entire Building	7,809	SF	4	\$34,059	Service from Main to Addition is not working. Control console located in main.
Power I	Distribution						
	Lighting and Power Panels - Above 100 A	Cellar	3	EA	7	\$0	
	Main Distribution Panels - 400 - 600 amp	Cellar	1	EA	7	\$0	
Electr	ical System Subtotal:					\$43,610	

Building: Addition

Category: Safty System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm_System	Entire Building	7,809	SF	4	\$15,522	System is tied into the Main building's 45 years old service and cannot be upgraded to support strobe lights. Panel located in main.

Safty System Subtotal: \$15,522

Building: Addition

Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Air Handling Unit- Package Single Zone- Indoor- Electric and DX Cooling Coil - 8001-12000 cfm	Kitchen ceiling	1	EA	6	\$3,350	DX coil not yet installed.
	Air Intake	Kitchen ceiling / Roof	1	EA	6	\$5,765	
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Kitchen ceiling	1	EA	6	\$1,857	
Heating	Devices						
	Gas/ Natural Draft Furnace - 201 - 500 MBH	Kitchen ceiling	1	EA	5	\$9,615	
	Gas/ Natural Draft Furnace - 201 - 500 MBH	Kitchen ceiling	1	EA	5	\$9,615	
	Wall Heater - Electric	1st Floor	2	EA	7	\$0	



4540 N Hamlin Ave Chicago, IL 60625

Building: Addition

Category: Mechanical System

Group Item - Type		Location	Quantity	Unit	Rank	Cost C	Comments
Temperature Control							
Electric Controls		Entire Building	7,809	SF	6	\$0	
Electric Thermostat		Entire Building	3	EA	6	\$0	
Ventilation							
Exhaust Fans- Indoo	r - 500 - 1500 CFM	Roof / 1st Floor	1	EA	6	\$592	
Exhaust Fans- Roof	Mounted - 1501 - 8000 CFM	Roof	1	EA	6	\$592	
Exhaust Fans- Roof	Mounted - 500 - 1500 CFM	Roof	1	EA	6	\$592	
Exhaust Fans- Roof	Mounted - Less than 500 CFM	Roof	3	EΑ	6	\$889	

Mechanical System Subtotal:

\$32,868

Building: Addition

Category: Plumbing System

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
Hot Water						
Gas Heater - Less than 150000 BTU/HR	1st Floor	1	EA	6	\$310	
Piping						
Domestic Piping-Cold Water Horizontal Lines	Entire Building	7,809	SF	6	\$1,898	
Domestic Piping-Hot Water Horizontal Lines	Entire Building	7,809	SF	6	\$1,452	
Sanitary Piping	Entire Building	7,809	SF	7	\$0	
Storm Piping	Entire Building	7,809	SF	7	\$0	
Vent Piping	Entire Building	7,809	SF	7	\$0	

Plumbing System Subtotal:

\$3,660

Building: Addition

Group	Item - Type	Location	Quantity	Unit	Rank	Cost Commen
Admini	strative Suites/Offices					
	Ceiling - Lay-in	First floor kitchen office	55	SF	6	\$165
	Doors - Wood Doors inclu hw	First floor kitchen office	1	EA	6	\$301
	Floor - Tile/Sheet	First floor kitchen office	55	SF	6	\$55
	Lighting - Lay-in	First floor kitchen office	1	EA	7	\$0
	Power Distribution	First floor kitchen office	6	EA	6	\$12,749
	Walls - Plaster/Drywall	First floor kitchen office	232	SF	6	\$640

4540 N Hamlin Ave Chicago, IL 60625

Building: Addition

oup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
chen							
	Ceiling - Lay-in	1st Floor	1,286	SF	6	\$3,862	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	1,286	SF	6	\$1,287	
	Lighting - Lay-in	1st Floor	13	EA	7	\$0	
	Walls - Plaster/Drywall	1st Floor	2,071	SF	6	\$5,716	
nch 8	& Multipurpose Room						
	Ceiling - Lay-in	First floor north end staff lunch break room	473	SF	6	\$1,420	
	Doors - Steel Doors incl hw	First floor north end staff lunch break room	1	EA	6	\$301	
	Floor - Tile/Sheet	First floor north end staff lunch break room	473	SF	6	\$473	
	Lighting - Lay-in	First floor north end staff lunch break room	11	EA	6	\$1,309	
	Walls - Plaster/Drywall	First floor north end staff lunch break room	1,270	SF	6	\$3,505	
	Ceiling - Lay-in	Lunch room and servery	4,015	SF	6	\$12,057	
	Ceiling - Plaster/Drywall	Lunch room and servery	885	SF	6	\$3,063	
	Doors - Steel Doors incl hw	Lunch room and servery	6	EA	6	\$1,806	
	Floor - Tile/Sheet	Lunch room and servery	4,900	SF	6	\$4,905	
	Lighting - Lay-in	Lunch room and servery	42	EA	7	\$0	
	Serving Line	Lunch room and servery	42	LF	6	\$2,500	
	Walls - Concrete Block	Lunch room and servery	2,990	SF	6	\$8,765	
	Walls - Plaster/Drywall	Lunch room and servery	3,624	SF	6	\$10,002	
stroo	om						
	Accessories	First floor south end kitchen staff bathroom	69	SF	6	\$636	
	Ceiling - Lay-in	First floor south end kitchen staff bathroom	69	SF	6	\$207	
	Doors - Wood Doors inclu hw	First floor south end kitchen staff bathroom	1	EA	6	\$301	
	Floor Drain	First floor south end kitchen staff bathroom	1	EA	6	\$1,059	
	Floor - Tile/Sheet	First floor south end kitchen staff bathroom	69	SF	6	\$69	
	Lavatory	First floor south end kitchen staff bathroom	4	EA	6	\$1,278	
	Lighting - Lay-in	First floor south end kitchen staff bathroom	2	EA	7	\$0	



4540 N Hamlin Ave Chicago, IL 60625

Building: Addition

Category: Rooms (Other Than Classrooms)

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments
Restroom					
Student Lockers - One Tier	First floor south end kitchen staff bathroom	4	EA	6	\$371
Walls - Plaster/Drywall	First floor south end kitchen staff bathroom	316	SF	6	\$872
Water Closet	First floor south end kitchen staff bathroom	1	EA	6	\$336

Rooms (Other Than Classrooms) Subtotal:

\$80,313

Building: Addition

Category: Building Interior

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
Corridor						
Ceiling - Lay-in	1st Floor	673	SF	6	\$2,021	
Floor - Tile/Sheet	1st Floor	673	SF	6	\$366	
Lighting - Lay-in	1st Floor	13	EA	7	\$0	
Walls - Plaster/Drywall	1st Floor	994	SF	6	\$4,406	
					A0.700	
Building Interior Subtotal:					\$6,793	

Building Interior Subtotal:

\$490,539

Total Building Cost

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Civil/Dr	rainage						
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	\$4,375	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	\$5,971	
Fencing	g						
	Fencing - Chain Link	Entire Site / Site - East	22	LF	6	\$413	
	Fencing - Guard Rail	Entire Site / Site - East	59	LF	6	\$682	
	Fencing - New Standard Ornamental	Entire Site	924	LF	6	\$29,479	South, west, north perimeter
	Fencing - New Standard Ornamental	Entire Site / East	777	LF	6	\$24,789	
Landsc	rape						
	Landscape - Grass	Entire Site / Site - East	6,639	SF	6	\$5,506	
	Landscape - Hardscape- Asphalt	Entire Site	12	SF	4	\$95	Playground southwest corner: potholes



4540 N Hamlin Ave Chicago, IL 60625

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Landsc	аре						
	Landscape - Hardscape- Concrete	Entire Site	5,616	SF	6	\$28,991	
	Parkway trees	Entire Site	49	EA	6	\$32,342	
	Planting Beds/ Area	Entire Site / East	4,237	SF	6	\$6,968	
	Play Area - Asphalt/ Hardscape	Entire Site / North East	19,624	SF	5	\$102,427	Need seal coating
	Play Area - Asphalt/ Hardscape	Entire Site / South East	20,884	SF	6	\$58,235	
	Play Area - Asphalt/ Hardscape	Entire Site / South West	2,446	SF	6	\$7,695	
	Trash Receptacles	Entire Site / East Courtyard	1	EA	6	\$312	
Parking	Lot						
	Surface - Asphalt	West / Parking Lot	31,152	SF	6	\$75,285	
	Surface - Concrete	West / Site - East	1,966	SF	6	\$4,751	Trash enclosure
	Trash Enclosure - Chain Links	West / East Courtyard	1,623	SF	6	\$28,477	
Playgro	und						
	Equipment - School Age 5-12	SW Courtyard / South West	2	EA	6	\$7,092	
	Surface - Square Rubber Mats	SW Courtyard / South West	300	SF	5	\$3,029	Damaged
Sidewal	ks						
	Sidewalks - Internal Walks	Entire Site	346	LF	6	\$4,156	
	Sidewalks - Perimeter Sidewalks	Entire Site	16,136	SF	6	\$32,074	
Signage	9						
	Flag Pole - Flag Pole	East Courtyard / East	1	EA	6	\$1,657	
	Marquee - Free Standing Back Lighted	East Courtyard / North East	1	EA	6	\$0	
Site S	ubtotal:					\$464,802	
Total	Site Cost					\$464,802	

Campus Total ^{2 3} \$9,256,541

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.



4540 N Hamlin Ave Chicago, IL 60625

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



4540 N Hamlin Ave Chicago, IL 60625

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main														-
Art Room	Regular Classroom	3rd Floor	308	306	946	0	0	8	140	70	40	N	Υ	Υ
Computer Lab	Regular Classroom	3rd Floor	310	308	932	0	0	8	120	60	40	N	Υ	N
Kindergarten	Kindergarten	1st Floor	118	Kindergarten	1,180	0	0	8	120	40	40	N	Υ	N
Pre School	Pre School	1st Floor	101	Reading Clinic	923	0	0	8	120	40	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	100	101	1,080	0	0	8	120	40	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	102	102	985	0	0	8	120	40	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	108	Storage by 104	623	0	0	8	80	40	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	112	105	923	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	113	108	839	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	114	106	923	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	115	109	839	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	116	107	761	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	117	110	985	0	0	8	120	40	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	119	111	923	0	0	8	120	40	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	120	Kindergarten	823	0	0	8	120	40	40	N	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	200	201	917	0	0	12	138	45	40	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	202	917	0	0	12	138	45	40	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	203	820	0	0	9	138	45	40	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	203	204	820	0	0	9	138	45	40	Υ	Υ	N
Regular Classroom	Other Instructional Use		205	205	795	0	0	14	115	38	40	Υ	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	207	820	0	0	7	115	38	40	Υ	Υ	N
Regular Classroom	Regular Classroom		207	206	785	0	0	10	115	38	40	Υ	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	209	808	0	0	9	115	38	40	Υ	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	208	862	0	0	12	115	38	40	Υ	Υ	N
Regular Classroom	Other Instructional Use	2nd Floor	210	210	862	0	0	12	115	38	40	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	862	0	0	13	115	38	40	Υ	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	213	862	0	0	8	115	38	40	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	215	214	862	0	0	16	115	38	40	Υ	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	215	862	0	0	10	115	38	40	Υ	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	216	795	0	0	10	115	38	40	Υ	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	217	753	0	0	7	115	38	40	Υ	N	N
Regular Classroom	Regular Classroom	2nd Floor	219	218	795	0	0	9	115	38	40	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	220	219	808	0	0	9	115	38	40	Υ	N	N
Regular Classroom	Regular Classroom	2nd Floor	222	220	820	0	0	7	138	45	40	Υ	N	N
Regular Classroom	Regular Classroom	2nd Floor	223	221	820	0	0	9	138	45	40	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	224	222	917	0	0	7	138	45	40	Υ	N	N
Regular Classroom	Regular Classroom	2nd Floor	225	223	917	0	0	9	138	45	40	Υ	Υ	N



4540 N Hamlin Ave Chicago, IL 60625

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main				+	*	•		*			*			*
Regular Classroom	Regular Classroom	3rd Floor	302	301	900	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	302	900	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	305	303	900	0	0	8	120	60	40	Υ	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	306	304	946	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	307	305	946	0	0	8	120	60	40	Υ	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	309	307	932	0	0	8	120	60	40	Υ	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	311	309	946	0	0	8	120	60	40	Υ	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	312	311	839	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	313	310	839	0	0	8	120	60	40	Υ	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	314	312	839	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	315	313	839	0	0	8	120	60	40	N	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	316	314	839	0	0	8	120	60	40	Υ	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	318	315	833	0	0	9	138	45	40	Υ	N	N
Regular Classroom	Regular Classroom	3rd Floor	319	316	833	0	0	9	138	45	40	Υ	N	N
Regular Classroom	Regular Classroom	3rd Floor	320	318	928	0	0	9	138	45	40	Υ	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	321	317	925	0	0	9	138	45	40	Υ	Υ	N
Science Classroom	Regular Classroom	3rd Floor	303	300	839	0	0	8	120	60	40	Υ	Υ	N
Vacant	Regular Classroom	2nd Floor	213	212	862	0	0	11	115	38	40	Υ	N	N