

## Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition<sup>1</sup>. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at [http://www.cps.edu/About\\_CPS/Policies\\_and\\_guidelines/Pages/facilitystandards.aspx](http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx). Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1960	2	49,043	\$2,632,514
SITE				\$222,649
<b>Campus Total</b>			<b>49,043</b>	<b>\$2,855,163</b>

### Building: Main

#### Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
	Entrance Control - Audio and Video	1 / North Entrances	1	EA	6	\$702	
	Exterior Doors - Exterior FRP Door	11 / West Entrances	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	1 / North Entrances	2	EA	6	\$1,263	
	Exterior Doors - Exterior FRP Door	2 / East Entrances	2	EA	7	\$0	
	Exterior Doors - Exterior Steel Door	10 / South Entrances	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	3 / South Entrances	1	EA	5	\$1,341	dented
	Exterior Doors - Exterior Steel Door	4 / South Entrances	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	5 / South Entrances	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	6 / South Entrances	2	EA	6	\$961	
	Exterior Doors - Exterior Steel Door	7 / South Entrances	1	EA	6	\$481	
	Exterior Doors - Exterior Steel Door	8 / West Entrances	1	EA	6	\$481	top of exterior staircase chainlink gate is chained shut
	Exterior Doors - Exterior Steel Door	9 / South Entrances	2	EA	6	\$961	
	Exterior Doors - Side lite	11 / West Entrances	2	EA	6	\$627	egress inhibited by gate
	Exterior Doors - Side lite	1 / North Entrances	2	EA	6	\$627	
	Exterior Doors - Side lite	2 / East Entrances	2	EA	6	\$627	
	Exterior Doors - Transom Lite	11 / West Entrances	2	EA	6	\$627	
	Exterior Doors - Transom Lite	1 / North Entrances	2	EA	6	\$627	
	Exterior Doors - Transom Lite	2 / East Entrances	2	EA	6	\$627	
	Exterior Stairs - Concrete	8 / West Entrances	44	LF	6	\$3,598	
	Stair Handrail - Steel_Stair Handrail	8 / West Entrances	20	LF	6	\$173	

**Building: Main**

**Category: Building Exterior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Entrance</b>							
<b>Foundation</b>							
	Foundation - Concrete	Entire Building	1,330	LF	7	\$0	
	Superstructure - Concrete	Entire Building	49,043	SF	7	\$0	
<b>Lighting</b>							
	Exterior Lighting - Wall Mounted	Entire Building	18	EA	6	\$5,197	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	5	\$1,710	
<b>Roof System</b>							
	Chimney - Metal Flue	A	20	LF	6	\$3,163	
	Coping - Metal	A	569	LF	6	\$18,275	gravel stop
	Coping - Metal	B	200	LF	6	\$6,424	gravel stop
	Downspouts - Interior Downspouts	A	72	LF	5	\$15,934	
	Downspouts - Interior Downspouts	B	30	LF	5	\$6,639	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	A	23,309	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	B	1,875	SF	7	\$0	
	Roof - Asphalt Gravel Ballast	A	22,309	SF	6	\$226,822	
	Roof - Asphalt Gravel Ballast	A	1,000	SF	4	\$52,996	ponding
	Roof - Modified Bitumen	B	400	SF	4	\$10,965	ponding
	Roof - Modified Bitumen	B	1,475	SF	6	\$13,879	
<b>Walls</b>							
	Exterior Walls - Brick	Entire Building	5,216	SF	5	\$92,714	minor mortar deterioration
<b>Windows</b>							
	Curtain wall - Insulated Panel	Entire Building	4,512	SF	5	\$168,982	dents throughout
	Curtain wall - Louver	Entire Building	300	SF	6	\$3,363	
	Curtain wall - Windows	Entire Building	7,972	SF	5	\$507,754	failing sealant, some windows inoperable
	Guard - Guards perforated	Entire Building / 1st Floor	4,124	SF	7	\$0	
	Lintels - Steel	Entire Building / South	78	LF	6	\$2,264	
	Skylite - Lexan	Entire Building	275	SF	7	\$0	
	Windows - Sash Aluminum Double-pane	Entire Building / South	288	SF	5	\$15,514	failing sealant, some windows inoperable
<b>Building Exterior Subtotal:</b>						<b>\$1,169,501</b>	

**Building: Main**

**Category: Electrical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

**Building: Main**

**Category: Electrical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Emergency System</b>							
	Automatic Transfer Switch	Boiler Room	1	EA	6	\$408	Switch is greater than 20 years of age
	Emergency Battery Packs - Corridors and Stairs	Entire Building	16	EA	6	\$3,240	
	Emergency Battery Packs - Gym	Entire Building / 1st Floor	4	EA	6	\$810	
	Emergency Battery Packs - Lunchrooms	Entire Building / 1st Floor	1	EA	6	\$203	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	\$810	
	Exit Signs - Corridors and Stairs	Entire Building	14	EA	6	\$2,096	
	Exit Signs - Gym	Entire Building / 1st Floor	6	EA	6	\$945	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	\$299	
	Security System - Intrusion Detection	Boiler Room	49,043	SF	6	\$12,624	
<b>Main Service</b>							
	Independent Electrical Service for emergency power	Boiler Room	1	EA	6	\$2,921	
	Main Electrical Service - 1000 A 120/208/3PH	Boiler Room	1	EA	6	\$4,540	No other information available on unit
	PA System	Entire Building	49,043	SF	6	\$16,130	
<b>Power Distribution</b>							
	Lighting and Power Panels - 100 A	Entire Building	7	EA	6	\$2,094	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	6	\$2,982	
	Main Distribution Panels - Greater than 600 amp	Entire Building / Boiler Room	1	EA	6	\$730	
<b>Electrical System Subtotal:</b>						<b>\$50,832</b>	

**Building: Main**

**Category: Safty System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Fire Alarm</b>							
	Fire Alarm Panel	Boiler Room	1	EA	6	\$6,406	
	Fire Alarm Strobe Lights	Boiler Room / Entire Building	49,043	SF	4	\$66,625	
	Fire Alarm_System	Boiler Room / Entire Building	49,043	SF	5	\$54,703	
<b>Safty System Subtotal:</b>						<b>\$127,733</b>	

**Building: Main**

**Category: Mechanical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-------	-------------	----------	----------	------	------	------	----------

## Building: Main

### Category: Mechanical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Air Handling Systems</b>							
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm	Entire Building	4	EA	6	\$13,400	
	Air Intake	Entire Building / South Façade	1	EA	6	\$5,765	
	Air Intake	Entire Building / West Façade	1	EA	6	\$5,765	
<b>Boiler Systems</b>							
	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	Boiler Room	2	EA	6	\$4,093	Boilers in good condition. No leaks
	Chemical Pot Feeder	Boiler Room	1	EA	7	\$0	
	Combustion Dampers	Boiler Room	2	EA	6	\$818	
	Glycol Feed System	Boiler Room	1	EA	7	\$0	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH	Boiler Room	2	EA	6	\$1,996	Boilers operate well and are have more than enough capacity
<b>Gas Booster</b>							
	Gas Booster	Boiler Room	2	EA	5	\$25,186	Gas boosters leak gas and are not used
<b>Heating Devices</b>							
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	\$1,417	
	Fin Tube - Hot Water	Entire Building	177	LF	6	\$1,671	
	Wall Heater - Electric	Entire Building	3	EA	5	\$1,610	Routine Maintenance
<b>Mechanical Plumbing</b>							
	Hot Water Pump - Less than 10	Boiler Room	4	EA	6	\$4,445	
	Hydronic Supply and Return - Steel	Entire Building	600	LF	6	\$46,066	HW supply and return
<b>Temperature Control</b>							
	DDC System	Entire Building	49,043	SF	6	\$28,053	
	Thermostats - DDC	Entire Building	37	EA	6	\$0	
<b>Unit Ventilation</b>							
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	32	EA	6	\$39,927	
<b>Ventilation</b>							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building / 1st Floor	1	EA	6	\$592	3000 CFM
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / 1st Floor	1	EA	6	\$592	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building / 1st Floor	1	EA	6	\$592	617 CFM
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	4	EA	6	\$2,370	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	6	\$592	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	4	EA	6	\$1,185	
	Type I Exhaust Hood- Kitchen	Entire Building / 1st Floor	1	EA	2	\$28,265	

**Building: Main**

**Category: Mechanical System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Mechanical System Subtotal:</b>						<b>\$214,399</b>	

**Building: Main**

**Category: Plumbing System**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Hot Water</b>							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	\$2,249	It has visible signs of deterioration of the casing. 1996

**Piping**

	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	49,043	SF	6	\$9,818	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	49,043	SF	6	\$11,922	
	Domestic Piping-Cold Water Risers	Entire Building	49,043	SF	6	\$9,117	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	49,043	SF	6	\$7,714	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	49,043	SF	6	\$9,117	
	Domestic Piping-Hot Water Return Lines	Entire Building	49,043	SF	6	\$7,013	
	Domestic Piping-Hot Water Return Risers	Entire Building	49,043	SF	6	\$7,013	
	Sanitary Piping	Entire Building	49,043	SF	6	\$44,884	
	Storm Piping	Entire Building	49,043	SF	6	\$42,780	
	Vent Piping	Entire Building	49,043	SF	6	\$32,962	

**Plumbing System Subtotal:**

**\$184,591**

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #100 (Counseling Room)</b>							
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	5	\$5,018	
	Ceiling - Plaster/Drywall	1st Floor	557	SF	6	\$1,928	
	Chalk Board	1st Floor	9	LF	4	\$826	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	557	SF	5	\$2,501	Missing tiles and cracks
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Marker Board	1st Floor	11	LF	6	\$236	Exposed metal edges
	Walls - Concrete Block	1st Floor	499	SF	6	\$1,463	
	Walls - Plaster/Drywall	1st Floor	220	SF	6	\$607	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #101 (Kindergarten)</b>							
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	40	LF	5	\$8,363	
	Ceiling - Plaster/Drywall	1st Floor	1,271	SF	6	\$4,398	
	Doors - Side-lite	1st Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	1,271	SF	6	\$1,272	
	Lighting - Pendent/Surface	1st Floor	43	EA	6	\$5,327	
	Marker Board	1st Floor	10	LF	6	\$214	
	Storage/ Closet	1st Floor	83	SF	6	\$602	
	Walls - Concrete Block	1st Floor	939	SF	6	\$2,753	
	Walls - Plaster/Drywall	1st Floor	161	SF	7	\$0	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #102 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	5	\$5,018	Deteriorated and stained
	Ceiling - Plaster/Drywall	1st Floor	850	SF	6	\$2,942	
	Chalk Board	1st Floor	22	LF	4	\$2,020	Obsolete material
	Doors - Side-lite	1st Floor	11	SF	6	\$184	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	850	SF	5	\$3,817	
	Lighting - Pendent/Surface	1st Floor	26	EA	7	\$0	
	Marker Board	1st Floor	28	LF	7	\$0	
	Storage/ Closet	1st Floor	12	SF	6	\$87	
	Walls - Concrete Block	1st Floor	363	SF	6	\$1,064	
	Walls - Plaster/Drywall	1st Floor	575	SF	7	\$0	
	Work Sink	1st Floor	1	EA	5	\$1,508	
<b>Classroom #103 (Kindergarten)</b>							
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	44	LF	6	\$1,111	Covered with plastic
	Ceiling - Plaster/Drywall	1st Floor	1,271	SF	6	\$4,398	Mismatched tile floor
	Doors - Side-lite	1st Floor	22	SF	6	\$368	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	\$602	
	Floor - Tile/Sheet	1st Floor	1,271	SF	6	\$1,272	Cracking
	Lighting - Pendent/Surface	1st Floor	45	EA	7	\$0	
	Marker Board	1st Floor	22	LF	7	\$0	
	Storage/ Closet	1st Floor	83	SF	6	\$602	Missing lens

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #103 (Kindergarten)</b>							
	Walls - Concrete Block	1st Floor	939	SF	6	\$2,753	
	Walls - Plaster/Drywall	1st Floor	161	SF	7	\$0	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #104 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	4	\$11,140	Overall, deteriorated, stained and delaminating.
	Ceiling - Plaster/Drywall	1st Floor	849	SF	7	\$0	
	Chalk Board	1st Floor	22	LF	4	\$2,020	Obsolete material
	Doors - Side-lite	1st Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	849	SF	6	\$850	
	Lighting - Pendent/Surface	1st Floor	25	EA	7	\$0	
	Marker Board	1st Floor	28	LF	6	\$600	
	Storage/ Closet	1st Floor	12	SF	6	\$87	
	Walls - Plaster/Drywall	1st Floor	943	SF	5	\$7,147	Damage wall near entry
	Work Sink	1st Floor	1	EA	5	\$1,508	
<b>Classroom #106 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	6	\$606	
	Ceiling - Plaster/Drywall	1st Floor	840	SF	6	\$2,907	
	Chalk Board	1st Floor	22	LF	4	\$2,020	
	Doors - Side-lite	1st Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile	1st Floor	840	SF	5	\$3,772	
	Lighting - Pendent/Surface	1st Floor	25	EA	6	\$3,097	
	Marker Board	1st Floor	28	LF	7	\$0	
	Storage/ Closet	1st Floor	12	SF	6	\$87	
	Walls - Plaster/Drywall	1st Floor	928	SF	5	\$7,033	Cracks on east wall
	Work Sink	1st Floor	1	EA	5	\$1,508	
<b>Classroom #108 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	6	\$606	
	Ceiling - Plaster/Drywall	1st Floor	842	SF	6	\$2,914	
	Chalk Board	1st Floor	22	LF	4	\$2,020	
	Doors - Side-lite	1st Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #108 (Regular Classroom)</b>							
	Floor - Tile/Sheet	1st Floor	842	SF	5	\$3,781	
	Lighting - Pendent/Surface	1st Floor	25	EA	7	\$0	
	Marker Board	1st Floor	28	LF	6	\$600	
	Storage/ Closet	1st Floor	12	SF	6	\$87	
	Walls - Plaster/Drywall	1st Floor	928	SF	6	\$2,561	
	Work Sink	1st Floor	1	EA	5	\$1,508	
<b>Classroom #110 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	5	\$5,018	
	Ceiling - Plaster/Drywall	1st Floor	854	SF	6	\$2,955	
	Chalk Board	1st Floor	22	LF	4	\$2,020	
	Doors - Side-lite	1st Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	854	SF	6	\$855	
	Lighting - Pendent/Surface	1st Floor	31	EA	7	\$0	
	Marker Board	1st Floor	22	LF	7	\$0	
	Storage/ Closet	1st Floor	13	SF	6	\$94	
	Walls - Plaster/Drywall	1st Floor	943	SF	6	\$2,603	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #112 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	7	\$0	Toilet paper dispenser
	Casework	1st Floor	24	LF	5	\$5,018	
	Ceiling - Plaster/Drywall	1st Floor	850	SF	6	\$2,942	
	Chalk Board	1st Floor	22	LF	4	\$2,020	
	Doors - Side-lite	1st Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	850	SF	6	\$851	
	Lighting - Pendent/Surface	1st Floor	32	EA	6	\$3,965	
	Marker Board	1st Floor	22	LF	6	\$471	
	Storage/ Closet	1st Floor	12	SF	6	\$87	
	Walls - Plaster/Drywall	1st Floor	943	SF	6	\$2,603	
	Work Sink	1st Floor	1	EA	6	\$379	
<b>Classroom #114 (Regular Classroom)</b>							
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	5	\$5,018	
	Ceiling - Plaster/Drywall	1st Floor	850	SF	6	\$2,942	



**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #114 (Regular Classroom)</b>							
	Chalk Board	1st Floor	22	LF	4	\$2,020	
	Doors - Side-lite	1st Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	850	SF	6	\$851	
	Lighting - Pendent/Surface	1st Floor	26	EA	7	\$0	
	Marker Board	1st Floor	28	LF	7	\$0	
	Storage/ Closet	1st Floor	12	SF	6	\$87	
	Walls - Plaster/Drywall	1st Floor	943	SF	7	\$0	
	Work Sink	1st Floor	1	EA	5	\$1,508	
<b>Classroom #201 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	50	LF	5	\$10,454	
	Ceiling - Lay-in	2nd Floor	1,094	SF	6	\$3,285	
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	1,094	SF	6	\$1,095	
	Lighting - Pendent/Surface	2nd Floor	35	EA	6	\$4,336	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Concrete Block	2nd Floor	186	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	889	SF	6	\$2,454	
	Work Sink	2nd Floor	1	EA	6	\$379	
<b>Classroom #202 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	22	LF	6	\$556	
	Ceiling - Plaster/Drywall	2nd Floor	854	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	Obsolete material
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	854	SF	6	\$855	
	Lighting - Pendent/Surface	2nd Floor	31	EA	6	\$3,841	
	Marker Board	2nd Floor	22	LF	6	\$471	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Concrete Block	2nd Floor	367	SF	6	\$1,076	
	Walls - Plaster/Drywall	2nd Floor	531	SF	6	\$1,466	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #203 (Regular Classroom)</b>							
	AC Units	2nd Floor	2	EA	7	\$0	
	Casework	2nd Floor	50	LF	5	\$10,454	
	Ceiling - Plaster/Drywall	2nd Floor	1,094	SF	7	\$0	
	Chalk Board	2nd Floor	12	LF	4	\$1,102	Obsolete material
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	1,094	SF	6	\$1,095	
	Lighting - Pendent/Surface	2nd Floor	35	EA	6	\$4,336	Missing lens
	Marker Board	2nd Floor	20	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Plaster/Drywall	2nd Floor	1,175	SF	6	\$3,243	
	Work Sink	2nd Floor	1	EA	7	\$0	
<b>Classroom #204 (Regular Classroom)</b>							
	AC Units		1	EA	7	\$0	
	Casework		24	LF	5	\$5,018	
	Ceiling - Plaster/Drywall		854	SF	6	\$2,955	
	Chalk Board		22	LF	4	\$2,020	Obsolete material
	Doors - Side-lite		11	SF	6	\$184	
	Doors - Steel Doors incl hw		1	EA	6	\$301	
	Floor - Tile/Sheet		854	SF	6	\$855	
	Lighting - Pendent/Surface		31	EA	7	\$0	
	Marker Board		22	LF	7	\$0	
	Storage/ Closet		13	SF	6	\$94	
	Walls - Plaster/Drywall		998	SF	6	\$2,754	
<b>Classroom #205 (Library)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	60	LF	6	\$1,515	
	Ceiling - Plaster/Drywall	2nd Floor	849	SF	6	\$2,938	
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	849	SF	6	\$850	
	Lighting - Pendent/Surface	2nd Floor	31	EA	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Concrete Block	2nd Floor	140	SF	6	\$410	
	Walls - Plaster/Drywall	2nd Floor	858	SF	6	\$2,368	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #206 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	24	LF	5	\$5,018	
	Ceiling - Plaster/Drywall	2nd Floor	854	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	Obsolete material
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	854	SF	6	\$855	
	Lighting - Pendent/Surface	2nd Floor	31	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Plaster/Drywall	2nd Floor	997	SF	6	\$2,752	
<b>Classroom #207 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	24	LF	5	\$5,018	
	Ceiling - Plaster/Drywall	2nd Floor	854	SF	7	\$0	
	Chalk Board	2nd Floor	12	LF	4	\$1,102	
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	854	SF	6	\$855	
	Lighting - Pendent/Surface	2nd Floor	31	EA	6	\$3,841	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Concrete Block	2nd Floor	140	SF	6	\$410	
	Walls - Plaster/Drywall	2nd Floor	858	SF	6	\$2,368	
<b>Classroom #208 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	24	LF	5	\$5,018	
	Ceiling - Plaster/Drywall	2nd Floor	854	SF	6	\$2,955	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	Obsolete material
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	854	SF	6	\$855	
	Lighting - Pendent/Surface	2nd Floor	31	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Plaster/Drywall	2nd Floor	998	SF	7	\$0	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #209 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	24	LF	6	\$606	
	Ceiling - Lay-in	2nd Floor	854	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	Obsolete material
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	854	SF	5	\$3,835	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Concrete Block	2nd Floor	140	SF	6	\$410	
	Walls - Plaster/Drywall	2nd Floor	858	SF	6	\$2,368	
<b>Classroom #210 (Computer Lab)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	24	LF	6	\$606	
	Ceiling - Lay-in	2nd Floor	854	SF	6	\$2,565	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	854	SF	6	\$855	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Plaster/Drywall	2nd Floor	998	SF	6	\$2,754	
	Wireless System	2nd Floor	1	EA	7	\$0	
<b>Classroom #211 (Music Room)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	24	LF	6	\$606	
	Ceiling - Lay-in	2nd Floor	854	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	854	SF	6	\$855	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	\$0	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #211 (Music Room)</b>							
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Concrete Block	2nd Floor	140	SF	6	\$410	
	Walls - Plaster/Drywall	2nd Floor	858	SF	5	\$6,503	
<b>Classroom #212 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	24	LF	6	\$606	
	Ceiling - Lay-in	2nd Floor	854	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	Obsolete material
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	854	SF	6	\$855	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	6	\$471	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Plaster/Drywall	2nd Floor	998	SF	6	\$2,754	
<b>Classroom #213 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	24	LF	5	\$5,018	
	Ceiling - Lay-in	2nd Floor	850	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	Obsolete material
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	850	SF	6	\$851	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Concrete Block	2nd Floor	140	SF	6	\$410	
	Walls - Plaster/Drywall	2nd Floor	858	SF	6	\$2,368	
<b>Classroom #214 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	24	LF	6	\$606	
	Ceiling - Lay-in	2nd Floor	850	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	Obsolete material

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #214 (Regular Classroom)</b>							
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	850	SF	5	\$3,817	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Plaster/Drywall	2nd Floor	998	SF	7	\$0	
<b>Classroom #215 (Science)</b>							
	AC Units	2nd Floor	2	EA	7	\$0	
	Casework	2nd Floor	50	LF	6	\$1,263	
	Ceiling - Lay-in	2nd Floor	1,094	SF	6	\$3,285	
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	1,094	SF	6	\$1,095	
	Lighting - Pendent/Surface	2nd Floor	35	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Plaster/Drywall	2nd Floor	889	SF	6	\$2,454	
	Work Sink	2nd Floor	1	EA	7	\$0	
<b>Classroom #216 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	3	LF	5	\$627	
	Casework	2nd Floor	21	LF	6	\$530	
	Ceiling - Lay-in	2nd Floor	878	SF	7	\$0	
	Chalk Board	2nd Floor	22	LF	4	\$2,020	Obsolete material
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	878	SF	6	\$879	
	Lighting - Lay-in	2nd Floor	15	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	Peeling paint
	Walls - Concrete Block	2nd Floor	339	SF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	678	SF	6	\$1,871	

**Building: Main**

**Category: Classrooms**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Classroom #217 (Regular Classroom)</b>							
	AC Units	2nd Floor	1	EA	7	\$0	
	Casework	2nd Floor	45	LF	7	\$0	
	Ceiling - Lay-in	2nd Floor	1,094	SF	7	\$0	
	Chalk Board	2nd Floor	12	LF	4	\$1,102	Obsolete material
	Doors - Side-lite	2nd Floor	11	SF	6	\$184	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor	1,094	SF	5	\$4,912	
	Lighting - Lay-in	2nd Floor	20	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	6	\$428	
	Storage/ Closet	2nd Floor	13	SF	6	\$94	
	Walls - Concrete Block	2nd Floor	358	SF	6	\$1,049	
	Walls - Plaster/Drywall	2nd Floor	717	SF	7	\$0	
	Work Sink	2nd Floor	1	EA	7	\$0	

**Classrooms Subtotal:**

**\$364,344**

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	AC Unit	116 - Teachers Lounge	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	116 - Teachers Lounge	596	SF	7	\$0	
	Doors - Side-lite	116 - Teachers Lounge	11	SF	6	\$184	
	Doors - Steel Doors incl hw	116 - Teachers Lounge	1	EA	6	\$301	
	Floor - Tile/Sheet	116 - Teachers Lounge	596	SF	6	\$597	
	Lighting - Pendent/Surface	116 - Teachers Lounge	17	EA	7	\$0	
	Storage/ Closet	116 - Teachers Lounge	265	SF	6	\$1,921	
	Walls - Plaster/Drywall	116 - Teachers Lounge	943	SF	6	\$2,603	
	Ceiling - Plaster/Drywall	1st Flr-PD Office-138	196	SF	6	\$678	
	Doors - Steel Doors incl hw	1st Flr-PD Office-138	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Flr-PD Office-138	196	SF	6	\$196	
	Lighting - Pendent/Surface	1st Flr-PD Office-138	2	EA	6	\$248	
	Walls - Concrete Block	1st Flr-PD Office-138	264	SF	6	\$774	
	Ceiling - Plaster/Drywall	229	104	SF	6	\$360	
	Doors - Steel Doors incl hw	229	1	EA	6	\$301	
	Floor - Tile/Sheet	229	104	SF	6	\$104	
	Lighting - Pendent/Surface	229	2	EA	7	\$0	

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Walls - Plaster/Drywall	229	308	SF	6	\$850	
	Ceiling - Plaster/Drywall	231	105	SF	6	\$363	
	Doors - Steel Doors incl hw	231	1	EA	6	\$301	
	Floor - Tile/Sheet	231	105	SF	6	\$105	
	Lighting - Pendent/Surface	231	2	EA	7	\$0	
	Walls - Plaster/Drywall	231	308	SF	6	\$850	
	Ceiling - Plaster/Drywall	232	105	SF	6	\$363	
	Doors - Steel Doors incl hw	232	1	EA	6	\$301	
	Floor - Tile/Sheet	232	105	SF	6	\$105	
	Lighting - Pendent/Surface	232	2	EA	6	\$248	
	Walls - Plaster/Drywall	232	308	SF	6	\$850	
	Ceiling - Plaster/Drywall	Kitchen Office	58	SF	5	\$532	
	Doors - Steel Doors incl hw	Kitchen Office	1	EA	6	\$301	
	Floor - Concrete	Kitchen Office	58	SF	6	\$31	
	Lighting - Pendent/Surface	Kitchen Office	1	EA	7	\$0	
	Walls - Concrete Block	Kitchen Office	190	SF	6	\$557	
	Walls - Plaster/Drywall	Kitchen Office	32	SF	5	\$243	
	AC Unit	Main Office	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	Main Office	468	SF	7	\$0	
	Doors - Side-lite	Main Office	133	SF	6	\$2,223	
	Doors - Store Front	Main Office	1	EA	5	\$2,969	
	Floor - Terrazzo	Main Office	154	SF	5	\$5,796	Large crack
	Floor - Tile/Sheet	Main Office	314	SF	5	\$1,410	Significant wear and cracking
	Lighting - Pendent/Surface	Main Office	11	EA	7	\$0	
	Storage/ Closet	Main Office	9	SF	5	\$145	
	Walls - Plaster/Drywall	Main Office	560	SF	6	\$1,546	
	Work Slnk	Main Office	1	EA	6	\$508	
	AC Unit	Mechanical Office	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	Mechanical Office	80	SF	7	\$0	
	Doors - Steel Doors incl hw	Mechanical Office	1	EA	5	\$1,174	
	Floor - Concrete Epoxy/ Painted	Mechanical Office	80	SF	5	\$137	
	Lighting - Pendent/Surface	Mechanical Office	2	EA	7	\$0	
	Walls - Concrete Block	Mechanical Office	249	SF	6	\$730	
	AC Unit	Rm 117 - Principal's Office	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	Rm 117 - Principal's Office	180	SF	6	\$623	
	Doors - Side-lite	Rm 117 - Principal's Office	61	SF	6	\$1,020	
	Doors - Wood Doors inclu hw	Rm 117 - Principal's Office	1	EA	6	\$301	



## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Administrative Suites/Offices</b>							
	Floor - Tile/Sheet	Rm 117 - Principal's Office	180	SF	4	\$1,740	Broken, missing and cracked tiles
	Lighting - Pendent/Surface	Rm 117 - Principal's Office	6	EA	7	\$0	
	Walls - Plaster/Drywall	Rm 117 - Principal's Office	240	SF	7	\$0	
<b>Gymnasia</b>							
	Ceiling - Plaster/Drywall	Floor 0.5	3,093	SF	5	\$44,540	
	Doors - Steel Doors incl hw	Floor 0.5	5	EA	6	\$1,505	
	Floor - Tile/Sheet	Floor 0.5	300	SF	6	\$300	
	Floor - Wood	Floor 0.5	2,793	SF	6	\$19,690	
	Lighting - Lay-in	Floor 0.5	23	EA	7	\$0	
	Lighting - Pendent/Surface	Floor 0.5	6	EA	6	\$743	
	Sound System	Floor 0.5	1	EA	6	\$41,654	
	Stage	Floor 0.5	484	SF	5	\$7,267	Water damage in ceiling tiles along east wall
	Stage Curtain	Floor 0.5	3	EA	6	\$0	
	Stage-Stairs - Terrazzo	Floor 0.5	114	LF	6	\$872	
	Storage/ Closet	Floor 0.5	300	SF	6	\$2,175	
	Walls - Concrete Block	Floor 0.5	1,616	SF	6	\$4,737	
	Walls - Structural Glazed Tile	Floor 0.5	1,616	SF	6	\$5,084	
<b>Kitchen</b>							
	Ceiling - Plaster/Drywall	1st Floor	576	SF	6	\$1,993	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	
	Floor - Tile Quarry	1st Floor	576	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	\$1,487	Cracked lens
	Walls - Structural Glazed Tile	1st Floor	593	SF	6	\$1,866	
<b>Lunch &amp; Multipurpose Room</b>							
	Ceiling - Plaster/Drywall	137-Lunch Room	894	SF	7	\$0	
	Doors - Steel Doors incl hw	137-Lunch Room	3	EA	6	\$903	
	Floor - Tile/Sheet	137-Lunch Room	894	SF	6	\$895	
	Lighting - Pendent/Surface	137-Lunch Room	33	EA	7	\$0	
	Serving Line	137-Lunch Room	21	LF	7	\$0	
	Walls - Plaster/Drywall	137-Lunch Room	66	SF	6	\$182	
	Walls - Structural Glazed Tile	137-Lunch Room	759	SF	6	\$2,388	
	Ceiling - Plaster/Drywall	2nd Floor Teachers Lounge	288	SF	6	\$997	
	Doors - Steel Doors incl hw	2nd Floor Teachers Lounge	1	EA	6	\$301	
	Floor - Tile/Sheet	2nd Floor Teachers Lounge	288	SF	6	\$288	
	Lighting - Pendent/Surface	2nd Floor Teachers Lounge	10	EA	7	\$0	
	Walls - Plaster/Drywall	2nd Floor Teachers Lounge	380	SF	6	\$1,049	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Lunch &amp; Multipurpose Room</b>							
<b>MDF_IDF</b>							
	Doors - Steel Doors incl hw	225	1	EA	6	\$301	
	Ventilation and Cooling	225	1	EA	6	\$1,855	
<b>Mechanical/ Service Rooms</b>							
	Storage Room	1st Floor Storage Room	198	SF	6	\$1,419	
	Janitor's Closet	2nd Floor -East Janitors Closet	45	SF	6	\$322	
	Janitor's Closet	2nd Floor -West Janitors Closet	45	SF	6	\$322	
	Storage Room	2nd Flr - East Storage	120	SF	6	\$860	
	Storage Room	2nd Flr - West Storage	120	SF	6	\$860	Cracks east wall
	Mechanical/ Service Rooms	Boiler Room Storage A	86	SF	6	\$616	Missing lamp lens
	Mechanical/ Service Rooms	Boiler Room	810	SF	6	\$5,803	
	Mechanical/ Service Rooms	Boiler Room-Storage B	50	SF	6	\$358	
<b>Restroom</b>							
	Accessories	1st Floor-Girls Restroom	200	SF	6	\$1,845	
	Ceiling - Plaster/Drywall	1st Floor-Girls Restroom	200	SF	5	\$1,833	
	Doors - Steel Doors incl hw	1st Floor-Girls Restroom	1	EA	6	\$301	
	Floor Drain	1st Floor-Girls Restroom	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girls Restroom	200	SF	6	\$423	
	Lavatory	1st Floor-Girls Restroom	4	EA	6	\$1,278	
	Lighting - Pendant/Surface	1st Floor-Girls Restroom	4	EA	7	\$0	
	Partitions	1st Floor-Girls Restroom	6	EA	6	\$1,782	
	Walls - Structural Glazed Tile	1st Floor-Girls Restroom	410	SF	5	\$20,831	
	Water Closet	1st Floor-Girls Restroom	6	EA	6	\$2,016	
	Accessories	116 - Teacher's Lounge	15	SF	6	\$138	
	Ceiling - Plaster/Drywall	116 - Teacher's Lounge	15	SF	6	\$52	
	Doors - Steel Doors incl hw	116 - Teacher's Lounge	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	116 - Teacher's Lounge	15	SF	6	\$32	
	Lavatory	116 - Teacher's Lounge	1	EA	6	\$320	
	Lighting - Pendant/Surface	116 - Teacher's Lounge	1	EA	7	\$0	
	Walls - Structural Glazed Tile	116 - Teacher's Lounge	120	SF	6	\$378	
	Water Closet	116 - Teacher's Lounge	1	EA	6	\$336	
	Accessories	1st Floor-Boys	116	SF	6	\$1,070	Missing soap dispensers
	Ceiling - Plaster/Drywall	1st Floor-Boys	116	SF	6	\$401	
	Doors - Steel Doors incl hw	1st Floor-Boys	1	EA	5	\$1,174	
	Floor Drain	1st Floor-Boys	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boys	116	SF	5	\$1,853	

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Lavatory	1st Floor-Boys	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st Floor-Boys	2	EA	7	\$0	
	Partitions	1st Floor-Boys	2	EA	6	\$594	
	Urinals	1st Floor-Boys	3	EA	6	\$1,008	
	Walls - Structural Glazed Tile	1st Floor-Boys	323	SF	7	\$0	
	Water Closet	1st Floor-Boys	2	EA	6	\$672	
	Accessories	1st Floor-Staff Restroom	163	SF	6	\$1,503	
	Ceiling - Plaster/Drywall	1st Floor-Staff Restroom	163	SF	7	\$0	
	Doors - Steel Doors incl hw	1st Floor-Staff Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Staff Restroom	70	SF	6	\$148	
	Floor - Tile/Sheet	1st Floor-Staff Restroom	93	SF	6	\$93	
	Lavatory	1st Floor-Staff Restroom	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st Floor-Staff Restroom	4	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor-Staff Restroom	1	EA	7	\$0	
	Partitions	1st Floor-Staff Restroom	2	EA	5	\$1,502	
	Walls - Plaster/Drywall	1st Floor-Staff Restroom	366	SF	5	\$2,774	Cracking on North Wall
	Water Closet	1st Floor-Staff Restroom	2	EA	6	\$672	
	Ceiling - Plaster/Drywall	230	14	SF	6	\$48	
	Doors - Steel Doors incl hw	230	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	230	14	SF	6	\$30	
	Lighting - Pendent/Surface	230	1	EA	7	\$0	
	Walls - Plaster/Drywall	230	98	SF	6	\$270	
	Water Closet	230	1	EA	6	\$336	
	Accessories	2nd Floor Boys	283	SF	6	\$2,610	
	Ceiling - Plaster/Drywall	2nd Floor Boys	283	SF	6	\$979	
	Doors - Steel Doors incl hw	2nd Floor Boys	2	EA	6	\$602	
	Floor Drain	2nd Floor Boys	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys	283	SF	5	\$4,520	
	Lavatory	2nd Floor Boys	4	EA	6	\$1,278	
	Lighting - Pendent/Surface	2nd Floor Boys	6	EA	7	\$0	
	Partitions	2nd Floor Boys	4	EA	6	\$1,188	
	Urinals	2nd Floor Boys	5	EA	6	\$1,680	
	Walls - Structural Glazed Tile	2nd Floor Boys	496	SF	6	\$1,560	
	Water Closet	2nd Floor Boys	4	EA	6	\$1,344	
	Accessories	2nd Floor Girls	289	SF	6	\$2,666	
	Ceiling - Plaster/Drywall	2nd Floor Girls	289	SF	6	\$1,000	
	Doors - Steel Doors incl hw	2nd Floor Girls	2	EA	6	\$602	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Floor Drain	2nd Floor Girls	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls	289	SF	6	\$612	
	Lavatory	2nd Floor Girls	4	EA	6	\$1,278	
	Lighting - Pendent/Surface	2nd Floor Girls	6	EA	7	\$0	
	Partitions	2nd Floor Girls	8	EA	6	\$2,375	
	Walls - Structural Glazed Tile	2nd Floor Girls	502	SF	6	\$1,579	
	Water Closet	2nd Floor Girls	8	EA	6	\$2,688	
	Accessories	2nd Floor Teachers Lounge	121	SF	6	\$1,116	
	Ceiling - Plaster/Drywall	2nd Floor Teachers Lounge	121	SF	6	\$419	
	Doors - Steel Doors incl hw	2nd Floor Teachers Lounge	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Teachers Lounge	121	SF	6	\$256	
	Lavatory	2nd Floor Teachers Lounge	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor Teachers Lounge	2	EA	7	\$0	
	Lighting - Wall Mounted	2nd Floor Teachers Lounge	2	EA	7	\$0	
	Partitions	2nd Floor Teachers Lounge	2	EA	6	\$594	
	Walls - Structural Glazed Tile	2nd Floor Teachers Lounge	419	SF	6	\$1,318	
	Water Closet	2nd Floor Teachers Lounge	2	EA	6	\$672	
	Accessories	Rm 101 - Restroom	15	SF	6	\$138	
	Ceiling - Plaster/Drywall	Rm 101 - Restroom	15	SF	6	\$52	
	Doors - Steel Doors incl hw	Rm 101 - Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Rm 101 - Restroom	15	SF	6	\$32	
	Lighting - Pendent/Surface	Rm 101 - Restroom	1	EA	6	\$124	
	Walls - Structural Glazed Tile	Rm 101 - Restroom	120	SF	6	\$378	
	Water Closet	Rm 101 - Restroom	1	EA	6	\$336	
	Accessories	Rm 102 - Restroom	15	SF	6	\$138	toilet paper dispenser
	Ceiling - Plaster/Drywall	Rm 102 - Restroom	15	SF	6	\$52	
	Doors - Steel Doors incl hw	Rm 102 - Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Rm 102 - Restroom	15	SF	6	\$32	
	Lighting - Pendent/Surface	Rm 102 - Restroom	1	EA	7	\$0	
	Walls - Structural Glazed Tile	Rm 102 - Restroom	120	SF	6	\$378	
	Water Closet	Rm 102 - Restroom	1	EA	6	\$336	
	Accessories	Rm 103 - Restroom	15	SF	6	\$138	Soap dispenser
	Ceiling - Plaster/Drywall	Rm 103 - Restroom	15	SF	6	\$52	
	Doors - Steel Doors incl hw	Rm 103 - Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Rm 103 - Restroom	15	SF	6	\$32	
	Lighting - Pendent/Surface	Rm 103 - Restroom	1	EA	6	\$124	
	Walls - Structural Glazed Tile	Rm 103 - Restroom	120	SF	6	\$378	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Water Closet	Rm 103 - Restroom	1	EA	6	\$336	
	Accessories	Rm 104 - Restroom	15	SF	6	\$138	toilet paper dispenser
	Ceiling - Plaster/Drywall	Rm 104 - Restroom	15	SF	6	\$52	
	Doors - Steel Doors incl hw	Rm 104 - Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Rm 104 - Restroom	15	SF	6	\$32	
	Lighting - Pendent/Surface	Rm 104 - Restroom	1	EA	6	\$124	
	Walls - Structural Glazed Tile	Rm 104 - Restroom	120	SF	6	\$378	
	Water Closet	Rm 104 - Restroom	1	EA	6	\$336	
	Accessories	Rm 106 - Restroom	15	SF	6	\$138	Toilet paper dispenser
	Ceiling - Plaster/Drywall	Rm 106 - Restroom	15	SF	6	\$52	
	Doors - Steel Doors incl hw	Rm 106 - Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Rm 106 - Restroom	15	SF	6	\$32	
	Lighting - Pendent/Surface	Rm 106 - Restroom	1	EA	6	\$124	
	Walls - Structural Glazed Tile	Rm 106 - Restroom	120	SF	6	\$378	
	Water Closet	Rm 106 - Restroom	1	EA	6	\$336	
	Accessories	Rm 108 - Restroom	15	SF	5	\$297	Broken toilet paper dispenser
	Ceiling - Plaster/Drywall	Rm 108 - Restroom	15	SF	6	\$52	
	Doors - Steel Doors incl hw	Rm 108 - Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Rm 108 - Restroom	15	SF	6	\$32	
	Lighting - Pendent/Surface	Rm 108 - Restroom	1	EA	6	\$124	
	Walls - Structural Glazed Tile	Rm 108 - Restroom	120	SF	6	\$378	
	Water Closet	Rm 108 - Restroom	1	EA	6	\$336	
	Ceiling - Plaster/Drywall	Rm 110 - Restroom	15	SF	6	\$52	
	Doors - Steel Doors incl hw	Rm 110 - Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Rm 110 - Restroom	15	SF	6	\$32	
	Lighting - Pendent/Surface	Rm 110 - Restroom	1	EA	6	\$124	
	Walls - Structural Glazed Tile	Rm 110 - Restroom	120	SF	6	\$378	
	Water Closet	Rm 110 - Restroom	1	EA	6	\$336	
	Ceiling - Plaster/Drywall	Rm 112 - Restroom	15	SF	6	\$52	
	Doors - Steel Doors incl hw	Rm 112 - Restroom	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Rm 112 - Restroom	15	SF	6	\$32	
	Lighting - Pendent/Surface	Rm 112 - Restroom	1	EA	7	\$0	
	Walls - Structural Glazed Tile	Rm 112 - Restroom	120	SF	6	\$378	
	Water Closet	Rm 112 - Restroom	1	EA	7	\$0	
	Accessories	Rm 114 - Restroom	15	SF	6	\$138	
	Ceiling - Plaster/Drywall	Rm 114 - Restroom	15	SF	6	\$52	
	Doors - Steel Doors incl hw	Rm 114 - Restroom	1	EA	6	\$301	

## Building: Main

### Category: Rooms (Other Than Classrooms)

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Restroom</b>							
	Floor - Tile Ceramic/ Porcelain	Rm 114 - Restroom	15	SF	6	\$32	
	Lighting - Pendent/Surface	Rm 114 - Restroom	1	EA	7	\$0	
	Walls - Structural Glazed Tile	Rm 114 - Restroom	120	SF	6	\$378	
	Water Closet	Rm 114 - Restroom	1	EA	6	\$336	
	Accessories	Staff A	77	SF	6	\$710	
	Ceiling - Plaster/Drywall	Staff A	77	SF	5	\$706	
	Doors - Steel Doors incl hw	Staff A	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Staff A	77	SF	6	\$163	
	Lavatory	Staff A	1	EA	6	\$320	
	Lighting - Pendent/Surface	Staff A	2	EA	7	\$0	
	Lighting - Wall Mounted	Staff A	1	EA	6	\$124	
	Partitions	Staff A	1	EA	6	\$297	
	Walls - Structural Glazed Tile	Staff A	259	SF	6	\$815	
	Water Closet	Staff A	1	EA	6	\$336	
	Accessories	Staff B	73	SF	7	\$0	Mirror, soap dispenser and paper towel dispenser
	Ceiling - Plaster/Drywall	Staff B	73	SF	7	\$0	
	Doors - Steel Doors incl hw	Staff B	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Staff B	73	SF	7	\$0	
	Lavatory	Staff B	1	EA	6	\$320	
	Lighting - Pendent/Surface	Staff B	2	EA	7	\$0	
	Lighting - Wall Mounted	Staff B	1	EA	6	\$124	
	Partitions	Staff B	1	EA	6	\$297	
	Showers	Staff B	1	EA	6	\$311	
	Walls - Structural Glazed Tile	Staff B	252	SF	6	\$793	
	Water Closet	Staff B	1	EA	6	\$336	
	Ceiling - Plaster/Drywall	Staff Mens 2nd Floor	81	SF	7	\$0	
	Doors - Steel Doors incl hw	Staff Mens 2nd Floor	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	Staff Mens 2nd Floor	81	SF	6	\$171	
	Lavatory	Staff Mens 2nd Floor	2	EA	7	\$0	
	Lighting - Pendent/Surface	Staff Mens 2nd Floor	2	EA	7	\$0	
	Lighting - Wall Mounted	Staff Mens 2nd Floor	2	EA	7	\$0	
	Partitions	Staff Mens 2nd Floor	1	EA	6	\$297	
	Urinals	Staff Mens 2nd Floor	1	EA	6	\$336	
	Walls - Structural Glazed Tile	Staff Mens 2nd Floor	51	SF	6	\$160	
	Water Closet	Staff Mens 2nd Floor	1	EA	6	\$336	

**Building: Main**

**Category: Rooms (Other Than Classrooms)**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Rooms (Other Than Classrooms) Subtotal:</b>						<b>\$295,271</b>	

**Building: Main**

**Category: Building Interior**

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Corridor</b>							
	Ceiling - Plaster/Drywall	1st Floor	150	SF	5	\$2,617	
	Ceiling - Plaster/Drywall	1st Floor	20	SF	4	\$606	
	Ceiling - Plaster/Drywall	1st Floor	3,439	SF	6	\$21,294	
	Doors - Steel Doors incl hw	1st Floor	16	EA	6	\$4,816	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	6	\$827	
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	7	\$0	
	Floor - Terrazzo	1st Floor	3,609	SF	5	\$135,834	
	Lighting - Pendent/Surface	1st Floor	57	EA	7	\$0	
	Walls - Structural Glazed Tile	1st Floor	4,352	SF	6	\$13,691	
	Walls - Tile Ceramic/ Porcelain	1st Floor	318	SF	6	\$1,000	
	Ceiling - Lay-in	2nd Floor	3,032	SF	6	\$9,105	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	6	\$1,204	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	6	\$827	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	2nd Floor	3,032	SF	6	\$1,648	
	Lighting - Lay-in	2nd Floor	43	EA	7	\$0	
	Walls - Structural Glazed Tile	2nd Floor	4,316	SF	6	\$13,578	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	318	SF	7	\$0	
<b>Safety</b>							
	Camera Viewing Station		1	EA	7	\$0	Viewing is located in the Principal's Office.
	Security Cameras		8	EA	7	\$0	There are 3 inside cameras and 5 outside cameras that were replaced in 2013.
<b>Stairs</b>							
	Ceiling - Lay-in	East	212	SF	7	\$0	
	Floor - Terrazzo	East	202	SF	6	\$1,696	
	Handrails	East	56	LF	5	\$644	
	Lighting - Lay-in	East	4	EA	7	\$0	
	Stairs - Terrazzo	East	105	LF	6	\$974	
	Walls - Structural Glazed Tile	East	912	SF	6	\$2,869	
	Ceiling - Lay-in	North / 1st Floor	215	SF	6	\$646	
	Floor - Terrazzo	North / 1st Floor	215	SF	6	\$1,805	

## Building: Main

### Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Stairs</b>							
	Handrails	North / 1st Floor	55	LF	5	\$632	Peeling paint
	Lighting - Lay-in	North / 1st Floor	3	EA	7	\$0	
	Stairs - Terrazzo	North / 1st Floor	95	LF	6	\$882	
	Walls - Structural Glazed Tile	North / 1st Floor	834	SF	6	\$2,624	
	Ceiling - Lay-in	West	212	SF	7	\$0	
	Floor - Terrazzo	West	202	SF	6	\$1,696	
	Handrails	West	56	LF	6	\$485	
	Lighting - Lay-in	West	4	EA	7	\$0	
	Stairs - Terrazzo	West	105	LF	6	\$974	
	Walls - Structural Glazed Tile	West	912	SF	6	\$2,869	
<b>Building Interior Subtotal:</b>						<b>\$225,843</b>	

## Total Building Cost

**\$2,632,514**

## SITE

### Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Civil/Drainage</b>							
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	5	\$12,850	
	Civil/ Drainage - Site Manhole	Entire Site / Parking Lot	1	EA	5	\$3,697	
<b>Fencing</b>							
	Fencing - Chain Link	Parking Lot- South	409	LF	5	\$24,945	
	Fencing - New Standard Ornamental	Entire Site	543	LF	6	\$17,323	Entire Site (N,E,W elevs.)
<b>Landscape</b>							
	Landscape - Grass	Entire Site	1,750	SF	5	\$2,653	
	Landscape - Hardscape- Asphalt		6,700	SF	4	\$52,887	Hardscape-Asphalt: major deterioration especially W and E ends
	Parkway trees	Site - East	2	EA	7	\$0	
	Retaining Wall - Concrete	Boiler Room	300	SF	6	\$7,031	entrance to boiler room basement
<b>Parking Lot</b>							
	Concrete Curbs	Parking Lot- South	258	LF	6	\$3,313	
	Lighting - Lighting	Entire Building	4	EA	6	\$1,861	mounted
	Surface - Asphalt	Parking Lot- East	400	SF	4	\$4,239	400 SF potholes cracks at east end
	Surface - Asphalt	Parking Lot- South	12,431	SF	5	\$56,706	



## SITE

### Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
<b>Parking Lot</b>							
<b>Sidewalks</b>							
	Sidewalks - Perimeter Sidewalks	Entire Site (N,E,W) / Entire Site	4,995	SF	5	\$35,143	
<b>Signage</b>							
	Flag Pole - Flag Pole	Front (N), E and W elevations	1	EA	7	\$0	Front (N)
	Monument - Building Mounted Cut Letter Sign	Front (N), E and W elevations	2	EA	6	\$0	E&W Elevations

**Site Subtotal:** **\$222,649**

**Total Site Cost** **\$222,649**

**Campus Total <sup>2 3</sup>** **\$2,855,163**

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

<sup>2</sup> As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

<sup>3</sup> The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

## Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- **Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- **For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- **Campus Total** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

## Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart-Board
<b>Main</b>														
Computer Lab	Regular Classroom	2nd Floor	210	205	867	1	10	66	77	87	40	Y	Y	N
Counseling Room	Counseling Room	1st Floor	100	109	557	0	1	6	145	72	40	Y	Y	N
Kindergarten	Kindergarten	1st Floor	101	110	1,354	1	1	10	249	125	40	Y	Y	N
Kindergarten	Kindergarten	1st Floor	103	111	1,354	1	2	10	249	125	40	Y	Y	N
Library	Regular Classroom	2nd Floor	205	207	862	1	2	10	145	72	40	Y	N	N
Music Room	Regular Classroom	2nd Floor	211	212	867	1	5	18	145	72	40	Y	N	N
Regular Classroom	Regular Classroom	1st Floor	102	101	862	1	2	8	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	1st Floor	104	102	861	1	2	10	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	1st Floor	106	103	852	1	2	8	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	1st Floor	108	104	854	1	2	8	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	1st Floor	110	106	867	1	2	10	145	72	40	Y	N	N
Regular Classroom	Regular Classroom	1st Floor	112	107	862	0	2	8	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	1st Floor	114	108	862	1	2	8	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	201	209	1,107	1	4	14	223	112	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	202	201	867	1	2	8	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	203	210	1,107	1	35	66	223	112	40	Y	Y	Y
Regular Classroom	Regular Classroom		204	202	867	1	2	10	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	206	203	867	1	2	10	145	72	40	Y	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	212	867	1	2	10	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	208	204	867	1	2	10	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	209	213	867	1	20	66	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	212	206	867	1	2	10	145	72	40	Y	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	213	213	863	1	2	10	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	214	207	863	1	2	10	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	216	208	891	1	2	10	145	72	40	Y	Y	N
Regular Classroom	Regular Classroom	2nd Floor	217	215	1,107	0	4	14	223	112	40	Y	Y	N
Science	Regular Classroom	2nd Floor	215	216	1,107	1	4	18	145	72	40	Y	N	N