9351 S Lowe Ave Chicago, IL 60620

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1961	1	31,653	\$2,740,447
2-Classroom Modular	0	1	1,633	\$176,775
2-Classroom Modular	0	1	1,633	\$172,351
SITE				\$599,174
Campus Total			34,919	\$3,688,747

Building: Main

p Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ance						
Entrance Control - Audio and Video	1 - Main / 1st Floor	1	EA	7	\$0	
Exterior Doors - Exterior Steel Door	1 - Main / 1st Floor	2	EΑ	6	\$961	
Exterior Doors - Exterior Steel Door	2	3	EΑ	6	\$1,442	
Exterior Doors - Exterior Steel Door	3	1	EΑ	6	\$481	
Exterior Doors - Exterior Steel Door	4	1	EΑ	5	\$1,341	
Exterior Doors - Exterior Steel Door	5	3	EA	5	\$4,024	graffiti
Exterior Doors - Exterior Steel Door	6	2	EΑ	5	\$2,683	graffiti
Exterior Doors - Exterior Steel Door	7	1	EΑ	5	\$1,341	
Exterior Doors - Exterior Steel Door	8	1	EA	5	\$1,341	
Exterior Doors - Side lite	1 - Main / 1st Floor	2	EA	6	\$627	
Exterior Doors - Side lite	6	2	EA	5	\$952	
Exterior Doors - Transom Lite	1 - Main	2	EA	6	\$627	
Exterior Doors - Transom Lite	2	3	EA	6	\$940	
Exterior Doors - Transom Lite	5	3	EA	6	\$940	
Exterior Doors - Transom Lite	6	2	EA	5	\$1,643	
Exterior Doors - Transom Lite	7	1	EA	5	\$822	
Exterior Doors - Transom Lite	8	1	EA	5	\$822	
Exterior Stairs - Concrete	1 - Main	18	LF	7	\$0	

9351 S Lowe Ave Chicago, IL 60620

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	ce						
	Exterior Stairs - Concrete	2	27	LF	7	\$0	
	Exterior Stairs - Concrete	3	7	LF	6	\$572	
	Exterior Stairs - Concrete	4	7	LF	6	\$572	
	Exterior Stairs - Concrete	5	27	LF	6	\$2,208	
	Exterior Stairs - Concrete	6	18	LF	6	\$1,472	
	Exterior Stairs - Concrete	7	11	LF	6	\$899	spalled corner at stair
	Exterior Stairs - Concrete	8	11	LF	6	\$899	
	Stair Handrail - Steel_Stair Handrail	1 - Main	6	LF	6	\$52	
	Stair Handrail - Steel_Stair Handrail	2	6	LF	6	\$52	
	Stair Handrail - Steel_Stair Handrail	5	6	LF	6	\$52	
	Stair Handrail - Steel_Stair Handrail	6	6	LF	6	\$52	
	Stair Handrail - Steel_Stair Handrail	7	4	LF	6	\$35	
	Stair Handrail - Steel_Stair Handrail	8	4	LF	6	\$35	
Founda	ation						
	Foundation - Concrete	Entire Building	1,186	LF	7	\$0	spalled concrete at all corners outside building
	Superstructure - Slab on Grade	Entire Building	31,653	SF	7	\$0	
Lightin	g						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	12	EA	6	\$6,438	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	4	\$2,060	
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	6	\$4,331	
Roof S	ystem						
	Chimney - Brick Chimney- Concrete/ Mortar Liner	B - Main Roof	22	LF	6	\$21,003	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	B - Main Roof	2	LF	5	\$5,703	concrete cap
	Chimney - Brick Chimney- Stainless Steel Liner	B - Main Roof	20	LF	6	\$19,094	peeling paint
	Coping - Metal	A - South Pitched Roof	30	LF	6	\$964	some loose seams
	Coping - Metal	B - Main Roof	1,076	LF	6	\$34,559	some loose seams
	Downspouts - Interior Downspouts	B - Main Roof	91	LF	6	\$3,024	clean debris from cages
	Roof Structure - Steel / Metal Deck/ Concrete Topping	A - South Pitched Roof	4,032	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	B - Main Roof	31,328	SF	7	\$0	
	Roof - Modified Bitumen	A - South Pitched Roof	4,032	SF	5	\$84,814	
	Roof - PVC Membrane	B - Main Roof	29,328	SF	6	\$242,408	
	Roof - PVC Membrane	B - Main Roof / West	2,000	SF	4	\$63,292	ponding and water present between membrane at 4 drains
Mell-							TUIMIN
Walls	Fatadar Walle - Bital	Follow D. Caller	0.700	05		•	
	Exterior Walls - Brick	Entire Building	8,780	SF	7	\$0	

9351 S Lowe Ave Chicago, IL 60620

Building: Main

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Walls							
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,779	SF	6	\$10,100	fascia
Windo	ws						
	Guard - Guards perforated	Entire Building	6,515	SF	6	\$83,196	
	Lintels - Steel	Entire Building	72	LF	6	\$2,090	
	Windows - Insulated Panel	Entire Building	1,708	SF	6	\$12,750	top 2' of all windows
	Windows - Louver	Entire Building	134	SF	6	\$1,000	
	Windows - Sash Aluminum Double-pane	Entire Building	5,617	SF	6	\$41,929	

Building Exterior Subtotal:

\$666,640

Building: Main

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Automatic Transfer Switch	Boiler Room	1	EA	6	\$408	
	Emergency A/C Power - Corridors and Stairs	Entire Building / 1st Floor	4,905	SF	6	\$1,473	
	Emergency A/C Power - Gym	Entire Building / 1st Floor	2,720	SF	6	\$1,011	
	Emergency A/C Power - Lunchrooms	Entire Building / 1st Floor	1,104	SF	6	\$410	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	5	EΑ	6	\$1,013	
	Exit Signs - Corridors and Stairs	Entire Building / 1st Floor	13	EΑ	6	\$1,947	
	Exit Signs - Gym	Entire Building / 1st Floor	2	EA	4	\$1,157	Greater than 20 years of age, and not spare parts available
	Exit Signs - Lunchroom	Entire Building / 1st Floor	1	EΑ	6	\$150	
	Security System - Intrusion Detection	Entire Building	31,653	SF	6	\$8,147	
Main S	ervice						
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	\$2,921	
	Main Electrical Service - 1200 A 120/208/3PH	Boiler Room	1	EΑ	6	\$5,078	
	PA System	Entire Building	31,653	SF	6	\$10,411	
Power I	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	14	EΑ	6	\$4,188	
	Main Distribution Panels - 400 - 600 amp	Entire Building / Boiler Room	1	EA	6	\$528	
						*	

Electrical System Subtotal:

\$38,840

Building: Main



9351 S Lowe Ave Chicago, IL 60620

Category: Safty System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Panel	Entire Building / Boiler Room	1	EA	6	\$6,406	
Fire Alarm Strobe Lights	Entire Building	31,653	SF	4	\$43,001	
Fire Alarm_System	Entire Building	31,653	SF	5	\$35,306	System is in good condition, but strobes need to be installed in classrooms.

Safty System Subtotal: \$84,712

Building: Main

Category: Mechanical System

Group I	tem - Type	Location	Quantity	Unit	Rank	Cost	Comments
Boiler Sys	stems						
E	Boiler Auxiliary- Non Condensing Hot Water - Less than 500 MBH	Boiler Room	14	EA	5	\$236,821	There are some leaking valves
(Chemical Pot Feeder	Boiler Room	1	EA	6	\$725	
(Combustion Dampers	Boiler Room	1	EA	6	\$409	
ŀ	Hot Water Pump	Boiler Room	2	EA	4	\$24,716	Pumps show sign of significant wear
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Soiler - Less than 500 MBH	Boiler Room	14	EA	3	\$718,774	All boilers are old and in poor condition. Controls are out dated. Burners are deteriorated. 14 boilers are a part of the modular boiler system.
Heating D	evices						
(Cabinet Heaters - With Hot Water Coil	Entire Building	10	EA	6	\$3,543	
F	Fin Tube - Hot Water	Entire Building	48	LF	6	\$453	
F	Radiators - Hot Water	Entire Building	6	EA	5	\$9,733	
\	Wall Heater - Electric	Entire Building	10	EA	5	\$5,366	
Mechanic	al Plumbing						
ŀ	Hydronic Supply and Return - Steel	Entire Building	500	LF	5	\$104,061	
Temperat	ure Control						
F	Pneumatic System	Entire Building	31,653	SF	5	\$109,086	
٦	Γhermostats - Pneumatic	Entire Building	32	EA	4	\$23,592	
Unit Vent	ilation						
l	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	28	EA	5	\$239,760	
Ventilatio	n						
Е	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	3	EA	6	\$1,777	
E	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building / Roof	4	EA	4	\$25,568	
E	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	19	EA	4	\$80,646	
E	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building / Roof	1	EA	3	\$4,245	
E	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building / Roof	1	EA	4	\$1,942	
KIDI ING		Page 4 of 22					Assessment Date: 6/19/1



\$272,345

9351 S Lowe Ave Chicago, IL 60620

Building: Main

Category: Mechanical System

Group Item - Type Location Quantity Unit Rank Cost Comments

Mechanical System Subtotal: \$1,591,216

Building: Main

Category: Plumbing System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wat	ter						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	\$310	
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	31,653	SF	4	\$22,632	Piping is old. The building suffers from leaks and there are many clamps installed.
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	31,653	SF	4	\$45,716	Piping is old. The building suffers from leaks and there are many clamps installed.
	Domestic Piping-Cold Water Risers	Entire Building	31,653	SF	4	\$25,348	Piping is old. The building suffers from leaks and there are many clamps installed.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	31,653	SF	4	\$17,200	Piping is old. The building suffers from leaks and there are many clamps installed.
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	31,653	SF	4	\$40,737	Piping is old. The building suffers from leaks and there are many clamps installed.
	Domestic Piping-Hot Water Return Lines	Entire Building	31,653	SF	4	\$27,158	Piping is old. The building suffers from leaks and there are many clamps installed.
	Domestic Piping-Hot Water Return Risers	Entire Building	31,653	SF	4	\$15,390	Piping is old. The building suffers from leaks and there are many clamps installed.
	Sanitary Piping	Entire Building	31,653	SF	6	\$28,969	
	Storm Piping	Entire Building	31,653	SF	6	\$27,611	
	Vent Piping	Entire Building	31,653	SF	6	\$21,274	

Plumbing System Subtotal:

Building: Main

Location	Quantity	Unit	Rank	Cost (Comments
1st Floor	1	EA	7	\$0	
1st Floor	24	LF	7	\$0	
1st Floor	768	SF	7	\$0	
1st Floor	16	LF	4	\$1,469	
1st Floor	1	EA	7	\$0	
1st Floor	768	SF	7	\$0	
	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1st Floor 1 1st Floor 24 1st Floor 768 1st Floor 16 1st Floor 1	1st Floor 1 EA 1st Floor 24 LF 1st Floor 768 SF 1st Floor 16 LF 1st Floor 1 EA	1st Floor 1 EA 7 1st Floor 24 LF 7 1st Floor 768 SF 7 1st Floor 16 LF 4 1st Floor 1 EA 7	1st Floor 1 EA 7 \$0 1st Floor 24 LF 7 \$0 1st Floor 768 SF 7 \$0 1st Floor 16 LF 4 \$1,469 1st Floor 1 EA 7 \$0



9351 S Lowe Ave Chicago, IL 60620

Building: Main

	Item - Type	Location	Quantity	l Ini+	Rank	Cost	Comments
_	pom #100 (Regular Classroom)	Location	Quantity	Oill	IVALIK	CUSI	Comments
Ciassic	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	818	SF	7	\$0	
	Work Sink	1st Floor	1	EA	7	\$0	
		13111001	ı	LA	,	ΨΟ	
Classro	oom #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	818	SF	7	\$0	
	Work Sink	1st Floor	1	EA	7	\$0	
Classro	oom #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	818	SF	7	\$0	
	Work Sink	1st Floor	1	EA	7	\$0	
Classro	oom #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	6	\$769	
						-	



9351 S Lowe Ave Chicago, IL 60620

Building: Main

Group tem - Type Location Quality Vinit Rank Comments Classroom #104 (Regular Classroom) 11 Floor 16 EA 7 50 Lighting - Pendent/Surface 11 Floor 16 EA 7 50 Wall - Concrete Block 11 Floor 18 SF 7 50 Classroom #104 (Regular Classroom) 11 Floor 18 EA 7 50 Classroom #104 (Regular Classroom) 11 Floor 18 EA 6 \$408 Calling - Plasser/Drywall 11 Floor 15 7 50 \$6 Calling - Plasser/Drywall 15 Floor 16 EB 7 50 Calling - Plasser/Drywall 15 Floor 16 EB 7 50 Chall-Board 15 Floor 16 EB 7 50 Lighting - Pendent/Surface 15 Floor 16 EB 7 50 Lighting - Pendent/Surface 15 Floor 15 Floor 16 EB 7 50		Item Type	Location	Ouantitus	l leit	Donle	Cont	Comments
Lighting - Pendent/Surface	•	•	Location	Quantity	Unit	Rank	Cost	Comments
Marker Eourd fish Floor 36 LF 7 \$0 Storage/ Closer 1st Floor 36 SF 7 \$0 Walls - Concrete Block 1st Floor 1818 SF 7 \$0 Concrete Block 1st Floor 181 EA 6 \$400 AC Units 1st Floor 15 SF 7 \$0 Celling - Pleater/Drywall 1st Floor 15 SF 7 \$0 Celling - Pleater/Drywall 1st Floor 16 LF 5 7 \$0 Complex - Pleater/Drywall 1st Floor 16 LF 7 \$0 \$0 Colling - Pendent/Surface 1st Floor 16 LF 7 \$0 \$0 Lighting - Pendent/Surface 1st Floor 16 LF 7 \$0 \$0 Lighting - Pendent/Surface 1st Floor 18 EB 7 \$0 \$0 Calleng - Pleater/Drywall 1st Floor 1st Floor 1	Classro		Ast Floor	40	^			
Storage Closet 1st Floor								
Marile - Concrete Block 1st Floor 1s								
Mork Sink								
Classroom #104 (Regular Classroom) AC Units								
AC Units		Work Sink	1st Floor	1	EA	7	\$0	
Casework 1st Floor 25 LF 7 \$0 Ceiling - Plaster/Dywall 1st Floor 158 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu tw 1st Floor 16 EA 7 \$0 Floor - Tile/Sheet 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 18 EF 7 \$0 Storage/ Closest 1st Floor 818 SF 7 \$0 Walls - Concrete Block 1st Floor 818 SF 7 \$0 Casework 1st Floor 1 EA 6 \$496 Casework 1st Floor 1 EA 9 \$496 Casework 1st Floor 1 EA 9 \$496 Casework 1st Floor 1 EA 7	Classro	oom #104 (Regular Classroom)						
Calling - Plaster/Dywall		AC Units	1st Floor	1	EA	6	\$496	
Chalk Board		Casework	1st Floor	24	LF	7	\$0	
Doors - Wood Doors inclut hw 1st Floor 1		Ceiling - Plaster/Drywall	1st Floor	158	SF	7	\$0	
Floor - Tile/Sheet		Chalk Board	1st Floor	16	LF	4	\$1,469	
Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 36 SF 7 \$0 Storage/ Closet 1st Floor 818 SF 7 \$0 Walls - Concrete Block 1st Floor 1818 SF 7 \$0 Work Sink 1st Floor 1 EA 6 \$496 AC Units 1st Floor 1 EA 6 \$496 Casework 1st Floor 768 SF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 16 LF 4 \$1,469 Conservord Doors inclu hw 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 16 LF 7 \$0 Horr - Tile/Sheet 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 81 SF		Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	\$0	
Marker Board		Floor - Tile/Sheet	1st Floor	768	SF	6	\$769	
Storage Closet 1st Floor 36 SF 7 \$0 Walls - Concrete Block 1st Floor 1st Floor		Lighting - Pendent/Surface	1st Floor	16	EΑ	7	\$0	
Walls - Concrete Block Work Sink 1st Floor 818 SF 7 7 \$0 Classroom #105 (Regular Classroom) AC Units 1st Floor 1 EA 6 6 \$496 Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 16 LF 4 \$1,469 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 16 EA 7 \$0 Floor - Tile/Sheet 1st Floor 16 EA 7 \$0 Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 EA 7 \$0 Walls - Concrete Block 1st Floor 81 SF 7 \$0 Walls - Concrete Block 1st Floor 81 SF 7 \$0 Walls - Concrete Block 1st Floor 1 EA 7 \$0 Walls - Concrete Block 1st Floor 1 EA 7 \$0 Classroom #106 (Regular Classroom) 1 SF 100 1 EA 5 \$0 </td <td></td> <td>Marker Board</td> <td>1st Floor</td> <td>16</td> <td>LF</td> <td>7</td> <td>\$0</td> <td></td>		Marker Board	1st Floor	16	LF	7	\$0	
Nork Sink		Storage/ Closet	1st Floor	36	SF	7	\$0	
Classroom#105 (Regular Classroom) AC Units		Walls - Concrete Block	1st Floor	818	SF	7	\$0	
AC Units		Work Sink	1st Floor	1	EA	7	\$0	
AC Units	Classro	oom #105 (Regular Classroom)						
Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0 Floor - Tile/Sheet 1st Floor 768 SF 7 \$0 Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 7 \$0 Marker Board 1st Floor 36 SF 7 \$0 Storage/ Closet 1st Floor 818 SF 7 \$0 Walls - Concrete Block 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom/ AC Units 1st Floor 1 EA 6 \$496 Casework 1st Floor 768 SF 7 \$0 Ceiling - Plaster/Drywall 1st			1st Floor	1	EA	6	\$496	
Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0 Floor - Tile/Sheet 1st Floor 768 SF 7 \$0 Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 7 \$0 Marker Board Oloset 1st Floor 36 SF 7 \$0 Storage/ Closet 1st Floor 81 SF 7 \$0 Walls - Concrete Block 1st Floor 81 SF 7 \$0 Work Sink 1st Floor 81 EA 7 \$0 Classroom) Casework 1st Floor 1 EA 6 \$496 Cailing - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 768 SF 7 \$0 Chalk Board <		Casework	1st Floor	24	LF	7	\$0	
Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0 Floor - Tile/Sheet 1st Floor 768 SF 7 \$0 Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 7 \$0 Marker Board Closet 1st Floor 36 SF 7 \$0 Storage/ Closet 1st Floor 31 EA 7 \$0 Walls - Concrete Block Work Sink 1st Floor 81 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom) Classroom) AC Units 1st Floor 1 EA 6 \$496 Casework Call Closer Cl		Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
Doors - Wood Doors inclu hw 1st Floor 1 EA 7 5 0 Floor - Tile/Sheet 1st Floor 768 SF 7 \$0 Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 7 \$0 Storage/ Closet 1st Floor 36 SF 7 \$0 Walls - Concrete Block Work Sink 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom #106 (Regular Classroom) 5 F 7 \$0 Casework 1st Floor 1 EA 6 \$496 Casework 1st Floor 768 SF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0		-	1st Floor	16	LF	4	\$1,469	
Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 7 \$0 Storage/ Closet 1st Floor 36 SF 7 \$0 Walls - Concrete Block 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom #106 (Regular Classroom) Classroom #106 (Regular Classroom) AC Units 1st Floor 1 EA 6 \$496 Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0		Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7		
Marker Board 1st Floor 16 LF 7 \$0 Storage/ Closet 1st Floor 36 SF 7 \$0 Walls - Concrete Block 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom #106 (Regular Classroom) Casework 1st Floor 1 EA 6 \$496 Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0		Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
Storage/ Closet 1st Floor 36 SF 7 \$0 Walls - Concrete Block 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom #106 (Regular Classroom) AC Units 1st Floor 1 EA 6 \$496 Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0		Lighting - Pendent/Surface	1st Floor	16	EΑ	7	\$0	
Walls - Concrete Block Work Sink 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom #106 (Regular Classroom) AC Units 1st Floor 1 EA 6 \$496 Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0		Marker Board	1st Floor	16	LF	7	\$0	
Work Sink 1st Floor 1 EA 7 7 \$0 Classroom #106 (Regular Classroom) AC Units 1st Floor 1 EA 6 \$496 Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0		Storage/ Closet	1st Floor	36	SF	7	\$0	
Classroom #106 (Regular Classroom) AC Units 1st Floor 1 EA 6 \$496 Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0		Walls - Concrete Block	1st Floor	818	SF	7	\$0	
AC Units 1st Floor 1 EA 6 \$496 Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0		Work Sink	1st Floor	1	EA	7	\$0	
AC Units 1st Floor 1 EA 6 \$496 Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0	Classro	oom #106 (Regular Classroom)						
Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0			1st Floor	1	EA	6	\$496	
Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0				24	LF	7		
Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0		Ceiling - Plaster/Drywall	1st Floor	768	SF	7		
Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0			1st Floor	16	LF	4		
		Doors - Wood Doors inclu hw			EA	7		
		Floor - Tile/Sheet	1st Floor	768	SF	7		



9351 S Lowe Ave Chicago, IL 60620

Building: Main

Group Item - Type Location of Midde (Regular Classroom) Comments Comments Lighting - Pendent/Surface 1st Floor 16 EA 7 SO Marker Dead 1st Floor 16 EA 7 SO Walks - Concrete Block 1st Floor 18 Fo 7 SO Classroom #107 (Regular Classroom) 1st Floor 1 EA 7 SO Classroom #107 (Regular Classroom) 1st Floor 1 EA 7 SO Classroom #107 (Regular Classroom) 1st Floor 76 ES 7 SO Classroom #107 (Regular Classroom) 1st Floor 76 ES 7 SO Classroom #107 (Regular Classroom) 1st Floor 76 ES 7 SO Claims Floor Floo		ory: Classrooms				_	_	_
Lighting - Pendent/Surface	_		Location	Quantity	Unit	Rank	Cost	Comments
Marker Board 1st Floor 36 LF 7 \$0 Storage/ Choest 1st Floor 181 SF 7 \$0 Walls - Concrete Block 1st Floor 181 SF 7 \$0 Concrete Block Wark Snk 1st Floor 18 ZF 7 \$0 Casework (Regular Classroom) AC Units 1st Floor 24 LF 7 \$0 Celling - Plaster/Drywall 1st Floor 76 SF 7 \$0 Colling - Plaster/Drywall 1st Floor 16 LF 7 \$0 Compose Need Doors inclu hw 1st Floor 16 LF 7 \$0 Floor - Tille/Sheet 1st Floor 16 LF 7 \$0 Lighting - Pendent/Surface 1st Floor 16 LF 7 \$0 Storage/ Closel 1st Floor 16 LF 7 \$0 Walle - Concrete Block 1st Floor 1	Classro							
Storage Closet 1st Floor 81		Lighting - Pendent/Surface		16				
Walls - Concrete Block Work Sink 1st Floor 818 BV 5 C 7 S0 Classroom #107 (Regular Classroom) Star Floor 1st Floor 2st T 5 C 5 S0 AC Unitis 1st Floor 2st T 7 S0 50 Celling - Plaster/Drywall 1st Floor 78 S0 5 T S0 50 Chalk Board 1st Floor 16 LP S S0 5 T S0 50 50 Chalk Board 1st Floor 16 LP S S0 7 S0 5				16	LF	7	\$0	
Mork Sink		Storage/ Closet	1st Floor	36	SF	7	\$0	
Classroom #107 (Regular Classroom) AC Units				818		7		
AC Units 1st Floor 1st Floor 2st Flo		Work Sink	1st Floor	1	EA	7	\$0	
Casework 1st Floor 24 LF 7 \$0 Celing - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 78 57 \$0 Lighting - Pendent/Surface 1st Floor 16 LF 7 \$0 Lighting - Pendent/Surface 1st Floor 16 LF 7 \$0 Marker Board 1st Floor 36 SF 7 \$0 Storage/Closet 1st Floor 818 SF 7 \$0 Walls - Concrete Block 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 18 SF 7 \$0 Casework 1st Floor 1 EA 7 \$0 Caling - Plaster/Drywall 1st Floor 1 EA 7 \$0 Chalk Board 1st Floor 1 EA 7	Classro	oom #107 (Regular Classroom)						
Ceiling - Plaster/Dywall		AC Units	1st Floor	1	EA	7	\$0	
Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 768 SF 7 \$0 Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 EA 7 \$0 Storage/ Closet 1st Floor 36 SF 7 \$0 Walls - Concrete Block 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 818 SF 7 \$0 Casework 1st Floor 24 LF 7 \$0 Casework 1st Floor 24 LF 7 \$0 Casework 1st Floor 24 LF 7 \$0 Casework 1st Floor 16 LF 7 \$0 Casework 1st Floor 16 LF 7 \$0 Casework 1st Floor 16 LF 7 \$0		Casework	1st Floor	24	LF	7	\$0	
Doors - Wood Doors inclu hw		Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
Floor - Tile/Sheet		Chalk Board	1st Floor	16	LF	4	\$1,469	
Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 7 \$0 Storage/ Closet 1st Floor 81 SF 7 \$0 Walls - Concrete Block 1st Floor 18 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Casework 1st Floor 1 EA 7 \$0 Casework 1st Floor 16 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 16 LF 7 \$0 Chalk Board 1st Floor 16 LF 7 \$0 Chalk Board 1st Floor 16 LF 7 \$0 Floor - Tile/Sheet 1st Floor 16 LF 7 \$0 Marker Board 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 1st Floor 1st Floor 1st Floor		Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
Marker Board 1st Floor 16 LF 7 \$0 Storage/ Closet 1st Floor 36 SF 7 \$0 Walls - Concrete Block 1st Floor 1 EA 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom #108 (Regular Classroom) AC Units 1st Floor 1 EA 7 \$0 Casework 1st Floor 78 SF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 78 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 78 SF 7 \$0 Lighting - Pendent/Surface 1st Floor 78 SF 7 \$0 Marker Board 1st Floor 1st Floor 16 LF 7 \$0 Walls - Concrete Block 1st Floor 1st Floor 81s SF 7 <t< td=""><td></td><td>Floor - Tile/Sheet</td><td>1st Floor</td><td>768</td><td>SF</td><td>7</td><td>\$0</td><td></td></t<>		Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
Storage/ Closet		Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
Mails		Marker Board	1st Floor	16	LF	7	\$0	
Nork Sink 1st Floor 1 EA 7 \$ \$ 0 \$ 0 \$		Storage/ Closet	1st Floor	36	SF	7	\$0	
Classroom #108 (Regular Classroom) AC Units		Walls - Concrete Block	1st Floor	818	SF	7	\$0	
AC Units		Work Sink	1st Floor	1	EA	7	\$0	
Casework 1st Floor 24 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0 Floor - Tile/Sheet 1st Floor 768 SF 7 \$0 Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 7 \$0 Storage/ Closet 1st Floor 36 SF 7 \$0 Walls - Concrete Block 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 818 SF 7 \$0 Classroom #111 (Kindergarten) AC Units 1st Floor 2 EA 6 \$991 Casework 1st Floor 50 LF 7 \$0 Ceilling - Plaster/Drywall	Classro	oom #108 (Regular Classroom)						
Ceiling - Plaster/Drywall 1st Floor 768 SF 7 \$0 Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0 Floor - Tile/Sheet 1st Floor 768 SF 7 \$0 Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 7 \$0 Storage/ Closet 1st Floor 36 SF 7 \$0 Walls - Concrete Block 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom #111 (Kindergarten) Casework 1st Floor 2 EA 6 \$991 Cailing - Plaster/Drywall 1st Floor 1,064 SF 6 \$3,682 Chalk Board 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor <td></td> <td>AC Units</td> <td>1st Floor</td> <td>1</td> <td>EA</td> <td>7</td> <td>\$0</td> <td></td>		AC Units	1st Floor	1	EA	7	\$0	
Chalk Board 1st Floor 16 LF 4 \$1,469 Doors - Wood Doors inclu hw 1st Floor 1 EA 7 \$0 Floor - Tile/Sheet 1st Floor 768 SF 7 \$0 Lighting - Pendent/Surface 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 7 \$0 Marker Board (Closet 1st Floor 36 SF 7 \$0 Storage/ Closet 1st Floor 818 SF 7 \$0 Walls - Concrete Block Work Sink 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 2 EA 6 \$991 Casswork 1st Floor 50 LF 7 \$0 Celling - Plaster/Drywall 1st Floor 1,664 SF 6 \$3,682 Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 </td <td></td> <td>Casework</td> <td>1st Floor</td> <td>24</td> <td>LF</td> <td>7</td> <td>\$0</td> <td></td>		Casework	1st Floor	24	LF	7	\$0	
Doors - Wood Doors inclu hw		Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
Floor - Tile/Sheet		Chalk Board	1st Floor	16	LF	4	\$1,469	
Lighting - Pendent/Surface 1st Floor 16 EA 7 \$ \$0 Marker Board 1st Floor 16 LF 7 \$ \$0 Storage/ Closet 1st Floor 36 SF 7 \$ \$0 Walls - Concrete Block 1st Floor 818 SF 7 \$ \$0 Work Sink 1st Floor 1 EA 7 \$ \$0 Classroom #111 (Kindergarten) AC Units 1st Floor 2 EA 6 \$991 Casework 1st Floor 50 LF 7 \$ \$0 Ceiling - Plaster/Drywall 1st Floor 1,064 SF 6 \$3,682 Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 EA 7 \$ \$0		Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
Marker Board 1st Floor 16 LF 7 \$0 Storage/ Closet 1st Floor 36 SF 7 \$0 Walls - Concrete Block Work Sink 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom #111 (Kindergarten) AC Units 1st Floor 2 EA 6 \$991 Casework 1st Floor 50 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 1,064 SF 6 \$3,682 Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 EA 7 \$0		Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
Storage/ Closet 1st Floor 36 SF 7 50 SF 7 \$0 SF 7		Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
Walls - Concrete Block Work Sink 1st Floor 818 SF 7 \$0 Work Sink 1st Floor 1 EA 7 \$0 Classroom #111 (Kindergarten) AC Units 1st Floor 2 EA 6 \$991 Casework 1st Floor 50 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 1,064 SF 6 \$3,682 Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 EA 7 \$0		Marker Board	1st Floor	16	LF	7	\$0	
Work Sink 1st Floor 1 EA 7 \$0 Classroom #111 (Kindergarten) St Floor 2 EA 6 \$991 AC Units 1st Floor 50 LF 7 \$0 Casework 1st Floor 50 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 1,064 SF 6 \$3,682 Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 EA 7 \$0		Storage/ Closet	1st Floor	36	SF	7	\$0	
Classroom #111 (Kindergarten) AC Units 1st Floor 2 EA 6 \$991 Casework 1st Floor 50 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 1,064 SF 6 \$3,682 Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 EA 7 \$0		Walls - Concrete Block	1st Floor	818	SF	7	\$0	
AC Units 1st Floor 2 EA 6 \$991 Casework 1st Floor 50 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 1,064 SF 6 \$3,682 Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 EA 7 \$0		Work Sink	1st Floor	1	EA	7	\$0	
Casework 1st Floor 50 LF 7 \$0 Ceiling - Plaster/Drywall 1st Floor 1,064 SF 6 \$3,682 Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 EA 7 \$0	Classro	oom #111 (Kindergarten)						
Ceiling - Plaster/Drywall 1st Floor 1,064 SF 6 \$3,682 Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 EA 7 \$0		AC Units	1st Floor	2	EA	6	\$991	
Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 EA 7 \$0		Casework	1st Floor	50	LF	7	\$0	
Chalk Board 1st Floor 12 LF 4 \$1,102 Doors - Wood Doors inclu hw 1st Floor 2 EA 7 \$0		Ceiling - Plaster/Drywall	1st Floor	1,064	SF	6	\$3,682	
		Chalk Board	1st Floor	12	LF	4	\$1,102	
Floor - Tile/Sheet 1st Floor 1,064 SF 7 \$0		Doors - Wood Doors inclu hw	1st Floor	2	EA	7	\$0	
		Floor - Tile/Sheet	1st Floor	1,064	SF	7	\$0	



9351 S Lowe Ave Chicago, IL 60620

Building: Main

up	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ssroc	om #111 (Kindergarten)						
	Lighting - Pendent/Surface	1st Floor	21	EA	7	\$0	
	Marker Board	1st Floor	8	LF	6	\$171	
	Storage/ Closet	1st Floor	42	SF	6	\$305	
	Walls - Concrete Block	1st Floor	1,292	SF	7	\$0	
	Work Sink	1st Floor	1	EA	7	\$0	
ssroc	om #114 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	856	SF	7	\$0	
ssroc	om #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EΑ	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	818	SF	7	\$0	
ssroc	om #116 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	



9351 S Lowe Ave Chicago, IL 60620

Building: Main

Froup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lassro	oom #116 (Regular Classroom)						
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	818	SF	7	\$0	
lassro	oom #117 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	818	SF	7	\$0	
lassro	oom #118 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	818	SF	7	\$0	
lassro	oom #119 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	818	SF	7	\$0	

9351 S Lowe Ave Chicago, IL 60620

Building: Main

(m #120 (Regular Classroom) AC Units Casework	1st Floor					
		1st Floor					
(Casework	13t F1001	1	EA	7	\$0	
		1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
,	Walls - Concrete Block	1st Floor	818	SF	6	\$2,398	
assroo	m #121 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	\$0	
1	Casework	1st Floor	24	LF	7	\$0	
1	Ceiling - Plaster/Drywall	1st Floor	654	SF	7	\$0	
1	Chalk Board	1st Floor	4	LF	4	\$367	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	654	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	13	EΑ	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	6	\$261	
	Walls - Concrete Block	1st Floor	551	SF	7	\$0	
,	Walls - Plaster/Drywall	1st Floor	209	SF	7	\$0	
assroo	m #122 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
1	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	818	SF	7	\$0	
assroo	m #123 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	\$0	
	Casework	1st Floor	24	LF	7	\$0	



\$39,733

9351 S Lowe Ave Chicago, IL 60620

Building: Main

Category: Classrooms

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #123 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Chalk Board	1st Floor	16	LF	4	\$1,469	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	768	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Storage/ Closet	1st Floor	36	SF	7	\$0	
	Walls - Concrete Block	1st Floor	818	SF	7	\$0	

Building: Main

Classrooms Subtotal:

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	AC Unit	110 Adjustment Office	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	110 Adjustment Office	384	SF	7	\$0	
	Doors - Wood Doors inclu hw	110 Adjustment Office	1	EA	7	\$0	
	Floor - Tile/Sheet	110 Adjustment Office	384	SF	7	\$0	
	Lighting - Pendent/Surface	110 Adjustment Office	8	EA	7	\$0	
	Power Distribution	110 Adjustment Office	4	EA	7	\$0	
	Storage/ Closet	110 Adjustment Office	6	SF	7	\$0	
	Walls - Concrete Block	110 Adjustment Office	656	SF	7	\$0	
	Work Sink	110 Adjustment Office	1	EA	7	\$0	
	AC Unit	Main Office	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	Main Office	408	SF	7	\$0	
	Doors - Side-lite	Main Office	5	SF	7	\$0	
	Doors - Store Front	Main Office	1	EA	7	\$0	
	Floor - Tile/Sheet	Main Office	408	SF	7	\$0	
	Lighting - Pendent/Surface	Main Office	7	EA	7	\$0	
	Power Distribution	Main Office	6	EA	7	\$0	
	Storage/ Closet	Main Office	24	SF	7	\$0	
	Walls - Concrete Block	Main Office	798	SF	7	\$0	
	Ceiling - Plaster/Drywall	Office Passageway	60	SF	6	\$208	
	Doors - Wood Doors inclu hw	Office Passageway	1	EA	6	\$301	
	Floor - Tile/Sheet	Office Passageway	60	SF	6	\$60	
	Lighting - Pendent/Surface	Office Passageway	3	EA	6	\$372	

9351 S Lowe Ave Chicago, IL 60620

Building: Main

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
_	strative Suites/Offices		•				
	Storage/ Closet	Office Passageway	184	SF	6	\$1,334	
	Walls - Concrete Block	Office Passageway	228	SF	6	\$668	
	AC Unit	Principal's Office	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	Principal's Office	234	SF	7	\$0	
	Doors - Wood Doors inclu hw	Principal's Office	2	EA	7	\$0	
	Floor - Tile/Sheet	Principal's Office	234	SF	7	\$0	
	Lighting - Pendent/Surface	Principal's Office	2	EA	7	\$0	
	Power Distribution	Principal's Office	5	EΑ	7	\$0	
	Storage/ Closet	Principal's Office	30	SF	7	\$0	
	Walls - Concrete Block	Principal's Office	760	SF	7	\$0	
	AC Unit	Teacher's Lounge	1	EA	7	\$0	
	Ceiling - Plaster/Drywall	Teacher's Lounge	204	SF	7	\$0	
	Doors - Wood Doors inclu hw	Teacher's Lounge	1	EA	7	\$0	
	Floor - Tile/Sheet	Teacher's Lounge	204	SF	7	\$0	
	Lighting - Pendent/Surface	Teacher's Lounge	4	EA	7	\$0	
	Power Distribution	Teacher's Lounge	4	EΑ	7	\$0	
	Walls - Concrete Block	Teacher's Lounge	532	SF	7	\$0	
	Work SInk	Teacher's Lounge	1	EA	7	\$0	
Gymna	sia						
	AC Unit	1st Floor	2	EA	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	2,720	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	7	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	2,720	SF	7	\$0	
	Lighting - Metal Halide/ High Pressure Sodium	1st Floor	10	EΑ	7	\$0	
	Storage/ Closet	1st Floor	240	SF	7	\$0	
	Walls - Concrete Block	1st Floor	1,836	SF	7	\$0	
	Walls - Structural Glazed Tile	1st Floor	1,428	SF	7	\$0	
Library							
	AC Unit	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	95	LF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Carpet	1st Floor	768	SF	6	\$1,636	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	\$0	
	Walls - Concrete Block	1st Floor	1,182	SF	7	\$0	



9351 S Lowe Ave Chicago, IL 60620

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Lunch	& Multipurpose Room						
	AC Unit	1st Floor	2	EA	6	\$991	
	Ceiling - Plaster/Drywall	1st Floor	1,104	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	1,104	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	\$0	
	Storage/ Closet	1st Floor	40	SF	7	\$0	
	Walls - Concrete Block	1st Floor	1,007	SF	7	\$0	
MDF_I	DF .						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	Location is within Computer Lab (Rm 121)
	Finishes	1st Floor	456	SF	7	\$0	
Mechai	nical/ Service Rooms						
	Boiler Room	1st Floor	936	SF	7	\$0	
	Janitor's Closet	1st Floor	25	SF	6	\$179	Janitor Closet
	Janitor's Closet	1st Floor	35	SF	6	\$251	Janitor Closet next to Girls Toilet Rm
	Mechanical/ Service Rooms	1st Floor	30	SF	7	\$0	Engineer's Office
	Storage Room	1st Floor	55	SF	6		Storage Rm next to Gym
	Storage Room	1st Floor	80	SF	6	\$573	
Restro	om						
	Accessories	111A	35	SF	7	\$0	
	Ceiling - Plaster/Drywall	111A	35	SF	7	\$0	
	Doors - Wood Doors inclu hw	111A	1	EA	7	\$0	
	Floor - Tile/Sheet	111A	35	SF	7	\$0	
	Lavatory	111A	1	EA	7	\$0	
	Lighting - Pendent/Surface	111A	1	EA	7	\$0	
	Walls - Concrete Block	111A	192	SF	7	\$0	
	Water Closet	111A	1	EA	7	\$0	
	Accessories	113A Kitchen	35	SF	7	\$0	
	Ceiling - Plaster/Drywall	113A Kitchen	35	SF	7	\$0	
	Doors - Wood Doors inclu hw	113A Kitchen	1	EΑ	7	\$0	
	Floor - Tile/Sheet	113A Kitchen	35	SF	7	\$0	
	Lavatory	113A Kitchen	1	EΑ	7	\$0	
	Lighting - Pendent/Surface	113A Kitchen	1	EA	7	\$0	
	Walls - Concrete Block	113A Kitchen	192	SF	7	\$0	
	Water Closet	113A Kitchen	1	EA	7	\$0	
	Accessories	East Corridor	264	SF	7	\$0	
	Ceiling - Plaster/Drywall	East Corridor	264	SF	7	\$0	

9351 S Lowe Ave Chicago, IL 60620

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Doors - Wood Doors inclu hw	East Corridor	1	EA	7	\$0	
	Floor Drain	East Corridor	1	EΑ	7	\$0	
	Floor - Tile Ceramic/ Porcelain	East Corridor	264	SF	7	\$0	
	Hand Dryer	East Corridor	2	EΑ	7	\$0	
	Lavatory	East Corridor	4	EΑ	7	\$0	
	Lighting - Pendent/Surface	East Corridor	2	EΑ	7	\$0	
	Partitions	East Corridor	5	EΑ	7	\$0	
	Walls - Structural Glazed Tile	East Corridor	720	SF	7	\$0	
	Water Closet	East Corridor	5	EΑ	7	\$0	
	Accessories	Engineer's Toilet	20	SF	6	\$184	
	Ceiling - Plaster/Drywall	Engineer's Toilet	20	SF	6	\$69	
	Doors - Steel Doors incl hw	Engineer's Toilet	1	EΑ	7	\$0	
	Floor - Tile/Sheet	Engineer's Toilet	20	SF	6	\$20	
	Lavatory	Engineer's Toilet	1	EΑ	6	\$320	
	Lighting - Pendent/Surface	Engineer's Toilet	1	EΑ	4	\$541	
	Walls - Concrete Block	Engineer's Toilet	162	SF	7	\$0	
	Water Closet	Engineer's Toilet	1	EΑ	7	\$0	
	Accessories	Principal's Toilet	20	SF	7	\$0	
	Ceiling - Plaster/Drywall	Principal's Toilet	20	SF	7	\$0	
	Doors - Wood Doors inclu hw	Principal's Toilet	1	EA	7	\$0	
	Floor - Tile/Sheet	Principal's Toilet	20	SF	7	\$0	
	Lavatory	Principal's Toilet	1	EΑ	7	\$0	
	Lighting - Pendent/Surface	Principal's Toilet	1	EA	4	\$541	
	Walls - Concrete Block	Principal's Toilet	162	SF	7	\$0	
	Water Closet	Principal's Toilet	1	EΑ	7	\$0	
	Accessories	South Corridor- West Mens	35	SF	7	\$0	
	Ceiling - Plaster/Drywall	South Corridor- West Mens	35	SF	7	\$0	
	Doors - Wood Doors inclu hw	South Corridor- West Mens	1	EA	7	\$0	
	Floor - Tile/Sheet	South Corridor- West Mens	35	SF	7	\$0	
	Lavatory	South Corridor- West Mens	1	EA	7	\$0	
	Lighting - Pendent/Surface	South Corridor- West Mens	1	EA	7	\$0	
	Walls - Concrete Block	South Corridor- West Mens	192	SF	7	\$0	
	Water Closet	South Corridor- West Mens	1	EΑ	7	\$0	
	Accessories	South Corridor- West Womens	70	SF	7	\$0	
	Ceiling - Plaster/Drywall	South Corridor- West Womens	70	SF	7	\$0	
	Doors - Wood Doors inclu hw	South Corridor- West Womens	1	EA	7	\$0	
	Floor - Tile/Sheet	South Corridor- West Womens	70	SF	7	\$0	

9351 S Lowe Ave Chicago, IL 60620

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	**						
	Lavatory	South Corridor- West Womens	2	EA	7	\$0	
	Lighting - Pendent/Surface	South Corridor- West Womens	1	EA	7	\$0	
	Partitions	South Corridor- West Womens	2	EA	7	\$0	
	Walls - Concrete Block	South Corridor- West Womens	432	SF	7	\$0	
	Water Closet	South Corridor- West Womens	2	EA	7	\$0	
	Accessories	South Corridor	348	SF	7	\$0	
	Accessories	South Corridor	264	SF	7	\$0	
	Ceiling - Plaster/Drywall	South Corridor	264	SF	7	\$0	
	Ceiling - Plaster/Drywall	South Corridor	348	SF	6	\$1,204	
	Doors - Wood Doors inclu hw	South Corridor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	South Corridor	1	EA	7	\$0	
	Floor Drain	South Corridor	1	EA	7	\$0	
	Floor Drain	South Corridor	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	South Corridor	264	SF	7	\$0	
	Floor - Tile Ceramic/ Porcelain	South Corridor	348	SF	7	\$0	
	Hand Dryer	South Corridor	2	EA	7	\$0	
	Hand Dryer	South Corridor	2	EA	7	\$0	
	Lavatory	South Corridor	4	EA	7	\$0	
	Lavatory	South Corridor	4	EA	7	\$0	
	Lighting - Pendent/Surface	South Corridor	2	EA	7	\$0	
	Lighting - Pendent/Surface	South Corridor	2	EA	7	\$0	
	Partitions	South Corridor	3	EA	7	\$0	
	Partitions	South Corridor	9	EA	6	\$2,672	
	Urinals	South Corridor	7	EA	6	\$2,352	
	Walls - Structural Glazed Tile	South Corridor	720	SF	7	\$0	
	Walls - Structural Glazed Tile	South Corridor	792	SF	7	\$0	
	Water Closet	South Corridor	9	EA	7	\$0	
	Water Closet	South Corridor	3	EA	7	\$0	
	Accessories	West Corridor	264	SF	7	\$0	
	Ceiling - Plaster/Drywall	West Corridor	264	SF	7	\$0	
	Doors - Wood Doors inclu hw	West Corridor	1	EA	7	\$0	
	Floor Drain	West Corridor	1	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	West Corridor	264	SF	7	\$0	
	Hand Dryer	West Corridor	2	EA	7	\$0	
	Lavatory	West Corridor	3	EA	7	\$0	
	Lighting - Pendent/Surface	West Corridor	2	EA	7	\$0	
	Partitions	West Corridor	2	EA	7	\$0	



9351 S Lowe Ave Chicago, IL 60620

Building: Main

Category: Rooms (Other Than Classrooms)

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
Restroom						
Urinals	West Corridor	4	EA	7	\$0	
Walls - Structural Glazed Tile	West Corridor	20	SF	7	\$0	
Water Closet	West Corridor	2	EA	7	\$0	

Rooms (Other Than Classrooms) Subtotal:

\$15,862

Building: Main

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Commen
Corrido	r						
	Ceiling - Plaster/Drywall	Corridor 1 / 1st Floor	1,430	SF	6	\$8,854	
	Floor - Tile/Sheet	Corridor 1 / 1st Floor	1,430	SF	7	\$0	
	Lighting - Pendent/Surface	Corridor 1 / 1st Floor	16	EA	7	\$0	
	Walls - Concrete Block	Corridor 1 / 1st Floor	2,805	SF	7	\$0	
	Ceiling - Plaster/Drywall	Corridor 2 / 1st Floor	1,456	SF	6	\$9,015	
	Drinking Fountains - Double Fountain	Corridor 2 / 1st Floor	2	EA	7	\$0	
	Floor - Tile/Sheet	Corridor 2 / 1st Floor	1,456	SF	7	\$0	
	Lighting - Pendent/Surface	Corridor 2 / 1st Floor	16	EA	7	\$0	
	Walls - Concrete Block	Corridor 2 / 1st Floor	3,162	SF	7	\$0	
	Ceiling - Plaster/Drywall	Corridor 3 / 1st Floor	1,456	SF	6	\$9,015	
	Drinking Fountains - Double Fountain	Corridor 3 / 1st Floor	2	EA	7	\$0	
	Floor - Tile/Sheet	Corridor 3 / 1st Floor	1,456	SF	7	\$0	
	Lighting - Pendent/Surface	Corridor 3 / 1st Floor	16	EA	7	\$0	
	Walls - Concrete Block	Corridor 3 / 1st Floor	3,162	SF	7	\$0	
	Ceiling - Plaster/Drywall	Passage 4 / 1st Floor	108	SF	7	\$0	
	Floor - Tile/Sheet	Passage 4 / 1st Floor	108	SF	7	\$0	
	Lighting - Pendent/Surface	Passage 4 / 1st Floor	2	EA	7	\$0	
	Walls - Concrete Block	Passage 4 / 1st Floor	460	SF	7	\$0	
	Ceiling - Plaster/Drywall	Passage 5 / 1st Floor	64	SF	7	\$0	
	Floor - Tile/Sheet	Passage 5 / 1st Floor	64	SF	7	\$0	
	Lighting - Pendent/Surface	Passage 5 / 1st Floor	2	EA	7	\$0	
	Walls - Concrete Block	Passage 5 / 1st Floor	272	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule 1 / 1st Floor	60	SF	7	\$0	
	Doors - Side-lite	Vestibule 1 / 1st Floor	2	EA	7	\$0	
	Doors - Wood Doors include hw	Vestibule 1 / 1st Floor	2	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Vestibule 1 / 1st Floor	60	SF	7	\$0	
	Lighting - Pendent/Surface	Vestibule 1 / 1st Floor	1	EA	4	\$541	T-12



9351 S Lowe Ave Chicago, IL 60620

Building: Main

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	r						
	Walls - Masonry	Vestibule 1 / 1st Floor	108	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule 2 / 1st Floor	136	SF	7	\$0	
	Doors - Wood Doors include hw	Vestibule 2 / 1st Floor	4	EΑ	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Vestibule 2 / 1st Floor	136	SF	7	\$0	
	Lighting - Pendent/Surface	Vestibule 2 / 1st Floor	2	EΑ	4	\$1,081	T-12
	Walls - Masonry	Vestibule 2 / 1st Floor	216	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule 3 / 1st Floor	135	SF	7	\$0	
	Doors - Wood Doors include hw	Vestibule 3 / 1st Floor	4	EΑ	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Vestibule 3 / 1st Floor	135	SF	7	\$0	
	Lighting - Pendent/Surface	Vestibule 3 / 1st Floor	2	EΑ	4	\$1,081	T-12
	Walls - Masonry	Vestibule 3 / 1st Floor	216	SF	7	\$0	
	Ceiling - Plaster/Drywall	Vestibule 4 / 1st Floor	60	SF	7	\$0	
	Doors - Wood Doors include hw	Vestibule 4 / 1st Floor	2	EA	7	\$0	
	Floor - Tile Ceramic/ Porcelain	Vestibule 4 / 1st Floor	60	SF	7	\$0	
	Lighting - Pendent/Surface	Vestibule 4 / 1st Floor	1	EA	4	\$541	T-12
	Walls - Masonry	Vestibule 4 / 1st Floor	108	SF	7	\$0	
Safety							
	Camera Viewing Station	Principal's Office	1	EA	7	\$0	
	Security Cameras	Principal's Office / Entire Building	5	EA	6	\$970	
Duildi	ng Interior Subtetal:					\$21,000	

Building Interior Subtotal: \$31,099

Total Building Cost \$2,740,447

Building: 2-Classroom Modular

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntrance						
Exterior Doors - Exterior Steel Door	1	1	EA	7	\$0	
Exterior Doors - Exterior Steel Door	1	1	EA	7	\$0	
Exterior Doors - Exterior Steel Door	1	1	EA	7	\$0	
Exterior Doors - Exterior Steel Door	1	1	EA	7	\$0	
Exterior Doors - Exterior Steel Door	2	1	EA	5	\$1,341	
Exterior Doors - Exterior Steel Door	2	1	EA	5	\$1,341	
Exterior Doors - Exterior Steel Door	2	1	EA	5	\$1,341	
Exterior Doors - Exterior Steel Door	2	1	EA	5	\$1,341	

9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntrand	ce						
	Exterior Doors - Exterior Steel Door	3	1	EA	5	\$1,341	
	Exterior Doors - Exterior Steel Door	3	1	EA	5	\$1,341	
	Exterior Doors - Exterior Steel Door	3	1	EA	5	\$1,341	
	Exterior Doors - Exterior Steel Door	3	1	EA	5	\$1,341	
	Exterior Stairs - Concrete	3	5	LF	6	\$409	
	Exterior Stairs - Concrete	3	5	LF	6	\$409	
	Exterior Stairs - Steel or Aluminum	1	20	LF	5	\$144	rusted
	Exterior Stairs - Steel or Aluminum	1	20	LF	5	\$144	rusted
	Exterior Stairs - Steel or Aluminum	1	20	LF	5	\$144	rusted
	Exterior Stairs - Steel or Aluminum	1	20	LF	5	\$144	rusted
	Exterior Stairs - Steel or Aluminum	2	20	LF	5	\$144	rusted
	Exterior Stairs - Steel or Aluminum	2	20	LF	5	\$144	rusted
	Exterior Stairs - Steel or Aluminum	2	20	LF	5	\$144	
	Exterior Stairs - Steel or Aluminum	2	20	LF	5	\$144	
	Exterior Stairs - Steel or Aluminum	3	20	LF	5	\$144	rusted
	Exterior Stairs - Steel or Aluminum	3	20	LF	5	\$144	
	Exterior Stairs - Steel or Aluminum	3	20	LF	5	\$144	rusted
	Exterior Stairs - Steel or Aluminum	3	20	LF	5	\$144	
	Ramp Handrail - Steel_Ramp Handrail	1	78	LF	6	\$676	
	Ramp Handrail - Steel_Ramp Handrail	1	78	LF	6	\$676	
	Ramp Handrail - Steel_Ramp Handrail	1	78	LF	6	\$676	
	Ramp Handrail - Steel_Ramp Handrail	1	78	LF	6	\$676	
	Ramps - Steel or Aluminum	1	39	LF	5	\$20,970	rusted
	Ramps - Steel or Aluminum	1	39	LF	5	\$20,970	rusted
	Ramps - Steel or Aluminum	1	39	LF	5	\$20,970	rusted
	Ramps - Steel or Aluminum	1	39	LF	5	\$20,970	rusted
	Stair Handrail - Steel_Stair Handrail	1	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	1	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	1	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	1	20	LF	6	\$173	
	Stair Handrail - Steel_Stair Handrail	2	12	LF	6	\$104	
	Stair Handrail - Steel_Stair Handrail	2	12	LF	6	\$104	
	Stair Handrail - Steel_Stair Handrail	2	12	LF	6	\$104	
	Stair Handrail - Steel_Stair Handrail	2	12	LF	6	\$104	
	Stair Handrail - Steel_Stair Handrail	3	12	LF	6	\$104	
	Stair Handrail - Steel_Stair Handrail	3	12	LF	6	\$104	
	Stair Handrail - Steel_Stair Handrail	3	12	LF	6	\$104	



9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ntranc	е						
	Stair Handrail - Steel_Stair Handrail	3	12	LF	6	\$104	
oundat	tion						
	Foundation - Concrete	Entire Building	188	LF	7	\$0	point supported by piers
	Foundation - Concrete	Entire Building	188	LF	7	\$0	point supported by piers
	Foundation - Concrete	Entire Building	188	LF	7	\$0	point supported with piers
	Foundation - Concrete	Entire Building	188	LF	7	\$0	point supported with piers
	Superstructure - Steel	Entire Building	1,633	SF	7	\$0	steel support frame at raised first floor
	Superstructure - Steel	Entire Building	1,633	SF	7	\$0	steel support frame at raised 1st floor
	Superstructure - Steel	Entire Building	1,633	SF	7	\$0	steel support frame at raised first floor
	Superstructure - Steel	Entire Building	1,633	SF	7	\$0	steel support frame at raised 1st floor
ghting	1						
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	\$1,155	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	\$1,155	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	\$1,030	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	\$1,030	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	\$1,155	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	\$1,155	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	\$1,030	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	\$1,030	
oof Sy	rstem						
	Downspouts - Exterior Downspouts	Roof C	22	LF	5	\$1,777	disconnected from gutter at east facade
	Downspouts - Exterior Downspouts	Roof C	22	LF	5	\$1,777	disconnected from gutter at east facade
	Downspouts - Exterior Downspouts	Roof D	22	LF	5	\$1,777	disconnected from gutter at east facade
	Downspouts - Exterior Downspouts	Roof D	22	LF	5	\$1,777	disconnected from gutter at east facade
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof C	1,633	SF	7	\$0	•
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof C	1,633	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof D	1,633	SF	7	\$0	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof D	1,633	SF	7	\$0	
	Roof - Metal	Roof C	1,633	SF	4	\$78,416	deteriorated, rusted, multiple leaks reported
	Roof - Metal	Roof C	1,633	SF	4	\$78,416	deteriorated, rusted, multiple leaks reported
	Roof - Metal	Roof D	1,633	SF	4	\$78,416	deteriorated, rusted, multiple leaks reported
	Roof - Metal	Roof D	1,633	SF	4	\$78,416	deteriorated, rusted, multiple leaks reported
alls							
	Exterior Walls - Wood Siding	Entire Building	1,940	SF	4	\$40,559	deteriorated, warped, and rotted wood; open hole at skirt base



9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular

Category: Building Exterior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Walls							
	Exterior Walls - Wood Siding	Entire Building	1,940	SF	4	\$40,559	deteriorated, warped, and rotted wood; open holes at base skirt
	Exterior Walls - Wood Siding	Entire Building	1,940	SF	4	\$40,559	deteriorated, warped, and rotted wood; open holes at base skirt
	Exterior Walls - Wood Siding	Entire Building	1,940	SF	4	\$40,559	deteriorated, warped, and rotted wood; open holes at skirt base
Windov	vs						
	Guard - Guards perforated	Entire Building	128	SF	5	\$1,962	
	Guard - Guards perforated	Entire Building	128	SF	5	\$1,962	
	Guard - Guards wire guard	Entire Building	128	SF	5	\$1,962	
	Guard - Guards wire guard	Entire Building	128	SF	5	\$1,962	
	Windows - Sash Aluminum	Entire Building	128	SF	5	\$4,596	
	Windows - Sash Aluminum	Entire Building	128	SF	5	\$4,596	
	Windows - Sash Aluminum	Entire Building	128	SF	5	\$4,596	
	Windows - Sash Aluminum	Entire Building	128	SF	5	\$4,596	
Buildi	ing Exterior Subtotal:				,	\$619,356	

Building: 2-Classroom Modular

Category: Electrical System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Emerge	ency System						
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	\$150	
Main Se	ervice						
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building / North Façade	1	EA	6	\$3,570	
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building / North Façade	1	EA	6	\$3,570	
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building / North Façade	1	EA	6	\$3,570	
	Main Electrical Service - 800 A and 120/208/3PH	Entire Building / North Façade	1	EA	6	\$3,570	
Power I	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	\$299	Fuses
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	\$299	Fuses
	Lighting and Power Panels - 100 A	Entire Building	14	EA	6	\$4,188	
	Lighting and Power Panels - 100 A	Entire Building	14	EA	6	\$4,188	



9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular

Category: Electrical System

Group Item - Type)	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution							
Lighting and	Power Panels - 100 A	Entire Building	2	EA	6	\$598	
Lighting and	Power Panels - 100 A	Entire Building	2	EA	6	\$598	
Main Distrib	oution Panels - Greater than 600 amp	Entire Building	1	EA	6	\$730	Fuses - Doors Screwed shut
Main Distrib	oution Panels - Greater than 600 amp	Entire Building	1	EA	6	\$730	Fuses - Doors Screwed shut
Main Distrib	oution Panels - Greater than 600 amp	Entire Building / Boiler Room	1	EA	6	\$730	
Main Distrib	oution Panels - Greater than 600 amp	Entire Building / Boiler Room	1	EA	6	\$730	

Electrical System Subtotal: \$27,970

Building: 2-Classroom Modular

Category: Safty System

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Sprinkl	er System						
	Sprinkler Heads	Entire Building	1,633	SF	7	\$0	
	Sprinkler Heads	Entire Building	1,633	SF	7	\$0	
	Sprinkler Heads	Entire Building	1,633	SF	7	\$0	
	Sprinkler Heads	Entire Building	1,633	SF	7	\$0	
	Sprinkler Piping	Entire Building	1,633	SF	6	\$304	
	Sprinkler Piping	Entire Building	1,633	SF	6	\$304	
	Sprinkler Piping	Entire Building	1,633	SF	6	\$304	
	Sprinkler Piping	Entire Building	1,633	SF	6	\$304	
	Wet Sprinkler System	Entire Building	1,633	SF	6	\$420	Operates on city pressure
	Wet Sprinkler System	Entire Building	1,633	SF	6	\$420	Operates on city pressure
	Wet Sprinkler System	Entire Building	1,633	SF	6	\$420	Operates on city pressure
	Wet Sprinkler System	Entire Building	1,633	SF	6	\$420	Operates on city pressure

Safty System Subtotal: \$2,896

Building: 2-Classroom Modular

Category: Mechanical System

Group Item - Type	Location	Quantity Unit Ra	ınk Cost	Comments
Temperature Control				
Electric Controls	Entire Building	1,633 SF	6 \$0	
Electric Controls	Entire Building	1,633 SF	6 \$0	
Electric Controls	Entire Building	1,633 SF (6 \$0	
Electric Controls	Entire Building	1,633 SF (6 \$0	



9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular Category: Mechanical System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Temperature Control						
Electric Thermostat	Entire Building	2	EA	6	\$0	
Electric Thermostat	Entire Building	2	EΑ	6	\$0	
Electric Thermostat	Entire Building	2	EA	6	\$0	
Electric Thermostat	Entire Building	2	EA	6	\$0	
Unit Ventilation						
Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	Wall mounted units. Each unit serves on of the 2 classrooms. Date not available.
Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	Wall mounted units. Each unit serves on of the 2 classrooms. Date not available.
Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	Wall mounted units. Each unit serves on of the 2 classrooms. Date not available.
Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Exterior Wall	2	EA	6	\$0	Wall mounted units. Each unit serves on of the 2 classrooms. Date not available.
Ventilation						
Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592	
Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EΑ	6	\$592	
Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592	
Exhaust Fans- Roof Mounted - Less than 500 CFM	Roof	2	EA	6	\$592	
Mechanical System Subtotal:					\$2,370	

Mechanical System Subtotal:

Building: 2-Classroom Modular Category: Plumbing System

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lot Water						
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	
Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	\$682	
Piping						
Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	1,633	SF	6	\$327	
Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	1,633	SF	6	\$327	
Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	1,633	SF	6	\$327	
Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	1,633	SF	6	\$327	
Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,633	SF	6	\$397	
Domestic Piping-Cold Water Horizontal Lines	Entire Building	1,633	SF	6	\$397	

9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular

Category: Plumbing System Group Item - Type Location Quantity Unit Rank Cost Comments **Piping** Domestic Piping-Cold Water Horizontal Lines **Entire Building** 1.633 SF 6 \$397 SF 6 \$397 Domestic Piping-Cold Water Horizontal Lines **Entire Building** 1.633 Domestic Piping-Cold Water Risers **Entire Building** 1.633 SF 6 \$304 SF 6 Domestic Piping-Cold Water Risers **Entire Building** 1.633 \$304 1,633 Domestic Piping-Cold Water Risers **Entire Building** SF 6 \$304 Domestic Piping-Cold Water Risers **Entire Building** 1.633 SF 6 \$304 1,633 Domestic Piping-Hot Water from Risers to Fixtures **Entire Building** SF 6 \$257 6 Domestic Piping-Hot Water from Risers to Fixtures **Entire Building** 1.633 SF \$257 Domestic Piping-Hot Water from Risers to Fixtures **Entire Building** 1.633 SF 6 \$257 SF 6 Domestic Piping-Hot Water from Risers to Fixtures **Entire Building** 1.633 \$257 Domestic Piping-Hot Water Horizontal Lines **Entire Building** 1.633 SF 6 \$304 SF 6 Domestic Piping-Hot Water Horizontal Lines **Entire Building** 1.633 \$304 Domestic Piping-Hot Water Horizontal Lines **Entire Building** SF 6 \$304 1,633 SF Domestic Piping-Hot Water Horizontal Lines **Entire Building** 1,633 6 \$304 Domestic Piping-Hot Water Return Lines **Entire Building** 1,633 SF 6 \$234 SF Domestic Piping-Hot Water Return Lines **Entire Building** 1,633 6 \$234 Domestic Piping-Hot Water Return Lines **Entire Building** 1,633 SF 6 \$234 Domestic Piping-Hot Water Return Lines **Entire Building** 1,633 SF 6 \$234 SF 6 \$234 Domestic Piping-Hot Water Return Risers **Entire Building** 1,633 Domestic Piping-Hot Water Return Risers **Entire Building** 1,633 SF 6 \$234 Domestic Piping-Hot Water Return Risers SF 6 \$234 **Entire Building** 1,633 SF \$234 Domestic Piping-Hot Water Return Risers **Entire Building** 1,633 6 Sanitary Piping **Entire Building** 1,633 SF 6 \$1,495 SF Sanitary Piping **Entire Building** 1,633 6 \$1,495 Sanitary Piping **Entire Building** 1,633 SF 6 \$1,495 Sanitary Piping **Entire Building** 1,633 SF 6 \$1,495 SF 6 Storm Piping **Entire Building** 1,633 \$1,424 SF Storm Piping **Entire Building** 1,633 6 \$1,424 SF 6 Storm Piping **Entire Building** 1,633 \$1,424 Storm Piping **Entire Building** 1,633 SF 6 \$1,424

Plumbing System Subtotal:

Vent Piping

Vent Piping

Vent Piping

Vent Piping

\$27,015

\$1,098

\$1,098

\$1.098

\$1,098

SF

SF

SF

SF

1,633

1,633

1.633

1,633

6

6

6

6

Entire Building

Entire Building

Entire Building

Entire Building

9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular

auori	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	om #101 (Art Room)						
	Ceiling - Plaster/Drywall	1st Floor	646	SF	7	\$0	FRP
	Ceiling - Plaster/Drywall	1st Floor	646	SF	7		FRP
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	646	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	646	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	\$0	
	Storage/ Closet	1st Floor	48	SF	7	\$0	
	Storage/ Closet	1st Floor	48	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	784	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	784	SF	7	\$0	
	•					·	
assro	om #101 (Music Room)						
	Ceiling - Plaster/Drywall	1st Floor	646	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	646	SF	7	\$0	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	646	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	646	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	\$0	
	Storage/ Closet	1st Floor	48	SF	7	\$0	
	Storage/ Closet	1st Floor	48	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	784	SF	7	\$0	FRP
	Walls - Plaster/Drywall	1st Floor	784	SF	7	\$0	FRP
assro	om #102 (Music Room)						
	Ceiling - Plaster/Drywall	1st Floor	616	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	616	SF	7	\$0	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	



9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular

Category: Classrooms

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #102 (Music Room)						
	Floor - Tile/Sheet	1st Floor	616	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	616	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	15	EΑ	7	\$0	
	Lighting - Pendent/Surface	1st Floor	15	EΑ	7	\$0	
	Storage/ Closet	1st Floor	18	SF	7	\$0	
	Storage/ Closet	1st Floor	18	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	750	SF	7	\$0	FRP
	Walls - Plaster/Drywall	1st Floor	750	SF	7	\$0	FRP
Classro	oom #102 (Store Room)						
	Ceiling - Plaster/Drywall	1st Floor	616	SF	7	\$0	FRP
	Ceiling - Plaster/Drywall	1st Floor	616	SF	7	\$0	FRP
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Chalk Board	1st Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Tile/Sheet	1st Floor	616	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	616	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	\$0	
	Storage/ Closet	1st Floor	18	SF	7	\$0	
	Storage/ Closet	1st Floor	18	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	750	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	750	SF	7	\$0	

Classrooms Subtotal: \$11,221

Building: 2-Classroom Modular

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments
Restroom					
Accessories	1st Floor	56	SF	6	\$517
Accessories	1st Floor	56	SF	6	\$517
Accessories	1st Floor	56	SF	6	\$517
Accessories	1st Floor	56	SF	6	\$517
Accessories	1st Floor	56	SF	6	\$517
Accessories	1st Floor	56	SF	7	\$0

9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	om						
	Accessories	1st Floor	56	SF	7	\$0	
	Accessories	1st Floor	56	SF	6	\$517	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	56	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	56	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	56	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	56	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	56	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	56	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	56	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	56	SF	7	\$0	
	Lavatory	1st Floor	1	EA	7	\$0	
	Lavatory	1st Floor	1	EA	7	\$0	
	Lavatory	1st Floor	1	EA	7	\$0	
	Lavatory	1st Floor	1	EA	7	\$0	
	Lavatory	1st Floor	1	EA	7	\$0	
	Lavatory	1st Floor	1	EΑ	7	\$0	
	Lavatory	1st Floor	1	EA	7	\$0	
	Lavatory	1st Floor	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	1	EA	4	\$541	T12 light fixture
	Lighting - Pendent/Surface	1st Floor	1	EA	4	\$541	T12 light fixture
	Lighting - Pendent/Surface	1st Floor	1	EA	4	\$541	T12 light fixture
						•	<u> </u>



9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular

Category: Rooms (Other Than Classrooms)

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
estroom						
Lighting - Pendent/Surface	1st Floor	1	EA	4	\$541	T12 light fixture
Lighting - Pendent/Surface	1st Floor	1	EA	4	\$541	T12 light fixture
Lighting - Pendent/Surface	1st Floor	1	EA	4	\$541	T12 light fixture
Lighting - Pendent/Surface	1st Floor	1	EA	4	\$541	T12 light fixture
Lighting - Pendent/Surface	1st Floor	1	EA	4	\$541	T12 light fixture
Walls - Concrete Block	1st Floor	30	SF	7	\$0	
Walls - Concrete Block	1st Floor	30	SF	7	\$0	
Walls - Concrete Block	1st Floor	30	SF	7	\$0	
Walls - Concrete Block	1st Floor	30	SF	7	\$0	
Walls - Concrete Block	1st Floor	30	SF	7	\$0	
Walls - Concrete Block	1st Floor	30	SF	7	\$0	
Walls - Concrete Block	1st Floor	30	SF	7	\$0	
Walls - Concrete Block	1st Floor	30	SF	7	\$0	
Water Closet	1st Floor	1	EA	7	\$0	
Water Closet	1st Floor	1	EA	7	\$0	
Water Closet	1st Floor	1	EA	7	\$0	
Water Closet	1st Floor	1	EA	7	\$0	
Water Closet	1st Floor	1	EA	7	\$0	
Water Closet	1st Floor	1	EA	7	\$0	
Water Closet	1st Floor	1	EA	7	\$0	
Water Closet	1st Floor	1	EΑ	7	\$0	

Rooms (Other Than Classrooms) Subtotal:

\$7,424

Building: 2-Classroom Modular

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	•						
	Ceiling - Plaster/Drywall	1st Floor	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	90	SF	7	\$0	
	Ceiling - Plaster/Drywall	1st Floor	90	SF	7	\$0	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	\$0	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	\$0	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	\$0	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	\$0	
	Floor - Tile/Sheet	1st Floor	90	SF	7	\$0	



9351 S Lowe Ave Chicago, IL 60620

Building: 2-Classroom Modular

Category: Building Interior

Group	Item - Type	Location	Quantity	Unit	Rank	Cost Comments	
Corrido	or						
	Floor - Tile/Sheet	1st Floor	90	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	90	SF	7	\$0	
	Floor - Tile/Sheet	1st Floor	90	SF	7	\$0	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	\$0	
	Walls - Concrete Block	1st Floor	288	SF	7	\$0	
	Walls - Concrete Block	1st Floor	288	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	288	SF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	288	SF	7	\$0	
Buildi	ing Interior Subtotal:					\$0	

Total Building Cost \$698,251

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Civil/Dr	rainage						
	Civil/ Drainage - Catch Basin	Entire Site	11	EA	7	\$0	
	Civil/ Drainage - Site Manhole	Entire Site	2	EA	7	\$0	
Fencing	g						
	Fencing - Chain Link	Entire Site	17	LF	4	\$1,561	S side of parking lot- missing or loose posts
	Fencing - Chain Link	Entire Site	189	LF	6	\$3,549	NE at parking lot
	Fencing - New Standard Ornamental	Entire Site	1,021	LF	6	\$32,573	
	Fencing - New Standard Ornamental	Entire Site	96	LF	5	\$13,670	N and courtyard- damaged or corroded section
	Fencing - Wood Fencing w/ Steel Frame	Entire Site / North East	136	LF	5	\$10,764	trash enclosure- damaged and slats missing
Landsc	ape						
	Benches	Entire Site / North West	1	EΑ	7	\$0	
	Landscape - Grass	Entire Site	30,542	SF	7	\$0	
	Landscape - Hardscape- Concrete	Entire Site	6,345	SF	6	\$32,755	
	Landscape - Hardscape- Concrete	Entire Site / Site - East	825	SF	5	\$9,049	cracked at door 5
	Parkway trees	Entire Site	58	EΑ	7	\$0	
	Planting Beds/ Area	Entire Site / Site South	1,520	SF	6	\$2,500	some loose stone pavers at perimeter



9351 S Lowe Ave Chicago, IL 60620

SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Landsc	ape						
	Play Area - Asphalt/ Hardscape	Entire Site	58,700	SF	5	\$267,772	deteriorated surface, cracking, loose patches
	Trash Receptacles	Entire Site / North West	1	EA	6	\$312	
Parking	g Lot						
	Concrete Curbs	Northeast	120	LF	7	\$0	
	Interior Plantings	Northeast	10	LF	7	\$0	
	Interior Plantings	Northeast / North East	1	LF	4	\$116	tree stump at corner
	Surface - Asphalt	Northeast	15,168	SF	6	\$36,657	restripe
	Trash Enclosure - Wood	Northeast	1,012	SF	5	\$41,765	
	Vehicular Screening	Northeast	265	LF	5	\$37,736	covers approximately 1/2 length of parking lot only
Playgro	ound						
	Equipment - School Age 5-12	Site North West	1	EA	6	\$3,546	
	Equipment - Swingset	Site North West	1	EA	4	\$16,656	broken, detached swing chains
	Surface - Square Rubber Mats	Site North West	4,900	SF	4	\$85,626	loose, deteriorated surface, graffiti/vandalism
Sidewa	lks						
	Sidewalks - Internal Walks	Entire Site / South East	76	LF	6	\$913	
	Sidewalks - Perimeter Sidewalks	Entire Site	14,832	SF	7	\$0	
Signage	e						
	Flag Pole - Flag Pole	South West	1	EA	6	\$1,657	
	Marquee - Free Standing Back Lighted	South West	1	EA	6	\$0	
Site S	Subtotal:					\$599,174	
Total	Site Cost					\$599,174	

Campus Total ^{2 3} \$4,037,872

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.



9351 S Lowe Ave Chicago, IL 60620

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



9351 S Lowe Ave Chicago, IL 60620

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main			+		+	1	-	-		+	-	 		+
Computer Lab	Computer Lab	1st Floor	121	121	654	0	60	60	158	74	40	N	Υ	N
Kindergarten	Kindergarten	1st Floor	111	111	1,064	1	6	12	130	102	40	Υ	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	100	100	768	0	6	14	158	74	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	101	101	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	768	0	6	14	158	74	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	105	105	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	106	106	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	107	107	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	108	108	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	114	114	768	0	6	14	158	74		N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	115	115	768	0	6	14	158	74	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	116	116	768	0	6	14	158	74	40	N	Υ	N
Regular Classroom	Regular Classroom	1st Floor	117	117	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	118	118	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	119	119	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	120	120	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	122	122	768	0	6	14	158	74	40	N	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	123	123	768	0	6	14	158	74	40	Υ	Υ	N
2-Classroom Mod	dular													
Art Room	Art Room	1st Floor	101	101	646	0	1	10	52	25	40	N	Υ	N
Music Room	Music Room	1st Floor	101	101	646	0	1	10	52	25	40	N	Υ	N
Music Room	Music Room	1st Floor	102	102	616	0	1	10	52	25	40	N	Υ	N
Store Room	Regular Classroom	1st Floor	102	02	616	0	1	10	52	25	40	N	Υ	N