

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1881 | 3 | 68,750 | \$3,727,625 |
| SITE | | | | \$179,832 |
| Campus Total | | | 68,750 | \$3,907,457 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|------------------------------|----------|------|------|-----------|------------------------|
| Entrand | ce de la constante de la consta | | | | | | |
| | Entrance Control - Audio | 1 Main N | 1 | EA | 6 | \$497 | |
| | Exterior Doors - Exterior Steel Door | 1 Main N | 3 | EA | 6 | \$1,442 | |
| | Exterior Doors - Exterior Steel Door | 2 NE | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | 3 S | 3 | EA | 6 | \$1,442 | |
| | Exterior Doors - Exterior Steel Door | 4 E | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 5 E | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | 6 S | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | at Fire escapes | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Transom Lite | 1 Main N | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | 2 NE | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | 3 S | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | at Fire escapes | 2 | EA | 6 | \$627 | |
| | Exterior Stairs - Concrete | 2 NE | 15 | LF | 6 | \$1,227 | |
| | Exterior Stairs - Concrete | 5 E | 5 | LF | 6 | \$409 | |
| ire Es | саре | | | | | | |
| | Fire Escape | Entire Building / South East | 160 | LF | 6 | \$101,082 | |
| ounda | tion | | | | | | |
| | Foundation - Masonry | Entire Building | 780 | LF | 7 | \$0 | |
| | Foundation - Masonry | Entire Building | 70 | LF | 5 | \$23,342 | Location: Boiler House |
| | Superstructure - Heavy Timber | Entire Building | 68,750 | SF | 7 | \$0 | |



Building: Main

Category: Building Exterior

| Foundation Lighting Exterior Lighting - Wall Me Roof System | punted | | | | | | |
|--|--------------------------|--------------------------------|--------|----|---|-----------|--|
| Exterior Lighting - Wall Me | punted | Entire Duilding | | | | | |
| Exterior Lighting - Wall Me | punted | Entire Duilding | | | | | |
| Roof System | | Entire Building | 7 | EA | 6 | \$2,021 | |
| | | | | | | | |
| Chimney - Brick Chimney | - Concrete/ Mortar Liner | #3 | 30 | LF | 5 | \$85,547 | Location: Top - efflorescence, cracks, open joints |
| Chimney - Brick Chimney | - Concrete/ Mortar Liner | #3 | 50 | LF | 6 | \$47,734 | Location: bottom |
| Coping - Clay Tile | | #1 / East | 30 | LF | 6 | \$964 | |
| Coping - Stone | | #1 / North | 144 | LF | 6 | \$4,625 | |
| Coping - Stone | | #3 | 219 | LF | 6 | | open joints |
| Coping - Stone | | #5 | 50 | LF | 6 | \$1,606 | open joints |
| Coping - Terra Cotta | | #1 | 445 | LF | 6 | | Location: S and SE |
| Downspouts - Exterior Do | ownspouts | #1 | 300 | LF | 6 | \$9,970 | |
| Downspouts - Exterior Do | ownspouts | #2 | 30 | LF | 6 | \$997 | |
| Downspouts - Exterior Do | ownspouts | #3 | 30 | LF | 6 | \$997 | |
| Downspouts - Exterior Do | | #4 | 15 | LF | 6 | \$498 | |
| Downspouts - Exterior Do | | #5 | 15 | LF | 6 | \$498 | |
| Downspouts - Interior Do | | #3 | 40 | LF | 6 | \$1,329 | |
| Parapet - 16" - 30" Heigh | | #1 | 80 | LF | 6 | \$3,196 | |
| Parapet - 16" - 30" Heigh | | #3 | 149 | LF | 6 | \$5,953 | |
| Parapet - 16" - 30" Heigh | t | #4 | 37 | LF | 6 | \$1,478 | |
| Parapet - 16" - 30" Heigh | t | #5 | 35 | LF | 6 | \$1,398 | |
| Parapet - 16" - 30" Heigh | | #5 | 15 | LF | 4 | \$10,135 | Location: East - spalling, crumbling, open joints |
| Parapet - Parapet < 16" H | | #1 | 539 | LF | 6 | \$11,484 | |
| Parapet - Parapet < 16" H | - | #3 | 70 | LF | 6 | \$1,491 | |
| Parapet - Parapet < 16" H | - | #4 | 60 | LF | 6 | \$1,278 | |
| Roof Structure - Heavy T | - | #1 | 16,400 | SF | 7 | \$0 | |
| Roof Structure - Heavy T | | #2 | 40 | SF | 7 | \$0 | |
| Roof Structure - Heavy T | | #3 | 2,991 | SF | 7 | \$0 | |
| Roof Structure - Heavy T | | #4 | 790 | SF | 7 | \$0 | |
| Roof Structure - Heavy T | | #5 | 270 | SF | 7 | \$0 | |
| Roof - Asphalt Gravel Ba | | #3 | 2,991 | SF | 6 | \$30,410 | |
| Roof - Modified Bitumen | | #1 | 16,400 | SF | 6 | \$154,314 | |
| Roof - Modified Bitumen | | #2 | 40 | SF | 6 | \$376 | |
| Roof - Modified Bitumen | | #4 | 790 | SF | 6 | \$7,433 | |
| Roof - Modified Bitumen | | #5 | 270 | SF | 6 | \$2,541 | |
| Walls | | | | | | | |
| Cornice - Metal Projecting |) | Entire Building / North Façade | 2,016 | LF | 6 | \$69,910 | Location: top of cornice |



Building: Main

Category: Building Exterior

| p Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------------------------|-----------------|----------|------|------|-----------|---|
| 5 | | | | | | |
| Exterior Walls - Brick | Entire Building | 10 | SF | 5 | \$238 | Location: N near Oriel |
| Exterior Walls - Brick | Entire Building | 26,831 | SF | 6 | \$180,331 | |
| Exterior Walls - Stone-Cast | Entire Building | 3,942 | SF | 6 | \$26,494 | |
| ows | | | | | | |
| Guard - Guards perforated | Entire Building | 1,274 | SF | 6 | \$16,269 | |
| Lintels - Brick | Entire Building | 32 | LF | 7 | \$0 | Location: North and South |
| Lintels - Steel | Entire Building | 325 | LF | 6 | \$9,434 | Location: West and North, North and South |
| Windows - Sash Aluminum Double-pane | Entire Building | 6,150 | SF | 5 | \$331.289 | |

Building Exterior Subtotal:

Building: Main

Category: Electrical System

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------------------|----------|------|------|----------|----------|
| merge | ncy System | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | \$408 | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 1,450 | SF | 6 | \$435 | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 16 | EA | 6 | \$3,240 | |
| | Emergency Battery Packs - Gym | Entire Building / 3rd Floor | 2 | EA | 6 | \$405 | |
| | Emergency Battery Packs - Lunchrooms | Entire Building / Basement | 2 | EA | 6 | \$405 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 16 | EA | 6 | \$2,396 | |
| | Exit Signs - Gym | Entire Building / 3rd Floor | 2 | EA | 6 | \$315 | |
| | Exit Signs - Lunchroom | Entire Building / Basement | 2 | EA | 6 | \$299 | |
| lain Se | ervice | | | | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | \$2,921 | |
| | Main Electrical Service - 1200 A 120/208/3PH | Electrical Room | 1 | EA | 6 | \$5,078 | |
| | PA System | 1st Floor | 58,750 | SF | 6 | \$19,323 | |
| ower D | Distribution | | | | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building / 3rd Floor | 3 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Basement | 3 | EA | 7 | \$0 | |
| lectri | ical System Subtotal: | | | | | \$35,225 | |

Building: Main

Category: Safty System



Mark Sheridan Elementary Math & Science Academy

533 W 27th St Chicago, IL 60616

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--------------------------|-----------------------------------|----------|------|------|----------|----------|
| Fire Ala | rm | | | | | | |
| | Fire Alarm Panel | Entire Building / Mechanical Room | 1 | EA | 3 | \$49,477 | |
| | Fire Alarm Strobe Lights | Entire Building | 68,750 | SF | 6 | \$24,578 | |
| | Fire Alarm_System | Entire Building | 68,750 | SF | 5 | \$76,684 | |
| | Fire Pump Controller | Entire Building / 1st Floor | 1 | EA | 4 | \$23,389 | |
| Pump R | oom Assembly | | | | | | |
| | Fire Pump - 25-50 hp | 1st Floor | 1 | EA | 6 | \$1,558 | |
| | Jockey Pump | 1st Floor | 1 | EA | 6 | \$758 | |
| Sprinkle | er System | | | | | | |
| | Dry Sprinkler System | Entire Building | 68,750 | SF | 6 | \$17,696 | |
| | Sprinkler Heads | Entire Building | 68,750 | SF | 7 | \$0 | |
| | Sprinkler Piping | Entire Building | 68,750 | SF | 6 | \$12,781 | |

Safty System Subtotal:

\$206,920

Building: Main

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|-----------------------------------|----------|------|------|-----------|----------------------------------|
| Air Con | ditioning | | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Basement | 1 | EA | 6 | \$3,334 | Split-system - Kitchen/Lunchroom |
| Air Hand | dling Systems | | | | | | |
| | Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 | Mechanical Room | 1 | EA | 5 | \$78,608 | Minor coil leaks. |
| | Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 | Mechanical Room | 1 | EA | 5 | \$78,608 | Minor coil leaks. |
| | Air Intake | Mechanical Room / Roof | 1 | EA | 5 | \$7,471 | |
| | Air Intake | Mechanical Room / Roof | 1 | EA | 5 | \$7,471 | |
| | Auxiliaries - 25001 - 35000 cfm | Mechanical Room | 1 | EA | 5 | \$16,577 | |
| | Auxiliaries - 25001 - 35000 cfm | Mechanical Room | 1 | EA | 5 | \$16,577 | |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | Mechanical Room / Roof | 100 | LF | 7 | \$0 | |
| | Return Duct Work - Masonry and Ducts- Missing or Existing Shaft | Mechanical Room / Roof | 100 | LF | 7 | \$0 | |
| | Zone Dampers | Mechanical Room / Entire Building | 25 | EA | 4 | \$119,817 | Actuators shot. |
| | Zone Dampers | Mechanical Room / Entire Building | 25 | EA | 4 | \$119,817 | Actuators shot. |
| Boiler S | ystems | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP | Basement / Boiler Room | 2 | EA | 6 | \$5,091 | |
| | Chemical Feed System | Basement / Boiler Room | 1 | EA | 6 | \$1,078 | |
| | Combustion Dampers | Basement / Boiler Room | 2 | EA | 6 | \$818 | |
| | Condensate Pump | Basement / Mechanical Room | 1 | EA | 6 | \$2,021 | |
| | Feed Water Pumps and Tank | Basement / Boiler Room | 1 | EA | 6 | \$2,545 | |



Building: Main

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--|----------------------------|----------|------|------|-----------|-----------------|
| Boiler S | Systems | | | | | | |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP | Basement / Boiler Room | 2 | EA | 6 | \$5,091 | |
| | Piping - Condensate Pipe- Steel | Basement | 400 | LF | 5 | \$4,879 | |
| | Piping - Steam Pipe- Steel | Basement / Entire Building | 400 | LF | 5 | \$5,634 | |
| | Steam Traps | Basement / Entire Building | 15 | EA | 5 | \$19,723 | |
| Heating | Devices | | | | | | |
| | Fin Tube - Steam | 1st Floor | 10 | LF | 6 | \$94 | |
| | Unit Heater - Electric | Basement | 2 | EA | 6 | \$556 | |
| | Wall Heater - Electric | Entire Building | 3 | EA | 6 | \$417 | |
| Temper | ature Control | | | | | | |
| | Pneumatic System | Entire Building | 68,750 | SF | 3 | \$357,858 | Actuators shot. |
| | Thermostats - Pneumatic | Entire Building | 50 | EA | 6 | \$0 | |
| /entilat | ion | | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building / Basement | 1 | EA | 6 | \$592 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building / Roof | 3 | EA | 6 | \$1,777 | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building / Basement | 1 | EA | 6 | \$920 | |
| Mecha | anical System Subtotal: | | | | | \$857,375 | |
| Buildi | ng: Main | | | | | | |
| | ng: Main | | | | | | |
| - | ory: Plumbing System | | | | | | |
| • | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Hot Wat | ter | | | | | | |
| | | | | | | | |

| Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 7 | \$0 | |
|--|-----------------|--------|----|---|----------|--------|
| g | | | | | | |
| Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 68,750 | SF | 6 | \$13,764 | Clamps |
| Domestic Piping-Cold Water Horizontal Lines | Entire Building | 68,750 | SF | 6 | \$16,713 | Clamps |
| Domestic Piping-Cold Water Risers | Entire Building | 68,750 | SF | 6 | \$12,781 | Clamps |
| Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 68,750 | SF | 6 | \$10,814 | Clamps |
| Domestic Piping-Hot Water Horizontal Lines | Entire Building | 68,750 | SF | 6 | \$12,781 | Clamps |
| Domestic Piping-Hot Water Return Lines | Entire Building | 68,750 | SF | 6 | \$9,831 | Clamps |
| Domestic Piping-Hot Water Return Risers | Entire Building | 68,750 | SF | 6 | \$9,831 | Clamps |
| Sanitary Piping | Entire Building | 68,750 | SF | 6 | \$62,920 | |
| Storm Piping | Entire Building | 68,750 | SF | 6 | \$59,971 | |
| Vent Piping | Entire Building | 68,750 | SF | 6 | \$46,207 | |



| oup Item - Type | Location | Quantity Unit | Rank | Cost Comments |
|------------------------|----------|---------------|------|---------------|
| ping | | | | |
| imps | | | | |
| Pumps - Ejector-Duplex | Basement | 1 EA | 5 | \$7,535 |
| Pumps - Sump-Duplex | Basement | 1 EA | 5 | \$7,535 |

Building: Main

| up | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|----------------------------------|----------|----------|------|------|---------|----------|
| ssroo | m #007 (Other Instructional Use) | | | | | | |
| | Casework | Basement | 6 | LF | 6 | \$152 | |
| | Ceiling - Exposed | Basement | 905 | SF | 6 | \$1,346 | |
| | Floor - Carpet | Basement | 905 | SF | 6 | \$1,928 | |
| | Lighting - Pendent/Surface | Basement | 14 | EA | 6 | \$1,735 | |
| | Marker Board | Basement | 12 | LF | 6 | \$257 | |
| , | Walls - Plaster/Drywall | Basement | 1,140 | SF | 6 | \$3,146 | |
| , | Work Sink | Basement | 1 | EA | 6 | \$379 | |
| ssroo | m #008 (Computer Lab) | | | | | | |
| | AC Units | Basement | 2 | EA | 6 | \$991 | |
| | Ceiling - Lay-in | Basement | 834 | SF | 6 | \$2,505 | |
| | Doors - Steel Doors incl hw | Basement | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Basement | 834 | SF | 6 | \$1,825 | |
| | Lighting - Pendent/Surface | Basement | 14 | EA | 6 | \$1,735 | |
| | Marker Board | Basement | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | Basement | 75 | SF | 6 | \$544 | |
| , | Walls - Plaster/Drywall | Basement | 1,000 | SF | 6 | \$2,760 | |
| , | Wireless System | Basement | 1 | EA | 6 | \$372 | |
| , | Work Sink | Basement | 1 | EA | 6 | \$379 | |
| ssroo | m #009 (Store Room) | | | | | | |
| | AC Units | Basement | 2 | EA | 6 | \$991 | |
| | Ceiling - Plaster/Drywall | Basement | 942 | SF | 5 | \$8,635 | peeling |
| | Doors - Steel Doors incl hw | Basement | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | Basement | 917 | SF | 6 | \$1,954 | |
| | Floor - Concrete Epoxy/ Painted | Basement | 25 | SF | 6 | \$13 | |
| | Lighting - Pendent/Surface | Basement | 7 | EA | 6 | \$867 | |



Building: Main

| Item - Type Location Quantity Unit Rank Cost Comment Comment Marker Board Basement 28 LF 7 \$0 \$0 Walls - Plaster/Drywall Basement 1,225 SF 6 \$3,381 \$1 wireless System Basement 1,225 SF 6 \$3,381 \$2 com #102 (Science) Dom #102 (Science) LF 6 \$505 \$3 \$ |
|--|
| Marker Board Basement 28 LF 7 \$0 Walls - Plaster/Drywall Basement 1,225 SF 6 \$3,381 Wireless System Basement 1 EA 6 \$372 com #102 (Science) I EA 6 \$372 casework 1st Floor 20 LF 6 \$505 Casework 1st Floor 35 LF 6 \$884 Ceiling - Plaster/Drywall 1st Floor 900 SF 6 \$3,115 Chalk Board 1st Floor 900 SF 6 \$535 Floor - Tile/Sheet 1st Floor 900 SF 6 \$3,858 Vork Sink 1st Floor 14 EA \$1,735 Walls - Plaster/Drywall 1st Floor 1,88 \$F 6 \$3,858 Work Sink 1st Floor 1,89 \$F 6 \$3,858 Work Sink 1st Floor 2 EA 6 \$496 |
| Walls - Plaster/Drywall Basement 1,225 SF 6 \$3,381 Wireless System Basement 1 EA 6 \$372 com #102 (Science) Ist Floor 20 LF 6 \$505 Casework 1st Floor 35 LF 6 \$884 Ceiling - Plaster/Drywall 1st Floor 900 SF 6 \$3,115 Chalk Board 1st Floor 900 SF 6 \$535 Floor - Tile/Sheet 1st Floor 900 SF 6 \$901 Lighting - Pendent/Surface 1st Floor 14 EA 6 \$1,735 Walls - Plaster/Drywall 1st Floor 1,398 SF 6 \$3,858 Work Sink 1st Floor 1,398 SF 6 \$3,858 Work Sink 1st Floor 2 EA 6 \$7,58 Casework 1st Floor 2 EA 6 \$1,735 Casework 1st Floor 2 <t< td=""></t<> |
| Wireless System Basement 1 EA 6 \$372 com #102 (Science) Casework 1st Floor 20 LF 6 \$505 Casework 1st Floor 35 LF 6 \$884 Ceiling - Plaster/Drywall 1st Floor 35 LF 6 \$884 Ceiling - Plaster/Drywall 1st Floor 900 SF 6 \$3,115 Chalk Board 1st Floor 24 LF 6 \$535 Floor - Tile/Sheet 1st Floor 900 SF 6 \$901 Lighting - Pendent/Surface 1st Floor 14 EA 6 \$1,735 Walls - Plaster/Drywall 1st Floor 1,398 SF 6 \$3,858 Work Sink 1st Floor 1,398 SF 6 \$3,758 Com #103 (Regular Classroom) 2 EA 6 \$496 Casework 7 LF 6 \$177 Ceiling - Plaster/Drywall SF 6 \$3, |
| Casework 1st Floor 20 LF 6 \$505 Casework 1st Floor 35 LF 6 \$884 Ceiling - Plaster/Drywall 1st Floor 900 SF 6 \$3,115 Chalk Board 1st Floor 24 LF 6 \$535 Floor - Tile/Sheet 1st Floor 900 SF 6 \$901 Lighting - Pendent/Surface 1st Floor 900 SF 6 \$901 Lighting - Pendent/Surface 1st Floor 14 EA 6 \$1,735 Walls - Plaster/Drywall 1st Floor 1,398 SF 6 \$3,858 Work Sink 1st Floor 1,398 SF 6 \$3,858 Com#103 (Regular Classroom) 2 EA 6 \$496 Casework 7 LF 6 \$417 Casework 7 LF 6 \$177 Ceiling - Plaster/Drywall 900 SF 6 \$3,115 Chalk B |
| Casework 1st Floor 20 LF 6 \$505 Casework 1st Floor 35 LF 6 \$884 Ceiling - Plaster/Drywall 1st Floor 900 SF 6 \$3,115 Chalk Board 1st Floor 24 LF 6 \$535 Floor - Tile/Sheet 1st Floor 900 SF 6 \$901 Lighting - Pendent/Surface 1st Floor 900 SF 6 \$901 Lighting - Pendent/Surface 1st Floor 14 EA 6 \$1,735 Walls - Plaster/Drywall 1st Floor 1,398 SF 6 \$3,858 Work Sink 1st Floor 1,398 SF 6 \$3,858 Com#103 (Regular Classroom) 2 EA 6 \$496 Casework 7 LF 6 \$417 Casework 7 LF 6 \$177 Ceiling - Plaster/Drywall 900 SF 6 \$3,115 Chalk B |
| Casework 1st Floor 35 LF 6 \$884 Ceiling - Plaster/Drywall 1st Floor 900 SF 6 \$3,115 Chalk Board 1st Floor 24 LF 6 \$535 Floor - Tile/Sheet 1st Floor 900 SF 6 \$901 Lighting - Pendent/Surface 1st Floor 14 EA 6 \$1,735 Walls - Plaster/Drywall 1st Floor 1,398 SF 6 \$3,858 Work Sink 1st Floor 2 EA 6 \$758 AC Units 2 EA 6 \$496 Casework 7 LF 6 \$496 Casework 7 LF 6 \$177 Ceiling - Plaster/Drywall SF 6 \$3,115 Chark Board 5 6 \$177 Celling - Plaster/Drywall SF 6 \$3,115 Chark Board 16 LF 5 \$837 |
| Ceiling - Plaster/Drywall 1st Floor 900 SF 6 \$3,115 Chalk Board 1st Floor 24 LF 6 \$535 Floor - Tile/Sheet 1st Floor 900 SF 6 \$901 Lighting - Pendent/Surface 1st Floor 14 EA 6 \$1,735 Walls - Plaster/Drywall 1st Floor 1,398 SF 6 \$3,858 Work Sink 1st Floor 2 EA 6 \$758 AC Units Casework Casework 7 LF 6 \$177 Ceiling - Plaster/Drywall 900 SF 6 \$177 Chalk Board 1 EA 6 \$496 Casework 7 LF 6 \$177 Ceiling - Plaster/Drywall 900 SF 6 \$3,115 Chalk Board 16 LF 5 \$837 |
| Chalk Board 1st Floor 24 LF 6 \$535 Floor - Tile/Sheet 1st Floor 900 SF 6 \$901 Lighting - Pendent/Surface 1st Floor 14 EA 6 \$1,735 Walls - Plaster/Drywall 1st Floor 1,398 SF 6 \$3,858 Work Sink 1st Floor 2 EA 6 \$758 Om #103 (Regular Classroom) AC Units 1 EA 6 \$496 Casework 7 LF 6 \$177 Ceiling - Plaster/Drywall SF 6 \$3,115 Chalk Board 6 \$3,115 \$837 |
| Floor - Tile/Sheet1st Floor900SF6\$901Lighting - Pendent/Surface1st Floor14EA6\$1,735Walls - Plaster/Drywall1st Floor1,398SF6\$3,858Work Sink1st Floor2EA6\$758 AC Units Casework7LF6\$177Ceiling - Plaster/Drywall900SF6\$3,115Chalk Board16LF5\$837 |
| Lighting - Pendent/Surface1st Floor14EA6\$1,735Walls - Plaster/Drywall1st Floor1,398SF6\$3,858Work Sink1st Floor2EA6\$758com #103 (Regular Classroom)AC Units1EA6\$496Casework7LF6\$177Ceiling - Plaster/Drywall900SF6\$3,115Chalk Board16LF5\$837 |
| Walls - Plaster/Drywall1st Floor1,398SF6\$3,858Work Sink1st Floor2EA6\$758com #103 (Regular Classroom)AC Units1EA6\$496Casework7LF6\$177Ceiling - Plaster/Drywall900SF6\$3,115Chalk Board16LF5\$837 |
| Work Sink1st Floor2EA6\$758com #103 (Regular Classroom)AC Units1EA6\$496Casework7LF6\$177Ceiling - Plaster/Drywall900SF6\$3,115Chalk Board16LF5\$837 |
| AC Units 1 EA 6 \$496 Casework 7 LF 6 \$177 Ceiling - Plaster/Drywall 900 SF 6 \$3,115 Chalk Board 16 LF 5 \$837 |
| AC Units 1 EA 6 \$496 Casework 7 LF 6 \$177 Ceiling - Plaster/Drywall 900 SF 6 \$3,115 Chalk Board 16 LF 5 \$837 |
| Ceiling - Plaster/Drywall 900 SF 6 \$3,115 Chalk Board 16 LF 5 \$837 |
| Ceiling - Plaster/Drywall 900 SF 6 \$3,115 Chalk Board 16 LF 5 \$837 |
| Chalk Board 16 LF 5 \$837 |
| Doors - Transom Window 36 SF 6 \$610 |
| |
| Doors - Wood Doors inclu hw 1 EA 6 \$301 |
| Floor - Tile/Sheet 900 SF 6 \$901 |
| Lighting - Pendent/Surface 14 EA 7 \$0 |
| Marker Board 32 LF 7 \$0 |
| Storage/ Closet 126 SF 6 \$914 |
| Walls - Plaster/Drywall 1,398 SF 6 \$3,858 |
| oom #104 (Regular Classroom) |
| AC Units 1 EA 6 \$496 |
| Casework 7 LF 6 \$177 |
| Ceiling - Plaster/Drywall 900 SF 6 \$3,115 |
| Chalk Board 33 LF 5 \$1,726 |
| Doors - Transom Window9SF6\$152 |
| Doors - Wood Doors inclu hw1EA6\$301 |
| Floor - Wood 900 SF 6 \$6,345 |
| Lighting - Pendent/Surface 14 EA 7 \$0 |
| Marker Board 33 LF 7 \$0 |
| Storage/ Closet 126 SF 6 \$914 |
| Walls - Plaster/Drywall 1,358 SF 6 \$3,748 |



Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|-----------------------------------|
| Classro | om #104 (Regular Classroom) | | | | | | |
| Classro | oom #105 (Kindergarten) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 8 | LF | 6 | \$202 | |
| | Ceiling - Lay-in | 1st Floor | 968 | SF | 6 | \$2,907 | |
| | Doors - Transom Window | 1st Floor | 48 | SF | 6 | \$813 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Wood | 1st Floor | 968 | SF | 6 | \$6,824 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 32 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,489 | SF | 6 | \$4,109 | Includes wainscoting on all walls |
| Classro | oom #106 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 6 | \$496 | |
| | Casework | | 7 | LF | 6 | \$177 | |
| | Ceiling - Plaster/Drywall | | 968 | SF | 6 | \$3,350 | |
| | Doors - Transom Window | | 32 | SF | 6 | \$542 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | | 968 | SF | 6 | \$969 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,489 | SF | 6 | \$4,109 | |
| Classro | oom #107 (Kindergarten) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 8 | LF | 6 | \$202 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 968 | SF | 6 | \$3,350 | |
| | Chalk Board | 1st Floor | 24 | LF | 4 | \$2,203 | |
| | Doors - Transom Window | 1st Floor | 48 | SF | 6 | \$813 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Wood | 1st Floor | 968 | SF | 6 | \$6,824 | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 6 | \$1,735 | |
| | Marker Board | 1st Floor | 36 | LF | 6 | \$771 | |
| | Storage/ Closet | 1st Floor | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,468 | SF | 6 | \$4,052 | Includes wainscoting on all walls |

Building: Main

| • | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|----------|----------|------|------|---------|-----------------------------------|
| Classro | oom #108 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | | 968 | SF | 6 | \$3,350 | |
| | Chalk Board | | 24 | LF | 5 | \$1,255 | |
| | Doors - Transom Window | | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | | 968 | SF | 6 | \$969 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 32 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,468 | SF | 6 | \$4,052 | Includes wainscoting on all walls |
| Classro | oom #201 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 7 | LF | 6 | \$177 | |
| | Ceiling - Plaster/Drywall | | 892 | SF | 6 | \$3,087 | |
| | Chalk Board | | 12 | LF | 5 | \$628 | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 892 | SF | 6 | \$6,289 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 33 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,489 | SF | 6 | \$4,109 | Includes wainscoting on all walls |
| lassro | oom #202 (Science) | | | | | | |
| | AC Units | | 1 | EA | 6 | \$496 | |
| | Casework | | 35 | LF | 6 | \$884 | |
| | Ceiling - Plaster/Drywall | | 900 | SF | 6 | \$3,115 | |
| | Doors - Transom Window | | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | | 900 | SF | 6 | \$901 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 12 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,398 | SF | 6 | \$3,858 | |
| | Work Sink | | 3 | EA | 6 | \$1,137 | |
| Classro | oom #203 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 6 | \$496 | |

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|----------|----------|------|------|---------|-----------------------------------|
| Classro | om #203 (Regular Classroom) | | | | | | |
| | Casework | | 7 | LF | 6 | \$177 | |
| | Ceiling - Plaster/Drywall | | 900 | SF | 6 | \$3,115 | |
| | Chalk Board | | 24 | LF | 5 | \$1,255 | |
| | Doors - Transom Window | | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | | 900 | SF | 6 | \$901 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 66 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,398 | SF | 6 | \$3,858 | |
| Classro | oom #204 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 6 | \$496 | |
| | Casework | | 7 | LF | 6 | \$177 | |
| | Ceiling - Plaster/Drywall | | 900 | SF | 6 | \$3,115 | |
| | Chalk Board | | 33 | LF | 5 | \$1,726 | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 900 | SF | 6 | \$6,345 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,358 | SF | 6 | \$3,748 | |
| Classro | oom #206 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 6 | \$496 | |
| | Casework | | 89 | LF | 6 | \$2,248 | |
| | Ceiling - Plaster/Drywall | | 968 | SF | 6 | \$3,350 | |
| | Doors - Transom Window | | 32 | SF | 6 | \$542 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | | 968 | SF | 6 | \$969 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 33 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,489 | SF | 6 | \$4,109 | Includes wainscoting on all walls |
| Classro | oom #207 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 6 | \$496 | |
| | Casework | | 89 | LF | 6 | \$2,248 | |

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|-----------------------------------|
| Classro | oom #207 (Regular Classroom) | | | | | | |
| | Ceiling - Plaster/Drywall | | 968 | SF | 6 | \$3,350 | |
| | Chalk Board | | 12 | LF | 5 | \$628 | |
| | Doors - Transom Window | | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | | 968 | SF | 6 | \$969 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 33 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,468 | SF | 6 | \$4,052 | Includes wainscoting on all walls |
| Classro | oom #208 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 6 | \$496 | |
| | Casework | | 89 | LF | 6 | \$2,248 | |
| | Ceiling - Plaster/Drywall | | 968 | SF | 6 | \$3,350 | |
| | Doors - Transom Window | | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Wood | | 968 | SF | 6 | \$6,824 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 60 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,468 | SF | 6 | \$4,052 | Includes wainscoting on all walls |
| Classro | oom #209 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 6 | \$496 | |
| | Casework | | 14 | LF | 6 | \$354 | |
| | Ceiling - Plaster/Drywall | | 936 | SF | 6 | \$3,239 | |
| | Doors - Transom Window | | 32 | SF | 6 | \$542 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Wood | | 936 | SF | 6 | \$6,599 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 33 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,403 | SF | 6 | \$3,872 | Includes wainscoting on all walls |
| Classro | oom #301 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 7 | LF | 6 | \$177 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 892 | SF | 6 | \$3,087 | |
| | Chalk Board | 1st Floor | 12 | LF | 5 | \$628 | |

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Pank | Cost | Comments |
|---------|-------------------------------|-----------|----------|------|-------|---------|-----------------------------------|
| - | boom #301 (Regular Classroom) | Eocation | Quantity | Unit | Ralik | COSI | Comments |
| CIASSIC | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 9 | EA | 6 | \$301 | |
| | Floor - Wood Doors Inclu nw | | | SF | 6 | | |
| | | 1st Floor | 892 | - | | \$6,289 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 33 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,489 | SF | 6 | \$4,109 | Includes wainscoting on all walls |
| Classro | oom #304 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 7 | LF | 6 | \$177 | |
| | Ceiling - Plaster/Drywall | | 900 | SF | 6 | \$3,115 | |
| | Doors - Transom Window | | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | | 1 | EA | 6 | \$301 | |
| | Floor - Wood | | 900 | SF | 6 | \$6,345 | |
| | Lighting - Pendent/Surface | | 14 | EA | 7 | \$0 | |
| | Marker Board | | 33 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,358 | SF | 6 | \$3,748 | |
| Classre | oom #305 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 75 | LF | 6 | \$1,894 | |
| | Ceiling - Plaster/Drywall | | 968 | SF | 6 | \$3,350 | |
| | Chalk Board | | 16 | LF | 5 | \$837 | |
| | Doors - Transom Window | | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Wood | | 968 | SF | 6 | \$6,824 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 52 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,489 | SF | 6 | \$4,109 | Includes wainscoting on all walls |
| Classro | oom #306 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 75 | LF | 6 | \$1,894 | |
| | Ceiling - Plaster/Drywall | | 968 | SF | 6 | \$3,350 | |
| | Chalk Board | | 24 | LF | 5 | \$1,255 | |
| | Doors - Transom Window | | 56 | SF | 6 | \$948 | |

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|----------|----------|------|------|---------|-----------------------------------|
| Classro | oom #306 (Regular Classroom) | | | | | | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Wood | | 968 | SF | 6 | \$6,824 | |
| | Lighting - Pendent/Surface | | 16 | EA | 6 | \$1,982 | |
| | Marker Board | | 52 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,489 | SF | 6 | \$4,109 | Includes wainscoting on all walls |
| Classro | oom #307 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 6 | \$496 | |
| | Casework | | 75 | LF | 6 | \$1,894 | |
| | Ceiling - Plaster/Drywall | | 968 | SF | 6 | \$3,350 | |
| | Chalk Board | | 33 | LF | 5 | \$1,726 | |
| | Doors - Transom Window | | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Wood | | 968 | SF | 6 | \$6,824 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 33 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,468 | SF | 6 | \$4,052 | Includes wainscoting on all walls |
| Classro | oom #308 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 75 | LF | 6 | \$1,894 | |
| | Ceiling - Plaster/Drywall | | 968 | SF | 6 | \$3,350 | |
| | Chalk Board | | 33 | LF | 5 | \$1,726 | |
| | Doors - Transom Window | | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Wood | | 968 | SF | 6 | \$6,824 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 33 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,468 | SF | 6 | \$4,052 | Includes wainscoting on all walls |
| Classro | oom #309 (Regular Classroom) | | | | | | |
| | AC Units | | 1 | EA | 7 | \$0 | |
| | Casework | | 75 | LF | 6 | \$1,894 | |
| | Ceiling - Plaster/Drywall | | 1,152 | SF | 6 | \$3,987 | |
| | Chalk Board | | 18 | LF | 5 | \$942 | |
| | Doors - Transom Window | | 24 | SF | 6 | \$406 | |

Building: Main

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|----------|-----------|------|------|---------|-----------------------------------|
| Classro | oom #309 (Regular Classroom) | | | | | | |
| | Doors - Wood Doors inclu hw | | 2 | EA | 6 | \$602 | |
| | Floor - Wood | | 1,152 | SF | 6 | \$8,121 | |
| | Lighting - Pendent/Surface | | 16 | EA | 7 | \$0 | |
| | Marker Board | | 33 | LF | 7 | \$0 | |
| | Storage/ Closet | | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | | 1,598 | SF | 6 | \$4,410 | Includes wainscoting on all walls |
| Class | rooms Subtotal: | | \$390,641 | | | | |

Building: Main

| oup It | em - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|--|----------|------|------|----------|----------|
| ministr | ative Suites/Offices | | | | | | |
| C | Ceiling - Plaster/Drywall | 1st Floor-008 Computer Office | 55 | SF | 6 | \$190 | |
| С | Doors - Wood Doors inclu hw | 1st Floor-008 Computer Office | 1 | EA | 6 | \$301 | |
| F | loor - Carpet | 1st Floor-008 Computer Office | 55 | SF | 6 | \$117 | |
| L | ighting - Pendent/Surface | 1st Floor-008 Computer Office | 1 | EA | 6 | \$124 | |
| F | Power Distribution | 1st Floor-008 Computer Office | 4 | EA | 6 | \$8,500 | |
| V | Valls - Masonry | 1st Floor-008 Computer Office | 222 | SF | 6 | \$698 | |
| A | SC Unit | 1st Floor-110 Assistant Principal's Office | 1 | EA | 6 | \$496 | |
| C | Ceiling - Plaster/Drywall | 1st Floor-110 Assistant Principal's Office | 430 | SF | 6 | \$1,488 | |
| С | Doors - Side-lite | 1st Floor-110 Assistant Principal's Office | 26 | SF | 6 | \$435 | |
| Г | Doors - Transom Window | 1st Floor-110 Assistant Principal's Office | 34 | SF | 6 | \$576 | |
| Γ | Doors - Wood Doors inclu hw | 1st Floor-110 Assistant Principal's Office | 2 | EA | 6 | \$602 | |
| F | iloor - Carpet | 1st Floor-110 Assistant Principal's Office | 430 | SF | 5 | \$2,207 | |
| L | ighting - Pendent/Surface | 1st Floor-110 Assistant Principal's Office | 7 | EA | 6 | \$867 | |
| F | Power Distribution | 1st Floor-110 Assistant Principal's Office | 8 | EA | 6 | \$16,999 | |
| S | Storage/ Closet | 1st Floor-110 Assistant Principal's Office | 42 | SF | 6 | \$305 | |
| V | Valls - Plaster/Drywall | 1st Floor-110 Assistant Principal's Office | 1,495 | SF | 6 | \$4,126 | |
| V | Vork SInk | 1st Floor-110 Assistant Principal's Office | 1 | EA | 6 | \$508 | |
| A | C Unit | 1st Floor-Main Office | 1 | EA | 6 | \$496 | |
| C | Ceiling - Plaster/Drywall | 1st Floor-Main Office | 536 | SF | 6 | \$1,855 | |
| C | Doors - Side-lite | 1st Floor-Main Office | 26 | SF | 6 | \$435 | |
| ٢ | Doors - Transom Window | 1st Floor-Main Office | 9 | SF | 6 | \$152 | |
| C | Doors - Wood Doors inclu hw | 1st Floor-Main Office | 1 | EA | 6 | \$301 | |
| F | loor - Carpet | 1st Floor-Main Office | 536 | SF | 5 | \$2,752 | |
| L | ighting - Pendent/Surface | 1st Floor-Main Office | 10 | EA | 6 | \$1,239 | |



| up I | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|------------------------------|----------|------|------|----------|----------|
| ninist | rative Suites/Offices | | | | | | |
| | Power Distribution | 1st Floor-Main Office | 14 | EA | 6 | \$29,748 | |
| | Storage/ Closet | 1st Floor-Main Office | 25 | SF | 6 | \$181 | |
| , | Walls - Plaster/Drywall | 1st Floor-Main Office | 1,470 | SF | 6 | \$4,057 | |
| | AC Unit | 1st Floor-Principal's Office | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor-Principal's Office | 429 | SF | 6 | \$1,485 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Principal's Office | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | 1st Floor-Principal's Office | 429 | SF | 5 | \$2,202 | |
| | Lighting - Pendent/Surface | 1st Floor-Principal's Office | 5 | EA | 6 | \$619 | |
| | Power Distribution | 1st Floor-Principal's Office | 12 | EA | 6 | \$25,499 | |
| , | Walls - Plaster/Drywall | 1st Floor-Principal's Office | 1,148 | SF | 6 | \$3,168 | |
| | AC Unit | 210 | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 210 | 221 | SF | 6 | \$765 | |
| | Doors - Transom Window | 210 | 105 | SF | 6 | \$1,778 | |
| | Doors - Wood Doors inclu hw | 210 | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 210 | 221 | SF | 6 | \$471 | |
| | Lighting - Pendent/Surface | 210 | 7 | EA | 7 | \$0 | |
| | Power Distribution | 210 | 6 | EA | 6 | \$12,749 | |
| , | Walls - Metal Panel | 210 | 366 | SF | 6 | \$2,732 | Wood |
| , | Walls - Plaster/Drywall | 210 | 507 | SF | 6 | \$1,399 | |
| | Ceiling - Plaster/Drywall | 310 Admin. Storage | 403 | SF | 6 | \$1,395 | |
| | Doors - Transom Window | 310 Admin. Storage | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 310 Admin. Storage | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 310 Admin. Storage | 403 | SF | 6 | \$2,841 | |
| | Lighting - Pendent/Surface | 310 Admin. Storage | 7 | EA | 6 | \$867 | |
| | Power Distribution | 310 Admin. Storage | 7 | EA | 6 | \$14,874 | |
| ; | Storage/ Closet | 310 Admin. Storage | 24 | SF | 6 | \$174 | |
| | Walls - Metal Panel | 310 Admin. Storage | 247 | SF | 5 | \$7,555 | Wood |
| , | Walls - Plaster/Drywall | 310 Admin. Storage | 987 | SF | 6 | \$2,724 | |
| | Ceiling - Plaster/Drywall | Basement-Engineer's Office | 5 | SF | 5 | \$62 | peeling |
| | Ceiling - Plaster/Drywall | Basement-Engineer's Office | 345 | SF | 6 | \$1,194 | |
| | Doors - Wood Doors inclu hw | Basement-Engineer's Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Basement-Engineer's Office | 350 | SF | 6 | \$766 | |
| | Lighting - Pendent/Surface | Basement-Engineer's Office | 4 | EA | 6 | \$496 | |
| | Power Distribution | Basement-Engineer's Office | 8 | EA | 6 | \$16,999 | |
| , | Walls - Plaster/Drywall | Basement-Engineer's Office | 774 | SF | 6 | \$2,136 | |
| | Walls - Plaster/Drywall | Basement-Engineer's Office | 6 | SF | 5 | \$31 | peeling |
| | Ceiling - Exposed | Basement-Faculty Lounge | 562 | SF | 6 | \$836 | - |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|----------------------------------|----------|------|------|---------------|------------------------|
| Admini | strative Suites/Offices | | | | | | |
| | Doors - Wood Doors inclu hw | Basement-Faculty Lounge | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Basement-Faculty Lounge | 562 | SF | 6 | \$1,230 | |
| | Lighting - Pendent/Surface | Basement-Faculty Lounge | 5 | EA | 6 | \$619 | |
| | Power Distribution | Basement-Faculty Lounge | 12 | EA | 6 | \$25,499 | |
| | Storage/ Closet | Basement-Faculty Lounge | 285 | SF | 6 | \$2,066 | |
| | Walls - Plaster/Drywall | Basement-Faculty Lounge | 1,180 | SF | 6 | \$3,257 | |
| | Work SInk | Basement-Faculty Lounge | 1 | EA | 6 | \$508 | |
| | Ceiling - Exposed | Basement-Janitor's Room | 162 | SF | 6 | \$241 | |
| | Doors - Wood Doors inclu hw | Basement-Janitor's Room | 2 | EA | 6 | \$602 | |
| | Floor - Concrete Epoxy/ Painted | Basement-Janitor's Room | 162 | SF | 6 | \$86 | |
| | Lighting - Pendent/Surface | Basement-Janitor's Room | 2 | EA | 6 | \$248 | |
| | Power Distribution | Basement-Janitor's Room | 4 | EA | 6 | \$8,500 | |
| | Storage/ Closet | Basement-Janitor's Room | 4 | SF | 6 | \$29 | |
| | Walls - Masonry | Basement-Janitor's Room | 688 | SF | 5 | \$28,433 | efflorescence, peeling |
| Gymna | sia | | | | | | |
| Cynna | Ceiling - Plaster/Drywall | 3rd Floor | 3,208 | SF | 6 | \$17,708 | |
| | Doors - Transom Window | 3rd Floor | 24 | SF | 6 | \$406 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 4 | EA | 6 | \$1,204 | |
| | Floor - Tile/Sheet | 3rd Floor | 530 | SF | 6 | | stage |
| | Floor - Wood | 3rd Floor | 2,668 | SF | 6 | \$18,809 | ologo - |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | \$0 | |
| | Stage | 3rd Floor | 800 | SF | 6 | \$4,622 | |
| | Stage Curtain | 3rd Floor | 5 | EA | 6 | \$0 | |
| | Stage-Stairs - Wood | 3rd Floor | 1 | LF | 6 | \$12 | |
| | Storage/ Closet | 3rd Floor | 210 | SF | 6 | \$1,523 | |
| | Walls - Plaster/Drywall | 3rd Floor | 3,112 | SF | 6 | \$8,589 | |
| | Walls - Plaster/Drywall | 3rd Floor | 125 | SF | 5 | \$638 | |
| | | | | - | | | |
| Kitchen | | B | | ~- | | A =0 (| |
| | Ceiling - Exposed | Basement-Kitchen, with Lunchroom | 485 | SF | 6 | \$721 | |
| | Floor - Tile | Basement-Kitchen, with Lunchroom | 485 | SF | 6 | \$1,061 | |
| | Lighting - Pendent/Surface | Basement-Kitchen, with Lunchroom | 6 | EA | 6 | \$743 | |
| | Walls - Plaster/Drywall | Basement-Kitchen, with Lunchroom | 652 | SF | 6 | \$1,799 | |
| Library | | | | | | | |
| | AC Unit | 1st Floor-109 Library | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor-109 Library | 90 | LF | 6 | \$2,273 | |
| | Ceiling - Plaster/Drywall | 1st Floor-109 Library | 968 | SF | 6 | \$3,350 | |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|--|----------|------|------|---------|----------------------------|
| Library | | | | | | | |
| | Doors - Side-lite | 1st Floor-109 Library | 30 | SF | 6 | \$502 | |
| | Doors - Transom Window | 1st Floor-109 Library | 10 | SF | 6 | \$169 | |
| | Doors - Wood Doors inclu hw | 1st Floor-109 Library | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 1st Floor-109 Library | 968 | SF | 6 | \$2,063 | |
| | Lighting - Pendent/Surface | 1st Floor-109 Library | 14 | EA | 7 | \$0 | |
| | Storage/ Closet | 1st Floor-109 Library | 126 | SF | 6 | \$914 | |
| | Walls - Plaster/Drywall | 1st Floor-109 Library | 132 | SF | 7 | \$0 | marker board |
| | Walls - Plaster/Drywall | 1st Floor-109 Library | 1,675 | SF | 6 | \$4,623 | |
| Lunch | & Multipurpose Room | | | | | | |
| | Ceiling - Plaster/Drywall | Basement-007 Multipurpose | 54 | SF | 4 | \$1,175 | peeling, cracked |
| | Ceiling - Plaster/Drywall | Basement-007 Multipurpose | 912 | SF | 6 | \$3,156 | |
| | Floor - Carpet | Basement-007 Multipurpose | 966 | SF | 5 | \$4,959 | |
| | Lighting - Pendent/Surface | Basement-007 Multipurpose | 14 | EA | 6 | \$1,735 | |
| | Market Board | Basement-007 Multipurpose | 12 | LF | 7 | \$0 | |
| | Storage/ Closet | Basement-007 Multipurpose | 225 | SF | 5 | \$3,629 | peeling, cracking at walls |
| | Walls - Masonry | Basement-007 Multipurpose | 100 | SF | 6 | \$315 | |
| | Walls - Plaster/Drywall | Basement-007 Multipurpose | 1,218 | SF | 5 | \$9,231 | |
| | Walls - Structural Glazed Tile | Basement-007 Multipurpose | 162 | SF | 6 | \$510 | |
| | Ceiling - Plaster/Drywall | Basement-Lunchroom 2, former Playroom | 830 | SF | 6 | \$2,872 | |
| | Floor - Tile | Basement-Lunchroom 2, former Playroom | 830 | SF | 6 | \$1,816 | |
| | Lighting - Pendent/Surface | Basement-Lunchroom 2, former Playroom | 14 | EA | 6 | \$1,735 | |
| | Walls - Plaster/Drywall | Basement-Lunchroom 2, former Playroom | 1,240 | SF | 6 | \$3,422 | |
| | Ceiling - Exposed | Basement-Lunchroom, with Kitchen | 720 | SF | 6 | \$1,071 | |
| | Doors - Wood Doors inclu hw | Basement-Lunchroom, with Kitchen | 2 | EA | 6 | \$602 | |
| | Floor - Tile | Basement-Lunchroom, with Kitchen | 720 | SF | 6 | \$1,575 | |
| | Lighting - Pendent/Surface | Basement-Lunchroom, with Kitchen | 12 | EA | 6 | \$1,487 | |
| | Serving Line | Basement-Lunchroom, with Kitchen | 20 | LF | 6 | \$1,190 | |
| | Storage/ Closet | Basement-Lunchroom, with Kitchen | 25 | SF | 6 | \$181 | |
| | Walls - Plaster/Drywall | Basement-Lunchroom, with Kitchen | 820 | SF | 6 | \$2,263 | |
| Mecha | nical/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 10 | SF | 6 | \$72 | |
| | Janitor's Closet | 3rd Floor | 24 | SF | 6 | \$172 | |
| | Air Tunnel | Basement | 532 | SF | 6 | \$3,294 | Warm Air Chamber |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|-------------------------------------|----------|------|------|---------|-------------------------------------|
| | nical/ Service Rooms | | quantity | | | 0001 | |
| | Boiler Room | Basement | 1,020 | SF | 6 | \$7,308 | |
| | Coal Room | Basement | 982 | SF | 6 | \$7,035 | |
| | Janitor's Closet | Basement | 25 | SF | 6 | \$179 | |
| | Mechanical/ Service Rooms | Basement | 750 | SF | 6 | | Engine Room |
| | Mechanical/ Service Rooms | Basement | 378 | SF | 6 | \$2,708 | |
| | Mechanical/ Service Rooms | Basement | 68 | SF | 6 | \$487 | Fire Pump Room |
| | Mechanical/ Service Rooms | Basement | 282 | SF | 6 | \$2,020 | Pump Room |
| | Mechanical/ Service Rooms | Basement | 765 | SF | 6 | \$5,481 | Engine Room |
| | Storage Room | Basement | 138 | SF | 6 | \$989 | |
| | Storage Room | Basement | 495 | SF | 5 | \$7,985 | water damage at lay in ceiling tile |
| | Storage Room | Basement | 350 | SF | 6 | \$2,508 | Kitchen Storage |
| | Storage Room | Basement | 28 | SF | 6 | \$201 | |
| | - | | | - | | | |
| Restro | | | | | | | |
| | Accessories | 1st Floor-105 Kindergarten Restroom | 70 | SF | 6 | \$646 | |
| | Ceiling - Plaster/Drywall | 1st Floor-105 Kindergarten Restroom | 70 | SF | 6 | \$242 | |
| | Doors - Wood Doors inclu hw | 1st Floor-105 Kindergarten Restroom | 3 | EA | 6 | \$903 | |
| | Floor - Wood | 1st Floor-105 Kindergarten Restroom | 70 | SF | 6 | \$493 | |
| | Lavatory | 1st Floor-105 Kindergarten Restroom | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 1st Floor-105 Kindergarten Restroom | 1 | EA | 5 | \$183 | no cover |
| | Partitions | 1st Floor-105 Kindergarten Restroom | 1 | EA | 6 | \$297 | |
| | Walls - Metal Panel | 1st Floor-105 Kindergarten Restroom | 110 | SF | 6 | \$821 | Item Type: Wood Panel |
| | Walls - Plaster/Drywall | 1st Floor-105 Kindergarten Restroom | 408 | SF | 6 | \$1,126 | |
| | Water Closet | 1st Floor-105 Kindergarten Restroom | 1 | EA | 6 | \$336 | |
| | Accessories | 1st Floor-107 Kindergarten Restroom | 30 | SF | 6 | \$277 | |
| | Ceiling - Plaster/Drywall | 1st Floor-107 Kindergarten Restroom | 30 | SF | 5 | \$275 | cracking |
| | Doors - Wood Doors inclu hw | 1st Floor-107 Kindergarten Restroom | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor-107 Kindergarten Restroom | 10 | SF | 6 | \$22 | |
| | Floor - Wood | 1st Floor-107 Kindergarten Restroom | 20 | SF | 6 | \$141 | |
| | Lavatory | 1st Floor-107 Kindergarten Restroom | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 1st Floor-107 Kindergarten Restroom | 1 | EA | 6 | \$124 | |
| | Walls - Metal Panel | 1st Floor-107 Kindergarten Restroom | 110 | SF | 6 | \$821 | Item Type: Wood Panel |
| | Walls - Plaster/Drywall | 1st Floor-107 Kindergarten Restroom | 250 | SF | 5 | \$1,895 | cracking |
| | Water Closet | 1st Floor-107 Kindergarten Restroom | 1 | EA | 6 | \$336 | |
| | Accessories | 1st Floor-Main Office Restroom | 44 | SF | 6 | \$406 | |
| | Ceiling - Lay-in | 1st Floor-Main Office Restroom | 44 | SF | 6 | \$132 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Main Office Restroom | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor-Main Office Restroom | 44 | SF | 6 | \$93 | |
| | | | | | | | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|--------------------------------|----------|------|------|---------|---------------------|
| Restro | om | | | | | | |
| | Lavatory | 1st Floor-Main Office Restroom | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 1st Floor-Main Office Restroom | 1 | EA | 6 | \$119 | |
| | Walls - Plaster/Drywall | 1st Floor-Main Office Restroom | 250 | SF | 6 | \$690 | |
| | Walls - Plaster/Drywall | 1st Floor-Main Office Restroom | 4 | SF | 5 | \$20 | peeling |
| | Water Closet | 1st Floor-Main Office Restroom | 1 | EA | 6 | \$336 | |
| | Accessories | 1st Floor-Teacher's Restroom | 70 | SF | 6 | \$646 | |
| | Ceiling - Lay-in | 1st Floor-Teacher's Restroom | 2 | SF | 5 | \$16 | water discoloration |
| | Ceiling - Lay-in | 1st Floor-Teacher's Restroom | 68 | SF | 6 | \$204 | |
| | Doors - Wood Doors inclu hw | 1st Floor-Teacher's Restroom | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor-Teacher's Restroom | 70 | SF | 6 | \$148 | |
| | Lavatory | 1st Floor-Teacher's Restroom | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 1st Floor-Teacher's Restroom | 2 | EA | 6 | \$238 | |
| | Walls - Plaster/Drywall | 1st Floor-Teacher's Restroom | 300 | SF | 6 | \$828 | |
| | Water Closet | 1st Floor-Teacher's Restroom | 1 | EA | 6 | \$336 | |
| | Accessories | 2nd Floor Boys | 212 | SF | 6 | \$1,955 | |
| | Ceiling - Plaster/Drywall | 2nd Floor Boys | 212 | SF | 6 | \$734 | |
| | Floor Drain | 2nd Floor Boys | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Boys | 212 | SF | 6 | \$449 | |
| | Lavatory | 2nd Floor Boys | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 2nd Floor Boys | 5 | EA | 7 | \$0 | |
| | Partitions | 2nd Floor Boys | 3 | EA | 6 | \$891 | |
| | Urinals | 2nd Floor Boys | 5 | EA | 6 | \$1,680 | |
| | Walls - Plaster/Drywall | 2nd Floor Boys | 554 | SF | 6 | \$1,529 | |
| | Walls - Tile Ceramic/ Porcelain | 2nd Floor Boys | 200 | SF | 6 | \$970 | Plastic Sheet |
| | Walls - Tile Ceramic/ Porcelain | 2nd Floor Boys | 1,785 | SF | 6 | \$4,033 | |
| | Water Closet | 2nd Floor Boys | 3 | EA | 6 | \$1,008 | |
| | Accessories | 2nd Floor Girls | 416 | SF | 6 | \$3,837 | |
| | Ceiling - Plaster/Drywall | 2nd Floor Girls | 416 | SF | 6 | \$1,440 | |
| | Floor Drain | 2nd Floor Girls | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Girls | 416 | SF | 6 | \$880 | |
| | Hand Dryer | 2nd Floor Girls | 1 | EA | 6 | \$230 | |
| | Lavatory | 2nd Floor Girls | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 2nd Floor Girls | 7 | EA | 7 | \$0 | |
| | Partitions | 2nd Floor Girls | 7 | EA | 6 | \$2,078 | |
| | Walls - Plaster/Drywall | 2nd Floor Girls | 710 | SF | 6 | \$1,960 | |
| | Walls - Tile | 2nd Floor Girls | 114 | SF | 6 | \$249 | Plastic sheet |
| | Walls - Tile Ceramic/ Porcelain | 2nd Floor Girls | 665 | SF | 6 | \$1,503 | |
| | | | | | | | |



| up | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|--|------------------------------------|----------|------|------|---------|-----------------------|
| stroo | om de la companya de | | | | | | |
| | Water Closet | 2nd Floor Girls | 7 | EA | 6 | \$2,352 | |
| | Accessories | 2nd Floor Mens | 93 | SF | 6 | \$858 | |
| | Ceiling - Lay-in | 2nd Floor Mens | 93 | SF | 6 | \$279 | |
| | Floor Drain | 2nd Floor Mens | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Mens | 93 | SF | 6 | \$197 | |
| | Lavatory | 2nd Floor Mens | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 2nd Floor Mens | 3 | EA | 6 | \$372 | |
| | Partitions | 2nd Floor Mens | 1 | EA | 6 | \$297 | |
| | Urinals | 2nd Floor Mens | 1 | EA | 6 | \$336 | |
| | Walls - Plaster/Drywall | 2nd Floor Mens | 84 | SF | 6 | \$232 | |
| | Walls - Tile Ceramic/ Porcelain | 2nd Floor Mens | 315 | SF | 6 | \$712 | |
| | Water Closet | 2nd Floor Mens | 1 | EA | 6 | \$336 | |
| | Accessories | 2nd Floor Womens | 67 | SF | 6 | \$618 | |
| | Ceiling - Plaster/Drywall | 2nd Floor Womens | 67 | SF | 6 | \$232 | |
| | Doors - Wood Doors inclu hw | 2nd Floor Womens | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor Womens | 67 | SF | 6 | \$142 | |
| | Lavatory | 2nd Floor Womens | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 2nd Floor Womens | 1 | EA | 7 | \$0 | |
| | Partitions | 2nd Floor Womens | 2 | EA | 6 | \$594 | |
| | Walls - Plaster/Drywall | 2nd Floor Womens | 313 | SF | 6 | \$864 | |
| | Water Closet | 2nd Floor Womens | 2 | EA | 6 | \$672 | |
| | Accessories | Basement-007 Multipurpose Restroom | 85 | SF | 6 | \$784 | |
| | Ceiling - Plaster/Drywall | Basement-007 Multipurpose Restroom | 85 | SF | 4 | \$1,280 | peeling, hole |
| | Doors - Wood Doors inclu hw | Basement-007 Multipurpose Restroom | 1 | EA | 6 | \$301 | |
| | Floor - Concrete Epoxy/ Painted | Basement-007 Multipurpose Restroom | 85 | SF | 4 | \$2,390 | cracks |
| | Lavatory | Basement-007 Multipurpose Restroom | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Basement-007 Multipurpose Restroom | 2 | EA | 6 | \$248 | |
| | Student Lockers - One Tier | Basement-007 Multipurpose Restroom | 6 | EA | 6 | \$557 | |
| | Walls - Plaster/Drywall | Basement-007 Multipurpose Restroom | 320 | SF | 6 | \$883 | |
| | Water Closet | Basement-007 Multipurpose Restroom | 1 | EA | 6 | \$336 | |
| | Accessories | Basement-Boiler Room Restroom | 30 | SF | 6 | \$277 | |
| | Ceiling - Exposed | Basement-Boiler Room Restroom | 30 | SF | 6 | \$45 | |
| | Doors - Wood Doors inclu hw | Basement-Boiler Room Restroom | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Basement-Boiler Room Restroom | 30 | SF | 6 | \$66 | |
| | Lighting - Pendent/Surface | Basement-Boiler Room Restroom | 1 | EA | 5 | \$183 | missing bulb socket |
| | Walls - Masonry | Basement-Boiler Room Restroom | 134 | SF | 6 | \$422 | |
| | Walls - Plaster/Drywall | Basement-Boiler Room Restroom | 78 | SF | 6 | \$215 | Item Type: Wood Panel |



| р | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----|---------------------------------|-----------------------------------|----------|------|------|---------|---------------------|
| roo | m | | | | | | |
| | Water Closet | Basement-Boiler Room Restroom | 1 | EA | 6 | \$336 | |
| | Accessories | Basement-Boy's Restroom | 289 | SF | 6 | \$2,666 | |
| | Ceiling - Plaster/Drywall | Basement-Boy's Restroom | 289 | SF | 6 | \$1,000 | |
| | Floor Drain | Basement-Boy's Restroom | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Basement-Boy's Restroom | 289 | SF | 6 | \$612 | |
| | Hand Dryer | Basement-Boy's Restroom | 1 | EA | 6 | \$230 | |
| | Lavatory | Basement-Boy's Restroom | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | Basement-Boy's Restroom | 5 | EA | 6 | \$619 | |
| | Partitions | Basement-Boy's Restroom | 3 | EA | 6 | \$891 | |
| | Urinals | Basement-Boy's Restroom | 4 | EA | 6 | \$1,344 | |
| | Walls - Masonry | Basement-Boy's Restroom | 212 | SF | 6 | \$667 | |
| | Walls - Plaster/Drywall | Basement-Boy's Restroom | 234 | SF | 6 | \$646 | |
| | Walls - Structural Glazed Tile | Basement-Boy's Restroom | 440 | SF | 6 | \$1,384 | |
| | Water Closet | Basement-Boy's Restroom | 3 | EA | 6 | \$1,008 | |
| | Accessories | Basement-Engineer Office Bathroom | 80 | SF | 6 | \$738 | |
| | Ceiling - Lay-in | Basement-Engineer Office Bathroom | 74 | SF | 6 | \$222 | |
| | Ceiling - Lay-in | Basement-Engineer Office Bathroom | 6 | SF | 5 | \$48 | water discoloration |
| | Doors - Wood Doors inclu hw | Basement-Engineer Office Bathroom | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | Basement-Engineer Office Bathroom | 80 | SF | 6 | \$169 | |
| | Lavatory | Basement-Engineer Office Bathroom | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | Basement-Engineer Office Bathroom | 1 | EA | 6 | \$119 | |
| | Walls - Plaster/Drywall | Basement-Engineer Office Bathroom | 250 | SF | 6 | \$690 | |
| | Walls - Tile Ceramic/ Porcelain | Basement-Engineer Office Bathroom | 38 | SF | 6 | \$86 | |
| | Water Closet | Basement-Engineer Office Bathroom | 1 | EA | 6 | \$336 | |
| | Accessories | Basement-Girl's Restroom | 350 | SF | 6 | \$3,228 | |
| | Ceiling - Plaster/Drywall | Basement-Girl's Restroom | 350 | SF | 5 | \$3,208 | |
| | Doors - Wood Doors inclu hw | Basement-Girl's Restroom | 1 | EA | 6 | \$301 | |
| | Floor Drain | Basement-Girl's Restroom | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Basement-Girl's Restroom | 350 | SF | 6 | \$741 | |
| | Hand Dryer | Basement-Girl's Restroom | 1 | EA | 6 | \$230 | |
| | Lavatory | Basement-Girl's Restroom | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | Basement-Girl's Restroom | 6 | EA | 6 | \$743 | |
| | Partitions | Basement-Girl's Restroom | 6 | EA | 6 | \$1,782 | |
| | Walls - Masonry | Basement-Girl's Restroom | 220 | SF | 6 | \$692 | |
| | Walls - Plaster/Drywall | Basement-Girl's Restroom | 200 | SF | 4 | \$2,013 | extreme peeling |
| | Walls - Structural Glazed Tile | Basement-Girl's Restroom | 412 | SF | 6 | \$1,296 | |
| | Water Closet | Basement-Girl's Restroom | 6 | EA | 6 | \$2,016 | |



| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------|----------|------|------|----------------|------------------------------|
| Rooms (Other Than Classrooms) Subtotal: | | | | | \$519,554 | |
| Building: Main | | | | | | |
| Category: Building Interior | | | | | | |
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Corridor | Location | Quantity | onit | Nank | 0031 | Comments |
| Ceiling - Plaster/Drywall | 1st Floor | 100 | SF | 5 | \$1 745 | Peeling paint |
| Ceiling - Plaster/Drywall | 1st Floor | 2,749 | SF | 6 | \$17,022 | |
| Drinking Fountains - Single Fountain | 1st Floor | 2,740 | EA | 6 | \$551 | |
| Floor - Wood | 1st Floor | 2,849 | SF | 6 | \$20,085 | |
| Lighting - Pendent/Surface | 1st Floor | 2,010 | EA | 7 | ¢20,000 \$0 | |
| Walls - Plaster/Drywall | 1st Floor | 100 | SF | 5 | \$1,004 | Cracking, peeling paint |
| Walls - Plaster/Drywall | 1st Floor | 3,950 | SF | 6 | \$17,510 | |
| Ceiling - Plaster/Drywall | 2nd Floor | 2,649 | SF | 6 | \$16,402 | |
| Ceiling - Plaster/Drywall | 2nd Floor | 100 | SF | 5 | \$1,745 | |
| Drinking Fountains - Single Fountain | 2nd Floor | 2 | EA | 4 | \$7,816 | low water pressure, outdated |
| Floor - Wood | 2nd Floor | 2,849 | SF | 6 | \$20,085 | |
| Lighting - Pendent/Surface | 2nd Floor | _,010 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 2nd Floor | 3,912 | SF | 6 | \$17,342 | |
| Walls - Plaster/Drywall | 2nd Floor | 100 | SF | 5 | \$1,004 | Cracking, peeling paint |
| Ceiling - Plaster/Drywall | 3rd Floor | 100 | SF | 5 | | Cracking |
| Ceiling - Plaster/Drywall | 3rd Floor | 718 | SF | 6 | \$4,446 | J |
| Ceiling - Splined | 3rd Floor | 358 | SF | 6 | \$1,034 | |
| Drinking Fountains - Single Fountain | 3rd Floor | 2 | EA | 5 | \$2,360 | |
| Floor - Tile/Sheet | 3rd Floor | 1,176 | SF | 6 | \$639 | |
| Lighting - Pendent/Surface | 3rd Floor | 16 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | 3rd Floor | 2,449 | SF | 6 | \$10,856 | |
| Ceiling - Plaster/Drywall | Basement | 2,879 | SF | 5 | \$36,271 | significant peeling paint |
| Doors - Side-lite | Basement | 44 | EA | 7 | \$0 | 5 1 51 |
| Doors - Transom Window | Basement | 226 | EA | 7 | \$0 | |
| Doors - Wood Doors include hw | Basement | 14 | EA | 6 | \$4,214 | |
| Floor - Concrete Epoxy/ Painted | Basement | 2,879 | SF | 6 | \$1,400 | |
| Lighting - Pendent/Surface | Basement | 35 | EA | 6 | \$4,336 | |
| Walls - Masonry | Basement | 618 | SF | 6 | | Glazed Brick |
| Walls - Masonry | Basement | 318 | SF | 6 | \$1,205 | Painted Brick |
| Walls - Plaster/Drywall | Basement | 3,358 | SF | 6 | \$14,886 | |
| Walls - Structural Glazed Tile | Basement | 178 | SF | 6 | \$560 | |



Building: Main

Category: Building Interior

| pup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------|-----------------|----------|------|------|-----------|----------|
| ety | | | | | | |
| Camera Viewing Station | Entire Building | 1 | EA | 7 | \$0 | |
| Security Cameras | Entire Building | 5 | EA | 6 | \$970 | |
| irs | | | | | | |
| Ceiling - Plaster/Drywall | #1 N Stair | 685 | SF | 6 | \$5,015 | |
| Floor - Asphalt | #1 N Stair | 465 | SF | 6 | \$3,604 | |
| Handrails | #1 N Stair | 178 | LF | 6 | \$1,543 | |
| Lighting - Pendent/Surface | #1 N Stair | 6 | EA | 6 | \$743 | |
| Stairs - Asphalt | #1 N Stair | 80 | LF | 6 | \$742 | |
| Walls - Plaster/Drywall | #1 N Stair | 3,376 | SF | 6 | \$9,317 | |
| Ceiling - Plaster/Drywall | #2 E Stair | 355 | SF | 6 | \$2,599 | |
| Ceiling - Splined | #2 E Stair | 350 | SF | 6 | \$1,011 | |
| Ceiling - Splined | #2 E Stair | 5 | SF | 4 | \$86 | |
| Ceiling - Splined | #2 E Stair | 10 | SF | 4 | \$171 | |
| Floor - Asphalt | #2 E Stair | 518 | SF | 6 | \$4,015 | |
| Handrails | #2 E Stair | 178 | LF | 6 | \$1,543 | |
| Lighting - Pendent/Surface | #2 E Stair | 7 | EA | 6 | \$867 | |
| Stairs - Asphalt | #2 E Stair | 80 | LF | 6 | \$742 | |
| Walls - Plaster/Drywall | #2 E Stair | 3,112 | SF | 6 | \$8,589 | |
| Ceiling - Exposed | #3 S Stair | 240 | SF | 6 | \$357 | |
| Ceiling - Plaster/Drywall | #3 S Stair | 325 | SF | 6 | \$2,380 | |
| Floor - Asphalt | #3 S Stair | 440 | SF | 6 | \$3,410 | |
| Handrails | #3 S Stair | 198 | LF | 6 | \$1,716 | |
| Lighting - Pendent/Surface | #3 S Stair | 6 | EA | 6 | \$743 | |
| Stairs - Asphalt | #3 S Stair | 88 | LF | 6 | \$817 | |
| Walls - Plaster/Drywall | #3 S Stair | 3,352 | SF | 6 | \$9,251 | |
| ilding Interior Subtotal: | | | | : | \$268,181 | |
| | | | | | | |
| tal Building Cost | | | | \$3 | ,727,625 | |

SITE

Category: Site

| 5 , | | | |
|--------------------------------|-------------|--------------------|---------------|
| Group Item - Type | Location | Quantity Unit Rank | Cost Comments |
| Civil/Drainage | | | |
| Civil/ Drainage - Catch Basin | Entire Site | 4 EA 6 | \$4,375 |
| Civil/ Drainage - Site Manhole | Entire Site | 8 EA 7 | \$0 |
| | | | |



\$3,907,457

533 W 27th St Chicago, IL 60616

SITE

| Category: Site | • • • • • • • • • • • • • • • • • • • | | | | - | - |
|---|---------------------------------------|----------|------|------|-----------|-------------------------------------|
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Civil/Drainage | | | | | | |
| encing | | | | | | |
| Fencing - Chain Link | Entire Site | 739 | LF | 6 | \$13,875 | |
| Fencing - Iron and Concrete Post | Entire Site / North | 426 | LF | 6 | \$15,625 | |
| andscape | | | | | | |
| Benches | Entire Site / North East | 22 | EA | 7 | \$0 | |
| Landscape - Grass | Entire Site | 16,324 | SF | 6 | \$13,539 | |
| Landscape - Hardscape- Concrete | Entire Site | 6,262 | SF | 6 | \$32,326 | Minor cracking throughout |
| Parkway trees | Entire Site | 21 | EA | 7 | \$0 | |
| Planting Beds/ Area | Entire Site | 2,118 | SF | 7 | \$0 | |
| Play Area - Asphalt/ Hardscape | Entire Site / South East | 14,300 | SF | 6 | \$34,559 | Minor cracks throughout |
| Trash Receptacles | Entire Site / East | 1 | EA | 7 | \$0 | |
| Parking Lot | | | | | | |
| Surface - Asphalt | Entire Site | 17,992 | SF | 6 | \$43,481 | Minor cracking throughout |
| Surface - Asphalt | Entire Site | 150 | SF | 5 | \$886 | Location: Drive isle, water ponding |
| idewalks | | | | | | |
| Sidewalks - Perimeter Sidewalks | Entire Site | 9,814 | SF | 6 | \$19,507 | |
| ignage | | | | | | |
| Flag Pole - Flag Pole | Entire Site / North West | 1 | EA | 6 | \$1,657 | Rust |
| Monument - Building Mounted Cut Letter Sign | Entire Site | 2 | EA | 6 | \$0 | Location: Entrances 1 and 3 |
| Site Subtotal: | | | | | \$179,832 | |
| Fotal Site Cost | | | | | \$179,832 | |

Campus Total ^{2 3}

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.



Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------------|--------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | + | + | * | | | | | • • • | | | | | | |
| Computer Lab | Computer Lab | Basement | 800 | 008 | 834 | 2 | 24 | 44 | 50 | 22 | 40 | Ν | N | Ν |
| Kindergarten | Regular Classroom | 1st Floor | 105 | 105 | 968 | 1 | 0 | 8 | 90 | 36 | 40 | Ν | Y | Ν |
| Kindergarten | Regular Classroom | 1st Floor | 107 | 107 | 968 | 0 | 0 | 8 | 100 | 42 | 40 | Ν | Y | Ν |
| Other Instructional Use | Multi Purpose Room | Basement | 007 | 007 | 905 | 0 | 0 | 12 | 0 | 0 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 103 | 103 | 900 | 1 | | 8 | 96 | 36 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 104 | 104 | 900 | 1 | | 8 | 116 | 42 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 106 | 106 | 968 | 1 | 2 | 8 | 90 | 27 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 108 | 108 | 968 | 1 | | 8 | 112 | 54 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 201 | 201 | 892 | | | 8 | 96 | 48 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 203 | 203 | 900 | 1 | | 8 | 96 | 36 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 204 | 201 | 900 | 1 | | 8 | 116 | 42 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 206 | 206 | 968 | 1 | 2 | 8 | 90 | 27 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 207 | 207 | 968 | | | 8 | 100 | 42 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 208 | 208 | 968 | 1 | | 8 | 112 | 54 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 209 | 209 | 936 | 1 | | 8 | 116 | 57 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 301 | 301 | 892 | 0 | 0 | 8 | 96 | 48 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 304 | 304 | 900 | 1 | | 8 | 116 | 42 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 305 | 305 | 968 | 1 | 2 | 8 | 90 | 27 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 306 | 306 | 968 | 1 | 2 | 8 | 90 | 27 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 307 | 307 | 968 | | | 8 | 100 | 42 | 40 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | | 308 | 308 | 968 | | | 10 | 112 | 54 | 40 | Ν | N | Ν |
| Regular Classroom | Regular Classroom | | 309 | 309 | 1,152 | 1 | 2 | 8 | 116 | 57 | 40 | Ν | Y | Ν |
| Science | Regular Classroom | 1st Floor | 102 | 102 | 900 | 1 | 0 | 8 | 96 | 36 | 40 | Ν | N | Ν |
| Science | Regular Classroom | | 202 | 202 | 900 | 1 | | 8 | 96 | 36 | 40 | Ν | N | Y |
| Store Room | Computer Lab | Basement | 009 | 009 | 942 | 1 | 2 | 38 | 36 | 15 | 40 | Ν | Y | Ν |