7831 S Prairie Ave Chicago, IL 60619

#### **Facility Assessment Report**

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About\_CPS/Policies\_and\_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary				
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need
Main	1925	2	88,210	\$4,028,859
Addition	1956	2	11,500	\$708,184
SITE				\$953,964
Campus Total			99,710	\$5,691,006

**Building: Main** 

**Category: Building Exterior** 

	ory. Danaing Exterior						
Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	ee						
	Entrance Control - Audio and Video	#1- NW- Main	1	EΑ	6	\$702	
	Exterior Doors - Exterior Steel Door	#1- NW- Main	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	#1.5- NW	1	EΑ	6	\$481	
	Exterior Doors - Exterior Steel Door	#10-E- Boiler House	1	EΑ	6	\$481	
	Exterior Doors - Exterior Steel Door	#11 -N- Boiler House	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	#2- SW	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	#3- SW	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	#4- S	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	#5- SE	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	#6- NE	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	#8- NW	2	EΑ	6	\$961	
	Exterior Doors - Exterior Steel Door	#9- NW	2	EΑ	6	\$961	
	Exterior Doors - Exterior Wood Door	#12- W- Boiler House	1	EΑ	4	\$3,823	deteriorated
	Exterior Doors - Transom Lite	#1- NW- Main	1	EΑ	6	\$313	
	Exterior Doors - Transom Lite	#1.5- NW	1	EΑ	6	\$313	
	Exterior Doors - Transom Lite	#2- SW	1	EΑ	6	\$313	
	Exterior Doors - Transom Lite	#3- SW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#4- S	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#5- SE	1	EA	6	\$313	

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

**Category: Building Exterior** 

	ory. Building Exterior						
•	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand							
	Exterior Doors - Transom Lite	#6- NE	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#8- NW	1	EA	6	\$313	
	Exterior Doors - Transom Lite	#9- NW	1	EA	6	\$313	
	Exterior Stairs - Concrete	#2- SW	50	LF	6	\$4,088	
	Exterior Stairs - Stone	#1- NW- Main	66	LF	5	\$17,897	open joints
	Exterior Stairs - Stone	#1.5- NW	3	LF	5		open joints
	Exterior Stairs - Stone	#10-E- Boiler House	3	LF	6	\$339	
	Exterior Stairs - Stone	#2- SW	6	LF	6	\$678	
	Exterior Stairs - Stone	#3- SW	46	LF	5		open joints
	Exterior Stairs - Stone	#4- S	46	LF	5	\$12,474	open joints
	Exterior Stairs - Stone	#5- SE	6	LF	6	\$678	
	Exterior Stairs - Stone	#6- NE	6	LF	6	\$678	
	Exterior Stairs - Stone	#8- NW	60	LF	6	\$6,779	
	Exterior Stairs - Stone	#9- NW	60	LF	6	\$6,779	
	Ramps - Concrete	#11 -N- Boiler House	5	LF	5	\$2,658	spalling
Founda	ation						
	Foundation - Concrete	Entire Building	20	LF	6	\$3,884	seepage in gas room
	Foundation - Concrete	Entire Building	46	LF	6	\$8,934	seepage in the connection tunnel
	Foundation - Concrete	Entire Building	904	LF	7	\$0	
	Superstructure - Concrete	Entire Building	40	SF	6	\$0	spalling of cement deck
	Superstructure - Concrete	Entire Building	70	SF	6	\$0	spalling of cement deck in gas room
	Superstructure - Concrete	Entire Building	88,100	SF	7	\$0	
Lightin	g						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	6	\$5,365	
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	\$2,021	
Roof S	ystem						
	Chimney - Metal Flue	Boiler Room Roof	140	LF	6	\$22,140	
	Coping - Terra Cotta	Boiler Room Roof	210	LF	6	\$6,745	Some open joints
	Coping - Terra Cotta	Low W Roof	30	LF	6	\$964	
	Coping - Terra Cotta	Main Roof	970	LF	6	\$31,154	
	Downspouts - Exterior Downspouts	Main Roof	99	LF	6	\$3,290	
	Downspouts - Interior Downspouts	Boiler Room Roof	18	LF	6	\$598	
	Downspouts - Interior Downspouts	Low W Roof	88	LF	6	\$2,925	
	Downspouts - Interior Downspouts	Main Roof	264	LF	6	\$8,774	
	Parapet - 16" - 30" Height	Boiler Room Roof	290	LF	6	\$11,587	
	Parapet - 16" - 30" Height	Low W Roof	30	LF	6	\$1,199	



7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

**Category: Building Exterior** 

rapet - 16" - 30" Height rapet - Parapet > 30" rapet - Parapet > 30" of Structure - Concrete of Structure - Concrete of Structure - Concrete of Structure - Steel with Clay Tile Arch of - Modified Bitumen of - Modified Bitumen	Main Roof Boiler Room Roof Main Roof Boiler Room Roof Low W Roof Main Roof Main Roof	60 20 910 2,740 88 24,730	LF LF SF SF	6 6 6 7 7	\$2,397 \$1,278 \$58,168 \$0	
rapet - Parapet > 30" rapet - Parapet > 30" of Structure - Concrete of Structure - Concrete of Structure - Concrete of Structure - Steel with Clay Tile Arch of - Modified Bitumen	Boiler Room Roof Main Roof Boiler Room Roof Low W Roof Main Roof Main Roof	20 910 2,740 88 24,730	LF LF SF SF	6 6	\$1,278 \$58,168 \$0	
rapet - Parapet > 30" of Structure - Concrete of Structure - Concrete of Structure - Concrete of Structure - Steel with Clay Tile Arch of - Modified Bitumen	Main Roof Boiler Room Roof Low W Roof Main Roof Main Roof	910 2,740 88 24,730	LF SF SF	6	\$58,168 \$0	
of Structure - Concrete of Structure - Concrete of Structure - Concrete of Structure - Steel with Clay Tile Arch of - Modified Bitumen	Boiler Room Roof Low W Roof Main Roof Main Roof	2,740 88 24,730	SF SF		\$0	
of Structure - Concrete of Structure - Concrete of Structure - Steel with Clay Tile Arch of - Modified Bitumen	Low W Roof Main Roof Main Roof	88 24,730	SF	7 7	* -	
of Structure - Concrete of Structure - Steel with Clay Tile Arch of - Modified Bitumen	Main Roof Main Roof	24,730	_	7		
of Structure - Steel with Clay Tile Arch of - Modified Bitumen	Main Roof	•	SF		\$0	
of - Modified Bitumen		2.700	٥.	7	\$0	
	Dailan Danna Danf	3,790	SF	7	\$0	
of - Modified Ritumen	Boiler Room Roof	2,740	SF	6	\$25,782	
or - Modified Diturneri	Low W Roof	88	SF	6	\$828	
of - Modified Bitumen	Main Roof	28,200	SF	6	\$265,345	
of - Tile Shingle	Main Roof	2,870	SF	6	\$23,147	
eek-Wall - Stone	Entire Building	77	SF	5	\$1,832	Doors:1,3,4- have cracks/spalling/or open joints
eek-Wall - Stone	Entire Building	66	SF	6	\$677	Doors: 2, 8, 9
rnice - Terra Cotta	Entire Building	970	LF	6	\$33,637	
erior Walls - Brick	Entire Building	32,010	SF	6	\$215,139	
erior Walls - Prefabricated Metal Panel Wall	Entire Building	816	SF	6	\$4,633	
erior Walls - Stone-Cast	Entire Building	2,910	SF	6	\$19,558	
erior Walls - Terra Cotta	Entire Building	7,840	SF	6	\$52,693	
ard - Guards wire guard	Entire Building / 1st Floor	1,904	SF	6	\$24,314	
tels - Steel	Entire Building	72	LF	6	\$2,090	
tels - Terra Cotta	Entire Building	24	LF	6	\$0	
ndows - Sash Lexan	Entire Building	3,578	SF	5	\$105,043	poor balances
	E & B 2 P	2,386	SF			
erre	eek-Wall - Stone nice - Terra Cotta erior Walls - Brick erior Walls - Prefabricated Metal Panel Wall erior Walls - Stone-Cast erior Walls - Terra Cotta  ard - Guards wire guard els - Steel els - Terra Cotta adows - Sash Lexan	eek-Wall - Stone Entire Building nice - Terra Cotta Entire Building erior Walls - Brick Entire Building erior Walls - Prefabricated Metal Panel Wall Entire Building erior Walls - Stone-Cast Entire Building erior Walls - Terra Cotta Entire Building erior Walls - Terra Cotta Entire Building erior Walls - Terra Cotta Entire Building erior Walls - Steel Entire Building erior Building erior Walls - Steel Entire Building erior Building	eek-Wall - Stone Entire Building 66 nice - Terra Cotta Entire Building 970 erior Walls - Brick Entire Building 32,010 erior Walls - Prefabricated Metal Panel Wall Entire Building 816 erior Walls - Stone-Cast Entire Building 2,910 erior Walls - Terra Cotta Entire Building 7,840 erior Walls - Terra Cotta Entire Building 7,840 erior Walls - Steel Entire Building 72 els - Steel Entire Building 72 els - Terra Cotta Entire Building 24 edows - Sash Lexan Entire Building 3,578	eek-Wall - Stone Entire Building 66 SF nice - Terra Cotta Entire Building 970 LF erior Walls - Brick Entire Building 32,010 SF erior Walls - Prefabricated Metal Panel Wall Entire Building 816 SF erior Walls - Stone-Cast Entire Building 2,910 SF erior Walls - Terra Cotta Entire Building 7,840 SF erior Walls - Terra Cotta Entire Building 7,840 SF erior Walls - Steel Entire Building 72 LF els - Steel Entire Building 24 LF edows - Sash Lexan Entire Building 3,578 SF	eek-Wall - Stone Entire Building 66 SF 6 enice - Terra Cotta Entire Building 970 LF 6 erior Walls - Brick Entire Building 32,010 SF 6 erior Walls - Prefabricated Metal Panel Wall Entire Building 816 SF 6 erior Walls - Stone-Cast Entire Building 2,910 SF 6 erior Walls - Terra Cotta Entire Building 7,840 SF 6 erior Walls - Terra Cotta Entire Building 7,840 SF 6 els - Steel Entire Building 72 LF 6 els - Terra Cotta Entire Building 24 LF 6	sek-Wall - Stone         Entire Building         66         SF         6         \$677           nice - Terra Cotta         Entire Building         970         LF         6         \$33,637           erior Walls - Brick         Entire Building         32,010         SF         6         \$215,139           erior Walls - Prefabricated Metal Panel Wall         Entire Building         816         SF         6         \$4,633           erior Walls - Stone-Cast         Entire Building         2,910         SF         6         \$19,558           erior Walls - Terra Cotta         Entire Building         7,840         SF         6         \$52,693           ard - Guards wire guard         Entire Building / 1st Floor         1,904         SF         6         \$24,314           els - Steel         Entire Building         72         LF         6         \$2,090           els - Terra Cotta         Entire Building         24         LF         6         \$0

**Building Exterior Subtotal:** 

\$1,047,242

**Building: Main** 

**Category: Electrical System** 

Group Item - Type	Location	Quantity Unit	Rank	Cost	Comments
Emergency System					
Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building / 1st Floor	4 EA	6	\$810	No other data available
Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building / 2nd Floor	4 EA	6	\$810	No other data available
Emergency Battery Packs - Corridors and Stairs	Entire Building / 1st Floor	1 EA	6	\$203	No other data available
Emergency Battery Packs - Corridors and Stairs	Entire Building / 2nd Floor	1 EA	6	\$203	No other data available



7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

**Category: Electrical System** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	ency System		•				
	Exit Signs - Auditoium	Entire Building / 1st Floor	6	EA	7	\$0	No other data available
	Exit Signs - Corridors and Stairs	Entire Building / 1st Floor	20	EA	7	\$0	No other data available
	Exit Signs - Corridors and Stairs	Entire Building / 2nd Floor	5	EA	7	\$0	No other data available
	Exit Signs - Corridors and Stairs	Entire Building / Basement	20	EA	7	\$0	No other data available
	Exit Signs - Gym	Entire Building / 1st Floor	3	EA	7	\$0	No other data available
	Exit Signs - Lunchroom	Entire Building / 1st Floor	2	EA	7	\$0	No other data available
	Security System - CCTV	Entire Building	88,210	SF	6	\$26,489	
	Security System - Intrusion Detection	Entire Building	88,210	SF	6	\$22,705	
Main S	ervice						
	Independent Electrical Service for emergency power	Basement	1	EA	4	\$18,799	Serves also the Addition
	Main Electrical Service - 1600 A 120/208/3PH	Basement / Electrical Room	1	EA	4	\$53,572	Also serves addition
	PA System	Entire Building	88,210	SF	6	\$29,012	Also serves addition
Power I	Distribution						
	Lighting and Power Panels - 100 A	Entire Building / Basement	1	EA	6	\$299	Cregier Electrical Panel: 102/208V 3P 4W 100A. S#: 30492
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497	Cregier Electrical Panel: 102/208V 3P 4W 225A. S#: 63770
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497	Cregier Electrical Panel: 102/208V 3P 4W 225A. S#: 63770
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497	Cregier Electrical Panel: 102/208V 3P 4W 225A. S#: 63770
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497	ITE Electrical Panel 120/208V 3P 4W 200A Cat#: EQ65/F-2
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497	GE Electrical Panel 102/208V 3P 4W 125A Cat# AQF3301MBX S#: AVB4
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497	Cregier Electrical Panel: 102/208V 3P 4W 225A. S#: 63770
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497	Cregier Electrical Panel: 102/208V 3P 4W 225A. S#: 63770
	Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497	Cat#: AF495, Date Code: Y537 120/208V 3P 4W 225A (Panel Blocked & Access is difficult)
	Lighting and Power Panels - Above 100 A	Entire Building / 2nd Floor	1	EA	6	\$497	Cregier Electrical Panel: 102/208V 3P 4W 225A. S#: 63770
	Lighting and Power Panels - Above 100 A	Entire Building / 2nd Floor	1	EA	6	\$497	Cregier Electrical Panel: 102/208V 3P 4W 225A. S#: 63770
	Lighting and Power Panels - Above 100 A	Entire Building / 2nd Floor	1	EA	6	\$497	Challenger Panel, 120/208v 3P 4W 200A Cat#: LC020DFG M#: 14
	Lighting and Power Panels - Above 100 A	Entire Building / Basement	1	EA	6	\$497	Cregier Electrical Panel: 102/208V 3P 4W 225A. S#: 30492



7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

**Category: Electrical System** 

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Power Distribution						
Lighting and Power Panels - Above 100 A	Entire Building / Boiler Room	1	EA	6	\$497	Cregier Electrical Panel: 102/208V 3P 4W 225A. S#: 30492, Type: NOB
Main Distribution Panels - Greater than 600 amp	Entire Building / Boiler Room	1	EA	6	\$730	Cregier Electrical Panel: 120/208V 3P 4W 1200A S#: 30492A
Main Distribution Panels - Greater than 600 amp	Entire Building / Electrical Room	1	EA	6	\$730	Cregier 120/208V 3P 4W 1600A Dwg#: 36750 S#: 30492 (Three Sections)
Transformers - 120/240 - 120/208	Entire Building / Boiler Room	1	EA	6	\$3,021	Powerformer Cat#: 213-444, KV: 75 240 to 208
Transformers - 120/240 - 120/208	Entire Building / Electrical Room	1	EA	6	\$3,021	Powerformer Cat#: 213-444, KV: 75 240 to 208

**Electrical System Subtotal:** 

\$166,868

**Building: Main** 

**Category: Safty System** 

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Fire Alarm						
Fire Alarm Panel	Basement	1	EA	6	\$6,406	Also serves the Addition
Fire Alarm_System	Basement / Entire Building	88,210	SF	4	\$175,335	

Safty System Subtotal:

\$181,741

**Building: Main** 

**Category: Mechanical System** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	\$44,262	
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	\$44,262	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	\$44,262	serves east side
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	5	\$34,007	serves south side
	Air Intake	Mechanical Room / Main Roof	2	EA	6	\$11,529	
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
	Air Intake	Mechanical Room / Roof	1	EA	6	\$5,765	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	\$5,788	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	\$5,788	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	\$5,788	

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

**Category: Mechanical System** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Air Han	dling Systems						
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	6	\$4,341	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room / Plenum	13	EA	5	\$55,748	12 in AHU-2, 13 in AHU-3
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room / Entire Building	200	LF	6	\$0	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	100	LF	6	\$0	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room / Entire Building	200	LF	6	\$0	
	Zone Dampers	Mechanical Room / Plenum	25	EA	5	\$53,154	
Boiler S	Systems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	6	\$5,091	
	Chemical Feed System	Boiler Room	1	EA	5	\$3,075	
	Combustion Dampers	Boiler Room	2	EA	6	\$818	
	Feed Water Pumps and Tank	Boiler Room / Bridge	1	EA	5	\$36,450	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	5	\$34,033	Also serves Addition
	Piping - Condensate Pipe- Steel	Boiler Room / Entire Building	200	LF	5	\$2,440	
	Piping - Steam Pipe- Steel	Boiler Room / Entire Building	200	LF	5	\$2,817	
	Steam Traps	Boiler Room / Entire Building	35	EA	5	\$46,021	
Gas Bo	oster						
	Gas Booster	Boiler Room	1	EA	5	\$12,593	M#: 2001-0076D-001, S#: A3116-062 (Inspection Pad Crumbing)
Heating	Devices						
	Radiators - Steam	Entire Building	12	EA	4	\$43,886	
	Unit Heater - Electric	Boiler Room	1	EA	6	\$278	Sterling Fan Powered, Natural Gas Unit Heater. (No Other Data Available)
	Unit Heater - Electric	Boiler Room / Entire Building	4	EA	6	\$1,111	(,
Mechar	nical Plumbing						
	Condenser Pump - Less than 10	Mechanical Room	2	EA	6	\$2,222	
Tempe	rature Control						
	Pneumatic System	Entire Building	92,725	SF	4	\$482,652	
	Thermostats - Pneumatic	Entire Building	25	EA	4	\$18,431	
Ventilat	ion						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Main Roof	2	EA	6	\$1,185	M#: DX118, S#: G08AZ26918, RPM = 882, 115V. 3P- 1/1HP



7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

**Category: Mechanical System** 

Group Item - Type Location Quantity Unit Rank Cost Comments

Mechanical System Subtotal: \$1,013,560

**Building: Main** 

**Category: Plumbing System** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Hot Wa	ter						
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	6	\$310	
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	2	EA	6	\$1,357	Capacity 119 gallons
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	88,210	SF	6	\$17,660	
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	88,210	SF	6	\$21,444	
	Domestic Piping-Cold Water Risers	Entire Building	88,210	SF	6	\$16,398	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	88,210	SF	6	\$13,875	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	88,210	SF	6	\$16,398	
	Domestic Piping-Hot Water Return Lines	Entire Building	88,210	SF	6	\$12,614	
	Domestic Piping-Hot Water Return Risers	Entire Building	88,210	SF	6	\$12,614	
	Sanitary Piping	Entire Building	88,210	SF	6	\$80,730	
	Storm Piping	Entire Building	88,210	SF	6	\$76,946	Parking Lot Backs up (Heavy Rains)
	Vent Piping	Entire Building	88,210	SF	6	\$59,286	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Boile Room and Basement / Boiler Room	2	EA	4	\$50,881	Also serves the Addition
	Pumps - Sump-Duplex	Boile Room and Basement / Basement	2	EA	6	\$2,774	
	Pumps - Sump-Duplex	Boile Room and Basement / Boiler Room	1	EA	6	\$1,387	

**Plumbing System Subtotal:** 

\$384,673

**Building: Main** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #102 (Store Room)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	736	SF	6	\$2,210	
	Chalk Board	1st Floor	40	LF	4	\$3,672	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	736	SF	6	\$5,189	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	



7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

_	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
•	oom #102 (Store Room)						
	Walls - Plaster/Drywall	1st Floor	1,090	SF	6	\$3,008	
	•		,			. ,	
Classro	oom #105 (Regular Classroom)						
	Casework	1st Floor	35	LF	6	\$884	
	Ceiling - Lay-in	1st Floor	762	SF	6	\$2,288	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	762	SF	6	\$5,372	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	31	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,060	SF	6	\$2,925	
	Work Sink	1st Floor	1	EA	6	\$379	
Classro	oom #106B (Kindergarten)						
	Casework	1st Floor	12	LF	6	\$303	
	Ceiling - Lay-in	1st Floor	831	SF	6	\$2,495	
	Chalk Board	1st Floor	8	LF	4	\$734	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	831	SF	6	\$5,858	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	12	LF	7	\$0	
	Walls - Masonry	1st Floor	64	SF	6	\$201	fireplace
	Walls - Plaster/Drywall	1st Floor	20	SF	5		damaged
	Walls - Plaster/Drywall	1st Floor	1,290	SF	6	\$3,560	aa.nagou
Classro	oom #107 (Regular Classroom)		,			, ,	
Olassic	Casework	1st Floor	8	LF	6	\$202	
	Ceiling - Lay-in	1st Floor	692	SF	6	\$2,078	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	692	SF	6	\$4,879	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	23	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,001	SF	6	\$2,763	
		13111001	1,001	Oi	O	Ψ2,700	
Classro	oom #108 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	736	SF	6	\$2,210	
	Chalk Board	1st Floor	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	736	SF	6	\$5,189	

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
-	oom #108 (Regular Classroom)						
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	3	SF	5	\$15	peeling
	Walls - Plaster/Drywall	1st Floor	1,090	SF	6	\$3,008	
Classr	oom #110 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	\$253	
	Ceiling - Lay-in	1st Floor	736	SF	6	\$2,210	
	Chalk Board	1st Floor	24	LF	4	\$2,203	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
	Floor - Wood	1st Floor	736	SF	6	\$5,189	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,090	SF	6	\$3,008	
Classr	oom #111 (Kindergarten)						
	AC Units	1st Floor	2	EA	6	\$991	
	Casework	1st Floor	29	LF	6	\$732	
	Ceiling - Lay-in	1st Floor	988	SF	6	\$2,967	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	988	SF	6	\$6,965	
	Lighting - Lay-in	1st Floor	14	EA	7	\$0	
	Marker Board	1st Floor	24	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,210	SF	6	\$3,339	
	Work Sink	1st Floor	1	EA	6	\$379	
Classr	oom #113 (Regular Classroom)						
	AC Units	1st Floor	1	EA	6	\$496	
	Casework	1st Floor	9	LF	6	\$227	
	Ceiling - Lay-in	1st Floor	5	SF	5	\$40	stained
	Ceiling - Lay-in	1st Floor	727	SF	6	\$2,183	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
	Floor - Wood	1st Floor	732	SF	6	\$5,161	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Marker Board	1st Floor	15	LF	7	\$0	
	Walls - Plaster/Drywall	1st Floor	1,036	SF	6	\$2,859	
	Walls - Plaster/Drywall	1st Floor	5	SF	5	\$26	bubbling / peeling / cracks



7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 


	Item - Type	Location	Quantity	Unit	Dank	Cost	Comments
•	oom #205 (Regular Classroom)	Location	Quantity	Unit	Rank	Cost	Comments
Classic	Casework	2nd Floor	7	LF	6	\$177	
	Ceiling - Lay-in	2nd Floor	7 701	SF	6	\$2,105	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	701	SF	6	\$4,942	
		2nd Floor		EA	7	\$4,942	
	Lighting - Lay-in Marker Board	2nd Floor	12 22	LF	7	\$0 \$0	
	Walls - Plaster/Drywall	2nd Floor	1,007	SF			
	Walls - Plaster/Drywall	ZIId Flooi	1,007	SF	6	\$2,779	
Classro	oom #206 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	736	SF	6	\$2,210	
	Doors - Transom Window	2nd Floor	9	SF	6	\$152	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor - Wood	2nd Floor	736	SF	6	\$5,189	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	14	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,166	SF	6	\$3,218	
Classro	oom #207 (Regular Classroom)						
	Casework	2nd Floor	9	LF	6	\$227	
	Ceiling - Lay-in	2nd Floor	729	SF	6	\$2,189	
	Chalk Board	2nd Floor	4	LF	4	\$367	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	729	SF	6	\$5,139	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	34	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,038	SF	6	\$2,865	
Classro	oom #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	558	SF	6	\$1,676	
	Chalk Board	2nd Floor	12	LF	4	\$1,102	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	558	SF	6	\$3,934	
	Lighting - Lay-in	2nd Floor	10	EA	7	\$0	
	Marker Board	2nd Floor	10	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	984	SF	6	\$2,716	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	\$10	cracked



7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

ıp	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
sro	om #208 (Regular Classroom)						
	om #209 (Regular Classroom)						
510	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	732	SF	6	\$2,198	
	Chalk Board	2nd Floor	4	LF	4	\$367	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$30 <i>1</i>	
	Floor - Wood	2nd Floor	732	SF	6	\$5,161	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$5,161 \$0	
	Marker Board	2nd Floor	28	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,036	SF	6		
	walls - Plaster/Drywall	211d F1001	1,036	SF	0	\$2,859	
sro	om #210 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	736	SF	6	\$2,210	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	736	SF	6	\$5,189	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	26	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	\$10	peeling
	Walls - Plaster/Drywall	2nd Floor	1,164	SF	6	\$3,213	
cro	om #212 (Regular Classroom)						
310	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	736	SF	6	\$2,210	
	Chalk Board	2nd Floor	20	LF	4	\$1,836	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood Doors Inclu IIW	2nd Floor	736	SF	6	\$5,189	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0,109	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,166	SF	6	\$3,218	
		2.10 1 1001	1,100	٥.	J	ΨΟ,Σ 10	
sro	om #214 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	736	SF	6	\$2,210	
	Chalk Board	2nd Floor	6	LF	4	\$551	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	736	SF	6	\$5,189	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	28	LF	7	\$0	





**Building: Main** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	oom #214 (Regular Classroom)						
	Walls - Plaster/Drywall	2nd Floor	1,166	SF	6	\$3,218	
Classro	oom #215 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	\$253	
	Ceiling - Lay-in	2nd Floor	729	SF	6	\$2,189	
	Chalk Board	2nd Floor	18	LF	4	\$1,653	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	729	SF	6	\$5,139	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	20	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	\$51	bubbling / peeling / cracks
	Walls - Plaster/Drywall	2nd Floor	1,022	SF	6	\$2,821	
Classro	oom #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	broken cover
	Casework	2nd Floor	13	LF	6	\$328	
	Ceiling - Lay-in	2nd Floor	514	SF	6	\$1,544	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	514	SF	6	\$1,125	
	Lighting - Lay-in	2nd Floor	9	EΑ	7	\$0	
	Marker Board	2nd Floor	16	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,043	SF	6	\$2,879	
Classro	oom #217 (Regular Classroom)						
	Casework	2nd Floor	15	LF	6	\$379	
	Ceiling - Lay-in	2nd Floor	734	SF	6	\$2,204	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Wood	2nd Floor	734	SF	6	\$5,175	
	Lighting - Lay-in	2nd Floor	12	EA	7	\$0	
	Marker Board	2nd Floor	44	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,043	SF	6	\$2,879	

**Classrooms Subtotal:** 

\$224,968

**Building: Main** 

**Category: Rooms (Other Than Classrooms)** 

Group Item - Type Location Quantity Unit Rank Cost Comments

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

Location	Quantity	Unit	Rank	Cost	Comments
1st - 103 Office	708	SF	6	\$2,126	
1st - 103 Office	2	EA	6	\$602	
1st - 103 Office	708	SF	6	\$4,991	
1st - 103 Office	12	EA	7	\$0	
1st - 103 Office	18	EA	6	\$38,248	
1st - 103 Office	1,016	SF	6	\$2,804	
1st - 109	1	EA	6	\$496	
1st - 109	416	SF	6	\$1,249	
1st - 109	1	EA	6	\$301	
1st - 109	416	SF	6	\$910	
1st - 109	6	EA	7	\$0	
1st - 109	10	EA	6	\$21,249	
1st - 109	889	SF	6	\$2,454	
1st - 133 Main Office	1	EA	6	\$496	
1st - 133 Main Office	325	SF	6	\$976	
1st - 133 Main Office	7	SF	6	\$119	
1st - 133 Main Office	1	EA	6	\$301	
1st - 133 Main Office	325	SF	6	\$2,291	
1st - 133 Main Office	6	EA	7	\$0	
1st - 133 Main Office	4	EA	6	\$8,500	
1st - 133 Main Office	789	SF	6	\$2,178	
1st - engineers office above boiler room	1	EA	6	\$496	
1st - engineers office above boiler room	75	SF	6	\$225	
1st - engineers office above boiler room	1	EA	6	\$301	
1st - engineers office above boiler room	75	SF	6	\$164	
1st - engineers office above boiler room	1	EA	7	\$0	
1st - engineers office above boiler room	4	EA	6	\$8,500	
1st - engineers office above boiler room	347	SF	6	\$958	
1st - engineers office above boiler room	1	EA	6	\$508	pedestal sink
1st - Office 1 in 133 Main Office	1	EA	6	\$496	
1st - Office 1 in 133 Main Office	126	SF	6	\$378	
1st - Office 1 in 133 Main Office	1	EA	6	\$301	
1st - Office 1 in 133 Main Office	126	SF	6	\$888	
1st - Office 1 in 133 Main Office	2	EA	7	\$0	
1st - Office 1 in 133 Main Office	4	EA	6	\$8,500	
1st - Office 1 in 133 Main Office	481	SF	6	\$1,328	
1st - Principle Office inside 133	160	SF	6	\$480	
	1st - 103 Office 1st - 109 1st - 133 Main Office 1st - engineers office above boiler room 1st - office 1 in 133 Main Office	1st - 103 Office       708         1st - 103 Office       2         1st - 103 Office       708         1st - 103 Office       12         1st - 103 Office       18         1st - 103 Office       1,016         1st - 109       1         1st - 109       416         1st - 109       4         1st - 109       6         1st - 109       10         1st - 109       889         1st - 133 Main Office       1         1st - 133 Main Office       325         1st - 133 Main Office       3         1st - 133 Main Office       4         1st - 133 Main Office       6         1st - 133 Main Office       7         1st - 133 Main Office       7         1st - 133 Main Office       4         1st - 133 Main Office       7         1st - 133 Main Office       7         1st - 133 Main Office       7         1st - 133 Main Office       1         1st - 134 Main Office       1	1st - 103 Office       708       SF         1st - 103 Office       2       EA         1st - 103 Office       708       SF         1st - 103 Office       12       EA         1st - 103 Office       18       EA         1st - 109       1       EA         1st - 109       1       EA         1st - 109       416       SF         1st - 109       416       SF         1st - 109       6       EA         1st - 109       10       EA         1st - 109       889       SF         1st - 133 Main Office       1       EA         1st - 133 Main Office       325       SF         1st - 133 Main Office       7       SF         1st - 133 Main Office       1       EA         1st - 133 Main Office       4       EA         1st - 133 Main Office       7       SF         1st - 133 Main Office       7       SF         1st - 133 Main Office       4       EA         1st - engineers office above boiler room       1       EA         1st - engineers office above boiler room       1       EA         1st - engineers office above boiler room       1	1st - 103 Office         708         SF         6           1st - 103 Office         2         EA         6           1st - 103 Office         708         SF         6           1st - 103 Office         12         EA         7           1st - 103 Office         18         EA         6           1st - 103 Office         1,016         SF         6           1st - 109         1         EA         6           1st - 109         416         SF         6           1st - 133 Main Office         1         EA         6           1st - 133 Main Office         325         SF         6           1st - 133 Main Office         7         <	1st - 103 Office         708         SF         6         \$2,126           1st - 103 Office         2         EA         6         \$602           1st - 103 Office         708         SF         6         \$4,991           1st - 103 Office         12         EA         7         \$0           1st - 103 Office         18         EA         6         \$38,248           1st - 109         1         EA         6         \$496           1st - 109         1         EA         6         \$496           1st - 109         416         SF         6         \$1,249           1st - 109         416         SF         6         \$1,249           1st - 109         416         SF         6         \$1,249           1st - 109         416         SF         6         \$910           1st - 109         416         SF         6         \$21,249           1st - 109         416         SF         6         \$21,249           1st - 133 Main Office         1         EA         6         \$24,54           1st - 133 Main Office         325         SF         6         \$21,249           1st - 133 Main Office

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

up Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
ninistrative Suites/Offices						
Doors - Wood Doors inclu hw	1st - Principle Office inside 133	1	EA	6	\$301	
Floor - Wood	1st - Principle Office inside 133	160	SF	6	\$1,128	
Lighting - Lay-in	1st - Principle Office inside 133	2	EA	7	\$0	
Power Distribution	1st - Principle Office inside 133	4	EA	6	\$8,500	
Walls - Plaster/Drywall	1st - Principle Office inside 133	538	SF	6	\$1,485	
Ceiling - Lay-in	1st- 106A Principal	372	SF	6	\$1,117	
Doors - Wood Doors inclu hw	1st- 106A Principal	1	EA	6	\$301	
Floor - Wood	1st- 106A Principal	372	SF	6	\$2,623	
Lighting - Lay-in	1st- 106A Principal	6	EA	7	\$0	
Power Distribution	1st- 106A Principal	4	EA	6	\$8,500	
Storage/ Closet	1st- 106A Principal	18	SF	6	\$131	
Walls - Plaster/Drywall	1st- 106A Principal	849	SF	6	\$2,343	
Ceiling - Plaster/Drywall	1st- Rm 104 Counseling Office	718	SF	6	\$2,485	
Doors - Wood Doors inclu hw	1st- Rm 104 Counseling Office	2	EA	6	\$602	
Floor - Wood	1st- Rm 104 Counseling Office	710	SF	6	\$5,005	
Floor - Wood	1st- Rm 104 Counseling Office	8	SF	4	\$334	rotted by windows
Lighting - Lay-in	1st- Rm 104 Counseling Office	12	EΑ	7	\$0	
Power Distribution	1st- Rm 104 Counseling Office	16	EΑ	6	\$33,998	
Walls - Plaster/Drywall	1st- Rm 104 Counseling Office	1,140	SF	6	\$3,146	
Walls - Plaster/Drywall	1st- Rm 104 Counseling Office	22	SF	5	\$112	efflorecense
Work Sink	1st- Rm 104 Counseling Office	1	EΑ	6	\$508	
Ceiling - Plaster/Drywall	2nd- 218-A Speech/Psychologist Office	138	SF	6	\$478	
Doors - Side-lite	2nd- 218-A Speech/Psychologist Office	14	SF	6	\$234	
Doors - Transom Window	2nd- 218-A Speech/Psychologist Office	4	SF	6	\$68	
Doors - Wood Doors inclu hw	2nd- 218-A Speech/Psychologist Office	1	EA	6	\$301	
Floor - Tile	2nd- 218-A Speech/Psychologist Office	138	SF	6	\$302	
Lighting - Pendent/Surface	2nd- 218-A Speech/Psychologist Office	2	EA	7	\$0	
Power Distribution	2nd- 218-A Speech/Psychologist Office	4	EA	6	\$8,500	
Walls - Plaster/Drywall	2nd- 218-A Speech/Psychologist Office	407	SF	6	\$1,123	
Work Slnk	2nd- 218-A Speech/Psychologist Office	1	EA	6	\$508	
AC Unit	2nd- Resource Room	1	EA	6	\$496	
Ceiling - Lay-in	2nd- Resource Room	539	SF	6	\$1,619	
Doors - Wood Doors inclu hw	2nd- Resource Room	1	EA	6	\$301	
Floor - Tile	2nd- Resource Room	539	SF	6	\$1,179	
Lighting - Lay-in	2nd- Resource Room	6	EA	7	\$0	
Power Distribution	2nd- Resource Room	6	EA	6	\$12,749	
Storage/ Closet	2nd- Resource Room	27	SF	6	\$196	

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Admini	strative Suites/Offices						
	Walls - Plaster/Drywall	2nd- Resource Room	1,045	SF	6	\$2,884	
	Walls - Plaster/Drywall	2nd- Resource Room	10	SF	5	\$51	peeling
	Work Slnk	2nd- Resource Room	1	EA	6	\$508	
	AC Unit	2nd- Rm 218 Speech & Psychologist	1	EA	6	\$496	
	Ceiling - Plaster/Drywall	2nd- Rm 218 Speech & Psychologist	490	SF	6	\$1,696	
	Ceiling - Plaster/Drywall	2nd- Rm 218 Speech & Psychologist	5	SF	5	\$62	efflorescence
	Doors - Wood Doors inclu hw	2nd- Rm 218 Speech & Psychologist	1	EA	6	\$301	
	Floor - Terrazzo	2nd- Rm 218 Speech & Psychologist	49	SF	6	\$107	
	Floor - Tile	2nd- Rm 218 Speech & Psychologist	446	SF	6	\$976	
	Lighting - Pendent/Surface	2nd- Rm 218 Speech & Psychologist	6	EA	7	\$0	
	Power Distribution	2nd- Rm 218 Speech & Psychologist	12	EA	6	\$25,499	
	Walls - Plaster/Drywall	2nd- Rm 218 Speech & Psychologist	4	SF	5	\$20	efflorescence
	Walls - Plaster/Drywall	2nd- Rm 218 Speech & Psychologist	1,439	SF	6	\$3,971	
	Work Slnk	2nd- Rm 218 Speech & Psychologist	1	EA	6	\$508	
Audito	rium & Theater						
	Balcony Seating	1st Floor	81	EA	6	\$14,087	
	Ceiling - Plaster/Drywall	1st Floor	4,020	SF	6	\$33,514	
	Ceiling - Plaster/Drywall	1st Floor	37	SF	5	\$1,166	water damaged in stairs to balcony & on ceiling above balcony
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	\$301	balcony door
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	\$1,505	
	Floor - Epoxy/ Painted	1st Floor	3,235	SF	6	\$1,712	balcony floor & main auditorium floor
	Floor - Terrazzo	1st Floor	192	SF	6	\$420	
	Floor - Tile Ceramic/ Porcelain	1st Floor	158	SF	6	\$334	stone floor in vestibule
	Floor - Wood	1st Floor	472	SF	6	\$3,328	stage floor
	Lighting - Chandelier, Incandescent	1st Floor	8	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	\$0	
	Main Floor Seating	1st Floor	94	EA	6	\$16,348	
	Sound System	1st Floor	1	EA	6	\$10,721	
	Stage	1st Floor	472	SF	6	\$2,727	
	Stage Curtain	1st Floor	4	EA	6	\$0	
	Stage Lighting System	1st Floor	1	EA	6	\$8,077	
	Stage-Stairs - Tile	1st Floor	10	LF	6	\$93	stone
	Stairs - Terrazzo	1st Floor	30	LF	6	\$230	
	Storage/ Closet	1st Floor	35	SF	6	\$254	
	Walls - Plaster/Drywall	1st Floor	5,313	SF	6	\$25,300	
	Walls - Tile Ceramic/ Porcelain	1st Floor	693	SF	6	\$1,566	stono

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Gymna	sia						
	Ceiling - Lay-in	1st Floor	2,721	SF	6	\$8,171	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	\$1,204	
	Floor - Wood	1st Floor	10	SF	4	\$417	wood floor is rotting by exit doors
	Floor - Wood	1st Floor	2,711	SF	6	\$19,112	
	Lighting - Lay-in	1st Floor	12	EA	7	\$0	
	Scoreboards	1st Floor	1	EA	6	\$2,244	
	Student Lockers - One Tier	1st Floor	10	EA	6	\$928	
	Walls - Masonry	1st Floor	1,519	SF	6	\$4,779	
	Walls - Plaster/Drywall	1st Floor	3,851	SF	6	\$10,628	
Library							
	AC Unit	2nd - 211 Library	2	EA	6	\$991	
	Casework	2nd - 211 Library	129	LF	6	\$3,258	
	Ceiling - Lay-in	2nd - 211 Library	1,447	SF	6	\$4,345	
	Doors - Wood Doors inclu hw	2nd - 211 Library	2	EA	6	\$602	
	Floor - Wood	2nd - 211 Library	1,447	SF	6	\$10,201	
	Lighting - Lay-in	2nd - 211 Library	24	EA	7	\$0	
	Walls - Plaster/Drywall	2nd - 211 Library	1,556	SF	6	\$4,294	
Locker/	Shower Room						
	Ceiling - Plaster/ Drywall	Boys Locker Rm (now storage)	6	SF	5	\$78	water damaged
	Ceiling - Plaster/ Drywall	Boys Locker Rm (now storage)	383	SF	6	\$1,325	
	Doors - Wood Doors inclu hw	Boys Locker Rm (now storage)	2	EA	6	\$602	
	Floor - Tile Ceramic/ Porcelain	Boys Locker Rm (now storage)	389	SF	6	\$823	
	Lavatory	Boys Locker Rm (now storage)	1	EA	6	\$320	
	Lighting - Pendent/Surface	Boys Locker Rm (now storage)	4	EA	7	\$0	
	Student Lockers - One Tier	Boys Locker Rm (now storage)	5	EA	6	\$464	
	Walls - Masonry	Boys Locker Rm (now storage)	141	SF	6	\$444	
	Walls - Plaster/Drywall	Boys Locker Rm (now storage)	563	SF	6	\$1,554	
	Walls - Plaster/Drywall	Boys Locker Rm (now storage)	15	SF	5	\$77	water damaged & crack
	AC Unit	Girl's Locker Room (now storage) located above Boy's Locker Rm on a mezzanine	1	EA	6	\$496	
	Ceiling - Plaster/ Drywall	Girl's Locker Room (now storage) located above Boy's Locker Rm on a mezzanine	561	SF	6	\$1,941	
	Doors - Wood Doors inclu hw	Girl's Locker Room (now storage) located above Boy's Locker Rm on a mezzanine	1	EA	6	\$301	

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker	/Shower Room						
	Floor - Carpet	Girl's Locker Room (now storage) located above Boy's Locker Rm on a mezzanine	561	SF	6	\$1,195	
	Floor - Terrazzo	Girl's Locker Room (now storage) located above Boy's Locker Rm on a mezzanine	68	SF	6	\$149	stairwell flooring
	Lighting - Pendent/Surface	Girl's Locker Room (now storage) located above Boy's Locker Rm on a mezzanine	7	EA	4	\$3,784	T12's
	Walls - Masonry	Girl's Locker Room (now storage) located above Boy's Locker Rm on a mezzanine	714	SF	6	\$2,246	
	Walls - Plaster/Drywall	Girl's Locker Room (now storage) located above Boy's Locker Rm on a mezzanine	179	SF	6	\$494	
Lunch	& Multipurpose Room						
	Ceiling - Lay-in	2nd- Rm 221 Teacher's Lounge	408	SF	6	\$1,225	
	Doors - Wood Doors inclu hw	2nd- Rm 221 Teacher's Lounge	1	EA	6	\$301	
	Floor - Wood	2nd- Rm 221 Teacher's Lounge	408	SF	6	\$2,876	
	Lighting - Lay-in	2nd- Rm 221 Teacher's Lounge	6	EA	7	\$0	
	Walls - Plaster/Drywall	2nd- Rm 221 Teacher's Lounge	908	SF	6	\$2,506	
MDF_II	DF .						
	AC Unit	2nd Floor	1	EA	6	\$496	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	\$301	
	Finishes	2nd Floor	149	SF	6	\$1,063	
Mechai	nical/ Service Rooms						
	Janitor's Closet	1st Floor	184	SF	6	\$1,318	
	Janitor's Closet	2nd Floor	52	SF	6	\$373	
	Storage Room	2nd Floor	178	SF	6	\$1,275	janitor equipment storage
	Air Intake Plenums	Basement	791	SF	6	\$4,898	
	Air Tunnel	Basement	4,918	SF	6	\$30,452	
	Air Tunnel	Basement	372	SF	5	\$4,953	tunnel to boiler - water leakage
	Boiler Room	Basement	2,491	SF	6	\$17,846	
	Crawl Space - Unfinished	Basement	16,756	SF	6	\$103,751	
	Interior Stairs	Basement	68	LF	6	\$614	
	Mechanical/ Service Rooms	Basement	3,765	SF	6	\$26,974	
	Storage Room	Basement	146	SF	5	\$2,355	water leakage



7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

pup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
p Room						
Ceiling - Plaster/Drywall	Projection Room in Auditorium	71	SF	6	\$246	
Doors - Wood Doors inclu hw	Projection Room in Auditorium	1	EA	6	\$301	
Floor - Concrete	Projection Room in Auditorium	71	SF	6	\$38	
Lighting - Pendent/Surface	Projection Room in Auditorium	1	EA	4	\$541	T12
Walls - Plaster/Drywall	Projection Room in Auditorium	298	SF	6	\$822	
stroom						
Accessories	1st - inside engineer office	22	SF	6	\$203	
Ceiling - Plaster/Drywall	1st - inside engineer office	22	SF	6	\$76	
Doors - Wood Doors inclu hw	1st - inside engineer office	1	EΑ	6	\$301	
Floor - Tile	1st - inside engineer office	22	SF	6	\$48	
Lighting - Pendent/Surface	1st - inside engineer office	1	EA	6	\$124	
Walls - Plaster/Drywall	1st - inside engineer office	220	SF	6	\$607	
Water Closet	1st - inside engineer office	1	EA	6	\$336	
Accessories	1st - inside Office 1 inside 133	26	SF	6	\$240	
Ceiling - Plaster/Drywall	1st - inside Office 1 inside 133	26	SF	6	\$90	
Doors - Wood Doors inclu hw	1st - inside Office 1 inside 133	1	EΑ	6	\$301	
Floor - Tile Ceramic/ Porcelain	1st - inside Office 1 inside 133	26	SF	6	\$55	
Lavatory	1st - inside Office 1 inside 133	1	EΑ	6	\$320	in base cabinet
Lighting - Wall Mounted	1st - inside Office 1 inside 133	1	EΑ	7	\$0	
Walls - Plaster/Drywall	1st - inside Office 1 inside 133	257	SF	6	\$709	
Water Closet	1st - inside Office 1 inside 133	1	EΑ	6	\$336	
Accessories	1st Floor	396	SF	6	\$3,653	
Ceiling - Plaster/Drywall	1st Floor	396	SF	6	\$1,370	
Doors - Transom Window	1st Floor	36	SF	6	\$610	
Doors - Wood Doors inclu hw	1st Floor	4	EA	6	\$1,204	
Floor Drain	1st Floor	1	EA	6	\$1,059	
Floor - Tile Ceramic/ Porcelain	1st Floor	396	SF	6	\$838	
Hand Dryer	1st Floor	2	EA	6	\$460	
Lavatory	1st Floor	2	EA	6	\$639	
Lighting - Pendent/Surface	1st Floor	6	EA	7	\$0	
Partitions	1st Floor	8	EA	6	\$2,375	
Walls - Masonry	1st Floor	370	SF	6	\$1,164	
Walls - Plaster/Drywall	1st Floor	370	SF	6	\$1,021	
Walls - Tile Ceramic/ Porcelain	1st Floor	100	SF	6	\$226	
Water Closet	1st Floor	9	EA	6	\$3,024	
Accessories	1st- Inside Rm 104	195	SF	6	\$1,799	
Ceiling - Lay-in	1st- Inside Rm 104	195	SF	6	\$586	

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restro	•		additity	Jint	···	- 5550	
11001.01	Doors - Wood Doors inclu hw	1st- Inside Rm 104	1	EA	6	\$301	
	Doors - Wood Doors inclu hw	1st- Inside Rm 104	1	EA	4	\$3,413	glass pane missing & hole in door
	Floor Drain	1st- Inside Rm 104	1	EA	6	\$1,059	glade parte timeering a viete in acci.
	Floor - Terrazzo	1st- Inside Rm 104	143	SF	6	\$313	
	Floor - Tile Ceramic/ Porcelain	1st- Inside Rm 104	52	SF	6	\$110	
	Lavatory	1st- Inside Rm 104	2	EA	6	\$639	
	Lighting - Pendent/Surface	1st- Inside Rm 104	3	EA	7	\$0	
	Partitions	1st- Inside Rm 104	1	EA	6	\$297	
	Walls - Plaster/Drywall	1st- Inside Rm 104	618	SF	6	\$1,706	
	Water Closet	1st- Inside Rm 104	2	EA	6	\$672	
	Accessories	1st- Men's (By Gym)	274	SF	6	\$2,527	
	Ceiling - Plaster/Drywall	1st- Men's (By Gym)	274	SF	6	\$948	
	Floor Drain	1st- Men's (By Gym)	1	EA	6	\$1,059	
	Floor - Concrete	1st- Men's (By Gym)	35	SF	6	\$19	
	Floor - Tile Ceramic/ Porcelain	1st- Men's (By Gym)	2	SF	5	\$42	missing around drain
	Floor - Tile Ceramic/ Porcelain	1st- Men's (By Gym)	239	SF	6	\$506	3
	Hand Dryer	1st- Men's (By Gym)	2	EΑ	6	\$460	
	Lavatory	1st- Men's (By Gym)	2	EΑ	6	\$639	
	Lighting - Pendent/Surface	1st- Men's (By Gym)	6	EΑ	7	\$0	
	Partitions	1st- Men's (By Gym)	3	EΑ	6	\$891	
	Urinals	1st- Men's (By Gym)	4	EΑ	6	\$1,344	
	Walls - Masonry	1st- Men's (By Gym)	417	SF	6	\$1,312	
	Walls - Plaster/Drywall	1st- Men's (By Gym)	278	SF	6	\$767	
	Water Closet	1st- Men's (By Gym)	2	EΑ	6	\$672	
	Ceiling - Plaster/Drywall	1st- Men's in Auditorium Vestibule (now storage)	67	SF	6	\$232	
	Doors - Wood Doors inclu hw	1st- Men's in Auditorium Vestibule (now storage)	1	EA	6	\$301	
	Floor - Carpet	1st- Men's in Auditorium Vestibule (now storage)	67	SF	6	\$143	
	Lighting - Pendent/Surface	1st- Men's in Auditorium Vestibule (now storage)	2	EA	4	\$1,081	T12
	Walls - Masonry	1st- Men's in Auditorium Vestibule (now storage)	331	SF	6	\$1,041	
	Walls - Plaster/Drywall	1st- Men's in Auditorium Vestibule (now storage)	138	SF	6	\$381	
	Water Closet	1st- Men's in Auditorium Vestibule (now storage)	1	EA	6	\$336	
	Accessories	1st- Women's (by Gym)	96	SF	6	\$885	

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Restroc	••						
	Ceiling - Plaster/Drywall	1st- Women's (by Gym)	96	SF	6	\$332	
	Doors - Wood Doors inclu hw	1st- Women's (by Gym)	1	EA	6	\$301	
	Floor - Tile Ceramic/ Porcelain	1st- Women's (by Gym)	96	SF	6	\$203	
	Lavatory	1st- Women's (by Gym)	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st- Women's (by Gym)	2	EA	7	\$0	
	Partitions	1st- Women's (by Gym)	1	EA	6	\$297	
	Walls - Masonry	1st- Women's (by Gym)	134	SF	6	\$422	
	Walls - Plaster/Drywall	1st- Women's (by Gym)	89	SF	6	\$246	
	Water Closet	1st- Women's (by Gym)	2	EA	6	\$672	
	Accessories	2nd Floor	159	SF	6	\$1,467	
	Accessories	2nd Floor	395	SF	6	\$3,643	
	Ceiling - Plaster/Drywall	2nd Floor	395	SF	6	\$1,367	
	Ceiling - Plaster/Drywall	2nd Floor	159	SF	6	\$550	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Transom Window	2nd Floor	18	SF	6	\$305	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	\$602	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor Drain	2nd Floor	1	EA	6	\$1,059	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	159	SF	6	\$337	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	395	SF	6	\$836	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	5	SF	5	\$104	tiles missing
	Hand Dryer	2nd Floor	2	EA	6	\$460	
	Hand Dryer	2nd Floor	2	EA	6	\$460	
	Lavatory	2nd Floor	2	EA	6	\$639	
	Lavatory	2nd Floor	2	EA	6	\$639	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	\$0	
	Lighting - Pendent/Surface	2nd Floor	3	EA	4	\$1,622	T12
	Partitions	2nd Floor	2	EA	6	\$594	
	Partitions	2nd Floor	5	EA	6	\$1,485	
	Urinals	2nd Floor	4	EA	6	\$1,344	
	Walls - Masonry	2nd Floor	370	SF	6	\$1,164	
	Walls - Masonry	2nd Floor	220	SF	6	\$692	
	Walls - Plaster/Drywall	2nd Floor	220	SF	6	\$607	
	Walls - Plaster/Drywall	2nd Floor	370	SF	6	\$1,021	
	Walls - Structural Glazed Tile	2nd Floor	100	SF	6	\$315	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	70	SF	6	\$158	

7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

roup Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
estroom						
Water Closet	2nd Floor	2	EA	6	\$672	
Water Closet	2nd Floor	5	EΑ	6	\$1,680	
Accessories	2nd- Teacher's Toilet in 221	77	SF	6	\$710	
Ceiling - Plaster/Drywall	2nd- Teacher's Toilet in 221	77	SF	6	\$266	
Doors - Wood Doors inclu hw	2nd- Teacher's Toilet in 221	1	EA	6	\$301	lock is broken
Floor - Tile Ceramic/ Porcelain	2nd- Teacher's Toilet in 221	77	SF	6	\$163	
Lavatory	2nd- Teacher's Toilet in 221	2	EΑ	6	\$639	
Lighting - Pendent/Surface	2nd- Teacher's Toilet in 221	2	EΑ	7	\$0	
Partitions	2nd- Teacher's Toilet in 221	1	EA	6	\$297	
Walls - Masonry	2nd- Teacher's Toilet in 221	231	SF	6	\$727	
Walls - Plaster/Drywall	2nd- Teacher's Toilet in 221	154	SF	6	\$425	
Water Closet	2nd- Teacher's Toilet in 221	2	EA	6	\$672	
Accessories	2nd- Women's RR	138	SF	6	\$1,273	
Ceiling - Plaster/Drywall	2nd- Women's RR	138	SF	6	\$478	
Doors - Wood Doors inclu hw	2nd- Women's RR	1	EA	6	\$301	
Floor - Tile Ceramic/ Porcelain	2nd- Women's RR	138	SF	6	\$292	
Lavatory	2nd- Women's RR	2	EA	6	\$639	
Lighting - Pendent/Surface	2nd- Women's RR	1	EΑ	7	\$0	
Partitions	2nd- Women's RR	1	EΑ	6	\$297	
Walls - Masonry	2nd- Women's RR	204	SF	6	\$642	
Walls - Plaster/Drywall	2nd- Women's RR	136	SF	6	\$375	
Walls - Structural Glazed Tile	2nd- Women's RR	130	SF	6	\$409	
Water Closet	2nd- Women's RR	2	EA	6	\$672	
Accessories	Boy's across from Auditorium	159	SF	6	\$1,467	
Ceiling - Plaster/Drywall	Boy's across from Auditorium	159	SF	6	\$550	
Doors - Transom Window	Boy's across from Auditorium	18	SF	6	\$305	
Doors - Wood Doors inclu hw	Boy's across from Auditorium	2	EA	6	\$602	
Floor Drain	Boy's across from Auditorium	1	EA	6	\$1,059	
Floor - Tile Ceramic/ Porcelain	Boy's across from Auditorium	159	SF	6	\$337	
Hand Dryer	Boy's across from Auditorium	2	EA	6	\$460	
Lavatory	Boy's across from Auditorium	2	EA	6	\$639	
Lighting - Pendent/Surface	Boy's across from Auditorium	3	EA	7	\$0	
Partitions	Boy's across from Auditorium	2	EA	6	\$594	
Urinals	Boy's across from Auditorium	1	EA	5	\$1,344	out of order
Urinals	Boy's across from Auditorium	3	EA	6	\$1,008	
Walls - Masonry	Boy's across from Auditorium	200	SF	6	\$629	
Walls - Plaster/Drywall	Boy's across from Auditorium	200	SF	6	\$552	



7831 S Prairie Ave Chicago, IL 60619

**Building: Main** 

**Category: Rooms (Other Than Classrooms)** 

Group Item - Type	Location	Quantity	Unit	Rank	Cost Comments
Restroom					
Walls - Structural Glazed Tile	Boy's across from Auditorium	110	SF	6	\$346
Water Closet	Boy's across from Auditorium	1	EA	6	\$336


Rooms (Other Than Classrooms) Subtotal:

\$762,491

**Building: Main** 

**Category: Building Interior** 

roup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
orrido	r						
	Ceiling - Lay-in	1st Floor	4,573	SF	6	\$13,733	
	Ceiling - Plaster/Drywall	1st Floor	484	SF	6	\$2,997	
	Doors - Side-lite	1st Floor	40	EA	6	\$669	
	Doors - Transom Window	1st Floor	56	EA	6	\$948	
	Doors - Wood Doors include hw	1st Floor	12	EA	6	\$3,612	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	6	\$1,103	
	Floor - Terrazzo	1st Floor	1,096	SF	6	\$9,200	
	Floor - Tile/Sheet	1st Floor	4,447	SF	6	\$2,416	
	Lighting - Lay-in	1st Floor	74	EA	7	\$0	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	\$0	
	Lighting - Wall Mounted	1st Floor	5	EA	7	\$0	
	Stairs - Terrazzo	1st Floor	8	LF	6	\$74	
	Student Lockers - One Tier	1st Floor	259	EA	5	\$36,300	
	Walls - Plaster/Drywall	1st Floor	10,128	SF	6	\$44,897	
	Walls - Structural Glazed Tile	1st Floor	1,584	SF	6	\$4,983	
	Walls - Tile Ceramic/ Porcelain	1st Floor	20	SF	6	\$63	
	Ceiling - Lay-in	2nd Floor	6,043	SF	6	\$18,147	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	6	\$1,103	
	Floor - Tile/Sheet	2nd Floor	10	SF	5	\$58	
	Floor - Tile/Sheet	2nd Floor	6,033	SF	6	\$3,278	
	Lighting - Lay-in	2nd Floor	68	EA	7	\$0	
	Student Lockers - One Tier	2nd Floor	324	EA	5	\$45,410	
	Walls - Plaster/Drywall	2nd Floor	7,509	SF	6	\$33,287	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	20	SF	6	\$63	
afety							
	Camera Viewing Station	1st Floor	2	EA	6	\$1,365	
	Metal Dedector	1st Floor	1	EA	6	\$881	





**Building: Main** 

**Category: Building Interior** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Safety							
	Security Cameras	1st Floor / Entire Building	6	EA	6	\$1,164	
	Security Cameras	1st Floor / Entire Building	6	EA	6	\$1,164	
Stairs							
	Ceiling - Lay-in	North East / 2nd Floor	241	SF	6	\$724	
	Floor - Terrazzo	North East	109	SF	6	\$915	
	Handrails	North East	62	LF	6	\$537	
	Lighting - Pendent/Surface	North East	2	EΑ	7	\$0	
	Stairs - Terrazzo	North East	28	LF	6	\$260	
	Walls - Plaster/Drywall	North East	967	SF	6	\$2,669	
	Ceiling - Lay-in	North / 2nd Floor	241	SF	6	\$724	
	Floor - Terrazzo	North	109	SF	6	\$915	
	Handrails	North	62	LF	6	\$537	
	Lighting - Pendent/Surface	North	2	EΑ	7	\$0	
	Stairs - Terrazzo	North	28	LF	6	\$260	
	Walls - Plaster/Drywall	North	967	SF	6	\$2,669	
	Ceiling - Lay-in	South / 2nd Floor	241	SF	6	\$724	
	Ceiling - Lay-in	South East / 2nd Floor	241	SF	6	\$724	
	Floor - Terrazzo	South East	109	SF	6	\$915	
	Handrails	South East	62	LF	6	\$537	
	Lighting - Pendent/Surface	South East	2	EA	7	\$0	
	Stairs - Terrazzo	South East	28	LF	6	\$260	
	Walls - Plaster/Drywall	South East	967	SF	6	\$2,669	
	Floor - Terrazzo	South	109	SF	6	\$915	
	Handrails	South	62	LF	6	\$537	
	Lighting - Pendent/Surface	South	2	EA	7	\$0	
	Stairs - Terrazzo	South	26	LF	6	\$241	
	Walls - Plaster/Drywall	South	967	SF	6	\$2,669	
Buildi	ng Interior Subtotal:				:	\$247,316	

zanamg mionor cabician


\$4,028,859

**Total Building Cost** 

**Building: Addition** 

**Category: Building Exterior** 

Group Item - Type Location Quantity Unit Rank Cost Comments





**Building: Addition** 

**Category: Building Exterior** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Entrand	ce						
	Exterior Doors - Exterior Steel Door	#7- NE	2	EA	6	\$961	
	Exterior Stairs - Concrete	#7- NE	20	LF	7	\$0	
	Exterior Stairs - Stone	#7- NE	6	LF	6	\$678	
	Ramp Handrail - Steel_Ramp Handrail	#7- NE	100	LF	6	\$867	
	Ramps - Concrete	#7- NE	50	LF	5	\$26,581	cracks & pitting
Founda	ation						
	Foundation - Concrete	Entire Building	325	LF	7	\$0	
	Superstructure - Concrete	Entire Building	11,500	SF	7	\$0	
Lightin	g						
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	2	EA	6	\$1,073	
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	\$1,155	
Roof S	ystem						
	Coping - Stone	Main Roof	325	LF	6	\$10,438	Some open joints
	Downspouts - Interior Downspouts	Main Roof	56	LF	6	\$1,861	
	Parapet - 16" - 30" Height	Main Roof	325	LF	6	\$12,985	
	Roof Structure - Concrete	Main Roof	5,500	SF	7	\$0	
	Roof - Modified Bitumen	Main Roof	5,500	SF	6	\$51,752	Some water ponding
Walls							
	Canopy - Concrete/ Stucco	Entire Building / East	85	SF	6	\$2,813	
	Cheek-Wall - Stone	Entire Building	18	SF	6	\$185	Door 7
	Exterior Walls - Brick	Entire Building	8,110	SF	6	\$54,507	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building / East	16	SF	5	\$104	rust & dents
	Exterior Walls - Stone-Cast	Entire Building	970	SF	6	\$6,519	
	Exterior Walls - Stone-Cast	Entire Building / North	5	SF	5	\$88	spalling
Windov	ws						
	Guard - Guards wire guard	Entire Building / 1st Floor	1,116	SF	6	\$14,251	
	Lintels - Steel	Entire Building	276	LF	6	\$8,012	
	Windows - Decorative	Entire Building / South	12	SF	6	\$90	
	Windows - Sash Lexan	Entire Building	1,860	SF	6	\$13,884	
						<b>***</b>	

**Building Exterior Subtotal:** 

\$208,803

**Building: Addition** 

**Category: Electrical System** 



7831 S Prairie Ave Chicago, IL 60619

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments				
Emergency System	mergency System									
Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	\$405	No Data Avaialble				
Exit Signs - Corridors and Stairs	Entire Building	4	EA	7	\$0	No Data Available				
Exit Signs - Lunchroom	Entire Building / 1st Floor	8	EA	7	\$0	No Data Available				
Security System - CCTV	Entire Building	11,500	SF	6	\$3,453					
Security System - Intrusion Detection	Entire Building	11,500	SF	6	\$2,960					
Main Service										
PA System	Entire Building	11,500	SF	6	\$3,782					
Power Distribution										
Lighting and Power Panels - Above 100 A	Entire Building / 1st Floor	1	EA	6	\$497					
Lighting and Power Panels - Above 100 A	Entire Building / 2nd Floor	1	EA	6	\$497					
Electrical System Subtotal:					\$11.595					

**Building: Addition** 

**Category: Safty System** 

Group Item - Type	Location	Quantity Unit Rank	Cost	Comments
Fire Alarm				
Fire Alarm Strobe Lights	Entire Building	11,500 SF 4	\$15,623	No Fire Alarm Strobes Lights installed in the Addition
Fire Alarm_System	Entire Building	11,500 SF 4	\$22,859	
Safty System Subtotal:			\$38,481	

**Building: Addition** 

**Category: Mechanical System** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments			
Air Han	ir Handling Systems									
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - Less than 8000 cfm	Basement / Mechanical Room	1	EA	5	\$24,083	serves north side - addition			
	Air Intake	Basement / Lower Roof	5	EA	6	\$28,823				
	Auxiliaries - Less than 8000 cfm	Basement / Mechanical Room	1	EA	6	\$3,321				
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement / Mechanical Room	5	EA	5	\$21,441				
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Basement / Entire Building	100	LF	6	\$0				
	Zone Dampers	Basement / Mechanical Room	13	EA	5	\$27,640				
/lechan	ical Plumbing									
	Condensate-Steel or Galvanized	Entire Building	200	LF	5	\$32,764				



7831 S Prairie Ave Chicago, IL 60619

**Building: Addition** 

**Category: Mechanical System** 

Group Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Temperature Control						
Pneumatic System	Entire Building	11,776	SF	4	\$61,296	
Thermostats - Pneumatic	Entire Building	18	EA	4	\$13,270	
Ventilation						
Exhaust Fans- Indoor - Less than 500 CFM	1st Floor, Lowe roof, 1st- Rm 151 Dining Hall & Kitchen / 1st Floor	1	EA	4	\$1,278	
Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	1st Floor, Lowe roof, 1st- Rm 151 Dining Hall & Kitchen / Lower Roof	1	EA	6	\$592	M#: L555180,, S#: GOBAZB0852, Order No: G65350-002A FX13BHFT, (Exterior Grease Trap is 3/4 Full & Should Be Cleaned)
Type I Exhaust Hood- Kitchen	1st Floor, Lowe roof, 1st- Rm 151 Dining Hall & Kitchen / 1st Floor	1	EA	6	\$1,248	
					<b>^</b>	

**Mechanical System Subtotal:** 

\$215,757

**Building: Addition** 

**Category: Plumbing System** 

Froup	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
lot Wat	ter						
	Electric Heater - 20 - 50 KW	Mechanical Room	1	EA	5	\$2,504	M#: ECS-40-200, S#: 1115A003760, 240V 1P 4500 Watts, 40 Gallon, 150 PSI.
	Gas Heater - Less than 150000 BTU/HR	1st Floor	1	EA	5	\$2,249	S#: RN-0896G0Z140, M#: G67-114, BTU/H 114,000, 67 Gallon, Power Vent HP = 1/4 RPM = 500 M#: 96-162381
Piping							
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	11,500	SF	6	\$2,302	No Data Available
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	11,500	SF	6	\$2,796	No Data Available
	Domestic Piping-Cold Water Risers	Entire Building	11,500	SF	6	\$2,138	No Data Available
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	11,500	SF	6	\$1,809	No Data Available
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	11,500	SF	6	\$2,138	No Data Available
	Domestic Piping-Hot Water Return Lines	Entire Building	11,500	SF	6	\$1,645	No Data Available
	Domestic Piping-Hot Water Return Risers	Entire Building	11,500	SF	6	\$1,645	No Data Available
	Sanitary Piping	Entire Building	11,500	SF	6	\$10,525	No Data Available
	Storm Piping	Entire Building	11,500	SF	6	\$10,031	No Data Available
	Vent Piping	Entire Building	11,500	SF	6	\$7,729	No Data Available
umps							
	Pumps - Sump-Duplex	Basement	2	EA	5	\$15,070	Power for one of the pumps is 50' orange extension cord plugged into a receptacle; (Location of Plug Point is: Air Chamber)



7831 S Prairie Ave Chicago, IL 60619

**Building: Addition** 

**Category: Plumbing System** 

Group Item - Type Location Quantity Unit Rank Cost Comments

Plumbing System Subtotal: \$62,580

**Building: Addition** 

om #100 (Lunch Room)						
Casework	1st Floor	13	LF	6	\$328	
Ceiling - Plaster/Drywall	1st Floor	10	SF	5	\$125	efflorescense
Ceiling - Plaster/Drywall	1st Floor	726	SF	6	\$2,512	
Chalk Board	1st Floor	40	LF	4	\$3,672	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	\$301	
Floor - Epoxy/ Painted	1st Floor	736	SF	6	\$389	epoxy ontop of VCT
Lighting - Pendent/Surface	1st Floor	14	EA	7	\$0	
Walls - Plaster/Drywall	1st Floor	1,065	SF	6	\$2,939	
Walls - Plaster/Drywall	1st Floor	25	SF	5	\$128	efflorescense
Work Sink	1st Floor	1	EA	6	\$379	
om #101 (Pre School)						
AC Units	1st Floor	2	EA	6	\$991	
Casework	1st Floor	65	LF	6	\$1,641	
Ceiling - Plaster/Drywall	1st Floor	1,276	SF	6	\$4,416	
Chalk Board	1st Floor	7	LF	4	\$643	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	\$602	
Floor - Carpet	1st Floor	567	SF	6	\$1,208	
Floor - Tile	1st Floor	709	SF	6	\$1,551	
Lighting - Pendent/Surface	1st Floor	23	EA	7	\$0	
Storage/ Closet	1st Floor	18	SF	6	\$131	
Walls - Plaster/Drywall	1st Floor	1,131	SF	6	\$3,121	
Work Sink	1st Floor	2	EA	6	\$758	1 in base cabinet / 1 wall hung lav
om #200 (Regular Classroom)						
Casework	2nd Floor	8	LF	6	\$202	
Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	\$125	peeling
Ceiling - Plaster/Drywall	2nd Floor	726	SF	6	\$2,512	
Chalk Board	2nd Floor	22	LF	4	\$2,020	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
Floor - Tile	2nd Floor	736	SF	6	\$1,610	
Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Ceiling - Plaster/Drywall Chalk Board Doors - Wood Doors inclu hw Floor - Epoxy/ Painted Lighting - Pendent/Surface Walls - Plaster/Drywall Walls - Plaster/Drywall Work Sink  Doom #101 (Pre School)  AC Units Casework Ceiling - Plaster/Drywall Chalk Board Doors - Wood Doors inclu hw Floor - Carpet Floor - Tile Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall Work Sink  Doom #200 (Regular Classroom)  Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Chalk Board Doors - Wood Doors inclu hw Floor - Tile	Ceiling - Plaster/Drywall 1st Floor Chalk Board 1st Floor Doors - Wood Doors inclu hw 1st Floor Floor - Epoxy/ Painted 1st Floor Lighting - Pendent/Surface 1st Floor Walls - Plaster/Drywall 1st Floor Work Sink 1st Floor  AC Units 1st Floor Casework 1st Floor Chalk Board 1st Floor Chalk Board 1st Floor Chalk Board 1st Floor Floor - Carpet 1st Floor Floor - Tile 1st Floor Storage/ Closet 1st Floor Walls - Plaster/Drywall 1st Floor Casework 2st Floor Floor - Tile 1st Floor Com #100 (Regular Classroom) Casework 2nd Floor Casework 2nd Floor Com #200 (Regular Classroom) Casework 2nd Floor Chalk Board 2nd Floor Com #200 (Regular Classroom) Casework 2nd Floor Casework 2nd Floor Chalk Board 2nd Floor Chalk Board 2nd Floor Casework 2nd Floor Com #200 (Regular Classroom) Casework 2nd Floor Chalk Board 2nd Floor Chalk Board 2nd Floor Doors - Wood Doors inclu hw 2nd Floor Floor - Tile 2nd Floor	Ceiling - Plaster/Drywall         1st Floor         726           Chalk Board         1st Floor         40           Doors - Wood Doors inclu hw         1st Floor         1           Floor - Epoxy/ Painted         1st Floor         736           Lighting - Pendent/Surface         1st Floor         14           Walls - Plaster/Drywall         1st Floor         25           Work Sink         1st Floor         25           Work Sink         1st Floor         2           AC Units         1st Floor         2           Casework         1st Floor         2           Casework         1st Floor         1,276           Chalk Board         1st Floor         7           Doors - Wood Doors inclu hw         1st Floor         7           Doors - Wood Doors inclu hw         1st Floor         2           Floor - Carpet         1st Floor         709           Lighting - Pendent/Surface         1st Floor         20           Storage/ Closet         1st Floor         18           Walls - Plaster/Drywall         1st Floor         1           Walls - Plaster/Drywall         1st Floor         1           Coework         2nd Floor         1 <t< td=""><td>Ceiling - Plaster/Drywall         1st Floor         726         SF           Chalk Board         1st Floor         40         LF           Doors - Wood Doors inclu hw         1st Floor         1         EA           Floor - Epoxyl Painted         1st Floor         736         SF           Lighting - Pendent/Surface         1st Floor         14         EA           Walls - Plaster/Drywall         1st Floor         25         SF           Work Sink         1st Floor         2         SF           Work Sink         1st Floor         2         EA           AC Units         1st Floor         2         EA           Casework         1st Floor         2         EA           Casework         1st Floor         5         LF           Casework         1st Floor         2         EA           Casework         1st Floor         7         LF           Doors - Wood Doors inclu hw         1st Floor         7         LF           Doors - Wood Doors inclu hw         1st Floor         567         SF           Floor - Carpet         1st Floor         2         EA           Floor - Tile         1st Floor         2         EA</td><td>  Ceiling - Plaster/Drywall</td><td>  Ceiling - Plaster/Drywall</td></t<>	Ceiling - Plaster/Drywall         1st Floor         726         SF           Chalk Board         1st Floor         40         LF           Doors - Wood Doors inclu hw         1st Floor         1         EA           Floor - Epoxyl Painted         1st Floor         736         SF           Lighting - Pendent/Surface         1st Floor         14         EA           Walls - Plaster/Drywall         1st Floor         25         SF           Work Sink         1st Floor         2         SF           Work Sink         1st Floor         2         EA           AC Units         1st Floor         2         EA           Casework         1st Floor         2         EA           Casework         1st Floor         5         LF           Casework         1st Floor         2         EA           Casework         1st Floor         7         LF           Doors - Wood Doors inclu hw         1st Floor         7         LF           Doors - Wood Doors inclu hw         1st Floor         567         SF           Floor - Carpet         1st Floor         2         EA           Floor - Tile         1st Floor         2         EA	Ceiling - Plaster/Drywall	Ceiling - Plaster/Drywall



7831 S Prairie Ave Chicago, IL 60619

**Building: Addition** 

	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
_	oom #200 (Regular Classroom)	Location	Quantity	O.III	Runk	0031	Communic
Giassi	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,060	SF	6	\$2,925	
	Walls - Plaster/Drywall	2nd Floor	30	SF	5		peeling & cracks
			00		-	ψ.50	1 <u>3 </u>
Classro	oom #201 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	\$0	
	Casework	2nd Floor	7	LF	6	\$177	
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	\$2,547	
	Chalk Board	2nd Floor	44	LF	4	\$4,039	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	736	SF	6	\$1,610	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	8	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	941	SF	6	\$2,597	
	Wireless System	2nd Floor	1	EA	6	\$372	
Classro	oom #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	6	\$496	
	Casework	2nd Floor	8	LF	6	\$202	
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	\$2,547	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	736	SF	6	\$1,610	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	\$3,008	
Classro	oom #203 (Regular Classroom)						
	Casework	2nd Floor	7	LF	6	\$177	
	Ceiling - Plaster/Drywall	2nd Floor	738	SF	6	\$2,554	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	\$301	
	Floor - Tile	2nd Floor	738	SF	6	\$1,615	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	22	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	935	SF	6	\$2,581	
Classro	oom #204 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	\$2,547	
	Chalk Board	2nd Floor	12	LF	4	\$1,102	
	Doors	2nd Floor	1		6	\$0	

7831 S Prairie Ave Chicago, IL 60619

**Building: Addition** 

**Category: Classrooms** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Classro	om #204 (Regular Classroom)						
	Floor - Tile	2nd Floor	1	SF	5	\$6	missing
	Floor - Tile	2nd Floor	735	SF	6	\$1,608	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Marker Board	2nd Floor	32	LF	7	\$0	
	Walls - Plaster/Drywall	2nd Floor	8	SF	5	\$41	peeling
	Walls - Plaster/Drywall	2nd Floor	1,082	SF	6	\$2,986	
	Work Sink	2nd Floor	1	EA	6	\$379	faucet is leaking

Classrooms Subtotal: \$71,388

**Building: Addition** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Locker	Shower Room						
	Accessories	1st- Kitchen Help Locker Rm/Office	116	SF	6	\$455	
	Ceiling - Plaster/ Drywall	1st- Kitchen Help Locker Rm/Office	116	SF	6	\$401	
	Doors - Wood Doors inclu hw	1st- Kitchen Help Locker Rm/Office	1	EA	6	\$301	
	Floor - Tile/Sheet	1st- Kitchen Help Locker Rm/Office	116	SF	6	\$116	
	Lavatory	1st- Kitchen Help Locker Rm/Office	1	EA	6	\$320	
	Lighting - Pendent/Surface	1st- Kitchen Help Locker Rm/Office	1	EA	7	\$0	
	Lighting - Pendent/Surface	1st- Kitchen Help Locker Rm/Office	1	EA	6	\$124	has a broken cover
	Lighting - Wall Mounted	1st- Kitchen Help Locker Rm/Office	1	EA	7	\$0	
	Walls - Plaster/Drywall	1st- Kitchen Help Locker Rm/Office	511	SF	6	\$1,410	
	Water Closet	1st- Kitchen Help Locker Rm/Office	1	EA	6	\$336	
Lunch	& Multipurpose Room						
	Ceiling - Plaster/Drywall	1st- Rm 151 Dining Hall & Kitchen	286	SF	6	\$990	
	Ceiling - Splined	1st- Rm 151 Dining Hall & Kitchen	1,098	SF	6	\$895	
	Doors - Wood Doors inclu hw	1st- Rm 151 Dining Hall & Kitchen	2	EA	6	\$602	
	Floor - Tile	1st- Rm 151 Dining Hall & Kitchen	12	SF	5	\$54	damaged
	Floor - Tile Ceramic/ Porcelain	1st- Rm 151 Dining Hall & Kitchen	1,372	SF	6	\$2,904	
	Lighting - Pendent/Surface	1st- Rm 151 Dining Hall & Kitchen	25	EA	7	\$0	
	Serving Line	1st- Rm 151 Dining Hall & Kitchen	17	LF	6	\$1,012	
	Storage/ Closet	1st- Rm 151 Dining Hall & Kitchen	117	SF	6	\$848	
	Walls - Plaster/Drywall	1st- Rm 151 Dining Hall & Kitchen	1,175	SF	6	\$3,243	
	Walls - Structural Glazed Tile	1st- Rm 151 Dining Hall & Kitchen	575	SF	6	\$1,809	



7831 S Prairie Ave Chicago, IL 60619

**Building: Addition** 

**Category: Rooms (Other Than Classrooms)** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Mechar	ical/ Service Rooms						
	Janitor's Closet	1st Floor	16	SF	6	\$115	bad odor
	Air Tunnel	Basement	1,191	SF	6	\$7,375	
	Crawl Space - Unfinished	Basement	3,647	SF	6	\$22,582	
	Interior Stairs	Basement	10	LF	6	\$90	
	Mechanical/ Service Rooms	Basement	495	SF	6	\$3,546	
Restro	om						
	Accessories	1st - inside 101	20	SF	6	\$184	
	Ceiling - Plaster/Drywall	1st - inside 101	20	SF	6	\$69	
	Doors - Wood Doors inclu hw	1st - inside 101	1	EΑ	6	\$301	
	Floor - Tile	1st - inside 101	20	SF	6	\$44	
	Lighting - Lay-in	1st - inside 101	1	EΑ	7	\$0	
	Walls - Plaster/Drywall	1st - inside 101	149	SF	6	\$411	
	Water Closet	1st - inside 101	1	EA	6	\$336	

Rooms (Other Than Classrooms) Subtotal:

\$50,872

**Building: Addition** 

**Category: Building Interior** 

Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
or						
Ceiling - Lay-in	1st Floor	966	SF	6	\$2,901	
Ceiling - Plaster/Drywall	1st Floor	66	SF	6	\$409	
Doors - Wood Doors include hw	1st Floor	2	EΑ	6	\$602	
Drinking Fountains - Double Fountain	1st Floor	1	EΑ	6	\$336	
Floor - Terrazzo	1st Floor	174	SF	6	\$1,461	
Floor - Tile Ceramic/ Porcelain	1st Floor	66	SF	6	\$184	
Floor - Tile/Sheet	1st Floor	858	SF	6	\$466	
Lighting - Lay-in	1st Floor	12	EA	7	\$0	
Lighting - Pendent/Surface	1st Floor	2	EA	7	\$0	
Student Lockers - One Tier	1st Floor	70	EA	5	\$9,811	
Walls - Plaster/Drywall	1st Floor	1,041	SF	6	\$4,615	
Walls - Structural Glazed Tile	1st Floor	1,041	SF	6	\$3,275	
Ceiling - Lay-in	2nd Floor	966	SF	6	\$2,901	
Drinking Fountains - Double Fountain	2nd Floor	1	EA	6	\$336	
Floor - Terrazzo	2nd Floor	29	SF	6	\$243	
Floor - Tile/Sheet	2nd Floor	966	SF	6	\$525	



7831 S Prairie Ave Chicago, IL 60619

**Building: Addition** 

**Category: Building Interior** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Corrido	or						
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	\$0	
	Stairs - Terrazzo	2nd Floor	4	LF	6	\$37	
	Student Lockers - One Tier	2nd Floor	68	68 EA	5	\$9,530	
	Walls - Plaster/Drywall	2nd Floor	714	SF	6	\$3,165	
	Walls - Structural Glazed Tile	2nd Floor	714	SF	6	\$2,246	
Safety							
	Security Cameras	Entire Building	3	EA	6	\$582	
Stairs							
	Ceiling - Plaster/Drywall	East / 2nd Floor	215	SF	6	\$1,574	
	Floor - Terrazzo	East	76	SF	6	\$638	
	Handrails	East	51	LF	6	\$442	
	Lighting - Pendent/Surface	East	2	EA	7	\$0	
	Stairs - Terrazzo	East	19	LF	6	\$176	
	Walls - Plaster/Drywall	East	381	SF	6	\$1,052	
	Walls - Structural Glazed Tile	East	381	SF	6	\$1,199	
<del></del>	ing Intorior Cultotal					¢40.700	

Building Interior Subtotal: \$48,706

Total Building Cost \$708,184

SITE

**Category: Site** 

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
Athletic	;						
	Surface - Asphalt	South	8,400	SF	6	\$20,300	no backboards
	Surface - Asphalt	South	13,500	SF	5	\$61,583	water ponding & cracks
Civil/Dr	rainage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	\$6,563	
	Civil/ Drainage - Site Manhole	Entire Site	12	EA	6	\$17,913	
Fencing	g						
	Fencing - Chain Link	Entire Site / South	200	LF	6	\$3,755	
	Fencing - New Standard Ornamental	Entire Site	1,650	LF	6	\$52,640	NE at parking lot & South
	Fencing - New Standard Ornamental	Entire Site / South East	5	LF	5	\$0	bent
	Fencing - Old Standard Ornamental	Entire Site / West	658	LF	6	\$34,062	



7831 S Prairie Ave Chicago, IL 60619

#### SITE

Category: Site

Group	Item - Type	Location	Quantity	Unit	Rank	Cost	Comments
encin	3						
	Fencing - Old Standard Ornamental	Entire Site / West	5	LF	5	\$835	door is off, rusted hinges
Landsc	ape						
	Benches	Entire Site / South	6	EA	6	\$2,580	
	Irrigation	Entire Site / South	37,500	SF	5	\$100,815	South Campus Pk not in use
	Landscape - Grass	Entire Site	92,580	SF	6	\$76,786	
	Parkway trees	Entire Site	50	EA	6	\$33,002	
	Play Area - Asphalt/ Hardscape	Entire Site / South	7,480	SF	6	\$18,077	Concrete
	Trash Receptacles	Entire Site / South	6	EA	6	\$1,874	
	Walking Path - Asphalt	Entire Site / South	20	SF	5	\$138	Door 9- cracks & movement
	Walking Path - Asphalt	Entire Site / South	20	SF	4	\$234	Door 8- Movement, cracks, deterioration
Parking	Lot						
	Concrete Curbs	NE Lot	780	LF	6	\$10,016	
	Interior Plantings	NE Lot	7,280	LF	6	\$309,709	
	Lighting - Pole Mounted	NE Lot / South	6	EA	6	\$8,715	
	Surface - Asphalt	NE Lot	18,830	SF	6	\$45,506	
	Surface - Concrete	NE Lot	1,730	SF	5	\$16,179	
	Trash Enclosure - Chain Links	NE Lot / East	470	SF	6	\$8,247	
	Trash Enclosure - Chain Links	NE Lot / North	350	SF	6	\$6,141	
	Vehicular Screening	NE Lot	40	LF	5	\$5,696	sparse
Playgro	ound						
	Equipment - Combo 3-12	South	1	EA	6	\$7,092	
	Equipment - Pre K 3-5	North	1	EA	6	\$3,546	
	Surface - Poured Surface	North	1,810	SF	6	\$13,252	
	Surface - Square Rubber Mats	South	3,690	SF	6	\$19,893	
Sidewa	lks						
	Sidewalks - Internal Walks	Entire Site	100	LF	5	\$5,777	Doors 1, 2 & 5: cracks, movement, pitting or deterioration
	Sidewalks - Internal Walks	Entire Site	1,510	LF	6	\$18,138	
	Sidewalks - Perimeter Sidewalks	Entire Site	21,210	SF	6	\$42,159	
	Sidewalks - Perimeter Sidewalks	Entire Site / South	50	SF	5	\$478	Movement
	Sidewalks - Perimeter Sidewalks	Entire Site / South West	150	SF	5	\$1,433	Cracks
Signag	e						
	Flag Pole - Building Mounted Flag Pole	West, south and southwest / West	1	EA	6	\$828	
	Marquee - Free Standing Back Lighted	West, south and southwest / West	1	EA	6	\$0	
	Monument - Building Mounted Cut Letter Sign	West, south and southwest	2	EA	6	\$0	South & SouthWest



7831 S Prairie Ave Chicago, IL 60619

#### SITE

Category: Site

Group Item - Type	Location	Quantity Unit Rank Cost	Comments
Signage			
Site Subtotal:		\$953,964	
Total Site Cost		\$953,964	

Campus Total <sup>2 3</sup> \$5,691,006

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding: these are viewed as separate capital needs.

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

<sup>&</sup>lt;sup>2</sup> As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

<sup>&</sup>lt;sup>3</sup> The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.



Regular Classroom

Regular Classroom

Regular Classroom

Regular Classroom

Regular Classroom

Regular Classroom

2nd Floor

2nd Floor

2nd Floor

## **Martha Ruggles Elementary School**

7831 S Prairie Ave Chicago, IL 60619

#### **Classroom Summary**

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main			!					"			•			
Kindergarten	Kindergarten	1st Floor	106B	106	831	1	3	20	125	36	40			
Kindergarten	Kindergarten	1st Floor	111	111	988	4	1	17	182	91	40		Υ	
Regular Classroom	Regular Classroom	1st Floor	105	105	762	1	2	9	130	65	40		Υ	
Regular Classroom	Regular Classroom	1st Floor	107	107	692	1	2	15	130	65	40		Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	108	108	736	1	3	21	90	39	40			
Regular Classroom	Regular Classroom	1st Floor	110	110	736	1	3	30	90	39	40			Υ
Regular Classroom	Regular Classroom	1st Floor	113	113	732	1	2	47	130	26	40		Υ	
Regular Classroom	Regular Classroom	2nd Floor	205	205	701	2	2	20	130	65	40		Υ	
Regular Classroom	Regular Classroom	2nd Floor	206	206	736	1	2	17	90	39	40			Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	729	2	2	14	130	65	40		Υ	
Regular Classroom	Regular Classroom	2nd Floor	208	208	558	2	2	27	63	23	40			
Regular Classroom	Regular Classroom	2nd Floor	209	209	732	2	2	10	130	65	40		Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	736	2	2	18	90	39	40			Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	736	1	2	18	90	39	40			
Regular Classroom	Regular Classroom	2nd Floor	214	214	736	1	2	18	90	39	40			Υ
Regular Classroom	Regular Classroom	2nd Floor	215	215	729	1	2	11	130	65	40			
Regular Classroom	Regular Classroom	2nd Floor	216	216	514	1	2	22	116	58	40	N	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	734	1	2	12	130	65	40			
Store Room	Regular Classroom	1st Floor	102	102	736	1	2	18	81	32	40			
Addition														
Computer Lab	Regular Classroom	2nd Floor	201	201	736	20	3	66	156	78	40		Υ	Υ
Lunch Room	Regular Classroom	1st Floor	100	100	736	1	2	19	126	57	40			
Pre School	Kindergarten	1st Floor	101	101	1,276	1	2	5	312	156	40			
Regular Classroom	Regular Classroom	2nd Floor	200	200	736	1	2	23	126	57	40			

Υ