1420 S Albany Ave Chicago, IL 60623

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1963 | 4 | 56,581 | \$2,753,852 |
| CPC | 1972 | 1 | 14,841 | \$1,817,987 |
| SITE | | | | \$431,593 |
| Campus Total | | | 71,422 | \$5,003,432 |

Building: Main

| | ory. Building Exterior | | • ••• | | | • • | • |
|---------|--------------------------------------|-------------------------------|----------|------|------|---------|----------|
| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Entrand | e | | | | | | |
| | Entrance Control - Audio and Video | #1- Main Accessible- E / East | 1 | EA | 6 | \$702 | |
| | Exterior Doors - Exterior FRP Door | #1- Main Accessible- E / East | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | #10- SW / South West | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | #11- S / South | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | #12- E / East | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | #13- SE / South East | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | #2- NE / North East | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | #3- NE / North East | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | #4- NE / North East | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | #5- NE | 1 | EA | 6 | \$631 | |
| | Exterior Doors - Exterior FRP Door | #6- NW / North West | 1 | EA | 6 | \$631 | |
| | Exterior Doors - Exterior FRP Door | #7- NW / North West | 1 | EA | 6 | \$631 | |
| | Exterior Doors - Exterior FRP Door | #8- W / West | 1 | EA | 6 | \$631 | |
| | Exterior Doors - Exterior FRP Door | #9- SW / South West | 1 | EA | 6 | \$631 | |
| | Exterior Doors - Exterior FRP Door | Boiler Room- NW / North West | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior Steel Door | #6.5- NW / North West | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | #8.5- W / West | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Side lite | #10- SW / South West | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Side lite | #11- S / South | 2 | EA | 6 | \$627 | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| | tom - Type | Location | Ouantitu | Heit | Dank | Cast | Comments |
|-------|--|--|----------|------|------|----------------|----------|
| | Item - Type | Location | Quantity | Unit | rank | COST | Comments |
| ntran | Exterior Doors - Transom Lite | #1- Main Accessible- E / East | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite Exterior Doors - Transom Lite | #1- Main Accessible- E / East #12- E / East | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite Exterior Doors - Transom Lite | #12- E / East #13- SE / South East | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | #2- NE / North East | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | #3- NE / North East | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite Exterior Doors - Transom Lite | #4- NE / North East | 1 | EA | 6 | | |
| | Exterior Doors - Transom Lite Exterior Doors - Transom Lite | #4- NE / North East #5- NE | 1 | EA | 6 | \$313 \$313 | |
| | Exterior Doors - Transom Lite | #6- NW / North West | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite Exterior Doors - Transom Lite | #6- NW / North West | 1 | EA | 6 | | |
| | Exterior Doors - Transom Lite Exterior Doors - Transom Lite | #8.5- W / West | - | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite Exterior Doors - Transom Lite | #9- SW / South West | 1 | EA | 6 | \$313 \$940 | |
| | | | 3 | | | | |
| | Exterior Stairs - Concrete | #11- S / South | 24 | LF | 6 | \$1,962 | Openius |
| | Exterior Stairs - Concrete | #4- NE / North East | 60 | LF | 5 | | Cracks |
| | Power Door Operator and Controls | #1- Main Accessible- E / East | 1 | EA | 6 | \$0 | |
| unda | ation | | | | | | |
| | Foundation - Concrete | Entire Building | 787 | LF | 7 | \$0 | |
| | Superstructure - Concrete | Entire Building | 56,581 | SF | 7 | \$0 | |
| ghtin | ng | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 6 | EA | 6 | \$3,219 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 18 | EA | 6 | \$5,197 | |
| of S | system | | | | | | |
| | Chimney - Metal Flue | Main Roof | 62 | LF | 6 | \$9,805 | |
| | Chimney - Metal Flue | Main Roof | 62 | LF | 6 | \$9,805 | |
| | Chimney - Metal Flue | Main Roof | 62 | LF | 6 | \$9,805 | |
| | Coping - Metal | Low NE roof | 420 | LF | 6 | \$13,489 | |
| | Coping - Metal | Low S roof | 287 | LF | 6 | \$9,218 | |
| | Coping - Metal | Low SE roof | 54 | LF | 6 | \$1,734 | |
| | Coping - Metal | Main Roof / Main Roofs | 516 | LF | 6 | \$16,573 | |
| | Downspouts - Interior Downspouts | Low NE roof | 49 | LF | 6 | \$1,628 | |
| | Downspouts - Interior Downspouts | Low S roof | 45 | LF | 6 | \$1,495 | |
| | Downspouts - Interior Downspouts | Low SE roof | 49 | LF | 6 | \$1,628 | |
| | Downspouts - Interior Downspouts | Main Roof | 275 | LF | 6 | \$9,139 | |
| | Roof Structure - Concrete | Low NE roof | 420 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | Low S roof | 4,960 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | Low SE roof | 420 | SF | 7 | \$0 | |
| | | | | | | | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| Walls Ca Ca Ca Ca Ca Ca Ca Ext Ext | conf - Asphalt Gravel Ballast coof - Asphalt Gravel Ballast canopy - Concrete/ Stucco | Low NE roof Low S roof Low SE roof Main Roof Entire Building Entire Building Entire Building Entire Building Entire Building | 420 4,960 420 11,860 | SF SF SF SF | 5 6 5 5 | \$50,430 \$9,916 \$280,006 | blisters blisters blisters severely blistered |
|---|---|---|-------------------------------|----------------------|------------------|----------------------------------|--|
| Ro Ro Ro Walls Ca Ca Ca Ca Ca Ext Ext | coof - Asphalt Gravel Ballast canopy - Concrete/ Stucco | Low S roof Low SE roof Main Roof Entire Building Entire Building Entire Building Entire Building Entire Building | 4,960 420 11,860 16 | SF SF SF | 6 5 5 | \$50,430 \$9,916 \$280,006 | blisters blisters |
| Roca Roca Caca Caca Caca Caca Caca Caca Caca C | coof - Asphalt Gravel Ballast coof - Asphalt Gravel Ballast canopy - Concrete/ Stucco | Low SE roof Main Roof Entire Building Entire Building Entire Building Entire Building | 420 11,860 16 | SF SF | 5 5 | \$9,916 \$280,006 | blisters |
| Ro Walls Ca Ca Ca Ca Ca Ca Ca Ext Ext | anopy - Concrete/ Stucco | Main Roof Entire Building Entire Building Entire Building Entire Building | 11,860 16 16 | SF | 5 | \$280,006 | |
| Walls Ca Ca Ca Ca Ca Ca Ca Ca Ext Ext | anopy - Concrete/ Stucco | Entire Building Entire Building Entire Building Entire Building | 16 16 | | | | severely blistered |
| Ca Ca Ca Ca Ca Ext Ext | anopy - Concrete/ Stucco | Entire Building Entire Building Entire Building | 16 | SF | 5 | | |
| Ca Ca Ca Ca Ca Ext Ext | anopy - Concrete/ Stucco | Entire Building Entire Building Entire Building | 16 | SF | 5 | | |
| Ca Ca Ca Ca Ca Ext Ext Ext | anopy - Concrete/ Stucco | Entire Building Entire Building Entire Building | | | J | \$2,352 | spalling |
| Cal Cal Cal Ext Ext Ext | anopy - Concrete/ Stucco anopy - Concrete/ Stucco anopy - Concrete/ Stucco | Entire Building | | SF | 5 | | spalling |
| Cal Cal Cal Ext Ext Ext | anopy - Concrete/ Stucco anopy - Concrete/ Stucco anopy - Concrete/ Stucco | · · | 103 | SF | 5 | \$15,143 | spalling |
| Ca Ca Ca Ext Ext Ext | anopy - Concrete/ Stucco anopy - Concrete/ Stucco | ŭ | 225 | SF | 5 | | spalling, cracks |
| Ca Ca Ext Ext Ext | anopy - Concrete/ Stucco | Entire Building | 16 | SF | 6 | \$712 | , 3 |
| Ca Ext Ext Ext | 17 | Entire Building | 103 | SF | 6 | \$4,581 | |
| Ext Ext Ext | allopy - Colliciate/ Stucco | Entire Building | 2,030 | SF | 6 | \$67,173 | |
| Ext Ext | kterior Walls - Brick | Entire Building | 10 | SF | 5 | \$238 | missing mortar at wall base |
| Ext | kterior Walls - Brick | Entire Building | 40 | SF | 5 | \$952 | missing mortar at wall base |
| | terior Walls - Brick | Entire Building | 15 | SF | 5 | \$357 | missing mortar at wall base |
| | kterior Walls - Brick | Entire Building | 10 | SF | 5 | \$238 | missing mortar at wall base |
| Ext | kterior Walls - Brick | Entire Building | 20 | SF | 5 | \$476 | missing mortar at wall base |
| Ext | kterior Walls - Brick | Entire Building | 10 | SF | 5 | \$238 | missing mortar at wall base |
| Ext | kterior Walls - Brick | Entire Building | 10 | SF | 5 | \$238 | missing mortar at wall base |
| Ext | kterior Walls - Brick | Entire Building | 16,284 | SF | 6 | \$109,445 | open joints |
| Ext | kterior Walls - Brick | Entire Building / Façade- NE | 240 | SF | 5 | \$5,714 | movement, open joints |
| Ext | kterior Walls - Brick | Entire Building / North Façade | 240 | SF | 4 | \$39,516 | movement, open joints |
| Ext | kterior Walls - Brick | Entire Building / South Façade | 240 | SF | 4 | \$39,516 | movement, open joints |
| Ext | kterior Walls - Brick | Entire Building / West Façade | 300 | SF | 6 | \$2,724 | |
| Ext | kterior Walls - Brick | Entire Building / West Façade | 240 | SF | 5 | \$5,714 | movement, open joints |
| Ext | kterior Walls - Concrete Block | Entire Building | 6 | SF | 5 | \$67 | spalling |
| Ext | kterior Walls - Concrete Block | Entire Building | 1,020 | SF | 5 | \$8,445 | spalling, cracks |
| Ext | kterior Walls - Concrete Block | Entire Building | 4 | SF | 5 | \$45 | spalling |
| Ext | kterior Walls - Concrete Block | Entire Building | 720 | SF | 5 | \$7,125 | spalling |
| Ext | kterior Walls - Stone-Cast | Entire Building | 6 | SF | 4 | \$1,090 | chipped and missing sill |
| Ext | kterior Walls - Stone-Cast | Entire Building | 3 | SF | 5 | \$53 | cracked |
| Ext | terior Walls - Stone-Cast | Entire Building | 138 | SF | 6 | \$927 | |
| Windows | | | | | | | |
| | erestory - Glass Double-Pane | Entire Building / 1st Floor | 288 | SF | 6 | \$2,698 | |
| | | • | | | | Ψ=,000 | |
| Cu | urtain wall - Glazed Double Pane | Entire Building | 132 | SF | 5 | \$8,821 | rust |



1420 S Albany Ave Chicago, IL 60623

Building: Main

Category: Building Exterior

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|----------|------|------|----------|----------|
| Windows | | | | | | |
| Curtain wall - Louver | Entire Building | 192 | SF | 6 | \$2,153 | |
| Guard - Guards perforated | Entire Building / 1st Floor | 1,495 | SF | 6 | \$19,091 | |
| Lintels - Steel | Entire Building | 50 | LF | 6 | \$1,451 | |
| Windows - Casement Aluminum Double-pane | Entire Building | 6,115 | SF | 6 | \$45,646 | |
| | | | | | | |

Building Exterior Subtotal:

\$924,619

Building: Main

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|-----------------------------------|----------|------|------|----------|-------------------|
| Emerge | ency System | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | \$408 | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 12,347 | SF | 6 | \$3,708 | |
| | Emergency A/C Power - Gym | Entire Building / 1st Floor | 3,242 | SF | 6 | \$1,205 | |
| | Emergency A/C Power - Lunchrooms | Entire Building / 1st Floor | 2,668 | SF | 6 | \$992 | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 51 | EA | 6 | \$10,328 | |
| | Emergency Battery Packs - Gym | Entire Building / 1st Floor | 7 | EA | 6 | \$1,418 | |
| | Emergency Battery Packs - Lunchrooms | Entire Building / 1st Floor | 2 | EA | 6 | \$405 | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 8 | EA | 6 | \$1,620 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 24 | EA | 6 | \$3,594 | |
| | Exit Signs - Gym | Entire Building / 1st Floor | 4 | EA | 6 | \$630 | |
| | Exit Signs - Lunchroom | Entire Building / 1st Floor | 4 | EA | 6 | \$599 | |
| | Security System - CCTV | Entire Building | 56,581 | SF | 6 | \$16,991 | |
| | Security System - Intrusion Detection | Entire Building | 56,581 | SF | 6 | \$14,564 | |
| Main S | ervice | | | | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | \$2,921 | |
| | Main Electrical Service - 1200 A 120/208/3PH | Electrical Room | 1 | EA | 4 | \$39,073 | |
| | PA System | Entire Building | 56,581 | SF | 6 | \$18,609 | |
| Power | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building / 3rd Floor | 1 | EA | 6 | \$299 | Location: Library |
| | Lighting and Power Panels - 100 A | Entire Building / Electrical Room | 1 | EA | 4 | \$4,849 | Fused EM panel |
| | Lighting and Power Panels - 100 A | Entire Building | 13 | EA | 6 | \$3,888 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Boiler Room | 1 | EA | 6 | \$528 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Boiler Room | 1 | EA | 6 | \$528 | |
| | | | | | | | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

Category: Electrical System

Group Item - Type Location Quantity Unit Rank Cost Comments

Electrical System Subtotal: \$127,157

Building: Main

Category: Safty System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------|-------------------------------|----------|------|------|-----------|---|
| Fire Alarm | | | | | | |
| Fire Alarm Panel | Boiler Room | 1 | EA | 6 | \$6,406 | Location: Engineers office. 2nd 4010 panel in elevator equipment room |
| Fire Alarm Strobe Lights | Boiler Room / Entire Building | 56,581 | SF | 4 | \$76,865 | Horns and bells only |
| Fire Alarm_System | Boiler Room / Entire Building | 56,581 | SF | 4 | \$112,466 | |

Safty System Subtotal: \$195,737

Building: Main

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|-----------------------------|----------|------|------|-----------|---------------------------------|
| Air Han | lling Systems | | | | | | |
| | Air Handling Unit- Package Multi Zone- Indoor- Hot Water and Chilled Water Coils - 6000-10000 cfm | Entire Building / 1st Floor | 1 | EA | 5 | \$42,727 | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 4000-8000 cfm | Entire Building | 1 | EA | 6 | \$3,350 | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm | Entire Building | 6 | EA | 5 | \$122,239 | |
| | Air Intake | Entire Building / 1st Floor | 1 | EA | 6 | \$5,765 | |
| | Air Intake | Entire Building | 6 | EA | 6 | \$34,588 | Air intakes at each floor level |
| | Air Intake | Entire Building | 1 | EA | 6 | \$5,765 | |
| | Auxiliaries - 4000-8000 cfm | Entire Building | 1 | EA | 6 | \$0 | |
| | Auxiliaries - 6000-10000 cfm | Entire Building / 1st Floor | 1 | EA | 6 | \$0 | |
| | Auxiliaries - Less than 4000 cfm | Entire Building | 6 | EA | 6 | \$0 | |
| | Zone Dampers | Entire Building | 5 | EA | 6 | \$4,165 | |
| Boiler S | ystems | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 2001 - 3000 MBH | Boiler Room | 2 | EA | 5 | \$120,265 | |
| | Chemical Pot Feeder | Boiler Room | 1 | EA | 5 | \$1,685 | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | \$818 | |
| | Glycol Feed System | Boiler Room | 1 | EA | 6 | \$539 | |
| | Non Condensing- Scotch Marine- Hot Water Boiler $$ - 3001 - 4000 MBH $$ | Boiler Room | 2 | EA | 5 | \$163,160 | Gas gun S10-G-20 2003 |



1420 S Albany Ave Chicago, IL 60623

Building: Main

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|-----------------------------|----------|------|------|-----------|--------------------------|
| Heating | Devices | | | | | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 11 | EA | 5 | \$19,303 | |
| | Fin Tube - Hot Water | Entire Building | 550 | LF | 6 | \$5,191 | |
| Mechan | ical Plumbing | | | | | | |
| | Hot Water Pump - Less than 10 | Boiler Room | 1 | EA | 5 | \$11,495 | Separate one for kitchen |
| | Hot Water Pump - Less than 10 | Boiler Room | 3 | EA | 5 | \$34,484 | For building |
| | Hydronic Supply and Return - Steel | Entire Building | 800 | LF | 6 | \$61,421 | |
| Temper | ature Control | | | | | | |
| | DDC System | Entire Building | 1 | SF | 6 | \$1 | |
| | Thermostats - DDC | Entire Building | 7 | EA | 6 | \$0 | |
| Unit Ver | ntilation | | | | | | |
| | Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only | Entire Building | 28 | EA | 6 | \$34,936 | |
| Ventilat | ion | | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 11 | EA | 6 | \$6,516 | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 3 | EA | 6 | \$1,777 | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building / 1st Floor | 2 | EA | 6 | \$1,840 | |
| Mecha | nical System Subtotal: | | | | , | \$682,032 | |

Building: Main

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------------------------|----------|------|------|----------|----------|
| Hot Wat | er | | | | | | |
| | Gas Heater - 300001 - 600000 BTU/HR | Boiler Room | 1 | EA | 5 | \$2,249 | |
| | Hot Water Storage Tank_Gas - 201 - 500 Gallons | Boiler Room | 1 | EA | 5 | \$2,249 | |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 56,581 | SF | 6 | \$11,328 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 56,581 | SF | 6 | \$13,755 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 56,581 | SF | 6 | \$10,518 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 56,581 | SF | 6 | \$8,900 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 56,581 | SF | 6 | \$10,518 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 56,581 | SF | 6 | \$8,091 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building / Electrical Room | 56,581 | SF | 6 | \$8,091 | |
| | Sanitary Piping | Entire Building | 56,581 | SF | 6 | \$51,783 | |
| | Storm Piping | Entire Building | 56,581 | SF | 6 | \$49,356 | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------------|-----------------|----------|------|------|----------|------------|
| Piping | | | | | | | |
| | Vent Piping | Entire Building | 56,581 | SF | 6 | \$38,028 | |
| Pumps | | | | | | | |
| | Pumps - Domestic Booster Pump-Simplex | Boiler Room | 1 | EA | 6 | \$1,446 | Cold water |
| | Pumps - Ejector-Duplex | Boiler Room | 1 | EA | 5 | \$7,535 | |
| | Pumps - Sump-Simplex | Boiler Room | 1 | EA | 5 | \$5,627 | |

Plumbing System Subtotal:

\$229,474

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|-------------|
| Classro | om #201/ 202 (Music Room) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 6 | \$991 | |
| | Casework | 2nd Floor | 35 | LF | 6 | \$884 | |
| | Ceiling - Lay-in | 2nd Floor | 1,628 | SF | 6 | \$4,889 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 212 | SF | 6 | \$734 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | 2nd Floor | 1,840 | SF | 6 | \$1,842 | |
| | Lighting - Lay-in | 2nd Floor | 27 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 32 | LF | 6 | \$685 | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 6 | \$145 | |
| | Walls - Masonry | 2nd Floor | 295 | SF | 6 | \$928 | Brick walls |
| | Walls - Plaster/Drywall | 2nd Floor | 885 | SF | 6 | \$2,443 | |
| | Work Sink | 2nd Floor | 2 | EA | 6 | \$758 | |
| Classro | oom #203 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 10 | LF | 6 | \$253 | |
| | Ceiling - Lay-in | 2nd Floor | 779 | SF | 6 | \$2,339 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 111 | SF | 6 | \$384 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 890 | SF | 6 | \$891 | |
| | Lighting - Lay-in | 2nd Floor | 13 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 6 | \$73 | |
| | Walls - Plaster/Drywall | 2nd Floor | 959 | SF | 6 | \$2,647 | |
| | | | | | | | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|------------|-----------|------|--------|---------|------------|
| • | oom #204 (Regular Classroom) | Location | Qualitity | Oint | ivalik | COSI | Commence |
| Ciassi | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 10 | LF | 6 | \$253 | |
| | Ceiling - Lay-in | 2nd Floor | 779 | SF | 6 | \$2,339 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 111 | SF | 6 | \$384 | |
| | Floor - Tile/Sheet | 2nd Floor | 890 | SF | 6 | \$891 | |
| | Lighting - Lay-in | 2nd Floor | 13 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 2nd Floor | 240 | SF | 6 | \$755 | Brick wall |
| | Walls - Nasoniy Walls - Plaster/Drywall | 2nd Floor | 719 | SF | 6 | \$1,984 | DIICK Wall |
| | Walls - Plaster/Drywali | 211d F1001 | 719 | SF | O | Ф1,904 | |
| Classro | oom #205 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | 2nd Floor | 779 | SF | 6 | \$2,339 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 111 | SF | 6 | \$384 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 890 | SF | 6 | \$891 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 2nd Floor | 240 | SF | 6 | \$755 | Brick wall |
| | Walls - Plaster/Drywall | 2nd Floor | 719 | SF | 6 | \$1,984 | |
| Classro | oom #206 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Casework | 2nd Floor | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | 2nd Floor | 890 | SF | 6 | \$2,673 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 111 | SF | 6 | \$384 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 890 | SF | 6 | \$891 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 2nd Floor | 240 | SF | 6 | \$755 | brick wall |
| | Walls - Plaster/Drywall | 2nd Floor | 719 | SF | 6 | \$1,984 | |
| Classro | oom #207 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-----------|----------|-------|------|---------|-------------|
| _ | oom #207 (Regular Classroom) | Location | Quantity | O.III | Runk | 0031 | Commonto |
| Giuooi | Casework | 2nd Floor | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | 2nd Floor | 779 | SF | 6 | \$2,339 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 111 | SF | 6 | \$384 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 890 | SF | 6 | \$891 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 2nd Floor | 240 | SF | 6 | \$755 | Brick wall |
| | Walls - Plaster/Drywall | 2nd Floor | 719 | SF | 6 | \$1,984 | |
| Classr | oom #208 (Regular Classroom) | | | | | , , | |
| J.uJJI | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | 2nd Floor | 834 | SF | 6 | \$2,505 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 111 | SF | 6 | \$384 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 945 | SF | 6 | \$946 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 2nd Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 2nd Floor | 288 | SF | 6 | \$906 | Brick wall |
| | Walls - Plaster/Drywall | 2nd Floor | 864 | SF | 6 | \$2,385 | |
| Classro | oom #301/ 302 (Faculty Lounge) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 6 | \$991 | |
| | Ceiling - Lay-in | 3rd Floor | 1,612 | SF | 6 | \$4,841 | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 228 | SF | 6 | \$789 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | 3rd Floor | 1,840 | SF | 6 | \$1,842 | |
| | Lighting - Lay-in | 3rd Floor | 27 | EA | 7 | \$0 | |
| | Storage/ Closet | 3rd Floor | 20 | SF | 6 | \$145 | |
| | Walls - Masonry | 3rd Floor | 390 | SF | 6 | \$1,227 | Brick walls |
| | Walls - Plaster/Drywall | 3rd Floor | 1,169 | SF | 6 | \$3,226 | |
| Classro | oom #303/304 (Library) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 6 | \$991 | |
| | Casework | 3rd Floor | 65 | LF | 6 | \$1,641 | |
| | Ceiling - Lay-in | 3rd Floor | 1,595 | SF | 6 | \$4,790 | |
| | | | | | | | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| Category: Classrooms | | | | | | |
|------------------------------------|-----------|----------|------|------|---------|------------|
| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classroom #303/304 (Library) | | | | | | |
| Ceiling - Plaster/Drywall | 3rd Floor | 228 | SF | 6 | \$789 | |
| Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | \$602 | |
| Floor - Tile/Sheet | 3rd Floor | 1,823 | SF | 6 | \$1,825 | |
| Lighting - Lay-in | 3rd Floor | 27 | EA | 7 | \$0 | |
| Storage/ Closet | 3rd Floor | 20 | SF | 6 | \$145 | |
| Walls - Masonry | 3rd Floor | 390 | SF | 6 | | Brick wall |
| Walls - Plaster/Drywall | 3rd Floor | 1,169 | SF | 6 | \$3,226 | |
| Classroom #305 (Regular Classroom) | | | | | | |
| AC Units | 3rd Floor | 1 | EA | 6 | \$496 | |
| Casework | 3rd Floor | 18 | LF | 6 | \$455 | |
| Ceiling - Lay-in | 3rd Floor | 779 | SF | 6 | \$2,339 | |
| Ceiling - Plaster/Drywall | 3rd Floor | 111 | SF | 6 | \$384 | |
| Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 3rd Floor | 890 | SF | 6 | \$891 | |
| Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | \$0 | |
| Marker Board | 3rd Floor | 12 | LF | 5 | \$608 | |
| Storage/ Closet | 3rd Floor | 10 | SF | 6 | \$73 | |
| Walls - Masonry | 3rd Floor | 240 | SF | 6 | \$755 | Brick wall |
| Walls - Plaster/Drywall | 3rd Floor | 719 | SF | 6 | \$1,984 | |
| Classroom #306 (Regular Classroom) | | | | | | |
| AC Units | 3rd Floor | 1 | EA | 6 | \$496 | |
| Casework | 3rd Floor | 18 | LF | 6 | \$455 | |
| Ceiling - Lay-in | 3rd Floor | 779 | SF | 6 | \$2,339 | |
| Ceiling - Plaster/Drywall | 3rd Floor | 111 | SF | 6 | \$384 | |
| Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 6 | \$301 | |
| Floor - Tile/Sheet | 3rd Floor | 890 | SF | 6 | \$891 | |
| Lighting - Lay-in | 3rd Floor | 12 | EΑ | 7 | \$0 | |
| Marker Board | 3rd Floor | 12 | LF | 6 | \$257 | |
| Storage/ Closet | 3rd Floor | 10 | SF | 6 | \$73 | |
| Walls - Masonry | 3rd Floor | 240 | SF | 6 | \$755 | Brick wall |
| Walls - Plaster/Drywall | 3rd Floor | 719 | SF | 6 | \$1,984 | |
| Classroom #307 (Regular Classroom) | | | | | | |
| AC Units | 3rd Floor | 1 | EA | 6 | \$496 | |
| Casework | 3rd Floor | 18 | LF | 6 | \$455 | |
| Ceiling - Lay-in | 3rd Floor | 779 | SF | 6 | \$2,339 | |
| Ceiling - Plaster/Drywall | 3rd Floor | 111 | SF | 6 | \$384 | |
| | | | | | | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| | ltom Type | Location | Quantity | l Init | Donk | Cont | Comments |
|--------|---|-----------|----------|--------|-------|---------|------------|
| | Item - Type | Location | Quantity | Ullit | Kalik | Cost | Comments |
| Ciassi | pom #307 (Regular Classroom) Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | \$301 | |
| | | | = | | | | |
| | Floor - Tile/Sheet | 3rd Floor | 890 | SF | 6 | \$891 | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 3rd Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 3rd Floor | 244 | SF | 6 | \$768 | Brick wall |
| | Walls - Plaster/Drywall | 3rd Floor | 731 | SF | 6 | \$2,017 | |
| Classr | oom #308 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | 3rd Floor | 834 | SF | 6 | \$2,505 | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 111 | SF | 6 | \$384 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 3rd Floor | 945 | SF | 6 | \$946 | |
| | Lighting - Lay-in | 3rd Floor | 12 | EΑ | 7 | \$0 | |
| | Marker Board | 3rd Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 3rd Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 3rd Floor | 288 | SF | 6 | \$906 | Brick wall |
| | Walls - Plaster/Drywall | 3rd Floor | 864 | SF | 6 | \$2,385 | |
| Classr | oom #401 (Regular Classroom) | | | | | | |
| | AC Units | 4th Floor | 1 | EA | 6 | \$496 | |
| | Casework | 4th Floor | 10 | LF | 6 | \$253 | |
| | Ceiling - Lay-in | 4th Floor | 834 | SF | 6 | \$2,505 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 118 | SF | 6 | \$408 | |
| | Doors - Wood Doors inclu hw | 4th Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 4th Floor | 945 | SF | 6 | \$946 | |
| | Lighting - Lay-in | 4th Floor | 13 | EA | 6 | \$1,547 | |
| | Marker Board | 4th Floor | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | 4th Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 4th Floor | 288 | SF | 6 | \$906 | Brick wall |
| | Walls - Plaster/Drywall | 4th Floor | 864 | SF | 6 | \$2,385 | |
| Classr | oom #402 (Regular Classroom) | | | | | | |
| | AC Units | 4th Floor | 1 | EA | 6 | \$496 | |
| | Casework | 4th Floor | 10 | LF | 6 | \$253 | |
| | Ceiling - Lay-in | 4th Floor | 779 | SF | 6 | \$2,339 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 111 | SF | 6 | \$384 | |
| | Doors - Wood Doors inclu hw | 4th Floor | 1 | EA | 6 | \$301 | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| | Item - Type | Location | Quantity | Linit | Dank | Cost | Comments |
|---------|------------------------------|-----------|----------|-------|------|---------|-------------|
| • | ••• | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | oom #402 (Regular Classroom) | 4th Floor | 000 | SF | | Ф004 | |
| | Floor - Tile/Sheet | 4th Floor | 890 | | 6 | \$891 | |
| | Lighting - Lay-in | | 13 | EA | 7 | \$0 | |
| | Marker Board | 4th Floor | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | 4th Floor | 10 | SF | 6 | \$73 | B : 1 |
| | Walls - Masonry | 4th Floor | 240 | SF | 6 | \$755 | Brick walls |
| | Walls - Plaster/Drywall | 4th Floor | 719 | SF | 6 | \$1,984 | |
| Classro | oom #403 (Office) | | | | | | |
| | AC Units | 4th Floor | 1 | EA | 6 | \$496 | |
| | Casework | 4th Floor | 10 | LF | 6 | \$253 | |
| | Ceiling - Lay-in | 4th Floor | 779 | SF | 6 | \$2,339 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 111 | SF | 6 | \$384 | |
| | Doors - Wood Doors inclu hw | 4th Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 4th Floor | 890 | SF | 6 | \$891 | |
| | Lighting - Lay-in | 4th Floor | 13 | EA | 7 | \$0 | |
| | Marker Board | 4th Floor | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | 4th Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 4th Floor | 240 | SF | 6 | \$755 | Brick wall |
| | Walls - Plaster/Drywall | 4th Floor | 719 | SF | 6 | \$1,984 | |
| Classro | oom #404 (Office) | | | | | | |
| | AC Units | 4th Floor | 1 | EA | 6 | \$496 | |
| | Casework | 4th Floor | 10 | LF | 6 | \$253 | |
| | Ceiling - Lay-in | 4th Floor | 779 | SF | 6 | \$2,339 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 111 | SF | 6 | \$384 | |
| | Doors - Wood Doors inclu hw | 4th Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 4th Floor | 890 | SF | 6 | \$891 | |
| | Lighting - Lay-in | 4th Floor | 13 | EA | 7 | \$0 | |
| | Marker Board | 4th Floor | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | 4th Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 4th Floor | 240 | SF | 6 | \$755 | Brick wall |
| | Walls - Plaster/Drywall | 4th Floor | 719 | SF | 6 | \$1,984 | |
| Classro | oom #405 (Regular Classroom) | | | | | | |
| | AC Units | 4th Floor | 1 | EA | 6 | \$496 | |
| | Casework | 4th Floor | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | 4th Floor | 779 | SF | 6 | \$2,339 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 111 | SF | 6 | \$384 | |
| | Doors - Steel Doors incl hw | 4th Floor | 1 | EA | 6 | \$301 | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| | ory: Classrooms | | | | | _ | _ |
|---------|------------------------------|-----------|----------|------|------|---------|------------|
| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | oom #405 (Regular Classroom) | | | | | | |
| | Floor - Tile/Sheet | 4th Floor | 890 | SF | 6 | \$891 | |
| | Lighting - Lay-in | 4th Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 4th Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 4th Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 4th Floor | 240 | SF | 6 | \$755 | Brick wall |
| | Walls - Plaster/Drywall | 4th Floor | 719 | SF | 6 | \$1,984 | |
| Classro | oom #406 (Art Room) | | | | | | |
| | AC Units | 4th Floor | 1 | EA | 6 | \$496 | |
| | Casework | 4th Floor | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | 4th Floor | 779 | SF | 6 | \$2,339 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 111 | SF | 6 | \$384 | |
| | Doors - Wood Doors inclu hw | 4th Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 4th Floor | 890 | SF | 6 | \$891 | |
| | Lighting - Lay-in | 4th Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 4th Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 4th Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 4th Floor | 240 | SF | 6 | \$755 | Brick wall |
| | Walls - Plaster/Drywall | 4th Floor | 719 | SF | 6 | \$1,984 | |
| | Work Sink | 4th Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #407 (Science Classroom) | | | | | | |
| | AC Units | 4th Floor | 1 | EA | 6 | \$496 | |
| | Casework | 4th Floor | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | 4th Floor | 864 | SF | 6 | \$2,595 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 111 | SF | 6 | \$384 | |
| | Doors - Wood Doors inclu hw | 4th Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 4th Floor | 975 | SF | 6 | \$2,133 | |
| | Lighting - Lay-in | 4th Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 4th Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 4th Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 4th Floor | 288 | SF | 6 | \$906 | Brick wall |
| | Walls - Plaster/Drywall | 4th Floor | 864 | SF | 6 | \$2,385 | |
| Classro | oom #408 (Regular Classroom) | | | | | | |
| | AC Units | 4th Floor | 1 | EA | 6 | \$496 | |
| | Casework | 4th Floor | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | 4th Floor | 834 | SF | 6 | \$2,505 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 111 | SF | 6 | \$384 | |
| | • | | | | | | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|-----------|----------|------|------|---------|------------|
| Classro | om #408 (Regular Classroom) | | | | | | |
| | Doors - Wood Doors inclu hw | 4th Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 4th Floor | 945 | SF | 6 | \$946 | |
| | Lighting - Lay-in | 4th Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 4th Floor | 12 | LF | 6 | \$257 | |
| | Storage/ Closet | 4th Floor | 10 | SF | 6 | \$73 | |
| | Walls - Masonry | 4th Floor | 288 | SF | 6 | \$906 | Brick wall |
| | Walls - Plaster/Drywall | 4th Floor | 864 | SF | 6 | \$2,385 | |

Classrooms Subtotal: \$192,352

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|-------------------|----------|------|------|---------|----------|
| Admini | strative Suites/Offices | | | | | | |
| | Ceiling - Splined | Engineer's Office | 70 | SF | 6 | \$57 | |
| | Doors - Wood Doors inclu hw | Engineer's Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Engineer's Office | 70 | SF | 6 | \$153 | |
| | Lighting - Pendent/Surface | Engineer's Office | 12 | EA | 7 | \$0 | |
| | Power Distribution | Engineer's Office | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Engineer's Office | 91 | SF | 6 | \$267 | |
| | Ceiling - Plaster/Drywall | Gym Office #1 | 64 | SF | 6 | \$221 | |
| | Doors - Wood Doors inclu hw | Gym Office #1 | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Gym Office #1 | 64 | SF | 6 | \$140 | |
| | Lighting - Pendent/Surface | Gym Office #1 | 1 | EA | 7 | \$0 | |
| | Power Distribution | Gym Office #1 | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Gym Office #1 | 95 | SF | 6 | \$278 | |
| | Ceiling - Plaster/Drywall | Gym Office #2 | 51 | SF | 6 | \$176 | |
| | Doors - Steel Doors incl hw | Gym Office #2 | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Gym Office #2 | 51 | SF | 6 | \$112 | |
| | Lighting - Pendent/Surface | Gym Office #2 | 1 | EA | 7 | \$0 | |
| | Power Distribution | Gym Office #2 | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Gym Office #2 | 87 | SF | 6 | \$255 | |
| | Ceiling - Lay-in | Main Office | 540 | SF | 6 | \$1,622 | |
| | Doors - Wood Doors inclu hw | Main Office | 2 | EA | 6 | \$602 | |
| | Floor - Tile | Main Office | 540 | SF | 6 | \$1,181 | |
| | Lighting - Lay-in | Main Office | 6 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Main Office | 4 | EΑ | 7 | \$0 | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|--------------------------|----------|------|------|----------|-----------------|
| Admini | istrative Suites/Offices | | | | | | |
| | Power Distribution | Main Office | 10 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Main Office | 702 | SF | 6 | \$2,058 | |
| | AC Unit | Principal's Office | 1 | EA | 6 | \$496 | |
| | Ceiling - Lay-in | Principal's Office | 254 | SF | 6 | \$763 | |
| | Doors - Side-lite | Principal's Office | 14 | SF | 6 | \$234 | |
| | Doors - Wood Doors inclu hw | Principal's Office | 1 | EA | 6 | \$301 | |
| | Floor - Wood | Principal's Office | 254 | SF | 6 | \$1,791 | |
| | Lighting - Pendent/Surface | Principal's Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | Principal's Office | 6 | EA | 7 | \$0 | |
| | Walls - Masonry | Principal's Office | 83 | SF | 6 | \$261 | |
| | Walls - Plaster/Drywall | Principal's Office | 165 | SF | 6 | \$455 | |
| | Walls - Structural Glazed Tile | Principal's Office | 83 | SF | 6 | \$261 | |
| | Ceiling - Lay-in | Room 101 Conference Room | 715 | SF | 6 | \$2,147 | |
| | Doors - Side-lite | Room 101 Conference Room | 14 | SF | 6 | \$234 | |
| | Doors - Wood Doors inclu hw | Room 101 Conference Room | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Room 101 Conference Room | 715 | SF | 6 | \$1,564 | |
| | Lighting - Pendent/Surface | Room 101 Conference Room | 8 | EA | 7 | \$0 | |
| | Power Distribution | Room 101 Conference Room | 8 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Room 101 Conference Room | 923 | SF | 6 | \$2,547 | |
| Gymna | asia | | | | | | |
| | Ceiling - Exposed | 1st Floor | 3,242 | SF | 6 | \$4,822 | |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 6 | \$1,204 | |
| | Floor - Tile | 1st Floor | 3,242 | SF | 6 | \$7,093 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | |
| | Scoreboards | 1st Floor | 1 | EA | 6 | \$2,244 | |
| | Sound System | 1st Floor | 1 | EA | 6 | \$41,654 | |
| | Stage | 1st Floor | 588 | SF | 6 | \$3,397 | |
| | Stage Curtain | 1st Floor | 2 | EA | 6 | \$0 | |
| | Stage Lighting System | 1st Floor | 1 | EA | 6 | \$12,369 | |
| | Stage-Stairs - Tile | 1st Floor | 124 | LF | 6 | \$1,151 | |
| | Storage/ Closet | 1st Floor | 330 | SF | 6 | \$2,393 | 2 @ 165 SF each |
| | Walls - Concrete Block | 1st Floor | 5,108 | SF | 6 | \$14,974 | |
| Kitcher | n | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 403 | SF | 6 | \$1,395 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 403 | SF | 6 | \$882 | |
| | | | | _ | - | | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|--------------------|----------|------|------|----------|---|
| itchen | | | | | | | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 524 | SF | 6 | \$1,536 | |
| ınch & | Multipurpose Room | | | | | | |
| | Ceiling - Lay-in | 1st flr #101 & 102 | 2,668 | SF | 6 | \$8,012 | |
| | Doors - Side-lite | 1st flr #101 & 102 | 12 | SF | 6 | \$201 | |
| | Doors - Wood Doors inclu hw | 1st flr #101 & 102 | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st flr #101 & 102 | 2,668 | SF | 6 | \$2,671 | |
| | Lighting - Lay-in | 1st flr #101 & 102 | 30 | EA | 7 | \$0 | |
| | Serving Line | 1st flr #101 & 102 | 27 | LF | 6 | \$1,607 | |
| | Storage/ Closet | 1st flr #101 & 102 | 25 | SF | 6 | \$181 | |
| | Walls - Masonry | 1st flr #101 & 102 | 1,017 | SF | 6 | \$3,199 | Brick |
| | Walls - Plaster/Drywall | 1st flr #101 & 102 | 1,017 | SF | 6 | \$2,807 | |
| DF_IDI | F | | | | | | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | \$301 | |
| | Finishes | 3rd Floor | 129 | SF | 6 | \$921 | |
| | Ventilation and Cooling | 3rd Floor | 1 | EA | 6 | \$1,855 | |
| chani | ical/ Service Rooms | | | | | | |
| | Vaults | 1st Floor | 97 | SF | 6 | \$695 | |
| | Janitor's Closet | 1st flr NE side | 21 | SF | 6 | \$150 | |
| | Storage Room | 1st flr NE side | 233 | SF | 6 | \$1,669 | SW of lunch room |
| | Storage Room | 1st flr NE side | 75 | SF | 6 | \$537 | Yard storage west of lunchroom |
| | Janitor's Closet | 2nd Floor | 40 | SF | 6 | \$287 | |
| | Storage Room | 2nd Floor | 129 | SF | 6 | \$924 | Book Storage |
| | Storage Room | 2nd Floor | 66 | SF | 6 | \$473 | |
| | Janitor's Closet | 3rd Floor | 40 | SF | 6 | \$287 | |
| | Storage Room | 3rd Floor | 129 | SF | 6 | \$924 | Book Storage |
| | Storage Room | 3rd Floor | 66 | SF | 6 | \$473 | |
| | Janitor's Closet | 4th Floor | 40 | SF | 6 | \$287 | |
| | Storage Room | 4th Floor | 195 | SF | 6 | \$1,397 | |
| | Boiler Room | Basement | 1,165 | SF | 5 | \$18,792 | T-12 lights Ranked a "4" |
| | Mechanical/ Service Rooms | Basement | 129 | SF | 6 | \$924 | Elevator Machine Room |
| | Mechanical/ Service Rooms | Basement | 62 | SF | 5 | \$1,000 | Electrical Room. Water infiltration during heavy rain through the phone lines |
| | Mechanical/ Service Rooms | Basement | 66 | SF | 6 | \$473 | Switch Gear Room |
| | Storage Room | Basement | 214 | SF | 6 | \$1,533 | |
| | Storage Room | Basement | 27 | SF | 6 | \$193 | Formerly Staff Restroom |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|-----------|----------|------|------|---------|----------|
| Mechar | nical/ Service Rooms | | | | | | |
| | Storage Room | Basement | 27 | SF | 6 | \$193 | |
| Restro | om | | | | | | |
| | Accessories | 1st Floor | 178 | SF | 6 | \$1,642 | |
| | Accessories | 1st Floor | 29 | SF | 6 | \$267 | |
| | Accessories | 1st Floor | 137 | SF | 6 | \$1,264 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 178 | SF | 6 | \$616 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 29 | SF | 6 | \$100 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 137 | SF | 6 | \$474 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EΑ | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EΑ | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st Floor | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 1st Floor | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile | 1st Floor | 29 | SF | 6 | \$63 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 178 | SF | 6 | \$377 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 137 | SF | 6 | \$290 | |
| | Lavatory | 1st Floor | 2 | EA | 6 | \$639 | |
| | Lavatory | 1st Floor | 2 | EΑ | 6 | \$639 | |
| | Lavatory | 1st Floor | 1 | EΑ | 6 | \$320 | |
| | Lighting - Pendent/Surface | 1st Floor | 3 | EΑ | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 1 | EA | 7 | \$0 | |
| | Partitions | 1st Floor | 3 | EA | 6 | \$891 | |
| | Partitions | 1st Floor | 1 | EA | 6 | \$297 | |
| | Urinals | 1st Floor | 2 | EA | 6 | \$672 | |
| | Walls - Concrete Block | 1st Floor | 201 | SF | 6 | \$589 | |
| | Walls - Concrete Block | 1st Floor | 228 | SF | 6 | \$668 | |
| | Walls - Plaster/Drywall | 1st Floor | 87 | SF | 6 | \$240 | |
| | Water Closet | 1st Floor | 3 | EA | 6 | \$1,008 | |
| | Water Closet | 1st Floor | 2 | EA | 6 | \$672 | |
| | Water Closet | 1st Floor | 1 | EA | 6 | \$336 | |
| | Accessories | 2nd Floor | 137 | SF | 6 | \$1,264 | |
| | Accessories | 2nd Floor | 29 | SF | 6 | \$267 | |
| | Accessories | 2nd Floor | 178 | SF | 6 | \$1,642 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 178 | SF | 6 | \$616 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 29 | SF | 6 | \$100 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 137 | SF | 6 | \$474 | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | | | |
|--------|---------------------------------|-----------|----------|------|------|---------|----------|--|--|--|--|
| Restro | estroom | | | | | | | | | | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | \$301 | | | | | |
| | Floor Drain | 2nd Floor | 1 | EΑ | 6 | \$1,059 | | | | | |
| | Floor Drain | 2nd Floor | 1 | EA | 6 | \$1,059 | | | | | |
| | Floor - Tile | 2nd Floor | 29 | SF | 6 | \$63 | | | | | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 178 | SF | 6 | \$377 | | | | | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 137 | SF | 6 | \$290 | | | | | |
| | Lavatory | 2nd Floor | 1 | EΑ | 6 | \$320 | | | | | |
| | Lavatory | 2nd Floor | 2 | EΑ | 6 | \$639 | | | | | |
| | Lavatory | 2nd Floor | 2 | EΑ | 6 | \$639 | | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 2 | EA | 7 | \$0 | | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 3 | EA | 7 | \$0 | | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 1 | EA | 7 | \$0 | | | | | |
| | Partitions | 2nd Floor | 1 | EA | 6 | \$297 | | | | | |
| | Partitions | 2nd Floor | 3 | EA | 6 | \$891 | | | | | |
| | Urinals | 2nd Floor | 2 | EA | 6 | \$672 | | | | | |
| | Walls - Concrete Block | 2nd Floor | 228 | SF | 6 | \$668 | | | | | |
| | Walls - Concrete Block | 2nd Floor | 201 | SF | 6 | \$589 | | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 87 | SF | 6 | \$240 | | | | | |
| | Water Closet | 2nd Floor | 2 | EΑ | 7 | \$0 | | | | | |
| | Water Closet | 2nd Floor | 1 | EΑ | 6 | \$336 | | | | | |
| | Water Closet | 2nd Floor | 3 | EΑ | 7 | \$0 | | | | | |
| | Accessories | 3rd Floor | 137 | SF | 6 | \$1,264 | | | | | |
| | Accessories | 3rd Floor | 178 | SF | 6 | \$1,642 | | | | | |
| | Accessories | 3rd Floor | 29 | SF | 6 | \$267 | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 29 | SF | 6 | \$100 | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 178 | SF | 6 | \$616 | | | | | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 137 | SF | 6 | \$474 | | | | | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | \$301 | | | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 6 | \$301 | | | | | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | \$301 | | | | | |
| | Floor Drain | 3rd Floor | 1 | EA | 6 | \$1,059 | | | | | |
| | Floor Drain | 3rd Floor | 1 | EA | 6 | \$1,059 | | | | | |
| | Floor - Tile | 3rd Floor | 29 | SF | 6 | \$63 | | | | | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor | 178 | SF | 6 | \$377 | | | | | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor | 137 | SF | 6 | \$290 | | | | | |
| | | | | | | | | | | | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-----------|----------|------|------|---------|----------|
| Restroc | om | | | | | | |
| | Lavatory | 3rd Floor | 2 | EA | 6 | \$639 | |
| | Lavatory | 3rd Floor | 2 | EA | 6 | \$639 | |
| | Lavatory | 3rd Floor | 1 | EA | 5 | \$1,590 | |
| | Lighting - Pendent/Surface | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 3rd Floor | 3 | EA | 7 | \$0 | |
| | Partitions | 3rd Floor | 3 | EA | 6 | \$891 | |
| | Partitions | 3rd Floor | 1 | EA | 6 | \$297 | |
| | Urinals | 3rd Floor | 2 | EA | 6 | \$672 | |
| | Walls - Concrete Block | 3rd Floor | 201 | SF | 6 | \$589 | |
| | Walls - Concrete Block | 3rd Floor | 228 | SF | 6 | \$668 | |
| | Walls - Plaster/Drywall | 3rd Floor | 87 | SF | 6 | \$240 | |
| | Water Closet | 3rd Floor | 1 | EA | 6 | \$336 | |
| | Water Closet | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Water Closet | 3rd Floor | 3 | EA | 6 | \$1,008 | |
| | Accessories | 4th Floor | 137 | SF | 6 | \$1,264 | |
| | Accessories | 4th Floor | 29 | SF | 6 | \$267 | |
| | Accessories | 4th Floor | 178 | SF | 6 | \$1,642 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 178 | SF | 6 | \$616 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 137 | SF | 6 | \$474 | |
| | Ceiling - Plaster/Drywall | 4th Floor | 29 | SF | 6 | \$100 | |
| | Doors - Steel Doors incl hw | 4th Floor | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 4th Floor | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 4th Floor | 1 | EA | 6 | \$301 | |
| | Floor Drain | 4th Floor | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 4th Floor | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile | 4th Floor | 29 | SF | 6 | \$63 | |
| | Floor - Tile Ceramic/ Porcelain | 4th Floor | 178 | SF | 6 | \$377 | |
| | Floor - Tile Ceramic/ Porcelain | 4th Floor | 137 | SF | 6 | \$290 | |
| | Lavatory | 4th Floor | 1 | EA | 6 | \$320 | |
| | Lavatory | 4th Floor | 2 | EA | 6 | \$639 | |
| | Lavatory | 4th Floor | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 4th Floor | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 4th Floor | 2 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 4th Floor | 3 | EA | 7 | \$0 | |
| | Partitions | 4th Floor | 1 | EA | 6 | \$297 | |
| | Partitions | 4th Floor | 3 | EA | 6 | \$891 | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

Category: Rooms (Other Than Classrooms)

| Froup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|---------------------------|----------|------|------|---------|----------|
| Restro | om | | | | | | |
| | Urinals | 4th Floor | 2 | EA | 6 | \$672 | |
| | Walls - Concrete Block | 4th Floor | 201 | SF | 6 | \$589 | |
| | Walls - Concrete Block | 4th Floor | 228 | SF | 6 | \$668 | |
| | Walls - Plaster/Drywall | 4th Floor | 87 | SF | 6 | \$240 | |
| | Water Closet | 4th Floor | 2 | EA | 6 | \$672 | |
| | Water Closet | 4th Floor | 3 | EA | 6 | \$1,008 | |
| | Water Closet | 4th Floor | 1 | EA | 6 | \$336 | |
| | Accessories | In the Kitchen Area | 75 | SF | 6 | \$692 | |
| | Ceiling - Plaster/Drywall | In the Kitchen Area | 75 | SF | 6 | \$260 | |
| | Doors - Wood Doors inclu hw | In the Kitchen Area | 1 | EA | 6 | \$301 | |
| | Floor - Tile | In the Kitchen Area | 75 | SF | 6 | \$164 | |
| | Lavatory | In the Kitchen Area | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | In the Kitchen Area | 2 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | In the Kitchen Area | 6 | EA | 6 | \$557 | |
| | Walls - Concrete Block | In the Kitchen Area | 147 | SF | 6 | \$431 | |
| | Water Closet | In the Kitchen Area | 1 | EA | 6 | \$336 | |
| | Accessories | In the Principal's Office | 25 | SF | 6 | \$231 | |
| | Ceiling - Plaster/Drywall | In the Principal's Office | 25 | SF | 6 | \$87 | |
| | Doors - Wood Doors inclu hw | In the Principal's Office | 1 | EA | 6 | \$301 | |
| | Floor - Wood | In the Principal's Office | 25 | SF | 6 | \$176 | |
| | Lavatory | In the Principal's Office | 1 | EA | 5 | \$1,590 | |
| | Lighting - Pendent/Surface | In the Principal's Office | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | In the Principal's Office | 63 | SF | 6 | \$185 | |
| | Water Closet | In the Principal's Office | 1 | EA | 6 | \$336 | |

Rooms (Other Than Classrooms) Subtotal:

\$233,289

Building: Main

| p Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|-----------|----------|------|------|---------|----------|
| dor | | | | | | |
| Ceiling - Lay-in | 1st Floor | 2,266 | SF | 6 | \$6,805 | |
| Doors - Steel Doors incl hw | 1st Floor | 6 | EA | 6 | \$1,806 | |
| Drinking Fountains - Double Fountain | 1st Floor | 2 | EA | 6 | \$672 | |
| Floor - Tile/Sheet | 1st Floor | 2,266 | SF | 6 | \$1,231 | |
| Lighting - Lay-in | 1st Floor | 23 | EA | 7 | \$0 | |
| Lighting - Pendent/Surface | 1st Floor | 4 | EΑ | 6 | \$496 | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--------------------------------------|-----------------|----------|------|------|----------|----------|
| orrido | | | | | | | |
| | Walls - Masonry | 1st Floor | 3,990 | SF | 6 | \$12,553 | |
| | Ceiling - Lay-in | 2nd Floor | 2,820 | SF | 6 | \$8,468 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 6 | EA | 6 | \$1,806 | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 1 | EA | 6 | \$336 | |
| | Floor - Tile/Sheet | 2nd Floor | 2,820 | SF | 6 | \$1,532 | |
| | Lighting - Lay-in | 2nd Floor | 43 | EA | 7 | \$0 | |
| | Walls - Masonry | 2nd Floor | 665 | SF | 6 | \$2,092 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,330 | SF | 6 | \$5,896 | |
| | Ceiling - Lay-in | 3rd Floor | 2,820 | SF | 6 | \$8,468 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 6 | EA | 6 | \$1,806 | |
| | Drinking Fountains - Double Fountain | 3rd Floor | 1 | EA | 6 | \$336 | |
| | Floor - Tile/Sheet | 3rd Floor | 2,820 | SF | 6 | \$1,532 | |
| | Lighting - Lay-in | 3rd Floor | 43 | EA | 7 | \$0 | |
| | Walls - Masonry | 3rd Floor | 665 | SF | 6 | \$2,092 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,330 | SF | 6 | \$5,896 | |
| | Ceiling - Lay-in | 4th Floor | 2,820 | SF | 6 | \$8,468 | |
| | Doors - Steel Doors incl hw | 4th Floor | 6 | EA | 6 | \$1,806 | |
| | Drinking Fountains - Double Fountain | 4th Floor | 1 | EA | 6 | \$336 | |
| | Floor - Tile/Sheet | 4th Floor | 2,820 | SF | 6 | \$1,532 | |
| | Lighting - Lay-in | 4th Floor | 43 | EA | 7 | \$0 | |
| | Walls - Masonry | 4th Floor | 665 | SF | 6 | \$2,092 | |
| | Walls - Plaster/Drywall | 4th Floor | 1,330 | SF | 6 | \$5,896 | |
| afety | | | | | | | |
| | Camera Viewing Station | Entire Building | 2 | EA | 6 | \$1,365 | |
| | Security Cameras | Entire Building | 26 | EA | 6 | \$5,045 | |
| | Security Cameras | Entire Building | 7 | EA | 6 | \$1,358 | |
| airs | | | | | | | |
| | Ceiling - Plaster/Drywall | North East | 576 | SF | 6 | \$4,217 | |
| | Floor - Tile | North East | 570 | SF | 6 | \$310 | |
| | Handrails | North East | 192 | LF | 6 | \$1,664 | |
| | Lighting - Pendent/Surface | North East | 12 | EA | 7 | \$0 | |
| | Stairs - Tile | North East | 90 | LF | 6 | \$835 | |
| | Walls - Masonry | North East | 1,390 | SF | 6 | \$4,373 | |
| | Walls - Plaster/Drywall | North East | 2,780 | SF | 6 | \$7,673 | |
| | Ceiling - Plaster/Drywall | North West | 548 | SF | 6 | \$4,012 | |
| | Floor - Tile | North West | 480 | SF | 6 | \$261 | |



1420 S Albany Ave Chicago, IL 60623

Building: Main

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|------------|----------|------|------|----------|----------|
| Stairs | | | | | | | |
| | Handrails | North West | 256 | LF | 6 | \$2,218 | |
| | Lighting - Pendent/Surface | North West | 8 | EA | 7 | \$0 | |
| | Stairs - Tile | North West | 120 | LF | 6 | \$1,114 | |
| | Walls - Masonry | North West | 737 | SF | 6 | \$2,319 | |
| | Walls - Plaster/Drywall | North West | 3,683 | SF | 6 | \$10,165 | |
| | Ceiling - Plaster/Drywall | South | 576 | SF | 6 | \$4,217 | |
| | Floor - Tile | South | 570 | SF | 6 | \$310 | |
| | Handrails | South | 192 | LF | 6 | \$1,664 | |
| | Lighting - Pendent/Surface | South | 12 | EA | 7 | \$0 | |
| | Stairs - Tile | South | 90 | LF | 6 | \$835 | |
| | Walls - Masonry | South | 1,390 | SF | 6 | \$4,373 | |
| | Walls - Plaster/Drywall | South | 2,780 | SF | 6 | \$7,673 | |
| Vertica | I Conveyance | | | | | | |
| | Elevator - Elevator- Roped Holeless Hydraulic | 1st Floor | 1 | EA | 6 | \$19,238 | |
| | | | | | | | |

Building Interior Subtotal: \$169,192

Total Building Cost \$2,753,852

Building: CPC

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|--------------------------------|----------|------|------|-------|----------|
| Entrance | | | | | | |
| Entrance Control - Audio and Video | #1- Main Accessible- N / North | 1 | EA | 6 | \$702 | |
| Entrance Control - Audio and Video | #9- W / West | 1 | EA | 6 | \$702 | |
| Exterior Doors - Exterior Steel Door | #1- Main Accessible- N / North | 2 | EA | 6 | \$961 | |
| Exterior Doors - Exterior Steel Door | #2- NE / North East | 1 | EA | 6 | \$481 | |
| Exterior Doors - Exterior Steel Door | #3- NE / North East | 1 | EA | 6 | \$481 | |
| Exterior Doors - Exterior Steel Door | #4- E / East | 1 | EA | 6 | \$481 | |
| Exterior Doors - Exterior Steel Door | #5- SE / South East | 1 | EA | 6 | \$481 | |
| Exterior Doors - Exterior Steel Door | #6- SE / South East | 1 | EA | 6 | \$481 | |
| Exterior Doors - Exterior Steel Door | #7- SW / South West | 1 | EA | 6 | \$481 | |
| Exterior Doors - Exterior Steel Door | #8- W / West | 2 | EA | 6 | \$961 | |
| Exterior Doors - Exterior Steel Door | #9- W / West | 1 | EA | 6 | \$481 | |



1420 S Albany Ave Chicago, IL 60623

Building: CPC

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|---------------------------------|----------|------|------|-----------|---|
| Founda | ation | | | | | | |
| | Foundation - Concrete | Entire Building | 463 | LF | 7 | \$0 | |
| | Superstructure - Steel | Entire Building | 14,841 | SF | 7 | \$0 | |
| Lightin | g | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 9 | EA | 6 | \$2,599 | |
| Roof S | ystem | | | | | | |
| | Chimney - Metal Flue | Main Roof | 28 | LF | 6 | \$4,428 | |
| | Coping - Metal | Main Roof / Entire Building | 461 | LF | 6 | \$14,806 | remove debris |
| | Coping - Metal | Main Roof / North Façade | 10 | LF | 5 | \$709 | open joint |
| | Downspouts - Exterior Downspouts | Main Roof / Entire Building | 72 | LF | 6 | \$2,393 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Main Roof / Entire Building | 14,841 | SF | 7 | \$0 | |
| | Roof - Metal | Main Roof / Entire Building | 17,331 | SF | 5 | \$477,575 | missing snow diverters; engineer reports leaks throughout during heavy rain - no evidence at time of site visit |
| Walls | | | | | | | |
| | Canopy - Metal | Entire Building / Main Entrance | 40 | SF | 6 | \$859 | |
| | Cornice - Metal Projecting | Entire Building | 471 | LF | 6 | \$16,333 | |
| | Exterior Walls - Concrete Block | Entire Building | 3,698 | SF | 6 | \$24,854 | Split face masonry |
| | Exterior Walls - Concrete Block | Entire Building / South East | 6 | SF | 5 | \$67 | Split face masonry - Ipen joints/ loose mortar |
| | Exterior Walls - Stone-Cast | Entire Building | 138 | SF | 6 | \$927 | |
| Windov | ws | | | | | | |
| | Guard - Guards wire guard | Entire Building | 1,242 | SF | 6 | \$15,860 | all are padlocked |
| | Lintels - Steel | Entire Building | 138 | LF | 6 | \$4,006 | |
| | Skylite - Glass Double-Pane | Entire Building | 32 | SF | 6 | \$765 | |
| | Skylite - Lexan | Entire Building / Main Roof | 1,991 | SF | 4 | \$537,168 | engineer reports leaks during heavy rains - not visible at time of site visit |
| | Windows - Sash Aluminum Double-pane | Entire Building | 1,242 | SF | 6 | \$9,271 | |
| Build | ing Exterior Subtotal: | | | | \$ | 1.119.310 | |

Building Exterior Subtotal:

\$1,119,310

Building: CPC

Category: Electrical System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|-----------|----------|------|------|---------|----------|
| Emergency System | | | | | | |
| Emergency A/C Power - Corridors and Stairs | 1st Floor | 2,208 | SF | 6 | \$663 | |
| Emergency Battery Packs - Corridors and Stairs | 1st Floor | 15 | EA | 6 | \$3,038 | |
| Emergency battery racks - Contdors and Stairs | 1511 1001 | 13 | LA | U | φ3,030 | |



1420 S Albany Ave Chicago, IL 60623

Building: CPC

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | |
|---------|--|-----------------------------------|----------|------|------|----------|---|--|--|
| Emerge | Emergency System | | | | | | | | |
| | Exit Signs - Corridors and Stairs | 1st Floor | 9 | EA | 6 | \$1,348 | | | |
| | Security System - CCTV | Entire Building | 14,841 | SF | 6 | \$4,457 | | | |
| | Security System - Intrusion Detection | Entire Building | 14,841 | SF | 6 | \$3,820 | | | |
| Main Se | rvice | | | | | | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | \$2,921 | | | |
| | Main Electrical Service - 1200 A 120/208/3PH | Electrical Room | 1 | EA | 6 | \$5,078 | | | |
| Power D | Distribution | | | | | | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 1 | EA | 4 | \$6,578 | Fused EM panel | | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 1 | EA | 4 | \$6,578 | Fire damaged. Re-build but cover still poor shape | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 3 | EA | 6 | \$1,491 | | | |
| Electri | ical System Subtotal: | | | | | \$35,970 | | | |

Building: CPC

Category: Safty System

| roup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | | | |
|--------------------------|-----------------------------------|----------|------|------|----------|----------|--|--|--|--|
| Fire Alarm | | | | | | | | | | |
| Fire Alarm Panel | Mechanical Room | 1 | EA | 6 | \$6,406 | | | | | |
| Fire Alarm Strobe Lights | Mechanical Room / Entire Building | 14,841 | SF | 6 | \$5,306 | | | | | |
| Fire Alarm_System | Mechanical Room / Entire Building | 14,841 | SF | 6 | \$7,216 | | | | | |
| prinkler System | | | | | | | | | | |
| Sprinkler Heads | Entire Building | 14,841 | SF | 6 | \$0 | | | | | |
| Sprinkler Piping | Entire Building | 14,841 | SF | 6 | \$2,759 | | | | | |
| Wet Sprinkler System | Entire Building | 14,841 | SF | 6 | \$3,820 | | | | | |
| Safty System Subtotal: | | | | | \$25,506 | | | | | |

Building: CPC

Category: Mechanical System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | | |
|--|----------------------------------|----------|------|------|----------|--------------------------|--|--|--|
| Air Conditioning | | | | | | | | | |
| Condensing Unit- Ground Mounted - 31-50 tons | Outdoor courtyard | 2 | EA | 5 | \$28,856 | Location: courtyard | | | |
| Condensing Unit- Ground Mounted - Less than 5 tons | Entire Building / East Courtyard | 2 | EA | 6 | \$6,667 | Split system compressors | | | |



1420 S Albany Ave Chicago, IL 60623

Building: CPC

Category: Mechanical System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------------|----------|------|------|-----------|--|
| Air Handling Systems | | | | | | |
| Air Handling Unit- Package Multi Zone- Indoor- Hot Water and DX Cooling Coils - 10001-15000 cfm | Mechanical Room | 2 | EA | 5 | \$104,356 | |
| Air Intake | Mechanical Room / Roofs | 2 | EA | 6 | \$11,529 | |
| Auxiliaries - 10001-15000 cfm | Mechanical Room | 2 | EA | 6 | \$0 | |
| Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM | Roof | 2 | EA | 6 | \$3,181 | |
| Zone Dampers | Mechanical Room / Entire Building | 12 | EA | 6 | \$9,996 | |
| Boiler Systems | | | | | | |
| Boiler Auxiliary- Non Condensing Hot Water - Less than 500 MBH | Mechanical Room | 7 | EA | 6 | \$14,325 | |
| Chemical Pot Feeder | Mechanical Room | 1 | EA | 5 | \$1,685 | |
| Combustion Dampers | Mechanical Room | 1 | EA | 6 | \$409 | |
| Glycol Feed System | Mechanical Room | 1 | EA | 6 | \$539 | |
| Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - Less than 500 MBH | Mechanical Room | 7 | EA | 5 | \$161,321 | Comprised of 7 individual boilers rated at 300 MBH input |
| Water Fill System | Mechanical Room | 1 | EA | 6 | \$1,168 | |
| Heating Devices | | | | | | |
| Cabinet Heaters - With Hot Water Coil | 1st Floor | 2 | EA | 5 | \$3,510 | |
| Unit Heater - Hot Water | 1st Floor | 2 | EA | 6 | \$558 | Location: Boiler room and mechanical room |
| Mechanical Plumbing | | | | | | |
| Hot Water Pump - Less than 10 | Mechanical Room | 2 | EA | 5 | \$22,990 | |
| Hydronic Supply and Return - Steel | Entire Building | 200 | LF | 6 | \$15,355 | |
| Temperature Control | | | | | | |
| DDC System | Mechanical Room | 14,841 | SF | 6 | \$8,489 | |
| Thermostats - DDC | Mechanical Room / Entire Building | 12 | EA | 6 | \$0 | |
| Ventilation | | | | | | |
| Exhaust Fans- Indoor - Less than 500 CFM | Entire Building | 9 | EA | 6 | \$2,666 | Powered toilet exhaust fans |
| Type II Exhaust Hood- Warming Kitchen | Entire Building / 1st Floor | 1 | EA | 6 | \$920 | |
| Mechanical System Subtotal: | | | | | \$398,521 | |

Mechanicai System Subtotai:

Building: CPC

Category: Plumbing System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------------|-----------------|----------|------|------|---------|----------|
| Hot Water | | | | | | |
| Electric Heater - Less than 20 KW | Mechanical Room | 1 | EA | 5 | \$2,443 | |
| Electric Heater - Less than 20 KW | Mechanical Room | 1 | EA | 6 | \$682 | |



1420 S Albany Ave Chicago, IL 60623

Building: CPC

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------------------------|----------|------|------|----------|----------|
| Hot Wat | ter | | | | | | |
| | Gas Heater - Less than 150000 BTU/HR | Mechanical Room | 1 | EA | 6 | \$310 | |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 14,841 | SF | 6 | \$2,971 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 14,841 | SF | 6 | \$3,608 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 14,841 | SF | 6 | \$2,759 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 14,841 | SF | 6 | \$2,334 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 14,841 | SF | 6 | \$2,759 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 14,841 | SF | 6 | \$2,122 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 14,841 | SF | 6 | \$2,122 | |
| | Sanitary Piping | Entire Building | 14,841 | SF | 6 | \$13,582 | |
| | Storm Piping | Entire Building | 14,841 | SF | 6 | \$12,946 | |
| | Vent Piping | Entire Building | 14,841 | SF | 6 | \$9,975 | |
| Pumps | | | | | | | |
| | Pumps - Ejector-Duplex | Entire Building / Mechanical Room | 1 | EA | 6 | \$1,387 | |
| | Pumps - Sump-Simplex | Entire Building / Mechanical Room | 1 | EA | 6 | \$745 | |

Plumbing System Subtotal: \$60,746

Building: CPC

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|-----------|----------|------|------|---------|----------|
| Classro | oom #101 (Kindergarten) | | | | | | |
| | Casework | 1st Floor | 28 | LF | 6 | \$707 | |
| | Ceiling - Exposed | 1st Floor | 1,041 | SF | 6 | \$1,548 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 1,041 | SF | 6 | \$2,278 | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 10 | LF | 6 | \$214 | |
| | Walls - Concrete Block | 1st Floor | 1,157 | SF | 6 | \$3,392 | |
| | Walls - Plaster/Drywall | 1st Floor | 386 | SF | 6 | \$1,065 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #102 (Kindergarten) | | | | | | |
| | Casework | 1st Floor | 30 | LF | 6 | \$758 | |
| | Ceiling - Exposed | 1st Floor | 1,041 | SF | 6 | \$1,548 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |



1420 S Albany Ave Chicago, IL 60623

Building: CPC

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|----------|
| _ | oom #102 (Kindergarten) | | • | | | | |
| | Floor - Tile | 1st Floor | 1,041 | SF | 6 | \$2,278 | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EΑ | 7 | \$0 | |
| | Marker Board | 1st Floor | 10 | LF | 6 | \$214 | |
| | Walls - Concrete Block | 1st Floor | 977 | SF | 6 | \$2,864 | |
| | Walls - Plaster/Drywall | 1st Floor | 326 | SF | 6 | \$900 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #103 (Pre School) | | | | | | |
| | Casework | 1st Floor | 22 | LF | 6 | \$556 | |
| | Ceiling - Exposed | 1st Floor | 1,041 | SF | 6 | \$1,548 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 1,041 | SF | 6 | \$2,278 | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 10 | LF | 6 | \$214 | |
| | Walls - Concrete Block | 1st Floor | 326 | SF | 6 | \$956 | |
| | Walls - Plaster/Drywall | 1st Floor | 977 | SF | 6 | \$2,696 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #104 (Pre School) | | | | | | |
| | Casework | 1st Floor | 22 | LF | 6 | \$556 | |
| | Ceiling - Exposed | 1st Floor | 1,041 | SF | 6 | \$1,548 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 1,041 | SF | 6 | \$2,278 | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 10 | LF | 6 | \$214 | |
| | Walls - Concrete Block | 1st Floor | 651 | SF | 6 | \$1,908 | |
| | Walls - Plaster/Drywall | 1st Floor | 651 | SF | 6 | \$1,797 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #105 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 22 | LF | 6 | \$556 | |
| | Ceiling - Exposed | 1st Floor | 1,041 | SF | 6 | \$1,548 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 1,041 | SF | 6 | \$2,278 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 10 | LF | 6 | \$214 | |
| | Walls - Concrete Block | 1st Floor | 651 | SF | 6 | \$1,908 | |
| | Walls - Plaster/Drywall | 1st Floor | 651 | SF | 6 | \$1,797 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |



1420 S Albany Ave Chicago, IL 60623

Building: CPC

Category: Classrooms

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------------------------|-----------|----------|------|------|----------|----------|
| Classroom #105 (Regular Classroom) | | | | | | |
| Classroom #106 (Regular Classroom) | | | | | | |
| Casework | 1st Floor | 22 | LF | 6 | \$556 | |
| Ceiling - Exposed | 1st Floor | 1,041 | SF | 6 | \$1,548 | |
| Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | 1st Floor | 1,041 | SF | 6 | \$2,278 | |
| Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | \$0 | |
| Marker Board | 1st Floor | 10 | LF | 6 | \$214 | |
| Walls - Concrete Block | 1st Floor | 651 | SF | 6 | \$1,908 | |
| Walls - Plaster/Drywall | 1st Floor | 651 | SF | 6 | \$1,797 | |
| Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classrooms Subtotal: | | | | | \$54,995 | |

Building: CPC

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|-------------------------------|----------|------|------|---------|----------|
| Adminis | strative Suites/Offices | | | | | | |
| | Ceiling - Exposed | Teacher's lounge on west side | 493 | SF | 6 | \$733 | |
| | Doors - Wood Doors inclu hw | Teacher's lounge on west side | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Teacher's lounge on west side | 493 | SF | 6 | \$1,079 | |
| | Lighting - Pendent/Surface | Teacher's lounge on west side | 6 | EA | 7 | \$0 | |
| | Power Distribution | Teacher's lounge on west side | 8 | EA | 7 | \$0 | |
| | Storage/ Closet | Teacher's lounge on west side | 28 | SF | 6 | \$203 | |
| | Walls - Concrete Block | Teacher's lounge on west side | 458 | SF | 6 | \$1,343 | |
| | Walls - Plaster/Drywall | Teacher's lounge on west side | 1,374 | SF | 6 | \$3,792 | |
| | Work SInk | Teacher's lounge on west side | 1 | EA | 6 | \$508 | |
| Clinic | | | | | | | |
| | Ceiling - Lay-in | NW corner | 1,342 | SF | 6 | \$4,030 | |
| | Doors - Wood Doors inclu hw | NW corner | 6 | EΑ | 6 | \$1,806 | |
| | Floor - Tile/Sheet | NW corner | 1,342 | SF | 6 | \$1,343 | |
| | Lighting - Lay-in | NW corner | 26 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | NW corner | 1,350 | SF | 6 | \$3,958 | |
| | Walls - Plaster/Drywall | NW corner | 2,325 | SF | 6 | \$6,417 | |
| Kitchen | | | | | | | |
| | Ceiling - Lay-in | SW corner | 445 | SF | 6 | \$1,336 | |
| | | | | | | | |



1420 S Albany Ave Chicago, IL 60623

Building: CPC

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------|-----------------------------|-----------------------|----------|------|------|----------|---|
| Kitchen | • • | Location | Quantity | Cint | Main | 0031 | Commonto |
| . W.COLIGI | Doors - Steel Doors incl hw | SW corner | 1 | EA | 6 | \$301 | |
| | Floor - Tile | SW corner | 445 | SF | 6 | \$974 | |
| | Lighting - Lay-in | SW corner | 8 | EA | 7 | \$0 | |
| | Walls - Concrete Block | SW corner | 455 | SF | 6 | \$1,334 | |
| | Walls - Metal Panel | SW corner | 455 | SF | 6 | | FRP panels |
| | | OVV COME | 400 | Oi | O | ψ5,550 | TRI panois |
| MDF_ID | DF | | | | | | |
| | Doors - Steel Doors incl hw | Basement | 1 | EA | 4 | | Door is missing |
| | Finishes | Basement | 53 | SF | 4 | \$1,477 | Finishes missing due to recent flooding |
| | Ventilation and Cooling | Basement | 1 | EA | 4 | \$16,431 | Missing |
| Mechar | nical/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 27 | SF | 6 | \$193 | |
| | Interior Stairs | Basement | 30 | LF | 6 | \$271 | |
| | Mechanical/ Service Rooms | Basement | 1,746 | SF | 6 | \$12,509 | |
| | | | | | | | |
| Restroc | | | | | | | |
| | Accessories | East side of corridor | 39 | SF | 6 | \$360 | |
| | Ceiling - Exposed | East side of corridor | 39 | SF | 6 | \$58 | |
| | Doors - Wood Doors inclu hw | East side of corridor | 1 | EA | 6 | \$301 | |
| | Floor Drain | East side of corridor | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile/Sheet | East side of corridor | 39 | SF | 6 | \$39 | |
| | Lavatory | East side of corridor | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | East side of corridor | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | East side of corridor | 234 | SF | 6 | \$686 | |
| | Walls - Plaster/Drywall | East side of corridor | 78 | SF | 6 | \$215 | |
| | Water Closet | East side of corridor | 1 | EA | 6 | \$336 | |
| | Accessories | Inside classroom #105 | 39 | SF | 6 | \$360 | |
| | Ceiling - Exposed | Inside classroom #105 | 39 | SF | 6 | \$58 | |
| | Doors - Wood Doors inclu hw | Inside classroom #105 | 1 | EA | 6 | \$301 | |
| | Floor Drain | Inside classroom #105 | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile/Sheet | Inside classroom #105 | 39 | SF | 6 | \$39 | |
| | Lavatory | Inside classroom #105 | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Inside classroom #105 | 1 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | Inside classroom #105 | 234 | SF | 6 | \$686 | |
| | Walls - Plaster/Drywall | Inside classroom #105 | 78 | SF | 6 | \$215 | |
| | Water Closet | Inside classroom #105 | 1 | EA | 6 | \$336 | |
| | Accessories | Inside classroom #106 | 39 | SF | 6 | \$360 | |
| | Ceiling - Exposed | Inside classroom #106 | 39 | SF | 6 | \$58 | |
| | U | | | | - | 7-0 | |



1420 S Albany Ave Chicago, IL 60623

Building: CPC

| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|------------------------------|----------|------|------|---------|------------------------------|
| Restro | • • | | _,, | | | - 5500 | |
| | Doors - Wood Doors inclu hw | Inside classroom #106 | 1 | EA | 6 | \$301 | |
| | Floor Drain | Inside classroom #106 | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile/Sheet | Inside classroom #106 | 39 | SF | 6 | \$39 | |
| | Lavatory | Inside classroom #106 | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Inside classroom #106 | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Inside classroom #106 | 234 | SF | 6 | \$686 | |
| | Walls - Plaster/Drywall | Inside classroom #106 | 78 | SF | 6 | \$215 | |
| | Water Closet | Inside classroom #106 | 1 | EA | 6 | \$336 | |
| | Accessories | Inside clinic | 39 | SF | 6 | \$360 | |
| | Ceiling - Lay-in | Inside clinic | 39 | SF | 6 | \$117 | |
| | Ceiling - Lay-in | Inside clinic | 39 | SF | 6 | \$117 | |
| | Doors - Wood Doors inclu hw | Inside clinic | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | Inside clinic | 1 | EA | 6 | \$301 | |
| | Floor Drain | Inside clinic | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | Inside clinic | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile/Sheet | Inside clinic | 39 | SF | 6 | \$39 | |
| | Floor - Tile/Sheet | Inside clinic | 39 | SF | 6 | \$39 | |
| | Lavatory | Inside clinic | 1 | EA | 6 | \$320 | |
| | Lavatory | Inside clinic | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | Inside clinic | 1 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Inside clinic | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Inside clinic | 176 | SF | 6 | \$516 | |
| | Walls - Concrete Block | Inside clinic | 176 | SF | 6 | \$516 | |
| | Walls - Plaster/Drywall | Inside clinic | 59 | SF | 6 | \$163 | |
| | Walls - Plaster/Drywall | Inside clinic | 59 | SF | 6 | \$163 | |
| | Water Closet | Inside clinic | 1 | EA | 6 | \$336 | |
| | Water Closet | Inside clinic | 1 | EA | 6 | \$336 | |
| | Accessories | Inside Kindegarten Room #101 | 39 | SF | 6 | \$360 | |
| | Ceiling - Exposed | Inside Kindegarten Room #101 | 39 | SF | 6 | \$58 | |
| | Doors - Wood Doors inclu hw | Inside Kindegarten Room #101 | 1 | EA | 6 | \$301 | Dutch door |
| | Floor Drain | Inside Kindegarten Room #101 | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile/Sheet | Inside Kindegarten Room #101 | 39 | SF | 6 | \$39 | |
| | Lavatory | Inside Kindegarten Room #101 | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Inside Kindegarten Room #101 | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Inside Kindegarten Room #101 | 234 | SF | 6 | \$686 | |
| | Walls - Plaster/Drywall | Inside Kindegarten Room #101 | 78 | SF | 5 | \$591 | Drywall repair not completed |
| | Water Closet | Inside Kindegarten Room #101 | 1 | EA | 6 | \$336 | |
| | | | | | | | |



1420 S Albany Ave Chicago, IL 60623

Building: CPC

| oup Item - Type | | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|------------------|-------------------------------|----------|------|------|---------|------------|
| stroom | | | | | | | |
| Accessories | | Inside Kindergarten Room #102 | 39 | SF | 6 | \$360 | |
| Ceiling - Exp | osed | Inside Kindergarten Room #102 | 39 | SF | 6 | \$58 | |
| Doors - Wood | d Doors inclu hw | Inside Kindergarten Room #102 | 1 | EA | 6 | \$301 | Dutch door |
| Floor Drain | | Inside Kindergarten Room #102 | 1 | EA | 6 | \$1,059 | |
| Floor - Tile/Sh | neet | Inside Kindergarten Room #102 | 39 | SF | 6 | \$39 | |
| Lavatory | | Inside Kindergarten Room #102 | 1 | EA | 6 | \$320 | |
| Lighting - Pe | ndent/Surface | Inside Kindergarten Room #102 | 1 | EA | 7 | \$0 | |
| Walls - Conc | rete Block | Inside Kindergarten Room #102 | 234 | SF | 6 | \$686 | |
| Walls - Plaste | er/Drywall | Inside Kindergarten Room #102 | 78 | SF | 6 | \$215 | |
| Water Closet | | Inside Kindergarten Room #102 | 1 | EA | 6 | \$336 | |
| Accessories | | Inside Pre-K #103 | 39 | SF | 6 | \$360 | |
| Ceiling - Exp | osed | Inside Pre-K #103 | 39 | SF | 6 | \$58 | |
| Doors - Wood | d Doors inclu hw | Inside Pre-K #103 | 1 | EA | 6 | \$301 | |
| Floor Drain | | Inside Pre-K #103 | 1 | EA | 6 | \$1,059 | |
| Floor - Tile/Sh | neet | Inside Pre-K #103 | 39 | SF | 6 | \$39 | |
| Lavatory | | Inside Pre-K #103 | 1 | EA | 6 | \$320 | |
| Lighting - Pe | ndent/Surface | Inside Pre-K #103 | 1 | EA | 7 | \$0 | |
| Walls - Conc | rete Block | Inside Pre-K #103 | 234 | SF | 6 | \$686 | |
| Walls - Plaste | er/Drywall | Inside Pre-K #103 | 78 | SF | 6 | \$215 | |
| Water Closet | | Inside Pre-K #103 | 1 | EA | 6 | \$336 | |
| Accessories | | Inside Pre-K #104 | 39 | SF | 6 | \$360 | |
| Ceiling - Exp | osed | Inside Pre-K #104 | 39 | SF | 6 | \$58 | |
| Doors - Wood | d Doors inclu hw | Inside Pre-K #104 | 1 | EA | 6 | \$301 | |
| Floor Drain | | Inside Pre-K #104 | 1 | EA | 6 | \$1,059 | |
| Floor - Tile/Sh | neet | Inside Pre-K #104 | 39 | SF | 6 | \$39 | |
| Lavatory | | Inside Pre-K #104 | 1 | EA | 6 | \$320 | |
| Lighting - Pe | ndent/Surface | Inside Pre-K #104 | 1 | EA | 7 | \$0 | |
| Walls - Conc | rete Block | Inside Pre-K #104 | 234 | SF | 6 | \$686 | |
| Walls - Plaste | er/Drywall | Inside Pre-K #104 | 78 | SF | 6 | \$215 | |
| Water Closet | | Inside Pre-K #104 | 1 | EA | 6 | \$336 | |
| Accessories | | Inside teacher's lounge | 39 | SF | 6 | \$360 | |
| Ceiling - Plas | ster/Drywall | Inside teacher's lounge | 39 | SF | 6 | \$135 | |
| Doors - Wood | d Doors inclu hw | Inside teacher's lounge | 1 | EA | 6 | \$301 | |
| Floor Drain | | Inside teacher's lounge | 1 | EA | 6 | \$1,059 | |
| Floor - Tile/Sh | neet | Inside teacher's lounge | 39 | SF | 6 | \$39 | |
| Lavatory | | Inside teacher's lounge | 1 | EA | 6 | \$320 | |
| Lighting - Pe | ndent/Surface | Inside teacher's lounge | 1 | EA | 7 | \$0 | |



1420 S Albany Ave Chicago, IL 60623

Building: CPC

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------|-------------------------|----------|------|------|-------|----------|
| Restroc | m | | | | | | |
| | Walls - Concrete Block | Inside teacher's lounge | 234 | SF | 6 | \$686 | |
| | Water Closet | Inside teacher's lounge | 1 | EΑ | 6 | \$336 | |
| | | | | | | | |

Rooms (Other Than Classrooms) Subtotal:

\$100,559

Building: CPC

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|-----------------|----------|------|------|----------|----------|
| Corrido | r | | | | | | |
| | Ceiling - Exposed | 1st Floor | 2,208 | SF | 6 | \$3,284 | |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 6 | \$1,204 | |
| | Drinking Fountains - Double Fountain | 1st Floor | 2 | EA | 6 | \$672 | |
| | Floor - Tile/Sheet | 1st Floor | 2,208 | SF | 6 | \$1,200 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 3,258 | SF | 6 | \$9,551 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,328 | SF | 6 | \$5,887 | |
| Safety | | | | | | | |
| | Security Cameras | Entire building | 2 | EA | 6 | \$388 | |
| | Security Cameras | Entire building | 1 | EA | 6 | \$194 | |
| Buildi | ng Interior Subtotal: | | | | | \$22,379 | |

\$1,817,987

Total Building Cost

SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|---------------------------------|----------|------|------|----------|--|
| Civil/D | rainage | | | | | | |
| | Civil/ Drainage - Catch Basin | Annex CPC - entire site | 1 | EA | 6 | \$1,094 | |
| | Civil/ Drainage - Catch Basin | Main site | 10 | EA | 6 | \$10,938 | |
| | Civil/ Drainage - Site Drain | Main site | 1 | EA | 6 | \$310 | Location - boiler room exterior stairwell. |
| | Civil/ Drainage - Site Manhole | Annex CPC - entire site | 2 | EA | 6 | \$2,985 | |
| | Civil/ Drainage - Site Manhole | Main site | 9 | EA | 6 | \$13,435 | |
| Fencin | g | | | | | | |
| | Fencing - Chain Link | Main - Entire site / Site South | 92 | LF | 5 | \$5,611 | bent |



1420 S Albany Ave Chicago, IL 60623

SITE

Category: Site

| Group | Item - Type | Location | | Unit | Rank | Cost | Comments | | | | |
|---------|-----------------------------------|-------------------------------------|--------|------|------|----------|--|--|--|--|--|
| Fencing | | | | | | | | | | | |
| | Fencing - New Standard Ornamental | Annex CPC / North West | 18 | LF | 6 | \$574 | | | | | |
| | Fencing - New Standard Ornamental | Annex CPC / South West | 55 | LF | 6 | \$1,755 | | | | | |
| | Fencing - New Standard Ornamental | Main - Entire site / Entire Site | 963 | LF | 6 | \$30,723 | | | | | |
| | Fencing - New Standard Ornamental | Main - Entire site / North West | 63 | LF | 6 | \$2,010 | new ornamental on concrete wall | | | | |
| Landsc | аре | | | | | | | | | | |
| | Benches | Main - Entire Site | 1 | EA | 6 | \$430 | building mounted north elevation (55 LF) | | | | |
| | Landscape - Grass | Annex CPC | 1,657 | SF | 6 | \$1,374 | | | | | |
| | Landscape - Grass | Annex CPC / Site North | 814 | SF | 5 | \$1,234 | bare soil | | | | |
| | Landscape - Grass | Main - Entire Site / Entire Site | 10,732 | SF | 6 | \$8,901 | | | | | |
| | Landscape - Hardscape- Concrete | Main - Entire Site / East Courtyard | 5,124 | SF | 6 | \$26,452 | | | | | |
| | Landscape - Hardscape- Concrete | Main - Entire Site / East Courtyard | 1,800 | SF | 5 | \$19,743 | near entrances - cracks, movement | | | | |
| | Landscape - Hardscape- Concrete | Main - Entire Site / Site West | 948 | SF | 6 | \$5,761 | | | | | |
| | Parkway trees | Annex CPC | 10 | EA | 6 | \$6,600 | | | | | |
| | Parkway trees | Main - Entire Site / Entire Site | 19 | EΑ | 6 | \$12,541 | | | | | |
| | Planting Beds/ Area | Annex CPC | 876 | SF | 6 | \$1,441 | | | | | |
| | Planting Beds/ Area | Main - Entire Site | 1,879 | SF | 6 | \$3,090 | | | | | |
| | Retaining Wall - Concrete | Main - Entire Site | 620 | SF | 5 | \$33,159 | Location: N & S site - hairline cracks and spalling | | | | |
| | Retaining Wall - Concrete | Main - Entire Site / Boiler Room | 476 | SF | 5 | \$29,970 | spalling at top perimeter | | | | |
| | Trash Receptacles | Main - Entire Site / North West | 1 | EA | 5 | \$505 | missing appropriate bin | | | | |
| | Trash Receptacles | Main - Entire Site / Site - East | 2 | EA | 6 | \$625 | | | | | |
| Parking | J Lot | | | | | | | | | | |
| | Concrete Curbs | Annex CPC - West site | 94 | LF | 6 | \$1,207 | | | | | |
| | Concrete Curbs | Main - N site | 406 | LF | 6 | \$5,214 | | | | | |
| | Concrete Curbs | Main - SW site | 283 | LF | 6 | \$3,634 | | | | | |
| | Interior Plantings | Main - N site | 90 | LF | 6 | \$3,829 | | | | | |
| | Interior Plantings | Main - SW site | 170 | LF | 6 | \$7,232 | | | | | |
| | Lighting - Pole Mounted | Main - N site | 4 | EA | 6 | \$5,810 | | | | | |
| | Surface - Asphalt | Annex CPC - West site | 1,011 | SF | 5 | \$4,612 | water ponding, worn surface | | | | |
| | Surface - Asphalt | Main - N site | 10,852 | SF | 6 | \$26,226 | | | | | |
| | Surface - Asphalt | Main - SW site | 4,123 | SF | 6 | \$9,964 | | | | | |
| | Trash Compactor | Main - SW site | 1 | EΑ | 6 | \$0 | | | | | |
| | Trash Enclosure - Chain Links | Main - SW site | 206 | SF | 6 | \$3,614 | | | | | |
| | Trash Enclosure - Masonry | Main - SW site | 306 | SF | 5 | \$21,599 | Location: at trash compactor - efflorescence and bent gate | | | | |
| | Vehicular Screening | Annex CPC - West site | 18 | LF | 6 | \$1,417 | Č | | | | |
| | Vehicular Screening | Main - N site | 63 | LF | 6 | \$4,960 | | | | | |
| | | | | | | | | | | | |



1420 S Albany Ave Chicago, IL 60623

SITE

Category: Site

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | | |
|---|---------------------------------------|----------|------|------|-----------|--|--|--|--|
| Playground | | | | | | | | | |
| Equipment - School Age 5-12 | Main - NW site | 1 | EA | 6 | \$3,546 | Graffiti | | | |
| Surface - Poured Surface | Main - NW site | 3,368 | SF | 5 | \$46,284 | missing sections and melted plastic on surface | | | |
| Sidewalks | | | | | | | | | |
| Sidewalks - Internal Walks | Annex CPC - entire site | 244 | LF | 6 | \$2,931 | | | | |
| Sidewalks - Internal Walks | Main - entire site | 697 | LF | 6 | \$8,372 | | | | |
| Sidewalks - Internal Walks | Main - entire site / Site West | 50 | LF | 4 | \$4,859 | cracks, spalling, pitting | | | |
| Sidewalks - Internal Walks | Main - entire site / South East | 30 | LF | 4 | \$2,915 | cracks, spalling | | | |
| Sidewalks - Internal Walks | Main - entire site / South West | 50 | LF | 4 | \$4,859 | cracks, movement, pitting | | | |
| Sidewalks - Perimeter Sidewalks | Annex CPC - entire site | 2,244 | SF | 6 | \$4,460 | | | | |
| Sidewalks - Perimeter Sidewalks | Annex CPC - entire site / Site - East | 50 | SF | 5 | \$478 | cracks | | | |
| Sidewalks - Perimeter Sidewalks | Annex CPC - entire site / Site North | 200 | SF | 4 | \$3,218 | cracks, water ponding, movement | | | |
| Sidewalks - Perimeter Sidewalks | Main - entire site | 10,445 | SF | 6 | \$20,762 | | | | |
| Sidewalks - Perimeter Sidewalks | Main - entire site / Site South | 350 | SF | 5 | \$3,343 | cracks | | | |
| Sidewalks - Perimeter Sidewalks | Main - entire site / South East | 175 | SF | 5 | \$1,672 | cracks | | | |
| Signage | | | | | | | | | |
| Flag Pole - Flag Pole | Annex CPC - NE site | 1 | EA | 6 | \$1,657 | | | | |
| Flag Pole - Flag Pole | Main - Entire site / South East | 1 | EA | 6 | \$1,657 | | | | |
| Marquee - Free Standing Back lighted w/ LED | Main - Entire site / Site - East | 1 | EA | 6 | \$0 | | | | |
| Monument - Building Mounted Cut Letter Sign | Main - Entire site / East Façade | 1 | EA | 6 | \$0 | | | | |
| Site Subtotal: | e Subtotal: | | | | | | | | |
| Total Site Cost | | | | | \$431,593 | | | | |

Campus Total ^{2 3} \$5,003,432

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.



1420 S Albany Ave Chicago, IL 60623

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



1420 S Albany Ave Chicago, IL 60623

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | | + | • | * | | | * | | | • | | | * |
| Art Room | Regular Classroom | 4th Floor | 406 | 406 | 890 | 1 | 8 | 22 | 72 | 12 | 40 | Υ | N | N |
| Faculty Lounge | Regular Classroom | 3rd Floor | 301/302 | 301/302 | 1,840 | 3 | 13 | 38 | 183 | 80 | 40 | Υ | N | N |
| Library | Regular Classroom | 3rd Floor | 303/304 | 303/304 | 1,823 | 2 | 16 | 36 | 240 | 80 | 40 | Υ | Υ | N |
| Music Room | Regular Classroom | 2nd Floor | 201/202 | 201/ 202 | 1,840 | 3 | 13 | 38 | 300 | 100 | 40 | Υ | Υ | N |
| Office | Regular Classroom | 4th Floor | 403 | 403 | 890 | 1 | 8 | 22 | 120 | 40 | 40 | Υ | Υ | N |
| Office | Regular Classroom | 4th Floor | 404 | 404 | 890 | 1 | 8 | 22 | 120 | 40 | 40 | Υ | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 890 | 1 | 8 | 22 | 120 | 40 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 890 | 1 | 8 | 22 | 120 | 40 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 890 | 1 | 8 | 22 | 72 | 12 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 890 | 1 | 8 | 22 | 72 | 12 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 890 | 1 | 8 | 22 | 72 | 12 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 945 | 1 | 8 | 22 | 111 | 18 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 305 | 305 | 890 | 1 | 8 | 22 | 72 | 12 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 306 | 890 | 1 | 8 | 22 | 72 | 12 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 307 | 307 | 890 | 1 | 8 | 22 | 72 | 12 | 40 | Υ | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 308 | 945 | 1 | 8 | 22 | 111 | 18 | 40 | Υ | N | Y |
| Regular Classroom | Regular Classroom | 4th Floor | 401 | 401 | 945 | 1 | 8 | 22 | 111 | 18 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | 4th Floor | 402 | 402 | 890 | 1 | 8 | 22 | 120 | 40 | 40 | N | Υ | Y |
| Regular Classroom | Regular Classroom | 4th Floor | 405 | 405 | 890 | 1 | 8 | 22 | 72 | 12 | 40 | Υ | N | N |
| Regular Classroom | Regular Classroom | 4th Floor | 408 | 408 | 945 | 1 | 8 | 22 | 111 | 18 | 40 | Υ | N | Y |
| Science Classroom | Regular Classroom | 4th Floor | 407 | 407 | 975 | 1 | 8 | 22 | 72 | 12 | 40 | Υ | N | N |
| CPC | | | | | | | | | | | | | | |
| Kindergarten | Kindergarten | 1st Floor | 101 | 101 | 1,041 | 1 | 2 | 12 | 240 | 120 | 40 | N | Υ | Υ |
| Kindergarten | Kindergarten | 1st Floor | 102 | 102 | 1,041 | 1 | 2 | 12 | 240 | 120 | 40 | N | Υ | Υ |
| Pre School | Pre School | 1st Floor | 103 | 103 | 1,041 | 1 | 6 | 12 | 240 | 120 | 40 | N | Υ | N |
| Pre School | Pre School | 1st Floor | 104 | 104 | 1,041 | 1 | 6 | 12 | 240 | 120 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 105 | 105 | 1,041 | 1 | 6 | 12 | 240 | 120 | 40 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 1st Floor | 106 | 106 | 1,041 | 1 | 6 | 12 | 240 | 120 | 40 | N | Υ | N |