

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|---------------------|------------------|------------------|-----------------------|--------------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1893 | 3 | 44,587 | \$1,781,893 |
| Addition 1 | 1925 | 2 | 44,037 | \$2,534,832 |
| Addition 2 | 1975 | 2 | 47,014 | \$1,882,332 |
| SITE | | | | \$417,360 |
| Campus Total | | | 135,638 | \$6,616,418 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------|--|------------------------------|----------|------|------|----------|---------------|
| Entrance | | | | | | | |
| | Exterior Doors - Exterior Steel Door | #5.4- NW - Old B.R. | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | #5.5- NW - Ct Yrd | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | #5.6- NW | 2 | EA | 6 | \$961 | flaking paint |
| | Exterior Doors - Exterior Steel Door | #6- NW | 4 | EA | 4 | \$15,290 | gaps |
| | Exterior Doors - Exterior Steel Door | #6.1- NW | 1 | EA | 6 | \$481 | peeling paint |
| | Exterior Doors - Exterior Steel Door | Fire Escape Doors | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Overhead Rolling/ Garage Door | #5.3- NW | 1 | EA | 6 | \$1,433 | graffiti |
| | Exterior Doors - Transom Lite | #6- NW | 3 | EA | 6 | \$940 | |
| | Exterior Doors - Transom Lite | Fire Escape Doors | 2 | EA | 6 | \$627 | |
| | Exterior Stairs - Concrete | #6- NW | 12 | LF | 6 | \$981 | |
| Fire Escape | | | | | | | |
| | Fire Escape | Entire Building / South East | 78 | LF | 6 | \$49,277 | |
| Foundation | | | | | | | |
| | Foundation - Masonry | Entire Building | 498 | LF | 7 | \$0 | |
| | Superstructure - Heavy Timber | Entire Building | 44,587 | SF | 7 | \$0 | |

Building: Main

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------|---|---|----------|------|------|----------|--|
| Lighting | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 6 | EA | 6 | \$3,219 | need bulbs |
| | Exterior Lighting - Wall Mounted | Entire Building | 5 | EA | 6 | \$1,444 | need bulbs |
| | Exterior Lighting - Wall Mounted | Entire Building / South Courtyard Façades | 1 | EA | 5 | \$427 | at Fire Escape, light is pulling off wall |
| Roof System | | | | | | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | Low S roof | 75 | LF | 6 | \$71,601 | appears to be abandoned in place with no cap |
| | Chimney - Metal Flue | Low S roof | 26 | LF | 6 | \$4,112 | |
| | Coping - Stone | Elevator roof | 53 | LF | 6 | \$1,702 | |
| | Coping - Stone | Low NE roof | 22 | LF | 6 | \$707 | |
| | Coping - Stone | Low S roof | 176 | LF | 6 | \$5,653 | |
| | Coping - Stone | Low SE roof | 30 | LF | 6 | \$964 | |
| | Coping - Stone | Upper E Roof | 228 | LF | 6 | \$7,323 | |
| | Coping - Terra Cotta | Center roof | 63 | LF | 5 | \$10,575 | open joints |
| | Coping - Terra Cotta | Low Ct Yd roof | 10 | LF | 6 | \$321 | |
| | Coping - Terra Cotta | Mid Ct. Yd. Roof | 30 | LF | 5 | \$5,036 | open joints |
| | Coping - Terra Cotta | Mid Ct. Yd. Roof | 3 | LF | 4 | \$746 | broken, gaps |
| | Coping | Upper W roof | 228 | LF | 6 | \$0 | |
| | Downspouts - Exterior Downspouts | Center roof | 2 | LF | 6 | \$66 | |
| | Downspouts - Exterior Downspouts | Elevator roof | 20 | LF | 6 | \$665 | |
| | Downspouts - Exterior Downspouts | Low Ct Yd roof | 10 | LF | 6 | \$332 | |
| | Downspouts - Exterior Downspouts | Low NE roof | 10 | LF | 4 | \$1,355 | missing |
| | Downspouts - Exterior Downspouts | Low S roof | 21 | LF | 6 | \$698 | |
| | Downspouts - Exterior Downspouts | Low SE roof | 15 | LF | 6 | \$498 | |
| | Downspouts - Exterior Downspouts | Mid Ct. Yd. Roof | 5 | LF | 6 | \$166 | |
| | Downspouts - Exterior Downspouts | Upper E Roof | 76 | LF | 6 | \$2,526 | |
| | Downspouts - Exterior Downspouts | Upper W roof | 70 | LF | 6 | \$2,326 | |
| | Parapet - 16" - 30" Height | Center roof | 63 | LF | 6 | \$2,517 | |
| | Parapet - 16" - 30" Height | Elevator roof | 53 | LF | 6 | \$2,118 | |
| | Parapet - 16" - 30" Height | Low Ct Yd roof | 10 | LF | 6 | \$400 | |
| | Parapet - 16" - 30" Height | Low NE roof | 22 | LF | 6 | \$879 | |
| | Parapet - 16" - 30" Height | Low S roof | 176 | LF | 6 | \$7,032 | |
| | Parapet - 16" - 30" Height | Low SE roof | 30 | LF | 6 | \$1,199 | |
| | Parapet - 16" - 30" Height | Mid Ct. Yd. Roof | 10 | LF | 6 | \$479 | |
| | Parapet - 16" - 30" Height | Mid Ct. Yd. Roof | 23 | LF | 4 | \$13,044 | falling |
| | Parapet - 16" - 30" Height | Upper E Roof | 120 | LF | 6 | \$4,795 | |
| | Parapet - 16" - 30" Height | Upper W roof | 120 | LF | 6 | \$4,795 | |
| | Parapet - Parapet > 30" | Upper E Roof / East Façade | 93 | LF | 5 | \$22,945 | spalling |

Building: Main

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------|---|------------------------------|----------|------|------|-----------|--|
| Roof System | | | | | | | |
| | Parapet - Parapet > 30" | Upper E Roof / Façade- NE | 15 | LF | 2 | \$16,116 | falling brick |
| | Parapet - Parapet > 30" | Upper W roof | 213 | LF | 6 | \$13,615 | |
| | Roof Structure - Concrete | Low S roof | 1,942 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | Low SE roof | 484 | SF | 7 | \$0 | |
| | Roof Structure - Heavy Timber | Center roof | 681 | SF | 7 | \$0 | |
| | Roof Structure - Heavy Timber | Low Ct Yd roof | 130 | SF | 7 | \$0 | |
| | Roof Structure - Heavy Timber | Low NE roof | 60 | SF | 7 | \$0 | |
| | Roof Structure - Heavy Timber | Mid Ct. Yd. Roof | 610 | SF | 7 | \$0 | |
| | Roof Structure - Heavy Timber | Upper E Roof | 4,690 | SF | 7 | \$0 | |
| | Roof Structure - Heavy Timber | Upper W roof | 4,690 | SF | 7 | \$0 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Elevator roof | 205 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | Center roof | 681 | SF | 6 | \$6,408 | |
| | Roof - Modified Bitumen | Elevator roof | 205 | SF | 6 | \$1,929 | |
| | Roof - Modified Bitumen | Low Ct Yd roof | 130 | SF | 6 | \$1,223 | |
| | Roof - Modified Bitumen | Low NE roof | 60 | SF | 6 | \$565 | remove roof debris |
| | Roof - Modified Bitumen | Low S roof | 1,942 | SF | 6 | \$18,273 | not accessible |
| | Roof - Modified Bitumen | Low SE roof | 484 | SF | 6 | \$4,554 | not accessible |
| | Roof - Modified Bitumen | Mid Ct. Yd. Roof | 610 | SF | 6 | \$5,740 | |
| | Roof - Modified Bitumen | Upper E Roof | 4,690 | SF | 6 | \$44,130 | |
| | Roof - Modified Bitumen | Upper W roof | 4,690 | SF | 6 | \$44,130 | |
| Walls | | | | | | | |
| | Cornice - Masonry Projecting Limestone | Entire Building | 498 | LF | 6 | \$17,269 | |
| | Cornice - Metal Projecting | Entire Building | 197 | LF | 6 | \$6,831 | |
| | Exterior Walls - Brick | Entire Building | 28,603 | SF | 6 | \$192,241 | ivy at S Elev. |
| | Exterior Walls - Brick | Entire Building | 5 | SF | 4 | \$823 | missing at Fire Escape |
| | Exterior Walls - Brick | Entire Building | 30 | SF | 5 | \$714 | at Overhead door- step cracks & open joints, failing wood lintel |
| | Exterior Walls - Brick | Entire Building / Courtyard | 5 | SF | 5 | \$119 | step cracks |
| | Exterior Walls - Brick | Entire Building / North East | 10 | SF | 5 | \$238 | step cracks |
| | Exterior Walls - Brick | Entire Building / South | 50 | SF | 5 | \$1,190 | step cracks |
| | Exterior Walls - Stone-Cast | Entire Building | 800 | SF | 6 | \$5,377 | |
| | Exterior Walls - Stone-Cut | Entire Building | 800 | SF | 6 | \$5,377 | |
| Windows | | | | | | | |
| | Guard - Guards perforated | Entire Building / 1st Floor | 1,240 | SF | 6 | \$15,835 | |
| | Guard - Guards perforated | Entire Building / North West | 6 | SF | 5 | \$0 | torn |
| | Lintels - Brick | Entire Building | 249 | LF | 6 | \$0 | |
| | Lintels - Steel | Entire Building | 10 | LF | 6 | \$290 | at overhead door |

Building: Main

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------|-------------------------------------|-----------------|----------|------|------|----------|----------------|
| Windows | | | | | | | |
| | Lintels - Stone | Entire Building | 301 | LF | 6 | \$0 | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 5,120 | SF | 6 | \$38,219 | |
| | Windows - Sash Aluminum | Entire Building | 320 | SF | 6 | \$2,389 | at Fire Escape |

Building Exterior Subtotal:

\$698,171

Building: Main

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------------|--|--|----------|------|------|----------|----------|
| Emergency System | | | | | | | |
| | Automatic Transfer Switch | Mechanical Room | 1 | EA | 6 | \$408 | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building and Basement / Entire Building | 6,608 | SF | 4 | \$12,946 | |
| | Emergency A/C Power - Students Toilets | Entire Building and Basement / Basement | 517 | SF | 4 | \$1,013 | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 5 | EA | 6 | \$1,013 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 13 | EA | 6 | \$1,947 | |
| | Security System - CCTV | Entire Building | 44,587 | SF | 6 | \$13,389 | |
| | Security System - Intrusion Detection | Entire Building | 44,587 | SF | 6 | \$11,477 | |

Main Service

| | | | | | | | |
|--|--|-----------------|--------|----|---|----------|-----------------------------------|
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | \$2,921 | |
| | Main Electrical Service - 1200 A 120/208/3PH | Electrical Room | 1 | EA | 6 | \$5,078 | Also serves Addition 1, conformed |
| | PA System | Entire Building | 44,587 | SF | 6 | \$14,665 | |

Power Distribution

| | | | | | | | |
|--|--|---|---|----|---|---------|-------------------------|
| | Lighting and Power Panels - 100 A | Basement, Boiler Room and Electrical Room / Boiler Room | 1 | EA | 4 | \$4,849 | |
| | Lighting and Power Panels - 100 A | Basement, Boiler Room and Electrical Room / Boiler Room | 1 | EA | 4 | \$4,849 | |
| | Lighting and Power Panels - Above 100 A | Basement, Boiler Room and Electrical Room / Basement | 1 | EA | 7 | \$0 | Location Fire Pump Room |
| | Lighting and Power Panels - Above 100 A | Basement, Boiler Room and Electrical Room / Basement | 1 | EA | 4 | \$6,578 | Location: Old Tank Room |
| | Lighting and Power Panels - Above 100 A | Basement, Boiler Room and Electrical Room / Electrical Room | 1 | EA | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Basement, Boiler Room and Electrical Room / Electrical Room | 1 | EA | 7 | \$0 | |

Building: Main

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------------------------|-------------|----------|----------|------|------|-----------------|----------|
| Electrical System Subtotal: | | | | | | \$81,132 | |

Building: Main

Category: Safty System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------------------|--|----------------------------|----------|------|------|-----------------|--------------------------|
| Fire Alarm | | | | | | | |
| | Fire Alarm Panel | Basement | 1 | EA | 6 | \$6,406 | Serves also Addition 1 |
| | Fire Alarm Strobe Lights | Basement / Entire Building | 44,587 | SF | 6 | \$15,940 | |
| | Fire Alarm_System | Basement / Entire Building | 44,587 | SF | 6 | \$21,678 | |
| | Fire Pump Controller | Basement | 1 | EA | 6 | \$1,823 | Location: Fire Pump Room |
| Pump Room Assembly | | | | | | | |
| | Fire Pump - Less than 25hp | Fire Pump Room / Basement | 1 | EA | 6 | \$1,558 | Location: Fire Pump Room |
| | Jockey Pump | Fire Pump Room / Basement | 1 | EA | 6 | \$758 | Location: Fire Pump Room |
| Sprinkler System | | | | | | | |
| | Combination Wet and Dry Sprinkler System | Entire Building | 44,587 | SF | 6 | \$11,477 | |
| | Sprinkler Heads | Entire Building | 44,587 | SF | 7 | \$0 | |
| | Sprinkler Piping | Entire Building | 44,587 | SF | 6 | \$8,289 | |
| Safty System Subtotal: | | | | | | \$67,928 | |

Building: Main

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|---|--|----------|------|------|----------|--|
| Air Handling Systems | | | | | | | |
| | Air Handling Unit- Built Up-Multi Zone-Double Delivery-Dual Temperature Coils - 15000 - 30000 cfm | Basement | 1 | EA | 6 | \$6,050 | |
| | Air Intake | Basement / North Façade | 1 | EA | 6 | \$5,765 | |
| | Auxiliaries - 15000 - 30000 cfm | Basement | 1 | EA | 6 | \$5,788 | |
| | Outdoor Return Fans- Air Handling Unit Type - Greater than 20000 CFM | Roof | 1 | EA | 6 | \$2,077 | |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | Basement / Entire Building | 100 | LF | 5 | \$96,198 | |
| | Zone Dampers | Basement | 24 | EA | 6 | \$19,993 | |
| Heating Devices | | | | | | | |
| | Cabinet Heaters - With Electric Coil | Basement Corridor and 1st Floor stairs | 2 | EA | 6 | \$713 | Basement Corridor and 1st Floor stairs |
| | Fin Tube - Electric | Entire Building and Basement / Entire Building | 120 | LF | 6 | \$1,133 | |

Building: Main

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------|--|--|----------|------|------|----------|--------------------------------|
| Heating Devices | | | | | | | |
| | Fin Tube - Hot Water | Entire Building and Basement / Basement | 16 | LF | 4 | \$2,574 | |
| | Unit Heater - Hot Water | Basement | 8 | EA | 6 | \$2,233 | |
| | Wall Heater - Electric | Basement, 1st and 2nd Floor Student Restrooms | 2 | EA | 6 | \$278 | |
| | Wall Heater - Electric | Basement, 1st and 2nd Floor Student Restrooms / Basement | 4 | EA | 4 | \$4,330 | |
| Mechanical Plumbing | | | | | | | |
| | Hot Water Pump - Less than 10 | Basement / Mechanical Room | 1 | EA | 6 | \$1,111 | near ceiling, near AHU, only 1 |
| | Hydronic Supply and Return - Steel | Basement | 500 | LF | 6 | \$38,388 | |
| Temperature Control | | | | | | | |
| | DDC System | Entire Building | 44,587 | SF | 6 | \$25,504 | |
| | Thermostats - DDC | Entire Building | 30 | EA | 6 | \$0 | engineer's estimate |
| Ventilation | | | | | | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Lower Roof, Roof and South Facade / Lower Roof | 1 | EA | 6 | \$592 | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Lower Roof, Roof and South Facade / Roof | 1 | EA | 6 | \$296 | |
| | Type I Exhaust Hood- Culinary Arts | Lower Roof, Roof and South Facade / South Façade | 1 | EA | 6 | \$1,248 | |

Mechanical System Subtotal: \$214,270

Building: Main

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------|--|-----------------|----------|------|------|----------|------------------------|
| Hot Water | | | | | | | |
| | Gas Heater - Less than 150000 BTU/HR | Boiler Room | 1 | EA | 7 | \$0 | Also serves Addition 1 |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 44,587 | SF | 6 | \$8,926 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 44,587 | SF | 6 | \$10,839 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 44,587 | SF | 6 | \$8,289 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 44,587 | SF | 6 | \$7,014 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 44,587 | SF | 6 | \$8,289 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 44,587 | SF | 6 | \$6,376 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 44,587 | SF | 6 | \$6,376 | |

Building: Main

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------|----------------------|-----------------|----------|------|------|----------|-----------------|
| Piping | | | | | | | |
| | Sanitary Piping | Entire Building | 44,587 | SF | 6 | \$40,806 | |
| | Storm Piping | Entire Building | 44,587 | SF | 6 | \$38,893 | |
| | Vent Piping | Entire Building | 44,587 | SF | 6 | \$29,967 | |
| Pumps | | | | | | | |
| | Pumps - Sump-Simplex | Basement | 1 | EA | 6 | \$745 | Inside Sump Pit |

Plumbing System Subtotal:

\$166,520

Building: Main

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|-----------------------------------|
| Classroom #130 (Faculty Lounge) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 690 | SF | 6 | \$2,388 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 1st Floor | 690 | SF | 6 | \$4,864 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 12 | SF | 5 | \$61 | Location: SE corner; water damage |
| | Walls - Plaster/Drywall | 1st Floor | 1,378 | SF | 6 | \$3,803 | |
| Classroom #131 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 6 | LF | 6 | \$152 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 690 | SF | 6 | \$2,388 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 1st Floor | 690 | SF | 6 | \$4,864 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 16 | LF | 6 | \$343 | |
| | Storage/ Closet | 1st Floor | 10 | SF | 6 | \$73 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,378 | SF | 6 | \$3,803 | |
| Classroom #133 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 6 | LF | 6 | \$152 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 690 | SF | 6 | \$2,388 | |

Building: Main

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|----------|
| Classroom #133 (Regular Classroom) | | | | | | | |
| | Chalk Board | 1st Floor | 30 | LF | 4 | \$2,754 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 1st Floor | 690 | SF | 6 | \$4,864 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 20 | SF | 6 | \$145 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,378 | SF | 6 | \$3,803 | |
| Classroom #141 (Faculty Lounge) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 12 | LF | 6 | \$303 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 621 | SF | 6 | \$2,149 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 1st Floor | 621 | SF | 6 | \$4,378 | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,300 | SF | 6 | \$3,588 | |
| Classroom #143 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 6 | LF | 6 | \$152 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 835 | SF | 6 | \$2,890 | |
| | Chalk Board | 1st Floor | 30 | LF | 4 | \$2,754 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 1st Floor | 835 | SF | 6 | \$5,887 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | \$1,858 | |
| | Marker Board | 1st Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 100 | SF | 6 | \$725 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,350 | SF | 6 | \$3,726 | |
| Classroom #145 (Vacant) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 8 | LF | 6 | \$202 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 782 | SF | 6 | \$2,706 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |

Building: Main

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|----------|
| Classroom #145 (Vacant) | | | | | | | |
| | Floor - Wood | 1st Floor | 782 | SF | 6 | \$5,513 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 24 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,430 | SF | 6 | \$3,947 | |
| Classroom #147 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 8 | LF | 6 | \$202 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 782 | SF | 6 | \$2,706 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 1st Floor | 782 | SF | 6 | \$5,513 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 16 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 25 | SF | 6 | \$181 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,430 | SF | 6 | \$3,947 | |
| Classroom #149 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 6 | LF | 6 | \$152 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 835 | SF | 6 | \$2,890 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 1st Floor | 835 | SF | 6 | \$5,887 | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 30 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 25 | SF | 6 | \$181 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,482 | SF | 6 | \$4,090 | |
| Classroom #230 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 650 | SF | 6 | \$2,249 | |
| | Chalk Board | 2nd Floor | 40 | LF | 4 | \$3,672 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 2nd Floor | 650 | SF | 6 | \$4,582 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 18 | LF | 7 | \$0 | |

Building: Main

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|----------|
| Classroom #230 (Regular Classroom) | | | | | | | |
| | Storage/ Closet | 2nd Floor | 85 | SF | 6 | \$616 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,275 | SF | 6 | \$3,519 | |
| Classroom #231 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 795 | SF | 6 | \$2,751 | |
| | Chalk Board | 2nd Floor | 8 | LF | 4 | \$734 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 2nd Floor | 795 | SF | 6 | \$5,605 | |
| | Lighting - Pendent/Surface | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 138 | SF | 6 | \$1,001 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,410 | SF | 6 | \$3,891 | |
| Classroom #232 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 715 | SF | 6 | \$2,474 | |
| | Doors - Transom Window | 2nd Floor | 19 | SF | 6 | \$322 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 2nd Floor | 715 | SF | 6 | \$5,041 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 12 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 6 | SF | 6 | \$44 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,336 | SF | 6 | \$3,687 | |
| Classroom #233 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 670 | SF | 6 | \$2,319 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 2nd Floor | 670 | SF | 6 | \$4,723 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 160 | SF | 6 | \$1,160 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,295 | SF | 6 | \$3,574 | |

Building: Main

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|----------|
| Classroom #233 (Regular Classroom) | | | | | | | |
| Classroom #243 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 825 | SF | 6 | \$2,855 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 2nd Floor | 825 | SF | 6 | \$5,816 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 96 | SF | 6 | \$696 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,436 | SF | 6 | \$3,963 | |
| Classroom #245 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 770 | SF | 6 | \$2,665 | |
| | Chalk Board | 2nd Floor | 52 | LF | 4 | \$4,774 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 2nd Floor | 770 | SF | 6 | \$5,428 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 18 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,388 | SF | 6 | \$3,831 | |
| Classroom #247 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 800 | SF | 6 | \$2,768 | |
| | Chalk Board | 2nd Floor | 42 | LF | 4 | \$3,856 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 2nd Floor | 800 | SF | 6 | \$5,640 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 156 | SF | 6 | \$1,131 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,414 | SF | 6 | \$3,902 | |

Building: Main

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|--------------------------|
| Classroom #249 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 860 | SF | 6 | \$2,976 | |
| | Chalk Board | 2nd Floor | 40 | LF | 4 | \$3,672 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 5 | \$1,174 | Missing window (glazing) |
| | Floor - Wood | 2nd Floor | 860 | SF | 6 | \$6,063 | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 178 | SF | 6 | \$1,291 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,466 | SF | 6 | \$4,046 | |
| Classroom #343 (Regular Classroom) | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 3rd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 835 | SF | 6 | \$2,890 | |
| | Chalk Board | 3rd Floor | 36 | LF | 4 | \$3,305 | |
| | Doors - Transom Window | 3rd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 3rd Floor | 835 | SF | 6 | \$5,887 | |
| | Lighting - Pendent/Surface | 3rd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 3rd Floor | 175 | SF | 6 | \$1,269 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,456 | SF | 6 | \$4,018 | |
| Classroom #345 (Regular Classroom) | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 3rd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 782 | SF | 6 | \$2,706 | |
| | Chalk Board | 3rd Floor | 30 | LF | 4 | \$2,754 | |
| | Doors - Transom Window | 3rd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 3rd Floor | 782 | SF | 6 | \$5,513 | |
| | Lighting - Pendent/Surface | 3rd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 3rd Floor | 175 | SF | 6 | \$1,269 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,430 | SF | 6 | \$3,947 | |

Building: Main

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|----------|
| Classroom #347 (Regular Classroom) | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 3rd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 790 | SF | 6 | \$2,734 | |
| | Chalk Board | 3rd Floor | 42 | LF | 4 | \$3,856 | |
| | Doors - Transom Window | 3rd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 3rd Floor | 790 | SF | 6 | \$5,569 | |
| | Lighting - Pendent/Surface | 3rd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 3rd Floor | 175 | SF | 6 | \$1,269 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,405 | SF | 6 | \$3,878 | |
| Classroom #349 (Regular Classroom) | | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 3rd Floor | 4 | LF | 6 | \$101 | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 835 | SF | 6 | \$2,890 | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | \$169 | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 3rd Floor | 835 | SF | 6 | \$5,887 | |
| | Lighting - Pendent/Surface | 3rd Floor | 15 | EA | 6 | \$1,858 | |
| | Marker Board | 3rd Floor | 22 | LF | 7 | \$0 | |
| | Storage/ Closet | 3rd Floor | 192 | SF | 6 | \$1,392 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,445 | SF | 6 | \$3,988 | |

Classrooms Subtotal:

\$308,515

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|-------------------------------------|-----------|----------|------|------|---------|----------|
| Administrative Suites/Offices | | | | | | | |
| | AC Unit | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 351 | SF | 6 | \$1,215 | |
| | Doors - Side-lite | 1st Floor | 36 | SF | 6 | \$602 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 1st Floor | 351 | SF | 6 | \$2,475 | |
| | Lighting - Chandelier, Incandescent | 1st Floor | 5 | EA | 7 | \$0 | |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|-----------------------------|-----------------------|----------|------|------|----------|----------------------|
| Administrative Suites/Offices | | | | | | | |
| | Power Distribution | 1st Floor | 8 | EA | 6 | \$16,999 | |
| | Walls - Plaster/Drywall | 1st Floor | 858 | SF | 6 | \$2,368 | |
| | Work Slnk | 1st Floor | 1 | EA | 6 | \$508 | |
| | Ceiling - Plaster/Drywall | 2nd Floor - Office | 366 | SF | 6 | \$1,267 | |
| | Doors - Side-lite | 2nd Floor - Office | 24 | SF | 6 | \$401 | |
| | Doors - Transom Window | 2nd Floor - Office | 30 | SF | 6 | \$508 | |
| | Doors - Wood Doors inclu hw | 2nd Floor - Office | 1 | EA | 6 | \$301 | |
| | Floor - Wood | 2nd Floor - Office | 366 | SF | 6 | \$2,580 | |
| | Lighting - Pendent/Surface | 2nd Floor - Office | 6 | EA | 7 | \$0 | |
| | Power Distribution | 2nd Floor - Office | 10 | EA | 6 | \$21,249 | |
| | Walls - Plaster/Drywall | 2nd Floor - Office | 956 | SF | 6 | \$2,638 | |
| | Work Slnk | 2nd Floor - Office | 1 | EA | 6 | \$508 | |
| | Ceiling - Plaster/Drywall | Engineer's Office | 131 | SF | 6 | \$453 | |
| | Doors - Wood Doors inclu hw | Engineer's Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Engineer's Office | 131 | SF | 6 | \$287 | |
| | Lighting - Pendent/Surface | Engineer's Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | Engineer's Office | 4 | EA | 6 | \$8,500 | |
| | Storage/ Closet | Engineer's Office | 24 | SF | 6 | \$174 | |
| | Walls - Concrete Block | Engineer's Office | 265 | SF | 6 | \$777 | |
| | Walls - Plaster/Drywall | Engineer's Office | 105 | SF | 6 | \$290 | |
| Locker/Shower Room | | | | | | | |
| | Accessories | Basement | 67 | SF | 6 | \$263 | |
| | Ceiling - Plaster/ Drywall | Basement | 67 | SF | 6 | \$232 | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | \$301 | |
| | Floor - Concrete | Basement | 67 | SF | 6 | \$35 | |
| | Lighting - Pendent/Surface | Basement | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Basement | 261 | SF | 6 | \$765 | |
| MDF_IDF | | | | | | | |
| | AC Unit | 2nd Floor - Room 233A | 1 | EA | 6 | \$496 | |
| | Doors - Wood Doors inclu hw | 2nd Floor - Room 233A | 1 | EA | 6 | \$301 | |
| | Finishes | 2nd Floor - Room 233A | 160 | SF | 5 | \$2,583 | Damaged |
| Mechanical/ Service Rooms | | | | | | | |
| | Storage Room | 2nd Floor | 36 | SF | 6 | \$258 | 241A, 233B |
| | Janitor's Closet | 3rd Floor | 8 | SF | 6 | \$57 | |
| | Mechanical/ Service Rooms | 3rd Floor | 8 | SF | 6 | \$57 | 361 B elevator equip |
| | Storage Room | 3rd Floor | 8 | SF | 6 | \$57 | |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------------|---------------------------------|-----------------------|----------|------|------|---------|--------------------------|
| Mechanical/ Service Rooms | | | | | | | |
| | Interior Stairs | Basement | 39 | LF | 6 | \$352 | |
| | Janitor's Closet | Basement | 65 | SF | 6 | \$466 | |
| | Vaults | Basement | 60 | SF | 5 | \$968 | Water Intrusion and mold |
| Restroom | | | | | | | |
| | Accessories | Basement Men's Locker | 31 | SF | 6 | \$286 | |
| | Ceiling - Plaster/Drywall | Basement Men's Locker | 31 | SF | 5 | \$284 | |
| | Doors - Wood Doors inclu hw | Basement Men's Locker | 1 | EA | 6 | \$301 | |
| | Floor - Concrete | Basement Men's Locker | 31 | SF | 6 | \$16 | |
| | Lavatory | Basement Men's Locker | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | Basement Men's Locker | 1 | EA | 6 | \$124 | |
| | Walls - Concrete Block | Basement Men's Locker | 175 | SF | 6 | \$513 | |
| | Water Closet | Basement Men's Locker | 1 | EA | 6 | \$336 | |
| | Accessories | Basement | 316 | SF | 6 | \$2,915 | |
| | Accessories | Basement | 201 | SF | 6 | \$1,854 | |
| | Ceiling - Plaster/Drywall | Basement | 201 | SF | 6 | \$696 | |
| | Ceiling - Plaster/Drywall | Basement | 316 | SF | 6 | \$1,094 | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | \$301 | |
| | Floor Drain | Basement | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | Basement | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | Basement | 316 | SF | 6 | \$669 | |
| | Floor - Tile Ceramic/ Porcelain | Basement | 201 | SF | 6 | \$425 | |
| | Hand Dryer | Basement | 1 | EA | 6 | \$230 | |
| | Hand Dryer | Basement | 1 | EA | 6 | \$230 | |
| | Lavatory | Basement | 3 | EA | 6 | \$959 | |
| | Lavatory | Basement | 4 | EA | 6 | \$1,278 | |
| | Lighting - Pendent/Surface | Basement | 4 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Basement | 7 | EA | 7 | \$0 | |
| | Partitions | Basement | 2 | EA | 6 | \$594 | |
| | Partitions | Basement | 5 | EA | 6 | \$1,485 | |
| | Walls - Concrete Block | Basement | 84 | SF | 6 | \$246 | |
| | Walls - Concrete Block | Basement | 87 | SF | 6 | \$255 | |
| | Walls - Structural Glazed Tile | Basement | 762 | SF | 6 | \$2,397 | |
| | Walls - Structural Glazed Tile | Basement | 448 | SF | 6 | \$1,409 | |
| | Water Closet | Basement | 5 | EA | 6 | \$1,680 | |
| | Water Closet | Basement | 2 | EA | 6 | \$672 | |
| | Accessories | Engineer's Office | 29 | SF | 6 | \$267 | |

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|-----------------------------|-------------------|----------|------|------|-------|----------|
| Restroom | | | | | | | |
| | Ceiling - Plaster/Drywall | Engineer's Office | 29 | SF | 6 | \$100 | |
| | Doors - Wood Doors inclu hw | Engineer's Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Engineer's Office | 29 | SF | 6 | \$63 | |
| | Lavatory | Engineer's Office | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Engineer's Office | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Engineer's Office | 130 | SF | 6 | \$381 | |
| | Walls - Plaster/Drywall | Engineer's Office | 41 | SF | 6 | \$113 | |
| | Water Closet | Engineer's Office | 1 | EA | 6 | \$336 | |

Rooms (Other Than Classrooms) Subtotal:

\$98,409

Building: Main

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|--------------------------------------|-----------|----------|------|------|----------|-----------------------|
| Corridor | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 3,220 | SF | 6 | \$19,938 | |
| | Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 6 | \$336 | |
| | Floor - Wood | 1st Floor | 3,220 | SF | 6 | \$22,701 | |
| | Lighting - Pendent/Surface | 1st Floor | 36 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 3,302 | SF | 6 | \$14,638 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 15 | SF | 5 | \$262 | Peeling, water damage |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,987 | SF | 6 | \$12,303 | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 1 | EA | 6 | \$336 | |
| | Floor - Wood | 2nd Floor | 2,002 | SF | 6 | \$14,114 | |
| | Lighting - Pendent/Surface | 2nd Floor | 32 | EA | 6 | \$3,965 | |
| | Stairs - Wood | 2nd Floor | 6 | LF | 6 | \$70 | |
| | Walls - Plaster/Drywall | 2nd Floor | 2,235 | SF | 6 | \$9,908 | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 986 | SF | 6 | \$6,105 | |
| | Floor - Wood | 3rd Floor | 986 | SF | 6 | \$6,951 | |
| | Lighting - Pendent/Surface | 3rd Floor | 14 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,950 | SF | 6 | \$8,644 | |

Safety

| | | | | | | | |
|--|------------------------|-----------------------------|---|----|---|---------|--|
| | Camera Viewing Station | 1st Floor | 3 | EA | 6 | \$2,048 | |
| | Security Cameras | 1st Floor / Entire Building | 5 | EA | 6 | \$970 | |

Building: Main

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------|-------------------------------------|----------|----------|------|------|---------|----------|
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | East | 345 | SF | 6 | \$2,526 | |
| | Floor - Concrete | East | 200 | SF | 6 | \$106 | |
| | Handrails | East | 144 | LF | 6 | \$1,248 | |
| | Lighting - Chandelier, Incandescent | East | 6 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | East | 72 | LF | 6 | \$668 | |
| | Walls - Plaster/Drywall | East | 2,379 | SF | 6 | \$6,566 | |
| | Ceiling - Plaster/Drywall | West | 345 | SF | 6 | \$2,526 | |
| | Floor - Concrete | West | 200 | SF | 6 | \$106 | |
| | Handrails | West | 144 | LF | 6 | \$1,248 | |
| | Lighting - Chandelier, Incandescent | West | 3 | EA | 6 | \$1,433 | |
| | Stairs - Terrazzo | West | 72 | LF | 6 | \$668 | |
| | Walls - Plaster/Drywall | West | 2,379 | SF | 6 | \$6,566 | |

Building Interior Subtotal:

\$146,949

Total Building Cost

\$1,781,893

Building: Addition 1

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|--------------------------------------|-------------------------|----------|------|------|---------|----------|
| Entrance | | | | | | | |
| | Entrance Control - Audio and Video | #1- NE- Main Accessible | 1 | EA | 6 | \$702 | |
| | Exterior Doors - Exterior Steel Door | #1- NE- Main Accessible | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | #1.5- NE | 6 | EA | 6 | \$2,883 | |
| | Exterior Doors - Exterior Steel Door | #1.5- NE | 3 | EA | 6 | \$1,442 | |
| | Exterior Doors - Exterior Steel Door | #5.1- NE | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | #5.2- NE | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | #6.2- N | 4 | EA | 6 | \$1,922 | |
| | Exterior Doors - Exterior Steel Door | #7- N | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | #8- NE | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Transom Lite | #1- NE- Main Accessible | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | #5.1- NE | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | #5.2- NE | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | #6.2- N | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | #7- N | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Transom Lite | #8- NE | 1 | EA | 6 | \$313 | |

Building: Addition 1

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------|---|-------------------------|----------|------|------|----------|------------------|
| Entrance | | | | | | | |
| | Exterior Stairs - Concrete | #5.1- NE | 30 | LF | 5 | \$3,287 | cracks |
| | Exterior Stairs - Concrete | #5.2- NE | 8 | LF | 6 | \$654 | |
| | Exterior Stairs - Concrete | #6.2- N | 32 | LF | 6 | \$2,617 | In route to door |
| | Exterior Stairs - Steel or Aluminum | #5.2- NE | 32 | LF | 6 | \$123 | |
| | Exterior Stairs - Stone | #1.5- NE | 90 | LF | 5 | \$24,405 | open joints |
| | Exterior Stairs - Stone | #5.1- NE | 6 | LF | 6 | \$678 | |
| | Exterior Stairs - Stone | #7- N | 32 | LF | 5 | \$8,677 | gaps |
| | Exterior Stairs - Stone | #8- NE | 12 | LF | 5 | \$3,254 | gaps |
| | Power Door Operator and Controls | #1- NE- Main Accessible | 2 | EA | 6 | \$0 | |
| | Stair Handrail - Steel_Stair Handrail | #5.1- NE | 15 | LF | 6 | \$130 | |
| | Stair Handrail - Steel_Stair Handrail | #5.2- NE | 20 | LF | 6 | \$173 | |
| | Stair Handrail - Steel_Stair Handrail | #6.2- N | 18 | LF | 6 | \$156 | |
| Fire Escape | | | | | | | |
| | Fire Escape | Façade- NW | 25 | LF | 6 | \$15,794 | |
| Foundation | | | | | | | |
| | Foundation - Concrete | Entire Building | 782 | LF | 7 | \$0 | |
| | Foundation - Concrete | Entire Building | 5 | LF | 5 | \$2,760 | seepage |
| | Superstructure - Concrete | Entire Building | 44,037 | SF | 7 | \$0 | |
| Lighting | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 9 | EA | 6 | \$4,829 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 5 | EA | 6 | \$1,444 | need bulbs |
| Roof System | | | | | | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | Main Roof | 42 | LF | 6 | \$40,097 | |
| | Coping - Metal | Low W roof | 20 | LF | 6 | \$642 | |
| | Coping - Metal | Mid W roof | 50 | LF | 6 | \$1,606 | |
| | Coping - Stone | Low E roof | 43 | LF | 6 | \$1,381 | |
| | Coping - Stone | Main Roof | 752 | LF | 6 | \$24,153 | some open joints |
| | Coping - Stone | Mid W roof | 65 | LF | 6 | \$2,088 | |
| | Downspouts - Exterior Downspouts | Mid W roof | 5 | LF | 6 | \$166 | |
| | Downspouts - Interior Downspouts | Low E roof | 18 | LF | 6 | \$598 | |
| | Downspouts - Interior Downspouts | Low W roof | 12 | LF | 6 | \$399 | |
| | Downspouts - Interior Downspouts | Main Roof | 222 | LF | 6 | \$7,378 | |
| | Parapet - 16" - 30" Height | Low W roof | 20 | LF | 6 | \$799 | |
| | Parapet - 16" - 30" Height | Main Roof | 100 | LF | 6 | \$3,995 | |
| | Parapet - Parapet < 16" Height | Mid W roof | 115 | LF | 6 | \$2,450 | |

Building: Addition 1

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------|---|------------------------------|----------|------|------|-----------|----------------------------|
| Roof System | | | | | | | |
| | Parapet - Parapet > 30" | Low E roof | 43 | LF | 6 | \$2,749 | |
| | Parapet - Parapet > 30" | Main Roof | 652 | LF | 6 | \$41,676 | |
| | Roof Structure - Concrete | Low E roof | 134 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | Low W roof | 276 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | Main Roof | 20,644 | SF | 7 | \$0 | |
| | Roof Structure - Concrete | Mid W roof | 724 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | Low E roof | 134 | SF | 6 | \$1,261 | |
| | Roof - Modified Bitumen | Low W roof | 276 | SF | 6 | \$2,597 | |
| | Roof - Modified Bitumen | Main Roof | 20,644 | SF | 6 | \$194,248 | |
| | Roof - Modified Bitumen | Mid W roof | 724 | SF | 5 | \$15,230 | poor seams |
| Walls | | | | | | | |
| | Cheek-Wall - Concrete | Entire Building | 56 | SF | 6 | \$574 | |
| | Cornice - Masonry Projecting Limestone | Entire Building | 2,361 | LF | 6 | \$81,874 | |
| | Exterior Walls - Brick | Entire Building | 23,537 | SF | 6 | \$158,192 | |
| | Exterior Walls - Brick | Entire Building / South | 20 | SF | 5 | \$476 | At roof- step cracks |
| | Exterior Walls - Prefabricated Metal Panel Wall | Entire Building | 600 | SF | 6 | \$3,406 | at South Link |
| | Exterior Walls - Stone-Cast | Entire Building | 3,148 | SF | 6 | \$21,158 | some open joints |
| | Exterior Walls - Stone-Cast | Entire Building / South West | 10 | SF | 4 | \$1,816 | spalling, cracks & bulging |
| Windows | | | | | | | |
| | Curtain wall - Glazed Double Pane | Entire Building | 100 | SF | 6 | \$1,121 | |
| | Guard - Guards perforated | Entire Building / 1st Floor | 1,015 | SF | 6 | \$12,961 | |
| | Lintels - Steel | Entire Building | 139 | LF | 6 | \$4,035 | |
| | Lintels - Stone | Entire Building | 309 | LF | 6 | \$0 | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 4,607 | SF | 6 | \$34,389 | |
| | Windows - Sash Aluminum Double-pane | Entire Building / North | 34 | SF | 5 | \$1,832 | broken panes |

Building Exterior Subtotal:

\$747,941

Building: Addition 1

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------------|---|-----------------------------|----------|------|------|----------|----------|
| Emergency System | | | | | | | |
| | Emergency A/C Power - Auditorium and Aisle Lighting | Entire Building / 1st Floor | 3,186 | SF | 6 | \$1,686 | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 5,938 | SF | 4 | \$11,633 | |
| | Emergency A/C Power - Gym | Entire Building / 1st Floor | 2,867 | SF | 6 | \$1,066 | |
| | Emergency A/C Power - Students Toilets | Entire Building | 1,245 | SF | 6 | \$463 | |

Building: Addition 1

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------|--|---|----------|------|------|----------|--|
| Emergency System | | | | | | | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 6 | EA | 6 | \$1,215 | |
| | Exit Signs - Auditorium | Entire Building and 1st Floor / 1st Floor | 10 | EA | 6 | \$1,497 | |
| | Exit Signs - Corridors and Stairs | Entire Building and 1st Floor / Entire Building | 11 | EA | 6 | \$1,647 | |
| | Exit Signs - Gym | Entire Building and 1st Floor / 1st Floor | 2 | EA | 6 | \$315 | |
| | Security System - CCTV | Entire Building | 44,037 | SF | 6 | \$13,224 | |
| | Security System - Intrusion Detection | Entire Building | 44,037 | SF | 6 | \$11,335 | |
| Main Service | | | | | | | |
| | PA System | Entire Building | 47,093 | SF | 6 | \$15,489 | |
| Power Distribution | | | | | | | |
| | Lighting and Power Panels - 100 A | Basement | 1 | EA | 4 | \$4,849 | No Panel Designation and Problem with Front Cover (Wiring Exposed) |
| | Lighting and Power Panels - 100 A | Basement | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Basement | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Basement | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Basement | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Basement | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Basement | 1 | EA | 7 | \$0 | |

Electrical System Subtotal:

\$64,420

Building: Addition 1

Category: Safty System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------|--------------------------|-----------------|----------|------|------|----------|----------|
| Fire Alarm | | | | | | | |
| | Fire Alarm Strobe Lights | Entire Building | 44,037 | SF | 6 | \$15,743 | |
| | Fire Alarm_System | Entire Building | 44,037 | SF | 6 | \$21,411 | |

Safty System Subtotal:

\$37,154

Building: Addition 1

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|---|----------|----------|------|------|---------|----------|
| Air Handling Systems | | | | | | | |
| | Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm | Basement | 1 | EA | 6 | \$3,321 | |
| | Air Handling Unit- Built Up- Single Zone- Steam Coils - 4000 - 8000 cfm | Basement | 1 | EA | 6 | \$3,321 | |

Building: Addition 1

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|---|--|----------|------|------|-----------|--|
| Air Handling Systems | | | | | | | |
| | Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 | Basement | 1 | EA | 5 | \$66,438 | Hosing Rusted & Corroded w/soft metal in certain areas |
| | Air Intake | Basement / West Façade | 2 | EA | 6 | \$11,529 | Location: West Exterior Wall |
| | Air Intake | Basement / West Façade | 1 | EA | 6 | \$5,765 | Location: West Exterior Wall |
| | Auxiliaries - 15001 - 25000 cfm | Basement | 1 | EA | 6 | \$5,788 | |
| | Auxiliaries - 4000 - 8000 cfm | Basement | 2 | EA | 6 | \$6,642 | |
| | Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM | Entire Building / Roof | 1 | EA | 6 | \$1,591 | |
| | Outdoor Return Fans- Air Handling Unit Type - 5000 - 10000 CFM | Entire Building / Roof | 1 | EA | 6 | \$1,591 | |
| | Outdoor Return Fans- Air Handling Unit Type - 5000 - 10000 CFM | Entire Building / Roof | 1 | EA | 6 | \$1,591 | |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | Basement / Entire Building | 200 | LF | 5 | \$192,395 | |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | Basement / Entire Building | 100 | LF | 5 | \$96,198 | |
| | Zone Dampers | Basement / Entire Building | 21 | EA | 6 | \$17,494 | Louvers Rusted & Corroded |
| Boiler Systems | | | | | | | |
| | Condensate Pump | Basement and Entire Building / Basement | 2 | EA | 5 | \$36,392 | |
| | Piping - Condensate Pipe- Steel | Basement and Entire Building / Entire Building | 500 | LF | 6 | \$944 | |
| | Piping - Steam Pipe- Steel | Basement and Entire Building / Entire Building | 500 | LF | 6 | \$944 | |
| | Steam Traps | Basement and Entire Building / Entire Building | 20 | EA | 5 | \$26,298 | |
| Heating Devices | | | | | | | |
| | Fin Tube - Steam | Entire Building | 24 | LF | 5 | \$1,954 | |
| | Radiators - Steam | Entire Building | 17 | EA | 5 | \$28,480 | |
| | Wall Heater - Electric | 1st and 2nd Floor / 1st Floor | 2 | EA | 6 | \$278 | |
| | Wall Heater - Electric | 1st and 2nd Floor / 2nd Floor | 2 | EA | 4 | \$2,165 | |
| Mechanical Plumbing | | | | | | | |
| | Condensate-Steel or Galvanized | Entire Building | 500 | LF | 6 | \$38,388 | |
| Temperature Control | | | | | | | |
| | DDC System | Entire Building | 44,037 | SF | 6 | \$25,189 | |
| | Thermostats - DDC | Entire Building | 15 | EA | 6 | \$0 | |
| Ventilation | | | | | | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Roof | 3 | EA | 6 | \$1,777 | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Roof | 1 | EA | 4 | \$1,942 | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Roof | 1 | EA | 6 | \$296 | |

Building: Addition 1

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------------------------|-------------|----------|----------|------|------|------------------|----------|
| Mechanical System Subtotal: | | | | | | \$578,710 | |

Building: Addition 1

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------|--|-----------------|----------|------|------|----------|----------|
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 44,037 | SF | 6 | \$8,816 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 44,037 | SF | 6 | \$10,705 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 44,037 | SF | 6 | \$8,186 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 44,037 | SF | 6 | \$6,927 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 44,037 | SF | 6 | \$8,186 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 44,037 | SF | 6 | \$6,297 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 44,037 | SF | 6 | \$6,297 | |
| | Sanitary Piping | Entire Building | 44,037 | SF | 6 | \$40,303 | |
| | Storm Piping | Entire Building | 44,037 | SF | 6 | \$38,413 | |
| | Vent Piping | Entire Building | 44,037 | SF | 6 | \$29,597 | |
| Pumps | | | | | | | |
| | Pumps - Sump-Duplex | Basement | 1 | EA | 6 | \$1,387 | |

Plumbing System Subtotal:

\$165,117

Building: Addition 1

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|---|
| Classroom #124 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 712 | SF | 6 | \$2,464 | |
| | Doors - Transom Window | 1st Floor | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 1st Floor | 712 | SF | 6 | \$1,558 | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 6 | \$1,487 | exposed electrical wiring above at hole in wall |
| | Marker Board | 1st Floor | 11 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,221 | SF | 6 | \$3,370 | |
| Classroom #126 (Kindergarten) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |

Building: Addition 1

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|---|
| Classroom #126 (Kindergarten) | | | | | | | |
| | Casework | 1st Floor | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 722 | SF | 6 | \$2,499 | |
| | Chalk Board | 1st Floor | 8 | LF | 4 | \$734 | |
| | Doors - Transom Window | 1st Floor | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 1st Floor | 722 | SF | 6 | \$1,580 | |
| | Lighting - Pendent/Surface | 1st Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 10 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,174 | SF | 6 | \$3,240 | |
| Classroom #127 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 32 | LF | 6 | \$808 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 768 | SF | 6 | \$2,658 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 768 | SF | 6 | \$1,680 | |
| | Lighting - Pendent/Surface | 1st Floor | 14 | EA | 6 | \$1,735 | exposed electrical wiring above at hole in wall |
| | Marker Board | 1st Floor | 19 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,281 | SF | 6 | \$3,535 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #129 (Kindergarten) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 19 | LF | 6 | \$480 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,194 | SF | 6 | \$4,132 | |
| | Doors - Transom Window | 1st Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | 1st Floor | 99 | SF | 6 | \$217 | |
| | Floor - Tile | 1st Floor | 1,095 | SF | 6 | \$2,396 | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 11 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 247 | SF | 6 | \$1,791 | wall crack at west storage |
| | Walls - Plaster/Drywall | 1st Floor | 1,247 | SF | 6 | \$3,442 | |
| | Work Sink | 1st Floor | 3 | EA | 6 | \$1,137 | 2 - in base cabinet / 1 - old cast iron pedestal in storage |
| Classroom #224 (Faculty Lounge) | | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 6 | \$991 | |

Building: Addition 1

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|-----------------------------|-----------|----------|------|------|---------|----------|
| Classroom #224 (Faculty Lounge) | | | | | | | |
| | Casework | 2nd Floor | 8 | LF | 6 | \$202 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 716 | SF | 6 | \$2,478 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Doors - Transom Window | 2nd Floor | 18 | SF | 6 | \$305 | |
| | Floor - Tile | 2nd Floor | 716 | SF | 6 | \$1,567 | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,255 | SF | 6 | \$3,464 | |
| Classroom #225 (Computer Lab) | | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 6 | \$991 | |
| | Casework | 2nd Floor | 9 | LF | 6 | \$227 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 720 | SF | 6 | \$2,492 | |
| | Chalk Board | 2nd Floor | 26 | LF | 4 | \$2,387 | |
| | Charging Station | 2nd Floor | 1 | EA | 6 | \$485 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 720 | SF | 6 | \$1,575 | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 9 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,242 | SF | 6 | \$3,428 | |
| | Wireless System | 2nd Floor | 1 | EA | 6 | \$372 | |
| Classroom #226 (Computer Lab) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 58 | LF | 6 | \$1,465 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 832 | SF | 6 | \$2,879 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 832 | SF | 6 | \$1,820 | |
| | Lighting - Pendent/Surface | 2nd Floor | 14 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,505 | SF | 6 | \$4,154 | |
| Classroom #229 (Multi Purpose Room) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 10 | LF | 6 | \$253 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 724 | SF | 6 | \$2,505 | |
| | Chalk Board | 2nd Floor | 46 | LF | 6 | \$1,026 | |
| | Doors - Transom Window | 2nd Floor | 9 | SF | 6 | \$152 | |

Building: Addition 1

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|-----------------------------|-----------|----------|------|------|---------|----------------------|
| Classroom #229 (Multi Purpose Room) | | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 714 | SF | 6 | \$1,562 | |
| | Floor - Tile | 2nd Floor | 10 | SF | 5 | \$58 | buldge / cracks |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | \$0 | 1 - charging station |
| | Marker Board | 2nd Floor | 18 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,248 | SF | 6 | \$3,444 | hole |

Classrooms Subtotal:

\$89,559

Building: Addition 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|--------------------------------|-------------------------------------|----------|------|------|----------|--|
| Administrative Suites/Offices | | | | | | | |
| | Ceiling | 1st - 120A Supply Rm / 122 Security | 576 | | 6 | \$0 | |
| | Doors - Wood Doors inclu hw | 1st - 120A Supply Rm / 122 Security | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 1st - 120A Supply Rm / 122 Security | 486 | SF | 6 | \$1,036 | |
| | Floor - Terrazzo | 1st - 120A Supply Rm / 122 Security | 16 | SF | 6 | \$43 | 16' Terrazzo stairs / 32' handrails |
| | Floor - Terrazzo | 1st - 120A Supply Rm / 122 Security | 28 | SF | 6 | \$61 | |
| | Lighting - Pendent/Surface | 1st - 120A Supply Rm / 122 Security | 7 | EA | 6 | \$867 | |
| | Power Distribution | 1st - 120A Supply Rm / 122 Security | 6 | EA | 6 | \$12,749 | exposed electrical wiring at open junction box |
| | Storage/ Closet | 1st - 120A Supply Rm / 122 Security | 171 | SF | 6 | \$1,240 | |
| | Walls - Plaster/Drywall | 1st - 120A Supply Rm / 122 Security | 619 | SF | 6 | \$1,708 | |
| | Walls - Structural Glazed Tile | 1st - 120A Supply Rm / 122 Security | 619 | SF | 6 | \$1,947 | |
| | Work Slnk | 1st - 120A Supply Rm / 122 Security | 2 | EA | 3 | \$15,339 | not in use/not operating |
| | AC Unit | 1st - 123 Main Office | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st - 123 Main Office | 326 | SF | 6 | \$1,128 | |
| | Doors - Transom Window | 1st - 123 Main Office | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st - 123 Main Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st - 123 Main Office | 326 | SF | 6 | \$713 | |
| | Lighting - Pendent/Surface | 1st - 123 Main Office | 3 | EA | 7 | \$0 | |
| | Power Distribution | 1st - 123 Main Office | 8 | EA | 6 | \$16,999 | |
| | Storage/ Closet | 1st - 123 Main Office | 157 | SF | 6 | \$1,138 | |
| | Walls - Plaster/Drywall | 1st - 123 Main Office | 963 | SF | 6 | \$2,658 | |
| | AC Unit | 1st - 125 Principle Office | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st - 125 Principle Office | 718 | SF | 6 | \$2,485 | |
| | Doors - Transom Window | 1st - 125 Principle Office | 9 | SF | 6 | \$152 | |
| | Doors - Wood Doors inclu hw | 1st - 125 Principle Office | 1 | EA | 6 | \$301 | |

Building: Addition 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|--------------------------------|---------------------------------------|----------|------|------|----------|----------------------------|
| Administrative Suites/Offices | | | | | | | |
| | Floor - Carpet | 1st - 125 Principle Office | 718 | SF | 6 | \$1,530 | |
| | Lighting - Pendent/Surface | 1st - 125 Principle Office | 12 | EA | 7 | \$0 | |
| | Power Distribution | 1st - 125 Principle Office | 11 | EA | 6 | \$23,374 | |
| | Storage/ Closet | 1st - 125 Principle Office | 3 | SF | 6 | \$22 | |
| | Walls - Plaster/Drywall | 1st - 125 Principle Office | 1,184 | SF | 6 | \$3,268 | |
| | Ceiling - Plaster/Drywall | 1st - Gym Office | 116 | SF | 6 | \$401 | |
| | Ceiling - Plaster/Drywall | 1st - Gym Office | 5 | SF | 4 | \$109 | cracks / peeling / stained |
| | Doors - Wood Doors inclu hw | 1st - Gym Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st - Gym Office | 111 | SF | 6 | \$243 | |
| | Lighting - Pendent/Surface | 1st - Gym Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | 1st - Gym Office | 2 | EA | 6 | \$4,250 | |
| | Walls - Masonry | 1st - Gym Office | 153 | SF | 6 | \$481 | |
| | Walls - Plaster/Drywall | 1st - Gym Office | 153 | SF | 6 | \$422 | |
| | Ceiling - Plaster/Drywall | 1st - janitors room inside 120A / 122 | 484 | SF | 6 | \$1,675 | |
| | Doors - Wood Doors inclu hw | 1st - janitors room inside 120A / 122 | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st - janitors room inside 120A / 122 | 484 | SF | 6 | \$1,059 | |
| | Lighting - Pendent/Surface | 1st - janitors room inside 120A / 122 | 7 | EA | 7 | \$0 | |
| | Power Distribution | 1st - janitors room inside 120A / 122 | 6 | EA | 6 | \$12,749 | |
| | Walls - Plaster/Drywall | 1st - janitors room inside 120A / 122 | 264 | SF | 6 | \$729 | |
| | Walls - Structural Glazed Tile | 1st - janitors room inside 120A / 122 | 594 | SF | 6 | \$1,869 | |
| | Work Slnk | 1st - janitors room inside 120A / 122 | 1 | EA | 6 | \$508 | |
| | Ceiling - Plaster/Drywall | 1st - Office in 123 | 137 | SF | 6 | \$474 | |
| | Doors - Wood Doors inclu hw | 1st - Office in 123 | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st - Office in 123 | 137 | SF | 6 | \$300 | |
| | Lighting - Pendent/Surface | 1st - Office in 123 | 1 | EA | 7 | \$0 | |
| | Power Distribution | 1st - Office in 123 | 2 | EA | 6 | \$4,250 | |
| | Walls - Plaster/Drywall | 1st - Office in 123 | 70 | SF | 6 | \$229 | wood paneling |
| | Walls - Plaster/Drywall | 1st - Office in 123 | 533 | SF | 6 | \$1,471 | |
| | Ceiling - Plaster/Drywall | 2nd - 287 Teachers Lounge | 168 | SF | 6 | \$581 | |
| | Doors - Wood Doors inclu hw | 2nd - 287 Teachers Lounge | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd - 287 Teachers Lounge | 168 | SF | 6 | \$368 | |
| | Lighting - Pendent/Surface | 2nd - 287 Teachers Lounge | 4 | EA | 7 | \$0 | |
| | Power Distribution | 2nd - 287 Teachers Lounge | 4 | EA | 6 | \$8,500 | |
| | Walls - Plaster/Drywall | 2nd - 287 Teachers Lounge | 906 | SF | 6 | \$2,500 | |
| | AC Unit | 2nd - Office | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd - Office | 616 | SF | 6 | \$2,132 | |
| | Doors - Transom Window | 2nd - Office | 9 | SF | 6 | \$152 | |

Building: Addition 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|---|--------------|----------|------|------|----------|--|
| Administrative Suites/Offices | | | | | | | |
| | Doors - Wood Doors inclu hw | 2nd - Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd - Office | 10 | SF | 4 | \$130 | cracks |
| | Floor - Tile | 2nd - Office | 606 | SF | 6 | \$1,326 | |
| | Lighting - Pendent/Surface | 2nd - Office | 10 | EA | 7 | \$0 | |
| | Power Distribution | 2nd - Office | 6 | EA | 6 | \$12,749 | |
| | Storage/ Closet | 2nd - Office | 425 | SF | 4 | \$11,845 | 229A - wall peeling / holes, cracks, stained ceiling |
| | Walls - Plaster/Drywall | 2nd - Office | 1,059 | SF | 6 | \$2,923 | |
| | AC Unit | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 690 | SF | 6 | \$2,388 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 2nd Floor | 641 | SF | 6 | \$1,366 | |
| | Floor - Terrazzo | 2nd Floor | 9 | SF | 6 | \$20 | 9 ft of terrazzo stairs, 18 ft handrails |
| | Lighting - Pendent/Surface | 2nd Floor | 6 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Power Distribution | 2nd Floor | 2 | EA | 6 | \$4,250 | |
| | Storage/ Closet | 2nd Floor | 104 | SF | 6 | \$754 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,489 | SF | 6 | \$4,109 | |
| Auditorium & Theater | | | | | | | |
| | Balcony Seating | 1st Floor | 175 | EA | 6 | \$30,435 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 3,626 | SF | 6 | \$30,230 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 12 | EA | 6 | \$3,612 | |
| | Floor - Terrazzo | 1st Floor | 440 | SF | 6 | \$963 | |
| | Floor - Tile/Sheet | 1st Floor | 3,186 | SF | 6 | \$3,189 | |
| | Lighting - Metal Halide/ High Pressure Sodium | 1st Floor | 6 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 10 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 1st Floor | 8 | EA | 7 | \$0 | |
| | Main Floor Seating | 1st Floor | 368 | EA | 6 | \$64,001 | |
| | Sound System | 1st Floor | 2 | EA | 6 | \$21,441 | |
| | Stage | 1st Floor | 759 | SF | 6 | \$4,385 | |
| | Stage Curtain | 1st Floor | 5 | EA | 6 | \$0 | |
| | Stage Lift | 1st Floor | 1 | EA | 6 | \$6,510 | |
| | Stage Lighting System | 1st Floor | 10 | EA | 7 | \$0 | 45 - colored spotlights / 10 - hanging |
| | Stage-Stairs - Wood | 1st Floor | 5 | LF | 6 | \$59 | |
| | Stairs - Terrazzo | 1st Floor | 62 | LF | 6 | \$474 | 10' up to stage / 52' Asphalt at balcony level |
| | Storage/ Closet | 1st Floor | 106 | SF | 6 | \$769 | projector room at balcony |
| | Walls - Plaster/Drywall | 1st Floor | 7,511 | SF | 6 | \$35,767 | |

Building: Addition 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------------|---|---------------------------|----------|------|------|----------|--|
| Auditorium & Theater | | | | | | | |
| | Walls - Plaster/Drywall | 1st Floor | 20 | SF | 5 | \$226 | cracks / holes at front of stage knee wall |
| Gymnasia | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st - 115 Gymnasium | 2,867 | SF | 6 | \$15,825 | |
| | Doors - Wood Doors inclu hw | 1st - 115 Gymnasium | 4 | EA | 6 | \$1,204 | |
| | Floor - Wood | 1st - 115 Gymnasium | 2,867 | SF | 6 | \$20,212 | |
| | Lighting - Metal Halide/ High Pressure Sodium | 1st - 115 Gymnasium | 12 | EA | 7 | \$0 | |
| | Scoreboards | 1st - 115 Gymnasium | 1 | EA | 6 | \$2,244 | |
| | Storage/ Closet | 1st - 115 Gymnasium | 91 | SF | 6 | \$660 | |
| | Walls - Concrete Block | 1st - 115 Gymnasium | 1,204 | SF | 6 | \$3,530 | |
| | Walls - Plaster/Drywall | 1st - 115 Gymnasium | 2,593 | SF | 6 | \$7,156 | |
| | Walls - Structural Glazed Tile | 1st - 115 Gymnasium | 1,446 | SF | 6 | \$4,549 | |
| Library | | | | | | | |
| | AC Unit | 2nd - 217 Library | 1 | EA | 6 | \$496 | |
| | Casework | 2nd - 217 Library | 66 | LF | 6 | \$1,667 | |
| | Ceiling - Plaster/Drywall | 2nd - 217 Library | 1,100 | SF | 6 | \$3,807 | |
| | Doors - Transom Window | 2nd - 217 Library | 18 | SF | 6 | \$305 | |
| | Doors - Wood Doors inclu hw | 2nd - 217 Library | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | 2nd - 217 Library | 1,100 | SF | 6 | \$2,344 | |
| | Lighting - Pendent/Surface | 2nd - 217 Library | 20 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd - 217 Library | 1,810 | SF | 6 | \$4,995 | |
| MDF_IDF | | | | | | | |
| | AC Unit | 2nd - 227A inside Library | 1 | EA | 6 | \$496 | |
| | Doors - Wood Doors inclu hw | 2nd - 227A inside Library | 1 | EA | 6 | \$301 | |
| | Finishes | 2nd - 227A inside Library | 961 | SF | 6 | \$6,857 | 126 sq.ft. drywall ceiling - peeling, cracks 126 sq.ft. tile floor - cracks, damages / 583 sq.ft. drywalls - cracks, peeling, bubbling |
| | Ventilation and Cooling | 2nd - 227A inside Library | 2 | EA | 6 | \$3,710 | cool temp in room |
| Mechanical/ Service Rooms | | | | | | | |
| | Janitor's Closet | 1st Floor | 29 | SF | 6 | \$208 | 122-J |
| | Janitor's Closet | 2nd Floor | 29 | SF | 6 | \$208 | 222 |
| | Storage Room | 2nd Floor | 232 | SF | 6 | \$1,662 | 288B / 286 |
| | Air Intake Plenums | Basement | 367 | SF | 6 | \$2,272 | |
| | Air Tunnel | Basement | 2,460 | SF | 6 | \$15,232 | |
| | Auditorium Plenums | Basement | 4,270 | SF | 6 | \$26,439 | |
| | Boiler Room | Basement | 2,006 | SF | 6 | \$14,372 | |

Building: Addition 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------------|---------------------------------|-------------------------------|----------|------|------|----------|---|
| Mechanical/ Service Rooms | | | | | | | |
| | Crawl Space - Unfinished | Basement | 6,574 | SF | 5 | \$87,522 | Pipe space - Seepage through the foundation walls |
| | Interior Stairs | Basement | 12 | LF | 6 | \$108 | steel |
| | Janitor's Closet | Basement | 5 | SF | 6 | \$36 | |
| | Mechanical/ Service Rooms | Basement | 3,226 | SF | 6 | \$23,112 | |
| | Storage Room | Basement | 543 | SF | 6 | \$3,890 | |
| Restroom | | | | | | | |
| | Accessories | 1st - Boys | 279 | SF | 6 | \$2,573 | |
| | Ceiling - Plaster/Drywall | 1st - Boys | 279 | SF | 6 | \$966 | |
| | Floor Drain | 1st - Boys | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st - Boys | 279 | SF | 6 | \$590 | |
| | Hand Dryer | 1st - Boys | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st - Boys | 4 | EA | 6 | \$1,278 | |
| | Lighting - Pendent/Surface | 1st - Boys | 5 | EA | 7 | \$0 | |
| | Urinals | 1st - Boys | 5 | EA | 6 | \$1,680 | |
| | Walls - Plaster/Drywall | 1st - Boys | 501 | SF | 6 | \$1,383 | |
| | Walls - Structural Glazed Tile | 1st - Boys | 501 | SF | 6 | \$1,576 | |
| | Water Closet | 1st - Boys | 1 | EA | 6 | \$336 | |
| | Accessories | 1st - Girls | 302 | SF | 6 | \$2,785 | |
| | Benches | 1st - Girls | 1 | LF | 6 | \$14 | |
| | Ceiling - Plaster/Drywall | 1st - Girls | 302 | SF | 6 | \$1,045 | |
| | Floor Drain | 1st - Girls | 1 | EA | 6 | \$1,059 | cover off |
| | Floor - Tile Ceramic/ Porcelain | 1st - Girls | 302 | SF | 6 | \$639 | |
| | Hand Dryer | 1st - Girls | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st - Girls | 4 | EA | 6 | \$1,278 | |
| | Lighting - Pendent/Surface | 1st - Girls | 4 | EA | 7 | \$0 | |
| | Partitions | 1st - Girls | 4 | EA | 6 | \$1,188 | |
| | Walls - Plaster/Drywall | 1st - Girls | 452 | SF | 6 | \$1,247 | |
| | Walls - Structural Glazed Tile | 1st - Girls | 452 | SF | 6 | \$1,422 | |
| | Water Closet | 1st - Girls | 5 | EA | 6 | \$1,680 | |
| | Accessories | 1st - inside Kindergarten 129 | 68 | SF | 6 | \$627 | |
| | Ceiling - Plaster/Drywall | 1st - inside Kindergarten 129 | 68 | SF | 6 | \$235 | |
| | Doors - Wood Doors inclu hw | 1st - inside Kindergarten 129 | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 1st - inside Kindergarten 129 | 68 | SF | 6 | \$144 | |
| | Lighting - Pendent/Surface | 1st - inside Kindergarten 129 | 1 | EA | 7 | \$0 | |
| | Walls - Masonry | 1st - inside Kindergarten 129 | 20 | SF | 6 | \$63 | |
| | Walls - Plaster/Drywall | 1st - inside Kindergarten 129 | 167 | SF | 6 | \$547 | granite |

Building: Addition 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|---------------------------------|---------------------------------------|----------|------|------|---------|----------|
| Restroom | | | | | | | |
| | Walls - Plaster/Drywall | 1st - inside Kindergarten 129 | 307 | SF | 6 | \$847 | |
| | Water Closet | 1st - inside Kindergarten 129 | 2 | EA | 6 | \$672 | |
| | Accessories | 1st - inside office in 123 | 26 | SF | 6 | \$240 | |
| | Ceiling - Plaster/Drywall | 1st - inside office in 123 | 26 | SF | 6 | \$90 | |
| | Doors - Wood Doors inclu hw | 1st - inside office in 123 | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 1st - inside office in 123 | 26 | SF | 6 | \$55 | |
| | Lavatory | 1st - inside office in 123 | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 1st - inside office in 123 | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st - inside office in 123 | 263 | SF | 6 | \$726 | |
| | Water Closet | 1st - inside office in 123 | 1 | EA | 6 | \$336 | |
| | Accessories | 1st - Men Assembly Hall Vestibule | 95 | SF | 6 | \$876 | |
| | Ceiling - Plaster/Drywall | 1st - Men Assembly Hall Vestibule | 95 | SF | 6 | \$329 | |
| | Doors - Wood Doors inclu hw | 1st - Men Assembly Hall Vestibule | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 1st - Men Assembly Hall Vestibule | 95 | SF | 6 | \$201 | |
| | Lavatory | 1st - Men Assembly Hall Vestibule | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 1st - Men Assembly Hall Vestibule | 2 | EA | 7 | \$0 | |
| | Partitions | 1st - Men Assembly Hall Vestibule | 1 | EA | 6 | \$297 | Granite |
| | Urinals | 1st - Men Assembly Hall Vestibule | 1 | EA | 6 | \$336 | |
| | Walls - Plaster/Drywall | 1st - Men Assembly Hall Vestibule | 199 | SF | 6 | \$549 | |
| | Walls - Structural Glazed Tile | 1st - Men Assembly Hall Vestibule | 199 | SF | 6 | \$626 | |
| | Water Closet | 1st - Men Assembly Hall Vestibule | 1 | EA | 6 | \$336 | |
| | Accessories | 1st - staff unisex | 59 | SF | 6 | \$544 | |
| | Ceiling - Plaster/Drywall | 1st - staff unisex | 59 | SF | 6 | \$204 | |
| | Doors - Steel Doors incl hw | 1st - staff unisex | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st - staff unisex | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st - staff unisex | 59 | SF | 6 | \$125 | |
| | Hand Dryer | 1st - staff unisex | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st - staff unisex | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 1st - staff unisex | 1 | EA | 7 | \$0 | |
| | Walls - Masonry | 1st - staff unisex | 80 | SF | 6 | \$252 | |
| | Walls - Plaster/Drywall | 1st - staff unisex | 184 | SF | 6 | \$508 | |
| | Walls - Tile Ceramic/ Porcelain | 1st - staff unisex | 5 | SF | 6 | \$11 | |
| | Water Closet | 1st - staff unisex | 1 | EA | 6 | \$336 | |
| | Accessories | 1st - Women's Assembly Hall vestibule | 94 | SF | 6 | \$867 | |
| | Ceiling - Plaster/Drywall | 1st - Women's Assembly Hall vestibule | 94 | SF | 6 | \$325 | |
| | Doors - Wood Doors inclu hw | 1st - Women's Assembly Hall vestibule | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st - Women's Assembly Hall vestibule | 1 | EA | 6 | \$1,059 | |

Building: Addition 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|---------------------------------|---------------------------------------|----------|------|------|----------|---------------|
| Restroom | | | | | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st - Women's Assembly Hall vestibule | 94 | SF | 6 | \$199 | |
| | Hand Dryer | 1st - Women's Assembly Hall vestibule | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st - Women's Assembly Hall vestibule | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 1st - Women's Assembly Hall vestibule | 1 | EA | 7 | \$0 | |
| | Partitions | 1st - Women's Assembly Hall vestibule | 1 | EA | 6 | \$297 | Granite |
| | Walls - Plaster/Drywall | 1st - Women's Assembly Hall vestibule | 201 | SF | 6 | \$555 | |
| | Walls - Structural Glazed Tile | 1st - Women's Assembly Hall vestibule | 201 | SF | 6 | \$632 | |
| | Water Closet | 1st - Women's Assembly Hall vestibule | 1 | EA | 6 | \$336 | |
| | Accessories | 2nd - Boys | 3,042 | SF | 6 | \$28,058 | |
| | Ceiling - Plaster/Drywall | 2nd - Boys | 304 | SF | 6 | \$1,052 | |
| | Floor Drain | 2nd - Boys | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd - Boys | 304 | SF | 6 | \$643 | |
| | Hand Dryer | 2nd - Boys | 1 | EA | 6 | \$230 | |
| | Lavatory | 2nd - Boys | 4 | EA | 6 | \$1,278 | |
| | Lighting - Pendent/Surface | 2nd - Boys | 5 | EA | 7 | \$0 | |
| | Urinals | 2nd - Boys | 5 | EA | 6 | \$1,680 | |
| | Walls - Plaster/Drywall | 2nd - Boys | 501 | SF | 6 | \$1,383 | |
| | Walls - Structural Glazed Tile | 2nd - Boys | 501 | SF | 6 | \$1,576 | |
| | Water Closet | 2nd - Boys | 1 | EA | 6 | \$336 | |
| | Accessories | 2nd - Girls | 350 | SF | 6 | \$3,228 | |
| | Ceiling - Plaster/Drywall | 2nd - Girls | 350 | SF | 6 | \$1,211 | |
| | Floor Drain | 2nd - Girls | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd - Girls | 350 | SF | 6 | \$741 | |
| | Hand Dryer | 2nd - Girls | 1 | EA | 6 | \$230 | |
| | Lavatory | 2nd - Girls | 4 | EA | 6 | \$1,278 | |
| | Lighting - Pendent/Surface | 2nd - Girls | 4 | EA | 7 | \$0 | |
| | Partitions | 2nd - Girls | 5 | EA | 6 | \$1,485 | |
| | Walls - Plaster/Drywall | 2nd - Girls | 513 | SF | 6 | \$1,416 | |
| | Walls - Structural Glazed Tile | 2nd - Girls | 513 | SF | 6 | \$1,614 | |
| | Water Closet | 2nd - Girls | 5 | EA | 6 | \$1,680 | |
| | Accessories | 2nd - inside 287 Teachers Lounge | 76 | SF | 6 | \$701 | |
| | Ceiling - Plaster/Drywall | 2nd - inside 287 Teachers Lounge | 76 | SF | 6 | \$263 | |
| | Doors - Wood Doors inclu hw | 2nd - inside 287 Teachers Lounge | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd - inside 287 Teachers Lounge | 76 | SF | 6 | \$161 | |
| | Lavatory | 2nd - inside 287 Teachers Lounge | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 2nd - inside 287 Teachers Lounge | 2 | EA | 6 | \$248 | |
| | Partitions | 2nd - inside 287 Teachers Lounge | 1 | EA | 6 | \$297 | granite slabs |

Building: Addition 1

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|---------------------------------|----------------------------------|----------|------|------|-------|---------------|
| Restroom | | | | | | | |
| | Walls - Plaster/Drywall | 2nd - inside 287 Teachers Lounge | 342 | SF | 6 | \$944 | |
| | Walls - Tile Ceramic/ Porcelain | 2nd - inside 287 Teachers Lounge | 126 | SF | 6 | \$285 | granite slabs |
| | Water Closet | 2nd - inside 287 Teachers Lounge | 2 | EA | 6 | \$672 | |

Rooms (Other Than Classrooms) Subtotal:

\$737,368

Building: Addition 1

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|--------------------------------------|-----------------|----------|------|------|----------|----------|
| Corridor | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 3,192 | SF | 6 | \$19,765 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 25 | SF | 5 | \$436 | |
| | Doors - Transom Window | 1st Floor | 14 | EA | 6 | \$237 | |
| | Doors - Wood Doors include hw | 1st Floor | 11 | EA | 6 | \$3,311 | |
| | Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 6 | \$336 | |
| | Floor - Terrazzo | 1st Floor | 158 | SF | 6 | \$1,326 | |
| | Floor - Tile/Sheet | 1st Floor | 3,034 | SF | 6 | \$1,649 | |
| | Lighting - Pendent/Surface | 1st Floor | 40 | EA | 7 | \$0 | |
| | Stairs - Concrete Stairs | 1st Floor | 11 | LF | 6 | \$91 | |
| | Student Lockers - One Tier | 1st Floor | 57 | EA | 6 | \$5,292 | |
| | Walls - Concrete Block | 1st Floor | 1,025 | SF | 6 | \$3,005 | |
| | Walls - Masonry | 1st Floor | 430 | SF | 6 | \$1,353 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,791 | SF | 6 | \$7,940 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 2,522 | SF | 6 | \$15,616 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 30 | SF | 5 | \$523 | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 1 | EA | 6 | \$336 | |
| | Floor - Terrazzo | 2nd Floor | 158 | SF | 6 | \$1,326 | |
| | Floor - Tile/Sheet | 2nd Floor | 2,364 | SF | 6 | \$1,285 | |
| | Lighting - Chandelier, Incandescent | 2nd Floor | 16 | EA | 6 | \$7,641 | |
| | Lighting - Pendent/Surface | 2nd Floor | 6 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | 2nd Floor | 104 | EA | 6 | \$9,655 | |
| | Walls - Concrete Block | 2nd Floor | 870 | SF | 6 | \$2,550 | |
| | Walls - Masonry | 2nd Floor | 430 | SF | 6 | \$1,353 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,300 | SF | 6 | \$5,763 | |
| Safety | | | | | | | |
| | Security Cameras | Entire building | 2 | EA | 6 | \$388 | |

Building: Addition 1

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------|-------------------------------------|-----------------|----------|------|------|---------|----------|
| Safety | | | | | | | |
| | Security Cameras | Entire building | 6 | EA | 6 | \$1,164 | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | North | 336 | SF | 6 | \$2,460 | |
| | Floor - Terrazzo | North | 112 | SF | 6 | \$940 | |
| | Handrails | North | 72 | LF | 6 | \$624 | |
| | Lighting - Chandelier, Incandescent | North | 2 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | North | 36 | LF | 6 | \$334 | |
| | Walls - Plaster/Drywall | North | 1,260 | SF | 6 | \$3,477 | |
| | Ceiling - Plaster/Drywall | South East | 336 | SF | 6 | \$2,460 | |
| | Floor - Terrazzo | South East | 112 | SF | 6 | \$940 | |
| | Handrails | South East | 72 | LF | 6 | \$624 | |
| | Lighting - Chandelier, Incandescent | South East | 2 | EA | 6 | \$955 | |
| | Stairs - Terrazzo | South East | 36 | LF | 6 | \$334 | |
| | Walls - Plaster/Drywall | South East | 1,260 | SF | 6 | \$3,477 | |
| Vertical Conveyance | | | | | | | |
| | Wheelchair Lift - Chair Lift | 1st Floor | 1 | EA | 6 | \$5,597 | |

Building Interior Subtotal:

\$114,564

Total Building Cost

\$2,534,832

Building: Addition 2

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|--------------------------------------|----------------|----------|------|------|---------|----------|
| Entrance | | | | | | | |
| | Entrance Control - Audio and Video | #3- SE | 1 | EA | 6 | \$702 | |
| | Entrance Control - Audio and Video | #5- SW | 1 | EA | 6 | \$702 | |
| | Exterior Doors - Exterior Steel Door | #4.1- SW- L.R. | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | #4.2- SW- B.R. | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Store Front | #2- SE | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Store Front | #3- SE | 4 | EA | 6 | \$2,184 | |
| | Exterior Doors - Store Front | #4- S | 3 | EA | 6 | \$1,638 | |
| | Exterior Doors - Store Front | #5- SW | 2 | EA | 6 | \$1,092 | |
| | Exterior Doors - Transom Lite | #4.1- SW- L.R. | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | #4.2- SW- B.R. | 1 | EA | 6 | \$313 | |

Building: Addition 2

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------|---|----------------------------|----------|------|------|-----------|-----------------------|
| Entrance | | | | | | | |
| | Exterior Doors - Transom Lite | #5- SW | 2 | EA | 6 | \$627 | |
| | Exterior Stairs - Concrete | #2- SE | 10 | LF | 6 | \$818 | |
| | Exterior Stairs - Concrete | #3- SE | 1 | LF | 5 | \$110 | spalling |
| | Exterior Stairs - Concrete | #4- S | 10 | LF | 6 | \$818 | |
| | Exterior Stairs - Concrete | #4.1- SW - L.R. | 39 | LF | 5 | \$4,274 | spalling |
| | Exterior Stairs - Concrete | #4.2- SW - B.R. | 39 | LF | 5 | \$4,274 | spalling |
| | Exterior Stairs - Concrete | #5- SW | 18 | LF | 6 | \$1,472 | |
| | Exterior Stairs - Stone | #2- SE | 6 | LF | 6 | \$678 | |
| | Exterior Stairs - Stone | #3- SE | 6 | LF | 6 | \$678 | |
| | Exterior Stairs - Stone | #4- S | 9 | LF | 6 | \$1,017 | |
| | Exterior Stairs - Stone | #5- SW | 6 | LF | 6 | \$678 | |
| | Power Door Operator and Controls | #3- SE | 2 | EA | 6 | \$0 | |
| | Ramp Handrail - Steel_Ramp Handrail | #3- SE | 55 | LF | 6 | \$477 | |
| | Ramps - Concrete | #3- SE | 24 | LF | 6 | \$3,606 | |
| | Stair Handrail - Steel_Stair Handrail | #4.1- SW - L.R. | 55 | LF | 6 | \$477 | |
| | Stair Handrail - Steel_Stair Handrail | #4.2- SW - B.R. | 55 | LF | 6 | \$477 | |
| Foundation | | | | | | | |
| | Foundation - Concrete | Entire Building | 664 | LF | 7 | \$0 | |
| | Foundation - Concrete | Entire Building / Basement | 20 | LF | 5 | \$11,039 | N basement- seepage |
| | Superstructure - Concrete | Entire Building | 47,014 | SF | 7 | \$0 | |
| Lighting | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 6 | EA | 6 | \$3,219 | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building / East | 4 | EA | 5 | \$8,720 | broken |
| | Exterior Lighting - Wall Mounted | Entire Building | 2 | EA | 5 | \$855 | at door 5 - broken |
| | Exterior Lighting - Wall Mounted | Entire Building | 8 | EA | 6 | \$2,310 | |
| Roof System | | | | | | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | Main Roof | 40 | LF | 6 | \$38,187 | has straps |
| | Coping - Metal | Main Roof | 717 | LF | 6 | \$23,028 | |
| | Downspouts - Interior Downspouts | Main Roof | 96 | LF | 6 | \$3,190 | |
| | Roof Structure - Concrete | Main Roof | 19,556 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | Main Roof | 19,556 | SF | 5 | \$411,366 | surface deterioration |
| Walls | | | | | | | |
| | Canopy - Concrete/ Stucco | Entire Building | 210 | SF | 6 | \$6,949 | at doors: 2,3,4 |
| | Canopy - Fabric | Entire Building | 195 | SF | 6 | \$2,995 | at door: 3 |
| | Exterior Walls - Brick | Entire Building | 3,252 | SF | 6 | \$21,857 | |

Building: Addition 2

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------|-------------------------------------|------------------------------|----------|------|------|----------|----------|
| Walls | | | | | | | |
| | Exterior Walls - Stone-Cast | Entire Building / East | 24 | SF | 6 | \$161 | |
| Windows | | | | | | | |
| | Curtain wall - Louver | Entire Building | 99 | SF | 6 | \$1,110 | |
| | Guard - Guards perforated | Entire Building / North East | 192 | SF | 6 | \$2,452 | rust |
| | Lintels - Steel | Entire Building | 33 | LF | 6 | \$958 | |
| | Windows - Insulated Panel | Entire Building | 784 | SF | 6 | \$5,852 | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 5,184 | SF | 6 | \$38,696 | |

Building Exterior Subtotal:

\$612,420

Building: Addition 2

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------|--|--|----------|------|------|----------|---------------------------|
| Emergency System | | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 3 | EA | 7 | \$0 | Location: Electrical Room |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 7 | \$0 | Location: Electrical Room |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 4,744 | SF | 6 | \$1,425 | |
| | Emergency A/C Power - Lunchrooms | Entire Building / Basement | 2,171 | SF | 6 | \$807 | |
| | Emergency A/C Power - Students Toilets | Entire Building | 1,284 | SF | 6 | \$477 | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building and Basement / Entire Building | 5 | EA | 6 | \$1,013 | |
| | Emergency Battery Packs - Lunchrooms | Entire Building and Basement / Basement | 3 | EA | 6 | \$608 | |
| | Emergency Generator- Outdoor- Natural Gas - 101 - 150 KW | West Courtyard | 1 | EA | 6 | \$13,513 | Feed from Panel: GDP-1 |
| | Exit Signs - Corridors and Stairs | Entire Building and Basement / Entire Building | 7 | EA | 6 | \$1,048 | |
| | Exit Signs - Lunchroom | Entire Building and Basement / Basement | 3 | EA | 6 | \$449 | |
| | Security System - CCTV | Entire Building | 47,014 | SF | 6 | \$14,118 | |
| | Security System - Intrusion Detection | Entire Building | 47,014 | SF | 6 | \$12,101 | |
| Main Service | | | | | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | \$2,921 | |
| | Main Electrical Service - 2000 A 120/208/3PH | Electrical Room | 1 | EA | 6 | \$8,232 | |
| | PA System | Entire Building | 47,014 | SF | 6 | \$15,463 | |
| Power Distribution | | | | | | | |
| | Lighting and Power Panels - Above 100 A | Boiler Room and Basement / Basement | 1 | EA | 7 | \$0 | Location: Electrical Room |
| | Lighting and Power Panels - Above 100 A | Boiler Room and Basement / Basement | 1 | EA | 7 | \$0 | Location: Electrical Room |

Building: Addition 2

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------|--|--|----------|------|------|----------|---------------------------|
| Power Distribution | | | | | | | |
| | Lighting and Power Panels - Above 100 A | Boiler Room and Basement / Basement | 1 | EA | 7 | \$0 | Location: Electrical Room |
| | Lighting and Power Panels - Above 100 A | Boiler Room and Basement / Boiler Room | 2 | EA | 4 | \$13,156 | |
| | Lighting and Power Panels - Above 100 A | Boiler Room and Basement / Boiler Room | 1 | EA | 4 | \$6,578 | |
| | Lighting and Power Panels - Above 100 A | Boiler Room and Basement / Boiler Room | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Boiler Room and Basement / Boiler Room | 1 | EA | 7 | \$0 | Location: Storage Room |
| | Main Distribution Panels - Less than 400 amp | Boiler Room and Basement / Basement | 1 | EA | 7 | \$0 | Location: Electrical Room |

Electrical System Subtotal: \$91,908

Building: Addition 2

Category: Safty System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------|--------------------------|----------------------------|----------|------|------|----------|---------------------------|
| Fire Alarm | | | | | | | |
| | Fire Alarm Panel | Basement | 1 | EA | 6 | \$6,406 | Location: Electrical Room |
| | Fire Alarm Strobe Lights | Basement / Entire Building | 47,014 | SF | 6 | \$16,808 | |
| | Fire Alarm_System | Basement / Entire Building | 47,014 | SF | 6 | \$22,858 | |

Safty System Subtotal: \$46,071

Building: Addition 2

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------|--|-------------------------------|----------|------|------|----------|--------------|
| Boiler Systems | | | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - Less than 50 HP | Boiler Room | 2 | EA | 6 | \$4,093 | |
| | Chemical Feed System | Boiler Room | 1 | EA | 6 | \$1,078 | |
| | Combustion Dampers | Boiler Room | 2 | EA | 6 | \$818 | |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 6 | \$2,545 | |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Less than 50 HP | Boiler Room | 2 | EA | 6 | \$4,093 | forced draft |
| | Piping - Condensate Pipe- Steel | Boiler Room | 500 | LF | 6 | \$944 | |
| | Piping - Steam Pipe- Steel | Boiler Room | 500 | LF | 6 | \$944 | |
| | Steam Traps | Boiler Room / Entire Building | 44 | EA | 6 | \$11,623 | |

Building: Addition 2

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------|---|---|----------|------|------|-----------|-----------------------------|
| Heat Exchangers | | | | | | | |
| | Heat Exchanger - Steam to Hot Water Shell Type | Boiler Room | 1 | EA | 6 | \$0 | |
| Heating Devices | | | | | | | |
| | Fin Tube - Hot Water | Entire Building | 44 | LF | 5 | \$3,583 | |
| | Unit Heater - Hot Water | Boiler Room | 1 | EA | 6 | \$279 | |
| | Unit Heater - Hot Water | Boiler Room | 2 | EA | 4 | \$6,483 | |
| Mechanical Plumbing | | | | | | | |
| | Condenser Pump - Less than 10 | Mechanical Room / Mechanical Building/Central Plant | 1 | EA | 6 | \$1,111 | |
| | Condenser Pump - Less than 10 | Mechanical Room | 1 | EA | 6 | \$1,111 | |
| | Hot Water Pump - 10 - 20 HP | Boiler Room | 2 | EA | 6 | \$2,485 | heat exchanger |
| | Hydronic Supply and Return - Galvanized | Entire Building | 500 | LF | 6 | \$38,660 | from and to heat exchanger |
| Temperature Control | | | | | | | |
| | DDC System | Entire Building | 47,014 | SF | 6 | \$26,892 | Location: Engineer's Office |
| | Thermostats - DDC | Entire Building | 40 | EA | 6 | \$0 | |
| Unit Ventilation | | | | | | | |
| | Unit Ventilators- Floor Mounted- Steam Heating Coils Only | Entire Building | 34 | EA | 5 | \$324,311 | |
| Ventilation | | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof and Kitchen / Roof | 3 | EA | 6 | \$1,777 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Roof and Kitchen / Roof | 2 | EA | 6 | \$1,185 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Roof and Kitchen / Roof | 1 | EA | 4 | \$4,245 | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Roof and Kitchen / Roof | 3 | EA | 6 | \$889 | |
| | Type I Exhaust Hood- Culinary Arts | Roof and Kitchen / Basement | 1 | EA | 7 | \$0 | |

Mechanical System Subtotal: \$439,148

Building: Addition 2

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------|--|-------------------------------|----------|------|------|----------|----------|
| Hot Water | | | | | | | |
| | Gas Heater - 150000 - 300000 BTU/HR | Entire Building / Boiler Room | 1 | EA | 6 | \$310 | |
| | Gas Heater - 150000 - 300000 BTU/HR | Entire Building / Boiler Room | 1 | EA | 6 | \$310 | |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 47,014 | SF | 6 | \$9,412 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 47,014 | SF | 6 | \$11,429 | |

Building: Addition 2

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------------|---|--|----------|------|------|------------------|----------|
| Piping | | | | | | | |
| | Domestic Piping-Cold Water Risers | Entire Building | 47,014 | SF | 6 | \$8,740 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 47,014 | SF | 6 | \$7,395 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 47,014 | SF | 6 | \$8,740 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 47,014 | SF | 6 | \$6,723 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 47,014 | SF | 6 | \$6,723 | |
| | Sanitary Piping | Entire Building | 47,014 | SF | 6 | \$43,027 | |
| | Storm Piping | Entire Building | 47,014 | SF | 6 | \$41,010 | |
| | Vent Piping | Entire Building | 47,014 | SF | 6 | \$31,598 | |
| Pumps | | | | | | | |
| | Pumps - Domestic Booster Pump-Simplex | Basement and Boiler Room / Boiler Room | 1 | EA | 6 | \$1,446 | |
| | Pumps - Sump-Duplex | Basement and Boiler Room / Basement | 1 | EA | 6 | \$1,387 | |
| Plumbing System Subtotal: | | | | | | \$178,250 | |

Building: Addition 2

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|-------------------|
| Classroom #100 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 854 | SF | 6 | \$1,868 | |
| | Floor - Tile | 1st Floor | 2 | SF | 5 | \$12 | |
| | Lighting - Pendant/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 1st Floor | 895 | SF | 6 | \$2,624 | |
| | Walls - Concrete Block | 1st Floor | 1 | SF | 5 | \$14 | Open junction box |
| Classroom #101 (Kindergarten) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Casework | 1st Floor | 30 | LF | 6 | \$758 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,031 | SF | 6 | \$3,568 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 1st Floor | 1,031 | SF | 6 | \$2,256 | |
| | Lighting - Pendant/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 8 | LF | 7 | \$0 | |

Building: Addition 2

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|----------------------------------|
| Classroom #101 (Kindergarten) | | | | | | | |
| | Storage/ Closet | 1st Floor | 90 | SF | 6 | \$653 | |
| | Walls - Concrete Block | 1st Floor | 1,071 | SF | 6 | \$3,140 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #102 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 1st Floor | 895 | SF | 6 | \$2,624 | |
| | Walls - Concrete Block | 1st Floor | 1 | SF | 5 | \$14 | Exposed wires at thermostat |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #103 (Kindergarten) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,031 | SF | 6 | \$3,568 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Tile | 1st Floor | 1,031 | SF | 6 | \$2,256 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 8 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 90 | SF | 6 | \$653 | |
| | Walls - Concrete Block | 1st Floor | 1,071 | SF | 6 | \$3,140 | |
| | Walls - Plaster/Drywall | 1st Floor | 35 | SF | 6 | \$97 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #104 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 1st Floor | 1 | SF | 5 | \$14 | Open junction box and thermostat |
| | Walls - Concrete Block | 1st Floor | 895 | SF | 6 | \$2,624 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |

Building: Addition 2

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|----------|
| Classroom #104 (Regular Classroom) | | | | | | | |
| Classroom #106 (Faculty Lounge) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 1st Floor | 896 | SF | 6 | \$2,627 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #107 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 879 | SF | 6 | \$3,042 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 879 | SF | 6 | \$1,923 | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 1st Floor | 890 | SF | 6 | \$2,609 | |
| | Walls - Plaster/Drywall | 1st Floor | 75 | SF | 6 | \$207 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #108 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 6 | \$386 | |
| | Storage/ Closet | 1st Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 1st Floor | 896 | SF | 6 | \$2,627 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #109 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |

Building: Addition 2

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|----------|
| Classroom #109 (Regular Classroom) | | | | | | | |
| | Floor - Tile | 1st Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 1st Floor | 896 | SF | 6 | \$2,627 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #110 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 1st Floor | 896 | SF | 6 | \$2,627 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #111 (Art Room) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 856 | SF | 6 | \$1,873 | |
| | Kiln | 1st Floor | 1 | EA | 6 | \$2,321 | |
| | Lighting - Lay-in | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 1st Floor | 821 | SF | 6 | \$2,407 | |
| | Walls - Plaster/Drywall | 1st Floor | 75 | SF | 6 | \$207 | |
| Classroom #112 (Regular Classroom) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 1st Floor | 896 | SF | 6 | \$2,627 | |

Building: Addition 2

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|-------------------|
| Classroom #112 (Regular Classroom) | | | | | | | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #113 (Computer Lab) | | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 856 | SF | 6 | \$2,962 | |
| | Charging Station | 1st Floor | 1 | EA | 6 | \$485 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 1st Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 46 | SF | 6 | \$334 | |
| | Walls - Concrete Block | 1st Floor | 895 | SF | 6 | \$2,624 | |
| | Walls - Concrete Block | 1st Floor | 1 | SF | 5 | \$14 | Open junction box |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classroom #200 (Other Instructional Use) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Casework | 2nd Floor | 28 | LF | 6 | \$707 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 26 | SF | 6 | \$189 | |
| | Walls - Concrete Block | 2nd Floor | 821 | SF | 6 | \$2,407 | |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| Classroom #201 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 2nd Floor | 820 | SF | 6 | \$2,404 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1 | SF | 5 | \$5 | Open junction box |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |

Building: Addition 2

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|----------------------|
| Classroom #202 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | \$1,836 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 6 | \$145 | |
| | Walls - Concrete Block | 2nd Floor | 820 | SF | 6 | \$2,404 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1 | SF | 5 | \$5 | Exposed junction box |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| Classroom #203 (Office) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 2nd Floor | 896 | SF | 6 | \$2,627 | |
| Classroom #204 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 6 | \$145 | |
| | Walls - Concrete Block | 2nd Floor | 821 | SF | 6 | \$2,407 | |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| Classroom #205 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |

Building: Addition 2

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|-------------------|
| Classroom #205 (Regular Classroom) | | | | | | | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 2nd Floor | 820 | SF | 6 | \$2,404 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1 | SF | 5 | \$5 | Open juntion box |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| Classroom #206 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 6 | \$145 | |
| | Walls - Concrete Block | 2nd Floor | 820 | SF | 6 | \$2,404 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1 | SF | 5 | \$5 | Open junction box |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| Classroom #207 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 879 | SF | 6 | \$3,042 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 879 | SF | 6 | \$1,923 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 2nd Floor | 889 | SF | 6 | \$2,606 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1 | SF | 5 | \$5 | Open junction box |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| Classroom #208 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 6 | \$145 | |
| | Walls - Concrete Block | 2nd Floor | 820 | SF | 6 | \$2,404 | |

Building: Addition 2

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|-------------------|
| Classroom #208 (Regular Classroom) | | | | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1 | SF | 5 | \$5 | Open junction box |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| Classroom #209 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Splined | 2nd Floor | 879 | SF | 6 | \$716 | |
| | Ceiling - Splined | 2nd Floor | 1 | SF | 5 | \$10 | Missing tile |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 878 | SF | 6 | \$1,921 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 46 | SF | 6 | \$334 | |
| | Walls - Concrete Block | 2nd Floor | 881 | SF | 6 | \$2,583 | |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| | Work Sink | 2nd Floor | 1 | EA | 6 | \$379 | |
| Classroom #210 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 2nd Floor | 820 | SF | 6 | \$2,404 | |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1 | SF | 5 | \$5 | Open junction box |
| Classroom #211 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Splined | 2nd Floor | 856 | SF | 6 | \$698 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 2nd Floor | 821 | SF | 6 | \$2,407 | |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |

Building: Addition 2

Category: Classrooms

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------------------------|-----------|----------|------|------|---------|--|
| Classroom #212 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | \$428 | |
| | Storage/ Closet | 2nd Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 2nd Floor | 821 | SF | 6 | \$2,407 | |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| Classroom #213 (Regular Classroom) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 19 | SF | 6 | \$138 | |
| | Walls - Concrete Block | 2nd Floor | 821 | SF | 6 | \$2,407 | |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |
| Classroom #215 (Office) | | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 856 | SF | 6 | \$2,962 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Storage/ Closet | 2nd Floor | 20 | SF | 6 | \$145 | |
| | Walls - Concrete Block | 2nd Floor | 820 | SF | 6 | \$2,404 | |
| | Walls - Metal Panel | 2nd Floor | 367 | SF | 6 | \$2,740 | Partition wall |
| | Walls - Plaster/Drywall | 2nd Floor | 1 | SF | 5 | \$5 | Open wire at junction box and thermostat |
| | Walls - Plaster/Drywall | 2nd Floor | 75 | SF | 6 | \$207 | |

Classrooms Subtotal:

\$250,758

Building: Addition 2

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|-----------------------------|---------------------------------|----------|------|------|----------|-----------------|
| Administrative Suites/Offices | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor 100R Teacher's Lounge | 158 | SF | 6 | \$547 | |
| | Doors - Wood Doors inclu hw | 1st Floor 100R Teacher's Lounge | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor 100R Teacher's Lounge | 158 | SF | 6 | \$346 | |
| | Lighting - Pendent/Surface | 1st Floor 100R Teacher's Lounge | 2 | EA | 7 | \$0 | |
| | Power Distribution | 1st Floor 100R Teacher's Lounge | 2 | EA | 6 | \$4,250 | |
| | Walls - Concrete Block | 1st Floor 100R Teacher's Lounge | 469 | SF | 6 | \$1,375 | |
| | AC Unit | 1st Floor 105 Main Office | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | 1st Floor 105 Main Office | 8 | SF | 5 | \$100 | Damaged |
| | Ceiling - Plaster/Drywall | 1st Floor 105 Main Office | 848 | SF | 6 | \$2,935 | |
| | Doors - Wood Doors inclu hw | 1st Floor 105 Main Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 1st Floor 105 Main Office | 856 | SF | 6 | \$1,873 | |
| | Lighting - Pendent/Surface | 1st Floor 105 Main Office | 16 | EA | 7 | \$0 | |
| | Power Distribution | 1st Floor 105 Main Office | 6 | EA | 6 | \$12,749 | |
| | Storage/ Closet | 1st Floor 105 Main Office | 46 | SF | 6 | \$334 | |
| | Walls - Concrete Block | 1st Floor 105 Main Office | 896 | SF | 6 | \$2,627 | |
| | Walls - Plaster/Drywall | 1st Floor 105 Main Office | 75 | SF | 6 | \$246 | |
| | Walls - Plaster/Drywall | 1st Floor 105 Main Office | 367 | SF | 6 | \$1,013 | Partitian walls |
| | Work Sink | 1st Floor 105 Main Office | 1 | EA | 6 | \$508 | |
| | Ceiling - Plaster/Drywall | 2nd Floor Women Faculty Room | 112 | SF | 6 | \$388 | |
| | Ceiling - Plaster/Drywall | 2nd Floor Women Faculty Room | 6 | SF | 5 | \$75 | Water damaged |
| | Doors - Wood Doors inclu hw | 2nd Floor Women Faculty Room | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor Women Faculty Room | 118 | SF | 6 | \$258 | |
| | Lighting - Pendent/Surface | 2nd Floor Women Faculty Room | 2 | EA | 6 | \$248 | |
| | Power Distribution | 2nd Floor Women Faculty Room | 4 | EA | 6 | \$8,500 | |
| | Walls - Concrete Block | 2nd Floor Women Faculty Room | 425 | SF | 6 | \$1,246 | |
| | Ceiling - Plaster/Drywall | Basement - inside Kitchen | 72 | SF | 6 | \$249 | |
| | Doors - Wood Doors inclu hw | Basement - inside Kitchen | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Basement - inside Kitchen | 72 | SF | 6 | \$158 | |
| | Lighting - Pendent/Surface | Basement - inside Kitchen | 1 | EA | 7 | \$0 | |
| | Power Distribution | Basement - inside Kitchen | 2 | EA | 6 | \$4,250 | |
| | Walls - Concrete Block | Basement - inside Kitchen | 170 | SF | 6 | \$498 | |
| | Walls - Plaster/Drywall | Basement - inside Kitchen | 170 | SF | 6 | \$469 | |
| Kitchen | | | | | | | |
| | Ceiling - Plaster/Drywall | Basement | 553 | SF | 6 | \$1,914 | |
| | Doors - Steel Doors incl hw | Basement | 2 | EA | 6 | \$602 | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Basement | 553 | SF | 6 | \$1,210 | |
| | Lighting - Pendent/Surface | Basement | 9 | EA | 7 | \$0 | |
| | Serving Line | Basement | 16 | LF | 6 | \$952 | |

Building: Addition 2

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|--------------------------------|---------------------------|----------|------|------|---------|---|
| Kitchen | | | | | | | |
| | Storage/ Closet | Basement | 156 | SF | 6 | \$1,131 | |
| | Walls - Concrete Block | Basement | 720 | SF | 6 | \$2,111 | |
| | Walls - Structural Glazed Tile | Basement | 223 | SF | 6 | \$702 | |
| Locker/Shower Room | | | | | | | |
| | Accessories | Basement - inside kitchen | 84 | SF | 6 | \$329 | |
| | Ceiling - Plaster/ Drywall | Basement - inside kitchen | 84 | SF | 6 | \$291 | |
| | Doors - Wood Doors inclu hw | Basement - inside kitchen | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | Basement - inside kitchen | 84 | SF | 6 | \$84 | |
| | Lavatory | Basement - inside kitchen | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | Basement - inside kitchen | 1 | EA | 6 | \$119 | old |
| | Lighting - Pendent/Surface | Basement - inside kitchen | 1 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | Basement - inside kitchen | 8 | EA | 6 | \$743 | |
| | Walls - Concrete Block | Basement - inside kitchen | 414 | SF | 6 | \$1,214 | |
| | Water Closet | Basement - inside kitchen | 1 | EA | 6 | \$336 | |
| Lunch & Multipurpose Room | | | | | | | |
| | AC Unit | Basement | 1 | EA | 6 | \$496 | |
| | Ceiling - Plaster/Drywall | Basement | 2,171 | SF | 6 | \$7,513 | |
| | Doors - Steel Doors incl hw | Basement | 4 | EA | 6 | \$1,204 | |
| | Floor - Tile | Basement | 2,171 | SF | 6 | \$4,750 | |
| | Lighting - Pendent/Surface | Basement | 26 | EA | 7 | \$0 | |
| | Serving Line | Basement | 6 | LF | 6 | \$357 | |
| | Storage/ Closet | Basement | 373 | SF | 6 | \$2,704 | 001 / storage rm |
| | Walls - Concrete Block | Basement | 1,203 | SF | 6 | \$3,527 | |
| | Walls - Plaster/Drywall | Basement | 720 | SF | 6 | \$1,987 | |
| Mechanical/ Service Rooms | | | | | | | |
| | Janitor's Closet | 1st Floor | 35 | SF | 6 | \$251 | |
| | Storage Room | 1st Floor | 44 | SF | 6 | \$315 | |
| | Janitor's Closet | 2nd Floor | 35 | SF | 6 | \$251 | |
| | Mechanical/ Service Rooms | 2nd Floor | 60 | SF | 6 | \$430 | |
| | Storage Room | 2nd Floor | 272 | SF | 6 | \$1,949 | |
| | Storage Room | 2nd Floor | 44 | SF | 5 | \$710 | Location: 272B Book Storage- water damaged at ceiling |
| | Storage Room | Basement | 72 | SF | 6 | \$516 | 002 |
| Restroom | | | | | | | |
| | Accessories | 101A | 30 | SF | 6 | \$277 | |

Building: Addition 2

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|---------------------------------|-----------|----------|------|------|---------|---------------|
| Restroom | | | | | | | |
| | Ceiling - Plaster/Drywall | 101A | 30 | SF | 6 | \$104 | |
| | Doors - Wood Doors inclu hw | 101A | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 101A | 30 | SF | 6 | \$66 | |
| | Lavatory | 101A | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 101A | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 101A | 174 | SF | 6 | \$480 | |
| | Water Closet | 101A | 1 | EA | 6 | \$336 | |
| | Accessories | 103A | 30 | SF | 6 | \$277 | |
| | Ceiling - Plaster/Drywall | 103A | 30 | SF | 6 | \$104 | |
| | Doors - Wood Doors inclu hw | 103A | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 103A | 30 | SF | 6 | \$66 | |
| | Lavatory | 103A | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | 103A | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 103A | 174 | SF | 6 | \$510 | |
| | Water Closet | 103A | 1 | EA | 5 | \$1,344 | Not working |
| | Accessories | 1st Floor | 336 | SF | 6 | \$3,099 | |
| | Accessories | 1st Floor | 61 | SF | 6 | \$563 | |
| | Accessories | 1st Floor | 306 | SF | 6 | \$2,822 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 326 | SF | 6 | \$1,128 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 10 | SF | 5 | \$125 | Peeling paint |
| | Ceiling - Plaster/Drywall | 1st Floor | 298 | SF | 6 | \$1,031 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 61 | SF | 6 | \$211 | |
| | Ceiling - Plaster/Drywall | 1st Floor | 8 | SF | 5 | \$100 | Peeling paint |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st Floor | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 1st Floor | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 1st Floor | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 336 | SF | 6 | \$711 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 61 | SF | 6 | \$129 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 306 | SF | 6 | \$648 | |
| | Hand Dryer | 1st Floor | 1 | EA | 6 | \$230 | |
| | Hand Dryer | 1st Floor | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st Floor | 1 | EA | 6 | \$320 | |
| | Lavatory | 1st Floor | 3 | EA | 6 | \$959 | |
| | Lavatory | 1st Floor | 3 | EA | 6 | \$959 | |
| | Lighting - Pendent/Surface | 1st Floor | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 3 | EA | 7 | \$0 | |

Building: Addition 2

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|---------------------------------|-----------|----------|------|------|---------|----------|
| Restroom | | | | | | | |
| | Lighting - Pendent/Surface | 1st Floor | 3 | EA | 7 | \$0 | |
| | Partitions | 1st Floor | 2 | EA | 6 | \$594 | |
| | Partitions | 1st Floor | 7 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 194 | SF | 6 | \$569 | |
| | Walls - Plaster/Drywall | 1st Floor | 37 | SF | 6 | \$102 | |
| | Walls - Structural Glazed Tile | 1st Floor | 758 | SF | 6 | \$2,385 | |
| | Walls - Structural Glazed Tile | 1st Floor | 762 | SF | 6 | \$2,397 | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor | 54 | SF | 6 | \$122 | |
| | Water Closet | 1st Floor | 2 | EA | 6 | \$672 | |
| | Water Closet | 1st Floor | 7 | EA | 6 | \$2,352 | |
| | Accessories | 275 | 39 | SF | 6 | \$360 | |
| | Ceiling - Plaster/Drywall | 275 | 39 | SF | 6 | \$135 | |
| | Doors - Wood Doors inclu hw | 275 | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 275 | 39 | SF | 5 | \$175 | |
| | Lavatory | 275 | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | 275 | 1 | EA | 4 | \$393 | |
| | Partitions | 275 | 1 | EA | 6 | \$297 | |
| | Walls - Concrete Block | 275 | 198 | SF | 6 | \$580 | |
| | Water Closet | 275 | 1 | EA | 6 | \$336 | |
| | Accessories | 2nd Floor | 61 | SF | 6 | \$563 | |
| | Accessories | 2nd Floor | 336 | SF | 6 | \$3,099 | |
| | Accessories | 2nd Floor | 306 | SF | 6 | \$2,822 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 61 | SF | 6 | \$211 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 306 | SF | 6 | \$1,059 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 336 | SF | 6 | \$1,163 | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor Drain | 2nd Floor | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 2nd Floor | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 2nd Floor | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 306 | SF | 6 | \$648 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 336 | SF | 6 | \$711 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 61 | SF | 6 | \$129 | |
| | Hand Dryer | 2nd Floor | 1 | EA | 6 | \$230 | |
| | Hand Dryer | 2nd Floor | 1 | EA | 6 | \$230 | |
| | Lavatory | 2nd Floor | 3 | EA | 6 | \$959 | |
| | Lavatory | 2nd Floor | 3 | EA | 6 | \$959 | |
| | Lavatory | 2nd Floor | 1 | EA | 6 | \$320 | |

Building: Addition 2

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|---------------------------------|-----------|----------|------|------|---------|----------|
| Restroom | | | | | | | |
| | Lighting - Pendent/Surface | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 5 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 5 | EA | 7 | \$0 | |
| | Partitions | 2nd Floor | 2 | EA | 6 | \$594 | |
| | Partitions | 2nd Floor | 7 | EA | 6 | \$2,078 | |
| | Urinals | 2nd Floor | 5 | EA | 6 | \$1,680 | |
| | Walls - Concrete Block | 2nd Floor | 194 | SF | 6 | \$569 | |
| | Walls - Plaster/Drywall | 2nd Floor | 37 | SF | 6 | \$102 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 762 | SF | 6 | \$2,397 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 758 | SF | 6 | \$2,385 | |
| | Walls - Tile Ceramic/ Porcelain | 2nd Floor | 54 | SF | 6 | \$122 | |
| | Water Closet | 2nd Floor | 7 | EA | 6 | \$2,352 | |
| | Water Closet | 2nd Floor | 1 | EA | 6 | \$336 | |
| | Water Closet | 2nd Floor | 2 | EA | 6 | \$672 | |

Rooms (Other Than Classrooms) Subtotal:

\$150,359

Building: Addition 2

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|--------------------------------------|-----------|----------|------|------|----------|----------|
| Corridor | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 2,312 | SF | 6 | \$14,316 | |
| | Doors - Steel Doors incl hw | 1st Floor | 8 | EA | 6 | \$2,408 | |
| | Drinking Fountains - Double Fountain | 1st Floor | 2 | EA | 6 | \$672 | |
| | Floor - Tile/Sheet | 1st Floor | 2,312 | SF | 6 | \$1,256 | |
| | Lighting | 1st Floor | 26 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | 1st Floor | 36 | EA | 6 | \$3,342 | |
| | Walls - Concrete Block | 1st Floor | 2,304 | SF | 6 | \$6,754 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 2,312 | SF | 6 | \$14,316 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 1 | EA | 6 | \$336 | |
| | Floor - Tile/Sheet | 2nd Floor | 2,312 | SF | 6 | \$1,256 | |
| | Lighting - Pendent/Surface | 2nd Floor | 26 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | 2nd Floor | 36 | EA | 6 | \$3,342 | |
| | Walls - Concrete Block | 2nd Floor | 2,304 | SF | 6 | \$6,754 | |
| | Ceiling - Plaster/Drywall | Basement | 1,284 | SF | 6 | \$7,950 | |
| | Floor - Tile/Sheet | Basement | 1,284 | SF | 6 | \$698 | |

Building: Addition 2

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------------|---|-----------------------------|----------|------|------|----------|----------|
| Corridor | | | | | | | |
| | Lighting - Pendent/Surface | Basement | 12 | EA | 7 | \$0 | |
| | Stairs - Concrete Stairs | Basement | 10 | LF | 6 | \$83 | |
| | Walls - Concrete Block | Basement | 3,358 | SF | 6 | \$9,844 | |
| Safety | | | | | | | |
| | Camera Viewing Station | 1st Floor | 3 | EA | 6 | \$2,048 | |
| | Security Cameras | 1st Floor / Entire Building | 6 | EA | 6 | \$1,164 | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | East | 144 | SF | 6 | \$1,054 | |
| | Floor - Terrazzo | East | 40 | SF | 6 | \$336 | |
| | Handrails | East | 72 | LF | 6 | \$624 | |
| | Lighting - Pendent/Surface | East | 2 | EA | 6 | \$248 | |
| | Stairs - Terrazzo | East | 36 | LF | 6 | \$334 | |
| | Walls - Concrete Block | East | 1,080 | SF | 6 | \$3,166 | |
| | Ceiling - Plaster/Drywall | North West | 144 | SF | 6 | \$1,054 | |
| | Floor - Terrazzo | North West | 40 | SF | 6 | \$336 | |
| | Handrails | North West | 72 | LF | 6 | \$624 | |
| | Lighting - Pendent/Surface | North West | 2 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | North West | 36 | LF | 6 | \$334 | |
| | Walls - Concrete Block | North West | 1,080 | SF | 6 | \$3,166 | |
| | Ceiling - Plaster/Drywall | South | 144 | SF | 6 | \$1,054 | |
| | Floor - Terrazzo | South | 40 | SF | 6 | \$336 | |
| | Handrails | South | 72 | LF | 6 | \$624 | |
| | Lighting - Pendent/Surface | South | 2 | EA | 6 | \$248 | |
| | Stairs - Terrazzo | South | 36 | LF | 6 | \$334 | |
| | Walls - Concrete Block | South | 1,080 | SF | 6 | \$3,166 | |
| Vertical Conveyance | | | | | | | |
| | Elevator - Elevator- Roped Holeless Hydraulic | 1st Floor | 1 | EA | 6 | \$19,238 | |

Building Interior Subtotal: \$113,417

Total Building Cost \$1,882,332

SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|-------------|----------|----------|------|------|------|----------|
|-------|-------------|----------|----------|------|------|------|----------|

SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------|-----------------------------------|-------------------------------|----------|------|------|----------|--|
| Athletic | | | | | | | |
| | Surface - Asphalt | West | 8,383 | SF | 6 | \$20,259 | |
| Civil/Drainage | | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 9 | EA | 6 | \$9,845 | |
| | Civil/ Drainage - Site Manhole | Entire Site | 8 | EA | 6 | \$11,942 | |
| Fencing | | | | | | | |
| | Fencing - Chain Link | Entire Site | 200 | LF | 6 | \$3,755 | |
| | Fencing - New Standard Ornamental | Entire Site | 1,403 | LF | 6 | \$44,760 | |
| | Fencing - Old Standard Ornamental | Entire Site / Site North | 417 | LF | 6 | \$21,586 | |
| Landscape | | | | | | | |
| | Benches | Entire Site / West | 2 | EA | 5 | \$1,775 | missing planks |
| | Landscape - Grass | Entire Site | 53,962 | SF | 6 | \$44,756 | |
| | Landscape - Hardscape- Concrete | Entire Site / North Courtyard | 1,233 | SF | 6 | \$7,494 | |
| | Landscape - Hardscape- Concrete | Entire Site / South Courtyard | 2,482 | SF | 5 | \$23,212 | cracks & spalling |
| | Parkway trees | Entire Site | 47 | EA | 7 | \$0 | |
| | Planting Beds/ Area | Entire Site | 600 | SF | 6 | \$987 | |
| | Play Area - Asphalt/ Hardscape | Entire Site / South | 4,931 | SF | 6 | \$11,917 | |
| | Retaining Wall - Concrete | Entire Site | 800 | SF | 6 | \$18,750 | Location: at basement wells - remove tree at NE addition 2 |
| | Retaining Wall - Concrete | Entire Site / North | 120 | SF | 6 | \$3,320 | |
| Parking Lot | | | | | | | |
| | Concrete Curbs | Entire Site | 250 | LF | 6 | \$3,210 | at planting bed |
| | Interior Plantings | Entire Site | 105 | LF | 6 | \$4,467 | |
| | Surface - Asphalt | Entire Site | 24,927 | SF | 6 | \$60,241 | |
| | Surface - Concrete | Entire Site / North | 1,125 | SF | 5 | \$10,521 | cracks |
| | Trash Enclosure - Chain Links | Entire Site / South West | 911 | SF | 5 | \$28,855 | bent gate |
| Playground | | | | | | | |
| | Equipment - Combo 3-12 | Southeast | 1 | EA | 6 | \$7,092 | graffiti |
| | Surface - Poured Surface | Southeast | 2,535 | SF | 6 | \$18,560 | |
| Sidewalks | | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 15 | LF | 5 | \$867 | door 2 spalling |
| | Sidewalks - Internal Walks | Entire Site | 271 | LF | 6 | \$3,255 | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 25,688 | SF | 6 | \$51,060 | |
| | Sidewalks - Perimeter Sidewalks | Entire Site / East | 250 | SF | 5 | \$2,388 | cracks & movement |

SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------|---|--------------------------|----------|------|------|---------|---------------------|
| Signage | | | | | | | |
| | Flag Pole - Building Mounted Flag Pole | Entire Site / North East | 1 | EA | 6 | \$828 | |
| | Flag Pole - Flag Pole | Entire Site / North East | 1 | EA | 6 | \$1,657 | |
| | Marquee - Building Mounted Back Lighted | Entire Site / North West | 1 | EA | 6 | \$0 | |
| | Marquee - Free Standing Back Lighted | Entire Site / East | 1 | EA | 6 | \$0 | |
| | Marquee - Free Standing Back Lighted | Entire Site / North East | 1 | EA | 6 | \$0 | |
| | Monument - Building Mounted Cut Letter Sign | Entire Site | 1 | EA | 6 | \$0 | Location: at door 6 |
| | Monument - Building Mounted Cut Letter Sign | Entire Site / North East | 1 | EA | 6 | \$0 | |
| | Monument - Sign | Entire Site / East | 1 | EA | 6 | \$0 | Location: at door 3 |

Site Subtotal:

\$417,360

Total Site Cost

\$417,360

Campus Total ^{2 3}

\$6,616,418

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- **Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- **For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- **Campus Total** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart-Board |
|-------------------|-------------------------|---------------|-------------|------------------------|-----------|---------------|--------------|----------------|--------------------|----------------------|-------------|-------------|-------------|-------------|
| Main | | | | | | | | | | | | | | |
| Faculty Lounge | Regular Classroom | 1st Floor | 130 | 130 | 690 | 1 | 1 | 6 | 161 | 84 | 40 | N | Y | N |
| Faculty Lounge | Regular Classroom | 1st Floor | 141 | 141 | 621 | 1 | 2 | 12 | 161 | 84 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 131 | 131 | 690 | 1 | 2 | 6 | 161 | 84 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 133 | 133 | 690 | 1 | 2 | 6 | 115 | 60 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 143 | 143 | 835 | 1 | 2 | 8 | 92 | 48 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 147 | 147 | 782 | 1 | | 9 | 92 | 48 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 149 | 149 | 835 | 1 | 2 | 6 | 92 | 48 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 230 | 230 | 650 | 1 | 2 | 10 | 140 | 70 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 231 | 231 | 795 | 1 | 2 | 10 | 196 | 98 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 232 | 232 | 715 | 1 | 2 | 8 | 168 | 84 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 233 | 233 | 670 | 1 | 2 | 10 | 140 | 70 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 243 | 243 | 825 | 1 | 2 | 12 | 112 | 56 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 245 | 245 | 770 | 1 | 2 | 10 | 112 | 56 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 247 | 247 | 800 | 1 | 2 | 8 | 112 | 56 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 249 | 249 | 860 | 1 | 2 | 10 | 112 | 56 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 343 | 343 | 835 | 1 | 2 | 4 | 92 | 48 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 345 | 345 | 782 | 1 | 2 | 8 | 92 | 48 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 347 | 347 | 790 | 1 | 2 | 8 | 112 | 56 | 40 | N | Y | N |
| Regular Classroom | Other Instructional Use | 3rd Floor | 349 | 349 | 835 | 1 | 2 | 10 | 112 | 56 | 40 | N | Y | N |
| Vacant | Regular Classroom | 1st Floor | 145 | 145 | 782 | 1 | 2 | 6 | 92 | 48 | 40 | N | Y | N |

| | | | | | | | | | | | | | | |
|--------------------|-------------------|-----------|-----|-----|-------|---|----|----|-----|-----|----|---|---|---|
| Addition 1 | | | | | | | | | | | | | | |
| Computer Lab | Regular Classroom | 2nd Floor | 225 | 219 | 720 | 1 | 1 | 24 | 150 | 75 | 40 | N | Y | N |
| Computer Lab | Regular Classroom | 2nd Floor | 226 | 216 | 832 | 1 | 40 | 90 | 205 | 102 | 40 | N | Y | N |
| Faculty Lounge | Regular Classroom | 2nd Floor | 224 | 214 | 716 | 0 | 0 | 6 | 150 | 75 | 40 | N | Y | N |
| Kindergarten | Regular Classroom | 1st Floor | 126 | 116 | 722 | 0 | 5 | 4 | 210 | 105 | 40 | N | Y | N |
| Kindergarten | Kindergarten | 1st Floor | 129 | 119 | 1,095 | 1 | 7 | 18 | 357 | 178 | 40 | N | Y | N |
| Multi Purpose Room | Regular Classroom | 2nd Floor | 229 | 217 | 724 | 1 | 4 | 16 | 150 | 75 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 124 | 114 | 712 | 1 | 0 | 6 | 150 | 75 | 40 | N | Y | N |
| Regular Classroom | Special Education | 1st Floor | 127 | 117 | 768 | 0 | 1 | 3 | 150 | 75 | 40 | N | Y | N |

| | | | | | | | | | | | | | | |
|-------------------|-------------------|-----------|-----|-----|-------|---|----|----|-----|-----|----|---|---|---|
| Addition 2 | | | | | | | | | | | | | | |
| Art Room | Regular Classroom | 1st Floor | 111 | 111 | 856 | 1 | 1 | 10 | 172 | 79 | 40 | N | Y | N |
| Computer Lab | Regular Classroom | 1st Floor | 113 | 113 | 856 | 1 | 11 | 36 | 172 | 79 | 40 | N | Y | N |
| Faculty Lounge | Regular Classroom | 1st Floor | 106 | 106 | 856 | 1 | 1 | 10 | 172 | 79 | 40 | N | Y | N |
| Kindergarten | Kindergarten | 1st Floor | 101 | 101 | 1,031 | 1 | 6 | 12 | 344 | 158 | 40 | N | N | N |
| Kindergarten | Kindergarten | 1st Floor | 103 | 103 | 1,031 | 1 | 6 | 12 | 344 | 158 | 40 | N | N | N |

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart-Board |
|-------------------------|-------------------|---------------|-------------|------------------------|-----------|---------------|--------------|----------------|--------------------|----------------------|-------------|-------------|-------------|-------------|
| Addition 2 | | | | | | | | | | | | | | |
| Office | Regular Classroom | 2nd Floor | 203 | 203 | 856 | 1 | 6 | 12 | 179 | 72 | 40 | N | Y | N |
| Office | Regular Classroom | 2nd Floor | 215 | 215 | 856 | 1 | 1 | 10 | 179 | 72 | 40 | N | Y | N |
| Other Instructional Use | Regular Classroom | 2nd Floor | 200 | 200 | 856 | 1 | 1 | 10 | 179 | 72 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 100 | 100 | 856 | 1 | 1 | 10 | 172 | 79 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 102 | 102 | 856 | 1 | 1 | 10 | 172 | 79 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 104 | 104 | 856 | 1 | 1 | 10 | 172 | 79 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 107 | 107 | 879 | 1 | 1 | 10 | 129 | 59 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 108 | 108 | 856 | 1 | 1 | 10 | 172 | 79 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 109 | 109 | 856 | 1 | 1 | 10 | 172 | 79 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 110 | 856 | 1 | 1 | 10 | 172 | 79 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 112 | 112 | 856 | 1 | 1 | 10 | 172 | 79 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 856 | 1 | 6 | 12 | 172 | 79 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 856 | 1 | 1 | 10 | 179 | 72 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 856 | 1 | 1 | 10 | 179 | 72 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 856 | 1 | 1 | 10 | 120 | 57 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 856 | 1 | 1 | 4 | 179 | 72 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 879 | 1 | 1 | 10 | 129 | 59 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 856 | 1 | 1 | 10 | 179 | 72 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 879 | 1 | 1 | 10 | 129 | 59 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 210 | 856 | 1 | 1 | 10 | 179 | 72 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 211 | 211 | 856 | 1 | 1 | 6 | 172 | 79 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | 212 | 856 | 1 | 1 | 10 | 179 | 72 | 40 | N | Y | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 213 | 213 | 856 | 1 | 1 | 10 | 179 | 72 | 40 | N | Y | N |