821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|-------------------------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1974 | 2 | 218,350 | \$10,227,944 |
| Linked Addition-Main Athletic | 1974 | 2 | 54,301 | \$2,319,587 |
| SITE | | | | \$1,308,454 |
| Campus Total | | | 272,651 | \$13,855,985 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|---|----------|------|------|---------|---|
| Entrand | ce | | | | | | |
| | Entrance Control - Audio and Video | Entrance 13-South | 1 | EA | 6 | \$702 | |
| | Entrance Control - Audio and Video | Entrance 15-East | 1 | EA | 6 | \$702 | |
| | Entrance Control - Audio and Video | Entrance 16-East | 1 | EA | 5 | \$1,567 | Video not working |
| | Entrance Control - Audio and Video | Entrance 7-West | 1 | EA | 5 | \$1,567 | Video not working properly |
| | Exterior Doors - Exterior FRP Door | Entrance 15-East | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | Entrance 16-East | 1 | EA | 6 | \$631 | |
| | Exterior Doors - Exterior FRP Door | Entrance 1-NW | 1 | EA | 5 | \$1,836 | 1-Interior door hardware damaged - Not working properly |
| | Exterior Doors - Exterior FRP Door | Entrance 1-NW | 1 | EA | 6 | \$631 | |
| | Exterior Doors - Exterior FRP Door | Entrance 2-NW | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | Entrance 5-West | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | Entrance 6-West | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | Entrance 7-West | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | Entrance 8-West | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior Steel Door | Entrance 24 - Basement corridor to loading dock elevated platform | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Exterior Steel Door | Exit 4-West | 2 | EA | 6 | \$961 | |
| | Exterior Doors - Overhead Rolling/ Garage Door | Entrance 22-East - Loading dock | 1 | EA | 6 | \$1,433 | |
| | Exterior Doors - Overhead Rolling/ Garage Door | Entrance 23 - Outside yard storage | 1 | EA | 6 | \$1,433 | |
| | Exterior Doors - Side lite | Entrance 10-West | 4 | EΑ | 6 | \$1,253 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

Category: Building Exterior

| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|--|----------|----------|--------|----------------|---|
| Entrand | • | | | Jt | | 0000 | |
| | Exterior Doors - Side lite | Entrance 11-SW - Classroom 182 | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 12-SW - Classroom 183 | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 13-South | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 14A-South | 4 | EA | 5 | \$1,904 | |
| | Exterior Doors - Side lite | Entrance 14-South | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 15-East | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 16-East | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 1-NW | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 2-NW | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 3-West | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 5-West | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 6-West | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 7-West | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 8-West | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 9-West | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Exit 4-West | 2 | EA | 6 | \$627 | |
| | Exterior Doors - Store Front | Entrance 10-West | 1 | EA | 5 | \$1,836 | Exterior door hardware damaged, ponding |
| | | | | | | | occurring due to water penetration from |
| | Estados Danos Otas Estad | Falson 44 0W Olassan 400 | 0 | ^ | 0 | #4.000 | underneath door |
| | Exterior Doors - Store Front | Entrance 11-SW - Classroom 182 | 2 | EΑ | 6 | \$1,092 | |
| | Exterior Doors - Store Front | Entrance 12-SW - Classroom 183 | 2 | EΑ | 6 | \$1,092 | |
| | Exterior Doors - Store Front | Entrance 13-South | 2 | EΑ | 6 | \$1,092 | |
| | Exterior Doors - Store Front | Entrance 14A-South | 2 | EΑ | 6 | \$1,092 | |
| | Exterior Doors - Store Front | Entrance 14-South | 2 | EΑ | 6 | \$1,092 | |
| | Exterior Doors - Store Front | Entrance 3-West | 2 | EΑ | 6 | \$1,092 | |
| | Exterior Doors - Store Front Exterior Doors - Transom Lite | Entrance 9-West Entrance 10-West | 2 1 | EA EA | 6 6 | \$1,092 | |
| | Exterior Doors - Transom Lite | Entrance 10-West Entrance 11-SW - Classroom 182 | 1 | EA | 6 | \$313 \$313 | |
| | Exterior Doors - Transom Lite | Entrance 17-5W - Classroom 183 | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 12-5w - Classroom 163 Entrance 13-South | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 14A-South | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 14-South | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 14-30um | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 15-East Entrance 16-East | 1 | EA | 6 | | |
| | Exterior Doors - Transom Lite | Entrance 10-East Entrance 1-NW | 1 | EA | 6 | \$313 \$313 | |
| | Exterior Doors - Transom Lite Exterior Doors - Transom Lite | Entrance 1-NW Entrance 2-NW | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite Exterior Doors - Transom Lite | Entrance 2-INW Entrance 3-West | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 5-West | 1 | EA | 6 | \$313 | |
| | EXIGNOL DOOLS - HAUSOM FIRE | Entrance 5-West | 1 | EA | Ö | Ф 313 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

Category: Building Exterior

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|---|----------|-------|--------|---------------|--|
| Entranc | 2. | Location | Quantity | Offic | Italik | COSI | Comments |
| Lilliand | Exterior Doors - Transom Lite | Entrance 6-West | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 7-West | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 8-West | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 9-West | 1 | EA | 6 | \$313 | |
| | | Exit 4-West | • | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | | 1 7 | LF | | | |
| | Exterior Stairs - Concrete | Entrance 24 - Basement corridor to loading dock elevated platform | 7 | _ | 6 | \$572 | |
| | Power Door Operator and Controls | Entrance 16-East | 1 | EA | 6 | \$0 | |
| | Power Door Operator and Controls | Entrance 7-West | 1 | EA | 6 | \$0 | |
| | Ramps - Concrete | Entrance 22-East - Loading dock | 5 | LF | 5 | \$2,658 | Area in between site drains cracked, loose with missing areas |
| | Ramps - Concrete | Entrance 22-East - Loading dock | 175 | LF | 6 | \$26,291 | |
| | Stair Handrail - Steel_Stair Handrail | Entrance 24 - Basement corridor to loading dock elevated platform | 14 | LF | 6 | \$121 | |
| Founda | tion | | | | | | |
| | Foundation - Concrete | Entire Building | 2,075 | LF | 7 | \$0 | |
| | Superstructure - Steel | Entire Building | 218,350 | SF | 7 | \$0 | |
| | | | | | | | |
| Lighting | | | | | | A= 100 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 12 | EA | 5 | | Per Building Engineer - Not operating |
| | Exterior Lighting - Wall Mounted | Entire Building | 1 | EA | 5 | | South - Damaged housing, cover, no bulb with exposed wiring hanging out - not working properly |
| | Exterior Lighting - Wall Mounted | Entire Building | 11 | EA | 6 | \$3,176 | |
| Roof Sy | ystem | | | | | | |
| | Coping - Metal | Roof 1 | 2,110 | LF | 6 | \$67,769 | |
| | Downspouts - Interior Downspouts | Roof 1 | 690 | LF | 6 | \$22,931 | |
| | Parapet - Parapet < 16" Height | Roof 1 | 2,110 | LF | 6 | \$44,958 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof 1 | 103,780 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | Roof 1 | 5,000 | SF | 4 | \$257,186 | Several areas blistering, bubbling, cracking, worn out with open seams throughout / Several holes in membrane around roof penetrations / Ponding occurring around mechanical equipment and roof drains |
| | Roof - Modified Bitumen | Roof 1 | 98,780 | SF | 6 | \$929,461 | |
| Walls | | | | | | | |
| vvalis | Exterior Walls - Brick | Entire Building | 29,655 | SF | 6 | \$199,311 | |
| | Exterior Walls - Brick | Entire Building / North Façade | 2,000 | SF | 5 | | Several areas cracked, chipped with loose or |
| | EXCIDITYTURE - DITOR | Entire Building / North Agade | 2,000 | OI. | 3 | ψ-17,019 | missing mortar joints / North - Stepped cracking with areas bulging out |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

Category: Building Exterior

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------------|-----------------|----------|------|------|-----------|----------|
| Walls | | | | | | |
| Windows | | | | | | |
| Curtain wall - Glazed Double Pane | Entire Building | 24,943 | SF | 6 | \$279,641 | |
| Curtain wall - Glazed Single Pane | Entire Building | 4,931 | SF | 6 | \$55,282 | |
| Curtain wall - Insulated Panel | Entire Building | 250 | SF | 6 | \$2,803 | |
| Skylite - Lexan | Entire Building | 60 | SF | 6 | \$1,434 | |

Building Exterior Subtotal:

\$2,002,909

Building: Main

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--|--|----------|------|------|----------|---|
| Emerge | ency System | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 2 | EA | 6 | \$816 | ATS #1,2 also serves the Annex |
| | Emergency A/C Power - Auditoium and Aisle Lighting | 1st floor, Entire Building / 1st Floor | 7,212 | SF | 6 | \$3,816 | |
| | Emergency A/C Power - Corridors and Stairs | 1st floor, Entire Building / Entire Building | 39,706 | SF | 6 | \$11,924 | |
| | Emergency A/C Power - Students Toilets | 1st floor, Entire Building / Entire Building | 3,857 | SF | 6 | \$1,434 | |
| | Exit Signs - Auditoium | Entire Building / 1st Floor | 6 | EA | 7 | \$0 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 44 | EA | 7 | \$0 | |
| | Exit Signs - Lunchroom | Entire Building / 1st Floor | 4 | EA | 7 | \$0 | |
| | Security System - CCTV | Entire Building | 218,350 | SF | 6 | \$65,571 | |
| | Security System - Intrusion Detection | Entire Building | 218,350 | SF | 6 | \$56,203 | |
| Main S | ervice | | | | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | \$2,921 | |
| | Main Electrical Service - 2001 to 3000 A 277/480/3PH | Electrical Room | 2 | EA | 7 | \$0 | |
| | PA System | Entire Building | 109,175 | SF | 6 | \$35,908 | Serves Butler College est. Sqft on coverage |
| | PA System | Entire Building | 109,175 | SF | 6 | \$35,908 | Serves Corliss est. Sqft on coverage |
| Power | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building / Electrical Room | 1 | EA | 7 | \$0 | Emergency lights fuse type |
| | Lighting and Power Panels - 100 A | Entire Building / Electrical Room | 7 | EA | 7 | \$0 | |
| | Lighting and Power Panels - 100 A | Entire Building / Electrical Room | 20 | EA | 7 | \$0 | |
| | Lighting and Power Panels - 100 A | Entire Building / Electrical Room | 5 | EA | 7 | \$0 | Emergency lights fuse type |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 2 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 1 | EA | 7 | \$0 | Serves 4/12 dock drive heaters are broken |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 2 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 2 | EA | 7 | \$0 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---|-----------------------------------|----------|------|------|---------|----------|
| Power | Distribution | | | | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 2 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 2 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 7 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 12 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 4 | EΑ | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 3 | EΑ | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Electrical Room | 1 | EΑ | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Electrical Room | 3 | EΑ | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Electrical Room | 3 | EΑ | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Electrical Room | 4 | EΑ | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Electrical Room | 2 | EΑ | 7 | \$0 | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building / Electrical Room | 6 | EΑ | 7 | \$0 | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building / Electrical Room | 1 | EΑ | 7 | \$0 | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building / Electrical Room | 5 | EΑ | 7 | \$0 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Electrical Room | 2 | EΑ | 6 | \$2,530 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Electrical Room | 2 | EΑ | 6 | \$2,530 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Electrical Room | 1 | EΑ | 6 | \$1,265 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Electrical Room | 1 | EΑ | 6 | \$1,265 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Electrical Room | 1 | EΑ | 6 | \$1,265 | |
| | Transformers - 277/480 - 120/208 | Entire Building / Electrical Room | 1 | EA | 6 | \$1,265 | |
| | | | | | | *** | |

Electrical System Subtotal:

\$224,619

Building: Main

Category: Safty System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------|---|----------|------|------|-----------|----------|
| Fire Al | arm | | | | | | |
| | Fire Alarm Panel | 1st Floor | 1 | EA | 6 | \$6,406 | |
| | Fire Alarm Strobe Lights | 1st Floor / Entire Building | 218,350 | SF | 6 | \$78,060 | |
| | Fire Alarm_System | 1st Floor / Entire Building | 218,350 | SF | 6 | \$106,162 | |
| | Fire Pump Controller | 1st Floor | 1 | EA | 7 | \$0 | |
| Pump | Room Assembly | | | | | | |
| | Fire Pump - 25-50 hp | Mechanical Room | 1 | EA | 6 | \$1,558 | |
| | Jockey Pump | Mechanical Room / Mechanical Building/Central Plant | 1 | EA | 6 | \$758 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

Category: Safty System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|--|----------|------|------|---------|--------------|
| Pump F | Room Assembly | | | | | | |
| Sprinkl | er System | | | | | | |
| | Combination Wet and Dry Sprinkler System | Basement, Entire Building / Mechanical Room | 218,350 | SF | 7 | \$0 | |
| | Dry Sprinkler System | Basement, Entire Building / Basement | 5,400 | SF | 7 | \$0 | Loading dock |
| | Sprinkler Heads | Basement, Entire Building / Entire Building | 218,350 | SF | 7 | \$0 | |
| | Sprinkler Piping | Basement, Entire Building / Entire Building | 218,350 | SF | 7 | \$0 | |
| | Wet Sprinkler System | Basement, Entire Building / Entire Building | 218,350 | SF | 7 | \$0 | |
| Safty | System Subtotal: | | | | \$ | 192,943 | |

Building: Main

Category: Mechanical System

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|----------|----------|------|------|---------|-----------------------|
| ir Con | ditioning | | | | | | |
| | Condensing Unit- Roof Mounted - 11-20 tons | Roof | 1 | EA | 7 | \$0 | Serves Butler College |
| | Condensing Unit- Roof Mounted - 5-10 tons | Roof | 1 | EA | 7 | \$0 | Serves Butler College |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 6 | \$3,334 | Serves MDF |
| ir Han | dling Systems | | | | | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 6 | \$2,792 | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 7 | \$0 | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 6 | \$2,792 | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - Greater than 60 tons | Roof | 1 | EA | 6 | \$2,792 | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - Greater than 60 tons | Roof | 1 | EA | 6 | \$2,792 | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - Greater than 60 tons | Roof | 1 | EA | 6 | \$2,792 | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - Greater than 60 tons | Roof | 1 | EA | 6 | \$2,792 | |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 21 - 30 tons | Roof | 1 | EA | 6 | \$2,792 | serve 2'nd floor East |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 21 - 30 tons | Roof | 1 | EA | 6 | \$2,792 | serves 3-d floor west |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

Category: Mechanical System

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------|--|--|----------|------|------|-------------|--|
| Air Hand | dling Systems | | | | | | |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 21 - 30 tons | Roof | 1 | EA | 6 | \$2,792 | Serves Kitchen |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 31 - 45 tons | Roof | 1 | EA | 6 | \$2,792 | Serves Auditorium |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 31 - 45 tons | Roof | 1 | EA | 6 | \$2,792 | serves 2'd floor West |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 31 - 45 tons | Roof | 1 | EA | 6 | \$2,792 | serves 3'd floor East |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 31 - 45 tons | Roof | 1 | EA | 6 | \$2,792 | servges gym |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 31 - 45 tons | Roof | 1 | EA | 6 | \$2,792 | Serves Auditorium |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Greater than 45 tons | Roof | 1 | EA | 6 | \$2,792 | serves gym |
| Heating | Devices | | | | | | |
| | Fin Tube - Electric | Entire Building | 2,250 | LF | 6 | \$21,236 | |
| | Under Floor Heating- Hot Water | Loading Dock / Basement | 1,200 | SF | 5 | \$1,160,170 | 4-12 Under floor Electric heat strips for dock area do not work. |
| | Unit Heater - Electric | Entire Building | 12 | EA | 6 | \$3,334 | |
| | Unit Heater - Electric | Entire Building | 2 | EA | 5 | \$2,015 | |
| Tempera | ature Control | | | | | | |
| | DDC System | Entire Building | 218,350 | SF | 5 | \$359,077 | Program not responding, no computer control. Manual operation only. |
| | Electric Controls | Entire Building | 218,350 | SF | 6 | \$0 | , , |
| | Electric Thermostat | Entire Building / 2nd Floor | 1 | EA | 7 | \$0 | Serves New Split System for Butler College |
| | Thermostats - DDC | Entire Building | 50 | EA | 6 | \$0 | |
| Ventilati | ion | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Electrical Room, Mechanical Room, Roof, 2nd floor / Mechanical Room | 2 | EA | 6 | \$1,185 | Serves Building |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Electrical Room, Mechanical Room, Roof, 2nd floor / Mechanical Room | 2 | EA | 6 | \$1,185 | Serves Dock |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Electrical Room, Mechanical Room, Roof, 2nd floor / Electrical Room | 1 | EA | 6 | \$592 | Serves Main Electrical room |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Electrical Room, Mechanical Room, Roof, 2nd floor / Roof | 15 | EA | 6 | \$8,886 | Serves RTU's |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Electrical Room, Mechanical Room, Roof, 2nd floor / Roof | 4 | EA | 4 | \$25,568 | Serves RTU's |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Electrical Room, Mechanical Room, Roof, 2nd floor / Roof | 3 | EA | 7 | \$0 | Serves Restrooms |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|--|----------|------|------|----------|--|
| Ventila | ion | | | | | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Electrical Room, Mechanical Room, Roof, 2nd floor / Roof | 1 | EA | 6 | \$592 | Serves Kitchen |
| | Lab Exhaust Hood | Electrical Room, Mechanical Room, Roof, 2nd floor / 2nd Floor | 1 | EA | 6 | \$1,248 | |
| | Roof Mounted Duct Work | Electrical Room, Mechanical Room, Roof, 2nd floor / Roof | 200 | LF | 6 | \$75,804 | Mounted on RTU's with exhaust fans |
| | Type II Exhaust Hood- Warming Kitchen | Electrical Room, Mechanical Room, Roof, 2nd floor / Roof | 1 | EA | 7 | \$0 | Hood is due for cleaning and service test of supression system |

Mechanical System Subtotal:

\$1,706,100

Building: Main

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | | | |
|--------|--|-----------------|----------|------|------|-----------|----------|--|--|--|
| Hot Wa | lot Water | | | | | | | | | |
| | Electric Heater - Greater than 50 KW | Mechanical Room | 2 | EA | 6 | \$1,364 | | | | |
| Piping | | | | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 218,350 | SF | 6 | \$43,714 | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 218,350 | SF | 6 | \$53,081 | | | | |
| | Domestic Piping-Cold Water Risers | Entire Building | 218,350 | SF | 6 | \$40,591 | | | | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 218,350 | SF | 6 | \$34,346 | | | | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 218,350 | SF | 6 | \$40,591 | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 218,350 | SF | 6 | \$31,224 | | | | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 218,350 | SF | 6 | \$31,224 | | | | |
| | Sanitary Piping | Entire Building | 218,350 | SF | 6 | \$199,834 | | | | |
| | Storm Piping | Entire Building | 218,350 | SF | 6 | \$190,467 | | | | |
| | Vent Piping | Entire Building | 218,350 | SF | 6 | \$146,753 | | | | |
| Pumps | | | | | | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | Mechanical Room | 1 | EA | 6 | \$1,977 | | | | |
| | Pumps - Ejector-Duplex | Mechanical Room | 1 | EA | 6 | \$1,387 | | | | |
| | Pumps - Sump-Duplex | Mechanical Room | 1 | EA | 6 | \$1,387 | | | | |

Plumbing System Subtotal:

\$817,940

Building: Main



Noble - Butler College Prep 821 E 103rd St Chicago, IL 60628

| | | | | | | Co-locating on | this campus are CORLISS HS and NOBLE - BUTLER H |
|---------|------------------------------------|----------|----------|------|------|----------------|---|
| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | om #015 (Music Room) | | | | | | |
| | Ceiling - Exposed | Basement | 2,220 | SF | 6 | \$3,302 | |
| | Doors - Wood Doors inclu hw | Basement | 2 | EA | 6 | \$602 | |
| | Floor - Concrete Epoxy/ Painted | Basement | 2,220 | SF | 6 | \$1,175 | |
| | Lighting - Pendent/Surface | Basement | 10 | EA | 7 | \$0 | |
| | Marker Board | Basement | 14 | LF | 7 | \$0 | |
| | Walls - Concrete Block | Basement | 318 | SF | 6 | \$932 | |
| | Walls - Plaster/Drywall | Basement | 996 | SF | 6 | \$2,749 | |
| Classro | om #016 (Art Room) | | | | | | |
| | Ceiling - Exposed | Basement | 827 | SF | 6 | \$1,230 | |
| | Doors - Wood Doors inclu hw | Basement | 2 | EA | 6 | \$602 | |
| | Floor - Concrete Epoxy/ Painted | Basement | 827 | SF | 6 | \$438 | |
| | Lighting - Pendent/Surface | Basement | 20 | EA | 7 | \$0 | |
| | Marker Board | Basement | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | Basement | 318 | SF | 6 | \$932 | |
| | Walls - Plaster/Drywall | Basement | 996 | SF | 6 | \$2,749 | |
| | Work Sink | Basement | 1 | EA | 6 | \$379 | |
| Classro | om #017 (Computer Lab) | | | | | | |
| | Ceiling - Plaster/Drywall | Basement | 1,048 | SF | 6 | \$3,627 | |
| | Doors - Wood Doors inclu hw | Basement | 1 | EΑ | 6 | \$301 | |
| | Floor - Wood | Basement | 1,048 | SF | 6 | \$7,388 | |
| | Lighting - Wall Mounted | Basement | 30 | EΑ | 6 | \$3,717 | |
| | Marker Board | Basement | 8 | LF | 6 | \$171 | |
| | Walls - Masonry | Basement | 2,620 | SF | 6 | \$8,243 | |
| Classro | om #0506 (Other Instructional Use) | | | | | | |
| | Ceiling - Plaster/Drywall | Basement | 2 | SF | 6 | \$7 | |
| | Doors - Steel Doors incl hw | Basement | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | Basement | 121 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Basement | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Basement | 302 | SF | 6 | \$885 | |
| Classro | om #0515 (Weight) | | | | | | |
| | Ceiling - Plaster/Drywall | Basement | 583 | SF | 6 | \$2,018 | |
| | Doors - Steel Doors incl hw | Basement | 1 | EA | 6 | \$301 | |
| | Floor - Sport Flooring | Basement | 583 | SF | 6 | \$1,259 | |
| | Lighting - Pendent/Surface | Basement | 8 | EA | 6 | \$991 | |
| | Wall Mirrors | Basement | 1 | SF | 6 | \$0 | |
| | Walls - Concrete Block | Basement | 875 | SF | 6 | \$2,565 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|------------------------|----------|----------|--------|------------|--------------------------------------|
| • | pom #112 (Computer Lab) | Location | Quantity | Oilit | Ivalik | COSI | Comments |
| Ciassi | Casework | 1st Floor | 6 | LF | 6 | \$152 | |
| | Ceiling - Lay-in | 1st Floor | 2,151 | SF | 6 | \$6,459 | |
| | Doors - Side-lite | 1st Floor | 2,131 | SF | 6 | | steel frame w/glass |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | \$234 | Steel solid panel w/glass lite |
| | Doors - Steel Doors incl hw | 1st Floor | | EA | | | |
| | Doors - Transom Window | 1st Floor | 4 225 | SF | 6 6 | \$1,204 | w/glass lites Steel frame w/glass |
| | Floor - Tile/Sheet | 1st Floor | 2,151 | SF | | \$2,153 | Steer frame w/grass |
| | | 1st Floor | , | | 6 | | |
| | Lighting - Lay-in | | 77 | EA | 7 | \$0 \$0 | |
| | Marker Board | 1st Floor 1st Floor | 6 | LF SF | 7 | \$0 | |
| | Walls - Concrete Block | | 473 | | 6 | \$1,387 | |
| | Walls - Metal Panel | 1st Floor | 1,420 | SF | 6 | \$10,600 | |
| Classro | oom #112A (Computer Lab) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 960 | SF | 6 | \$2,883 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 960 | SF | 6 | \$961 | |
| | Lighting - Lay-in | 1st Floor | 15 | EA | 6 | \$1,785 | |
| | Marker Board | 1st Floor | 10 | LF | 6 | \$214 | |
| | Walls - Masonry | 1st Floor | 480 | SF | 6 | \$1,510 | |
| | Walls - Metal Panel | 1st Floor | 960 | SF | 6 | \$7,166 | |
| Classro | oom #113 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 2,151 | SF | 6 | \$6,459 | |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | | Steel solid panel w/glass lite |
| | Doors - Side-lite | 1st Floor | 180 | SF | 6 | \$3,009 | Steel framed - glass |
| | Doors - Steel Doors incl hw | 1st Floor | 5 | EA | 6 | | w/glazing |
| | Doors - Transom Window | 1st Floor | 358 | SF | 6 | \$6,061 | |
| | Floor - Tile/Sheet | 1st Floor | 2,151 | SF | 6 | \$2,153 | |
| | Lighting - Lay-in | 1st Floor | 77 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 6 | LF | 7 | \$0 | |
| | Walls - Metal Panel | 1st Floor | 1,800 | SF | 6 | \$13,436 | |
| Classro | oom #114 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 6 | LF | 6 | \$152 | |
| | Ceiling - Lay-in | 1st Floor | 1,611 | SF | 6 | \$4,838 | |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | \$234 | steel panel w/glass insert lite |
| | Doors - Side-lite | 1st Floor | 100 | SF | 6 | \$1,672 | - |
| | Doors - Steel Doors incl hw | 1st Floor | 5 | EA | 6 | | w/ glazing |
| | Doors - Transom Window | 1st Floor | 152 | SF | 6 | \$2,574 | steel frame - glass |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-----------|----------|--------|---------|----------|----------|
| • | oom #114 (Regular Classroom) | 200411011 | quantity | O.I.I. | rturiit | 0001 | |
| | Floor - Tile/Sheet | 1st Floor | 1,611 | SF | 6 | \$1,613 | |
| | Lighting - Lay-in | 1st Floor | 66 | EA | 6 | \$7,852 | |
| | Marker Board | 1st Floor | 8 | LF | 6 | \$171 | |
| | Walls - Metal Panel | 1st Floor | 1,671 | SF | 6 | \$12,473 | |
| Classro | oom #114A (Computer Lab) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 960 | SF | 6 | \$2,883 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 960 | SF | 6 | \$961 | |
| | Lighting - Lay-in | 1st Floor | 30 | EΑ | 6 | \$3,569 | |
| | Marker Board | 1st Floor | 6 | LF | 6 | \$129 | |
| | Walls - Metal Panel | 1st Floor | 2,102 | SF | 6 | \$15,691 | |
| Classro | oom #122 (Science Lab Level 3) | | | | | | |
| | Casework | 1st Floor | 8 | LF | 6 | \$202 | |
| | Ceiling - Lay-in | 1st Floor | 1,818 | SF | 6 | \$5,459 | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EΑ | 6 | \$602 | |
| | Floor - Tile/Sheet | 1st Floor | 1,818 | SF | 6 | \$1,820 | |
| | Lighting - Lay-in | 1st Floor | 36 | EΑ | 5 | \$5,839 | |
| | Marker Board | 1st Floor | 24 | LF | 7 | \$0 | |
| | Walls - Metal Panel | 1st Floor | 1,640 | SF | 6 | \$12,242 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #124 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,449 | SF | 6 | \$4,351 | |
| | Chalk Board | 1st Floor | 4 | LF | 4 | \$367 | |
| | Doors - Side-lite | 1st Floor | 10 | SF | 6 | \$167 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EΑ | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 7 | SF | 6 | \$119 | |
| | Floor - Tile/Sheet | 1st Floor | 1,449 | SF | 6 | \$1,450 | |
| | Lighting - Lay-in | 1st Floor | 27 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 210 | SF | 6 | \$616 | |
| | Walls - Masonry | 1st Floor | 365 | SF | 6 | \$1,148 | Brick |
| | Walls - Metal Panel | 1st Floor | 303 | SF | 6 | \$2,262 | |
| | Work Sink | 1st Floor | 2 | EA | 6 | \$758 | |
| Classro | oom #136 (Science Lab Level 2) | | | | | | |
| | Casework | 1st Floor | 100 | LF | 6 | \$2,525 | |
| | Ceiling - Lay-in | 1st Floor | 2,610 | SF | 6 | \$7,838 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Linit | Dank | Cost | Comments |
|---------|-------------------------------|-----------|----------|-------|-------|----------|--------------|
| • | om #136 (Science Lab Level 2) | Location | Quantity | Offic | Kalik | COSI | Comments |
| Ciassic | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Eye Wash Station | 1st Floor | 1 | EA | 6 | \$336 | |
| | Floor - Tile/Sheet | 1st Floor | | SF | | | |
| | Gas Line | | 2,610 | | 6 | \$2,613 | |
| | | 1st Floor | 10 | EA | 6 | \$5,091 | |
| | Lighting - Lay-in | 1st Floor | 102 | EA | 6 | \$12,136 | |
| | Marker Board | 1st Floor | 12 | LF | 6 | \$257 | |
| | Science Lab Shower | 1st Floor | 1 | EA | 6 | \$379 | |
| | Walls - Concrete Block | 1st Floor | 780 | SF | 6 | \$2,287 | |
| | Walls - Metal Panel | 1st Floor | 2,340 | SF | 6 | \$17,467 | |
| | Work Sink | 1st Floor | 10 | EA | 6 | \$3,790 | |
| Classro | om #139 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 662 | SF | 6 | \$1,988 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 662 | SF | 6 | \$663 | |
| | Lighting - Lay-in | 1st Floor | 28 | EΑ | 6 | \$3,331 | |
| | Walls - Concrete Block | 1st Floor | 233 | SF | 6 | \$683 | |
| | Walls - Masonry | 1st Floor | 349 | SF | 6 | \$1,098 | Brick |
| | Walls - Metal Panel | 1st Floor | 585 | SF | 6 | \$4,367 | |
| Classro | om #141 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 750 | SF | 6 | \$2,252 | |
| | Doors - Side-lite | 1st Floor | 7 | SF | 6 | \$117 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 1st Floor | 750 | SF | 6 | \$751 | |
| | Lighting - Lay-in | 1st Floor | 14 | EΑ | 6 | \$1,666 | |
| | Marker Board | 1st Floor | 8 | LF | 6 | \$171 | |
| | Walls - Concrete Block | 1st Floor | 170 | SF | 6 | \$498 | |
| | Walls - Masonry | 1st Floor | 120 | SF | 6 | \$378 | |
| | Walls - Metal Panel | 1st Floor | 1,035 | SF | 6 | \$7,726 | |
| Classro | oom #143 (Store Room) | | | | | | |
| | Casework | 1st Floor | 12 | LF | 6 | \$303 | |
| | Ceiling - Lay-in | 1st Floor | 441 | SF | 6 | \$1,324 | |
| | Chalk Board | 1st Floor | 6 | LF | 6 | \$134 | |
| | Doors - Side-lite | 1st Floor | 6 | SF | 6 | \$100 | |
| | Doors - Transom Window | 1st Floor | 30 | SF | 6 | \$508 | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | \$301 | w/glass lite |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group t Classroom #13 (Store Round) Command Store Round Ser 6 | | Mana Truna | 1 | 0 | I leade | Danis | 0 | Commonto |
|--|---------|---------------------------------------|-----------|----------|---------|-------|----------|----------|
| Floor - Carpet | • | • • | Location | Quantity | Unit | Rank | Cost | Comments |
| Lighting - Lay-in Walls - Concrete Block Walls - Metal Panel Nation Nation | Classro | · · · · · · · · · · · · · · · · · · · | | | | | | |
| Walls - Concrete Block 1st Floor 623 SF 6 6 SS54 Calways - Metal Panel 1st Floor 66 SF 6 6 SS54 Ceiling - Layin 1st Floor 454 SF 6 6 S163 Doors - Side-Ilbe 1st Floor 1 F 6 5 167 Doors - Side-Ibe Doors inch Inw 1st Floor 47 SF 6 5 119 Floor - Transon Window 1st Floor 48 SF 6 5 8454 Lighting - Layin 1st Floor 48 SF 6 5 8454 Lighting - Layin 1st Floor 48 SF 6 6 \$322 Walls - Concrete Block 1st Floor 48 SF 6 6 \$332 Walls - Metal Panel 1st Floor 48 SF 6 6 \$332 Classroom #171 (Regular Classroom) 8 LF 6 8 \$202 7 \$0 Classroom #171 (Regular Classroom) 8 LF 6 \$ \$202 \$ \$202 Classroom #171 (Regular Classroom) 1st Floor 1st Floor 4 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ | | • | | | | | | |
| Mails - Metal Panel 1st Floor 686 85 6 \$4,966 | | | | | | | | |
| Caling - Layin | | | | | | | | |
| Celling - Lay-in | | Walls - Metal Panel | 1st Floor | 668 | SF | 6 | \$4,986 | |
| Doors - Side-life | Classro | oom #168 (Office) | | | | | | |
| Doors - Steel Doors incl hw 1st Floor 1 | | Ceiling - Lay-in | 1st Floor | 454 | SF | 6 | \$1,363 | |
| Doors - Transom Window 1st Floor 7 | | Doors - Side-lite | 1st Floor | 10 | SF | 6 | \$167 | |
| Floor - Tile/Sheet | | Doors - Steel Doors incl hw | 1st Floor | 1 | EΑ | 6 | \$301 | |
| Lighting - Layrin 1st Floor 8 EA 7 \$0 Walls - Concrete Block 1st Floor 721 \$F 6 \$132 Casework 1st Floor 8 LF 6 \$202 Casework 1st Floor 8 LF 6 \$202 Celling - Layrin 1st Floor 90 2F 6 \$202 Chalk Board 1st Floor 12 LF 6 \$27,09 Chalk Board 1st Floor 14 SF 6 \$224 Doors - Side-life 1st Floor 1 EA 6 \$234 Doors - Steel Doors ind hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 90 SF 6 \$169 Floor - Tile/Sheet 1st Floor 90 SF 6 \$343 Walls - Metal Panel 1st Floor 16 LF 6 \$343 Walls - Metal Panel 1st Floor 1s< | | Doors - Transom Window | 1st Floor | 7 | SF | 6 | \$119 | |
| Walls - Concrete Block Walls - Metal Panel 1st Floor 45 5F 6 \$132 Walls - Metal Panel 1st Floor 721 5F 6 \$5,382 Classroom #171 (Regular Classroom) Casework 1st Floor 8 LF 6 \$2,02 Ceiling - Lay-in 1st Floor 12 LF 6 \$2,68 Chalk Board 1st Floor 14 SF 6 \$2,68 Doors - Stdel-Ite 1st Floor 1 EA 6 \$301 Doors - Steel Doors incl hw 1st Floor 10 SF 6 \$301 Doors - Transom Window 1st Floor 902 SF 6 \$169 Horr Floard 1st Floor 902 SF 6 \$303 Walls - Metal Panel 1st Floor 963 SF 6 \$344 Work Sink 1st Floor 1st Floor 5 6 \$37,188 Work Sink 1st Floor 550 SF 6 \$4 | | Floor - Tile/Sheet | 1st Floor | 454 | SF | 6 | \$454 | |
| Walls - Metal Panel 1st Floor 721 SF 6 \$5,382 Classroom #171 (Regular Classroom) Casework 1st Floor 8 LF 6 \$202 Ceiling - Lay-in 1st Floor 902 SF 6 \$2,09 Chalk Board 1st Floor 14 SF 6 \$2,28 Doors - Side-lite 1st Floor 14 SF 6 \$224 Doors - Side-lite 1st Floor 1 EA 6 \$224 Doors - Transom Window 1st Floor 1 EA 6 \$159 Floor - Tile/Sheet 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 EA 7 \$0 Malker Metal Panel 1st Floor 16 EA 6 \$343 Walls - Metal Panel 1st Floor 15 6 \$404 Casework 1st Floor | | Lighting - Lay-in | 1st Floor | 8 | EA | 7 | \$0 | |
| Casework | | Walls - Concrete Block | 1st Floor | 45 | SF | 6 | \$132 | |
| Casework 1st Floor 8 LF 6 \$202 Celling - Lay-in 1st Floor 902 SF 6 \$2,709 Chalk Board 1st Floor 12 LF 6 \$268 Doors - Side-litle 1st Floor 14 SF 6 \$234 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 16 EA 7 \$0 Lighting - Lay-in 1st Floor 16 LF 6 \$343 Walls - Metal Panel 1st Floor 16 LF 6 \$343 Work Sink 1st Floor 15 EA 6 \$37,88 Work Sink 1st Floor 16 LF 6 \$37,88 Work Sink 1st Floor 16 LF 6 \$404 Casework 1st Floor 15 S 6 <td></td> <td>Walls - Metal Panel</td> <td>1st Floor</td> <td>721</td> <td>SF</td> <td>6</td> <td>\$5,382</td> <td></td> | | Walls - Metal Panel | 1st Floor | 721 | SF | 6 | \$5,382 | |
| Ceiling - Lay-in 1st Floor 902 SF 6 \$2,709 Chalk Board 1st Floor 12 LF 6 \$268 Doors - Sideel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$301 Floor - Tile/Sheet 1st Floor 10 SF 6 \$169 Lighting - Lay-in 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 6 \$343 Work Sink 1st Floor 16 LF 6 \$344 Work Sink 1st Floor 15 6 \$340 Casework 1st Floor 15 6 \$404 Ceiling - Lay-in 1st Floor 15 5 6 \$1,652 Doors - Sidel Doors incl hw 1st Floor 14 SF 6 \$234 < | Classro | oom #171 (Regular Classroom) | | | | | | |
| Chalk Board 1st Floor 12 LF 6 \$268 Doors - Side-lite 1st Floor 14 SF 6 \$234 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 902 SF 6 \$903 Lighting - Lay-in 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 963 SF 6 \$7,188 Work Sink 1st Floor 963 SF 6 \$7,188 Work Sink 1st Floor 16 LF 6 \$349 Casework 1st Floor 16 LF 6 \$404 Celling - Lay-in 1st Floor 15 6 \$31,652 Doors - Side-lite 1st Floor 1 EA 6 | | Casework | 1st Floor | 8 | LF | 6 | \$202 | |
| Doors - Side-lite | | Ceiling - Lay-in | 1st Floor | 902 | SF | 6 | \$2,709 | |
| Doors - Steel Doors incl hw | | Chalk Board | 1st Floor | 12 | LF | 6 | \$268 | |
| Doors - Transom Window | | Doors - Side-lite | 1st Floor | 14 | SF | 6 | \$234 | |
| Floor - Tile/Sheet | | Doors - Steel Doors incl hw | 1st Floor | 1 | EΑ | 6 | \$301 | |
| Lighting - Lay-in 1st Floor 16 EA 7 \$0 Marker Board 1st Floor 16 LF 6 \$343 Walls - Metal Panel 1st Floor 963 SF 6 \$7,188 Work Sink 1st Floor 1 EA 6 \$379 Classroom/ Casework 1st Floor 16 LF 6 \$404 Ceiling - Lay-in 1st Floor 550 SF 6 \$1,652 Doors - Side-lite 1st Floor 14 SF 6 \$234 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 11 EA 7 \$0 Walls - Malls - Metal Panel 1st Floor 110 SF 6 \$322 <td></td> <td>Doors - Transom Window</td> <td>1st Floor</td> <td>10</td> <td>SF</td> <td>6</td> <td>\$169</td> <td></td> | | Doors - Transom Window | 1st Floor | 10 | SF | 6 | \$169 | |
| Marker Board 1st Floor 16 LF 6 \$343 Walls - Metal Panel 1st Floor 963 SF 6 \$7,188 Work Sink 1st Floor 1 EA 6 \$379 Classroom/ Casework 1st Floor 16 LF 6 \$404 Ceiling - Lay-in 1st Floor 550 SF 6 \$1,652 Doors - Side-lite 1st Floor 14 SF 6 \$234 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Oncrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Floor - Tile/Sheet | 1st Floor | 902 | SF | 6 | \$903 | |
| Walls - Metal Panel 1st Floor 963 SF 6 \$7,188 Work Sink 1st Floor 1 EA 6 \$379 Classroom#172 (Regular Classroom) Casework 1st Floor 16 LF 6 \$404 Ceiling - Lay-in 1st Floor 550 SF 6 \$1,652 Doors - Side-lite 1st Floor 1 EA 6 \$234 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Lighting - Lay-in | 1st Floor | 16 | EΑ | 7 | \$0 | |
| Work Sink 1st Floor 1 EA 6 \$379 Classroom #172 (Regular Classroom) Casework 1st Floor 16 LF 6 \$404 Ceiling - Lay-in 1st Floor 550 SF 6 \$1,652 Doors - Side-lite 1st Floor 14 SF 6 \$234 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Marker Board | 1st Floor | 16 | LF | 6 | \$343 | |
| Classroom #172 (Regular Classroom) Casework 1st Floor 16 LF 6 \$404 Ceiling - Lay-in 1st Floor 550 SF 6 \$1,652 Doors - Side-lite 1st Floor 14 SF 6 \$234 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Walls - Metal Panel | 1st Floor | 963 | SF | 6 | \$7,188 | |
| Casework 1st Floor 16 LF 6 \$404 Ceiling - Lay-in 1st Floor 550 SF 6 \$1,652 Doors - Side-lite 1st Floor 14 SF 6 \$234 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Ceiling - Lay-in 1st Floor 550 SF 6 \$1,652 Doors - Side-lite 1st Floor 14 SF 6 \$234 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | Classro | oom #172 (Regular Classroom) | | | | | | |
| Doors - Side-lite 1st Floor 14 SF 6 \$234 Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Casework | 1st Floor | 16 | LF | 6 | \$404 | |
| Doors - Steel Doors incl hw 1st Floor 1 EA 6 \$301 Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Ceiling - Lay-in | 1st Floor | 550 | SF | 6 | \$1,652 | |
| Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Doors - Side-lite | 1st Floor | 14 | SF | 6 | \$234 | |
| Doors - Transom Window 1st Floor 10 SF 6 \$169 Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet 1st Floor 550 SF 6 \$551 Lighting - Lay-in 1st Floor 11 EA 7 \$0 Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Doors - Transom Window | 1st Floor | 10 | SF | 6 | | |
| Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Floor - Tile/Sheet | 1st Floor | 550 | SF | 6 | \$551 | |
| Walls - Concrete Block 1st Floor 110 SF 6 \$322 Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | Lighting - Lay-in | 1st Floor | 11 | EA | 7 | \$0 | |
| Walls - Metal Panel 1st Floor 642 SF 6 \$4,792 | | | 1st Floor | 110 | SF | 6 | \$322 | |
| | | Walls - Metal Panel | | | | | | |
| | | Work Sink | 1st Floor | 1 | EA | 6 | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|----------|----------|
| Classro | oom #172 (Regular Classroom) | | • | | | | |
| Classr | oom #173 (Regular Classroom) | | | | | | |
| Ciassi | Casework | 1st Floor | 10 | LF | 6 | \$253 | |
| | Ceiling - Lay-in | 1st Floor | 1,340 | SF | 6 | \$4,024 | |
| | Doors - Side-lite | 1st Floor | 10 | SF | 6 | \$167 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | . 14 | SF | 6 | \$237 | |
| | Floor - Tile/Sheet | 1st Floor | 1,340 | SF | 6 | \$1,341 | |
| | Lighting - Lay-in | 1st Floor | 24 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 8 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 1,675 | SF | 6 | \$4,910 | |
| | Walls - Metal Panel | 1st Floor | 1,675 | SF | 6 | \$12,503 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| | | 1311 1331 | · | | · · | ψσ. σ | |
| Classro | oom #175 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 6 | LF | 6 | \$152 | |
| | Ceiling - Lay-in | 1st Floor | 702 | SF | 6 | \$2,108 | |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 1st Floor | 702 | SF | 6 | \$703 | |
| | Lighting - Lay-in | 1st Floor | 14 | EA | 6 | \$1,666 | |
| | Marker Board | 1st Floor | 8 | LF | 6 | \$171 | |
| | Storage/ Closet | 1st Floor | 8 | SF | 6 | \$58 | |
| | Walls - Concrete Block | 1st Floor | 220 | SF | 6 | \$645 | |
| | Walls - Metal Panel | 1st Floor | 725 | SF | 6 | \$5,412 | |
| Classro | oom #176 (Culinary) | | | | | | |
| | Casework | 1st Floor | 18 | LF | 6 | \$455 | |
| | Ceiling - Lay-in | 1st Floor | 1,392 | SF | 6 | \$4,180 | |
| | Culinary Kitchen Equipment | 1st Floor | 1 | EA | 6 | \$4,027 | |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EΑ | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 1st Floor | 1,392 | SF | 6 | \$1,393 | |
| | Lighting - Lay-in | 1st Floor | 26 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 10 | LF | 7 | \$0 | |
| | Walls - Metal Panel | 1st Floor | 11,218 | SF | 6 | \$83,738 | |
| | Work Sink | 1st Floor | 4 | EA | 6 | \$1,516 | |
| | TOTA ONIN | 13111001 | 7 | | 3 | Ψ1,010 | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|----------|
| • | oom #176 (Culinary) | | | • | | | |
| | | | | | | | |
| Classro | oom #181 (Lunch Room) | | | | | | |
| | Casework | 1st Floor | 12 | LF | 6 | \$303 | |
| | Ceiling - Lay-in | 1st Floor | 1,363 | SF | 6 | \$4,093 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 1,363 | SF | 6 | \$1,364 | |
| | Lighting - Lay-in | 1st Floor | 53 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 52 | SF | 6 | \$152 | |
| | Walls - Metal Panel | 1st Floor | 1,218 | SF | 6 | \$9,092 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #182 (Lunch Room) | | | | | | |
| | Casework | 1st Floor | 12 | LF | 6 | \$303 | |
| | Ceiling - Lay-in | 1st Floor | 1,439 | SF | 6 | \$4,321 | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | \$918 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 1,439 | SF | 6 | \$1,440 | |
| | Lighting - Lay-in | 1st Floor | 55 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 225 | SF | 6 | \$660 | |
| | Walls - Metal Panel | 1st Floor | 900 | SF | 6 | \$6,718 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #183 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,838 | SF | 6 | \$5,520 | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | \$1,102 | |
| | Doors - Side-lite | 1st Floor | 10 | SF | 6 | \$167 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 7 | SF | 6 | \$119 | |
| | Floor - Tile/Sheet | 1st Floor | 1,838 | SF | 6 | \$1,840 | |
| | Lighting - Lay-in | 1st Floor | 36 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 4 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 170 | SF | 6 | \$498 | |
| | Walls - Metal Panel | 1st Floor | 1,170 | SF | 6 | \$8,734 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| Classro | oom #184 (Computer Lab) | | | | | | |
| | Ceiling - Exposed | 1st Floor | 1,092 | SF | 6 | \$1,624 | |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | | | | | | • | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|-----------------------------|-----------|----------|------|------|---------|-------------|
| | om #184 (Computer Lab) | | | | | | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 1st Floor | 1,092 | SF | 6 | \$1,093 | |
| | Lighting - Lay-in | 1st Floor | 21 | EA | 6 | \$2,498 | |
| | Marker Board | 1st Floor | 20 | LF | 6 | \$428 | |
| | Walls - Metal Panel | 1st Floor | 1,142 | SF | 6 | \$8,525 | |
| ssroc | om #185 (Regular Classroom) | | · | | | | |
| | Ceiling - Lay-in | 1st Floor | 867 | SF | 6 | \$2,604 | |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 1st Floor | 867 | SF | 6 | \$868 | |
| | Lighting - Lay-in | 1st Floor | 21 | EA | 6 | \$2,498 | |
| | Marker Board | 1st Floor | 15 | LF | 6 | \$321 | |
| | Storage/ Closet | 1st Floor | 145 | SF | 6 | \$1,051 | |
| | Walls - Metal Panel | 1st Floor | 1,222 | SF | 6 | \$9,122 | |
| ssroc | om #189 (Regular Classroom) | | • | | | , , | |
| | Ceiling - Lay-in | 1st Floor | 867 | SF | 6 | \$2,604 | |
| | Chalk Board | 1st Floor | 12 | LF | 6 | \$268 | |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 1st Floor | 867 | SF | 6 | \$868 | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 16 | LF | 7 | \$0 | |
| | Walls - Metal Panel | 1st Floor | 944 | SF | 6 | \$7,047 | |
| | Work Sink | 1st Floor | 1 | EA | 6 | \$379 | |
| ssroc | om #190 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 867 | SF | 6 | \$2,604 | |
| | Doors - Side-lite | 1st Floor | 4 | SF | 6 | \$67 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 8 | SF | 6 | \$135 | Solid panel |
| | Floor - Tile/Sheet | 1st Floor | 867 | SF | 6 | \$868 | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 24 | LF | 7 | \$0 | |
| | Walls - Masonry | 1st Floor | 236 | SF | 6 | \$742 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| • | tem - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|------------------------------|-----------|----------|------|------|----------|-------------------|
| ssroor | m #190 (Regular Classroom) | | | | | | |
| ssroor | m #192 (Regular Classroom) | | | | | | |
| (| Ceiling - Lay-in | 1st Floor | 1,067 | SF | 6 | \$3,204 | |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 1st Floor | 10 | SF | 6 | \$169 | |
| F | Floor - Tile/Sheet | 1st Floor | 1,067 | SF | 6 | \$1,068 | |
| L | Lighting - Lay-in | 1st Floor | 24 | EA | 6 | \$2,855 | |
| N | Marker Board | 1st Floor | 20 | LF | 6 | \$428 | |
| 5 | Storage/ Closet | 1st Floor | 147 | SF | 6 | \$1,066 | |
| ٧ | Walls - Concrete Block | 1st Floor | 400 | SF | 6 | \$1,173 | |
| ٧ | Walls - Metal Panel | 1st Floor | 657 | SF | 6 | \$4,904 | |
| ssroor | m #201 (Science Lab Level 3) | | | | | | |
| (| Casework | 2nd Floor | 50 | LF | 6 | \$1,263 | |
| | Ceiling - Lay-in | 2nd Floor | 1,226 | SF | 6 | \$3,682 | |
| | Doors - Side-lite | 2nd Floor | 28 | SF | 6 | \$468 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EΑ | 6 | \$602 | |
| | Doors - Transom Window | 2nd Floor | 20 | SF | 6 | \$339 | |
| Е | Eye Wash Station | 2nd Floor | 1 | EΑ | 6 | \$336 | |
| | Floor - Tile/Sheet | 2nd Floor | 1,226 | SF | 6 | \$1,227 | |
| F | Fume Hood | 2nd Floor | 1 | EΑ | 6 | \$816 | |
| | Gas Line | 2nd Floor | 10 | EA | 6 | \$5,091 | |
| L | Lighting - Lay-in | 2nd Floor | 20 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | \$0 | |
| 5 | Science Lab Elements | 2nd Floor | 1,226 | SF | 6 | \$8,310 | |
| 5 | Science Lab Shower | 2nd Floor | 1 | EΑ | 6 | \$379 | |
| ٧ | Walls - Metal Panel | 2nd Floor | 1,402 | SF | 6 | \$10,465 | |
| ٧ | Work Sink | 2nd Floor | 1 | EΑ | 7 | \$0 | Drinking fountain |
| ٧ | Work Sink | 2nd Floor | 10 | EA | 6 | \$3,790 | - |
| ssroor | m #203 (Regular Classroom) | | | | | | |
| (| Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Doors - Side-lite | 2nd Floor | 7 | SF | 6 | \$117 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| F | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| L | _ighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | | | | LF | | | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|-----------|----------|------|------|---------|----------|
| lassro | om #203 (Regular Classroom) | | | | | | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| lassro | om #204 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| lassro | om #205 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Chalk Board | 2nd Floor | 12 | LF | 6 | \$268 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 8 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 14 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| lassro | om #206 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | \$428 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| lassro | om #216 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 740 | SF | 6 | \$2,222 | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-------------|----------|-------|------|---------|----------|
| _ | oom #216 (Regular Classroom) | Location | quantity | Oilit | rain | 0031 | Comments |
| Olassic | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 740 | SF | 6 | \$741 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 273 | SF | 6 | \$800 | |
| | Walls - Metal Panel | 2nd Floor | 818 | SF | 6 | \$6,106 | |
| Classro | oom #223 (Regular Classroom) | | | | | | |
| Classic | Casework | 2nd Floor | 6 | LF | 6 | \$152 | |
| | Ceiling - Lay-in | 2nd Floor | 800 | SF | 6 | \$2,402 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 800 | SF | 6 | \$801 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 9 | LF | 7 | \$0 | |
| | Walls - Metal Panel | 2nd Floor | 1,055 | SF | 6 | \$7,875 | |
| | | 2110 1 1001 | 1,000 | O. | O | ψ1,010 | |
| Classro | oom #224 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EΑ | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EΑ | 7 | \$0 | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| Classro | oom #225 (Science Lab Level 3) | | | | | | |
| | Casework | 2nd Floor | 6 | LF | 6 | \$152 | |
| | Ceiling - Lay-in | 2nd Floor | 2,451 | SF | 6 | \$7,360 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 2,451 | SF | 6 | \$2,453 | |
| | Lighting - Lay-in | 2nd Floor | 92 | EA | 7 | \$0 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Commo |
|--------|--------------------------------|-------------|----------|------|------|----------------|-------|
| • | oom #225 (Science Lab Level 3) | | | | | - 3331 | |
| | Marker Board | 2nd Floor | 9 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 868 | SF | 6 | \$2,545 | |
| | Walls - Metal Panel | 2nd Floor | 2,504 | SF | 6 | \$18,691 | |
| | Work Sink | 2nd Floor | 9 | EA | 6 | \$3,411 | |
| | 4020 (Caianaa Lab Laval 2) | | | | | . , | |
| iassro | oom #230 (Science Lab Level 3) | 2nd Floor | 440 | | | ሲ ህ ደብረ | |
| | Casework | | 140 | LF | 6 | \$3,536 | |
| | Ceiling - Lay-in | 2nd Floor | 1,780 | SF | 6 | \$5,345 | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 6 | \$334 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 3 | EA | 6 | \$903 | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 6 | \$711 | |
| | Eye Wash Station | 2nd Floor | 1 | EA | 6 | \$336 | |
| | Floor - Tile/Sheet | 2nd Floor | 1,780 | SF | 6 | \$1,782 | |
| | Gas Line | 2nd Floor | 8 | EA | 6 | \$4,073 | |
| | Lighting - Lay-in | 2nd Floor | 72 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 34 | LF | 7 | \$0 | |
| | Science Lab Elements | 2nd Floor | 1,780 | SF | 6 | \$12,065 | |
| | Science Lab Shower | 2nd Floor | 1 | EA | 6 | \$379 | |
| | Walls - Concrete Block | 2nd Floor | 786 | SF | 6 | \$2,304 | |
| | Walls - Metal Panel | 2nd Floor | 1,250 | SF | 6 | \$9,331 | |
| | Work Sink | 2nd Floor | 15 | EA | 6 | \$5,685 | |
| assro | oom #233 (Science Lab Level 3) | | | | | | |
| | Casework | 2nd Floor | 80 | LF | 6 | \$2,020 | |
| | Ceiling - Lay-in | 2nd Floor | 2,537 | SF | 6 | \$7,619 | |
| | Chalk Board | 2nd Floor | 16 | LF | 6 | \$357 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Eye Wash Station | 2nd Floor | 1 | EΑ | 6 | \$336 | |
| | Floor - Tile/Sheet | 2nd Floor | 2,537 | SF | 6 | \$2,540 | |
| | Fume Hood | 2nd Floor | 1 | EA | 6 | \$816 | |
| | Gas Line | 2nd Floor | 10 | EA | 6 | \$5,091 | |
| | Lighting - Lay-in | 2nd Floor | 60 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 24 | LF | 7 | \$0 | |
| | Science Lab Shower | 2nd Floor | 1 | EA | 6 | \$379 | |
| | Walls - Concrete Block | 2nd Floor | 450 | SF | 6 | \$1,319 | |
| | Walls - Metal Panel | 2nd Floor | 3,805 | SF | 6 | \$28,403 | |
| | Work Sink | 2nd Floor | 10 | EA | 6 | \$3,790 | |
| | TT OIL OIL M | 2110 1 1001 | 10 | L/ (| J | ψ0,100 | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| - | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-------------------------------------|-----------|----------|------|------|---------|---|
| lassro | om #234 (Science Lab Level 3) | | | | | | |
| | Casework | 2nd Floor | 45 | LF | 6 | \$1,136 | |
| | Ceiling - Lay-in | 2nd Floor | 1,675 | SF | 6 | \$5,030 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 1,675 | SF | 6 | \$1,677 | |
| | Lighting - Chandelier, Incandescent | 2nd Floor | 2 | EA | 4 | \$2,113 | Incandescent Fixtures in storage closet |
| | Lighting - Lay-in | 2nd Floor | 55 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 50 | LF | 7 | \$0 | |
| | Science Lab Elements | 2nd Floor | 1,390 | SF | 6 | \$9,422 | |
| | Storage/ Closet | 2nd Floor | 285 | SF | 6 | \$2,066 | |
| | Walls - Metal Panel | 2nd Floor | 858 | SF | 6 | \$6,405 | |
| | Walls - Metal Panel | 2nd Floor | 426 | SF | 6 | \$3,856 | |
| | Walls - Plaster/Drywall | 2nd Floor | 409 | SF | 6 | \$1,129 | |
| | Work Sink | 2nd Floor | 10 | EA | 6 | \$3,790 | |
| lassro | om #236 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 907 | SF | 6 | \$2,724 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EΑ | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 907 | SF | 6 | \$908 | |
| | Lighting - Lay-in | 2nd Floor | 11 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 770 | SF | 6 | \$2,257 | |
| | Walls - Metal Panel | 2nd Floor | 275 | SF | 6 | \$2,053 | |
| lassro | om #243 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 767 | SF | 6 | \$2,303 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 767 | SF | 6 | \$768 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 26 | LF | 7 | \$0 | |
| | Walls - Metal Panel | 2nd Floor | 1,044 | SF | 6 | \$7,793 | |
| lassro | om #244 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|-----------|----------|------|------|---------|----------|
| Classro | om #244 (Regular Classroom) | | | | | | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 1 | SF | 6 | \$3 | |
| | Walls - Plaster/Drywall | 2nd Floor | 918 | SF | 6 | \$2,534 | |
| Classro | om #245 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 767 | SF | 6 | \$2,303 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 767 | SF | 6 | \$768 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 729 | SF | 6 | \$2,137 | |
| | Walls - Metal Panel | 2nd Floor | 729 | SF | 6 | \$5,442 | |
| Classro | om #250 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 620 | SF | 6 | \$1,862 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 2nd Floor | 620 | SF | 6 | \$1,356 | |
| | Lighting - Lay-in | 2nd Floor | 13 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 246 | SF | 6 | \$721 | |
| | Walls - Metal Panel | 2nd Floor | 702 | SF | 6 | \$5,240 | |
| | Walls - Plaster/Drywall | 2nd Floor | 168 | SF | 6 | \$464 | |
| Classro | om #251 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 620 | SF | 6 | \$1,862 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 620 | SF | 6 | \$621 | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 12 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 728 | SF | 6 | \$2,134 | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|------|------|---------|----------|
| Classro | oom #251 (Regular Classroom) | | | | | | |
| | Walls - Metal Panel | 2nd Floor | 728 | SF | 6 | \$5,434 | |
| Classro | oom #252 (Regular Classroom) | | | | | | |
| Olubbit | Ceiling - Lay-in | 2nd Floor | 615 | SF | 6 | \$1,847 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 615 | SF | 6 | \$616 | |
| | Lighting - Lay-in | 2nd Floor | 11 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 62 | SF | 6 | \$182 | |
| | Walls - Metal Panel | 2nd Floor | 819 | SF | 6 | \$6,114 | |
| Classro | oom #253 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 767 | SF | 6 | \$2,303 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 767 | SF | 6 | \$768 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Masonry | 2nd Floor | 364 | SF | 6 | \$1,145 | |
| | Walls - Metal Panel | 2nd Floor | 1,092 | SF | 6 | \$8,151 | |
| Classro | oom #254 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile | 2nd Floor | 765 | SF | 6 | \$1,674 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| Classro | oom #255 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 767 | SF | 6 | \$2,303 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| p Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------|-----------|----------|---------|--------|---------|----------|
| sroom #255 (Regular Classroom) | 2004.1011 | Quantity | O.I.I.C | rtanit | 0001 | |
| Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| Floor - Tile/Sheet | 2nd Floor | 767 | SF | 6 | \$768 | |
| Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| Walls - Metal Panel | 2nd Floor | 728 | SF | 6 | \$5,434 | |
| Walls - Plaster/Drywall | 2nd Floor | 728 | SF | 6 | \$2,009 | |
| sroom #273 (Faculty Lounge) | | | | | | |
| Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| Lighting - Lay-in | 2nd Floor | 14 | EA | 6 | \$1,666 | |
| Marker Board | 2nd Floor | 20 | LF | 6 | \$428 | |
| Walls - Concrete Block | 2nd Floor | 220 | SF | 6 | \$645 | |
| Walls - Metal Panel | 2nd Floor | 880 | SF | 6 | \$6,569 | |
| sroom #274 (Regular Classroom) | | | | | | |
| Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| sroom #275 (Regular Classroom) | | | | | | |
| Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| Lighting - Lay-in | 2nd Floor | 14 | EA | 7 | \$0 | |
| Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| LE DITTED LIO | Da 04 a | | | | | Δ. |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| roun | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|-----------|----------|------|------|---------|----------|
| - | om #275 (Regular Classroom) | 2004.1011 | Quartity | 0 | rain | 000. | Commone |
| | | | | | | | |
| lassroc | om #276 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| assroc | om #277 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| assroc | om #278 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 13 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| assroc | om #280 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 923 | SF | 6 | \$2,772 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 923 | SF | 6 | \$924 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | | | | | | _ | |
|---------|------------------------------|-----------|----------|------|------|---------|----------|
| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Classro | oom #280 (Regular Classroom) | | | | | | |
| | Lighting - Lay-in | 2nd Floor | 17 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 115 | SF | 6 | \$337 | |
| | Walls - Metal Panel | 2nd Floor | 921 | SF | 6 | \$6,875 | |
| Classro | oom #281 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| Classro | oom #283 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Chalk Board | 2nd Floor | 6 | LF | 6 | \$134 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EΑ | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| Classro | oom #284 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 765 | SF | 6 | \$2,297 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 765 | SF | 6 | \$766 | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 12 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 2nd Floor | 990 | SF | 6 | \$7,390 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| up | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------|-----------------------------|-----------|----------|------|------|---------|----------|
| • | om #288 (Faculty Lounge) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 605 | SF | 6 | \$1,817 | |
| | Doors - Side-lite | 2nd Floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 2nd Floor | 605 | SF | 6 | \$606 | |
| | Lighting - Lay-in | 2nd Floor | 11 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 200 | SF | 6 | \$586 | |
| | Walls - Metal Panel | 2nd Floor | 793 | SF | 6 | \$5,919 | |
| ssro | om #292 (Fitness Room) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,697 | SF | 6 | \$5,096 | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 6 | \$334 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Doors - Transom Window | 2nd Floor | 122 | SF | 6 | \$2,066 | |
| | Floor - Sport Flooring | 2nd Floor | 1,697 | SF | 6 | \$3,664 | |
| | Lighting - Lay-in | 2nd Floor | 34 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | \$0 | |
| | Walls - Masonry | 2nd Floor | 513 | SF | 6 | \$1,614 | Brick |
| | Walls - Plaster/Drywall | 2nd Floor | 980 | SF | 6 | \$2,705 | |
| ssro | om #293 (Dance Room) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 848 | SF | 6 | \$2,547 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Floor - Sport Flooring | 2nd Floor | 848 | SF | 6 | \$1,831 | |
| | Lighting - Lay-in | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Wall Mirrors | 2nd Floor | 2 | EA | 6 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 360 | SF | 6 | \$1,055 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,103 | SF | 5 | \$8,360 | |
| ssro | om #294 (Weight) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 985 | SF | 6 | \$2,958 | |
| | Doors - Side-lite | 2nd Floor | 36 | SF | 6 | \$602 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Doors - Transom Window | 2nd Floor | 45 | SF | 6 | \$762 | |
| | Floor - Sport Flooring | 2nd Floor | 985 | SF | 6 | \$2,127 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 130 | SF | 6 | \$381 | |
| | Walls - Plaster/Drywall | 2nd Floor | 931 | SF | 6 | \$2,569 | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|------------------------------|-----------|----------|-------|------|------------|----------|
| • | oom #300 (Regular Classroom) | Location | Quantity | Oilit | Nank | 0031 | Comments |
| Olassi | Ceiling - Lay-in | 1st Floor | 1,119 | SF | 6 | \$3,360 | |
| | Doors - Side-lite | 1st Floor | 20 | SF | 6 | \$334 | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | 1st Floor | 1,119 | SF | 6 | \$2,384 | |
| | Lighting - Lay-in | 1st Floor | 22 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 36 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,450 | SF | 6 | \$4,002 | |
| Classe | · | | ,,,,, | | | ¥ 1,00= | |
| Classro | oom #301 (Regular Classroom) | 1st Floor | 823 | SF | 6 | ¢0.474 | |
| | Ceiling - Lay-in | | | | 6 | \$2,471 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 823 | SF | 6 | \$824 | |
| | Lighting - Lay-in | 1st Floor | 19 | EA | 7 | \$0 \$0 | |
| | Marker Board | 1st Floor | 40 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,352 | SF | 6 | \$3,731 | |
| Classro | oom #302 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 935 | SF | 6 | \$2,808 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile/Sheet | 1st Floor | 935 | SF | 6 | \$936 | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 22 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 1st Floor | 197 | SF | 6 | \$578 | |
| | Walls - Plaster/Drywall | 1st Floor | 613 | SF | 6 | \$1,692 | |
| Classro | oom #317 (Choral Room) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,306 | SF | 6 | \$3,922 | |
| | Chalk Board | 1st Floor | 12 | LF | 6 | \$268 | |
| | Doors - Store Front | 1st Floor | 1 | EA | 6 | \$1,208 | |
| | Floor - Carpet | 1st Floor | 1,306 | SF | 6 | \$2,783 | |
| | Lighting - Lay-in | 1st Floor | 24 | EΑ | 6 | \$2,855 | |
| | Marker Board | 1st Floor | 8 | LF | 6 | \$171 | |
| | Risers | 1st Floor | 96 | LF | 6 | \$2,161 | |
| | Sound System | 1st Floor | 2 | EA | 6 | \$2,884 | |
| | Walls - Concrete Block | 1st Floor | 3,437 | SF | 6 | \$10,076 | |
| Classro | oom #319 (Band Room) | | | | | | |
| | Casework | 3rd Floor | 54 | LF | 6 | \$1,364 | |
| | Ceiling - Lay-in | 3rd Floor | 1,959 | SF | 6 | \$5,883 | |
| | | | • | | | • | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comm |
|--------|------------------------------|-----------|----------|------|------|----------|------|
| • | oom #319 (Band Room) | | | | | | |
| | Chalk Board | 3rd Floor | 12 | LF | 6 | \$268 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | 3rd Floor | 1,959 | SF | 6 | \$4,174 | |
| | Lighting - Lay-in | 3rd Floor | 38 | EΑ | 7 | \$0 | |
| | Marker Board | 3rd Floor | 12 | LF | 7 | \$0 | |
| | Risers | 3rd Floor | 96 | LF | 6 | \$2,161 | |
| | Sound Panels | 3rd Floor | 70 | EΑ | 6 | \$282 | |
| | Walls - Concrete Block | 3rd Floor | 4,408 | SF | 6 | \$12,922 | |
| lassro | oom #404 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 90 | LF | 6 | \$2,273 | |
| | Ceiling - Lay-in | 2nd Floor | 892 | SF | 6 | \$2,679 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 892 | SF | 6 | \$893 | |
| | Lighting - Lay-in | 2nd Floor | 24 | EA | 6 | \$2,855 | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | \$257 | |
| | Walls - Concrete Block | 2nd Floor | 669 | SF | 6 | \$1,961 | |
| | Work Sink | 2nd Floor | 2 | EA | 6 | \$758 | |
| lassro | om #406 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 90 | LF | 6 | \$2,273 | |
| | Ceiling - Lay-in | 2nd Floor | 892 | SF | 6 | \$2,679 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 2nd Floor | 892 | SF | 6 | \$893 | |
| | Lighting - Lay-in | 2nd Floor | 24 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 12 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 1,019 | SF | 6 | \$2,987 | |
| | Work Sink | 2nd Floor | 2 | EA | 6 | \$758 | |
| assrc | om #408 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 90 | LF | 6 | \$2,273 | |
| | Ceiling - Lay-in | 2nd Floor | 892 | SF | 6 | \$2,679 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | 2nd Floor | 892 | SF | 6 | \$893 | |
| | Lighting - Lay-in | 2nd Floor | 24 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 12 | LF | 7 | \$0 | |
| | Walls - Concrete Block | 2nd Floor | 1,019 | SF | 6 | \$2,987 | |
| | Work Sink | 2nd Floor | 2 | EA | 6 | \$758 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

Category: Classrooms

Group Item - Type Location Quantity Unit Rank Cost Comments

Classrooms Subtotal: \$1,262,968

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|--|----------|------|------|---------|----------|
| Adminis | strative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | 271 servery prep rm 2nd floor | 82 | SF | 6 | \$246 | |
| | Doors - Steel Doors incl hw | 271 servery prep rm 2nd floor | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | 271 servery prep rm 2nd floor | 82 | SF | 6 | \$179 | |
| | Lighting - Lay-in | 271 servery prep rm 2nd floor | 2 | EA | 7 | \$0 | |
| | Power Distribution | 271 servery prep rm 2nd floor | 4 | EA | 7 | \$0 | |
| | Storage/ Closet | 271 servery prep rm 2nd floor | 87 | SF | 6 | \$631 | |
| | Walls - Tile Ceramic/ Porcelain | 271 servery prep rm 2nd floor | 435 | SF | 6 | \$983 | |
| | Work Slnk | 271 servery prep rm 2nd floor | 1 | EA | 6 | \$508 | |
| | Ceiling - Lay-in | 000B Kitchen Office Basement | 124 | SF | 6 | \$372 | |
| | Doors - Steel Doors incl hw | 000B Kitchen Office Basement | 1 | EA | 6 | \$301 | |
| | Floor - Epoxy/ Painted | 000B Kitchen Office Basement | 124 | SF | 6 | \$66 | |
| | Lighting - Lay-in | 000B Kitchen Office Basement | 2 | EA | 7 | \$0 | |
| | Power Distribution | 000B Kitchen Office Basement | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 000B Kitchen Office Basement | 450 | SF | 6 | \$1,319 | |
| | Ceiling - Lay-in | 000D Womens Custodial Office Basement | 254 | SF | 6 | \$763 | |
| | Doors - Steel Doors incl hw | 000D Womens Custodial Office Basement | 1 | EA | 6 | \$301 | |
| | Floor - Concrete Epoxy/ Painted | 000D Womens Custodial Office Basement | 254 | SF | 6 | \$134 | |
| | Lighting - Lay-in | 000D Womens Custodial Office Basement | 4 | EA | 7 | \$0 | |
| | Power Distribution | 000D Womens Custodial Office Basement | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 000D Womens Custodial Office Basement | 609 | SF | 6 | \$1,785 | |
| | Ceiling - Lay-in | 000G Men's Custodial Office Basement | 254 | SF | 6 | \$763 | |
| | Doors - Steel Doors incl hw | 000G Men's Custodial Office Basement | 1 | EA | 6 | \$301 | |
| | Floor - Concrete Epoxy/ Painted | 000G Men's Custodial Office Basement | 254 | SF | 6 | \$134 | |
| | Lighting - Lay-in | 000G Men's Custodial Office Basement | 4 | EA | 7 | \$0 | |
| | Power Distribution | 000G Men's Custodial Office Basement | 8 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 000G Men's Custodial Office Basement | 609 | SF | 6 | \$1,785 | |
| | AC Unit | 002 Engineer Corridor Basement | 1 | EA | 6 | \$496 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|--------------------------------|----------|------|------|---------|---|
| Adminis | strative Suites/Offices | | | | | | |
| | Ceiling - Exposed | 002 Engineer Corridor Basement | 406 | SF | 6 | \$604 | |
| | Doors - Wood Doors inclu hw | 002 Engineer Corridor Basement | 2 | EΑ | 6 | \$602 | |
| | Floor - Epoxy/ Painted | 002 Engineer Corridor Basement | 406 | SF | 6 | \$215 | |
| | Lighting - Pendent/Surface | 002 Engineer Corridor Basement | 2 | EA | 7 | \$0 | |
| | Power Distribution | 002 Engineer Corridor Basement | 6 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 002 Engineer Corridor Basement | 609 | SF | 6 | \$1,681 | |
| | AC Unit | 002A Engineer Office | 1 | EA | 6 | \$496 | |
| | Ceiling - Lay-in | 002A Engineer Office | 146 | SF | 6 | \$438 | |
| | Doors - Wood Doors inclu hw | 002A Engineer Office | 2 | EA | 6 | \$602 | |
| | Floor - Carpet | 002A Engineer Office | 209 | SF | 6 | \$445 | |
| | Lighting - Lay-in | 002A Engineer Office | 1 | EA | 7 | \$0 | |
| | Power Distribution | 002A Engineer Office | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 002A Engineer Office | 647 | SF | 6 | \$1,897 | |
| | Ceiling - Plaster/Drywall | 0510 Faculty Office | 135 | SF | 6 | \$467 | |
| | Doors - Steel Doors incl hw | 0510 Faculty Office | 1 | EA | 6 | \$301 | |
| | Floor - Concrete Epoxy/ Painted | 0510 Faculty Office | 135 | SF | 6 | \$71 | |
| | Lighting - Pendent/Surface | 0510 Faculty Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | 0510 Faculty Office | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 0510 Faculty Office | 337 | SF | 6 | \$988 | |
| | Ceiling - Plaster/Drywall | 0521 Faculty Office | 135 | SF | 6 | \$467 | |
| | Doors - Steel Doors incl hw | 0521 Faculty Office | 1 | EA | 6 | \$301 | |
| | Floor - Concrete Epoxy/ Painted | 0521 Faculty Office | 135 | SF | 6 | \$71 | |
| | Lighting - Pendent/Surface | 0521 Faculty Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | 0521 Faculty Office | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 0521 Faculty Office | 337 | SF | 6 | \$988 | 4 one tier lockers and three two tier lockers |
| | Ceiling - Lay-in | 100 Dean's Office | 316 | SF | 6 | \$949 | |
| | Doors - Steel Doors incl hw | 100 Dean's Office | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 100 Dean's Office | 316 | SF | 6 | \$673 | |
| | Lighting - Lay-in | 100 Dean's Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | 100 Dean's Office | 8 | EA | 7 | \$0 | |
| | Walls - Metal Panel | 100 Dean's Office | 790 | SF | 6 | \$5,897 | |
| | Ceiling - Lay-in | 100A Dean's Office | 240 | SF | 6 | \$721 | |
| | Doors - Steel Doors incl hw | 100A Dean's Office | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 100A Dean's Office | 240 | SF | 6 | \$511 | |
| | Lighting - Lay-in | 100A Dean's Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | 100A Dean's Office | 6 | EA | 7 | \$0 | |
| | Walls - Metal Panel | 100A Dean's Office | 600 | SF | 6 | \$4,479 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| oup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|----------------------------------|----------|------|------|---------|----------|
| ministrative Suites/Offices | | | | | | |
| Ceiling - Lay-in | 101 Principal's Office 1st floor | 235 | SF | 6 | \$706 | |
| Doors - Steel Doors incl hw | 101 Principal's Office 1st floor | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 101 Principal's Office 1st floor | 235 | SF | 6 | \$501 | |
| Lighting - Lay-in | 101 Principal's Office 1st floor | 4 | EA | 7 | \$0 | |
| Power Distribution | 101 Principal's Office 1st floor | 8 | EA | 7 | \$0 | |
| Walls - Metal Panel | 101 Principal's Office 1st floor | 540 | SF | 6 | \$4,031 | |
| Ceiling - Lay-in | 101A Conference Office 1st floor | 316 | SF | 6 | \$949 | |
| Doors - Steel Doors incl hw | 101A Conference Office 1st floor | 2 | EA | 6 | \$602 | |
| Floor - Carpet | 101A Conference Office 1st floor | 316 | SF | 6 | \$673 | |
| Lighting - Lay-in | 101A Conference Office 1st floor | 6 | EA | 7 | \$0 | |
| Power Distribution | 101A Conference Office 1st floor | 8 | EA | 7 | \$0 | |
| Walls - Metal Panel | 101A Conference Office 1st floor | 790 | SF | 6 | \$5,897 | |
| Ceiling - Lay-in | 101B Secretary Office | 183 | SF | 6 | \$550 | |
| Doors - Steel Doors incl hw | 101B Secretary Office | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 101B Secretary Office | 183 | SF | 6 | \$390 | |
| Lighting - Lay-in | 101B Secretary Office | 4 | EA | 7 | \$0 | |
| Power Distribution | 101B Secretary Office | 8 | EA | 7 | \$0 | |
| Walls - Metal Panel | 101B Secretary Office | 460 | SF | 6 | \$3,434 | |
| Ceiling - Lay-in | 101C Assistant Principal Office | 210 | SF | 6 | \$631 | |
| Doors - Steel Doors incl hw | 101C Assistant Principal Office | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 101C Assistant Principal Office | 210 | SF | 6 | \$447 | |
| Lighting - Lay-in | 101C Assistant Principal Office | 4 | EA | 7 | \$0 | |
| Power Distribution | 101C Assistant Principal Office | 8 | EA | 7 | \$0 | |
| Walls - Metal Panel | 101C Assistant Principal Office | 525 | SF | 6 | \$3,919 | |
| Ceiling - Lay-in | 103 Copy Room | 181 | SF | 6 | \$544 | |
| Doors - Steel Doors incl hw | 103 Copy Room | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 103 Copy Room | 181 | SF | 6 | \$386 | |
| Lighting - Lay-in | 103 Copy Room | 4 | EA | 7 | \$0 | |
| Power Distribution | 103 Copy Room | 16 | EA | 7 | \$0 | |
| Walls - Metal Panel | 103 Copy Room | 460 | SF | 6 | \$3,434 | |
| Ceiling - Lay-in | 104 Main Office | 843 | SF | 6 | \$2,532 | |
| Doors - Steel Doors incl hw | 104 Main Office | 2 | EA | 6 | \$602 | |
| Floor - Carpet | 104 Main Office | 843 | SF | 6 | \$1,796 | |
| Floor - Tile/Sheet | 104 Main Office | 843 | SF | 6 | \$844 | |
| Lighting - Lay-in | 104 Main Office | 17 | EA | 7 | \$0 | |
| Power Distribution | 104 Main Office | 24 | EA | 7 | \$0 | |
| Walls - Concrete Block | 104 Main Office | 758 | SF | 6 | \$2,222 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------------------|-----------------------------|----------|------|------|----------|----------|
| Administrative Suites/Offices | | | | | | |
| Walls - Metal Panel | 104 Main Office | 1,770 | SF | 6 | \$13,212 | |
| Ceiling - Lay-in | 105 Office 1st floor | 156 | SF | 6 | \$468 | |
| Doors - Side-lite | 105 Office 1st floor | 7 | SF | 6 | \$117 | |
| Doors - Steel Doors incl hw | 105 Office 1st floor | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 105 Office 1st floor | 165 | SF | 6 | \$352 | |
| Lighting - Lay-in | 105 Office 1st floor | 4 | EA | 7 | \$0 | |
| Power Distribution | 105 Office 1st floor | 4 | EΑ | 7 | \$0 | |
| Walls - Metal Panel | 105 Office 1st floor | 390 | SF | 6 | \$2,911 | |
| Ceiling - Lay-in | 108 Girls Cot 1st floor | 110 | SF | 6 | \$330 | |
| Doors - Steel Doors incl hw | 108 Girls Cot 1st floor | 1 | EΑ | 6 | \$301 | |
| Floor - Tile/Sheet | 108 Girls Cot 1st floor | 110 | SF | 6 | \$110 | |
| Lighting - Lay-in | 108 Girls Cot 1st floor | 2 | EΑ | 7 | \$0 | |
| Power Distribution | 108 Girls Cot 1st floor | 4 | EΑ | 7 | \$0 | |
| Walls - Metal Panel | 108 Girls Cot 1st floor | 275 | SF | 6 | \$2,053 | |
| Ceiling - Lay-in | 109 Nurse Office 1st floor | 293 | SF | 6 | \$880 | |
| Doors - Side-lite | 109 Nurse Office 1st floor | 14 | SF | 6 | \$234 | |
| Doors - Steel Doors incl hw | 109 Nurse Office 1st floor | 1 | EΑ | 6 | \$301 | |
| Doors - Transom Window | 109 Nurse Office 1st floor | 10 | SF | 6 | \$169 | |
| Floor - Tile/Sheet | 109 Nurse Office 1st floor | 293 | SF | 6 | \$293 | |
| Lighting - Lay-in | 109 Nurse Office 1st floor | 6 | EΑ | 6 | \$714 | |
| Power Distribution | 109 Nurse Office 1st floor | 10 | EΑ | 6 | \$21,249 | |
| Walls - Metal Panel | 109 Nurse Office 1st floor | 733 | SF | 6 | \$5,472 | |
| Ceiling - Lay-in | 109A Nurse Office 1st floor | 232 | SF | 6 | \$697 | |
| Doors - Side-lite | 109A Nurse Office 1st floor | 14 | SF | 6 | \$234 | |
| Doors - Steel Doors incl hw | 109A Nurse Office 1st floor | 1 | EA | 6 | \$301 | |
| Doors - Transom Window | 109A Nurse Office 1st floor | 10 | SF | 6 | \$169 | |
| Floor - Tile/Sheet | 109A Nurse Office 1st floor | 232 | SF | 6 | \$232 | |
| Lighting - Lay-in | 109A Nurse Office 1st floor | 4 | EA | 7 | \$0 | |
| Power Distribution | 109A Nurse Office 1st floor | 8 | EA | 7 | \$0 | |
| Walls - Metal Panel | 109A Nurse Office 1st floor | 580 | SF | 6 | \$4,329 | |
| Ceiling - Lay-in | 110 Exam Room 1st floor | 230 | SF | 6 | \$691 | |
| Doors - Side-lite | 110 Exam Room 1st floor | 14 | SF | 6 | \$234 | |
| Doors - Steel Doors incl hw | 110 Exam Room 1st floor | 1 | EA | 6 | \$301 | |
| Doors - Transom Window | 110 Exam Room 1st floor | 10 | SF | 6 | \$169 | |
| Floor - Carpet | 110 Exam Room 1st floor | 230 | SF | 6 | \$490 | |
| Lighting - Lay-in | 110 Exam Room 1st floor | 4 | EA | 7 | \$0 | |
| Power Distribution | 110 Exam Room 1st floor | 8 | EA | 7 | \$0 | |
| | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| up Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|-----------------------------------|----------|------|------|----------|----------|
| inistrative Suites/Offices | | | | | | |
| Walls - Metal Panel | 110 Exam Room 1st floor | 575 | SF | 6 | \$4,292 | |
| Ceiling - Lay-in | 137 Teacher Office 1st floor | 650 | SF | 6 | \$1,952 | |
| Doors - Steel Doors incl hw | 137 Teacher Office 1st floor | 1 | EΑ | 6 | \$301 | |
| Floor - Tile/Sheet | 137 Teacher Office 1st floor | 650 | SF | 6 | \$651 | |
| Lighting - Pendent/Surface | 137 Teacher Office 1st floor | 7 | EA | 7 | \$0 | |
| Power Distribution | 137 Teacher Office 1st floor | 12 | EA | 7 | \$0 | |
| Storage/ Closet | 137 Teacher Office 1st floor | 60 | SF | 6 | \$435 | |
| Walls - Concrete Block | 137 Teacher Office 1st floor | 975 | SF | 6 | \$2,858 | |
| Walls - Plaster/Drywall | 137 Teacher Office 1st floor | 260 | SF | 6 | \$718 | |
| Work SInk | 137 Teacher Office 1st floor | 1 | EA | 6 | \$508 | |
| Ceiling - Lay-in | 145 Audio Visual 1st floor | 630 | SF | 6 | \$1,892 | |
| Doors - Steel Doors incl hw | 145 Audio Visual 1st floor | 2 | EA | 6 | \$602 | |
| Floor - Carpet | 145 Audio Visual 1st floor | 630 | SF | 6 | \$1,342 | |
| Lighting - Lay-in | 145 Audio Visual 1st floor | 6 | EA | 7 | \$0 | |
| Power Distribution | 145 Audio Visual 1st floor | 10 | EA | 7 | \$0 | |
| Walls - Masonry | 145 Audio Visual 1st floor | 110 | SF | 6 | \$346 | |
| Walls - Metal Panel | 145 Audio Visual 1st floor | 1,197 | SF | 6 | \$8,935 | |
| Ceiling - Lay-in | 146 Material Production 1st floor | 630 | SF | 6 | \$1,892 | |
| Doors - Steel Doors incl hw | 146 Material Production 1st floor | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 146 Material Production 1st floor | 630 | SF | 6 | \$1,342 | |
| Lighting - Lay-in | 146 Material Production 1st floor | 8 | EA | 7 | \$0 | |
| Power Distribution | 146 Material Production 1st floor | 8 | EA | 7 | \$0 | |
| Walls - Concrete Block | 146 Material Production 1st floor | 787 | SF | 6 | \$2,307 | |
| Walls - Metal Panel | 146 Material Production 1st floor | 787 | SF | 6 | \$5,875 | |
| Ceiling - Lay-in | 151 Office 1st floor | 240 | SF | 6 | \$721 | |
| Doors - Steel Doors incl hw | 151 Office 1st floor | 1 | EA | 6 | \$301 | |
| Floor - Carpet | 151 Office 1st floor | 240 | SF | 6 | \$511 | |
| Lighting - Lay-in | 151 Office 1st floor | 3 | EA | 7 | \$0 | |
| Power Distribution | 151 Office 1st floor | 8 | EA | 7 | \$0 | |
| Walls - Metal Panel | 151 Office 1st floor | 600 | SF | 6 | \$4,479 | |
| Ceiling - Lay-in | 152 Office 1st floor | 380 | SF | 6 | \$1,141 | |
| Doors - Side-lite | 152 Office 1st floor | 100 | SF | 6 | \$1,672 | |
| Doors - Steel Doors incl hw | 152 Office 1st floor | 1 | EA | 6 | \$301 | |
| Doors - Transom Window | 152 Office 1st floor | 30 | SF | 6 | \$508 | |
| Floor - Carpet | 152 Office 1st floor | 380 | SF | 6 | \$810 | |
| Lighting - Lay-in | 152 Office 1st floor | 5 | EA | 6 | \$595 | |
| Power Distribution | 152 Office 1st floor | 8 | EA | 6 | \$16,999 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------|-----------------------------|-----------------------------------|----------|------|------|---------|------------|
| mini | strative Suites/Offices | | | | | | |
| | Walls - Metal Panel | 152 Office 1st floor | 950 | SF | 6 | \$7,091 | |
| | Ceiling - Lay-in | 156 Office 1st floor | 520 | SF | 6 | \$1,562 | |
| | Doors - Side-lite | 156 Office 1st floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 156 Office 1st floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 156 Office 1st floor | 10 | SF | 6 | \$169 | |
| | Floor - Carpet | 156 Office 1st floor | 520 | SF | 6 | \$1,108 | |
| | Lighting - Lay-in | 156 Office 1st floor | 8 | EA | 6 | \$952 | |
| | Power Distribution | 156 Office 1st floor | 2 | EA | 6 | \$4,250 | |
| | Walls - Concrete Block | 156 Office 1st floor | 260 | SF | 6 | \$762 | |
| | Walls - Metal Panel | 156 Office 1st floor | 1,040 | SF | 6 | \$7,763 | Glass wall |
| | Ceiling - Lay-in | 170A Teacher Office 1st floor | 580 | SF | 6 | \$1,742 | |
| | Doors - Steel Doors incl hw | 170A Teacher Office 1st floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 170A Teacher Office 1st floor | 580 | SF | 6 | \$581 | |
| | Lighting - Lay-in | 170A Teacher Office 1st floor | 9 | EA | 7 | \$0 | |
| | Power Distribution | 170A Teacher Office 1st floor | 16 | EA | 7 | \$0 | |
| | Walls - Metal Panel | 170A Teacher Office 1st floor | 1,218 | SF | 6 | \$9,092 | |
| | Work Sink | 170A Teacher Office 1st floor | 2 | EΑ | 6 | \$1,016 | |
| | Ceiling - Lay-in | 174 Teacher Office 1st floor | 140 | SF | 6 | \$420 | |
| | Doors - Steel Doors incl hw | 174 Teacher Office 1st floor | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile/Sheet | 174 Teacher Office 1st floor | 140 | SF | 6 | \$140 | |
| | Lighting - Lay-in | 174 Teacher Office 1st floor | 2 | EA | 7 | \$0 | |
| | Power Distribution | 174 Teacher Office 1st floor | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 174 Teacher Office 1st floor | 90 | SF | 6 | \$264 | |
| | Walls - Metal Panel | 174 Teacher Office 1st floor | 260 | SF | 6 | \$1,941 | |
| | Ceiling - Lay-in | 180 office, in room 182 1st floor | 194 | SF | 6 | \$583 | |
| | Doors - Side-lite | 180 office, in room 182 1st floor | 10 | SF | 6 | \$167 | |
| | Doors - Steel Doors incl hw | 180 office, in room 182 1st floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 180 office, in room 182 1st floor | 7 | SF | 6 | \$119 | |
| | Floor - Tile | 180 office, in room 182 1st floor | 194 | SF | 6 | \$424 | |
| | Lighting - Lay-in | 180 office, in room 182 1st floor | 4 | EA | 7 | \$0 | |
| | Power Distribution | 180 office, in room 182 1st floor | 2 | EA | 7 | \$0 | |
| | Walls - Metal Panel | 180 office, in room 182 1st floor | 590 | SF | 6 | \$4,404 | |
| | Ceiling - Lay-in | 188 Faculty Prep. Office | 241 | SF | 6 | \$724 | |
| | Doors - Steel Doors incl hw | 188 Faculty Prep. Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 188 Faculty Prep. Office | 241 | SF | 6 | \$241 | |
| | Lighting - Lay-in | 188 Faculty Prep. Office | 5 | EA | 7 | \$0 | |
| | Power Distribution | 188 Faculty Prep. Office | 4 | EA | 7 | \$0 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|---------------------------------|----------|------|------|----------|-------------|
| Adminis | strative Suites/Offices | | | | | | |
| | Walls - Plaster/Drywall | 188 Faculty Prep. Office | 556 | SF | 6 | \$1,535 | |
| | Ceiling - Lay-in | 207 Faculty Planning 2nd floor | 442 | SF | 6 | \$1,327 | |
| | Doors - Steel Doors incl hw | 207 Faculty Planning 2nd floor | 1 | EΑ | 6 | \$301 | |
| | Floor - Tile/Sheet | 207 Faculty Planning 2nd floor | 442 | SF | 6 | \$442 | |
| | Lighting - Lay-in | 207 Faculty Planning 2nd floor | 9 | EΑ | 7 | \$0 | |
| | Power Distribution | 207 Faculty Planning 2nd floor | 8 | EA | 7 | \$0 | |
| | Walls - Metal Panel | 207 Faculty Planning 2nd floor | 890 | SF | 6 | \$6,643 | |
| | Ceiling - Lay-in | 208 police room 2nd floor | 293 | SF | 6 | \$880 | |
| | Doors - Steel Doors incl hw | 208 police room 2nd floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | 208 police room 2nd floor | 293 | SF | 6 | \$641 | |
| | Lighting - Lay-in | 208 police room 2nd floor | 6 | EA | 7 | \$0 | |
| | Power Distribution | 208 police room 2nd floor | 12 | EA | 7 | \$0 | |
| | Walls - Metal Panel | 208 police room 2nd floor | 698 | SF | 6 | \$5,210 | |
| | Ceiling - Lay-in | 209 Office 2nd floor | 450 | SF | 6 | \$1,351 | |
| | Doors - Steel Doors incl hw | 209 Office 2nd floor | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 209 Office 2nd floor | 450 | SF | 6 | \$959 | |
| | Lighting - Lay-in | 209 Office 2nd floor | 3 | EA | 6 | \$357 | |
| | Power Distribution | 209 Office 2nd floor | 4 | EA | 7 | \$0 | |
| | Walls - Metal Panel | 209 Office 2nd floor | 675 | SF | 6 | \$5,039 | |
| | Ceiling - Lay-in | 210 Office | 405 | SF | 6 | \$1,216 | |
| | Doors - Steel Doors incl hw | 210 Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 210 Office | 405 | SF | 6 | \$405 | |
| | Lighting - Lay-in | 210 Office | 8 | EA | 7 | \$0 | |
| | Power Distribution | 210 Office | 6 | EA | 7 | \$0 | |
| | Walls - Metal Panel | 210 Office | 908 | SF | 6 | \$6,778 | |
| | Work SInk | 210 Office | 1 | EA | 6 | \$508 | |
| | Ceiling - Lay-in | 210-211 Office 2nd floor | 405 | SF | 6 | \$1,216 | |
| | Doors - Side-lite | 210-211 Office 2nd floor | 10 | SF | 6 | \$167 | |
| | Doors - Steel Doors incl hw | 210-211 Office 2nd floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 210-211 Office 2nd floor | 25 | SF | 6 | \$423 | |
| | Floor - Tile/Sheet | 210-211 Office 2nd floor | 405 | SF | 6 | \$405 | |
| | Lighting - Lay-in | 210-211 Office 2nd floor | 8 | EA | 6 | \$952 | |
| | Power Distribution | 210-211 Office 2nd floor | 6 | EA | 6 | \$12,749 | |
| | Walls - Metal Panel | 210-211 Office 2nd floor | 809 | SF | 6 | \$6,039 | Metal panel |
| | Work SInk | 210-211 Office 2nd floor | 1 | EA | 6 | \$508 | |
| | Ceiling - Lay-in | 2-121 servery prep rm 1st floor | 127 | SF | 6 | \$381 | |
| | Doors - Steel Doors incl hw | 2-121 servery prep rm 1st floor | 1 | EA | 6 | \$301 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|---------------------------------|---------------------------------|----------|------|------|---------|-------------------|
| • | strative Suites/Offices | | | | | | |
| | Floor - Terrazzo | 2-121 servery prep rm 1st floor | 127 | SF | 6 | \$278 | |
| | Lighting - Lay-in | 2-121 servery prep rm 1st floor | 2 | EA | 7 | \$0 | |
| | Power Distribution | 2-121 servery prep rm 1st floor | 4 | EΑ | 7 | \$0 | |
| | Walls - Tile Ceramic/ Porcelain | 2-121 servery prep rm 1st floor | 362 | SF | 6 | \$818 | |
| | Work Sink | 2-121 servery prep rm 1st floor | 1 | EA | 6 | \$508 | |
| | Ceiling - Lay-in | 219 Conference Room 2nd floor | 650 | SF | 6 | \$1,952 | |
| | Doors - Side-lite | 219 Conference Room 2nd floor | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 219 Conference Room 2nd floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 219 Conference Room 2nd floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile/Sheet | 219 Conference Room 2nd floor | 650 | SF | 6 | \$651 | |
| | Lighting - Lay-in | 219 Conference Room 2nd floor | 5 | EA | 7 | \$0 | |
| | Power Distribution | 219 Conference Room 2nd floor | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 219 Conference Room 2nd floor | 110 | SF | 6 | \$322 | |
| | Walls - Metal Panel | 219 Conference Room 2nd floor | 780 | SF | 6 | \$5,822 | |
| | Ceiling - Lay-in | 221 Office 2nd floor | 292 | SF | 6 | \$877 | |
| | Doors - Side-lite | 221 Office 2nd floor | 7 | SF | 6 | \$117 | Solid steel panel |
| | Doors - Steel Doors incl hw | 221 Office 2nd floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 221 Office 2nd floor | 12 | SF | 6 | \$203 | |
| | Floor - Tile/Sheet | 221 Office 2nd floor | 292 | SF | 6 | \$292 | |
| | Lighting - Lay-in | 221 Office 2nd floor | 3 | EA | 7 | \$0 | |
| | Power Distribution | 221 Office 2nd floor | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 221 Office 2nd floor | 91 | SF | 6 | \$267 | |
| | Walls - Metal Panel | 221 Office 2nd floor | 692 | SF | 6 | \$5,166 | |
| | Ceiling - Lay-in | 249 Office 2nd floor | 360 | SF | 6 | \$1,081 | |
| | Doors - Steel Doors incl hw | 249 Office 2nd floor | 2 | EA | 6 | \$602 | |
| | Floor - Tile/Sheet | 249 Office 2nd floor | 360 | SF | 6 | \$360 | |
| | Lighting - Lay-in | 249 Office 2nd floor | 9 | EA | 7 | \$0 | |
| | Power Distribution | 249 Office 2nd floor | 12 | EA | 7 | \$0 | |
| | Walls - Metal Panel | 249 Office 2nd floor | 730 | SF | 6 | \$5,449 | |
| | Ceiling - Lay-in | 269 Office | 405 | SF | 6 | \$1,216 | |
| | Doors - Side-lite | 269 Office | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 269 Office | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 269 Office | 56 | SF | 6 | \$948 | |
| | Floor - Tile/Sheet | 269 Office | 405 | SF | 6 | \$405 | |
| | Lighting - Lay-in | 269 Office | 8 | EA | 7 | \$0 | |
| | Power Distribution | 269 Office | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 269 Office | 81 | SF | 6 | \$237 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|-------------------------------------|-------------|----------|------|---------|----------|
| strative Suites/Offices | | -, , | - | | | |
| Walls - Metal Panel | 269 Office | 728 | SF | 6 | \$5,434 | |
| Ceiling - Lay-in | 287 Administrative Office 2nd floor | 450 | SF | 6 | \$1,351 | |
| Doors - Side-lite | 287 Administrative Office 2nd floor | 14 | SF | 6 | \$234 | |
| Doors - Steel Doors incl hw | 287 Administrative Office 2nd floor | 1 | EA | 6 | \$301 | |
| Doors - Transom Window | 287 Administrative Office 2nd floor | 10 | SF | 6 | \$169 | |
| Floor - Carpet | 287 Administrative Office 2nd floor | 450 | SF | 6 | \$959 | |
| Lighting - Lay-in | 287 Administrative Office 2nd floor | 5 | EA | 7 | \$0 | |
| Power Distribution | 287 Administrative Office 2nd floor | 8 | EA | 7 | \$0 | |
| Walls - Concrete Block | 287 Administrative Office 2nd floor | 110 | SF | 6 | \$322 | |
| Walls - Metal Panel | 287 Administrative Office 2nd floor | 655 | SF | 6 | \$4,889 | |
| Ceiling - Lay-in | 287A Office 2nd floor | 350 | SF | 6 | \$1,051 | |
| Doors - Side-lite | 287A Office 2nd floor | 14 | SF | 6 | \$234 | |
| Doors - Steel Doors incl hw | 287A Office 2nd floor | 1 | EA | 6 | \$301 | |
| Doors - Transom Window | 287A Office 2nd floor | 10 | SF | 6 | \$169 | |
| Floor - Carpet | 287A Office 2nd floor | 350 | SF | 6 | \$746 | |
| Lighting - Lay-in | 287A Office 2nd floor | 3 | EA | 7 | \$0 | |
| Power Distribution | 287A Office 2nd floor | 8 | EA | 7 | \$0 | |
| Walls - Metal Panel | 287A Office 2nd floor | 665 | SF | 6 | \$4,964 | |
| Ceiling - Lay-in | 287B Office 2nd floor | 140 | SF | 6 | \$420 | |
| Doors - Side-lite | 287B Office 2nd floor | 14 | SF | 6 | \$234 | |
| Doors - Steel Doors incl hw | 287B Office 2nd floor | 1 | EA | 6 | \$301 | |
| Doors - Transom Window | 287B Office 2nd floor | 10 | SF | 6 | \$169 | |
| Floor - Carpet | 287B Office 2nd floor | 140 | SF | 6 | \$298 | |
| Lighting - Lay-in | 287B Office 2nd floor | 2 | EA | 7 | \$0 | |
| Power Distribution | 287B Office 2nd floor | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | 287B Office 2nd floor | 180 | SF | 6 | \$528 | |
| Walls - Metal Panel | 287B Office 2nd floor | 210 | SF | 6 | \$1,568 | |
| Ceiling - Lay-in | 308 Office 1st floor | 350 | SF | 6 | \$1,051 | |
| Doors - Steel Doors incl hw | 308 Office 1st floor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 308 Office 1st floor | 350 | SF | 6 | \$350 | |
| Lighting - Lay-in | 308 Office 1st floor | 1 | EA | 7 | \$0 | |
| Power Distribution | 308 Office 1st floor | 4 | EA | 7 | \$0 | |
| Walls - Concrete Block | 308 Office 1st floor | 735 | SF | 6 | \$2,155 | |
| Ceiling - Lay-in | 309 Office 1st floor | 350 | SF | 6 | \$1,051 | |
| Doors - Steel Doors incl hw | 309 Office 1st floor | 1 | EA | 6 | \$301 | |
| Floor - Tile/Sheet | 309 Office 1st floor | 350 | SF | 6 | \$350 | |
| Lighting - Lay-in | 309 Office 1st floor | 1 | EA | 7 | \$0 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| roup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-------------------------------------|----------------------|----------|------|------|---------|---------------|
| Admini | strative Suites/Offices | | | | | | |
| | Power Distribution | 309 Office 1st floor | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 309 Office 1st floor | 735 | SF | 6 | \$2,155 | |
| | Ceiling - Lay-in | 310 Office 1st floor | 350 | SF | 6 | \$1,051 | |
| | Doors - Steel Doors incl hw | 310 Office 1st floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 310 Office 1st floor | 350 | SF | 6 | \$350 | |
| | Lighting - Lay-in | 310 Office 1st floor | 1 | EA | 7 | \$0 | |
| | Power Distribution | 310 Office 1st floor | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 310 Office 1st floor | 735 | SF | 6 | \$2,155 | |
| | Ceiling - Lay-in | 312 Office 1st floor | 750 | SF | 6 | \$2,252 | |
| | Doors - Steel Doors incl hw | 312 Office 1st floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 312 Office 1st floor | 750 | SF | 6 | \$751 | |
| | Lighting - Lay-in | 312 Office 1st floor | 3 | EΑ | 7 | \$0 | |
| | Power Distribution | 312 Office 1st floor | 6 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | 312 Office 1st floor | 1,875 | SF | 6 | \$5,497 | |
| | Ceiling - Plaster/Drywall | 400 Control Room | 320 | SF | 6 | \$1,107 | |
| | Doors - Steel Doors incl hw | 400 Control Room | 1 | EΑ | 6 | \$301 | |
| | Doors - Transom Window | 400 Control Room | 9 | SF | 6 | \$152 | Solid panel |
| | Floor - Tile/Sheet | 400 Control Room | 320 | SF | 6 | \$320 | |
| | Lighting - Chandelier, Incandescent | 400 Control Room | 6 | EA | 7 | \$0 | |
| | Power Distribution | 400 Control Room | 8 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | 400 Control Room | 768 | SF | 6 | \$2,251 | |
| | Ceiling - Lay-in | 404A Teacher Office | 420 | SF | 6 | \$1,261 | |
| | Doors - Steel Doors incl hw | 404A Teacher Office | 1 | EA | 6 | \$301 | |
| | Floor - Concrete Epoxy/ Painted | 404A Teacher Office | 420 | SF | 6 | \$222 | |
| | Lighting - Lay-in | 404A Teacher Office | 3 | EA | 7 | \$0 | |
| | Power Distribution | 404A Teacher Office | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 404A Teacher Office | 790 | SF | 6 | \$2,316 | |
| | Ceiling - Lay-in | 408 JORTC | 640 | SF | 6 | \$1,922 | |
| | Doors - Steel Doors incl hw | 408 JORTC | 2 | EA | 6 | \$602 | |
| | Doors - Transom Window | 408 JORTC | 9 | SF | 6 | \$152 | one door only |
| | Floor - Concrete Epoxy/ Painted | 408 JORTC | 640 | SF | 6 | \$339 | |
| | Lighting - Lay-in | 408 JORTC | 7 | EA | 7 | \$0 | |
| | Power Distribution | 408 JORTC | 8 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 408 JORTC | 1,060 | SF | 6 | \$3,107 | |
| | Ceiling - Lay-in | Rm 121 1st floor | 272 | SF | 6 | \$817 | |
| | Doors - Steel Doors incl hw | Rm 121 1st floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Rm 121 1st floor | 272 | SF | 6 | \$595 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| oup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------------------------------|-----------------------------|----------|------|------|---------|----------|
| dministrative Suites/Offices | | | | | | |
| Lighting - Lay-in | Rm 121 1st floor | 11 | EA | 7 | \$0 | |
| Power Distribution | Rm 121 1st floor | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | Rm 121 1st floor | 229 | SF | 6 | \$671 | |
| Walls - Metal Panel | Rm 121 1st floor | 229 | SF | 6 | \$1,709 | |
| Ceiling - Lay-in | Rm 123, in rm 124 1st floor | 346 | SF | 6 | \$1,039 | |
| Floor - Tile | Rm 123, in rm 124 1st floor | 346 | SF | 6 | \$757 | |
| Lighting - Lay-in | Rm 123, in rm 124 1st floor | 6 | EA | 7 | \$0 | |
| Power Distribution | Rm 123, in rm 124 1st floor | 10 | EA | 7 | \$0 | |
| Walls - Concrete Block | Rm 123, in rm 124 1st floor | 42 | SF | 6 | \$123 | |
| Walls - Metal Panel | Rm 123, in rm 124 1st floor | 710 | SF | 6 | \$5,300 | |
| Work Slnk | Rm 123, in rm 124 1st floor | 1 | EA | 6 | \$508 | |
| Ceiling - Lay-in | Rm 125 1st floor | 209 | SF | 6 | \$628 | |
| Doors - Steel Doors incl hw | Rm 125 1st floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | Rm 125 1st floor | 209 | SF | 6 | \$457 | |
| Lighting - Lay-in | Rm 125 1st floor | 4 | EA | 7 | \$0 | |
| Power Distribution | Rm 125 1st floor | 4 | EA | 7 | \$0 | |
| Walls - Masonry | Rm 125 1st floor | 149 | SF | 6 | \$469 | Brick |
| Walls - Metal Panel | Rm 125 1st floor | 435 | SF | 6 | \$3,247 | |
| Ceiling - Lay-in | Rm 142 Office | 387 | SF | 6 | \$1,162 | |
| Doors - Side-lite | Rm 142 Office | 10 | SF | 6 | \$167 | |
| Doors - Steel Doors incl hw | Rm 142 Office | 1 | EA | 6 | \$301 | |
| Doors - Transom Window | Rm 142 Office | 7 | SF | 6 | \$119 | |
| Floor - Carpet | Rm 142 Office | 387 | SF | 6 | \$825 | |
| Lighting - Lay-in | Rm 142 Office | 7 | EA | 7 | \$0 | |
| Power Distribution | Rm 142 Office | 16 | EA | 7 | \$0 | |
| Walls - Concrete Block | Rm 142 Office | 118 | SF | 6 | \$346 | |
| Walls - Masonry | Rm 142 Office | 67 | SF | 6 | \$211 | Brick |
| Walls - Metal Panel | Rm 142 Office | 224 | SF | 6 | \$1,672 | |
| Walls - Plaster/Drywall | Rm 142 Office | 455 | SF | 6 | \$1,256 | |
| Work SInk | Rm 142 Office | 1 | EA | 6 | \$508 | |
| Ceiling - Lay-in | Rm 142A office | 177 | SF | 6 | \$532 | |
| Doors - Steel Doors incl hw | Rm 142A office | 1 | EA | 6 | \$301 | |
| Floor - Carpet | Rm 142A office | 177 | SF | 6 | \$377 | |
| Lighting - Lay-in | Rm 142A office | 3 | EA | 7 | \$0 | |
| Power Distribution | Rm 142A office | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | Rm 142A office | 175 | SF | 6 | \$513 | |
| Walls - Metal Panel | Rm 142A office | 100 | SF | 6 | \$746 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Commer |
|-------|-----------------------------|-------------------|----------|------|------|---------|--------|
| dmini | strative Suites/Offices | | | | | | |
| | Walls - Plaster/Drywall | Rm 142A office | 275 | SF | 6 | \$759 | |
| | Ceiling - Lay-in | Rm 142B Office | 308 | SF | 6 | \$925 | |
| | Doors - Steel Doors incl hw | Rm 142B Office | 1 | EΑ | 6 | \$301 | |
| | Doors - Transom Window | Rm 142B Office | 96 | SF | 6 | \$1,625 | |
| | Floor - Tile | Rm 142B Office | 308 | SF | 6 | \$674 | |
| | Lighting - Lay-in | Rm 142B Office | 5 | EΑ | 7 | \$0 | |
| | Power Distribution | Rm 142B Office | 6 | EΑ | 7 | \$0 | |
| | Walls - Masonry | Rm 142B Office | 20 | SF | 6 | \$63 | Brick |
| | Walls - Metal Panel | Rm 142B Office | 237 | SF | 6 | \$1,769 | |
| | Walls - Plaster/Drywall | Rm 142B Office | 373 | SF | 6 | \$1,029 | |
| | Ceiling - Lay-in | Rm 144 1st floor | 560 | SF | 6 | \$1,682 | |
| | Doors - Side-lite | Rm 144 1st floor | 7 | SF | 6 | \$117 | |
| | Doors - Steel Doors incl hw | Rm 144 1st floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | Rm 144 1st floor | 10 | SF | 6 | \$169 | |
| | Floor - Carpet | Rm 144 1st floor | 560 | SF | 6 | \$1,193 | |
| | Lighting - Lay-in | Rm 144 1st floor | 10 | EΑ | 7 | \$0 | |
| | Power Distribution | Rm 144 1st floor | 27 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | Rm 144 1st floor | 81 | SF | 6 | \$237 | |
| | Walls - Masonry | Rm 144 1st floor | 288 | SF | 6 | \$906 | Brick |
| | Walls - Metal Panel | Rm 144 1st floor | 347 | SF | 6 | \$2,590 | |
| | Work SInk | Rm 144 1st floor | 1 | EA | 6 | \$508 | |
| | Ceiling - Lay-in | Rm 220 2nd floor | 292 | SF | 6 | \$877 | |
| | Doors - Steel Doors incl hw | Rm 220 2nd floor | 1 | EΑ | 6 | \$301 | |
| | Doors - Transom Window | Rm 220 2nd floor | 12 | SF | 6 | \$203 | |
| | Floor - Tile/Sheet | Rm 220 2nd floor | 292 | SF | 6 | \$292 | |
| | Lighting - Lay-in | Rm 220 2nd floor | 6 | EA | 7 | \$0 | |
| | Power Distribution | Rm 220 2nd floor | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Rm 220 2nd floor | 91 | SF | 6 | \$267 | |
| | Walls - Metal Panel | Rm 220 2nd floor | 692 | SF | 6 | \$5,166 | |
| | Ceiling - Lay-in | Rm 222 2nd floor | 291 | SF | 6 | \$874 | |
| | Doors - Steel Doors incl hw | Rm 222 2nd floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | Rm 222 2nd floor | 21 | SF | 6 | \$356 | |
| | Floor - Tile | Rm 222 2nd floor | 291 | SF | 6 | \$637 | |
| | Lighting - Lay-in | Rm 222 2nd floor | 6 | EA | 7 | \$0 | |
| | Power Distribution | Rm 222 2nd floor | 4 | EA | 7 | \$0 | |
| | Walls - Metal Panel | Rm 222 2nd floor | 694 | SF | 6 | \$5,180 | |
| | Ceiling - Lay-in | Rm 234A 2nd floor | 369 | SF | 6 | \$1,108 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|-------------------|----------|------|------|---------|----------|
| Admini | strative Suites/Offices | | | | | | |
| | Doors - Steel Doors incl hw | Rm 234A 2nd floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Rm 234A 2nd floor | 369 | SF | 6 | \$807 | |
| | Lighting - Lay-in | Rm 234A 2nd floor | 15 | EA | 7 | \$0 | |
| | Power Distribution | Rm 234A 2nd floor | 8 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Rm 234A 2nd floor | 767 | SF | 6 | \$2,248 | |
| | Walls - Metal Panel | Rm 234A 2nd floor | 275 | SF | 6 | \$2,053 | |
| | Work Slnk | Rm 234A 2nd floor | 1 | EA | 6 | \$508 | |
| | Ceiling - Lay-in | Rm 242 2nd floor | 288 | SF | 6 | \$865 | |
| | Doors - Side-lite | Rm 242 2nd floor | 7 | SF | 6 | \$117 | |
| | Doors - Steel Doors incl hw | Rm 242 2nd floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | Rm 242 2nd floor | 10 | SF | 6 | \$169 | |
| | Floor - Carpet | Rm 242 2nd floor | 288 | SF | 6 | \$614 | |
| | Lighting - Lay-in | Rm 242 2nd floor | 6 | EA | 7 | \$0 | |
| | Power Distribution | Rm 242 2nd floor | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Rm 242 2nd floor | 99 | SF | 6 | \$290 | |
| | Walls - Metal Panel | Rm 242 2nd floor | 398 | SF | 6 | \$2,971 | |
| | Ceiling - Lay-in | Rm 242A 2nd floor | 191 | SF | 6 | \$574 | |
| | Doors - Side-lite | Rm 242A 2nd floor | 10 | SF | 6 | \$167 | |
| | Doors - Steel Doors incl hw | Rm 242A 2nd floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | Rm 242A 2nd floor | 98 | SF | 6 | \$1,659 | |
| | Floor - Carpet | Rm 242A 2nd floor | 191 | SF | 6 | \$407 | |
| | Lighting - Lay-in | Rm 242A 2nd floor | 6 | EA | 7 | \$0 | |
| | Power Distribution | Rm 242A 2nd floor | 8 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Rm 242A 2nd floor | 99 | SF | 6 | \$290 | |
| | Walls - Metal Panel | Rm 242A 2nd floor | 398 | SF | 6 | \$2,971 | |
| | Ceiling - Lay-in | Rm 242B 2nd floor | 96 | SF | 6 | \$288 | |
| | Doors - Side-lite | Rm 242B 2nd floor | 10 | SF | 6 | \$167 | |
| | Doors - Steel Doors incl hw | Rm 242B 2nd floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | Rm 242B 2nd floor | 29 | SF | 6 | \$491 | |
| | Floor - Carpet | Rm 242B 2nd floor | 96 | SF | 6 | \$205 | |
| | Lighting - Lay-in | Rm 242B 2nd floor | 2 | EA | 7 | \$0 | |
| | Power Distribution | Rm 242B 2nd floor | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Rm 242B 2nd floor | 195 | SF | 6 | \$572 | |
| | Walls - Metal Panel | Rm 242B 2nd floor | 125 | SF | 6 | \$933 | |
| | Ceiling - Lay-in | Rm 282 2nd floor | 309 | SF | 6 | \$928 | |
| | Doors - Steel Doors incl hw | Rm 282 2nd floor | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Rm 282 2nd floor | 309 | SF | 6 | \$676 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|----------------------------|----------|------|------|----------|----------|
| Admini | strative Suites/Offices | | - | | | | |
| | Lighting - Lay-in | Rm 282 2nd floor | 6 | EA | 7 | \$0 | |
| | Power Distribution | Rm 282 2nd floor | 16 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Rm 282 2nd floor | 44 | SF | 6 | \$129 | |
| | Walls - Metal Panel | Rm 282 2nd floor | 567 | SF | 6 | \$4,232 | |
| | Ceiling - Lay-in | Rm 290 2nd floor | 158 | SF | 6 | \$474 | |
| | Doors - Side-lite | Rm 290 2nd floor | 7 | SF | 6 | \$117 | |
| | Doors - Steel Doors incl hw | Rm 290 2nd floor | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | Rm 290 2nd floor | 10 | SF | 6 | \$169 | |
| | Floor - Tile | Rm 290 2nd floor | 158 | SF | 6 | \$346 | |
| | Lighting - Lay-in | Rm 290 2nd floor | 3 | EA | 7 | \$0 | |
| | Power Distribution | Rm 290 2nd floor | 6 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Rm 290 2nd floor | 150 | SF | 6 | \$440 | |
| | Walls - Metal Panel | Rm 290 2nd floor | 257 | SF | 6 | \$1,918 | |
| Auditor | ium & Theater | | | | | | |
| | Ceiling - Exposed | 300 Auditorium & Theater | 7,212 | SF | 6 | \$10,726 | |
| | Doors - Steel Doors incl hw | 300 Auditorium & Theater | 6 | EA | 6 | \$1,806 | |
| | Floor - Carpet | 300 Auditorium & Theater | 7,212 | SF | 6 | \$15,367 | |
| | Lighting - Pendent/Surface | 300 Auditorium & Theater | 46 | EA | 7 | \$0 | |
| | Main Floor Seating | 300 Auditorium & Theater | 500 | EA | 6 | \$86,958 | |
| | Sound System | 300 Auditorium & Theater | 1 | EA | 6 | \$10,721 | |
| | Stage | 300 Auditorium & Theater | 2,447 | SF | 6 | \$14,137 | |
| | Stage Curtain | 300 Auditorium & Theater | 16 | EA | 6 | \$0 | |
| | Stage Lighting System | 300 Auditorium & Theater | 1 | EA | 6 | \$8,077 | |
| | Stage-Stairs - Wood | 300 Auditorium & Theater | 14 | LF | 6 | \$164 | |
| | Walls - Masonry | 300 Auditorium & Theater | 11,040 | SF | 6 | \$34,732 | Brick |
| Kitchen | 1 | | | | | | |
| | Ceiling - Splined | 000A Kitchen @ Basement | 1,586 | SF | 6 | \$1,293 | |
| | Doors - Steel Doors incl hw | 000A Kitchen @ Basement | 6 | EA | 6 | \$1,806 | |
| | Floor - Terrazzo | 000A Kitchen @ Basement | 1,586 | SF | 6 | \$3,470 | |
| | Lighting - Lay-in | 000A Kitchen @ Basement | 60 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 000A Kitchen @ Basement | 1,845 | SF | 6 | \$5,804 | |
| Library | | | | | | | |
| | Ceiling - Lay-in | 154 Library Main 1st floor | 13,612 | SF | 6 | \$40,877 | |
| | Doors - Steel Doors incl hw | 154 Library Main 1st floor | 4 | EA | 6 | \$1,204 | |
| | Floor - Carpet | 154 Library Main 1st floor | 13,612 | SF | 6 | \$29,003 | |
| | Lighting - Lay-in | 154 Library Main 1st floor | 272 | EA | 7 | \$0 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Categ | ory: Rooms (Other Than Classrooms) | | | | | | |
|---------|------------------------------------|------------------------------|----------|------|------|----------|-----------------|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Library | | | | | | | |
| | Walls - Concrete Block | 154 Library Main 1st floor | 2,065 | SF | 6 | \$6,054 | |
| | Walls - Metal Panel | 154 Library Main 1st floor | 6,195 | SF | 6 | \$46,243 | |
| Locker/ | Shower Room | | | | | | |
| | Accessories | 0500 Men's Locker Basement | 780 | SF | 6 | \$3,056 | |
| | Benches, ped mounted | 0500 Men's Locker Basement | 30 | LF | 6 | \$3,266 | concrete |
| | Ceiling - Plaster/ Drywall | 0500 Men's Locker Basement | 780 | SF | 6 | \$2,699 | |
| | Floor Drain | 0500 Men's Locker Basement | 1 | EA | 6 | \$1,059 | |
| | Floor - Concrete Epoxy/ Painted | 0500 Men's Locker Basement | 780 | SF | 6 | \$413 | |
| | Lighting - Pendent/Surface | 0500 Men's Locker Basement | 4 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | 0500 Men's Locker Basement | 80 | EA | 6 | \$7,427 | |
| | Student Lockers - Two Tier | 0500 Men's Locker Basement | 7 | EA | 6 | \$325 | Handicap locker |
| | Student Lockers - Two Tier | 0500 Men's Locker Basement | 80 | EA | 6 | \$3,713 | |
| | Walls - Concrete Block | 0500 Men's Locker Basement | 2,262 | SF | 6 | \$6,631 | |
| | Accessories | 0504 Men's Showers Basement | 730 | SF | 6 | \$2,860 | |
| | Ceiling - Plaster/ Drywall | 0504 Men's Showers Basement | 730 | SF | 6 | \$2,526 | |
| | Floor Drain | 0504 Men's Showers Basement | 12 | EA | 6 | \$12,710 | |
| | Floor - Tile Ceramic/ Porcelain | 0504 Men's Showers Basement | 730 | SF | 6 | \$1,545 | |
| | Lighting - Pendent/Surface | 0504 Men's Showers Basement | 16 | EA | 6 | \$1,982 | |
| | Showers | 0504 Men's Showers Basement | 34 | EA | 6 | \$10,588 | |
| | Walls - Tile Ceramic/ Porcelain | 0504 Men's Showers Basement | 1,825 | SF | 6 | \$4,123 | |
| | Accessories | 0505 Men's Locker Room | 346 | SF | 6 | \$1,356 | |
| | Benches, ped mounted | 0505 Men's Locker Room | 60 | LF | 6 | \$6,533 | Concrete |
| | Ceiling - Plaster/ Drywall | 0505 Men's Locker Room | 346 | SF | 6 | \$1,197 | |
| | Doors - Steel Doors incl hw | 0505 Men's Locker Room | 2 | EA | 6 | \$602 | |
| | Floor Drain | 0505 Men's Locker Room | 3 | EA | 6 | \$3,177 | |
| | Floor - Epoxy/ Painted | 0505 Men's Locker Room | 346 | SF | 6 | \$183 | |
| | Lighting - Pendent/Surface | 0505 Men's Locker Room | 5 | EA | 6 | \$619 | |
| | Student Lockers - One Tier | 0505 Men's Locker Room | 36 | EA | 6 | \$3,342 | |
| | Student Lockers - Two Tier | 0505 Men's Locker Room | 27 | EA | 6 | \$1,253 | |
| | Walls - Concrete Block | 0505 Men's Locker Room | 865 | SF | 6 | \$2,536 | |
| | Accessories | 0519 Women's Locker Basement | 1,462 | SF | 6 | \$5,728 | |
| | Benches, ped mounted | 0519 Women's Locker Basement | 90 | LF | 6 | \$9,799 | Concrete |
| | Ceiling - Plaster/ Drywall | 0519 Women's Locker Basement | 1,462 | SF | 6 | \$5,059 | |
| | Doors - Steel Doors incl hw | 0519 Women's Locker Basement | 3 | EA | 6 | \$903 | |
| | Floor Drain | 0519 Women's Locker Basement | 5 | EA | 6 | \$5,296 | |
| | Floor - Concrete Epoxy/ Painted | 0519 Women's Locker Basement | 1,462 | SF | 6 | \$774 | |
| | Lighting - Pendent/Surface | 0519 Women's Locker Basement | 8 | EA | 7 | \$0 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|---|----------|------|------|----------|--------------------|
| Locker/ | Shower Room | | | | | | |
| | Student Lockers - One Tier | 0519 Women's Locker Basement | 180 | EA | 6 | \$16,710 | |
| | Walls - Concrete Block | 0519 Women's Locker Basement | 3,655 | SF | 6 | \$10,715 | |
| | Accessories | 0526 Women's Showers Basement | 730 | SF | 6 | \$2,860 | |
| | Ceiling - Plaster/ Drywall | 0526 Women's Showers Basement | 730 | SF | 6 | \$2,526 | |
| | Floor Drain | 0526 Women's Showers Basement | 12 | EA | 6 | \$12,710 | |
| | Floor - Tile Ceramic/ Porcelain | 0526 Women's Showers Basement | 730 | SF | 6 | \$1,545 | |
| | Lighting - Pendent/Surface | 0526 Women's Showers Basement | 16 | EA | 6 | \$1,982 | |
| | Showers | 0526 Women's Showers Basement | 38 | EA | 6 | \$11,834 | |
| | Walls - Tile Ceramic/ Porcelain | 0526 Women's Showers Basement | 1,825 | SF | 6 | \$4,123 | |
| Lunch 8 | & Multipurpose Room | | | | | | |
| | Ceiling - Lay-in | 2-121 servery (north) 1st floor | 439 | SF | 6 | \$1,318 | |
| | Doors - Steel Doors incl hw | 2-121 servery (north) 1st floor | 4 | EA | 6 | \$1,204 | |
| | Floor - Terrazzo | 2-121 servery (north) 1st floor | 439 | SF | 6 | \$960 | |
| | Lighting - Lay-in | 2-121 servery (north) 1st floor | 10 | EA | 7 | \$0 | |
| | Serving Line | 2-121 servery (north) 1st floor | 37 | LF | 6 | \$2,202 | |
| | Walls - Tile Ceramic/ Porcelain | 2-121 servery (north) 1st floor | 819 | SF | 6 | \$1,850 | |
| | Ceiling - Lay-in | 2-214 lunch rm (2nd flr north) | 2,735 | SF | 6 | \$8,213 | |
| | Floor - Tile/Sheet | 2-214 lunch rm (2nd flr north) | 2,735 | SF | 6 | \$2,738 | |
| | Lighting - Lay-in | 2-214 lunch rm (2nd flr north) | 54 | EA | 7 | \$0 | |
| | Walls - Masonry | 2-214 lunch rm (2nd flr north) | 580 | SF | 6 | \$1,825 | |
| | Walls - Metal Panel | 2-214 lunch rm (2nd flr north) | 608 | SF | 6 | \$4,538 | |
| | Ceiling - Splined | 271 servery (Southwest) 2nd floor | 439 | SF | 6 | \$358 | |
| | Doors - Steel Doors incl hw | 271 servery (Southwest) 2nd floor | 4 | EA | 6 | \$1,204 | |
| | Floor - Terrazzo | 271 servery (Southwest) 2nd floor | 439 | SF | 6 | \$960 | |
| | Lighting - Lay-in | 271 servery (Southwest) 2nd floor | 10 | EA | 7 | \$0 | |
| | Serving Line | 271 servery (Southwest) 2nd floor | 37 | LF | 6 | \$2,202 | |
| | Walls - Tile Ceramic/ Porcelain | 271 servery (Southwest) 2nd floor | 694 | SF | 6 | \$1,568 | |
| | Ceiling - Lay-in | 2nd floor lunchroom, across from rm 289 | 2,735 | SF | 6 | \$8,213 | |
| | Doors - Steel Doors incl hw | 2nd floor lunchroom, across from rm 289 | 4 | EA | 6 | \$1,204 | w/full glass lites |
| | Floor - Tile/Sheet | 2nd floor lunchroom, across from rm 289 | 2,735 | SF | 6 | \$2,738 | |
| | Lighting - Lay-in | 2nd floor lunchroom, across from rm 289 | 53 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd floor lunchroom, across from rm 289 | 274 | SF | 6 | \$803 | |
| | Walls - Masonry | 2nd floor lunchroom, across from rm 289 | 845 | SF | 6 | \$2,658 | |
| | Walls - Plaster/Drywall | 2nd floor lunchroom, across from rm 289 | 472 | SF | 6 | \$1,303 | |
| MDF_ID | F | | | | | | |
| | Doors - Steel Doors incl hw | 118 MDF IDF | 2 | EA | 6 | \$602 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|-------------|----------|------|------|-----------|--|
| MDF_I |)F | | | | | | |
| | Finishes | 118 MDF_IDF | 290 | SF | 6 | \$2,069 | |
| | Ventilation and Cooling | 118 MDF_IDF | 1 | EA | 6 | \$1,855 | |
| | Doors - Steel Doors incl hw | 134 MDF_IDF | 1 | EA | 6 | \$301 | |
| | Finishes | 134 MDF_IDF | 80,150 | SF | 6 | \$571,926 | |
| | Ventilation and Cooling | 134 MDF_IDF | 1 | EA | 6 | \$1,855 | |
| | Doors - Steel Doors incl hw | 191 MDF_IDF | 3 | EA | 6 | \$903 | |
| | Finishes | 191 MDF_IDF | 430 | SF | 6 | \$3,068 | |
| | Ventilation and Cooling | 191 MDF_IDF | 1 | EA | 6 | \$1,855 | |
| Mechar | nical/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 27 | SF | 6 | \$193 | In girls restroom next to 144 |
| | Janitor's Closet | 1st Floor | 24 | SF | 6 | \$172 | In boys restroom |
| | Mechanical/ Service Rooms | 1st Floor | 40 | SF | 6 | \$287 | In rm 124 |
| | Mechanical/ Service Rooms | 1st Floor | 40 | SF | 6 | \$287 | Elec closet across from rm 129 |
| | Storage Room | 1st Floor | 310 | SF | 6 | \$2,221 | Recieving. Has elevator access |
| | Storage Room | 1st Floor | 1,918 | SF | 6 | \$13,741 | 120, 135, 147, 149, 177,187, 406-1 Storage |
| | Janitor's Closet | 2nd Floor | 21 | SF | 6 | \$150 | Across from rm 254 |
| | Janitor's Closet | 2nd Floor | 21 | SF | 6 | \$150 | Across from men's staff near rm 275 |
| | Janitor's Closet | 2nd Floor | 22 | SF | 6 | \$158 | Across from rm 204 |
| | Mechanical/ Service Rooms | 2nd Floor | 9 | SF | 6 | \$64 | In boys restroom across from 293 |
| | Mechanical/ Service Rooms | 2nd Floor | 19 | SF | 6 | \$136 | across from rm 253 |
| | Mechanical/ Service Rooms | 2nd Floor | 17 | SF | 6 | \$122 | Electrical closet across from rm 288 |
| | Mechanical/ Service Rooms | 2nd Floor | 50 | SF | 6 | \$358 | In rm 250 |
| | Mechanical/ Service Rooms | 2nd Floor | 24 | SF | 6 | \$172 | Across from rm 204 |
| | Mechanical/ Service Rooms | 2nd Floor | 50 | SF | 6 | \$358 | Across from rm 268/269 |
| | Mechanical/ Service Rooms | 2nd Floor | 4 | SF | 6 | \$29 | Across from rm 275 |
| | Mechanical/ Service Rooms | 2nd Floor | 11 | SF | 6 | \$79 | Across from rm 204 |
| | Storage Room | 2nd Floor | 15 | SF | 6 | \$107 | Laundry /storage rm across from rm 244 |
| | Storage Room | 2nd Floor | 1,020 | SF | 6 | \$7,308 | Rm 248 , 279, 289 Storage |
| | Air Intake Plenums | Basement | 788 | SF | 6 | \$4,879 | 012 |
| | Boiler Room | Basement | 675 | SF | 6 | \$4,836 | 002B-1 Boiler Room |
| | Coal Room | Basement | 750 | SF | 6 | \$5,373 | 002B-2 |
| | Interior Stairs | Basement | 14 | LF | 6 | \$126 | 7-steps up to loading dock platform, 6-steps down from basement corridor to underground area floor level |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| • | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|---------------------------------|----------|------|------|----------|---|
| Mechai | nical/ Service Rooms | | | | | | |
| | Loading Docks | Basement | 1,000 | SF | 5 | \$16,130 | Areas of concrete ceiling / walls cracked with staining, crumbling, peeling occurring and evidence of water penetration / Areas of lay-in ceiling damaged due to delivery trucks, Several ceiling surface lights damaged and not working properly |
| | Loading Docks | Basement | 4,400 | SF | 6 | \$31,523 | Entire Underground area included beyond entrance 22 / Elevated platform - 410sf |
| | Mechanical/ Service Rooms | Basement | 200 | SF | 6 | \$1,433 | 011 Mechanical room |
| | Mechanical/ Service Rooms | Basement | 125 | SF | 6 | \$896 | 009 Elevator room |
| | Mechanical/ Service Rooms | Basement | 830 | SF | 6 | \$5,946 | 004 Electrical room |
| | Mechanical/ Service Rooms | Basement | 530 | SF | 6 | \$3,797 | 003C Pump room |
| | Mechanical/ Service Rooms | Basement | 175 | SF | 5 | \$2,823 | 010 fire pump room - Ponding occurring |
| | Mechanical/ Service Rooms | Basement | 2,434 | SF | 6 | \$17,438 | 002B-1, 014 |
| | Storage Room | Basement | 285 | SF | 6 | \$2,042 | 003B - Outside yard storage |
| | Storage Room | Basement | 3,133 | SF | 6 | \$22,446 | 000E, 000H, I, 001, 002, 003, 013, 018 all the storage are adding together |
| Prep R | oom | | | | | | |
| | Casework | 201A Prep Room | 10 | LF | 6 | \$253 | |
| | Ceiling - Lay-in | 201A Prep Room | 430 | SF | 6 | \$1,291 | |
| | Doors - Steel Doors incl hw | 201A Prep Room | 1 | EA | 6 | \$301 | |
| | Floor - Tile/Sheet | 201A Prep Room | 430 | SF | 6 | \$430 | |
| | Lighting - Lay-in | 201A Prep Room | 4 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 201A Prep Room | 940 | SF | 6 | \$2,594 | |
| | Work Sink | 201A Prep Room | 1 | EA | 6 | \$379 | |
| | Casework | 227 Prep Room | 10 | LF | 6 | \$253 | |
| | Ceiling - Lay-in | 227 Prep Room | 650 | SF | 6 | \$1,952 | |
| | Doors - Side-lite | 227 Prep Room | 14 | SF | 6 | \$234 | |
| | Doors - Steel Doors incl hw | 227 Prep Room | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | 227 Prep Room | 56 | SF | 6 | \$948 | |
| | Floor - Tile/Sheet | 227 Prep Room | 650 | SF | 6 | \$651 | |
| | Lighting - Lay-in | 227 Prep Room | 9 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 227 Prep Room | 120 | SF | 6 | \$352 | |
| | Walls - Metal Panel | 227 Prep Room | 420 | SF | 6 | \$3,135 | |
| | Walls - Plaster/Drywall | 227 Prep Room | 360 | SF | 6 | \$994 | |
| | Work Sink | 227 Prep Room | 1 | EA | 6 | \$379 | |
| Restro | om | | | | | | |
| | Accessories | 000D-1 Women's Custodial Toilet | 47 | SF | 6 | \$434 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|---------------------------------|----------|------|------|---------|----------|
| estroo | • | | | | | | |
| | Ceiling - Plaster/Drywall | 000D-1 Women's Custodial Toilet | 47 | SF | 6 | \$163 | |
| | Doors - Steel Doors incl hw | 000D-1 Women's Custodial Toilet | 1 | EA | 6 | \$301 | |
| | Floor Drain | 000D-1 Women's Custodial Toilet | 1 | EA | 6 | \$1,059 | |
| | Floor - Concrete Epoxy/ Painted | 000D-1 Women's Custodial Toilet | 47 | SF | 6 | \$25 | |
| | Lavatory | 000D-1 Women's Custodial Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 000D-1 Women's Custodial Toilet | 1 | EA | 6 | \$119 | |
| | Partitions | 000D-1 Women's Custodial Toilet | 1 | EA | 6 | \$297 | |
| | Walls - Concrete Block | 000D-1 Women's Custodial Toilet | 307 | SF | 6 | \$900 | |
| | Water Closet | 000D-1 Women's Custodial Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 000G-1 Men's Custodial Toilet | 123 | SF | 6 | \$1,134 | |
| | Benches | 000G-1 Men's Custodial Toilet | 20 | LF | 6 | \$289 | |
| | Ceiling - Plaster/Drywall | 000G-1 Men's Custodial Toilet | 123 | SF | 6 | \$426 | |
| | Doors - Steel Doors incl hw | 000G-1 Men's Custodial Toilet | 1 | EA | 6 | \$301 | |
| | Floor Drain | 000G-1 Men's Custodial Toilet | 1 | EA | 6 | \$1,059 | |
| | Floor - Concrete Epoxy/ Painted | 000G-1 Men's Custodial Toilet | 123 | SF | 6 | \$65 | |
| | Lavatory | 000G-1 Men's Custodial Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 000G-1 Men's Custodial Toilet | 1 | EA | 7 | \$0 | |
| | Partitions | 000G-1 Men's Custodial Toilet | 1 | EA | 6 | \$297 | |
| | Student Lockers - One Tier | 000G-1 Men's Custodial Toilet | 20 | EA | 6 | \$1,857 | |
| | Urinals | 000G-1 Men's Custodial Toilet | 1 | EA | 6 | \$336 | |
| | Walls - Concrete Block | 000G-1 Men's Custodial Toilet | 307 | SF | 6 | \$900 | |
| | Water Closet | 000G-1 Men's Custodial Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 0510-1 Men Staff | 155 | SF | 6 | \$1,430 | |
| | Ceiling - Plaster/Drywall | 0510-1 Men Staff | 155 | SF | 6 | \$536 | |
| | Doors - Steel Doors incl hw | 0510-1 Men Staff | 1 | EA | 6 | \$301 | |
| | Floor Drain | 0510-1 Men Staff | 2 | EA | 6 | \$2,118 | |
| | Floor - Tile Ceramic/ Porcelain | 0510-1 Men Staff | 155 | SF | 6 | \$328 | |
| | Hand Dryer | 0510-1 Men Staff | 1 | EA | 6 | \$230 | |
| | Lavatory | 0510-1 Men Staff | 2 | EA | 6 | \$639 | |
| | Lighting - Pendent/Surface | 0510-1 Men Staff | 3 | EA | 6 | \$372 | |
| | Partitions | 0510-1 Men Staff | 1 | EA | 6 | \$297 | |
| | Showers | 0510-1 Men Staff | 1 | EA | 6 | \$311 | |
| | Urinals | 0510-1 Men Staff | 1 | EA | 6 | \$336 | |
| | Walls - Concrete Block | 0510-1 Men Staff | 387 | SF | 6 | \$1,134 | |
| | Water Closet | 0510-1 Men Staff | 1 | EA | 6 | \$336 | |
| | Accessories | 0511 Men's Toilet | 265 | SF | 6 | \$2,444 | |
| | Ceiling - Plaster/Drywall | 0511 Men's Toilet | 265 | SF | 6 | \$917 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---------------------------------|--------------------------|----------|---------------|------|---------|----------|
| stroo | | 2004.1011 | Quantity | U iiit | rum | 0001 | |
| | Doors - Steel Doors incl hw | 0511 Men's Toilet | 1 | EA | 6 | \$301 | |
| | Floor - Tile Ceramic/ Porcelain | 0511 Men's Toilet | 265 | SF | 6 | \$561 | |
| | Lavatory | 0511 Men's Toilet | 2 | EA | 6 | \$639 | |
| | Lighting - Lay-in | 0511 Men's Toilet | 2 | EA | 7 | \$0 | |
| | Partitions | 0511 Men's Toilet | 2 | EA | 6 | \$594 | |
| | Urinals | 0511 Men's Toilet | 2 | EA | 6 | \$672 | |
| | Walls - Concrete Block | 0511 Men's Toilet | 662 | SF | 6 | \$1,941 | |
| | Walls - Tile Ceramic/ Porcelain | 0511 Men's Toilet | 50 | SF | 6 | \$113 | |
| | Water Closet | 0511 Men's Toilet | 2 | EA | 6 | \$672 | |
| | Accessories | 0521-1 Women Staff | 155 | SF | 6 | \$1,430 | |
| | Ceiling - Plaster/Drywall | 0521-1 Women Staff | 155 | SF | 6 | \$536 | |
| | Doors - Steel Doors incl hw | 0521-1 Women Staff | 1 | EA | 6 | \$301 | |
| | Floor Drain | 0521-1 Women Staff | 3 | EA | 6 | \$3,177 | |
| | Floor - Tile Ceramic/ Porcelain | 0521-1 Women Staff | 155 | SF | 6 | \$328 | |
| | Hand Dryer | 0521-1 Women Staff | 1 | EA | 6 | \$230 | |
| | Lavatory | 0521-1 Women Staff | 2 | EA | 7 | \$0 | Basin |
| | Lighting - Pendent/Surface | 0521-1 Women Staff | 3 | EA | 7 | \$0 | |
| | Partitions | 0521-1 Women Staff | 1 | EA | 6 | \$297 | |
| | Showers | 0521-1 Women Staff | 2 | EA | 6 | \$623 | |
| | Walls - Tile Ceramic/ Porcelain | 0521-1 Women Staff | 387 | SF | 6 | \$874 | |
| | Water Closet | 0521-1 Women Staff | 1 | EA | 6 | \$336 | |
| | Accessories | 101-1 Principal's Toilet | 25 | SF | 6 | \$231 | |
| | Ceiling - Plaster/Drywall | 101-1 Principal's Toilet | 25 | SF | 6 | \$87 | |
| | Doors - Steel Doors incl hw | 101-1 Principal's Toilet | 1 | EA | 6 | \$301 | |
| | Floor Drain | 101-1 Principal's Toilet | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile/Sheet | 101-1 Principal's Toilet | 25 | SF | 6 | \$25 | |
| | Lavatory | 101-1 Principal's Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | 101-1 Principal's Toilet | 1 | EA | 6 | \$124 | |
| | Walls - Metal Panel | 101-1 Principal's Toilet | 202 | SF | 6 | \$1,508 | |
| | Water Closet | 101-1 Principal's Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 109C Unisex Staff Toilet | 36 | SF | 6 | \$332 | |
| | Ceiling - Plaster/Drywall | 109C Unisex Staff Toilet | 36 | SF | 6 | \$125 | |
| | Doors - Steel Doors incl hw | 109C Unisex Staff Toilet | 1 | EA | 6 | \$301 | |
| | Floor Drain | 109C Unisex Staff Toilet | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | 109C Unisex Staff Toilet | 36 | SF | 6 | \$79 | |
| | Lavatory | 109C Unisex Staff Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | 109C Unisex Staff Toilet | 1 | EA | 6 | \$124 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|--------------------------------|----------|------|------|---------|-------------|
| strooi | n | | | | | | |
| | Walls - Concrete Block | 109C Unisex Staff Toilet | 196 | SF | 6 | \$575 | |
| | Water Closet | 109C Unisex Staff Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 1st floor women's at south end | 386 | SF | 6 | \$3,560 | |
| | Ceiling - Plaster/Drywall | 1st floor women's at south end | 386 | SF | 6 | \$1,336 | |
| | Floor - Terrazzo | 1st floor women's at south end | 386 | SF | 6 | \$845 | |
| | Lighting - Lay-in | 1st floor women's at south end | 9 | EA | 6 | \$1,071 | |
| | Walls - Concrete Block | 1st floor women's at south end | 630 | SF | 6 | \$2,117 | |
| | Walls - Concrete Block | 1st floor women's at south end | 630 | SF | 6 | \$2,117 | Brick walls |
| | Water Closet | 1st floor women's at south end | 8 | EA | 6 | \$2,688 | |
| | Accessories | 210A Womens Staff Toilet | 24 | SF | 6 | \$221 | |
| | Ceiling - Lay-in | 210A Womens Staff Toilet | 24 | SF | 6 | \$72 | |
| | Doors - Steel Doors incl hw | 210A Womens Staff Toilet | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | 210A Womens Staff Toilet | 24 | SF | 6 | \$53 | |
| | Lavatory | 210A Womens Staff Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | 210A Womens Staff Toilet | 1 | EA | 6 | \$124 | |
| | Walls - Metal Panel | 210A Womens Staff Toilet | 200 | SF | 6 | \$1,493 | |
| | Water Closet | 210A Womens Staff Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 211 Unisex Stafft Toilet | 24 | SF | 6 | \$221 | |
| | Benches | 211 Unisex Stafft Toilet | 6 | LF | 6 | \$87 | |
| | Ceiling - Lay-in | 211 Unisex Stafft Toilet | 24 | SF | 6 | \$72 | |
| | Doors - Steel Doors incl hw | 211 Unisex Stafft Toilet | 1 | EA | 6 | \$301 | |
| | Floor Drain | 211 Unisex Stafft Toilet | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | 211 Unisex Stafft Toilet | 24 | SF | 6 | \$53 | |
| | Hand Dryer | 211 Unisex Stafft Toilet | 1 | EA | 6 | \$230 | |
| | Lavatory | 211 Unisex Stafft Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | 211 Unisex Stafft Toilet | 1 | EA | 6 | \$124 | |
| | Walls - Metal Panel | 211 Unisex Stafft Toilet | 200 | SF | 6 | \$1,493 | |
| | Water Closet | 211 Unisex Stafft Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 243A Boys Toilet | 290 | SF | 6 | \$2,675 | |
| | Benches | 243A Boys Toilet | 6 | LF | 6 | \$87 | |
| | Ceiling - Plaster/Drywall | 243A Boys Toilet | 290 | SF | 6 | \$1,004 | |
| | Doors - Steel Doors incl hw | 243A Boys Toilet | 1 | EA | 6 | \$301 | |
| | Floor Drain | 243A Boys Toilet | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 243A Boys Toilet | 290 | SF | 6 | \$614 | |
| | Lavatory | 243A Boys Toilet | 6 | EA | 6 | \$1,918 | |
| | Lighting - Lay-in | 243A Boys Toilet | 9 | EA | 7 | \$0 | |
| | Partitions | 243A Boys Toilet | 5 | EA | 6 | \$1,485 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comment |
|--------|---------------------------------|---|----------|------|------|---------|---------|
| Restro | ** | | | | | - 5561 | 50 |
| - 3 3. | Student Lockers - Two Tiers | 243A Boys Toilet | 8 | EA | 6 | \$371 | |
| | Student Lockers - Two Tiers | 243A Boys Toilet | 30 | EA | 6 | \$1,393 | |
| | Urinals | 243A Boys Toilet | 5 | EA | 6 | \$1,680 | |
| | Walls - Plaster/Drywall | 243A Boys Toilet | 478 | SF | 6 | \$1,319 | |
| | Walls - Tile Ceramic/ Porcelain | 243A Boys Toilet | 239 | SF | 6 | \$540 | |
| | Water Closet | 243A Boys Toilet | 5 | EA | 6 | \$1,680 | |
| | Accessories | 243B Girls Toilet | 265 | SF | 6 | \$2,444 | |
| | Benches | 243B Girls Toilet | 6 | LF | 6 | \$87 | |
| | Ceiling - Plaster/Drywall | 243B Girls Toilet | 265 | SF | 6 | \$917 | |
| | Doors - Steel Doors incl hw | 243B Girls Toilet | 1 | EA | 6 | \$301 | |
| | Floor Drain | 243B Girls Toilet | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | 243B Girls Toilet | 265 | SF | 6 | \$580 | |
| | Lavatory | 243B Girls Toilet | 6 | EA | 6 | \$1,918 | |
| | Lighting - Lay-in | 243B Girls Toilet | 9 | EA | 7 | \$0 | |
| | Partitions | 243B Girls Toilet | 7 | EA | 6 | \$2,078 | |
| | Student Lockers - One Tier | 243B Girls Toilet | 8 | EA | 6 | \$743 | |
| | Student Lockers - Three Tiers | 243B Girls Toilet | 30 | EA | 6 | \$928 | |
| | Walls - Plaster/Drywall | 243B Girls Toilet | 478 | SF | 6 | \$1,319 | |
| | Walls - Tile Ceramic/ Porcelain | 243B Girls Toilet | 228 | SF | 6 | \$515 | |
| | Water Closet | 243B Girls Toilet | 9 | EA | 6 | \$3,024 | |
| | Accessories | 268A Womens Staff Toilet | 24 | SF | 6 | \$221 | |
| | Ceiling - Lay-in | 268A Womens Staff Toilet | 24 | SF | 6 | \$72 | |
| | Doors - Steel Doors incl hw | 268A Womens Staff Toilet | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | 268A Womens Staff Toilet | 24 | SF | 6 | \$53 | |
| | Lavatory | 268A Womens Staff Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | 268A Womens Staff Toilet | 1 | EA | 6 | \$124 | |
| | Walls - Plaster/Drywall | 268A Womens Staff Toilet | 200 | SF | 6 | \$552 | |
| | Water Closet | 268A Womens Staff Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 269A Staff Mens Toilet | 24 | SF | 6 | \$221 | |
| | Ceiling - Lay-in | 269A Staff Mens Toilet | 24 | SF | 6 | \$72 | |
| | Doors - Steel Doors incl hw | 269A Staff Mens Toilet | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | 269A Staff Mens Toilet | 24 | SF | 6 | \$53 | |
| | Lavatory | 269A Staff Mens Toilet | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | 269A Staff Mens Toilet | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 269A Staff Mens Toilet | 200 | SF | 6 | \$552 | |
| | Water Closet | 269A Staff Mens Toilet | 1 | EA | 6 | \$336 | |
| | Accessories | 2nd floor staff men's in boys across from 209 | 26 | SF | 6 | \$240 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|-----------------------------|---|----------|------|------|---------|----------|
| stroo | m | | | | | | |
| | Ceiling - Plaster/Drywall | 2nd floor staff men's in boys across from 209 | 26 | SF | 6 | \$90 | |
| | Doors - Steel Doors incl hw | 2nd floor staff men's in boys across from 209 | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | 2nd floor staff men's in boys across from 209 | 26 | SF | 6 | \$57 | |
| | Lavatory | 2nd floor staff men's in boys across from 209 | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 2nd floor staff men's in boys across from 209 | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 2nd floor staff men's in boys across from 209 | 131 | SF | 6 | \$384 | |
| | Water Closet | 2nd floor staff men's in boys across from 209 | 1 | EA | 6 | \$336 | |
| | Accessories | 301A Boys Toilet | 290 | SF | 6 | \$2,675 | |
| | Ceiling - Plaster/Drywall | 301A Boys Toilet | 221 | SF | 6 | \$765 | |
| | Floor Drain | 301A Boys Toilet | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | 301A Boys Toilet | 253 | SF | 6 | \$554 | |
| | Lavatory | 301A Boys Toilet | 5 | EA | 6 | \$1,598 | |
| | Lighting - Lay-in | 301A Boys Toilet | 6 | EA | 7 | \$0 | |
| | Partitions | 301A Boys Toilet | 2 | EA | 6 | \$594 | |
| | Urinals | 301A Boys Toilet | 4 | EA | 6 | \$1,344 | |
| | Walls - Concrete Block | 301A Boys Toilet | 723 | SF | 6 | \$2,119 | |
| | Water Closet | 301A Boys Toilet | 2 | EA | 6 | \$672 | |
| | Accessories | 301B Girls Toilet | 265 | SF | 6 | \$2,444 | |
| | Ceiling - Plaster/Drywall | 301B Girls Toilet | 265 | SF | 6 | \$917 | |
| | Floor Drain | 301B Girls Toilet | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | 301B Girls Toilet | 265 | SF | 6 | \$580 | |
| | Lavatory | 301B Girls Toilet | 5 | EA | 6 | \$1,598 | |
| | Lighting - Lay-in | 301B Girls Toilet | 9 | EA | 7 | \$0 | |
| | Partitions | 301B Girls Toilet | 4 | EA | 6 | \$1,188 | |
| | Walls - Concrete Block | 301B Girls Toilet | 392 | SF | 6 | \$1,149 | |
| | Walls - Masonry | 301B Girls Toilet | 228 | SF | 6 | \$717 | Brick |
| | Water Closet | 301B Girls Toilet | 5 | EA | 6 | \$1,680 | |
| | Accessories | Basement inside engineer's office | 72 | SF | 6 | \$664 | |
| | Ceiling - Plaster/Drywall | Basement inside engineer's office | 72 | SF | 6 | \$249 | |
| | Doors - Wood Doors inclu hw | Basement inside engineer's office | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | Basement inside engineer's office | 72 | SF | 6 | \$158 | |
| | Lavatory | Basement inside engineer's office | 1 | EΑ | 6 | \$320 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|----------------------------|-----------------------------------|----------|------|------|---------|--|
| Restro | om | | | | | | |
| | Lighting - Pendent/Surface | Basement inside engineer's office | 1 | EA | 7 | \$0 | |
| | Partitions | Basement inside engineer's office | 2 | EA | 6 | \$594 | |
| | Showers | Basement inside engineer's office | 1 | EA | 6 | \$311 | w/terrazzo basin |
| | Walls - Concrete Block | Basement inside engineer's office | 274 | SF | 6 | \$803 | |
| | Water Closet | Basement inside engineer's office | 1 | EA | 6 | \$336 | |
| | Accessories | Boys restroom across from 172 | 290 | SF | 6 | \$2,675 | |
| | Ceiling - Plaster/Drywall | Boys restroom across from 172 | 221 | SF | 6 | \$765 | |
| | Ceiling - Plaster/Drywall | Boys restroom across from 172 | 32 | SF | 4 | \$562 | Water stains, cracking Damaged drywall |
| | Floor Drain | Boys restroom across from 172 | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | Boys restroom across from 172 | 253 | SF | 6 | \$554 | |
| | Lavatory | Boys restroom across from 172 | 2 | EA | 6 | \$639 | |
| | Lighting - Lay-in | Boys restroom across from 172 | 6 | EA | 7 | \$0 | |
| | Partitions | Boys restroom across from 172 | 2 | EA | 6 | \$594 | |
| | Urinals | Boys restroom across from 172 | 3 | EA | 6 | \$1,008 | |
| | Walls - Concrete Block | Boys restroom across from 172 | 484 | SF | 6 | \$1,419 | |
| | Walls - Concrete Block | Boys restroom across from 172 | 239 | SF | 6 | \$803 | Brick |
| | Water Closet | Boys restroom across from 172 | 2 | EA | 6 | \$672 | |
| | Accessories | Boys restroom across from 274 | 290 | SF | 6 | \$2,675 | |
| | Ceiling - Plaster/Drywall | Boys restroom across from 274 | 290 | SF | 6 | \$1,004 | |
| | Floor Drain | Boys restroom across from 274 | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | Boys restroom across from 274 | 290 | SF | 6 | \$634 | |
| | Lavatory | Boys restroom across from 274 | 3 | EA | 6 | \$959 | |
| | Lighting - Lay-in | Boys restroom across from 274 | 6 | EA | 7 | \$0 | |
| | Partitions | Boys restroom across from 274 | 2 | EA | 6 | \$594 | |
| | Urinals | Boys restroom across from 274 | 2 | EA | 6 | \$672 | |
| | Walls - Concrete Block | Boys restroom across from 274 | 386 | SF | 6 | \$1,132 | |
| | Walls - Masonry | Boys restroom across from 274 | 239 | SF | 6 | \$752 | Brick |
| | Water Closet | Boys restroom across from 274 | 2 | EA | 6 | \$672 | |
| | Accessories | Boys restroom across from rm 204 | 290 | SF | 6 | \$2,675 | |
| | Ceiling - Plaster/Drywall | Boys restroom across from rm 204 | 290 | SF | 6 | \$1,004 | |
| | Floor Drain | Boys restroom across from rm 204 | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | Boys restroom across from rm 204 | 290 | SF | 6 | \$634 | |
| | Lavatory | Boys restroom across from rm 204 | 3 | EA | 6 | \$959 | |
| | Lighting - Lay-in | Boys restroom across from rm 204 | 7 | EA | 7 | \$0 | |
| | Partitions | Boys restroom across from rm 204 | 2 | EA | 6 | \$594 | |
| | Urinals | Boys restroom across from rm 204 | 4 | EA | 6 | \$1,344 | |
| | Walls - Concrete Block | Boys restroom across from rm 204 | 398 | SF | 6 | \$1,167 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| up Item - Type troom | Location | Quantity | | | | |
|-----------------------------|-----------------------------------|----------|----|---|---------|----------|
| | | | | | | Comments |
| Walls - Masonry | Boys restroom across from rm 204 | 239 | SF | 6 | \$752 | Brick |
| Water Closet | Boys restroom across from rm 204 | 2 | EA | 6 | \$672 | Briok |
| Accessories | Boy's restroom near rm 124 | 406 | SF | 6 | \$3,745 | |
| Ceiling - Plaster/Drywall | Boy's restroom near rm 124 | 406 | SF | 6 | \$1,405 | |
| Doors - Steel Doors incl hw | Boy's restroom near rm 124 | 1 | EA | 6 | \$301 | |
| Floor Drain | Boy's restroom near rm 124 | 1 | EA | 6 | \$1,059 | |
| Floor - Terrazzo | Boy's restroom near rm 124 | 406 | SF | 6 | \$888 | |
| Lighting - Lay-in | Boy's restroom near rm 124 | 9 | EA | 7 | \$0 | |
| Partitions | Boy's restroom near rm 124 | 3 | EA | 6 | \$891 | |
| Urinals | Boy's restroom near rm 124 | 6 | EA | 6 | \$2,016 | |
| Walls - Concrete Block | · · | 581 | SF | 6 | \$1,703 | |
| | Boy's restroom near rm 124 | 720 | SF | 6 | | Brick |
| Walls - Masonry | Boy's restroom near rm 124 | | EA | | | BIICK |
| Water Closet | Boy's restroom near rm 124 | 3 | | 6 | \$1,008 | |
| Accessories | Boys rm across from 109 | 265 | SF | 6 | \$2,444 | |
| Ceiling - Plaster/Drywall | Boys rm across from 109 | 265 | SF | 6 | \$917 | |
| Floor - Terrazzo | Boys rm across from 109 | 265 | SF | 6 | \$580 | |
| Lavatory | Boys rm across from 109 | 3 | EA | 6 | \$959 | |
| Lighting - Lay-in | Boys rm across from 109 | 7 | EA | 7 | \$0 | |
| Partitions | Boys rm across from 109 | 2 | EA | 6 | \$594 | |
| Urinals | Boys rm across from 109 | 4 | EA | 6 | \$1,344 | |
| Walls - Concrete Block | Boys rm across from 109 | 328 | SF | 6 | \$962 | |
| Walls - Masonry | Boys rm across from 109 | 305 | SF | 6 | \$960 | Brick |
| Water Closet | Boys rm across from 109 | 2 | EA | 6 | \$672 | |
| Accessories | Girls restroom across from 171 | 265 | SF | 6 | \$2,444 | |
| Ceiling - Plaster/Drywall | Girls restroom across from 171 | 265 | SF | 6 | \$917 | |
| Floor Drain | Girls restroom across from 171 | 1 | EA | 6 | \$1,059 | |
| Floor - Terrazzo | Girls restroom across from 171 | 265 | SF | 6 | \$580 | |
| Lavatory | Girls restroom across from 171 | 3 | EA | 6 | \$959 | |
| Lighting - Lay-in | Girls restroom across from 171 | 6 | EA | 7 | \$0 | |
| Partitions | Girls restroom across from 171 | 4 | EA | 6 | \$1,188 | |
| Walls - Concrete Block | Girls restroom across from 171 | 228 | SF | 6 | \$766 | Brick |
| Walls - Concrete Block | Girls restroom across from 171 | 498 | SF | 6 | \$1,460 | |
| Water Closet | Girls restroom across from 171 | 5 | EA | 6 | \$1,680 | |
| Accessories | Girls restroom across from rm 288 | 265 | SF | 6 | \$2,444 | |
| Ceiling - Plaster/Drywall | Girls restroom across from rm 288 | 265 | SF | 6 | \$917 | |
| Floor Drain | Girls restroom across from rm 288 | 1 | EA | 6 | \$1,059 | |
| Floor - Terrazzo | Girls restroom across from rm 288 | 265 | SF | 6 | \$580 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|---|------------|-------|--------|----------------|----------|
| Restroc | • | | - additity | J.III | . will | 0031 | |
| | Lavatory | Girls restroom across from rm 288 | 3 | EA | 6 | \$959 | |
| | Lighting - Lay-in | Girls restroom across from rm 288 | 9 | EA | 7 | \$0 | |
| | Partitions | Girls restroom across from rm 288 | 4 | EA | 6 | \$1,188 | |
| | Walls - Concrete Block | Girls restroom across from rm 288 | 392 | SF | 6 | \$1,149 | |
| | Walls - Masonry | Girls restroom across from rm 288 | 228 | SF | 6 | | Brick |
| | Water Closet | Girls restroom across from rm 288 | 5 | EA | 6 | \$1,680 | Briok |
| | Accessories | Girls restroom next to 144 | 385 | SF | 6 | \$3,551 | |
| | Ceiling - Plaster/Drywall | Girls restroom next to 144 | 385 | SF | 6 | \$1,332 | |
| | Doors - Steel Doors incl hw | Girls restroom next to 144 | 1 | EA | 6 | \$301 | |
| | Floor Drain | Girls restroom next to 144 | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | Girls restroom next to 144 | 385 | SF | 6 | \$842 | |
| | Lavatory | Girls restroom next to 144 | 4 | EA | 6 | \$1,278 | |
| | Lighting - Lay-in | Girls restroom next to 144 | 9 | EA | 7 | \$1,278 | |
| | Partitions | Girls restroom next to 144 | 6 | EA | 6 | \$1,782 | |
| | Walls - Concrete Block | Girls restroom next to 144 | 565 | SF | 6 | \$1,762 | |
| | Walls - Masonry | Girls restroom next to 144 | 510 | SF | 6 | | Priok |
| | Water Closet | Girls restroom next to 144 | 7 | EA | 6 | \$1,604 | DIICK |
| | | | | | | \$2,352 | |
| | Accessories | In boys restroom near rm 124 | 29 | SF | 6 | \$267 | |
| | Ceiling - Plaster/Drywall | In boys restroom near rm 124 | 29 | SF | 6 | \$100 \$204 | |
| | Doors - Steel Doors incl hw | In boys restroom near rm 124 | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | In boys restroom near rm 124 | 29 | SF | 6 | \$63 | |
| | Lavatory | In boys restroom near rm 124 | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | In boys restroom near rm 124 | 7 | EA | 7 | \$0 | |
| | Walls - Concrete Block | In boys restroom near rm 124 | 186 | SF | 6 | \$545 | |
| | Water Closet | In boys restroom near rm 124 | 1 | EA | 6 | \$336 | |
| | Accessories | Men's staff restroom in boys rm across 275 | 26 | SF | 6 | \$240 | |
| | Ceiling - Plaster/Drywall | Men's staff restroom in boys rm across 275 | 26 | SF | 6 | \$90 | |
| | Doors - Steel Doors incl hw | Men's staff restroom in boys rm across 275 | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | Men's staff restroom in boys rm across 275 | 26 | SF | 6 | \$57 | |
| | Lavatory | Men's staff restroom in boys rm across 275 | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | Men's staff restroom in boys rm across 275 | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Men's staff restroom in boys rm across 275 | 131 | SF | 6 | \$384 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | l Ini# | Pank | Cost | Comments |
|--------|-----------------------------|--|-----------|--------|-------|---------|-----------------|
| - | • • | Location | Qualitity | Uill | Nailk | CUST | Comments |
| Restro | Water Closet | Men's staff restroom in boys rm across 275 | 1 | EA | 6 | \$336 | |
| | Accessories | Unisex staff toilet across from 171 | 36 | SF | 6 | \$332 | |
| | Ceiling - Plaster/Drywall | Unisex staff toilet across from 171 | 36 | SF | 6 | \$125 | |
| | Doors - Steel Doors incl hw | Unisex staff toilet across from 171 | 1 | EA | 6 | \$301 | |
| | Floor Drain | Unisex staff toilet across from 171 | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | Unisex staff toilet across from 171 | 36 | SF | 6 | \$79 | |
| | Hand Dryer | Unisex staff toilet across from 171 | 1 | EA | 6 | \$230 | |
| | Lavatory | Unisex staff toilet across from 171 | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | Unisex staff toilet across from 171 | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Unisex staff toilet across from 171 | 196 | SF | 6 | \$575 | |
| | Water Closet | Unisex staff toilet across from 171 | 1 | EA | 5 | \$1,344 | Not operational |
| | Accessories | Womens staff restroom across from 288 | 26 | SF | 6 | \$240 | |
| | Ceiling - Plaster/Drywall | Womens staff restroom across from 288 | 26 | SF | 6 | \$90 | |
| | Doors - Steel Doors incl hw | Womens staff restroom across from 288 | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | Womens staff restroom across from 288 | 26 | SF | 6 | \$57 | |
| | Lavatory | Womens staff restroom across from 288 | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | Womens staff restroom across from 288 | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Womens staff restroom across from 288 | 131 | SF | 6 | \$384 | |
| | Water Closet | Womens staff restroom across from 288 | 1 | EA | 6 | \$336 | |
| | Accessories | Womens staff restroom in girls rm | 95 | SF | 6 | \$876 | |
| | Accessories | Womens staff restroom in girls rm across fro 204 | 26 | SF | 6 | \$240 | |
| | Ceiling - Plaster/Drywall | Womens staff restroom in girls rm across fro 204 | 26 | SF | 6 | \$90 | |
| | Doors - Steel Doors incl hw | Womens staff restroom in girls rm across fro 204 | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | Womens staff restroom in girls rm across fro 204 | 26 | SF | 6 | \$57 | |
| | Lavatory | Womens staff restroom in girls rm across fro 204 | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | Womens staff restroom in girls rm across fro 204 | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Womens staff restroom in girls rm across fro 204 | 131 | SF | 6 | \$384 | |
| | Water Closet | Womens staff restroom in girls rm across fro 204 | 1 | EA | 6 | \$336 | |
| | Ceiling - Lay-in | Womens staff restroom in girls rm | 95 | SF | 6 | \$285 | |
| | Doors - Steel Doors incl hw | Womens staff restroom in girls rm | 1 | EA | 6 | \$301 | |
| | Floor Drain | Womens staff restroom in girls rm | 1 | EA | 6 | \$1,059 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|---|----------|------|------|---------|----------|
| Restro | om | | | | | | |
| | Floor - Terrazzo | Womens staff restroom in girls rm | 95 | SF | 6 | \$208 | |
| | Hand Dryer | Womens staff restroom in girls rm | 1 | EA | 6 | \$230 | |
| | Lavatory | Womens staff restroom in girls rm | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | Womens staff restroom in girls rm | 3 | EA | 7 | \$0 | |
| | Accessories | Womens staff restroom in girls rm next to 144 | 27 | SF | 6 | \$249 | |
| | Ceiling - Plaster/Drywall | Womens staff restroom in girls rm next to 144 | 27 | SF | 6 | \$93 | |
| | Doors - Steel Doors incl hw | Womens staff restroom in girls rm next to 144 | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | Womens staff restroom in girls rm next to 144 | 27 | SF | 6 | \$59 | |
| | Lavatory | Womens staff restroom in girls rm next to 144 | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | Womens staff restroom in girls rm next to 144 | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Womens staff restroom in girls rm next to 144 | 177 | SF | 6 | \$519 | |
| | Water Closet | Womens staff restroom in girls rm next to 144 | 1 | EA | 6 | \$336 | |
| | Walls - Concrete Block | Womens staff restroom in girls rm | 362 | SF | 6 | \$1,061 | |
| | Water Closet | Womens staff restroom in girls rm | 1 | EA | 6 | \$336 | |
| | | | | | | | |

Rooms (Other Than Classrooms) Subtotal:

\$2,004,999

Building: Main

| oup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|-----------|----------|------|------|-----------|------------|
| orridor | | | | | | |
| Ceiling - Lay-in | 1st Floor | 27,106 | SF | 6 | \$81,399 | |
| Doors - Steel Doors incl hw | 1st Floor | 22 | EA | 6 | \$6,622 | |
| Doors - Store Front | 1st Floor | 16 | EA | 6 | \$19,331 | |
| Doors - Transom Window | 1st Floor | 7,016 | EA | 6 | \$118,789 | |
| Drinking Fountains - Double Fountain | 1st Floor | 5 | EA | 6 | \$1,680 | |
| Drinking Fountains - Single Fountain | 1st Floor | 2 | EA | 6 | \$551 | |
| Floor - Terrazzo | 1st Floor | 27,106 | SF | 6 | \$227,530 | |
| Lighting - Lay-in | 1st Floor | 411 | EA | 7 | \$0 | |
| Lighting - Lay-in | 1st Floor | 416 | EA | 4 | \$139,714 | Can lights |
| Walls - Concrete Block | 1st Floor | 32,527 | SF | 6 | \$95,353 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|--------------------------------|--------------|----------|--------|---------------------|--|
| Corrido | • • | 2004.0.1 | quantity | 01111 | rtum | 0001 | |
| | Walls - Metal Panel | 1st Floor | 46,008 | SF | 6 | \$343,431 | |
| | Walls - Plaster/Drywall | 1st Floor | 24,398 | SF | 6 | \$108,156 | |
| | Ceiling - Lay-in | 2nd Floor | 9,306 | SF | 6 | \$27,946 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 10 | EA | 6 | \$3,010 | |
| | Doors - Store Front | 2nd Floor | 16 | EA | 6 | \$19,331 | |
| | Doors - Transom Window | 2nd Floor | 880 | EA | 6 | \$14,899 | |
| | Drinking Fountains - Double Fountain | 2nd Floor | 5 | EA | 6 | \$1,680 | |
| | Floor - Tile/Sheet | 2nd Floor | 9,306 | SF | 6 | \$5,057 | |
| | Lighting - Chandelier, Incandescent | 2nd Floor | 27 | EΑ | 6 | | Can lights |
| | Lighting - Lay-in | 2nd Floor | 407 | EA | 7 | \$0 | 3 |
| | Student Lockers - One Tier | 2nd Floor | 504 | EA | 6 | \$46,789 | |
| | Student Lockers - Two Tiers | 2nd Floor | 359 | EA | 6 | \$16,664 | |
| | Walls - Concrete Block | 2nd Floor | 24,395 | SF | 6 | \$71,514 | |
| | Walls - Metal Panel | 2nd Floor | 46,080 | SF | 6 | \$343,969 | |
| | Walls - Plaster/Drywall | 2nd Floor | 35,237 | SF | 6 | \$156,206 | |
| 0.4. | , | | | | | | |
| Safety | | = | | | | ^ | |
| | Camera Viewing Station | 1st Floor | 4 | EA | 6 | \$2,730 | Camera viewing for main building and annex. Main office, Engineers office, Principals office, Security office. |
| | Metal Dedector | 1st Floor | 2 | EA | 6 | \$1.761 | Entrance 7 |
| | Security Cameras | 1st Floor / Entire Building | 2 | EA | 6 | \$388 | 2-underground loading dock area |
| | Security Cameras | 1st Floor / Entire Building | 11 | EA | 6 | \$2,134 | 3 3 |
| | • | ű | | | | , , | |
| Stairs | 0 | 0.1.1.1.1 | | | | | |
| | Ceiling - Plaster/Drywall | Stairwell # 1 | 650 | SF | 6 | \$4,759 | |
| | Floor - Terrazzo | Stairwell # 1 | 240 | SF | 7 | \$0 | |
| | Handrails | Stairwell # 1 | 52 | LF | 6 | \$451 | |
| | Lighting - Chandelier, Incandescent | Stairwell # 1 | 8 | EA | 7 | \$0 \$0 | |
| | Stairs - Terrazzo | Stairwell # 1 Stairwell # 1 | 26 | LF | 7 | \$0 | Deiels Force |
| | Walls - Masonry | | 1,625 | SF SF | 6 | | Brick Face |
| | Ceiling - Plaster/Drywall | Stairwell # 2 | 1,765 | _ | 6 | \$12,923 | |
| | Floor - Terrazzo | Stairwell # 2 | 412 | SF | 6 | \$3,458 | |
| | Handrails | Stairwell # 2 Stairwell # 2 | 78 | LF | 6 | \$676 | |
| | Lighting - Chandelier, Incandescent | | 16 | EA | 7 | \$0 \$0 | |
| | Stairs - Terrazzo | Stairwell # 2 | 312 | LF | 7 | \$0 | |
| | Walls - Masonry | Stairwell # 2 Stairwell # 3 | 780 1.765 | SF SF | 6 | \$2,454 \$12,923 | |
| | Ceiling - Plaster/Drywall | | 1,765 | SF | 6 7 | \$12,923 | |
| | Floor - Terrazzo | Stairwell # 3 | 412 | SF | 1 | \$0 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

| Handrails Stairwell # 3 79 LF 6 \$976 Lighting - Chandelier, Incandescent Stairwell # 3 16 EA 6 \$7,641 Sheirs - Terrazzo Sheirwell # 3 16 EA 6 \$7,641 Sheirs - Terrazzo Sheirwell # 3 780 LF 7 \$0 Walls - Masonny Stairwell # 4 420 SF 6 \$24,54 Brick Face Stairwell # 4 420 SF 6 \$24,54 Brick Face Stairwell # 4 420 SF 6 \$26,25 Floor - Terrazzo Stairwell # 4 440 LF 6 \$1,248 Lighting - Linyin Stairwell # 4 440 LF 6 \$1,248 Lighting - Linyin Stairwell # 4 4 4 4 4 4 4 4 4 4 | Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|---------|---------------------------------------|---------------|----------|------|------|----------|------------|
| Lighting - Chandelleri, Incandescent Stairwell # 3 16 EA 6 \$7,641 Stairs - Terrazzo Stairwell # 3 312 LF 7 50 Wallis - Masonny Stairwell # 4 420 SF 6 \$2,245 Brick Face Stairwell # 4 420 SF 6 \$2,245 Floor - Terrazzo Stairwell # 4 420 SF 6 \$2,245 Lighting - Lay-in Stairwell # 4 420 SF 6 \$3,248 Lighting - Lay-in Stairwell # 4 44 LF 6 \$1,248 Lighting - Lay-in Stairwell # 4 44 LF 6 \$1,248 Lighting - Lay-in Stairwell # 4 420 SF 6 \$6,95 Salirs - Terrazzo Stairwell # 4 2,128 SF 6 \$6,95 Celling - Exposed Stairwell # 5 420 SF 6 \$6,95 Floor - Terrazzo Stairwell # 5 420 SF 6 \$6,95 Floor - Terrazzo Stairwell # 5 420 SF 6 \$6,95 Floor - Terrazzo Stairwell # 5 420 SF 6 \$6,95 Lighting - Lay-in Stairwell # 5 144 LF 6 \$1,248 Lighting - Lay-in Stairwell # 5 14 EA 7 \$0 Wallis - Masonny Stairwell # 6 7 5 6 \$6,95 Celling - Plaster/Dywall Stairwell # 6 7 5 6 \$6,95 Celling - Plaster/Dywall Stairwell # 6 7 5 6 \$6,95 Celling - Plaster/Dywall Stairwell # 6 7 5 6 \$6,95 Celling - Plaster/Dywall Stairwell # 6 7 5 6 \$6,95 Celling - Plaster/Dywall Stairwell # 6 7 5 6 \$6,95 Celling - Plaster/Dywall Stairwell # 6 7 5 6 \$6,95 Celling - Plaster/Dywall Stairwell # 7 7 7 5 Lighting - Chandeller, Incandescent Stairwell # 7 7 7 5 Lighting - Chandeller, Incandescent Stairwell # 7 7 7 7 7 7 Lighting - Chandeller, Incandescent Stairwell # 7 7 7 7 7 7 7 Lighting - Chandeller, Incandescent Stairwell # 8 7 7 7 7 7 7 7 7 7 | Stairs | | | | | | | |
| Stairs - Terrazzo | | Handrails | Stairwell # 3 | 78 | LF | 6 | \$676 | |
| Walls - Maconny | | Lighting - Chandelier, Incandescent | Stairwell # 3 | 16 | EΑ | 6 | \$7,641 | |
| Ceiling - Exposed Stairwell # 4 | | Stairs - Terrazzo | Stairwell # 3 | 312 | LF | 7 | \$0 | |
| Floor - Terrazzo | | Walls - Masonry | Stairwell # 3 | 780 | SF | 6 | \$2,454 | Brick Face |
| Handrails Stairwell #4 144 LF 6 \$ \$1,248 Lighting - Lay-in Stairwell #4 14 LF 7 \$0 Stairs - Terrazzo Stairwell #4 72 LF 7 \$0 Walls - Masonry Stairwell #4 2,128 SF 6 \$6,695 Ceiling - Exposed Stairwell #5 420 SF 6 \$6,695 Ceiling - Exposed Stairwell #5 420 SF 6 \$6,695 Ceiling - Exposed Stairwell #5 420 SF 6 \$6,695 Floor - Terrazzo Stairwell #6 144 LF 6 \$1,248 Lighting - Lay-in Stairwell #6 144 LF 6 \$1,248 Lighting - Lay-in Stairwell #6 144 LF 6 \$1,248 Lighting - Lay-in Stairwell #6 144 LF 7 \$0 Walls - Masonry Stairwell #6 2,128 SF 6 \$6,695 Ceiling - Plaster/Dywell Stairwell #6 2,128 SF 6 \$6,695 Ceiling - Plaster/Dywell Stairwell #6 78 LF 6 \$676 Lighting - Chandelier, Incandescent Stairwell #6 78 LF 6 \$676 Stairs - Terrazzo Stairwell #6 78 LF 6 \$676 Stairs - Terrazzo Stairwell #6 78 LF 6 \$676 Stairs - Terrazzo Stairwell #6 78 LF 6 \$676 Stairs - Terrazzo Stairwell #6 78 LF 6 \$676 Stairs - Terrazzo Stairwell #7 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell #7 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell #7 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell #7 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell #7 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell #7 1,765 SF 6 \$2,454 Ceiling - Plaster/Dywall Stairwell #7 1,765 SF 6 \$2,454 Ceiling - Plaster/Dywall Stairwell #7 1,765 SF 6 \$2,454 Ceiling - Exposed Stairwell #7 1,760 SF 6 \$2,454 Ceiling - Exposed Stairwell #7 1,760 SF 6 \$2,454 Ceiling - Exposed Stairwell #8 936 SF 7 \$0 Stairwell #8 936 SF 7 \$0 Handrails Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF 7 \$0 Walls - Masonry Stairwell #8 936 SF | | Ceiling - Exposed | Stairwell # 4 | 420 | SF | 6 | \$625 | |
| Lighting - Lay-in Stairs - Terrazzo Stairwell # 4 14 EA 7 \$0 Stairs - Terrazzo Stairwell # 4 72 LF 7 \$0 Celling - Exposed Celling - Exposed Stairwell # 5 420 SF 6 \$6.695 Floor - Terrazzo Stairwell # 5 420 SF 6 \$6.25 Floor - Terrazzo Stairwell # 5 140 Lighting - Lay-in Stairwell # 5 144 Lighting - Lay-in Stairwell # 5 7 2 LF 7 \$0 Walls - Masonry Stairwell # 5 7 2 LF 7 \$0 Walls - Masonry Stairwell # 5 7 2 LF 7 \$0 Walls - Masonry Stairwell # 6 1,765 SF 6 \$6.895 Celling - Plester/Drywell Stairwell # 6 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell # 6 1,765 SF 7 \$0 Handralls Stairwell # 6 1,765 SF 7 \$0 Handralls Stairwell # 6 1,765 SF 7 \$0 Walls - Masonry Stairwell # 6 1,765 SF 7 \$0 Handralls Stairwell # 6 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell # 6 1,765 SF 6 \$2,454 Celling - Plester/Drywall Stairwell # 7 1,765 SF 6 \$1,923 Floor - Terrazzo Stairwell # 7 1,765 SF 6 \$1,923 Floor - Terrazzo Stairwell # 7 1,765 SF 6 \$2,454 Celling - Exposed Stairwell # 7 1,765 SF 6 \$2,454 Celling - Exposed Stairwell # 7 1,765 SF 6 \$2,454 Celling - Exposed Stairwell # 8 420 SF 6 \$6.25 Floor - Terrazzo Stairwell # 8 92 LF 7 \$0 Handralls Stairwell # 8 92 Lighting - Lay-in Stairs - Terrazzo Stairwell # 8 92 Lighting - Lay-in Stairs - Terrazzo Stairwell # 8 92 Lighting - Lay-in Stairs - Terrazzo Stairwell # 8 92 Lighting - Lay-in | | Floor - Terrazzo | Stairwell # 4 | 235 | SF | 7 | \$0 | |
| Stairs - Terrazzo | | Handrails | Stairwell # 4 | 144 | LF | 6 | \$1,248 | |
| Walls - Masonry | | Lighting - Lay-in | Stairwell # 4 | 14 | EΑ | 7 | \$0 | |
| Ceiling - Exposed | | Stairs - Terrazzo | Stairwell # 4 | 72 | LF | 7 | \$0 | |
| Floor - Terrazzo | | Walls - Masonry | Stairwell # 4 | 2,128 | SF | 6 | \$6,695 | |
| Handrails | | Ceiling - Exposed | Stairwell # 5 | 420 | SF | 6 | \$625 | |
| Lighting - Lay-in | | Floor - Terrazzo | Stairwell # 5 | 235 | SF | 7 | \$0 | |
| Stairs - Terrazzo | | Handrails | Stairwell # 5 | 144 | LF | 6 | \$1,248 | |
| Walls - Masonry Stairwell # 5 2,128 SF 6 \$6,695 Ceiling - Plaster/Drywall Stairwell # 6 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell # 6 412 SF 7 \$0 Handrails Stairwell # 6 16 EA 7 \$0 Lighting - Chandelier, Incandescent Stairwell # 6 312 LF 7 \$0 Stairs - Terrazzo Stairwell # 6 78 SF 6 \$2,454 Ceiling - Plaster/Drywall Stairwell # 7 1,765 SF 6 \$2,454 Ceiling - Plaster/Drywall Stairwell # 7 412 SF 7 \$0 Handrails Stairwell # 7 412 SF 7 \$0 Handrails Stairwell # 7 16 EA 7 \$0 Stairs - Terrazzo Stairwell # 7 780 SF 6 \$2,454 Ceiling - Exposed Stairwell # 8 420 SF 6 \$62,454 <td< td=""><td></td><td>Lighting - Lay-in</td><td>Stairwell # 5</td><td>14</td><td>EA</td><td>7</td><td>\$0</td><td></td></td<> | | Lighting - Lay-in | Stairwell # 5 | 14 | EA | 7 | \$0 | |
| Ceiling - Plaster/Drywall Stairwell # 6 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell # 6 412 SF 7 \$0 Handrails Stairwell # 6 78 LF 6 \$676 Lighting - Chandelier, Incandescent Stairwell # 6 16 EA 7 \$0 Stairs - Terrazzo Stairwell # 6 312 LF 7 \$0 Walls - Masonry Stairwell # 6 780 SF 6 \$2,454 Ceiling - Plaster/Drywall Stairwell # 7 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell # 7 412 SF 6 \$2,454 Ceiling - Plaster/Drywall Stairwell # 7 412 SF 7 \$0 Handrails Stairwell # 7 412 SF 7 \$0 Handrails Stairwell # 7 16 EA 7 \$0 Stairs - Terrazzo Stairwell # 7 780 SF 6 \$2,454 Ceiling - Exposed Stairwell # 8 420 SF 6 \$625 Floor - Terrazzo Stairwell # 8 | | Stairs - Terrazzo | Stairwell # 5 | 72 | LF | 7 | \$0 | |
| Floor - Terrazzo | | Walls - Masonry | Stairwell # 5 | 2,128 | SF | 6 | \$6,695 | |
| Handrails | | Ceiling - Plaster/Drywall | Stairwell # 6 | 1,765 | SF | 6 | \$12,923 | |
| Lighting - Chandelier, Incandescent Stairwell # 6 16 EA 7 \$0 Stairs - Terrazzo Stairwell # 6 312 LF 7 \$0 Walls - Masonry Stairwell # 6 780 SF 6 \$2,454 Ceiling - Plaster/Drywall Stairwell # 7 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell # 7 412 SF 7 \$0 Handrails Stairwell # 7 16 EA 7 \$0 Lighting - Chandelier, Incandescent Stairwell # 7 16 EA 7 \$0 Stairs - Terrazzo Stairwell # 7 312 LF 7 \$0 Walls - Masonry Stairwell # 8 420 SF 6 \$2,454 Ceiling - Exposed Stairwell # 8 420 SF 6 \$625 Floor - Terrazzo Stairwell # 8 936 SF 7 \$0 Handrails Stairwell # 8 92 LF 6 \$797 Lighting - Lay-in Stairwell # 8 46 LF 7 \$0 | | Floor - Terrazzo | Stairwell # 6 | 412 | SF | 7 | \$0 | |
| Stairs - Terrazzo Stairwell # 6 312 LF 7 \$0 Walls - Masonry Stairwell # 6 780 SF 6 \$2,454 Ceiling - Plaster/Drywall Stairwell # 7 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell # 7 412 SF 7 \$0 Handrails Stairwell # 7 78 LF 6 \$676 Lighting - Chandelier, Incandescent Stairwell # 7 16 EA 7 \$0 Stairs - Terrazzo Stairwell # 7 312 LF 7 \$0 Stairs - Masonry Stairwell # 7 780 SF 6 \$2,454 Ceiling - Exposed Stairwell # 8 420 SF 6 \$625 Floor - Terrazzo Stairwell # 8 936 SF 7 \$0 Handrails Stairwell # 8 92 LF 6 \$797 Lighting - Lay-in Stairwell # 8 46 LF 7 \$0 Stairwell # 8 | | Handrails | Stairwell # 6 | 78 | LF | 6 | \$676 | |
| Walls - Masonry Stainwell # 6 780 SF 6 \$2,454 Ceiling - Plaster/Drywall Stainwell # 7 1,765 SF 6 \$12,923 Floor - Terrazzo Stainwell # 7 412 SF 7 \$0 Handrails Stainwell # 7 78 LF 6 \$676 Lighting - Chandelier, Incandescent Stainwell # 7 16 EA 7 \$0 Stairs - Terrazzo Stainwell # 7 312 LF 7 \$0 Walls - Masonry Stainwell # 7 780 SF 6 \$2,454 Ceiling - Exposed Stainwell # 8 420 SF 6 \$625 Floor - Terrazzo Stainwell # 8 936 SF 7 \$0 Handrails Stainwell # 8 92 LF 6 \$797 Lighting - Lay-in Stainwell # 8 46 LF 7 \$0 Stairs - Terrazzo Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 | | Lighting - Chandelier, Incandescent | Stairwell # 6 | 16 | EA | 7 | \$0 | |
| Ceiling - Plaster/Drywall Stairwell # 7 1,765 SF 6 \$12,923 Floor - Terrazzo Stairwell # 7 412 SF 7 \$0 Handrails Stairwell # 7 78 LF 6 \$676 Lighting - Chandelier, Incandescent Stairwell # 7 16 EA 7 \$0 Stairs - Terrazzo Stairwell # 7 780 SF 6 \$2,454 Walls - Masonry Stairwell # 8 420 SF 6 \$625 Floor - Terrazzo Stairwell # 8 936 SF 7 \$0 Handrails Stairwell # 8 92 LF 6 \$797 Lighting - Lay-in Stairwell # 8 6 EA 7 \$0 Stairs - Terrazzo Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 ***Protical Conveyance | | Stairs - Terrazzo | Stairwell # 6 | 312 | LF | 7 | \$0 | |
| Floor - Terrazzo | | Walls - Masonry | Stairwell # 6 | 780 | SF | 6 | \$2,454 | |
| Handrails Stairwell # 7 78 | | Ceiling - Plaster/Drywall | Stairwell # 7 | 1,765 | SF | 6 | \$12,923 | |
| Lighting - Chandelier, Incandescent Stairwell # 7 16 EA 7 \$0 Stairs - Terrazzo Stairwell # 7 312 LF 7 \$0 Walls - Masonry Stairwell # 7 780 SF 6 \$2,454 Ceiling - Exposed Stairwell # 8 420 SF 6 \$625 Floor - Terrazzo Stairwell # 8 936 SF 7 \$0 Handrails Stairwell # 8 92 LF 6 \$797 Lighting - Lay-in Stairwell # 8 6 EA 7 \$0 Stairs - Terrazzo Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 | | Floor - Terrazzo | Stairwell # 7 | 412 | SF | 7 | \$0 | |
| Stairs - Terrazzo Stairwell # 7 312 LF 7 \$0 Walls - Masonry Stairwell # 7 780 SF 6 \$2,454 Ceiling - Exposed Stairwell # 8 420 SF 6 \$625 Floor - Terrazzo Stairwell # 8 936 SF 7 \$0 Handrails Stairwell # 8 92 LF 6 \$797 Lighting - Lay-in Stairwell # 8 6 EA 7 \$0 Stairs - Terrazzo Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 | | Handrails | Stairwell # 7 | 78 | LF | 6 | \$676 | |
| Walls - Masonry Stairwell # 7 780 SF 6 \$2,454 Ceiling - Exposed Stairwell # 8 420 SF 6 \$625 Floor - Terrazzo Stairwell # 8 936 SF 7 \$0 Handrails Stairwell # 8 92 LF 6 \$797 Lighting - Lay-in Stairwell # 8 6 EA 7 \$0 Stairs - Terrazzo Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 | | Lighting - Chandelier, Incandescent | Stairwell # 7 | 16 | EA | 7 | \$0 | |
| Ceiling - Exposed Stairwell # 8 420 SF 6 \$625 Floor - Terrazzo Stairwell # 8 936 SF 7 \$0 Handrails Stairwell # 8 92 LF 6 \$797 Lighting - Lay-in Stairwell # 8 6 EA 7 \$0 Stairs - Terrazzo Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 | | Stairs - Terrazzo | Stairwell # 7 | 312 | LF | 7 | \$0 | |
| Floor - Terrazzo Stairwell # 8 936 SF 7 \$0 Handrails Stairwell # 8 92 LF 6 \$797 Lighting - Lay-in Stairwell # 8 6 EA 7 \$0 Stairs - Terrazzo Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 Vertical Conveyance | | Walls - Masonry | Stairwell # 7 | 780 | SF | 6 | \$2,454 | |
| Handrails Stairwell # 8 92 LF 6 \$797 Lighting - Lay-in Stairwell # 8 6 EA 7 \$0 Stairs - Terrazzo Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 /ertical Conveyance | | Ceiling - Exposed | Stairwell # 8 | 420 | SF | 6 | \$625 | |
| Lighting - Lay-in Stairwell # 8 6 EA 7 \$0 Stairs - Terrazzo Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 Vertical Conveyance | | Floor - Terrazzo | Stairwell # 8 | 936 | SF | 7 | \$0 | |
| Stairs - Terrazzo Stairwell # 8 46 LF 7 \$0 Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 /ertical Conveyance | | Handrails | Stairwell # 8 | 92 | LF | 6 | \$797 | |
| Walls - Masonry Stairwell # 8 1,040 SF 6 \$3,272 /ertical Conveyance | | Lighting - Lay-in | Stairwell # 8 | 6 | EA | 7 | \$0 | |
| /ertical Conveyance | | Stairs - Terrazzo | Stairwell # 8 | 46 | LF | 7 | \$0 | |
| · | | Walls - Masonry | Stairwell # 8 | 1,040 | SF | 6 | \$3,272 | |
| · | Vertica | Conveyance | | | | | | |
| | | · · · · · · · · · · · · · · · · · · · | 1st Floor | 2 | EA | 6 | \$38,476 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Main

Category: Building Interior

Group Item - Type Location Quantity Unit Rank Cost Comments

Building Interior Subtotal: \$2,015,465

Total Building Cost \$10,227,944

Building: Linked Addition-Main Athletic

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|---|----------|------|------|---------|---|
| Entrand | ce | | | | | | |
| | Entrance Control - Audio and Video | Entrance 21-North | 1 | EA | 6 | \$702 | |
| | Entrance Control - Audio | Entrance 21-North | 1 | EA | 5 | \$994 | Not being used |
| | Exterior Doors - Exterior FRP Door | Entrance 17-East | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | Entrance 18-NE | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior FRP Door | Entrance 21-North | 2 | EA | 6 | \$1,263 | |
| | Exterior Doors - Exterior Steel Door | Entrance 23-East - Sloped driveway down to loading dock | 1 | EA | 6 | \$481 | |
| | Exterior Doors - Exterior Steel Door | Exit 19-NE - Gym | 4 | EA | 5 | \$5,365 | dented |
| | Exterior Doors - Exterior Steel Door | Exit 20-NE - Gym | 4 | EA | 5 | \$5,365 | dented |
| | Exterior Doors - Side lite | Entrance 17-East | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 21-North | 4 | EA | 6 | \$1,253 | |
| | Exterior Doors - Side lite | Entrance 23-East - Sloped driveway down to loading dock | 1 | EA | 5 | \$476 | Rusted, peeling, bent at bottom of lite |
| | Exterior Doors - Transom Lite | Entrance 17-East | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 18-NE | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Entrance 21-North | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Transom Lite | Entrance 23-East - Sloped driveway down to loading dock | 1 | EA | 6 | \$313 | |
| | Exterior Doors - Transom Lite | Exit 19-NE - Gym | 1 | EA | 5 | \$822 | dented |
| | Exterior Doors - Transom Lite | Exit 20-NE - Gym | 1 | EA | 5 | \$822 | dented |
| | Exterior Stairs - Concrete | Exit 19-NE - Gym | 12 | LF | 6 | \$981 | |
| | Exterior Stairs - Concrete | Exit 20-NE - Gym | 12 | LF | 5 | \$1,315 | spalling |
| Founda | tion | | | | | | |
| | Foundation - Concrete | Entire Building | 945 | LF | 7 | \$0 | |
| | Superstructure - Steel | Entire Building | 54,301 | SF | 7 | \$0 | |
| Lightin | g | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 4 | EA | 5 | \$1,710 | |
| | Exterior Lighting - Wall Mounted | Entire Building | 4 | EA | 6 | \$1,155 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Linked Addition-Main Athletic

Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|-----------------|----------|------|------|-----------|--|
| Roof Sy | ystem | | | | | | |
| | Coping - Metal | Roof 2 | 800 | LF | 6 | \$25,694 | |
| | Coping - Metal | Roof 3 | 145 | LF | 6 | \$4,657 | |
| | Downspouts - Interior Downspouts | Roof 2 | 240 | LF | 6 | \$7,976 | |
| | Downspouts - Interior Downspouts | Roof 3 | 45 | LF | 6 | \$1,495 | |
| | Parapet - Parapet < 16" Height | Roof 2 | 800 | LF | 6 | \$17,046 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof 2 | 40,000 | SF | 7 | \$0 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof 3 | 2,020 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | Roof 2 | 37,000 | SF | 6 | \$348,148 | |
| | Roof - Modified Bitumen | Roof 2 | 3,000 | SF | 5 | \$74,217 | Majority of sloped areas around roof drains blistering, bubbling, worn out with small open joints throughout |
| | Roof - Modified Bitumen | Roof 3 | 2,020 | SF | 6 | \$19,007 | |
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 15,340 | SF | 6 | \$103,100 | |
| Windov | vs | | | | | | |
| | Curtain wall - Glazed Double Pane | Entire Building | 35 | SF | 5 | \$0 | Cracked, bullet holes |
| | Curtain wall - Glazed Double Pane | Entire Building | 8,335 | SF | 6 | \$93,445 | |
| | Curtain wall - Glazed Single Pane | Entire Building | 1,500 | SF | 6 | \$16,817 | |

Building Exterior Subtotal:

\$739,024

Building: Linked Addition-Main Athletic

Category: Electrical System

| ding 4,503 20,250 11,723 | SF | 6 6 6 | \$1,352 \$7,529 | ATS 3,4 Generator powered |
|--------------------------------|-----------------|-------------|--|--|
| ding 4,503 20,250 11,723 | SF SF | 6 | \$1,352 \$7,529 | , |
| 20,250 11,723 | SF | 6 | \$7,529 | Generator powered |
| 11,723 | | | ' ' | Generator powered |
| , - | SF | 6 | 04050 | |
| | | J | \$4,359 | |
| 262 | SF | 6 | \$97 | |
| 6 | EA | 6 | \$1,215 | |
| 1 | EA | 7 | \$0 | Also Serves Main |
| ding 3 | EA | 7 | \$0 | |
| 6 | EA | 7 | \$0 | |
| 6 | EA | 4 | \$3,407 | Broken also parts missing |
| 54,301 | SF | 6 | \$16,307 | |
| (| 6 1 dding 3 6 6 | 1 EA | 6 EA 6 1 EA 7 dding 3 EA 7 6 EA 7 6 EA 4 | 6 EA 6 \$1,215 1 EA 7 \$0 dding 3 EA 7 \$0 6 EA 7 \$0 6 EA 4 \$3,407 |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Linked Addition-Main Athletic

Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------------|----------|------|------|----------|---------------------------|
| Emerge | ency System | | | | | | |
| | Security System - Intrusion Detection | Entire Building | 54,301 | SF | 6 | \$13,977 | |
| Main Se | arvice | | | | | | |
| mum o | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | \$2,921 | |
| | Main Electrical Service - 1200 A 120/208/3PH | Electrical Room | . 1 | EA | 7 | \$0 | |
| | Main Electrical Service - 2000 A 277/480/3PH | Electrical Room | 1 | EA | 7 | \$0 | |
| | PA System | Entire Building | 54,301 | SF | 6 | \$17,860 | Served from main building |
| Power I | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Electrical Room | 3 | EA | 7 | \$0 | Emergency fuse type |
| | Lighting and Power Panels - 100 A | Electrical Room | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - 100 A | Electrical Room | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - 100 A | Electrical Room | 3 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Electrical Room | 1 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Electrical Room | 1 | EA | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Electrical Room | 1 | EA | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Electrical Room | 2 | EA | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Electrical Room | 2 | EA | 7 | \$0 | |
| | Main Distribution Panels - Greater than 600 amp | Electrical Room | 1 | EA | 7 | \$0 | |
| | Transformers - 277/480 - 120/208 | Electrical Room | 1 | EA | 6 | \$1,265 | |
| | Transformers - 277/480 - 120/208 | Electrical Room | 1 | EA | 6 | \$1,265 | |
| | Transformers - 277/480 - 120/208 | Electrical Room | 1 | EA | 6 | \$1,265 | |

Electrical System Subtotal: \$73,634

Building: Linked Addition-Main Athletic

Category: Safty System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost Comments | |
|--------------------------|-----------------------------------|----------|------|------|---------------|--|
| Fire Alarm | | | | | | |
| Fire Alarm Panel | Electrical Room | 1 | EA | 6 | \$6,406 | |
| Fire Alarm Strobe Lights | Electrical Room / Entire Building | 54,301 | SF | 6 | \$19,413 | |
| Fire Alarm_System | Electrical Room / Entire Building | 54,301 | SF | 6 | \$26,401 | |
| | | | | | | |

Safty System Subtotal: \$52,220

Building: Linked Addition-Main Athletic

Category: Mechanical System



821 E 103rd St Chicago, IL 60628

| | | | | | | Co-locating on | this campus are CORLISS HS and NOBLE - BUTLER HS |
|----------|--|--|----------|------|------|----------------|--|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Air Han | dling Systems | | | | | | |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 21 - 30 tons | Roof | 1 | EA | 6 | \$2,792 | Serves Hallways |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Greater than 45 tons | Roof | 1 | EA | 7 | \$0 | Serves Locker rooms |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Greater than 45 tons | Roof | 1 | EA | 6 | \$2,792 | Serves both Gym's |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - Greater than 45 tons | Roof | 1 | EA | 6 | \$2,792 | Serves Boy's Gym |
| Heating | Devices | | | | | | |
| | Cabinet Heaters - With Electric Coil | Entire Building | 2 | EA | 6 | \$713 | |
| | Duct Heater - Electric | Mechanical Building/Central Plant / Mechanical Room | 1 | | 7 | \$0 | |
| | Fin Tube - Electric | Entire Building | 110 | LF | 6 | \$1,038 | |
| | Unit Heater - Electric | Mechanical Room | 1 | EA | 6 | \$278 | |
| | Unit Heater - Gas | Mechanical Room | 1 | EA | 6 | \$278 | |
| Temper | ature Control | | | | | | |
| | Pneumatic System | Entire Building | 54,301 | SF | 5 | \$187,138 | Leaks air, not sealed. In operation |
| | Thermostats - Pneumatic | Entire Building | 5 | EA | 6 | \$0 | Serves RTU's |
| Ventilat | ion | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof | 3 | EA | 7 | \$0 | Serves RTU's |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Roof | 1 | EΑ | 7 | \$0 | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Roof | 1 | EΑ | 7 | \$0 | |
| | Roof Mounted Duct Work | Roof | 60 | LF | 6 | \$22,741 | Minor rusting on top of RTU's |
| | Roof Mounted Duct Work | Roof | 30 | LF | 7 | \$0 | Serves RTU25 (1) Locker rooms |
| Mecha | anical System Subtotal: | | | | | \$220,561 | |

Building: Linked Addition-Main Athletic

Category: Plumbing System

| | 3 - 7 | | | | | |
|--------|--|-----------------|----------|------|------|---------------|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost Comments |
| Hot Wa | ter | | | | | |
| | Gas Heater - 300001 - 600000 BTU/HR | Mechanical Room | 3 | EA | 7 | \$0 |
| | Hot Water Storage Tank_Gas - 201 - 500 Gallons | Mechanical Room | 3 | EA | 7 | \$0 |
| Piping | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 54,301 | SF | 6 | \$10,871 |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 54,301 | SF | 6 | \$13,201 |
| | Domestic Piping-Cold Water Risers | Entire Building | 54,301 | SF | 6 | \$10,095 |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 54,301 | SF | 6 | \$8,542 |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 54,301 | SF | 6 | \$10,095 |
| | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Linked Addition-Main Athletic

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|-----------------|----------|------|------|----------|---------------------------|
| Piping | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 54,301 | SF | 6 | \$7,765 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 54,301 | SF | 6 | \$7,765 | |
| | Sanitary Piping | Entire Building | 54,301 | SF | 6 | \$49,696 | |
| | Storm Piping | Entire Building | 54,301 | SF | 6 | \$47,367 | |
| | Vent Piping | Entire Building | 54,301 | SF | 6 | \$36,496 | |
| Pool Sy | rstems | | | | | | |
| | Pool Drain Piping | Mechanical Room | 75 | LF | 6 | \$2,147 | Not in service since 2000 |
| | Pool Filtration System including Pump | Mechanical Room | 1 | EA | 5 | \$19,025 | Not in service since 2000 |
| | Pool Hot Water Heater - Gas Fired | Mechanical Room | 1 | EA | 5 | \$2,924 | Not in service since 2000 |
| | Pool Supply and Return Piping | Mechanical Room | 150 | LF | 6 | \$7,207 | Not in service since 2000 |
| Pumps | | | | | | | |
| | Pumps - Ejector-Duplex | Mechanical Room | 1 | EA | 6 | \$1,387 | |
| | Pumps - Sump-Duplex | Mechanical Room | 1 | EA | 6 | \$1,387 | |

Plumbing System Subtotal:

\$235,969

Building: Linked Addition-Main Athletic

Category: Classrooms

| p Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---|-----------|----------|------|------|---------|----------|
| sroom #1-615 (Weight) | | | | | | |
| Ceiling - Splined | 1st Floor | 858 | SF | 6 | \$699 | |
| Doors - Side-lite | 1st Floor | 3 | SF | 6 | \$50 | |
| Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | 1st Floor | 858 | SF | 6 | \$1,877 | |
| Lighting - Metal Halide/ High Pressure Sodium | 1st Floor | 6 | EA | 7 | \$0 | |
| Marker Board | 1st Floor | 15 | LF | 7 | \$0 | |
| Walls - Concrete Block | 1st Floor | 2,481 | SF | 6 | \$7,273 | |
| sroom #1-618 (Vacant) | | | | | | |
| Ceiling - Splined | 1st Floor | 858 | SF | 6 | \$699 | |
| Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| Floor - Tile | 1st Floor | 858 | SF | 6 | \$1,877 | |
| Lighting - Metal Halide/ High Pressure Sodium | 1st Floor | 6 | EA | 7 | \$0 | |
| Marker Board | 1st Floor | 15 | LF | 7 | \$0 | |
| Walls - Concrete Block | 1st Floor | 2,481 | SF | 6 | \$7,273 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Linked Addition-Main Athletic

Category: Classrooms

Group Item - Type Location Quantity Unit Rank Cost Comments

Classrooms Subtotal: \$20,351

Building: Linked Addition-Main Athletic

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|--------------------------------|----------|------|------|---------|-------------------|
| Adminis | strative Suites/Offices | | | | | | |
| | Ceiling - Splined | 605 office in gym | 110 | SF | 6 | \$90 | |
| | Doors - Side-lite | 605 office in gym | 10 | SF | 6 | \$167 | |
| | Doors - Steel Doors incl hw | 605 office in gym | 1 | EA | 6 | \$301 | w/full glass lite |
| | Floor - Tile | 605 office in gym | 110 | SF | 6 | \$241 | |
| | Lighting - Lay-in | 605 office in gym | 2 | EA | 7 | \$0 | |
| | Power Distribution | 605 office in gym | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 605 office in gym | 299 | SF | 6 | \$877 | |
| | Ceiling - Splined | 607 office in gym | 110 | SF | 6 | \$90 | |
| | Doors - Side-lite | 607 office in gym | 10 | SF | 6 | \$167 | |
| | Doors - Steel Doors incl hw | 607 office in gym | 1 | EA | 6 | \$301 | w/full glass lite |
| | Floor - Tile | 607 office in gym | 110 | SF | 6 | \$241 | |
| | Lighting - Pendent/Surface | 607 office in gym | 2 | EA | 7 | \$0 | |
| | Power Distribution | 607 office in gym | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 607 office in gym | 299 | SF | 6 | \$877 | |
| | Ceiling - Splined | 608 office in gym | 110 | SF | 6 | \$90 | |
| | Doors - Side-lite | 608 office in gym | 10 | SF | 6 | \$167 | |
| | Doors - Steel Doors incl hw | 608 office in gym | 1 | EA | 6 | \$301 | w/glass lite |
| | Floor - Tile | 608 office in gym | 110 | SF | 6 | \$241 | |
| | Lighting - Pendent/Surface | 608 office in gym | 2 | EA | 7 | \$0 | |
| | Power Distribution | 608 office in gym | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 608 office in gym | 299 | SF | 6 | \$877 | |
| | Ceiling - Plaster/Drywall | 614 office in pool area | 81 | SF | 6 | \$280 | |
| | Doors - Side-lite | 614 office in pool area | 10 | SF | 6 | \$167 | |
| | Doors - Store Front | 614 office in pool area | 1 | EA | 6 | \$1,208 | |
| | Floor - Tile Ceramic/ Porcelain | 614 office in pool area | 81 | SF | 6 | \$171 | |
| | Lighting - Lay-in | 614 office in pool area | 2 | EA | 7 | \$0 | |
| | Power Distribution | 614 office in pool area | 4 | EA | 7 | \$0 | |
| | Walls - Masonry | 614 office in pool area | 249 | SF | 6 | \$783 | Brick |
| | Ceiling - Plaster/Drywall | At entrance 18 Across from gym | 392 | SF | 6 | \$1,357 | |
| | Doors - Steel Doors incl hw | At entrance 18 Across from gym | 1 | EA | 6 | \$301 | |
| | Floor - Tile | At entrance 18 Across from gym | 392 | SF | 6 | \$858 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Linked Addition-Main Athletic

| p Item - Type |) | Location | Quantity | Unit | Rank | Cost | Comments |
|-------------------|------------------------------------|--|----------|------|------|-----------|-------------------|
| inistrative Suite | es/Offices | | | | | | |
| Lighting - L | ay-in | At entrance 18 Across from gym | 10 | EA | 7 | \$0 | |
| Power Distr | ribution | At entrance 18 Across from gym | 10 | EA | 7 | \$0 | |
| Walls - Con | ncrete Block | At entrance 18 Across from gym | 579 | SF | 6 | \$1,697 | |
| Walls - Plas | ster/Drywall | At entrance 18 Across from gym | 104 | SF | 6 | \$287 | |
| nasia | | | | | | | |
| Bleacher Se | eating | 1st Floor | 1,184 | EA | 6 | \$34,269 | |
| Ceiling - Ex | xposed | 1st Floor | 20,250 | SF | 6 | \$30,116 | |
| Doors - Stee | el Doors incl hw | 1st Floor | 6 | EA | 6 | \$1,806 | w/full glass lite |
| Doors - Trai | nsom Window | 1st Floor | 3,410 | SF | 6 | \$57,735 | |
| Floor - Woo | od | 1st Floor | 20,250 | SF | 6 | \$142,760 | |
| Lighting - M | Metal Halide/ High Pressure Sodium | 1st Floor | 128 | EA | 7 | \$0 | |
| Scoreboard | s | 1st Floor | 2 | EA | 6 | \$4,489 | |
| Sound Syste | em | 1st Floor | 1 | EA | 6 | \$41,654 | |
| Walls - Con | ncrete Block | 1st Floor | 13,672 | SF | 6 | \$40,079 | |
| er/Shower Roo | om | | | | | | |
| Accessories | S | Girls locker/shower rm, outside rm 1-618 | 184 | SF | 6 | \$721 | |
| Benches, pe | ed mounted | Girls locker/shower rm, outside rm 1-618 | 4 | LF | 6 | \$436 | |
| Ceiling - Pla | aster/ Drywall | Girls locker/shower rm, outside rm 1-618 | 184 | SF | 6 | \$637 | |
| Doors - Stee | el Doors incl hw | Girls locker/shower rm, outside rm 1-618 | 1 | EA | 6 | \$301 | |
| Floor Drain | | Girls locker/shower rm, outside rm 1-618 | 2 | EA | 6 | \$2,118 | |
| Floor - Tile (| Ceramic/ Porcelain | Girls locker/shower rm, outside rm 1-618 | 184 | SF | 6 | \$389 | |
| Lavatory | | Girls locker/shower rm, outside rm 1-618 | 1 | EA | 6 | \$320 | |
| Lighting - L | .ay-in | Girls locker/shower rm, outside rm 1-618 | 6 | EA | 7 | \$0 | |
| Partitions | | Girls locker/shower rm, outside rm 1-618 | 2 | EA | 6 | \$594 | |
| Showers | | Girls locker/shower rm, outside rm 1-618 | 1 | EA | 6 | \$311 | |
| Student Loc | ckers - One Tier | Girls locker/shower rm, outside rm 1-618 | 14 | EA | 6 | \$1,300 | |
| Walls - Cor | ncrete Block | Girls locker/shower rm, outside rm 1-618 | 456 | SF | 6 | \$1,337 | |
| Walls - Tile | e Ceramic/ Porcelain | Girls locker/shower rm, outside rm 1-618 | 27 | SF | 6 | \$61 | |
| Water Close | et | Girls locker/shower rm, outside rm 1-618 | 2 | EA | 6 | \$672 | |
| Accessories | S | Unisex locker/shower rm at door 18 | 220 | SF | 6 | \$862 | |
| Benches, pe | ed mounted | Unisex locker/shower rm at door 18 | 4 | LF | 6 | \$436 | |
| Ceiling - Pla | aster/ Drywall | Unisex locker/shower rm at door 18 | 220 | SF | 6 | \$761 | |
| Doors - Stee | el Doors incl hw | Unisex locker/shower rm at door 18 | 1 | EA | 6 | \$301 | |
| Floor Drain | | Unisex locker/shower rm at door 18 | 2 | EA | 6 | \$2,118 | |
| Floor - Tile (| Ceramic/ Porcelain | Unisex locker/shower rm at door 18 | 220 | SF | 6 | \$466 | |
| Lighting - L | _ay-in | Unisex locker/shower rm at door 18 | 6 | EA | 7 | \$0 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Linked Addition-Main Athletic

| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|------------------------------------|----------|------|------|-----------|---------------------------------------|
| cker/s | Shower Room | | | | | | |
| | Student Lockers - One Tier | Unisex locker/shower rm at door 18 | 4 | EA | 6 | \$371 | All ADA labeled lockers |
| | Walls - Tile Ceramic/ Porcelain | Unisex locker/shower rm at door 18 | 687 | SF | 6 | \$1,552 | |
| chan | ical/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 46 | SF | 6 | \$330 | between boys and girls restrooms |
| | Mechanical/ Service Rooms | 1st Floor | 29 | SF | 6 | \$208 | Electrical closet at rm 1-618 |
| | Mechanical/ Service Rooms | 1st Floor | 35 | SF | 6 | \$251 | Electrical closet at classroom 1-615 |
| | Storage Room | 1st Floor | 136 | SF | 6 | \$974 | Storage in gym |
| | Storage Room | 1st Floor | 44 | SF | 6 | \$315 | Between boys and girls restrooms |
| | Storage Room | 1st Floor | 100 | SF | 6 | \$716 | |
| | Storage Room | 1st Floor | 238 | SF | 6 | \$1,705 | Storage in gym |
| | Storage Room | 1st Floor | 148 | SF | 6 | \$1,060 | Storage rm in gym |
| | Interior Stairs | 2nd Floor | 43 | LF | 6 | \$388 | Concrete stairs in pool balcony |
| | Mechanical/ Service Rooms | 2nd Floor | 197 | SF | 6 | \$1,411 | Balcony electrical closet |
| | Storage Room | 2nd Floor | 109 | SF | 6 | \$781 | Balcony storage rm |
| | Boiler Room | Basement | 2,130 | SF | 6 | \$15,260 | 504 Storage |
| | Interior Stairs | Basement | 12 | LF | 7 | \$0 | Up to locker room from boiler room |
| | Mechanical/ Service Rooms | Basement | 345 | SF | 6 | \$2,472 | 505 Electrical room |
| | Mechanical/ Service Rooms | Basement | 160 | SF | 6 | \$1,146 | 507 Gas meter room |
| ol & N | Natatorium | | | | | | |
| | Accessories | 1st Floor | 11,623 | SF | 6 | \$7,978 | |
| | Bleachers Seating/Plank Seating | 1st Floor | 16 | EΑ | 6 | \$463 | |
| | Ceiling - Splined (Moister Resistance) | 1st Floor | 10,872 | SF | 6 | \$11,349 | |
| | Ceiling - Splined (Moister Resistance) | 1st Floor | 200 | SF | 5 | \$2,508 | Missing/damaged tiles in balcony area |
| | Ceiling - Splined (Moister Resistance) | 1st Floor | 200 | SF | 5 | \$2,508 | Water damage South west corner |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EΑ | 6 | \$1,204 | |
| | Doors - Transom Window | 1st Floor | 1,612 | SF | 6 | \$27,293 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 2,510 | SF | 6 | \$5,312 | |
| | Lighting - Lay-in | 1st Floor | 21 | EA | 7 | \$0 | |
| | Lighting - Metal Halide/ High Pressure Sodium | 1st Floor | 32 | EA | 7 | \$0 | |
| | Pool Basin | 1st Floor | 4,556 | SF | 6 | \$154,147 | |
| | Pool Deck | 1st Floor | 2,814 | SF | 6 | \$26,719 | |
| | Pool Deck Drains | 1st Floor | 36 | EA | 6 | \$15,194 | |
| | Storage/ Closet | 1st Floor | 29 | SF | 6 | \$210 | |
| | Walls - Masonry | 1st Floor | 6,405 | SF | 6 | \$20,150 | |
| stroo | om | | | | | | |
| | Accessories | Boys restroom across from gym | 131 | SF | 6 | \$1,208 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Linked Addition-Main Athletic

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|--------------------------------|----------|------|------|---------|---------------------------|
| Restroc | om | | | | | | |
| | Ceiling - Plaster/Drywall | Boys restroom across from gym | 131 | SF | 6 | \$453 | |
| | Doors - Steel Doors incl hw | Boys restroom across from gym | 2 | EA | 6 | \$602 | |
| | Floor Drain | Boys restroom across from gym | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | Boys restroom across from gym | 131 | SF | 6 | \$287 | |
| | Lavatory | Boys restroom across from gym | 2 | EA | 6 | \$639 | |
| | Lighting - Lay-in | Boys restroom across from gym | 3 | EA | 7 | \$0 | |
| | Partitions | Boys restroom across from gym | 1 | EA | 6 | \$297 | |
| | Partitions | Boys restroom across from gym | 1 | EA | 5 | \$751 | HC Stall door broken/bent |
| | Urinals | Boys restroom across from gym | 2 | EA | 6 | \$672 | |
| | Walls - Concrete Block | Boys restroom across from gym | 374 | SF | 6 | \$1,096 | |
| | Walls - Masonry | Boys restroom across from gym | 103 | SF | 6 | \$324 | Brick |
| | Water Closet | Boys restroom across from gym | 2 | EΑ | 6 | \$672 | |
| | Accessories | Girls restroom across from gym | 131 | SF | 6 | \$1,208 | |
| | Ceiling - Plaster/Drywall | Girls restroom across from gym | 1 | SF | 6 | \$3 | |
| | Doors - Steel Doors incl hw | Girls restroom across from gym | 2 | EΑ | 6 | \$602 | |
| | Floor Drain | Girls restroom across from gym | 1 | EA | 6 | \$1,059 | |
| | Floor - Terrazzo | Girls restroom across from gym | 131 | SF | 6 | \$287 | |
| | Lavatory | Girls restroom across from gym | 3 | EA | 6 | \$959 | |
| | Lighting - Lay-in | Girls restroom across from gym | 3 | EA | 7 | \$0 | |
| | Partitions | Girls restroom across from gym | 2 | EA | 6 | \$594 | |
| | Walls - Concrete Block | Girls restroom across from gym | 374 | SF | 6 | \$1,096 | |
| | Walls - Masonry | Girls restroom across from gym | 103 | SF | 6 | \$324 | Brick |
| | Water Closet | Girls restroom across from gym | 3 | EA | 6 | \$1,008 | |
| | Accessories | In 605 office | 20 | SF | 6 | \$184 | |
| | Ceiling - Splined | In 605 office | 20 | SF | 6 | \$16 | |
| | Doors - Steel Doors incl hw | In 605 office | 1 | EΑ | 6 | \$301 | |
| | Floor - Terrazzo | In 605 office | 20 | SF | 6 | \$44 | |
| | Lavatory | In 605 office | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | In 605 office | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | In 605 office | 156 | SF | 6 | \$457 | |
| | Water Closet | In 605 office | 1 | EA | 6 | \$336 | |
| | Accessories | In 607 office | 20 | SF | 6 | \$184 | |
| | Ceiling - Splined | In 607 office | 20 | SF | 6 | \$16 | |
| | Doors - Steel Doors incl hw | In 607 office | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | In 607 office | 20 | SF | 6 | \$44 | |
| | Lavatory | In 607 office | 1 | EA | 6 | \$320 | |
| | | | | | | | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Linked Addition-Main Athletic

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost (| Comments |
|--------|-----------------------------|--|----------|------|------|-----------------|----------|
| Restro | om | | | | | | |
| | Walls - Concrete Block | In 607 office | 156 | SF | 6 | \$457 | |
| | Water Closet | In 607 office | 1 | EA | 6 | \$336 | |
| | Accessories | In 608 office | 20 | SF | 6 | \$184 | |
| | Ceiling - Splined | In 608 office | 20 | SF | 6 | \$16 | |
| | Doors - Steel Doors incl hw | In 608 office | 1 | EA | 6 | \$301 | |
| | Floor - Terrazzo | In 608 office | 20 | SF | 6 | \$44 | |
| | Lavatory | In 608 office | 1 | EA | 6 | \$320 | |
| | Lighting - Wall Mounted | In 608 office | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | In 608 office | 156 | SF | 6 | \$457 | |
| | Water Closet | In 608 office | 1 | EA | 6 | \$336 | |
| | Accessories | Unisex staff restroom next to elevator | 107 | SF | 6 | \$987 | |
| | Ceiling - Plaster/Drywall | Unisex staff restroom next to elevator | 107 | SF | 6 | \$370 | |
| | Doors - Steel Doors incl hw | Unisex staff restroom next to elevator | 1 | EA | 6 | \$301 | |
| | Floor Drain | Unisex staff restroom next to elevator | 1 | EΑ | 6 | \$1,059 | |
| | Floor - Terrazzo | Unisex staff restroom next to elevator | 107 | SF | 6 | \$234 | |
| | Lavatory | Unisex staff restroom next to elevator | 1 | EA | 6 | \$320 | |
| | Lighting - Pendent/Surface | Unisex staff restroom next to elevator | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Unisex staff restroom next to elevator | 354 | SF | 6 | \$1,038 | |
| | Water Closet | Unisex staff restroom next to elevator | 1 | EA | 6 | \$336 | |
| | /0:1 =1 | | | | | A-0- 000 | |

Rooms (Other Than Classrooms) Subtotal:

\$707,983

Building: Linked Addition-Main Athletic

| up Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------------|-----------|----------|------|------|-----------|--|
| ridor | | | | | | |
| Ceiling - Plaster/Drywall | 1st Floor | 1,109 | SF | 6 | \$6,867 | |
| Ceiling - Splined | 1st Floor | 74 | SF | 5 | \$715 | |
| Ceiling - Splined | 1st Floor | 1,700 | SF | 6 | \$4,911 | |
| Doors - Steel Doors incl hw | 1st Floor | 8 | EA | 6 | \$2,408 | |
| Doors - Store Front | 1st Floor | 2 | EA | 6 | \$2,416 | |
| Doors - Transom Window | 1st Floor | 450 | EA | 6 | \$7,619 | |
| Drinking Fountains - Double Fountain | 1st Floor | 1 | EA | 6 | \$336 | |
| Drinking Fountains - Single Fountain | 1st Floor | 1 | EA | 6 | \$276 | |
| Floor - Terrazzo | 1st Floor | 4,089 | SF | 5 | \$153,900 | Cracking/ heaving at east end near door 18 |
| Floor - Tile Ceramic/ Porcelain | 1st Floor | 114 | SF | 6 | \$318 | |
| Lighting - Lay-in | 1st Floor | 26 | EA | 4 | \$8,732 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Linked Addition-Main Athletic

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|---|----------|------|------|----------|--|
| Corrido | or . | | • | | | | |
| | Lighting - Metal Halide/ High Pressure Sodium | 1st Floor | 16 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EA | 4 | \$9,732 | |
| | Walls - Concrete Block | 1st Floor | 458 | SF | 6 | \$1,343 | |
| | Walls - Masonry | 1st Floor | 8,164 | SF | 6 | \$25,684 | |
| | Ceiling - Exposed | Basement - From loading dock entrance 22 to storage/boiler room 504 | 340 | SF | 7 | \$0 | |
| | Floor - Concrete | Basement - From loading dock entrance 22 to storage/boiler room 504 | 340 | SF | 6 | \$180 | |
| | Lighting - Wall Mounted | Basement - From loading dock entrance 22 to storage/boiler room 504 | 2 | EA | 6 | | No covers |
| | Walls - Concrete Block | Basement - From loading dock entrance 22 to storage/boiler room 504 | 835 | SF | 6 | \$2,806 | |
| | Walls - Concrete Block | Basement - From loading dock entrance 22 to storage/boiler room 504 | 100 | SF | 5 | | Cracked areas with large gaps, exposed rebar and evidence of water penetration |
| | Walls - Concrete Block | Basement - From loading dock entrance 22 to storage/boiler room 504 | 760 | SF | 6 | \$2,554 | |
| Safety | | | | | | | |
| | Security Cameras | Entire building | 4 | EA | 6 | \$776 | |
| | Security Cameras | Entire building | 6 | EA | 6 | \$1,164 | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | #10 W Center | 150 | SF | 6 | \$1,098 | |
| | Floor - Terrazzo | #10 W Center | 50 | SF | 7 | \$0 | |
| | Handrails | #10 W Center | 70 | LF | 6 | \$607 | |
| | Lighting - Pendent/Surface | #10 W Center | 2 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | #10 W Center | 70 | LF | 7 | \$0 | |
| | Walls - Masonry | #10 W Center | 350 | SF | 6 | \$1,101 | |
| | Ceiling - Plaster/Drywall | #11 E Center | 150 | SF | 6 | \$1,098 | |
| | Floor - Terrazzo | #11 E Center | 50 | SF | 7 | \$0 | |
| | Handrails | #11 E Center | 70 | LF | 6 | \$607 | |
| | Lighting - Pendent/Surface | #11 E Center | 2 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | #11 E Center | 70 | LF | 7 | \$0 | |
| | Walls - Masonry | #11 E Center | 350 | SF | 6 | \$1,101 | |
| | Ceiling - Plaster/Drywall | #12 NE | 150 | SF | 6 | \$1,098 | |
| | Floor - Terrazzo | #12 NE | 50 | SF | 7 | \$0 | |
| | Handrails | #12 NE | 40 | LF | 6 | \$347 | |
| | Lighting - Pendent/Surface | #12 NE | 2 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | #12 NE | 40 | LF | 7 | \$0 | |
| | Walls - Masonry | #12 NE | 350 | SF | 6 | \$1,101 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Building: Linked Addition-Main Athletic

Category: Building Interior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-------------------------------|----------|----------|------|------|----------|---|
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | #13 SW | 150 | SF | 6 | \$1,098 | |
| | Floor - Terrazzo | #13 SW | 50 | SF | 7 | \$0 | |
| | Handrails | #13 SW | 40 | LF | 6 | \$347 | |
| | Lighting - Pendent/Surface | #13 SW | 2 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | #13 SW | 40 | LF | 7 | \$0 | |
| | Walls - Masonry | #13 SW | 350 | SF | 6 | \$1,101 | |
| | Ceiling - Plaster/Drywall | #14 SE | 150 | SF | 6 | \$1,098 | |
| | Floor - Terrazzo | #14 SE | 50 | SF | 6 | \$420 | |
| | Handrails | #14 SE | 40 | LF | 6 | \$347 | |
| | Lighting - Pendent/Surface | #14 SE | 2 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | #14 SE | 40 | LF | 7 | \$0 | |
| | Walls - Masonry | #14 SE | 350 | SF | 6 | \$1,101 | |
| | Ceiling - Plaster/Drywall | #9 NW | 150 | SF | 6 | \$1,098 | |
| | Floor - Terrazzo | #9 NW | 50 | SF | 7 | \$0 | |
| | Handrails | #9 NW | 40 | LF | 6 | \$347 | |
| | Lighting - Pendent/Surface | #9 NW | 2 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | #9 NW | 40 | LF | 7 | \$0 | |
| | Walls - Masonry | #9 NW | 350 | SF | 6 | \$1,101 | |
| Vertica | I Conveyance | | | | | | |
| | Elevator - Hydraulic Elevator | | 1 | EA | 6 | \$19,238 | Access to basement, 1st flr, pool balcony |
| | in a laterieu Caletetela | | | | | *000 040 | |

Building Interior Subtotal:

\$269,846

Total Building Cost

\$2,319,587

SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-------------------|-------------------|----------|------|------|----------|---|
| Athleti | c | | | | | | |
| | Lighting | East | 1 | EA | 5 | \$5,734 | West side of football field in between SE parking lot drive - leaning, not working properly |
| | Lighting | East | 2 | EA | 6 | \$7,209 | Pole lights |
| | Lighting | East | 2 | EA | 6 | \$7,209 | W,S - 2-pole lights |
| | Surface - Asphalt | NE corner of site | 12,620 | SF | 4 | \$99,617 | Abandoned with cracks, holes and vegetation throughout |
| | Surface - Natural | East | 74,555 | SF | 6 | \$61,836 | |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|-----------------------------------|-------------|----------|------|------|-----------|---|
| Athletic | C | | | | | | |
| | Surface - Natural | East | 53,426 | SF | 6 | \$44,312 | |
| Civil/Dr | rainage | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 24 | EA | 6 | \$26,252 | |
| | Civil/ Drainage - Site Drain | Entire Site | 2 | EA | 6 | \$621 | Entrance 22 - underneath loading dock overhead door - Recently repaired |
| | Civil/ Drainage - Site Manhole | Entire Site | 21 | EA | 6 | \$31,348 | 5-underground loading dock area |
| Fencing | g | | | | | | |
| | Fencing - Chain Link | Entire Site | 1,325 | LF | 4 | \$121,643 | Several sections cracked, not supported properly, bent, leaning throughout / SE - poles present, no attached fencing / Baseball backstop, N, E, S sides of sports fields covered with vegetation |
| | Fencing - Chain Link | Entire Site | 2,415 | LF | 6 | \$45,344 | |
| | Fencing - Iron and Concrete Post | Entire Site | 125 | LF | 6 | \$4,585 | West - Custom fencing around sitting / outside garden area adjacent to entrance 10 |
| | Fencing - New Standard Ornamental | Entire Site | 70 | LF | 6 | \$2,233 | NE Entry Gate / Walkway from Entrance 10 to outside sitting / garden |
| Landso | cape | | | | | | |
| | Benches | Entire Site | 10 | EA | 7 | \$0 | Concrete |
| | Landscape - Grass | Entire Site | 159,080 | SF | 6 | \$131,941 | |
| | Landscape - Hardscape- Asphalt | Entire Site | 12,275 | SF | 6 | \$29,665 | South of parking lot - Abandoned sport court |
| | Landscape - Hardscape- Concrete | Entire Site | 2,200 | SF | 5 | \$24,130 | Entrances 7-9 - Several areas cracked, chipped, sinking, uneven with loose and missing pieces throughout / West - Outside sitting-garden area - Several areas cracked, chipped with loose and missing pieces throughout |
| | Landscape - Hardscape- Concrete | Entire Site | 18,060 | SF | 6 | \$93,231 | |
| | Landscape - Hardscape- Pavers | Entire Site | 100 | SF | 4 | \$1,630 | At outside sitting / garden area - majority cracked with vegetation and missing mortar joints throughout |
| | Lighting - Pole Mounted | Entire Site | 2 | EA | 5 | \$4,070 | South of parking lot - Abandoned sport court lighting - both slightly leaning, not working properly |
| | Lighting - Pole Mounted | Entire Site | 1 | EA | 6 | \$1,084 | |
| | Parkway trees | Entire Site | 55 | EA | 6 | \$36,302 | |
| | Planting Beds/ Area | Entire Site | 2,160 | SF | 6 | \$3,552 | |
| | Retaining Wall - Concrete | Entire Site | 9,995 | SF | 6 | \$234,260 | |
| | Trash Receptacles | Entire Site | 3 | EA | 6 | \$937 | |
| Parking | g Lot | | | | | | |
| | Concrete Curbs | NE | 370 | LF | 6 | \$4,751 | |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

SITE

Category: Site

Campus Total ^{2 3}

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|----------------------|----------|------|------|----------|---|
| Parking | Lot | | | | | | |
| | Concrete Curbs | SE | 1,210 | LF | 7 | \$0 | East - Entry asphalt driveway and sloped driveway down to loading dock curbing |
| | Concrete Curbs | SE | 20 | LF | 5 | \$722 | Sloped driveway down to loading dock - Area cracked, chipped with missing pieces / East side of entry driveway - cracked, chipped with missing pieces |
| | Concrete Curbs | SE | 670 | LF | 7 | \$0 | NE Parking lot |
| | Lighting - Pole Mounted | SE | 3 | EA | 6 | \$4,357 | |
| | Lighting - Pole Mounted | SE | 3 | EA | 5 | \$8,392 | Leaning, not working properly |
| | Surface - Asphalt | NE | 10,635 | SF | 6 | \$25,702 | |
| | Surface - Asphalt | NE | 3,000 | SF | 4 | \$26,941 | Several potholes, cracking with loose pieces throughout |
| | Surface - Asphalt | SE | 10,960 | SF | 6 | \$30,562 | East - Parking lots / underground entry driveway |
| | Surface - Asphalt | SE | 5,000 | SF | 4 | \$44,902 | Several potholes, cracked with loose pieces throughout |
| | Surface - Asphalt | SE | 22,120 | SF | 6 | \$53,457 | Parking Lot |
| Sidewa | ks | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 415 | LF | 5 | \$20,682 | Entrances 2 - Several areas cracked with potholes throughout / South - from public sidewalk to SE parking - several areas cracked and spalling |
| | Sidewalks - Internal Walks | Entire Site | 1,700 | LF | 6 | \$20,420 | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 350 | SF | 5 | \$3,343 | South - Majority of concrete apron at entrances 13, 14 cracked, uneven with gaps throughout |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 22,880 | SF | 6 | \$45,479 | |
| Signage | • | | | | | | |
| | Flag Pole - Flag Pole | South / Site South | 2 | EA | 7 | \$0 | |
| | Marquee - Free Standing Back Lighted | South / Site South | 1 | EA | 6 | \$0 | |
| | Monument - Building Mounted Cut Letter Sign | South / South Façade | 1 | EA | 7 | \$0 | |
| | Monument - Sign | South | 2 | EA | 7 | \$0 | Above entrances 13, 14 - Wall mounted / South - Freestanding sign |
| Site S | ubtotal: | | | | \$1 | ,308,454 | |
| Total | Site Cost | | | | \$1 | ,308,454 | |

\$13,855,985



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

- ¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.
- ² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.
- ³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------------|-------------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | | ! | + | ! | 1 | | - | | - | | | | + |
| Art Room | Art Room | Basement | 016 | 016 | 827 | 0 | 1 | 15 | 80 | 40 | 40 | Υ | Υ | N |
| Band Room | Band Room | 3rd Floor | 319 | 319 | 1,959 | 1 | 4 | 6 | 374 | 0 | 40 | N | N | N |
| Choral Room | Choral Room | 1st Floor | 317 | 317 | 1,306 | 1 | 4 | 8 | 170 | 0 | 40 | N | N | N |
| Computer Lab | Computer Lab | Basement | 017 | 017 | 1,048 | 1 | 1 | 8 | 20 | 8 | 40 | N | N | N |
| Computer Lab | Computer Lab | 1st Floor | 112 | 112 | 2,151 | 1 | 20 | 40 | 0 | 0 | 40 | N | N | Υ |
| Computer Lab | Computer Lab | 1st Floor | 112A | 112A | 960 | 1 | 4 | 12 | 0 | 0 | 40 | N | N | N |
| Computer Lab | Computer Lab | 1st Floor | 114A | 114A | 960 | 1 | 4 | 12 | 520 | 0 | 40 | N | N | N |
| Computer Lab | Computer Lab | 1st Floor | 184 | 184 | 1,092 | 1 | 30 | 40 | 442 | 0 | 40 | N | Υ | N |
| Culinary | Culinary | 1st Floor | 176 | 176 | 1,392 | 1 | 2 | 29 | 272 | 0 | 40 | N | N | N |
| Dance Room | Dance Room | 2nd Floor | 293 | 293 | 848 | 1 | 6 | 12 | 288 | 0 | 40 | N | N | N |
| Faculty Lounge | Regular Classroom | 2nd Floor | 273 | 273 | 765 | 1 | 9 | 26 | 341 | 0 | 40 | N | N | N |
| Faculty Lounge | Regular Classroom | 2nd Floor | 288 | 288 | 605 | 1 | 2 | 14 | 0 | 0 | 40 | N | N | N |
| Fitness Room | Fitness Room | 2nd Floor | 292 | 292 | 1,697 | 2 | 2 | 16 | 0 | 0 | 40 | N | N | N |
| Lunch Room | Regular Classroom | 1st Floor | 181 | 181 | 1,363 | 1 | 8 | 38 | 130 | 0 | 40 | N | N | N |
| Lunch Room | Regular Classroom | 1st Floor | 182 | 182 | 1,439 | 1 | 9 | 46 | 225 | 0 | 40 | N | N | N |
| Music Room | Music Room | Basement | 015 | 015 | 2,220 | 0 | 1 | 4 | 160 | 80 | 40 | Υ | Υ | N |
| Office | Regular Classroom | 1st Floor | 168 | 168 | 454 | 1 | 4 | 36 | 102 | 0 | 40 | N | N | N |
| Other Instructional Use | Other Instructional Use | Basement | 0506 | 0506 | 121 | 0 | 0 | 4 | 0 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 113 | 113 | 1,910 | 1 | 10 | 70 | 280 | 0 | 40 | N | N | Υ |
| Regular Classroom | Regular Classroom | 1st Floor | 114 | 114 | 1,611 | 1 | 10 | 20 | 0 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 124 | 124 | 1,449 | 1 | 9 | 40 | 525 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 139 | 139 | 662 | 0 | 7 | 25 | 0 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 141 | 141 | 750 | 1 | 2 | 8 | 0 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 171 | 171 | 902 | 1 | 6 | 20 | 204 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 172 | 172 | 550 | 1 | 4 | 16 | 136 | 0 | 40 | N | N | N |
| Regular Classroom | Lunch Room | 1st Floor | 173 | 173 | 1,340 | 1 | 6 | 12 | 360 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 175 | 175 | 702 | 1 | 4 | 16 | 170 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 183 | 183 | 1,838 | 1 | 0 | 18 | 330 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 185 | 185 | 867 | 1 | 6 | 32 | 0 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 189 | 189 | 867 | 1 | 8 | 16 | 0 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 190 | 190 | 867 | 1 | 10 | 20 | 0 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 192 | 192 | 1,067 | 1 | 34 | 140 | 0 | 0 | 40 | N | N | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 765 | 1 | 6 | 18 | 170 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 765 | 1 | 6 | 18 | 186 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 765 | 1 | 6 | 18 | 170 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 765 | 1 | 8 | 18 | 330 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 216 | 216 | 740 | 1 | 10 | 20 | 0 | 0 | 40 | N | Υ | N |



821 E 103rd St Chicago, IL 60628

Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|---------------------|---------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | • | | | • | • | • | • | | | | • | • | | • |
| Regular Classroom | Regular Classroom | 2nd Floor | 223 | 223 | 800 | 1 | 10 | 20 | 35 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 224 | 224 | 765 | 1 | 6 | 18 | 330 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 236 | 236 | 907 | 1 | 16 | 50 | 0 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 243 | 243 | 767 | 1 | 10 | 20 | 210 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 244 | 244 | 765 | 1 | 10 | 20 | 155 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 245 | 245 | 767 | 1 | 10 | 20 | 210 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 250 | 250 | 620 | 1 | 1 | 6 | 0 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 251 | 251 | 620 | 1 | 10 | 20 | 210 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 252 | 252 | 615 | 1 | 3 | 10 | 124 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 253 | 253 | 767 | 1 | 10 | 20 | 210 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 254 | 254 | 765 | 1 | 6 | 22 | 155 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 255 | 255 | 767 | 1 | 10 | 20 | 210 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 274 | 274 | 765 | 1 | 8 | 22 | 155 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 275 | 275 | 765 | 1 | 8 | 24 | 155 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 276 | 276 | 765 | 1 | 8 | 24 | 155 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 277 | 277 | 765 | 1 | 6 | 16 | 204 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 278 | 278 | 765 | 1 | 9 | 26 | 341 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 280 | 280 | 923 | 1 | 8 | 30 | 186 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 281 | 281 | 765 | 1 | 6 | 16 | 204 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 283 | 283 | 765 | 1 | 6 | 16 | 374 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 284 | 284 | 765 | 1 | 8 | 20 | 155 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 300 | 300 | 1,119 | 2 | 3 | 22 | 0 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 301 | 301 | 823 | 1 | 2 | 12 | 0 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 302 | 302 | 935 | 1 | 3 | 20 | 356 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 404 | 404 | 892 | 1 | 10 | 20 | 560 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 406 | 406 | 892 | 1 | 10 | 20 | 210 | 0 | 40 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 408 | 408 | 892 | 1 | 10 | 20 | 210 | 0 | 40 | N | Υ | N |
| Science Lab Level 2 | Science Lab Level 2 | 1st Floor | 136 | 136 | 2,610 | 1 | 20 | 40 | 0 | 0 | 40 | N | Υ | N |
| Science Lab Level 3 | Science Lab Level 3 | 1st Floor | 122 | 122 | 1,818 | 1 | 15 | 30 | 175 | 0 | 40 | N | Υ | N |
| Science Lab Level 3 | Science Lab Level 3 | 2nd Floor | 201 | 201 | 1,226 | 1 | 2 | 50 | 272 | 0 | 40 | N | N | N |
| Science Lab Level 3 | Science Lab Level 3 | 2nd Floor | 225 | 225 | 2,451 | 1 | 20 | 40 | 0 | 0 | 40 | N | Υ | N |
| Science Lab Level 3 | Science Lab Level 3 | 2nd Floor | 230 | 230 | 1,780 | 1 | 15 | 94 | 0 | 0 | 40 | N | Υ | N |
| Science Lab Level 3 | Science Lab Level 3 | 2nd Floor | 233 | 233 | 2,537 | 1 | 10 | 20 | 210 | 0 | 40 | N | Υ | N |
| Science Lab Level 3 | Science Lab Level 3 | 2nd Floor | 234 | 234 | 1,390 | 1 | 11 | 90 | 0 | 0 | 40 | N | Υ | N |
| Store Room | Computer Lab | 1st Floor | 143 | 143 | 441 | 1 | 20 | 40 | 120 | 0 | 40 | N | N | Υ |
| Weight | Weight | Basement | 0515 | 0515 | 583 | 1 | 0 | 2 | 448 | 0 | 40 | N | N | N |
| Weight | Weight | 2nd Floor | 294 | 294 | 985 | 2 | 3 | 18 | 280 | 0 | 40 | N | N | N |



821 E 103rd St Chicago, IL 60628 Co-locating on this campus are CORLISS HS and NOBLE - BUTLER HS

Classroom Summary

| | Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|---|---------------|----------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| N | Main | | | | | | | | | | | | | | |

| Linked Additi | on-Main Athletic | | | | | | | | | | | | | |
|---------------|-------------------|-----------|-------|-------|-----|---|---|----|-----|---|----|---|---|---|
| Vacant | Regular Classroom | 1st Floor | 1-618 | 1-618 | 858 | 0 | 1 | 12 | 372 | 0 | 40 | N | N | N |
| Weight | Regular Classroom | 1st Floor | 1-615 | 1-615 | 858 | 0 | 1 | 10 | 372 | 0 | 40 | N | N | N |