

Facility Assessment Report

This report contains the detailed findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 2013 | 3 | 212,285 | \$1,204,848 |
| SITE | | | | \$331,607 |
| Campus Total | | | 212,285 | \$1,536,455 |

Building: Main

Category: Building Exterior

| | ory. Building Exterior | | | | | | - |
|---------|--|----------|----------|------|------|------|----------|
| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| Entrand | e | | | | | | |
| | Entrance Control - Audio | #3 E | 1 | EA | 7 | \$0 | |
| | Entrance Control - Audio and Video | #1 N | 1 | EA | 7 | \$0 | |
| | Entrance Control - Audio and Video | #4 E | 1 | EA | 7 | \$0 | |
| | Entrance Control - Audio and Video | #5.1 S | 1 | EA | 7 | \$0 | |
| | Entrance Control - Audio and Video | #5.2 S | 1 | EA | 7 | \$0 | |
| | Entrance Control - Audio and Video | #6 W | 1 | EA | 7 | \$0 | |
| | Entrance Control - Audio and Video | #7_LL W | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | #2 N | 4 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | #4.1 S | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | #5.1 S | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | #8 W | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Exterior Steel Door | #9 E | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Overhead Rolling/ Garage Door | #5.2 S | 1 | EA | 7 | \$0 | |
| | Exterior Doors - Side lite | #3 E | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Side lite | #5 S | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Side lite | #8 W | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | #1 N | 6 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | #3 E | 2 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | #4 E | 5 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | #5 S | 3 | EA | 7 | \$0 | |
| | Exterior Doors - Store Front | #6 W | 4 | EA | 7 | \$0 | |



Category: Building Exterior

| Ext Ext | terior Doors - Store Front terior Doors - Transom Lite terior Doors - Transom Lite | #7_LL W #3 E | 4 | EA | 7 | | |
|-------------|--|---------------------------|---------|----|---|---------|------------------------------|
| Ext Ext | terior Doors - Transom Lite terior Doors - Transom Lite | | 4 | FA | 7 | | |
| Ext | terior Doors - Transom Lite | #3 E | | | 1 | \$0 | |
| | | | 1 | EA | 7 | \$0 | |
| Ext | torios Doors - Trongons Lita | #4 E | 5 | EA | 7 | \$0 | |
| | terior Doors - Transom Lite | #4.1 S | 1 | EA | 7 | \$0 | Louver |
| Ext | terior Doors - Transom Lite | #5 S | 5 | EA | 7 | \$0 | |
| Ext | terior Doors - Transom Lite | #5.1 S | 1 | EA | 7 | \$0 | |
| Ext | terior Stairs - Concrete | #1 N | 660 | LF | 7 | \$0 | |
| Ext | terior Stairs - Concrete | #7_LL W | 380 | LF | 7 | \$0 | |
| Pov | wer Door Operator and Controls | #1 N | 2 | EA | 7 | \$0 | |
| Pov | wer Door Operator and Controls | #3 E | 2 | EA | 7 | \$0 | |
| Pov | wer Door Operator and Controls | #4 E | 2 | EA | 7 | \$0 | |
| Pov | wer Door Operator and Controls | #6 W | 1 | EA | 7 | \$0 | |
| Rai | mp Handrail - Steel_Ramp Handrail | #1 N | 220 | LF | 7 | \$0 | |
| Rar | mp Handrail - Steel_Ramp Handrail | #3 E | 250 | LF | 7 | \$0 | |
| Rai | amp Handrail - Steel_Ramp Handrail | #4 E | 250 | LF | 7 | \$0 | |
| Rar | amps | #4 E | 125 | LF | 7 | \$0 | |
| Rai | amps - Concrete | #1 N | 110 | LF | 7 | \$0 | |
| Rar | amps - Concrete | #3 E | 125 | LF | 7 | \$0 | |
| Sta | air Handrail - Steel_Stair Handrail | #1 N | 150 | LF | 7 | \$0 | |
| Sta | air Handrail - Steel_Stair Handrail | #7_LL W | 80 | LF | 7 | \$0 | |
| Foundation | ı | | | | | | |
| Fou | undation - Concrete | Entire Building | 1,783 | LF | 7 | \$0 | |
| Sup | perstructure - Metal Deck/ Concrete Topping | Entire Building | 212,285 | SF | 7 | \$0 | |
| Lighting | | | | | | | |
| Ext | terior Lighting - Wall Mounted | Entire Building | 11 | EA | 6 | \$3,176 | Lens/ trim is broken |
| Ext | terior Lighting - Wall Mounted | Entire Building | 26 | EA | 6 | \$7,507 | |
| Roof Syster | m | | | | | | |
| Chi | nimney - Metal Flue | Roof #2 | 10 | LF | 7 | \$0 | |
| Cop | pping - Metal | Roof #1 | 841 | LF | 7 | \$0 | |
| Cop | pping - Metal | Roof #2 / Entire Building | 2,142 | LF | 7 | \$0 | |
| Cop | pping - Metal | Roof #3 | 616 | LF | 7 | \$0 | |
| Dov | ownspouts - Interior Downspouts | Roof #1 | 544 | LF | 7 | \$0 | |
| | ownspouts - Interior Downspouts | Roof #2 / Entire Building | 3,211 | LF | 7 | \$0 | |
| Dov | ownspouts - Interior Downspouts | Roof #2 / North West | 1 | LF | 5 | \$0 | Missing One Roof Drain Grate |
| | ownspouts - Interior Downspouts | Roof #3 | 546 | LF | 7 | \$0 | |
| Par | rapet - 16" - 30" Height | Roof #1 | 312 | LF | 7 | \$0 | |



Category: Building Exterior

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|-----------------------------|----------|------|------|------------|------------------|
| Roof S | ystem | | | | | | |
| | Parapet - 16" - 30" Height | Roof #2 / Entire Building | 1,110 | LF | 7 | \$0 | |
| | Parapet - Parapet < 16" Height | Roof #1 | 85 | LF | 7 | \$0 | |
| | Parapet - Parapet < 16" Height | Roof #2 / Penthouse | 1,032 | LF | 7 | \$0 | |
| | Parapet - Parapet < 16" Height | Roof #3 | 418 | LF | 7 | \$0 | |
| | Parapet - Parapet > 30" | Roof #1 | 444 | LF | 7 | \$0 | |
| | Parapet - Parapet > 30" | Roof #3 | 198 | LF | 7 | \$0 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof #1 | 33,830 | SF | 7 | \$0 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof #2 / Entire Building | 40,923 | SF | 7 | \$0 | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof #3 | 11,752 | SF | 7 | \$0 | |
| | Roof - Modified Bitumen | Roof #1 | 33,830 | SF | 7 | \$0 | Green Roof |
| | Roof - Modified Bitumen | Roof #2 / Entire Building | 39,923 | SF | 7 | \$0 | Part Green House |
| | Roof - Modified Bitumen | Roof #2 / Entire Building | 1,000 | SF | 3 | \$51,437 | Leaks reported |
| | Roof - Modified Bitumen | Roof #3 | 11,752 | SF | 7 | \$0 | |
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 100 | SF | 6 | \$908 | Effloresence |
| | Exterior Walls - Brick | Entire Building | 3,761,59 | SF | 7 | \$0 | |
| | Exterior Walls | Entire Building | 2,547 | SF | 7 | \$0 | |
| | Exterior Walls - Prefabricated Metal Panel Wall | Entire Building | 8,182 | SF | 7 | \$0 | |
| | Exterior Walls - Prefabricated Metal Panel Wall | Entire Building / Penthouse | 4,377 | SF | 7 | \$0 | |
| Windov | vs | | | | | | |
| | Clerestory - Glass Double-Pane | Entire Building | 1,471 | SF | 7 | \$0 | |
| | Curtain wall - Glazed Double Pane | Entire Building | 13,533 | SF | 7 | \$0 | |
| | Guard - Guards perforated | Entire Building | 5,611 | SF | 7 | \$0 | |
| | Lintels - Steel | Entire Building | 913 | LF | 7 | \$0 | |
| | Storefront Windows | Entire Building | 2,504 | SF | 7 | \$0 | |
| | Windows - Casement Aluminum Double-pane | Entire Building | 10,951 | SF | 7 | \$0 | |
| | Windows - Louver | Entire Building | 288 | SF | 7 | \$0 | |
| | | | | | | *** | |

Building Exterior Subtotal:

\$63,029

Building: Main

Category: Electrical System

| Group Item - Type | Location | Quantity | Unit | Rank | Cost Comments |
|--|-----------------|----------|------|------|---------------|
| Emergency System | | | | | |
| Automatic Transfer Switch | Electrical Room | 3 | EA | 7 | \$0 |
| Emergency A/C Power - Corridors and Stairs | Entire Building | 43,081 | SF | 7 | \$0 |



Category: Electrical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|-----------------------------------|----------|------|------|------|----------|
| Emerge | ncy System | | | | | | |
| | Emergency A/C Power - Gym | Entire Building / 1st Floor | 5,635 | SF | 7 | \$0 | |
| | Emergency A/C Power - Lunchrooms | Entire Building / 1st Floor | 4,269 | SF | 7 | \$0 | |
| | Emergency A/C Power - Pool | Entire Building / 1st Floor | 8,005 | SF | 7 | \$0 | |
| | Emergency A/C Power - Students Toilets | Entire Building | 4,734 | SF | 7 | \$0 | |
| | Emergency Battery Packs - Auditoium and Aisle Lighting | Entire Building / 1st Floor | 4 | EA | 7 | \$0 | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 3 | EA | 7 | \$0 | |
| | Emergency Generator- Indoor- Natural Gas - Above 250 KW | Mechanical Room | 1 | EA | 7 | \$0 | |
| | Exit Signs - Corridors and Stairs | Entire Building | 24 | EA | 7 | \$0 | |
| | Exit Signs - Gym | Entire Building / 1st Floor | 6 | EA | 7 | \$0 | |
| | Exit Signs - Lunchroom | Entire Building / 1st Floor | 7 | EA | 7 | \$0 | |
| | Exit Signs - Pool | Entire Building / 1st Floor | 5 | EΑ | 7 | \$0 | |
| | Security System - CCTV | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Security System - Intrusion Detection | Entire Building | 212,285 | SF | 7 | \$0 | |
| | UPS - Less than 30 KW | Electrical Room | 1 | EA | 7 | \$0 | |
| Main Se | ervice | | | | | | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 7 | \$0 | |
| | Main Electrical Service - 2001 to 3000 A 277/480/3PH | Electrical Room | 1 | EΑ | 7 | \$0 | |
| | Main Electrical Service - Greater than 3000 A 120/208/3PH | Electrical Room | 1 | EA | 7 | \$0 | |
| | PA System | Electrical Room / Entire Building | 212,285 | SF | 7 | \$0 | |
| Power I | Distribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building / Electrical Room | 3 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 14 | EA | 7 | \$0 | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 12 | EA | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Electrical Room | 1 | EA | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Electrical Room | 2 | EA | 7 | \$0 | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building / Electrical Room | 2 | EA | 7 | \$0 | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 2 | EA | 7 | \$0 | |
| | Transformers - 277/480 - 120/208 | Entire Building | 4 | EA | 7 | \$0 | |
| Electr | ical System Subtotal: | | | | | \$0 | |

Building: Main

Category: Safty System

Group Item - Type Location Quantity Unit Rank Cost Comments







Category: Safty System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--------------------------|-----------------------------------|----------|------|------|------|-------------------------|
| Fire Ala | ırm | | | | | | |
| | Fire Alarm Panel | Entire Building / Electrical Room | 1 | EA | 7 | \$0 | |
| | Fire Alarm Strobe Lights | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Fire Alarm_System | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Fire Pump Controller | Entire Building / Mechanical Room | 1 | EA | 7 | \$0 | |
| Pump F | Room Assembly | | | | | | |
| | Fire Pump - 25-50 hp | Mechanical Room | 1 | EΑ | 7 | \$0 | |
| | Jockey Pump | Mechanical Room | 1 | EA | 7 | \$0 | |
| Sprinkl | er System | | | | | | |
| | Dry Sprinkler System | Entire Building / 1st Floor | 4,000 | SF | 7 | \$0 | |
| | Sprinkler Heads | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Sprinkler Piping | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Wet Sprinkler System | Entire Building | 208,285 | SF | 7 | \$0 | minus loading dock area |
| Safty | System Subtotal: | | | | | \$0 | |

Building: Main

Category: Mechanical System


| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|---|----------|------|------|------|---------------------------------|
| Air Con | ditioning | | | | | | |
| | Chemical Pot Feeder | Roof / Mechanical Room | 1 | EA | 7 | \$0 | |
| | Chiller-Air Cooled-Scroll Type-Roof Mounted - Greater than 200 tons | Roof | 1 | EA | 7 | \$0 | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 4 | EA | 7 | \$0 | serves MDF room, computer rooms |
| | Glycol Feed | Roof / Mechanical Room | 1 | EA | 7 | \$0 | |
| | Pipes - Chilled Water Pipe- Copper | Roof / Entire Building | 1,000 | LF | 7 | \$0 | |
| | Pressure Fill System | Roof / Mechanical Room | 1 | EA | 7 | \$0 | |
| Air Han | dling Systems | | | | | | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm | Mechanical Room - AHU-3 / Mechanical Room | 1 | EA | 7 | \$0 | serves gym and stage |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm | Mechanical Room - AHU-4 / Mechanical Room | 1 | EA | 7 | \$0 | serves gym |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm | Mechanical Room - AHU-6 / Mechanical Room | 1 | EA | 7 | \$0 | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm | Penthouse - AHU-2 / Penthouse | 1 | EA | 7 | \$0 | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm | Penthouse AHU-1 / Penthouse | 1 | EA | 7 | \$0 | |
| | Air Intake | Mechanical Room - AHU-3 / Façade- NE | 1 | EA | 7 | \$0 | |
| DACK C | NE THE VADDS HS | Page 5 of 56 | | | | | Assessment Date: 10/26/11 |



Category: Mechanical System

| Conta Energy Energy Energy Energy Fan F | ntake ntake | Mechanical Room - AHU-4 / Façade-SW Mechanical Room - AHU-6 / Façade-SE Penthouse - AHU-2 / Roof Penthouse AHU-1 / Roof Roof Mechanical Room - AHU-3 / Mechanical Room Mechanical Room - AHU-4 / Mechanical Room Mechanical Room - AHU-6 / Mechanical Room Penthouse - AHU-2 / Penthouse Penthouse AHU-1 / Penthouse | 1 1 1 1 1 1 | EA EA EA EA EA | 7 7 7 7 7 7 | \$0 \$0 \$0 \$0 \$0 \$0 | condensor portion at roof |
|---|--|---|----------------------------|----------------------------|----------------------------|--|---------------------------|
| Air In Air In Air In Dehu Conta Energ Energ Energ Indoo Indoo VAV | ntake ntake ntake umidification Unit- Indoor- Electric Heating- DX Cooling with Self tained Compressor - Greater than 8000 cfm rgy Recovery Unit | SW Mechanical Room - AHU-6 / Façade- SE Penthouse - AHU-2 / Roof Penthouse AHU-1 / Roof Roof Mechanical Room - AHU-3 / Mechanical Room Mechanical Room - AHU-4 / Mechanical Room Mechanical Room - AHU-6 / Mechanical Room Penthouse - AHU-2 / Penthouse Penthouse AHU-1 / Penthouse | 1 1 1 1 1 | EA EA EA EA | 7 7 7 7 7 | \$0 \$0 \$0 \$0 \$0 | condensor portion at roof |
| Air In Air In Dehu Conta Energ Energ Energ Energ Indoo Indoo VAV | ntake ntake umidification Unit- Indoor- Electric Heating- DX Cooling with Self tained Compressor - Greater than 8000 cfm rgy Recovery Unit | Penthouse - AHU-2 / Roof Penthouse AHU-1 / Roof Roof Mechanical Room - AHU-3 / Mechanical Room Mechanical Room - AHU-4 / Mechanical Room Mechanical Room - AHU-6 / Mechanical Room Penthouse - AHU-2 / Penthouse Penthouse AHU-1 / Penthouse | 1 1 1 1 | EA EA EA | 7 7 7 7 | \$0 \$0 \$0 | condensor portion at roof |
| Air In Dehu Conta Energ Energ Energ Energ Indoor Indoor VAV | ntake umidification Unit- Indoor- Electric Heating- DX Cooling with Self tained Compressor - Greater than 8000 cfm rgy Recovery Unit | Penthouse AHU-1 / Roof Roof Mechanical Room - AHU-3 / Mechanical Room Mechanical Room - AHU-4 / Mechanical Room Mechanical Room - AHU-6 / Mechanical Room Penthouse - AHU-2 / Penthouse Penthouse AHU-1 / Penthouse | 1 1 1 1 | EA EA EA | 7 7 7 | \$0 \$0 \$0 | condensor portion at roof |
| Dehu Conta Energ Energ Energ Energ Fan F Indoo Indoo VAV | umidification Unit- Indoor- Electric Heating- DX Cooling with Self tained Compressor - Greater than 8000 cfm rgy Recovery Unit | Roof Mechanical Room - AHU-3 / Mechanical Room Mechanical Room - AHU-4 / Mechanical Room Mechanical Room - AHU-6 / Mechanical Room Penthouse - AHU-2 / Penthouse Penthouse AHU-1 / Penthouse | 1 1 1 | EA EA | 7 7 7 | \$0 \$0 | condensor portion at roof |
| Energy Energy Energy Energy Energy Energy Fan F Indoor VAV VAV | tained Compressor - Greater than 8000 cfm rgy Recovery Unit | Mechanical Room - AHU-3 / Mechanical Room Mechanical Room - AHU-4 / Mechanical Room Mechanical Room - AHU-6 / Mechanical Room Penthouse - AHU-2 / Penthouse Penthouse AHU-1 / Penthouse | 1 1 1 | EA EA | 7 | \$0 | condensor portion at roof |
| Energ Energ Energ Fan F Indoc Indoc VAV | rgy Recovery Unit rgy Recovery Unit rgy Recovery Unit rgy Recovery Unit | Room Mechanical Room - AHU-4 / Mechanical Room Mechanical Room - AHU-6 / Mechanical Room Penthouse - AHU-2 / Penthouse Penthouse AHU-1 / Penthouse | 1 | EA | 7 | · | |
| Energ Energ Fan F Indoc Indoc VAV | rgy Recovery Unit rgy Recovery Unit | Room Mechanical Room - AHU-6 / Mechanical Room Penthouse - AHU-2 / Penthouse Penthouse AHU-1 / Penthouse | 1 | | | \$0 | |
| Energ Energ Fan I Indoo Indoo VAV | rgy Recovery Unit | Room Penthouse - AHU-2 / Penthouse Penthouse AHU-1 / Penthouse | | EA | - | | |
| Energ Fan F Indoc Indoc VAV VAV | rgy Recovery Unit | Penthouse AHU-1 / Penthouse | 1 | | 7 | \$0 | |
| Fan F Indoc Indoc VAV VAV | • | | | EA | 7 | \$0 | |
| Indoc Indoc VAV VAV | Power Box - Fan Power Box with Hot Water Coil | | 1 | EA | 7 | \$0 | |
| Indoo VAV VAV | | Entire Building | 30 | EA | 6 | \$14,784 | |
| VAV VAV | or Return Fans- Centrifugal Inline - 10001 - 20000 CFM | Entire Building | 3 | EA | 7 | \$0 | for AHU-3, AHU-4, AHU-5 |
| VAV | or Return Fans- Centrifugal Inline - Greater than 20000 CFM | Entire Building | 3 | EA | 7 | \$0 | for AHU-1, AHU-2, AHU-6 |
| | Вох | Mechanical Room - AHU-3 / Electrical Room | 3 | EA | 7 | \$0 | |
| VAV | Вох | Mechanical Room - AHU-4 / Entire Building | 3 | EA | 7 | \$0 | |
| | Вох | Mechanical Room - AHU-6 / Entire Building | 30 | EA | 7 | \$0 | |
| VAV | Box | Penthouse - AHU-2 / Entire Building | 58 | EA | 7 | \$0 | |
| VAV | Box | Penthouse AHU-1 / Entire Building | 68 | EA | 7 | \$0 | |
| Boiler System | ns | | | | | | |
| Boile | er Auxiliary- Condensing Hot Water - 2001 - 3000 HP | Boiler Room | 3 | EA | 7 | \$0 | |
| Cher | mical Pot Feeder | Boiler Room / Mechanical Room | 1 | EA | 7 | \$0 | |
| Com | bustion Dampers | Boiler Room | 3 | EA | 7 | \$0 | |
| | densing- Hot Water Boiler - 2001 - 3000 MBH | Boiler Room | 3 | EA | 7 | \$0 | |
| Glyco | ol Feed System | Boiler Room / Mechanical Room | 1 | EA | 7 | \$0 | |
| Wate | er Fill System | Boiler Room / Mechanical Room | 1 | EA | 7 | \$0 | |
| Heating Device | ces | | | | | | |
| Cabi | | 1st Floor | 4 | EA | 7 | \$0 | near entrances |
| Cabi | inet Heaters - With Hot Water Coil | Entire Building | 6 | EA | 7 | \$0 | |
| Fin T | net Heaters - With Hot Water Coil inet Heaters - With Hot Water Coil | Entire building | 150 | LF | 7 | ሰ ስ | |
| Unit | | Entire Building | 130 | | | \$0 | |
| Unit I | inet Heaters - With Hot Water Coil | • | 4 | EA | 7 | \$0 \$0 | |







Category: Mechanical System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------|--|-----------------------------|----------|------|------|--------------------------|-------------------|
| Heating | Devices | | | | | | |
| Mechan | ical Plumbing | | | | | | |
| Wiccitati | Chilled Water Pump - 10 - 20 HP | Mechanical Room | 2 | EA | 7 | \$0 | |
| | Chilled Water Pump - Less than 10 | Mechanical Room | 2 | EA | 7 | \$0 | secondary pumps |
| | Hot Water Pump - 21 - 50 HP | Mechanical Room | 2 | EA | 7 | \$0 | Secondary parries |
| | Hot Water Pump - Less than 10 | Mechanical Room | 2 | EA | 7 | \$0 | Secondary pumps |
| | Hydronic Supply and Return - Copper | Entire Building | 2,000 | LF | 7 | \$0 | |
| Temper | ature Control | | | | | | |
| | DDC System | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Electric Thermostat | Entire Building | 2 | EA | 7 | \$0 | |
| | Thermostats - DDC | Entire Building | 166 | EA | 7 | \$0 | |
| Ventilat | ion | | | | | | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Entire Building | 5 | EA | 7 | \$0 | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building / Roof | 2 | EA | 7 | \$0 | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building / Roof | 2 | EA | 7 | \$0 | |
| | Lab Exhaust Hood | Entire Building | 4 | EA | 7 | \$0 | |
| | Type I Exhaust Hood- Kitchen | Entire Building / 1st Floor | 1 | EA | 7 | \$0 | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building / 1st Floor | 1 | EA | 7 | \$0 | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building / 1st Floor | 1 | EA | 7 | \$0 | |
| Mochs | unical System Subtotal: | | | | | \$1 <i>4</i> 78 <i>4</i> | |

Mechanical System Subtotal:

\$14,784

Building: Main

Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-------------------------------|----------|------|------|------|----------|
| Hot Wat | er | | | | | | |
| | Gas Heater - 300001 - 600000 BTU/HR | Boiler Room / Mechanical Room | 3 | EA | 7 | \$0 | |
| Piping | | | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Domestic Piping-Cold Water Risers | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Sanitary Piping | Entire Building | 212,285 | SF | 7 | \$0 | |







Category: Plumbing System

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------------|-----------------------------|----------|------|------|------|----------|
| Piping | | | | | | | |
| | Storm Piping | Entire Building | 212,285 | SF | 7 | \$0 | |
| | Vent Piping | Entire Building | 212,285 | SF | 7 | \$0 | |
| Pool Sy | stems | | | | | | |
| | Pool Drain Piping | 1st Floor / Basement | 100 | LF | 7 | \$0 | |
| | Pool Filtration System including Pump | 1st Floor | 1 | EA | 7 | \$0 | |
| | Pool Hot Water Heater - Gas Fired | 1st Floor | 1 | EA | 7 | \$0 | |
| | Pool Supply and Return Piping | 1st Floor / Basement | 100 | LF | 7 | \$0 | |
| Pumps | | | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | 1st Floor / Mechanical Room | 1 | EA | 7 | \$0 | |
| | Pumps - Ejector-Simplex | 1st Floor / Mechanical Room | 1 | EA | 7 | \$0 | |
| | Pumps - Sump-Duplex | 1st Floor / Mechanical Room | 2 | EA | 7 | \$0 | |
| | Pumps - Sump-Simplex | 1st Floor | 2 | EA | 7 | \$0 | |
| Plumb | oing System Subtotal: | | | | | \$0 | |

Building: Main

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost Comments | |
|---------|--|----------|----------|------|------|---------------|--|
| Classro | om #008 (Fitness Room) | | | | | | |
| | Ceiling - Lay-in | Basement | 1,305 | SF | 7 | \$0 | |
| | Doors - Side-lite | Basement | 20 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Basement | 5 | EA | 7 | \$0 | |
| | Doors - Transom Window | Basement | 16 | SF | 7 | \$0 | |
| | Floor - Weight/ Fitness Room Floor Matting | Basement | 1,305 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Basement | 16 | EA | 7 | \$0 | |
| | Storage/ Closet | Basement | 51 | SF | 7 | \$0 | |
| | Walls - Concrete Block | Basement | 1,000 | SF | 7 | \$0 | |
| Classro | om #010 (Regular Classroom) | | | | | | |
| | Ceiling - Exposed | Basement | 1,320 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Basement | 3 | EΑ | 7 | \$0 | |
| | Floor - Epoxy/ Painted | Basement | 1,320 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Basement | 14 | EΑ | 7 | \$0 | |
| | Marker Board | Basement | 14 | LF | 7 | \$0 | |
| | Storage/ Closet | Basement | 439 | SF | 7 | \$0 | |
| | Walls - Concrete Block | Basement | 1,698 | SF | 7 | \$0 | |
| | | | | | | | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|----------------------------------|-----------|----------|------|------|---------|----------|
| | oom #119 (Computer Lab) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 744 | SF | 6 | \$2,234 | |
| | Charging Station | 1st Floor | 1 | EA | 6 | \$485 | |
| | Doors - Side-lite | 1st Floor | 12 | SF | 6 | \$201 | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | 1st Floor | 744 | SF | 6 | \$1,585 | |
| | Lighting - Lay-in | 1st Floor | 23 | EA | 7 | \$0 | |
| | Marker Board | 1st Floor | 18 | LF | 7 | \$0 | |
| | Storage/ Closet | 1st Floor | 79 | SF | 6 | \$573 | |
| | Walls - Plaster/Drywall | 1st Floor | 1,120 | SF | 6 | \$3,091 | |
| | Wireless System | 1st Floor | 1 | EA | 6 | \$372 | |
| Classro | oom #200B (Art Room) | | | | | | |
| | Casework | 2nd Floor | 60 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,098 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 24 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 1,098 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,257 | SF | 7 | \$0 | |
| | Work Sink | 2nd Floor | 3 | EA | 7 | \$0 | |
| Classro | oom #200E (Art Room) | | | | | | |
| | Casework | 2nd Floor | 60 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,098 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 36 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 3 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 1,098 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 12 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,257 | SF | 7 | \$0 | |
| | Work Sink | 2nd Floor | 3 | EA | 7 | \$0 | |
| Classro | oom #200G - Choral (Choral Room) | | | | | | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,093 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Floor - Carpet | 2nd Floor | 1,093 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 9 | EA | 7 | \$0 | |
| | Sound System | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,224 | SF | 7 | \$0 | |
| | | | | | | | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-----------|----------|------|------|------|----------|
| Classro | om #200I - Instrume (Band Room) | | | | | | |
| | Casework | 2nd Floor | 30 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 1,612 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 24 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 3 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | \$0 | |
| | Floor - Carpet | 2nd Floor | 1,612 | SF | 7 | \$0 | |
| | Instrument Storage Casework | 2nd Floor | 106 | LF | 7 | \$0 | |
| | Lighting - Pendent/Surface | 2nd Floor | 19 | EA | 7 | \$0 | |
| | Risers | 2nd Floor | 18 | LF | 7 | \$0 | |
| | Sound System | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,898 | SF | 7 | \$0 | |
| Classro | om #200I-4 (Music Room) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 154 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 2nd Floor | 154 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 446 | SF | 7 | \$0 | |
| Classro | om #200I-5 (Music Room) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 104 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 2nd Floor | 104 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 384 | SF | 7 | \$0 | |
| 01 | | | | | | | |
| Classro | om #200I-6 (Music Room) | 0.15 | 0.4 | 05 | | ФО. | |
| | Ceiling - Lay-in | 2nd Floor | 84 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Carpet | 2nd Floor | 84 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 360 | SF | 7 | \$0 | |
| Classro | om #217 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 718 | SF | 7 | \$0 | |
| | | | | | | | |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|------------------------|----------|----------|--------|------------|----------|
| _ | oom #217 (Regular Classroom) | Location | Quantity | Jint | Naiik | CUSI | Commence |
| CidSSfC | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor 2nd Floor | 12 | SF EA | 7 7 | \$0 \$0 | |
| | Doors - Steel Doors Inclinw Doors - Transom Window | 2nd Floor 2nd Floor | 10 | SF | 7 7 | \$0 \$0 | |
| | Floor - Tile | 2nd Floor | | SF | | \$0 \$0 | |
| | | | 718 | _ | 7 | | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,036 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| Classro | oom #219 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 718 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 718 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EΑ | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,036 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| Classro | oom #220 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 718 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 40 | SF | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 718 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,036 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| Classro | oom #221 (Regular Classroom) | | | | | | |
| 2.40070 | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 680 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | \$0 | |
| | Doord Transcom Window | | .0 | | - | | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|------------|----------|------|------|------|-------------------------|
| Classro | oom #221 (Regular Classroom) | | | | | | |
| | Floor - Tile | 2nd Floor | 680 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,040 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| Classro | oom #222 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 680 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 680 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,040 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| Classro | oom #223 (Computer Lab) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,227 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 24 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 20 | SF | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 1,227 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 25 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,762 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 84 | SF | 7 | \$0 | |
| Classro | oom #224 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 718 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 718 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,036 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| DAOK | DE THE VARDS HS | Dogo 12 of | 7.50 | | | | Appearant Date: 10/26/1 |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-----------|----------|------|------|---------|----------|
| Classro | oom #224 (Regular Classroom) | | | | | | |
| Classro | oom #225 (Computer Lab) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,111 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 24 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 20 | SF | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 1,111 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 25 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,586 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 84 | SF | 7 | \$0 | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | \$0 | |
| Classro | oom #226 (Science) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 880 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 880 | SF | 7 | \$0 | |
| | Gas Line | 2nd Floor | 10 | EΑ | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 25 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Science Lab Elements | 2nd Floor | 72 | SF | 7 | \$0 | |
| | Science Lab Shower | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,286 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| | Work Sink | 2nd Floor | 5 | EA | 7 | \$0 | |
| Classro | oom #227 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 735 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 735 | SF | 6 | \$1,608 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,080 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| | | | | | | | |



| Item - Type | S LF 7 \$0 S SF 7 \$0 2 SF 7 \$0 1 EA 7 \$0 0 SF 7 \$0 | LF 7 SF 7 SF 7 | LF | | | m #229 (Regular Classroom) |
|---|--|----------------------|----|-------|-----------|---------------------------------|
| Ceiling - Lay-in 2nd Floor 735 SF 7 \$0 Doors - Side-lite 2nd Floor 12 SF 7 \$0 Doors - Steel Doors incl hw 2nd Floor 1 EA 7 \$0 Doors - Transom Window 2nd Floor 10 SF 7 \$0 Floor - Tile 2nd Floor 735 SF 7 \$0 | 5 SF 7 \$0 2 SF 7 \$0 1 EA 7 \$0 0 SF 7 \$0 | SF 7 SF 7 | | 16 | | |
| Doors - Side-lite 2nd Floor 12 SF 7 \$0 Doors - Steel Doors incl hw 2nd Floor 1 EA 7 \$0 Doors - Transom Window 2nd Floor 10 SF 7 \$0 Floor - Tile 2nd Floor 735 SF 7 \$0 | 2 SF 7 \$0 1 EA 7 \$0 0 SF 7 \$0 | SF 7 | SF | | 2nd Floor | Casework |
| Doors - Steel Doors incl hw 2nd Floor 1 EA 7 \$0 Doors - Transom Window 2nd Floor 10 SF 7 \$0 Floor - Tile 2nd Floor 735 SF 7 \$0 | I EA 7 \$0 O SF 7 \$0 | | | 735 | 2nd Floor | Ceiling - Lay-in |
| Doors - Transom Window 2nd Floor 10 SF 7 \$0 Floor - Tile 2nd Floor 735 SF 7 \$0 | SF 7 \$0 | FΔ 7 | SF | 12 | 2nd Floor | Doors - Side-lite |
| Floor - Tile 2nd Floor 735 SF 7 \$0 | | | EA | 1 | 2nd Floor | Doors - Steel Doors incl hw |
| | SF 7 \$0 | SF 7 | SF | 10 | 2nd Floor | Doors - Transom Window |
| Lighting Louis 40 EA 7 CO | | SF 7 | SF | 735 | 2nd Floor | Floor - Tile |
| Lighting - Lay-in 2nd Floor 18 EA 7 \$0 | B EA 7 \$0 | EA 7 | EA | 18 | 2nd Floor | Lighting - Lay-in |
| Marker Board 2nd Floor 16 LF 7 \$0 | 5 LF 7 \$0 | LF 7 | LF | 16 | 2nd Floor | Marker Board |
| Walls - Plaster/Drywall 2nd Floor 1,080 SF 7 \$0 |) SF 7 \$0 | SF 7 | SF | 1,080 | 2nd Floor | Walls - Plaster/Drywall |
| Walls - Structural Glazed Tile 2nd Floor 42 SF 7 \$0 | 2 SF 7 \$0 | SF 7 | SF | 42 | 2nd Floor | Walls - Structural Glazed Tile |
| sroom #230 (Science) | | | | | | m #230 (Science) |
| Casework 2nd Floor 16 LF 7 \$0 | 6 LF 7 \$0 | LF 7 | LF | 16 | 2nd Floor | |
| Ceiling - Plaster/Drywall 2nd Floor 925 SF 7 \$0 | SF 7 \$0 | SF 7 | SF | 925 | 2nd Floor | Ceiling - Plaster/Drywall |
| Doors - Steel Doors incl hw 2nd Floor 2 EA 7 \$0 | 2 EA 7 \$0 | EA 7 | EA | 2 | 2nd Floor | Doors - Steel Doors incl hw |
| Floor - Tile 2nd Floor 912 SF 7 \$0 | 2 SF 7 \$0 | SF 7 | SF | 912 | 2nd Floor | Floor - Tile |
| Floor - Tile Ceramic/ Porcelain 2nd Floor 13 SF 7 \$0 | 3 SF 7 \$0 | SF 7 | SF | 13 | 2nd Floor | Floor - Tile Ceramic/ Porcelain |
| Gas Line 2nd Floor 16 EA 7 \$0 | 6 EA 7 \$0 | EA 7 | EΑ | 16 | 2nd Floor | Gas Line |
| Lighting - Lay-in 2nd Floor 25 EA 7 \$0 | 5 EA 7 \$0 | EA 7 | EΑ | 25 | 2nd Floor | Lighting - Lay-in |
| Marker Board 2nd Floor 16 LF 7 \$0 | 5 LF 7 \$0 | LF 7 | LF | 16 | 2nd Floor | Marker Board |
| Science Lab Elements 2nd Floor 74 SF 7 \$0 | \$ SF 7 \$0 | SF 7 | SF | 74 | 2nd Floor | Science Lab Elements |
| Science Lab Shower 2nd Floor 1 EA 7 \$0 | EA 7 \$0 | EA 7 | EA | 1 | 2nd Floor | Science Lab Shower |
| Walls - Plaster/Drywall 2nd Floor 1,356 SF 7 \$0 | S SF 7 \$0 | SF 7 | SF | 1,356 | 2nd Floor | Walls - Plaster/Drywall |
| Walls - Structural Glazed Tile 2nd Floor 42 SF 7 \$0 | 2 SF 7 \$0 | SF 7 | SF | 42 | 2nd Floor | Walls - Structural Glazed Tile |
| Work Sink 2nd Floor 8 EA 7 \$0 | 3 EA 7 \$0 | EA 7 | EA | 8 | 2nd Floor | Work Sink |
| sroom #231 (Regular Classroom) | | | | | | m #231 (Regular Classroom) |
| Casework 2nd Floor 16 LF 7 \$0 | | | | 16 | | Casework |
| Ceiling - Lay-in 2nd Floor 735 SF 7 \$0 | S SF 7 \$0 | SF 7 | SF | 735 | 2nd Floor | Ceiling - Lay-in |
| Doors - Side-lite 2nd Floor 12 SF 7 \$0 | 2 SF 7 \$0 | SF 7 | SF | 12 | | Doors - Side-lite |
| Doors - Steel Doors incl hw 2nd Floor 1 EA 7 \$0 | EA 7 \$0 | EA 7 | EA | 1 | 2nd Floor | Doors - Steel Doors incl hw |
| Doors - Transom Window 2nd Floor 10 SF 7 \$0 | | SF 7 | SF | 10 | 2nd Floor | |
| Floor - Tile 2nd Floor 735 SF 7 \$0 | | SF 7 | SF | 735 | 2nd Floor | Floor - Tile |
| Lighting - Lay-in 2nd Floor 18 EA 7 \$0 | | EA 7 | EA | 18 | | |
| Marker Board 2nd Floor 16 LF 7 \$0 | | | | 16 | 2nd Floor | |
| Walls - Plaster/Drywall 2nd Floor 1,080 SF 7 \$0 | | SF 7 | SF | 1,080 | 2nd Floor | Walls - Plaster/Drywall |
| Walls - Structural Glazed Tile 2nd Floor 42 SF 7 \$0 | 2 SF 7 \$0 | SF 7 | SF | 42 | 2nd Floor | Walls - Structural Glazed Tile |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---------------------------------|-------------|----------|------|------|---------|----------|
| - | oom #233 (Regular Classroom) | 20040011 | quantity | Oint | Num | 0031 | Commonto |
| J10331 C | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 718 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 718 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,036 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| | | 2.13 . 155. | | 0. | · | Ψ | |
| Classro | oom #234 (Science Lab Level 3) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 925 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 24 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 7 | \$0 | |
| | Eye Wash Station | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 912 | SF | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 13 | SF | 7 | \$0 | |
| | Fume Hood | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Gas Line | 2nd Floor | 16 | EA | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 25 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Science Lab Elements | 2nd Floor | 74 | SF | 7 | \$0 | |
| | Science Lab Shower | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,356 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| | Work Sink | 2nd Floor | 8 | EA | 7 | \$0 | |
| Classro | oom #236 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 651 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 84 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 10 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 735 | SF | 6 | \$1,608 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | | | . 0 | - | | + • | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-----------|----------|------|------|---------|----------|
| Classro | oom #236 (Regular Classroom) | | | | | | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,080 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| Classro | oom #237 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 17 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 680 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 680 | SF | 6 | \$1,488 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,040 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| Classro | oom #238 (Regular Classroom) | | | | | | |
| | Casework | 2nd Floor | 17 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 2nd Floor | 600 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 80 | SF | 7 | \$0 | |
| | Doors - Side-lite | 2nd Floor | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 7 | \$0 | |
| | Floor - Tile | 2nd Floor | 680 | SF | 6 | \$1,488 | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,040 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 2nd Floor | 42 | SF | 7 | \$0 | |
| Classro | oom #317 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 718 | SF | 6 | \$2,156 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 718 | SF | 6 | \$1,571 | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,174 | SF | 6 | \$3,240 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--|-----------|----------|-------|--------|------------|----------|
| _ | pom #319 (Regular Classroom) | Loudion | Quantity | Oille | rturik | 0031 | Comments |
| Olassik | Casework | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 718 | SF | 6 | \$2,156 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 718 | SF | 6 | \$1,571 | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,174 | SF | 6 | \$3,240 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| Classe | | | | | | 40 | |
| Ciassro | com #320 (Regular Classroom) Casework | 3rd Floor | 16 | LF | 7 | \$0 | |
| | | 3rd Floor | 718 | SF | | | |
| | Ceiling - Lay-in | | | | 6 | \$2,156 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 7 | \$0 \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | | \$0 \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | | |
| | Floor - Tile | 3rd Floor | 718 | SF | 6 | \$1,571 | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,174 | SF | 6 | \$3,240 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| Classro | oom #321 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 680 | SF | 6 | \$2,042 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 680 | SF | 6 | \$1,488 | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,130 | SF | 6 | \$3,119 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| Classro | oom #322 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 680 | SF | 6 | \$2,042 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| | | | | | | | |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|--------------------------------|-----------|----------|------|------|---------|-------------|
| • | om #322 (Regular Classroom) | | | - '- | | | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 680 | SF | 6 | \$1,488 | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,130 | SF | 6 | \$3,119 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| lassro | om #323 (Computer Lab) | | | | | | |
| | Casework | 3rd Floor | 3 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 1,110 | SF | 6 | \$3,333 | |
| | Charging Station | 3rd Floor | 1 | EA | 6 | \$485 | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 16 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 1,110 | SF | 6 | \$2,429 | |
| | Lighting - Lay-in | 3rd Floor | 29 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,502 | SF | 6 | \$4,145 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 40 | SF | 7 | \$0 | |
| | Wireless System | 3rd Floor | 1 | EA | 6 | \$372 | |
| assro | om #324 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 680 | SF | 6 | \$2,042 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 680 | SF | 6 | \$1,488 | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,130 | SF | 6 | \$3,119 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| lassro | om #325 (Computer Lab) | | | | | | |
| | Casework | 3rd Floor | 3 | LF | 6 | \$76 | |
| | Ceiling - Lay-in | 3rd Floor | 1,110 | SF | 6 | \$3,333 | |
| | Charging Station | 3rd Floor | 1 | EA | 6 | \$485 | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 7 | \$0 | |
| | AF THE VARROLIO | D 40 | | | | | A 1 D - 1 - |



| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------|---------------------------------|-----------|----------|------|------|---------|----------|
| - | oom #325 (Computer Lab) | | | | | | |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 16 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 1,110 | SF | 6 | \$2,429 | |
| | Lighting - Lay-in | 3rd Floor | 28 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,502 | SF | 6 | \$4,145 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 40 | SF | 7 | \$0 | |
| | Wireless System | 3rd Floor | 1 | EA | 6 | \$372 | |
| ssrc | oom #326 (Science Lab Level 1) | | | | | | |
| | Casework | 3rd Floor | 33 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 1,225 | SF | 6 | \$3,679 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 6 | \$336 | |
| | Floor - Tile | 3rd Floor | 1,213 | SF | 6 | \$2,654 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor | 12 | SF | 7 | \$0 | |
| | Gas Line | 3rd Floor | 8 | EA | 6 | \$4,073 | |
| | Lighting - Lay-in | 3rd Floor | 26 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Science Lab Elements | 3rd Floor | 60 | SF | 6 | \$407 | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 6 | \$379 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,196 | SF | 6 | \$3,301 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 120 | SF | 7 | \$0 | |
| | Work Sink | 3rd Floor | 8 | EA | 6 | \$3,032 | |
| src | oom #327 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 10 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 735 | SF | 6 | \$2,207 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 735 | SF | 6 | \$1,608 | |
| | Lighting - Lay-in | 3rd Floor | 15 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Storage/ Closet | 3rd Floor | 22 | SF | 6 | \$160 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,174 | SF | 6 | \$3,240 | |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------|---------------------------------|-----------|----------|------|----------|---------|----------|
| _ | oom #327 (Regular Classroom) | | | • | | | |
| U iuuui. | Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| | | 0.4.1.66. | | ٠. | • | 40 | |
| Classro | oom #329 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 33 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 735 | SF | 6 | \$2,207 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 735 | SF | 6 | \$1,608 | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,174 | SF | 6 | \$3,240 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| Classro | oom #330 (Science Lab Level 1) | | | | | | |
| | Casework | 3rd Floor | 33 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 1,225 | SF | 6 | \$3,679 | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EΑ | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 16 | SF | 7 | \$0 | |
| | Eye Wash Station | 3rd Floor | 1 | EΑ | 6 | \$336 | |
| | Floor - Tile | 3rd Floor | 1,213 | SF | 6 | \$2,654 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor | 12 | SF | 6 | \$25 | |
| | Gas Line | 3rd Floor | 8 | EΑ | 6 | \$4,073 | |
| | Lighting - Lay-in | 3rd Floor | 26 | EΑ | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Science Lab Elements | 3rd Floor | 60 | SF | 6 | \$407 | |
| | Science Lab Shower | 3rd Floor | 1 | EΑ | 6 | \$379 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,196 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 120 | SF | 7 | \$0 | |
| | Work Sink | 3rd Floor | 8 | EA | 6 | \$3,032 | |
| Classro | oom #331 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 6 | \$404 | |
| | Ceiling - Lay-in | 3rd Floor | 735 | SF | 6 | \$2,207 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 735 | SF | 6 | \$1,608 | |
| | . 100. | ord Floor | 700 | ٥. | <u> </u> | Ψ1,000 | |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|------------|----------|-------|--------|---------|----------|
| _ | oom #331 (Regular Classroom) | Location | Quantity | Oilit | IXAIIK | 0031 | Comments |
| Classic | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,174 | SF | 6 | \$3,240 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| | Wallo Structural Glazed File | ord i looi | 20 | O. | , | ΨΟ | |
| Classro | oom #333 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 718 | SF | 6 | \$2,156 | |
| | Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EΑ | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| | Floor - Tile | 3rd Floor | 718 | SF | 6 | \$1,571 | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 1,174 | SF | 6 | \$3,240 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| Classro | oom #334 (Science Lab Level 2) | | | | | | |
| | Casework | 3rd Floor | 33 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 1,225 | SF | 6 | \$3,679 | |
| | Doors - Side-lite | 3rd Floor | 16 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 16 | SF | 7 | \$0 | |
| | Eye Wash Station | 3rd Floor | 1 | EΑ | 6 | \$336 | |
| | Floor - Tile | 3rd Floor | 1,213 | SF | 6 | \$2,654 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor | 12 | SF | 7 | \$0 | |
| | Fume Hood | 3rd Floor | 1 | EA | 6 | \$816 | |
| | Gas Line | 3rd Floor | 8 | EA | 6 | \$4,073 | |
| | Lighting - Lay-in | 3rd Floor | 26 | EΑ | 7 | \$0 | |
| | Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Science Lab Elements | 3rd Floor | 60 | SF | 6 | \$407 | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 6 | \$379 | |
| | Walls - Plaster/Drywall | 3rd Floor | 120 | SF | 6 | \$331 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 1,196 | SF | 7 | \$0 | |
| | Work Sink | 3rd Floor | 8 | EA | 6 | \$3,032 | |
| Classro | oom #336 (Regular Classroom) | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 3rd Floor | 718 | SF | 6 | \$2,156 | |
| | | | | | | | |



Category: Classrooms

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------------|-----------|----------|------|------|---------|--------------|
| lassroom #336 (Regular Classroom) | | | | | | |
| Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw | 3rd Floor | 1 | EΑ | 7 | \$0 | |
| Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| Floor - Tile | 3rd Floor | 718 | SF | 6 | \$1,571 | |
| Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| Walls - Plaster/Drywall | 3rd Floor | 1,174 | SF | 6 | \$3,240 | |
| Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| lassroom #337 (Regular Classroom) | | | | | | |
| Casework | 3rd Floor | 16 | LF | 6 | \$404 | |
| Ceiling - Lay-in | 3rd Floor | 680 | SF | 6 | \$2,042 | |
| Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| Floor - Tile | 3rd Floor | 680 | SF | 6 | \$1,488 | |
| Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| Walls - Plaster/Drywall | 3rd Floor | 1,130 | SF | 6 | \$3,119 | |
| Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 7 | \$0 | |
| assroom #338 (Regular Classroom) | | | | | | |
| Casework | 3rd Floor | 16 | LF | 7 | \$0 | |
| Ceiling - Lay-in | 3rd Floor | 1 | SF | 4 | \$14 | water damage |
| Ceiling - Lay-in | 3rd Floor | 679 | SF | 6 | \$2,039 | |
| Doors - Side-lite | 3rd Floor | 8 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | \$0 | |
| Doors - Transom Window | 3rd Floor | 8 | SF | 7 | \$0 | |
| Floor - Tile | 3rd Floor | 680 | SF | 6 | \$1,488 | |
| Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | \$0 | |
| Marker Board | 3rd Floor | 16 | LF | 7 | \$0 | |
| Walls - Plaster/Drywall | 3rd Floor | 1,130 | SF | 6 | \$3,119 | |
| Walls - Plaster/Drywall | 3rd Floor | 4 | SF | 5 | \$20 | damaged |
| Walls - Structural Glazed Tile | 3rd Floor | 20 | SF | 6 | \$63 | |
| | | | | | | |

Classrooms Subtotal: \$175,094

Building: Main



| p Item - Type | | Location | Quantity | Unit | Rank | Cost | Comments |
|----------------------|-----------------|-------------------------|----------|------|------|---------|--------------|
| inistrative Suites/O | ffices | | | | | | |
| Ceiling - Lay-in | | 1st FIr- Library Office | 117 | SF | 6 | \$351 | |
| Doors - Store Fr | ont | 1st Flr- Library Office | 1 | EA | 6 | \$1,208 | |
| Floor - Tile | | 1st FIr- Library Office | 117 | SF | 6 | \$256 | |
| Lighting - Lay-ir | 1 | 1st FIr- Library Office | 2 | EA | 7 | \$0 | |
| Power Distribution | on | 1st FIr- Library Office | 8 | EA | 7 | \$0 | |
| Walls - Plaster/[| Drywall | 1st FIr- Library Office | 376 | SF | 6 | \$1,038 | |
| Ceiling - Lay-in | | Cot Room 132I | 185 | SF | 7 | \$0 | |
| Doors - Steel Do | oors incl hw | Cot Room 132I | 1 | EA | 7 | \$0 | |
| Floor - Tile | | Cot Room 132I | 185 | SF | 7 | \$0 | |
| Lighting - Lay-ir | 1 | Cot Room 132I | 3 | EA | 7 | \$0 | |
| Power Distribution | on | Cot Room 132I | 12 | EA | 7 | \$0 | |
| Walls - Concrete | e Block | Cot Room 132I | 350 | SF | 7 | \$0 | |
| Walls - Plaster/[| Drywall | Cot Room 132I | 230 | SF | 7 | \$0 | |
| Work SInk | | Cot Room 132I | 1 | EA | 7 | \$0 | |
| Ceiling - Lay-in | | Rm 003D | 110 | SF | 7 | \$0 | |
| Doors - Side-lite | | Rm 003D | 10 | SF | 7 | \$0 | |
| Doors - Steel Do | oors incl hw | Rm 003D | 1 | EΑ | 7 | \$0 | |
| Floor - Tile | | Rm 003D | 110 | SF | 7 | \$0 | |
| Lighting - Lay-ir | 1 | Rm 003D | 2 | EA | 7 | \$0 | |
| Power Distribution | on | Rm 003D | 5 | EA | 7 | \$0 | |
| Walls - Concrete | e Block | Rm 003D | 290 | SF | 7 | \$0 | |
| Ceiling - Lay-in | | Rm 003E - CPD office | 115 | SF | 7 | \$0 | |
| Doors - Side-lite | | Rm 003E - CPD office | 30 | SF | 7 | \$0 | |
| Doors - Steel Do | pors incl hw | Rm 003E - CPD office | 1 | EA | 7 | \$0 | |
| Floor - Tile | | Rm 003E - CPD office | 115 | SF | 7 | \$0 | |
| Lighting - Lay-ir | n | Rm 003E - CPD office | 2 | EA | 7 | \$0 | |
| Power Distribution | on | Rm 003E - CPD office | 5 | EA | 7 | \$0 | |
| Walls - Concrete | e Block | Rm 003E - CPD office | 302 | SF | 7 | \$0 | |
| Ceiling - Lay-in | | Rm 004F - Men's Trainer | 77 | SF | 7 | \$0 | WIP |
| Ceiling - Lay-in | | Rm 004F - Men's Trainer | 8 | SF | 4 | \$112 | Missing tile |
| Doors - Steel Do | pors incl hw | Rm 004F - Men's Trainer | 1 | EA | 7 | \$0 | |
| Floor - Tile Cera | mic/ Porcelain | Rm 004F - Men's Trainer | 85 | SF | 7 | \$0 | |
| Lighting - Lay-ir | n | Rm 004F - Men's Trainer | 1 | EA | 7 | \$0 | |
| Power Distribution | on | Rm 004F - Men's Trainer | 6 | EA | 7 | \$0 | |
| Walls - Concrete | e Block | Rm 004F - Men's Trainer | 134 | SF | 7 | \$0 | |
| Walls - Tile Cera | amic/ Porcelain | Rm 004F - Men's Trainer | 134 | SF | 7 | \$0 | |
| Ceiling - Lay-in | | Rm 004G - Coach office | 88 | SF | 7 | \$0 | |
| Doors - Side-lite | | Rm 004G - Coach office | 28 | SF | 7 | \$0 | |
| Doors - Steel Do | pors incl hw | Rm 004G - Coach office | 1 | EA | 7 | \$0 | |



| roup Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------------|---|----------|------|------|---------|-----------------------------|
| dministrative Suites/Offices | | | | | | |
| Floor - Tile | Rm 004G - Coach office | 88 | SF | 7 | \$0 | |
| Lighting - Lay-in | Rm 004G - Coach office | 1 | EA | 7 | \$0 | |
| Power Distribution | Rm 004G - Coach office | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | Rm 004G - Coach office | 226 | SF | 7 | \$0 | |
| Ceiling - Exposed | Rm 005A - Pool office | 177 | SF | 6 | \$263 | Hairline cracks in concrete |
| Doors - Side-lite | Rm 005A - Pool office | 42 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw | Rm 005A - Pool office | 1 | EΑ | 7 | \$0 | |
| Floor - Tile | Rm 005A - Pool office | 177 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | Rm 005A - Pool office | 3 | EA | 7 | \$0 | |
| Power Distribution | Rm 005A - Pool office | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | Rm 005A - Pool office | 350 | SF | 7 | \$0 | |
| Ceiling - Exposed | Rm 005B - Pool office | 177 | SF | 6 | \$263 | Hairline cracks in concrete |
| Doors - Side-lite | Rm 005B - Pool office | 42 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw | Rm 005B - Pool office | 1 | EA | 7 | \$0 | |
| Floor - Tile | Rm 005B - Pool office | 177 | SF | 7 | \$0 | |
| Lighting - Pendent/Surface | Rm 005B - Pool office | 3 | EΑ | 7 | \$0 | |
| Power Distribution | Rm 005B - Pool office | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | Rm 005B - Pool office | 350 | SF | 7 | \$0 | |
| Ceiling - Lay-in | Rm 006A - Coach office | 88 | SF | 7 | \$0 | |
| Doors - Side-lite | Rm 006A - Coach office | 28 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw | Rm 006A - Coach office | 1 | EA | 7 | \$0 | |
| Floor - Tile | Rm 006A - Coach office | 88 | SF | 7 | \$0 | |
| Lighting - Lay-in | Rm 006A - Coach office | 1 | EA | 7 | \$0 | |
| Power Distribution | Rm 006A - Coach office | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | Rm 006A - Coach office | 226 | SF | 7 | \$0 | |
| Ceiling - Lay-in | Rm 006B - Women's Trainer | 85 | SF | 7 | \$0 | WIP |
| Doors - Steel Doors incl hw | Rm 006B - Women's Trainer | 1 | EA | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain | Rm 006B - Women's Trainer | 85 | SF | 7 | \$0 | |
| Lighting - Lay-in | Rm 006B - Women's Trainer | 1 | EA | 7 | \$0 | |
| Power Distribution | Rm 006B - Women's Trainer | 6 | EA | 7 | \$0 | |
| Walls - Concrete Block | Rm 006B - Women's Trainer | 134 | SF | 7 | \$0 | |
| Walls - Tile Ceramic/ Porcelain | Rm 006B - Women's Trainer | 134 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall | Rm 100B- Library's Community Resource Rm | 362 | SF | 6 | \$1,253 | |
| Doors - Side-lite | Rm 100B- Library's Community Resource Rm | 148 | SF | 6 | \$2,474 | |
| Doors - Store Front | Rm 100B- Library's Community Resource Rm | 1 | EA | 6 | \$1,208 | |



| o Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------------------------|--|----------|------|------|---------|-------------|
| nistrative Suites/Offices | | | | | | |
| Floor - Carpet | Rm 100B- Library's Community Resource Rm | 362 | SF | 6 | \$771 | |
| Lighting - Lay-in | Rm 100B- Library's Community Resource Rm | 8 | EA | 7 | \$0 | |
| Power Distribution | Rm 100B- Library's Community Resource Rm | 4 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | Rm 100B- Library's Community Resource Rm | 464 | SF | 6 | \$1,281 | |
| Work Sink | Rm 100B- Library's Community Resource Rm | 1 | EA | 6 | \$508 | |
| Ceiling - Lay-in | Rm 100F- Library Work Rm | 432 | SF | 6 | \$1,297 | |
| Doors - Side-lite | Rm 100F- Library Work Rm | 109 | SF | 7 | \$0 | |
| Doors - Store Front | Rm 100F- Library Work Rm | 2 | EA | 7 | \$0 | |
| Doors - Transom Window | Rm 100F- Library Work Rm | 6 | SF | 7 | \$0 | |
| Floor - Tile | Rm 100F- Library Work Rm | 432 | SF | 6 | \$945 | |
| Lighting - Lay-in | Rm 100F- Library Work Rm | 11 | EA | 7 | \$0 | |
| Power Distribution | Rm 100F- Library Work Rm | 24 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | Rm 100F- Library Work Rm | 676 | SF | 6 | \$1,866 | |
| Work Slnk | Rm 100F- Library Work Rm | 1 | EA | 6 | \$508 | |
| Ceiling - Lay-in | Rm 103A- Lighting Control Rm for Auditorium/Gym | 163 | SF | 6 | \$489 | |
| Doors - Steel Doors incl hw | Rm 103A- Lighting Control Rm for Auditorium/Gym | 1 | EA | 6 | \$301 | |
| Floor - Tile | Rm 103A- Lighting Control Rm for Auditorium/Gym | 163 | SF | 6 | \$357 | |
| Lighting - Lay-in | Rm 103A- Lighting Control Rm for Auditorium/Gym | 2 | EA | 7 | \$0 | |
| Lighting - Pendent/Surface | Rm 103A- Lighting Control Rm for Auditorium/Gym | 1 | EA | 6 | | Track light |
| Power Distribution | Rm 103A- Lighting Control Rm for Auditorium/Gym | 12 | EA | 7 | \$0 | |
| Walls - Concrete Block | Rm 103A- Lighting Control Rm for Auditorium/Gym | 455 | SF | 6 | \$1,334 | |
| Ceiling - Lay-in | Rm 103A1- Spot & Follow Rm for Auditorium/Gym | 178 | SF | 6 | \$535 | |
| Doors - Steel Doors incl hw | Rm 103A1- Spot & Follow Rm for Auditorium/Gym | 1 | EA | 6 | \$301 | |
| Floor - Tile | Rm 103A1- Spot & Follow Rm for Auditorium/Gym | 178 | SF | 6 | \$389 | |
| Lighting - Lay-in | Rm 103A1- Spot & Follow Rm for Auditorium/Gym | 2 | EA | 7 | \$0 | |



| up li | tem - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|-----------------------------|--|----------|------|------|---------|-------------|
| ninistr | rative Suites/Offices | | | | | | |
| L | Lighting - Pendent/Surface | Rm 103A1- Spot & Follow Rm for Auditorium/Gym | 1 | EA | 6 | \$124 | Track light |
| F | Power Distribution | Rm 103A1- Spot & Follow Rm for Auditorium/Gym | 14 | EA | 7 | \$0 | |
| ١ | Walls - Concrete Block | Rm 103A1- Spot & Follow Rm for Auditorium/Gym | 485 | SF | 6 | \$1,422 | |
| (| Ceiling - Lay-in | Rm 103B- ADA Balcony Seating Area for Auditorium/Gym | 237 | SF | 6 | \$712 | |
| [| Doors - Steel Doors incl hw | Rm 103B- ADA Balcony Seating Area for Auditorium/Gym | 4 | EA | 6 | \$1,204 | |
| | Floor - Tile | Rm 103B- ADA Balcony Seating Area for Auditorium/Gym | 237 | SF | 6 | \$519 | |
| L | Lighting - Lay-in | Rm 103B- ADA Balcony Seating Area for Auditorium/Gym | 6 | EA | 7 | \$0 | |
| | Power Distribution | Rm 103B- ADA Balcony Seating Area for Auditorium/Gym | 2 | EA | 7 | \$0 | |
| 9 | Storage/ Closet | Rm 103B- ADA Balcony Seating Area for Auditorium/Gym | 230 | SF | 6 | \$1,668 | Rm 103B1 |
| ١ | Walls - Concrete Block | Rm 103B- ADA Balcony Seating Area for Auditorium/Gym | 472 | SF | 6 | \$1,384 | |
| (| Ceiling - Lay-in | Rm 105A- ADA Balcony Seating Area for Auditorium/Gym | 92 | SF | 6 | \$276 | |
| (| Ceiling - Plaster/Drywall | Rm 105A- ADA Balcony Seating Area for Auditorium/Gym | 84 | SF | 6 | \$291 | |
| [| Doors - Steel Doors incl hw | Rm 105A- ADA Balcony Seating Area for Auditorium/Gym | 4 | EA | 6 | \$1,204 | |
| | Floor - Tile | Rm 105A- ADA Balcony Seating Area for Auditorium/Gym | 176 | SF | 6 | \$385 | |
| L | Lighting - Lay-in | Rm 105A- ADA Balcony Seating Area for Auditorium/Gym | 4 | EA | 7 | \$0 | |
| F | Power Distribution | Rm 105A- ADA Balcony Seating Area for Auditorium/Gym | 2 | EA | 7 | \$0 | |
| ١ | Walls - Concrete Block | Rm 105A- ADA Balcony Seating Area for Auditorium/Gym | 337 | SF | 6 | \$988 | |
| (| Ceiling - Lay-in | Rm 105B- Sound Rm for Auditorium/Gym | 163 | SF | 6 | \$489 | |
| | Doors - Steel Doors incl hw | Rm 105B- Sound Rm for Auditorium/Gym | 1 | EA | 6 | \$301 | |
| F | Floor - Tile | Rm 105B- Sound Rm for Auditorium/Gym | 163 | SF | 6 | \$357 | |
| L | Lighting - Lay-in | Rm 105B- Sound Rm for Auditorium/Gym | 2 | EA | 7 | \$0 | |



| Group Ite | m - Type | Location | Quantity | Unit | Rank | Cost | Commen |
|-----------|---------------------------|---|----------|------|------|---------|-------------|
| dministra | ive Suites/Offices | | | | | | |
| Lig | hting - Pendent/Surface | Rm 105B- Sound Rm for Auditorium/Gym | 1 | EA | 6 | \$124 | Track light |
| Po | wer Distribution | Rm 105B- Sound Rm for Auditorium/Gym | 14 | EA | 7 | \$0 | |
| W | alls - Concrete Block | Rm 105B- Sound Rm for Auditorium/Gym | 455 | SF | 6 | \$1,334 | |
| Ce | iling - Lay-in | Rm 113-Security Office | 66 | SF | 6 | \$198 | |
| Do | ors - Steel Doors incl hw | Rm 113-Security Office | 1 | EA | 6 | \$301 | |
| Flo | oor - Tile | Rm 113-Security Office | 66 | SF | 6 | \$144 | |
| Lig | hting - Lay-in | Rm 113-Security Office | 2 | EA | 7 | \$0 | |
| Po | wer Distribution | Rm 113-Security Office | 6 | EA | 7 | \$0 | |
| W | alls - Concrete Block | Rm 113-Security Office | 432 | SF | 6 | \$1,266 | |
| Ce | iling - Lay-in | Rm 115- Police Office | 66 | SF | 6 | \$198 | |
| Do | ors - Steel Doors incl hw | Rm 115- Police Office | 1 | EA | 6 | \$301 | |
| Flo | oor - Tile | Rm 115- Police Office | 66 | SF | 6 | \$144 | |
| Lig | hting - Lay-in | Rm 115- Police Office | 2 | EΑ | 7 | \$0 | |
| Po | wer Distribution | Rm 115- Police Office | 6 | EΑ | 7 | \$0 | |
| Sto | orage/ Closet | Rm 115- Police Office | 66 | SF | 6 | \$479 | |
| W | alls - Concrete Block | Rm 115- Police Office | 424 | SF | 6 | \$1,243 | 113A |
| Ce | iling - Lay-in | Rm 120- College Career Center | 320 | SF | 6 | \$961 | |
| Do | ors - Steel Doors incl hw | Rm 120- College Career Center | 1 | EA | 6 | \$301 | |
| Flo | oor - Carpet | Rm 120- College Career Center | 320 | SF | 6 | \$682 | |
| Lig | hting - Lay-in | Rm 120- College Career Center | 4 | EA | 7 | \$0 | |
| Po | wer Distribution | Rm 120- College Career Center | 12 | EA | 7 | \$0 | |
| W | alls - Concrete Block | Rm 120- College Career Center | 496 | SF | 6 | \$1,454 | |
| W | alls - Plaster/Drywall | Rm 120- College Career Center | 165 | SF | 6 | \$455 | |
| Ce | iling - Lay-in | Rm 120A- Case Manager | 98 | SF | 6 | \$294 | |
| Do | ors - Steel Doors incl hw | Rm 120A- Case Manager | 1 | EA | 6 | \$301 | |
| Flo | oor - Carpet | Rm 120A- Case Manager | 98 | SF | 6 | \$209 | |
| Lig | hting - Lay-in | Rm 120A- Case Manager | 2 | EA | 7 | \$0 | |
| Po | wer Distribution | Rm 120A- Case Manager | 8 | EA | 7 | \$0 | |
| W | alls - Plaster/Drywall | Rm 120A- Case Manager | 356 | SF | 6 | \$983 | |
| Ce | iling - Lay-in | Rm 122- Mail/Copy Work Rm | 385 | SF | 6 | \$1,156 | |
| Do | ors - Steel Doors incl hw | Rm 122- Mail/Copy Work Rm | 3 | EA | 6 | \$903 | |
| Flo | oor - Carpet | Rm 122- Mail/Copy Work Rm | 385 | SF | 6 | \$820 | |
| Lig | hting - Lay-in | Rm 122- Mail/Copy Work Rm | 6 | EA | 7 | \$0 | |
| Po | wer Distribution | Rm 122- Mail/Copy Work Rm | 12 | EA | 7 | \$0 | |
| W | alls - Plaster/Drywall | Rm 122- Mail/Copy Work Rm | 769 | SF | 6 | \$2,122 | |



| Group Item - Type | Location | Quantity | Unit | Rank | Cost | С |
|------------------------------|---|----------|------|------|---------|---|
| dministrative Suites/Offices | | | | | | |
| Work SInk | Rm 122- Mail/Copy Work Rm | 1 | EA | 6 | \$508 | |
| Ceiling - Lay-in | Rm 124- Main Office North | 737 | SF | 6 | \$2,213 | |
| Doors - Side-lite | Rm 124- Main Office North | 1 | SF | 6 | \$17 | |
| Doors - Store Front | Rm 124- Main Office North | 1 | EΑ | 6 | \$1,208 | |
| Floor - Carpet | Rm 124- Main Office North | 737 | SF | 6 | \$1,570 | |
| Lighting - Lay-in | Rm 124- Main Office North | 13 | EΑ | 7 | \$0 | |
| Power Distribution | Rm 124- Main Office North | 22 | EΑ | 7 | \$0 | |
| Walls - Plaster/Drywall | Rm 124- Main Office North | 2,004 | SF | 6 | \$5,531 | |
| Ceiling - Lay-in | Rm 124C- Principal | 205 | SF | 6 | \$616 | |
| Doors - Steel Doors incl hw | Rm 124C- Principal | 1 | EΑ | 6 | \$301 | |
| Floor - Carpet | Rm 124C- Principal | 205 | SF | 6 | \$437 | |
| Lighting - Lay-in | Rm 124C- Principal | 4 | EA | 7 | \$0 | |
| Power Distribution | Rm 124C- Principal | 8 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | Rm 124C- Principal | 517 | SF | 6 | \$1,427 | |
| Ceiling - Lay-in | Rm 124D- Asst Principal | 151 | SF | 6 | \$453 | |
| Doors - Steel Doors incl hw | Rm 124D- Asst Principal | 1 | EΑ | 6 | \$301 | |
| Floor - Carpet | Rm 124D- Asst Principal | 151 | SF | 6 | \$322 | |
| Lighting - Lay-in | Rm 124D- Asst Principal | 2 | EA | 7 | \$0 | |
| Power Distribution | Rm 124D- Asst Principal | 6 | EΑ | 7 | \$0 | |
| Walls - Plaster/Drywall | Rm 124D- Asst Principal | 459 | SF | 6 | \$1,267 | |
| Ceiling - Lay-in | Rm 124E- Counselor | 151 | SF | 6 | \$453 | |
| Doors - Steel Doors incl hw | Rm 124E- Counselor | 1 | EΑ | 6 | \$301 | |
| Floor - Carpet | Rm 124E- Counselor | 151 | SF | 6 | \$322 | |
| Lighting - Lay-in | Rm 124E- Counselor | 2 | EΑ | 7 | \$0 | |
| Power Distribution | Rm 124E- Counselor | 6 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | Rm 124E- Counselor | 459 | SF | 6 | \$1,267 | |
| Ceiling - Lay-in | Rm 124F- IB & Diploma Career Coordinator | 169 | SF | 6 | \$508 | |
| Doors - Steel Doors incl hw | Rm 124F- IB & Diploma Career Coordinator | 1 | EA | 6 | \$301 | |
| Floor - Carpet | Rm 124F- IB & Diploma Career Coordinator | 169 | SF | 6 | \$360 | |
| Lighting - Lay-in | Rm 124F- IB & Diploma Career Coordinator | 2 | EA | 7 | \$0 | |
| Power Distribution | Rm 124F- IB & Diploma Career Coordinator | 6 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | Rm 124F- IB & Diploma Career Coordinator | 490 | SF | 6 | \$1,352 | |
| Ceiling - Lay-in | Rm 124G- Conference Rm | 224 | SF | 6 | \$673 | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|-----------------------------|------------------------------------|----------|------|------|---------|--|
| Admini | strative Suites/Offices | | | | | | |
| | Doors - Steel Doors incl hw | Rm 124G- Conference Rm | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | Rm 124G- Conference Rm | 224 | SF | 6 | \$477 | |
| | Lighting - Lay-in | Rm 124G- Conference Rm | 6 | EA | 7 | \$0 | |
| | Power Distribution | Rm 124G- Conference Rm | 12 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 124G- Conference Rm | 540 | SF | 6 | \$1,490 | 2 walls have acoustic material on them |
| | Ceiling - Lay-in | Rm 125A- Kitchen Manager Office | 151 | SF | 6 | \$453 | |
| | Doors - Side-lite | Rm 125A- Kitchen Manager Office | 26 | SF | 6 | \$435 | |
| | Doors - Steel Doors incl hw | Rm 125A- Kitchen Manager Office | 1 | EA | 6 | \$301 | |
| | Floor - Tile | Rm 125A- Kitchen Manager Office | 151 | SF | 6 | \$330 | |
| | Lighting - Lay-in | Rm 125A- Kitchen Manager Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | Rm 125A- Kitchen Manager Office | 10 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Rm 125A- Kitchen Manager Office | 459 | SF | 6 | \$1,346 | |
| | Ceiling - Lay-in | Rm 126- Main Office South | 737 | SF | 6 | \$2,213 | |
| | Doors - Side-lite | Rm 126- Main Office South | 1 | SF | 6 | \$17 | |
| | Doors - Store Front | Rm 126- Main Office South | 1 | EA | 6 | \$1,208 | |
| | Floor - Carpet | Rm 126- Main Office South | 737 | SF | 6 | \$1,570 | |
| | Lighting - Lay-in | Rm 126- Main Office South | 13 | EA | 7 | \$0 | |
| | Power Distribution | Rm 126- Main Office South | 22 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 126- Main Office South | 2,004 | SF | 6 | \$5,531 | |
| | Ceiling - Lay-in | Rm 126C- Principal | 205 | SF | 6 | \$616 | |
| | Doors - Steel Doors incl hw | Rm 126C- Principal | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | Rm 126C- Principal | 205 | SF | 6 | \$437 | |
| | Lighting - Lay-in | Rm 126C- Principal | 4 | EA | 7 | \$0 | |
| | Power Distribution | Rm 126C- Principal | 8 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 126C- Principal | 517 | SF | 6 | \$1,427 | |
| | Ceiling - Lay-in | Rm 126D- Asst Principal | 151 | SF | 6 | \$453 | |
| | Doors - Steel Doors incl hw | Rm 126D- Asst Principal | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | Rm 126D- Asst Principal | 151 | SF | 6 | \$322 | |
| | Lighting - Lay-in | Rm 126D- Asst Principal | 2 | EA | 7 | \$0 | |
| | Power Distribution | Rm 126D- Asst Principal | 6 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 126D- Asst Principal | 459 | SF | 6 | \$1,267 | |
| | Ceiling - Lay-in | Rm 126F- Operations Manager Office | 169 | SF | 6 | \$508 | |
| | Doors - Steel Doors incl hw | Rm 126F- Operations Manager Office | 1 | EA | 6 | \$301 | |
| | Floor - Carpet | Rm 126F- Operations Manager Office | 169 | SF | 6 | \$360 | |
| | Lighting - Lay-in | Rm 126F- Operations Manager Office | 2 | EA | 7 | \$0 | |
| | Power Distribution | Rm 126F- Operations Manager Office | 6 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 126F- Operations Manager Office | 490 | SF | 6 | \$1,352 | |
| | | | | | | | |



| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|------|--------------------------------|-------------------------------|----------|------|------|---------|--|
| lmin | istrative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | Rm 126G- Conference Rm | 224 | SF | 6 | \$673 | |
| | Doors - Steel Doors incl hw | Rm 126G- Conference Rm | 1 | EΑ | 6 | \$301 | |
| | Floor - Carpet | Rm 126G- Conference Rm | 224 | SF | 6 | \$477 | |
| | Lighting - Lay-in | Rm 126G- Conference Rm | 6 | EA | 7 | \$0 | |
| | Power Distribution | Rm 126G- Conference Rm | 12 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 126G- Conference Rm | 540 | SF | 6 | \$1,490 | 2 walls have acoustic material on them |
| | Ceiling - Lay-in | Rm 128- Mail/Copy Work Rm | 385 | SF | 6 | \$1,156 | |
| | Doors - Steel Doors incl hw | Rm 128- Mail/Copy Work Rm | 3 | EA | 6 | \$903 | |
| | Floor - Carpet | Rm 128- Mail/Copy Work Rm | 385 | SF | 6 | \$820 | |
| | Lighting - Lay-in | Rm 128- Mail/Copy Work Rm | 6 | EA | 7 | \$0 | |
| | Power Distribution | Rm 128- Mail/Copy Work Rm | 12 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 128- Mail/Copy Work Rm | 769 | SF | 6 | \$2,122 | |
| | Work SInk | Rm 128- Mail/Copy Work Rm | 1 | EΑ | 6 | \$508 | |
| | Ceiling - Lay-in | Rm 132E - Media Center office | 70 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Rm 132E - Media Center office | 1 | EΑ | 7 | \$0 | |
| | Floor - Tile | Rm 132E - Media Center office | 70 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Rm 132E - Media Center office | 1 | EΑ | 7 | \$0 | |
| | Power Distribution | Rm 132E - Media Center office | 8 | EΑ | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 132E - Media Center office | 320 | SF | 7 | \$0 | |
| | Work SInk | Rm 132E - Media Center office | 1 | EΑ | 7 | \$0 | |
| | Ceiling - Lay-in | Rm 200A - Department Office | 347 | SF | 7 | \$0 | |
| | Doors - Side-lite | Rm 200A - Department Office | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Rm 200A - Department Office | 2 | EΑ | 7 | \$0 | |
| | Floor - Tile | Rm 200A - Department Office | 347 | SF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Rm 200A - Department Office | 16 | EΑ | 7 | \$0 | |
| | Power Distribution | Rm 200A - Department Office | 32 | EΑ | 7 | \$0 | |
| | Storage/ Closet | Rm 200A - Department Office | 135 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 200A - Department Office | 677 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | Rm 215 - Attendance Office | 240 | SF | 7 | \$0 | |
| | Doors - Side-lite | Rm 215 - Attendance Office | 12 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Rm 215 - Attendance Office | 2 | EA | 7 | \$0 | |
| | Doors - Transom Window | Rm 215 - Attendance Office | 10 | SF | 7 | \$0 | |
| | Floor - Tile | Rm 215 - Attendance Office | 240 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Rm 215 - Attendance Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | Rm 215 - Attendance Office | 6 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 215 - Attendance Office | 304 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Rm 215 - Attendance Office | 42 | SF | 7 | \$0 | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|-----------------------------|----------------------------|----------|------|------|---------|----------|
| - | istrative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | Rm 216 - Department Office | 738 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Rm 216 - Department Office | 1 | EA | 7 | \$0 | |
| | Floor - Tile | Rm 216 - Department Office | 738 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Rm 216 - Department Office | 12 | EA | 7 | \$0 | |
| | Power Distribution | Rm 216 - Department Office | 56 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 216 - Department Office | 1,052 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | Rm 315- Attendance Office | 195 | SF | 6 | \$586 | |
| | Doors - Side-lite | Rm 315- Attendance Office | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Rm 315- Attendance Office | 1 | EA | 6 | \$301 | |
| | Doors - Transom Window | Rm 315- Attendance Office | 8 | SF | 7 | \$0 | |
| | Floor - Tile | Rm 315- Attendance Office | 195 | SF | 6 | \$427 | |
| | Lighting - Lay-in | Rm 315- Attendance Office | 4 | EA | 7 | \$0 | |
| | Power Distribution | Rm 315- Attendance Office | 16 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Rm 315- Attendance Office | 452 | SF | 6 | \$1,325 | |
| | Walls - Plaster/Drywall | Rm 315- Attendance Office | 150 | SF | 6 | \$414 | |
| | Ceiling - Lay-in | Rm 316- Work Room | 740 | SF | 6 | \$2,222 | |
| | Doors - Hardware | Rm 316- Work Room | 8 | EA | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Rm 316- Work Room | 1 | EA | 7 | \$0 | |
| | Doors - Transom Window | Rm 316- Work Room | 8 | SF | 7 | \$0 | |
| | Floor - Tile | Rm 316- Work Room | 740 | SF | 6 | \$1,619 | |
| | Lighting - Lay-in | Rm 316- Work Room | 12 | EA | 7 | \$0 | |
| | Power Distribution | Rm 316- Work Room | 58 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 316- Work Room | 1,177 | SF | 6 | \$3,248 | |
| linic | | | | | | | |
| | Ceiling - Lay-in | Exam Room 132G | 144 | SF | 7 | \$0 | |
| | Doors - Side-lite | Exam Room 132G | 10 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Exam Room 132G | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | Exam Room 132G | 144 | SF | 7 | \$0 | VCT |
| | Lighting - Lay-in | Exam Room 132G | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Exam Room 132G | 100 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | Exam Room 132G | 357 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | Exam Room 132H | 124 | SF | 7 | \$0 | |
| | Doors - Side-lite | Exam Room 132H | 10 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Exam Room 132H | 1 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | Exam Room 132H | 124 | SF | 7 | \$0 | VCT |
| | Lighting - Lay-in | Exam Room 132H | 2 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Exam Room 132H | 87 | SF | 7 | \$0 | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------------|---------------------------------|----------|------|------|---------|--------------------|
| Clinic | | | | | | | |
| | Walls - Plaster/Drywall | Exam Room 132H | 370 | SF | 7 | \$0 | |
| Gymnas | sia | | | | | | |
| | Bleacher Seating | Basement | 600 | EA | 7 | \$0 | Recessed |
| | Ceiling - Exposed | Basement | 5,635 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Basement | 12 | EΑ | 7 | \$0 | |
| | Floor - Tile/Sheet | Basement | 2,304 | SF | 7 | \$0 | |
| | Floor - Wood | Basement | 3,331 | SF | 7 | \$0 | |
| | Lighting - Metal Halide/Sodium Vapor | Basement | 58 | EΑ | 7 | \$0 | |
| | Main Floor Seating | Basement | 720 | EΑ | 7 | \$0 | Recessed |
| | Scoreboards | Basement | 1 | EA | 7 | \$0 | |
| | Sound System | Basement | 1 | EA | 7 | \$0 | |
| | Stage | Basement | 2,304 | SF | 7 | \$0 | |
| | Stage Curtain | Basement | 5 | EA | 7 | \$0 | |
| | Stage Lift | Basement | 1 | EA | 7 | \$0 | Located in Stair G |
| | Stage Lighting System | Basement | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Basement | 3,536 | SF | 7 | \$0 | |
| | Walls - Masonry | Basement | 6,656 | SF | 7 | \$0 | |
| | Walls - Metal Panel | Basement | 7,360 | SF | 7 | \$0 | |
| Kitchen | | | | | | | |
| | Ceiling - Lay-in | Rm 125 | 1,188 | SF | 6 | \$3,568 | |
| | Doors - Steel Doors incl hw | Rm 125 | 5 | ĒΑ | 6 | \$1,505 | |
| | Floor - Tile Ceramic/ Porcelain | Rm 125 | 1,188 | SF | 6 | \$2,514 | |
| | Lighting - Lay-in | Rm 125 | 17 | EA | 7 | \$0 | |
| | Storage/ Closet | Rm 125 | 300 | SF | 6 | \$2,175 | 125F -Dry storage |
| | Walls - Concrete Block | Rm 125 | 1,242 | SF | 6 | \$3,641 | , 0 |
| Library | | | | | | | |
| | Casework | 132 - Media Center | 90 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | 132 - Media Center | 1,508 | SF | 7 | \$0 | |
| | Doors - Side-lite | 132 - Media Center | 80 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 132 - Media Center | 3 | EA | 7 | \$0 | |
| | Floor - Tile/Sheet | 132 - Media Center | 1,508 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 132 - Media Center | 24 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 132 - Media Center | 500 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 132 - Media Center | 1,400 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 132 - Media Center | 35 | SF | 7 | \$0 | |
| | Ceiling - Lay-in | 1st Flr- Chicago Public Library | 2,000 | SF | 6 | \$6,006 | |



| Celling - Plaster/Drywall |
|--|
| Ceiling - Plaster/Drywall |
| Doors - Side-lite 1st Fir- Chicago Public Library 86 SF 6 \$1,438 Doors - Store Front 1st Fir- Chicago Public Library 4 EA 6 \$4,833 Doors - Store Front 1st Fir- Chicago Public Library 30 SF 6 \$5,08 Floor - Carpet 1st Fir- Chicago Public Library 5,235 SF 6 \$5,08 Floor - Carpet 1st Fir- Chicago Public Library 5,235 SF 6 \$11,154 needs to be cleaned Floor - Tile Ceramic/ Porcelain 1st Fir- Chicago Public Library 65 SF 6 \$11,154 needs to be cleaned Floor - Tile Ceramic/ Porcelain 1st Fir- Chicago Public Library 65 SF 6 \$138 by restrooms Lighting - Lay-in 1st Fir- Chicago Public Library 50 EA 7 \$0 |
| Doors - Store Front 1st FIr - Chicago Public Library 30 SF 6 \$508 Floor - Carpet 1st FIr - Chicago Public Library 5,235 SF 6 \$508 Floor - Carpet 1st FIr - Chicago Public Library 5,235 SF 6 \$11,154 needs to be cleaned Floor - Tile Ceramic/ Porcelain 1st FIr - Chicago Public Library 65 SF 6 \$138 by restrooms Lighting - Lay-in 1st FIr - Chicago Public Library 50 EA 7 \$0 Lighting - Pendent/Surface 1st FIr - Chicago Public Library 110 EA 7 \$0 Storage/ Closet 1st FIr - Chicago Public Library 150 SF 6 \$1,131 16B Walls - Masonry 1st FIr - Chicago Public Library 1,892 SF 6 \$7,000 Walls - Plaster/Drywall 1st FIr - Chicago Public Library 1,892 SF 6 \$5,222 Locker/Shower Room Locker/Shower Room Men's gym & team lockers/showers 1,153 SF 6 \$4,518 Benches, ped mounted Men's gym & team lockers/showers 1,153 SF 6 \$1,171 Hairline cracks in concrete Doors - Steel Doors incl hw Men's gym & team lockers/showers 4 EA 7 \$0 Floor Drain Men's gym & team lockers/showers 4 EA 7 \$0 Floor Drain |
| Doors - Transom Window 1st Fir - Chicago Public Library 5,235 SF 6 \$11,154 needs to be cleaned Floor - Carpet 1st Fir - Chicago Public Library 5,235 SF 6 \$11,154 needs to be cleaned Floor - Tile Ceramic/ Porcelain 1st Fir - Chicago Public Library 65 SF 6 \$138 by restrooms Lighting - Lay-in 1st Fir - Chicago Public Library 50 EA 7 \$0 Lighting - Pendent/Surface 1st Fir - Chicago Public Library 110 EA 7 \$0 Storage/ Closet 1st Fir - Chicago Public Library 156 SF 6 \$1,131 116B Walls - Masonry Walls - Masonry Walls - Plaster/Drywall 1st Fir - Chicago Public Library 1,892 SF 6 \$7,000 Walls - Plaster/Drywall Locker/Shower Room Locker/Shower Room Men's gym & team lockers/showers 1,153 SF 6 \$4,518 Benches, ped mounted Men's gym & team lockers/showers 1,153 SF 6 \$1,715 Hairline cracks in concrete Doors - Steel Doors incl hw Men's gym & team lockers/showers 4 EA 7 \$0 Floor Drain |
| Floor - Tile Ceramic/ Porcelain Lighting - Lay-in Lighting - Pendent/Surface 1st Flr- Chicago Public Library Lighting - Pendent/Surface 1st Flr- Chicago Public Library 110 EA 7 \$0 Lighting - Pendent/Surface 1st Flr- Chicago Public Library 110 EA 7 \$0 Storage/ Closet 1st Flr- Chicago Public Library 156 SF 6 \$1,131 116B Walls - Masonry Walls - Plaster/Drywall 1st Flr- Chicago Public Library 1st Flr- Chicago Publi |
| Lighting - Lay-in Lighting - Pendent/Surface 1st Flr- Chicago Public Library 110 EA 7 \$0 Storage/ Closet 1st Flr- Chicago Public Library 110 EA 7 \$0 Storage/ Closet 1st Flr- Chicago Public Library 156 SF 6 \$1,131 116B Walls - Masonry Walls - Masonry Walls - Plaster/Drywall 1st Flr- Chicago Public Library 1,892 SF 6 \$7,000 Walls - Plaster/Drywall 1st Flr- Chicago Public Library 1,892 SF 6 \$5,222 Locker/Shower Room Locker/Shower Room Men's gym & team lockers/showers 1,153 SF 6 \$4,518 Benches, ped mounted Men's gym & team lockers/showers 1,153 SF 6 \$1,715 Hairline cracks in concrete Doors - Steel Doors incl hw Men's gym & team lockers/showers Men's g |
| Lighting - Pendent/Surface 1st FIr- Chicago Public Library 110 EA 7 \$0 Storage/ Closet 1st FIr- Chicago Public Library 156 SF 6 \$1,131 116B Walls - Masonry Walls - Masonry Walls - Plaster/Drywall 1st FIr- Chicago Public Library 1st FIr- Chicago Public L |
| Storage/ Closet Walls - Masonry Walls - Masonry Walls - Plaster/Drywall Accessories Benches, ped mounted Men's gym & team lockers/showers Doors - Steel Doors incl hw Floor Drain Storage/ Closet 1st Flr- Chicago Public Library 1st Flr- Chicago Public Library 2,225 SF 6 \$7,000 \$7,0 |
| Walls - Masonry Walls - Plaster/Drywall 1st FIr- Chicago Public Library 1st FIr- Chicago Public L |
| Walls - Plaster/Drywall1st Flr- Chicago Public Library1,892SF6\$5,222Locker/Shower RoomAccessoriesMen's gym & team lockers/showers1,153SF6\$4,518Benches, ped mountedMen's gym & team lockers/showers241LF7\$0Ceiling - ExposedMen's gym & team lockers/showers1,153SF6\$1,715Hairline cracks in concreteDoors - Steel Doors incl hwMen's gym & team lockers/showers4EA7\$0Floor DrainMen's gym & team lockers/showers4EA7\$0 |
| Locker/Shower RoomAccessoriesMen's gym & team lockers/showers1,153SF6\$4,518Benches, ped mountedMen's gym & team lockers/showers241LF7\$0Ceiling - ExposedMen's gym & team lockers/showers1,153SF6\$1,715Hairline cracks in concreteDoors - Steel Doors incl hwMen's gym & team lockers/showers4EA7\$0Floor DrainMen's gym & team lockers/showers4EA7\$0 |
| Accessories Men's gym & team lockers/showers 1,153 SF 6 \$4,518 Benches, ped mounted Men's gym & team lockers/showers 241 LF 7 \$0 Ceiling - Exposed Men's gym & team lockers/showers 1,153 SF 6 \$1,715 Hairline cracks in concrete Doors - Steel Doors incl hw Men's gym & team lockers/showers 4 EA 7 \$0 Floor Drain Men's gym & team lockers/showers 4 EA 7 \$0 |
| Accessories Men's gym & team lockers/showers 1,153 SF 6 \$4,518 Benches, ped mounted Men's gym & team lockers/showers 241 LF 7 \$0 Ceiling - Exposed Men's gym & team lockers/showers 1,153 SF 6 \$1,715 Hairline cracks in concrete Doors - Steel Doors incl hw Men's gym & team lockers/showers 4 EA 7 \$0 Floor Drain Men's gym & team lockers/showers 4 EA 7 \$0 |
| Ceiling - Exposed Men's gym & team lockers/showers 1,153 SF 6 \$1,715 Hairline cracks in concrete Doors - Steel Doors incl hw Men's gym & team lockers/showers 4 EA 7 \$0 Floor Drain Men's gym & team lockers/showers 4 EA 7 \$0 |
| Doors - Steel Doors incl hw Men's gym & team lockers/showers 4 EA 7 \$0 Floor Drain Men's gym & team lockers/showers 4 EA 7 \$0 |
| Floor Drain Men's gym & team lockers/showers 4 EA 7 \$0 |
| 5 , |
| Floor - Concrete Fnow/ Painted Men's gym & team lockers/showers 1.012 SF 7 \$0 |
| Floor Contract Epoxy Familia (with the contract of the contrac |
| Floor - Tile Ceramic/ Porcelain Men's gym & team lockers/showers 141 SF 7 \$0 |
| Lighting - Lay-in Men's gym & team lockers/showers 27 EA 7 \$0 |
| Showers Men's gym & team lockers/showers 6 EA 7 \$0 |
| Student Lockers - One Tier Men's gym & team lockers/showers 168 EA 7 \$0 |
| Student Lockers - Two Tier Men's gym & team lockers/showers 112 EA 7 \$0 |
| Walls - Concrete Block Men's gym & team lockers/showers 1,788 SF 7 \$0 |
| Walls - Tile Ceramic/ Porcelain Men's gym & team lockers/showers 268 SF 7 \$0 |
| Accessories Men's pool lockers 510 SF 7 \$0 |
| Benches, ped mounted Men's pool lockers 50 LF 7 \$0 |
| Ceiling - Exposed Men's pool lockers 510 SF 7 \$0 |
| Doors - Steel Doors incl hw Men's pool lockers 2 EA 7 \$0 |
| Floor Drain Men's pool lockers 5 EA 7 \$0 |
| Floor - Concrete Epoxy/ Painted Men's pool lockers 330 SF 7 \$0 |
| Floor - Tile Ceramic/ Porcelain Men's pool lockers 180 SF 7 \$0 |
| Hand Dryer Men's pool lockers 1 EA 7 \$0 |
| Lavatory Men's pool lockers 3 EA 7 \$0 |
| Lighting - Lay-in Men's pool lockers 10 EA 7 \$0 |
| Partitions Men's pool lockers 2 EA 7 \$0 |
| Showers Men's pool lockers 5 EA 7 \$0 |



| ıp Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------------|------------------------------------|----------|------|------|---------|-----------------------------|
| ker/Shower Room | | | | | | |
| Student Lockers - One Tier | Men's pool lockers | 30 | EA | 7 | \$0 | |
| Student Lockers - Two Tier | Men's pool lockers | 92 | EA | 7 | \$0 | |
| Urinals | Men's pool lockers | 1 | EA | 7 | \$0 | |
| Walls - Concrete Block | Men's pool lockers | 1,086 | SF | 7 | \$0 | |
| Walls - Tile Ceramic/ Porcelain | Men's pool lockers | 256 | SF | 7 | \$0 | |
| Water Closet | Men's pool lockers | 2 | EA | 7 | \$0 | |
| Accessories | Women's gym & team lockers/showers | 1,153 | SF | 6 | \$4,518 | |
| Benches, ped mounted | Women's gym & team lockers/showers | 241 | LF | 7 | \$0 | |
| Ceiling - Exposed | Women's gym & team lockers/showers | 1,153 | SF | 6 | \$1,715 | Hairline cracks in concrete |
| Doors - Steel Doors incl hw | Women's gym & team lockers/showers | 4 | EA | 7 | \$0 | |
| Floor Drain | Women's gym & team lockers/showers | 4 | EA | 7 | \$0 | |
| Floor - Epoxy/ Painted | Women's gym & team lockers/showers | 1,012 | SF | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain | Women's gym & team lockers/showers | 141 | SF | 7 | \$0 | |
| Lighting - Lay-in | Women's gym & team lockers/showers | 27 | EΑ | 7 | \$0 | |
| Showers | Women's gym & team lockers/showers | 6 | EΑ | 7 | \$0 | |
| Student Lockers - One Tier | Women's gym & team lockers/showers | 179 | EΑ | 7 | \$0 | |
| Student Lockers - Two Tier | Women's gym & team lockers/showers | 88 | EΑ | 7 | \$0 | |
| Walls - Concrete Block | Women's gym & team lockers/showers | 1,788 | SF | 7 | \$0 | |
| Walls - Tile Ceramic/ Porcelain | Women's gym & team lockers/showers | 268 | SF | 7 | \$0 | |
| Accessories | Women's pool lockers | 490 | SF | 7 | \$0 | |
| Benches, ped mounted | Women's pool lockers | 73 | LF | 7 | \$0 | |
| Ceiling - Exposed | Women's pool lockers | 490 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw | Women's pool lockers | 2 | EΑ | 7 | \$0 | |
| Floor Drain | Women's pool lockers | 5 | EΑ | 7 | \$0 | |
| Floor - Epoxy/ Painted | Women's pool lockers | 310 | SF | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain | Women's pool lockers | 180 | SF | 7 | \$0 | |
| Hand Dryer | Women's pool lockers | 2 | EΑ | 7 | \$0 | |
| Lavatory | Women's pool lockers | 3 | EΑ | 7 | \$0 | |
| Lighting - Lay-in | Women's pool lockers | 10 | EA | 7 | \$0 | |
| Partitions | Women's pool lockers | 2 | EA | 7 | \$0 | |
| Showers | Women's pool lockers | 5 | EA | 7 | \$0 | |
| Student Lockers - One Tier | Women's pool lockers | 30 | EA | 7 | \$0 | |
| Student Lockers - Two Tier | Women's pool lockers | 92 | EA | 7 | \$0 | |
| Walls - Concrete Block | Women's pool lockers | 992 | SF | 7 | \$0 | |
| Walls - Tile Ceramic/ Porcelain | Women's pool lockers | 256 | SF | 7 | \$0 | |
| Water Closet | Women's pool lockers | 3 | EA | 7 | \$0 | |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|--------------------------------|-------------------------------------|----------|------|------|----------|-------------------------------|
| Lunch 8 | & Multipurpose Room | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Flr- Library's Multi-Purpose Rm | 1,184 | SF | 6 | \$4,097 | |
| | Doors - Side-lite | 1st Flr- Library's Multi-Purpose Rm | 146 | SF | 6 | \$2,441 | |
| | Doors - Store Front | 1st Flr- Library's Multi-Purpose Rm | 2 | EA | 6 | \$2,416 | |
| | Doors - Transom Window | 1st Flr- Library's Multi-Purpose Rm | 18 | SF | 6 | \$305 | |
| | Floor - Carpet | 1st Flr- Library's Multi-Purpose Rm | 1,184 | SF | 6 | \$2,523 | |
| | Lighting - Lay-in | 1st Flr- Library's Multi-Purpose Rm | 11 | EΑ | 7 | \$0 | |
| | Market Board | 1st Flr- Library's Multi-Purpose Rm | 12 | LF | 7 | \$0 | |
| | Walls - Masonry | 1st Flr- Library's Multi-Purpose Rm | 731 | SF | 6 | \$2,300 | |
| | Walls - Plaster/Drywall | 1st Flr- Library's Multi-Purpose Rm | 731 | SF | 6 | \$2,017 | has acoustic panels on 1 wall |
| | Ceiling - Lay-in | Rm 107- Multi Purpose Rm | 1,832 | SF | 6 | \$5,501 | |
| | Doors - Side-lite | Rm 107- Multi Purpose Rm | 64 | SF | 6 | \$1,070 | |
| | Doors - Store Front | Rm 107- Multi Purpose Rm | 4 | EA | 6 | \$4,833 | |
| | Doors - Transom Window | Rm 107- Multi Purpose Rm | 24 | SF | 6 | \$406 | |
| | Floor - Wood | Rm 107- Multi Purpose Rm | 1,832 | SF | 6 | \$12,915 | |
| | Lighting - Lay-in | Rm 107- Multi Purpose Rm | 14 | EA | 7 | \$0 | |
| | Storage/ Closet | Rm 107- Multi Purpose Rm | 79 | SF | 6 | \$573 | |
| | Walls - Concrete Block | Rm 107- Multi Purpose Rm | 1,845 | SF | 6 | \$5,409 | |
| | Ceiling - Exposed | Rm 121- Student Cafeteria | 1,641 | SF | 6 | \$2,440 | |
| | Ceiling - Lay-in | Rm 121- Student Cafeteria | 820 | SF | 6 | \$2,462 | |
| | Ceiling - Plaster/Drywall | Rm 121- Student Cafeteria | 3 | SF | 5 | \$37 | water damaged |
| | Ceiling - Plaster/Drywall | Rm 121- Student Cafeteria | 1,805 | SF | 6 | \$6,246 | - |
| | Doors - Side-lite | Rm 121- Student Cafeteria | 779 | SF | 6 | \$13,022 | |
| | Doors - Steel Doors incl hw | Rm 121- Student Cafeteria | 4 | EA | 6 | \$1,204 | stainless steel |
| | Doors - Store Front | Rm 121- Student Cafeteria | 4 | EA | 6 | \$4,833 | |
| | Doors - Transom Window | Rm 121- Student Cafeteria | 18 | SF | 6 | \$305 | |
| | Floor - Terrazzo | Rm 121- Student Cafeteria | 4,269 | SF | 6 | \$9,340 | |
| | Lighting - Lay-in | Rm 121- Student Cafeteria | 22 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Rm 121- Student Cafeteria | 61 | EA | 7 | \$0 | |
| | Storage/ Closet | Rm 121- Student Cafeteria | 6 | SF | 6 | \$44 | |
| | Walls - Masonry | Rm 121- Student Cafeteria | 560 | SF | 6 | \$1,762 | columns |
| | Walls - Structural Glazed Tile | Rm 121- Student Cafeteria | 1,665 | SF | 6 | \$5,238 | |
| | Ceiling - Lay-in | Rm 121A- Faculty Cafeteria | 311 | SF | 6 | \$934 | |
| | Doors - Side-lite | Rm 121A- Faculty Cafeteria | 78 | SF | 6 | \$1,304 | |
| | Doors - Store Front | Rm 121A- Faculty Cafeteria | 2 | EA | 6 | \$2,416 | |
| | Doors - Transom Window | Rm 121A- Faculty Cafeteria | 9 | SF | 6 | \$152 | |
| | Floor - Terrazzo | Rm 121A- Faculty Cafeteria | 311 | SF | 6 | \$680 | |
| | Lighting - Lay-in | Rm 121A- Faculty Cafeteria | 4 | EΑ | 7 | \$0 | |



| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---|----------------------------|----------|------|------|---------|---------------------------------------|
| nch & | & Multipurpose Room | | | | | | |
| | Walls - Structural Glazed Tile | Rm 121A- Faculty Cafeteria | 639 | SF | 6 | \$2,010 | |
| | Ceiling - Lay-in | Rm 123- Servery | 1,030 | SF | 6 | \$3,093 | |
| | Doors - Side-lite | Rm 123- Servery | 96 | SF | 6 | \$1,605 | |
| | Doors - Steel Doors incl hw | Rm 123- Servery | 2 | EA | 6 | \$602 | |
| | Doors - Store Front | Rm 123- Servery | 4 | EA | 6 | \$4,833 | |
| | Doors - Transom Window | Rm 123- Servery | 18 | SF | 6 | \$305 | |
| | Floor - Terrazzo | Rm 123- Servery | 1,030 | SF | 6 | \$2,254 | |
| | Lighting - Lay-in | Rm 123- Servery | 16 | EA | 7 | \$0 | |
| | Serving Line | Rm 123- Servery | 50 | LF | 6 | \$2,976 | |
| | Walls - Structural Glazed Tile | Rm 123- Servery | 1,157 | SF | 6 | \$3,640 | |
| F_ID |)F | | | | | | |
| | Doors - Steel Doors incl hw | Rm 116 | 1 | EA | 6 | \$301 | |
| | Finishes | Rm 116 | 275 | SF | 6 | \$1,962 | |
| | Ventilation and Cooling | Rm 116 | 1 | EA | 6 | \$1,855 | |
| chani | nical/ Service Rooms | | | | | | |
| | Mechanical/ Service Rooms | 1st Floor | 358 | SF | 6 | \$2,565 | 107B, 116A, elec closets in 123, 127A |
| | Storage Room | 1st Floor | 521 | SF | 6 | \$3,733 | 109, 114, Yard Storage |
| | Vaults | 1st Floor | 118 | SF | 6 | \$845 | N&S Main Office vaults |
| | Janitor's Closet | 2nd Floor | 40 | SF | 7 | \$0 | |
| | Mechanical/ Service Rooms | 2nd Floor | 96 | SF | 7 | \$0 | |
| | Storage Room | 2nd Floor | 289 | SF | 7 | \$0 | |
| | Janitor's Closet | 3rd Floor | 37 | SF | 6 | \$265 | Rm 335B |
| | Mechanical/ Service Rooms | 3rd Floor | 40 | SF | 6 | \$287 | Rm 318B |
| | Storage Room | 3rd Floor | 58 | SF | 6 | \$416 | Rm 313 |
| | Janitor's Closet | Basement | 171 | SF | 7 | \$0 | Laundry room 012 |
| | Mechanical/ Service Rooms | Basement | 8,436 | SF | 7 | \$0 | |
| | Storage Room | Basement | 2,655 | SF | 7 | \$0 | |
| ol & N | Natatorium | | | | | | |
| | Accessories | Basement | 1,948 | SF | 7 | \$0 | |
| | Bleachers Seating/Plank Seating | Basement | 115 | EA | 6 | \$3,328 | on Balcony |
| | Ceiling - Exposed | Basement | 7,082 | SF | 7 | \$0 | |
| | Ceiling - Plaster/ Drywall | Basement | 500 | SF | 6 | \$2,760 | on Balcony |
| | Doors - Steel Doors incl hw | Basement | 17 | EA | 7 | \$0 | |
| | Floor - Concrete | Basement | 923 | SF | 6 | \$488 | Balcony floor |
| | Lighting - Lay-in | Basement | 7 | EA | 7 | \$0 | Recessed cans- on balcony |
| | Lighting - Metal Halide/ High Pressure Sodium | Basement | 37 | EA | 7 | \$0 | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-------------------------|----------|------|------|---------|-----------------|
| Pool & | Natatorium | | | | | | |
| | Pool Basin | Basement | 3,948 | SF | 7 | \$0 | |
| | Pool Deck | Basement | 3,134 | SF | 7 | \$0 | |
| | Pool Deck Drains | Basement | 6 | EA | 7 | \$0 | |
| | Storage/ Closet | Basement | 408 | SF | 7 | \$0 | |
| | Walls - Masonry | Basement | 3,200 | SF | 7 | \$0 | |
| | Walls - Metal Panel | Basement | 1,700 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Basement | 4,304 | SF | 7 | \$0 | |
| Prep Ro | oom | | | | | | |
| | Ceiling - Lay-in | Rm 121B- Dishwashing Rm | 291 | SF | 6 | \$874 | |
| | Doors - Steel Doors incl hw | Rm 121B- Dishwashing Rm | 1 | EA | 6 | \$301 | stainless steel |
| | Floor - Tile Ceramic/ Porcelain | Rm 121B- Dishwashing Rm | 291 | SF | 6 | \$616 | |
| | Lighting - Lay-in | Rm 121B- Dishwashing Rm | 4 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Rm 121B- Dishwashing Rm | 625 | SF | 6 | \$1,832 | |
| | Work Sink | Rm 121B- Dishwashing Rm | 2 | EA | 6 | \$758 | |
| | Ceiling - Exposed | Rm 127- Loading Dock | 1,312 | SF | 6 | \$1,951 | |
| | Doors - Steel Doors incl hw | Rm 127- Loading Dock | 2 | EA | 6 | \$602 | |
| | Floor - Concrete Epoxy/ Painted | Rm 127- Loading Dock | 1,312 | SF | 6 | \$694 | |
| | Lighting - Pendent/Surface | Rm 127- Loading Dock | 20 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | Rm 127- Loading Dock | 2,900 | SF | 6 | \$8,501 | |
| | Casework | Rm 228 | 22 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Rm 228 | 265 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Rm 228 | 3 | EA | 7 | \$0 | |
| | Doors - Transom Window | Rm 228 | 10 | SF | 7 | \$0 | |
| | Floor - Tile | Rm 228 | 265 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Rm 228 | 10 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 228 | 578 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Rm 228 | 42 | SF | 7 | \$0 | |
| | Work Sink | Rm 228 | 1 | EA | 7 | \$0 | |
| | Casework | Rm 232 | 22 | LF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Rm 232 | 265 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Rm 232 | 3 | EA | 7 | \$0 | |
| | Doors - Transom Window | Rm 232 | 10 | SF | 7 | \$0 | |
| | Floor - Tile | Rm 232 | 265 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Rm 232 | 10 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 232 | 578 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Rm 232 | 42 | SF | 7 | \$0 | |
| | Work Sink | Rm 232 | 1 | EA | 7 | \$0 | |



| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---------------------------------|-----------------------------|----------|------|------|---------|-------------|
| p Ro | oom | | | | | | |
| | Casework | Rm 332 | 24 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | Rm 332 | 366 | SF | 6 | \$1,099 | |
| | Doors - Side-lite | Rm 332 | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Rm 332 | 3 | EA | 7 | \$0 | |
| | Doors - Transom Window | Rm 332 | 8 | SF | 7 | \$0 | |
| | Floor - Tile | Rm 332 | 366 | SF | 6 | \$801 | |
| | Lighting - Lay-in | Rm 332 | 10 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 332 | 800 | SF | 6 | \$2,208 | |
| | Work Sink | Rm 332 | 1 | EΑ | 6 | \$379 | |
| | Casework | Rm 338 | 30 | LF | 7 | \$0 | |
| | Ceiling - Lay-in | Rm 338 | 366 | SF | 6 | \$1,099 | |
| | Doors - Side-lite | Rm 338 | 8 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Rm 338 | 3 | EA | 7 | \$0 | |
| | Doors - Transom Window | Rm 338 | 8 | SF | 7 | \$0 | |
| | Floor - Tile | Rm 338 | 366 | SF | 6 | \$801 | |
| | Lighting - Lay-in | Rm 338 | 10 | EA | 7 | \$0 | |
| | Walls - Plaster/Drywall | Rm 338 | 800 | SF | 6 | \$2,208 | |
| | Work Sink | Rm 338 | 1 | EΑ | 6 | \$379 | |
| stroo | om | | | | | | |
| | Accessories | 1st Flr- Near MDF Rm 116 | 42 | SF | 6 | \$387 | |
| | Ceiling - Lay-in | 1st Flr- Near MDF Rm 116 | 42 | SF | 6 | \$126 | |
| | Doors - Steel Doors incl hw | 1st Flr- Near MDF Rm 116 | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st Flr- Near MDF Rm 116 | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Flr- Near MDF Rm 116 | 42 | SF | 6 | \$89 | |
| | Hand Dryer | 1st Flr- Near MDF Rm 116 | 1 | EΑ | 6 | \$230 | |
| | Lavatory | 1st Flr- Near MDF Rm 116 | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 1st Flr- Near MDF Rm 116 | 1 | EΑ | 7 | \$0 | |
| | Walls - Structural Glazed Tile | 1st Flr- Near MDF Rm 116 | 230 | SF | 6 | \$724 | |
| | Water Closet | 1st Flr- Near MDF Rm 116 | 1 | EA | 6 | \$336 | |
| | Accessories | 1st FIr- Next to MDF Rm 116 | 632 | SF | 6 | \$5,829 | |
| | Ceiling - Plaster/Drywall | 1st FIr- Next to MDF Rm 116 | 632 | SF | 6 | \$2,187 | |
| | Floor Drain | 1st FIr- Next to MDF Rm 116 | 2 | EA | 6 | \$2,118 | |
| | Floor - Tile Ceramic/ Porcelain | 1st FIr- Next to MDF Rm 116 | 632 | SF | 6 | \$1,338 | |
| | Hand Dryer | 1st FIr- Next to MDF Rm 116 | 5 | EA | 6 | \$1,150 | |
| | Lavatory | 1st FIr- Next to MDF Rm 116 | 9 | EA | 6 | \$2,876 | |
| | Lighting - Pendent/Surface | 1st FIr- Next to MDF Rm 116 | 25 | EA | 7 | | cove lights |
| | Partitions | 1st FIr- Next to MDF Rm 116 | 9 | EA | 6 | \$2,672 | |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comment |
|---------|---------------------------------|--|----------|------|------|---------|-------------|
| Restroc | •• | | | | | | |
| | Urinals | 1st FIr- Next to MDF Rm 116 | 6 | EA | 6 | \$2,016 | |
| | Walls - Structural Glazed Tile | 1st FIr- Next to MDF Rm 116 | 1,065 | SF | 6 | \$3,350 | |
| | Water Closet | 1st FIr- Next to MDF Rm 116 | 10 | EA | 6 | \$3,360 | |
| | Accessories | 1st FIr- Next to Security Office 113 | 720 | SF | 6 | \$6,641 | |
| | Ceiling - Plaster/Drywall | 1st FIr- Next to Security Office 113 | 720 | SF | 6 | \$2,492 | |
| | Floor Drain | 1st FIr- Next to Security Office 113 | 2 | EΑ | 6 | \$2,118 | |
| | Floor - Tile Ceramic/ Porcelain | 1st FIr- Next to Security Office 113 | 720 | SF | 6 | \$1,524 | |
| | Hand Dryer | 1st FIr- Next to Security Office 113 | 5 | EΑ | 6 | \$1,150 | |
| | Lavatory | 1st FIr- Next to Security Office 113 | 9 | EΑ | 6 | \$2,876 | |
| | Lighting - Pendent/Surface | 1st FIr- Next to Security Office 113 | 25 | EA | 7 | \$0 | cove lights |
| | Partitions | 1st FIr- Next to Security Office 113 | 15 | EA | 6 | \$4,454 | |
| | Walls - Structural Glazed Tile | 1st FIr- Next to Security Office 113 | 1,165 | SF | 6 | \$3,665 | |
| | Water Closet | 1st FIr- Next to Security Office 113 | 17 | EΑ | 6 | \$5,712 | |
| | Accessories | 1st FIr-in Main Office North Rm 124 | 66 | SF | 6 | \$609 | |
| | Ceiling - Lay-in | 1st FIr-in Main Office North Rm 124 | 66 | SF | 6 | \$198 | |
| | Doors - Steel Doors incl hw | 1st FIr-in Main Office North Rm 124 | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st FIr-in Main Office North Rm 124 | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st FIr-in Main Office North Rm 124 | 66 | SF | 6 | \$140 | |
| | Hand Dryer | 1st FIr-in Main Office North Rm 124 | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st FIr-in Main Office North Rm 124 | 1 | EΑ | 6 | \$320 | |
| | Lighting - Lay-in | 1st FIr-in Main Office North Rm 124 | 1 | EΑ | 7 | \$0 | |
| | Walls - Concrete Block | 1st FIr-in Main Office North Rm 124 | 56 | SF | 6 | \$164 | |
| | Walls - Tile Ceramic/ Porcelain | 1st Flr-in Main Office North Rm 124 | 241 | SF | 6 | \$545 | |
| | Water Closet | 1st Flr-in Main Office North Rm 124 | 1 | EA | 6 | \$336 | |
| | Accessories | 1st FIr-in Main Office South Rm 126 | 66 | SF | 6 | \$609 | |
| | Ceiling - Lay-in | 1st FIr-in Main Office South Rm 126 | 66 | SF | 6 | \$198 | |
| | Doors - Steel Doors incl hw | 1st FIr-in Main Office South Rm 126 | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st Flr-in Main Office South Rm 126 | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Flr-in Main Office South Rm 126 | 66 | SF | 6 | \$140 | |
| | Hand Dryer | 1st FIr-in Main Office South Rm 126 | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st Flr-in Main Office South Rm 126 | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 1st Flr-in Main Office South Rm 126 | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Flr-in Main Office South Rm 126 | 56 | SF | 6 | \$164 | |
| | Walls - Tile Ceramic/ Porcelain | 1st FIr-in Main Office South Rm 126 | 241 | SF | 6 | \$545 | |
| | Water Closet | 1st Flr-in Main Office South Rm 126 | 1 | EA | 6 | \$336 | |
| | Accessories | 1st FIr-Unisex in Kitchen (used as a Mens) | 66 | SF | 6 | \$609 | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|---|----------|------|------|---------|----------|
| Restroo | m | | | | | | |
| | Ceiling - Lay-in | 1st FIr-Unisex in Kitchen (used as a Mens) | 66 | SF | 6 | \$198 | |
| | Doors - Steel Doors incl hw | 1st FIr-Unisex in Kitchen (used as a Mens) | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st Flr-Unisex in Kitchen (used as a Mens) | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Flr-Unisex in Kitchen (used as a Mens) | 66 | SF | 6 | \$140 | |
| | Hand Dryer | 1st FIr-Unisex in Kitchen (used as a Mens) | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st Flr-Unisex in Kitchen (used as a Mens) | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 1st Flr-Unisex in Kitchen (used as a Mens) | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st Flr-Unisex in Kitchen (used as a Mens) | 297 | SF | 6 | \$871 | |
| | Water Closet | 1st Flr-Unisex in Kitchen (used as a Mens) | 1 | EA | 6 | \$336 | |
| | Accessories | 1st FIr-Unisex in Kitchen (used as Women's) | 37 | SF | 6 | \$341 | |
| | Ceiling - Lay-in | 1st FIr-Unisex in Kitchen (used as Women's) | 37 | SF | 6 | \$111 | |
| | Doors - Steel Doors incl hw | 1st FIr-Unisex in Kitchen (used as Women's) | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st FIr-Unisex in Kitchen (used as Women's) | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st Flr-Unisex in Kitchen (used as Women's) | 37 | SF | 6 | \$78 | |
| | Hand Dryer | 1st Flr-Unisex in Kitchen (used as Women's) | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st Flr-Unisex in Kitchen (used as Women's) | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 1st FIr-Unisex in Kitchen (used as Women's) | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | 1st FIr-Unisex in Kitchen (used as Women's) | 225 | SF | 6 | \$660 | |
| | Water Closet | 1st Flr-Unisex in Kitchen (used as Women's) | 1 | EA | 6 | \$336 | |
| | Accessories | 1st- Men's in Library | 134 | SF | 6 | \$1,236 | |
| | Ceiling - Plaster/Drywall | 1st- Men's in Library | 134 | SF | 6 | \$464 | |
| | Doors - Steel Doors incl hw | 1st- Men's in Library | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st- Men's in Library | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st- Men's in Library | 134 | SF | 6 | \$284 | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---------------------------------|-------------------------|----------|------|------|---------|-------------|
| Restroo | • • | | | | | | |
| | Hand Dryer | 1st- Men's in Library | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st- Men's in Library | 1 | EA | 5 | | not working |
| | Lavatory | 1st- Men's in Library | 1 | EA | 6 | \$320 | |
| | Lighting - Lay-in | 1st- Men's in Library | 3 | EA | 7 | \$0 | |
| | Partitions | 1st- Men's in Library | 3 | EA | 6 | \$891 | |
| | Walls - Structural Glazed Tile | 1st- Men's in Library | 400 | SF | 6 | \$1,258 | |
| | Water Closet | 1st- Men's in Library | 3 | EA | 6 | \$1,008 | |
| | Accessories | 1st- Women's in Library | 200 | SF | 6 | \$1,845 | |
| | Ceiling - Plaster/Drywall | 1st- Women's in Library | 194 | SF | 6 | \$671 | |
| | Ceiling - Plaster/Drywall | 1st- Women's in Library | 6 | SF | 5 | \$75 | crack |
| | Doors - Steel Doors incl hw | 1st- Women's in Library | 1 | EA | 6 | \$301 | |
| | Floor Drain | 1st- Women's in Library | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 1st- Women's in Library | 200 | SF | 6 | \$423 | |
| | Hand Dryer | 1st- Women's in Library | 1 | EA | 6 | \$230 | |
| | Lavatory | 1st- Women's in Library | 2 | EA | 6 | \$639 | |
| | Lighting - Lay-in | 1st- Women's in Library | 5 | EA | 7 | \$0 | |
| | Partitions | 1st- Women's in Library | 4 | EA | 6 | \$1,188 | |
| | Walls - Structural Glazed Tile | 1st- Women's in Library | 503 | SF | 6 | \$1,582 | |
| | Water Closet | 1st- Women's in Library | 5 | EA | 6 | \$1,680 | |
| | Accessories | 3rd Flr- Near 320 | 42 | SF | 6 | \$387 | |
| | Accessories | 3rd Flr- Near 320 | 294 | SF | 6 | \$2,712 | |
| | Accessories | 3rd Flr- Near 320 | 294 | SF | 6 | \$2,712 | |
| | Ceiling - Lay-in | 3rd Flr- Near 320 | 42 | SF | 6 | \$126 | |
| | Ceiling - Plaster/Drywall | 3rd Flr- Near 320 | 294 | SF | 6 | \$1,017 | |
| | Ceiling - Plaster/Drywall | 3rd Flr- Near 320 | 294 | SF | 6 | \$1,017 | |
| | Doors - Steel Doors incl hw | 3rd Flr- Near 320 | 1 | EA | 7 | \$0 | |
| | Floor Drain | 3rd Flr- Near 320 | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 3rd Flr- Near 320 | 1 | EA | 6 | \$1,059 | |
| | Floor Drain | 3rd Flr- Near 320 | 1 | EA | 6 | \$1,059 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Flr- Near 320 | 42 | SF | 6 | \$89 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Flr- Near 320 | 294 | SF | 6 | \$622 | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Flr- Near 320 | 294 | SF | 6 | \$622 | |
| | Hand Dryer | 3rd Flr- Near 320 | 1 | EA | 6 | \$230 | |
| | Hand Dryer | 3rd Flr- Near 320 | 3 | EA | 6 | \$690 | |
| | Hand Dryer | 3rd Flr- Near 320 | 3 | EA | 6 | \$690 | |
| | Lavatory | 3rd Flr- Near 320 | 1 | EA | 6 | \$320 | |
| | Lavatory | 3rd Flr- Near 320 | 5 | EA | 6 | \$1,598 | |



| oup Item - Type | | Location | Quantity | Unit | Rank | Cost | Comment |
|---------------------|----------------|----------------------|----------|------|------|---------|-------------|
| stroom | | | | | | | |
| Lavatory | | 3rd Flr- Near 320 | 5 | EA | 6 | \$1,598 | |
| Lighting - Lay-in | | 3rd FIr- Near 320 | 1 | EA | 7 | \$0 | |
| Lighting - Lay-in | | 3rd Flr- Near 320 | 12 | EA | 7 | \$0 | cove lights |
| Lighting - Penden | t/Surface | 3rd FIr- Near 320 | 25 | EA | 7 | \$0 | cove lights |
| Partitions | | 3rd FIr- Near 320 | 3 | EA | 6 | \$891 | |
| Partitions | | 3rd FIr- Near 320 | 5 | EA | 6 | \$1,485 | |
| Urinals | | 3rd FIr- Near 320 | 3 | EA | 6 | \$1,008 | |
| Walls - Concrete E | Block | 3rd FIr- Near 320 | 240 | SF | 6 | \$704 | |
| Walls - Structural | Glazed Tile | 3rd FIr- Near 320 | 634 | SF | 6 | \$1,995 | |
| Walls - Structural | Glazed Tile | 3rd FIr- Near 320 | 634 | SF | 6 | \$1,995 | |
| Water Closet | | 3rd FIr- Near 320 | 1 | EA | 6 | \$336 | |
| Water Closet | | 3rd FIr- Near 320 | 3 | EA | 6 | \$1,008 | |
| Water Closet | | 3rd FIr- Near 320 | 6 | EA | 6 | \$2,016 | |
| Accessories | | 3rd FIr- Near 333 | 42 | SF | 6 | \$387 | |
| Ceiling - Lay-in | | 3rd FIr- Near 333 | 42 | SF | 6 | \$126 | |
| Doors - Steel Door | rs incl hw | 3rd FIr- Near 333 | 1 | EA | 7 | \$0 | |
| Floor Drain | | 3rd FIr- Near 333 | 1 | EA | 6 | \$1,059 | |
| Floor - Tile Cerami | ic/ Porcelain | 3rd FIr- Near 333 | 42 | SF | 6 | \$89 | |
| Hand Dryer | | 3rd FIr- Near 333 | 1 | EA | 6 | \$230 | |
| Lavatory | | 3rd FIr- Near 333 | 1 | EA | 6 | \$320 | |
| Lighting - Lay-in | | 3rd FIr- Near 333 | 1 | EA | 7 | \$0 | |
| Walls - Concrete E | Block | 3rd FIr- Near 333 | 180 | SF | 6 | \$528 | |
| Walls - Tile Ceram | nic/ Porcelain | 3rd FIr- Near 333 | 60 | SF | 6 | \$136 | |
| Water Closet | | 3rd FIr- Near 333 | 1 | EA | 6 | \$336 | |
| Accessories | | 3rd FIr- Next to 333 | 294 | SF | 6 | \$2,712 | |
| Accessories | | 3rd FIr- Next to 333 | 294 | SF | 6 | \$2,712 | |
| Ceiling - Plaster/D | Drywall | 3rd FIr- Next to 333 | 294 | SF | 6 | \$1,017 | |
| Ceiling - Plaster/D | | 3rd FIr- Next to 333 | 294 | SF | 6 | \$1,017 | |
| Floor Drain | • | 3rd FIr- Next to 333 | 1 | EA | 6 | \$1,059 | |
| Floor Drain | | 3rd FIr- Next to 333 | 1 | EA | 6 | \$1,059 | |
| Floor - Tile Cerami | ic/ Porcelain | 3rd FIr- Next to 333 | 294 | SF | 6 | \$622 | |
| Floor - Tile Cerami | ic/ Porcelain | 3rd FIr- Next to 333 | 294 | SF | 6 | \$622 | |
| Hand Dryer | | 3rd FIr- Next to 333 | 3 | EA | 6 | \$690 | |
| Hand Dryer | | 3rd FIr- Next to 333 | 3 | EA | 6 | \$690 | |
| Lavatory | | 3rd FIr- Next to 333 | 5 | EA | 6 | \$1,598 | |
| Lavatory | | 3rd FIr- Next to 333 | 5 | EA | 6 | \$1,598 | |
| | | | | | 7 | | cove lights |



| _ | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|----------------------|----------|------|------|---------|-----------------------------|
| Restro | • | | | | | | |
| | Lighting - Pendent/Surface | 3rd FIr- Next to 333 | 25 | EA | 7 | \$0 | cove lights |
| | Partitions | 3rd FIr- Next to 333 | 5 | EΑ | 6 | \$1,485 | • |
| | Partitions | 3rd FIr- Next to 333 | 3 | EΑ | 6 | \$891 | |
| | Urinals | 3rd FIr- Next to 333 | 3 | EΑ | 6 | \$1,008 | |
| | Walls - Structural Glazed Tile | 3rd FIr- Next to 333 | 634 | SF | 6 | \$1,995 | |
| | Walls - Structural Glazed Tile | 3rd FIr- Next to 333 | 634 | SF | 6 | \$1,995 | |
| | Water Closet | 3rd FIr- Next to 333 | 6 | EΑ | 6 | \$2,016 | |
| | Water Closet | 3rd FIr- Next to 333 | 3 | EA | 6 | \$1,008 | |
| | Accessories | Basement NE | 209 | SF | 6 | \$1,928 | |
| | Accessories | Basement NE | 144 | SF | 6 | \$1,328 | |
| | Ceiling - Exposed | Basement NE | 144 | SF | 6 | \$214 | Hairline cracks in concrete |
| | Ceiling - Exposed | Basement NE | 209 | SF | 6 | \$311 | Hairline cracks in concrete |
| | Floor Drain | Basement NE | 1 | EA | 7 | \$0 | |
| | Floor Drain | Basement NE | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | Basement NE | 144 | SF | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | Basement NE | 209 | SF | 7 | \$0 | |
| | Hand Dryer | Basement NE | 2 | EΑ | 7 | \$0 | |
| | Hand Dryer | Basement NE | 2 | EA | 7 | \$0 | |
| | Lavatory | Basement NE | 3 | EΑ | 7 | \$0 | |
| | Lavatory | Basement NE | 2 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Basement NE | 3 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Basement NE | 3 | EA | 7 | \$0 | |
| | Partitions | Basement NE | 2 | EA | 7 | \$0 | |
| | Partitions | Basement NE | 2 | EA | 7 | \$0 | |
| | Urinals | Basement NE | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Basement NE | 440 | SF | 7 | \$0 | |
| | Walls - Concrete Block | Basement NE | 460 | SF | 7 | \$0 | |
| | Water Closet | Basement NE | 2 | EA | 7 | \$0 | |
| | Water Closet | Basement NE | 3 | EA | 7 | \$0 | |
| | Accessories | Basement NW | 144 | SF | 6 | \$1,328 | |
| | Accessories | Basement NW | 144 | SF | 6 | \$1,328 | |
| | Ceiling - Exposed | Basement NW | 144 | SF | 6 | \$214 | Hairline cracks in concrete |
| | Ceiling - Exposed | Basement NW | 144 | SF | 6 | \$214 | Hairline cracks in concrete |
| | Doors - Steel Doors incl hw | Basement NW | 1 | EA | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Basement NW | 1 | EA | 7 | \$0 | |
| | Floor Drain | Basement NW | 1 | EA | 7 | \$0 | |
| | Floor Drain | Basement NW | 1 | EA | 7 | \$0 | |



| Group Ite | em - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-----------|--------------------------------|-------------|----------|------|------|---------|-----------------------------|
| Restroom | | | | | | | |
| FI | loor - Tile Ceramic/ Porcelain | Basement NW | 144 | SF | 7 | \$0 | |
| FI | loor - Tile Ceramic/ Porcelain | Basement NW | 144 | SF | 7 | \$0 | |
| Н | land Dryer | Basement NW | 2 | EA | 7 | \$0 | |
| Н | land Dryer | Basement NW | 2 | EA | 7 | \$0 | |
| La | avatory | Basement NW | 2 | EA | 7 | \$0 | |
| La | avatory | Basement NW | 2 | EA | 7 | \$0 | |
| Li | ighting - Lay-in | Basement NW | 3 | EA | 7 | \$0 | |
| Li | ighting - Lay-in | Basement NW | 3 | EA | 7 | \$0 | |
| P | Partitions | Basement NW | 2 | EA | 7 | \$0 | |
| P | Partitions | Basement NW | 2 | EA | 7 | \$0 | |
| U | Jrinals | Basement NW | 2 | EA | 7 | \$0 | |
| W | Valls - Concrete Block | Basement NW | 396 | SF | 7 | \$0 | |
| W | Valls - Concrete Block | Basement NW | 396 | SF | 7 | \$0 | |
| W | Vater Closet | Basement NW | 2 | EA | 7 | \$0 | |
| W | Vater Closet | Basement NW | 3 | EA | 7 | \$0 | |
| A | ccessories | Basement SW | 198 | SF | 6 | \$1,826 | |
| A | ccessories | Basement SW | 198 | SF | 6 | \$1,826 | |
| С | Ceiling - Exposed | Basement SW | 198 | SF | 6 | \$294 | Hairline cracks in concrete |
| С | Ceiling - Exposed | Basement SW | 198 | SF | 6 | \$294 | Hairline cracks in concrete |
| D | Doors - Steel Doors incl hw | Basement SW | 1 | EA | 7 | \$0 | |
| D | Doors - Steel Doors incl hw | Basement SW | 1 | EA | 7 | \$0 | |
| FI | loor Drain | Basement SW | 1 | EA | 7 | \$0 | |
| FI | loor Drain | Basement SW | 1 | EA | 7 | \$0 | |
| FI | loor - Tile Ceramic/ Porcelain | Basement SW | 198 | SF | 7 | \$0 | |
| FI | loor - Tile Ceramic/ Porcelain | Basement SW | 198 | SF | 7 | \$0 | |
| Н | land Dryer | Basement SW | 2 | EA | 7 | \$0 | |
| Н | land Dryer | Basement SW | 2 | EA | 7 | \$0 | |
| La | avatory | Basement SW | 3 | EA | 7 | \$0 | |
| La | avatory | Basement SW | 3 | EA | 7 | \$0 | |
| Li | ighting - Lay-in | Basement SW | 1 | EA | 7 | \$0 | |
| Li | ighting - Lay-in | Basement SW | 1 | EA | 7 | \$0 | |
| Li | ighting - Wall Mounted | Basement SW | 9 | EA | 7 | \$0 | |
| Li | ighting - Wall Mounted | Basement SW | 9 | EA | 7 | \$0 | |
| P | Partitions | Basement SW | 2 | EA | 7 | \$0 | |
| P | Partitions | Basement SW | 3 | EA | 7 | \$0 | |
| U | Irinals | Basement SW | 2 | EA | 7 | \$0 | |
| W | Valls - Concrete Block | Basement SW | 496 | SF | 7 | \$0 | |



| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------|---------------------------------|------------------|-------------|------|------|---------|-----------------|
| Restro | | | - Juan nity | Jt | ··· | - 0001 | |
| | Walls - Concrete Block | Basement SW | 496 | SF | 7 | \$0 | |
| | Water Closet | Basement SW | 2 | EA | 7 | \$0 | |
| | Water Closet | Basement SW | 4 | EA | 7 | \$0 | |
| | Accessories | Boys - Near 218 | 276 | SF | 6 | \$2,546 | |
| | Ceiling - Exposed | Boys - Near 218 | 20 | SF | 6 | \$42 | Hairline cracks |
| | Ceiling - Exposed | Boys - Near 218 | 256 | SF | 7 | \$0 | Tanino oracio |
| | Floor Drain | Boys - Near 218 | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | Boys - Near 218 | 276 | SF | 7 | \$0 | |
| | Hand Dryer | Boys - Near 218 | 2 | EA | 7 | \$0 | |
| | Lavatory | Boys - Near 218 | 4 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Boys - Near 218 | 9 | EA | 7 | \$0 | |
| | Partitions | Boys - Near 218 | 3 | EA | 7 | \$0 | |
| | Urinals | Boys - Near 218 | 3 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Boys - Near 218 | 691 | SF | 7 | \$0 | |
| | Water Closet | Boys - Near 218 | 3 | EA | 7 | \$0 | |
| | Accessories | Boy's - Near 235 | 276 | SF | 6 | \$2,546 | |
| | Ceiling - Exposed | Boy's - Near 235 | 256 | SF | 7 | \$0 | |
| | Ceiling - Exposed | Boy's - Near 235 | 20 | SF | 6 | \$42 | Hairline cracks |
| | Floor Drain | Boy's - Near 235 | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | Boy's - Near 235 | 276 | SF | 7 | \$0 | |
| | Hand Dryer | Boy's - Near 235 | 2 | EA | 7 | \$0 | |
| | Lavatory | Boy's - Near 235 | 4 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Boy's - Near 235 | 9 | EA | 7 | \$0 | |
| | Partitions | Boy's - Near 235 | 3 | EA | 7 | \$0 | |
| | Urinals | Boy's - Near 235 | 3 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Boy's - Near 235 | 691 | SF | 7 | \$0 | |
| | Water Closet | Boy's - Near 235 | 3 | EA | 7 | \$0 | |
| | Accessories | Girls - Near 218 | 276 | SF | 6 | \$2,546 | |
| | Ceiling - Exposed | Girls - Near 218 | 40 | SF | 6 | \$71 | Hairline cracks |
| | Ceiling - Exposed | Girls - Near 218 | 236 | SF | 7 | \$0 | |
| | Floor Drain | Girls - Near 218 | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | Girls - Near 218 | 276 | SF | 7 | \$0 | |
| | Hand Dryer | Girls - Near 218 | 2 | EA | 7 | \$0 | |
| | Lavatory | Girls - Near 218 | 4 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Girls - Near 218 | 9 | EA | 7 | \$0 | |
| | Partitions | Girls - Near 218 | 5 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Girls - Near 218 | 691 | SF | 7 | \$0 | |
| | | | | - | | , , | |




| oup | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|-------|---------------------------------|---------------------|----------|------|------|------|-----------------|
| estro | om | | | | | | |
| | Water Closet | Girls - Near 218 | 6 | EA | 7 | \$0 | |
| | Accessories | Girls - Near 235 | 276 | SF | 7 | \$0 | |
| | Ceiling - Exposed | Girls - Near 235 | 266 | SF | 7 | \$0 | |
| | Ceiling - Exposed | Girls - Near 235 | 10 | SF | 6 | \$21 | Hairline cracks |
| | Floor Drain | Girls - Near 235 | 1 | EA | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | Girls - Near 235 | 276 | SF | 7 | \$0 | |
| | Hand Dryer | Girls - Near 235 | 2 | EA | 7 | \$0 | |
| | Lavatory | Girls - Near 235 | 4 | EA | 7 | \$0 | |
| | Lighting - Lay-in | Girls - Near 235 | 9 | EA | 7 | \$0 | |
| | Partitions | Girls - Near 235 | 5 | EA | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Girls - Near 235 | 691 | SF | 7 | \$0 | |
| | Water Closet | Girls - Near 235 | 6 | EΑ | 7 | \$0 | |
| | Accessories | In pool office 005A | 128 | SF | 7 | \$0 | |
| | Ceiling - Exposed | In pool office 005A | 128 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | In pool office 005A | 1 | EΑ | 7 | \$0 | |
| | Floor Drain | In pool office 005A | 2 | EΑ | 7 | \$0 | |
| | Floor - Concrete Epoxy/ Painted | In pool office 005A | 128 | SF | 7 | \$0 | |
| | Hand Dryer | In pool office 005A | 1 | EΑ | 7 | \$0 | |
| | Lavatory | In pool office 005A | 1 | EΑ | 7 | \$0 | |
| | Lighting - Lay-in | In pool office 005A | 3 | EA | 7 | \$0 | |
| | Showers | In pool office 005A | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | In pool office 005A | 340 | SF | 7 | \$0 | |
| | Walls - Tile Ceramic/ Porcelain | In pool office 005A | 72 | SF | 7 | \$0 | |
| | Water Closet | In pool office 005A | 1 | EA | 7 | \$0 | |
| | Accessories | In pool office 005B | 128 | SF | 7 | \$0 | |
| | Ceiling - Exposed | In pool office 005B | 128 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | In pool office 005B | 1 | EA | 7 | \$0 | |
| | Floor Drain | In pool office 005B | 2 | EA | 7 | \$0 | |
| | Floor - Concrete Epoxy/ Painted | In pool office 005B | 128 | SF | 7 | \$0 | |
| | Hand Dryer | In pool office 005B | 1 | EA | 7 | \$0 | |
| | Lavatory | In pool office 005B | 1 | EA | 7 | \$0 | |
| | Lighting - Lay-in | In pool office 005B | 3 | EA | 7 | \$0 | |
| | Showers | In pool office 005B | 1 | EA | 7 | \$0 | |
| | Walls - Concrete Block | In pool office 005B | 340 | SF | 7 | \$0 | |
| | Walls - Tile Ceramic/ Porcelain | In pool office 005B | 72 | SF | 7 | \$0 | |
| | Water Closet | In pool office 005B | 1 | EA | 7 | \$0 | |
| | Accessories | In Rm 004G | 128 | SF | 7 | \$0 | |



| Restroom Benches In Rm 004G 8 LF 7 \$0 Ceiling - Plaster/Drywall In Rm 004G 128 SF 7 \$0 Doors - Steel Doors incl hw In Rm 004G 2 EA 7 \$0 Floor Drain In Rm 004G 1 EA 7 \$0 Floor - Tile In Rm 004G 64 SF 7 \$0 Floor - Tile Ceramic/ Porcelain In Rm 004G 64 SF 7 \$0 Hand Dryer In Rm 004G 1 EA 7 \$0 Lavatory In Rm 004G 1 EA 7 \$0 Lighting - Lay-in In Rm 004G 2 EA 7 \$0 Showers In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 | m - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--|--------------------------------|-------------------|----------|------|------|------|----------|
| Ceiling - Plaster/Drywall In Rm 004G 128 SF 7 \$0 Doors - Steel Doors incl hw In Rm 004G 2 EA 7 \$0 Floor Drain In Rm 004G 1 EA 7 \$0 Floor - Tile In Rm 004G 64 SF 7 \$0 Floor - Tile Ceramic/ Porcelain In Rm 004G 64 SF 7 \$0 Hand Dryer In Rm 004G 1 EA 7 \$0 Lavatory In Rm 004G 1 EA 7 \$0 Lighting - Lay-in In Rm 004G 2 EA 7 \$0 Showers In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 | | | | | | | |
| Ceiling - Plaster/Drywall In Rm 004G 128 SF 7 \$0 Doors - Steel Doors incl hw In Rm 004G 2 EA 7 \$0 Floor Drain In Rm 004G 1 EA 7 \$0 Floor - Tile In Rm 004G 64 SF 7 \$0 Floor - Tile Ceramic/ Porcelain In Rm 004G 64 SF 7 \$0 Hand Dryer In Rm 004G 1 EA 7 \$0 Lavatory In Rm 004G 1 EA 7 \$0 Lighting - Lay-in In Rm 004G 2 EA 7 \$0 Showers In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 | nches | In Rm 004G | 8 | LF | 7 | \$0 | |
| Doors - Steel Doors incl hw In Rm 004G 2 EA 7 \$0 Floor Drain In Rm 004G 1 EA 7 \$0 Floor - Tile In Rm 004G 64 SF 7 \$0 Floor - Tile Ceramic/ Porcelain In Rm 004G 64 SF 7 \$0 Hand Dryer In Rm 004G 1 EA 7 \$0 Lavatory In Rm 004G 1 EA 7 \$0 Lighting - Lay-in In Rm 004G 2 EA 7 \$0 Showers In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 Staff | ling - Plaster/Drywall | In Rm 004G | 128 | SF | 7 | \$0 | |
| Floor - Tile In Rm 004G 64 SF 7 \$0 Floor - Tile Ceramic/ Porcelain In Rm 004G 64 SF 7 \$0 Hand Dryer In Rm 004G 1 EA 7 \$0 Lavatory In Rm 004G 1 EA 7 \$0 Lighting - Lay-in In Rm 004G 2 EA 7 \$0 Showers In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 Staff | ors - Steel Doors incl hw | In Rm 004G | 2 | EA | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain In Rm 004G 64 SF 7 \$0 Hand Dryer In Rm 004G 1 EA 7 \$0 Lavatory In Rm 004G 1 EA 7 \$0 Lighting - Lay-in In Rm 004G 2 EA 7 \$0 Showers In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 Staff | or Drain | In Rm 004G | 1 | EA | 7 | \$0 | |
| Hand Dryer In Rm 004G 1 EA 7 \$0 Lavatory In Rm 004G 1 EA 7 \$0 Lighting - Lay-in In Rm 004G 2 EA 7 \$0 Showers In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 | or - Tile | In Rm 004G | 64 | SF | 7 | \$0 | |
| Lavatory In Rm 004G 1 EA 7 \$0 Lighting - Lay-in In Rm 004G 2 EA 7 \$0 Showers In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 | or - Tile Ceramic/ Porcelain | In Rm 004G | 64 | SF | 7 | \$0 | |
| Lighting - Lay-in In Rm 004G 2 EA 7 \$0 Showers In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 Staff | nd Dryer | In Rm 004G | 1 | EA | 7 | \$0 | |
| Showers In Rm 004G 1 EA 7 \$0 Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 Staff | atory | In Rm 004G | 1 | EA | 7 | \$0 | |
| Student Lockers - One Tier In Rm 004G 8 EA 7 \$0 Staff | nting - Lay-in | In Rm 004G | 2 | EA | 7 | \$0 | |
| | owers | In Rm 004G | 1 | EA | 7 | \$0 | |
| Walls - Concrete Block In Rm 004G 464 SF 7 \$0 | dent Lockers - One Tier | In Rm 004G | 8 | EA | 7 | \$0 | Staff |
| | ills - Concrete Block | In Rm 004G | 464 | SF | 7 | \$0 | |
| Walls - Tile Ceramic/ Porcelain In Rm 004G 72 SF 7 \$0 | ılls - Tile Ceramic/ Porcelain | In Rm 004G | 72 | SF | 7 | \$0 | |
| Water Closet In Rm 004G 1 EA 7 \$0 | iter Closet | In Rm 004G | 1 | EA | 7 | \$0 | |
| Accessories Near 218 56 SF 7 \$0 | essories | Near 218 | 56 | SF | 7 | \$0 | |
| Ceiling - Lay-in Near 218 56 SF 7 \$0 | ling - Lay-in | Near 218 | 56 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw Near 218 1 EA 7 \$0 | ors - Steel Doors incl hw | Near 218 | 1 | EA | 7 | \$0 | |
| Floor Drain Near 218 1 EA 7 \$0 | or Drain | Near 218 | 1 | EA | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain Near 218 56 SF 7 \$0 | or - Tile Ceramic/ Porcelain | Near 218 | 56 | SF | 7 | \$0 | |
| Hand Dryer Near 218 1 EA 7 \$0 | nd Dryer | Near 218 | 1 | EA | 7 | \$0 | |
| Lavatory Near 218 1 EA 7 \$0 | atory | Near 218 | 1 | EA | 7 | \$0 | |
| Lighting - Lay-in Near 218 1 EA 7 \$0 | nting - Lay-in | Near 218 | 1 | EA | 7 | \$0 | |
| Walls - Concrete Block Near 218 304 SF 7 \$0 | ills - Concrete Block | Near 218 | 304 | SF | 7 | \$0 | |
| Water Closet Near 218 1 EA 7 \$0 | iter Closet | Near 218 | 1 | EA | 7 | \$0 | |
| Accessories | cessories | Near 235 | 56 | SF | 7 | \$0 | |
| Ceiling - Lay-in Near 235 56 SF 7 \$0 | ling - Lay-in | Near 235 | 56 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw Near 235 1 EA 7 \$0 | ors - Steel Doors incl hw | Near 235 | 1 | EA | 7 | \$0 | |
| Floor Drain Near 235 1 EA 7 \$0 | or Drain | Near 235 | 1 | EA | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain Near 235 56 SF 7 \$0 | or - Tile Ceramic/ Porcelain | Near 235 | 56 | SF | 7 | \$0 | |
| Hand Dryer Near 235 1 EA 7 \$0 | nd Dryer | Near 235 | 1 | EA | 7 | \$0 | |
| Lavatory Near 235 1 EA 7 \$0 | atory | Near 235 | 1 | EA | 7 | \$0 | |
| Lighting - Lay-in Near 235 1 EA 7 \$0 | nting - Lay-in | Near 235 | 1 | EA | 7 | \$0 | |
| Walls - Concrete Block Near 235 304 SF 7 \$0 | ills - Concrete Block | Near 235 | 304 | SF | 7 | \$0 | |
| Water Closet Near 235 1 EA 7 \$0 | iter Closet | Near 235 | 1 | EA | 7 | \$0 | |
| Accessories Near Media Center 119 SF 7 \$0 | cessories | Near Media Center | 119 | SF | 7 | \$0 | |
| Ceiling - Plaster/Drywall Near Media Center 119 SF 7 \$0 | ling - Plaster/Drywall | Near Media Center | 119 | SF | 7 | \$0 | |
| Doors - Steel Doors incl hw Near Media Center 1 EA 7 \$0 | ors - Steel Doors incl hw | Near Media Center | 1 | EA | 7 | \$0 | |







Category: Rooms (Other Than Classrooms)

| up Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------------------------------|-------------------|----------|------|------|------|----------|
| troom | | | | | | |
| Floor Drain | Near Media Center | 1 | EA | 7 | \$0 | |
| Floor - Tile Ceramic/ Porcelain | Near Media Center | 119 | SF | 7 | \$0 | |
| Hand Dryer | Near Media Center | 1 | EA | 7 | \$0 | |
| Lavatory | Near Media Center | 1 | EA | 7 | \$0 | |
| Lighting - Lay-in | Near Media Center | 2 | EA | 7 | \$0 | |
| Showers | Near Media Center | 1 | EA | 7 | \$0 | |
| Walls - Plaster/Drywall | Near Media Center | 230 | SF | 7 | \$0 | |
| Walls - Tile Ceramic/ Porcelain | Near Media Center | 260 | SF | 7 | \$0 | |
| Water Closet | Near Media Center | 1 | EΑ | 7 | \$0 | |

Rooms (Other Than Classrooms) Subtotal:

\$521,621

Building: Main

| p Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|--------------------------------|-----------|----------|------|------|----------|-------------------------|
| dor | | | | | | |
| Ceiling - Lay-in | 1st Floor | 6,791 | SF | 6 | \$20,393 | Total Sq Ft 12,182 |
| Ceiling - Lay-in | 1st Floor | 10 | SF | 4 | \$156 | water stains |
| Ceiling - Plaster/Drywall | 1st Floor | 310 | SF | 6 | \$2,700 | in Main Lobby Vestibule |
| Ceiling - Plaster/Drywall | 1st Floor | 5,310 | SF | 6 | \$32,879 | |
| Doors - Side-lite | 1st Floor | 475 | EA | 7 | \$0 | |
| Doors - Steel Doors incl hw | 1st Floor | 2 | EΑ | 7 | \$0 | |
| Doors - Store Front | 1st Floor | 17 | EA | 7 | \$0 | |
| Doors - Transom Window | 1st Floor | 125 | EΑ | 7 | \$0 | |
| Drinking Fountains | 1st Floor | 4 | EΑ | 7 | \$0 | |
| Floor - Lay-in | 1st Floor | 908 | SF | 6 | \$0 | |
| Floor - Terrazzo | 1st Floor | 11,274 | SF | 7 | \$0 | |
| Floor - Tile/Sheet | 1st Floor | 240 | SF | 7 | \$0 | |
| Lighting - Lay-in | 1st Floor | 146 | EA | 7 | \$0 | 26 are cans |
| Lighting - Pendent/Surface | 1st Floor | 10 | EA | 7 | \$0 | |
| Lighting - Wall Mounted | 1st Floor | 6 | EΑ | 7 | \$0 | |
| Walls - Concrete Block | 1st Floor | 532 | SF | 6 | \$1,560 | |
| Walls - Masonry | 1st Floor | 240 | SF | 7 | \$0 | in Main Lobby Vestibule |
| Walls - Masonry | 1st Floor | 2,867 | SF | 7 | \$0 | |
| Walls - Plaster/Drywall | 1st Floor | 5,013 | SF | 6 | \$22,223 | |
| Walls - Structural Glazed Tile | 1st Floor | 5,818 | SF | 7 | \$0 | |
| Ceiling - Exposed | 2nd Floor | 368 | SF | 7 | \$0 | |



| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|---------|---|-----------|----------|-------|--------|----------|--------------------|
| Corrido | | Location | Quantity | Oilit | Runk | 0031 | Commence |
| ooma | Ceiling - Lay-in | 2nd Floor | 284 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 3,398 | SF | 7 | \$0 | |
| | Doors - Steel Doors incl hw | 2nd Floor | 19 | EA | 7 | \$0 | |
| | Doors - Transom Window | 2nd Floor | 880 | EA | 7 | \$0 | |
| | Drinking Fountains - Single Water Cooler | 2nd Floor | 6 | EA | 7 | \$0 | |
| | Floor - Terrazzo | 2nd Floor | 11,985 | SF | 7 | \$0 | |
| | Floor - Tile/Sheet | 2nd Floor | 86 | SF | 7 | \$0 | |
| | Lighting - Lay-in | 2nd Floor | 215 | EA | 7 | \$0 | |
| | Lighting - Lay-in Lighting - Wall Mounted | 2nd Floor | 108 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | 2nd Floor | 621 | EA | 7 | \$0 | |
| | Walls - Masonry | 2nd Floor | 551 | SF | 7 | \$0 | |
| | • | 2nd Floor | | SF | | | |
| | Walls - Plaster/Drywall | | 342 | SF | 7 7 | \$0 | |
| | Walls - Structural Glazed Tile Walls - Structural Glazed Tile | 2nd Floor | 17,762 | _ | | \$0 | |
| | | 2nd Floor | 670 | SF | 7 | \$0 | T-1-1 Ov. 51 0 405 |
| | Ceiling - Plaster/Drywall | 3rd Floor | 9,465 | SF | 6 | \$58,606 | Total Sq Ft 9,465 |
| | Doors - Side-lite | 3rd Floor | 295 | EA | 7 | \$0 | |
| | Doors - Store Front | 3rd Floor | 6 | EA | 7 | \$0 | |
| | Doors - Transom Window | 3rd Floor | 12 | EA | 7 | \$0 | |
| | Drinking Fountains - Single Water Cooler | 3rd Floor | 4 | EA | 6 | \$1,267 | |
| | Floor - Terrazzo | 3rd Floor | 9,465 | SF | 6 | \$79,450 | |
| | Lighting - Lay-in | 3rd Floor | 173 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 3rd Floor | 54 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 3rd Floor | 156 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | 3rd Floor | 621 | EA | 6 | \$57,651 | |
| | Walls - Masonry | 3rd Floor | 828 | SF | 7 | \$0 | |
| | Walls - Plaster/Drywall | 3rd Floor | 6,931 | SF | 6 | \$30,725 | |
| | Walls - Structural Glazed Tile | 3rd Floor | 7,937 | SF | 7 | \$0 | |
| | Ceiling - Exposed | Basement | 197 | SF | 6 | \$293 | |
| | Ceiling - Lay-in | Basement | 4,226 | SF | 7 | \$0 | |
| | Doors - Side-lite | Basement | 10 | EA | 7 | \$0 | |
| | Doors - Steel Doors incl hw | Basement | 16 | EA | 7 | \$0 | |
| | Floor - Concrete Epoxy/ Painted | Basement | 35 | SF | 7 | \$0 | |
| | Floor - Terrazzo | Basement | 4,188 | SF | 7 | \$0 | |
| | Lighting - Lay-in | Basement | 53 | EA | 7 | \$0 | |
| | Walls - Concrete Block | Basement | 740 | SF | 7 | \$0 | |
| | Walls - Masonry | Basement | 461 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Basement | 5,211 | SF | 7 | \$0 | |







| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|--------------------------------|----------------------------------|----------|------|------|----------|--|
| Safety | ,, | | • | | | | |
| | Camera Viewing Station | | 3 | EA | 6 | \$2,048 | Principal, Main Office & Security Desk |
| | Metal Dedector | | 3 | EA | 6 | \$2,642 | , |
| | Security Cameras | | 156 | EA | 6 | \$30,270 | |
| | Security Cameras | | 50 | EΑ | 6 | \$9,702 | |
| . | | | | | | | |
| Stairs | 0.11. DL + /D 11 | O | 0.004 | 05 | | 40 | |
| | Ceiling - Plaster/Drywall | Stair A | 2,004 | SF | 7 | \$0 | |
| | Floor - Terrazzo | Stair A | 1,570 | SF | 7 | \$0 | |
| | Handrails | Stair A | 376 | LF | 7 | \$0 | |
| | Lighting - Pendent/Surface | Stair A | 36 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | Stair A | 3 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | Stair A | 79 | LF | 7 | \$0 | |
| | Walls - Masonry | Stair A | 1,526 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Stair A | 876 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Stair F | 1,309 | SF | 7 | \$0 | |
| | Floor - Asphalt | Stair F | 310 | SF | 7 | \$0 | |
| | Floor - Concrete | Stair F | 421 | SF | 6 | \$223 | |
| | Handrails | Stair F | 176 | LF | 7 | \$0 | |
| | Lighting - Lay-in | Stair F | 7 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Stair F | 6 | EA | 7 | \$0 | |
| | Stairs - Concrete | Stair F | 27 | LF | 7 | \$0 | |
| | Walls - Concrete Block | Stair F | 3,036 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Stair G | 584 | SF | 7 | \$0 | |
| | Floor - Concrete | Stair G | 438 | SF | 6 | \$232 | |
| | Handrails | Stair G | 48 | LF | 7 | \$0 | |
| | Lighting - Lay-in | Stair G | 6 | EΑ | 7 | \$0 | |
| | Lighting - Pendent/Surface | Stair G | 4 | EΑ | 7 | \$0 | |
| | Stairs - Concrete | Stair G | 20 | LF | 7 | \$0 | |
| | Walls - Concrete Block | Stair G | 2,561 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Stair L | 525 | SF | 7 | \$0 | |
| | Floor - Concrete | Stair L | 406 | SF | 7 | \$0 | |
| | Handrails | Stair L | 74 | LF | 7 | \$0 | |
| | Lighting - Lay-in | Stair L | 6 | EA | 7 | \$0 | |
| | Stairs - Concrete | Stair L | 17 | LF | 7 | \$0 | |
| | Walls - Concrete Block | Stair L | 1,756 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Stairwell K (ground to 1st only) | 540 | SF | 6 | \$3,954 | |
| | Floor - Terrazzo | Stairwell K (ground to 1st only) | 309 | SF | 6 | \$2,594 | |
| | Handrails | Stairwell K (ground to 1st only) | 44 | LF | 6 | \$381 | |
| | Taratano | otaliwon it (ground to 1st only) | 44 | | J | ψοσι | |



| | Itom - Type | Location | Ougntitu | l Init | Dank | Coct | Comments |
|-------|--------------------------------|--|----------|--------|--------|------------|----------|
| | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
| tairs | Lighting Dondont/Surface | Ctainwall V (ground to 1 at anh) | 6 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Stairwell K (ground to 1st only) | | | 7 | | |
| | Stairs - Terrazzo | Stairwell K (ground to 1st only) | 11 | LF | 6 | \$102 | |
| | Walls - Masonry | Stairwell K (ground to 1st only) | 250 | SF | 6 | \$787 | |
| | Walls - Structural Glazed Tile | Stairwell K (ground to 1st only) | 1,127 | SF | 6 | \$3,546 | |
| | Ceiling - Plaster/Drywall | Stairwell B (1st to 3rd) | 960 | SF | 6 | \$7,029 | |
| | Floor - Terrazzo | Stairwell B (1st to 3rd) | 532 | SF | 7 | \$0 | |
| | Handrails | Stairwell B (1st to 3rd) | 114 | LF | 7 | \$0 | |
| | Lighting - Lay-in | Stairwell B (1st to 3rd) | 18 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | Stairwell B (1st to 3rd) | 9 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | Stairwell B (1st to 3rd) | 57 | LF | 6 | \$529 | |
| | Walls - Structural Glazed Tile | Stairwell B (1st to 3rd) | 3,330 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Stairwell C (1st to 3rd) | 617 | SF | 6 | \$4,517 | |
| | Floor - Terrazzo | Stairwell C (1st to 3rd) | 360 | SF | 7 | \$0 | |
| | Handrails | Stairwell C (1st to 3rd) | 298 | LF | 7 | \$0 | |
| | Lighting - Lay-in | Stairwell C (1st to 3rd) | 9 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | Stairwell C (1st to 3rd) | 12 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | Stairwell C (1st to 3rd) | 93 | LF | 6 | \$863 | |
| | Walls - Structural Glazed Tile | Stairwell C (1st to 3rd) | 2,160 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Stairwell D (Basement to 2nd) | 955 | SF | 6 | \$6,992 | |
| | Floor - Concrete | Stairwell D (Basement to 2nd) | 172 | SF | 6 | \$91 | |
| | Floor - Terrazzo | Stairwell D (Basement to 2nd) | 237 | SF | 7 | \$0 | |
| | Handrails | Stairwell D (Basement to 2nd) | 118 | LF | 7 | \$0 | |
| | Lighting - Lay-in | Stairwell D (Basement to 2nd) | 5 | EA | 7 | \$0 | |
| | Lighting - Pendent/Surface | Stairwell D (Basement to 2nd) | 6 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | Stairwell D (Basement to 2nd) | 4 | EA | 7 | \$0 | |
| | Stairs - Concrete | Stairwell D (Basement to 2nd) | 30 | LF | 6 | \$249 | |
| | Stairs - Terrazzo | Stairwell D (Basement to 2nd) | 29 | LF | 6 | \$269 | |
| | Walls - Concrete Block | Stairwell D (Basement to 2nd) | 1,577 | SF | 6 | \$4,623 | |
| | Walls - Masonry | Stairwell D (Basement to 2nd) | 434 | SF | 7 | \$0 | |
| | Ceiling - Plaster/Drywall | Stairwell E (2nd Floor to 1st) | 412 | SF | 6 | \$3,016 | |
| | Floor - Terrazzo | Stairwell E (2nd Floor to 1st) Stairwell E (2nd Floor to 1st) | 145 | SF | 7 | \$3,010 | |
| | | , | | LF | 7 7 | | |
| | Handrails | Stairwell E (2nd Floor to 1st) | 36 | | | \$0 \$0 | |
| | Lighting - Lay-in | Stairwell E (2nd Floor to 1st) | 3 | EΑ | 7 | \$0 \$0 | |
| | Lighting - Wall Mounted | Stairwell E (2nd Floor to 1st) | 4 | EA | 7 | \$0 | |
| | Stairs - Terrazzo | Stairwell E (2nd Floor to 1st) | 18 | LF | 6 | \$167 | |
| | Walls - Masonry | Stairwell E (2nd Floor to 1st) | 931 | SF | 7 | \$0 | |
| | Walls - Structural Glazed Tile | Stairwell E (2nd Floor to 1st) | 615 | SF | 7 | \$0 | |







Category: Building Interior

| Group Item - Type | Location | Quantity | Unit | Rank | Cost | Comments | |
|---------------------------------|----------|----------|------|------|----------|-----------|--|
| Vertical Conveyance | | | | | | | |
| Elevator - Hydraulic Elevator | | 1 | EA | 6 | \$19,238 | | |
| Elevator - Lula | | 1 | EA | 6 | \$11,667 | | |
| Wheelchair Lift - Platform Lift | | 1 | EΑ | 6 | \$6,690 | for stage | |
| | | | | | 1400 004 | | |

Building Interior Subtotal: \$430,321

Total Building Cost \$1,204,848

SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|-----------------------------------|--------------------------|----------|------|------|-----------|-------------------------|
| Athletic | : | | | | | | |
| | Metal Bleachers | Entire Site | 105 | LF | 7 | \$0 | |
| | Metal Bleachers | Entire Site | 2,520 | LF | 6 | \$112,432 | |
| | Surface - Asphalt | Entire Site | 17,238 | SF | 7 | \$0 | |
| | Surface - Natural | Entire Site | 44,120 | SF | 6 | \$36,593 | |
| | Surface - Synthetic | Entire Site | 74,133 | SF | 7 | \$0 | |
| Civil/Dr | rainage | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 28 | EA | 7 | \$0 | |
| | Civil/ Drainage - Site Drain | Entire Site | 2 | EA | 7 | \$0 | |
| | Civil/ Drainage - Site Manhole | Entire Site | 7 | EA | 7 | \$0 | |
| Fencing | g | | | | | | |
| | Fencing - Chain Link | Entire Site | 1,604 | LF | 7 | \$0 | |
| | Fencing - New Standard Ornamental | Entire Site | 490 | LF | 7 | \$0 | |
| Landsc | cape | | | | | | |
| | Benches | Entire Site | 30 | EA | 7 | \$0 | Concrete Seating |
| | Benches | Entire Site | 37 | EA | 7 | \$0 | Concrete |
| | Irrigation | Entire Site / South West | 44,120 | SF | 6 | \$49,842 | Baseball Field |
| | Landscape - Grass | Entire Site | 29,741 | SF | 6 | \$24,667 | |
| | Lighting | Entire Site | 36 | EA | 6 | \$0 | Landscape/ Up Lighting |
| | Lighting - Pole Mounted | Entire Site | 24 | EA | 6 | \$26,010 | |
| | Parkway trees | Entire Site | 38 | EA | 6 | \$25,082 | |
| | Planting Beds/ Area | Entire Site | 1,085 | SF | 6 | \$1,784 | |
| | Retaining Wall - Concrete | Entire Site | 3,220 | SF | 7 | \$0 | |
| | Retaining Wall - Masonry | Entire Site | 602 | SF | 7 | \$0 | |
| DACK | DE THE VARDS HS | Dago 52 of 56 | | | | | Accomment Date: 10/26/4 |



SITE

Category: Site

| Group | Item - Type | Location | Quantity | Unit | Rank | Cost | Comments |
|----------|---|-------------|----------|------|------|-----------|----------|
| Landsca | ape | | | | | | |
| | Trash Receptacles | Entire Site | 8 | EA | 6 | \$2,498 | |
| Parking | Lot | | | | | | |
| | Interior Plantings | Entire Site | 668 | LF | 6 | \$28,418 | |
| | Lighting - Pole Mounted | Entire Site | 12 | EA | 6 | \$17,430 | |
| | Pavers | Entire Site | 37,221 | SF | 7 | \$0 | |
| | Trash Compactor | Entire Site | 1 | EA | 6 | \$0 | |
| | Vehicular Screening | Entire Site | 85 | LF | 6 | \$6,693 | |
| Sidewal | ks | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 1,127 | LF | 7 | \$0 | |
| | Sidewalks - Internal Walks | Entire Site | 10 | LF | 6 | \$157 | |
| | Sidewalks - Internal Walks | Entire Site | 6,650 | LF | 7 | \$0 | Pavers |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 21,596 | SF | 7 | \$0 | |
| Signage | | | | | | | |
| | Flag Pole - Flag Pole | Entire Site | 3 | EA | 7 | \$0 | |
| | Monument - Building Mounted Cut Letter Sign | Entire Site | 1 | EA | 7 | \$0 | |
| Site S | ubtotal: | | | | | \$331,607 | |
| Total \$ | Site Cost | | | | | \$331,607 | |

Campus Total ^{2 3} \$1,536,455

Definitions

• Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.



Back of the Yards IB HS

2111 W 47th St Chicago, IL 60609

- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.







Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------------|------------------|-----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | + | | | | | | | | | | - | | - |
| Art Room | Art Room | 2nd Floor | 200B | NA | 1,098 | 0 | 28 | 36 | 424 | 0 | 40 | N | N | N |
| Art Room | Art Room | 2nd Floor | 200E | NA | 1,098 | 0 | 28 | 34 | 424 | 0 | 40 | N | N | N |
| Band Room | Band Room | 2nd Floor | 200I - Instrume | e Instrumental | 1,612 | 0 | 22 | 38 | 484 | 0 | 40 | N | N | N |
| Choral Room | Choral Room | 2nd Floor | 200G - Choral | Choral | 1,093 | 0 | 28 | 32 | 352 | 0 | 40 | N | N | N |
| Computer Lab | Other Instructional Use | 1st Floor | 119 | NA | 744 | 1 | 22 | 50 | 0 | 0 | 40 | N | N | N |
| Computer Lab | Computer Lab | 2nd Floor | 223 | NA | 1,227 | 1 | 60 | 68 | 193 | 42 | 40 | N | N | N |
| Computer Lab | Computer Lab | 2nd Floor | 225 | NA | 1,111 | 1 | 58 | 66 | 193 | 42 | 40 | N | N | N |
| Computer Lab | Computer Lab | 3rd Floor | 323 | NA | 1,110 | 1 | 38 | 80 | 174 | 44 | 40 | N | N | Υ |
| Computer Lab | Computer Lab | 3rd Floor | 325 | NA | 1,110 | 1 | 34 | 80 | 174 | 44 | 40 | N | N | Υ |
| Fitness Room | Fitness Room | Basement | 008 | Fitness | 1,305 | 0 | 8 | 18 | 0 | 0 | 40 | N | N | N |
| Music Room | Music Room | 2nd Floor | 2001-4 | Practice Room | 154 | 0 | 0 | 6 | 0 | 0 | 40 | N | N | N |
| Music Room | Music Room | 2nd Floor | 2001-5 | Practice Room | 104 | 0 | 0 | 6 | 0 | 0 | 40 | N | N | N |
| Music Room | Music Room | 2nd Floor | 2001-6 | Practice Room | 84 | 0 | 0 | 6 | 0 | 0 | 40 | N | N | N |
| Regular Classroom | Vacant | Basement | 010 | Athletic Storag | 1,320 | 0 | 0 | 0 | 0 | 0 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 217 | NA | 718 | 0 | 16 | 20 | 109 | 22 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 219 | NA | 718 | 0 | 16 | 20 | 109 | 22 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 220 | NA | 718 | 0 | 16 | 20 | 37 | 6 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 221 | NA | 680 | 0 | 6 | 18 | 109 | 22 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 222 | NA | 680 | 0 | 6 | 18 | 190 | 36 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 224 | NA | 718 | 0 | 16 | 20 | 109 | 22 | 20 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 227 | NA | 735 | 0 | 16 | 20 | 109 | 22 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 229 | NA | 735 | 0 | 16 | 20 | 109 | 22 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 231 | NA | 735 | 0 | 10 | 20 | 109 | 22 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 233 | NA | 718 | 0 | 16 | 20 | 109 | 22 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 236 | NA | 735 | 0 | 10 | 20 | 113 | 22 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 237 | NA | 680 | 0 | 6 | 18 | 190 | 36 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 238 | NA | 680 | 0 | 6 | 18 | 190 | 36 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 317 | NA | 718 | 0 | 7 | 28 | 116 | 29 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 319 | NA | 718 | 0 | 5 | 20 | 116 | 29 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 320 | NA | 718 | 0 | 7 | 28 | 116 | 29 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 321 | NA | 680 | 0 | 5 | 20 | 174 | 44 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 322 | NA | 680 | 0 | 5 | 20 | 174 | 44 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 324 | NA | 680 | 0 | 5 | 20 | 174 | 44 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 327 | NA | 735 | 0 | 7 | 28 | 116 | 29 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 329 | NA | 735 | 0 | 7 | 28 | 116 | 29 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 331 | NA | 735 | 0 | 7 | 28 | 116 | 29 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 333 | NA | 718 | 0 | 7 | 28 | 116 | 29 | 40 | N | N | N |

Back of the Yards IB HS

2111 W 47th St Chicago, IL 60609

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|---------------------|---------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | <u> </u> | | | | | | | | | - | | | + |
| Regular Classroom | Regular Classroom | 3rd Floor | 336 | NA | 718 | 0 | 7 | 28 | 116 | 29 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 337 | NA | 680 | 0 | 5 | 20 | 174 | 44 | 40 | N | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 338 | NA | 680 | 0 | 5 | 20 | 174 | 44 | 40 | N | Ν | N |
| Science | Science | 2nd Floor | 226 | NA | 880 | 0 | 24 | 30 | 193 | 42 | 40 | N | Ν | N |
| Science | Science | 2nd Floor | 230 | NA | 925 | 0 | 26 | 30 | 197 | 40 | 40 | N | Ν | N |
| Science Lab Level 1 | Science Lab Level 1 | 3rd Floor | 326 | NA | 1,225 | 1 | 12 | 42 | 145 | 36 | 40 | N | Ν | N |
| Science Lab Level 1 | Science Lab Level 1 | 3rd Floor | 330 | NA | 1,225 | 1 | 12 | 42 | 209 | 52 | 40 | N | Ν | N |
| Science Lab Level 2 | Science Lab Level 2 | 3rd Floor | 334 | NA | 1,225 | 1 | 12 | 42 | 145 | 36 | 40 | N | Ν | N |
| Science Lab Level 3 | Science Lab Level 3 | 2nd Floor | 234 | NA | 925 | 0 | 34 | 42 | 197 | 40 | 40 | N | Ν | N |