

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1896	2	55,812
Field House	1924	1	2,715
Campus Total			58,527

Catego	Category : Exterior				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Cell Equ	ipment						
•	Cell Equipment - Antenna	Entire Building	6	EA	7	10+ years	
	Cell Equipment - Cabinets	Entire Building	3	EA	7	10+ years	
	Cell Equipment - Generator	Entire Building	1	EA	7	10+ years	
Entrance	3						
	Entrance Control - Audio and Video	#1 SE	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#1 SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 SE	1	EA	6	10+ years	
	Power Door Operator and Controls	#1 SE	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#2 S	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 S	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#3 SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 SW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 SW	7	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#4 NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 NW	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 W	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 W	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5.5 N	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6 N	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 N	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7 E	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 E	1	EA	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Entrance Control - Audio and Video	#8 NE	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#8 NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 NE	1	EA	6	10+ years	
Fire Esca	ape						
	Fire Escape	North Façade	90	LF	6	10+ years	
Foundati	ion						
	Foundation - Concrete	Entire Building	640	LF	7	10+ years	
	Foundation - Concrete	Entire Building	20	LF	6	10+ years	Seepage, possible movement at mai
							entry lobby; floor is cracked, and settlement of 1/2 inch difference
	Superstructure - Heavy Timber	Entire Building	51,472	SF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	4,340	SF	7	10+ years	
Liahtina							
-00	Exterior Lighting - Wall Mounted	Entire Building	17	EA	6	10+ years	
Roof Sys	stem						
	Coping - Stone	#1	61	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#1	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	#1	61	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#1	386	SF	6	10+ years	
	Roof Structure - Heavy Timber	#1	386	SF	7	10+ years	
	Access Ladder - Metal	#2	1	EA	7	10+ years	
	Access Ladder - Wood	#2	1	EA	5	2-5 years	
	Coping - Clay Tile	#2	167	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#2	78	LF	6	10+ years	
	Parapet - 16" - 30" Height	#2	167	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#2	3,200	SF	6	10+ years	
	Roof Hatch - Metal	#2	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	#2	3,200	SF	7	10+ years	
	Access Ladder - Metal	#3	3,200	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	#3	50	LF	6	10+ years	
	Liner					•	
	Coping - Clay Tile	#3	366	LF	6	10+ years	Cracks
	Downspouts - Exterior Downspouts	#3	84	LF	6	10+ years	
	Parapet - 16" - 30" Height	#3	100	LF	6	10+ years	
	Parapet - 16" - 30" Height	#3	83	LF	5	10+ years	Open joints
	Parapet - Parapet > 30"	#3	183	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#3	6,678	SF	6	10+ years	
	Roof Hatch - Metal	#3	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	#3	6,678	SF	7	10+ years	



atego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	#4	1	EA	7	10+ years	
	Access Ladder - Wood	#4	1	EA	5	2-5 years	
	Coping - Clay Tile	#4	130	LF	6	10+ years	
	Coping - Clay Tile	#4	5	LF	6	10+ years	Previous water infiltration
	Downspouts - Exterior Downspouts	#4	78	LF	6	10+ years	
	Parapet - 16" - 30" Height	#4	135	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#4	3,618	SF	6	10+ years	
	Roof Hatch - Metal	#4	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	#4	3,618	SF	7	10+ years	
	Coping - Stone	#5	63	LF	6	10+ years	
	Downspouts - Exterior Downspouts	#5	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	#5	63	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#5	386	SF	6	10+ years	
	Roof Structure - Heavy Timber	#5	386	SF	7	10+ years	
	Coping - Clay Tile	#6	341	LF	6	10+ years	
	Coping - Clay Tile	#6	1	LF	5	1-2 years	Hole
	Downspouts - Exterior Downspouts	#6	52	LF	6	10+ years	
	Parapet - Parapet < 16" Height	#6	342	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	#6	3,944	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	#6	3,977	SF	7	10+ years	
	The state of the s	0	3,011	О.	•	.o. you.o	
alls							
	Cornice - Masonry Projecting Limestone	Entire Building	252	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	1,216	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	16,365	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	2,888	SF	4	0-1 year	Open Joints, cracks, efflorescense
	Exterior Walls - Stone-Cut	Entire Building	3,399	SF	6	10+ years	•
	Exterior Walls - Stone-Cut	Entire Building	43	SF	5	10+ years	
indows							
HIGOWS	Guard - Guards perforated	Entire Building	2,185	SF	6	10+ years	
	Lintels - Brick	Entire Building	157	LF	6	10+ years	
	Lintels - Steel	Entire Building	9	LF	5	10+ years	
	Lintels - Stone	Entire Building	715	LF	6	10+ years	
	Windows - Decorative	Entire Building	528	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,321	SF	6	10+ years	
	Times To Guoti / Harring Double parie	Zitillo Dallallig	0,021	51	J	ioi youis	
atego	ry : Electrical		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System						
<u> </u>	Automatic Transfer Switch	Boiler Room	1	EA	4	2-5 years	ATS has more than 20 years of service

Campus Name: Burley Page : 3 of 26 Assessment Date: 02/13/2020



Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - CCTV	Entire Building	55,812	SF	5	6-10 years	Security cameras are only exterior
	Security System - Intrusion Detection	Entire Building	55,812	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	25	EΑ	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	4	EΑ	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	36	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	5	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,330	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	6,207	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,546	SF	6	6-10 years	
lain Ser							
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	PA System	Main office	55,812	SF	3	0-1 year	PA does not work
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	ΕA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	ΕA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	ΕA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	
	amp	Littile building	ı	LA	U	10+ years	
atego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Aları							
	Fire Alarm Panel	Entire Building	1	EA	3	1-2 years	Panel has more than 30 years of service

Campus Name: Burley Page : 4 of 26 Assessment Date: 02/13/2020



Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Strobe Lights	Entire Building	18,000	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	55,812	SF	4	2-5 years	FA system has over 45 years of
							service
	Fire Pump Controller	Entire Building	1	EA	4	2-5 years	FP controleer has over 55 years of
							service and replacement parts not
							available.
Pumn Ri	oom Assembly						
<u>r ump ix</u>	Fire Pump - 25-50 hp	Sprinkler	1	EA	5	6-10 years	
	1 lie 1 ump - 25-50 mp	Ophilikiei		LA	3	0-10 years	
Sprinkle	r System						
•	Dry Sprinkler System	Electrical Room	55,812	SF	6	6-10 years	
	Sprinkler Heads	Electrical Room	55,812	SF	4	2-5 years	Heads are more than 40 years old.
	Sprinkler Piping	Electrical Room	55,812	SF	5	6-10 years	
Catego	ry : Mechanical		R	uilding	· Main		
Calego	ry . Mechanica			unung	. IVICIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	lling Systems		•			•	
	Air Handling Unit- Built Up-Multi Zone-	Entire Building	1	EA	5	6-10 years	
	Double Delivery- Steam Coils - 30001 -	g				5 10 <b>,</b> 555	
	45000 cfm						
	Air Intake	Entire Building	1	EA	6	6-10 years	
	Auxiliaries - 30001 - 45000 cfm	Entire Building	1	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts-	Entire Building	100	LF	5	6-10 years	
	Missing or Existing Shaft	-				•	
	Zone Dampers	Entire Building	10	EA	6	6-10 years	
	Zone Dampers	Entire Building	17	EA	5	6-10 years	
Boiler Sy	votomo						
DUIRI 3)	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	6-10 years	
	Pressure Boiler - 76 - 100 HP	Bollot Room	2	L/\	0	o io years	
	Chemical Feed System	Boiler Room	1	EA	7	10+ years	
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EΑ	5	6-10 years	
	Steam- Low Pressure Boiler - 76 - 100 HP		_	_, .	J	5 .5 ,5a.5	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	6-10 years	
	Steam Traps	Boiler Room	45	EA	5	6-10 years	
	•					-	
	Devices						

Campus Name: Burley Page : 5 of 26 Assessment Date: 02/13/2020



Category : Mechanical

# Augustus H Burley Elementary School 1630 W Barry AVENUE, Chicago, IL 60657

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Radiators - Steam	Basement	2	EΑ	5	1-2 years	Leaking, needs repairs.
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Gas	Entire Building	1	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	14	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	2	0-1 year	Heater is old, in poor condition, not work and not cost efective for repair
_Tempera	ture Control						
	Pneumatic System	Entire Building	55,912	SF	4	2-5 years	There are several air leaks in the tubing
	Thermostats - Pneumatic	Entire Building	27	EA	6	6-10 years	
_Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	4	2-5 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	4	2-5 years	More than 30 years of age and is rusted.
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
_	_						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group Hot Wate	er .		Quantity		Rank	Replacement	Comments
•		Location  Boiler Room	Quantity 1	EA	Rank 5	6-10 years	Comments
•	er Gas Heater - 150000 - 300000 BTU/HR		•			·	Comments
Hot Wate	er .		•			·	Galvanized pipe rusted.
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers	Boiler Room  Entire Building  Entire Building	1	EA SF SF	5	6-10 years	
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures	Boiler Room  Entire Building Entire Building Entire Building	55,812	EA SF	5	6-10 years 2-5 years	
_Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines	Boiler Room  Entire Building Entire Building Entire Building Entire Building	55,812 55,812 55,812 55,812	EA SF SF SF SF	5 4 4	6-10 years 2-5 years 2-5 years	
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines	Boiler Room  Entire Building Entire Building Entire Building Entire Building Entire Building	55,812 55,812 55,812	EA SF SF SF SF SF	5 4 4 4	6-10 years 2-5 years 2-5 years 2-5 years	
_Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines	Boiler Room  Entire Building Entire Building Entire Building Entire Building	55,812 55,812 55,812 55,812	EA SF SF SF SF	5 4 4 4 4	6-10 years 2-5 years 2-5 years 2-5 years 2-5 years	
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines	Boiler Room  Entire Building Entire Building Entire Building Entire Building Entire Building	55,812 55,812 55,812 55,812 55,812	EA SF SF SF SF SF	5 4 4 4 4	6-10 years  2-5 years  2-5 years  2-5 years  2-5 years  2-5 years	
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Sanitary Piping	Boiler Room  Entire Building	55,812 55,812 55,812 55,812 55,812 55,812	EA SF SF SF SF SF	5 4 4 4 4 4 4	6-10 years  2-5 years	
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Sanitary Piping Storm Piping	Boiler Room  Entire Building	55,812 55,812 55,812 55,812 55,812 55,812 55,812 55,812 55,812	SF SF SF SF SF SF	5 4 4 4 4 4 4	6-10 years  2-5 years  6-10 years  6-10 years	
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Sanitary Piping	Boiler Room  Entire Building	55,812 55,812 55,812 55,812 55,812 55,812 55,812 55,812	EA SF SF SF SF SF SF SF	5 4 4 4 4 4 4 4 5	6-10 years  2-5 years  6-10 years	
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Sanitary Piping Storm Piping	Boiler Room  Entire Building	55,812 55,812 55,812 55,812 55,812 55,812 55,812 55,812 55,812	EA SF SF SF SF SF SF SF SF SF	5 4 4 4 4 4 4 4 5 5	6-10 years  2-5 years  6-10 years  6-10 years	
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR  Domestic Piping-Cold Water Horizontal Lines Domestic Piping-Cold Water Risers Domestic Piping-Cold Water from Risers to Fixtures Domestic Piping-Hot Water Horizontal Lines Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Sanitary Piping Storm Piping	Boiler Room  Entire Building	55,812 55,812 55,812 55,812 55,812 55,812 55,812 55,812 55,812	EA SF SF SF SF SF SF SF SF SF	5 4 4 4 4 4 4 4 5 5	6-10 years  2-5 years  6-10 years  6-10 years	

Building : Main

Campus Name: Burley Page : 6 of 26 Assessment Date: 02/13/2020



Recommend

**Building: Main Category: Plumbing** 

Group Item - Type Location Quantity UOM Rank Replacement Comments

Catagory : Boom Building : Main

Catego	ry : Room		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Administ	rative Suites/Offices							
	AC Unit	1st Floor-clerk space	1	EA	7	6-10 years		
	Ceiling - Lay-in	1st Floor-clerk space	389	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-clerk space	1	EA	6	10+ years		
	Floor - Wood	1st Floor-clerk space	389	SF	7	10+ years		
	Lighting - Lay-in	1st Floor-clerk space	7	EA	6	10+ years		
	Power Distribution	1st Floor-clerk space	8	EA	6	10+ years		
	Walls - Plaster/Drywall	1st Floor-clerk space	400	SF	6	10+ years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor-clerk space	450	SF	6	10+ years		
	AC Unit	1st a Floor-Principal's Office	1	EA	7	6-10 years		
	Ceiling - Lay-in	1st a Floor-Principal's Office	264	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st a Floor-Principal's Office	1	EA	6	10+ years		
	Floor - Wood	1st a Floor-Principal's Office	264	SF	7	10+ years		
	Lighting - Lay-in	1st a Floor-Principal's Office	4	EA	7	10+ years		
	Power Distribution	1st a Floor-Principal's Office	8	EA	7	10+ years		
	Storage/ Closet	1st a Floor-Principal's Office	95	SF	7	10+ years		
	Storage/ Closet	1st a Floor-Principal's Office	78	SF	7	10+ years		
	Walls - Plaster/Drywall	1st a Floor-Principal's Office	646	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor- Office 209	170	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor- Office 209	1	EA	7	10+ years		
	Floor - Tile/Sheet	2nd Floor- Office 209	170	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor- Office 209	1	EA	7	6-10 years		
	Power Distribution	2nd Floor- Office 209	6	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor- Office 209	461	SF	7	10+ years		
	Walls - Vinyl Coated Gypsum Panel	2nd Floor- Office 209	282	SF	7	10+ years		
	AC Unit	2nd Floor-Office 204	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor-Office 204	253	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor-Office 204	1	EA	7	10+ years		
	Floor - Wood	2nd Floor-Office 204	253	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor-Office 204	6	EA	7	6-10 years		
	Power Distribution	2nd Floor-Office 204	8	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor-Office 204	1,003	SF	7	10+ years		
	AC Unit	Basement-004 Teacher's Lounge	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement-004 Teacher's Lounge	285	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Basement-004 Teacher's Lounge	1	EA	6	10+ years		
	Floor - Tile	Basement-004 Teacher's Lounge	285	SF	6	10+ years		
	Lighting - Pendent/Surface	Basement-004 Teacher's Lounge	6	EA	6	10+ years		
	Power Distribution	Basement-004 Teacher's Lounge	18	EA	6	10+ years		
	Walls - Plaster/Drywall	Basement-004 Teacher's Lounge	720	SF	6	10+ years		
	Work SInk	Basement-004 Teacher's Lounge	1	EA	7	6-10 years		
		3.				,		



Catego	ry : Room		R	uilding	: Main		1000 W Barry AVENUE, Officago, IE 00007
Juliogo				anamg	····	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Basement-Engineer's Office	175	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Engineer's Office	1	ĒΑ	6	10+ years	
	Floor - Tile	Basement-Engineer's Office	175	SF	6	10+ years	
	Lighting - Lay-in	Basement-Engineer's Office	2	EA	6	10+ years	
	Power Distribution	Basement-Engineer's Office	6	EΑ	6	10+ years	
	Walls - Plaster/Drywall	Basement-Engineer's Office	435	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Lunchroom Office	125	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Lunchroom Office	123	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement-Lunchroom Office	125	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-Lunchroom Office	2	EA	6	10+ years	
	Power Distribution		6		6	•	
	Walls - Masonry	Basement-Lunchroom Office Basement-Lunchroom Office		EA SF	6	10+ years	
			240		_	10+ years	
	Walls - Plaster/Drywall	Basement-Lunchroom Office	240	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Speech Therapist Office	52	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Speech Therapist Office	1	EA	6	10+ years	
	Floor - Concrete	Basement-Speech Therapist Office	52	SF	5	1-2 years	
	Lighting - Pendent/Surface	Basement-Speech Therapist Office	1	EA	6	10+ years	
	Power Distribution	Basement-Speech Therapist Office	2	EA	6	10+ years	
	Walls - Metal Panel	Basement-Speech Therapist Office	170	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Speech Therapist Office	170	SF	6	10+ years	
_							
_Gymnas		0-4 51	0.055	0.5		40	
	Ceiling - Plaster/Drywall	3rd Floor	3,255	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	8	EA	7	10+ years	
	Floor - Wood	3rd Floor	2,705	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Scoreboards	3rd Floor	1	EA	7	6-10 years	
	Sound System	3rd Floor	1	EA	7	6-10 years	
	Stage	3rd Floor	550	SF	7	10+ years	
	Stage Curtain	3rd Floor	3	EA	7	10+ years	
	Stage Lighting System	3rd Floor	1	EA	7	6-10 years	
	Stage-Stairs - Asphalt	3rd Floor	10	LF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,965	SF	7	10+ years	
	M. 10						
Lunch &	Multipurpose Room	D (N)				0.40	
	AC Unit	Basement-N Lunchroom	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-N Lunchroom	870	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-N Lunchroom	4	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement-N Lunchroom	870	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-N Lunchroom	19	EA	6	10+ years	
	Storage/ Closet	Basement-N Lunchroom	65	SF	7	10+ years	
	Walls - Masonry	Basement-N Lunchroom	1,412	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	Basement-S Lunchroom/warming kitchen	2	EA	7	6-10 years	
	Ceiling - Lay-in	Basement-S Lunchroom/warming kitchen	1,210	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-S Lunchroom/warming kitchen	2	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement-S Lunchroom/warming kitchen	1,210	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement-S Lunchroom/warming kitchen	27	EA	6	10+ years	
	Serving Line	Basement-S Lunchroom/warming kitchen	13	LF	6	6-10 years	
	Walls - Masonry	Basement-S Lunchroom/warming kitchen	750	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-S Lunchroom/warming kitchen	1,083	SF	6	10+ years	
MDF_ID							
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	14	SF	7	10+ years	
	Janitor's Closet	2nd Floor	14	SF	7	10+ years	
	Storage Room	2nd Floor	92	SF	7	10+ years	
	Janitor's Closet	3rd Floor	15	SF	7	10+ years	
	Air Intake Plenums	Basement	320	SF	7	10+ years	
	Air Tunnel	Basement	340	SF	7	10+ years	
	Boiler Room	Basement	1,798	SF	7	10+ years	
	Janitor's Closet	Basement	20	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	145	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	250	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	75	SF	7	10+ years	
	Storage Room	Basement	172	SF	7		
	Storage Room Storage Room		180	SF SF	7	10+ years	
		Basement		SF SF		10+ years	
	Storage Room	Basement	455	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor-Men's Staff Restroom	162	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Men's Staff Restroom	162	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Men's Staff Restroom	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor-Men's Staff Restroom	162	SF	6	10+ years	
	Hand Dryer	1st Floor-Men's Staff Restroom	1	EA	7	6-10 years	
	<del> </del>		•	<b></b> - ·	•	- 1- ,	



Catego	ry : Room		В	uilding	: Main		·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st Floor-Men's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Men's Staff Restroom	2	EA	6	10+ years	
	Partitions	1st Floor-Men's Staff Restroom	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Men's Staff Restroom	780	SF	6	10+ years	
	Water Closet	1st Floor-Men's Staff Restroom	2	EA	6	6-10 years	
	Accessories	1st Floor-Women's Staff Restroom	162	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Women's Staff Restroom	162	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Women's Staff Restroom	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Women's Staff Restroom	162	SF	6	10+ years	
	Hand Dryer	1st Floor-Women's Staff Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Women's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Women's Staff Restroom	2	EA	6	10+ years	
	Partitions	1st Floor-Women's Staff Restroom	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Women's Staff Restroom	780	SF	6	10+ years	
	Water Closet	1st Floor-Women's Staff Restroom	2	ĒΑ	6	6-10 years	
	Accessories	2nd Floor-Boys Restroom	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Boys Restroom	263	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Boys Restroom	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor-Boys Restroom	263	SF	7	10+ years	
	Floor Drain	2nd Floor-Boys Restroom	2	EA	7	10+ years	
	Hand Dryer	2nd Floor-Boys Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-Boys Restroom	2	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor-Boys Restroom	6	EA	6	10+ years	
	Partitions	2nd Floor-Boys Restroom	3	EA	7	10+ years	
	Urinals	2nd Floor-Boys Restroom	7	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor-Boys Restroom	267	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Boys Restroom	534	SF	6	10+ years	
	Water Closet	2nd Floor-Boys Restroom	3	EA	6	6-10 years	
	Accessories	2nd Floor-Girls Restroom	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Girls Restroom	263	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Girls Restroom	203	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor-Girls Restroom	263	SF	7	10+ years	
	Floor Drain	2nd Floor-Girls Restroom	203	EA	7	10+ years	
	Hand Dryer	2nd Floor-Girls Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-Girls Restroom	2	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor-Girls Restroom	6	EA	6	10+ years	
	Partitions	2nd Floor-Girls Restroom	9	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Girls Restroom	534	SF	7	•	
	Water Closet	2nd Floor-Girls Restroom	9	EA	6	10+ years 6-10 years	
	Accessories	2nd Floor-Women's Restroom	123	SF	7		
		2nd Floor-Women's Restroom 2nd Floor-Women's Restroom	123	SF SF	7 7	6-10 years	
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw		_	SF EA		10+ years	
		2nd Floor-Women's Restroom	1		6	10+ years	
	Floor - Terrazzo	2nd Floor-Women's Restroom	123	SF	7	10+ years	
	Hand Dryer	2nd Floor-Women's Restroom	1	EA	7	6-10 years	

Campus Name: Burley Page : 10 of 26 Assessment Date: 02/13/2020



Category : Room		В	uilding	: Main		-	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	2nd Floor-Women's Restroom	2	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor-Women's Restroom	2	EA	7	10+ years	
	Partitions	2nd Floor-Women's Restroom	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor-Women's Restroom	80	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor-Women's Restroom	173	SF	7	10+ years	
	Water Closet	2nd Floor-Women's Restroom	2	EA	6	6-10 years	
	Accessories	Basement-Boy's Restroom	152	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Boy's Restroom	152	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Boy's Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Boy's Restroom	152	SF	7	10+ years	
	Floor Drain	Basement-Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement-Boy's Restroom	2	EA	7	6-10 years	
	Lavatory	Basement-Boy's Restroom	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Boy's Restroom	3	EA	6	10+ years	
	Partitions	Basement-Boy's Restroom	4	EA	7	10+ years	
	Urinals	Basement-Boy's Restroom	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement-Boy's Restroom	165	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-Boy's Restroom	430	SF	6	10+ years	
	Water Closet	Basement-Boy's Restroom	4	EA	6	6-10 years	
	Accessories	Basement-Engineer's Restroom	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Engineer's Restroom	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Engineer's Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Engineer's Restroom	50	SF	6	10+ years	
	Floor Drain	Basement-Engineer's Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement-Engineer's Restroom	1	EA	7	6-10 years	
	Lavatory	Basement-Engineer's Restroom	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Basement-Engineer's Restroom	1	EA	6	10+ years	
	Showers	Basement-Engineer's Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement-Engineer's Restroom	315	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-Engineer's Restroom	65	SF	6	10+ years	
	Water Closet	Basement-Engineer's Restroom	1	EA	6	6-10 years	
	Accessories	Basement-Girl's Restroom	510	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Girl's Restroom	510	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Girl's Restroom	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Girl's Restroom	510	SF	6	10+ years	
	Floor Drain	Basement-Girl's Restroom	2	EA	7	10+ years	
	Hand Dryer	Basement-Girl's Restroom	2	EA	7	6-10 years	
	Lavatory	Basement-Girl's Restroom	2	EA	6		
	Lavatory Lighting - Pendent/Surface	Basement-Girl's Restroom	7	EA	6	10+ years 10+ years	
	Partitions	Basement-Girl's Restroom	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement-Girl's Restroom	365	SF	<i>7</i> 6	•	
	Walls - Plaster/Drywaii Walls - Tile Ceramic/ Porcelain	Basement-Girl's Restroom	800	SF SF		10+ years	
	Water Closet	Basement-Girl's Restroom Basement-Girl's Restroom		SF EA	6 6	10+ years	
	Accessories	Basement-Girl's Restroom Basement-Men's Staff Restroom	10 155	SF	6 7	6-10 years	
	Accessories	Dasement-wens Stan Nestroom	100	SI-	,	6-10 years	



Catego	Category: Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement-Men's Staff Restroom	155	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Men's Staff Restroom	2	EA	6	10+ years	
	Floor - Tile	Basement-Men's Staff Restroom	70	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Men's Staff Restroom	85	SF	6	10+ years	
	Floor Drain	Basement-Men's Staff Restroom	1	EA	7	10+ years	
	Hand Dryer	Basement-Men's Staff Restroom	1	EA	7	6-10 years	
	Lavatory	Basement-Men's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Men's Staff Restroom	2	EA	6	10+ years	
	Lighting - Wall Mounted	Basement-Men's Staff Restroom	1	EA	6	10+ years	
	Partitions	Basement-Men's Staff Restroom	2	EA	7	10+ years	
	Urinals	Basement-Men's Staff Restroom	1	EA	6	10+ years	
	Walls - Plaster/Drywall	Basement-Men's Staff Restroom	365	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-Men's Staff Restroom	225	SF	6	10+ years	
	Water Closet	Basement-Men's Staff Restroom	2	EA	6	6-10 years	
	Accessories	Basement-Women's Staff Restroom	145	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Women's Staff Restroom	145	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Women's Staff Restroom	2	EA	6	10+ years	
	Floor - Tile	Basement-Women's Staff Restroom	60	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement-Women's Staff Restroom	85	SF	6	10+ years	
	Hand Dryer	Basement-Women's Staff Restroom	1	EA	7	6-10 years	
	Lavatory	Basement-Women's Staff Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Women's Staff Restroom	2	EA	7	10+ years	
	Lighting - Wall Mounted	Basement-Women's Staff Restroom	1	EA	7	10+ years	
	Partitions	Basement-Women's Staff Restroom	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement-Women's Staff Restroom	345	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement-Women's Staff Restroom	255	SF	6	10+ years	
	Water Closet	Basement-Women's Staff Restroom	2	ĒΑ	6	6-10 years	
	Accessories	Main Office	51	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	51	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main Office	51	SF	6	10+ years	
	Lavatory	Main Office	1	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	Main Office	1	EA	6	10+ years	
	Walls - Plaster/Drywall	Main Office	310	SF	6	10+ years	
	Water Closet	Main Office	1	ĒΑ	6	6-10 years	
	Accessories	Restroom 001	24	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom 001	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom 001	1	EA	6	10+ years	
	Floor - Tile	Restroom 001	24	SF	6	10+ years	
	Lavatory	Restroom 001	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Restroom 001	1	EA	6	10+ years	
	Walls - Plaster/Drywall	Restroom 001	160	SF	6	10+ years	
	Water Closet	Restroom 001	100	EA	6	6-10 years	
	Accessories	Restroom 002	30	SF	7	6-10 years	
	7.000001100	110011001111002	30	51	,	o to yours	



Category : Room

# Augustus H Burley Elementary School 1630 W Barry AVENUE, Chicago, IL 60657

atego	ry : Room			ullaing	. IVIAIII		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	Restroom 002	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom 002	1	EA	6	10+ years	
	Floor - Tile	Restroom 002	30	SF	6	10+ years	
	Lavatory	Restroom 002	1	EA	6	6-10 years	
	Lighting - Lay-in	Restroom 002	1	EA	6	10+ years	
	Walls - Plaster/Drywall	Restroom 002	175	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Restroom 002	43	SF	6	10+ years	
	Water Closet	Restroom 002	1	EA	6	6-10 years	
atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
assroc	m #001 (Kindergarten)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	765	SF	6	10+ years	
	Chalk Board	Basement	4	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years	
	Floor - Wood	Basement	765	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	6	10+ years	
	Walls - Masonry	Basement	1,054	SF	6	10+ years	
	Work Sink	Basement	1	EA	7	6-10 years	
lassroc	om #002 (Pre School)						
	AC Units	Basement	2	EA	7	6-10 years	
	Casework	Basement	5	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	Basement	1,039	SF	6	10+ years	
	Doors - Transom Window	Basement	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	ĒΑ	6	10+ years	
	Floor - Tile	Basement	378	SF	6	10+ years	
	Floor - Wood	Basement	661	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	18	ĒΑ	6	10+ years	
	Marker Board	Basement	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	Basement	1,788	SF	6	10+ years	
	Work Sink	Basement	1,765	EA	7	6-10 years	
assroc	om #003 (Kindergarten)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Lay-in	Basement	822	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	2	EA	6	10+ years	
	Floor - Tile	Basement	822	SF	6	10+ years	
	Lighting - Lay-in	Basement		EA	6	10+ years	
			14	LF	_	-	
	Marker Board	Basement Basement	8 960	SF	6 6	6-10 years	
	Walls - Plaster/Drywall	Basement	960	ЭF	О	10+ years	

**Building : Main** 

Campus Name: Burley Page : 13 of 26 Assessment Date: 02/13/2020



Category : Classroom		В	uilding	: Main			
0	Hans Time	Laastian	<b>0</b>	11014	Devil	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #005 (Kindergarten)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Lay-in	Basement	339	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	339	SF	6	10+ years	
	Lighting - Lay-in	Basement	6	EA	6	10+ years	
	Marker Board	Basement	8	LF	6	6-10 years	
	Walls - Plaster/Drywall	Basement	663	SF	6	10+ years	
	a	24666		•	· ·	.o. you.o	
lassroc	m #101 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,048	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	262	SF	6	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Nooroo	om #102 (Regular Classroom)						
Jassioo	AC Units	1st Floor	1	ГΛ	7	6.10 years	
			1	EA SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748		7	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,048	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	748	SF	7	10+ years	
	Chalk Board	1st Floor	8	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	30	EA	6	10+ years 10+ years	
	Floor - Wood Doors Inclu riw	1st Floor	830	SF	7	•	
	FIOUI - WOOU	151 11001	830	SF	′	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,085	SF	6	10+ years	
Classroo	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,085	SF	7	10+ years	
	vvalis - i lastei/Diywali	13(1100)	1,003	OI .	,	10+ years	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	_ 1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	135	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,085	SF	6	10+ years	
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	748	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,048	SF	6	10+ years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	748	SF	7	10+ years	
	Doors - Transom Window	1st Floor	30	SF SF	6	10+ years 10+ years	
	Doors - Wood Doors inclu hw	1st Floor	30	Sr EA	6	-	
	DOOLS - MADOR DOOLS HICH HM	151 F1001	1	ĽA	О	10+ years	



Category : Classroom	Bu	ilding	: Main		
		_		Recommend	
Group Item - Type Location	Quantity	UOM	Rank	Replacement	Comments
Floor - Wood 1st Floor	748	SF	7	10+ years	
Lighting - Pendent/Surface 1st Floor	14	EΑ	7	10+ years	
Marker Board 1st Floor	20	LF	6	6-10 years	
Storage/ Closet 1st Floor	125	SF	7	10+ years	
Walls - Plaster/Drywall 1st Floor	1,048	SF	6	10+ years	
Classroom #201 (Regular Classroom)					
AC Units 2nd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall 2nd Floor	748	SF	7	10+ years	
Doors - Transom Window 2nd Floor	30	SF	7	10+ years	
Doors - Wood Doors inclu hw 2nd Floor	1	EA	7	10+ years	
Floor - Wood 20013 HIGH TW 2nd Floor	748	SF	7	10+ years	
Lighting - Pendent/Surface 2nd Floor	14	EA	7	6-10 years	
Marker Board 2nd Floor	20	LF	7	6-10 years	
Storage/ Closet 2nd Floor	125	SF	7	10+ years	
Walls - Plaster/Drywall 2nd Floor	1,048	SF	7	10+ years	
vvalis - i lastel/biywali 2nd i looi	1,040	Oi	,	10+ years	
Classroom #202 (Regular Classroom)					
AC Units 2nd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall 2nd Floor	748	SF	7	10+ years	
Doors - Transom Window 2nd Floor	30	SF	7	10+ years	
Doors - Wood Doors inclu hw 2nd Floor	1	EA	7	10+ years	
Floor - Wood 2nd Floor	748	SF	7	10+ years	
Lighting - Pendent/Surface 2nd Floor	14	EA	7	6-10 years	
Marker Board 2nd Floor	20	LF	7	6-10 years	
Storage/ Closet 2nd Floor	92	SF	7	10+ years	
Walls - Plaster/Drywall 2nd Floor	1,048	SF	7	10+ years	
Work Sink 2nd Floor	1	EA	7	10+ years	
Classroom #203 (Regular Classroom)					
AC Units 2nd Floor	1	EA	7	6-10 years	
Casework 2nd Floor	25	LF	7	10+ years	
Ceiling - Plaster/Drywall 2nd Floor	748	SF	7	10+ years	
Doors - Transom Window 2nd Floor	30	SF	7	10+ years	
Doors - Wood Doors inclu hw 2nd Floor	1	ĒΑ	7	10+ years	
Floor - Wood 2nd Floor	748	SF	7	10+ years	
Lighting - Pendent/Surface 2nd Floor	14	EA	7	6-10 years	
Marker Board 2nd Floor	20	LF	7	6-10 years	
Storage/ Closet 2nd Floor	125	SF	7	10+ years	
Walls - Plaster/Drywall 2nd Floor	1,310	SF	7	10+ years	
Work Sink 2nd Floor	1,310	EA	7	10+ years	
2.10.11001	·	`	•	. o . youro	
Classroom #205 (Regular Classroom)					



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	36	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,085	SF	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor 2nd Floor	125	SF		•	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,085	SF SF	7 7	10+ years 10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,048	SF	7	10+ years	
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	748	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	748	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,048	SF	7	10+ years	
	vvalis - r iastei/DiyWall	Z110 1 1001	1,040	J.	1	TOT years	



Catego	ry : Classroom		В	1630 W Barry AVENUE, Chicago, IL 60637			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	760	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,385	SF	7	10+ years	
Classroo	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	795	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	795	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	130	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,485	SF	6	10+ years	
Classroo	m #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	865	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	865	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	170	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,568	SF	7	10+ years	
Classroo	m #304 (Regular Classroom)						
CidooiUC	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	7	6-10 years 10+ years	
			875	SF		10+ years 10+ years	
	Ceiling - Lay-in	3rd Floor			7	•	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	880	SF	7	10+ years	



Catego	ry : Classroom		R	uilding	· Main		-
Jaicgo				anding	. Wall	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Lighting - Lay-in	3rd Floor	7	EA	7	6-10 years	Comments
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	95	SF	7	•	
	Walls - Plaster/Drywall	3rd Floor	1,325	SF	7	10+ years	
	Walls - Flaster/Drywall	314 F1001	1,323	SF	,	10+ years	
Classroc	nm #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	775	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	26	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	150	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,565	SF	7	10+ years	
N							
Jassroc	om #308 (Special Education)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	775	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Wood	3rd Floor	775	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	140	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor		4-4-El	0.005			40	
	Ceiling - Plaster/Drywall	1st Floor	2,065	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EΑ	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	2,065	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	4,118	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,065	SF	6	10+ years	
		2nd Floor	85	SF	6	10+ years	
	Doors - Transom Window						
	Doors - Transom Window Doors - Wood Doors include hw	2nd Floor	8	EA EA	6 7	10+ years	



Catego	ry : Interior		R	uilding	· Main		1030 W Barry AVENUE, Chicago, IL 00037
Catego	y . Interior			unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. ос. р	Floor - Wood	2nd Floor	2,065	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	ĒA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,118	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,465	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	40	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	196	SF	7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,465	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4,085	SF	7	10+ years	
	Ceiling - Exposed	Basement	1,956	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	858	SF	6	10+ years	
	Doors - Transom Window	Basement	80	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	12	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	2,120	SF	7	10+ years	
	Floor - Tile/Sheet	Basement	945	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	32	EA	6	10+ years	
	Lighting - Wall Mounted	Basement	8	EA	6	10+ years	
	Walls - Masonry	Basement	2,100	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	5,495	SF	6	10+ years	
Safety							
Salety	Camera Viewing Station	1st Floor	2	EA	7	6-10 years	
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Carriera viewing Station	13(1100)	1	LA	,	0-10 years	
Stairs							
	Ceiling - Plaster/Drywall	E Stairs	432	SF	7	10+ years	
	Floor - Asphalt	E Stairs	612	SF	7	10+ years	
	Handrails	E Stairs	156	LF	7	10+ years	
	Lighting - Pendent/Surface	E Stairs	10	EA	7	6-10 years	
	Stairs - Asphalt	E Stairs	518	LF	7	10+ years	
	Walls - Plaster/Drywall	E Stairs	3,696	SF	7	10+ years	
	Ceiling - Plaster/Drywall	W Stairs	432	SF	7	10+ years	
	Floor - Asphalt	W Stairs	612	SF	7	10+ years	
	Handrails	W Stairs	156	LF	7	10+ years	
	Lighting - Pendent/Surface	W Stairs	10	EA	7	6-10 years	
	Stairs - Asphalt	W Stairs	518	LF	7	10+ years	
	Walls - Plaster/Drywall	W Stairs	3,696	SF	7	10+ years	



Catego	Category : Exterior			Building : Field House				
	_					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance								
	Entrance Control - Audio and Video	#10 S	1	EA	7	10+ years		
	Exterior Doors - Exterior Wood Door	#10 S	1	EA	5	6-10 years		
	Exterior Stairs - Concrete	#10 S	3	LF	5	10+ years		
	Exterior Doors - Exterior Wood Door	#11 S	1	EA	5	1-2 years		
	Exterior Doors - Exterior Wood Door	#12 Exit N	1	EA	5	6-10 years		
	Exterior Doors - Exterior Wood Door	#13 Exit N	1	EA	5	6-10 years		
	Exterior Doors - Exterior Wood Door	#9 Exit S	1	EA	5	1-2 years		
_Foundat	ion							
	Foundation - Concrete	Entire Building	250	LF	7	10+ years		
	Foundation - Concrete	Entire Building	3	LF	6	10+ years		
	Superstructure - Heavy Timber	Entire Building	2,715	SF	7	10+ years		
Lighting								
_ 0 0	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	10+ years		
Roof Sys	stem							
,	Downspouts - Exterior Downspouts	Entire Building	52	LF	6	10+ years		
	Roof - Asphalt Shingle	Entire Building	3,394	SF	5	6-10 years	Solar panels present	
	Roof Structure - Heavy Timber	Entire Building	2,715	SF	7	10+ years		
Walls								
	Exterior Walls - Brick	Entire Building	288	SF	6	10+ years		
	Exterior Walls - Brick	Entire Building	2	SF	4	0-1 year	Missing	
	Exterior Walls - Wood Siding	Entire Building	1,518	SF	6	10+ years	-	
	Exterior Walls - Wood Siding	Entire Building	1,517	SF	4	0-1 year	Holes, splitting, broken	
Windows	S							
	Guard - Guards wire guard	Entire Building	56	SF	5	6-10 years		
	Lintels - Steel	Entire Building	30	LF	6	10+ years		
	Windows - Wood- Single-pane	Entire Building	56	SF	5	6-10 years	Peeling paint	
Catego	ry : Electrical		В	uilding	: Field H	louse		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Power D	istribution							
	Lighting and Power Panels - Above 100 A	Mechanical Room	1	EA	4	0-1 year	Panel is substantially deteriorated	



Heating Devices

Category : Mechanical

Group Item - Type

#### **Augustus H Burley Elementary School**

**Building : Field House** 

Quantity

Location

Recommend

**UOM Rank Replacement Comments** 

1630 W Barry AVENUE, Chicago, IL 60657

	Gas/ Natural Draft Furnace - 101 - 200 MBH	Mechanical Room	1	EA	5	6-10 years	
Гетрега	ature Control						
	Electric Thermostat	1st Floor	1	EA	6	6-10 years	
/entilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	2	EA	4	2-5 years	Fan is more than 15 years old.
atego	ry : Plumbing		В	uilding	: Field H	louse	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	· ·	Location	Quantity	UOW	Kalik	Replacement	Comments
ioi wate	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	2,715	SF	6	6-10 years	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	2,715	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Lines	Entire Building	2,717	SF	6	2-5 years	
	Sanitary Piping	Entire Building	2,715	SF	6	6-10 years	
	Vent Piping	Entire Building	2,715	SF	6	6-10 years	
Catego	ry : Classroom		В	uilding	: Field H	louse	
						Recommend	
Proup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	om #109E (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	686	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA SF	7 7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,055	SF	/	10+ years	
lassroo	om #109W (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	7	10+ years	
	Doors - Wood Doors inclu hw Floor - Concrete Epoxy/ Painted	1st Floor	1	EA	7	10+ years	
	FIGUR - CONCRETE FROM // PAINTED	1st Floor	686	SF	7	10+ years	
	1 loor Gonordie Epoxy/ 1 ainted					•	



Catego	Category : Classroom			Building : Field House				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	6-10 years		
	Marker Board	1st Floor	8	LF	7	6-10 years		
	Storage/ Closet	1st Floor	41	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,055	SF	7	10+ years		
Catego	ory : Room		В	uilding	: Field I	louse		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Mechan	ical/ Service Rooms							
	Mechanical/ Service Rooms	1st Floor	70	SF	7	10+ years		
	Storage Room	1st Floor	70	SF	7	10+ years		
Restroo	m							
	Accessories	1st Floor-109E Restroom	38	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor-109E Restroom	38	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-109E Restroom	1	EΑ	6	10+ years		
	Floor - Concrete Epoxy/ Painted	1st Floor-109E Restroom	38	SF	7	6-10 years		
	Floor Drain	1st Floor-109E Restroom	1	ĒΑ	7	10+ years		
	Lavatory	1st Floor-109E Restroom	1	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor-109E Restroom	1	EA	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor-109E Restroom	242	SF	7	10+ years		
	Water Closet	1st Floor-109E Restroom	1	EA	6	10+ years		
	Accessories	1st Floor-109W Restroom	38	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor-109W Restroom	38	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-109W Restroom	1	EA	7	10+ years		
	Floor - Concrete Epoxy/ Painted	1st Floor-109W Restroom	38	SF	7	10+ years		
	Floor Drain	1st Floor-109W Restroom	1	EA	7	10+ years		
	Lavatory	1st Floor-109W Restroom	1	EA	7	10+ years		
	Lighting - Wall Mounted	1st Floor-109W Restroom	1	EA	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor-109W Restroom	242	SF	7	10+ years		
	Water Closet	1st Floor-109W Restroom	1	EA	7	10+ years		
Catego	ory : Interior		В	uildina	: Field I	louse		
3			_			Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Plaster/Drywall	1st Floor	175	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	173	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	460	SF	7	10+ years		
	•					,		



Category : Site	Building : Site
outegory . One	Bullating . Oite

	y . Site		ь				
	<del></del>		0			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
thletic							
	Lighting	North Courtyard	2	EA	6	10+ years	
	Surface - Asphalt	North Courtyard	4,000	SF	6	10+ years	
	Surface - Synthetic	North Courtyard	4,904	SF	6	10+ years	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	11	EA	6	10+ years	
_							
encing	Familian Obain Link	Fasting Oite	457		-	40	
	Fencing - Chain Link	Entire Site	457	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	209	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	198	LF	5	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	287	LF	6	10+ years	
andscar	ne.						
	Benches	Entire Site	10	EA	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	21,286	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	1,050	SF	4	1-2 years	Crumbling, holes, cracks, heaving
	Landscape - Hardscape- Concrete	Entire Site	2,510	SF	6	10+ years	3, 111, 111, 111, 111, 111, 111, 111, 1
	Landscape - Hardscape- Concrete	Entire Site	250	SF	4	1-2 years	Cracked, holes
	Lighting - Pole Mounted	Entire Site	3	ĒΑ	6	10+ years	
	Parkway trees	Entire Site	5	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	1,200	SF	6	10+ years	
	Play Area - Synthetic Turf Play Field	Entire Site	7,660	SF	6	10+ years	
	Trash Receptacles	Entire Site	7,000	EA	6	10+ years	
	Trasti Neceptacies	Littile Site	2	LA	O	10+ years	
arking L	ot						
	Surface - Asphalt	E Parking Lot	3,620	SF	6	10+ years	
Playgrou	nd						
iaygiuu	Equipment - School Age 5-12	NE Playground	1	EA	6	10+ years	
	Surface - Square Rubber Mats	NE Playground	2,358	SF	4	2-5 years	
	Equipment - Pre K 3-5	NW Playground	1	EA	6	10+ years	
	Surface - Poured Surface	NW Playground	1,600	SF	6	10+ years	
	Surface - I Oured Surface	1444 F layground	1,000	OI.	Ü	10+ years	
idewalk							
	Sidewalks - Internal Walks	Entire Site	50	LF	5	1-2 years	Cracks, crumbling
	Sidewalks - Perimeter Sidewalks	Entire Site	5,035	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	10	SF	5	1-2 years	Cracks, uneven

Campus Name: Burley Page : 24 of 26 Assessment Date: 02/13/2020



Catego	ry : Site		E	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Signage							
- 5 5	Flag Pole - Building Mounted Flag Pole Marquee - Free Standing Back Lighted	Entire Site Entire Site	1	EA EA	6 6	10+ years 10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Burley Page: 25 of 26 Assessment Date: 02/13/2020

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Ν

Ν



Kindergarten

**Classroom Summary** 

Kindergarten

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main					, , , , , , , , , , , , , , , , , , ,				
Computer Lab	Library	1st Floor	101	101	748	140	58	N	N
Kindergarten	Kindergarten	Basement	003	003	822	62	28	N	N
Kindergarten	Kindergarten	Basement	005	005	339	124	40	N	N
Kindergarten	Regular Classroom	Basement	001	001	765	62	28	N	N
Pre School	Pre School	Basement	002	002	1,039	34	12	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	748	140	58	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	830	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	830	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	830	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	748	140	58	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	748	140	58	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	748	140	58	Y	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	748	140	58	Y	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	830	140	58	Y	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	748	140	58	Y	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	748	140	58	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	760	140	58	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	795	140	58	Y	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	865	140	58	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	880	140	58	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	775	140	58	Υ	N
Regular Classroom	Special Education	2nd Floor	202	202	748	140	58	Υ	N
Regular Classroom	Special Education	2nd Floor	206	206	830	140	58	Υ	N
Special Education	Regular Classroom	3rd Floor	308	308	775	140	58	Υ	N
Building : Field House									
Art Room	Regular Classroom	1st Floor	109W	109W	686	72		N	N
141 1	121								

Campus Name: Burley	Page : 26 of 26	Assessment Date: 02/13/2020

109E

109E

686

84

1st Floor