

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1963 | 3 | 61,645 |
| Campus Total | | | 61,645 |

Category : Exterior Building : Main

| | | | | | | Recommend | |
|----------|--------------------------------------|---------------|----------|-----|------|-------------|-------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | | | | | | | |
| | Entrance Control - Audio | #1 Main - S | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | #1 Main - S | 3 | EΑ | 6 | 6-10 years | |
| | Exterior Doors - Transom Lite | #1 Main - S | 3 | EA | 6 | 6-10 years | |
| | Power Door Operator and Controls | #1 Main - S | 1 | EA | 4 | 0-1 year | Not working |
| | Exterior Doors - Exterior Steel Door | #2 Exit - W | 1 | EΑ | 6 | 6-10 years | |
| | Exterior Stairs - Concrete | #2 Exit - W | 15 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #3 Exit - W | 1 | EΑ | 6 | 6-10 years | |
| | Exterior Stairs - Concrete | #3 Exit - W | 15 | LF | 5 | 10+ years | |
| | Entrance Control - Audio | #4 - N | 1 | EΑ | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | #4 - N | 2 | EΑ | 6 | 6-10 years | |
| | Exterior Doors - Side lite | #4 - N | 2 | EΑ | 6 | 6-10 years | |
| | Power Door Operator and Controls | #4 - N | 1 | EΑ | 4 | 0-1 year | not working |
| | Ramps - Concrete | #4 - N | 18 | LF | 6 | 10+ years | • |
| | Exterior Doors - Exterior Steel Door | #4.5 Exit - N | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | #5 Exit - N | 1 | EΑ | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | #6 - N | 1 | EΑ | 6 | 6-10 years | |
| | Exterior Doors - Transom Lite | #6 - N | 1 | EΑ | 6 | 6-10 years | |
| | Entrance Control - Audio and Video | #7 - E | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | #7 - E | 2 | EΑ | 6 | 6-10 years | |
| | Exterior Doors - Side lite | #7 - E | 2 | EΑ | 6 | 6-10 years | |
| | Exterior Doors - Transom Lite | #7 - E | 4 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Concrete | #7 - E | 5 | LF | 6 | 10+ years | |
| | Ramp Handrail - Steel_Ramp Handrail | #7 - E | 21 | LF | 6 | 6-10 years | |
| | Ramps - Concrete | #7 - E | 21 | LF | 6 | 10+ years | |



| : Exterior | | В | uilding | : Main | | |
|---|-----------------|----------|----------|---------------------------------------|--------------------------|---------------------------------------|
| tem - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | | | | | | |
| Foundation - Concrete | Entire Building | 955 | LF | 7 | 10+ years | |
| Superstructure - Concrete | Entire Building | 61,645 | SF | 7 | 10+ years | |
| | | | | | | |
| Exterior Lighting - Parapet or Roof Mounted | Entire Building | 8 | EA | 6 | 6-10 years | |
| Exterior Lighting - Wall Mounted | Entire Building | 13 | EA | 6 | 6-10 years | |
| Exterior Lighting - Wall Mounted | Entire Building | 1 | EA | 5 | 0-1 year | broken fixture |
| em . | | | | | | |
| Access Ladder - Metal | Main Roof | 1 | EA | 7 | 6-10 years | |
| Coping - Metal | Main Roof | 640 | LF | 6 | 6-10 years | |
| Downspouts - Interior Downspouts | Main Roof | 252 | LF | 6 | 6-10 years | |
| Parapet - Parapet < 16" Height | Main Roof | 640 | LF | 6 | 10+ years | |
| Roof - Metal | Main Roof | 140 | SF | 6 | 10+ years | |
| Roof - Modified Bitumen | Main Roof | 18,249 | SF | 6 | 6-10 years | |
| Roof Hatch - Metal | Main Roof | 1 | EA | 7 | 6-10 years | |
| Roof Structure - Concrete | Main Roof | 18,249 | SF | 7 | 10+ years | |
| Access Ladder - Metal | North Roof | 1 | EA | 7 | 6-10 years | |
| Chimney - Brick Chimney- Concrete/ Mortar Liner | North Roof | 25 | LF | 6 | 10+ years | Bottom |
| Chimney - Brick Chimney- Concrete/ Mortar Liner | North Roof | 13 | LF | 5 | 6-10 years | Top: efflorescence |
| Coping - Metal | North Roof | 267 | LF | 6 | 6-10 years | |
| Downspouts - Interior Downspouts | North Roof | 26 | LF | 6 | 6-10 years | |
| Roof - Modified Bitumen | North Roof | 6,031 | SF | 6 | 6-10 years | |
| Roof Structure - Concrete | North Roof | 6,031 | SF | 7 | 10+ years | |
| Access Ladder - Metal | West Roof | 1 | EA | 7 | 6-10 years | |
| Coping - Metal | West Roof | 278 | LF | 6 | 6-10 years | |
| Downspouts - Interior Downspouts | West Roof | 52 | LF | 6 | 6-10 years | |
| Roof - Modified Bitumen | West Roof | 6,251 | SF | 6 | 6-10 years | |
| Roof Structure - Concrete | West Roof | 6,251 | SF | 7 | 10+ years | |
| | | | | | | |
| Canopy - Concrete/ Stucco | Entire Building | 380 | SF | 6 | 6-10 years | |
| Canopy - Concrete/ Stucco | Entire Building | 100 | SF | 5 | 2-5 years | |
| Exterior Walls - Brick | Entire Building | 19,425 | SF | 6 | 10+ years | |
| Exterior Walls - Concrete Block | Entire Building | 14 | SF | 6 | 10+ years | |
| | | | | | | |
| Curtain wall - Insulated Panel | Entire Building | 306 | SF | 6 | 6-10 years | |
| Curtain wall - Windows | • | | | | | |
| | | 3 | <u> </u> | · · · · · · · · · · · · · · · · · · · | · · | · · · · · · · · · · · · · · · · · · · |



| Catego | ry : Exterior | | В | uilding | : Main | _ | |
|--------|---|-----------------|----------|---------|---------|--------------------------|--|
| | | | 0 | 11014 | | Recommend | 0 |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Guard - Guards wire guard | Entire Building | 3,458 | SF | 6 | 6-10 years | |
| | Lintels - Steel | Entire Building | 1,395 | LF | 6 | 10+ years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 8,694 | SF | 6 | 6-10 years | |
| atego | ry : Electrical | | В | uilding | : Main | | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| • | ncy System | | - Luay | | 110.111 | | |
| gc | Automatic Transfer Switch | Electrical Room | 1 | EA | 4 | 2-5 years | Serves main building. Deteriorate Not reliable |
| | Emergency A/C Power - Corridors and Stairs | Electrical Room | 8,809 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Lunchrooms | Electrical Room | 3,621 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Multipurpose | Electrical Room | 2,555 | SF | 6 | 6-10 years | |
| | Room Exit Signs - Corridors and Stairs | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 2 | ΕA | 2 | 0-1 year | No battariy, no AC generator |
| | Exit Signs - Lunchroom | Entire Building | 4 | EΑ | 2 | 0-1 year | No battariy, no AC generator |
| | Exit Signs - Multipurpose Room | Entire Building | 5 | EΑ | 2 | 0-1 year | No battariy, no AC generator |
| | Security System - CCTV | Entire Building | 61,600 | SF | 5 | 6-10 years | rie zanany, ne rie generater |
| | Security System - Intrusion Detection | Entire Building | 61,600 | SF | 5 | 6-10 years | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 20 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Lunchrooms | Entire Building | 5 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Multipurpose Room | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 6 | EA | 6 | 6-10 years | |
| in Se | rvice | | | | | | |
| | PA System | Electrical Room | 61,600 | SF | 5 | 6-10 years | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | 6-10 years | |
| | Main Electrical Service - 1000 A 120/208/3PH | Electrical Room | 1 | EA | 6 | 10+ years | |
| | Main Electrical Service - 1600 A 120/208/3PH | Electrical Room | 1 | EA | 6 | 10+ years | |
| ower D | vistribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 2 | EA | 6 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 5 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 6 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Name: Foreday | | | _, ` | | 2 .2 ; 54.5 | |

Campus Name: Faraday Page : 3 of 25 Assessment Date: 12/23/2019



| ry : Electrical | | Building : Main | | | | |
|---|--|--|--|---|---|--|
| | | | J | | Recommend | |
| Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 4 | 2-5 years | deteriorated. Replacement parts difficult to find. |
| Lighting and Power Panels - Above 100 A | Entire Building | 4 | EA | 4 | 2-5 years | deteriorated. Replacement parts difficult to find. |
| Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 4 | 2-5 years | deteriorated. Replacement parts difficult to find. |
| Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 4 | 2-5 years | deteriorated. Replacement parts difficult to find. |
| Main Distribution Panels - Greater than 600 amp | Entire Building | 1 | EA | 6 | 10+ years | difficult to find. |
| y : Fire Protection | | В | uilding | : Main | | |
| | | 0 | 11014 | | | |
| | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | |
| | | | | | • | |
| <u> </u> | | • | | | • | |
| Fire Alarm_System | Entire Building | 61,645 | SF | 6 | 10+ years | |
| y : Mechanical | | В | uilding | : Main | | |
| | | | | | Recommend | |
| | Location | Quantity | UOM | Rank | Replacement | Comments |
| tioning | | | | | | |
| Heat Pump- Floor Mounted- Electric Heating & DX Cooling- Remote Mounted Compressor - Less than 3 tons | Roof | 6 | EA | 5 | 6-10 years | |
| ing Systems | | | | | | |
| Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 15001-20000 cfm | 2nd Floor | 1 | EA | 5 | 6-10 years | |
| Air Intake | 2nd Floor | 1 | EA | 6 | 10+ years | |
| Auxiliaries - 15001-20000 cfm | 2nd Floor | 1 | EA | 5 | 6-10 years | |
| Zone Dampers | | 9 | EA | | 10+ vears | |
| Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | | | | | | |
| Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 5 | 6-10 years | |
| | Dailar Daam | 1 | EA | 6 | 10+ years | |
| Chemical Feed System | Boiler Room | I I | | | | |
| Chemical Feed System | | <u>-</u> | EΑ | 6 | | |
| | Boiler Room Boiler Room Boiler Room | 1 2 | | 6 5 | 10+ years 6-10 years | |
| i | Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A Main Distribution Panels - 400 - 600 amp Main Distribution Panels - Greater than 600 amp ry: Fire Protection Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type itioning Heat Pump- Floor Mounted- Electric Heating & DX Cooling- Remote Mounted Compressor - Less than 3 tons ling Systems Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 15001-20000 cfm Air Intake Auxiliaries - 15001-20000 cfm Zone Dampers Indoor Return Fans- Centrifugal Squirrel | Lighting and Power Panels - Above 100 A Entire Building Lighting and Power Panels - Above 100 A Entire Building Main Distribution Panels - 400 - 600 amp Entire Building Main Distribution Panels - Greater than 600 amp Main Distribution Panels - Greater than 600 Entire Building Main Distribution Panels - Greater than 600 Entire Building Main Distribution Panels - Greater than 600 Entire Building Fire Protection Item - Type Location Ty: Mechanical Item - Type Location Itioning Heat Pump- Floor Mounted- Electric Heating & DX Cooling- Remote Mounted Compressor - Less than 3 tons Iling Systems Air Handling Unit- Package Multi Zone-Indoor- Steam Coils - 15001-20000 cfm Air Intake Auxiliaries - 15001-20000 cfm Zone Dampers Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM | Lighting and Power Panels - Above 100 A Entire Building 4 Lighting and Power Panels - Above 100 A Entire Building 1 Main Distribution Panels - 400 - 600 amp Entire Building 1 Main Distribution Panels - Greater than 600 amp Entire Building 1 Main Distribution Panels - Greater than 600 Entire Building 1 Item - Type Location Quantity The Fire Alarm Panel Entire Building 1 Fire Alarm Strobe Lights Entire Building 61,645 Fire Alarm_System Entire Building 61,645 Fire Alarm_System Entire Building 61,645 Try: Mechanical B Item - Type Location Quantity Itioning Heat Pump- Floor Mounted- Electric Heating & DX Cooling- Remote Mounted Compressor - Less than 3 tons Iting_Systems Air Handling Unit- Package Multi Zone-Indoor- Steam Coils - 15001-20000 cfm Air Intake 2nd Floor 1 Auxiliaries - 15001-20000 cfm 2nd Floor 1 Zone Dampers 2nd Floor 9 Indoor Return Fans- Centrifugal Squirrel 2nd Floor 2nd Floor 9 Indoor Return Fans- Centrifugal Squirrel 2nd Floor 1 Cage - 5000 - 10000 CFM | Lighting and Power Panels - Above 100 A Entire Building 4 EA Lighting and Power Panels - Above 100 A Entire Building 1 EA Main Distribution Panels - 400 - 600 amp Entire Building 1 EA Main Distribution Panels - Greater than 600 Entire Building 1 EA Main Distribution Panels - Greater than 600 Entire Building 1 EA manp Ty: Fire Protection Quantity UOM The Alarm Panel Entire Building 1 EA Fire Alarm Strobe Lights Entire Building 61,645 SF Fire Alarm_System Entire Building 61,645 SF Ty: Mechanical Building Item - Type Location Quantity UOM Itioning Item - Type Location 1 EA Aurillariae - 15001-20000 cfm Air I Handling Unit- Package Multi Zone- Indoor- Steam Coils - 15001-20000 cfm Air I I I EA Zone Dampers 2nd Floor 1 EA Zone Dampers 2nd Floor 9 EA Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM | Lighting and Power Panels - Above 100 A Entire Building 4 EA 4 Lighting and Power Panels - Above 100 A Entire Building 1 EA 4 Main Distribution Panels - 400 - 600 amp Entire Building 1 EA 4 Main Distribution Panels - Greater than 600 Entire Building 1 EA 6 Main Distribution Panels - Greater than 600 Entire Building 1 EA 6 Main Distribution Panels - Greater than 600 Entire Building 1 EA 6 Main Distribution Panels - Greater than 600 Entire Building 1 EA 6 Fire Protection Quantity UOM Rank Main Type Location Quantity UOM Rank Entire Building 61,645 SF 6 Fire Alarm Strobe Lights Entire Building 61,645 SF 6 Fire Alarm_System Entire Building 61,645 SF 6 Fire Alarm_System Entire Building 61,645 SF 6 Fory: Mechanical Building: Main Item - Type Location Quantity UOM Rank Itioning Heat Pump- Floor Mounted- Electric Heating & Not Cooling- Remote Mounted Compressor - Less than 3 tons Iling Systems Air Handling Unit- Package Multi Zone-Indoor- Steam Coils - 15001-20000 cfm Air Intake 2nd Floor 1 EA 5 Auxiliaries - 15001-20000 cfm 2nd Floor 1 EA 6 Auxiliaries - 15001-20000 cfm 2nd Floor 1 EA 5 Zone Dampers 2nd Floor 9 EA 5 Indoor Return Fans- Centrifugal Squirrel 2nd Floor 1 EA 6 Cage - 5000 - 10000 CFM | Lighting and Power Panels - Above 100 A Entire Building 4 EA 4 2-5 years Lighting and Power Panels - Above 100 A Entire Building 1 EA 4 2-5 years Main Distribution Panels - 400 - 600 amp Entire Building 1 EA 4 2-5 years Main Distribution Panels - Greater than 600 Entire Building 1 EA 6 10+ years Main Distribution Panels - Greater than 600 Entire Building 1 EA 6 10+ years Main Distribution Panels - Greater than 600 Entire Building 1 EA 6 10+ years Main Distribution Panels - Greater than 600 Entire Building 1 EA 6 10+ years Pry : Fire Protection Quantity UOM Rank Replacement Mem - Type Location Quantity 5 F 6 10+ years Fire Alarm Strobe Lights Entire Building 61,645 SF 6 10+ years Fire Alarm_System Entire Building 61,645 SF 6 10+ years Pry : Mechanical Building : Main Recommend Replacement Meter - Type Location Quantity UOM Rank Replacement Meter - Type Location Quantity UOM Rank Replacement Michael Pump- Floor Mounted - Electric Heating 8 DX Cooling- Remote Mounted Compressor - Less than 3 tons Main Distribution Panels - Above 100 Panels - 1000 Pane |



| Catego | ry : Mechanical | | В | uilding | : Main | | | |
|------------|--|-----------------|----------|---------|--------|-------------|-------------------------------------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Feed Water Pumps and Tank | Boiler Room | 1 | EA | 6 | 10+ years | | |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP | Boiler Room | 2 | EA | 5 | 6-10 years | | |
| | Piping - Condensate Pipe- Steel | Boiler Room | 200 | LF | 5 | 10+ years | | |
| | Piping - Steam Pipe- Steel | Boiler Room | 200 | LF | 5 | 10+ years | | |
| | Steam Traps | Boiler Room | 12 | EA | 5 | 6-10 years | | |
| Heat Exc | changers | | | | | | | |
| | Heat Exchanger - Steam to Hot Water Shell | Boiler Room | 1 | EA | 5 | 6-10 years | | |
| | Туре | | | | | | | |
| Heating | | | | | | | | |
| | Wall Heater - Electric | Entire Building | 2 | EA | 6 | 10+ years | | |
| | Wall Heater - Electric | Entire Building | 5 | EA | 5 | 6-10 years | | |
| | Fin Tube - Hot Water | Entire Building | 60 | LF | 5 | 10+ years | | |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 14 | EA | 5 | 6-10 years | | |
| | Duct Heater - Hot Water | Mechanical Room | 2 | | 5 | 6-10 years | | |
| Mechani | cal Plumbing | | | | | | | |
| | Hot Water Pump - Less than 10 | Boiler Room | 2 | EA | 6 | 6-10 years | | |
| | Hydronic Supply and Return - Steel | Entire Building | 400 | LF | 6 | 6-10 years | | |
| Tempera | ature Control | | | | | | | |
| • | Electric Thermostat | Entire Building | 60 | EA | 6 | 6-10 years | | |
| | Pneumatic System | Entire Building | 58,600 | SF | 4 | 2-5 years | leaks. Difficult to control | |
| | Thermostats - Pneumatic | Entire Building | 9 | ĒΑ | 4 | 2-5 years | not calibrated, leaking | |
| Unit Ven | tilation | | | | | | | |
| | Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only | Entire Building | 40 | EA | 6 | 10+ years | | |
| | Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only | Entire Building | 2 | EA | 5 | 6-10 years | | |
| Ventilatio | on. | | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 3 | EA | 6 | 10+ years | | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 1 | EA | 5 | 6-10 years | Noisy, deteriorated | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building | 2 | EA | 6 | 10+ years | | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building | 1 | EA | 6 | 10+ years | | |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building | 1 | EΑ | 6 | 10+ years | Was previously used above a cooking | |

Campus Name: Faraday Page : 5 of 25 Assessment Date: 12/23/2019



Michael Faraday Elementary School

| Catego | y : Mechanical | | В | uilding | : Main | | 250 W Monroe STREET, Chicago, IL 60624 |
|----------------|---|---------------------------|--|---------|--------|-------------|--|
| | , | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| · | | | , and the second | | | | range. Kitchen is now a warming kitchen only. |
| Catego | y : Plumbing | | Building : Main | | | | |
| _ | - | | 0 | 11014 | | Recommend | • |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Hot Wate | | D 1 D | | Ε.Δ. | | 0.5 | |
| | Gas Heater - 150000 - 300000 BTU/HR | Boiler Room | 1 | EA | 4 | 2-5 years | Beyond service life. Deteriorated |
| Piping | | | | | | | |
| — | Domestic Piping-Cold Water Horizontal Lines | Entire Building | 61,645 | SF | 4 | 2-5 years | More than 50 years old. Plumbing is major maintenance problem, frequen |
| | Lines | | | | | | leaks |
| | Domestic Piping-Cold Water Risers | Entire Building | 61,645 | SF | 4 | 2-5 years | More than 50 years old. Plumbing is |
| | | | | | | | major maintenance problem, frequer leaks |
| | Domestic Piping-Cold Water from Risers to | Entire Building | 61,645 | SF | 4 | 2-5 years | More than 50 years old. Plumbing is |
| | Fixtures | ŭ | · | | | • | major maintenance problem, frequer leaks |
| | Domestic Piping-Hot Water Horizontal Lines | Entire Building | 61,645 | SF | 4 | 2-5 years | More than 50 years old. Plumbing is |
| | | | | | | | major maintenance problem, frequer leaks |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 61,645 | SF | 4 | 2-5 years | More than 50 years old. Plumbing is |
| | | | | | | | major maintenance problem, frequen |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 61,645 | SF | 4 | 2-5 years | leaks More than 50 years old. Plumbing is |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 61,045 | SF | 4 | 2-5 years | major maintenance problem, frequen |
| | | | | | | | leaks |
| | Domestic Piping-Hot Water from Risers to | Entire Building | 61,645 | SF | 4 | 2-5 years | More than 50 years old. Plumbing is |
| | Fixtures | | | | | | major maintenance problem, frequer |
| | Sanitary Piping | Entire Building | 61.645 | SF | 6 | 10+ years | leaks |
| | Storm Piping | Entire Building | 61,645 | SF | 5 | 6-10 years | |
| | Vent Piping | Entire Building | 61,645 | SF | 6 | 10+ years | |
| Pumps | | | | | | | |
| Lumps | Pumps - Domestic Booster Pump-Simplex | 1st Floor and Boiler Room | 1 | EA | 5 | 6-10 years | |
| | Pumps - Sump-Simplex | 1st Floor and Boiler Room | 1 | EA | 6 | 10+ years | |

Category : Room Building : Main

| | | | | | | Recommend | |
|-------|---------------------------|----------|----------|-----|------|-------------|----------|
| Grou | p Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Admii | nistrative Suites/Offices | | | | | | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|-----------------------------|---------------------------|----------|---------|--------|-------------|----------|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Plaster/Drywall | 1st Floor | 368 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 368 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 8 | EA | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 31 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 699 | SF | 6 | 10+ years | |
| | AC Unit | 1st Floor | 2 | EΑ | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 535 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 535 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 8 | EA | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 31 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 981 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor Teachers Lounge | 309 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor Teachers Lounge | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor Teachers Lounge | 309 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor Teachers Lounge | 4 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor Teachers Lounge | 2,722 | SF | 6 | 10+ years | |
| | AC Unit | Engineer's Office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Engineer's Office | 82 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Engineer's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Engineer's Office | 82 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Engineer's Office | 1 | EA | 6 | 6-10 years | |
| | Power Distribution | Engineer's Office | 6 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | Engineer's Office | 97 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Kitchen Manager's Office | 116 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Kitchen Manager's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Kitchen Manager's Office | 116 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Kitchen Manager's Office | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Kitchen Manager's Office | 4 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | Kitchen Manager's Office | 133 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Nurse's Office | 72 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Nurse's Office | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | Nurse's Office | 72 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Nurse's Office | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | Nurse's Office | 6 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | Nurse's Office | 85 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Treatment Room | 247 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Treatment Room | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Treatment Room | 247 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Treatment Room | 4 | ĒΑ | 6 | 6-10 years | |
| | Power Distribution | Treatment Room | 4 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | Treatment Room | 284 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Waiting Room | 98 | SF | 6 | 10+ years | |
| | č , | 3 | | | | , | |



| Catego | ry : Room | | В | uilding | : Main | | <u> </u> |
|---------|---|--------------|----------|----------|--------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | Waiting Room | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Waiting Room | 98 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Waiting Room | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Waiting Room | 2 | EA | 6 | 10+ years | |
| | Storage/ Closet | Waiting Room | 26 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Waiting Room | 116 | SF | 6 | 10+ years | |
| Gymnas | ia | | | | | | |
| • | Ceiling - Lay-in | 1st Floor | 3,621 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 4 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 3,621 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 18 | EΑ | 7 | 6-10 years | |
| | Scoreboards | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage | 1st Floor | 523 | SF | 6 | 10+ years | |
| | Stage Curtain | 1st Floor | 4 | EA | 5 | 6-10 years | |
| | Stage Curtain Stage Lift | 1st Floor | 1 | EA | 7 | 10+ years | |
| | | 1st Floor | 1 | EA | 7 | | |
| | Stage Lighting System | | • | | - | 6-10 years | |
| | Stage-Stairs - Wood | 1st Floor | 5 | LF | 6 | 10+ years | |
| | Storage/ Closet | 1st Floor | 47 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 2,082 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 2,082 | SF | 6 | 10+ years | |
| Kitchen | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,012 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,012 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 7 | 6-10 years | |
| | Serving Line | 1st Floor | 20 | LF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 1,174 | SF | 6 | 10+ years | |
| Library | | | | | | | |
| - | AC Unit | 2nd Floor | 4 | EA | 5 | 6-10 years | |
| | Casework | 2nd Floor | 42 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,398 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,398 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 24 | EA | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 124 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 1,473 | SF | 6 | 10+ years | |
| Lunch & | Multipurpose Room | | | | | | |
| unon Q | Ceiling - Lay-in | 1st Floor | 1,916 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in Ceiling - Plaster/Drywall | | | SF SF | | • | |
| | Ceiling - Flaster/Drywall | 1st Floor | 638 | SF | 6 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Main | | | | |
|----------|---------------------------------|------------|----------|---------|--------|-------------|---------------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | | | |
| | Floor - Tile | 1st Floor | 2,555 | SF | 6 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | 56 | EΑ | 7 | 6-10 years | | | |
| | Storage/ Closet | 1st Floor | 43 | SF | 7 | 10+ years | | | |
| | Storage/ Closet | 1st Floor | 35 | SF | 7 | 10+ years | | | |
| | Storage/ Closet | 1st Floor | 193 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 1st Floor | 2,938 | SF | 6 | 10+ years | | | |
| MDF ID | F | | | | | | | | |
| <u> </u> | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | | | |
| | Finishes | 3rd Floor | 320 | SF | 7 | 10+ years | | | |
| | Window AC Unit | 3rd Floor | 1 | EA | 7 | 6-10 years | | | |
| | Wildow AC Chit | 314 1 1001 | ' | LA | , | 0-10 years | | | |
| Mechan | ical/ Service Rooms | | | | | | | | |
| | Boiler Room | 1st Floor | 995 | SF | 7 | 10+ years | | | |
| | Janitor's Closet | 1st Floor | 43 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 1st Floor | 38 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 1st Floor | 219 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 1st Floor | 47 | SF | 7 | 10+ years | | | |
| | Storage Room | 1st Floor | 97 | SF | 7 | 10+ years | | | |
| | Storage Room | 1st Floor | 105 | SF | 7 | 10+ years | | | |
| | Storage Room | 1st Floor | 28 | SF | 7 | 10+ years | | | |
| | Janitor's Closet | 3rd Floor | 138 | SF | 7 | 10+ years | | | |
| | Mechanical/ Service Rooms | 3rd Floor | 92 | SF | 7 | 10+ years | | | |
| | Storage Room | 3rd Floor | 123 | SF | 7 | 10+ years | | | |
| Restroo | m | | | | | | | | |
| | Accessories | 1st Floor | 285 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 285 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | ĒΑ | 6 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 283 | SF | 6 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 2 | SF | 4 | 0-1 year | Missing Tiles | | |
| | Floor Drain | 1st Floor | _ 1 | EA | 7 | 10+ years | ges | | |
| | Lavatory | 1st Floor | 3 | EA | 6 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | 2 | EA | 7 | 6-10 years | | | |
| | Partitions | 1st Floor | 2 | EA | 7 | 10+ years | | | |
| | Urinals | 1st Floor | 5 | EA | 6 | 10+ years | | | |
| | Walls - Structural Glazed Tile | 1st Floor | 327 | SF | 6 | 10+ years | | | |
| | Water Closet | 1st Floor | 2 | EA | 6 | 10+ years | | | |
| | Accessories | 1st Floor | 315 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 315 | SF | 6 | 10+ years | | | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 315 | SF | 6 | , | | | |
| | Floor - The Ceramic/ Porcelain | 191 11001 | 315 | SF | О | 10+ years | | | |



| Catego | y: Room Building: Main | | | | | | |
|--------|---------------------------------|-------------|----------|------------|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor | 3 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 2 | EΑ | 6 | 6-10 years | |
| | Partitions | 1st Floor | 6 | EΑ | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 1st Floor | 362 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor | 6 | EA | 6 | 10+ years | |
| | Accessories | 1st Floor | 40 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 40 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 40 | SF | 6 | 10+ years | |
| | Lavatory | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 89 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Accessories | 1st Floor | 42 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 42 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 42 | SF | 6 | 10+ years | |
| | Lavatory | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Lighting - Wall Mounted | 1st Floor | 1 | ĒΑ | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 93 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Accessories | 1st Floor | 40 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 40 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 40 | SF | 6 | 10+ years | |
| | Lavatory | 1st Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 89 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor | 1 | EΑ | 6 | 10+ years | |
| | Accessories | 1st Floor | 40 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 40 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 40 | SF | 6 | 10+ years | |
| | Lavatory | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 1 | EΑ | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 89 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Accessories | 2nd Floor | 285 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 285 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 285 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor | 3 | EA | 6 | 10+ years | |
| | Lavatory | 2110 1 1001 | 3 | <u>-</u> A | U | TOT years | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|---------------------------------|------------------------|----------|---------|--------|------------------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Urinals | 2nd Floor | 5 | EA | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 327 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Accessories | 2nd Floor | 315 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 315 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd Floor | 315 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd Floor | 1 | ĒΑ | 7 | 10+ years | |
| | Lavatory | 2nd Floor | 3 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 2 | ĒΑ | 6 | 6-10 years | |
| | Partitions | 2nd Floor | 6 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 2nd Floor | 362 | SF | 6 | 10+ years | |
| | Water Closet | 2nd Floor | 6 | EA | 6 | 10+ years | |
| | Accessories | 3rd Floor | 285 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 285 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor | 285 | SF | 6 | 10+ years | |
| | Floor Drain | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Lavatory | 3rd Floor | 3 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Partitions | 3rd Floor | 2 | EA | 7 | - | |
| | Urinals | 3rd Floor | 5 | EA | 6 | 10+ years 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 327 | SF | 6 | | |
| | Water Closet | 3rd Floor | | EA | | 10+ years | |
| | Accessories | 3rd Floor 3rd Floor | 2 315 | SF | 6 7 | 10+ years | |
| | | 3rd Floor | 315 | SF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | | | | | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd Floor | 315 | SF | 6 | 10+ years | |
| | Floor Drain | 3rd Floor | 1 | EΑ | 7 | 10+ years | |
| | Lavatory | 3rd Floor | 3 | EΑ | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 2 | EΑ | 6 | 6-10 years | |
| | Partitions | 3rd Floor | 6 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | 3rd Floor | 362 | SF | 6 | 10+ years | |
| | Water Closet | 3rd Floor | 6 | EA | 6 | 10+ years | |
| | Accessories | In Engineer's Office | 32 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | In Engineer's Office | 32 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | In Engineer's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | In Engineer's Office | 32 | SF | 6 | 10+ years | |
| | Lavatory | In Engineer's Office | 1 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | In Engineer's Office | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | In Engineer's Office | 39 | SF | 6 | 10+ years | |
| | Water Closet | In Engineer's Office | 1 | EA | 6 | 10+ years | |
| | | | | | | | |



| Catego | ry : Room | | В | uilding | : Main | | |
|----------|---------------------------------|--------------------------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Accessories | Men's Room, 1st Floor | 106 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Men's Room, 1st Floor | 106 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Men's Room, 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Men's Room, 1st Floor | 106 | SF | 6 | 10+ years | |
| | Lavatory | Men's Room, 1st Floor | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Men's Room, 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Partitions | Men's Room, 1st Floor | 1 | EA | 7 | 10+ years | |
| | Urinals | Men's Room, 1st Floor | 2 | EA | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | Men's Room, 1st Floor | 122 | SF | 6 | 10+ years | |
| | Water Closet | Men's Room, 1st Floor | 1 | EA | 6 | 10+ years | |
| | Accessories | Restroom inside Treatment Room | 68 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Restroom inside Treatment Room | 68 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Restroom inside Treatment Room | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | Restroom inside Treatment Room | 68 | SF | 6 | 10+ years | |
| | Lavatory | Restroom inside Treatment Room | 1 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | Restroom inside Treatment Room | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | Restroom inside Treatment Room | 82 | SF | 6 | 10+ years | |
| | Water Closet | Restroom inside Treatment Room | 1 | EA | 6 | 10+ years | |
| | Accessories | Unisex Room, 2nd Floor | 39 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Unisex Room, 2nd Floor | 39 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Unisex Room, 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Unisex Room, 2nd Floor | 39 | SF | 6 | 10+ years | |
| | Lavatory | Unisex Room, 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Unisex Room, 2nd Floor | 1 | EΑ | 7 | 6-10 years | |
| | Lighting - Wall Mounted | Unisex Room, 2nd Floor | 1 | EΑ | 6 | 6-10 years | |
| | Walls - Concrete Block | Unisex Room, 2nd Floor | 51 | SF | 6 | 10+ years | |
| | Water Closet | Unisex Room, 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Accessories | Women's Room, 1st Floor | 115 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Women's Room, 1st Floor | 115 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Women's Room, 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Women's Room, 1st Floor | 115 | SF | 6 | 10+ years | |
| | Lavatory | Women's Room, 1st Floor | 2 | ĒΑ | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Women's Room, 1st Floor | 2 | ΕA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | Women's Room, 1st Floor | 2 | EΑ | 6 | 6-10 years | |
| | Partitions | Women's Room, 1st Floor | 3 | EA | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | Women's Room, 1st Floor | 136 | SF | 6 | 10+ years | |
| | Water Closet | Women's Room, 1st Floor | 2 | EA | 6 | 10+ years | |
| Catego | ry : Classroom | | В | uilding | : Main | | |
| ge | | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | om #102 (Office) | | | | | | |
| | Casework | 1st Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 712 | SF | 6 | 10+ years | |

Campus Name: Faraday Page : 12 of 25 Assessment Date: 12/23/2019



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|----------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 819 | SF | 6 | 10+ years | |
| Classroo | om #103 (Office) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 996 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 996 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 943 | SF | 6 | 10+ years | |
| | | | 1 | | 7 | • | |
| | Work Sink | 1st Floor | I | EA | , | 10+ years | |
| Classroo | om #104 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 712 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 819 | SF | 6 | 10+ years | |
| Classroo | om #105 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 40 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 996 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 996 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 943 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classro | om #106 (Kindergarten) | | | | | | |
| CIASSIU | | 1ot Floor | 22 | 1.5 | | 10 | |
| | Casework | 1st Floor | 28 | LF CF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 712 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | | | | | | | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------------|-----------|----------|---------|--------|-------------|--------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 706 | SF | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 6 | SF | 4 | 0-1 year | Leaks Stains |
| | Lighting - Lay-in | 1st Floor | 12 | EΑ | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 819 | SF | 6 | 10+ years | |
| Classroc | om #107 (Kindergarten) | | | | | | |
| | AC Units | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 40 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 996 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 996 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 10 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 31 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 943 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| lassroo | om #108 (Regular Classroom) | | | | | | |
| 21000101 | Casework | 1st Floor | 28 | LF | 6 | 10+ years | |
| | Casework Ceiling - Lay-in | 1st Floor | 712 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 712 | SF | 6 | • | |
| | | 1st Floor | 12 | EA | 7 | 10+ years | |
| | Lighting - Lay-in Marker Board | 1st Floor | 12 | LF | 6 | 6-10 years | |
| | | | | | - | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 819 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroc | m #109 (Office) | | | | | | |
| | Casework | 1st Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 14 | EΑ | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 62 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 788 | SF | 6 | 10+ years | |
| Classroc | om #110 (Office) | | | | | | |
| | Casework | 1st Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 712 | SF | 6 | 10+ years | |
| | g - , | | 712 | ٥. | Ŭ | .o. youro | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------------|------------------------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 14 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 819 | SF | 6 | 10+ years | |
| Classroo | om #200 (Office) | | | | | | |
| | Casework | 2nd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | | 2nd Floor | 12 | EA | 6 | • | |
| | Lighting - Lay-in Marker Board | | | | - | 6-10 years | |
| | | 2nd Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 819 | SF | 6 | 10+ years | |
| Classroo | om #201 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | ĒΑ | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 62 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 788 | SF | 6 | 10+ years | |
| Classroo | om #202 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor 2nd Floor | 28 | LF | 6 | • | |
| | | | | SF | | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 819 | SF | 6 | 10+ years | |
| Classroo | om #203 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | TIOUT THO | 2110 1 1001 | 712 | 01 | U | TOT years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|------------------------|----------|---------|--------|------------------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 62 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 788 | SF | 6 | 10+ years | |
| Classroc | om #204 (Store Room) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | ĒΑ | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 819 | SF | 6 | 10+ years | |
| Classroc | om #206 (Office) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 819 | SF | 6 | 10+ years | |
| Classroo | om #208 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 819 | SF | 6 | 10+ years | |
| Classroo | om #209 (Store Room) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 12 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor 2nd Floor | 712 | SF | 6 | 10+ years 10+ years | |
| | | | | | 6 | • | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | ю | 6-10 years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|------------|-----------------------------|-----------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 2nd Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 62 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 788 | SF | 6 | 10+ years | |
| Classroo | m #210 (Special Education) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 24 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ΕA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | | | LF | | • | |
| | | 2nd Floor | 12 | SF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 819 | | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | m #211 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 62 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 788 | SF | 6 | 10+ years | |
| Classroo | m #212 (Regular Classroom) | | | | | | |
| ZICIOOI OC | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | • | |
| | | | | | | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 819 | SF | 6 | 10+ years | |
| Classroo | m #213 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 712 | SF | 6 | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 62 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 788 | SF | 6 | 10+ years | |
| Classroc | om #300 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 5 | 6-10 years | |
| | Casework | 3rd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EΑ | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 819 | SF | 6 | 10+ years | |
| Classroc | om #301 (Computer Lab) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 712 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 788 | SF | 6 | 10+ years | |
| | Wireless System | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroc | om #302 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 12 | LF | 6 | | |
| | | | | | _ | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 819 | SF | 6 | 10+ years | |
| lassroc | om #303 (Store Room) | Ond Flag | | | | 0.40 | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 20 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 712 | SF | 6 | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|---|-----------|----------|----------|--------|-------------------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 62 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 788 | SF | 6 | 10+ years | |
| Classroo | om #304 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | ĒA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 819 | SF | 6 | 10+ years | |
| Classroo | om #305 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 62 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 788 | SF | 6 | 10+ years | |
| Classroo | om #306 (Regular Classroom) | | | | | | |
| | AC Units | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 28 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 819 | SF | 6 | 10+ years | |
| Classroo | om #307 (Computer Lab) | | | | | | |
| CIGSSIUL | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 21 | LF | 6 | 6-10 years 10+ years | |
| | | | | SF | 6 | • | |
| | Ceiling - Lay-in Doors - Wood Doors inclu hw | 3rd Floor | 712 1 | | - | 10+ years | |
| | | 3rd Floor | | EA SF | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 712 | | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 6 | 6-10 years | |

Campus Name: Faraday Page : 19 of 25 Assessment Date: 12/23/2019



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|---|------------------------|----------|----------|--------|-------------------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 3rd Floor | 26 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 788 | SF | 6 | 10+ years | |
| | Wireless System | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroo | om #308 (Science Classroom) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 45 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,199 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,199 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 18 | ĒΑ | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 689 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 689 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 2 | EA | 7 | 10+ years | |
| Classroo | om #309 (Regular Classroom) | | | | | | |
| Olassioo | AC Units | 4th Floor | 1 | EA | 7 | 6-10 years | |
| | Casework | 4th Floor | 21 | LF | 6 | 10+ years | |
| | Casework Ceiling - Lay-in | 4th Floor | 712 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 4th Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 4th Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 4th Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 4th Floor | 20 | LF | 6 | | |
| | Walls - Concrete Block | 4th Floor | 788 | SF | 6 | 6-10 years 10+ years | |
| Classroo | om #311 (Store Room) | | | | | | |
| Classiuu | , | 3rd Floor | 4 | ГΛ | 7 | 6.10 veers | |
| | AC Units | 3rd Floor 3rd Floor | 1 21 | EA LF | 7 6 | 6-10 years | |
| | Casework | | | | - | 10+ years | |
| | Ceiling - Lay-in Doors - Wood Doors inclu hw | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 62 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 788 | SF | 6 | 10+ years | |
| Classroo | m #312 (Other Instructional Use) | | | | | | |
| | AC Units | 3rd Floor | 3 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 65 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 1,836 | SF | 6 | 10+ years | |



| alego | ry : Classroom | | В | uilding | : Main | | |
|--------------------------|--|---|---|---|--|---|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,836 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 30 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 44 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,434 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 646 | SF | 6 | 10+ years | |
| | • | | | | | , | |
| Classroc | m #313 (Music Room) | | | | | | |
| | AC Units | 3rd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 3rd Floor | 21 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 24 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EΑ | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 16 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 788 | SF | 6 | 10+ years | |
| Catego | ry : Interior | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| | | | | | | | |
| | Item - Type | Location | Quantity | UOM | Rank | | Comments |
| • | - | | • | | | Replacement | Comments |
| • | Ceiling - Plaster/Drywall | 1st Floor | 3,038 | SF | 6 | Replacement 10+ years | Comments |
| | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain | 1st Floor 1st Floor | 3,038 | SF EA | 6 5 | Replacement 10+ years 10+ years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet | 1st Floor 1st Floor 1st Floor | 3,038 4 3,038 | SF EA SF | 6 5 7 | 10+ years 10+ years 10+ years 10+ years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface | 1st Floor 1st Floor 1st Floor 1st Floor | 3,038 4 3,038 21 | SF EA SF EA | 6 5 7 7 | 10+ years 10+ years 10+ years 10+ years 6-10 years | Comments |
| | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block | 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor | 3,038 4 3,038 21 896 | SF EA SF EA SF | 6 5 7 7 6 | 10+ years 10+ years 10+ years 10+ years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile | 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor | 3,038 4 3,038 21 896 2,688 | SF EA SF EA SF SF | 6 5 7 7 6 6 | 10+ years 10+ years 10+ years 10+ years 6-10 years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall | 1st Floor 2nd Floor | 3,038 4 3,038 21 896 | SF EA SF EA SF SF SF | 6 5 7 7 6 6 6 | 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile | 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor | 3,038 4 3,038 21 896 2,688 3,038 4 | SF EA SF EA SF SF SF EA | 6 5 7 7 6 6 | 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet | 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 3,038 4 3,038 21 896 2,688 3,038 | SF EA SF EA SF SF SF | 6 5 7 7 6 6 6 7 7 | 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years | Comments |
| | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain | 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor | 3,038 4 3,038 21 896 2,688 3,038 4 | SF EA SF EA SF SF SF EA | 6 5 7 7 6 6 6 | 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet | 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 3,038 4 3,038 21 896 2,688 3,038 4 3,038 | SF EA SF EA SF SF EA SF | 6 5 7 7 6 6 6 7 7 | 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years | Comments |
| | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface | 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 3,038 4 3,038 21 896 2,688 3,038 4 3,038 21 | SF EA SF EA SF SF EA SF EA | 6 5 7 7 6 6 6 7 7 | Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile | 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor | 3,038 4 3,038 21 896 2,688 3,038 4 3,038 21 896 2,688 | SF EA SF EA SF EA SF EA SF | 6 5 7 7 6 6 6 7 7 6 | Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall | 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 2st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor | 3,038 4 3,038 21 896 2,688 3,038 4 3,038 21 896 | SF EA SF EA SF EA SF EA SF SF SF | 6 5 7 7 6 6 6 7 7 6 6 | Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain | 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor | 3,038 4 3,038 21 896 2,688 3,038 4 3,038 21 896 2,688 3,038 4 | SF EA SF EA SF EA SF EA SF EA | 6 5 7 7 6 6 6 7 7 6 6 6 | Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years | Comments |
| • | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet | 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 3,038 4 3,038 21 896 2,688 3,038 4 3,038 21 896 2,688 3,038 4 3,038 | SF EA SF EA SF EA SF EA SF | 6 5 7 7 6 6 6 7 7 6 6 6 7 7 | Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years | Comments |
| | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface | 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 3,038 4 3,038 21 896 2,688 3,038 4 3,038 21 896 2,688 3,038 4 3,038 | SF EA | 6 5 7 7 6 6 6 7 7 6 6 6 7 7 | Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years | Comments |
| Group Corridor | Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Fountain Floor - Tile/Sheet | 1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor | 3,038 4 3,038 21 896 2,688 3,038 4 3,038 21 896 2,688 3,038 4 3,038 | SF EA SF EA SF EA SF EA SF | 6 5 7 7 6 6 6 7 7 6 6 6 7 7 | Replacement 10+ years 10+ years 10+ years 6-10 years 10+ years | Comments |



| Catego | ry : Interior | | В | uilding | : Main | | |
|----------|--|-----------------|----------|---------|--------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Camera Viewing Station | Entire building | 1 | EΑ | 7 | 6-10 years | |
| | Security Cameras | Entire building | 5 | EA | 7 | 6-10 years | |
| | Security Cameras | Entire building | 6 | EA | 7 | 6-10 years | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | East | 432 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | East | 432 | SF | 6 | 10+ years | |
| | Handrails | East | 152 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | East | 6 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | East | 69 | LF | 6 | 10+ years | |
| | Walls - Concrete Block | East | 394 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | East | 394 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | West | 432 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | West | 432 | SF | 6 | 10+ years | |
| | Handrails | West | 152 | LF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | West | 6 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | West | 69 | LF | 6 | 10+ years | |
| | Walls - Concrete Block | West | 394 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | West | 394 | SF | 6 | 10+ years | |
| Vertical | Conveyance | | | | | | |
| | Elevator - Elevator- Roped Holeless Hydraulic | | 1 | EA | 7 | 10+ years | |

Campus Name: Faraday Page : 22 of 25 Assessment Date: 12/23/2019



| Category : Site | Building : Site |
|-----------------|-----------------|
|-----------------|-----------------|

| Category: Site | | | В | Building : Site | | | | |
|----------------|---|---------------------|----------|-----------------|------|---|---------------------------|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| Civil/Dra | inage | | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 5 | EA | 6 | 6-10 years | | |
| | Civil/ Drainage - Site Manhole | Entire Site | 9 | EA | 6 | 6-10 years | | |
| | • | | | | | • | | |
| encing | | | | | | | | |
| 9 | Fencing - Chain Link | Entire Site | 196 | LF | 6 | 6-10 years | | |
| | Fencing - New Standard Ornamental | Entire Site | 875 | LF | 6 | 6-10 years | repaint | |
| | Fencing - New Standard Ornamental | Entire Site | 268 | LF | 6 | 6-10 years | roof | |
| | 3 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 | | | | | , | | |
| andsca | pe | | | | | | | |
| | Benches | Entire Site | 2 | EA | 6 | 6-10 years | | |
| | Irrigation | Entire Site | 62,550 | SF | 4 | 0-1 year | not working | |
| | Landscape - Grass | Entire Site | 76,585 | SF | 6 | 6-10 years | | |
| | Parkway trees | Entire Site | 22 | EΑ | 6 | 6-10 years | | |
| | Planting Beds/ Area | Entire Site | 550 | SF | 6 | 6-10 years | | |
| | Play Area - Asphalt/ Hardscape | Entire Site | 3,960 | SF | 6 | 6-10 years | | |
| | Trash Receptacles | Entire Site | 3 | EA | 6 | 6-10 years | | |
| Parking I | ot. | | | | | | | |
| -arking i | Concrete Curbs | Parking Lot- North | 135 | LF | 6 | 6-10 years | | |
| | Surface - Asphalt | Parking Lot- North | 5,610 | SF | 4 | 0-10 years 0-1 year | Worn area of parking lot | |
| | Surface - Aspirali | Parking Lot- North | 8,960 | SF | 6 | 6-10 years | World area or parking lot | |
| | Trash Enclosure - Chain Links | Parking Lot- North | 128 | SF | 6 | 6-10 years | | |
| | Trasii Eficiosule - Chain Links | Parking Lot- North | 120 | SF | O | 0-10 years | | |
| laygrou | nd | | | | | | | |
| , , | Equipment - Pre K 3-5 | Northeast Courtyard | 1 | EA | 6 | 6-10 years | | |
| | Surface - Poured Surface | Northeast Courtyard | 1,761 | SF | 6 | 6-10 years | Some patching | |
| | Equipment - School Age 5-12 | Northwest Courtyard | 1 | EA | 6 | 6-10 years | | |
| | Surface - Poured Surface | Northwest Courtyard | 3,032 | SF | 6 | 6-10 years | | |
| | | | | | | | | |
| Sidewalk | | | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 983 | LF | 6 | 10+ years | | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 8,056 | SF | 6 | 10+ years | | |
| Signage | | | | | | | | |
| -guaya | Flag Pole - Flag Pole | South Courtyard | 1 | EA | 6 | 6-10 years | | |
| | Marquee - Free Standing Back Lighted | South Courtyard | 1 | EΑ | 6 | 6-10 years | | |
| | | 222 200, 5 | • | | • | 3 .0 ,00.0 | | |



Michael Faraday Elementary School

3250 W Monroe STREET, Chicago, IL 60624

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Faraday Page : 24 of 25 Assessment Date: 12/23/2019



Classroom Summary

| | | | Floor Plan | | Glazed | Operable | | | | | |
|-------------------------|-------------------|---------------|------------|--------|--------|----------|--------|--------|--------|--|--|
| | | | Room | Room | Area | Window | Window | Window | Smart- | | |
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board | | |
| Building : Main | | | | | | | | | | | |
| Computer Lab | Regular Classroom | 3rd Floor | 301 | 301 | 712 | 174 | 56 | Υ | N | | |
| Computer Lab | Regular Classroom | 3rd Floor | 307 | 307 | 712 | 174 | 56 | Υ | N | | |
| Kindergarten | Kindergarten | 1st Floor | 107 | 107 | 996 | 261 | 84 | Υ | N | | |
| Kindergarten | Regular Classroom | 1st Floor | 106 | 106 | 712 | 126 | 54 | Υ | N | | |
| Music Room | Regular Classroom | 3rd Floor | 313 | 313 | 712 | 174 | 56 | Υ | N | | |
| Office | Kindergarten | 1st Floor | 103 | 103 | 996 | 261 | 84 | Υ | N | | |
| Office | Regular Classroom | 1st Floor | 102 | 102 | 712 | 126 | 54 | Υ | N | | |
| Office | Regular Classroom | 1st Floor | 109 | 109 | 712 | 174 | 56 | Υ | N | | |
| Office | Regular Classroom | 1st Floor | 110 | 110 | 712 | 126 | 54 | Υ | N | | |
| Office | Regular Classroom | 2nd Floor | 200 | 200 | 712 | 112 | 48 | Υ | N | | |
| Office | Regular Classroom | 2nd Floor | 206 | 206 | 712 | 112 | 48 | Υ | N | | |
| Other Instructional Use | Regular Classroom | 3rd Floor | 312 | 312 | 1,836 | 224 | 96 | Υ | Ν | | |
| Regular Classroom | Kindergarten | 1st Floor | 105 | 105 | 996 | 261 | 84 | Y | N | | |
| Regular Classroom | Regular Classroom | 1st Floor | 104 | 104 | 712 | 126 | 54 | Y | N | | |
| Regular Classroom | Regular Classroom | 1st Floor | 108 | 108 | 712 | 126 | 54 | Y | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 712 | 174 | 56 | Y | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 712 | 112 | 48 | Y | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 712 | 174 | 56 | Y | Υ | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 712 | 112 | 48 | Y | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 211 | 211 | 712 | 174 | 56 | Y | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | 212 | 712 | 112 | 48 | Υ | N | | |
| Regular Classroom | Regular Classroom | 2nd Floor | 213 | 213 | 712 | 174 | 56 | Y | N | | |
| Regular Classroom | Regular Classroom | 3rd Floor | 300 | 300 | 712 | 112 | 48 | Υ | N | | |
| Regular Classroom | Regular Classroom | 3rd Floor | 302 | 302 | 712 | 112 | 48 | Υ | N | | |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | 304 | 712 | 112 | 48 | Υ | N | | |
| Regular Classroom | Regular Classroom | 3rd Floor | 305 | 305 | 712 | 174 | 56 | Υ | N | | |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 306 | 712 | 112 | 48 | Υ | N | | |
| Regular Classroom | Regular Classroom | 4th Floor | 309 | 309 | 712 | 174 | 56 | Y | N | | |
| Science Classroom | Science Classroom | 3rd Floor | 308 | 308 | 1,199 | 105 | 42 | Υ | N | | |
| Special Education | Regular Classroom | 2nd Floor | 210 | 210 | 712 | 112 | 48 | Υ | N | | |
| Store Room | Regular Classroom | 2nd Floor | 204 | 204 | 712 | 112 | 48 | Υ | N | | |
| Store Room | Regular Classroom | 2nd Floor | 209 | 209 | 712 | 174 | 56 | Υ | N | | |
| Store Room | Regular Classroom | 3rd Floor | 303 | 303 | 712 | 174 | 56 | Υ | N | | |
| Store Room | Regular Classroom | 3rd Floor | 311 | 311 | 712 | 174 | 56 | Υ | N | | |