



#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1903	3	74,643
Campus Total			74,643

Category: Exterior **Building: Main** Recommend Item - Type Location Quantity **UOM** Rank Replacement Comments Group Entrance Entrance Control - Audio and Video 1 Main S EΑ 7 1 10+ years Exterior Doors - Exterior FRP Door 1 Main S 2 EΑ 7 10+ years Exterior Doors - Transom Lite 1 Main S 2 FΑ 7 10+ years 2 Exterior Doors - Exterior Wood Door FΑ 2 W 6 10+ years 2 Exterior Doors - Transom Lite 2 W EΑ 7 10+ years Exterior Stairs - Concrete 2 W 12 LF 7 10+ years 2 EΑ Exterior Doors - Exterior Wood Door 3 W 6 10+ years 12 1 F Exterior Stairs - Concrete 3 W 7 10+ years Exterior Doors - Exterior Steel Door EΑ 7 4 N 1 10+ years Exterior Doors - Transom Lite 4 N 1 FΑ 7 10+ years 2 EΑ 7 Exterior Doors - Exterior Steel Door 4.5 N 10+ years Exterior Doors - Exterior Wood Door 5 E 2 FΑ 6 10+ years LF Exterior Stairs - Concrete 5 E 4 6 10+ years 7 Entrance Control - Audio 6 E 1 FΑ 10+ years Exterior Doors - Exterior Wood Door 6 E 4 EΑ 6 10+ years Exterior Doors - Transom Lite 6 E 2 EΑ 7 10+ years LF Exterior Stairs - Concrete 6 E 16 4 1-2 years Cracks/pieces missing. Exterior Doors - Exterior Steel Door North Fire Escape 3 EΑ 7 10+ years Exterior Doors - Exterior Steel Door 3 FΑ 7 10+ years West Fire Escape Fire Escape LF 7 Fire Escape **Entire Building** 129 10+ years Fire Escape LF 6 **Entire Building** 98 10+ years



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Foundati							
	Foundation - Masonry	Entire Building	629	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	71,844	SF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	2,799	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	14	EA	6	6-10 years	
Roof Sys	etem						
_ROOF Gys	Chimney - Brick Chimney- Stainless Steel	Low	55	LF	6	10+ years	
	Liner	LOW	00		O	101 years	
	Chimney - Metal Flue	Low	20	LF	6	10+ years	
	Coping - Clay Tile	Low	219	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Low	100	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low	219	LF	6	10+ years	
	Roof - Modified Bitumen	Low	2,799	SF	3	0-1 year	Leakage throughout the low roof
	Roof Structure - Steel with Clay Tile Arch	Low	2,799	SF	7	10+ years	3 3
	Access Ladder - Metal	Main	2	EA	7	10+ years	
	Access Ladder - Wood	Main	1	EA	4	1-2 years	Outdated and not attached properly
	Coping - Stone	Main	140	LF	7	10+ years	,
	Downspouts - Exterior Downspouts	Main	1,235	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main	140	LF	7	10+ years	
	Roof - Asphalt Shingle	Main	10,606	SF	6	10+ years	
	Roof - Modified Bitumen	Main	7,370	SF	5	2-5 years	Cracking.
	Roof Hatch - Metal	Main	2	EA	7	10+ years	•
	Roof Structure - Heavy Timber	Main	17,387	SF	7	10+ years	
Walls							
	Cornice - Masonry Projecting Limestone	Entire Building	78	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	24,660	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,218	SF	5	6-10 years	
	Exterior Walls - Stone-Cut	Entire Building	7,309	SF	6	10+ years	
Windows							
	Guard - Guards perforated	Entire Building	2,021	SF	6	10+ years	
	Lintels - Brick	Entire Building	11	LF	7	10+ years	
	Lintels - Steel	Entire Building	576	LF	7	10+ years	
	Lintels - Stone	Entire Building	343	LF	7	10+ years	
	Windows - Decorative	Entire Building	80	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	7,816	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
J. 5up		_304	Quantity	00111	- taint		



						Replacement	
mergen	cy System					<u>.</u>	
9	Automatic Transfer Switch	Electrical Room	1	EA	7	10+ years	
	Security System - Intrusion Detection	Entire Building	71,844	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	26	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	4	0-1 year	Signs hard to read.
	Exit Signs - Gym	Entire Building	7	EA	7	10+ years	Ç
	Exit Signs - Lunchroom	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	35	EA	7	10+ years	
	Emergency Battery Packs - Gym	Entire Building	7	EA	7	10+ years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	7	10+ years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	7	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,710	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	5,771	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,934	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1,255	SF	6	6-10 years	
ain Ser							
	Main Electrical Service - 1200 A 120/240/3PH	Basement	1	EA	7	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	71,844	SF	4	2-5 years	PA system is over 35 years age.
wer Di	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	1-2 years	Panel is in poor condition and deteriorated
	Lighting and Power Panels - Above 100 A	Entire Building	16	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	4	1-2 years	Panels in poor condition and deteriorated
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	2-5 years	
ategor	y : Fire Protection		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
re Alarr	7.						
	Fire Alarm Panel	Basement	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Basement	74,643	SF	6	6-10 years	
	Fire Alarm_System	Basement	74,643	SF	6	6-10 years	
	Fire Pump Controller	Basement	1	EA	4	0-1 year	Fire pump controller is over 40 year old, is obsolete.



Catego	ry : Fire Protection		В	uilding	: Main		•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Pump - 25-50 hp	Basement	1	EA	4	2-5 years	Pump is over 40 years old.
Sprinkler	System						
	Dry Sprinkler System	Entire Building	74,643	SF	5	6-10 years	
	Sprinkler Heads	Entire Building	74,643	SF	3	0-1 year	A large number of sprinkler heads are painted. Need to be replaced.
	Sprinkler Piping	Entire Building	74,643	SF	4	0-1 year	Leakage of air in fire sprinkler system.
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - Greater than 35000 cfm	Basement	1	EA	5	6-10 years	
	Air Intake	Basement	2	EA	6	6-10 years	
	Auxiliaries - Greater than 35000 cfm	Basement	<u>-</u> 1	EΑ	5	2-5 years	Bypass dampers corroded and coils
	, taranian o	2400	·		ŭ	_ 0 ,00.0	fins bent.
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	100	LF	6	6-10 years	
	Zone Dampers	Basement	38	EA	6	6-10 years	1 actuator has been removed.
Boiler Sy	stems						
Í	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Basement	2	EA	5	6-10 years	
	Chemical Feed System	Basement	1	EA	6	6-10 years	
	Combustion Dampers	Basement	2	EA	6	6-10 years	
	Condensate Pump	Basement	1	EA	6	6-10 years	
	Feed Water Pumps and Tank	Basement	1	EA	6	6-10 years	2 pumps.
	Non Condensing - Fire Tube - Scotch Marine- Steam - Low Pressure Boiler - 76 - 100 HP	Basement	2	EA	5	6-10 years	
	Piping - Condensate Pipe- Steel	Basement	200	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Basement	200	LF	5	6-10 years	
	Steam Traps	Basement	12	EA	5	6-10 years	
Heating [	Devices						
_	Wall Heater - Electric	Basement	4	EA	5	6-10 years	
	Fin Tube - Steam	Basement	100	LF	6	6-10 years	
	Unit Heater - Gas	Boiler Room	2	EA	5	2-5 years	
Tempera	ture Control						
-	Pneumatic System	Entire Building	74,643	SF	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	37	ĒΑ	6	6-10 years	

Campus Name: Hamilton Page : 4 of 21 Assessment Date: 02/17/2020



Categoi	ry : Mechanical		В	uilding	: Main		<del>-</del>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Thermostats - Pneumatic	Entire Building	1	EA	4	0-1 year	No compressed air.
Ventilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	7	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	
Categoi	ry : Plumbing		В	uilding	: Main		
	<del></del>	1				Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR	Basement	1	EA	5	6-10 years	Leak present but water heater installed in 2013.
Piping							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	74,643	SF	6	6-10 years	
	Domestic Piping-Cold Water Risers	Entire Building	74,643	SF	6	6-10 years	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	74,643	SF	6	6-10 years	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	74,643	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Lines	Entire Building	74,643	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	74,643	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	74,643	SF	6	6-10 years	
	Sanitary Piping	Entire Building	74,643	SF	6	6-10 years	
	Storm Piping	Entire Building	74,643	SF	6	6-10 years	
	Vent Piping	Entire Building	74,643	SF	6	6-10 years	
Categoi	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices	405 4 4 9 4 4 4				0.10	
	AC Unit	105 - 1st flr. principal	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	105 - 1st flr. principal	614	SF	6	10+ years	
	Doors - Transom Window	105 - 1st flr. principal	16	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	105 - 1st flr. principal	2	EA	6	6-10 years	
	Floor - Wood	105 - 1st flr. principal	614	SF	6	10+ years	
	Lighting - Pendent/Surface	105 - 1st flr. principal	6	EA	6	6-10 years	
	Power Distribution	105 - 1st flr. principal	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	105 - 1st flr. principal	1,178	SF	6	10+ years	
	AC Unit	Engineer's Office	1	EA	7	6-10 years	
0	Jame: Hamilton	D	age : 5 of 21				Assessment Date: 02/17/20

Campus Name: Hamilton Page : 5 of 21 Assessment Date: 02/17/2020



Catego	ry : Room		В	uilding	: Main		50 W Gomelia Avenge, Gileago, le 60057
<b>.</b>				9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Engineer's Office	392	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	392	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	3	EA	6	6-10 years	
	Power Distribution	Engineer's Office	8	EA	6	10+ years	
	Storage/ Closet	Engineer's Office	16	SF	5	10+ years	
	Walls - Concrete Block	Engineer's Office	224	SF	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	224	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Office	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	6	10+ years	
	Floor - Tile	Kitchen Office	60	SF	6	•	
			1	EA		10+ years	
	Lighting - Pendent/Surface	Kitchen Office			6	6-10 years	
	Power Distribution	Kitchen Office	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	Kitchen Office	260	SF	6	10+ years	
_Gymnas							
	Ceiling - Plaster/Drywall	3rd Flr. Gym	5,771	SF	6	10+ years	Paint chipping and peeling.
	Doors - Transom Window	3rd Flr. Gym	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Flr. Gym	4	EA	6	10+ years	
	Floor - Sport Flooring	3rd Flr. Gym	5,771	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Flr. Gym	24	EA	7	10+ years	
	Lighting - Wall Mounted	3rd Flr. Gym	10	EA	7	10+ years	
	Scoreboards	3rd Flr. Gym	1	EA	7	10+ years	
	Sound System	3rd Flr. Gym	1	ΕA	7	6-10 years	
	Stage	3rd Flr. Gym	1,386	SF	6	10+ years	
	Stage Curtain	3rd Flr. Gym	10	EA	7	6-10 years	
	Stage Lighting System	3rd Fir. Gym	10	EA	7	6-10 years	
	Stage-Stairs - Wood	3rd Fir. Gym	24	LF	7	10+ years	
	Walls - Plaster/Drywall	3rd Fir. Gym	6,363	SF	6	,	
	vvalis - Flaster/Drywali	Sid Fil. Gyili	0,303	SF	0	10+ years	
_Kitchen							
	Ceiling - Plaster/Drywall	Bsmt. / Kitchen	880	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Bsmt. / Kitchen	3	EA	6	10+ years	
	Floor - Tile	Bsmt. / Kitchen	842	SF	6	10+ years	
	Lighting - Pendent/Surface	Bsmt. / Kitchen	18	EA	6	6-10 years	
	Walls - Plaster/Drywall	Bsmt. / Kitchen	1,142	SF	6	10+ years	
_Librarv							
	AC Unit	106 library	2	EA	5	6-10 years	
	Casework	106 library	95	LF	6	6-10 years	
	Ceiling - Lay-in	106 library	1,260	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	106 library	2	EA	6	10+ years	
	Floor - Wood	106 library	1,260	SF	6	10+ years	

Campus Name: Hamilton Page : 6 of 21 Assessment Date: 02/17/2020



Catego	ory : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	106 library	22	EA	6	6-10 years	
	Walls - Plaster/Drywall	106 library	1,562	SF	6	10+ years	
Lunch 8	Multipurpose Room						
	Ceiling - Plaster/Drywall	Basement Lunchroom	1,110	SF	6	10+ years	
	Floor - Tile	Basement Lunchroom	1,150	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement Lunchroom	14	EA	6	6-10 years	
	Serving Line	Basement Lunchroom	16	LF	6	10+ years	
	Walls - Masonry	Basement Lunchroom	1,060	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement Lunchroom	253	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Boy's Playroom	1,934	SF	6	10+ years	
	Floor - Epoxy/ Painted	Boy's Playroom	1,934	SF	7	10+ years	
	Lighting - Pendent/Surface	Boy's Playroom	18	EA	6	6-10 years	
	Walls - Masonry	Boy's Playroom	655	SF	6	10+ years	
	Walls - Plaster/Drywall	Boy's Playroom	184	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	Boy's Playroom	920	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Boy's Playroom #2	880	SF	6	10+ years	
	Floor - Epoxy/ Painted	Boy's Playroom #2	880	SF	7	10+ years	
	Lighting - Pendent/Surface	Boy's Playroom #2	18	EA	6	6-10 years	
	Walls - Masonry	Boy's Playroom #2	571	SF	6	10+ years	
	Walls - Plaster/Drywall	Boy's Playroom #2	571	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Girl's Playroom	1,934	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girl's Playroom	1	EA	6	10+ years	
	Floor - Epoxy/ Painted	Girl's Playroom	1,934	SF	7	10+ years	
	Lighting - Pendent/Surface	Girl's Playroom	18	EA	6	6-10 years	
	Walls - Masonry	Girl's Playroom	655	SF	6	10+ years	
	Walls - Metal Panel	Girl's Playroom	920	SF	6	10+ years	
	Walls - Plaster/Drywall	Girl's Playroom	184	SF	6	10+ years	
_MDF_ID	)F						
	Doors - Steel Doors incl hw	2nd Flr. MDF/IDF	1	EA	6	10+ years	
	Finishes	2nd Flr. MDF/IDF	125	SF	7	10+ years	
	Window AC Unit	2nd Flr. MDF/IDF	1	ĒΑ	7	6-10 years	
Mechan	ical/ Service Rooms						
	Air Intake Plenums	Basement	250	SF	5	10+ years	
	Air Tunnel	Basement	880	SF	5	10+ years	
	Boiler Room	Basement	1,440	SF	5	10+ years	
	Coal Room	Basement	840	SF	5	10+ years	
	Janitor's Closet	Basement	15	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	910	SF	5	10+ years	
	Storage Room	Basement	330	SF	5	10+ years	
	212.232 1100	230	000	٥.	Ŭ	10. 300.0	



Catego	ry : Room		В	uilding	: Main	<u> </u>	550 W Comelia AVENDE, Chicago, ic 60657
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Restroo	m		•			•	
	Accessories	101 Inside	40	SF	5	6-10 years	
	Ceiling - Lay-in	101 Inside	40	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	101 Inside	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	101 Inside	40	SF	6	10+ years	
	Lavatory	101 Inside	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	101 Inside	1	EΑ	6	6-10 years	
	Partitions	101 Inside	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	101 Inside	220	SF	6	10+ years	
	Water Closet	101 Inside	1	ĒΑ	6	10+ years	
	Accessories	105 Toilet	38	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	105 Toilet	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105 Toilet	1	ĒA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	105 Toilet	38	SF	6	10+ years	
	Lavatory	105 Toilet	1	ĒA	6	6-10 years	
	Lighting - Pendent/Surface	105 Toilet	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	105 Toilet	220	SF	6	10+ vears	
	Water Closet	105 Toilet	1	EA	6	10+ years	
	Accessories	1st flr. unisex	38	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st flr. unisex	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr. unisex	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr. unisex	38	SF	6	10+ years	
	Lavatory	1st flr. unisex	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st flr. unisex	1	EA	6	6-10 years	
	Partitions	1st flr. unisex	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st flr. unisex	220	SF	6	10+ years	
	Water Closet	1st flr. unisex	1	EA	6	10+ years	
	Accessories	2nd Floor Staff	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Staff	28	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Staff	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Staff	28	SF	6	10+ years	
	Floor Drain	2nd Floor Staff	1	EA	7	6-10 years	
	Hand Dryer	2nd Floor Staff	1	EA	7	6-10 years	
	Lavatory	2nd Floor Staff	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Staff	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor Staff	230	SF	6	10+ years	
	Water Closet	2nd Floor Staff	1	EA	6	6-10 years	
	Accessories	2nd Flr. Girls	251	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Flr. Girls	251	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr. Girls	251	SF	6	10+ years	
	Floor Drain	2nd Flr. Girls	1	EA	7	10+ years	
	Hand Dryer	2nd Flr. Girls	2	EA	7	6-10 years	
	Lavatory	2nd Flr. Girls	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Flr. Girls	6	EA	6	6-10 years	



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd Flr. Girls	5	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Flr. Girls	730	SF	6	10+ years	
	Water Closet	2nd Flr. Girls	5	EA	6	6-10 years	
	Accessories	2nd flr. Boys	251	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd flr. Boys	251	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd flr. Boys	251	SF	6	10+ years	
	Floor Drain	2nd flr. Boys	1	EA	7	10+ years	
	Hand Dryer	2nd flr. Boys	2	EA	7	6-10 years	
	Lavatory	2nd flr. Boys	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd flr. Boys	6	EA	7	6-10 years	
	Partitions	2nd flr. Boys	2	EA	7	6-10 years	
	Urinals	2nd flr. Boys	5	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd flr. Boys	522	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd flr. Boys	208	SF	6	10+ years	
	Water Closet	2nd flr. Boys	2	EA	6	6-10 years	
	Accessories	Basement Coat Closet Toilet	38	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Basement Coat Closet Toilet	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement Coat Closet Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Coat Closet Toilet	32	SF	6	10+ years	
	Lavatory	Basement Coat Closet Toilet	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement Coat Closet Toilet	1	EA	6	6-10 years	
	Partitions	Basement Coat Closet Toilet	1	EA	7	6-10 years	
	Urinals	Basement Coat Closet Toilet	1	EA	6	10+ years	
	Walls - Concrete Block	Basement Coat Closet Toilet	51	SF	6	10+ years	
	Water Closet	Basement Coat Closet Toilet	1	EA	6	10+ years	
	Accessories	Basement Toilet in Store Room	76	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement Toilet in Store Room	76	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement Toilet in Store Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Toilet in Store Room	76	SF	6	10+ years	
	Lavatory	Basement Toilet in Store Room	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement Toilet in Store Room	1	EA	6	6-10 years	
	Partitions	Basement Toilet in Store Room	2	EA	5	6-10 years	
	Walls - Concrete Block	Basement Toilet in Store Room	281	SF	6	10+ years	
	Water Closet	Basement Toilet in Store Room	2	EA	6	10+ years	
	Accessories	Boiler Room	38	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Boiler Room	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boiler Room	38	SF	6	10+ years	
	Lavatory	Boiler Room	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	6	6-10 years	
	Showers	Boiler Room	1	EA	5	6-10 years	
	Walls - Plaster/Drywall	Boiler Room	192	SF	4	0-1 year	Holes in walls and paint chipping and peeling.
	Water Closet	Boiler Room	1	EA	6	10+ years	

Campus Name: Hamilton Page : 9 of 21 Assessment Date: 02/17/2020



Catego	ategory : Room Building : Main						
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	Bsmt. Boys	396	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Bsmt. Boys	396	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Bsmt. Boys	396	SF	6	10+ years	
	Floor Drain	Bsmt. Boys	2	EA	7	10+ years	
	Hand Dryer	Bsmt. Boys	2	EA	5	6-10 years	
	Lavatory	Bsmt. Boys	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Bsmt. Boys	6	EA	6	6-10 years	
	Partitions	Bsmt. Boys	3	EA	5	6-10 years	
	Urinals	Bsmt. Boys	10	EA	6	6-10 years	
	Walls - Concrete Block	Bsmt. Boys	628	SF	6	10+ years	
	Water Closet	Bsmt. Boys	3	EA	6	10+ years	
	Accessories	Bsmt. Girls	396	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Bsmt. Girls	396	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Bsmt. Girls	396	SF	6	10+ years	
	Floor Drain	Bsmt. Girls	2	EA	7	10+ years	
	Hand Dryer	Bsmt. Girls	2	EΑ	5	6-10 years	
	Lavatory	Bsmt. Girls	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Bsmt. Girls	6	EA	6	6-10 years	
	Partitions	Bsmt. Girls	12	EA	5	6-10 years	
	Walls - Concrete Block	Bsmt. Girls	628	SF	6	10+ years	
	Water Closet	Bsmt. Girls	12	EA	6	10+ years	

Category: Classroom

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #008 (Dance Room)						
	Casework	Basement	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,127	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Wood	Basement	1,127	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	35	EA	6	6-10 years	
	Marker Board	Basement	12	LF	6	6-10 years	
	Storage/ Closet	Basement	75	SF	5	10+ years	
	Wall Mirrors	Basement	15	SF	7	10+ years	
	Walls - Concrete Block	Basement	1,040	SF	5	10+ years	
	Weight/ Fitness Room Floor Matting	Basement	900	SF	6	10+ years	
_Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	10+ years	
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	

**Building: Main** 

Campus Name: Hamilton Page : 10 of 21 Assessment Date: 02/17/2020



Category : Classroom			В	uilding	: Main		
Ţ						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	125	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	6-10 years	
	ŕ					•	
lassroo	m #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	10+ years	
	Walls - Flaster/Drywall	13(1100)	1,212	OI.	O	10+ years	
lassroc	m #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	10+ years	
_	·					•	
lassroc	m #104 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	607	SF	6	10+ years	
	Doors - Transom Window	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	607	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,149	SF	6	6-10 years	
laceroo	m #107 (Regular Classroom)						
11000100	AC Units	1st Floor	1	EA	5	6-10 years	
		1st Floor		SF			
	Ceiling - Lay-in		860		6	6-10 years	
	Doors - Transom Window	1st Floor	28	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	



Category : Classroom			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,336	SF	6	10+ years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall		1,272	SF	6	•	
	walls - Plaster/Drywall	1st Floor	1,272	SF	0	10+ years	
Classroo	m #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	5	6-10 years	
Classroo	om #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	10+ years	
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood Doors Inclu IIW	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	36	LF	6		
	Storage/ Closet	1st Floor	120	SF	_	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	5 6	10+ years 10+ years	
01	77 //OO4 (Daniela Olasana)						
Classroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	



Category : Classroom		В	uilding	: Main		, ,		
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Wood	2nd Floor	871	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	36	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	175	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years		
Classroo	m #202 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years		
	Floor - Wood	2nd Floor	871	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	16	ĒΑ	7	6-10 years		
	Marker Board	2nd Floor	75	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	175	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years		
	Traile Tractor, 21, Trail		.,	О.	· ·	.o. you.o		
Classroo	m #203 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	863	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage.	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Floor - Wood	2nd Floor	871	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years		
	Marker Board	2nd Floor	75	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	175	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years		
_Classroo	m #204 (Science)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	1,171	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	1,155	SF	4	0-1 year	Water damage.	
	Doors - Transom Window	2nd Floor	42	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years		
	Floor - Wood	2nd Floor	1,171	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years		
	Marker Board	2nd Floor	62	LF	6	6-10 years		
	Storage/ Closet	2nd Floor	175	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,682	SF	6	10+ years		
	·		.,002	٥.	ŭ	,		
_Classroo	m #205 (Art Room)							

Campus Name: Hamilton Page : 13 of 21 Assessment Date: 02/17/2020



Catego	Category : Classroom		В	Building : Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	860	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	50	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,336	SF	6	10+ years	
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor 2nd Floor	607	SF	6	10+ years	
	Doors - Transom Window	2nd Floor		SF	6	-	
			9			10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	607	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,149	SF	6	10+ years	
Classroo	om #207 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	858	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2	SF	4	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	10+ years	S
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	6	6-10 years	
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,336	SF	6	10+ years	
Classroo	om #208 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years 10+ years	
			1	EA	6		
	Doors - Wood Doors inclu hw	2nd Floor				10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board Storage/ Closet	2nd Floor 2nd Floor	75 50	LF SF	7 7	6-10 years	
		2nd Lloor	EO	C.L	7	10+ years	



Catego	Category : Classroom		В	uilding		W Comelia Avervoe, Chicago, le 00057	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	
Classro	om #209 (Regular Classroom)						
Classion	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Chalk Board	2nd Floor 2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor 2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
		2nd Floor		SF		•	
	Floor - Wood	2nd Floor 2nd Floor	871		6 7	10+ years	
	Lighting - Pendent/Surface		16	EA LF		6-10 years	
	Marker Board	2nd Floor	24		7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	75	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	
Classro	om #301 (Regular Classroom)						
Classion	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	863	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage.
	Doors - Transom Window	3rd Floor	9	SF	6	•	water damage.
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years 10+ years	
			•	SF	6	10+ years	
	Floor - Wood Lighting - Pendent/Surface	3rd Floor 3rd Floor	871 14	Sr EA	6	6-10 years	
				LF	-		
	Marker Board	3rd Floor	40		6	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	10+ years	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	867	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	4	SF	4	0-1 year	Water damage.
	Chalk Board	3rd Floor	20	LF	4	2-5 years	-
	Doors - Wood Doors inclu hw	3rd Floor	9	EA	6	10+ years	



Catego	Category : Classroom		В	uilding	: Main		50 W Comelia Avenue, Chicago, il 60657
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	58	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	10+ years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	871	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	855	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	16	SF	4	0-1 year	Water damage.
	Doors - Steel Doors incl hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	10+ years	
Classroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	847	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	24	SF	4	0-1 year	Water damage.
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	-
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	28	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	10+ years	
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
		-				<b>,</b>	



Catego	ry : Classroom		В	Building : Main					
_				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	3rd Floor	863	SF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage.		
	Doors - Steel Doors incl hw	3rd Floor	1	EA	6	10+ years	-		
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years			
	Floor - Wood	3rd Floor	871	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years			
	Marker Board	3rd Floor	36	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	175	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	10+ years			

Category : Interior **Building: Main** 

							Recommend	
Group	Item - Type	Location	Quanti	ty	UOM	Rank	Replacement	Comments
Corridor								
	Ceiling - Lay-in	1st Floor	2,8	24	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor		4	EA	5	10+ years	
	Floor - Asphalt Floor	1st Floor	2,7	35	SF	6	10+ years	
	Lighting - Lay-in	1st Floor		34	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	5,7	44	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2,7	20	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor		2	EA	7	10+ years	
	Floor - Asphalt Floor	2nd Floor	2,7	20	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor		26	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,5	76	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,4	00	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor		4	EA	7	10+ years	
	Floor - Asphalt Floor	3rd Floor	1,4	00	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor		18	EA	6	6-10 years	
	Student Lockers - Two Tiers	3rd Floor		75	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,6	99	SF	6	10+ years	
	Ceiling - Lay-in	Basement		41	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	3,4	78	SF	6	10+ years	
	Ceiling - Splined	Basement		84	SF	6	10+ years	
	Doors - Side-lite	Basement		24	SF	6	10+ years	
	Doors - Transom Window	Basement		48	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement		8	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	3,1	25	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement		84	SF	6	10+ years	
	Floor - Wood	Basement	3	94	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement		10	EA	6	6-10 years	
	Stairs - Wood	Basement		12	LF	6	10+ years	
	Walls - Masonry	Basement	1,5		SF	6	10+ years	
	Walls - Masonry	Basement		00	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	1,1	98	SF	6	10+ years	



Catego	ry : Interior		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	Basement	20	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement	439	SF	6	10+ years	
Safety							
•	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	1	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	East stairs	75	SF	6	10+ years	
	Floor - Asphalt	East stairs	84	SF	6	10+ years	
	Handrails	East stairs	169	LF	7	10+ years	
	Lighting - Chandelier, Incandescent	East stairs	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	East stairs	3	EA	6	6-10 years	
	Stairs - Asphalt	East stairs	84	LF	6	10+ years	
	Walls - Plaster/Drywall	East stairs	140	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	75	SF	6	10+ years	
	Floor - Asphalt	South	84	SF	6	10+ years	
	Handrails	South	72	LF	7	10+ years	
	Lighting - Wall Mounted	South	2	EA	7	6-10 years	
	Stairs - Asphalt	South	18	LF	6	10+ years	
	Walls - Plaster/Drywall	South	140	SF	6	10+ years	
	Ceiling - Lay-in	West stairs	75	SF	6	10+ years	
	Floor - Asphalt	West stairs	84	SF	6	10+ years	
	Handrails	West stairs	169	LF	7	10+ years	
	Lighting - Chandelier, Incandescent	West stairs	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	West stairs	3	EA	6	6-10 years	
	Stairs - Asphalt	West stairs	84	LF	6	10+ years	
	Walls - Plaster/Drywall	West stairs	140	SF	6	10+ years	





Category : Site **Building: Site** 

	Calego	ry . Site		B	unung	. Site		
Civil/Drainage - Site Manhole   Entire Site   5 EA 7 10+ years	_						Recommend	
Encling   Fancing   Chain Link   Entire Site   S EA 7   10+ years		<del>-</del>	Location	Quantity	UOM	Rank	Replacement	Comments
Fencing - Chain Link	Civil/Dra							
Fencing - Chain Link		Civil/ Drainage - Site Manhole	Entire Site	5	EA	7	10+ years	
Fencing - Chain Link		•					•	
Fencing - Chain Link	Fencina							
Fencing - New Standard Ornamental   Entire Site   250 LF   6 10+ years		Fencing - Chain Link	Entire Site	370	1 F	6	10± vears	
Fencing - Wood Fencing w/ Steel Frame						-		
Benches								
Benches		rending - wood rending w oteer rame	Littlie Oite	250	LI	U	10+ years	
Benches	Londooo	20						
Landscape - Grass	Landsca							
Landscape - Hardscape- Asphalt								
Landscape - Hardscape- Concrete   Entire Site   513   SF   7   10+ years								
Landscape - Hardscape - Pavers								
Parkway trees								
Planting Beds/ Area								
Play Area - Asphalt/ Hardscape						· ·		
Play Area - Synthetic Turf Play Field   Entire Site   4,080   SF   7   10+ years						-		
Refaining Wall - Masonry   Entire Site   201   SF   7   10+ years								
Parking   Lot								
Parking Lot								
Pavers		Trash Receptacles	Entire Site	2	EA	7	10+ years	
Pavers	Parking I	ot						
Surface - Asphalt North 17,365 SF 7 10+ years Surface - Asphalt North 100 SF 5 1-2 years Draining issues on the entrance part Trash Enclosure - Chain Links North 1,058 SF 7 10+ years  Playground  Equipment - School Age 5-12 NE 1 EA 7 10+ years Surface - Poured Surface NE 1,188 SF 7 10+ years Equipment - Pre K 3-5 South east 1 EA 7 10+ years Surface - Poured Surface South east 1,800 SF 7 10+ years Surface - Poured Surface South east 1,800 SF 7 10+ years Surface - Poured Surface South east 1,800 SF 7 10+ years  Sidewalks  Sidewalks - Perimeter Sidewalks Entire Site 12,006 SF 7 10+ years  Marquee - Free Standing Back Lighted Site SE 1 EA 7 10+ years Marquee - Free Standing Back Lighted Site SE 1 EA 7 10+ years Monument - Building Mounted Cut Letter Site SE 1 EA 7 10+ years	<del> </del>		North	1 096	SF	7	10+ vears	
Surface - Asphalt								
Playground								Draining issues on the entrance pad
Playground   Equipment - School Age 5-12   NE								Draining looded on the ontrailed pad
Equipment - School Age 5-12 NE 1 EA 7 10+ years Surface - Poured Surface NE 1,188 SF 7 10+ years Equipment - Pre K 3-5 South east 1 EA 7 10+ years Surface - Poured Surface South east 1,800 SF 7 10+ years Sidewalks - Perimeter Sidewalks Entire Site 12,006 SF 7 10+ years  Signage  Flag Pole - Flag Pole Site SE 1 EA 7 10+ years Marquee - Free Standing Back Lighted Site SE 1 EA 7 10+ years Monument - Building Mounted Cut Letter Site SE 1 EA 7 10+ years		Tradit Endodate Chain Entre	140141	1,000	O.	•	101 youro	
Surface - Poured Surface Equipment - Pre K 3-5 Surface - Poured Surface Surface - Poured Surface South east Surface - Poured Surface South east Sidewalks  Sidewalks - Perimeter Sidewalks Entire Site  12,006 SF 7 10+ years	Playgrou	nd						
Surface - Poured Surface Equipment - Pre K 3-5 Surface - Poured Surface Surface - Poured Surface South east Surface - Poured Surface South east Sidewalks  Sidewalks - Perimeter Sidewalks Entire Site 12,006 SF 7 10+ years		Equipment - School Age 5-12	NE	1	EA	7	10+ years	
Equipment - Pre K 3-5 South east 1 EA 7 10+ years Surface - Poured Surface South east 1,800 SF 7 10+ years  Sidewalks  Sidewalks - Perimeter Sidewalks Entire Site 12,006 SF 7 10+ years  Flag Pole - Flag Pole Site SE 1 EA 7 10+ years Marquee - Free Standing Back Lighted Site SE 1 EA 7 10+ years Monument - Building Mounted Cut Letter Site SE 1 EA 7 10+ years		Surface - Poured Surface	NE	1,188	SF	7		
Sidewalks Sidewalks - Perimeter Sidewalks Entire Site  12,006 SF 7 10+ years  Signage  Flag Pole - Flag Pole Marquee - Free Standing Back Lighted Monument - Building Mounted Cut Letter Site SE 1 EA 7 10+ years		Equipment - Pre K 3-5	South east		EA	7		
Sidewalks Sidewalks - Perimeter Sidewalks Entire Site  12,006 SF 7 10+ years  Signage  Flag Pole - Flag Pole Marquee - Free Standing Back Lighted Monument - Building Mounted Cut Letter Site SE 1 EA 7 10+ years		Surface - Poured Surface	South east	1,800	SF	7	10+ years	
Signage  Flag Pole - Flag Pole Marquee - Free Standing Back Lighted Monument - Building Mounted Cut Letter  Site SE  12,006  SF  7  10+ years							·	
Signage  Flag Pole - Flag Pole Marquee - Free Standing Back Lighted Monument - Building Mounted Cut Letter Site SE  1 EA 7 10+ years 1 EA 7 10+ years 1 EA 7 10+ years	Sidewalk	S						
Signage  Flag Pole - Flag Pole Marquee - Free Standing Back Lighted Monument - Building Mounted Cut Letter Site SE  1 EA 7 10+ years 1 EA 7 10+ years 1 EA 7 10+ years		Sidewalks - Perimeter Sidewalks	Entire Site	12,006	SF	7	10+ years	
Flag Pole - Flag Pole Site SE 1 EA 7 10+ years  Marquee - Free Standing Back Lighted Site SE 1 EA 7 10+ years  Monument - Building Mounted Cut Letter Site SE 1 EA 7 10+ years				,			, , , , , ,	
Marquee - Free Standing Back Lighted Site SE 1 EA 7 10+ years  Monument - Building Mounted Cut Letter Site SE 1 EA 7 10+ years	Signage							
Monument - Building Mounted Cut Letter Site SE 1 EA 7 10+ years				1				
				1		7	10+ years	
		Monument - Building Mounted Cut Letter	Site SE	1	EA	7	10+ years	
							-	

Campus Name: Hamilton Page : 19 of 21 Assessment Date: 02/17/2020



### **Alexander Hamilton Elementary School**

1650 W Cornelia AVENUE, Chicago, IL 60657

Category : Site Building : Site

Recommend
Group Item - Type Location Quantity UOM Rank Replacement Comments

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Hamilton Page: 20 of 21 Assessment Date: 02/17/2020



**Classroom Summary** 

Olassi com Gammary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	•	•	•						•
Art Room	Regular Classroom	2nd Floor	205	205	860	118	64	N	N
Computer Lab	Regular Classroom	2nd Floor	208	208	871	177	80	N	Υ
Dance Room	Regular Classroom	Basement	800	800	1,127	88	35	N	N
Music Room	Regular Classroom	2nd Floor	207	207	860	118	64	N	Υ
Regular Classroom	Multi Purpose Room	2nd Floor	206	206	607	80	40	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	871	189	94	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	871	118	80	N	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	871	177	80	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	607	80	40	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	860	118	64	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	871	177	80	N	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	871	118	80	N	Υ
Regular Classroom	Regular Classroom	1st Floor	110	110	871	177	80	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	871	189	94	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	871	118	80	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	871	177	80	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	871	118	80	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	871	177	80	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	871	150	60	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	302	302	871	118	80	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	303	871	177	80	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	308	308	871	177	80	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	309	309	871	118	80	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	310	310	871	177	80	N	Υ
Science	Regular Classroom	2nd Floor	204	204	1,171	120	60	N	N