

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1905	3	54,868
Annex	1960	3	25,716
Campus Total			80,584

Catego	ry : Exterior	В	Building : Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	#2 - W	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	#2 - W	3	EA	7	10+ years	
	Exterior Stairs - Concrete	#2 - W	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2 - W	20	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#3 - W	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	#3 - W	3	EA	7	10+ years	
	Exterior Stairs - Concrete	#3 - W	40	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4 - SW	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	#4 - SW	3	EA	7	10+ years	
	Exterior Stairs - Concrete	#4 - SW	40	LF	6	10+ years	
	Entrance Control - Audio and Video	#5 - S	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#5 - S	2	EA	6	10+ years	
	Power Door Operator and Controls	#5 - S	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#6 - SE	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 - SE	5	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7 - E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 - E	5	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#8 - Boiler Room - E	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	#9 - E	2	EA	7	10+ years	
Fire Esca	ape						
	Fire Escape	Auditorium	27	LF	6	10+ years	
	Fire Escape	Auditorium	27	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
Crou-	Itom Type	Location	Ouantitu	UOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oundati	on						
	Foundation - Masonry	Entire Building	750	LF	7	10+ years	
	Foundation - Masonry	Entire Building	30	LF	5	2-5 years	
	Superstructure - Heavy Timber	Entire Building	54,868	SF	7	10+ years	
ighting	Estarion Limbting Mounted	Fatina Duildina	7			40	
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	1-2 years	
Roof Sys	stem						
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Low E Roof	65	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Low E Roof	25	LF	4	2-5 years	
	Coping - Stone	Low E Roof	188	LF	5	10+ years	
	Downspouts - Exterior Downspouts	Low E Roof	14	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low E Roof	20	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Low E Roof	168	LF	6	10+ years	
	Roof - Modified Bitumen	Low E Roof	1,880	SF	5	2-5 years	recent roof assessment and planne replacement
	Roof Structure - Steel with Clay Tile Arch	Low E Roof	1,880	SF	7	10+ years	ropidooment
	Coping - Metal	Low N Roof	18	ĹF	6	6-10 years	
	Coping - Stone	Low N Roof	17	LF	5	10+ years	
	Downspouts - Exterior Downspouts	Low N Roof	11	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low N Roof	17	LF	6	10+ years	
	Roof - Modified Bitumen	Low N Roof	315	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Low N Roof	315	SF	7	10+ years	
	Coping - Metal	Low NE Roof	38	LF	6	6-10 years	
	Coping - Stone	Low NE Roof	60	LF	5	10+ years	
	Downspouts - Exterior Downspouts	Low NE Roof	11	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Low NE Roof	60	LF	6	10+ years	
	Roof - Modified Bitumen	Low NE Roof	1,240	SF	5	2-5 years	recent roof assessment and planne
	Deat Otherstone Otes Little Cl. Till A. I.	Law NE Daa/	4.040	0.5	-	•	repair
	Roof Structure - Steel with Clay Tile Arch	Low NE Roof	1,240	SF	7	10+ years	
	Coping - Clay Tile	Low SE Roof	15	LF	5	10+ years	
	Coping - Stone	Low SE Roof	115	LF	5	10+ years	
	Downspouts - Exterior Downspouts	Low SE Roof	11	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Low SE Roof	130	LF	7	10+ years	recent parapet repair
	Roof - Modified Bitumen	Low SE Roof	1,030	SF	5	2-5 years	recent roof assessment and planne replacement
	Roof Structure - Steel with Clay Tile Arch	Low SE Roof	1,030	SF	7	10+ years	•
	Coping - Terra Cotta	Low W Roof	23	ĹF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Exterior Downspouts	Low W Roof	28	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low W Roof	16	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Low W Roof	7	LF	6	10+ years	
	Roof - Modified Bitumen	Low W Roof	90	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Low W Roof	90	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	2	EA	7	10+ years	
	Coping - Clay Tile	Main Roof	350	LF	5	10+ years	
	Coping - Stone	Main Roof	153	LF	5	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	195	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	70	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Main Roof	120	LF	6	10+ years	
	Parapet - Parapet > 30"	Main Roof	313	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	9,542	SF	5	2-5 years	recent roof assessment and planned replacement
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	replacement
	Roof Structure - Steel with Clay Tile Arch	Main Roof	9,542	SF	7	10+ years	
	Coping - Clay Tile	Upper Roof	246	LF	5	10+ years	
	Downspouts - Exterior Downspouts	Upper Roof	138	LF	6	10+ years	
	Parapet - 16" - 30" Height	Upper Roof	40	LF	7	10+ years	recent parapet repair
	Parapet - Parapet < 16" Height	Upper Roof	206	LF	6	10+ years	recent parapet repair
	Roof - Modified Bitumen	Upper Roof	3,755	SF	5		recent reef accessment and planned
		• •				2-5 years	recent roof assessment and planned replacement
	Roof Structure - Steel with Clay Tile Arch	Upper Roof	3,755	SF	7	10+ years	
Walls							
	Cornice - Masonry Projecting Limestone	Entire Building	450	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	29,523	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	545	SF	5	2-5 years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	162	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	900	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	14	SF	5	2-5 years	
	Exterior Walls - Stone-Cut	Entire Building	915	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	365	SF	5	2-5 years	
Windows	3						
	Guard - Guards perforated	Entire Building	89	SF	6	10+ years	
	Lintels - Brick	Entire Building	30	LF	6	10+ years	
	Lintels - Steel	Entire Building	347	LF	6	10+ years	
	Lintels - Stone	Entire Building	181	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,646	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
	717-						



					Replacement	
Emergency System						
Automatic Transfer Switch	Basement	3	EA	6	10+ years	
Emergency A/C Power - Auditoium and	Entire Building	3,770	SF	6	6-10 years	
Aisle Lighting	ŭ	,			,	
Emergency A/C Power - Corridors and	Entire Building	9,532	SF	6	6-10 years	
Stairs	•				•	
Emergency A/C Power - Gym	Entire Building	3,800	SF	6	6-10 years	
Emergency A/C Power - Lunchrooms	Entire Building	3,378	SF	6	6-10 years	
Emergency A/C Power - Students Toilets	Entire Building	1,689	SF	6	6-10 years	
Emergency Battery Packs - Auditoium and	Entire Building	4	EA	6	6-10 years	
Aisle Lighting						
Emergency Battery Packs - Corridors and	Entire Building	7	EA	6	6-10 years	
Stairs						
Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
Exit Signs - Auditoium	Entire Building	7	EA	5	1-2 years	2 fire escape exit signs need to be
						replaced in the auditorium. Signage
						unclear
Exit Signs - Corridors and Stairs	Entire Building	13	EA	6	6-10 years	
Exit Signs - Gym	Entire Building	4	EA	4	1-2 years	One of the exit signs has the metal
F '(0' )	E (		_ ^	•	0.40	wire guard hanging loose.
Exit Signs - Lunchroom	Entire Building	3	EA	6	6-10 years	
Security System - CCTV	Entire Building	54,862	SF	6	6-10 years	
Security System - Intrusion Detection	Entire Building	54,862	SF	6	6-10 years	
Emergency Generator- Outdoor- Natural	Exterior - Central Courtyard	1	EA	6	6-10 years	
Gas - 101 - 150 KW						
Main Service						
Main Electrical Service - 1200 A	Electrical Room	1	EA	6	6-10 years	
120/208/3PH	Licotriodi (toom	•		Ü	o ro youro	
Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	
emergency power	Liberioa i reem	·	_, `	Ü	o io youro	
PA System	Entire Building	54,862	SF	6	6-10 years	
Gyddani	g	0 .,00=	О.	Ū	0 .0 you.0	
Power Distribution						
Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
Lighting and Power Panels - 100 A	Entire Building	4	EA	6	6-10 years	
Lighting and Power Panels - 100 A	Entire Building	1	EA	4	2-5 years	"LP-GYM" Poor condition
Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	



ALL A	SCHOOIS					75	527 S Harvard AVENUE, Chicago, IL 60620
						Replacement	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
	·	· ·				•	
Catego	ry : Fire Protection		В	uilding	: Main		
o allege	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
	· · · · · · · · · · · · · · · · · · ·	2004	Quantity	00	rtariit	rtopiacomont	
_Fire Alar		EL (: IB				0.5	
	Fire Alarm Panel	Electrical Room	1	EA	6	2-5 years	
	Fire Alarm Strobe Lights	Electrical Room	54,868	SF	6	2-5 years	
	Fire Alarm_System	Electrical Room	54,868	SF	5	2-5 years	
			_				
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Hand	lling Systems						
	Air Handling Unit- Built Up-Multi Zone-	Boiler Room	1	EA	5	2-5 years	
	Double Delivery- Steam Coils - 30001 -		•	== =	-	- ,	
	45000 cfm						
	Air Intake	Boiler Room	1	EA	5	2-5 years	
	Auxiliaries - 30001 - 45000 cfm	Boiler Room	1	ĒΑ	5	2-5 years	
	Return Duct Work - Indoor- Vertical Shaft	Boiler Room	100	LF	5	2-5 years	
	and Ducts				•	,	
	Zone Dampers	Boiler Room	30	EA	5	2-5 years	Dampers need to be manually
	20110 2 apo.to	20		_, ,	Ū	_ 0 ,00.0	operated and show signs of aging
	Air Handling Unit- Built Up-Multi Zone-	Boiler Room	1	EA	5	2-5 years	op comment and control or againg
	Steam Coils - 15001 - 25000 cfm		•		•	,	
	Air Intake	Boiler Room	1	EA	5	2-5 years	
	Auxiliaries - 15001 - 25000 cfm	Boiler Room	1	ΕA	5	2-5 years	
	Return Duct Work - Indoor- Vertical Shaft	Boiler Room	100	LF	5	2-5 years	
	and Ducts	20			Ū	_ 0 ,00.0	
	Zone Dampers	Boiler Room	2	EA	5	2-5 years	
	Zono Bamporo	Bollot 1100III	-	_/ \	· ·	2 o youro	
Boiler Sv	votomo						
_boller Sy		Deiler Deem	2	ΕΛ		0.40.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Tub as were replaced for one of the
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	6	6-10 years	Tubes were replaced for one of the
	Pressure Boiler - 76 - 100 HP	Dailer Dann	4	_^	_	0.40	boilers
	Chemical Feed System	Boiler Room	1	EA	5	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	5	6-10 years	The object of the distriction
	Combustion Dampers	Boiler Room	3	EA	5	6-10 years	The photos provided by the
	Orandon anto Burea	Daile a Daare	•	_^	-	0.40	accessors are not very clear.
	Condensate Pump	Boiler Room	2	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	2	EA	6	6-10 years	
	Steam- Low Pressure Boiler - 76 - 100 HP	D 11 D			_	0.40	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	6-10 years	
	Steam Traps	Boiler Room	24	EA	6	6-10 years	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
I4 F							
teat Exc	Changers Steam to Het Weter Shell	Boiler Room	1	ГΛ	5	6.10 voore	Inaulation from the hot water nining
	Heat Exchanger - Steam to Hot Water Shell Type	Bollet Room	'	EA	5	6-10 years	Insulation from the hot water piping missing.
leating I	Devices						
•	Unit Heater - Gas	Boiler Room	1	EA	4	2-5 years	
	Wall Heater - Electric	Entire Building	5	EA	5	6-10 years	
	Fin Tube - Electric	Entire Building	90	LF	6	6-10 years	
empera	ture Control						
·	Pneumatic System	Entire Building	54,868	SF	4	1-2 years	The Older Pnematic system does n work effectively
	Thermostats - Pneumatic	Entire Building	28	EA	5	2-5 years	,
	Thermostats - Pneumatic	Entire Building	2	EA	4	0-1 year	Thermostats in Room 302,204 need to be replaced.
/entilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Kitchen, Elevator Machine Room, Roof	1	EA	4	2-5 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Kitchen, Elevator Machine Room, Roof	1	EA	4	2-5 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Kitchen, Elevator Machine Room, Roof	2	EA	4	2-5 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Kitchen, Elevator Machine Room, Roof	2	EA	4	6-10 years	Fan Covers are missing. Belts need to be changed and serviced
Catego	ry : Plumbing		В	uilding	: Main		
Group  Hot Wate	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ioi wate	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Dated 1992
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	1	EA	4	0-1 year	Storage Tank Leaks and needs to I replaced
Piping							
19	Domestic Piping-Cold Water Horizontal Lines	Entire Building	54,868	SF	4	2-5 years	Old, galvanized
	Domestic Piping-Cold Water Risers	Entire Building	54,868	SF	4	2-5 years	Old, galvanized
	Domestic Piping-Cold Water from Risers to	Entire Building	54,868	SF	6	6-10 years	-
	Fixtures	Entire Building		SF			



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Lines	Entire Building	54,868	SF	4	6-10 years	Old, galvanized
	Domestic Piping-Hot Water Return Risers	Entire Building	54,868	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	54,868	SF	6	6-10 years	
	Fixtures	· ·				•	
	Sanitary Piping	Entire Building	54,868	SF	6	6-10 years	
	Storm Piping	Entire Building	54,868	SF	6	6-10 years	
	Vent Piping	Entire Building	54,868	SF	6	6-10 years	
Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Boiler Room and Basement	1	EA	5	6-10 years	
	Pumps - Ejector-Simplex	Boiler Room and Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Boiler Room and Basement	1	EA	6	6-10 years	

Category: Room **Building: Main** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Adminis	trative Suites/Offices						
	AC Unit	1st Floor-Principal's Office-Room 100	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Principal's Office-Room 100	296	SF	6	6-10 years	
	Doors - Transom Window	1st Floor-Principal's Office-Room 100	3	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office-Room 100	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Principal's Office-Room 100	296	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Principal's Office-Room 100	2	EA	7	6-10 years	
	Power Distribution	1st Floor-Principal's Office-Room 100	8	EA	6	6-10 years	
	Storage/ Closet	1st Floor-Principal's Office-Room 100	30	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Principal's Office-Room 100	650	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Engineer's Office	298	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement-Engineer's Office	2	EA	6	10+ years	
	Floor - Tile	Basement-Engineer's Office	298	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement-Engineer's Office	3	EA	7	6-10 years	
	Power Distribution	Basement-Engineer's Office	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement-Engineer's Office	560	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Kitchen Office-B13	155	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement-Kitchen Office-B13	1	EA	6	10+ years	
	Floor - Tile	Basement-Kitchen Office-B13	155	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Basement-Kitchen Office-B13	1	EΑ	7	6-10 years	
	Power Distribution	Basement-Kitchen Office-B13	4	EA	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Basement-Kitchen Office-B13	408	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Teacher's Lounge	855	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement-Teacher's Lounge	2	EA	6	10+ years	
	Floor - Tile	Basement-Teacher's Lounge	855	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement-Teacher's Lounge	5	ĒΑ	7	6-10 years	
	Storage/ Closet	Basement-Teacher's Lounge	16	SF	7	6-10 years	
	Walls - Masonry	Basement-Teacher's Lounge	864	SF	6	10+ years	
Auditoriu	um & Theater						
	Balcony Seating	1st Floor	54	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	730	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	3,770	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	5,770	EA	6	10+ years	
	Floor - Carpet	1st Floor	1,885	SF	6	6-10 years	
	Floor - Tile	1st Floor	230	SF	6	10+ years	
	Floor - Wood	1st Floor	2,385	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	2,303	EA	7	6-10 years	
	Lighting - Lay-iii Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Lighting - Pendent/Surface  Lighting - Wall Mounted	1st Floor	5	EA	6	6-10 years	
	Main Floor Seating	1st Floor	250	EA	7	6-10 years	
	Stage	1st Floor	762	SF	6	•	
		1st Floor	762	EA	7	6-10 years	
	Stage Curtain	1st Floor	1	EA	7 7	6-10 years	
	Stage Lighting System		1	EA	7	6-10 years	
	Stage Lighting System	1st Floor 1st Floor	10	LF	, 6	6-10 years	
	Stage-Stairs - Wood	1st Floor	-	SF	_	6-10 years	
	Storage/ Closet		128		7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	7,595	SF	6	10+ years	
Gymnas		0.151				0.40	
	Ceiling - Plaster/Drywall	3rd Floor	3,800	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	3,800	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	3rd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	3,828	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,642	SF	6	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	Basement	471	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	471	SF	6	10+ years	
		2300	.,,	<b>.</b>	Ŭ	, 50	



Catego	ry : Room		В	uilding	: Main				
	_					Recommend	_		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	Basement	6	EA	7	6-10 years			
	Walls - Concrete Block	Basement	180	SF	6	10+ years			
	Walls - Masonry	Basement	180	SF	6	10+ years			
	Walls - Plaster/Drywall	Basement	360	SF	6	10+ years			
Lunch &	Multipurpose Room								
	Ceiling - Plaster/Drywall	Basement-Lunchroom A	1,113	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	Basement-Lunchroom A	3	ĒΑ	6	10+ years			
	Floor - Tile	Basement-Lunchroom A	1,113	SF	6	10+ years			
	Lighting - Pendent/Surface	Basement-Lunchroom A	13	EA	7	6-10 years			
	Serving Line	Basement-Lunchroom A	10	LF	6	6-10 years			
	Walls - Masonry	Basement-Lunchroom A	678	SF	6	10+ years			
	Walls - Vinyl Coated Gypsum Panel	Basement-Lunchroom A	555	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Basement-Lunchroom B	1,113	SF	6	6-10 years			
	Doors - Wood Doors inclu hw			EA	6	-			
		Basement-Lunchroom B	2	SF		10+ years			
	Floor - Tile	Basement-Lunchroom B	1,113		6	10+ years			
	Lighting - Pendent/Surface	Basement-Lunchroom B	14	EA	7	6-10 years			
	Market Board	Basement-Lunchroom B	20	LF	7	6-10 years			
	Storage/ Closet	Basement-Lunchroom B	33	SF	7	6-10 years			
	Walls - Plaster/Drywall	Basement-Lunchroom B	1,233	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Basement-Servery B02	1,152	SF	6	10+ years			
	Floor - Tile	Basement-Servery B02	1,152	SF	6	10+ years			
	Lighting - Pendent/Surface	Basement-Servery B02	6	EA	7	6-10 years			
	Serving Line	Basement-Servery B02	10	LF	6	6-10 years			
	Walls - Masonry	Basement-Servery B02	630	SF	6	10+ years			
	Walls - Plaster/Drywall	Basement-Servery B02	630	SF	6	10+ years			
MDF ID	F								
_	Doors - Steel Doors incl hw	Room 104A	1	EA	6	10+ years			
	Finishes	Room 104A	158	SF	7	10+ years			
	Window AC Unit	Room 104A	1	ĒΑ	7	6-10 years			
Mechani	cal/ Service Rooms								
	Janitor's Closet	3rd floor-Janitor's closet	25	SF	5	6-10 years			
	Air Intake Plenums	Basement	46	SF	5	6-10 years			
	Air Intake Plenums	Basement	411	SF	5	6-10 years			
	Air Tunnel	Basement	45	SF	5	6-10 years			
	Boiler Room	Basement	1,654	SF	5	6-10 years			
	Coal Room	Basement	443	SF	5	6-10 years			
	Mechanical/ Service Rooms	Basement	10	SF	5 5	6-10 years			
	Mechanical/ Service Rooms	Basement	52	SF	5 5	6-10 years			
				SF SF					
	Mechanical/ Service Rooms	Basement	411	SF SF	5	6-10 years			
	Mechanical/ Service Rooms	Basement	86	2F	5	6-10 years			



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Mechanical/ Service Rooms	Basement	940	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement	65	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement	600	SF	5	6-10 years	
	Storage Room	Basement	662	SF	5	6-10 years	
	Vaults	Basement	95	SF	5	10+ years	
	Janitor's Closet	Janitor's Closet	25	SF	5	6-10 years	
Restroon	n						
	Accessories	1st Floor-Principal's Office Restroom	29	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Principal's Office Restroom	29	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office Restroom	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Principal's Office Restroom	29	SF	6	10+ years	
	Lavatory	1st Floor-Principal's Office Restroom	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Principal's Office Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Principal's Office Restroom	110	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor-Principal's Office Restroom	110	SF	6	10+ years	
	Water Closet	1st Floor-Principal's Office Restroom	1	EA	6	6-10 years	
	Accessories	2nd Floor	230	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	230	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	230	SF	6	10+ years	
	Hand Dryer	2nd Floor	230	EA	7	6-10 years	
		2nd Floor	2	EA	6		
	Lavatory	2nd Floor	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	4	EA		6-10 years	
	Partitions Walls - Plaster/Drywall	2nd Floor 2nd Floor	241	SF	7 6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	725	SF		10+ years	
					6	10+ years	
	Water Closet	2nd Floor	4	EA SF	6	6-10 years	
	Accessories	2nd Floor	230		5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	230	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	230	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EΑ	7	6-10 years	
	Hand Dryer	2nd Floor	1	EΑ	7	6-10 years	
	Lavatory	2nd Floor	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	6-10 years	
	Partitions	2nd Floor	2	EA	5	6-10 years	
	Urinals	2nd Floor	2	EA	6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	966	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	6	6-10 years	
	Accessories	Basement	718	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	718	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Basement	718	SF	6	10+ years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Hand Dryer	Basement	1	EA	7	6-10 years	
	Lavatory	Basement	5	EA	6	6-10 years	

Campus Name: Harvard Page : 10 of 32 Assessment Date: 07/31/2019



Group	Item - Type					Recommend	
Group		1	O. antitu	LIONA	Dank		Comments
		Location	Quantity	UOM EA	Rank	Replacement	Comments
	Lighting - Pendent/Surface Partitions	Basement	4 13	EA EA	7 7	6-10 years	
		Basement	_			6-10 years	
	Walls - Structural Glazed Tile	Basement	1,700	SF	6	10+ years	
	Water Closet	Basement	13	EA	6	6-10 years	
	Accessories	Basement	506	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	506	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Basement	506	SF	6	10+ years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Hand Dryer	Basement	2	EA	7	6-10 years	
	Lavatory	Basement	4	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement	4	EA	6	6-10 years	
	Partitions	Basement	4	EA	7	6-10 years	
	Urinals	Basement	7	EA	6	6-10 years	
	Walls - Structural Glazed Tile	Basement	819	SF	6	10+ years	
	Water Closet	Basement	4	EA	6	6-10 years	
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #100 (Regular Classroom)						
	AC Units	1st Floor	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	938	SF	6	6-10 years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	938	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒA	7	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	211	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,722	SF	6	10+ years	
laceroo	m #101 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	938	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood Bools Inclu IIW	1st Floor	938	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
				LF		-	
	Marker Board	1st Floor	24		7	6-10 years	
	Storage/ Closet	1st Floor	211	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,722	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	832	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	832	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Storage/ Closet	1st Floor	158	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,419	SF	6	10+ years	
Classroo	om #103 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	832	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Wood	1st Floor	832	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Storage/ Closet	1st Floor	158	SF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,419	SF	6	10+ years	
	Wireless System	1st Floor	1,419	EA	7	6-10 years	
	Wireless System	13111001	ı	LA	,	0-10 years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	884	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	34	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	176	SF	5	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,398	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	884	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	34	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	176	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,398	SF	6	6-10 years	
	vvalis - i-lasici/Diywali	ZIIU FIUUI	1,390	SI-	U	o- 10 years	

Campus Name: Harvard Page : 12 of 32 Assessment Date: 07/31/2019



Catego	Category : Classroom			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #203 (Regular Classroom)						
Ciassioo	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	832	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	832	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	6-10 years	
	Marker Board	2nd Floor	34	LF	6	6-10 years	
	Storage/ Closet	2nd Floor 2nd Floor	158	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor		SF			
		2nd Floor 2nd Floor	1,291		6	10+ years	Doint pooling and aradians
	Walls - Plaster/Drywall	∠na Floor	128	SF	6	10+ years	Paint peeling and cracking.
Classroo	m #204 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	832	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	1	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	832	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	6-10 years	
	Marker Board	2nd Floor	34	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	158	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,419	SF	6	10+ years	
	Walls Tlastel/Dlywall	2110 1 1001	1,410	O.	Ū	101 years	
Classroo	m #301 (Art Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	938	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	938	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	211	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,722	SF	6	10+ years	
01	77. //200 (D. a.u.lan Olasana)						
Jassroo	m #302 (Regular Classroom)	01 []				0.40	
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	938	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	938	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	

Campus Name: Harvard Page: 13 of 32 Assessment Date: 07/31/2019



Catego	ry : Classroom		В	Building : Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	Marker Board	3rd Floor	40	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	211	SF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,722	SF	6	10+ years		
	•		,			,		
Classroo	m #303 (Science Classroom)							
01000100	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	621	SF	6	6-10 years		
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years		
		3rd Floor	2	EA		•		
	Doors - Wood Doors inclu hw			SF	6	10+ years		
	Floor - Tile	3rd Floor	621		6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years		
	Marker Board	3rd Floor	34	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	234	SF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	6	10+ years		
	Work Sink	3rd Floor	1	EA	7	6-10 years		
Classroo	m #304 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	651	SF	6	6-10 years		
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	651	SF	6	-		
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years 6-10 years		
	Marker Board	3rd Floor	40	LF				
					7	6-10 years		
	Storage/ Closet	3rd Floor	234	SF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,400	SF	6	10+ years		
Classroo	m #305 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	459	SF	6	6-10 years		
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	459	SF	6	10+ years		
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	6-10 years		
	Marker Board	3rd Floor	28	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,232	SF	6	10+ years		
_	•					,		
Catego	ry : Interior		В	uilding	: Main	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Plaster/Drywall	1st Floor	2,190	SF	6	6-10 years		
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years		



Catego	Category : Interior			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Asphalt Floor	1st Floor	2,190	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	4,508	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,190	SF	6	6-10 years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Asphalt Floor	2nd Floor	2,190	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,508	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,190	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	6-10 years	
	Floor - Asphalt Floor	3rd Floor	2,190	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4,508	SF	6	10+ years	
	Ceiling - Lay-in	Basement - North East	224	SF	6	6-10 years	
	Floor - Tile/Sheet	Basement - North East	224	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement - North East	1	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement - North East	4	LF	6	10+ years	
	Walls - Plaster/Drywall	Basement - North East	600	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - North West	214	SF	6	6-10 years	
	Doors - Wood Doors include hw	Basement - North West	4	EA	6	10+ years	
	Floor - Tile/Sheet	Basement - North West	214	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	Basement - North West	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement - North West	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement - North West	1,242	SF	6	10+ years	
	Walls - Structural Glazed Tile	Basement - North West	102	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - South East	150	SF	6	6-10 years	
	Floor - Asphalt Floor	Basement - South East	150	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - South East	2	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement - South East	4	LF	6	10+ years	
	Walls - Plaster/Drywall	Basement - South East	500	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - South West	484	SF	6	6-10 years	
	Doors - Wood Doors include hw	Basement - South West	2	EA	6	10+ years	
	Floor - Tile/Sheet	Basement - South West	484	SF	5	10+ years	
	Lighting - Pendent/Surface	Basement - South West	2	EA	7	6-10 years	
	Walls - Concrete Block	Basement - South West	880	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - West	66	SF	6	6-10 years	
	Doors - Wood Doors include hw	Basement - West	2	EA	6	10+ years	
	Floor - Asphalt Floor	Basement - West	66	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement - West	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Basement - West	102	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement - West	306	SF	6	10+ years	
_Safetv							
Curciy	Security Cameras	entire Building	6	EA	7	6-10 years	

Campus Name: Harvard Page : 15 of 32 Assessment Date: 07/31/2019



Catego	ry : Interior		В	Building : Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
o							
Stairs	Ceiling - Plaster/Drywall	North West	762	SF	6	6-10 years	
	Floor - Asphalt	North West	510	SF	6	10+ years	
	Floor - Terrazzo	North West	252	SF	6	10+ years	
	Handrails	North West	224	LF	5	6-10 years	
	Lighting - Pendent/Surface	North West	8	EA	7	6-10 years	
	Stairs - Asphalt	North West	112	LF	6	10+ years	
	Walls - Plaster/Drywall	North West	3,136	SF	6	10+ years	
	Walls - Traster/Drywaii Walls - Structural Glazed Tile	North West	102	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South West	762	SF	6	6-10 years	
	Floor - Asphalt	South West	510	SF	6	10+ years	
	Floor - Terrazzo	South West	252	SF	6	10+ years	
	Handrails	South West	224	LF	5	6-10 years	
	Lighting - Pendent/Surface	South West	8	EA	7	6-10 years	
	Stairs - Asphalt	South West	112	LF	6	10+ years	
	Walls - Plaster/Drywall	South West	3,136	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West	300	SF	6	6-10 years	
	Floor - Asphalt	West	300	SF	6	10+ years	
	Handrails	West	45	LF	7	6-10 years	
	Lighting - Pendent/Surface	West	3	EA	7	6-10 years	
	Stairs - Asphalt	West	20	LF	6	10+ years	
	Walls - Plaster/Drywall	West	1,134	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	West	378	SF	6	10+ years	

Campus Name: Harvard Page : 16 of 32 Assessment Date: 07/31/2019







Category : Exterior **Building: Annex** 

	I y . Exterior			ununig	. ,	Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
•	• • • • • • • • • • • • • • • • • • •	Location	Quantity	OOW	Kalik	Replacement	Comments	
trance								
	Entrance Control - Audio and Video	#1 - Main - W	1	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	#1 - Main - W	2	EA	7	10+ years		
	Exterior Doors - Transom Lite	#1 - Main - W	4	EA	7	10+ years		
	Power Door Operator and Controls	#1 - Main - W	2	EΑ	7	10+ years		
	Exterior Doors - Exterior Steel Door	#10 - E	2	EA	7	10+ years		
	Exterior Doors - Side lite	#10 - E	2	EA	7	10+ years		
	Exterior Doors - Transom Lite	#10 - E	2	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	#11 - NE	2	EA	7	10+ years		
	Exterior Stairs - Stone	#11 - NE	6	LF	7	10+ years		
	Entrance Control - Audio and Video	#12 - W	1	EA	7	6-10 years		
	Exterior Doors - Exterior Steel Door	#12 - W	2	EΑ	7	10+ years		
			_		-	, , , , , , , , , , , , , , , , , , , ,		
ındat	ion							
	Foundation - Concrete	Entire Building	620	LF	7	10+ years		
	Superstructure - Concrete	Entire Building	25,716	SF	7	10+ years		
		-						
hting								
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	10+ years		
of Sy	stem							
	Access Ladder - Metal	Elevator Tower Roof	1	EA	7	10+ years		
	Coping - Stone	Elevator Tower Roof	55	LF	6	10+ years		
	Downspouts - Interior Downspouts	Elevator Tower Roof	57	LF	6	10+ years		
	Parapet - Parapet > 30"	Elevator Tower Roof	55	LF	6	10+ years		
	Roof - Modified Bitumen	Elevator Tower Roof	184	SF	5	2-5 years		
	Roof Structure - Steel / Metal Deck/	Elevator Tower Roof	184	SF	7	10+ years		
	Concrete Topping							
	Access Ladder - Metal	Link Roof	1	EA	7	10+ years		
	Coping - Stone	Link Roof	142	LF	6	10+ years		
	Downspouts - Interior Downspouts	Link Roof	29	LF	6	10+ years		
	Parapet - 16" - 30" Height	Link Roof	142	LF	6	10+ years		
	Roof - Modified Bitumen	Link Roof	732	SF	5	2-5 years		
	Roof Structure - Steel / Metal Deck/	Link Roof	732	SF	7	10+ years		
	Concrete Topping		. 2=		-	· ,		
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years		
	Chimney - Metal Flue	Main Roof	27	LF	6	10+ years		
	Coping - Metal	Main Roof	509	LF	6	6-10 years		
	Downspouts - Interior Downspouts	Main Roof	92	LF	6	10+ years		
	Roof - Modified Bitumen	Main Roof	11,668	SF	5	2-5 years		
	NOOL - MOUINEU DIUNNEN				7	10+ years		
	Roof Hatch - Metal	Main Root	1					
	Roof Hatch - Metal Roof Structure - Concrete	Main Roof Main Roof	1 11,668	EA SF	7	10+ years		



Group

Walls

**Category: Exterior** 

Item - Type

Canopy - Concrete/ Stucco

Canopy - Concrete/ Stucco

#### John Harvard Elementary School of Excellence 7527 S Harvard AVENUE, Chicago, IL 60620

Replacement Comments

Recommend

10+ years

10+ years

**Building: Annex** 

SF

SF

UOM Rank

6

6

Quantity

1,020

58

Exterior Walls - Brick	Entire Building	9,721	SF	6	10+ years	
Exterior Walls - Brick	Entire Building	2	SF	4	1-2 years	
Exterior Walls - Stone-Cast	Entire Building	109	SF	6	10+ years	
Vindows						
Clerestory - Glass Double-Pane	Entire Building	26	SF	6	10+ years	
Curtain wall - Glazed Double Pane	Entire Building	96	SF	6	10+ years	
Curtain wall - Insulated Panel	Entire Building	792	SF	6	10+ years	
Curtain wall - Louver	Entire Building	90	SF	6	10+ years	
Guard - Guards perforated	Entire Building	362	SF	6	10+ years	
Lintels - Steel	Entire Building	396	LF	6	10+ years	
Windows - Sash Aluminum Double-	pane Entire Building	3,910	SF	6	10+ years	
Category : Electrical		В	uilding	: Annex		
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emergency System	Location	Quantity	JOIN	Rain	Керіасетен	Comments
Emergency A/C Power - Corridors	and Entire Building	5,665	SF	6	6-10 years	
Stairs						
Emergency A/C Power - Students		880	SF	6	6-10 years	
Emergency Battery Packs - Student		5	EA	6	6-10 years	
Exit Signs - Corridors and Stairs	Entire Building	7	EA	5	2-5 years	Lamps need to be replaced in 3 exit signs in the 1st and 2nd floor
						corridors
Security System - CCTV	Entire Building	25,716	SF	6	6-10 years	Corridors
Security System - Intrusion Detection		25,716	SF	6	6-10 years	
Automatic Transfer Switch	Mechanical Room	25,710	EA	6	6-10 years	
Automatic Transfer Switch	Wednamear Room	ı	LA	O	0-10 years	
Main Service						
PA System	Entire Building	25,716	SF	6	6-10 years	
Independent Electrical Service for	Mechanical Room	1	EA	6	6-10 years	
emergency power Main Electrical Service - 800 A and	Less Mechanical Room	1	EA	6	6 10 years	
than 120/208/3PH	Less Wechanical Room	1	EA	0	6-10 years	
Danier Dietrikution						
Power Distribution  Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
Lighting and Power Panels - 100 A		1	EA	6	6-10 years	
Lighting and Power Panels - 100 A		1	EA	4	0-10 years 0-1 year	Corroded and deteriorated.
Campus Name: Harvard		Page : 18 of 32				Assessment Date: 07/31/20

Location

**Entire Building** 

Entire Building



Unit Ventilators- Floor Mounted- Hot Water

### John Harvard Elementary School of Excellence 7527 S Harvard AVENUE, Chicago, IL 60620

						1.	27 O Harvard Avenue, Officago, le 00020
Catego	ry : Electrical		В	uilding	: Annex	(	•
				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
		· ·				•	
Catego	ry : Fire Protection		В	uilding	: Annex	(	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Mechanical Room	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Mechanical Room	25,716	SF	6	6-10 years	
	Fire Alarm_System	Mechanical Room	25,716	SF	4	0-1 year	Fire Alarm system does not
							communicate with 2nd floor strobe
							lights. Problem in fire alarm system
							communication.
^atono	ry : Mechanical		R	uildina	: Annex	•	
Jalego	ry . Mechanica			ununig	. Alliex	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	-						
AII CONC	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	10+ years	
	than 5 tons						
Heating	Davicas						
Teaming	Cabinet Heaters - With Hot Water Coil	Entire Building	14	EA	4	0-1 year	The hot water lines to the Cabinet
	Cabinet ricators With Flot Water Con	Little Ballang	17	_/\	7	o i youi	heaters in the common areas have
							been removed during modifications.
							solution is currently being worked
							through to enable the system.
	Fin Tube - Hot Water	Entire Building	40	LF	6	6-10 years	2 3g 10 0.100.0 0,0101111
	Wall Heater - Electric	Entire Building	6	EA	5	6-10 years	
			· ·		-	<b>,</b>	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	600	LF	5	2-5 years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	2	EA	5	6-10 years	
Tompore	ature Control						
rempera	Pneumatic System	Entire Building	25,716	SF	4	1.2 40000	Old Pneumatic controls need to be
	Frieditidiic System	Entire building	25,716	SF	4	1-2 years	replaced with DDC System
	Thermostats - Pneumatic	Entire Building	15	EA	6	6-10 years	. sp. acca mai 220 cyclom
lmit \/c :-	Atlastic in						
Jnit Ven	uiauui						

Campus Name: Harvard Page : 19 of 32 Assessment Date: 07/31/2019

**Entire Building** 

15

EΑ

5

6-10 years



3	y : Mechanical	В	ullaing	: Annex			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Heating Coils Only						
Ventilatio	n						
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	6	6-10 years	
	CFM						
	Exhaust Fans- Roof Mounted - Less than	Entire Building	2	EA	6	6-10 years	
	500 CFM						
_			_		_		
Categor	y : Plumbing		В	uilding	: Annex		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	
Piping							
	Domestic Piping-Cold Water Horizontal	Entire Building	25,716	SF	4	2-5 years	Over 40 years, galvanized
	Lines						
	Domestic Piping-Cold Water Risers	Entire Building	25,716	SF	4	2-5 years	Over 40 years, galvanized
	Domestic Piping-Cold Water from Risers to	Entire Building	25,716	SF	6	6-10 years	
	Fixtures	Fating Delibing	05.740	0.	4	0.5	O
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	25,716	SF	4	2-5 years	Over 40 years, galvanized
	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Entire Building Entire Building	25,716 25,716	SF SF	4 6	6-10 years	Over 40 years, galvanized
	Domestic Piping-not Water Return Risers  Domestic Piping-Hot Water from Risers to	Entire Building Entire Building	25,716	SF	6	6-10 years 6-10 years	
	Fixtures	Entire ballaring	23,710	OI	O	0-10 years	
	Sanitary Piping	Entire Building	25,716	SF	6	6-10 years	
	Storm Piping	Entire Building	25,716	SF	6	6-10 years	
	Vent Piping	Entire Building	25,716	SF	6	6-10 years	
	1 3	3	,			,	
Categor	ry : Room		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administı	ative Suites/Offices						
	AC Unit	1st Floor-Assistant Principal's	1	EA	7	6-10 years	
		Office-107A				•	
	Ceiling - Plaster/Drywall	1st Floor-Assistant Principal's	180	SF	6	6-10 years	
		Office-107A					
	Doors - Wood Doors inclu hw	1st Floor-Assistant Principal's	1	EA	6	10+ years	
	E. T.	Office-107A	400	05	•	40	
	Floor - Tile	1st Floor-Assistant Principal's	180	SF	6	10+ years	
	Lighting Dondont/Curfoss	Office-107A	^	г^	_	6.10	
	Lighting - Pendent/Surface	1st Floor-Assistant Principal's Office-107A	2	EA	6	6-10 years	
		OIIICE-10/A					

Campus Name: Harvard Page : 20 of 32 Assessment Date: 07/31/2019



Recommend Replacement Commend Power Distribution	Building : Annex						
Power Distribution							
Office-107A   Storage/ Closet   1st Floor-Assistant Principal's   18	nts						
Office-107A  Walls - Concrete Block  1st Floor-Assistant Principal's Office-107A  AC Unit Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor-Main Office-107 Floor - Tile Lighting - Pendent/Surface Power Distribution Storage/ Closet Walls - Concrete Block SF Office-107A  1 EA 7 6-10 years 1st Floor-Main Office-107 365 SF 6 10+ years 1st Floor-Main Office-107 2 EA 6 10+ years 1st Floor-Main Office-107 365 SF 6 10+ years 1st Floor-Main Office-107 6 EA 6 6-10 years 1st Floor-Main Office-107 10 EA 6 6-10 years 1st Floor-Main Office-107 21 SF 5 6-10 years Walls - Concrete Block 1st Floor-Main Office-107 1,280 SF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor-Room 213A-Teacher 238 SF 6 6-10 years							
Office-107A  AC Unit							
Ceiling - Plaster/Drywall 1st Floor-Main Office-107 365 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor-Main Office-107 2 EA 6 10+ years Floor - Tile 1st Floor-Main Office-107 365 SF 6 10+ years Lighting - Pendent/Surface 1st Floor-Main Office-107 6 EA 6 6-10 years Power Distribution 1st Floor-Main Office-107 10 EA 6 6-10 years Storage/ Closet 1st Floor-Main Office-107 21 SF 5 6-10 years Walls - Concrete Block 1st Floor-Main Office-107 1,280 SF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor-Room 213A-Teacher 238 SF 6 6-10 years							
Doors - Wood Doors inclu hw1st Floor-Main Office-1072EA610+ yearsFloor - Tile1st Floor-Main Office-107365SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office-1076EA66-10 yearsPower Distribution1st Floor-Main Office-10710EA66-10 yearsStorage/ Closet1st Floor-Main Office-10721SF56-10 yearsWalls - Concrete Block1st Floor-Main Office-1071,280SF610+ yearsCeiling - Plaster/Drywall2nd Floor-Room 213A-Teacher238SF66-10 years							
Doors - Wood Doors inclu hw1st Floor-Main Office-1072EA610+ yearsFloor - Tile1st Floor-Main Office-107365SF610+ yearsLighting - Pendent/Surface1st Floor-Main Office-1076EA66-10 yearsPower Distribution1st Floor-Main Office-10710EA66-10 yearsStorage/ Closet1st Floor-Main Office-10721SF56-10 yearsWalls - Concrete Block1st Floor-Main Office-1071,280SF610+ yearsCeiling - Plaster/Drywall2nd Floor-Room 213A-Teacher238SF66-10 years							
Floor - Tile 1st Floor-Main Office-107 365 SF 6 10+ years Lighting - Pendent/Surface 1st Floor-Main Office-107 6 EA 6 6-10 years Power Distribution 1st Floor-Main Office-107 10 EA 6 6-10 years Storage/ Closet 1st Floor-Main Office-107 21 SF 5 6-10 years Walls - Concrete Block 1st Floor-Main Office-107 1,280 SF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor-Room 213A-Teacher 238 SF 6 6-10 years							
Lighting - Pendent/Surface 1st Floor-Main Office-107 6 EA 6 6-10 years Power Distribution 1st Floor-Main Office-107 10 EA 6 6-10 years Storage/ Closet 1st Floor-Main Office-107 21 SF 5 6-10 years Walls - Concrete Block 1st Floor-Main Office-107 1,280 SF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor-Room 213A-Teacher 238 SF 6 6-10 years							
Power Distribution1st Floor-Main Office-10710EA66-10 yearsStorage/ Closet1st Floor-Main Office-10721SF56-10 yearsWalls - Concrete Block1st Floor-Main Office-1071,280SF610+ yearsCeiling - Plaster/Drywall2nd Floor-Room 213A-Teacher238SF66-10 years							
Storage/ Closet 1st Floor-Main Office-107 21 SF 5 6-10 years Walls - Concrete Block 1st Floor-Main Office-107 1,280 SF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor-Room 213A-Teacher 238 SF 6 6-10 years							
Walls - Concrete Block 1st Floor-Main Office-107 1,280 SF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor-Room 213A-Teacher 238 SF 6 6-10 years							
Ceiling - Plaster/Drywall 2nd Floor-Room 213A-Teacher 238 SF 6 6-10 years							
Resource Room							
Doors - Wood Doors inclu hw 2nd Floor-Room 213A-Teacher 1 EA 6 10+ years Resource Room							
Floor - Tile 2nd Floor-Room 213A-Teacher 238 SF 6 10+ years Resource Room							
Lighting - Pendent/Surface 2nd Floor-Room 213A-Teacher 4 EA 6 6-10 years Resource Room							
Power Distribution 2nd Floor-Room 213A-Teacher 4 EA 6 6-10 years Resource Room							
Walls - Concrete Block 2nd Floor-Room 213A-Teacher 558 SF 6 10+ years Resource Room							
Work SInk 2nd Floor-Room 213A-Teacher 1 EA 7 6-10 years Resource Room							
Library							
AC Unit 2nd Floor-Room 205 2 EA 7 6-10 years							
Casework 2nd Floor-Room 205 54 LF 6 6-10 years							
Ceiling - Splined 2nd Floor-Room 205 1,164 SF 6 6-10 years							
Doors - Wood Doors inclu hw 2nd Floor-Room 205 2 EA 6 10+ years							
Floor - Carpet 2nd Floor-Room 205 1,164 SF 6 10+ years							
Lighting - Pendent/Surface 2nd Floor-Room 205 20 EA 6 6-10 years							
Walls - Concrete Block 2nd Floor-Room 205 1,287 SF 6 10+ years							
_MDF_IDF							
Doors - Steel Doors incl hw 1sr Floor-105C 1 EA 6 10+ years							
Other Cooling Unit 1sr Floor-105C 1 EA 7 6-10 years							
Window AC Ūnit 1sr Floor-105C 1 EA 7 6-10 years							



Catego	ry : Room		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	23	SF	5	6-10 years	
	Mechanical/ Service Rooms	1st Floor	331	SF	5	6-10 years	
	Vaults	1st Floor	50	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	23	SF	5	6-10 years	
	damen a closer	2114 1 1001	20	O.	J	o ro youro	
Restrooi	n						
	Accessories	105A-1st Floor-Kindergarten	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	105A-1st Floor-Kindergarten	52	SF	6	6-10 years	
	Doors - Transom Window	105A-1st Floor-Kindergarten	1	SF	6	10+ years	
	Floor - Tile	105A-1st Floor-Kindergarten	52	SF	6	10+ years	
	Floor Drain	105A-1st Floor-Kindergarten	1	EA	7	10+ years	
	Hand Dryer	105A-1st Floor-Kindergarten	1	EA	7	6-10 years	
	Lavatory	105A-1st Floor-Kindergarten	1	ΕA	6	6-10 years	
	Lighting - Pendent/Surface	105A-1st Floor-Kindergarten	1	ΕA	7	6-10 years	
	Walls - Concrete Block	105A-1st Floor-Kindergarten	261	SF	6	10+ years	
	Water Closet	105A-1st Floor-Kindergarten	1	EA	6	6-10 years	
	Accessories	107C-1st Floor-Principal's Office	61	SF	7	6-10 years	
	7.0000001100	Restroom	0.	Ο.	•	o to youro	
	Ceiling - Plaster/Drywall	107C-1st Floor-Principal's Office	61	SF	6	6-10 years	
	Coming Tradicity Dry Wan	Restroom	01	O.	· ·	o ro youro	
	Doors - Wood Doors inclu hw	107C-1st Floor-Principal's Office	1	EA	6	10+ years	
	Doors - Wood Doors Inclu IIW	Restroom	'	LA	U	10+ years	
	Floor - Tile	107C-1st Floor-Principal's Office	61	SF	6	10+ years	
	1 1001 - 1 116	Restroom	01	01	U	10+ years	
	Lavatory	107C-1st Floor-Principal's Office	1	EA	6	6-10 years	
	Lavatory	Restroom	ı	LA	O	0-10 years	
	Lighting Bondont/Surface	107C-1st Floor-Principal's Office	1	EA	7	6-10 years	
	Lighting - Pendent/Surface		I	EA	1	6-10 years	
	Walla Canarata Diagle	Restroom	070	SF	^	40	
	Walls - Concrete Block	107C-1st Floor-Principal's Office	279	5F	6	10+ years	
	Matar Class	Restroom	4	_^	^	0.40	
	Water Closet	107C-1st Floor-Principal's Office	1	EA	6	6-10 years	
		Restroom	222	0=	_	0.40	
	Accessories	1st Floor	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	220	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	220	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	5	6-10 years	
	Lavatory	1st Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	
	Partitions	1st Floor	1	EA	7	6-10 years	
	Urinals	1st Floor	2	EA	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	513	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	6-10 years	

Campus Name: Harvard Page : 22 of 32 Assessment Date: 07/31/2019



Catego	ry : Room		В	uilding	: Annex		. 5 :
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	30	SF	6	10+ years	
	Lavatory	1st Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	207	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	6-10 years	
	Accessories	1st Floor	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	220	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	220	SF	6	10+ years	
	Floor Drain	1st Floor	1	ĒΑ	7	6-10 years	
	Hand Dryer	1st Floor	1	EΑ	7	6-10 years	
	Lavatory	1st Floor	2	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	3	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	513	SF	6	10+ years	
	Water Closet	1st Floor	3	EA	6	6-10 years	
	Accessories	1st Floor-Room 111	48	SF	7	•	
	Ceiling - Plaster/Drywall	1st Floor-Room 111	48	SF	6	6-10 years 6-10 years	
	Doors - Wood Doors inclu hw	1st Floor-Room 111	1	EA	6		
	Floor - Tile	1st Floor-Room 111	48	SF	6	10+ years	
						10+ years	
	Hand Dryer	1st Floor-Room 111	1	EΑ	7	6-10 years	
	Lavatory	1st Floor-Room 111	•	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Room 111	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor-Room 111	252	SF	6	10+ years	
	Water Closet	1st Floor-Room 111	1	EA	6	6-10 years	
	Accessories	2nd Floor	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	220	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	220	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	6-10 years	
	Partitions	2nd Floor	1	EA	5	6-10 years	
	Urinals	2nd Floor	1	EA	6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	513	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	6	6-10 years	
	Accessories	2nd Floor	220	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	220	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	220	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	6-10 years	
	•		_		-	,	

Campus Name: Harvard Page : 23 of 32 Assessment Date: 07/31/2019



Catego	ry : Room		В	uilding	: Annex		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	6-10 years	
	Partitions	2nd Floor	3	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	513	SF	6	10+ years	
	Water Closet	2nd Floor	3	EA	6	6-10 years	
	Accessories	2nd Floor	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	42	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	42	SF	6	10+ years	
	Lavatory	2nd Floor	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	234	SF	6	10+ years	
	Water Closet	2nd Floor	1	EA	6	6-10 years	
Catego	ry : Classroom		В	uildina	: Annex		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #105 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	876	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	876	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	56	SF	5	6-10 years	
	Walls - Concrete Block	1st Floor	1,521	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #106 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	744	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	0-1 year	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	834	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	990	SF	6	•	
	Work Sink		990		7	10+ years	
	Work Sink	1st Floor	1	EA	/	6-10 years	
Classroo	om #108 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	710 Office						
	Casework	1st Floor	5	LF SF	6	6-10 years	



Catego	ry : Classroom		Building : Annex					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	744	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years		
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	990	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	6-10 years		
Classroo	om #109 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	5	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	744	SF	5	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years		
	Floor - Tile	1st Floor	744	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years		
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	990	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	6-10 years		
N	are #440 (Deculey Classes are)							
Jassroc	om #110 (Regular Classroom)	4 . =				2.12		
	AC Units	1st Floor	2	EΑ	7	6-10 years		
	Casework	1st Floor	5	LF	6	2-5 years		
	Ceiling - Plaster/Drywall	1st Floor	651	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	651	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years		
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	936	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	6-10 years		
Classroc	om #111 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	5	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	651	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	651	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years		
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	936	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	6-10 years		
Classroo	om #112 (Regular Classroom)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	5	LF	6	6-10 years		
	Casework	13111001	5	ᄕ	U	0-10 years		



Catego	ry : Classroom		Building : Annex				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	651	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	651	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	936	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroc	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	744	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	744	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	990	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7		
	WOIR SIIIR	2110 F1001	ı	EA	,	6-10 years	
lassroc	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	745	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	845	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	112	SF	6	10+ years	
Classroc	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	736	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	8	SF	5	1-2 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	744	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	990	SF	6	10+ years	
`laceroo	om #209 (Regular Classroom)						
viassinc	AC Units	2nd Floor	4	ГΛ	7	6.10 years	
		2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	445	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	300	SF	5	1-2 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	745	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	6	6-10 years	

Campus Name: Harvard Page : 26 of 32 Assessment Date: 07/31/2019



Catego	ry : Classroom		В	Building : Annex					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Marker Board	2nd Floor	16	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	845	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	112	SF	6	10+ years			
Classras	m #240 (Degular Classroom)								
Classioo	m #210 (Regular Classroom)	0:1 []		Ε.	7	0.40			
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	745	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years			
	Walls - Concrete Block	2nd Floor	845	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	112	SF	6	10+ years			
Classroo	m #211 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	•			
						10+ years			
	Floor - Tile Quarry	2nd Floor	745	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	112	SF	6	10+ years			
Classroo	m #212 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	6-10 years			
	Doors - Store Front	2nd Floor	1	ĒΑ	6	10+ years			
	Floor - Tile	2nd Floor	745	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	6	6-10 years			
	Walls - Concrete Block	2nd Floor	845	SF	6	10+ years			
						,			
	Walls - Plaster/Drywall	2nd Floor	112	SF	6	10+ years			
Catego	ry : Interior		В	uilding	: Annex				
O	Ham Time	Location	0	11014	Devil	Recommend	Comments		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Plaster/Drywall	1st Floor	2,667	SF	6	6-10 years			
	Doors - Store Front	1st Floor	4	EA	6	10+ years			
	Doors - Transom Window	1st Floor	205	SF	6	10+ years			
	Doors - Wood Doors include hw	1st Floor	6	EA	6	10+ years			
	Drinking Fountains - Double Fountain	1st Floor	2	EA	5	6-10 years			
	Drinking Fountains - Single Fountain	1st Floor	1	EA	5	6-10 years			



Catego	Category : Interior			uildina	: Annex		527 O Haivard Avenoe, Onleago, ie 00020
	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Quarry	1st Floor	116	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	16	SF	5	10+ years	
	Floor - Tile/Sheet	1st Floor	2,535	SF	5	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	23	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	5,295	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	478	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	2,586	SF	6	6-10 years	
	Ceiling - Splined	2nd Floor	10	SF	4	1-2 years	Water stained
	Doors - Wood Doors include hw	2nd Floor	2	EA	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	5	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	5	6-10 years	
	Floor - Terrazzo	2nd Floor	144	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,452	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	18	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	ΕA	7	6-10 years	
	Stairs - Concrete Stairs	2nd Floor	22	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	5,180	SF	6	10+ years	
	Walls - Masonry	2nd Floor	864	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	356	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	192	SF	6	6-10 years	
	Floor - Terrazzo	3rd Floor	192	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	2	ĒΑ	6	6-10 years	
	Walls - Concrete Block	3rd Floor	504	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	56	SF	6	10+ years	
						Ţ	
_Safety							
	Camera Viewing Station	entire building	1	EΑ	7	6-10 years	
	Security Cameras	entire building	5	EA	7	6-10 years	
	Security Cameras	entire building	3	EA	5	6-10 years	
_Stairs	Osilia a Disetas/Danasall	Nigotis Eggs	000	05		0.40	
	Ceiling - Plaster/Drywall	North East	209	SF	6	6-10 years	
	Floor - Terrazzo	North East	100	SF LF	6	10+ years	
	Handrails	North East	64		5	6-10 years	
	Lighting - Pendent/Surface	North East	3	EA	7	6-10 years	
	Stairs - Terrazzo	North East	32	LF	6	10+ years	
	Walls - Concrete Block	North East	794	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	North East	88	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South West	209	SF	6	6-10 years	
	Floor - Terrazzo	South West	100	SF	6	10+ years	
	Handrails	South West	64	LF	5	6-10 years	
	Lighting - Pendent/Surface	South West	3	EA	6	6-10 years	
	Stairs - Terrazzo	South West	32	LF	6	10+ years	

Campus Name: Harvard Page : 28 of 32 Assessment Date: 07/31/2019



Catego	Category : Interior			Building : Annex					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	Walls - Concrete Block Walls - Tile Ceramic/ Porcelain	South West South West	794 88	SF SF	6 6	10+ years 10+ years			
_Vertical	Vertical Conveyance								
	Elevator - Elevator- Machine Roomless		1	EA	6	6-10 years			

Campus Name: Harvard Page : 29 of 32 Assessment Date: 07/31/2019







Category : Site **Building: Site** 

Catego	ry . Site			unung	. Oile		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Synthetic	South	4,869	SF	7	10+ years	
	Surface - Asphalt	South	1,672	SF	6	10+ years	
	Ouridoc /topridit	Court	1,072	Oi.	O	101 years	
Civil/Dra	inaga						
CIVII/DIa		Fating Oite		Ε.		40	
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	6	10+ years	
Fancina							
Fencing	Fencing - Chain Link	West, North Courtyard and South	246	LF	6	10+ years	
	Fencing - Iron and Concrete Post	West, North Courtyard and South	173	LF	6	10+ years	
	Fencing - New Standard Ornamental	West, North Courtyard and South	42	LF	6	10+ years	
	Fencing - Old Standard Ornamental	West, North Courtyard and South	304	LF	6	10+ years	
	Fencing - Old Standard Ornamental	West, North Courtyard and South	48	LF	4	1-2 years	
	r ending - Old Standard Smarnerital	West, North Courtyard and South	40	LI	7	1-2 years	
Landsca	pe						
	Landscape - Grass	Entire Site	7,128	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	1,364	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	238	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	1,124	SF	6	10+ years	
	Lighting - Pole Mounted	Entire Site		EA	6	10+ years	
	Parkway trees	Entire Site	26	EA	6	10+ years	
	Parkway trees	Entire Site	3	EA	4	1-2 years	
	Planting Beds/ Area	Entire Site	1,500	SF	6	10+ years	
	Planting Beds/ Area	Entire Site	1,250	SF	4	1-2 years	South end of site at the southern end
	· ·					•	of the parking lot
	Trash Receptacles	Entire Site	6	EA	6	10+ years	
Parking							
	Concrete Curbs	South	316	LF . –	6	10+ years	
	Interior Plantings	South	242	LF	6	10+ years	
	Lighting - Pole Mounted	South	6	EA	6	10+ years	
	Pavers	South	21,141	SF	6	10+ years	
	Surface - Asphalt	South	10,486	SF	6	10+ years	
	Trash Enclosure - Chain Links	South	300	SF	6	10+ years	
Dlovers	and						
Playgrou	Equipment - Pre K 3-5	N Courtyard	1	EA	7	10+ years	
	Surface - Poured Surface	N Courtyard N Courtyard	685	SF	7	10+ years	
	Equipment - School Age 5-12	S Playground	1	EA	7	10+ years	
	Surface - Poured Surface	S Playground	1,320	SF	7	10+ years	
	Surface - I Guieu Surface	o i laygiouriu	1,320	Ji	,	10+ years	



Catego	ry : Site		В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Sidewall	(S						
	Sidewalks - Internal Walks	Entire Site	245	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	28,068	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	50	SF	5	1-2 years	
Signage							
0 0	Flag Pole - Flag Pole	Northwest and Main Entrance	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Northwest and Main Entrance	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Northwest and Main Entrance	1	EA	7	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Harvard Page: 31 of 32 Assessment Date: 07/31/2019

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

Classicolli Sullillary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		<u> </u>	1	•		•		•	
Art Room	Regular Classroom	3rd Floor	301	301	938	198	99	N	N
Computer Lab	Regular Classroom	1st Floor	103	104	832	204	104	N	N
Music Room	Regular Classroom	2nd Floor	204	204	832	133	58	N	N
Office	Regular Classroom	1st Floor	101	102	938	198	99	N	N
Regular Classroom	Regular Classroom	1st Floor	100	101	938	198	99	N	N
Regular Classroom	Regular Classroom	1st Floor	102	103	832	204	68	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	884	204	68	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	884	204	68	Y	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	832	133	58	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	938	198	99	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	651	198	99	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	459	132	66	N	N
Science Classroom	Regular Classroom	3rd Floor	303	303	621	198	99	N	Y
Building : Annex				•					
Kindergarten	Regular Classroom	1st Floor	106	106	744	156	78	N	N
Kindergarten	Regular Classroom	1st Floor	108	108	744	156	78	N	N
Pre School	Kindergarten	1st Floor	105	105	876	231	115	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	744	156	78	N	N
Regular Classroom	Regular Classroom	1st Floor	110	110	651	156	78	N	N
Regular Classroom	Regular Classroom	1st Floor	111	111	651	156	78	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	651	98	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	744	156	78	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	745	184	96	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	744	156	78	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	745	184	96	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	745	184	96	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	745	184	96	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	745	184	96	N	N