



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1913	3	62,706
Campus Total			62,706

Catego	Category : Exterior			uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Cell Equ	pment		-			<u>-</u>	
•	Cell Equipment - Cabinets	Entire Building	6	EA	7	10+ years	
Entrance							
	Entrance Control - Audio and Video	1 - Main	1	EA	6	10+ years	
	Exterior Doors - Store Front	1 - Main	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	1 - Main	4	EA	7	10+ years	
	Exterior Stairs - Concrete	1 - Main	16	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	1 - Main	50	LF	6	10+ years	
	Ramps - Concrete	1 - Main	24	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	1 - Main	15	LF	6	10+ years	
	Entrance Control - Audio and Video	2	1	EA	6	10+ years	Missing cover
	Exterior Doors - Exterior Steel Door	2	3	EΑ	6	10+ years	· ·
	Exterior Doors - Transom Lite	2	3	EΑ	6	10+ years	
	Exterior Stairs - Concrete	2	24	LF	6	10+ years	
	Entrance Control - Audio and Video	3	1	EA	6	10+ years	Missing cover
	Exterior Doors - Exterior Steel Door	3	3	EΑ	6	10+ years	•
	Exterior Doors - Transom Lite	3	3	EA	6	10+ years	
	Exterior Stairs - Concrete	3	36	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	4	5	EA	5	0-1 year	These door exterior surfaces are in very poor shape and require extensive maintenance, one of the door frame trims is missing
	Exterior Doors - Transom Lite	4	5	EA	6	10+ years	· ·
	Exterior Stairs - Concrete	4	120	LF	5	0-1 year	Cracking.





Catego	ry : Exterior		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	5	1	EA	6	10+ years	
oundati	ion						
	Foundation - Masonry	Entire Building	817	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	62,706	SF	7	10+ years	
ighting							
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	Α	2	EA	4	0-1 year	Anchors have pulled away from wal
	Access Ladder - Metal	Α	2	EA	4	0-1 year	Attachment point of upper ladder ha
							been displaced because of
		-					deteriorating mortar
	Chimney - Brick Chimney- Stainless Steel	A	30	LF	6	10+ years	
	Liner	۸	400	. –	_	4.0	Deteriorete des electron desetion
	Coping - Metal	A	486	LF	5	1-2 years	Deteriorated sealant and rusting
	Coning Motel	۸	100	LF	F	1.0	coping
	Coping - Metal	A	108	LF	5	1-2 years	Deteriorated sealant and rusting coping
	Downspouts - Interior Downspouts	A	348	LF	6	10+ years	coping
	Parapet - 16" - 30" Height	A	112	LF	7	10+ years	
	Parapet - 16" - 30" Height	Ä	10	LF	5	1-2 years	Mortar deterioration and loose brick
	Parapet - Parapet > 30"	Ä	100	LF	7	10+ years	Mortal deterioration and loose brick
	Parapet - Parapet > 30"	A	372	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast		50,388	SF	6	-	
		A	50,366			10+ years	
	Roof Hatch - Metal	A	50.000	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	A	50,388	SF	7	10+ years	
	Access Ladder - Metal	В	1	EA	7	10+ years	
	Coping - Metal	В	60	LF	6	10+ years	
	Coping - Stone	В	208	LF	6	10+ years	
	Downspouts - Interior Downspouts	В	52	LF	6	10+ years	
	Parapet - 16" - 30" Height	В	218	LF	7	10+ years	
	Parapet - Parapet < 16" Height	В	50	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	В	8,128	SF	7	10+ years	
	Roof - Asphalt Gravel Ballast	В	50	SF	2	0-1 year	Per engineer, active leak near
							stairwell.
	Roof Structure - Steel with Clay Tile Arch	В	8,178	SF	7	10+ years	
	Coping - Stone	С	203	LF	6	10+ years	
	Downspouts - Interior Downspouts	С	54	LF	6	10+ years	
	Parapet - 16" - 30" Height	С	84	LF	7	10+ years	
	Parapet - Parapet < 16" Height	С	19	LF	7	10+ years	





Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - Parapet > 30"	C	100	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	C	4,140	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	С	4,140	SF	7	10+ years	
Walls							
	Cheek-Wall - Stone	Entire Building	135	SF	6	10+ years	
	Cornice - Cast Stone	Entire Building	225	LF	5	0-1 year	Deteriorating mortar and cracking.
	Cornice - Masonry Projecting Limestone	Entire Building	594	LF	7	10+ years	
	Cornice - Metal Projecting	Entire Building	600	LF	5	0-1 year	Metal corners is rusting throughout where are a few areas where the metal has rusted through
	Exterior Walls - Brick	Entire Building	35,382	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	505	SF	5	2-5 years	Deteriorating mortar
	Exterior Walls - Brick	Entire Building	10	SF	4	1-2 years	There is water damage at entrance for
	Exterior Walls - Stone-Cast	Entire Building	3,268	SF	6	10+ years	101
Vindows	3						
	Guard - Guards perforated	Entire Building	1,671	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	20	SF	5	1-2 years	Guard has fallen away from the window and needs to be replaced
	Guard - Guards wire guard	Entire Building	21	SF	6	10+ years	•
	Lintels - Steel	Entire Building	427	LF	6	10+ years	
	Lintels - Steel	Entire Building	300	LF	6	10+ years	
	Storefront Windows	Entire Building	81	SF	6	10+ years	
	Windows - Louver	Entire Building	114	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,789	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ncv System	Location	Quantity	COIII	raint	Ropidoomont	
-5-	Security System - CCTV	Boiler Room	62,706	SF	5	6-10 years	External only
	Security System - Intrusion Detection	Boiler Room	62,706	SF	6	6-10 years	· · · · · · · · · · · · · · · · · · ·
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,464	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	5,611	SF	6	10+ years	
	Exit Signs - Auditoium	Entire Building	3	EA	4	1-2 years	Lettering worn, difficult to read.
	Exit Signs - Corridors and Stairs	Entire Building	12	EA	6	6-10 years	Lottoring worm, aimount to read.
	Exit Signs - Comdors and Stairs Exit Signs - Gym	Entire Building	6	EA	4	1-2 years	Lettering worn, difficult to read.
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	Lettering worn, difficult to fead.
	Emergency Battery Packs - Corridors and	Entire Building	8	EA	6	6-10 years	



Park Manor Elementary School 7037 S Rhodes AVENUE, Chicago, IL 60637

XIII S	schools					70	037 S Rhodes AVENUE, Chicago, IL 6063
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Battery Packs - Gym	Entire Building	3	EA	6	6-10 years	
	Emergency Generator- Indoor- Natural Gas	Generator Room	1	EA	6	10+ years	
	- Below 60 KW						
	Automatic Transfer Switch	Mechanical Room	2	EA	6	10+ years	
lain Sei	vice						
	PA System	1st Floor	62,706	SF	5	2-5 years	
	Main Electrical Service - 1200 A	Electrical Room	1	EA	4	1-2 years	More than 50 years old, not reliable
	120/208/3PH					,	,
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	2-5 years	Older panels
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	r
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	7	10+ years	EM panel
	Lighting and Power Panels - Above 100 A	Entire Building	5	EΑ	6	2-5 years	Older panels
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	10+ years	Older pariolo
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	2-5 years	Older disconnect panel
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	7	10+ years	Older disconnect parier
	amp	Entire Ballating	'	LA	,	10+ years	
	Main Distribution Panels - Less than 400	Entire Building	1	EA	7	10+ years	
	amp	Littile Ballaling	'	LA	,	10+ years	
	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	10+ years	
	amp	Littile Building	ı	LA	U	10+ years	
atego	ry : Fire Protection		В	uilding	: Main		
			_			Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar			,				
ii C 7 (idi	Fire Alarm Panel	Entire Building	1	EA	3	1-2 years	Old relay technology
	Fire Alarm_System	Entire Building	62,706	SF	4	1-2 years	Old not reliable technology, no
	File Alaini_System	Entire Building	02,700	SI	4	1-2 years	strobes.
							stropes.
atego	ry : Mechanical		В	uilding	: Main		
						Recommend	
∂roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Hand	ling Systems						
	Air Handling Unit- Built Up- Multi Zone- Hot	Mechanical Room	1	EA	5	6-10 years	
	Water Coils - 25001 - 35000 cfm	Machanical Dagge	4	Г^	_	6.40	
	Air Handling Unit- Built Up- Multi Zone- Hot	Mechanical Room	1	EA	5	6-10 years	
	Water Coils - Greater than 35000 cfm	Machaniaal D	•	_ ^	-	40	Minanasanasian
	Air Intake	Mechanical Room	2	EΑ	5	10+ years	Minor corrosion on housing
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	10+ years	




Park Manor Elementary School 7037 S Rhodes AVENUE, Chicago, IL 60637

Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	5	10+ years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	60	LF	6	10+ years	
	and Ducts						
	Zone Dampers	Mechanical Room	32	EA	5	10+ years	DDC, manually operated. Software
							issue
	Outdoor Return Fans- Air Handling Unit	Roof	3	EA	6	10+ years	
	Type - Greater than 20000 CFM						
Boiler Sy	ystems						
DOILCE CY	Boiler Auxiliary- Scotch Marine- Hot Water	Boiler Room	2	EA	6	10+ years	
	Boiler - 2001 - 3000 MBH	Bollet Koolii	2	LA	O	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Non Condensing- Scotch Marine- Hot Water	Boiler Room	2	EA	6	10+ years	
	Boiler - 2001 - 3000 MBH	Bollet Koolii	2	LA	O	10+ years	
	Water Fill System	Boiler Room	1	EA	6	10+ years	
	Water i iii System	Doller Room	'	LA	O	10+ years	
Gas Boo	ster						
	Gas Booster	Mechanical Room	3	EA	5	6-10 years	
Heating I	Dovices						
пеашу	Unit Heater - Electric	Boiler Room	1	EA	5	2-5 years	
	Unit Heater - Gas	Boiler Room	1	EA	6		
	Fin Tube - Electric	Entire Building	34	LF	6	10+ years 10+ years	
			-	EA			
	Wall Heater - Electric	Entire Building	11		6	10+ years	
	Wall Heater - Electric	Entire Building	1	EA	5	10+ years	
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	300	LF	6	10+ years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	2	EA	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Mechanical Room	2	EA	6	6-10 years	
Tempera	ature Control	Entire Building	62,706	SF	4	0.1 year	DDC actuators are manually
	DDC System	Entire building	62,706	or	4	0-1 year	operated. Software has not worked in years. Software needs to be corrected
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	Serve unit heaters
	Thermostats - DDC	Entire Building	30	EA	6	6-10 years	DDC software does not work
Ventilatio	on.						
vendiado	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	



Park Manor Elementary School 7037 S Rhodes AVENUE, Chicago, IL 60637

	tegory : Mechanical			uilding	. IVIAIII				
				J		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years			
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	5	6-10 years			
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	2-5 years			
	Roof Mounted Duct Work	Entire Building	70	LF	7	10+ years	Serve return fans		
Categor	ry : Plumbing		В	uilding	: Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Hot Wate	er								
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	2-5 years			
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	1	EA	6	6-10 years			
Piping									
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	62,706	SF	6	6-10 years	Per engineer, pipes are good, requiring occasional repair of leaks		
	Domestic Piping-Cold Water Risers	Entire Building	62,706	SF	6	6-10 years			
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	62,706	SF	6	6-10 years			
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	62,706	SF	6	6-10 years			
	Domestic Piping-Hot Water Return Lines	Entire Building	62,706	SF	6	6-10 years			
	Domestic Piping-Hot Water Return Risers	Entire Building	62,706	SF	6	6-10 years			
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	62,706	SF	6	6-10 years			
	Sanitary Piping	Entire Building	62,706	SF	6	10+ years			
	Storm Piping	Entire Building	62,706	SF	6	10+ years			
	Vent Piping	Entire Building	62,706	SF	6	10+ years			
Pumps									
	Pumps - Domestic Booster Pump-Simplex	Pump Room off the Boiler Room	1	EA	5	2-5 years			
Categor	ry : Room		В	uilding	: Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Administr	rative Suites/Offices								
	Ceiling - Plaster/Drywall	1st Floor gym office off stage	284	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor gym office off stage	2	EA	6	10+ years			
	Floor - Tile	1st Floor gym office off stage	284	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor gym office off stage	2	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor gym office off stage	703	SF	6	10+ years			







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drywall 2nd Floor office 211 338 SF 6 10+ vears Doors - Wood Doors inclu hw EΑ 6 2nd Floor office 211 1 10+ years Floor - Epoxy/ Painted 2nd Floor office 211 338 SF 7 10+ years Lighting - Pendent/Surface 2 EΑ 7 2nd Floor office 211 6-10 years SF Walls - Plaster/Drywall 2nd Floor office 211 930 6 10+ years SF Ceiling - Plaster/Drywall 3rd floor office #311 340 6 10+ years Doors - Wood Doors inclu hw 3rd floor office #311 EΑ 6 10+ years 1 SF Floor - Epoxy/ Painted 3rd floor office #311 340 7 10+ years Lighting - Pendent/Surface 3rd floor office #311 2 EΑ 7 10+ years Walls - Plaster/Drywall SF 3rd floor office #311 885 6 10+ years SF Ceiling - Exposed Custodian office outside gvm 302 6 10+ years Doors - Steel Doors incl hw Custodian office outside gym 1 EΑ 6 10+ years Floor - Tile Custodian office outside gym 302 SF 6 10+ years EΑ 6 Lighting - Pendent/Surface Custodian office outside gym 2 6-10 years Walls - Plaster/Drywall Custodian office outside gym SF 6 883 10+ years Ceiling - Plaster/Drywall SF 6 Engineer's office 203 10+ years Doors - Wood Doors inclu hw EΑ Engineer's office 1 6 10+ years Floor - Concrete Engineer's office 203 SF 5 2-5 years EΑ Lighting - Pendent/Surface Engineer's office 5 6 6-10 years Walls - Plaster/Drywall Engineer's office 794 SF 6 10+ years Work SInk Engineer's office 1 EΑ 7 10+ years Lunchroom office SF 10+ years Ceiling - Lay-in 40 6 Doors - Wood Doors inclu hw 6 Lunchroom office 1 EΑ 10+ years SF Floor - Terrazzo Lunchroom office 40 6 10+ years 2 EΑ 6 6-10 years Lighting - Lay-in Lunchroom office Walls - Plaster/Drywall Lunchroom office 171 SF 6 10+ years Ceiling - Plaster/Drywall SF Office 312 270 4 0-1 year Water damage. Doors - Wood Doors inclu hw Office 312 EΑ 5 0-1 year Missing door handle 1 SF Floor - Tile Office 312 270 6 10+ years Lighting - Pendent/Surface Office 312 3 EΑ 7 10+ years Power Distribution Office 312 4 EΑ 7 10+ years Walls - Plaster/Drywall Office 312 572 SF 6 10+ years 7 Work SInk Office 312 FΑ 10+ years 1 Ceiling - Plaster/Drywall Principal's office 232 SF 6 10+ years Doors - Wood Doors inclu hw Principal's office 2 EΑ 6 10+ years SF 6 Floor - Tile Principal's office 232 10+ years Lighting - Pendent/Surface Principal's office 4 EΑ 7 6-10 years Walls - Plaster/Drywall Principal's office 718 SF 6 10+ years AC Unit main office 1 EΑ 7 6-10 years SF Ceiling - Plaster/Drywall main office 486 6 10+ vears Doors - Wood Doors inclu hw main office EΑ 6 10+ years 1 SF 6 Floor - Tile main office 486 10+ years Lighting - Pendent/Surface main office 7 EΑ 6 10+ years SF 7 Storage/ Closet main office 57 10+ years





	ry : Room		В	uilding	: Main	,,	037 3 Kilodes Avende, Chicago, ie 60637
24.590						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	main office	830	SF	6	10+ years	
	Ceiling - Plaster/Drywall	office 300, floor 3.5b	260	SF	6	10+ years	
	Doors - Transom Window	office 300, floor 3.5b	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	office 300, floor 3.5b	1	EA	6	10+ years	
	Floor - Wood	office 300, floor 3.5b	260	SF	5	2-5 years	
	Lighting - Pendent/Surface	office 300, floor 3.5b	3	EA	7	10+ years	
	Walls - Plaster/Drywall	office 300, floor 3.5b	591	SF	6	10+ years	
_Gvmnas	ia						
	Bleacher Seating	1st Floor	367	EA	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	5,354	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	9	EΑ	6	10+ years	
	Floor - Tile	1st Floor	5,354	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	50	EA	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	1,374	SF	6	10+ years	
	Stage Curtain	1st Floor	3	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Tile	1st Floor	42	LF	6	10+ years	
	Storage/ Closet	1st Floor	136	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	5,756	SF	6	10+ years	
	Walls - Flastel/Drywall	151 [100]	5,750	SF	O	10+ years	
_Kitchen							
	Ceiling - Lay-in	1st Floor	472	SF	6	10+ years	
	Floor - Terrazzo	1st Floor	472	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	7	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	50	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	407	SF	6	10+ years	
Library	A C I Init	Ond Floor			7	0.40	
	AC Unit	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	92	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,663	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,651	SF	6	10+ years	0 1 1/1:
	Floor - Tile	2nd Floor	12	SF	4	1-2 years	Cracked/chipped.
	Lighting - Pendent/Surface	2nd Floor	29	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,910	SF	6	10+ years	
Lunch &	Multipurpose Room						
	AC Unit	1st Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	1,720	SF	6	10+ years	
	3 7		.,. 20		-	- ,	





Catego	ry : Room		R	uilding	: Main		037 S Rhodes AVENUE, Chicago, IL 6063.
Outogo	, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,			unung			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
O. Gup	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years	
	Floor - Tile	1st Floor	1,720	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	25	EA	6	10+ years	
	Serving Line	1st Floor	20	LF	6	10+ years	
	Storage/ Closet	1st Floor	135	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,341	SF	6	10+ years	
MDF ID	F						
<u></u>	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	100	SF	7	10+ years	
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	
	Willdow Ale Gliik	2110111001	'	L/\	•	o to years	
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	1,325	SF	7	10+ years	
	Janitor's Closet	1st Floor	30	SF	5	10+ years	
	Janitor's Closet	1st Floor	11	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	331	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	677	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	2,282	SF	5	10+ years	
	Storage Room	1st Floor	64	SF	5	10+ years	
	Janitor's Closet	2nd Floor	15	SF	5	10+ years	
	Janitor's Closet	2nd Floor	57	SF	5	10+ years	
	Janitor's Closet	3rd Floor	18	SF	5	10+ years	
Restroor	n						
	Accessories	107a	45	SF	7	6-10 years	
	Ceiling - Lay-in	107a	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	107a	1	EA	6	10+ years	
	Floor - Tile	107a	45	SF	6	10+ years	
	Lavatory	107a	1	EA	6	10+ years	
	Lighting - Lay-in	107a	1	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	107a	87	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	107a	87	SF	6	10+ years	
	Water Closet	107a	1	ĒΑ	6	10+ years	
	Accessories	109a	38	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	109a	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	109a	1	EA	6	10+ years	
	Floor - Tile	109a	38	SF	6	10+ years	
	Lavatory	109a	1	EA	6	10+ years	
	Lighting - Pendent/Surface	109a	1	EA	6	10+ years	
	Partitions	109a 109a	1	EA	7	10+ years	
	Walls - Plaster/Drywall	109a 109a	240	SF	6	10+ years	
	Water Closet	109a 109a	1	EA	7	10+ years	
	vvaidi Ciusti	103a	I .	ĽA	,	iot years	







Building: Main Category: Room Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Accessories 1st Floor boys 341 SF 6-10 years 7 341 SF Ceiling - Plaster/Drywall 1st Floor boys 6 10+ years Doors - Wood Doors inclu hw 1st Floor boys 2 EΑ 6 10+ years Floor - Tile Ceramic/ Porcelain SF 6 1st Floor boys 341 10+ years 7 Floor Drain 1st Floor boys 2 EΑ 10+ years Hand Dryer 7 1st Floor boys 1 EΑ 6-10 years 1st Floor boys 1 EΑ 10+ years Lavatory 6 Lighting - Pendent/Surface 1st Floor boys 9 EΑ 6 6-10 years **Partitions** 1st Floor boys 6 EΑ 5 10+ years Urinals 1st Floor boys 10 EΑ 6 10+ years Walls - Plaster/Drywall 1st Floor boys 477 SF 6 10+ years Walls - Structural Glazed Tile 1st Floor boys 477 SF 6 10+ years Water Closet 1st Floor boys 6 EΑ 6 10+ years SF 7 Accessories 1st Floor girls 336 6-10 years Ceiling - Plaster/Drywall 1st Floor girls SF 336 6 10+ years Doors - Wood Doors inclu hw 2 FΑ 6 1st Floor girls 10+ years Floor - Terrazzo 308 SF 1st Floor airls 6 10+ years SF Floor - Tile 1st Floor girls 28 6 10+ years EΑ Floor Drain 1st Floor airls 1 7 10+ vears Hand Dryer 1st Floor girls 1 EΑ 7 6-10 years Lavatory 1st Floor girls 1 EΑ 6 10+ years Lighting - Pendent/Surface 9 6 1st Floor girls EΑ 6-10 years 12 EΑ 5 **Partitions** 1st Floor girls 10+ years SF Walls - Plaster/Drywall 1st Floor girls 509 6 10+ years Walls - Structural Glazed Tile 1st Floor girls 509 SF 6 10+ years Water Closet 1st Floor airls 12 EΑ 6 10+ years SF 7 Accessories 2nd Floor boys 424 6-10 years Ceiling - Plaster/Drywall 2nd Floor boys 424 SF 6 10+ years Doors - Wood Doors inclu hw EΑ 2nd Floor boys 2 6 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor boys 424 SF 6 10+ years 2nd Floor boys Floor Drain 2 FΑ 7 10+ vears Hand Drver 2nd Floor boys 1 EΑ 7 6-10 years 2nd Floor boys 1 FΑ 6 10+ vears Lavatory Lighting - Pendent/Surface 2nd Floor boys 9 FΑ 6 6-10 years 6 5 **Partitions** 2nd Floor boys EΑ 10+ years EΑ 6 Urinals 2nd Floor boys 10 10+ years Walls - Plaster/Drywall SF 2nd Floor boys 515 6 10+ years Walls - Structural Glazed Tile 515 SF 2nd Floor boys 6 10+ years Water Closet 2nd Floor boys 6 EΑ 6 10+ years SF 7 Accessories 2nd Floor airls 316 6-10 years SF Ceiling - Plaster/Drywall 2nd Floor girls 316 6 10+ years Doors - Wood Doors inclu hw 2nd Floor airls 3 FΑ 6 10+ years Floor - Terrazzo 2nd Floor girls 316 SF 6 10+ years Floor Drain 7 2nd Floor girls EΑ 10+ years

Campus Name: Park Manor Page : 10 of 23 Assessment Date: 08/19/2020





atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	2nd Floor girls	1	EA	7	6-10 years	
	Lavatory	2nd Floor girls	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor girls	5	EΑ	6	6-10 years	
	Partitions	2nd Floor girls	10	EA	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor girls	408	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor girls	408	SF	6	10+ years	
	Water Closet	2nd Floor girls	10	EA	6	10+ years	
	Accessories	3rd Floor boys	426	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor boys	426	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor boys	4	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor boys	426	SF	6	10+ years	
	Floor Drain	3rd Floor boys	2	EA	7	10+ years	
	Hand Dryer	3rd Floor boys	1	EA	7	6-10 years	
	Lavatory	3rd Floor boys	6	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor boys	9	EA		6-10 years	
	Partitions		6	EA	6		
		3rd Floor boys	_		5	10+ years	
	Urinals	3rd Floor boys	8	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor boys	496	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor boys	496	SF	6	10+ years	
	Water Closet	3rd Floor boys	6	EA	6	10+ years	
	Accessories	3rd Floor girls	316	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor girls	316	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor girls	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor girls	316	SF	6	10+ years	
	Floor Drain	3rd Floor girls	1	EA	7	10+ years	
	Hand Dryer	3rd Floor girls	1	EA	7	6-10 years	
	Lavatory	3rd Floor girls	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor girls	5	EA	6	6-10 years	
	Partitions	3rd Floor girls	10	EA	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor girls	328	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor girls	328	SF	6	10+ years	
	Water Closet	3rd Floor girls	10	EA	6	10+ years	
		3rd floor girls 3rd floor accessible unisex, north	90	SF	7	6-10 years	
	Accessories		90	SF	1	0-10 years	
	Osilian Disease/Deservell	end	00	SF	^	40	
	Ceiling - Plaster/Drywall	3rd floor accessible unisex, north	90	21	6	10+ years	
		end			_		
	Doors - Wood Doors inclu hw	3rd floor accessible unisex, north	1	EA	7	10+ years	
		end					
	Floor - Tile Ceramic/ Porcelain	3rd floor accessible unisex, north	90	SF	6	10+ years	
		end					
	Floor Drain	3rd floor accessible unisex, north	1	EA	7	10+ years	
		end				•	
	Hand Dryer	3rd floor accessible unisex, north	1	EA	7	10+ years	
	<i>j</i> -	end	•		-	- ,	







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lavatory 3rd floor accessible unisex, north FΑ 10+ years 7 end Lighting - Pendent/Surface 3rd floor accessible unisex, north 1 FΑ 7 10+ years end Walls - Plaster/Drywall 3rd floor accessible unisex, north 452 SF 6 10+ years end Water Closet EΑ 3rd floor accessible unisex, north 1 7 10+ years end Accessories Engineer's toilet 12 SF 7 6-10 years SF Ceiling - Plaster/Drywall Engineer's toilet 12 10+ years 6 Doors - Wood Doors inclu hw Engineer's toilet 1 EΑ 6 10+ years Floor - Concrete Engineer's toilet 12 SF 7 10+ years Lighting - Pendent/Surface EΑ 6 6-10 years Engineer's toilet 1 5 **Partitions** Engineer's toilet 1 EΑ 10+ years Walls - Plaster/Drywall SF Engineer's toilet 36 6 10+ years Water Closet FΑ 6 Engineer's toilet 1 10+ years 25 SF 7 Accessories Lunch Room Toilet 6-10 years SF Ceiling - Plaster/Drywall Lunch Room Toilet 25 6 10+ years Doors - Wood Doors inclu hw Lunch Room Toilet 1 EΑ 6 10+ years Floor - Tile Lunch Room Toilet 25 SF 6 10+ years Lavatory Lunch Room Toilet 1 EΑ 6 10+ years Lunch Room Toilet 7 Lighting - Wall Mounted 1 EΑ 10+ years 70 SF Walls - Plaster/Drywall Lunch Room Toilet 6 10+ years SF Walls - Tile Ceramic/ Porcelain Lunch Room Toilet 70 6 10+ years Water Closet EΑ 7 Lunch Room Toilet 1 10+ years SF Accessories Main office toilet room 52 7 6-10 years SF Ceiling - Plaster/Drywall Main office toilet room 52 6 10+ years Doors - Wood Doors inclu hw Main office toilet room EΑ 6 1 10+ years SF Floor - Tile Main office toilet room 52 6 10+ years Lavatory Main office toilet room 1 EΑ 6 10+ years Main office toilet room Lighting - Wall Mounted 1 FΑ 6 10+ vears **Partitions** Main office toilet room 1 EΑ 7 10+ years Walls - Plaster/Drywall SF 328 6 Main office toilet room 10+ years Water Closet Main office toilet room FΑ 7 1 10+ years SF 7 Accessories Principal's toilet 98 6-10 years Ceiling - Plaster/Drywall SF Principal's toilet 98 6 10+ years Doors - Wood Doors inclu hw Principal's toilet 1 EΑ 6 10+ years Floor - Tile 98 SF Principal's toilet 6 10+ years Lavatory Principal's toilet 1 EΑ 6 10+ years Lighting - Pendent/Surface 7 Principal's toilet 1 EΑ 10+ years Walls - Plaster/Drywall SF Principal's toilet 443 6 10+ years FΑ 7 Water Closet Principal's toilet 10+ years 1 Accessories boiler room toilet 14 SF 7 6-10 years SF Ceiling - Plaster/Drywall boiler room toilet 14 10+ years





Category : Room

rous	Itom Type	Location	Ouantitu	LIOM	Donk	Recommend	Comments
roup	Item - Type Doors - Steel Doors incl hw	Location	Quantity	UOM EA	Rank	Replacement	Comments
		boiler room toilet	1		6 4	10+ years	Class data via rata d
	Floor - Concrete	boiler room toilet	14	SF		0-1 year	Floor deteriorated.
	Lighting - Pendent/Surface	boiler room toilet	1	EA	6	6-10 years	Daint anadian and analism
	Walls - Masonry	boiler room toilet	129	SF	5	0-1 year	Paint cracking and peeling.
	Water Closet	boiler room toilet	1	EA	6	10+ years	
ategor	y : Classroom		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	m #106 (Office)		,				
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	804	SF	6	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Floor - Tile	1st Floor	804	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	40	LF	6	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,385	SF	6	10+ years	
	·		,			,	
lassroor	m #107 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	918	SF	6	10+ years	
	Doors - Side-lite	1st Floor	9	SF	6	10+ years	
	Doors - Transom Window	1st Floor	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	918	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	162	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,174	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassrooi	m #108 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	4	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	816	SF	6	10+ years	
	Doors - Side-lite	1st Floor	9	SF	7	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Lighting 1 chacht/banaoc	1301 1001	17	L/\	,	ioi years	

Building: Main





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	34	LF	6	6-10 years	
	Storage/ Closet	1st Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,399	SF	6	10+ years	
lassroc	om #109 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	972	SF	6	10+ years	
	Doors - Transom Window	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	972	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	6	10+ years	
	Marker Board	1st Floor	13	LF	6	6-10 years	
	Storage/ Closet	1st Floor	73	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,440	SF	6	10+ years	
	Walls Flastel/Dlywall	13011001	1,770	O.	Ü	101 years	
lassroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	836	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	836	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,422	SF	6	10+ years	
lassroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	816	SF	4	0-1 year	Tiles popping up and buckling, tile
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	cracked and missing
	Marker Board	2nd Floor	34	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,446	SF	6	10+ years	
locaroa	om #203 (Office)						







Catego	ry : Classroom		R	uilding	: Main	,,	037 3 KIIOUES AVENUE, CITICAGO, IL 60637
Jaiogo	. ,						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	828	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	828	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,387	SF	6	10+ years	
_Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	804	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	804	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,389	SF	6	10+ years	
_Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	26	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,399	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	





Catego	ry : Classroom		В	uilding	: Main	-	037 3 Kilodes AVENUE, Chicago, IL 60037
3 4.0 90	. ,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	26	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,399	SF	6	10+ years	
Classroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,399	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
<u> </u>	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	864	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	864	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,446	SF	6	10+ years	
Classro	om #301 (Regular Classroom)						
CIGSSIUC	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	838	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	10+ years	
	Floor - Tile	3rd Floor	838	SF	6	10+ years 10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	SF EA	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,338	SF SF	<i>7</i> 6	10+ years 10+ years	
	•		1,,555		-	- ,	
Classroo	om #302 (Multi Purpose Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	





Category : Classroom			В						
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Casework	3rd Floor	6	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	824	SF	6	10+ years			
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile	3rd Floor	824	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years			
	Marker Board	3rd Floor	16	LF	6	6-10 years			
	Storage/ Closet	3rd Floor	54	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,350	SF	6	10+ years			
Classroc	m #303 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	12	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years			
	Chalk Board	3rd Floor	16	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile	3rd Floor	816	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years			
	Marker Board	3rd Floor	16	LF	6	6-10 years			
	Storage/ Closet	3rd Floor	28	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,341	SF	6	10+ years			
Classroc	m #304 (Regular Classroom)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Casework	3rd Floor	6	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	810	SF	6	10+ years			
	Chalk Board	3rd Floor	10	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile	3rd Floor	810	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years			
	Storage/ Closet	3rd Floor	54	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,334	SF	6	10+ years			
Classroc	m #305 (Science Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	38	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years			
	Chalk Board	3rd Floor	6	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	10	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years			
	Floor - Tile	3rd Floor	816	SF	6	10+ years			





Category : Classroom			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,341	SF	6	10+ years	
	Work Sink	3rd Floor	4	EA	7	10+ years	
Classroc	om #306 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	810	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	10+ years	
	Floor - Tile	3rd Floor	810	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7		
	Walls - Plaster/Drywall	3rd Floor	1,334	SF	6	10+ years	
	vvalis - Plaster/Drywali	3rd Floor	1,334	SF	6	10+ years	
Classroc	om #307 (Art Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	824	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	824	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,350	SF	6	10+ years	
lassror	om #308 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	10+ years	
	Floor - Tile	3rd Floor	808	SF	6	•	
	Floor - Tile Floor - Tile	3rd Floor	8	SF SF	4	10+ years 0-1 year	Missing/chipped.
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	-	wiissii ig/ci iippeu.
				LF	6	10+ years	
	Marker Board	3rd Floor	16			6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,341	SF	6	10+ years	
Nooros	om #309 (Computer Lab)						





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	864	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	918	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	50	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,394	SF	6	10+ years	
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	828	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	828	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,354	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	3,946	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	10	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	10	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	30	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	3,916	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	33	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	5,412	SF	6	10+ years	
	walls - Flastel/Diywall		0,712				
	Walls - Flaster/Drywaii Walls - Structural Glazed Tile	1st Floor		SF	6	10+ years	
	Walls - Structural Glazed Tile		75 926	SF	6 6	10+ years 10+ years	
		1st Floor	75			10+ years 10+ years 10+ years	
	Walls - Structural Glazed Tile Ceiling - Lay-in Ceiling - Plaster/Drywall	1st Floor 2nd Floor 2nd Floor	75 926	SF SF	6	10+ years 10+ years	
	Walls - Structural Glazed Tile Ceiling - Lay-in Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain	1st Floor 2nd Floor 2nd Floor 2nd Floor	75 926	SF SF SF EA	6 6	10+ years 10+ years 10+ years	
	Walls - Structural Glazed Tile Ceiling - Lay-in Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	75 926 1,781 1	SF SF SF EA EA	6 6 7	10+ years 10+ years 10+ years 10+ years	
	Walls - Structural Glazed Tile Ceiling - Lay-in Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	75 926 1,781 1 3 2,707	SF SF SF EA EA SF	6 6 7 7	10+ years 10+ years 10+ years 10+ years 10+ years	
	Walls - Structural Glazed Tile Ceiling - Lay-in Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	1st Floor 2nd Floor	75 926 1,781 1 3 2,707	SF SF EA EA SF EA	6 6 7 7 7 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Walls - Structural Glazed Tile Ceiling - Lay-in Ceiling - Plaster/Drywall Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	75 926 1,781 1 3 2,707	SF SF SF EA EA SF	6 6 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years	







Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	3rd Floor	144	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,563	SF	6	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,707	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	22	EA	7	10+ years	
	Student Lockers - One Tier	3rd Floor	153	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5,242	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Auditorium Vestibule	257	SF	6	10+ years	
	Doors - Steel Doors incl hw	Auditorium Vestibule	5	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Auditorium Vestibule	188	SF	5	10+ years	
	Lighting - Pendent/Surface	Auditorium Vestibule	5	EA	6	6-10 years	
	Stairs - Concrete Stairs	Auditorium Vestibule	92	LF	6	10+ years	
	Walls - Structural Glazed Tile	Auditorium Vestibule	482	SF	6	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
Stairs							
<u> Ctarro</u>	Ceiling - Plaster/Drywall	North	1,035	SF	6	10+ years	
	Floor - Tile	North	958	SF	6	10+ years	
	Handrails	North	172	LF	5	10+ years	
	Lighting - Lay-in	North	1	EA	6	10+ years	
	Lighting - Pendent/Surface	North	8	EA	7	10+ years	
	Stairs - Rubber	North	390	LF	6	10+ years	
	Walls - Plaster/Drywall	North	3,129	SF	6	10+ years	
	Walls - Structural Glazed Tile	North	64	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	1,035	SF	6	10+ years	
	Floor - Tile	South	958	SF	6	10+ years	
	Handrails	South	172	LF	5	10+ years	
	Lighting - Lay-in	South	1	EA	6	10+ years	
	Lighting - Pendent/Surface	South	8	EA	6	10+ years	
	Stairs - Rubber	South	390	LF	6	10+ years	
	Walls - Plaster/Drywall	South	3,129	SF	6	10+ years	
	Walls - Structural Glazed Tile	South	64	SF	6	10+ years	



Category : Site Building : Site

Category : Site			Building : Site					
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
•		Location	Quantity	UOIVI	Naiik	Replacement	Comments	
ivil/Dra	Civil/ Drainage - Catch Basin	Entire Site	3	EA	6	10+ years		
	Civil/ Drainage - Catch Basin Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years		
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	6	10+ years		
	Olvin Brainage Olic Marillole	Littlic Oilo	J		O	101 years		
encing								
	Fencing - New Standard Ornamental	Entire Site	482	LF	6	10+ years		
	Fencing - New Standard Ornamental	Entire Site	620	LF	6	10+ years	Minor rusting.	
	Fencing - New Standard Ornamental	Entire Site	15	LF	4	1-2 years	Fencing posts out of alignment	
andsca	pe							
	Landscape - Grass	Entire Site	2,783	SF	6	10+ years		
	Landscape - Hardscape- Asphalt	Entire Site	3,000	SF	6	10+ years		
	Landscape - Hardscape- Concrete	Entire Site	300	SF	7	10+ years		
	Lighting - Pole Mounted	Entire Site	4	EA	7	10+ years		
	Parkway trees	Entire Site	30	EA	7	10+ years		
	Parkway trees	Entire Site	2	EA	4	1-2 years	Missing.	
	Planting Beds/ Area	Entire Site	3,318	SF	6	10+ years	9.	
	Play Area - Synthetic Turf Play Field	Entire Site	10,165	SF	6	10+ years		
	Trash Receptacles	Entire Site	2	EA	7	10+ years		
	·					·		
Parking								
	Concrete Curbs	North	493	LF	6	10+ years		
	Interior Plantings	North	330	LF	6	10+ years		
	Surface - Asphalt	North	13,915	SF	6	10+ years		
	Surface - Asphalt	North	2,125	SF	4	0-1 year	Cracking, potholes, and grass growing.	
	Trash Enclosure - Chain Links	North	1,450	SF	6	10+ years	g. 5 g.	
	Vehicular Screening	North	268	LF	7	10+ years		
	Surface - Asphalt	South	2,000	SF	4	1-2 years	Buckled and damaged by weeds	
Playgrou	and							
-aygrot	Equipment - School Age 5-12	South	2	EA	7	10+ years		
	Surface - Poured Surface	South	3,000	SF	4	0-1 year	Holes throughout.	
Sidewalk	(S							
vvull	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	7	10+ years		
	Sidewalks - Perimeter Sidewalks	Entire Site	15,009	SF	7	10+ years		
	Sidewalks - Perimeter Sidewalks	Entire Site	50	SF	4	1-2 years	Driveway apron is cracked.	
						*		
Signage								



Category : Site

Park Manor Elementary School

7037 S Rhodes AVENUE, Chicago, IL 60637

Calego	y . Oile		<u> </u>	unung	. Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Building Mounted Back Lighted	Entire Site	1	EA	7	10+ years	
	w/ LED						

Building . Site

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Park Manor Page : 22 of 23 Assessment Date: 08/19/2020

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			•	•		•			
Art Room	Regular Classroom	3rd Floor	307	307	878	165	75	N	N
Computer Lab	Regular Classroom	3rd Floor	309	309	918	150	60	N	N
Kindergarten	Kindergarten	1st Floor	109	109	1,045	160	60	N	N
Multi Purpose Room	Regular Classroom	3rd Floor	302	302	878	150	60	N	N
Office	Regular Classroom	1st Floor	106	106	858	160	60	N	N
Office	Regular Classroom	1st Floor	108	108	870	160	60	N	N
Office	Regular Classroom	2nd Floor	203	203	852	165	45	N	N
Pre School	Pre School	1st Floor	107	107	1,080	120	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	890	165	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	870	150	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	858	150	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	840	165	45	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	870	165	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	870	165	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	918	150	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	892	165	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	844	165	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	864	150	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	864	150	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	870	150	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	882	150	60	N	N
Science Classroom	Regular Classroom	3rd Floor	305	305	870	165	75	N	N