

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1910	5	455,800
Campus Total			455,800

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	#1 Exit - W	3	EA	4	1-2 years	This is a wood door that has a thin layer of sheet metal nailed to the face
	Exterior Doors - Transom Lite	#1 Exit - W	1	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	#10 Exit - N	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#10 Exit - N	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#10 Exit - N	12	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#11 - N	4	EA	5	10+ years	Frame is corroding at base
	Exterior Doors - Transom Lite	#11 - N	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#12 Exit - N	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#12 Exit - N	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#12 Exit - N	48	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#13 - W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#13 - W	1	EA	6	10+ years	Glazing putty needs to be redone
	Exterior Stairs - Concrete	#13 - W	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#14 - W	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#14 - W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#14 - W	16	LF	5	10+ years	
	Exterior Doors - Exterior Wood Door	#15 Exit - W	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#15 Exit - W	2	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	#16 - W	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#16 - W	2	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	#17 Exit - W	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#17 Exit - W	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#18 - W	4	EA	6	10+ years	

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Doors - Transom Lite	#18 - W	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#19 - Interior Courtyard	2	EA	6	10+ years	Base of door is corroding and needs repair and painting
	Exterior Doors - Transom Lite	#19 - Interior Courtyard	1	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	#19.5 - Interior Courtyard	1	EA	4	1-2 years	Door has several patches due to rodent infestation
	Exterior Stairs - Concrete	#19.5 - Interior Courtyard	4	LF	5	1-2 years	Repair broken concrete
	Exterior Doors - Exterior Steel Door	#2 - S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 - S	20	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#20 - Interior Courtyard	4	EA	4	2-5 years	
	Exterior Doors - Transom Lite	#20 - Interior Courtyard	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#20 - Interior Courtyard	45	LF	5	1-2 years	Concrete landing is spalling has broken areas creating trip hazards
	Exterior Doors - Overhead Rolling/ Garage Door	#20.5 - Interior Courtyard	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#20.5 - Interior Courtyard	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#20.5 - Interior Courtyard	10	LF	5	1-2 years	Vegetation growth in cracks
	Exterior Doors - Exterior Wood Door	#21 - Interior Courtyard	4	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#21 - Interior Courtyard	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	#22 - Interior Courtyard	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#22 - Interior Courtyard	3	LF	5	6-10 years	
	Exterior Doors - Exterior Steel Door	#22.5 Exit - Interior Courtyard	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#22.5 Exit - Interior Courtyard	15	LF	5	6-10 years	
	Exterior Doors - Exterior FRP Door	#23 - Interior Courtyard	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#23 - Interior Courtyard	4	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#24 - Interior Courtyard	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#24 - Interior Courtyard	4	LF	7	10+ years	
	Exterior Doors - Exterior Wood Door	#25 Exit - Interior Courtyard	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#25 Exit - Interior Courtyard	18	LF	7	10+ years	
	Entrance Control - Audio and Video	#3 Main - S	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#3 Main - S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 Main - S	3	EA	6	10+ years	
	Power Door Operator and Controls	#3 Main - S	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#4 - S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 - S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#4 - S	30	LF	7	10+ years	
	Stair Handrail - Steel_ Stair Handrail	#4 - S	20	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#5 - E	3	EA	4	1-2 years	Base of doors and frames is showing extensive rusting
	Exterior Doors - Transom Lite	#5 - E	1	EA	6	10+ years	
	Ramps - Concrete	#5 - E	3	LF	5	0-1 year	Repair concrete ramp, it is broken with a piece missing
	Entrance Control - Audio and Video	#6 - E	1	EA	7	6-10 years	

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Doors - Exterior Steel Door	#6 - E	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 - E	4	EA	6	10+ years	
	Power Door Operator and Controls	#6 - E	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#7 Exit - E	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 Exit - E	4	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 Exit - E	12	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#8 - E	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#8 - E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 - E	10	LF	4	1-2 years	Separation of stairs.
	Exterior Doors - Overhead Rolling/ Garage Door	#8.5 - E	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8.5 - E	2	EA	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage Door	#8.7 - E	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#9 - N	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#9 - N	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 - N	12	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#9 - N	40	LF	7	10+ years	
	Ramps - Concrete	#9 - N	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#9 - N	12	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	F1-Fire Escape Exit	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	F1-Fire Escape Exit	1	EA	6	10+ years	
	Exterior Stairs - Stone	F1-Fire Escape Exit	5	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	F10- Fire Escape Exit	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	F10- Fire Escape Exit	1	EA	6	10+ years	
	Exterior Stairs - Stone	F10- Fire Escape Exit	5	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	F11-Fire escape exit	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	F11-Fire escape exit	1	EA	6	10+ years	
	Exterior Stairs - Concrete	F11-Fire escape exit	5	LF	5	1-2 years	Concrete cracking at edge and chips falling off.
	Exterior Doors - Exterior Steel Door	F2-Fire escape exit	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	F2-Fire escape exit	1	EA	6	10+ years	
	Exterior Stairs - Stone	F2-Fire escape exit	5	LF	5	1-2 years	Broken terra-cotta
	Exterior Doors - Exterior Steel Door	F3-Fire Escape Exit	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	F3-Fire Escape Exit	1	EA	6	10+ years	
	Exterior Stairs - Concrete	F3-Fire Escape Exit	5	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	F4-Fire Escape Exit	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	F4-Fire Escape Exit	1	EA	6	10+ years	
	Exterior Stairs - Concrete	F4-Fire Escape Exit	5	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	F5-Fire Escape Exit	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	F5-Fire Escape Exit	1	EA	5	10+ years	
	Exterior Stairs - Concrete	F5-Fire Escape Exit	6	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	F6-Fire Escape Exit	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	F6-Fire Escape Exit	1	EA	6	10+ years	

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Stairs - Concrete	F6-Fire Escape Exit	5	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	F7-Fire Escape Exit	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	F7-Fire Escape Exit	1	EA	6	10+ years	
	Exterior Stairs - Concrete	F7-Fire Escape Exit	5	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	F8-Fire escape Exit	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	F8-Fire escape Exit	1	EA	6	10+ years	
	Exterior Stairs - Concrete	F8-Fire escape Exit	5	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	F9-Fire escape exit	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	F9-Fire escape exit	1	EA	6	10+ years	
	Exterior Stairs - Concrete	F9-Fire escape exit	6	LF	6	10+ years	
Fire Escape							
	Fire Escape	NE Elevations of Parking Courtyard	344	LF	5	10+ years	There is quite a bit of corrosion, but not severe. Prep and painting recommended.
	Fire Escape	NE Elevations of Parking Courtyard	1	LF	5	0-1 year	Angle has detached from fire escape, and rod at masonry has become corroded and deteriorated.
Foundation							
	Foundation - Concrete	Entire Building	3,944	LF	7	10+ years	
	Foundation - Concrete	Entire Building	50	LF	6	0-1 year	Water leaks from boiler room
	Superstructure - Steel with Clay Tile Arch	Entire Building	455,800	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	58	EA	6	6-10 years	
Roof System							
	Downspouts - Exterior Downspouts	Asphalt Shingle Roof to West of Interior Courtyard	5	LF	4	1-2 years	Coming apart at the seems.
	Roof - Asphalt Shingle	Asphalt Shingle Roof to West of Interior Courtyard	752	SF	5	10+ years	Roofing does not appear to be professionally done. Portions not finished and hanging off the edges.
	Roof Structure - Steel with Clay Tile Arch	Asphalt Shingle Roof to West of Interior Courtyard	752	SF	7	10+ years	
	Coping - Terra Cotta	Dome Roof Over Library	110	LF	7	10+ years	
	Coping - Terra Cotta	Dome Roof Over Library	50	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Dome Roof Over Library	120	LF	6	10+ years	
	Parapet - Parapet > 30"	Dome Roof Over Library	135	LF	7	10+ years	
	Parapet - Parapet > 30"	Dome Roof Over Library	25	LF	6	10+ years	
	Roof - Metal	Dome Roof Over Library	6,021	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Dome Roof Over Library	4,014	SF	7	10+ years	

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Downspouts - Exterior Downspouts	Main Roof	2,515	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	45	LF	5	1-2 years	Broken pipe
	Roof - Metal	Main Roof	5,229	SF	7	10+ years	
	Roof - Tile Shingle	Main Roof	70,021	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	75,250	SF	7	10+ years	
	Access Ladder - Metal	NE High Roof	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	NE High Roof	130	LF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	NE High Roof	10	LF	6	10+ years	
	Coping - Terra Cotta	NE High Roof	432	LF	7	10+ years	
	Coping - Terra Cotta	NE High Roof	200	LF	6	10+ years	Previous sealing was done directly over distressed mortar
	Downspouts - Exterior Downspouts	NE High Roof	356	LF	6	10+ years	
	Parapet - 16" - 30" Height	NE High Roof	290	LF	7	10+ years	
	Parapet - 16" - 30" Height	NE High Roof	30	LF	6	10+ years	
	Parapet - Parapet > 30"	NE High Roof	190	LF	7	10+ years	
	Parapet - Parapet > 30"	NE High Roof	15	LF	6	10+ years	
	Parapet - Parapet > 30"	NE High Roof	8	LF	4	0-1 year	Corner of parapet is falling off the face of the building
	Roof - Asphalt Gravel Ballast	NE High Roof	21,905	SF	6	6-10 years	
	Roof Hatch - Metal	NE High Roof	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	NE High Roof	21,905	SF	6	10+ years	There are broken and missing tiles
	Chimney - Metal Flue	NE Low Roof	6	LF	7	10+ years	
	Chimney - Metal Flue	NE Low Roof	10	LF	6	10+ years	
	Coping - Terra Cotta	NE Low Roof	243	LF	7	10+ years	
	Coping - Terra Cotta	NE Low Roof	30	LF	6	10+ years	
	Downspouts - Exterior Downspouts	NE Low Roof	125	LF	6	10+ years	
	Parapet - 16" - 30" Height	NE Low Roof	173	LF	7	10+ years	
	Parapet - Parapet < 16" Height	NE Low Roof	102	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	NE Low Roof	7,843	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	NE Low Roof	7,843	SF	7	10+ years	
	Access Ladder - Metal	SW High Roof	2	EA	4	0-1 year	Obsolete ladder not anchored at the base
	Access Ladder - Wood	SW High Roof	2	EA	4	0-1 year	This one latter is very unsafe, and the transition from ladder to ladder is dangerous
	Coping - Terra Cotta	SW High Roof	376	LF	7	10+ years	
	Coping - Terra Cotta	SW High Roof	100	LF	6	10+ years	
	Downspouts - Exterior Downspouts	SW High Roof	351	LF	6	10+ years	
	Downspouts - Exterior Downspouts	SW High Roof	5	LF	5	0-1 year	Repair damaged gutter
	Parapet - 16" - 30" Height	SW High Roof	238	LF	7	10+ years	
	Parapet - Parapet > 30"	SW High Roof	158	LF	6	10+ years	
	Parapet - Parapet > 30"	SW High Roof	80	LF	5	1-2 years	Spalling brick at base of parapet

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Roof - Asphalt Gravel Ballast	SW High Roof	9,511	SF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	SW High Roof	10	SF	3	0-1 year	Flashing is missing at mechanical duct penetration through brick
	Roof Hatch - Metal	SW High Roof	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	SW High Roof	9,521	SF	7	10+ years	
	Access Ladder - Metal	South Roof	6	EA	4	0-1 year	Three 25'+ ladders which are too dangerous and too wobbly, too high to climb
	Access Ladder - Metal	South Roof	3	EA	4	0-1 year	Ladders are not only obsolete but also are unsafe in the transition from one space to the next.
	Coping - Clay Tile	South Roof	257	LF	5	6-10 years	
	Downspouts - Interior Downspouts	South Roof	90	LF	6	6-10 years	
	Parapet - 16" - 30" Height	South Roof	156	LF	5	6-10 years	
	Parapet - Parapet < 16" Height	South Roof	101	LF	5	6-10 years	
	Roof - Modified Bitumen	South Roof	4,118	SF	5	6-10 years	Roof ladders and access points are dangerous and we could not access the roofs. Condition based on engineer's opinion.
	Roof Structure - Steel with Clay Tile Arch	South Roof	4,118	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Southwest Low Roof	140	LF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Southwest Low Roof	150	LF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Southwest Low Roof	20	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Southwest Low Roof	30	LF	6	10+ years	
	Coping - Clay Tile	Southwest Low Roof	72	LF	6	10+ years	
	Coping - Clay Tile	Southwest Low Roof	12	LF	5	1-2 years	Broken clay tile
	Coping - Clay Tile	Southwest Low Roof	40	LF	4	1-2 years	Clay tile this improperly installed. This has created for flashing installation or conflict with the flashing and poorcoverage of the masonry
	Coping - Terra Cotta	Southwest Low Roof	394	LF	7	10+ years	
	Coping - Terra Cotta	Southwest Low Roof	100	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Southwest Low Roof	153	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Southwest Low Roof	2	LF	5	1-2 years	Missing a section of downspout at interior courtyard
	Parapet - 16" - 30" Height	Southwest Low Roof	222	LF	7	10+ years	
	Parapet - 16" - 30" Height	Southwest Low Roof	38	LF	5	1-2 years	
	Parapet - 16" - 30" Height	Southwest Low Roof	20	LF	5	10+ years	
	Parapet - Parapet < 16" Height	Southwest Low Roof	214	LF	7	10+ years	
	Parapet - Parapet > 30"	Southwest Low Roof	40	LF	6	10+ years	

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Parapet - Parapet > 30"	Southwest Low Roof	40	LF	5	1-2 years	
	Roof - Asphalt Gravel Ballast	Southwest Low Roof	11,160	SF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Southwest Low Roof	40	SF	4	1-2 years	Soft spot under fire escape landing
	Roof - EPDM/ Synthetic Rubber	Southwest Low Roof	3,000	SF	6	10+ years	This ponding is present more than 48 hours
	Roof - Modified Bitumen	Southwest Low Roof	300	SF	6	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Southwest Low Roof	14,544	SF	7	10+ years	
	Access Ladder - Metal	Southwest high roof South	2	EA	5	2-5 years	
	Parapet - Parapet > 30"	Southwest high roof South	40	LF	6	10+ years	
	Roof - Modified Bitumen	Southwest high roof South	2,340	SF	6	6-10 years	Roof needs minor repairs and if possible a silver coating
	Roof Hatch - Metal	Southwest high roof South	1	EA	3	1-2 years	Inactive hatch
	Roof Structure - Steel with Clay Tile Arch	Southwest high roof South	2,340	SF	7	10+ years	
	Access Ladder - Metal	Southwest high roof north	1	EA	5	2-5 years	
	Parapet - Parapet > 30"	Southwest high roof north	40	LF	5	10+ years	
	Roof - Modified Bitumen	Southwest high roof north	2,340	SF	6	6-10 years	Roof needs minor repairs and if possible a silver coating
	Roof Structure - Steel with Clay Tile Arch	Southwest high roof north	2,340	SF	7	10+ years	
	Access Ladder - Metal	West Roof	2	EA	7	10+ years	
	Access Ladder - Metal	West Roof	1	EA	4	2-5 years	
	Coping - Clay Tile	West Roof	474	LF	7	10+ years	
	Downspouts - Exterior Downspouts	West Roof	225	LF	7	10+ years	
	Downspouts - Interior Downspouts	West Roof	350	LF	7	10+ years	
	Parapet - 16" - 30" Height	West Roof	350	LF	7	10+ years	
	Parapet - Parapet < 16" Height	West Roof	124	LF	7	10+ years	
	Roof - Modified Bitumen	West Roof	13,868	SF	7	10+ years	
	Roof Hatch - Metal	West Roof	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	West Roof	13,868	SF	7	10+ years	

Walls

	Canopy - Concrete/ Stucco	Entire Building	813	SF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	13,520	LF	6	10+ years	Copper cornice, difficult to see from the ground. Most sections of service from the rooftops are in good condition.
	Exterior Walls - Brick	Entire Building	71,470	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	25	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	63,870	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	130	SF	4	0-1 year	Cracked masonry and open joints near downspout at Southwest low roof Also open joints and brick and stone At South facade
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	11,050	SF	7	10+ years	

Category : Exterior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Walls - Terra Cotta	Entire Building	3,000	SF	6	10+ years	No graffiti, but dirty
	Exterior Walls - Terra Cotta	Entire Building	3,430	SF	5	10+ years	Some joints are completely open
	Exterior Walls - Terra Cotta	Entire Building	20	SF	4	1-2 years	Broken Stone
Windows							
	Clerestory - Glass Single-Pane	Entire Building	1,034	SF	6	10+ years	
	Clerestory - Glass Single-Pane	Entire Building	216	SF	4	1-2 years	Highly distressed windows, uncared-for, and rotten wood.
	Guard - Guards wire guard	Entire Building	6,550	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	20	SF	5	10+ years	
	Lintels - Brick	Entire Building	185	LF	6	10+ years	
	Lintels - Steel	Entire Building	1,590	LF	6	10+ years	
	Lintels - Steel	Entire Building	170	LF	4	0-1 year	Rusting and bowed steel angles
	Lintels - Terra Cotta	Entire Building	3,311	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	4	LF	4	0-1 year	Broken and missing lintel
	Skylite - Glass Single-Pane	Entire Building	2,450	SF	6	10+ years	
	Windows - Decorative	Entire Building	750	SF	6	2-5 years	
	Windows - Louver	Entire Building	344	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	31,599	SF	5	6-10 years	These windows are metal windows that resemble historical windows. They're in need of sealing and repainting
	Windows - Wood- Single-pane	Entire Building	20,700	SF	4	1-2 years	Many windows are inoperable, and the windows are obsolete
	Windows - Wood- Single-pane	Entire Building	800	SF	3	0-1 year	Many of these windows are falling apart and rotted with frames in window sashes not fitting properly. There are openings where the weather comes directly into the building through the windows

Category : Electrical

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emergency System							
	Emergency Generator- Outdoor- Natural Gas - 101 - 150 KW	Central Courtyard	1	EA	6	10+ years	
	Automatic Transfer Switch	Electrical Room	3	EA	6	10+ years	
	Security System - CCTV	Entire Building	455,800	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	455,800	SF	5	6-10 years	
	Exit Signs - Auditorium	Entire Building	19	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	126	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	12	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	8	EA	6	6-10 years	

Category : Electrical

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exit Signs - Gym	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	24	EA	6	6-10 years	
	Exit Signs - Pool	Entire Building	8	EA	6	6-10 years	
	Emergency Battery Packs - Auditorium and Aisle Lighting	Entire Building	14	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	5	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	45	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	10	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	24	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	5	EA	6	6-10 years	
	Emergency Battery Packs - Pool	Entire Building	6	EA	6	6-10 years	
	Emergency A/C Power - Auditorium and Aisle Lighting	Entire Building	9,695	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	46,793	SF	6	10+ years	
	Emergency A/C Power - Gym	Entire Building	3,892	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	6,026	SF	6	10+ years	
	Emergency A/C Power - Pool	Entire Building	2,947	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	2,193	SF	6	10+ years	

Main Service

	Main Electrical Service - 1200 A 277/480/3PH	Electrical Room	1	EA	7	10+ years	2010 installation
	Main Electrical Service - 2001 to 3000 A 277/480/3PH	Electrical Room	1	EA	6	6-10 years	Older switchgear, more than 30 years old
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	455,800	SF	6	6-10 years	

Power Distribution

	Lighting and Power Panels - 100 A	Entire Building	40	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	4	1-2 years	Old and deteriorated
	Lighting and Power Panels - Above 100 A	Entire Building	38	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	16	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	1-2 years	Old and deteriorated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	6	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	14	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	4	EA	7	10+ years	

Category : Electrical

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	7	EA	6	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	1	EA	4	2-5 years	Hot, corroded enclosure,
	Transformers - 277/480 - 120/208	Entire Building	1	EA	4	2-5 years	Corroded, not reliable, hot
	Transformers - 277/480 - 120/240	Entire Building	5	EA	6	10+ years	

Category : Fire Protection

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Fire Alarm</u>							
	Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Entire Building	455,800	SF	6	10+ years	
	Fire Alarm_System	Entire Building	455,800	SF	6	10+ years	

Category : Mechanical

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Air Conditioning</u>							
	Condensing Unit- Ground Mounted - Less than 5 tons	Entire Building	1	EA	6	6-10 years	Wall mounted, serves office
	Condensing Unit- Ground Mounted - Less than 5 tons	Entire Building	1	EA	6	6-10 years	Wall mounted, serves office
	Condensing Unit- Ground Mounted - Less than 5 tons	Entire Building	3	EA	6	6-10 years	Serve main office areas, above ceiling evaporators
	Condensing Unit- Ground Mounted - Less than 5 tons	Entire Building	5	EA	5	2-5 years	2010 installation, serve main office areas, minor surface corrosion.
	Chemical Pot Feeder	Roof	1	EA	6	10+ years	
	Chiller-Water Cooled- Cetrifugal - 301-400 tons	Roof	2	EA	6	10+ years	Serves air handlers only
	Cooling Tower - Closed Cell	Roof	2	EA	5	10+ years	Twin style, parallel connection. Motor needs to be replaced on second tower.
	Glycol Feed	Roof	1	EA	6	10+ years	
	Pipes - Chilled Water Pipe- Steel	Roof	500	LF	6	10+ years	Connect to dual temp pumps
	Pipes - Dual Temperature Pipe- Copper	Roof	3,000	LF	7	10+ years	

Air Handling Systems

	Fan Coil Unit- Celing Mounted - Electric	1st Floor	10	EA	6	2-5 years	Serve office areas, part of split systems,assessed as part of interiors
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Attic	2	EA	5	2-5 years	Serve north section of building
	Air Handling Unit- Built Up- Multi Zone- Dual	Mechanical Room - AHU-1	1	EA	6	10+ years	AHU 1, serves northwest front section

Category : Mechanical

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Temperature Coils - Greater than 35000 cfm						
	Air Intake	Mechanical Room - AHU-1	1	EA	6	10+ years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room - AHU-1	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-1	200	LF	5	10+ years	
	Zone Dampers	Mechanical Room - AHU-1	41	EA	5	10+ years	Per engineer, some zone dampers are manually operated
	Air Handling Unit- Built Up- Multi Zone- Dual	Mechanical Room - AHU-2	1	EA	6	10+ years	AHU-2, serves south end
	Temperature Coils - Greater than 35000 cfm						
	Air Intake	Mechanical Room - AHU-2	1	EA	6	10+ years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room - AHU-2	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-2	200	LF	5	10+ years	
	Zone Dampers	Mechanical Room - AHU-2	30	EA	5	10+ years	Per engineer, some zone dampers are manually operated
	Air Handling Unit- Built Up- Multi Zone- Dual	Mechanical Room - AHU-3	1	EA	6	10+ years	AHU 3, serves southeast corner
	Temperature Coils - Greater than 35000 cfm						
	Air Intake	Mechanical Room - AHU-3	1	EA	6	10+ years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room - AHU-3	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-3	200	LF	5	10+ years	
	Zone Dampers	Mechanical Room - AHU-3	17	EA	5	6-10 years	Per engineer, some dampers are manually operated
	Air Handling Unit- Built Up- Multi Zone- Dual	Mechanical Room - AHU-4	1	EA	6	10+ years	AHU 4, serves north area, located on first floor
	Temperature Coils - Greater than 35000 cfm						
	Air Intake	Mechanical Room - AHU-4	1	EA	6	10+ years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room - AHU-4	1	EA	6	10+ years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room - AHU-4	200	LF	5	10+ years	
	Zone Dampers	Mechanical Room - AHU-4	14	EA	5	6-10 years	A few dampers are manually operated
	Air Handling Unit- Built Up- Single Zone- Dual	Mechanical Room - AHU-5	1	EA	6	10+ years	AHU 5 serves northeast corner of school
	Temperature Coils - Greater than 35000 cfm						
	Air Intake	Mechanical Room - AHU-5	1	EA	6	10+ years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room - AHU-5	1	EA	6	10+ years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-5	150	LF	6	10+ years	
	Air Handling Unit- Built Up- Multi Zone- Dual	Mechanical Room - AHU-6	1	EA	6	6-10 years	AHU 6, serves auditorium and west side, area in under construction in 9-2020
	Temperature Coils - Greater than 35000 cfm						
	Air Intake	Mechanical Room - AHU-6	1	EA	6	6-10 years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room - AHU-6	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room - AHU-6	200	LF	5	6-10 years	

Category : Mechanical

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	and Ducts						
	Zone Dampers	Mechanical Room - AHU-6	35	EA	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Dual Temperature Coils - Greater than 35000 cfm	Mechanical Room - AHU-7	1	EA	4	2-5 years	AHU7, serves classrooms area
	Air Intake	Mechanical Room - AHU-7	1	EA	6	6-10 years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room - AHU-7	1	EA	6	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room - AHU-7	10	EA	4	1-2 years	Mechanical system is changed from high pressure 65 psi to low pressure 11 psi. Piping wasn't changed. Distance and pressure is not enough to bring back return. Steam coils are fill in with condensate
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-7	200	LF	6	6-10 years	
	Zone Dampers	Mechanical Room - AHU-7	32	EA	6	6-10 years	
	Outdoor Return Fans- inline Centrifugal - Greater than 20000 CFM	Roof	5	EA	6	10+ years	
	Roof Top Unit-Single Zone-Roof Mounted-Electric and DX Cooling with Self Contained Compressor - 11 - 20 tons	Roof	1	EA	5	6-10 years	Currently not used, operational, located at upper roof, serves west side
	Roof Top Unit-Single Zone-Roof Mounted-Electric and DX Cooling with Self Contained Compressor - 11 - 20 tons	Roof	1	EA	5	6-10 years	Currently not used, operational, located at upper roof, serves east side
Boiler Systems							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - Greater than 300 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Feed System	Boiler Room	1	EA	5	10+ years	
	Chemical Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	4	EA	6	10+ years	
	Condensate Pump	Boiler Room	2	EA	5	2-5 years	Per engineer, other condensate pump passes service life under auditorium.
	Condensate Pump	Boiler Room	2	EA	4	1-2 years	Corroded and significantly aged.
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	10+ years	Under maintenance
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Greater than 300 HP	Boiler Room	2	EA	6	10+ years	
	Piping - Condensate Pipe- Steel	Boiler Room	1,000	LF	6	2-5 years	Per engineer, minor condensate pipe repairs occasional done. Sections of pipe replaced with copper
	Piping - Steam Pipe- Steel	Boiler Room	1,000	LF	6	2-5 years	Per engineer, occasional steam pipe leaks repaired, minor, section of pipes replaced with copper

Category : Mechanical

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Steam Traps	Boiler Room	50	EA	5	2-5 years	
<u>Heat Exchangers</u>							
	Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	2	EA	6	10+ years	Serve 7 air handlers, connected to dual temp pumps, no hot water pump
<u>Heating Devices</u>							
	Radiators - Steam	Entire Building	14	EA	6	10+ years	Behind decorative grill
	Radiators - Steam	Entire Building	5	EA	5	6-10 years	Paint is deteriorated, per engineer, functional
	Wall Heater - Electric	Entire Building	15	EA	6	10+ years	
	Wall Heater - Electric	Entire Building	5	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	3	EA	4	0-1 year	Exposed insulated wires, older, deteriorated
	Fin Tube - Electric	Entire Building	30	LF	6	10+ years	Serves main office areas
	Fin Tube - Steam	Entire Building	150	LF	6	10+ years	
	Cabinet Heaters - With Steam Coil	Entire Building	10	EA	6	10+ years	
	Unit Heater - Electric	Entire Building	4	EA	5	2-5 years	
	Unit Heater - Steam	Entire Building	10	EA	6	10+ years	
<u>Mechanical Plumbing</u>							
	Dual Temperature Pump - Greater than 50 HP	Boiler Room	2	EA	6	6-10 years	
	Condenser Pump - 21 - 50 HP	Mechanical Room	2	EA	6	10+ years	
<u>Temperature Control</u>							
	DDC System	Entire Building	455,800	SF	5	6-10 years	Some actuators do not respond. Per engineer, 20% of the building in manually controlled. Software not upgraded
	Electric Thermostat	Entire Building	26	EA	6	6-10 years	For split systems and unit heaters, single zone units
	Thermostats - DDC	Entire Building	172	EA	6	10+ years	
	Thermostats - DDC	Entire Building	3	EA	4	2-5 years	Not reliable, not calibrated, need repair
<u>Ventilation</u>							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	10+ years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	6	EA	6	10+ years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	5	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	6	EA	6	2-5 years	

Category : Mechanical

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	4	1-2 years	Noisy, corroded
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	10+ years	
	Roof Mounted Duct Work	Entire Building	300	LF	6	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	3	EA	6	10+ years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	10+ years	Dishwasher exhaust fan
	Type II Exhaust Hood- Warming Kitchen	Entire Building	4	EA	6	10+ years	In serving, cafeteria area

Category : Plumbing

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Hot Water</u>							
	Gas Heater - Greater than 600000 BTU/HR	Boiler Room	2	EA	6	6-10 years	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room	2	EA	6	6-10 years	
<u>Piping</u>							
	Domestic Piping-Cold Water Horizontal Lines	Entire Building	455,800	SF	6	6-10 years	Per engineer, pipe leaks are occasionally repaired, for minor leaks
	Domestic Piping-Cold Water Risers	Entire Building	455,800	SF	6	6-10 years	
	Domestic Piping-Cold Water from Risers to Fixtures	Entire Building	455,800	SF	6	6-10 years	
	Domestic Piping-Hot Water Horizontal Lines	Entire Building	455,800	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Lines	Entire Building	455,800	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	455,800	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	455,800	SF	6	6-10 years	
	Sanitary Piping	Entire Building	455,800	SF	6	6-10 years	
	Storm Piping	Entire Building	455,800	SF	6	6-10 years	
	Vent Piping	Entire Building	455,800	SF	6	6-10 years	
<u>Pool Systems</u>							
	Pool Drain Piping	near pool	200	LF	6	6-10 years	Pipes require occasional repairs, minor leaks
	Pool Filtration System including Pump	near pool	1	EA	6	10+ years	
	Pool Hot Water Heater - Gas Fired	near pool	1	EA	6	10+ years	Opened for repair in 9/2020

Category : Plumbing

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Pool Supply and Return Piping	near pool	200	LF	6	10+ years	

Pumps

	Pumps - Domestic Booster Pump-Duplex	Mechanical Room	1	EA	6	10+ years	
	Pumps - Ejector-Simplex	Mechanical Room	1	EA	6	10+ years	Under boiler room
	Pumps - Sump-Duplex	Mechanical Room	2	EA	6	6-10 years	Pumps located under auditorium
	Pumps - Sump-Simplex	Mechanical Room	2	EA	6	10+ years	Under elevators

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Administrative Suites/Offices

	Ceiling - Plaster/Drywall	109 Kiln Room	266	SF	6	10+ years	
	Doors - Wood Doors inclu hw	109 Kiln Room	1	EA	6	10+ years	
	Floor - Concrete	109 Kiln Room	266	SF	5	10+ years	
	Lighting - Pendent/Surface	109 Kiln Room	4	EA	7	6-10 years	
	Power Distribution	109 Kiln Room	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	109 Kiln Room	870	SF	6	10+ years	
	Work Slnk	109 Kiln Room	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	110 Office	260	SF	6	10+ years	
	Doors - Wood Doors inclu hw	110 Office	1	EA	6	10+ years	
	Floor - Carpet	110 Office	260	SF	6	6-10 years	
	Lighting - Pendent/Surface	110 Office	2	EA	7	6-10 years	
	Power Distribution	110 Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	110 Office	648	SF	6	10+ years	
	Ceiling - Lay-in	113/111 Administrative Office	1,451	SF	6	10+ years	
	Doors - Wood Doors inclu hw	113/111 Administrative Office	2	EA	6	10+ years	
	Floor - Tile	113/111 Administrative Office	1,451	SF	7	10+ years	
	Lighting - Lay-in	113/111 Administrative Office	32	EA	7	6-10 years	
	Power Distribution	113/111 Administrative Office	30	EA	6	10+ years	
	Walls - Plaster/Drywall	113/111 Administrative Office	1,638	SF	6	10+ years	
	Walls - Plaster/Drywall	113/111 Administrative Office	30	SF	5	0-1 year	Water damage
	Ceiling - Lay-in	115 Attendance Office	1,265	SF	6	10+ years	
	Ceiling - Lay-in	115 Attendance Office	6	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	115 Attendance Office	2	EA	6	10+ years	
	Floor - Tile	115 Attendance Office	1,271	SF	6	10+ years	
	Lighting - Lay-in	115 Attendance Office	20	EA	6	6-10 years	
	Power Distribution	115 Attendance Office	20	EA	6	10+ years	
	Walls - Plaster/Drywall	115 Attendance Office	1,461	SF	6	10+ years	
	Work Slnk	115 Attendance Office	1	EA	7	10+ years	
	Ceiling - Lay-in	117 Records Office in Main Office	248	SF	6	10+ years	
	Doors - Side-lite	117 Records Office in Main Office	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	117 Records Office in Main Office	1	EA	6	10+ years	
	Floor - Carpet	117 Records Office in Main Office	248	SF	6	6-10 years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Pendent/Surface	117 Records Office in Main Office	2	EA	7	6-10 years	
	Power Distribution	117 Records Office in Main Office	6	EA	6	10+ years	
	Walls - Plaster/Drywall	117 Records Office in Main Office	285	SF	6	10+ years	
	Ceiling - Lay-in	119 Office	233	SF	6	10+ years	
	Ceiling - Lay-in	119 Office	8	SF	5	0-1 year	Missing tile
	Doors - Wood Doors inclu hw	119 Office	1	EA	6	10+ years	
	Floor - Carpet	119 Office	241	SF	6	6-10 years	
	Lighting - Lay-in	119 Office	2	EA	7	6-10 years	
	Power Distribution	119 Office	4	EA	6	10+ years	
	Walls - Plaster/Drywall	119 Office	139	SF	6	10+ years	
	Walls - Structural Glazed Tile	119 Office	139	SF	6	10+ years	
	Ceiling - Exposed	122A ROTC Office	111	SF	6	10+ years	
	Doors - Side-lite	122A ROTC Office	120	SF	6	10+ years	
	Doors - Wood Doors inclu hw	122A ROTC Office	1	EA	6	10+ years	
	Floor - Tile	122A ROTC Office	111	SF	5	10+ years	
	Lighting - Pendent/Surface	122A ROTC Office	2	EA	7	6-10 years	
	Power Distribution	122A ROTC Office	4	EA	7	10+ years	
	Walls - Masonry	122A ROTC Office	239	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Towel Room	234	SF	6	10+ years	Paint Peeling
	Doors - Wood Doors inclu hw	1st Floor Towel Room	1	EA	6	10+ years	
	Floor - Concrete	1st Floor Towel Room	234	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor Towel Room	3	EA	7	6-10 years	
	Power Distribution	1st Floor Towel Room	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Towel Room	635	SF	5	10+ years	Paint Peeling
	Work Slnk	1st Floor Towel Room	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	219A Office	425	SF	5	10+ years	
	Doors - Wood Doors inclu hw	219A Office	1	EA	6	10+ years	
	Floor - Tile	219A Office	425	SF	6	10+ years	
	Lighting - Pendent/Surface	219A Office	3	EA	7	6-10 years	
	Power Distribution	219A Office	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	219A Office	1,092	SF	6	10+ years	
	Ceiling - Plaster/Drywall	263 Gym Office	329	SF	5	10+ years	
	Ceiling - Plaster/Drywall	263 Gym Office	10	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	263 Gym Office	3	EA	6	10+ years	
	Floor - Tile	263 Gym Office	336	SF	5	10+ years	
	Lighting - Pendent/Surface	263 Gym Office	5	EA	6	6-10 years	
	Power Distribution	263 Gym Office	8	EA	7	10+ years	
	Storage/ Closet	263 Gym Office	8	SF	5	10+ years	
	Walls - Plaster/Drywall	263 Gym Office	958	SF	6	10+ years	
	Walls - Plaster/Drywall	263 Gym Office	20	SF	4	0-1 year	Water damage
	Ceiling - Lay-in	501C	110	SF	6	10+ years	
	Doors - Wood Doors inclu hw	501C	1	EA	6	10+ years	
	Floor - Wood	501C	110	SF	6	10+ years	
	Lighting - Lay-in	501C	2	EA	6	6-10 years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Power Distribution	501C	2	EA	6	10+ years	
	Walls - Plaster/Drywall	501C	475	SF	6	10+ years	
	Ceiling - Plaster/Drywall	After School Office, 2nd Floor	83	SF	6	10+ years	
	Doors - Wood Doors inclu hw	After School Office, 2nd Floor	1	EA	6	10+ years	
	Floor - Carpet	After School Office, 2nd Floor	83	SF	6	10+ years	
	Lighting - Pendent/Surface	After School Office, 2nd Floor	1	EA	7	10+ years	
	Power Distribution	After School Office, 2nd Floor	4	EA	6	10+ years	
	Walls - Plaster/Drywall	After School Office, 2nd Floor	101	SF	6	10+ years	
	Ceiling - Lay-in	Assistant Principal's Office Room 110	819	SF	6	10+ years	
	Ceiling - Lay-in	Assistant Principal's Office Room 110	6	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	Assistant Principal's Office Room 110	1	EA	6	10+ years	
	Floor - Carpet	Assistant Principal's Office Room 110	825	SF	6	6-10 years	
	Lighting - Lay-in	Assistant Principal's Office Room 110	2	EA	7	6-10 years	
	Power Distribution	Assistant Principal's Office Room 110	6	EA	6	10+ years	
	Storage/ Closet	Assistant Principal's Office Room 110	12	SF	5	10+ years	
	Walls - Plaster/Drywall	Assistant Principal's Office Room 110	883	SF	6	10+ years	
	Ceiling - Lay-in	Counselor's Office, Room 128	814	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselor's Office, Room 128	1	EA	6	10+ years	
	Floor - Carpet	Counselor's Office, Room 128	814	SF	6	10+ years	
	Lighting - Lay-in	Counselor's Office, Room 128	16	EA	7	10+ years	
	Power Distribution	Counselor's Office, Room 128	14	EA	6	10+ years	
	Walls - Plaster/Drywall	Counselor's Office, Room 128	936	SF	6	10+ years	
	Ceiling - Exposed	Engineer's Office	445	SF	6	10+ years	
	Doors - Transom Window	Engineer's Office	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	2	EA	6	10+ years	
	Floor - Tile	Engineer's Office	445	SF	5	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	10	EA	6	6-10 years	
	Power Distribution	Engineer's Office	6	EA	7	10+ years	
	Storage/ Closet	Engineer's Office	89	SF	5	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	950	SF	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	50	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	In Room 229	28	SF	6	10+ years	
	Doors - Steel Doors incl hw	In Room 229	1	EA	6	10+ years	
	Floor - Tile	In Room 229	28	SF	6	10+ years	
	Lighting - Pendent/Surface	In Room 229	1	EA	7	10+ years	
	Power Distribution	In Room 229	4	EA	6	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	In Room 229	49	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Library Office	252	SF	6	10+ years	
	Doors - Side-lite	Library Office	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Library Office	1	EA	6	10+ years	
	Floor - Carpet	Library Office	252	SF	6	6-10 years	
	Lighting - Pendent/Surface	Library Office	6	EA	7	10+ years	
	Power Distribution	Library Office	12	EA	7	10+ years	
	Walls - Structural Glazed Tile	Library Office	298	SF	6	10+ years	
	Ceiling - Splined	Lunch Room Manager's Office	112	SF	4	1-2 years	Adhesive failing and majority of tiles missing.
	Doors - Wood Doors inclu hw	Lunch Room Manager's Office	1	EA	6	10+ years	
	Floor - Tile	Lunch Room Manager's Office	112	SF	6	10+ years	
	Lighting - Pendent/Surface	Lunch Room Manager's Office	1	EA	7	6-10 years	
	Power Distribution	Lunch Room Manager's Office	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Lunch Room Manager's Office	558	SF	6	10+ years	
	Ceiling - Lay-in	Main Office	1,290	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Office	2	EA	6	10+ years	
	Floor - Tile	Main Office	1,290	SF	6	10+ years	
	Lighting - Lay-in	Main Office	22	EA	7	6-10 years	
	Power Distribution	Main Office	14	EA	6	10+ years	
	Storage/ Closet	Main Office	65	SF	5	10+ years	
	Storage/ Closet	Main Office	75	SF	5	10+ years	
	Walls - Plaster/Drywall	Main Office	1,483	SF	6	10+ years	
	Work Slnk	Main Office	1	EA	7	10+ years	
	Ceiling - Lay-in	Music Teacher's Office	85	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Music Teacher's Office	1	EA	6	10+ years	
	Floor - Wood	Music Teacher's Office	85	SF	6	10+ years	
	Lighting - Lay-in	Music Teacher's Office	2	EA	7	10+ years	
	Power Distribution	Music Teacher's Office	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Music Teacher's Office	98	SF	6	10+ years	
	Ceiling - Lay-in	Nurse's Office, Room 121A	248	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Nurse's Office, Room 121A	2	EA	6	10+ years	
	Floor - Tile	Nurse's Office, Room 121A	248	SF	6	10+ years	
	Lighting - Lay-in	Nurse's Office, Room 121A	6	EA	7	6-10 years	
	Power Distribution	Nurse's Office, Room 121A	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Nurse's Office, Room 121A	285	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Office 136	290	SF	5	10+ years	
	Ceiling - Plaster/Drywall	Office 136	32	SF	4	0-1 year	Section of ceiling removed.
	Doors - Wood Doors inclu hw	Office 136	1	EA	6	10+ years	
	Floor - Wood	Office 136	322	SF	5	2-5 years	
	Lighting - Pendent/Surface	Office 136	8	EA	7	6-10 years	
	Power Distribution	Office 136	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Office 136	370	SF	6	10+ years	Painting needed.
	Ceiling - Lay-in	Office in Room 211	452	SF	6	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	Office in Room 211	1	EA	6	10+ years	
	Floor - Tile	Office in Room 211	452	SF	6	10+ years	
	Lighting - Lay-in	Office in Room 211	8	EA	7	6-10 years	
	Power Distribution	Office in Room 211	6	EA	6	10+ years	
	Storage/ Closet	Office in Room 211	140	SF	7	10+ years	
	Walls - Plaster/Drywall	Office in Room 211	533	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Office in Room 213	157	SF	6	10+ years	
	Doors - Steel Doors incl hw	Office in Room 213	1	EA	6	10+ years	
	Floor - Tile	Office in Room 213	157	SF	6	10+ years	
	Lighting - Pendent/Surface	Office in Room 213	3	EA	7	6-10 years	
	Power Distribution	Office in Room 213	2	EA	6	10+ years	
	Walls - Plaster/Drywall	Office in Room 213	514	SF	6	10+ years	
	Work Slnk	Office in Room 213	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Office in Room 219	157	SF	5	10+ years	Paint peeling
	Doors - Wood Doors inclu hw	Office in Room 219	1	EA	6	10+ years	
	Floor - Tile	Office in Room 219	157	SF	6	10+ years	
	Lighting - Pendent/Surface	Office in Room 219	3	EA	7	6-10 years	
	Power Distribution	Office in Room 219	2	EA	6	10+ years	
	Walls - Structural Glazed Tile	Office in Room 219	158	SF	6	10+ years	
	Work Slnk	Office in Room 219	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Office in Room 234B	157	SF	6	10+ years	
	Doors - Steel Doors incl hw	Office in Room 234B	1	EA	6	10+ years	
	Floor - Wood	Office in Room 234B	157	SF	6	2-5 years	
	Lighting - Pendent/Surface	Office in Room 234B	3	EA	7	6-10 years	
	Power Distribution	Office in Room 234B	2	EA	6	10+ years	
	Walls - Plaster/Drywall	Office in Room 234B	185	SF	6	10+ years	
	Work Slnk	Office in Room 234B	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Office in Room 419	1,197	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office in Room 419	1	EA	6	10+ years	
	Floor - Wood	Office in Room 419	1,197	SF	6	10+ years	
	Lighting - Lay-in	Office in Room 419	18	EA	7	10+ years	
	Power Distribution	Office in Room 419	10	EA	6	10+ years	
	Storage/ Closet	Office in Room 419	46	SF	7	10+ years	
	Walls - Plaster/Drywall	Office in Room 419	1,408	SF	6	10+ years	
	Ceiling - Lay-in	Office in the Main Office	248	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Office in the Main Office	1	EA	6	10+ years	
	Floor - Carpet	Office in the Main Office	248	SF	6	6-10 years	
	Lighting - Pendent/Surface	Office in the Main Office	2	EA	7	6-10 years	
	Power Distribution	Office in the Main Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Office in the Main Office	904	SF	6	10+ years	
	Ceiling - Lay-in	Office, Room 207	273	SF	6	10+ years	
	Ceiling - Lay-in	Office, Room 207	6	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	Office, Room 207	2	EA	6	10+ years	
	Floor - Tile	Office, Room 207	279	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Lay-in	Office, Room 207	5	EA	7	6-10 years	
	Power Distribution	Office, Room 207	8	EA	6	10+ years	
	Storage/ Closet	Office, Room 207	45	SF	5	10+ years	
	Storage/ Closet	Office, Room 207	36	SF	4	0-1 year	Plaster is falling off wall and paint peeling
	Walls - Plaster/Drywall	Office, Room 207	320	SF	6	10+ years	
	Work Slnk	Office, Room 207	1	EA	7	10+ years	
	Ceiling - Lay-in	Principal's Office Suite	520	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office Suite	5	EA	6	10+ years	
	Floor - Tile	Principal's Office Suite	520	SF	6	10+ years	
	Lighting - Pendent/Surface	Principal's Office Suite	8	EA	7	6-10 years	
	Power Distribution	Principal's Office Suite	10	EA	6	10+ years	
	Storage/ Closet	Principal's Office Suite	8	SF	5	10+ years	
	Walls - Plaster/Drywall	Principal's Office Suite	285	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Programming Office, Room 132	357	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Programming Office, Room 132	1	EA	6	10+ years	
	Floor - Wood	Programming Office, Room 132	357	SF	6	10+ years	
	Lighting - Pendent/Surface	Programming Office, Room 132	8	EA	7	6-10 years	
	Power Distribution	Programming Office, Room 132	8	EA	6	10+ years	
	Walls - Plaster/Drywall	Programming Office, Room 132	421	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Resource Room, 2nd Floor	1,031	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Resource Room, 2nd Floor	2	EA	6	10+ years	
	Floor - Carpet	Resource Room, 2nd Floor	1,031	SF	6	6-10 years	
	Lighting - Chandelier, Incandescent	Resource Room, 2nd Floor	3	EA	7	6-10 years	
	Power Distribution	Resource Room, 2nd Floor	8	EA	6	10+ years	
	Walls - Plaster/Drywall	Resource Room, 2nd Floor	1,243	SF	6	10+ years	
	AC Unit	Room 106 (Attendance Office)	2	EA	7	6-10 years	
	Ceiling - Lay-in	Room 106 (Attendance Office)	1,315	SF	6	10+ years	
	Doors - Transom Window	Room 106 (Attendance Office)	176	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 106 (Attendance Office)	2	EA	6	10+ years	
	Floor - Tile	Room 106 (Attendance Office)	1,315	SF	5	10+ years	
	Lighting - Lay-in	Room 106 (Attendance Office)	24	EA	6	6-10 years	
	Power Distribution	Room 106 (Attendance Office)	24	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 106 (Attendance Office)	1,381	SF	6	10+ years	
	Ceiling - Lay-in	Room 128 Special Education	879	SF	6	6-10 years	
	Doors - Transom Window	Room 128 Special Education	264	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 128 Special Education	1	EA	6	10+ years	
	Floor - Carpet	Room 128 Special Education	879	SF	5	2-5 years	
	Lighting - Lay-in	Room 128 Special Education	14	EA	7	6-10 years	
	Storage/ Closet	Room 128 Special Education	113	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 128 Special Education	934	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 221 Staff Lounge	443	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 221 Staff Lounge	1	EA	6	10+ years	
	Floor - Tile	Room 221 Staff Lounge	443	SF	5	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Pendent/Surface	Room 221 Staff Lounge	6	EA	7	6-10 years	
	Power Distribution	Room 221 Staff Lounge	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Room 221 Staff Lounge	513	SF	6	10+ years	
	Ceiling - Lay-in	Room 234A	183	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 234A	1	EA	5	2-5 years	
	Floor - Wood	Room 234A	183	SF	5	2-5 years	
	Lighting - Lay-in	Room 234A	6	EA	7	6-10 years	
	Power Distribution	Room 234A	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Room 234A	215	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Social worker office 342	195	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Social worker office 342	1	EA	7	10+ years	
	Floor - Wood	Social worker office 342	195	SF	7	10+ years	
	Lighting - Pendent/Surface	Social worker office 342	2	EA	7	6-10 years	
	Power Distribution	Social worker office 342	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Social worker office 342	390	SF	7	10+ years	
	Work Slnk	Social worker office 342	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Workroom next to 177 Storage	1,065	SF	5	10+ years	
	Doors - Store Front	Workroom next to 177 Storage	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Workroom next to 177 Storage	1,065	SF	5	10+ years	
	Lighting - Pendent/Surface	Workroom next to 177 Storage	28	EA	6	6-10 years	
	Power Distribution	Workroom next to 177 Storage	8	EA	7	10+ years	
	Walls - Masonry	Workroom next to 177 Storage	2,218	SF	6	10+ years	

Auditorium & Theater

	Balcony Seating	1st Floor	500	EA	5	2-5 years	
	Ceiling - Plaster/Drywall	1st Floor	9,695	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	12	EA	6	10+ years	
	Floor - Concrete	1st Floor	9,695	SF	5	10+ years	
	Floor - Wood	1st Floor	188	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	54	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	35	EA	7	6-10 years	
	Main Floor Seating	1st Floor	1,270	EA	5	2-5 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	2,396	SF	6	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	14	LF	7	10+ years	
	Stairs - Terrazzo	1st Floor	10	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,114	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	10,034	SF	5	10+ years	

Gymnasias

	Ceiling - Plaster/Drywall	165 & Balcony	11,519	SF	6	10+ years	
--	---------------------------	---------------	--------	----	---	-----------	--

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Plaster/Drywall	165 & Balcony	100	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	165 & Balcony	2	EA	6	10+ years	
	Doors - Transom Window	165 & Balcony	912	SF	6	10+ years	
	Doors - Wood Doors inclu hw	165 & Balcony	5	EA	6	10+ years	
	Floor - Wood	165 & Balcony	10,141	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	165 & Balcony	40	EA	7	6-10 years	
	Scoreboards	165 & Balcony	1	EA	7	6-10 years	
	Storage/ Closet	165 & Balcony	489	SF	5	10+ years	
	Walls - Plaster/Drywall	165 & Balcony	6,529	SF	6	10+ years	
	Walls - Structural Glazed Tile	165 & Balcony	5,151	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	4,059	SF	5	10+ years	
	Doors - Transom Window	1st Floor	662	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	4,059	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	75	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,085	SF	6	10+ years	Painting needed. Damaged portion of wall repaired but not well.
	Walls - Structural Glazed Tile	1st Floor	2,084	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	880	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	320	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	880	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	919	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 200	1,238	SF	6	10+ years	
	Doors - Steel Doors incl hw	Room 200	1	EA	6	10+ years	
	Floor - Sport Flooring	Room 200	1,238	SF	5	10+ years	
	Lighting - Pendent/Surface	Room 200	21	EA	6	6-10 years	
	Walls - Plaster/Drywall	Room 200	1,460	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 201, Weight Room	1,277	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 201, Weight Room	3	EA	6	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	Room 201, Weight Room	1,277	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 201, Weight Room	20	EA	6	6-10 years	
	Walls - Plaster/Drywall	Room 201, Weight Room	1,468	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 205, Weight Room	1,277	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 205, Weight Room	2	EA	6	10+ years	
	Floor - Wood	Room 205, Weight Room	1,277	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 205, Weight Room	20	EA	6	6-10 years	
	Storage/ Closet	Room 205, Weight Room	425	SF	5	10+ years	Labeled 204 Gymnasium at door.
	Walls - Plaster/Drywall	Room 205, Weight Room	1,468	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 206	3,892	SF	5	10+ years	
	Doors - Steel Doors incl hw	Room 206	2	EA	6	10+ years	
	Floor - Wood	Room 206	3,892	SF	6	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Metal Halide/Sodium Vapor	Room 206	12	EA	6	6-10 years	
	Walls - Plaster/Drywall	Room 206	2,162	SF	6	10+ years	
	Walls - Plaster/Drywall	Room 206	75	SF	4	0-1 year	Plaster over brick has fallen off.
	Walls - Structural Glazed Tile	Room 206	2,237	SF	6	10+ years	
Kitchen							
	Ceiling - Lay-in	2nd Floor	1,422	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	2nd Floor	1,422	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	22	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	124	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,677	SF	6	10+ years	
Library							
	Casework	1st Floor	1,200	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	6,665	SF	6	10+ years	
	Doors - Transom Window	1st Floor	576	SF	6	10+ years	
	Doors - Wood Doors incl hw	1st Floor	8	EA	6	10+ years	
	Floor - Carpet	1st Floor	6,465	SF	6	6-10 years	
	Floor - Tile/Sheet	1st Floor	200	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	32	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	3,821	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,000	SF	6	10+ years	
Locker/Shower Room							
	Accessories	105 Staff Locker Room	128	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	105 Staff Locker Room	128	SF	6	10+ years	
	Doors - Wood Doors incl hw	105 Staff Locker Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	105 Staff Locker Room	128	SF	6	10+ years	
	Lavatory	105 Staff Locker Room	1	EA	6	10+ years	
	Lighting - Pendent/Surface	105 Staff Locker Room	3	EA	7	6-10 years	
	Partitions	105 Staff Locker Room	2	EA	5	10+ years	
	Student Lockers - One Tier	105 Staff Locker Room	4	EA	6	10+ years	
	Walls - Plaster/Drywall	105 Staff Locker Room	624	SF	6	10+ years	
	Water Closet	105 Staff Locker Room	2	EA	6	10+ years	
	Accessories	126A Locker Room	489	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	126A Locker Room	289	SF	6	10+ years	
	Ceiling - Plaster/Drywall	126A Locker Room	200	SF	4	0-1 year	Water damage
	Doors - Wood Doors incl hw	126A Locker Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	126A Locker Room	489	SF	6	10+ years	
	Floor Drain	126A Locker Room	1	EA	7	10+ years	
	Lavatory	126A Locker Room	2	EA	6	10+ years	
	Lighting - Pendent/Surface	126A Locker Room	2	EA	6	6-10 years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Partitions	126A Locker Room	2	EA	5	10+ years	
	Showers	126A Locker Room	4	EA	5	10+ years	
	Student Lockers - One Tier	126A Locker Room	4	EA	6	10+ years	
	Student Lockers - Three Tiers	126A Locker Room	35	EA	6	10+ years	
	Walls - Structural Glazed Tile	126A Locker Room	655	SF	6	10+ years	
	Water Closet	126A Locker Room	2	EA	6	10+ years	
	Ceiling - Plaster/Drywall	165A Women's Locker Room	364	SF	6	10+ years	Paint cracking and peeling
	Doors - Wood Doors inclu hw	165A Women's Locker Room	2	EA	6	10+ years	
	Floor - Tile/Sheet	165A Women's Locker Room	364	SF	5	10+ years	
	Student Lockers - One Tier	165A Women's Locker Room	20	EA	6	10+ years	
	Student Lockers - Two Tier	165A Women's Locker Room	30	EA	6	10+ years	
	Walls - Plaster/Drywall	165A Women's Locker Room	1,029	SF	6	10+ years	
	Accessories	165D Men's Locker Room	3,488	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	165D Men's Locker Room	3,472	SF	5	10+ years	
	Ceiling - Plaster/Drywall	165D Men's Locker Room	16	SF	4	0-1 year	Water damage near pipes
	Doors - Transom Window	165D Men's Locker Room	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	165D Men's Locker Room	2	EA	6	10+ years	
	Floor - Terrazzo	165D Men's Locker Room	3,000	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	165D Men's Locker Room	488	SF	6	10+ years	
	Floor Drain	165D Men's Locker Room	2	EA	7	10+ years	
	Hand Dryer	165D Men's Locker Room	2	EA	7	6-10 years	
	Lavatory	165D Men's Locker Room	2	EA	6	10+ years	
	Lighting - Pendent/Surface	165D Men's Locker Room	13	EA	5	6-10 years	
	Partitions	165D Men's Locker Room	2	EA	5	10+ years	
	Showers	165D Men's Locker Room	12	EA	5	10+ years	
	Student Lockers - Two Tier	165D Men's Locker Room	140	EA	7	10+ years	
	Urinals	165D Men's Locker Room	5	EA	6	10+ years	
	Walls - Plaster/Drywall	165D Men's Locker Room	3,087	SF	5	10+ years	
	Walls - Structural Glazed Tile	165D Men's Locker Room	1,510	SF	6	10+ years	
	Water Closet	165D Men's Locker Room	2	EA	6	10+ years	
	Accessories	208 Men's Locker Room	1,133	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	208 Men's Locker Room	1,133	SF	6	10+ years	
	Doors - Wood Doors inclu hw	208 Men's Locker Room	1	EA	6	10+ years	
	Floor - Concrete	208 Men's Locker Room	1,133	SF	5	10+ years	
	Floor Drain	208 Men's Locker Room	6	EA	7	10+ years	
	Lighting - Pendent/Surface	208 Men's Locker Room	14	EA	6	6-10 years	
	Lighting - Wall Mounted	208 Men's Locker Room	4	EA	7	6-10 years	
	Showers	208 Men's Locker Room	6	EA	5	10+ years	
	Student Lockers - One Tier	208 Men's Locker Room	30	EA	6	10+ years	
	Student Lockers - Three Tiers	208 Men's Locker Room	57	EA	6	10+ years	
	Walls - Plaster/Drywall	208 Men's Locker Room	2,838	SF	5	10+ years	
	Walls - Plaster/Drywall	208 Men's Locker Room	45	SF	4	0-1 year	Section of lockers removed and wall was not repaired.
	Accessories	208 Women's Locker Room	2,405	SF	5	6-10 years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Plaster/Drywall	208 Women's Locker Room	2,405	SF	6	10+ years	
	Doors - Wood Doors inclu hw	208 Women's Locker Room	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	208 Women's Locker Room	2,405	SF	6	10+ years	
	Floor Drain	208 Women's Locker Room	12	EA	7	10+ years	
	Hand Dryer	208 Women's Locker Room	6	EA	7	6-10 years	
	Lavatory	208 Women's Locker Room	2	EA	6	10+ years	
	Lighting - Pendent/Surface	208 Women's Locker Room	30	EA	6	6-10 years	
	Lighting - Wall Mounted	208 Women's Locker Room	6	EA	6	6-10 years	
	Partitions	208 Women's Locker Room	2	EA	5	10+ years	
	Showers	208 Women's Locker Room	38	EA	7	10+ years	
	Student Lockers - Three Tiers	208 Women's Locker Room	162	EA	6	10+ years	
	Student Lockers - Two Tier	208 Women's Locker Room	84	EA	6	10+ years	
	Walls - Plaster/Drywall	208 Women's Locker Room	8,867	SF	5	10+ years	
	Walls - Structural Glazed Tile	208 Women's Locker Room	182	SF	7	10+ years	
	Water Closet	208 Women's Locker Room	2	EA	6	10+ years	
	Accessories	226A Men's Locker Room	854	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	226A Men's Locker Room	850	SF	6	10+ years	
	Ceiling - Plaster/Drywall	226A Men's Locker Room	4	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	226A Men's Locker Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	226A Men's Locker Room	854	SF	6	10+ years	
	Floor Drain	226A Men's Locker Room	2	EA	7	10+ years	
	Hand Dryer	226A Men's Locker Room	2	EA	7	6-10 years	
	Lavatory	226A Men's Locker Room	1	EA	7	10+ years	
	Lavatory	226A Men's Locker Room	1	EA	4	0-1 year	Damaged
	Lighting - Pendent/Surface	226A Men's Locker Room	14	EA	5	6-10 years	
	Partitions	226A Men's Locker Room	2	EA	5	10+ years	
	Showers	226A Men's Locker Room	6	EA	5	10+ years	
	Student Lockers - One Tier	226A Men's Locker Room	32	EA	6	10+ years	
	Student Lockers - Three Tiers	226A Men's Locker Room	48	EA	6	10+ years	
	Walls - Plaster/Drywall	226A Men's Locker Room	1,007	SF	6	10+ years	
	Water Closet	226A Men's Locker Room	2	EA	6	10+ years	
	Accessories	Next to Pool	814	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Next to Pool	814	SF	6	10+ years	
	Doors - Steel Doors incl hw	Next to Pool	2	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Next to Pool	814	SF	7	10+ years	
	Floor Drain	Next to Pool	4	EA	7	10+ years	
	Hand Dryer	Next to Pool	1	EA	7	6-10 years	
	Lavatory	Next to Pool	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Next to Pool	8	EA	7	6-10 years	
	Partitions	Next to Pool	1	EA	5	10+ years	
	Showers	Next to Pool	5	EA	7	10+ years	
	Student Lockers - One Tier	Next to Pool	3	EA	7	10+ years	
	Student Lockers - Three Tiers	Next to Pool	54	EA	6	10+ years	
	Urinals	Next to Pool	1	EA	6	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	Next to Pool	468	SF	6	10+ years	
	Walls - Structural Glazed Tile	Next to Pool	468	SF	5	2-5 years	
	Water Closet	Next to Pool	1	EA	6	10+ years	
	Accessories	Next to the Pool	799	SF	7	6-10 years	
	Ceiling - Exposed	Next to the Pool	799	SF	6	10+ years	
	Doors - Steel Doors incl hw	Next to the Pool	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Next to the Pool	799	SF	6	10+ years	
	Floor Drain	Next to the Pool	7	EA	7	10+ years	
	Hand Dryer	Next to the Pool	4	EA	7	6-10 years	
	Lavatory	Next to the Pool	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Next to the Pool	10	EA	7	6-10 years	
	Partitions	Next to the Pool	1	EA	5	10+ years	
	Showers	Next to the Pool	9	EA	7	10+ years	
	Walls - Plaster/Drywall	Next to the Pool	688	SF	6	10+ years	
	Walls - Structural Glazed Tile	Next to the Pool	229	SF	6	10+ years	
	Water Closet	Next to the Pool	1	EA	6	10+ years	

Lunch & Multipurpose Room

	Ceiling - Lay-in	2nd Floor	6,008	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	18	SF	4	0-1 year	Water damage
	Doors - Wood Doors incl hw	2nd Floor	8	EA	6	10+ years	
	Floor - Tile	2nd Floor	6,076	SF	6	10+ years	
	Floor - Tile	2nd Floor	50	SF	5	1-2 years	Cracked, damaged tiles
	Lighting - Lay-in	2nd Floor	70	EA	7	6-10 years	
	Serving Line	2nd Floor	106	LF	6	10+ years	
	Storage/ Closet	2nd Floor	450	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6,930	SF	5	2-5 years	
	Ceiling - Lay-in	Faculty Lunch Room, 2nd Floor	1,141	SF	6	10+ years	
	Doors - Wood Doors incl hw	Faculty Lunch Room, 2nd Floor	2	EA	6	10+ years	
	Floor - Tile	Faculty Lunch Room, 2nd Floor	1,141	SF	6	10+ years	
	Lighting - Lay-in	Faculty Lunch Room, 2nd Floor	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	Faculty Lunch Room, 2nd Floor	1,346	SF	5	10+ years	
	Ceiling - Plaster/Drywall	Men's Faculty Lounge	240	SF	5	2-5 years	
	Doors - Transom Window	Men's Faculty Lounge	36	SF	6	10+ years	
	Doors - Wood Doors incl hw	Men's Faculty Lounge	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men's Faculty Lounge	240	SF	6	10+ years	
	Lighting - Pendent/Surface	Men's Faculty Lounge	4	EA	7	10+ years	
	Walls - Concrete Block	Men's Faculty Lounge	274	SF	5	2-5 years	
	Ceiling - Lay-in	Room 342	2,327	SF	6	10+ years	
	Chalk Board	Room 342	40	LF	4	2-5 years	
	Doors - Wood Doors incl hw	Room 342	4	EA	6	10+ years	
	Floor - Tile/Sheet	Room 342	2,327	SF	5	2-5 years	
	Lighting - Lay-in	Room 342	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 342	2,412	SF	6	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	AC Unit	Staff Lounge Rm: 112	1	EA	7	6-10 years	
	Ceiling - Lay-in	Staff Lounge Rm: 112	765	SF	6	10+ years	
	Ceiling - Lay-in	Staff Lounge Rm: 112	8	SF	4	0-1 year	Buckled tile
	Doors - Transom Window	Staff Lounge Rm: 112	54	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Staff Lounge Rm: 112	1	EA	5	2-5 years	
	Floor - Tile	Staff Lounge Rm: 112	773	SF	7	10+ years	
	Lighting - Lay-in	Staff Lounge Rm: 112	6	EA	7	10+ years	
	Walls - Structural Glazed Tile	Staff Lounge Rm: 112	835	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Staff Lounge Room 376A	504	SF	6	10+ years	
	Doors - Transom Window	Staff Lounge Room 376A	92	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Staff Lounge Room 376A	1	EA	6	10+ years	
	Floor - Carpet	Staff Lounge Room 376A	504	SF	6	10+ years	
	Lighting - Pendent/Surface	Staff Lounge Room 376A	14	EA	7	10+ years	
	Walls - Plaster/Drywall	Staff Lounge Room 376A	559	SF	6	10+ years	

MDF_IDF

	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Finishes	3rd Floor	298	SF	5	2-5 years	
	Other Cooling Unit	3rd Floor	1	EA	7	6-10 years	Ductless split system

Mechanical/ Service Rooms

	Janitor's Closet	1st Floor	36	SF	5	10+ years	
	Janitor's Closet	1st Floor	17	SF	5	10+ years	
	Loading Docks	1st Floor	610	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	504	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	448	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	477	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	2,562	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	504	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	1,194	SF	5	10+ years	
	Storage Room	1st Floor	1,074	SF	5	10+ years	
	Storage Room	1st Floor	1,298	SF	5	10+ years	
	Storage Room	1st Floor	715	SF	5	10+ years	
	Storage Room	1st Floor	700	SF	5	10+ years	
	Janitor's Closet	2nd Floor	90	SF	7	10+ years	
	Storage Room	2nd Floor	186	SF	7	10+ years	
	Janitor's Closet	3rd Floor	30	SF	7	10+ years	
	Janitor's Closet	3rd Floor	34	SF	7	10+ years	
	Janitor's Closet	3rd Floor	20	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	448	SF	5	10+ years	
	Storage Room	3rd Floor	150	SF	7	10+ years	
	Storage Room	3rd Floor	2,586	SF	5	10+ years	
	Storage Room	3rd Floor	489	SF	5	10+ years	
	Janitor's Closet	4th Floor	36	SF	7	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Janitor's Closet	4th Floor	30	SF	7	10+ years	
	Storage Room	4th Floor	94	SF	7	10+ years	
	Mechanical/ Service Rooms	5th Floor	96	SF	7	10+ years	
Pool & Natatorium							
	Accessories	1st Floor	2,947	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	2,947	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	2,947	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	7	EA	7	6-10 years	
	Pool Basin	1st Floor	2,038	SF	6	10+ years	
	Pool Deck	1st Floor	909	SF	6	10+ years	
	Pool Deck Drains	1st Floor	6	EA	7	10+ years	
	Storage/ Closet	1st Floor	150	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	425	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,389	SF	6	10+ years	
Prep Room							
	Ceiling - Plaster/Drywall	In Room 213	146	SF	6	10+ years	
	Ceiling - Plaster/Drywall	In Room 213	30	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	In Room 213	1	EA	6	10+ years	
	Floor - Tile	In Room 213	176	SF	5	10+ years	
	Lighting - Pendent/Surface	In Room 213	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	In Room 213	202	SF	6	10+ years	
	Work Sink	In Room 213	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	In Room 217	176	SF	6	10+ years	
	Doors - Steel Doors incl hw	In Room 217	1	EA	6	10+ years	
	Floor - Tile	In Room 217	176	SF	6	10+ years	
	Lighting - Pendent/Surface	In Room 217	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	In Room 217	531	SF	6	10+ years	
	Work Sink	In Room 217	1	EA	7	10+ years	
	Ceiling - Lay-in	In Room 219	176	SF	7	10+ years	
	Doors - Steel Doors incl hw	In Room 219	1	EA	6	10+ years	
	Floor - Tile	In Room 219	176	SF	6	10+ years	
	Lighting - Pendent/Surface	In Room 219	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	In Room 219	531	SF	6	10+ years	
	Work Sink	In Room 219	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	In Room 229	176	SF	6	10+ years	
	Doors - Steel Doors incl hw	In Room 229	1	EA	6	10+ years	
	Floor - Tile	In Room 229	176	SF	6	10+ years	
	Lighting - Pendent/Surface	In Room 229	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	In Room 229	202	SF	6	10+ years	
	Work Sink	In Room 229	1	EA	7	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Restroom</u>							
	Accessories	1st Floor	85	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	85	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	85	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	49	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	49	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st Floor	324	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	324	SF	6	10+ years	Painting needed.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	324	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	5	10+ years	
	Urinals	1st Floor	3	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	360	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	360	SF	6	10+ years	
	Water Closet	1st Floor	2	EA	6	10+ years	
	Accessories	1st Floor	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	32	SF	6	10+ years	
	Lavatory	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	171	SF	6	10+ years	
	Water Closet	1st Floor	1	EA	6	10+ years	
	Accessories	1st Floor Across Stair #4	101	SF	7	6-10 years	
	Ceiling - Exposed	1st Floor Across Stair #4	101	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Across Stair #4	101	SF	7	10+ years	
	Floor Drain	1st Floor Across Stair #4	1	EA	7	10+ years	
	Hand Dryer	1st Floor Across Stair #4	2	EA	7	6-10 years	
	Lavatory	1st Floor Across Stair #4	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Across Stair #4	1	EA	7	6-10 years	
	Partitions	1st Floor Across Stair #4	1	EA	5	10+ years	
	Urinals	1st Floor Across Stair #4	1	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Across Stair #4	347	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Across Stair #4	184	SF	6	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Water Closet	1st Floor Across Stair #4	1	EA	6	10+ years	
	Accessories	1st Floor Across from 112B	144	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor Across from 112B	72	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Across from 112B	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Across from 112B	1	EA	6	10+ years	
	Floor - Tile	1st Floor Across from 112B	144	SF	5	10+ years	
	Floor Drain	1st Floor Across from 112B	1	EA	7	10+ years	
	Hand Dryer	1st Floor Across from 112B	2	EA	7	6-10 years	
	Lavatory	1st Floor Across from 112B	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor Across from 112B	4	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor Across from 112B	1	EA	7	6-10 years	
	Urinals	1st Floor Across from 112B	1	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Across from 112B	624	SF	7	10+ years	
	Water Closet	1st Floor Across from 112B	1	EA	6	10+ years	
	Accessories	1st Floor Across from Principals Office Suite	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Across from Principals Office Suite	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Across from Principals Office Suite	1	EA	6	10+ years	
	Floor - Tile	1st Floor Across from Principals Office Suite	35	SF	5	10+ years	
	Hand Dryer	1st Floor Across from Principals Office Suite	1	EA	7	6-10 years	
	Lavatory	1st Floor Across from Principals Office Suite	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Across from Principals Office Suite	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor Across from Principals Office Suite	171	SF	6	10+ years	
	Water Closet	1st Floor Across from Principals Office Suite	1	EA	6	10+ years	
	Accessories	1st Floor Across from Stair #4	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Across from Stair #4	35	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Across from Stair #4	1	EA	6	10+ years	
	Floor - Tile	1st Floor Across from Stair #4	35	SF	5	10+ years	
	Hand Dryer	1st Floor Across from Stair #4	1	EA	7	6-10 years	
	Lavatory	1st Floor Across from Stair #4	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Across from Stair #4	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor Across from Stair #4	171	SF	6	10+ years	
	Water Closet	1st Floor Across from Stair #4	1	EA	6	10+ years	
	Accessories	1st Floor Girl's Restroom Next to 123	370	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Girl's Restroom Next to	370	SF	7	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	123 1st Floor Girl's Restroom Next to	2	EA	7	10+ years	
	Floor - Tile	123 1st Floor Girl's Restroom Next to	370	SF	7	6-10 years	
	Floor Drain	123 1st Floor Girl's Restroom Next to	1	EA	7	10+ years	
	Lavatory	123 1st Floor Girl's Restroom Next to	1	EA	7	10+ years	
	Lighting - Pendent/Surface	123 1st Floor Girl's Restroom Next to	6	EA	6	2-5 years	
	Partitions	123 1st Floor Girl's Restroom Next to	8	EA	7	10+ years	
	Walls - Plaster/Drywall	123 1st Floor Girl's Restroom Next to	300	SF	7	10+ years	
	Walls - Structural Glazed Tile	123 1st Floor Girl's Restroom Next to	370	SF	7	10+ years	
	Water Closet	123 1st Floor Girl's Restroom Next to	8	EA	7	6-10 years	
	Accessories	1st Floor South	445	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor South	445	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor South	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor South	445	SF	6	10+ years	
	Floor Drain	1st Floor South	1	EA	7	10+ years	
	Hand Dryer	1st Floor South	1	EA	7	6-10 years	
	Lavatory	1st Floor South	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor South	6	EA	7	6-10 years	
	Partitions	1st Floor South	9	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor South	255	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor South	255	SF	6	10+ years	
	Water Closet	1st Floor South	9	EA	6	10+ years	
	Accessories	1st Inside 165 Gymnasium	445	SF	7	6-10 years	
	Benches	1st Inside 165 Gymnasium	3	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Inside 165 Gymnasium	445	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Inside 165 Gymnasium	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Inside 165 Gymnasium	445	SF	6	10+ years	
	Floor Drain	1st Inside 165 Gymnasium	1	EA	7	10+ years	
	Hand Dryer	1st Inside 165 Gymnasium	1	EA	7	6-10 years	
	Lavatory	1st Inside 165 Gymnasium	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Inside 165 Gymnasium	6	EA	7	6-10 years	
	Showers	1st Inside 165 Gymnasium	1	EA	7	10+ years	
	Student Lockers - One Tier	1st Inside 165 Gymnasium	8	EA	7	10+ years	
	Walls - Concrete Block	1st Inside 165 Gymnasium	255	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Inside 165 Gymnasium	255	SF	7	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Water Closet	1st Inside 165 Gymnasium	1	EA	6	10+ years	
	Accessories	217B	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	217B	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	217B	1	EA	6	10+ years	
	Floor - Tile	217B	32	SF	5	10+ years	
	Lavatory	217B	1	EA	6	10+ years	
	Lighting - Pendent/Surface	217B	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	217B	171	SF	6	10+ years	
	Water Closet	217B	1	EA	6	10+ years	
	Accessories	265A Restroom Inside Kitchen	72	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	265A Restroom Inside Kitchen	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	265A Restroom Inside Kitchen	1	EA	6	10+ years	
	Floor - Terrazzo	265A Restroom Inside Kitchen	72	SF	6	10+ years	
	Lavatory	265A Restroom Inside Kitchen	1	EA	6	10+ years	
	Lighting - Pendent/Surface	265A Restroom Inside Kitchen	1	EA	7	6-10 years	
	Partitions	265A Restroom Inside Kitchen	2	EA	5	10+ years	
	Walls - Plaster/Drywall	265A Restroom Inside Kitchen	442	SF	6	10+ years	
	Water Closet	265A Restroom Inside Kitchen	2	EA	6	10+ years	
	Accessories	2nd Floor	463	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	458	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	4	0-1 year	Water damage
	Floor - Tile Ceramic/ Porcelain	2nd Floor	463	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Partitions	2nd Floor	5	EA	5	10+ years	
	Walls - Concrete Block	2nd Floor	273	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	273	SF	6	10+ years	
	Water Closet	2nd Floor	5	EA	6	10+ years	
	Accessories	2nd Floor	255	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	255	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	255	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	6-10 years	
	Partitions	2nd Floor	4	EA	5	10+ years	
	Urinals	2nd Floor	6	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	73	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	73	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	146	SF	6	10+ years	
	Water Closet	2nd Floor	4	EA	6	10+ years	
	Accessories	2nd Floor Across from 219A	244	SF	7	6-10 years	13 h

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor Across from 219A	244	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Across from 219A	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Across from 219A	244	SF	6	10+ years	
	Floor Drain	2nd Floor Across from 219A	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Across from 219A	2	EA	7	6-10 years	
	Lavatory	2nd Floor Across from 219A	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Across from 219A	2	EA	7	6-10 years	
	Partitions	2nd Floor Across from 219A	2	EA	5	10+ years	
	Urinals	2nd Floor Across from 219A	3	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor Across from 219A	591	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Across from 219A	313	SF	6	10+ years	
	Water Closet	2nd Floor Across from 219A	2	EA	6	10+ years	
	Accessories	2nd Floor Girl's Restroom next to 223	370	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girl's Restroom next to 223	370	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girl's Restroom next to 223	2	EA	7	10+ years	
	Floor - Tile	2nd Floor Girl's Restroom next to 223	370	SF	7	10+ years	
	Floor Drain	2nd Floor Girl's Restroom next to 223	1	EA	7	10+ years	
	Lavatory	2nd Floor Girl's Restroom next to 223	4	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girl's Restroom next to 223	6	EA	7	6-10 years	
	Partitions	2nd Floor Girl's Restroom next to 223	8	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Girl's Restroom next to 223	300	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Girl's Restroom next to 223	370	SF	7	10+ years	
	Water Closet	2nd Floor Girl's Restroom next to 223	8	EA	7	10+ years	
	Accessories	4th Floor	255	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	4th Floor	255	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	4th Floor	255	SF	6	10+ years	
	Floor Drain	4th Floor	1	EA	7	10+ years	
	Hand Dryer	4th Floor	1	EA	7	6-10 years	
	Lavatory	4th Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	2	EA	7	6-10 years	
	Partitions	4th Floor	2	EA	7	10+ years	
	Urinals	4th Floor	3	EA	6	10+ years	
	Walls - Concrete Block	4th Floor	73	SF	6	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	4th Floor	73	SF	6	10+ years	
	Walls - Structural Glazed Tile	4th Floor	146	SF	6	10+ years	
	Water Closet	4th Floor	2	EA	6	10+ years	
	Accessories	4th Floor	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	4th Floor	245	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	4th Floor	245	SF	6	10+ years	
	Floor Drain	4th Floor	1	EA	7	10+ years	
	Hand Dryer	4th Floor	1	EA	7	6-10 years	
	Lavatory	4th Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	2	EA	7	6-10 years	
	Partitions	4th Floor	5	EA	7	10+ years	
	Walls - Concrete Block	4th Floor	70	SF	6	10+ years	
	Walls - Plaster/Drywall	4th Floor	70	SF	6	10+ years	
	Walls - Structural Glazed Tile	4th Floor	140	SF	6	10+ years	
	Water Closet	4th Floor	5	EA	6	10+ years	
	Accessories	Girls Restroom Next To 323	350	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls Restroom Next To 323	350	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Restroom Next To 323	350	SF	6	10+ years	
	Floor Drain	Girls Restroom Next To 323	1	EA	7	10+ years	
	Hand Dryer	Girls Restroom Next To 323	1	EA	7	6-10 years	
	Lavatory	Girls Restroom Next To 323	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girls Restroom Next To 323	2	EA	7	6-10 years	
	Partitions	Girls Restroom Next To 323	7	EA	7	10+ years	
	Walls - Plaster/Drywall	Girls Restroom Next To 323	950	SF	6	10+ years	
	Walls - Structural Glazed Tile	Girls Restroom Next To 323	450	SF	7	10+ years	
	Water Closet	Girls Restroom Next To 323	7	EA	6	10+ years	
	Accessories	Girls Restroom Next to 368	450	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls Restroom Next to 368	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Girls Restroom Next to 368	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Restroom Next to 368	450	SF	6	10+ years	
	Floor Drain	Girls Restroom Next to 368	1	EA	7	10+ years	
	Hand Dryer	Girls Restroom Next to 368	1	EA	7	6-10 years	
	Lavatory	Girls Restroom Next to 368	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girls Restroom Next to 368	6	EA	6	6-10 years	
	Partitions	Girls Restroom Next to 368	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Girls Restroom Next to 368	600	SF	6	10+ years	
	Walls - Structural Glazed Tile	Girls Restroom Next to 368	250	SF	6	10+ years	
	Water Closet	Girls Restroom Next to 368	10	EA	6	10+ years	
	Accessories	In 122 ROTC Classroom	196	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In 122 ROTC Classroom	196	SF	6	10+ years	
	Floor - Tile	In 122 ROTC Classroom	196	SF	4	1-2 years	Large sections of tile missing and remaining is very old and outdated.
	Hand Dryer	In 122 ROTC Classroom	1	EA	7	6-10 years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lavatory	In 122 ROTC Classroom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In 122 ROTC Classroom	1	EA	7	6-10 years	
	Urinals	In 122 ROTC Classroom	1	EA	6	10+ years	
	Walls - Structural Glazed Tile	In 122 ROTC Classroom	236	SF	5	10+ years	
	Water Closet	In 122 ROTC Classroom	1	EA	6	10+ years	
	Accessories	In Engineers Office	38	SF	7	6-10 years	
	Ceiling - Exposed	In Engineers Office	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Engineers Office	1	EA	6	10+ years	
	Floor - Terrazzo	In Engineers Office	38	SF	6	10+ years	
	Lavatory	In Engineers Office	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In Engineers Office	1	EA	7	6-10 years	
	Walls - Concrete Block	In Engineers Office	108	SF	6	10+ years	
	Walls - Plaster/Drywall	In Engineers Office	225	SF	6	10+ years	
	Water Closet	In Engineers Office	1	EA	6	10+ years	
	Accessories	In Principals Office Suite	48	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Principals Office Suite	48	SF	5	10+ years	Cracking and missing plaster
	Doors - Wood Doors inclu hw	In Principals Office Suite	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Principals Office Suite	48	SF	6	10+ years	
	Lavatory	In Principals Office Suite	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In Principals Office Suite	2	EA	7	6-10 years	
	Partitions	In Principals Office Suite	1	EA	5	10+ years	
	Walls - Plaster/Drywall	In Principals Office Suite	72	SF	5	10+ years	
	Water Closet	In Principals Office Suite	1	EA	6	10+ years	
	Accessories	In Room 207	18	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Room 207	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Room 207	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Room 207	18	SF	6	10+ years	
	Lighting - Pendent/Surface	In Room 207	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	In Room 207	234	SF	6	10+ years	
	Water Closet	In Room 207	1	EA	6	10+ years	
	Accessories	In Room 221	62	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Room 221	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Room 221	1	EA	6	10+ years	
	Floor - Terrazzo	In Room 221	62	SF	6	10+ years	
	Lavatory	In Room 221	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In Room 221	1	EA	6	6-10 years	
	Partitions	In Room 221	1	EA	5	10+ years	
	Walls - Plaster/Drywall	In Room 221	234	SF	6	10+ years	
	Water Closet	In Room 221	1	EA	6	10+ years	
	Ceiling - Plaster/Drywall	In Room 234B	19	SF	6	10+ years	
	Floor - Terrazzo	In Room 234B	19	SF	6	10+ years	
	Partitions	In Room 234B	1	EA	7	10+ years	
	Walls - Plaster/Drywall	In Room 234B	39	SF	6	10+ years	
	Water Closet	In Room 234B	1	EA	6	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Accessories	In Room121A	64	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Room121A	64	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Room121A	1	EA	6	10+ years	
	Floor - Terrazzo	In Room121A	64	SF	6	10+ years	
	Lavatory	In Room121A	1	EA	6	10+ years	
	Lighting - Pendent/Surface	In Room121A	1	EA	7	6-10 years	
	Partitions	In Room121A	1	EA	5	10+ years	
	Walls - Plaster/Drywall	In Room121A	90	SF	6	10+ years	
	Water Closet	In Room121A	1	EA	6	10+ years	
	Accessories	Ladies RM: 310B	400	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Ladies RM: 310B	400	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Ladies RM: 310B	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Ladies RM: 310B	30	SF	6	10+ years	
	Floor Drain	Ladies RM: 310B	1	EA	7	10+ years	
	Hand Dryer	Ladies RM: 310B	1	EA	7	6-10 years	
	Lavatory	Ladies RM: 310B	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Ladies RM: 310B	6	EA	6	6-10 years	
	Partitions	Ladies RM: 310B	8	EA	7	10+ years	
	Walls - Concrete Block	Ladies RM: 310B	1,025	SF	6	10+ years	
	Water Closet	Ladies RM: 310B	8	EA	6	10+ years	
	Accessories	Men's Room next to Auditorium	166	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	Men's Room next to Auditorium	166	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Men's Room next to Auditorium	1	EA	6	10+ years	
	Floor - Terrazzo	Men's Room next to Auditorium	166	SF	6	10+ years	
	Lavatory	Men's Room next to Auditorium	2	EA	6	2-5 years	
	Lighting - Pendent/Surface	Men's Room next to Auditorium	3	EA	6	6-10 years	
	Partitions	Men's Room next to Auditorium	4	EA	7	10+ years	
	Urinals	Men's Room next to Auditorium	2	EA	5	2-5 years	
	Walls - Plaster/Drywall	Men's Room next to Auditorium	95	SF	6	10+ years	
	Walls - Structural Glazed Tile	Men's Room next to Auditorium	95	SF	6	10+ years	
	Water Closet	Men's Room next to Auditorium	2	EA	6	2-5 years	
	Accessories	Men's Room, 4th Floor	62	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men's Room, 4th Floor	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Men's Room, 4th Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	Men's Room, 4th Floor	59	SF	6	10+ years	
	Floor - Tile/Sheet	Men's Room, 4th Floor	3	SF	4	0-1 year	Cracking
	Lavatory	Men's Room, 4th Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Men's Room, 4th Floor	1	EA	7	6-10 years	
	Partitions	Men's Room, 4th Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Men's Room, 4th Floor	62	SF	6	10+ years	
	Water Closet	Men's Room, 4th Floor	1	EA	6	10+ years	
	Accessories	Next To 319	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Next To 319	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Next To 319	1	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Next To 319	30	SF	6	10+ years	
	Hand Dryer	Next To 319	1	EA	7	6-10 years	
	Lavatory	Next To 319	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Next To 319	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Next To 319	70	SF	7	10+ years	
	Water Closet	Next To 319	1	EA	6	10+ years	
	Accessories	Next to 318	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Next to 318	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Next to 318	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Next to 318	40	SF	6	10+ years	
	Lavatory	Next to 318	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Next to 318	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Next to 318	92	SF	6	10+ years	
	Water Closet	Next to 318	1	EA	6	10+ years	
	Accessories	Restroom in 211	76	SF	7	6-10 years	
	Ceiling - Lay-in	Restroom in 211	76	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in 211	1	EA	6	10+ years	
	Floor - Tile	Restroom in 211	76	SF	6	10+ years	
	Lavatory	Restroom in 211	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Restroom in 211	1	EA	6	6-10 years	
	Partitions	Restroom in 211	1	EA	5	6-10 years	
	Walls - Plaster/Drywall	Restroom in 211	489	SF	5	10+ years	
	Water Closet	Restroom in 211	1	EA	6	10+ years	
	Accessories	Room 325C	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 325C	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 325C	1	EA	6	10+ years	
	Floor - Concrete	Room 325C	30	SF	6	10+ years	
	Lavatory	Room 325C	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Room 325C	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 325C	47	SF	6	10+ years	
	Water Closet	Room 325C	1	EA	6	10+ years	
	Accessories	Room 325D	253	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 325D	253	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 325D	253	SF	6	10+ years	
	Hand Dryer	Room 325D	1	EA	7	6-10 years	
	Lavatory	Room 325D	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Room 325D	2	EA	7	6-10 years	
	Partitions	Room 325D	2	EA	7	10+ years	
	Urinals	Room 325D	3	EA	6	10+ years	
	Walls - Plaster/Drywall	Room 325D	146	SF	6	10+ years	
	Walls - Structural Glazed Tile	Room 325D	145	SF	6	10+ years	
	Water Closet	Room 325D	2	EA	6	10+ years	
	Accessories	Room 328A	253	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 328A	253	SF	6	10+ years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	Room 328A	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 328A	253	SF	6	10+ years	
	Floor Drain	Room 328A	1	EA	7	10+ years	
	Hand Dryer	Room 328A	1	EA	7	6-10 years	
	Lavatory	Room 328A	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Room 328A	2	EA	6	6-10 years	
	Partitions	Room 328A	4	EA	5	10+ years	
	Walls - Plaster/Drywall	Room 328A	245	SF	6	10+ years	
	Walls - Structural Glazed Tile	Room 328A	246	SF	6	10+ years	
	Water Closet	Room 328A	4	EA	6	10+ years	
	Ceiling - Plaster/Drywall	Room 356	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 356	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 356	72	SF	6	10+ years	
	Lavatory	Room 356	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Room 356	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 356	96	SF	6	10+ years	
	Water Closet	Room 356	2	EA	6	10+ years	
	Accessories	Room 379A	253	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 379A	253	SF	6	10+ years	
	Doors - Transom Window	Room 379A	91	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 379A	253	SF	6	10+ years	
	Hand Dryer	Room 379A	1	EA	7	6-10 years	
	Lavatory	Room 379A	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Room 379A	4	EA	6	6-10 years	
	Partitions	Room 379A	2	EA	7	10+ years	
	Urinals	Room 379A	4	EA	6	10+ years	
	Walls - Plaster/Drywall	Room 379A	145	SF	6	10+ years	
	Walls - Structural Glazed Tile	Room 379A	146	SF	6	10+ years	
	Water Closet	Room 379A	2	EA	6	10+ years	
	Accessories	Staff Restroom 376B	173	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff Restroom 376B	173	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Staff Restroom 376B	173	SF	6	10+ years	
	Hand Dryer	Staff Restroom 376B	1	EA	7	6-10 years	
	Lavatory	Staff Restroom 376B	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Staff Restroom 376B	2	EA	7	6-10 years	
	Partitions	Staff Restroom 376B	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Staff Restroom 376B	210	SF	6	10+ years	
	Water Closet	Staff Restroom 376B	2	EA	6	10+ years	
	Accessories	Unisex Room, 4th Floor	75	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex Room, 4th Floor	75	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex Room, 4th Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Room, 4th Floor	75	SF	6	10+ years	
	Floor Drain	Unisex Room, 4th Floor	1	EA	7	10+ years	
	Hand Dryer	Unisex Room, 4th Floor	1	EA	7	6-10 years	

Category : Room

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lavatory	Unisex Room, 4th Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Unisex Room, 4th Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Unisex Room, 4th Floor	100	SF	6	10+ years	
	Walls - Structural Glazed Tile	Unisex Room, 4th Floor	150	SF	6	10+ years	
	Water Closet	Unisex Room, 4th Floor	1	EA	6	10+ years	
	Accessories	Women's Room next to Auditorium	166	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	Women's Room next to Auditorium	166	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Women's Room next to Auditorium	1	EA	6	10+ years	
	Floor - Terrazzo	Women's Room next to Auditorium	166	SF	6	10+ years	
	Lavatory	Women's Room next to Auditorium	2	EA	6	2-5 years	
	Lighting - Pendent/Surface	Women's Room next to Auditorium	3	EA	7	6-10 years	
	Partitions	Women's Room next to Auditorium	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Women's Room next to Auditorium	95	SF	6	10+ years	
	Walls - Structural Glazed Tile	Women's Room next to Auditorium	95	SF	6	10+ years	
	Water Closet	Women's Room next to Auditorium	2	EA	7	10+ years	
	Accessories	Women's Room, 4th Floor	62	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's Room, 4th Floor	62	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Women's Room, 4th Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	Women's Room, 4th Floor	62	SF	6	10+ years	
	Lavatory	Women's Room, 4th Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Women's Room, 4th Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Women's Room, 4th Floor	62	SF	7	10+ years	
	Water Closet	Women's Room, 4th Floor	1	EA	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #100 (Computer Lab)							
	AC Units	1st Floor	3	EA	7	6-10 years	
	Ceiling - Splined	1st Floor	1,252	SF	4	2-5 years	Adhesive failed in other locations and likely to spread to the remaining ceiling.
	Ceiling - Splined	1st Floor	60	SF	4	0-1 year	Adhesive failed and tiles missing
	Doors - Side-lite	1st Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,312	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	27	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	355	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,607	SF	6	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroom #101 (Regular Classroom)							
	Casework	1st Floor	6	LF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	1st Floor	864	SF	6	10+ years	
	Chalk Board	1st Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	864	SF	5	2-5 years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	971	SF	6	10+ years	Paint is peeling.
<hr/> Classroom #103 (Computer Lab) <hr/>							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	864	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	10+ years	
	Floor - Wood	1st Floor	864	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	48	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	971	SF	6	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
<hr/> Classroom #105 (Regular Classroom) <hr/>							
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	861	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	3	SF	4	0-1 year	Broken tile
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	864	SF	5	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	940	SF	6	10+ years	
<hr/> Classroom #107 (Art Room) <hr/>							
	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,307	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	3	SF	4	0-1 year	Broken tile
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years	
	Floor - Wood	1st Floor	1,310	SF	5	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,506	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
<hr/> Classroom #108 (Regular Classroom) <hr/>							
	AC Units	1st Floor	1	EA	7	2-5 years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	1st Floor	1,170	SF	6	10+ years	
	Chalk Board	1st Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,170	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,247	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	2-5 years	
<hr/> Classroom #114 (Art Room) <hr/>							
	AC Units	1st Floor	2	EA	7	2-5 years	
	Casework	1st Floor	28	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	1,169	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,169	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	1,247	SF	6	10+ years	
<hr/> Classroom #116 (Special Program) <hr/>							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Exposed	1st Floor	1,475	SF	6	10+ years	
	Doors - Transom Window	1st Floor	160	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Concrete	1st Floor	1,474	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Storage/ Closet	1st Floor	228	SF	5	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,570	SF	5	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
<hr/> Classroom #118 (Computer Lab) <hr/>							
	AC Units	1st Floor	1	EA	5	2-5 years	
	Ceiling - Lay-in	1st Floor	1,161	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	8	SF	5	1-2 years	Damaged tile
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,169	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	27	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	1,247	SF	6	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
<hr/> Classroom #120 (Regular Classroom) <hr/>							

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	AC Units	1st Floor	1	EA	7	2-5 years	
	Ceiling - Lay-in	1st Floor	1,669	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,669	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	21	EA	7	6-10 years	
	Marker Board	1st Floor	48	LF	6	6-10 years	
	Walls - Concrete Block	1st Floor	623	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	624	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
<hr/> Classroom #121 (Regular Classroom) <hr/>							
	Ceiling - Lay-in	1st Floor	543	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	3	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	546	SF	5	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	621	SF	5	10+ years	
<hr/> Classroom #122 (Special Program) <hr/>							
	AC Units	1st Floor	2	EA	7	2-5 years	
	Ceiling - Exposed	1st Floor	2,240	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	2,240	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	31	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	2,320	SF	6	10+ years	
<hr/> Classroom #123 (Regular Classroom) <hr/>							
	Ceiling - Plaster/Drywall	1st Floor	818	SF	6	10+ years	Paint is peeling.
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	818	SF	5	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	108	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	940	SF	6	10+ years	
<hr/> Classroom #125 (Regular Classroom) <hr/>							
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	702	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	175	SF	5	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	830	SF	5	2-5 years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	940	SF	6	10+ years	
<hr/>							
<u>Classroom #127 (Regular Classroom)</u>							
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	810	SF	5	6-10 years	
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Water damage
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	818	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	40	SF	4	1-2 years	Water damage
<hr/>							
<u>Classroom #129 (Regular Classroom)</u>							
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	757	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	757	SF	5	2-5 years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
<hr/>							
<u>Classroom #130 (Regular Classroom)</u>							
	AC Units	1st Floor	1	EA	7	2-5 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	841	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	841	SF	5	2-5 years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	971	SF	6	10+ years	
<hr/>							
<u>Classroom #131 (Regular Classroom)</u>							

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	757	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	757	SF	5	2-5 years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	42	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
<hr/> Classroom #134 (Special Program) <hr/>							
	AC Units	1st Floor	2	EA	5	2-5 years	
	Casework	1st Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	2,140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	2,140	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,114	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	40	SF	4	1-2 years	Damaged and removed drywall
<hr/> Classroom #171 (Laboratory/Shop) <hr/>							
	Ceiling - Exposed	1st Floor	434	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Concrete	1st Floor	4,340	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	88	EA	5	6-10 years	
	Storage/ Closet	1st Floor	864	SF	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	24	EA	6	10+ years	
	Walls - Masonry	1st Floor	4,474	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
<hr/> Classroom #173 (Store Room) <hr/>							
	Ceiling - Exposed	1st Floor	864	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Concrete	1st Floor	864	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	25	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	35	SF	5	10+ years	
	Storage/ Closet	1st Floor	75	SF	5	10+ years	
	Walls - Masonry	1st Floor	902	SF	5	10+ years	
<hr/> Classroom #175 (Computer Lab) <hr/>							
	Ceiling - Exposed	1st Floor	1,161	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Concrete	1st Floor	1,161	SF	7	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	64	LF	6	6-10 years	
	Walls - Masonry	1st Floor	1,123	SF	6	10+ years	
<hr/> Classroom #177 (Store Room) <hr/>							
	Ceiling - Exposed	1st Floor	1,170	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Concrete	1st Floor	1,170	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Marker Board	1st Floor	64	LF	6	6-10 years	
	Walls - Masonry	1st Floor	1,123	SF	6	10+ years	
<hr/> Classroom #209 (Regular Classroom) <hr/>							
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	858	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3	SF	4	0-1 year	Broken tile
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	861	SF	5	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	986	SF	6	10+ years	
<hr/> Classroom #212 (Regular Classroom) <hr/>							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	861	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	861	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	986	SF	6	10+ years	
<hr/> Classroom #213 (Science Lab Level 3) <hr/>							
	Casework	2nd Floor	60	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,378	SF	5	10+ years	Painting needed
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,378	SF	6	10+ years	
	Gas Line	2nd Floor	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	6	6-10 years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	2nd Floor	5	LF	6	6-10 years	
	Science Lab Elements	2nd Floor	1,378	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,522	SF	5	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
<hr/> Classroom #214 (Regular Classroom) <hr/>							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	861	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	861	SF	5	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	986	SF	6	10+ years	
<hr/> Classroom #215 (Science Lab Level 3) <hr/>							
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,318	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,324	SF	6	10+ years	
	Gas Line	2nd Floor	2	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	17	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Science Lab Elements	2nd Floor	1,324	SF	7	10+ years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,522	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
<hr/> Classroom #216 (Regular Classroom) <hr/>							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	861	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	861	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	980	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	6	SF	5	0-1 year	Damaged plaster
Classroom #217 (Science Lab Level 3)							
	Casework	2nd Floor	48	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,244	SF	5	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,244	SF	7	10+ years	
	Gas Line	2nd Floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	24	EA	7	6-10 years	
	Marker Board	2nd Floor	4	LF	6	6-10 years	
	Science Lab Elements	2nd Floor	1,244	SF	7	10+ years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,430	SF	6	10+ years	
Classroom #218 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	675	SF	6	10+ years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	675	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	5	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	791	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroom #219 (Science Lab Level 3)							
	Casework	2nd Floor	60	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,245	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,245	SF	6	10+ years	
	Gas Line	2nd Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,486	SF	6	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
Classroom #220 (Computer Lab)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,047	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	2nd Floor	3	SF	4	0-1 year	Buckled tile
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,042	SF	6	10+ years	
	Floor - Tile	2nd Floor	8	SF	4	0-1 year	Missing tiles
	Lighting - Lay-in	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	5	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,138	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
<hr/>							
<u>Classroom #222 (Regular Classroom)</u>							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	860	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	848	SF	5	10+ years	
	Floor - Tile	2nd Floor	12	SF	4	0-1 year	Damaged
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	48	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,011	SF	6	10+ years	
<hr/>							
<u>Classroom #223 (Science Classroom)</u>							
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	830	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	830	SF	6	6-10 years	
	Gas Line	2nd Floor	1	EA	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Science Lab Elements	2nd Floor	830	SF	7	10+ years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	968	SF	6	10+ years	
<hr/>							
<u>Classroom #224 (Regular Classroom)</u>							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	860	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	860	SF	5	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	60	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	977	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	30	SF	4	0-1 year	Water damage
<hr/>							
<u>Classroom #225 (Regular Classroom)</u>							
	Ceiling - Lay-in	2nd Floor	552	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	552	SF	5	2-5 years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	4	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	651	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
<hr/>							
<u>Classroom #227 (Regular Classroom)</u>							
	Casework	2nd Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	552	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	552	SF	6	2-5 years	
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	651	SF	6	10+ years	
<hr/>							
<u>Classroom #228 (Computer Lab)</u>							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,020	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,020	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	66	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,213	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
<hr/>							
<u>Classroom #229 (Science Lab Level 3)</u>							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	60	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	992	SF	6	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	992	SF	6	10+ years	
	Gas Line	2nd Floor	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	10+ years	
	Science Lab Elements	2nd Floor	992	SF	7	10+ years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,170	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Work Sink	2nd Floor	2	EA	7	10+ years	
Classroom #232 (Computer Lab)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,626	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,626	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	24	EA	7	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,918	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroom #234 (Special Education)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,660	SF	6	10+ years	
	Chalk Board	2nd Floor	60	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,660	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,845	SF	6	10+ years	
Classroom #236 (Special Education)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	525	SF	6	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	525	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	647	SF	6	10+ years	
Classroom #238 (Special Education)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	525	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	525	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	612	SF	6	10+ years	
Classroom #239 (Regular Classroom)							

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	858	SF	5	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	858	SF	5	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Marker Board	2nd Floor	17	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,012	SF	5	10+ years	
<hr/> Classroom #240 (Special Education) <hr/>							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	955	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	10+ years	
	Floor - Wood	2nd Floor	955	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,126	SF	6	10+ years	
<hr/> Classroom #242 (Regular Classroom) <hr/>							
	Ceiling - Plaster/Drywall	2nd Floor	850	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	850	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Marker Board	2nd Floor	5	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,012	SF	6	10+ years	
<hr/> Classroom #300 (Computer Lab) <hr/>							
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	865	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Carpet	3rd Floor	857	SF	6	10+ years	
	Floor - Carpet	3rd Floor	8	SF	4	0-1 year	Ripped
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	10+ years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	925	SF	6	10+ years	
<hr/> Classroom #301 (Regular Classroom) <hr/>							
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	865	SF	6	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	865	SF	6	2-5 years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	925	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #302 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	857	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water Stains
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	865	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	925	SF	6	10+ years	
<u>Classroom #303 (Regular Classroom)</u>							
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	865	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	865	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	30	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,211	SF	6	10+ years	
<u>Classroom #305 (Regular Classroom)</u>							
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	865	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	863	SF	6	10+ years	
	Floor - Tile	3rd Floor	2	SF	4	0-1 year	Missing Tiles
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	925	SF	6	10+ years	
<u>Classroom #307 (Regular Classroom)</u>							
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	865	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	865	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	48	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	925	SF	5	10+ years	
<u>Classroom #308 (Regular Classroom)</u>							

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	AC Units	3rd Floor	1	EA	5	2-5 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	865	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	865	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	925	SF	5	2-5 years	
<hr/> Classroom #309 (Regular Classroom)							
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,107	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,100	SF	6	10+ years	
	Floor - Tile	3rd Floor	7	SF	4	0-1 year	Cracked Tiles
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	40	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,160	SF	5	10+ years	
<hr/> Classroom #310 (Art Room)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,278	SF	6	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,278	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	28	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,345	SF	5	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
<hr/> Classroom #311 (Laboratory/Shop)							
	Casework	3rd Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,275	SF	6	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,278	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	21	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,341	SF	5	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
<hr/> Classroom #312 (Art Room)							
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	48	LF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	3rd Floor	1,262	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	16	SF	5	1-2 years	Water stains
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,278	SF	6	10+ years	
	Instructional Surface	3rd Floor	36	LF	6	10+ years	
	Lighting - Lay-in	3rd Floor	30	EA	7	10+ years	
	Storage/ Closet	3rd Floor	204	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,341	SF	6	10+ years	
	Work Sink	3rd Floor	8	EA	7	10+ years	
<hr/>							
Classroom #313 (Science Lab Level 1)							
	Casework	3rd Floor	80	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,416	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,406	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	0-1 year	Missing Tiles Throughout
	Lighting - Pendent/Surface	3rd Floor	38	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,577	SF	6	10+ years	
	Work Sink	3rd Floor	14	EA	7	10+ years	
<hr/>							
Classroom #314 (Art Room)							
	AC Units	3rd Floor	1	EA	7	10+ years	
	Casework	3rd Floor	44	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,278	SF	6	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,278	SF	6	10+ years	
	Instructional Surface	3rd Floor	36	LF	6	10+ years	
	Lighting - Lay-in	3rd Floor	30	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,341	SF	6	10+ years	
	Work Sink	3rd Floor	8	EA	7	10+ years	
<hr/>							
Classroom #315 (Science Classroom)							
	Casework	3rd Floor	60	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,046	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,046	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	10+ years	
	Storage/ Closet	3rd Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,107	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Work Sink	3rd Floor	7	EA	7	10+ years	
Classroom #316 (Regular Classroom)							
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	309	SF	5	10+ years	Paint peeling
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	309	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	10+ years	
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	347	SF	5	10+ years	
Classroom #317 (Science Lab Level 3)							
	Casework	3rd Floor	60	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,046	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,036	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	0-1 year	Cracked Tiles Throughout
	Lighting - Pendent/Surface	3rd Floor	30	EA	7	10+ years	
	Science Lab Elements	3rd Floor	1,046	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,107	SF	6	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
Classroom #318 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	845	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	5	2-5 years	
Classroom #319 (Science Lab Level 3)							
	Casework	3rd Floor	78	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,224	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,224	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	20	EA	7	10+ years	
	Marker Board	3rd Floor	12	LF	6	10+ years	
	Science Lab Elements	3rd Floor	1,224	SF	7	10+ years	
	Storage/ Closet	3rd Floor	491	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,283	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Work Sink	3rd Floor	9	EA	7	10+ years	
<hr/> Classroom #320 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	845	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<hr/> Classroom #321 (Regular Classroom) <hr/>							
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	673	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	673	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	705	SF	6	10+ years	
<hr/> Classroom #322 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	845	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<hr/> Classroom #323 (Regular Classroom) <hr/>							
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	845	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	2-5 years	
	Floor - Tile	3rd Floor	845	SF	6	2-5 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<hr/> Classroom #324 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	3rd Floor	845	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	879	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	25	SF	4	0-1 year	Water damage
<hr/> Classroom #325 (Regular Classroom) <hr/>							
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	845	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	48	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<hr/> Classroom #327 (Regular Classroom) <hr/>							
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	845	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	48	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<hr/> Classroom #328 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	845	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	48	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<hr/> Classroom #329 (Regular Classroom) <hr/>							
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	845	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	845	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	48	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #330 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	845	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<u>Classroom #331 (Regular Classroom)</u>							
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years	
	Chalk Board	3rd Floor	48	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	845	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<u>Classroom #332 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	5	2-5 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	845	SF	7	10+ years	
	Chalk Board	3rd Floor	48	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	845	SF	6	6-10 years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<u>Classroom #334 (Computer Lab)</u>							
	AC Units	3rd Floor	1	EA	5	2-5 years	
	Ceiling - Lay-in	3rd Floor	1,270	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,270	SF	6	2-5 years	
	Lighting - Lay-in	3rd Floor	21	EA	6	6-10 years	
	Marker Board	3rd Floor	58	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,353	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	10+ years	
<u>Classroom #336 (Computer Lab)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	543	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	Ceiling - Lay-in	3rd Floor	8	SF	5	1-2 years	Buckling	
	Chalk Board	3rd Floor	16	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	551	SF	6	6-10 years		
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	604	SF	6	10+ years		
<hr/>								
Classroom #338 (Computer Lab)								
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	551	SF	7	10+ years		
	Chalk Board	3rd Floor	16	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	551	SF	7	6-10 years		
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	604	SF	7	10+ years		
<hr/>								
Classroom #340 (Computer Lab)								
	AC Units	3rd Floor	2	EA	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	738	SF	7	10+ years		
	Chalk Board	3rd Floor	8	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	738	SF	7	6-10 years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,004	SF	7	10+ years		
<hr/>								
Classroom #351 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	8	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	825	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year	Missing Tiles / Water Stains	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	845	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years		
	Marker Board	3rd Floor	48	LF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	904	SF	5	2-5 years		
<hr/>								
Classroom #353 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	20	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	845	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years		

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	3rd Floor	48	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<hr/> Classroom #355 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	805	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	40	SF	4	0-1 year	Water Stains Throughout
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	845	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
<hr/> Classroom #357 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	845	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	845	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	7	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	904	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
<hr/> Classroom #358 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	848	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	846	SF	6	10+ years	
	Floor - Tile	3rd Floor	2	SF	4	0-1 year	Cracked Tiles
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	60	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	907	SF	6	10+ years	
<hr/> Classroom #359 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	915	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	915	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	974	SF	6	10+ years	
<hr/> Classroom #360 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	848	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	848	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	907	SF	6	10+ years	
<hr/> Classroom #361 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	2-5 years	
	Ceiling - Lay-in	3rd Floor	915	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	915	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	974	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
<hr/> Classroom #362 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	2-5 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	848	SF	6	10+ years	
	Chalk Board	3rd Floor	15	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	848	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	974	SF	6	10+ years	
<hr/> Classroom #363 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	5	6-10 years	
	Casework	3rd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	915	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	915	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	974	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
<hr/> Classroom #364 (Computer Lab) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	848	SF	6	10+ years	
	Chalk Board	3rd Floor	66	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	848	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	907	SF	6	10+ years	
<hr/> Classroom #365 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	915	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	905	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	0-1 year	Cracked Tiles
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	974	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
<hr/> Classroom #366 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	848	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	848	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	66	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	907	SF	6	10+ years	
<hr/> Classroom #367 (Regular Classroom) <hr/>							
	Ceiling - Lay-in	3rd Floor	345	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	345	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	4	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	465	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #368 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	5	2-5 years	Missing front cover
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	848	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	848	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	66	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	974	SF	6	10+ years	
<u>Classroom #369 (Science Lab Level 1)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	100	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	2,544	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	2,544	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	22	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Science Lab Elements	3rd Floor	2,544	SF	7	10+ years	
	Science Lab Fume Hood	3rd Floor	1	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	3,409	SF	6	10+ years	
	Work Sink	3rd Floor	10	EA	7	10+ years	
<u>Classroom #370 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	848	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	848	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	974	SF	6	10+ years	
<u>Classroom #371 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	46	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,028	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,028	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,086	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Classroom #372 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	848	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	848	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	66	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	974	SF	6	10+ years	
<u>Classroom #373 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	688	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	688	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	48	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	746	SF	6	10+ years	
<u>Classroom #374 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	848	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	848	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	66	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	907	SF	6	10+ years	
<u>Classroom #375 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	688	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	688	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	48	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	746	SF	5	10+ years	
<u>Classroom #376 (Regular Classroom)</u>							
	AC Units	3rd Floor	1	EA	7	6-10 years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	848	SF	6	10+ years	
	Chalk Board	3rd Floor	32	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	848	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	907	SF	6	10+ years	
<hr/> Classroom #377 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	688	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	688	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	32	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	746	SF	5	10+ years	
<hr/> Classroom #379 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	688	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	688	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	48	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	746	SF	6	10+ years	
<hr/> Classroom #381 (Regular Classroom) <hr/>							
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	688	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	688	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	48	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	746	SF	6	10+ years	
<hr/> Classroom #415 (Regular Classroom) <hr/>							
	Casework	4th Floor	46	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	445	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	10+ years	
	Floor - Wood	4th Floor	890	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Lay-in	4th Floor	18	EA	7	6-10 years	
	Marker Board	4th Floor	26	LF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	435	SF	6	10+ years	
	Walls - Plaster/Drywall	4th Floor	10	SF	4	0-1 year	Peeled Paint
	Work Sink	4th Floor	1	EA	7	10+ years	
Classroom #416 (Regular Classroom)							
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	890	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	10+ years	
	Floor - Wood	4th Floor	890	SF	6	10+ years	
	Lighting - Lay-in	4th Floor	14	EA	7	6-10 years	
	Marker Board	4th Floor	66	LF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,057	SF	6	10+ years	
Classroom #417 (Regular Classroom)							
	Casework	4th Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	890	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	10+ years	
	Floor - Wood	4th Floor	890	SF	6	10+ years	
	Lighting - Lay-in	4th Floor	18	EA	7	6-10 years	
	Marker Board	4th Floor	26	LF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,057	SF	6	10+ years	
	Work Sink	4th Floor	1	EA	7	10+ years	
Classroom #418 (Regular Classroom)							
	Casework	4th Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	890	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	10+ years	
	Floor - Wood	4th Floor	890	SF	6	10+ years	
	Lighting - Lay-in	4th Floor	14	EA	7	6-10 years	
	Marker Board	4th Floor	66	LF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,057	SF	6	10+ years	
Classroom #420 (Music Room)							
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	1,335	SF	6	10+ years	
	Chalk Board	4th Floor	12	LF	4	2-5 years	
	Doors - Side-lite	4th Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	10+ years	
	Floor - Wood	4th Floor	1,335	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Lay-in	4th Floor	24	EA	7	6-10 years	
	Storage/ Closet	4th Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	1,588	SF	6	10+ years	
	Work Sink	4th Floor	1	EA	7	10+ years	
<hr/> Classroom #421 (Music Room) <hr/>							
	Casework	4th Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	1,405	SF	6	10+ years	
	Chalk Board	4th Floor	8	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	10+ years	
	Floor - Wood	4th Floor	1,405	SF	6	10+ years	
	Lighting - Lay-in	4th Floor	24	EA	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,590	SF	6	10+ years	
	Work Sink	4th Floor	1	EA	7	10+ years	
<hr/> Classroom #422 (Regular Classroom) <hr/>							
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	890	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	10+ years	
	Floor - Wood	4th Floor	890	SF	6	10+ years	
	Lighting - Lay-in	4th Floor	21	EA	7	6-10 years	
	Marker Board	4th Floor	66	LF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,057	SF	6	10+ years	
<hr/> Classroom #423 (Regular Classroom) <hr/>							
	Casework	4th Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	445	SF	6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	445	SF	6	10+ years	
	Chalk Board	4th Floor	24	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	10+ years	
	Floor - Tile	4th Floor	880	SF	6	10+ years	
	Floor - Tile	4th Floor	10	SF	4	0-1 year	Cracked Tiles
	Lighting - Lay-in	4th Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,057	SF	6	10+ years	
<hr/> Classroom #424 (Regular Classroom) <hr/>							
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	890	SF	6	10+ years	
	Chalk Board	4th Floor	66	LF	4	2-5 years	
	Doors - Steel Doors incl hw	4th Floor	1	EA	6	10+ years	
	Floor - Wood	4th Floor	890	SF	6	10+ years	

Category : Classroom

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Lay-in	4th Floor	21	EA	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,057	SF	6	10+ years	

Classroom #425 (Regular Classroom)

	Casework	4th Floor	49	LF	6	10+ years	
	Ceiling - Lay-in	4th Floor	445	SF	6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	445	SF	6	10+ years	
	Chalk Board	4th Floor	16	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	4th Floor	1	EA	6	10+ years	
	Floor - Wood	4th Floor	890	SF	6	10+ years	
	Lighting - Lay-in	4th Floor	18	EA	7	6-10 years	
	Marker Board	4th Floor	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,057	SF	6	10+ years	
	Work Sink	4th Floor	1	EA	7	10+ years	

Classroom #500 (Music Room)

	AC Units	5th Floor	3	EA	7	6-10 years	
	Ceiling - Lay-in	5th Floor	3,211	SF	6	10+ years	
	Doors - Steel Doors incl hw	5th Floor	2	EA	6	10+ years	
	Doors - Wood Doors inclu hw	5th Floor	1	EA	6	10+ years	
	Floor - Tile	5th Floor	3,211	SF	6	10+ years	
	Lighting - Lay-in	5th Floor	60	EA	7	6-10 years	
	Storage/ Closet	5th Floor	125	SF	7	10+ years	
	Storage/ Closet	5th Floor	95	SF	7	10+ years	
	Storage/ Closet	5th Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	5th Floor	3,596	SF	5	10+ years	

Category : Interior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Corridor</u>							
	Ceiling - Lay-in	1st Floor	9,992	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	33	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	1st Floor	1,900	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	11	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	11,900	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	25	SF	4	0-1 year	Cracked tiles
	Lighting - Lay-in	1st Floor	64	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	761	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	6,857	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	6,837	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	4	0-1 year	Water damage

Category : Interior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	2nd Floor	8,529	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	0-1 year	Missing/damaged tiles
	Drinking Fountains - Single Water Cooler	2nd Floor	9	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	4,270	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	4,230	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	40	SF	4	0-1 year	Cracked tiles
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	734	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10,078	SF	5	10+ years	
	Ceiling - Lay-in	3rd Floor	12,195	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	80	SF	4	0-1 year	Water damage or missing tiles.
	Doors - Wood Doors include hw	3rd Floor	2	EA	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	8	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	11,260	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,000	SF	5	2-5 years	
	Floor - Tile/Sheet	3rd Floor	15	SF	4	0-1 year	Cracked or missing tiles.
	Lighting - Lay-in	3rd Floor	102	EA	7	10+ years	
	Student Lockers - One Tier	3rd Floor	648	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	12,395	SF	6	10+ years	
	Ceiling - Lay-in	4th Floor	2,988	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	4th Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	4th Floor	2,888	SF	7	10+ years	
	Floor - Tile/Sheet	4th Floor	100	SF	4	0-1 year	Cracked Tiles Throughout
	Lighting - Lay-in	4th Floor	22	EA	7	10+ years	
	Student Lockers - One Tier	4th Floor	211	EA	6	10+ years	
	Walls - Plaster/Drywall	4th Floor	3,436	SF	6	10+ years	
	Ceiling - Lay-in	5th Floor	175	SF	6	10+ years	
	Floor - Tile/Sheet	5th Floor	175	SF	7	10+ years	
	Lighting - Lay-in	5th Floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	5th Floor	504	SF	6	10+ years	

Safety

Camera Viewing Station	Entire Building	3	EA	7	10+ years
Metal Dedector	Entire Building	2	EA	7	10+ years
Security Cameras	Entire Building	10	EA	7	10+ years
Security Cameras	Entire Building	42	EA	7	10+ years

Stairs

Ceiling - Plaster/Drywall	S-1	163	SF	6	10+ years
Floor - Asphalt	S-1	163	SF	6	10+ years
Handrails	S-1	380	LF	5	10+ years
Lighting - Pendent/Surface	S-1	10	EA	7	6-10 years
Stairs - Asphalt	S-1	815	LF	6	10+ years

Category : Interior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	S-1	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	S-11	163	SF	6	10+ years	
	Floor - Terrazzo	S-11	163	SF	6	10+ years	
	Handrails	S-11	380	LF	7	10+ years	
	Lighting - Pendent/Surface	S-11	10	EA	7	10+ years	
	Stairs - Terrazzo	S-11	489	LF	6	10+ years	
	Walls - Concrete Block	S-11	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	S-15	163	SF	6	10+ years	
	Floor - Terrazzo	S-15	163	SF	6	10+ years	
	Handrails	S-15	380	LF	7	10+ years	
	Lighting - Pendent/Surface	S-15	10	EA	7	10+ years	
	Stairs - Terrazzo	S-15	489	LF	6	10+ years	
	Walls - Concrete Block	S-15	165	SF	6	10+ years	
	Ceiling - Lay-in	S-17	163	SF	6	10+ years	
	Floor - Terrazzo	S-17	163	SF	6	10+ years	
	Handrails	S-17	389	LF	5	10+ years	
	Lighting - Lay-in	S-17	10	EA	7	6-10 years	
	Stairs - Terrazzo	S-17	489	LF	6	10+ years	
	Walls - Plaster/Drywall	S-17	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	S-2	163	SF	6	10+ years	Paint peeling
	Floor - Asphalt	S-2	163	SF	6	10+ years	
	Handrails	S-2	380	LF	5	10+ years	
	Lighting - Pendent/Surface	S-2	10	EA	7	6-10 years	
	Stairs - Asphalt	S-2	815	LF	6	10+ years	
	Walls - Plaster/Drywall	S-2	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	S-3	163	SF	6	10+ years	
	Floor - Asphalt	S-3	163	SF	6	10+ years	
	Handrails	S-3	380	LF	7	10+ years	
	Lighting - Pendent/Surface	S-3	10	EA	7	10+ years	
	Stairs - Asphalt	S-3	652	LF	6	10+ years	
	Walls - Plaster/Drywall	S-3	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	S-4	163	SF	6	10+ years	
	Floor - Asphalt	S-4	163	SF	6	10+ years	
	Handrails	S-4	380	LF	5	10+ years	
	Lighting - Pendent/Surface	S-4	10	EA	7	6-10 years	
	Stairs - Asphalt	S-4	652	LF	6	10+ years	
	Walls - Plaster/Drywall	S-4	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	S-5	163	SF	6	10+ years	
	Floor - Terrazzo	S-5	163	SF	6	10+ years	
	Handrails	S-5	380	LF	7	10+ years	
	Lighting - Pendent/Surface	S-5	10	EA	7	10+ years	
	Stairs - Terrazzo	S-5	489	LF	6	10+ years	
	Walls - Plaster/Drywall	S-5	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	S-6	163	SF	6	10+ years	

Category : Interior

Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Terrazzo	S-6	163	SF	6	10+ years	
	Handrails	S-6	380	LF	7	10+ years	
	Lighting - Pendent/Surface	S-6	10	EA	7	10+ years	
	Stairs - Terrazzo	S-6	489	LF	6	10+ years	
	Walls - Plaster/Drywall	S-6	165	SF	6	10+ years	
	Ceiling - Lay-in	S-7	163	SF	6	10+ years	
	Floor - Terrazzo	S-7	163	SF	6	10+ years	
	Handrails	S-7	380	LF	5	10+ years	
	Lighting - Lay-in	S-7	10	EA	6	6-10 years	
	Stairs - Terrazzo	S-7	489	LF	6	10+ years	
	Walls - Concrete Block	S-7	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	S-8	163	SF	6	10+ years	
	Floor - Terrazzo	S-8	163	SF	6	10+ years	
	Handrails	S-8	380	LF	7	10+ years	
	Lighting - Pendent/Surface	S-8	10	EA	7	10+ years	
	Stairs - Terrazzo	S-8	489	LF	6	10+ years	
	Walls - Concrete Block	S-8	165	SF	6	10+ years	
<hr/>							
Vertical Conveyance							
	Elevator - Elevator- Roped Holeless Hydraulic	1st Floor	3	EA	6	10+ years	

Category : Site

Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Athletic</u>							
	Lighting	Northwest	6	EA	6	10+ years	
	Metal Bleachers	Northwest	240	LF	7	10+ years	
	Surface - Concrete	Northwest	1,662	SF	7	10+ years	
	Surface - Natural	Northwest	8,418	SF	7	10+ years	
	Surface - Synthetic	Northwest	76,135	SF	7	10+ years	
<u>Civil/Drainage</u>							
	Civil/ Drainage - Catch Basin	Entire Site	12	EA	6	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	5	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	4	0-1 year	Catch basin has failed and dropped
	Civil/ Drainage - Site Drain	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	17	EA	6	10+ years	
<u>Fencing</u>							
	Fencing - Chain Link	Entire Site	871	LF	7	10+ years	New fence
	Fencing - Chain Link	Entire Site	855	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	10	LF	5	1-2 years	Fence post has come out of alignment
	Fencing - Iron and Concrete Post	Entire Site	986	LF	7	10+ years	This is a 25 foot tall netting fence with large metal posts. It wraps around the turf field
	Fencing - Iron and Concrete Post	Entire Site	1,545	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	741	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	20	LF	4	0-1 year	Damaged gate equipment and post
	Fencing - New Standard Ornamental	Entire Site	364	LF	4	1-2 years	Fence is very rusted and beyond repair
<u>Landscape</u>							
	Benches	Entire Site	5	EA	6	2-5 years	
	Benches	Entire Site	3	EA	5	1-2 years	
	Benches	Entire Site	3	EA	4	0-1 year	Rusted, damaged benches
	Irrigation	Entire Site	136,500	SF	6	10+ years	
	Landscape - Grass	Entire Site	111,600	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	6,920	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	400	SF	5	1-2 years	Broken concrete hard scape
	Landscape - Hardscape- Concrete	Entire Site	40	SF	4	1-2 years	Concrete is damaged
	Landscape - Hardscape- Concrete	Entire Site	500	SF	4	1-2 years	Broken concrete. The concrete has settled cracking around a manhole
	Landscape - Hardscape- Pavers	Entire Site	2,350	SF	6	10+ years	
	Parkway trees	Entire Site	45	EA	6	10+ years	Needs cleaning some joints and weeding

Category : Site

Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Planting Beds/ Area	Entire Site	24,900	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	425	SF	6	10+ years	
	Trash Receptacles	Entire Site	10	EA	7	10+ years	
Parking Lot							
	Surface - Asphalt	Interior Courtyard	6,210	SF	6	6-10 years	
	Trash Enclosure - Chain Links	Interior Courtyard	384	SF	7	10+ years	The enclosure is for electrical equipment
	Concrete Curbs	SW of site	212	LF	7	10+ years	
	Interior Plantings	SW of site	62	LF	5	10+ years	
	Lighting - Pole Mounted	SW of site	1	EA	6	10+ years	
	Surface - Asphalt	SW of site	26,500	SF	4	0-1 year	Highly distressed surface
Sidewalks							
	Sidewalks - Internal Walks	Entire Site	1,290	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	21,700	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	456	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	250	SF	4	1-2 years	Concrete is damaged
Signage							
	Marquee - Free Standing Back Lighted	SW courtyard	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	SW courtyard	1	EA	6	10+ years	
	Monument - Sign	SW courtyard	1	EA	7	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Building : Main									
Art Room	Art Room	1st Floor	114	116	1,169	54	27	N	N
Art Room	Laboratory/Shop	1st Floor	107	112	1,310	104	91	N	Y
Art Room	Regular Classroom	3rd Floor	310	310	1,278	273	96	N	N
Art Room	Special Program	3rd Floor	312	313	1,278	273	96	N	N
Art Room	Special Program	3rd Floor	314	315	1,278	273	96	N	N
Computer Lab	Computer Lab	2nd Floor	228	228	1,020	209	75	N	N
Computer Lab	Laboratory/Shop	1st Floor	175	173	1,161	96	36	N	Y
Computer Lab	Multi Purpose Room	3rd Floor	334	331	1,270	24	16	N	N
Computer Lab	Multi Purpose Room	3rd Floor	336	331	551	48	32	N	N
Computer Lab	Multi Purpose Room	3rd Floor	338	331	551	144	96	N	N
Computer Lab	Multi Purpose Room	3rd Floor	340	340	738	144	96	N	N
Computer Lab	Regular Classroom	1st Floor	100	101	1,312	390	220	N	N
Computer Lab	Regular Classroom	1st Floor	103	104	864	162	53	N	Y
Computer Lab	Regular Classroom	1st Floor	118	118	1,169	96	0		
Computer Lab	Regular Classroom	2nd Floor	220	218	1,050	186	60	N	Y
Computer Lab	Regular Classroom	2nd Floor	232	230 & 229	1,626	304	105	N	Y
Computer Lab	Regular Classroom	3rd Floor	300	300	865	729	256	N	N
Computer Lab	Regular Classroom	3rd Floor	364	362	848	182	64	N	N
Laboratory/Shop	Laboratory/Shop	1st Floor	171	170	4,340	144	54	N	N
Laboratory/Shop	Laboratory/Shop	3rd Floor	311	312	1,278	273	96	N	N
Music Room	Art Room	4th Floor	420	420	1,335	208	90	N	N
Music Room	Music Room	4th Floor	421	421	1,405	182	84	N	N
Music Room	Music Room	5th Floor	500	500	3,211	124	30	N	N
Regular Classroom	Art Room	4th Floor	417	419	890	120	0	N	N
Regular Classroom	Art Room	4th Floor	425	426	890	120	0	N	N
Regular Classroom	Laboratory/Shop	3rd Floor	367	363	345	91	32	N	N
Regular Classroom	Lunch Room	3rd Floor	316	316	309	136	48	N	N
Regular Classroom	Office	3rd Floor	357	353	845	136	48	N	N
Regular Classroom	Regular Classroom	1st Floor	101	103	864	162	53	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	864	162	53	N	N
Regular Classroom	Regular Classroom	1st Floor	108	113	1,170	228	80	N	N
Regular Classroom	Regular Classroom	1st Floor	120	120	1,669	228	80	N	N
Regular Classroom	Regular Classroom	1st Floor	121	NA	546	114	62	N	N
Regular Classroom	Regular Classroom	1st Floor	123	NA	818	160	75	N	N
Regular Classroom	Regular Classroom	1st Floor	125	135	830	160	75	N	N
Regular Classroom	Regular Classroom	1st Floor	127	136	818	160	75	N	N
Regular Classroom	Regular Classroom	1st Floor	129	137	757	160	75	N	N
Regular Classroom	Regular Classroom	1st Floor	130	130	841	144	60	N	Y

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Regular Classroom	Regular Classroom	1st Floor	131	138	757	160	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	211	861	195	114	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	214	861	162	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	212	861	162	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	214	861	126	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	217	675	90	36	N	N
Regular Classroom	Regular Classroom	2nd Floor	222	223	860	133	45	N	N
Regular Classroom	Regular Classroom	2nd Floor	224	224	860	114	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	225	235	552	160	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	239	239	858	141	30	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	303	865	162	95	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	865	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	304	865	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	865	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	865	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	309	865	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	311	1,107	273	96	N	N
Regular Classroom	Regular Classroom	3rd Floor	318	317	845	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	320	318	845	182	64		
Regular Classroom	Regular Classroom	3rd Floor	321	327	673	109	54		Y
Regular Classroom	Regular Classroom	3rd Floor	322	323	845	182	64		
Regular Classroom	Regular Classroom	3rd Floor	323	334	845	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	324	324	845	182	64		
Regular Classroom	Regular Classroom	3rd Floor	325	335	845	182	64	N	Y
Regular Classroom	Regular Classroom	3rd Floor	327	336	845	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	845	136	48	N	Y
Regular Classroom	Regular Classroom	3rd Floor	329	337	845	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	330	329	845	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	331	338	845	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	332	330	845	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	351	350	845	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	353	351	845	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	355	352	845	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	358	356	848	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	359	355	915	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	360	358	848	112	45	N	N
Regular Classroom	Regular Classroom	3rd Floor	361	357	915	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	362	360	848	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	363	359	915	228	80	N	Y
Regular Classroom	Regular Classroom	3rd Floor	365	361	915	228	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	366	364	848	182	64	N	N

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Regular Classroom	Regular Classroom	3rd Floor	368	366	848	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	370	368	848	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	371	369	1,028	273	96	N	Y
Regular Classroom	Regular Classroom	3rd Floor	372	370	848	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	373	371	688	273	96	N	N
Regular Classroom	Regular Classroom	3rd Floor	374	372	848	182	64	N	N
Regular Classroom	Regular Classroom	3rd Floor	375	373	688	273	96	N	N
Regular Classroom	Regular Classroom	3rd Floor	376	374	848	136	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	377	375	688	273	96	N	N
Regular Classroom	Regular Classroom	3rd Floor	379	377	688	273	96	N	N
Regular Classroom	Regular Classroom	3rd Floor	381	379	688	273	96	N	N
Regular Classroom	Regular Classroom	4th Floor	415	416	890	120	40	N	N
Regular Classroom	Regular Classroom	4th Floor	416	417	890	112	45	N	N
Regular Classroom	Regular Classroom	4th Floor	418	418	890	144	60	N	N
Regular Classroom	Regular Classroom	4th Floor	422	423	890	128	45	N	N
Regular Classroom	Regular Classroom	4th Floor	423	425	890	120	0	N	N
Regular Classroom	Regular Classroom	4th Floor	424	424	890	112	45	N	N
Regular Classroom	Science Classroom	2nd Floor	227	236	552	160	75	N	N
Regular Classroom	Special Program	2nd Floor	242	239	850	224	105	N	N
Science Classroom	Science Lab Level 3	2nd Floor	223	234	830	160	75	N	N
Science Classroom	Special Program	3rd Floor	315	320	1,046	273	96	N	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	313	319	1,416	410	144	N	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	369	365	2,544	182	64	N	N
Science Lab Level 3	Regular Classroom	2nd Floor	229	237 & 238	992	152	60	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	213	219	1,378	248	120	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	215	220	1,324	246	120	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	217	NA	1,244	204	99	N	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	219	222	1,245	217	105	N	N
Science Lab Level 3	Science Lab Level 3	3rd Floor	319	322	1,224	400	144	N	N
Science Lab Level 3	Special Program	3rd Floor	317	321	1,046	273	96	N	Y
Special Education	Multi Purpose Room	2nd Floor	234	231	1,660	16	0	N	N
Special Education	Multi Purpose Room	2nd Floor	236	231	525	80	30	N	Y
Special Education	Multi Purpose Room	2nd Floor	238	231	525	80	30	N	N
Special Education	Multi Purpose Room	2nd Floor	240	240	955	208	90	N	N
Special Program	Library	1st Floor	134	131	2,140	288	120	N	Y
Special Program	Special Program	1st Floor	116	117	1,474	46	0	N	N
Special Program	Special Program	1st Floor	122	124	2,240	52	14	N	N
Store Room	Laboratory/Shop	1st Floor	177	177	1,170	96	45	N	N
Store Room	Regular Classroom	1st Floor	173	175	864	72	27	N	N