

Facility Assessment Report

This report contains a summary of the results from the facility assessment completed on the date noted in the document footer below. This report will roll-up each assessed item with identical rank and total the quantity into a single line, regardless of item location (for location data, see the detailed report). Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1963 | 3 | 63,816 | \$3,285,225 |
| SITE | | | | \$111,414 |
| Campus Total | | | 63,816 | \$3,396,639 |

Building: Main

Category: Building Exterior

| Entrance Control - Audio | 1 | EA | 6 | \$497 |
|---|--|---|--|---|
| Entrance Control - Audio and Video | 2 | EA | 6 | \$1,403 |
| Exterior Doors - Exterior Steel Door | 9 | EA | 6 | \$4,325 |
| Exterior Doors - Side lite | 4 | EA | 6 | \$1,253 |
| Exterior Doors - Store Front | 3 | EA | 5 | \$5,509 |
| Exterior Doors - Store Front | 2 | EA | 6 | \$1,092 |
| Exterior Doors - Transom Lite | 1 | EA | 6 | \$313 |
| Exterior Stairs - Concrete | 96 | LF | 6 | \$7,850 |
| Power Door Operator and Controls | 1 | EA | 6 | \$0 |
| Ramp Handrail - Steel_Ramp Handrail | 134 | LF | 6 | \$1,161 |
| Ramps - Concrete | 80 | LF | 6 | \$12,019 |
| Ramps - Concrete | 6 | LF | 7 | \$0 |
| Stair Handrail - Steel_Stair Handrail | 32 | LF | 6 | \$277 |
| | | | | |
| Foundation - Concrete | 1,002 | LF | 7 | \$0 |
| Superstructure - Concrete | 5 | SF | 5 | \$0 |
| Superstructure - Concrete | 63,811 | SF | 7 | \$0 |
| | | | | |
| Exterior Lighting - Parapet or Roof Mounted | 10 | EA | 6 | \$5,365 |
| | Entrance Control - Audio and Video Exterior Doors - Exterior Steel Door Exterior Doors - Side lite Exterior Doors - Store Front Exterior Doors - Store Front Exterior Doors - Transom Lite Exterior Stairs - Concrete Power Door Operator and Controls Ramp Handrail - Steel_Ramp Handrail Ramps - Concrete Ramps - Concrete Stair Handrail - Steel_Stair Handrail Foundation - Concrete Superstructure - Concrete Superstructure - Concrete | Entrance Control - Audio and Video2Exterior Doors - Exterior Steel Door9Exterior Doors - Side lite4Exterior Doors - Store Front3Exterior Doors - Store Front2Exterior Doors - Transom Lite1Exterior Stairs - Concrete96Power Door Operator and Controls1Ramp Handrail - Steel_Ramp Handrail134Ramps - Concrete6Stair Handrail - Steel_Stair Handrail32Foundation - Concrete5Superstructure - Concrete5Superstructure - Concrete1,002Exterior Lighting - Parapet or Roof Mounted10 | Entrance Control - Audio and Video2EAExterior Doors - Exterior Steel Door9EAExterior Doors - Side lite4EAExterior Doors - Store Front3EAExterior Doors - Store Front2EAExterior Doors - Transom Lite1EAExterior Stairs - Concrete96LFPower Door Operator and Controls1EARamp Handrail - Steel_Ramp Handrail134LFRamps - Concrete80LFStair Handrail - Steel_Stair Handrail32LFFoundation - Concrete1,002LFSuperstructure - Concrete5SFSuperstructure - Concrete5SFSuperstructure - Concrete10EA | Entrance Control - Audio and Video2EA6Exterior Doors - Exterior Steel Door9EA6Exterior Doors - Side lite4EA6Exterior Doors - Store Front3EA5Exterior Doors - Store Front2EA6Exterior Doors - Transom Lite1EA6Exterior Stairs - Concrete96LF6Power Door Operator and Controls1EA6Ramps - Concrete80LF6Ramps - Concrete6LF7Stair Handrail - Steel_Stair Handrail32LF7Stair Handrail - Steel_Stair Handrail1,002LF7Superstructure - Concrete5SF5Superstructure - Concrete63,811SF7Exterior Lighting - Parapet or Roof Mounted10EA6 |



Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|---|----------|------|------|------------|
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 1 | EA | 4 | \$1,030 |
| | Exterior Lighting - Wall Mounted | 1 | EA | 5 | \$427 |
| | Exterior Lighting - Wall Mounted | 24 | EA | 6 | \$6,930 |
| Roof System | | | | | |
| | Chimney - Brick Chimney- Concrete/ Mortar Liner | 36 | LF | 5 | \$102,656 |
| | Coping - Metal | 1,172 | LF | 6 | \$37,642 |
| | Coping - Metal | 25 | LF | 7 | \$C |
| | Downspouts - Exterior Downspouts | 26 | LF | 7 | \$0 |
| | Downspouts - Interior Downspouts | 351 | LF | 7 | \$0 |
| | Parapet - 16" - 30" Height | 25 | LF | 7 | \$0 |
| | Roof - Modified Bitumen | 390 | SF | 4 | \$10,691 |
| | Roof - Modified Bitumen | 29,704 | SF | 5 | \$624,833 |
| | Roof - Modified Bitumen | 82 | SF | 6 | \$772 |
| | Roof Structure - Concrete | 30,094 | SF | 7 | \$0 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 82 | SF | 7 | \$0 |
| Walls | | | | | |
| | Canopy - Concrete/ Stucco | 3,114 | SF | 6 | \$103,043 |
| | Canopy - Metal | 97 | SF | 7 | \$0 |
| | Cheek-Wall - Concrete | 5 | SF | 5 | \$118 |
| | Exterior Walls - Brick | 1,867 | SF | 5 | \$44,452 |
| | Exterior Walls - Brick | 21,273 | SF | 7 | \$0 |
| | Exterior Walls - Precast Panel Wall | 960 | SF | 7 | \$0 |
| Windows | | | | | |
| | Curtain wall - Insulated Panel | 323 | SF | 6 | \$3,621 |
| | Curtain wall - Louver | 25 | SF | 6 | \$280 |
| | Curtain wall - Louver | 125 | SF | 7 | \$0 |
| | Guard - Guards perforated | 6,741 | SF | 6 | \$86,082 |
| | Lintels - Steel | 14 | LF | 5 | \$4,732 |
| | Lintels - Steel | 1,477 | LF | 6 | \$42,876 |
| | Windows - Sash Aluminum | 328 | SF | 7 | \$0 |
| | Windows - Sash Aluminum Double-pane | 8,778 | SF | 7 | \$0 |
| Building Extor | | | | | ¢1 111 250 |

Building Exterior Subtotal:

\$1,111,250

Building: Main



\$60,247

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--|----------|------|------|----------|
| Emergency System | n | | | | |
| | Automatic Transfer Switch | 1 | EA | 6 | \$408 |
| | Emergency A/C Power - Corridors and Stairs | 10,516 | SF | 6 | \$3,158 |
| | Emergency A/C Power - Gym | 3,603 | SF | 6 | \$1,340 |
| | Emergency A/C Power - Multipurpose Room | 1,516 | SF | 6 | \$564 |
| | Emergency Battery Packs - Corridors and Stairs | 25 | EA | 6 | \$5,063 |
| | Emergency Battery Packs - Gym | 4 | EA | 6 | \$810 |
| | Emergency Battery Packs - Lunchrooms | 6 | EA | 6 | \$1,215 |
| | Emergency Battery Packs - Students Toilets | 4 | EA | 6 | \$810 |
| | Exit Signs - Corridors and Stairs | 12 | EA | 6 | \$1,797 |
| | Exit Signs - Gym | 4 | EA | 6 | \$630 |
| | Exit Signs - Lunchroom | 5 | EA | 6 | \$749 |
| | Security System - CCTV | 63,816 | SF | 6 | \$19,164 |
| | Security System - Intrusion Detection | 63,816 | SF | 6 | \$16,426 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 1 | EA | 6 | \$2,921 |
| | Main Electrical Service - 1600 A 120/208/3PH | 1 | EA | 6 | \$5,641 |
| | PA System | 63,816 | SF | 6 | \$20,989 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 1 | EA | 6 | \$299 |
| | Lighting and Power Panels - Above 100 A | 18 | EA | 6 | \$8,946 |
| | Main Distribution Panels - 400 - 600 amp | 2 | EA | 6 | \$1,055 |
| Electrical Syst | em Subtotal: | | | | \$91,984 |
| Building: Mair | | | | | |
| - | | | | | |
| Category: Saft | y System | | | | |

| 0, | | | | | |
|------------|--------------------------|----------|------|------|----------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 6 | \$6,406 |
| | Fire Alarm Strobe Lights | 63,816 | SF | 6 | \$22,814 |
| | Fire Alarm_System | 63,816 | SF | 6 | \$31,027 |
| | | | | | |

Safty System Subtotal:

| Building: Ma | in | | | | | |
|---------------|------------------|--------------|----------|------|------|---------------------------|
| Category: Me | echanical System | | | | | |
| Group | Item - Type | | Quantity | Unit | Rank | Cost |
| NOBLE - JOHNS | ON HS | Page 3 of 18 | | | | Assessment Date: 6/4/2015 |



Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|---|----------|------|------|-----------|
| Air Conditioning | | | | | |
| | Condensing Unit- Roof Mounted - 5-10 tons | 2 | EA | 6 | \$6,667 |
| | Condensing Unit- Roof Mounted - Less than 5 tons | 2 | EA | 6 | \$6,667 |
| Air Handling Systems | | | | | |
| | Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 15001-20000 cfm | 1 | EA | 6 | \$3,350 |
| | Air Intake | 1 | EA | 6 | \$5,765 |
| | Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM | 1 | EA | 6 | \$1,857 |
| | Roof Top Unit-Multi Zone-Roof Mounted- Electric Coils - Less than 10 tons | 4 | EA | 6 | \$8,205 |
| | Zone Dampers | 6 | EA | 6 | \$4,998 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 201 - 300 HP | 2 | EA | 6 | \$1,996 |
| | Chemical Feed System | 1 | EA | 6 | \$1,078 |
| | Combustion Dampers | 4 | EA | 5 | \$10,208 |
| | Condensate Pump | 2 | EA | 5 | \$36,392 |
| | Feed Water Pumps and Tank | 1 | EA | 5 | \$36,450 |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP | 2 | EA | 6 | \$1,996 |
| | Piping - Condensate Pipe- Steel | 250 | LF | 6 | \$472 |
| | Piping - Steam Pipe- Steel | 250 | LF | 6 | \$472 |
| | Steam Traps | 25 | EA | 5 | \$32,872 |
| Gas Booster | | | | | |
| | Gas Booster | 2 | EA | 6 | \$998 |
| Heat Exchangers | | | | | |
| | Heat Exchanger - Steam to Hot Water Shell Type | 1 | EA | 5 | \$11,535 |
| Heating Devices | | | | | |
| | Fin Tube - Electric | 10 | LF | 6 | \$94 |
| | Fin Tube - Hot Water | 40 | LF | 6 | \$378 |
| | Radiators - Hot Water | 2 | EA | 5 | \$3,244 |
| | Radiators - Hot Water | 13 | EA | 6 | \$3,611 |
| | Unit Heater - Electric | 6 | EA | 6 | \$1,667 |
| Mechanical Plumbing | | | | | |
| | Hot Water Pump - Less than 10 | 2 | EA | 6 | \$2,222 |
| | Hydronic Supply and Return - Galvanized | 500 | LF | 6 | \$38,660 |
| Temperature Control | | | | | |
| | Pneumatic System | 63,816 | SF | 5 | \$219,929 |
| | Thermostats - Pneumatic | 23 | EA | 4 | \$16,956 |



Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|---|----------|------|------|-----------|
| Temperature Contro | bl | | | | |
| | Thermostats - Pneumatic | 20 | EA | 6 | \$0 |
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only | 9 | EA | 4 | \$167,388 |
| | Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only | 30 | EA | 5 | \$256,886 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | 4 | EA | 6 | \$2,370 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 2 | EA | 4 | \$8,489 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 6 | EA | 6 | \$3,554 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 2 | EA | 6 | \$592 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 1 | EA | 7 | \$0 |
| | Lab Exhaust Hood | 1 | EA | 6 | \$1,248 |
| | Type I Exhaust Hood- Kitchen | 1 | EA | 2 | \$28,265 |
| Mechanical Sys | tem Subtotal: | | | | \$927,533 |

Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------|--|----------|------|------|----------|
| Hot Water | | | | | |
| | Gas Heater - 300001 - 600000 BTU/HR | 1 | EA | 6 | \$310 |
| | Hot Water Storage Tank_Gas - 201 - 500 Gallons | 1 | EA | 6 | \$678 |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 63,816 | SF | 6 | \$12,776 |
| | Domestic Piping-Cold Water Horizontal Lines | 63,816 | SF | 6 | \$15,514 |
| | Domestic Piping-Cold Water Risers | 63,816 | SF | 6 | \$11,863 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 63,816 | SF | 6 | \$10,038 |
| | Domestic Piping-Hot Water Horizontal Lines | 63,816 | SF | 6 | \$11,863 |
| | Domestic Piping-Hot Water Return Lines | 63,816 | SF | 6 | \$9,126 |
| | Domestic Piping-Hot Water Return Risers | 63,816 | SF | 6 | \$9,126 |
| | Sanitary Piping | 63,816 | SF | 6 | \$58,404 |
| | Storm Piping | 63,816 | SF | 6 | \$55,667 |
| | Vent Piping | 63,816 | SF | 6 | \$42,891 |
| Pumps | | | | | |
| | Pumps - Domestic Booster Pump-Simplex | 1 | EA | 6 | \$1,446 |
| | Pumps - Sump-Simplex | 1 | EA | 6 | \$745 |



Building: Main

| Category: P | lumbing System | | | | |
|-------------|-----------------|----------|------|------|-----------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Pumps | | | | | |
| Plumbing S | ystem Subtotal: | | | | \$240,447 |

Plumbing System Subtotal:

Building: Main

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|-----------------------------|----------|------|------|---------|
| Art Room (1 room) | | | | | |
| | AC Units | 1 | EA | 5 | \$1,826 |
| | Ceiling - Plaster/Drywall | 542 | SF | 6 | \$1,876 |
| | Doors - Hardware | 1 | EA | 7 | \$C |
| | Floor - Tile | 542 | SF | 7 | \$C |
| | Lighting - Pendent/Surface | 11 | EA | 4 | \$5,947 |
| | Marker Board | 8 | LF | 7 | \$C |
| | Walls - Concrete Block | 319 | SF | 6 | \$935 |
| | Walls - Plaster/Drywall | 603 | SF | 6 | \$1,664 |
| Choral Room (1 roo | m) | | | | |
| | AC Units | 1 | EA | 5 | \$1,826 |
| | Ceiling - Plaster/Drywall | 477 | SF | 7 | \$C |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$C |
| | Floor - Tile | 477 | SF | 7 | \$C |
| | Lighting - Pendent/Surface | 11 | EA | 4 | \$5,947 |
| | Marker Board | 6 | LF | 7 | \$C |
| | Walls - Plaster/Drywall | 812 | SF | 6 | \$2,241 |
| Computer Lab (1 roo | om) | | | | |
| | AC Units | 1 | EA | 5 | \$1,826 |
| | Casework | 36 | LF | 6 | \$909 |
| | Ceiling - Plaster/Drywall | 744 | SF | 6 | \$2,575 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile | 744 | SF | 6 | \$1,628 |
| | Lighting - Pendent/Surface | 16 | EA | 4 | \$8,650 |
| | Marker Board | 16 | LF | 6 | \$343 |
| | Storage/ Closet | 36 | SF | 6 | \$261 |
| | Walls - Concrete Block | 819 | SF | 6 | \$2,401 |
| Dance Room (1 roor | n) | | | | |
| | AC Units | 1 | EA | 5 | \$1,826 |



Building: Main

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|--|----------|------|------|---------|
| Dance Room (1 r | oom) | | | | |
| | Casework | 30 | LF | 6 | \$758 |
| | Ceiling - Plaster/Drywall | 16 | SF | 6 | \$55 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Concrete Epoxy/ Painted | 744 | SF | 6 | \$394 |
| | Lighting - Pendent/Surface | 16 | EA | 4 | \$8,650 |
| | Marker Board | 12 | LF | 6 | \$257 |
| | Storage/ Closet | 36 | SF | 6 | \$261 |
| | Walls - Concrete Block | 819 | SF | 6 | \$2,401 |
| Fitness Room (1 | room) | | | | |
| | AC Units | 1 | EA | 5 | \$1,826 |
| | Ceiling - Plaster/Drywall | 832 | SF | 6 | \$2,879 |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$0 |
| | Floor - Weight/ Fitness Room Floor Matting | 832 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | 16 | EA | 4 | \$8,650 |
| | Marker Board | 12 | LF | 7 | \$0 |
| | Wall Mirrors | 160 | SF | 7 | \$0 |
| | Walls - Concrete Block | 776 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 221 | SF | 7 | \$0 |
| Office (2 rooms) | | | | | |
| | AC Units | 1 | EA | 5 | \$1,826 |
| | AC Units | 1 | EA | 6 | \$496 |
| | Ceiling - Plaster/Drywall | 927 | SF | 6 | \$3,208 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile | 927 | SF | 6 | \$2,028 |
| | Lighting - Pendent/Surface | 10 | EA | 4 | \$5,406 |
| | Lighting - Pendent/Surface | 8 | EA | 7 | \$0 |
| | Marker Board | 32 | LF | 6 | \$685 |
| | Storage/ Closet | 32 | SF | 6 | \$232 |
| | Walls - Concrete Block | 641 | SF | 6 | \$1,879 |
| | Walls - Concrete Block | 224 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 522 | SF | 7 | \$0 |
| Other Instruction | al Use (2 rooms) | | | | |
| | AC Units | 4 | EA | 5 | \$7,303 |
| | Casework | 40 | LF | 6 | \$1,010 |
| | Ceiling - Plaster/Drywall | 1,747 | SF | 6 | \$6,046 |
| | Doors - Transom Window | 1 | SF | 6 | \$17 |

6350 S Stewart Ave Chicago, IL 60621

Building: Main

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------|----------|------|------|-----------|
| Other Instruction | al Use (2 rooms) | | | | |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile | 1,747 | SF | 6 | \$3,822 |
| | Lighting - Pendent/Surface | 16 | EA | 4 | \$8,650 |
| | Lighting - Pendent/Surface | 20 | EA | 7 | \$0 |
| | Marker Board | 62 | LF | 6 | \$1,328 |
| | Storage/ Closet | 136 | SF | 6 | \$986 |
| | Walls - Concrete Block | 1,829 | SF | 6 | \$5,362 |
| Regular Classroo | om (23 rooms) | | | | |
| | AC Units | 32 | EA | 5 | \$58,426 |
| | AC Units | 2 | EA | 6 | \$991 |
| | Casework | 596 | LF | 6 | \$15,051 |
| | Casework | 40 | LF | 7 | \$0 |
| | Ceiling - Lay-in | 744 | SF | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 12,947 | SF | 6 | \$44,804 |
| | Ceiling - Plaster/Drywall | 3,716 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 16 | EA | 6 | \$4,816 |
| | Doors - Wood Doors inclu hw | 8 | EA | 7 | \$0 |
| | Floor - Tile | 154 | SF | 5 | \$768 |
| | Floor - Tile | 11,754 | SF | 6 | \$25,717 |
| | Floor - Tile | 4,828 | SF | 7 | \$0 |
| | Floor - Tile/Sheet | 812 | SF | 6 | \$813 |
| | Lighting - Lay-in | 16 | EA | 4 | \$5,374 |
| | Lighting - Pendent/Surface | 235 | EA | 4 | \$127,050 |
| | Lighting - Pendent/Surface | 64 | EA | 6 | \$7,929 |
| | Lighting - Pendent/Surface | 48 | EA | 7 | \$0 |
| | Marker Board | 36 | LF | 5 | \$1,824 |
| | Marker Board | 524 | LF | 6 | \$11,225 |
| | Marker Board | 168 | LF | 7 | \$0 |
| | Storage/ Closet | 504 | SF | 6 | \$3,654 |
| | Walls - Concrete Block | 13,231 | SF | 6 | \$38,787 |
| | Walls - Concrete Block | 4,726 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 1,530 | SF | 7 | \$0 |
| Science (2 rooms | s) | | | | |
| • | AC Units | 5 | EA | 5 | \$9,129 |
| | Casework | 124 | LF | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 2,212 | SF | 7 | \$0 |
| | | | | | |



Building: Main

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|-----------------------------|----------|------|------|----------|
| Science (2 rooms) | | | | | |
| | Doors - Wood Doors inclu hw | 4 | EA | 7 | \$0 |
| | Eye Wash Station | 1 | EA | 7 | \$0 |
| | Floor - Tile | 1,106 | SF | 7 | \$0 |
| | Floor - Tile/Sheet | 1,106 | SF | 7 | \$0 |
| | Lighting - Pendent/Surface | 44 | EA | 4 | \$23,788 |
| | Marker Board | 32 | LF | 7 | \$0 |
| | Storage/ Closet | 115 | SF | 7 | \$0 |
| | Walls - Concrete Block | 2,012 | SF | 7 | \$0 |
| | Work Sink | 9 | EA | 7 | \$0 |
| Science Classroom | n (1 room) | | | | |
| | AC Units | 2 | EA | 5 | \$3,652 |
| | Casework | 36 | LF | 6 | \$909 |
| | Ceiling - Plaster/Drywall | 812 | SF | 6 | \$2,810 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile | 812 | SF | 6 | \$1,777 |
| | Lighting - Pendent/Surface | 16 | EA | 6 | \$1,982 |
| | Marker Board | 36 | LF | 6 | \$771 |
| | Storage/ Closet | 36 | SF | 6 | \$261 |
| | Walls - Concrete Block | 813 | SF | 6 | \$2,383 |
| Science Lab Level | 1 (1 room) | | | | |
| | Casework | 24 | LF | 6 | \$606 |
| | Ceiling - Lay-in | 1,030 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile | 1,030 | SF | 6 | \$2,254 |
| | Fume Hood | 1 | EA | 6 | \$816 |
| | Gas Line | 8 | EA | 6 | \$4,073 |
| | Lighting - Lay-in | 24 | EA | 7 | \$0 |
| | Marker Board | 12 | LF | 6 | \$257 |
| | Science Lab Elements | 1,030 | SF | 7 | \$0 |
| | Science Lab Shower | 1 | EA | 6 | \$379 |
| | Storage/ Closet | 70 | SF | 6 | \$508 |
| | Walls - Concrete Block | 958 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 230 | SF | 7 | \$0 |
| | Work Sink | 8 | EA | 6 | \$3,032 |
| Science Lab Level | 3 (2 rooms) | | | | |
| | AC Units | 1 | EA | 5 | \$1,826 |



Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------------|-----------------------------|----------|------|------|---------|
| Science Lab Level 3 (2 roo | oms) | | | | |
| | Casework | 36 | LF | 6 | \$909 |
| | Ceiling - Plaster/Drywall | 812 | SF | 6 | \$2,810 |
| | Ceiling - Plaster/Drywall | 1,085 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile | 1,897 | SF | 6 | \$4,150 |
| | Gas Line | 8 | EA | 6 | \$4,073 |
| | Lighting - Lay-in | 24 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 16 | EA | 4 | \$8,650 |
| | Marker Board | 44 | LF | 6 | \$943 |
| | Science Lab Elements | 812 | SF | 6 | \$5,504 |
| | Science Lab Elements | 1,085 | SF | 7 | \$0 |
| | Science Lab Shower | 1 | EA | 6 | \$379 |
| | Storage/ Closet | 84 | SF | 6 | \$609 |
| | Walls - Concrete Block | 861 | SF | 6 | \$2,524 |
| | Walls - Concrete Block | 958 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 230 | SF | 7 | \$0 |
| | Work Sink | 8 | EA | 6 | \$3,032 |

Classrooms Subtotal:

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|-----------------------------|----------|------|------|---------|
| Administrative S | Suites/Offices | | | | |
| | AC Unit | 5 | EA | 5 | \$9,129 |
| | AC Unit | 1 | EA | 6 | \$496 |
| | Ceiling | 94 | | 6 | \$0 |
| | Ceiling - Lay-in | 471 | SF | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 949 | SF | 6 | \$3,284 |
| | Ceiling - Plaster/Drywall | 666 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 5 | EA | 6 | \$1,505 |
| | Doors - Wood Doors inclu hw | 8 | EA | 7 | \$0 |
| | Floor - Carpet | 188 | SF | 6 | \$401 |
| | Floor - Carpet | 1,061 | SF | 7 | \$0 |
| | Floor - Tile/Sheet | 931 | SF | 6 | \$932 |
| | Lighting - Lay-in | 6 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 3 | EA | 4 | \$1,622 |

\$563,830



Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|--------------------------------|----------|------|------|----------|
| Administrative Su | lites/Offices | | | | |
| | Lighting - Pendent/Surface | 25 | EA | 7 | \$0 |
| | Power Distribution | 36 | EA | 6 | \$76,496 |
| | Power Distribution | 6 | EA | 7 | \$0 |
| | Storage/ Closet | 15 | SF | 6 | \$109 |
| | Storage/ Closet | 190 | SF | 7 | \$0 |
| | Walls - Concrete Block | 1,533 | SF | 6 | \$4,494 |
| | Walls - Concrete Block | 2,628 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 128 | SF | 6 | \$353 |
| | Walls - Plaster/Drywall | 740 | SF | 7 | \$0 |
| | Work SInk | 1 | EA | 6 | \$508 |
| Gymnasia | | | | | |
| | Bleacher Seating | 80 | EA | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 3,603 | SF | 7 | \$0 |
| | Doors - Steel Doors incl hw | 4 | EA | 7 | \$0 |
| | Floor - Tile | 3,603 | SF | 7 | \$0 |
| | Lighting - Wall Mounted | 36 | EA | 7 | \$0 |
| | Scoreboards | 1 | EA | 7 | \$0 |
| | Sound System | 1 | EA | 7 | \$0 |
| | Stage | 715 | SF | 7 | \$0 |
| | Stage Curtain | 2 | EA | 7 | \$0 |
| | Stage Lift | 1 | EA | 7 | \$0 |
| | Stage Lighting System | 1 | EA | 7 | \$0 |
| | Stage-Stairs - Terrazzo | 12 | LF | 6 | \$92 |
| | Stage-Stairs - Wood | 7 | LF | 7 | \$0 |
| | Storage/ Closet | 45 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 2,323 | SF | 6 | \$6,411 |
| | Walls - Structural Glazed Tile | 2,323 | SF | 6 | \$7,308 |
| Kitchen | | | | | |
| | AC Unit | 1 | EA | 5 | \$1,826 |
| | Ceiling - Plaster/Drywall | 1,003 | SF | 6 | \$3,471 |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$0 |
| | Floor - Tile/Sheet | 1,003 | SF | 6 | \$1,004 |
| | Lighting - Pendent/Surface | 16 | EA | 7 | \$0 |
| | Serving Line | 46 | LF | 7 | \$0 |
| | Storage/ Closet | 60 | SF | 6 | \$435 |
| | Walls - Structural Glazed Tile | 1,008 | SF | 7 | \$0 |



Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------|---------------------------------|----------|------|------|----------|
| Locker/Shower R | loom | | | | |
| | Accessories | 809 | SF | 7 | \$0 |
| | Benches, ped mounted | 9 | LF | 7 | \$0 |
| | Ceiling - Plaster/ Drywall | 347 | SF | 6 | \$1,201 |
| | Ceiling - Plaster/ Drywall | 462 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 3 | EA | 7 | \$0 |
| | Floor - Tile Ceramic/ Porcelain | 809 | SF | 7 | \$0 |
| | Floor Drain | 9 | EA | 6 | \$9,532 |
| | Floor Drain | 8 | EA | 7 | \$0 |
| | Hand Dryer | 1 | EA | 6 | \$230 |
| | Hand Dryer | 2 | EA | 7 | \$0 |
| | Lavatory | 3 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 22 | EA | 7 | \$0 |
| | Partitions | 12 | EA | 7 | \$0 |
| | Showers | 13 | EA | 7 | \$0 |
| | Student Lockers - One Tier | 4 | EA | 7 | \$0 |
| | Student Lockers - Three Tiers | 74 | EA | 7 | \$0 |
| | Student Lockers - Two Tier | 72 | EA | 7 | \$0 |
| | Walls - Concrete Block | 154 | SF | 6 | \$451 |
| | Walls - Concrete Block | 154 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 154 | SF | 6 | \$425 |
| | Walls - Plaster/Drywall | 154 | SF | 7 | \$0 |
| | Walls - Structural Glazed Tile | 308 | SF | 6 | \$969 |
| | Walls - Structural Glazed Tile | 190 | SF | 7 | \$0 |
| | Walls - Tile Ceramic/ Porcelain | 218 | SF | 7 | \$0 |
| | Water Closet | 2 | EA | 6 | \$672 |
| | Water Closet | 1 | EA | 7 | \$0 |
| Lunch & Multipu | rpose Room | | | | |
| · · · | AC Unit | 2 | EA | 5 | \$3,652 |
| | Ceiling - Plaster/Drywall | 1,516 | SF | 7 | \$0 |
| | Doors - Hardware | 2 | EA | 7 | \$0 |
| | Floor - Tile/Sheet | 1,516 | SF | 6 | \$1,518 |
| | Lighting - Lay-in | 2 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 32 | EA | 7 | \$0 |
| | Serving Line | 18 | LF | 7 | \$0 |
| | Walls - Concrete Block | 3,547 | SF | 6 | \$10,398 |
| | | | | | |



Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|---------------------------------|----------|------|------|----------|
| MDF_IDF | | | | | |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Finishes | 469 | SF | 7 | \$0 |
| Mechanical/ Servic | ce Rooms | | | | |
| | Crawl Space - Unfinished | 27,780 | SF | 7 | \$0 |
| | Janitor's Closet | 96 | SF | 6 | \$688 |
| | Mechanical/ Service Rooms | 27 | SF | 6 | \$193 |
| | Storage Room | 243 | SF | 6 | \$1,741 |
| Prep Room | | | | | |
| • | Casework | 5 | LF | 6 | \$126 |
| | Ceiling - Lay-in | 191 | SF | 7 | \$0 |
| | Doors | 1 | | 6 | \$0 |
| | Floor - Tile/Sheet | 191 | SF | 6 | \$191 |
| | Lighting - Lay-in | 4 | EA | 7 | \$0 |
| | Walls - Plaster/Drywall | 521 | SF | 7 | \$0 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Restroom | | | | | |
| | Accessories | 1,401 | SF | 6 | \$12,922 |
| | Accessories | 652 | SF | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 1,711 | SF | 6 | \$5,921 |
| | Ceiling - Plaster/Drywall | 331 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 5 | EA | 6 | \$1,505 |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$0 |
| | Floor - Tile Ceramic/ Porcelain | 1,582 | SF | 6 | \$3,348 |
| | Floor - Tile Ceramic/ Porcelain | 288 | SF | 7 | \$0 |
| | Floor - Tile/Sheet | 183 | SF | 6 | \$183 |
| | Floor Drain | 6 | EA | 6 | \$6,355 |
| | Floor Drain | 1 | EA | 7 | \$0 |
| | Hand Dryer | 8 | EA | 6 | \$1,840 |
| | Hand Dryer | 4 | EA | 7 | \$0 |
| | Lavatory | 18 | EA | 6 | \$5,753 |
| | Lavatory | 6 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 1 | EA | 6 | \$124 |
| | Lighting - Pendent/Surface | 25 | EA | 7 | \$0 |
| | Lighting - Wall Mounted | 1 | EA | 6 | \$124 |
| | Lighting - Wall Mounted | 1 | EA | 7 | \$0 |
| | Partitions | 12 | EA | 6 | \$3,563 |



Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------|--------------------------------|----------|------|------|-----------|
| Restroom | | | | | |
| | Partitions | 11 | EA | 7 | \$0 |
| | Urinals | 8 | EA | 6 | \$2,688 |
| | Urinals | 4 | EA | 7 | \$0 |
| | Walls - Concrete Block | 354 | SF | 6 | \$1,038 |
| | Walls - Concrete Block | 211 | SF | 7 | \$0 |
| | Walls - Structural Glazed Tile | 3,364 | SF | 6 | \$10,583 |
| | Walls - Structural Glazed Tile | 497 | SF | 7 | \$0 |
| | Water Closet | 21 | EA | 6 | \$7,056 |
| | Water Closet | 9 | EA | 7 | \$0 |
| Rooms (Other | r Than Classrooms) Subtotal: | | | | \$215,545 |

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|--------------------------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Plaster/Drywall | 10,515 | SF | 6 | \$65,108 |
| | Doors - Side-lite | 20 | EA | 7 | \$0 |
| | Doors - Steel Doors incl hw | 2 | EA | 7 | \$0 |
| | Doors - Store Front | 5 | EA | 6 | \$6,041 |
| | Drinking Fountains - Single Fountain | 13 | EA | 7 | \$0 |
| | Floor - Tile/Sheet | 4,323 | SF | 6 | \$2,349 |
| | Floor - Tile/Sheet | 6,192 | SF | 7 | \$0 |
| | Lighting - Lay-in | 25 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 94 | EA | 7 | \$0 |
| | Student Lockers - One Tier | 141 | EA | 7 | \$0 |
| | Student Lockers - Two Tiers | 625 | EA | 7 | \$0 |
| | Walls - Concrete Block | 6,649 | SF | 7 | \$0 |
| | Walls - Structural Glazed Tile | 6,649 | SF | 7 | \$0 |
| Safety | | | | | |
| | Camera Viewing Station | 2 | EA | 7 | \$0 |
| | Security Cameras | 58 | EA | 7 | \$0 |
| Stairs | | | | | |
| | Ceiling - Plaster/Drywall | 709 | SF | 7 | \$0 |
| | Floor - Terrazzo | 545 | SF | 7 | \$0 |
| | Handrails | 248 | LF | 7 | \$0 |



\$3,285,225

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------------|---|----------|------|------|----------|
| Stairs | | | | | |
| | Lighting - Pendent/Surface | 7 | EA | 7 | \$0 |
| | Lighting - Wall Mounted | 2 | EA | 7 | \$0 |
| | Stairs - Terrazzo | 96 | LF | 6 | \$891 |
| | Walls - Structural Glazed Tile | 3,880 | SF | 7 | \$0 |
| Vertical Conveyance | | | | | |
| | Elevator - Elevator- Roped Holeless Hydraulic | 1 | EA | 7 | \$0 |
| Building Interior Subtotal: | | | | | \$74,389 |

Total Building Cost

SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|---|----------|------|------|----------|
| Athletic | | | | | |
| | Surface - Synthetic including exc & retention | 25,851 | SF | 7 | \$0 |
| Civil/Drainage | | | | | |
| | Civil/ Drainage - Catch Basin | 3 | EA | 7 | \$0 |
| | Civil/ Drainage - Site Manhole | 1 | EA | 7 | \$0 |
| Fencing | | | | | |
| | Fencing - Chain Link | 1,055 | LF | 6 | \$19,809 |
| | Fencing - New Standard Ornamental | 10 | LF | 5 | \$1,424 |
| | Fencing - New Standard Ornamental | 369 | LF | 7 | \$0 |
| Landscape | | | | | |
| | Landscape - Grass | 10,928 | SF | 6 | \$9,064 |
| | Landscape - Hardscape- Concrete | 1,029 | SF | 7 | \$0 |
| | Parkway trees | 21 | EA | 7 | \$0 |
| | Planting Beds/ Area | 1,565 | SF | 6 | \$2,574 |
| | Play Area - Asphalt/ Hardscape | 6,554 | SF | 6 | \$15,839 |
| | Trash Receptacles | 2 | EA | 7 | \$0 |
| Parking Lot | | | | | |
| | Surface - Asphalt | 400 | SF | 4 | \$4,239 |
| | Surface - Asphalt | 9,600 | SF | 5 | \$43,792 |
| | Trash Enclosure - Chain Links | 934 | SF | 7 | \$0 |



SITE

| Category: Site | | | | | |
|-----------------|--------------------------------------|----------|------|------|-----------|
| Group | Item - Type | Quantity | Unit | Rank | Cost |
| Parking Lot | | | | | |
| Sidewalks | | | | | |
| | Sidewalks - Internal Walks | 40 | LF | 6 | \$480 |
| | Sidewalks - Perimeter Sidewalks | 30 | SF | 5 | \$287 |
| | Sidewalks - Perimeter Sidewalks | 6,163 | SF | 6 | \$12,250 |
| Signage | | | | | |
| | Flag Pole - Flag Pole | 1 | EA | 6 | \$1,657 |
| | Marquee - Free Standing Back Lighted | 1 | EA | 7 | \$0 |
| Site Subtotal: | | | | | \$111,414 |
| Total Site Cost | | | | | \$111,414 |

Campus Total ^{2 3}

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

\$3,396,639



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------------|-------------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | - | - | | | | | II | | | | | | |
| Art Room | | 1st Floor | 113 | 113 | 542 | 1 | 2 | 12 | 144 | 72 | 40 | Ν | Ν | Y |
| Choral Room | Lunch Room | 1st Floor | 111 | 111 | 477 | 1 | 2 | 6 | 90 | 45 | 40 | N | Ν | Y |
| Computer Lab | Computer Lab | 2nd Floor | 212 | 212 | 744 | 1 | 4 | 14 | 136 | 56 | 40 | Ν | Y | Y |
| Dance Room | Regular Classroom | 2nd Floor | 200 | 200 | 744 | 1 | 4 | 16 | 136 | 56 | 40 | Ν | Ν | Ν |
| Fitness Room | Regular Classroom | 1st Floor | 102 | 102 | 832 | 1 | 2 | 6 | 160 | 80 | 40 | Ν | Y | Y |
| Office | Regular Classroom | 2nd Floor | 207 | 207 | 540 | 1 | 5 | 12 | 136 | 56 | 40 | Ν | Y | Y |
| Office | Regular Classroom | 3rd Floor | 314 | 314 | 387 | 1 | 4 | 8 | 68 | 28 | 40 | Ν | Y | Ν |
| Other Instructional Use | Regular Classroom | 2nd Floor | 213 | 213 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | N | Y | Y |
| Other Instructional Use | Regular Classroom | 3rd Floor | 300 | 300 | 935 | 1 | 6 | 16 | 187 | 77 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 101 | 101 | 812 | 1 | 5 | 12 | 144 | 80 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 103 | 103 | 812 | 1 | 5 | 12 | 144 | 80 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 105 | 105 | 812 | 1 | 5 | 12 | 144 | 80 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 106 | 106 | 725 | 1 | 6 | 12 | 160 | 80 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 108 | 108 | 387 | 1 | 4 | 8 | 80 | 40 | 50 | Ν | Y | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 110 | 760 | 2 | 2 | 8 | 144 | 72 | 50 | Ν | Y | Y |
| Regular Classroom | | 1st Floor | 112 | 112 | 520 | 1 | 2 | 6 | 90 | 45 | 40 | Ν | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 744 | 1 | 4 | 16 | 136 | 56 | 40 | N | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 744 | 1 | 4 | 16 | 136 | 56 | 40 | N | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 744 | 1 | 4 | 16 | 136 | 56 | 40 | N | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 744 | 1 | 4 | 16 | 136 | 56 | 40 | N | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 210 | 744 | 1 | 4 | 16 | 136 | 56 | 40 | N | Ν | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 211 | 211 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 303 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 304 | 304 | 738 | 1 | 4 | 12 | 136 | 56 | 50 | N | Ν | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 305 | 305 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 307 | 307 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 309 | 309 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | Ν | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 311 | 311 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | N | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 313 | 313 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | N | Y | Y |
| Science | Kindergarten | 1st Floor | 107 | 107 | 1,106 | 1 | 5 | 20 | 216 | 120 | 40 | N | Y | Y |
| Science | Kindergarten | 1st Floor | 109 | 109 | 1,106 | 1 | 5 | 20 | 216 | 120 | 40 | Ν | Y | Y |
| Science Classroom | Other Instructional Use | 3rd Floor | 301 | 301 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | N | Y | Y |
| Science Lab Level 1 | Science Lab Level 1 | 3rd Floor | 310 | 310 | 1,030 | 1 | 10 | 34 | 187 | 77 | 40 | N | N | Y |
| Science Lab Level 3 | Science Lab Level 3 | 2nd Floor | 201 | 201 | 812 | 1 | 5 | 12 | 136 | 56 | 40 | N | Y | Y |



Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|---------------------|---------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | | | | | | | | | | | | | |
| Science Lab Level 3 | Science Lab Level 2 | 3rd Floor | 312 | 312 | 1,085 | 1 | 10 | 36 | 187 | 77 | 40 | N | N | Y |