

Facility Assessment Report

This report contains a summary of the results from the facility assessment completed on the date noted in the document footer below. This report will roll-up each assessed item with identical rank and total the quantity into a single line, regardless of item location (for location data, see the detailed report). Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1978 | 3 | 60,718 | \$1,948,182 |
| SITE | | | | \$138,322 |
| Campus Total | | | 60,718 | \$2,086,504 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------|---|-------------|------|------|--------------------------|
| Entrance | | | | | |
| | Entrance Control - Audio and Video | 2 | EA | 7 | \$0 |
| | Exterior Doors - Exterior Steel Door | 5 | EA | 6 | \$2,403 |
| | Exterior Doors - Side lite | 1 | EA | 6 | \$313 |
| | Exterior Doors - Store Front | 6 | EA | 6 | \$3,276 |
| | Exterior Doors - Store Front | 4 | EA | 7 | \$ 0 |
| | Exterior Doors - Transom Lite | 4 | EA | 6 | \$1,253 |
| | Exterior Stairs - Concrete | 105 | LF | 6 | \$8,586 |
| | Power Door Operator and Controls | 2 | EA | 7 | \$0 |
| | Ramp Handrail - Steel_Ramp Handrail | 135 | LF | 7 | \$O |
| | Ramps - Concrete | 5 | LF | 4 | \$6,952 |
| | Ramps - Concrete | 60 | LF | 6 | \$9,014 |
| | Stair Handrail - Wood_Stair Handrail | 18 | LF | 7 | \$0 |
| Foundation | | | | | |
| | Foundation - Concrete | 910 | LF | 7 | \$0 |
| | Superstructure - Steel | 59,150 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | 3 | EA | 7 | \$0 |
| | Exterior Lighting - Wall Mounted | 1 | EA | 5 | \$427 |
| | Exterior Lighting - Wall Mounted | 37 | EA | 6 | \$10,684 |
| CREELEV | | ogo 1 of 14 | | | Accomment Date: 4/9/2014 |



832 W Sheridan Rd Chicago, IL 60613

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|---|----------|------|------|-----------|
| Lighting | | | | | |
| Roof System | | | | | |
| | Coping - Stone | 1,205 | LF | 6 | \$38,702 |
| | Downspouts - Interior Downspouts | 417 | LF | 6 | \$13,858 |
| | Parapet - 16" - 30" Height | 55 | LF | 6 | \$2,632 |
| | Parapet - 16" - 30" Height | 1,060 | LF | 7 | \$0 |
| | Parapet - Parapet > 30" | 90 | LF | 7 | \$0 |
| | Roof - Modified Bitumen | 6,500 | SF | 5 | \$136,729 |
| | Roof - Modified Bitumen | 22,089 | SF | 6 | \$207,844 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 28,589 | SF | 7 | \$0 |
| Walls | | | | | |
| | Exterior Walls - Brick | 50 | SF | 6 | \$454 |
| | Exterior Walls - Brick | 33,500 | SF | 7 | \$0 |
| Windows | | | | | |
| | Guard - Guards perforated | 850 | SF | 6 | \$10,854 |
| | Lintels - Steel | 395 | LF | 6 | \$11,466 |
| | Storefront Windows | 190 | SF | 6 | \$2,130 |
| | Windows - Casement Aluminum Double-pane | 330 | SF | 7 | \$0 |
| | Windows - Louver | 144 | SF | 5 | \$12,330 |
| | Windows - Sash Aluminum Double-pane | 1,790 | SF | 7 | \$0 |
| Duilding Fyter | Sea Outros del | | | | ¢470.040 |

Building Exterior Subtotal:

\$479,910

Building: Main

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|---|----------|------|------|----------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 1 | EA | 4 | \$8,200 |
| | Automatic Transfer Switch | 2 | EA | 6 | \$816 |
| | Emergency A/C Power - Auditoium and Aisle Lighting | 2,500 | SF | 6 | \$1,323 |
| | Emergency A/C Power - Corridors and Stairs | 8,788 | SF | 6 | \$2,639 |
| | Emergency A/C Power - Gym | 4,000 | SF | 6 | \$1,487 |
| | Emergency A/C Power - Lunchrooms | 1,814 | SF | 6 | \$674 |
| | Emergency A/C Power - Students Toilets | 369 | SF | 6 | \$137 |
| | Emergency Battery Packs - Corridors and Stairs | 6 | EA | 6 | \$1,215 |
| | Emergency Generator- Outdoor- Diesel - 151 - 200 KW | 1 | EA | 6 | \$12,534 |



832 W Sheridan Rd Chicago, IL 60613

Building: Main

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|---|----------|------|------|----------|
| Emergency System | | | | | |
| | Exit Signs - Auditoium | 1 | EA | 7 | \$0 |
| | Exit Signs - Corridors and Stairs | 12 | EA | 7 | \$0 |
| | Exit Signs - Gym | 2 | EA | 7 | \$0 |
| | Exit Signs - Lunchroom | 2 | EA | 7 | \$0 |
| | Security System - Intrusion Detection | 59,150 | SF | 6 | \$15,225 |
| Main Service | | | | | |
| | Main Electrical Service - 1000 A 277/480/3PH | 1 | EA | 6 | \$4,755 |
| | Main Electrical Service - 2000 A 277/480/3PH | 1 | EA | 6 | \$8,662 |
| | PA System | 59,150 | SF | 6 | \$19,454 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - Above 100 A | 17 | EA | 6 | \$8,449 |
| | Main Distribution Panels - 400 - 600 amp | 1 | EA | 7 | \$0 |
| | Main Distribution Panels - Greater than 600 amp | 2 | EA | 7 | \$0 |
| | Main Distribution Panels - Less than 400 amp | 1 | EA | 7 | \$0 |
| | Transformers - 277/480 - 120/208 | 1 | EA | 4 | \$18,709 |
| | Transformers - 277/480 - 120/208 | 2 | EA | 6 | \$2,530 |

Electrical System Subtotal:

\$106,811

Building: Main

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------|--------------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 6 | \$6,406 |
| | Fire Alarm Strobe Lights | 59,150 | SF | 6 | \$21,146 |
| | Fire Alarm_System | 59,150 | SF | 6 | \$28,759 |

Safty System Subtotal:

\$56,311

Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|-----------------------------|----------|------|------|-----------|
| Air Conditioning | | | | | |
| | Cooling Tower - Closed Cell | 1 | EA | 4 | \$176,132 |



832 W Sheridan Rd Chicago, IL 60613

Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|---|----------|------|------|-----------|
| Air Handling Systems | | | | | |
| | Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained Compressor - 5 - 10 tons | 6 | EA | 6 | \$12,307 |
| | Roof Top Unit-Single Zone-Roof Mounted- Electric and DX Cooling with Self Contained Compressor - Less than 5 tons | 1 | EA | 6 | \$1,903 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Electric- Hot Water Boiler - 1001 - 2000 MBH | 1 | EA | 5 | \$20,007 |
| | Chemical Pot Feeder | 1 | EA | 6 | \$725 |
| | Electric- Hot Water Boiler - 1001 - 2000 MBH | 1 | EA | 5 | \$46,699 |
| Heating Devices | | | | | |
| | Cabinet Heaters - With Electric Coil | 4 | EA | 6 | \$1,426 |
| | PTAC - Electric Heating and Self Contained Cooling | 2 | EA | 6 | \$482 |
| | Unit Heater - Electric | 3 | EA | 6 | \$833 |
| | Wall Heater - Electric | 1 | EA | 4 | \$1,083 |
| | Wall Heater - Electric | 5 | EA | 6 | \$695 |
| Mechanical Plumbing | | | | | |
| | Hot Water Pump - 10 - 20 HP | 2 | EA | 4 | \$106,585 |
| Temperature Control | | | | | |
| | Electric Controls | 59,150 | SF | 6 | \$0 |
| | Electric Thermostat | 55 | EA | 6 | \$0 |
| Unit Ventilation | | | | | |
| | Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only | 45 | EA | 6 | \$56,147 |
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | 1 | EA | 6 | \$592 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 11 | EA | 6 | \$6,516 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 5 | EA | 6 | \$1,481 |
| | Type I Exhaust Hood- Kitchen | 1 | EA | 6 | \$1,248 |
| | | | | | |

Mechanical System Subtotal:

\$434,862

Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------|------------------------------|----------|------|------|-------|
| Hot Water | | | | | |
| | Electric Heater - 20 - 50 KW | 1 | EA | 6 | \$682 |



832 W Sheridan Rd Chicago, IL 60613

Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------|--|----------|------|------|----------|
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 59,150 | SF | 6 | \$11,842 |
| | Domestic Piping-Cold Water Horizontal Lines | 59,150 | SF | 6 | \$14,379 |
| | Domestic Piping-Cold Water Risers | 59,150 | SF | 6 | \$10,996 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 59,150 | SF | 6 | \$9,304 |
| | Domestic Piping-Hot Water Horizontal Lines | 59,150 | SF | 6 | \$10,996 |
| | Domestic Piping-Hot Water Return Lines | 59,150 | SF | 6 | \$8,458 |
| | Domestic Piping-Hot Water Return Risers | 59,150 | SF | 6 | \$8,458 |
| | Sanitary Piping | 59,150 | SF | 7 | \$0 |
| | Storm Piping | 59,150 | SF | 7 | \$0 |
| | Vent Piping | 59,150 | SF | 7 | \$0 |
| Pumps | | | | | |
| | Pumps - Domestic Booster Pump-Duplex | 1 | EA | 6 | \$1,977 |
| | Pumps - Sump-Simplex | 1 | EA | 2 | \$11,443 |

Plumbing System Subtotal:

\$88,537

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|-----------------------------|----------|------|------|---------|
| Computer Lab (1 roor | n) | | | | |
| | Ceiling - Lay-in | 780 | SF | 6 | \$2,342 |
| | Chalk Board | 18 | LF | 4 | \$1,653 |
| | Charging Station | 2 | EA | 7 | \$0 |
| | Doors - Side-lite | 20 | SF | 6 | \$334 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile | 780 | SF | 6 | \$1,707 |
| | Lighting - Lay-in | 18 | EA | 7 | \$0 |
| | Walls - Concrete Block | 900 | SF | 6 | \$2,638 |
| | Walls - Plaster/Drywall | 266 | SF | 6 | \$734 |
| Kindergarten (2 room | s) | | | | |
| | Casework | 48 | LF | 6 | \$1,212 |
| | Ceiling - Lay-in | 1,401 | SF | 6 | \$4,207 |
| | Chalk Board | 36 | LF | 4 | \$3,305 |
| | Doors - Side-lite | 40 | SF | 6 | \$669 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile | 1,401 | SF | 6 | \$3,065 |



832 W Sheridan Rd Chicago, IL 60613

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|-----------------------------|--------------|------|------|---------------------------|
| Kindergarten (2 ro | oms) | | | | |
| | Lighting - Lay-in | 28 | EA | 7 | \$0 |
| | Walls - Concrete Block | 1,717 | SF | 6 | \$5,033 |
| | Work Sink | 2 | EA | 6 | \$758 |
| Other Instructiona | I Use (4 rooms) | | | | |
| | Casework | 11 | LF | 6 | \$278 |
| | Ceiling - Exposed | 140 | SF | 7 | \$0 |
| | Ceiling - Lay-in | 2,171 | SF | 6 | \$6,520 |
| | Chalk Board | 18 | LF | 4 | \$1,653 |
| | Doors - Side-lite | 40 | SF | 6 | \$669 |
| | Doors - Steel Doors incl hw | 1 | EA | 7 | \$0 |
| | Doors - Transom Window | 7 | SF | 6 | \$119 |
| | Doors - Wood Doors inclu hw | 1 | EA | 4 | \$3,413 |
| | Doors - Wood Doors inclu hw | 9 | EA | 6 | \$2,709 |
| | Floor - Carpet | 1,232 | SF | 5 | \$6,325 |
| | Floor - Carpet | 365 | SF | 6 | \$778 |
| | Floor - Tile | 714 | SF | 6 | \$1,562 |
| | Lighting - Lay-in | 42 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 4 | EA | 7 | \$0 |
| | Marker Board | 6 | LF | 6 | \$129 |
| | Marker Board | 10 | LF | 7 | \$0 |
| | Storage/ Closet | 47 | SF | 6 | \$341 |
| | Walls - Concrete Block | 2,786 | SF | 6 | \$8,167 |
| | Walls - Metal Panel | 340 | SF | 7 | \$0 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Pre School (1 room | n) | | | | |
| | Casework | 60 | LF | 6 | \$1,515 |
| | Ceiling - Lay-in | 2,190 | SF | 6 | \$6,577 |
| | Doors - Side-lite | 20 | SF | 6 | \$334 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile | 2,190 | SF | 6 | \$4,792 |
| | Lighting - Lay-in | 38 | EA | 7 | \$0 |
| | Walls - Concrete Block | 1,800 | SF | 7 | \$0 |
| | Work Sink | 2 | EA | 6 | \$758 |
| Regular Classroon | n (22 rooms) | | | | |
| | Casework | 28 | LF | 4 | \$12,997 |
| | Casework | 26 | LF | 5 | \$5,436 |
| CDEELEV | | Dogo 6 of 14 | | | Assessment Date: 4/9/2017 |



Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cos |
|--------------------|-----------------------------|----------|------|------|----------|
| Regular Classroom | (22 rooms) | | | | |
| | Casework | 398 | LF | 6 | \$10,05 |
| | Ceiling - Lay-in | 16,550 | SF | 6 | \$49,700 |
| | Ceiling - Lay-in | 875 | SF | 7 | \$0 |
| | Chalk Board | 360 | LF | 4 | \$33,050 |
| | Doors - Side-lite | 420 | SF | 6 | \$7,02 |
| | Doors - Wood Doors inclu hw | 1 | EA | 4 | \$3,413 |
| | Doors - Wood Doors inclu hw | 1 | EA | 5 | \$1,174 |
| | Doors - Wood Doors inclu hw | 20 | EA | 6 | \$6,020 |
| | Floor - Carpet | 3,720 | SF | 4 | \$34,205 |
| | Floor - Carpet | 3,056 | SF | 5 | \$15,689 |
| | Floor - Carpet | 670 | SF | 6 | \$1,428 |
| | Floor - Tile | 9,979 | SF | 6 | \$21,833 |
| | Lighting - Lay-in | 374 | EA | 7 | \$0 |
| | Marker Board | 16 | LF | 7 | \$(|
| | Storage/ Closet | 63 | SF | 6 | \$45 |
| | Walls - Concrete Block | 52 | SF | 5 | \$73 |
| | Walls - Concrete Block | 19,925 | SF | 6 | \$58,410 |
| | Walls - Plaster/Drywall | 600 | SF | 6 | \$1,65 |
| | Work Sink | 18 | EA | 6 | \$6,822 |
| cience Lab Level 3 | 3 (1 room) | | | | |
| | Casework | 52 | LF | 5 | \$10,872 |
| | Ceiling - Lay-in | 928 | SF | 6 | \$2,78 |
| | Chalk Board | 18 | LF | 4 | \$1,65 |
| | Doors - Side-lite | 20 | SF | 6 | \$33 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$60 |
| | Floor - Tile | 928 | SF | 6 | \$2,03 |
| | Gas Line | 1 | EA | 7 | \$ |
| | Lighting - Lay-in | 18 | EA | 7 | \$ |
| | Storage/ Closet | 66 | SF | 6 | \$47 |
| | Walls - Concrete Block | 20 | SF | 5 | \$28 |
| | Walls - Concrete Block | 980 | SF | 6 | \$2,87 |
| | Work Sink | 3 | EA | 5 | \$4,52 |
| | Work Sink | 1 | EA | 6 | \$379 |

Classrooms Subtotal: \$372,784

Building: Main



832 W Sheridan Rd Chicago, IL 60613

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|---------------------------------|----------|------|------|---------------------|
| Administrative S | uites/Offices | | | | |
| | AC Unit | 1 | EA | 7 | \$0 |
| | Ceiling - Lay-in | 58 | SF | 5 | \$345 |
| | Ceiling - Lay-in | 286 | SF | 6 | \$859 |
| | Ceiling - Lay-in | 1,465 | SF | 7 | \$0 |
| | Doors - Wood Doors inclu hw | 9 | EA | 6 | \$2,709 |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$0 |
| | Floor - Carpet | 882 | SF | 4 | \$8,110 |
| | Floor - Carpet | 641 | SF | 6 | \$1,366 |
| | Floor - Tile | 234 | SF | 6 | \$512 |
| | Floor - Tile Ceramic/ Porcelain | 52 | SF | 6 | \$110 |
| | Lighting - Lay-in | 7 | EA | 6 | \$833 |
| | Lighting - Lay-in | 34 | EA | 7 | \$0 |
| | Power Distribution | 26 | EA | 6 | \$55,247 |
| | Power Distribution | 28 | EA | 7 | \$0 |
| | Storage/ Closet | 49 | SF | 6 | \$355 |
| | Walls - Concrete Block | 3,460 | SF | 6 | \$10,143 |
| | Walls - Concrete Block | 939 | SF | 7 | \$0 |
| Auditorium & Th | eater | | | | |
| | Ceiling - Lay-in | 2,500 | SF | 5 | \$14,872 |
| | Doors - Transom Window | 28 | SF | 6 | \$474 |
| | Doors - Wood Doors inclu hw | 4 | EA | 6 | \$1,204 |
| | Floor - Carpet | 2,700 | SF | 4 | \$24,826 |
| | Lighting - Lay-in | 44 | EA | 7 | \$0 |
| | Sound System | 1 | EA | 7 | \$0 |
| | Stage | 460 | SF | 5 | \$6,907 |
| | Stage Lift | 1 | EA | 7 | \$0 |
| | Stage-Stairs - Tile | 36 | LF | 5 | \$646 |
| | Stairs - Tile | 112 | LF | 6 | \$1,039 |
| | Storage/ Closet | 250 | SF | 6 | \$1,813 |
| | Walls - Concrete Block | 2,335 | SF | 6 | \$6,845 |
| | Walls - Plaster/Drywall | 240 | SF | 6 | \$1,143 |
| Gymnasia | | | | | |
| | Ceiling - Exposed | 4,000 | SF | 6 | \$5,949 |
| | Doors - Transom Window | 28 | SF | 6 | \$474 |
| | Doors - Wood Doors inclu hw | 6 | EA | 6 | \$1,806 |
| | Floor - Tile | 4,000 | SF | 6 | \$8,752 |
| | Lighting - Pendent/Surface | 24 | EA | 7 | \$0 |
| | Scoreboards | 1 | EA | 7 | \$0 |
| ODEELEV | | D0-(44 | | | A 1 D - 1 4/0/004 A |



832 W Sheridan Rd Chicago, IL 60613

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------|---------------------------------|----------|------|------|----------|
| Gymnasia | | | | | |
| | Sound System | 1 | EA | 7 | \$0 |
| | Storage/ Closet | 60 | SF | 6 | \$435 |
| | Walls - Concrete Block | 500 | SF | 5 | \$7,043 |
| | Walls - Concrete Block | 4,870 | SF | 6 | \$14,276 |
| Kitchen | | | | | |
| | Ceiling - Lay-in | 956 | SF | 6 | \$2,871 |
| | Doors - Wood Doors inclu hw | 5 | EA | 6 | \$1,505 |
| | Floor - Tile Ceramic/ Porcelain | 956 | SF | 6 | \$2,023 |
| | Lighting - Lay-in | 27 | EA | 7 | \$0 |
| | Serving Line | 23 | LF | 7 | \$0 |
| | Storage/ Closet | 205 | SF | 6 | \$1,486 |
| | Walls - Concrete Block | 1,400 | SF | 6 | \$4,104 |
| Library | | | | | |
| | Casework | 135 | LF | 6 | \$3,409 |
| | Ceiling - Lay-in | 2,400 | SF | 6 | \$7,207 |
| | Doors - Side-lite | 20 | SF | 6 | \$334 |
| | Doors - Transom Window | 14 | SF | 6 | \$237 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Carpet | 2,400 | SF | 6 | \$5,114 |
| | Lighting - Lay-in | 47 | EA | 7 | \$0 |
| | Walls - Concrete Block | 2,160 | SF | 6 | \$6,332 |
| Lunch & Multipur | pose Room | | | | |
| | Ceiling - Lay-in | 1,814 | SF | 6 | \$5,447 |
| | Floor - Tile | 1,814 | SF | 6 | \$3,969 |
| | Lighting - Lay-in | 25 | EA | 7 | \$0 |
| | Walls - Concrete Block | 1,528 | SF | 6 | \$4,479 |
| Mechanical/ Servi | ice Rooms | | | | |
| | Janitor's Closet | 9 | SF | 6 | \$64 |
| | Loading Docks | 190 | SF | 6 | \$1,361 |
| | Storage Room | 76 | SF | 6 | \$544 |
| Restroom | | | | | |
| | Accessories | 511 | SF | 6 | \$4,713 |
| | Accessories | 718 | SF | 7 | \$0 |
| | Ceiling - Plaster/Drywall | 641 | SF | 6 | \$2,218 |
| | Ceiling - Plaster/Drywall | 588 | SF | 7 | \$0 |

832 W Sheridan Rd Chicago, IL 60613

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|---------------------------------|----------|------|------|----------|
| Restroom | | | | | |
| | Doors - Wood Doors inclu hw | 6 | EA | 6 | \$1,806 |
| | Doors - Wood Doors inclu hw | 2 | EA | 7 | \$0 |
| | Floor - Tile | 1,056 | SF | 6 | \$2,310 |
| | Floor - Tile Ceramic/ Porcelain | 155 | SF | 6 | \$328 |
| | Floor Drain | 6 | EA | 6 | \$6,355 |
| | Floor Drain | 3 | EA | 7 | \$0 |
| | Hand Dryer | 1 | EA | 6 | \$230 |
| | Hand Dryer | 5 | EA | 7 | \$0 |
| | Lavatory | 14 | EA | 6 | \$4,474 |
| | Lavatory | 4 | EA | 7 | \$0 |
| | Lighting - Lay-in | 12 | EA | 6 | \$1,428 |
| | Lighting - Lay-in | 12 | EA | 7 | \$0 |
| | Lighting - Pendent/Surface | 2 | EA | 4 | \$1,081 |
| | Lighting - Pendent/Surface | 3 | EA | 7 | \$0 |
| | Lighting - Wall Mounted | 1 | EA | 4 | \$393 |
| | Lighting - Wall Mounted | 1 | EA | 6 | \$124 |
| | Lighting - Wall Mounted | 2 | EA | 7 | \$0 |
| | Partitions | 2 | EA | 4 | \$3,973 |
| | Partitions | 20 | EA | 6 | \$5,939 |
| | Showers | 2 | EA | 6 | \$623 |
| | Urinals | 8 | EA | 6 | \$2,688 |
| | Urinals | 5 | EA | 7 | \$0 |
| | Walls - Concrete Block | 2,917 | SF | 6 | \$8,551 |
| | Walls - Concrete Block | 810 | SF | 7 | \$0 |
| | Walls - Plaster/Drywall | 188 | SF | 6 | \$519 |
| | Water Closet | 2 | EA | 4 | \$15,339 |
| | Water Closet | 1 | EA | 5 | \$1,344 |
| | Water Closet | 16 | EA | 6 | \$5,376 |
| | Water Closet | 7 | EA | 7 | \$0 |

Rooms (Other Than Classrooms) Subtotal:

\$299,994

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|------------------|----------|------|------|----------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 7,957 | SF | 6 | \$23,895 |

832 W Sheridan Rd Chicago, IL 60613

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost | |
|-------------------|--------------------------------------|----------|------|------|-----------|--|
| Corridor | | | | | | |
| | Doors - Side-lite | 60 | EA | 6 | \$1,003 | |
| | Doors - Wood Doors include hw | 10 | EA | 6 | \$3,010 | |
| | Drinking Fountains - Double Fountain | 1 | EA | 7 | \$0 | |
| | Drinking Fountains - Single Fountain | 4 | EA | 6 | \$1,103 | |
| | Floor - Tile/Sheet | 7,957 | SF | 6 | \$4,324 | |
| | Lighting - Lay-in | 20 | EA | 6 | \$2,380 | |
| | Lighting - Lay-in | 63 | EA | 7 | \$0 | |
| | Student Lockers - One Tier | 24 | EA | 5 | \$3,364 | |
| | Walls - Concrete Block | 10,586 | SF | 6 | \$31,033 | |
| Safety | | | | | | |
| | Camera Viewing Station | 1 | EA | 4 | \$5,461 | |
| | Security Cameras | 2 | EA | 4 | \$2,651 | |
| Stairs | | | | | | |
| | Ceiling - Plaster/Drywall | 1,153 | SF | 7 | \$0 | |
| | Floor - Tile Ceramic/ Porcelain | 831 | SF | 6 | \$5,573 | |
| | Handrails | 300 | LF | 6 | \$2,600 | |
| | Lighting - Lay-in | 2 | EA | 6 | \$238 | |
| | Lighting - Lay-in | 20 | EA | 7 | \$0 | |
| | Lighting - Wall Mounted | 12 | EA | 7 | \$0 | |
| | Stairs - Tile | 594 | LF | 6 | \$5,513 | |
| | Walls - Concrete Block | 5,740 | SF | 6 | \$16,827 | |
| Vertical Conveyan | ce | | | | | |
| | Elevator - Hydraulic Elevator | 1 | EA | 7 | \$0 | |
| Building Interi | or Subtotal: | | | | \$108,973 | |

Total Building Cost \$1,948,182

SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|--------------------------------|----------|------|------|------|
| Civil/Drainage | | | | | |
| | Civil/ Drainage - Catch Basin | 5 | EA | 7 | \$0 |
| | Civil/ Drainage - Site Manhole | 8 | EA | 7 | \$0 |



832 W Sheridan Rd Chicago, IL 60613

\$138,322

SITE

Category: Site

Total Site Cost

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|--|----------|------|------|-----------|
| Fencing | | | | | |
| | Fencing - Chain Link | 186 | LF | 6 | \$3,492 |
| | Fencing - Guard Rail | 107 | LF | 7 | \$0 |
| | Fencing - New Standard Ornamental | 796 | LF | 6 | \$25,395 |
| Landscape | | | | | |
| | Benches | 2 | EA | 7 | \$0 |
| | Landscape - Grass | 3,630 | SF | 7 | \$0 |
| | Landscape - Hardscape- Concrete | 2,390 | SF | 5 | \$27,849 |
| | Landscape - Hardscape- Concrete | 8,410 | SF | 7 | \$0 |
| | Parkway trees | 2 | EA | 7 | \$0 |
| | Planting Beds/ Area | 450 | SF | 7 | \$0 |
| | Play Area - Asphalt/ Hardscape | 8,730 | SF | 6 | \$21,098 |
| | Trash Receptacles | 3 | EA | 6 | \$937 |
| Parking Lot | | | | | |
| | Concrete Curbs | 390 | LF | 6 | \$5,008 |
| | Surface - Asphalt | 4,300 | SF | 5 | \$19,615 |
| | Surface - Asphalt | 2,600 | SF | 7 | \$0 |
| | Surface - Concrete | 470 | SF | 6 | \$1,136 |
| Playground | | | | | |
| | Equipment - Combo 3-12 | 1 | EA | 6 | \$7,092 |
| | Equipment - Pre K 3-5 | 1 | EA | 7 | \$0 |
| | Surface - Poured Surface | 840 | SF | 7 | \$0 |
| | Surface - Square Rubber Mats | 2,215 | SF | 6 | \$11,941 |
| Sidewalks | | | | | |
| | Sidewalks - Perimeter Sidewalks | 7,425 | SF | 6 | \$14,759 |
| Signage | | | | | |
| | Flag Pole - Building Mounted Flag Pole | 1 | EA | 7 | \$0 |
| | Marquee - Building Mounted Back Lighted w/ LED | 1 | EA | 7 | \$0 |
| | Monument - Building Mounted Cut Letter Sign | 1 | EA | 7 | \$0 |
| Site Subtotal: | | | | | \$138,322 |



832 W Sheridan Rd Chicago, IL 60613

\$2,086,504

Campus Total ^{2 3}

- ¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.
- ² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.
- ³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



Horace Greeley Elementary School 832 W Sheridan Rd Chicago, IL 60613

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------------|-------------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | ., | • | | | | | - | | • | • | | | |
| Computer Lab | Other Instructional Use | 2nd Floor | 221 | 221 | 780 | 1 | 40 | 80 | 60 | 7 | 50 | N | Υ | Υ |
| Kindergarten | Kindergarten | 1st Floor | 144 | 144 | 852 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | N |
| Kindergarten | Kindergarten | 1st Floor | 151 | 151 | 549 | 1 | 1 | 6 | 35 | 7 | 50 | N | Υ | Υ |
| Other Instructional Use | Other Instructional Use | 2nd Floor | 214 | | 400 | 1 | 1 | 12 | 0 | 0 | | N | Υ | N |
| Other Instructional Use | Faculty Lounge | 2nd Floor | 228 | | 1,099 | 1 | 1 | 14 | 60 | 7 | | N | Υ | N |
| Other Instructional Use | Other Instructional Use | 3rd Floor | 314 | 314 | 707 | 1 | 0 | 6 | 35 | 7 | 50 | N | Υ | Υ |
| Other Instructional Use | | 3rd Floor | 330 | | 140 | | | 2 | 0 | 0 | | N | Ν | N |
| Pre School | Pre School | 1st Floor | 140/141 | 140 | 2,190 | 2 | 0 | 12 | 100 | 0 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 145 | 145 | 852 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 146 | 146 | 875 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 147 | 147 | 928 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 1st Floor | 148 | 148 | 875 | 1 | 0 | 11 | 60 | 7 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 215 | 215 | 652 | 1 | 0 | 21 | 25 | 0 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 216 | 216 | 550 | 1 | 0 | 6 | 35 | 7 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 217 | 217 | 780 | 1 | 0 | 8 | 60 | 7 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 218 | 218 | 800 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 219 | 219 | 800 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 220 | 220 | 800 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 221B | 223 | 528 | 1 | 0 | 6 | 35 | 7 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 316 | 316 | 875 | 1 | 0 | 6 | 35 | 7 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 317 | 317 | 852 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 318 | 318 | 577 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 320 | 320 | 962 | 1 | 0 | 8 | 95 | 14 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 321 | 321 | 852 | 1 | 0 | 6 | 60 | 5 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 322 | 322 | 852 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 323 | 323 | 852 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 324 | 324 | 852 | 1 | 0 | 8 | 60 | 7 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 325 | 325 | 556 | 1 | 0 | 14 | 35 | 7 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 326 | 326 | 928 | 1 | 0 | 8 | 60 | 7 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | 3rd Floor | 328 | 328 | 875 | 1 | 0 | 6 | 60 | 7 | 50 | N | Υ | Υ |
| Science Lab Level 3 | Science Lab Level 3 | 2nd Floor | 224 | 224 | 994 | 1 | 0 | 14 | 60 | 7 | 50 | N | Υ | Υ |