

Facility Assessment Report

This report contains a summary of the results from the facility assessment completed on the date noted in the document footer below. This report will roll-up each assessed item with identical rank and total the quantity into a single line, regardless of item location (for location data, see the detailed report). Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

| Campus Summary | | | | |
|----------------------|------------------|------------------|-----------------------|---------------|
| Building Name | Year Constructed | Number of Floors | Building Area (Sq Ft) | Assessed Need |
| Main | 1902 | 3 | 62,100 | \$3,649,822 |
| Gymnasium/auditorium | 1913 | 2 | 7,750 | \$533,876 |
| SITE | | | | \$304,519 |
| Campus Total | | | 69,850 | \$4,488,216 |

Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|--------------------------------------|----------|------|------|----------|
| Entrance | | | | | |
| | Entrance Control - Audio and Video | 1 | EA | 6 | \$702 |
| | Exterior Doors - Exterior Steel Door | 1 | EA | 5 | \$1,341 |
| | Exterior Doors - Exterior Steel Door | 12 | EA | 6 | \$5,767 |
| | Exterior Doors - Side lite | 6 | EA | 6 | \$1,880 |
| | Exterior Doors - Store Front | 4 | EA | 7 | \$0 |
| | Exterior Doors - Transom Lite | 1 | EA | 5 | \$822 |
| | Exterior Doors - Transom Lite | 13 | EA | 6 | \$4,073 |
| | Exterior Stairs - Concrete | 51 | LF | 7 | \$0 |
| Fire Escape | | | | | |
| | Fire Escape | 80 | LF | 5 | \$84,002 |
| Foundation | | | | | |
| | Foundation - Concrete | 948 | LF | 7 | \$0 |
| | Superstructure - Heavy Timber | 62,100 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Wall Mounted | 13 | EA | 6 | \$3,754 |



Building: Main

Category: Building Exterior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|---|----------|------|------|-----------|
| Roof System | | | | | |
| | Chimney | 5 | LF | 4 | \$0 |
| | Chimney | 70 | LF | 6 | \$0 |
| | Coping - Clay Tile | 593 | LF | 6 | \$19,046 |
| | Coping - Stone | 56 | LF | 6 | \$1,799 |
| | Coping - Terra Cotta | 382 | LF | 6 | \$12,269 |
| | Downspouts - Exterior Downspouts | 128 | LF | 6 | \$4,254 |
| | Downspouts - Interior Downspouts | 240 | LF | 6 | \$7,976 |
| | Parapet - 16" - 30" Height | 931 | LF | 6 | \$37,197 |
| | Parapet - Parapet > 30" | 100 | LF | 6 | \$6,392 |
| | Roof - Asphalt Gravel Ballast | 2,500 | SF | 4 | \$70,070 |
| | Roof - Asphalt Gravel Ballast | 5,000 | SF | 5 | \$118,047 |
| | Roof - Asphalt Gravel Ballast | 6,533 | SF | 6 | \$66,423 |
| | Roof - Modified Bitumen | 100 | SF | 4 | \$5,144 |
| | Roof - Modified Bitumen | 2,500 | SF | 5 | \$52,588 |
| | Roof - Modified Bitumen | 2,456 | SF | 6 | \$23,109 |
| | Roof Structure - Concrete | 4,688 | SF | 7 | \$0 |
| | Roof Structure - Heavy Timber | 14,033 | SF | 7 | \$0 |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 368 | SF | 7 | \$0 |
| Walls | | | | | |
| | Cornice - Metal Projecting | 373 | LF | 5 | \$56,118 |
| | Exterior Walls - Brick | 9,245 | SF | 5 | \$195,397 |
| | Exterior Walls - Brick | 12,323 | SF | 6 | \$96,392 |
| | Exterior Walls - Stone-Cast | 1,520 | SF | 6 | \$10,216 |
| | Exterior Walls - Stone-Cut | 400 | SF | 5 | \$5,377 |
| Windows | | | | | |
| | Guard - Guards perforated | 1,303 | SF | 5 | \$19,974 |
| | Guard - Guards perforated | 250 | SF | 6 | \$3,192 |
| | Lintels - Steel | 290 | LF | 6 | \$8,418 |
| | Lintels - Stone | 325 | LF | 6 | \$0 |
| | Windows - Louver | 24 | SF | 5 | \$2,055 |
| | Windows - Sash Aluminum Double-pane | 5,387 | SF | 5 | \$290,187 |

Building Exterior Subtotal:

\$1,213,980

Building: Main

Category: Electrical System



1746 S Miller St Chicago, IL 60608

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--|----------|------|------|----------|
| Emergency System | | | | | |
| | Automatic Transfer Switch | 1 | EA | 6 | \$408 |
| | Automatic Transfer Switch | 1 | EA | 7 | \$0 |
| | Emergency A/C Power - Corridors and Stairs | 10,766 | SF | 7 | \$0 |
| | Emergency A/C Power - Lunchrooms | 2,732 | SF | 7 | \$0 |
| | Emergency A/C Power - Students Toilets | 1,190 | SF | 7 | \$0 |
| | Exit Signs - Corridors and Stairs | 16 | EA | 6 | \$2,396 |
| | Exit Signs - Lunchroom | 4 | EA | 6 | \$599 |
| | Security System - Intrusion Detection | 62,100 | SF | 6 | \$15,985 |
| | UPS - Less than 30 KW | 1 | EA | 6 | \$7,886 |
| Main Service | | | | | |
| | Independent Electrical Service for emergency power | 2 | EA | 6 | \$5,841 |
| | Main Electrical Service - 1200 A 120/208/3PH | 1 | EA | 7 | \$0 |
| | PA System | 62,100 | SF | 6 | \$20,425 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 1 | EA | 4 | \$4,849 |
| | Lighting and Power Panels - 100 A | 10 | EA | 6 | \$2,991 |
| | Lighting and Power Panels - 100 A | 11 | EA | 7 | \$0 |
| | Lighting and Power Panels - Above 100 A | 1 | EA | 4 | \$6,578 |
| | Main Distribution Panels - 400 - 600 amp | 1 | EA | 7 | \$0 |
| | Transformers - 120/240 - 120/208 | 1 | EA | 6 | \$3,021 |

Electrical System Subtotal:

\$70,979

Building: Main

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------------------|--------------------------|----------|------|------|----------|
| Fire Alarm | | | | | |
| | Fire Alarm Panel | 1 | EA | 4 | \$49,477 |
| | Fire Alarm Strobe Lights | 62,100 | SF | 7 | \$0 |
| | Fire Alarm_System | 62,100 | SF | 6 | \$30,193 |
| | Fire Pump Controller | 1 | EA | 6 | \$1,823 |
| Pump Room Assembly | | | | | |
| | Fire Pump - 25-50 hp | 1 | EA | 5 | \$8,163 |
| Sprinkler System | | | | | |
| | Dry Sprinkler System | 62,100 | SF | 6 | \$15,985 |
| | Sprinkler Heads | 62,100 | SF | 6 | \$0 |
| | Sprinkler Piping | 62,100 | SF | 6 | \$11,544 |
| | | | | | |



1746 S Miller St Chicago, IL 60608

Building: Main

Category: Safty System

Group Item - Type Quantity Unit Rank Cost

Safty System Subtotal:

\$117,184

Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|---|----------|------|------|-----------|
| Air Handling Systems | | | | | |
| | Air Handling Unit- Built Up-Multi Zone-Double Delivery- Steam Coils - 15000 - 30000 cfm | 1 | EA | 5 | \$112,299 |
| | Air Intake | 1 | EA | 4 | \$17,616 |
| | Auxiliaries - 15000 - 30000 cfm | 1 | EA | 3 | \$36,420 |
| | Return Duct Work | 100 | LF | 4 | \$0 |
| | Zone Dampers | 23 | EA | 5 | \$44,011 |
| Boiler Systems | | | | | |
| | Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP | 2 | EA | 5 | \$34,033 |
| | Chemical Feed System | 1 | EA | 7 | \$0 |
| | Combustion Dampers | 3 | EA | 4 | \$19,660 |
| | Condensate Pump | 1 | EA | 3 | \$44,329 |
| | Condensate Pump | 1 | EA | 5 | \$18,196 |
| | Feed Water Pumps and Tank | 1 | EA | 5 | \$36,450 |
| | Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler | 2 | EA | 5 | \$0 |
| | Piping - Condensate Pipe- Steel | 150 | LF | 4 | \$27,179 |
| | Piping - Steam Pipe- Steel | 150 | LF | 5 | \$2,113 |
| | Steam Traps | 10 | EA | 5 | \$13,149 |
| Heating Devices | | | | | |
| | Unit Heater - Steam | 2 | EA | 5 | \$1,819 |
| | Wall Heater - Electric | 6 | EA | 5 | \$3,220 |
| | Wall Heater - Electric | 1 | EA | 6 | \$139 |
| Temperature Control | | | | | |
| | Pneumatic System | 62,100 | SF | 3 | \$323,243 |
| | Thermostats | 32 | EA | 4 | \$0 |
| Ventilation | | | | | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | 1 | EA | 3 | \$4,245 |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | 1 | EA | 3 | \$6,392 |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | 1 | EA | 4 | \$6,392 |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | 1 | EA | 7 | \$0 |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 4 | EA | 3 | \$7,768 |
| | | | | | |



1746 S Miller St Chicago, IL 60608

Building: Main

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|--|----------|------|------|---------|
| Ventilation | | | | | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | 4 | EA | 4 | \$7,768 |
| | Type I Exhaust Hood- Kitchen | 1 | EA | 6 | \$1,248 |
| | Type II Exhaust Hood- Warming Kitchen | 1 | EA | 6 | \$920 |

Mechanical System Subtotal: \$768,608

Building: Main

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------|--|----------|------|------|----------|
| Hot Water | | | | | |
| | Gas Heater - 300001 - 600000 BTU/HR | 1 | EA | 4 | \$34,950 |
| Piping | | | | | |
| | Domestic Piping-Cold Water from Risers to Fixtures | 62,100 | SF | 4 | \$44,402 |
| | Domestic Piping-Cold Water Horizontal Lines | 62,100 | SF | 4 | \$89,691 |
| | Domestic Piping-Cold Water Risers | 62,100 | SF | 4 | \$49,730 |
| | Domestic Piping-Hot Water from Risers to Fixtures | 62,100 | SF | 4 | \$33,745 |
| | Domestic Piping-Hot Water Horizontal Lines | 62,100 | SF | 4 | \$79,923 |
| | Domestic Piping-Hot Water Return Lines | 62,100 | SF | 4 | \$53,282 |
| | Domestic Piping-Hot Water Return Risers | 62,100 | SF | 4 | \$30,193 |
| | Sanitary Piping | 62,100 | SF | 5 | \$0 |
| | Storm Piping | 62,100 | SF | 5 | \$0 |
| | Vent Piping | 62,100 | SF | 5 | \$0 |
| Pumps | | | | | |
| | Pumps - Domestic Booster Pump-Simplex | 1 | EA | 5 | \$8,937 |
| | Pumps - Ejector-Duplex | 1 | EA | 6 | \$1,387 |
| | Pumps - Sump-Simplex | 1 | EA | 6 | \$745 |

Plumbing System Subtotal: \$426,983

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------|------------------|----------|------|------|---------|
| Computer Lab (1 room) | | | | | |
| | AC Units | 2 | EA | 6 | \$991 |
| | Ceiling - Lay-in | 858 | SF | 6 | \$2,577 |

Joseph Jungman Elementary School 1746 S Miller St Chicago, IL 60608

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|-----------------------------|----------|------|------|---------|
| Computer Lab (1 ro | oom) | | | | |
| | Chalk Board | 20 | LF | 4 | \$1,836 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Wood | 858 | SF | 6 | \$6,049 |
| | Lighting - Pendent/Surface | 14 | EA | 6 | \$1,735 |
| | Marker Board | 20 | LF | 6 | \$428 |
| | Walls - Plaster/Drywall | 1,534 | SF | 6 | \$4,234 |
| | Wireless System | 1 | EA | 6 | \$372 |
| Kindergarten (1 roo | om) | | | | |
| | Casework | 33 | LF | 6 | \$833 |
| | Ceiling | 948 | | 6 | \$0 |
| | Doors - Transom Window | 41 | SF | 6 | \$694 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Wood | 948 | SF | 6 | \$6,683 |
| | Marker Board | 10 | LF | 6 | \$214 |
| | Walls - Plaster/Drywall | 1,416 | SF | 6 | \$3,908 |
| Office (1 room) | | | | | |
| | Casework | 8 | LF | 6 | \$202 |
| | Chalk Board | 10 | LF | 4 | \$918 |
| | Doors - Transom Window | 25 | SF | 6 | \$423 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Wood | 950 | SF | 6 | \$6,697 |
| | Lighting - Pendent/Surface | 16 | EA | 6 | \$1,982 |
| | Storage/ Closet | 92 | SF | 6 | \$667 |
| | Walls - Plaster/Drywall | 1,612 | SF | 6 | \$4,449 |
| Pre School (1 room | n) | | | | |
| | Casework | 12 | LF | 6 | \$303 |
| | Ceiling - Lay-in | 887 | SF | 6 | \$2,664 |
| | Doors - Transom Window | 9 | SF | 6 | \$152 |
| | Doors - Wood Doors inclu hw | 1 | EA | 6 | \$301 |
| | Floor - Tile/Sheet | 887 | SF | 6 | \$888 |
| | Lighting - Pendent/Surface | 16 | EA | 6 | \$1,982 |
| | Walls - Plaster/Drywall | 1,560 | SF | 6 | \$4,305 |
| Regular Classroom | n (15 rooms) | | | | |
| | AC Units | 10 | EA | 6 | \$4,956 |
| | Casework | 42 | LF | 6 | \$1,061 |
| | | | | | • |

1746 S Miller St Chicago, IL 60608

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------------------|-----------------------------|-------------|------|--------|------------------|
| Regular Classroom (15 r | ooms) | | | | |
| | Ceiling | 2,214 | | 6 | \$0 |
| | Ceiling - Lay-in | 13,086 | SF | 6 | \$39,297 |
| | Ceiling - Plaster/Drywall | 945 | SF | 6 | \$3,270 |
| | Chalk Board | 210 | LF | 4 | \$19,279 |
| | Doors | 1 | | 6 | \$0 |
| | Doors - Transom Window | 735 | SF | 6 | \$12,444 |
| | Doors - Wood Doors inclu hw | 20 | EA | 6 | \$6,020 |
| | Floor | 1,107 | | 6 | \$0 |
| | Floor - Tile/Sheet | 3,214 | SF | 6 | \$3,217 |
| | Floor - Wood | 11,924 | SF | 6 | \$84,063 |
| | Lighting | 16 | | 6 | \$0 |
| | Lighting - Lay-in | 15 | EA | 6 | \$1,785 |
| | Lighting - Pendent/Surface | 208 | EA | 6 | \$25,770 |
| | Marker Board | 98 | LF | 6 | \$2,099 |
| | Marker Board | 148 | LF | 7 | \$0 |
| | Storage/ Closet | 2,140 | SF | 6 | \$15,515 |
| | Walls | 2,740 | | 6 | \$0 |
| | Walls - Plaster/Drywall | 31,057 | SF | 6 | \$85,714 |
| | Work Sink | 1 | EA | 6 | \$379 |
| Science Classroom (2 ro | oms) | | | | |
| | Ceiling - Lay-in | 2,214 | SF | 6 | \$6,649 |
| | Chalk Board | 18 | LF | 4 | \$1,653 |
| | Doors - Transom Window | 41 | SF | 6 | \$694 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile/Sheet | 1,107 | SF | 6 | \$1,108 |
| | Floor - Wood | 1,107 | SF | 6 | \$7,804 |
| | Lighting - Pendent/Surface | 32 | EA | 6 | \$3,965 |
| | Marker Board | 62 | LF | 7 | \$0 |
| | Storage/ Closet | 226 | SF | 6 | \$1,639 |
| | Walls - Plaster/Drywall | 4,940 | SF | 6 | \$13,634 |
| | Walls Flascorblywall | -1,0-10 | OI . | O . | Ψ10,004 |
| Store Room (1 room) | Casework | 20 | LF | | |
| | | 20 1,107 | SF | 6 6 | \$505 \$3,324 |
| | Ceiling - Lay-in | | | | |
| | Chalk Board | 24 | LF | 6 | \$535 |
| | Doors - Transom Window | 41 | SF | 6 | \$694 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |



1746 S Miller St Chicago, IL 60608

Building: Main

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|----------------------------|----------|------|------|---------|
| Store Room (1 room) | | | | | |
| | Floor - Wood | 1,107 | SF | 6 | \$7,804 |
| | Lighting - Pendent/Surface | 16 | EA | 6 | \$1,982 |
| | Storage/ Closet | 216 | SF | 6 | \$1,566 |
| | Walls - Plaster/Drywall | 2,740 | SF | 6 | \$7,562 |

Classrooms Subtotal: \$425,186

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|---------------------------------|----------|------|------|-----------|
| Administrative S | uites/Offices | | | | |
| | AC Unit | 1 | EA | 6 | \$496 |
| | Ceiling - Exposed | 905 | SF | 6 | \$1,346 |
| | Ceiling - Lay-in | 1,188 | SF | 6 | \$3,568 |
| | Ceiling - Plaster/Drywall | 1,067 | SF | 6 | \$3,692 |
| | Doors - Side-lite | 187 | SF | 6 | \$3,126 |
| | Doors - Transom Window | 17 | SF | 6 | \$288 |
| | Doors - Wood Doors inclu hw | 2 | EA | 5 | \$2,348 |
| | Doors - Wood Doors inclu hw | 13 | EA | 6 | \$3,913 |
| | Floor - Carpet | 552 | SF | 6 | \$1,176 |
| | Floor - Concrete | 583 | SF | 6 | \$308 |
| | Floor - Tile Ceramic/ Porcelain | 70 | SF | 6 | \$148 |
| | Floor - Tile/Sheet | 827 | SF | 6 | \$828 |
| | Floor - Wood | 1,068 | SF | 6 | \$7,529 |
| | Lighting - Lay-in | 20 | EA | 6 | \$2,380 |
| | Lighting - Pendent/Surface | 43 | EA | 6 | \$5,327 |
| | Power Distribution | 65 | EA | 6 | \$138,117 |
| | Storage/ Closet | 12 | SF | 6 | \$87 |
| | Walls - Concrete Block | 760 | SF | 6 | \$2,271 |
| | Walls - Masonry | 1,060 | SF | 6 | \$3,335 |
| | Walls - Plaster/Drywall | 5,230 | SF | 6 | \$14,434 |
| Kitchen | | | | | |
| | Ceiling | 872 | | 6 | \$0 |
| | Doors - Steel Doors incl hw | 1 | EA | 6 | \$301 |
| | Doors - Wood Doors inclu hw | 3 | EA | 6 | \$903 |
| | Floor - Tile Ceramic/ Porcelain | 872 | SF | 6 | \$1,846 |

1746 S Miller St Chicago, IL 60608

Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|-----------------------------|----------|------|------|----------|
| Kitchen | | | | | |
| | Lighting - Pendent/Surface | 19 | EA | 6 | \$2,354 |
| | Storage/ Closet | 72 | SF | 6 | \$522 |
| | Walls - Concrete Block | 1,030 | SF | 6 | \$3,019 |
| | Walls - Masonry | 320 | SF | 6 | \$1,007 |
| Lunch & Multipurp | pose Room | | | | |
| | Ceiling - Lay-in | 2,732 | SF | 6 | \$8,204 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Concrete | 1,805 | SF | 6 | \$955 |
| | Floor - Wood | 927 | SF | 6 | \$6,535 |
| | Lighting - Lay-in | 36 | EA | 6 | \$4,283 |
| | Lighting - Pendent/Surface | 11 | EA | 6 | \$1,363 |
| | Serving Line | 20 | LF | 6 | \$1,190 |
| | Walls - Masonry | 1,408 | SF | 6 | \$4,430 |
| | Walls - Plaster/Drywall | 1,611 | SF | 6 | \$4,446 |
| MDF_IDF | | | | | |
| | AC Unit | 1 | EA | 6 | \$496 |
| | Doors - Wood Doors inclu hw | 7 | EA | 6 | \$2,107 |
| | Finishes | 216 | SF | 6 | \$1,541 |
| Mechanical/ Service | ce Rooms | | | | |
| | Air Intake Plenums | 1,684 | SF | 6 | \$10,427 |
| | Boiler Room | 1,215 | SF | 6 | \$8,705 |
| | Coal Room | 540 | SF | 6 | \$3,869 |
| | Janitor's Closet | 60 | SF | 6 | \$430 |
| | Mechanical/ Service Rooms | 462 | SF | 6 | \$3,310 |
| | Storage Room | 615 | SF | 6 | \$4,406 |
| Restroom | | | | | |
| | Accessories | 1,850 | SF | 6 | \$17,063 |
| | Accessories | 208 | SF | 7 | \$0 |
| | Benches | 6 | LF | 6 | \$87 |
| | Ceiling | 70 | | 6 | \$0 |
| | Ceiling - Exposed | 72 | SF | 6 | \$107 |
| | Ceiling - Lay-in | 506 | SF | 6 | \$1,520 |
| | Ceiling - Plaster/Drywall | 1,410 | SF | 6 | \$4,879 |
| | Doors | 2 | | 6 | \$0 |
| | Doors - Transom Window | 2 | SF | 6 | \$34 |
| | | | | | , - |



Building: Main

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|---------------------------------|----------|------|------|-------------|
| Restroom | | | | | |
| | Doors - Wood Doors inclu hw | 12 | EA | 6 | \$3,612 |
| | Doors - Wood Doors inclu hw | 1 | EA | 7 | \$0 |
| | Floor - Concrete | 434 | SF | 6 | \$230 |
| | Floor - Terrazzo | 726 | SF | 6 | \$1,588 |
| | Floor - Tile Ceramic/ Porcelain | 604 | SF | 6 | \$1,278 |
| | Floor - Tile Ceramic/ Porcelain | 208 | SF | 7 | \$0 |
| | Floor - Tile/Sheet | 86 | SF | 6 | \$86 |
| | Floor Drain | 3 | EA | 6 | \$3,177 |
| | Floor Drain | 1 | EA | 7 | \$0 |
| | Hand Dryer | 3 | EA | 6 | \$690 |
| | Hand Dryer | 1 | EA | 7 | \$0 |
| | Lavatory | 15 | EA | 6 | \$4,794 |
| | Lavatory | 3 | EA | 7 | \$ 0 |
| | Lighting | 5 | | 7 | \$ 0 |
| | Lighting - Pendent/Surface | 2 | EA | 4 | \$1,081 |
| | Lighting - Pendent/Surface | 38 | EA | 6 | \$4,708 |
| | Lighting - Wall Mounted | 2 | EA | 4 | \$786 |
| | Partitions | 23 | EA | 6 | \$6,829 |
| | Partitions | 2 | EA | 7 | \$ 0 |
| | Urinals | 6 | EA | 6 | \$2,016 |
| | Urinals | 6 | EA | 7 | \$ 0 |
| | Walls | 420 | | 6 | \$ 0 |
| | Walls - Concrete Block | 2,164 | SF | 6 | \$6,344 |
| | Walls - Plaster/Drywall | 4,680 | SF | 6 | \$12,916 |
| | Walls - Plaster/Drywall | 564 | SF | 7 | \$O |
| | Walls - Tile Ceramic/ Porcelain | 114 | SF | 6 | \$258 |
| | Walls - Tile Ceramic/ Porcelain | 256 | SF | 7 | \$0 |
| | Water Closet | 30 | EA | 6 | \$10,079 |
| | Water Closet | 2 | EA | 7 | \$0 |

Rooms (Other Than Classrooms) Subtotal:

\$356,132

Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|-------------------|----------|------|------|---------|
| Corridor | | | | | |
| | Ceiling - Exposed | 1,544 | SF | 6 | \$2,296 |

\$3,649,822



Building: Main

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|---------------------|--|----------|------|------|-----------|
| Corridor | | | | | |
| | Ceiling - Lay-in | 5,010 | SF | 6 | \$15,045 |
| | Ceiling - Plaster/Drywall | 4,509 | SF | 6 | \$28,523 |
| | Doors - Side-lite | 128 | EA | 6 | \$2,140 |
| | Doors - Store Front | 2 | EA | 6 | \$2,416 |
| | Doors - Transom Window | 178 | EA | 6 | \$3,014 |
| | Doors - Wood Doors include hw | 17 | EA | 6 | \$5,117 |
| | Drinking Fountains - Single Fountain | 11 | EA | 6 | \$3,033 |
| | Drinking Fountains - Single Water Cooler | 8 | EA | 6 | \$2,534 |
| | Floor - Asphalt Floor | 9,620 | SF | 6 | \$14,582 |
| | Floor - Terrazzo | 162 | SF | 6 | \$1,360 |
| | Floor - Tile/Sheet | 804 | SF | 6 | \$437 |
| | Lighting - Pendent/Surface | 116 | EA | 6 | \$14,372 |
| | Student Lockers - One Tier | 128 | EA | 6 | \$11,883 |
| | Walls - Masonry | 2,522 | SF | 6 | \$7,934 |
| | Walls - Plaster/Drywall | 14,814 | SF | 6 | \$65,670 |
| Stairs | | | | | |
| | Ceiling - Exposed | 448 | SF | 6 | \$666 |
| | Ceiling - Lay-in | 3,075 | SF | 6 | \$9,234 |
| | Ceiling - Plaster/Drywall | 1,883 | SF | 6 | \$13,787 |
| | Floor - Asphalt | 1,671 | SF | 6 | \$12,951 |
| | Handrails | 488 | LF | 6 | \$4,229 |
| | Lighting - Pendent/Surface | 25 | EA | 6 | \$3,097 |
| | Stairs - Asphalt | 1,494 | LF | 6 | \$13,865 |
| | Walls - Concrete Block | 108 | SF | 6 | \$317 |
| | Walls - Masonry | 1,536 | SF | 6 | \$4,832 |
| | Walls - Plaster/Drywall | 9,940 | SF | 6 | \$27,433 |
| Vertical Conveyance | | | | | |
| | Elevator - Hydraulic Elevator | 1 | EA | 7 | \$0 |
| | Wheelchair Lift - Platform Lift | 1 | EA | 7 | \$0 |
| Building Interior | Subtotal: | | | | \$270,768 |

Building: Gymnasium/auditorium

Total Building Cost



1746 S Miller St Chicago, IL 60608

| Category: | Building | Exterior |
|-----------|----------|----------|
|-----------|----------|----------|

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-------------|---|----------|------|------|----------|
| Entrance | | | | | |
| | Exterior Doors - Exterior Steel Door | 6 | EA | 6 | \$2,883 |
| | Exterior Doors - Transom Lite | 4 | EA | 6 | \$1,253 |
| | Exterior Stairs - Concrete | 32 | LF | 6 | \$2,617 |
| Foundation | | | | | |
| | Foundation - Concrete | 396 | LF | 7 | \$0 |
| | Superstructure - Steel with Clay Tile Arch | 7,750 | SF | 7 | \$0 |
| Lighting | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | 5 | EA | 6 | \$2,683 |
| Roof System | | | | | |
| | Coping - Clay Tile | 306 | LF | 6 | \$9,828 |
| | Downspouts - Exterior Downspouts | 28 | LF | 6 | \$931 |
| | Downspouts - Interior Downspouts | 140 | LF | 6 | \$4,653 |
| | Parapet - 16" - 30" Height | 275 | LF | 6 | \$10,987 |
| | Parapet - Parapet < 16" Height | 31 | LF | 6 | \$661 |
| | Roof - Asphalt Gravel Ballast | 7,750 | SF | 6 | \$78,797 |
| | Roof Structure - Steel with Clay Tile Arch | 7,750 | SF | 7 | \$0 |
| Walls | | | | | |
| | Cheek-Wall - Stone | 12 | SF | 6 | \$123 |
| | Cornice - Metal Projecting | 140 | LF | 5 | \$21,063 |
| | Exterior Walls - Brick | 20 | SF | 4 | \$3,293 |
| | Exterior Walls - Brick | 3,250 | SF | 5 | \$68,690 |
| | Exterior Walls - Brick | 3,852 | SF | 6 | \$25,889 |
| | Exterior Walls - Stone-Cut | 75 | SF | 5 | \$1,197 |
| | Exterior Walls - Stone-Cut | 233 | SF | 6 | \$1,566 |
| Windows | | | | | |
| | Guard - Guards perforated | 200 | SF | 6 | \$2,554 |
| | Lintels - Steel | 35 | LF | 6 | \$1,016 |
| | Windows - Sash Aluminum Double-pane | 200 | SF | 5 | \$10,774 |
| | | | | | |

Building Exterior Subtotal:

\$251,456

Building: Gymnasium/auditorium

Category: Electrical System

Group Item - Type Quantity Unit Rank Cost

1746 S Miller St Chicago, IL 60608

Building: Gymnasium/auditorium

Category: Electrical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|-----------------------------|-----------------------------------|----------|------|------|---------|
| Emergency System | | | | | |
| | Exit Signs - Auditoium | 7 | EA | 6 | \$1,048 |
| | Exit Signs - Corridors and Stairs | 3 | EA | 6 | \$449 |
| Power Distribution | | | | | |
| | Lighting and Power Panels - 100 A | 2 | EA | 6 | \$598 |
| Electrical System Subtotal: | | | | | \$2,096 |

Building: Gymnasium/auditorium

Category: Safty System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|--------------------------|----------|------|------|---------|
| Fire Alarm | | | | | |
| | Fire Alarm Strobe Lights | 7,750 | SF | 7 | \$0 |
| | Fire Alarm_System | 7,750 | SF | 6 | \$3,768 |
| Sprinkler System | | | | | |
| | Dry Sprinkler System | 7,750 | SF | 6 | \$1,995 |
| | Sprinkler Heads | 7,750 | SF | 6 | \$0 |
| | Sprinkler Piping | 7,750 | SF | 6 | \$1,441 |
| Safty System S | Subtotal: | | | | \$7,204 |

Building: Gymnasium/auditorium

Category: Mechanical System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------------|---|----------|------|------|----------|
| Air Handling Systems | | | | | |
| | Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm | 1 | EA | 5 | \$44,262 |
| | Air Intake | 1 | EA | 3 | \$17,616 |
| | Auxiliaries - 15001 - 25000 cfm | 1 | EA | 4 | \$36,420 |
| | Return Duct Work | 100 | LF | 4 | \$0 |

Mechanical System Subtotal: \$98,298

Building: Gymnasium/auditorium

Category: Plumbing System

| | Group | Item - Type | Quantity | Unit | Rank | Cost |
|--|-------|-------------|----------|------|------|------|
|--|-------|-------------|----------|------|------|------|



1746 S Miller St Chicago, IL 60608

\$27,817

Building: Gymnasium/auditorium

Category: Plumbing System

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|--------|---|----------|------|------|----------|
| Piping | | | | | |
| | Domestic Piping-Cold Water Horizontal Lines | 7,750 | SF | 4 | \$11,193 |
| | Domestic Piping-Hot Water Horizontal Lines | 7,750 | SF | 4 | \$9,974 |
| | Domestic Piping-Hot Water Return Lines | 7,750 | SF | 4 | \$6,650 |
| | Sanitary Piping | 7,750 | SF | 5 | \$0 |
| | Storm Piping | 7,750 | SF | 5 | \$0 |
| | Vent Piping | 7,750 | SF | 5 | \$0 |

Building: Gymnasium/auditorium

Plumbing System Subtotal:

Category: Classrooms

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|------------------|-----------------------------|----------|------|------|---------|
| Regular Classroo | om (1 room) | | | | |
| | AC Units | 1 | EA | 6 | \$496 |
| | Ceiling - Lay-in | 1,008 | SF | 6 | \$3,027 |
| | Chalk Board | 10 | LF | 4 | \$918 |
| | Doors - Wood Doors inclu hw | 2 | EA | 6 | \$602 |
| | Floor - Tile/Sheet | 1,008 | SF | 6 | \$1,009 |
| | Lighting - Pendent/Surface | 14 | EA | 6 | \$1,735 |
| | Marker Board | 18 | LF | 6 | \$386 |
| | Storage/ Closet | 150 | SF | 6 | \$1,088 |
| | Walls - Plaster/Drywall | 1,534 | SF | 6 | \$4,234 |

Classrooms Subtotal: \$13,493

Building: Gymnasium/auditorium

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|-----------------------------|----------|------|------|----------|
| Gymnasia | | | | | |
| | Bleacher Seating | 572 | EA | 6 | \$16,556 |
| | Ceiling - Plaster/Drywall | 7,488 | SF | 6 | \$41,332 |
| | Doors - Wood Doors inclu hw | 9 | EA | 6 | \$2,709 |
| | Floor - Tile/Sheet | 2,394 | SF | 6 | \$2,396 |
| | Floor - Wood | 3,712 | SF | 6 | \$26,169 |
| | Lighting - Pendent/Surface | 50 | EA | 6 | \$6,195 |
| | Sound System | 1 | EA | 7 | \$0 |

1746 S Miller St Chicago, IL 60608

Building: Gymnasium/auditorium

Category: Rooms (Other Than Classrooms)

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|-------------------------|----------|------|------|----------|
| Gymnasia | | | | | |
| | Stage | 1,280 | SF | 6 | \$7,395 |
| | Stage Curtain | 2 | EA | 6 | \$0 |
| | Stage Lighting System | 1 | EA | 7 | \$0 |
| | Stage-Stairs - Wood | 30 | LF | 6 | \$352 |
| | Storage/ Closet | 30 | SF | 6 | \$218 |
| | Walls - Plaster/Drywall | 7,085 | SF | 6 | \$19,554 |

Rooms (Other Than Classrooms) Subtotal:

\$122,875

Building: Gymnasium/auditorium

Category: Building Interior

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------|-------------------------------|----------|------|------|---------|
| Corridor | | | | | |
| | Ceiling - Plaster/Drywall | 244 | SF | 6 | \$1,511 |
| | Doors - Wood Doors include hw | 4 | EA | 6 | \$1,204 |
| | Floor - Concrete | 84 | SF | 6 | \$44 |
| | Floor - Tile/Sheet | 160 | SF | 6 | \$87 |
| | Lighting - Pendent/Surface | 4 | EA | 6 | \$496 |
| | Walls - Concrete Block | 378 | SF | 6 | \$1,108 |
| | Walls - Plaster/Drywall | 682 | SF | 6 | \$3,023 |
| Stairs | | | | | |
| | Ceiling - Plaster/Drywall | 104 | SF | 6 | \$761 |
| | Floor - Asphalt | 16 | SF | 6 | \$124 |
| | Handrails | 61 | LF | 6 | \$529 |
| | Stairs - Asphalt | 88 | LF | 6 | \$817 |
| | Walls - Plaster/Drywall | 338 | SF | 6 | \$933 |
| | | | | | |

Building Interior Subtotal:

\$10,637

Total Building Cost \$533,876

SITE

Category: Site

Group Item - Type Quantity Unit Rank Cost



1746 S Miller St Chicago, IL 60608

SITE

Category: Site

| Group | Item - Type | Quantity | Unit | Rank | Cost |
|----------------|---|----------|------|------|-----------|
| Civil/Drainage | | | | | |
| | Civil/ Drainage - Catch Basin | 1 | EA | 6 | \$1,094 |
| | Civil/ Drainage - Site Manhole | 5 | EA | 6 | \$7,464 |
| Fencing | | | | | |
| | Fencing - Chain Link | 20 | LF | 5 | \$1,220 |
| | Fencing - Guard Rail | 279 | LF | 6 | \$3,224 |
| | Fencing - New Standard Ornamental | 1,057 | LF | 5 | \$150,516 |
| Landscape | | | | | |
| | Benches | 3 | EA | 6 | \$1,290 |
| | Landscape - Grass | 11,640 | SF | 6 | \$9,654 |
| | Parkway trees | 25 | EA | 6 | \$16,501 |
| | Play Area - Asphalt/ Hardscape | 10,704 | SF | 6 | \$25,868 |
| Parking Lot | | | | | |
| | Surface - Asphalt | 16,110 | SF | 6 | \$38,933 |
| Playground | | | | | |
| | Equipment - School Age 5-12 | 2 | EA | 6 | \$7,092 |
| | Equipment - Swingset | 1 | EA | 5 | \$0 |
| | Surface - Square Rubber Mats | 4,070 | SF | 5 | \$41,090 |
| Sidewalks | | | | | |
| | Sidewalks - Perimeter Sidewalks | 60 | SF | 5 | \$573 |
| | Sidewalks - Perimeter Sidewalks | 10,907 | SF | 7 | \$0 |
| Signage | | | | | |
| | Flag Pole - Building Mounted Flag Pole | 1 | EA | 7 | \$0 |
| | Marquee - Free Standing Back lighted w/ LED | 1 | EA | 6 | \$0 |
| Site Subtotal: | | | | | \$304,519 |

Total Site Cost \$304,519

Campus Total ^{2 3} \$4,488,216

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.



1746 S Miller St Chicago, IL 60608

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



1746 S Miller St Chicago, IL 60608

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Voice Outlets | Data Outlets | Elect. Outlets | Glazed Window Area | Operable Window Area | Noise Level | Window Stop | Power Strip | Smart- Board |
|-------------------|-------------------|------------------|----------------|------------------------------|-----------|------------------|-----------------|-------------------|--------------------------|----------------------------|----------------|----------------|----------------|-----------------|
| Main | | | + | - | + | - | - | + | | + | - | 1 | | |
| Computer Lab | Regular Classroom | | 201 | 201 | 858 | 0 | 0 | 70 | 85 | 34 | 50 | N | Υ | N |
| Kindergarten | Pre School | | 102 | 102 | 948 | 0 | 4 | 10 | 1,460 | 16 | 50 | N | Υ | Υ |
| Office | Regular Classroom | | 104 | 104 | 950 | 0 | 0 | 8 | 123 | 12 | 51 | N | Υ | Υ |
| Pre School | Pre School | Basement | 100 | 100 | 887 | 0 | 5 | 25 | 160 | 16 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 101 | 101 | 1,030 | 0 | 0 | 10 | 123 | 70 | 51 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 105 | 105 | 1,107 | 0 | 0 | 13 | 123 | 51 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 106 | 106 | 1,030 | 0 | 0 | 11 | 123 | 51 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 108 | 108 | 1,045 | 0 | 0 | 11 | 140 | 12 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 200 | 200 | 887 | 0 | 5 | 25 | 160 | 16 | 50 | Υ | Υ | N |
| Regular Classroom | Regular Classroom | | 203 | 203 | 945 | 0 | 0 | 20 | 140 | 67 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 205 | 205 | 1,107 | 0 | 0 | 13 | 147 | 67 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 206 | 206 | 1,107 | 0 | 0 | 11 | 123 | 51 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 208 | 208 | 1,000 | 0 | 0 | 16 | 190 | 84 | 40 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 301 | 301 | 1,107 | 0 | 0 | 25 | 123 | 51 | 50 | N | Υ | N |
| Regular Classroom | Library | | 302 | 302 | 1,107 | 0 | 5 | 25 | 105 | 9 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 303 | 303 | 1,452 | 0 | 15 | 40 | 172 | 85 | 50 | N | Υ | N |
| Regular Classroom | Regular Classroom | | 305 | 305 | 1,107 | 0 | 40 | 50 | 142 | 68 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 306 | 306 | 1,107 | 0 | 0 | 26 | 142 | 68 | 50 | N | Υ | Υ |
| Regular Classroom | Regular Classroom | | 308 | 308 | 1,107 | 0 | 5 | 25 | 190 | 84 | 50 | N | Υ | N |
| Science Classroom | Regular Classroom | | 204 | 204 | 1,107 | 0 | 0 | 18 | 123 | 12 | 51 | N | Υ | N |
| Science Classroom | Regular Classroom | | 300 | 300 | 1,107 | 0 | 5 | 25 | 142 | 68 | 50 | N | Υ | N |
| Store Room | Regular Classroom | | 304 | 304 | 1,107 | 0 | 13 | 26 | 142 | 68 | 50 | N | Υ | N |
| Gymnasium/audi | torium | | | | | | | | | | | | | |
| Cymnasiani, addi | COLIGIN | | T | T | 1 | Т | I | 1 | | 1 | | | | 1 |

| Gymnasium/auditorium | | | | | | | | | | | | | |
|----------------------|-------------------|-----|-----|-------|---|---|----|-----|----|----|---|---|---|
| Regular Classroom | Regular Classroom | 109 | 109 | 1,008 | 0 | 0 | 12 | 193 | 81 | 40 | N | Υ | Υ |