1850 N Newland Ave Chicago, IL 60707

Facility Assessment Report

This report contains a summary of the results from the facility assessment completed on the date noted in the document footer below. This report will roll-up each assessed item with identical rank and total the quantity into a single line, regardless of item location (for location data, see the detailed report). Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings or floors. Each facility item is ranked on a 7-point scale: rank 7 means the item is in new or in good condition and no work is required while rank 1 means the item has failed and has lead to an immediate life safety condition¹. The remaining ranks choices generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). For additional detail and definition on rank values as they relate to each assessed item, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx. Definitions for Quantity, Unit, Cost and Campus Total can be found at the end of this report.

Campus Summary									
Building Name	Year Constructed	Number of Floors	Building Area (Sq Ft)	Assessed Need					
Main	1930	3	79,775	\$2,254,859					
SITE				\$95,371					
Campus Total			79,775	\$2,350,230					

Building: Main

Category: Building Exterior

Group	Item - Type	Quantity	Unit	Rank	Cost
Entrance					
	Entrance Control - Audio and Video	1	EA	7	\$0
	Exterior Doors - Exterior AMP Door	9	EA	6	\$6,067
	Exterior Doors - Exterior FRP Door	6	EA	6	\$3,788
	Exterior Doors - Exterior FRP Door	3	EA	7	\$0
	Exterior Doors - Exterior Steel Door	3	EA	6	\$1,442
	Exterior Doors - Transom Lite	6	EA	6	\$1,880
	Exterior Stairs - Concrete	163	LF	6	\$13,328
	Exterior Stairs - Concrete	424	LF	7	\$0
	Exterior Stairs - Stone	64	LF	5	\$17,355
	Power Door Operator and Controls	1	EA	7	\$0
	Ramp Handrail - Steel_Ramp Handrail	314	LF	6	\$2,721
	Ramps - Concrete	158	LF	6	\$23,737
	Stair Handrail - Steel_Stair Handrail	70	LF	6	\$607
	Stair Handrail - Steel_Stair Handrail	101	LF	7	\$0
Foundation					
	Foundation - Concrete	1,170	LF	7	\$0
	Superstructure - Steel with Clay Tile Arch	79,775	SF	7	\$0
Lighting					
	Exterior Lighting - Parapet or Roof Mounted	13	EA	6	\$6,975
SAVRE		Page 1 of 15			Assessment Date: 9/25/2014



1850 N Newland Ave Chicago, IL 60707

Building: Main

Category: Building Exterior

Group	Item - Type	Quantity	Unit	Rank	Cost
Lighting					
	Exterior Lighting - Wall Mounted	16	EA	6	\$4,620
Roof System					
	Chimney - Brick Chimney- Concrete/ Mortar Liner	10	LF	5	\$28,516
	Chimney - Brick Chimney- Concrete/ Mortar Liner	120	LF	6	\$114,562
	Coping - Stone	240	LF	5	\$26,282
	Coping - Stone	41	LF	7	\$0
	Coping - Terra Cotta	1,344	LF	6	\$43,166
	Downspouts - Exterior Downspouts	53	LF	4	\$7,180
	Downspouts - Exterior Downspouts	321	LF	7	\$0
	Downspouts - Interior Downspouts	354	LF	7	\$0
	Parapet - 16" - 30" Height	354	LF	7	\$0
	Parapet - Parapet < 16" Height	297	LF	7	\$0
	Parapet - Parapet > 30"	958	LF	7	\$0
	Roof - Asphalt Gravel Ballast	32,319	SF	6	\$328,597
	Roof Structure - Concrete	29,294	SF	7	\$0
	Roof Structure - Steel with Clay Tile Arch	3,025	SF	7	\$0
Walls					
	Cheek-Wall - Concrete	103	SF	6	\$1,056
	Cheek-Wall - Stone	144	SF	5	\$3,427
	Cheek-Wall - Stone	744	SF	6	\$7,628
	Exterior Walls - Brick	40,717	SF	7	\$0
	Exterior Walls - Stone-Cut	100	SF	7	\$0
	Exterior Walls - Terra Cotta	9,150	SF	6	\$61,497
Windows					
	Guard - Guards perforated	2,706	SF	7	\$0
	Guard - Guards wire guard	21	SF	6	\$268
	Lintels - Steel	848	LF	7	\$0
	Lintels - Terra Cotta	12	LF	6	\$0
	Skylite - Glass Single-Pane	350	SF	6	\$8,363
	Storefront Windows	200	SF	6	\$2,242
	Windows - Louver	30	SF	6	\$224
	Windows - Sash Aluminum Double-pane	7,500	SF	7	\$0

Building Exterior Subtotal:

\$715,528

Building: Main

1850 N Newland Ave Chicago, IL 60707

Category: Electrical Systen	Category	: Electrica	ıl System
-----------------------------	----------	-------------	-----------

Group	Item - Type	Quantity	Unit	Rank	Cost
Emergency System					
	Automatic Transfer Switch	2	EA	6	\$816
	Emergency A/C Power - Corridors and Stairs	18,537	SF	6	\$5,567
	Emergency A/C Power - Gym	2,885	SF	6	\$1,073
	Emergency Battery Packs - Auditoium and Aisle Lighting	4	EA	6	\$810
	Emergency Battery Packs - Corridors and Stairs	6	EA	6	\$1,215
	Exit Signs - Auditoium	12	EA	7	\$0
	Exit Signs - Corridors and Stairs	26	EA	7	\$0
	Exit Signs - Gym	4	EA	7	\$0
	Exit Signs - Lunchroom	3	EA	7	\$0
	Security System - Intrusion Detection	79,775	SF	6	\$20,534
Main Service					
	Independent Electrical Service for emergency power	1	EA	6	\$2,921
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	1	EA	7	\$0
	PA System	79,775	SF	6	\$26,238
Power Distribution					
	Lighting and Power Panels - 100 A	10	EA	6	\$2,991
	Lighting and Power Panels - 100 A	1	EA	7	\$0
	Lighting and Power Panels - Above 100 A	7	EA	6	\$3,479
	Lighting and Power Panels - Above 100 A	4	EA	7	\$0
	Main Distribution Panels - Greater than 600 amp	1	EA	6	\$730
Electrical System	Subtotal:				\$66,374

Building: Main

Category: Safty System

Group	Item - Type	Quantity	Unit	Rank	Cost
Fire Alarm					
	Fire Alarm Panel	1	EA	6	\$6,406
	Fire Alarm Strobe Lights	79,775	SF	6	\$28,520
	Fire Alarm_System	79,775	SF	6	\$38,787

Safty System Subtotal: \$73,712

Building: Main

Category: Mechanical System

Group Item - Type Quantity Unit Rank Cost



1850 N Newland Ave Chicago, IL 60707

Building: Main

Category: Mechanical System

Group	Item - Type	Quantity	Unit	Rank	Cost
Air Conditioning					
	Condensing Unit- Roof Mounted - Less than 5 tons	1	EA	2	\$11,133
Air Handling Systems					
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	2	EA	5	\$111,297
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	1	EA	5	\$66,438
	Air Intake	1	EA	4	\$17,616
	Air Intake	2	EA	5	\$14,941
	Auxiliaries - 15001 - 25000 cfm	1	EA	5	\$14,899
	Auxiliaries - 25001 - 35000 cfm	2	EA	5	\$33,155
	Reheat Boxes - Reheat Boxes with Steam Coil	11	EA	6	\$11,562
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	100	LF	4	\$0
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	100	LF	5	\$131,341
	Zone Dampers	42	EA	6	\$34,987
Boiler Systems					
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	2	EA	6	\$5,091
	Chemical Feed System	1	EA	6	\$1,078
	Combustion Dampers	2	EA	6	\$818
	Condensate Pump	3	EA	6	\$6,063
	Feed Water Pumps and Tank	1	EA	6	\$2,545
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 151 - 200 HP	2	EA	6	\$5,091
	Piping - Condensate Pipe- Steel	900	LF	6	\$1,699
	Piping - Steam Pipe- Steel	900	LF	6	\$1,699
	Steam Traps	36	EA	6	\$9,509
Gas Booster					
	Gas Booster	2	EA	6	\$998
Heating Devices					
	Fin Tube - Steam	2	LF	5	\$163
	Radiators - Steam	27	EA	5	\$45,234
	Unit Heater - Electric	2	EA	6	\$556
	Unit Heater - Gas	2	EA	6	\$556
	Wall Heater - Electric	14	EA	7	\$0
Temperature Control					
	Pneumatic System	79,775	SF	6	\$42,209
	Thermostats - Pneumatic	42	EA	6	\$0



1850 N Newland Ave Chicago, IL 60707

Building: Main

Category: Mechanical System

Group	Item - Type	Quantity	Unit	Rank	Cost
Unit Ventilation					
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	1	EA	3	\$19,993
Ventilation					
	Exhaust Fans- Indoor - Less than 500 CFM	1	EA	4	\$1,278
	Exhaust Fans- Indoor - Less than 500 CFM	1	EA	6	\$296
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	2	EA	6	\$1,185
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	2	EA	6	\$1,185
	Exhaust Fans- Roof Mounted - Less than 500 CFM	4	EA	6	\$1,185
	Type I Exhaust Hood- Kitchen	1	EA	2	\$28,265

Mechanical System Subtotal:

\$624,063

Building: Main

Category: Plumbing System

Group	Item - Type	Quantity	Unit	Rank	Cost
Hot Water					
	Gas Heater - 150000 - 300000 BTU/HR	1	EA	6	\$310
	Gas Heater - 150000 - 300000 BTU/HR	1	EA	7	\$0
Piping					
	Domestic Piping-Cold Water from Risers to Fixtures	79,775	SF	6	\$15,971
	Domestic Piping-Cold Water Horizontal Lines	79,775	SF	6	\$19,393
	Domestic Piping-Cold Water Risers	79,775	SF	6	\$14,830
	Domestic Piping-Hot Water from Risers to Fixtures	79,775	SF	6	\$12,549
	Domestic Piping-Hot Water Horizontal Lines	79,775	SF	6	\$14,830
	Domestic Piping-Hot Water Return Lines	79,775	SF	6	\$11,408
	Domestic Piping-Hot Water Return Risers	79,775	SF	6	\$11,408
	Sanitary Piping	79,775	SF	6	\$73,010
	Storm Piping	79,775	SF	6	\$69,588
	Vent Piping	79,775	SF	6	\$53,617
Pumps					
	Pumps - Domestic Booster Pump-Duplex	1	EA	6	\$1,977
	Pumps - Domestic Booster Pump-Simplex	1	EA	5	\$8,937
	Pumps - Sump-Duplex	1	EA	5	\$7,535
DII : O	ntom Culptotal				¢245.262

Plumbing System Subtotal:

\$315,362



1850 N Newland Ave Chicago, IL 60707

Building: Main

Category: Classrooms

Group	Item - Type	Quantity	Unit	Rank	Cost
Kindergarten (2 roor	ms)				
	AC Units	3	EA	6	\$1,487
	Casework	44	LF	7	\$0
	Ceiling - Plaster/Drywall	2,446	SF	7	\$0
	Doors - Transom Window	49	SF	7	\$0
	Doors - Wood Doors inclu hw	2	EA	6	\$602
	Doors - Wood Doors inclu hw	3	EA	7	\$0
	Floor - Carpet	250	SF	7	\$0
	Floor - Wood	2,196	SF	7	\$0
	Lighting - Pendent/Surface	44	EA	7	\$0
	Marker Board	40	LF	7	\$0
	Storage/ Closet	210	SF	7	\$0
	Walls - Plaster/Drywall	2,823	SF	7	\$0
Pre School (1 room)					
The ochoor (Thoolin)	AC Units	1	EA	6	\$496
	Casework	17	LF	7	\$0
	Ceiling - Plaster/Drywall	802	SF	7	\$0
	Doors - Wood Doors inclu hw	2	EA	6	\$602
	Floor - Tile/Sheet	748	SF	7	\$0
	Floor - Wood	54	SF	7	\$0
	Lighting - Pendent/Surface	13	EA	7	\$0
	Marker Board	6	LF	7	\$0
	Walls - Plaster/Drywall	842	SF	7	\$0
Regular Classroom					
Regulai Classicolli	AC Units	24	EA	6	\$11,894
	AC Units	1	EA	7	\$0
	Casework	24	LF	7	\$0
	Ceiling - Plaster/Drywall	1,456	SF	6	\$5,039
	Ceiling - Plaster/Drywall	15,438	SF	7	\$0
	Doors - Transom Window	434	SF	7	\$0
	Doors - Wood Doors inclu hw	5	EA	6	\$1,505
	Doors - Wood Doors inclu hw	40	EA	7	\$1,303
	Floor - Wood	756	SF	6	\$5,330
	Floor - Wood	16,442	SF	7	\$5,330 \$0
			EA EA		
	Lighting - Pendent/Surface	305		7	\$0 \$0
	Marker Board	481	LF	7	\$0 \$0
	Storage/ Closet	304	SF	7	\$0



1850 N Newland Ave Chicago, IL 60707

Building: Main

Category: Classrooms

Group	Item - Type	Quantity	Unit	Rank	Cost
Regular Classro	om (23 rooms)				
	Walls - Plaster/Drywall	1,134	SF	6	\$3,130
	Walls - Plaster/Drywall	28,008	SF	7	\$0
Science Classro	om (1 room)				
	AC Units	1	EA	6	\$496
	Casework	49	LF	6	\$1,237
	Ceiling - Plaster/Drywall	944	SF	7	\$0
	Chalk Board	2	LF	4	\$184
	Doors - Wood Doors inclu hw	3	EA	6	\$903
	Floor - Tile/Sheet	944	SF	6	\$945
	Lighting - Pendent/Surface	16	EA	7	\$0
	Marker Board	6	LF	6	\$129
	Storage/ Closet	144	SF	5	\$2,323
	Walls - Plaster/Drywall	1,190	SF	7	\$0
	Walls - Tile Ceramic/ Porcelain	65	SF	7	\$0
	Work Sink	3	EA	5	\$4,523
Special Program	(1 room)				
	AC Units	1	EA	6	\$496
	Casework	8	LF	7	\$0
	Ceiling - Plaster/Drywall	728	SF	7	\$0
	Doors - Transom Window	12	SF	7	\$0
	Doors - Wood Doors inclu hw	1	EA	7	\$0
	Floor - Tile/Sheet	728	SF	7	\$0
	Lighting - Pendent/Surface	14	EA	7	\$0
	Marker Board	12	LF	7	\$0
	Walls - Plaster/Drywall	1,134	SF	7	\$0

Classrooms Subtotal:

\$41,318

Building: Main

Group	Item - Type	Quantity	Unit	Rank	Cost			
Administrative Suites/Offices								
	AC Unit	3	EA	6	\$1,487			
	AC Unit	1	EA	7	\$0			
	Ceiling - Plaster/Drywall	88	SF	6	\$305			
	Ceiling - Plaster/Drywall	1,723	SF	7	\$0			



1850 N Newland Ave Chicago, IL 60707

Building: Main

Group	Item - Type	Quantity	Unit	Rank	Cost
Administrative Suit	tes/Offices				
	Doors - Side-lite	39	SF	7	\$0
	Doors - Transom Window	58	SF	7	\$0
	Doors - Wood Doors inclu hw	7	EA	6	\$2,107
	Doors - Wood Doors inclu hw	8	EA	7	\$0
	Floor - Carpet	260	SF	4	\$2,391
	Floor - Carpet	155	SF	6	\$330
	Floor - Carpet	632	SF	7	\$0
	Floor - Tile/Sheet	608	SF	7	\$0
	Floor - Wood	156	SF	7	\$0
	Lighting - Pendent/Surface	23	EA	7	\$0
	Power Distribution	32	EA	7	\$0
	Walls - Plaster/Drywall	1,505	SF	6	\$4,154
	Walls - Plaster/Drywall	4,452	SF	7	\$0
	Work Sink	1	EA	7	\$0
Auditorium & Theat	ter				
	Balcony Seating	176	EA	6	\$30,609
	Ceiling - Plaster/Drywall	6,414	SF	7	\$0
	Doors - Wood Doors inclu hw	18	EA	6	\$5,418
	Floor - Concrete	1,186	SF	6	\$628
	Floor - Tile/Sheet	3,858	SF	7	\$0
	Floor - Wood	1,370	SF	7	\$0
	Lighting - Chandelier, Incandescent	5	EA	6	\$2,388
	Lighting - Pendent/Surface	4	EA	7	\$0
	Lighting - Wall Mounted	21	EA	7	\$0
	Main Floor Seating	514	EA	6	\$89,393
	Sound System	1	EA	7	\$0
	Stage	1,370	SF	7	\$0
	Stage Curtain	1	EA	5	\$12,287
	Stage Curtain	3	EA	6	\$0
	Stage Lift	1	EA	6	\$6,510
	Stage Lighting System	1	EA	6	\$8,077
	Stage-Stairs - Wood	26	LF	7	\$0
	Storage/ Closet	244	SF	7	\$0
	Walls - Plaster/Drywall	6,841	SF	7	\$0
Green House					
	Finishes	347	SF	5	\$4,158
					. *



1850 N Newland Ave Chicago, IL 60707

Building: Main

Group	Item - Type	Quantity	Unit	Rank	Cost
Green House					
	Glazing	340	SF	5	\$28,953
	Mechanical	347	SF	5	\$1,350
	Plumbing	347	SF	6	\$198
Gymnasia					
	Ceiling - Plaster/Drywall	10	SF	5	\$200
	Ceiling - Plaster/Drywall	2,875	SF	7	\$0
	Doors - Wood Doors inclu hw	6	EA	6	\$1,806
	Floor - Wood	2,885	SF	7	\$0
	Lighting - Metal Halide/Sodium Vapor	8	EA	6	\$1,070
	Lighting - Wall Mounted	4	EA	7	\$0
	Storage/ Closet	250	SF	6	\$1,813
	Walls - Masonry	1,256	SF	7	\$0
	Walls - Plaster/Drywall	40	SF	5	\$204
	Walls - Plaster/Drywall	3,664	SF	7	\$0
Kitchen					
	AC Unit	1	EA	6	\$496
	Ceiling - Plaster/Drywall	386	SF	7	\$0
	Doors - Transom Window	6	SF	7	\$0
	Doors - Wood Doors inclu hw	1	EA	7	\$0
	Floor - Tile/Sheet	386	SF	7	\$0
	Lighting - Pendent/Surface	6	EA	7	\$0
	Serving Line	18	LF	7	\$0
	Walls - Plaster/Drywall	624	SF	7	\$0
Library					
	AC Unit	2	EA	7	\$0
	Casework	50	LF	7	\$0
	Ceiling - Plaster/Drywall	1,452	SF	7	\$0
	Doors - Wood Doors inclu hw	2	EA	7	\$0
	Floor - Wood	1,484	SF	7	\$0
	Lighting - Pendent/Surface	28	EA	7	\$0
	Storage/ Closet	32	SF	7	\$0
	Walls - Plaster/Drywall	2,210	SF	7	\$0
Locker/Shower Room	m				
	Accessories	100	SF	6	\$392
	Ceiling - Plaster/ Drywall	100	SF	6	\$346



1850 N Newland Ave Chicago, IL 60707

Building: Main

Group	Item - Type	Quantity	Unit	Rank	Cost
Locker/Shower R	coom				
	Doors - Wood Doors inclu hw	2	EA	6	\$602
	Floor - Concrete	100	SF	6	\$53
	Lavatory	1	EA	4	\$7,342
	Lighting - Pendent/Surface	1	EA	6	\$124
	Lighting - Pendent/Surface	1	EA	7	\$0
	Walls - Plaster/Drywall	400	SF	6	\$1,104
	Walls - Tile Ceramic/ Porcelain	20	SF	6	\$45
	Water Closet	1	EA	7	\$0
Lunch & Multipu	rpose Room				
·	AC Unit	3	EA	6	\$1,487
	Ceiling - Plaster/Drywall	1,802	SF	7	\$0
	Doors - Wood Doors inclu hw	3	EA	7	\$0
	Floor - Tile/Sheet	740	SF	7	\$0
	Floor - Wood	1,062	SF	7	\$0
	Lighting - Pendent/Surface	34	EA	7	\$0
	Storage/ Closet	106	SF	7	\$0
	Walls - Plaster/Drywall	2,340	SF	7	\$0
MDF_IDF					
	Doors - Steel Doors incl hw	1	EA	7	\$0
	Finishes	90	SF	7	\$0
	Ventilation and Cooling	1	EA	5	\$7,815
Mechanical/ Serv	rice Rooms				
	Air Intake Plenums	4,440	SF	6	\$27,492
	Air Tunnel	2,136	SF	6	\$13,226
	Boiler Room	1,874	SF	6	\$13,426
	Coal Room	388	SF	6	\$2,780
	Mechanical/ Service Rooms	9,354	SF	6	\$67,015
	Storage Room	220	SF	5	\$3,549
	Storage Room	93	SF	6	\$666
	Storage Room	136	SF	7	\$0
Restroom					
	Accessories	23	SF	6	\$212
	Accessories	2,149	SF	7	\$0
	Ceiling - Plaster/Drywall	105	SF	6	\$363
	Ceiling - Plaster/Drywall	2,067	SF	7	\$0

1850 N Newland Ave Chicago, IL 60707

Building: Main

Category: Rooms (Other Than Classrooms)

Group	Item - Type	Quantity	Unit	Rank	Cost
Restroom					
	Doors - Transom Window	54	SF	7	\$0
	Doors - Wood Doors inclu hw	1	EA	5	\$1,174
	Doors - Wood Doors inclu hw	3	EA	6	\$903
	Doors - Wood Doors inclu hw	12	EA	7	\$0
	Floor - Concrete	23	SF	6	\$12
	Floor - Tile Ceramic/ Porcelain	10	SF	5	\$209
	Floor - Tile Ceramic/ Porcelain	1,847	SF	7	\$0
	Floor - Tile/Sheet	23	SF	4	\$222
	Floor - Tile/Sheet	269	SF	7	\$0
	Floor Drain	1	EA	5	\$2,094
	Floor Drain	7	EA	7	\$0
	Lavatory	2	EA	6	\$639
	Lavatory	20	EA	7	\$0
	Lighting - Pendent/Surface	1	EA	6	\$124
	Lighting - Pendent/Surface	31	EA	7	\$0
	Partitions	2	EA	6	\$594
	Partitions	30	EA	7	\$0
	Urinals	2	EA	4	\$15,339
	Urinals	10	EA	7	\$0
	Walls - Masonry	4,399	SF	7	\$0
	Walls - Plaster/Drywall	560	SF	5	\$4,244
	Walls - Plaster/Drywall	140	SF	6	\$386
	Walls - Plaster/Drywall	1,553	SF	7	\$0
	Walls - Structural Glazed Tile	382	SF	7	\$0
	Walls - Tile Ceramic/ Porcelain	449	SF	7	\$0
	Water Closet	36	EA	7	\$0

Rooms (Other Than Classrooms) Subtotal:

\$380,309

Building: Main

Category: Building Interior

Group	Item - Type	Quantity	Unit	Rank	Cost
Corridor	· ·				
	Ceiling - Lay-in	44	SF	7	\$0
	Ceiling - Plaster/Drywall	11,244	SF	7	\$0
	Doors - Wood Doors include hw	8	EA	5	\$9,393
	Doors - Wood Doors include hw	12	EA	6	\$3,612

1850 N Newland Ave Chicago, IL 60707

Building: Main

Category: Building Interior

Group	Item - Type	Quantity	Unit	Rank	Cost	
Corridor						
	Doors - Wood Doors include hw	1	EA	7	\$0	
	Drinking Fountains - Double Fountain	3	EA	7	\$0	
	Drinking Fountains - Single Water Cooler	4	EA	7	\$0	
	Floor - Terrazzo	364	SF	6	\$3,055	
	Floor - Terrazzo	996	SF	7	\$0	
	Floor - Tile/Sheet	9,928	SF	7	\$0	
	Lighting - Lay-in	1	EA	7	\$0	
	Lighting - Pendent/Surface	101	EA	7	\$0	
	Student Lockers - One Tier	549	EA	7	\$0	
	Walls - Masonry	9,112	SF	7	\$0 \$3,489	
	Walls - Plaster/Drywall	787	SF	6		
	Walls - Plaster/Drywall	12,879	SF	7	\$0	
	Walls - Structural Glazed Tile	192	SF	7	\$0	
Stairs						
	Ceiling - Plaster/Drywall	3,280	SF	7	\$0	
	Doors - Wood Doors include hw Drinking Fountains - Double Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Student Lockers - One Tier Walls - Masonry Walls - Plaster/Drywall Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Floor - Terrazzo Handrails Lighting - Pendent/Surface Lighting - Pendent/Surface Lighting - Wall Mounted Stairs - Terrazzo Walls - Masonry Walls - Plaster/Drywall	2,568	SF	7	\$0	
	Handrails	576	LF	7	\$0	
	Lighting - Pendent/Surface	20	EA	6	\$2,478	
	Doors - Wood Doors include hw Drinking Fountains - Double Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Student Lockers - One Tier Walls - Masonry Walls - Plaster/Drywall Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Floor - Terrazzo Handrails Lighting - Pendent/Surface Lighting - Pendent/Surface Lighting - Wall Mounted Stairs - Terrazzo Walls - Masonry Walls - Plaster/Drywall	8	EA	7	\$0	
	Doors - Wood Doors include hw Drinking Fountains - Double Fountain Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Terrazzo Floor - Tile/Sheet Lighting - Lay-in Lighting - Pendent/Surface Student Lockers - One Tier Walls - Masonry Walls - Plaster/Drywall Walls - Plaster/Drywall Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Floor - Terrazzo Handrails Lighting - Pendent/Surface Lighting - Pendent/Surface Lighting - Wall Mounted Stairs - Terrazzo Walls - Masonry Walls - Plaster/Drywall	4	EA	7	\$0	
	Stairs - Terrazzo	1,880	LF	7	\$0	
	Walls - Masonry	10,012	SF	7	\$0	
	Walls - Plaster/Drywall	200	SF	5	\$1,241	
	Walls - Plaster/Drywall	5,408	SF	6	\$14,926	
	Walls - Plaster/Drywall	4,404	SF	7	\$0	
Vertical Conveyance	ee					
	Elevator - Hydraulic Elevator	1	EA	7	\$0	
Building Interio	or Subtotal:				\$38,193	

Total Building Cost \$2,254,859

SITE

Category: Site

Group Item - Type Quantity Unit Rank Cost



1850 N Newland Ave Chicago, IL 60707

\$95,371

SITE

Category: Site

Total Site Cost

Group	Item - Type	Quantity	Unit	Rank	Cost
Civil/Drainage					
	Civil/ Drainage - Catch Basin	5	EA	7	\$0
	Civil/ Drainage - Site Manhole	5	EA	7	\$0
Fencing					
	Fencing - Chain Link	102	LF	6	\$1,915
	Fencing - New Standard Ornamental	1,207	LF	7	\$0
Landscape					
	Landscape - Grass	156,860	SF	7	\$0
	Landscape - Hardscape- Concrete	3,480	SF	7	\$0
	Parkway trees	53	EA	7	\$0
	Planting Beds/ Area	2,955	SF	7	\$0
	Play Area - Asphalt/ Hardscape	25,100	SF	7	\$0
	Retaining Wall - Concrete	462	SF	6	\$10,828
	Trash Receptacles	4	EA	6	\$1,249
Parking Lot					
	Interior Plantings	4	LF	7	\$0
	Surface - Asphalt	2,200	SF	7	\$0
	Surface - Concrete	560	SF	6	\$1,353
	Trash Enclosure - Chain Links	560	SF	6	\$9,826
	Vehicular Screening	100	LF	7	\$0
Playground					
	Equipment - School Age 5-12	1	EA	6	\$3,546
	Surface - Square Rubber Mats	2,325	SF	5	\$23,473
Sidewalks					
	Sidewalks - Internal Walks	10	LF	5	\$578
	Sidewalks - Internal Walks	143	LF	7	\$0
	Sidewalks - Perimeter Sidewalks	20,600	SF	6	\$40,947
Signage					
	Flag Pole - Flag Pole	1	EA	6	\$1,657
	Marquee - Free Standing Back Lighted	1	EA	6	\$0
Site Subtotal:					\$95,371

SAYRE Page 13 of 15 Assessment Date: 9/25/2014



1850 N Newland Ave Chicago, IL 60707

Campus Total ^{2 3} \$2,350,230

- ¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in this report; by the time the report is compiled, they have been resolved.
- ² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.
- ³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.
- Campus Total also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.



1850 N Newland Ave Chicago, IL 60707

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Voice Outlets	Data Outlets	Elect. Outlets	Glazed Window Area	Operable Window Area	Noise Level	Window Stop	Power Strip	Smart- Board
Main	•		•		•	•				•	•			•
Kindergarten	Pre School		104	104	1,563	0	6	16	197	18	40	Υ	N	N
Kindergarten	Kindergarten		111	111	1,093	2	10	28	234	27	40	Υ	N	N
Pre School	Pre School		103	103	802	1	5	6	260	30	40	Υ	N	N
Regular Classroom	Regular Classroom	1st Floor	100	100	728	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		101	101	728	0	8	22	143	15	40	Υ	Υ	N
Regular Classroom	Regular Classroom		106	106	728	1	6	10	143	18	40	Υ	N	N
Regular Classroom	Regular Classroom		200	200	740	0	2	14	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		201	201	740	0	2	14	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		202	202	736	0	2	14	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		203	203	740	0	2	14	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		204	204	650	0	4	12	156	15	40	Υ	N	N
Regular Classroom	Regular Classroom		206	206	740	0	2	14	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		208	208	740	0	2	14	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		210	210	740	0	2	14	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		300	300	740	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		302	302	740	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		304	304	740	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		305	305	740	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		306	306	742	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		307	307	740	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		308	308	740	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		309	309	740	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		310	310	740	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		311	311	740	0	4	12	156	15	40	Υ	N	N
Regular Classroom	Regular Classroom		312	312	740	0	8	22	143	15	40	Υ	N	N
Regular Classroom	Regular Classroom		313	313	740	0	8	22	156	15	40	Υ	N	N
Science Classroom	Science Classroom	1st Floor	108	108	1,088	0	3	11	287	18	40	Υ	Υ	N
Special Program	Regular Classroom		102	102	728	0	8	22	143	15	40	Υ	N	N