

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

- Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- Total Campus Need** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|--|----------------|------|----------|------|----------|-----------|
| Canopy | | Concrete/ Stucco Canopy | entrances | 7 | 608 | SF | \$0 | |
| Canopy | | Concrete/ Stucco Canopy | South Façade | 6 | 108 | SF | \$3,058 | |
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Roof | 6 | 4 | LF | \$2,002 | clay flue |
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Boiler Room | 6 | 51 | LF | \$25,526 | no liner |
| Doors | | Exterior Steel Door | throughout | 6 | 5 | EA | \$1,652 | |
| Doors | | Exterior Steel Door | throughout | 7 | 10 | EA | \$0 | |
| Doors | | Exterior Wood Door | throughout | 7 | 2 | EA | \$0 | |
| Doors | | Exterior Wood Door | throughout | 6 | 6 | EA | \$1,925 | |
| Doors | | Overhead Rolling / Garage Door | East Entrances | 7 | 2 | EA | \$0 | |
| Doors | | Side Lite | throughout | 7 | 11 | EA | \$0 | |
| Doors | | Store Front Door | throughout | 7 | 6 | EA | \$0 | |
| Doors | | Transom Lite | throughout | 7 | 9 | EA | \$0 | |
| Entrance | | Concrete Exterior Stairs | East Entrances | 7 | 90 | LF | \$0 | |
| Entrance | | Entrance Controls - Audio and Video | Main Entrance | 7 | 1 | EA | \$0 | |

Building: Main
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|---|----------------------------------|------|----------|------|------------------|-------------------------------------|
| Entrance | | Stair Handrails | East Entrances | 6 | 20 | LF | \$0 | |
| Foundation | | Concrete Foundation | throughout | 7 | 1,613 | LF | \$0 | |
| Foundation | | Concrete Foundation | North Courtyard | 5 | 3 | LF | \$1,339 | tree growing out of foundation |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | throughout | 6 | 2 | EA | \$1,001 | |
| Lighting | | Exterior Lights - Wall Mounted | throughout | 6 | 29 | EA | \$6,221 | |
| Lintels | | Lintels - Steel | throughout | 6 | 359 | LF | \$13,553 | |
| Parapet | | Coping - Stone | Roofs | 7 | 645 | LF | \$0 | |
| Parapet | | Coping - Stone | W elevation of gymnasium | 6 | 111 | LF | \$0 | |
| Parapet | | Coping - Terra Cotta | Roofs | 7 | 127 | LF | \$0 | |
| Parapet | | Coping - Terra Cotta | gymnasium roofs | 6 | 528 | LF | \$0 | |
| Parapet | | Parapet < 16" Height | gymnasium roof | 7 | 222 | LF | \$0 | |
| Parapet | | Parapet < 16" Height | NE & E elevations | 7 | 127 | LF | \$0 | |
| Parapet | | Parapet > 30" Height | SW elevation | 6 | 45 | LF | \$11,680 | |
| Parapet | | Parapet 16" to 30" Height | Roofs | 7 | 1,017 | LF | \$0 | |
| Roof System | | Exterior Downspouts | Roofs | 7 | 476 | LF | \$0 | |
| Roof System | | Interior Downspouts | Roofs | 7 | 226 | LF | \$0 | |
| Roof System | | Modified Bitumen Roof | Roofs | 5 | 26,579 | SF | \$313,566 | water ponding, soft, worn & bubbles |
| Roof System | | Modified Bitumen Roof | gymnasium roof | 6 | 12,947 | SF | \$91,645 | |
| Roof System | | Roof Structure: Concrete | Roofs | 7 | 21,162 | SF | \$0 | |
| Roof System | | Roof Structure: Steel/Metal Deck/Concrete Topping | gymnasium roof | 7 | 16,684 | SF | \$0 | |
| Superstructure | | Concrete | Entire Building | 7 | 89,361 | SF | \$0 | |
| Walls | | Brick | main entrance - N & S elevations | 5 | 20 | SF | \$453 | |
| Walls | | Brick | S courtyard, 3rd floor | 4 | 4 | SF | \$302 | |
| Walls | | Brick | South Courtyard | 5 | 40 | SF | \$906 | |
| Walls | | Brick | throughout | 6 | 53,466 | SF | \$353,228 | |
| Walls | | Prefabricated Metal Panel Wall | W elevation of gymnasium | 6 | 250 | SF | \$2,124 | |
| Walls | | Stone - Cast | throughout | 6 | 2,800 | SF | \$40,040 | |
| Windows | | Window - Guards perforated | North Façade | 6 | 150 | SF | \$0 | |
| Windows | | Window - Guards perforated | throughout | 7 | 3,775 | SF | \$0 | |
| Windows | | Window - Guards wire guard | door #6 | 6 | 24 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | throughout | 7 | 9,809 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | throughout | 5 | 516 | SF | \$17,820 | balance issues |
| EXTERIOR Sub Total | | | | | | | \$888,040 | |

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------|----------|------|----------|------|------|--------|
|-------|-----------|------|----------|------|----------|------|------|--------|

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------|-----------|--|-------------------|------|----------|------|-----------|--------|
| Emergency System | | Automatic Transfer switch | Boiler Room | 6 | 2 | EA | \$2,860 | |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Entire Building | 6 | 12,054 | SF | \$5,171 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | 1st Floor | 6 | 9,253 | SF | \$4,896 | |
| Emergency System | | Emergency A/C power - Students Toilets | Student Toilets | 6 | 2,545 | SF | \$1,092 | |
| Emergency System | | Emergency generator 60 to 100 KW natural gas - Outdoor | Central Courtyard | 6 | 1 | EA | \$10,511 | |
| Emergency System | | Exit Signs - Auditorium | 1st Floor | 7 | 6 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Entire Building | 7 | 20 | EA | \$0 | |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | 1st Floor | 7 | 8 | EA | \$0 | |
| Emergency System | | Public Announcement System | Entire Building | 6 | 89,361 | SF | \$53,670 | |
| Emergency System | | Security System - Intrusion detection | Entire Building | 7 | 89,361 | SF | \$0 | |
| Emergency System | | UPS 30 KW and below | Basement | 6 | 1 | EA | \$8,580 | |
| Main Service | | Main Electrical service 2000 A 120/208/3PH | Boiler Room | 4 | 1 | EA | \$161,304 | |
| Power Distribution | | Lighting and power panels | Entire Building | 6 | 16 | EA | \$11,440 | |
| Power Distribution | | Main distribution panels 400-600 amp | Boiler Room | 4 | 3 | EA | \$36,465 | |
| Power Distribution | | Main distribution panels less than 400 amp | Boiler Room | 7 | 3 | EA | \$0 | |

ELECTRICAL Sub Total \$295,988

Building: Main
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------|-----------|--------------------------|-----------------|------|----------|------|-----------|--|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 3 | 89,361 | SF | \$189,124 | Strobe lights are not provided or not located in all areas |
| Fire Alarm | | Fire Alarm System | Entire Building | 4 | 89,361 | SF | \$315,632 | |

FIRE PROTECTION Sub Total \$504,756

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|-----------------|------|----------|------|----------|--------|
| Air Conditioning | | Condensing Unit - Ground Mounted less than 5 tons | 1st Floor | 7 | 1 | EA | \$0 | |
| Air Conditioning | | Window A/C Unit | Entire Building | 5 | 43 | EA | \$46,118 | |
| Air Handling Systems | | Air Handling Unit Package - Single Zone - Hot Water 12,001 to 20,000 cfm | Basement | 4 | 1 | EA | \$75,790 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|-----------------|------|----------|------|--------------------|---------------------------------------|
| Air Handling Systems | | Air Handling Unit Package - Single Zone - Hot Water less than 4,000 cfm | Basement | 4 | 1 | EA | \$35,750 | |
| Air Handling Systems | | Air intake for all Air Handling Units except built up AHU | Roof | 5 | 1 | EA | \$5,720 | |
| Air Handling Systems | | Fan Coil Unit - Hot Water-Heating | 3rd Floor | 4 | 1 | EA | \$13,442 | |
| Boiler Systems | | Boiler Assembly - Non-Condensing Scotch Marine Hot Water Boiler 2,001MBH-3,000 MBH | Boiler Room | 4 | 2 | EA | \$331,760 | |
| Boiler Systems | | Boiler Auxiliary Non-Condensing Hot Water Boiler 2,001MBH-3,000 MBH | Boiler Room | 4 | 2 | EA | \$111,540 | |
| Boiler Systems | | Combustion Dampers | Boiler Room | 6 | 2 | EA | \$572 | |
| Boiler Systems | | Gas Boosters | Basement | 6 | 1 | EA | \$1,301 | |
| Heating Devices | | Fin Tube Hot Water | Entire Building | 5 | 200 | LF | \$17,160 | |
| Heating Devices | | Radiators - Hot Water | Entire Building | 4 | 217 | EA | \$273,073 | |
| Mechanical Plumbing | | Piping - Hydronic Supply and Return - Steel or Galvanized | Entire Building | 5 | 1,200 | LF | \$59,374 | |
| Mechanical Plumbing | | Pumps - Hot Water 11 to 20 HP | Boiler Room | 4 | 1 | EA | \$26,813 | |
| Temperature Control | | Pneumatic System | Entire Building | 4 | 89,361 | SF | \$638,931 | |
| Temperature Control | | Thermostats - Pneumatic | Entire Building | 4 | 11 | EA | \$7,236 | |
| Ventilation | | Exhaust Fan - Indoor | Gym - 1st Floor | 4 | 2 | EA | \$11,154 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 6 | 1 | EA | \$229 | |
| Ventilation | | Lab Exhaust Hood | 307 | 4 | 1 | EA | \$32,890 | |
| Ventilation | | Type II Exhaust Hood - Warming Kitchen | 1st Floor | 3 | 1 | EA | \$6,149 | equipment is located outside the hood |
| MECHANICAL Sub Total | | | | | | | \$1,695,000 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------|-----------|--|-----------------|------|----------|------|-----------|--------|
| Hot Water | | Hot Water Heater - Gas 150,000 -300,000 BTU/HR | Boiler Room | 6 | 1 | EA | \$4,147 | |
| Hot Water | | Storage Tank less than 500 gallons | Boiler Room | 4 | 2 | EA | \$29,744 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 4 | 89,361 | SF | \$29,391 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 4 | 89,361 | SF | \$57,504 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 4 | 89,361 | SF | \$19,168 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 4 | 89,361 | SF | \$40,892 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 4 | 89,361 | SF | \$48,559 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 4 | 89,361 | SF | \$213,403 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 4 | 89,361 | SF | \$176,345 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 4 | 89,361 | SF | \$102,229 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-------------------------------|-----------------|------|----------|------|------------------|--------|
| Piping | | Sanitary Piping | Entire Building | 5 | 89,361 | SF | \$54,948 | |
| Piping | | Storm Piping | Entire Building | 5 | 89,361 | SF | \$42,169 | |
| Piping | | Vent Piping | Entire Building | 5 | 89,361 | SF | \$31,947 | |
| Pumps | | Domestic Booster Pump simplex | Boiler Room | 5 | 1 | EA | \$8,580 | |
| Pumps | | Sump Pump | Basement | 4 | 2 | EA | \$23,738 | |
| PLUMBING Sub Total | | | | | | | \$882,763 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|---------------------------|-------------------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Exposed | Kitchen Manager's Office | 7 | 146 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 202 | 6 | 237 | SF | \$671 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Main Office | 7 | 216 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Principal's Office | 6 | 175 | SF | \$495 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 100 | 7 | 437 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Main Office Waiting Room | 7 | 107 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 216 | 6 | 178 | SF | \$504 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 101 | 7 | 720 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 300, Counselor's Office | 6 | 249 | SF | \$705 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Gym Teacher's Office | 6 | 87 | SF | \$246 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 109, Nurse's Office | 7 | 168 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 117, Counselor's Office | 6 | 458 | SF | \$1,297 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 206, Conference Room | 6 | 1,272 | SF | \$3,602 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 2nd Floor | 7 | 162 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 205 Parent Patrol Office | 7 | 223 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Engineer's Office | 6 | 202 | SF | \$572 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|-----------------------------------|-------------------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Maintenance Lounge | 6 | 281 | SF | \$796 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Room 300, Counselor's Office | 7 | 249 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Room 216 | 6 | 178 | SF | \$255 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Room 202 | 7 | 237 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Room 205 Parent Patrol Office | 7 | 223 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | 2nd Floor | 7 | 162 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Engineer's Office | 6 | 202 | SF | \$289 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Room 101 | 6 | 720 | SF | \$1,030 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Principal's Office | 7 | 175 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Main Office | 7 | 216 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Room 206, Conference Room | 7 | 1,272 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile Ceramic/Porcelain | Room 117, Counselor's Office | 7 | 458 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 100 | 6 | 437 | SF | \$625 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 109, Nurse's Office | 7 | 168 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Gym Teacher's Office | 6 | 87 | SF | \$124 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Maintenance Lounge | 6 | 281 | SF | \$402 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Kitchen Manager's Office | 6 | 146 | SF | \$209 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Main Office Waiting Room | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Principal's Office | 7 | 4 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Main Office | 7 | 4 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 109, Nurse's Office | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 101 | 7 | 16 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|----------------------------|-------------------------------|------|----------|------|-------|--------|
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 117, Counselor's Office | 7 | 10 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Gym Teacher's Office | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Kitchen Manager's Office | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Engineer's Office | 7 | 3 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 100 | 7 | 10 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Maintenance Lounge | 7 | 3 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 206, Conference Room | 7 | 19 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 2nd Floor | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 205 Parent Patrol Office | 7 | 3 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 202 | 7 | 4 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 300, Counselor's Office | 6 | 3 | SF | \$2 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 216 | 7 | 3 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Main Office Waiting Room | 7 | 307 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Main Office | 7 | 380 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Room 101 | 7 | 1,100 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Kitchen Manager's Office | 7 | 619 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Room 202 | 7 | 646 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Room 100 | 7 | 200 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 2nd Floor | 7 | 358 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Principal's Office | 7 | 428 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 216 | 6 | 400 | SF | \$944 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 205 Parent Patrol Office | 7 | 418 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------------|-------------------------------|--------------------------------|------------------------------|------|----------|------|----------|--------|
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Engineer's Office | 6 | 459 | SF | \$1,083 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 109, Nurse's Office | 7 | 562 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 117, Counselor's Office | 6 | 866 | SF | \$2,043 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Structural Glazed Tile | Gym Teacher's Office | 7 | 315 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Structural Glazed Tile | Maintenance Lounge | 7 | 525 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Structural Glazed Tile | Room 100 | 7 | 600 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Structural Glazed Tile | Room 300, Counselor's Office | 7 | 756 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Structural Glazed Tile | Room 206, Conference Room | 7 | 1,430 | SF | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Main Floor Seating | 1st Floor | 7 | 200 | EA | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Sound System | 1st Floor | 7 | 1 | EA | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Stage Curtains | 1st Floor | 7 | 2 | EA | \$0 | |
| Choral Room | Classroom | Risers | | 7 | 216 | LF | \$0 | |
| Doors | | Interior Steel Doors incl hw | throughout | 6 | 4 | EA | \$1,133 | |
| Doors | | Interior Wood Doors incl hw | throughout | 7 | 88 | EA | \$0 | |
| Doors | | Interior Wood Doors incl hw | throughout | 7 | 4 | EA | \$0 | |
| Doors | | Interior Wood Doors incl hw | throughout | 6 | 88 | EA | \$24,916 | |
| Doors | | Side-lite | throughout | 7 | 27 | SF | \$0 | |
| Doors | | Transom Window | throughout | 7 | 11 | SF | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 1st Floor | 7 | 2 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 2nd Floor | 7 | 2 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 3rd Floor | 7 | 2 | EA | \$0 | |
| GreenHouse | | Finishes | In Room 210 | 6 | 200 | SF | \$0 | |
| GreenHouse | | Glazing | In Room 210 | 6 | 280 | SF | \$4,637 | |
| Gymnasium / Auditorium | Competition Gymnasium | Bleacher Seating | 1st Floor | 7 | 770 | EA | \$0 | |
| Gymnasium / Auditorium | Competition Gymnasium | Ceiling - Splined | 1st Floor | 6 | 9,253 | SF | \$86,007 | |
| Gymnasium / Auditorium | Competition Gymnasium | Flooring - Wood | 1st Floor | 6 | 9,253 | SF | \$69,864 | |
| Gymnasium / Auditorium | Competition Gymnasium | Lighting - Pendant/Surface | 1st Floor | 7 | 24 | EA | \$0 | |
| Gymnasium / Auditorium | Competition Gymnasium | Scoreboards | 1st Floor | 7 | 1 | EA | \$0 | |
| Gymnasium / Auditorium | Competition Gymnasium | Sound System | 1st Floor | 7 | 1 | EA | \$0 | |
| Gymnasium / Auditorium | Competition Gymnasium | Walls - Concrete Block | 1st Floor | 7 | 13,332 | SF | \$0 | |
| Kitchen | Warming Kitchen | Ceiling - Splined | 1st Floor | 6 | 791 | SF | \$2,262 | |
| Kitchen | Warming Kitchen | Flooring - Tile/Sheet | 1st Floor | 6 | 791 | SF | \$1,131 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|-----------------|-------------------------------|----------------------------|------|----------|------|---------|--------|
| Kitchen | Warming Kitchen | Lighting - Pendant/Surface | 1st Floor | 7 | 9 | SF | \$0 | |
| Kitchen | Warming Kitchen | Wall - Structural Glazed Tile | 1st Floor | 7 | 1,223 | SF | \$0 | |
| Library | Library | Flooring Tile/ Sheet | Room 106 | 6 | 1,135 | SF | \$1,623 | |
| Library | Library | Lighting - Pendant/ Surface | Room 106 | 7 | 16 | SF | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | In the Kitchen Area | 6 | 2 | EA | \$98 | |
| Locker/Shower Room | Staff Restroom | Showers | 3rd Floor Women's Room | 6 | 7 | EA | \$1,702 | |
| Locker/Shower Room | Staff Restroom | Showers | In Room 216 | 7 | 1 | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | In the Kitchen Area | 6 | 2 | EA | \$486 | |
| Locker/Shower Room | Staff Restroom | Showers | In Gym Teacher's Office | 7 | 1 | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 2nd Floor | 7 | 1 | EA | \$0 | |
| Lunchroom | Lunchroom | Ceiling - Splined | Former Stage Platform Area | 6 | 2,225 | SF | \$4,773 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Former Stage Platform Area | 7 | 2,225 | SF | \$0 | |
| Lunchroom | Lunchroom | Lighting - Pendant/Surface | Former Stage Platform Area | 7 | 18 | SF | \$0 | |
| Lunchroom | Lunchroom | Serving Line | Former Stage Platform Area | 7 | 24 | LF | \$0 | |
| Lunchroom | Lunchroom | Wall - Concrete Block | Former Stage Platform Area | 7 | 1,794 | SF | \$0 | |
| Lunchroom | Lunchroom | Wall - Structural Glazed Tile | Former Stage Platform Area | 7 | 598 | SF | \$0 | |
| MDF/IDF | | Finishes | 2nd Floor | 7 | 96 | SF | \$0 | |
| MDF/IDF | | Ventilation and Cooling | 2nd Floor | 7 | 1 | EA | \$0 | |
| Mechanical/Service Rooms | | Air Tunnels | Basement | 7 | 440 | SF | \$0 | |
| Mechanical/Service Rooms | | Boiler Room | Basement | 7 | 828 | SF | \$0 | |
| Mechanical/Service Rooms | | Janitor's Closet | In Kitchen | 7 | 1 | SF | \$0 | |
| Mechanical/Service Rooms | | Janitor's Closet | Entire Building | 7 | 3 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 1st Floor | 7 | 148 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement | 7 | 57 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement | 7 | 721 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement | 7 | 110 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | In Room 101 | 7 | 30 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Room 220 | 6 | 656 | SF | \$3,096 | |
| Mechanical/Service Rooms | | Storage Room | Room 112 | 6 | 278 | SF | \$1,312 | |
| Mechanical/Service Rooms | | Storage Room | Room 201 | 7 | 120 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | 2nd Floor | 7 | 42 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | 3rd Floor East Cells | 6 | 1,865 | SF | \$8,801 | |
| Mechanical/Service Rooms | | Storage Room | 3rd Floor East | 7 | 130 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | 3rd Floor East Cells | 5 | 420 | SF | \$4,757 | |
| Mechanical/Service Rooms | | Storage Room | In Gym | 7 | 178 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | In Room 100 | 7 | 60 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Basement | 7 | 242 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------------------------|--------------|--------------------------------------|------|----------|------|---------|--------|
| Mechanical/Service Rooms | | Storage Room | In the Gym | 7 | 449 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | In the Lobby of the Gym | 7 | 181 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | In Room 217 (Chapel) | 6 | 100 | SF | \$472 | |
| Mechanical/Service Rooms | | Storage Room | In Room 106 Library | 7 | 50 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Basement | 7 | 910 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Next to Room 215 (Community Room) | 7 | 45 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Office next to Chapel | 6 | 130 | SF | \$613 | |
| Mechanical/Service Rooms | | Storage Room | In Room 217 | 7 | 50 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Room 215 | 6 | 685 | SF | \$3,233 | |
| Mechanical/Service Rooms | | Storage Room | 3rd Floor Art Storage | 7 | 70 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | In Room 308 | 6 | 310 | SF | \$1,463 | |
| Mechanical/Service Rooms | | Storage Room | Room 219 Art Supply Room | 7 | 132 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd Floor Men's Room | 7 | 84 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | In the Main Office | 6 | 31 | SF | \$239 | |
| Staff Restroom | Staff Restroom | Accessories | In the Engineer's Office | 6 | 44 | SF | \$340 | |
| Staff Restroom | Staff Restroom | Accessories | In the Kitchen Area | 6 | 458 | SF | \$3,537 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Boy's Room Next to the Gym | 6 | 82 | SF | \$633 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Girl's Room next to Lunchroom | 6 | 82 | SF | \$633 | |
| Staff Restroom | Staff Restroom | Accessories | In Gym Teacher's Office | 6 | 42 | SF | \$324 | |
| Staff Restroom | Staff Restroom | Accessories | In Room 216 | 7 | 50 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd Floor Boy's Room | 6 | 339 | SF | \$2,618 | |
| Staff Restroom | Staff Restroom | Accessories | Basement | 6 | 64 | SF | \$494 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 3rd Floor Boy's Room | 6 | 339 | SF | \$2,618 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 1st Floor Boy's Room | 6 | 339 | SF | \$2,618 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 3rd Floor Girl's Room | 6 | 329 | SF | \$2,541 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd Floor Girl's Room | 6 | 329 | SF | \$2,541 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 1st Floor Girl's Room | 6 | 329 | SF | \$2,541 | |
| Staff Restroom | Staff Restroom | Accessories | In Room 300 | 7 | 84 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 3rd Floor Women's Room | 6 | 586 | SF | \$4,525 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd Floor | 6 | 37 | SF | \$286 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|---------------------------|-------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Accessories | Boy's Room In Gym | 6 | 204 | SF | \$1,575 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Girl's Room in Gym | 6 | 203 | SF | \$1,568 | |
| Staff Restroom | Staff Restroom | Ceiling - Exposed | Basement | 6 | 64 | SF | \$121 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Gym Teacher's Office | 6 | 42 | SF | \$119 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Room 300 | 7 | 84 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 3rd Floor Boy's Room | 6 | 339 | SF | \$960 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Girl's Room | 6 | 329 | SF | \$932 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Boy's Room | 6 | 339 | SF | \$960 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 1st Floor Boy's Room | 6 | 339 | SF | \$960 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 3rd Floor Girl's Room | 6 | 329 | SF | \$932 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 1st Floor Girl's Room | 6 | 329 | SF | \$932 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 3rd Floor Women's Room | 6 | 586 | SF | \$1,659 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd Floor | 7 | 37 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Boy's Room In Gym | 6 | 204 | SF | \$578 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In the Main Office | 6 | 31 | SF | \$88 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Girl's Room next to Lunchroom | 6 | 82 | SF | \$232 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Boy's Room Next to the Gym | 6 | 82 | SF | \$232 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In the Kitchen Area | 6 | 458 | SF | \$1,297 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In the Engineer's Office | 6 | 44 | SF | \$125 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd Floor Men's Room | 7 | 84 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Room 216 | 7 | 50 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Girl's Room in Gym | 6 | 203 | SF | \$575 | |
| Staff Restroom | Staff Restroom | Floor Drain | In the Kitchen Area | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 3rd Floor Women's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | In Gym Teacher's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | Basement | 6 | 64 | SF | \$302 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Terrazzo | Boy's Room Next to the Gym | 6 | 82 | SF | \$464 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|-------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Flooring - Terrazzo | Girl's Room next to Lunchroom | 7 | 82 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Terrazzo | In Gym Teacher's Office | 6 | 42 | SF | \$238 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Terrazzo | Boy's Room In Gym | 6 | 204 | SF | \$1,155 | |
| Staff Restroom | Staff Restroom | Flooring - Terrazzo | In the Kitchen Area | 6 | 458 | SF | \$2,594 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Terrazzo | Girl's Room in Gym | 6 | 203 | SF | \$1,150 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 3rd Floor Women's Room | 6 | 586 | SF | \$1,492 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 3rd Floor Girl's Room | 7 | 329 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor | 7 | 37 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | In the Engineer's Office | 7 | 44 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor Men's Room | 7 | 84 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | In Room 300 | 7 | 84 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 1st Floor Girl's Room | 7 | 329 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor Girl's Room | 7 | 329 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 1st Floor Boy's Room | 7 | 339 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | In Room 216 | 6 | 50 | SF | \$127 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 3rd Floor Boy's Room | 7 | 339 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor Boy's Room | 7 | 339 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | In the Main Office | 7 | 31 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Boy's Room Next to the Gym | 6 | 1 | EA | \$217 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Girl's Room next to Lunchroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 1st Floor Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 3rd Floor Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 2nd Floor Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In the Kitchen Area | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 2nd Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 3rd Floor Boy's Room | 7 | 2 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------|-------------------------------|------|----------|------|------|--------|
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 1st Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 1st Floor Girl's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 3rd Floor Girl's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd Floor Girl's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 2nd Floor Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 3rd Floor Women's Room | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Room 216 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Boy's Room In Gym | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Girl's Room in Gym | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In the Main Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Gym Teacher's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Girl's Room next to Lunchroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Boy's Room Next to the Gym | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In the Engineer's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Room 300 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In the Main Office | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 2nd Floor | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Girl's Room next to Lunchroom | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 2nd Floor Men's Room | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In the Engineer's Office | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In the Kitchen Area | 7 | 6 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Boy's Room Next to the Gym | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In Gym Teacher's Office | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Basement | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Boy's Room In Gym | 7 | 3 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In Room 216 | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 3rd Floor Women's Room | 7 | 8 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------|-------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In Room 300 | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 1st Floor Girl's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Girl's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 3rd Floor Girl's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 1st Floor Boy's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Boy's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 3rd Floor Boy's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Girl's Room in Gym | 7 | 3 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | In Room 216 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 3rd Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 2nd Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 2nd Floor Men's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | In the Kitchen Area | 6 | 5 | EA | \$897 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Girl's Room next to Lunchroom | 6 | 2 | EA | \$359 | |
| Staff Restroom | Staff Restroom | Partitions | Basement | 6 | 1 | EA | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Girl's Room in Gym | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Boy's Room In Gym | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 3rd Floor Women's Room | 6 | 7 | EA | \$1,255 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 3rd Floor Girl's Room | 6 | 5 | EA | \$897 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 1st Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | In Room 300 | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd Floor Girl's Room | 6 | 5 | EA | \$897 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 1st Floor Girl's Room | 6 | 5 | EA | \$897 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Boy's Room Next to the Gym | 7 | 1 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|--------------------------------|-------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Urinals | Boy's Room In Gym | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 3rd Floor Boy's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 1st Floor Boy's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 2nd Floor Boy's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | Basement | 6 | 449 | SF | \$1,284 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | In the Main Office | 7 | 164 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In Room 216 | 6 | 200 | SF | \$472 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 2nd Floor | 6 | 101 | SF | \$238 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 3rd Floor Women's Room | 7 | 512 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Girl's Room | 7 | 756 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 3rd Floor Girl's Room | 7 | 756 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | In the Kitchen Area | 7 | 842 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | In the Engineer's Office | 7 | 235 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 2nd Floor Men's Room | 7 | 368 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Girl's Room next to Lunchroom | 7 | 365 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 1st Floor Boy's Room | 7 | 738 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 3rd Floor Boy's Room | 7 | 738 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Boy's Room | 7 | 738 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Boy's Room Next to the Gym | 7 | 279 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Boy's Room In Gym | 7 | 733 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | In Room 300 | 7 | 368 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | In Gym Teacher's Office | 7 | 182 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Girl's Room in Gym | 7 | 451 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 1st Floor Girl's Room | 7 | 756 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 2nd Floor | 7 | 102 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 3rd Floor Women's Room | 7 | 512 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | In Room 216 | 6 | 100 | SF | \$255 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|--------------------------------------|-------------------------------|-------------------------------|------|----------|------|------------------|--------|
| Staff Restroom | Staff Restroom | Water Closet | In the Main Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 1st Floor Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 3rd Floor Girl's Room | 7 | 6 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In Room 216 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In the Engineer's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd Floor Men's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In the Kitchen Area | 6 | 6 | EA | \$2,231 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Boy's Room Next to the Gym | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd Floor Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In Gym Teacher's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 3rd Floor Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Girl's Room in Gym | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Boy's Room In Gym | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 3rd Floor Women's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In Room 300 | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 1st Floor Girl's Room | 7 | 6 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Girl's Room next to Lunchroom | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd Floor Girl's Room | 7 | 6 | EA | \$0 | |
| Theater | Auditorium - Dedicated | Ceiling - Plaster/Drywall | 1st Floor | 6 | 1,245 | SF | \$10,646 | |
| Theater | Auditorium - Dedicated | Flooring - Tile/Sheet | 1st Floor | 7 | 1,245 | SF | \$0 | |
| Theater | Auditorium - Dedicated | Lighting - Pendant/ Surface | 1st Floor | 7 | 32 | SF | \$0 | |
| Theater | Auditorium - Dedicated | Wall - Concrete Block | 1st Floor | 7 | 434 | SF | \$0 | |
| Theater | Auditorium - Dedicated | Wall - Structural Glazed Tile | 1st Floor | 7 | 1,302 | SF | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 3 | EA | \$1,158 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 3 | EA | \$0 | |
| INTERIOR Sub Total | | | | | | | \$308,718 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------|----------|------|----------|------|------|--------|
|-------|-----------|------|----------|------|----------|------|------|--------|

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-------------------------------|-----------------------------|--------------------------|------|----------|------|---------|--------|
| ADMIN_FLOOR | Administrative Suites/Offices | Administrative Office Floor | Main Office Waiting Room | 7 | 107 | SF | \$0 | |
| Casework | Classroom | Casework | | 7 | 32 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 50 | LF | \$1,788 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 7 | 32 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 32 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 7 | 32 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 40 | LF | \$1,430 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 7 | 32 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 7 | 32 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 7 | 32 | LF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 755 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 625 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 625 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 570 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 625 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 570 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 625 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 400 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Ceiling | Classroom | Plaster/Drywall | | 6 | 186 | SF | \$527 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 825 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 625 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 908 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 945 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 710 | SF | \$2,010 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 340 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 780 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 710 | SF | \$2,010 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,150 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 685 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 845 | SF | \$1,813 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 625 | SF | \$1,341 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 680 | SF | \$1,459 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 680 | SF | \$1,459 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 945 | SF | \$2,027 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 811 | SF | \$1,740 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 625 | SF | \$1,341 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 780 | SF | \$1,673 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 717 | SF | \$1,538 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 744 | SF | \$1,596 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 785 | SF | \$1,684 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 4 | LF | \$486 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|------------------------|-----------|------|----------|------|----------|--------|
| Chalk Board | Classroom | Chalk Board | | 4 | 5 | LF | \$608 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 8 | LF | \$972 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 8 | LF | \$972 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| CLASSROOM | Classroom | Science Lab Elements | | 7 | 845 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | 1st Floor | 7 | 788 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | 2nd Floor | 7 | 784 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | 2nd Floor | 7 | 788 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | 1st Floor | 7 | 784 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | 3rd Floor | 7 | 784 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | 3rd Floor | 7 | 788 | SF | \$0 | |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 7 | 18 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 1st Floor | 7 | 18 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 3rd Floor | 7 | 18 | EA | \$0 | |
| Corridors | Corridors | Plaster/Drywall | 3rd Floor | 7 | 881 | SF | \$0 | |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 7 | 881 | SF | \$0 | |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 7 | 881 | SF | \$0 | |
| Corridors | Corridors | Stair Handrails | 2nd Floor | 7 | 228 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | 1st Floor | 7 | 114 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | 3rd Floor | 7 | 228 | LF | \$0 | |
| Corridors | Corridors | Stairs | 1st Floor | 7 | 84 | EA | \$0 | |
| Corridors | Corridors | Structural Glazed Tile | 3rd Floor | 7 | 2,353 | SF | \$0 | |
| Corridors | Corridors | Structural Glazed Tile | 2nd Floor | 7 | 2,353 | SF | \$0 | |
| Corridors | Corridors | Structural Glazed Tile | 1st Floor | 7 | 2,353 | SF | \$0 | |
| Corridors | Corridors | Student Lockers | 2nd Floor | 6 | 217 | EA | \$31,031 | |
| Corridors | Corridors | Student Lockers | 3rd Floor | 6 | 217 | EA | \$31,031 | |
| Corridors | Corridors | Student Lockers | 1st Floor | 6 | 175 | EA | \$25,025 | |
| Corridors | Corridors | Terrazzo | 1st Floor | 6 | 4,018 | SF | \$22,753 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|------------------------|-----------|------|----------|------|----------|--------|
| Corridors | Corridors | Tile Ceramic/Porcelain | 2nd Floor | 6 | 4,018 | SF | \$10,227 | |
| Corridors | Corridors | Tile Ceramic/Porcelain | 3rd Floor | 6 | 4,018 | SF | \$10,227 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 1st Floor | 6 | 4,018 | SF | \$11,377 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 3rd Floor | 6 | 4,018 | SF | \$11,377 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 2nd Floor | 6 | 4,018 | SF | \$11,377 | |
| Stairs | Corridors | Asphalt | 2nd Floor | 7 | 118 | SF | \$0 | |
| Stairs | Corridors | Asphalt | 1st Floor | 7 | 118 | SF | \$0 | |
| Stairs | Corridors | Asphalt | 3rd Floor | 7 | 118 | SF | \$0 | |
| Stairs | Corridors | Terrazzo | 2nd Floor | 7 | 168 | SF | \$0 | |
| Stairs | Corridors | Terrazzo | 3rd Floor | 7 | 168 | SF | \$0 | |
| Floor | Classroom | Carpet | | 7 | 625 | SF | \$0 | |
| Floor | Classroom | Carpet | | 6 | 1,150 | SF | \$1,645 | |
| Floor | Classroom | Carpet | | 6 | 570 | SF | \$815 | |
| Floor | Classroom | Carpet | | 6 | 400 | SF | \$572 | |
| Floor | Classroom | Carpet | | 7 | 186 | SF | \$0 | |
| Floor | Classroom | Carpet | | 6 | 680 | SF | \$972 | |
| Floor | Classroom | Carpet | | 7 | 755 | SF | \$0 | |
| Floor | Classroom | Carpet | | 7 | 340 | SF | \$0 | |
| Floor | Classroom | Carpet | | 6 | 710 | SF | \$1,015 | |
| Floor | Classroom | Carpet | | 6 | 710 | SF | \$1,015 | |
| Floor | Classroom | Carpet | | 6 | 680 | SF | \$972 | |
| Floor | Classroom | Concrete | | 7 | 845 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 570 | SF | \$815 | |
| Floor | Classroom | Tile/Sheet | | 6 | 680 | SF | \$972 | |
| Floor | Classroom | Tile/Sheet | | 6 | 680 | SF | \$972 | |
| Floor | Classroom | Tile/Sheet | | 7 | 625 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 625 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 685 | SF | \$980 | |
| Floor | Classroom | Tile/Sheet | | 6 | 625 | SF | \$894 | |
| Floor | Classroom | Tile/Sheet | | 6 | 945 | SF | \$1,351 | |
| Floor | Classroom | Tile/Sheet | | 6 | 715 | SF | \$1,022 | |
| Floor | Classroom | Tile/Sheet | | 7 | 625 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 780 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 908 | SF | \$1,298 | |
| Floor | Classroom | Tile/Sheet | | 6 | 825 | SF | \$1,180 | |
| Floor | Classroom | Tile/Sheet | | 7 | 744 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 625 | SF | \$894 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Floor | Classroom | Tile/Sheet | | 6 | 717 | SF | \$1,025 | |
| Floor | Classroom | Tile/Sheet | | 6 | 780 | SF | \$1,115 | |
| Floor | Classroom | Tile/Sheet | | 6 | 625 | SF | \$894 | |
| Floor | Classroom | Tile/Sheet | | 6 | 811 | SF | \$1,160 | |
| Floor | Classroom | Tile/Sheet | | 6 | 945 | SF | \$1,351 | |
| Floor | Classroom | Tile/Sheet | | 6 | 785 | SF | \$1,123 | |
| LIBRARY_CEILING | Library | Plaster/Drywall | Room 106 | 7 | 1,135 | SF | \$0 | |
| LIBRARY_WALL | Library | Concrete Block | Room 106 | 7 | 1,570 | SF | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 25 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 12 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 24 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 16 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 12 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 12 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 12 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 16 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 12 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 12 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 3 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 16 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|-----------------|----------|------|----------|------|------|--------|
| Lighting | Classroom | Pendant/Surface | | 7 | 12 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 2 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 16 | EA | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 4 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 4 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 4 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 16 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 6 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 150 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 170 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 300 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 160 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 150 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 250 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 170 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 150 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 200 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 150 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 150 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 170 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 150 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 170 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 150 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 283 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 291 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 1,225 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 269 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 271 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 160 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------------------------|----------|------|----------|------|---------|--------|
| Wall | Classroom | Concrete Block | | 7 | 283 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 150 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 150 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 160 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 160 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 160 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 160 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 271 | SF | \$0 | |
| Wall | Classroom | Masonry | | 7 | 450 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,000 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 400 | SF | \$944 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 630 | SF | \$1,486 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 520 | SF | \$1,227 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 600 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 760 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 760 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 700 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 810 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 810 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 700 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 700 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 808 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 680 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 700 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 700 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 700 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 700 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 850 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 813 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 900 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 865 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 810 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 828 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 850 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 819 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 700 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 920 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 810 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|------------------------|----------|------|----------|------|------------------|--------|
| Wall | Classroom | Structural Glazed Tile | | 7 | 810 | SF | \$0 | |
| Wall | Classroom | Structural Glazed Tile | | 7 | 874 | SF | \$0 | |
| ROOM Sub Total | | | | | | | \$309,168 | |

Building Main Sub Total \$4,884,433

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|---|---------------------------|------|----------|------|----------|--------------------------|
| Civil/Drainage | | Catch Basin | S site | 7 | 1 | EA | \$0 | |
| Civil/Drainage | | Site Drain | North Courtyard | 7 | 1 | EA | \$0 | |
| Civil/Drainage | | Site Drain | middle courtyard | 6 | 2 | EA | \$223 | |
| Civil/Drainage | | Site Manhole | throughout site | 7 | 3 | EA | \$0 | |
| Fencing | | Chain Link | throughout site | 6 | 473 | LF | \$6,784 | |
| Fencing | | Ornamental Iron | S & SW site | 7 | 280 | LF | \$0 | |
| Fencing | | Wood Fencing w/ Steel Frame | SE site | 6 | 204 | LF | \$2,503 | |
| Landscape | | Asphalt Play Area/Hardscape | S site | 6 | 11,318 | SF | \$9,711 | |
| Landscape | | Benches | middle courtyard | 7 | 1 | EA | \$0 | |
| Landscape | | Grass | throughout site | 6 | 12,271 | SF | \$4,913 | |
| Landscape | | Hardscape - Concrete | middle courtyard | 4 | 1,338 | SF | \$25,256 | holes/cracks/poor pitch |
| Landscape | | Hardscape - Concrete | North Courtyard | 4 | 1,057 | SF | \$19,952 | cracks/movement/drainage |
| Landscape | | Hardscape - Concrete | entrances | 7 | 2,335 | SF | \$0 | |
| Landscape | | Parkway trees | throughout site perimeter | 7 | 20 | EA | \$0 | |
| Landscape | | Planting Beds/ Areas | throughout site | 6 | 3,467 | SF | \$0 | |
| Landscape | | Retaining Wall - Concrete | throughout site | 7 | 280 | SF | \$0 | |
| Landscape | | Trash Receptacles | throughout site | 7 | 3 | EA | \$0 | |
| Parking Lot | | Asphalt | S site | 6 | 10,296 | SF | \$8,834 | |
| Parking Lot | | Lights, Pole Mounted | SE site | 7 | 1 | EA | \$0 | |
| Parking Lot | | Trash Compactor | SE site | 6 | 1 | EA | \$3,575 | |
| Parking Lot | | Trash Enclosure | SE site | 6 | 716 | SF | \$7,679 | |
| Parking Lot | | Vehicular Screening | S & SW site | 6 | 290 | LF | \$0 | |
| Sidewalks | | Internal Walks | S site | 7 | 50 | LF | \$0 | |
| Sidewalks | | Perimeter Sidewalks | throughout site perimeter | 6 | 15,687 | SF | \$29,611 | |
| Signage | | Flag Pole | Main Entrance | 7 | 1 | EA | \$0 | |
| Signage | | Marquee - Building Mounted Back Lighted | NW site | 7 | 1 | EA | \$0 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---|-----------|------|----------|------|----------|------|-----------------------|------------------|
| | | | | | | | SITE Sub Total | \$119,041 |
| | | | | | | | SITE Sub Total | \$119,041 |
| Total Campus Need ^{2 3} | | | | | | | \$5,003,474 | |

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-----------------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|---------------|----------|
| Building: Main | | | | | | | | | | | | | | |
| 102 | 570 | 1 | 0 | 4 | 40 | 88 | 44 | 1 | N | N | Y | Classroom | | |
| 103 | 1150 | 1 | 0 | 4 | 40 | 176 | 88 | 1 | N | N | Y | Classroom | | |
| 104 | 625 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 105 | 625 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 107 | 570 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 108 | 625 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 200 | 625 | 1 | 13 | 30 | 40 | 132 | 66 | 2 | N | N | Y | Classroom | | |
| 204 | 755 | 1 | 0 | 6 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 207 | 625 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 208 | 680 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 209 | 680 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 210 | 945 | 1 | 0 | 4 | 40 | 198 | 66 | 1 | N | Y | Y | Classroom | | |
| 211 | 710 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 212 | 825 | 1 | 0 | 6 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 213 | 710 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 214 | 908 | 1 | 0 | 6 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 217 | 685 | 1 | 0 | 4 | 40 | 110 | 55 | 1 | N | N | Y | Classroom | | |
| 218 | 400 | 1 | 0 | 4 | 40 | 66 | 33 | 1 | N | N | Y | Classroom | | |
| 220 | 780 | 1 | 0 | 8 | 40 | 66 | 33 | 1 | N | N | N | Classroom | | |
| 221 | 186 | 1 | 0 | 4 | 40 | 66 | 33 | 1 | N | N | Y | Classroom | | |
| 301 | 625 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 302 | 785 | 1 | 0 | 12 | 40 | 176 | 88 | 1 | N | N | Y | Classroom | | |
| 303 | 717 | 1 | 0 | 12 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 304 | 780 | 1 | 0 | 8 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 305 | 680 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 306 | 680 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | Y | Y | Classroom | | |
| 307 | 744 | 1 | 0 | 12 | 40 | 132 | 66 | 1 | N | Y | Y | Classroom | | |
| 307B | 845 | 1 | 0 | 6 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 308 | 945 | 1 | 0 | 4 | 40 | 198 | 66 | 2 | N | Y | Y | Classroom | | |
| 309 | 811 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | Y | Classroom | | |
| 310 | 625 | 1 | 0 | 4 | 40 | 132 | 66 | 1 | N | N | N | Classroom | | |
| 316 | 340 | 0 | 0 | 4 | 40 | 66 | 33 | 0 | N | N | Y | Classroom | | |
| Art Studio | 715 | 0 | 0 | 4 | 40 | 132 | 66 | 0 | N | N | Y | Classroom | | |
| Other | 437 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Room 100 |
| Other | 1135 | | | | | | | | N | N | N | Library | | Room 106 |
| Other | 178 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Room 216 |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|-------------------------------|
| Other | 50 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Room 216 |
| Other | 339 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd Floor Boy's Room |
| Other | 720 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Room 101 |
| Other | 107 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Main Office Waiting Room |
| Other | 82 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Boy's Room Next to the Gym |
| Other | 791 | | | | | | | | N | N | N | Kitchen | Warming Kitchen | 1st Floor |
| Other | 146 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Kitchen Manager's Office |
| Other | 458 | | | | | | | | N | N | N | Restroom | Staff Restroom | In the Kitchen Area |
| Other | 1245 | | | | | | | | N | N | N | Auditorium & Theater | Auditorium - Dedicated | 1st Floor |
| Other | 64 | | | | | | | | N | N | N | Restroom | Staff Restroom | Basement |
| Other | 458 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Room 117, Counselor's Office |
| Other | 339 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 3rd Floor Boy's Room |
| Other | 31 | | | | | | | | N | N | N | Restroom | Staff Restroom | In the Main Office |
| Other | 281 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Maintenance Lounge |
| Other | 175 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Principal's Office |
| Other | 216 | | | 6 | | | | | N | N | N | Administrative Suites/Offices | | Main Office |
| Other | 4018 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | 4018 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 4018 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 202 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Engineer's Office |
| Other | 44 | | | | | | | | N | N | N | Restroom | Staff Restroom | In the Engineer's Office |
| Other | 168 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Room 109, Nurse's Office |
| Other | 162 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | 2nd Floor |
| Other | 339 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 1st Floor Boy's Room |
| Other | 329 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 3rd Floor Girl's Room |
| Other | 329 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd Floor Girl's Room |
| Other | 329 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 1st Floor Girl's Room |
| Other | 249 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Room 300, Counselor's Office |
| Other | 84 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Room 300 |
| Other | 586 | | | | | | | | N | N | N | Restroom | Staff Restroom | 3rd Floor Women's Room |
| Other | 82 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Girl's Room next to Lunchroom |
| Other | 223 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Room 205 Parent Patrol Office |
| Other | 2225 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Former Stage Platform Area |
| Other | 37 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd Floor |
| Other | 1272 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Room 206, Conference Room |
| Other | 9253 | | | | | | | | N | N | N | Gymnasia | Competition Gymnasium | 1st Floor |
| Other | 204 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Boy's Room In Gym |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|-------------------------|
| Other | 203 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Girl's Room in Gym |
| Other | 87 | | | 2 | | | | | N | N | Y | Administrative Suites/Offices | | Gym Teacher's Office |
| Other | 42 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Gym Teacher's Office |
| Other | 84 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd Floor Men's Room |
| Other | 237 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Room 202 |