

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

- Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- Total Campus Need** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|---|--------------------------|------|----------|------|-----------|-----------------------------------|
| Canopy | | Metal Canopy | West End at 4 story bldg | 6 | 872 | SF | \$20,986 | refinish |
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | East Façade | 5 | 60 | LF | \$107,250 | tuckpoint- capped, no longer used |
| Chimney | | Metal Flue | Lower Roof | 7 | 1 | LF | \$0 | |
| Cornice | | Cornice - Masonry Projecting/Limestone | West End at 4 Story Bldg | 6 | 218 | LF | \$6,687 | open joints |
| Doors | | Exterior Steel Door | Entire Building | 6 | 26 | EA | \$8,589 | worn exterior finish |
| Doors | | Transom Lite | Entire Building | 6 | 10 | EA | \$2,831 | |
| Entrance | | Concrete Exterior Stairs | Main Entrance | 7 | 46 | LF | \$0 | |
| Entrance | | Concrete Ramp | Main Entrance | 7 | 30 | LF | \$0 | |
| Entrance | | Entrance Controls - Audio and Video | Main Entrance | 7 | 1 | EA | \$0 | |
| Entrance | | Ramp Handrails | Main Entrance | 6 | 60 | LF | \$0 | refinish |
| Fire Escape | | Fire Escapes | NE and SE | 6 | 10 | LF | \$1,019 | refinish |
| Foundation | | Masonry Foundation | Entire Building | 7 | 600 | SF | \$0 | |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Entire Building | 6 | 7 | EA | \$3,504 | |
| Lintels | | Lintels - Brick | East End of 4 stroy bldg | 7 | 293 | LF | \$0 | |

Building: Main
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-------------------------------------|----------------------------------|------|----------|------|------------------|--|
| Lintels | | Lintels - Steel | West Façade | 5 | 84 | LF | \$24,024 | rusty/corroded |
| Lintels | | Lintels - Stone | West End @ 4 story bldg | 6 | 216 | LF | \$0 | open joints |
| Parapet | | Coping - Clay Tile | main and low roofs | 6 | 493 | LF | \$0 | open joints |
| Parapet | | Coping - Terra Cotta | West End @ 4 story bldg | 6 | 260 | LF | \$0 | open joints |
| Parapet | | Parapet < 16" Height | main and low roofs | 6 | 493 | LF | \$76,773 | |
| Parapet | | Parapet > 30" Height | West End @ 4 story bldg | 6 | 259 | LF | \$67,222 | |
| Roof System | | Asphalt Gravel Ballast Roof | Roofs | 6 | 14,100 | SF | \$89,927 | flashings repaired- snow covered |
| Roof System | | Exterior Downspouts | Entire Building | 6 | 292 | LF | \$5,428 | |
| Roof System | | Roof Structure: Heavy Timber | Entire Building | 7 | 14,100 | SF | \$0 | |
| Superstructure | | Heavy Timber | Entire Building | 7 | 50,000 | SF | \$0 | |
| Walls | | Brick | Top Corner at NE of 4 story bldg | 4 | 100 | SF | \$7,550 | |
| Walls | | Brick | West End @ 4 story bldg | 6 | 9,220 | SF | \$60,913 | |
| Walls | | Brick | West End @ 4 story bldg | 6 | 2,707 | SF | \$17,884 | painted |
| Walls | | Brick | East End of 4 story bldg | 5 | 13,717 | SF | \$310,707 | tuckpoint |
| Walls | | Stone - Cut | Base of West Facade | 6 | 424 | SF | \$6,063 | peeling paint and open joints |
| Walls | | Stone - Cut | West Facade at Base | 7 | 2,120 | SF | \$0 | |
| Windows | | Window - Guards perforated | Entire Building | 6 | 1,600 | SF | \$0 | refinish |
| Windows | | Windows - Sash Aluminum Double-pane | Electrical Room | 6 | 5,540 | SF | \$47,533 | 4-5 windows do not open and require repair |
| EXTERIOR Sub Total | | | | | | | \$864,891 | |

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------|-----------|--|-----------------|------|----------|------|----------|--------|
| Emergency System | | Automatic Transfer switch | Basement | 7 | 1 | EA | \$0 | |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Entire Building | 6 | 8,084 | SF | \$3,468 | |
| Emergency System | | Emergency A/C power - Students Toilets | Entire Building | 6 | 1,007 | SF | \$432 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | Entire Building | 6 | 15 | EA | \$1,609 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Entire Building | 6 | 22 | EA | \$5,128 | |
| Emergency System | | Independent Electrical Service for emergency power | Basement | 6 | 1 | EA | \$1,430 | |
| Emergency System | | Public Announcement System | Main Office | 6 | 50,000 | SF | \$30,030 | |
| Emergency System | | Security System - Intrusion detection | Basement | 6 | 50,000 | SF | \$46,475 | |
| Main Service | | Main Electrical service 2000 to 3000 A 120/208/3PH | Basement | 6 | 1 | EA | \$24,310 | |
| Power Distribution | | Lighting and power panels | Basement | 6 | 2 | EA | \$1,430 | |

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|-----------------|------|----------|------|------------------|--------|
| Power Distribution | | Lighting and power panels | Entire Building | 6 | 7 | EA | \$5,005 | |
| Power Distribution | | Main distribution panels 400-600 amp | Basement | 6 | 1 | EA | \$1,430 | |
| Power Distribution | | Main distribution panels above 600 amp | Basement | 6 | 2 | EA | \$4,290 | |
| ELECTRICAL Sub Total | | | | | | | \$125,037 | |

Building: Main
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|--|-----------------|------|----------|------|------------------|--------|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 6 | 50,000 | SF | \$17,875 | |
| Fire Alarm | | Fire Alarm System | Basement | 6 | 50,500 | SF | \$61,383 | |
| Fire Alarm | | Fire Pump Controller | Fire Pump Room | 6 | 1 | EA | \$2,145 | |
| Pump Room Assembly | | Fire Pump less than 25hp | Fire Pump Room | 6 | 1 | EA | \$3,160 | |
| Sprinkler System | | Combination Wet and Dry Sprinkler System | Entire Building | 6 | 50,000 | SF | \$35,750 | |
| Sprinkler System | | Sprinkler Heads | Entire Building | 6 | 50,000 | SF | \$2,860 | |
| FIRE PROTECTION Sub Total | | | | | | | \$123,173 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|-----------------|------|----------|------|-----------|--------|
| Air Conditioning | | Condensing Unit - Roof Mounted less than 5 tons | Roof | 6 | 1 | EA | \$858 | |
| Air Handling Systems | | Fan Coil Unit - Electric | MDF Room | 6 | 1 | EA | \$1,187 | |
| Air Handling Systems | | Fan Power Box With Hot Water Coil | Entire Building | 5 | 29 | EA | \$55,985 | |
| Air Handling Systems | | Roof Top Unit - Single Zone - Gas-Heating greater than 45 tons | Roof | 5 | 3 | EA | \$171,600 | |
| Air Handling Systems | | Variable Air Volume (VAV) Box With Hot Water Coil | Entire Building | 5 | 10 | EA | \$16,445 | |
| Boiler Systems | | Boiler Assembly - Non-Condensing Flexible Tube Hot Water Boiler 1,001MBH-2,000 MBH | Boiler Room | 6 | 1 | EA | \$7,865 | |
| Boiler Systems | | Boiler Auxiliary Non-Condensing Hot Water Boiler 1,001MBH-2,000 MBH | Boiler Room | 6 | 1 | EA | \$5,005 | |
| Boiler Systems | | Chemical Pot Feeder - Hot Water | Boiler Room | 6 | 1 | EA | \$300 | |
| Heat Exchangers | | Heat Exchanger - Steam to Hot Water Shell Type | Boiler Room | 5 | 1 | EA | \$12,441 | |
| Heating Devices | | Cabinet Heaters With Hot Water Coils | Entire Building | 5 | 6 | EA | \$11,154 | |
| Heating Devices | | Fin Tube Hot Water | Entire Building | 6 | 536 | LF | \$9,198 | |
| Heating Devices | | Unit Heater - Hot Water | Basement | 5 | 4 | EA | \$11,440 | |
| Heating Devices | | Wall Heater - Electric | Entire Building | 6 | 4 | EA | \$412 | |
| Mechanical Plumbing | | Condensate Assembly - Pumps and Tank | Boiler Room | 6 | 1 | EA | \$715 | |
| Mechanical Plumbing | | Piping - Condensate - Steel or Galvanized | Boiler Room | 6 | 150 | LF | \$1,030 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|-----------------|------|----------|------|------------------|--------|
| Mechanical Plumbing | | Piping - Hydronic Supply and Return - Steel or Galvanized | Entire Building | 6 | 250 | LF | \$2,217 | |
| Mechanical Plumbing | | Piping - Steam - Steel or Galvanized | Boiler Room | 6 | 50 | LF | \$443 | |
| Mechanical Plumbing | | Pumps - Hot Water 5 to 10 HP | Boiler Room | 6 | 2 | EA | \$4,004 | |
| Mechanical Plumbing | | Pumps - Hot Water less than 5 HP | Boiler Room | 6 | 1 | EA | \$1,430 | |
| Temperature Control | | Direct Digital Control (DDC) System | Entire Building | 5 | 50,000 | SF | \$250,250 | |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | Entire Building | 6 | 42 | EA | \$6,006 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 6 | 2 | EA | \$858 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Lower Roof | 6 | 1 | EA | \$229 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 6 | 2 | EA | \$458 | |
| Ventilation | | Lab Exhaust Hood | 3rd Floor | 6 | 4 | EA | \$13,156 | |
| Ventilation | | Type I Exhaust Hood - Kitchen or Culinary Arts | Kitchen | 7 | 2 | EA | \$0 | |
| MECHANICAL Sub Total | | | | | | | \$584,684 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|--|-----------------|------|----------|------|------------------|--------|
| Hot Water | | Hot Water Heater - Gas 150,000 -300,000 BTU/HR | Basement | 6 | 2 | EA | \$8,294 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 4 | 50,000 | SF | \$16,445 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 4 | 50,000 | SF | \$32,175 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 4 | 50,000 | SF | \$10,725 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 4 | 50,000 | SF | \$22,880 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 4 | 50,000 | SF | \$27,170 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 4 | 50,000 | SF | \$119,405 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 4 | 50,000 | SF | \$98,670 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 4 | 50,000 | SF | \$57,200 | |
| Piping | | Sanitary Piping | Entire Building | 5 | 50,000 | SF | \$30,745 | |
| Piping | | Storm Piping | Entire Building | 5 | 50,000 | SF | \$23,595 | |
| Piping | | Vent Piping | Entire Building | 5 | 50,000 | SF | \$17,875 | |
| Pumps | | Domestic Booster Pump duplex | Fire Pump Room | 6 | 1 | EA | \$3,146 | |
| Pumps | | Sump Pump | Basement | 6 | 1 | EA | \$1,359 | |
| PLUMBING Sub Total | | | | | | | \$469,684 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------|----------|------|----------|------|------|--------|
|-------|-----------|------|----------|------|----------|------|------|--------|

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|---------------------------|--|------|----------|------|-------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in 303 | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | next rm 203 FP Art Room | 6 | 106 | SF | \$300 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in 205 | 6 | 113 | SF | \$320 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in 206 | 6 | 113 | SF | \$320 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in 103 | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in 305 | 6 | 113 | SF | \$320 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Other | 6 | 300 | SF | \$849 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | office next to 103 | 7 | 136 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in 203 | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in 202 | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in 300A | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 200A FP rm 200's wardrobe | 7 | 250 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | in rm 201 | 7 | 108 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | office next to 303 FP 301.5 adjusting rm | 7 | 170 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in 302 | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | basement teachers lounge | 7 | 675 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | library offices | 7 | 980 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | kitchen office | 6 | 190 | SF | \$538 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | custodial office | 7 | 175 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | main office | 6 | 300 | SF | \$849 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in 306 | 6 | 113 | SF | \$320 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | in rm 301 | 7 | 108 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|-----------------------|--|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | library offices | 6 | 980 | SF | \$1,401 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | custodial office | 6 | 175 | SF | \$250 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Other | 7 | 300 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | next rm 203 FP Art Room | 6 | 106 | SF | \$152 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | office next to 303 FP 301.5 adjusting rm | 7 | 170 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | office next to 103 | 7 | 136 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in 202 | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in 103 | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | main office | 7 | 300 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 200A FP rm 200's wardrobe | 7 | 250 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | kitchen office | 7 | 190 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in 302 | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in 205 | 7 | 113 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in 206 | 7 | 113 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in 306 | 7 | 113 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in 305 | 7 | 113 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in 303 | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in 203 | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in 300A | 7 | 150 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | in rm 301 | 7 | 108 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | in rm 201 | 7 | 108 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | basement teachers lounge | 7 | 675 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|----------------------------|--|------|----------|------|------|--------|
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in 303 | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in 305 | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in 203 | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in 300A | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in 206 | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | custodial office | 6 | 3 | SF | \$2 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | office next to 103 | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | office next to 303 FP 301.5 adjusting rm | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in 202 | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in 103 | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | main office | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in 306 | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 200A FP rm 200's wardrobe | 7 | 5 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in 302 | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | next rm 203 FP Art Room | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in 205 | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | kitchen office | 7 | 4 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | library offices | 6 | 24 | SF | \$17 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | basement teachers lounge | 7 | 13 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Other | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Wall Mounted | in rm 201 | 7 | 2 | EA | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Wall Mounted | in rm 301 | 7 | 2 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|-------------------------|--|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | office next to 103 | 6 | 525 | SF | \$1,239 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in 202 | 6 | 602 | SF | \$1,420 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in 103 | 6 | 602 | SF | \$1,420 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | main office | 7 | 505 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 200A FP rm 200's wardrobe | 6 | 778 | SF | \$1,836 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in 305 | 6 | 500 | SF | \$1,180 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | custodial office | 7 | 520 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | kitchen office | 6 | 630 | SF | \$1,486 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | library offices | 7 | 1,380 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | basement teachers lounge | 7 | 965 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in 302 | 6 | 602 | SF | \$1,420 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | office next to 303 FP 301.5 adjusting rm | 6 | 744 | SF | \$1,755 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Other | 7 | 505 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in 306 | 6 | 500 | SF | \$1,180 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in 303 | 6 | 602 | SF | \$1,420 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | in rm 301 | 6 | 530 | SF | \$1,251 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in 300A | 6 | 602 | SF | \$1,420 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in 205 | 6 | 500 | SF | \$1,180 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | in rm 201 | 6 | 530 | SF | \$1,251 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in 206 | 6 | 500 | SF | \$1,180 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in 203 | 6 | 602 | SF | \$1,420 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | next rm 203 FP Art Room | 6 | 540 | SF | \$1,274 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------|---------------------------------|------------------------------|--------------------------------|------|----------|------|----------|--------|
| Doors | | Interior Steel Doors incl hw | Entire Building | 7 | 24 | EA | \$0 | |
| Doors | | Interior Steel Doors incl hw | Entire Building | 6 | 17 | EA | \$4,813 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 7 | 8 | EA | \$0 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 6 | 66 | EA | \$18,687 | |
| Doors | | Transom Window | Entire Building | 7 | 300 | SF | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 3rd Floor | 7 | 3 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 1st Floor | 7 | 3 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 2nd Floor | 7 | 3 | EA | \$0 | |
| Kitchen | Cooking Kitchen | Ceiling - Lay-In | Basement | 6 | 920 | SF | \$2,631 | |
| Kitchen | Cooking Kitchen | Flooring - Tile/Sheet | Basement | 7 | 920 | SF | \$0 | |
| Kitchen | Cooking Kitchen | Lighting - Lay-In | Basement | 6 | 12 | SF | \$9 | |
| Kitchen | Cooking Kitchen | Wall - Plaster/Drywall | Basement | 6 | 950 | SF | \$2,242 | |
| Locker/Shower Room | Adult Standard Student Restroom | Benches | 3rd fl girls rm 313 fp302.5 | | | LF | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Benches | 2nd fl girls rm 213 | | | LF | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Benches | 1st fl girls rm 113 | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | 1st fl men rm 114 | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | basement mens north | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | basement womens north | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | basement womens south | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | basement mens south | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | UNDER RENOVATION- INACCESSIBLE | | | | | |
| Locker/Shower Room | Staff Restroom | Benches | 2nd fl men rm 214 fp202.5 | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | 3rd fl men rm 314 fp302.5 | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | 2nd fl men rm 214 fp202.5 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | 1st fl men rm 114 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | basement mens north | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | basement womens north | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | basement womens south | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | basement mens south | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | UNDER RENOVATION- INACCESSIBLE | | | | | |
| Locker/Shower Room | Staff Restroom | Lockers | 3rd fl men rm 314 fp302.5 | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Lockers | 3rd fl girls rm 313 fp302.5 | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Lockers | 2nd fl girls rm 213 | | | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|---------------------------------|---------------------------|--|------|----------|------|----------|--------|
| Locker/Shower Room | Adult Standard Student Restroom | Lockers | 1st fl girls rm 113 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | basement womens south | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 1st fl men rm 114 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 3rd fl men rm 314 fp302.5 | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Showers | 1st fl girls rm 113 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | basement mens north | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | basement womens north | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | basement mens south UNDER RENOVATION- INACCESSIBLE | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Showers | 3rd fl girls rm 313 fp302.5 | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Showers | 2nd fl girls rm 213 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 2nd fl men rm 214 fp202.5 | | | EA | \$0 | |
| Lunchroom | Cooking Kitchen | Serving Line | Basement | | | LF | \$0 | |
| Mechanical/Service Rooms | | Boiler Room | Basement | 6 | 380 | SF | \$1,793 | |
| Mechanical/Service Rooms | | Janitor's Closet | Basement | 7 | 5 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement | 6 | 3,260 | SF | \$15,384 | |
| Mechanical/Service Rooms | | Storage Room | Basement | 6 | 330 | SF | \$1,557 | |
| Mechanical/Service Rooms | | Storage Room | main office | 7 | 105 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | 1st fl girls rm 113 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 3rd fl men rm 314 fp302.5 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | 3rd fl girls rm 313 fp302.5 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | 2nd fl girls rm 213 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd fl men rm 214 fp202.5 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | basement mens south UNDER RENOVATION- INACCESSIBLE | 7 | 38 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | basement womens south | 7 | 175 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | basement womens north | 7 | 38 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 1st fl men rm 114 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | basement mens north | 7 | 72 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | basement womens north | 6 | 38 | SF | \$108 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | 1st fl girls rm 113 | 7 | 114 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|---------------------------------|-----------------------------------|--|------|----------|------|-------|--------|
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd fl men rm 214 fp202.5 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 1st fl men rm 114 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | basement mens north | 7 | 72 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | basement mens south UNDER RENOVATION- INACCESSIBLE | 6 | 38 | SF | \$108 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 3rd fl men rm 314 fp302.5 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd fl girls rm 213 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | 3rd fl girls rm 313 fp302.5 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | basement womens south | 6 | 175 | SF | \$495 | |
| Staff Restroom | Staff Restroom | Floor Drain | basement mens south UNDER RENOVATION- INACCESSIBLE | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 2nd fl men rm 214 fp202.5 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | 2nd fl girls rm 213 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 3rd fl men rm 314 fp302.5 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | basement womens south | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | basement womens north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | basement mens north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 1st fl men rm 114 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | 1st fl girls rm 113 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | 3rd fl girls rm 313 fp302.5 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 2nd fl men rm 214 fp202.5 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | basement womens north | 7 | 38 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 1st fl girls rm 113 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 1st fl men rm 114 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | basement mens north | 7 | 72 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | basement mens south UNDER RENOVATION- INACCESSIBLE | 7 | 38 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 3rd fl men rm 314 fp302.5 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 3rd fl girls rm 313 fp302.5 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | basement womens south | 7 | 175 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|---------------------------------|-----------------------------------|--|------|----------|------|-------|--------|
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd fl girls rm 213 | 7 | 114 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | basement mens south UNDER RENOVATION- INACCESSIBLE | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | 2nd fl men rm 214 fp202.5 | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | 2nd fl girls rm 213 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | 3rd fl men rm 314 fp302.5 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | basement womens south | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | basement womens north | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | basement mens north | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | 1st fl men rm 114 | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | 1st fl girls rm 113 | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | 3rd fl girls rm 313 fp302.5 | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | 1st fl girls rm 113 | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 3rd fl men rm 314 fp302.5 | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 2nd fl men rm 214 fp202.5 | 7 | 2 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | 2nd fl girls rm 213 | 7 | 2 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | 3rd fl girls rm 313 fp302.5 | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | basement mens south UNDER RENOVATION- INACCESSIBLE | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | basement womens south | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | basement womens north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 1st fl men rm 114 | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | basement mens north | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 3rd fl men rm 314 fp302.5 | 7 | 2 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Pendant/ Surface | 1st fl girls rm 113 | 7 | 2 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 2nd fl men rm 214 fp202.5 | 7 | 2 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Pendant/ Surface | 2nd fl girls rm 213 | 7 | 2 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Pendant/ Surface | 3rd fl girls rm 313 fp302.5 | 7 | 2 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 1st fl men rm 114 | 7 | 2 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|---------------------------------|-------------------------|--|------|----------|------|-------|--------|
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | basement mens north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | basement womens south | 6 | 6 | EA | \$172 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | basement womens north | 6 | 1 | EA | \$29 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | basement mens south UNDER RENOVATION- INACCESSIBLE | 6 | 1 | EA | \$29 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | 3rd fl girls rm 313 fp302.5 | 7 | 4 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | 2nd fl girls rm 213 | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 3rd fl men rm 314 fp302.5 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | basement mens south UNDER RENOVATION- INACCESSIBLE | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | basement womens south | 6 | 5 | EA | \$897 | |
| Staff Restroom | Staff Restroom | Partitions | basement womens north | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | basement mens north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 1st fl men rm 114 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | 1st fl girls rm 113 | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 2nd fl men rm 214 fp202.5 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | 2nd fl men rm 214 fp202.5 | 7 | 3 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | 1st fl girls rm 113 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | 1st fl men rm 114 | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | basement mens north | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | basement womens south | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | basement mens south UNDER RENOVATION- INACCESSIBLE | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | 3rd fl men rm 314 fp302.5 | 7 | 3 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | 3rd fl girls rm 313 fp302.5 | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | 2nd fl girls rm 213 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | basement womens north | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 1st fl men rm 114 | 7 | 108 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Plaster/Drywall | 1st fl girls rm 113 | 7 | 130 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | basement mens north | 7 | 135 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | basement womens north | 7 | 100 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------|---------------------------------|--------------------------------|--------------------------------|------|----------|------|------|--------|
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | basement womens south | 7 | 215 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | basement mens south | 7 | 100 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 3rd fl men rm 314 fp302.5 | 7 | 108 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Plaster/Drywall | 3rd fl girls rm 313 fp302.5 | 7 | 130 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Plaster/Drywall | 2nd fl girls rm 213 | 7 | 130 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 2nd fl men rm 214 fp202.5 | 7 | 108 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | basement womens north | 7 | 130 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | 1st fl girls rm 113 | 7 | 312 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | basement mens north | 7 | 185 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | basement womens south | 7 | 305 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | basement mens south | 7 | 130 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | UNDER RENOVATION- INACCESSIBLE | | | | | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | 3rd fl men rm 314 fp302.5 | 7 | 258 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | 3rd fl girls rm 313 fp302.5 | 7 | 312 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | 2nd fl girls rm 213 | 7 | 312 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | 2nd fl men rm 214 fp202.5 | 7 | 258 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | 1st fl men rm 114 | 7 | 258 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | 3rd fl girls rm 313 fp302.5 | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 1st fl men rm 114 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | basement mens north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | basement womens north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | basement womens south | 7 | 5 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | 1st fl girls rm 113 | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 3rd fl men rm 314 fp302.5 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | 2nd fl girls rm 213 | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd fl men rm 214 fp202.5 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | basement mens south | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | UNDER RENOVATION- INACCESSIBLE | | | | | |
| Vertical Conveyance | | Elevator - Machine Roomless | Entire Building | 7 | 1 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-----------|----------|------|----------|------|-----------------|--------|
| Vocational Shop | Classroom | Work Sink | | 6 | 10 | EA | \$3,861 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| INTERIOR Sub Total | | | | | | | \$83,316 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 86 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 12 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 25 | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 760 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 760 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 760 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 760 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 760 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 322 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 585 | SF | \$1,656 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,040 | SF | \$2,945 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 815 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 815 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 815 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 815 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 815 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 815 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 585 | SF | \$1,656 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,670 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------|-----------|--------------------|-----------------------------------|------|----------|------|---------|--------|
| Corridors | Corridors | Drinking Fountains | basement including exit vestibule | | | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 7 | 1,953 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 3rd Floor | 7 | 1,953 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | basement including exit vestibule | 6 | 2,225 | EA | \$1,591 | |
| Corridors | Corridors | Pendant/Surface | South Stairs | 7 | 868 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | North Stairs | 7 | 868 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 1st Floor | 7 | 1,953 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | Center Stairs | 7 | 784 | EA | \$0 | |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 6 | 2,472 | SF | \$5,833 | |
| Corridors | Corridors | Plaster/Drywall | 3rd Floor | 6 | 2,472 | SF | \$5,833 | |
| Corridors | Corridors | Plaster/Drywall | North Stairs | 6 | 3,563 | SF | \$8,407 | |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 6 | 2,472 | SF | \$5,833 | |
| Corridors | Corridors | Plaster/Drywall | Center Stairs | 6 | 1,958 | SF | \$4,620 | |
| Corridors | Corridors | Plaster/Drywall | South Stairs | 6 | 3,563 | SF | \$8,407 | |
| Corridors | Corridors | Plaster/Drywall | basement including exit vestibule | 6 | 3,070 | SF | \$7,244 | |
| Corridors | Corridors | Stair Handrails | North Stairs | 6 | 160 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | 2nd Floor | | | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | 3rd Floor | | | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | South Stairs | 6 | 160 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | 1st Floor | | | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | Center Stairs | 6 | 78 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | basement including exit vestibule | | | LF | \$0 | |
| Corridors | Corridors | Stairs | South Stairs | 6 | 79 | EA | \$565 | |
| Corridors | Corridors | Stairs | 1st Floor | | | EA | \$0 | |
| Corridors | Corridors | Stairs | South Stairs | 6 | 5 | EA | \$36 | |
| Corridors | Corridors | Stairs | basement including exit vestibule | 6 | 6 | EA | \$43 | |
| Corridors | Corridors | Stairs | 3rd Floor | | | EA | \$0 | |
| Corridors | Corridors | Stairs | 2nd Floor | | | EA | \$0 | |
| Corridors | Corridors | Stairs | North Stairs | 6 | 79 | EA | \$565 | |
| Corridors | Corridors | Stairs | North Stairs | 6 | 5 | EA | \$36 | |
| Corridors | Corridors | Student Lockers | South Stairs | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | basement including exit vestibule | 6 | 52 | EA | \$7,436 | |
| Corridors | Corridors | Student Lockers | 3rd Floor | 7 | 122 | EA | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|---------------------|-----------------------------------|------|----------|------|---------|--------|
| Corridors | Corridors | Student Lockers | 2nd Floor | 7 | 97 | EA | \$0 | |
| Corridors | Corridors | Student Lockers | 1st Floor | 7 | 76 | EA | \$0 | |
| Corridors | Corridors | Student Lockers | Center Stairs | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | North Stairs | | | EA | \$0 | |
| Corridors | Corridors | Terrazzo | South Stairs | 6 | 190 | SF | \$1,076 | |
| Corridors | Corridors | Terrazzo | North Stairs | 6 | 190 | SF | \$1,076 | |
| Corridors | Corridors | Terrazzo | Center Stairs | 6 | 290 | SF | \$1,642 | |
| Corridors | Corridors | Tile/Sheet Flooring | Center Stairs | 7 | 336 | SF | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | North Stairs | 6 | 233 | SF | \$333 | |
| Corridors | Corridors | Tile/Sheet Flooring | South Stairs | 6 | 233 | SF | \$333 | |
| Corridors | Corridors | Tile/Sheet Flooring | basement including exit vestibule | 6 | 2,160 | SF | \$3,089 | |
| Corridors | Corridors | Wall Mounted | Center Stairs | 7 | 336 | EA | \$0 | |
| Corridors | Corridors | Walls | North Stairs | 6 | 70 | SF | \$165 | |
| Corridors | Corridors | Walls | South Stairs | 6 | 70 | SF | \$165 | |
| Corridors | Corridors | Walls | basement including exit vestibule | 7 | 110 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 1st Floor | 7 | 1,953 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 3rd Floor | 7 | 1,953 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Center Stairs | 6 | 930 | SF | \$2,633 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | basement including exit vestibule | 6 | 2,225 | SF | \$6,300 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | South Stairs | 6 | 868 | SF | \$2,458 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | North Stairs | 6 | 868 | SF | \$2,458 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 2nd Floor | 7 | 1,953 | SF | \$0 | |
| Stairs | Corridors | Tile | Center Stairs | 6 | 50 | SF | \$378 | |
| Floor | Classroom | Carpet | | 6 | 1,040 | SF | \$1,487 | |
| Floor | Classroom | Tile/Sheet | | 6 | 760 | SF | \$1,087 | |
| Floor | Classroom | Tile/Sheet | | 7 | 815 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 815 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 815 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 815 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 760 | SF | \$1,087 | |
| Floor | Classroom | Tile/Sheet | | 6 | 760 | SF | \$1,087 | |
| Floor | Classroom | Tile/Sheet | | 6 | 585 | SF | \$837 | |
| Floor | Classroom | Tile/Sheet | | 7 | 815 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 815 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 760 | SF | \$1,087 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------------|-----------------|----------|------|----------|------|----------|--------|
| Floor | Classroom | Tile/Sheet | | 6 | 585 | SF | \$837 | |
| Floor | Classroom | Tile/Sheet | | 6 | 760 | SF | \$1,087 | |
| Floor | Classroom | Tile/Sheet | | 7 | 815 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 815 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 815 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 815 | SF | \$0 | |
| Floor | Classroom | Wood | | 5 | 1,992 | SF | \$28,201 | |
| KITCHEN_WALL | Cooking Kitchen | Kitchen Walls | Basement | 7 | 190 | SF | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 4 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 16 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 34 | EA | \$2,431 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 3 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 16 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 6 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 5 | LF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------------|-----------|-----------------|----------|------|----------|------|--------------------|--------|
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 4 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 16 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 5 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 40 | LF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,201 | SF | \$2,834 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,023 | SF | \$2,414 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,023 | SF | \$2,414 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 2,407 | SF | \$5,679 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,023 | SF | \$2,414 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,023 | SF | \$2,414 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,235 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 2,137 | SF | \$5,042 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,023 | SF | \$2,414 | |
| ROOM Sub Total | | | | | | | \$213,461 | |
| Building Main Sub Total | | | | | | | \$2,464,245 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------|----------|------|----------|------|------|--------|
|-------|-----------|------|----------|------|----------|------|------|--------|

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|---------------------|-----------------------------------|------|----------|------|-----------------|---|
| Civil/Drainage | | Catch Basin | Entire Site | 7 | 2 | EA | \$0 | |
| Civil/Drainage | | Site Manhole | Entire Site | 7 | 7 | EA | \$0 | |
| Fencing | | Chain Link | Site - East | 4 | 134 | LF | \$14,372 | damaged and disconnected |
| Fencing | | Chain Link | fire escape and between buildings | 7 | 60 | LF | \$0 | |
| Landscape | | Trash Receptacles | Site ζ West | 7 | 2 | EA | \$0 | |
| Parking Lot | | Asphalt | site- north and south | 5 | 480 | SF | \$1,359 | missing surface- brick below is exposed |
| Parking Lot | | Asphalt | site- north and south | 7 | 11,840 | SF | \$0 | |
| Parking Lot | | Concrete | Site ζ North | 7 | 2,316 | SF | \$0 | |
| Parking Lot | | Concrete | Site - East | 6 | 1,496 | SF | \$0 | cracking and displacement |
| Sidewalks | | Perimeter Sidewalks | Site ζ West | 7 | 2,070 | SF | \$0 | |
| Signage | | Flag Pole | Site ζ West | 7 | 1 | EA | \$0 | |
| SITE Sub Total | | | | | | | \$15,731 | |
| SITE Sub Total | | | | | | | \$15,731 | |

Total Campus Need ^{2 3} \$2,479,976

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked “1” in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-----------------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|---------------------------------|--|
| Building: Main | | | | | | | | | | | | | | |
| 101 | 760 | 1 | 15 | 10 | 40 | 90 | 45 | | Y | Y | Y | Classroom | | |
| 102 | 685 | 1 | 12 | 14 | 40 | 90 | 45 | | Y | Y | Y | Classroom | | |
| 103 | 815 | 1 | 8 | 16 | 40 | 100 | 50 | | Y | Y | Y | Classroom | | |
| 104 | 815 | 1 | 8 | 16 | 40 | 100 | 50 | | Y | Y | Y | Classroom | | |
| 1105 | 1992 | 2 | 2 | 16 | 40 | 120 | 60 | | N | Y | Y | Classroom | | |
| 125 | 1040 | 4 | 24 | 26 | 40 | 50 | 25 | | N | N | Y | Classroom | | |
| 200 | 760 | 1 | 18 | 36 | 40 | 90 | 45 | | Y | Y | Y | Classroom | | |
| 201 | 760 | 1 | 15 | 10 | 40 | 90 | 45 | | Y | Y | Y | Classroom | | |
| 202 | 685 | 1 | 12 | 14 | 40 | 90 | 45 | | Y | Y | Y | Classroom | | |
| 203 | 815 | 1 | 15 | 16 | 40 | 100 | 50 | | Y | Y | Y | Classroom | | |
| 204 | 815 | 1 | 15 | 16 | 40 | 100 | 50 | | Y | Y | Y | Classroom | | |
| 205 | 815 | 1 | 15 | 16 | 40 | 80 | 40 | | Y | Y | Y | Classroom | | |
| 206 | 815 | 1 | 15 | 16 | 40 | 80 | 40 | | Y | Y | Y | Classroom | | |
| 300 | 760 | 1 | 18 | 36 | 40 | 90 | 45 | | Y | Y | Y | Classroom | | |
| 301 | 760 | 1 | 15 | 10 | 40 | 90 | 45 | | Y | Y | Y | Classroom | | |
| 303 | 815 | 1 | 15 | 16 | 40 | 100 | 50 | | Y | Y | Y | Classroom | | |
| 304 | 815 | 1 | 15 | 16 | 40 | 90 | 40 | | Y | Y | Y | Classroom | | |
| 305 | 815 | 1 | 15 | 16 | 40 | 80 | 40 | | Y | Y | Y | Classroom | | |
| 306 | 815 | 1 | 15 | 16 | 40 | 80 | 40 | | Y | Y | Y | Classroom | | |
| Other | 675 | | | 10 | | | | | N | N | N | Administrative Suites/Offices | | basement teachers lounge |
| Other | 38 | | | | | | | | N | N | N | Restroom | Staff Restroom | basement mens south UNDER RENOVATION- INACCESSIBLE |
| Other | 114 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd fl men rm 214 fp202.5 |
| Other | 114 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | 2nd fl girls rm 213 |
| Other | 175 | | | | | | | | N | N | N | Restroom | Staff Restroom | basement womens south |
| Other | 170 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | office next to 303 FP 301.5 adjusting rm |
| Other | 38 | | | | | | | | N | N | N | Restroom | Staff Restroom | basement womens north |
| Other | 72 | | | | | | | | N | N | N | Restroom | Staff Restroom | basement mens north |
| Other | 114 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | 3rd fl girls rm 313 fp302.5 |
| Other | 250 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | 200A FP rm 200's wardrobe |
| Other | 175 | | | 12 | | | | | N | N | N | Administrative Suites/Offices | | custodial office |
| Other | 2225 | | | | | | | | N | N | N | Corridors | | basement including exit vestibule |
| Other | 920 | | | | | | | | N | N | N | Kitchen | Cooking Kitchen | Basement |
| Other | 190 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | kitchen office |
| Other | 980 | | | 26 | | | | | N | N | N | Administrative Suites/Offices | | library offices |
| Other | 150 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Office in 302 |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|---------------------------------|---------------------------|
| Other | 114 | | | | | | | | N | N | N | Restroom | Staff Restroom | 3rd fl men rm 314 fp302.5 |
| Other | 114 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | 1st fl girls rm 113 |
| Other | 113 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Office in 206 |
| Other | 113 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Office in 205 |
| Other | 106 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | next rm 203 FP Art Room |
| Other | 1953 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | 1953 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 1953 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | | | | | | | | | N | N | N | Corridors | | Center Stairs |
| Other | 300 | | | 12 | | | | | N | N | N | Administrative Suites/Offices | | main office |
| Other | 300 | | | 12 | | | | | N | N | N | Administrative Suites/Offices | | |
| Other | 108 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | in rm 201 |
| Other | 114 | | | | | | | | N | N | N | Restroom | Staff Restroom | 1st fl men rm 114 |
| Other | 113 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Office in 306 |
| Other | | | | | | | | | N | N | N | Corridors | | South Stairs |
| Other | 150 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Office in 103 |
| Other | 136 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | office next to 103 |
| Other | 150 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Office in 202 |
| Other | 113 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Office in 305 |
| Other | 150 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Office in 303 |
| Other | 150 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Office in 203 |
| Other | 150 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Office in 300A |
| Other | 108 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | in rm 301 |
| Other | | | | | | | | | N | N | N | Corridors | | North Stairs |