

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

- Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- Total Campus Need** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|--|-------------------------------------|------|----------|------|-----------|--------|
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Top section | 5 | 28 | LF | \$50,050 | |
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Bottom section | 6 | 60 | LF | \$30,030 | |
| Cornice | | Cornice - Metal Projecting | Entire Building | 5 | 1,748 | LF | \$517,201 | |
| Doors | | Exterior Steel Door | Entire Building | 6 | 18 | EA | \$5,946 | |
| Doors | | Exterior Steel Door | South and West play rooms | 4 | 3 | EA | \$9,910 | |
| Doors | | Transom Lite | Entire Building | 6 | 106 | EA | \$30,013 | |
| Entrance | | Concrete Exterior Stairs | Entire Building | 7 | 76 | LF | \$0 | |
| Entrance | | Entrance Controls - Audio | Main Entrance | 6 | 1 | EA | \$429 | |
| Fire Escape | | Fire Escapes | Gym West and Auditorium North/South | 5 | 6 | LF | \$1,911 | |
| Foundation | | Masonry Foundation | Basement | 7 | 21,900 | SF | \$0 | |
| Lighting | | Exterior Lights - Wall Mounted | Building Wall | 6 | 14 | EA | \$3,003 | |
| Lintels | | Lintels - Steel | Entire Building | 6 | 376 | LF | \$14,195 | |
| Lintels | | Lintels - Steel | West Façade | 4 | 64 | LF | \$27,914 | |
| Lintels | | Lintels - Steel | South Door | 5 | 12 | LF | \$3,432 | |

Building: Main
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|---|--------------------------------------|------|----------|------|--------------------|--------|
| Lintels | | Lintels - Stone | Entire Building | 6 | 298 | LF | \$0 | |
| Parapet | | Coping - Clay Tile | High Roofs | 5 | 280 | LF | \$16,569 | |
| Parapet | | Coping - Clay Tile | Roof | 7 | 383 | LF | \$0 | |
| Parapet | | Coping - Metal | North at High Roof | 6 | 25 | LF | \$0 | |
| Parapet | | Coping - Stone | Vestibules and misc. high roof areas | 5 | 185 | LF | \$16,132 | |
| Parapet | | Parapet < 16" Height | Lower Roofs | 6 | 451 | LF | \$70,233 | |
| Parapet | | Parapet > 30" Height | High Roofs | 6 | 100 | LF | \$25,955 | |
| Parapet | | Parapet 16" to 30" Height | High Roofs | 6 | 322 | LF | \$66,859 | |
| Roof System | | Asphalt Gravel Ballast Roof | Lower Roofs | 6 | 1,904 | SF | \$12,143 | |
| Roof System | | Exterior Downspouts | Entire Building | 7 | 173 | LF | \$0 | |
| Roof System | | Interior Downspouts | Entire Building | 6 | 290 | LF | \$0 | |
| Roof System | | Interior Downspouts | NorthWest Roof | 5 | 58 | LF | \$6,221 | |
| Roof System | | Metal Roof | Main Roofs | 5 | 13,177 | SF | \$235,539 | |
| Roof System | | Modified Bitumen Roof | Main Roofs | 6 | 6,819 | SF | \$48,268 | |
| Roof System | | Roof Structure: Steel with Clay Tile Arch | Main Roofs | 7 | 21,900 | SF | \$0 | |
| Superstructure | | Steel with Clay Tile Arch | Entire Building | 7 | 74,800 | SF | \$0 | |
| Walls | | Brick | West at the top of 1 story | 4 | 150 | SF | \$11,326 | |
| Walls | | Brick | West at the top of 1 story | 5 | 2,400 | SF | \$54,363 | |
| Walls | | Brick | Entire Building | 6 | 28,186 | SF | \$186,214 | |
| Walls | | Stone - Cast | East, North, and South Entrances | 6 | 1,610 | SF | \$23,023 | |
| Walls | | Stone - Cut | West at base | 6 | 820 | SF | \$11,726 | |
| Windows | | Window - Guards perforated | Entire Building | 6 | 3,875 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 6 | 8,073 | SF | \$69,266 | |
| EXTERIOR Sub Total | | | | | | | \$1,547,868 | |

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------|-----------|---|-------------------|------|----------|------|----------|--|
| Emergency System | | Automatic Transfer switch | Electrical Room | 6 | 1 | EA | \$1,430 | |
| Emergency System | | Emergency A/C power - Auditorium and aisle lighting | 1st Floor | 6 | 3,735 | SF | \$5,074 | |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Entire Building | 6 | 10,580 | SF | \$4,539 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Gym and Lunchroom | 6 | 5,378 | SF | \$2,845 | |
| Emergency System | | Emergency A/C power - Students Toilets | Entire Building | 6 | 2,176 | SF | \$934 | |
| Emergency System | | Emergency generator below 60 KW diesel - Outdoor | West Courtyard | 5 | 1 | EA | \$14,872 | Currently not working but scheduled for repair |

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|--------------------|------|----------|------|------------------|------------|
| Emergency System | | Exit Signs - Auditorium | 1st Floor | 7 | 4 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Entire Building | 7 | 23 | EA | \$0 | |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | Gym and Lunchroom | 7 | 5 | EA | \$0 | |
| Emergency System | | Independent Electrical Service for emergency power | Electrical Room | 6 | 1 | EA | \$1,430 | |
| Emergency System | | Public Announcement System | 1st Floor | 6 | 74,800 | SF | \$44,925 | |
| Emergency System | | Security System - Intrusion detection | Basement | 6 | 74,800 | SF | \$69,527 | |
| Main Service | | Main Electrical service 2000 to 3000 A 120/208/3PH | Electrical Room | 6 | 1 | EA | \$24,310 | |
| Power Distribution | | Lighting and power panels | Entire Building | 6 | 18 | EA | \$12,870 | |
| Power Distribution | | Lighting and power panels | Pump and Tank Room | 4 | 1 | EA | \$5,434 | With Fuses |
| Power Distribution | | Main distribution panels 400-600 amp | Electrical Room | 6 | 1 | EA | \$1,430 | |
| Power Distribution | | Main distribution panels above 600 amp | Basement | 6 | 4 | EA | \$8,580 | |
| ELECTRICAL Sub Total | | | | | | | \$198,199 | |

Building: Main
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|-------------------|--------------------|------|----------|------|------------------|--------|
| Fire Alarm | | Fire Alarm System | Pump and Tank Room | 4 | 78,600 | SF | \$277,623 | |
| FIRE PROTECTION Sub Total | | | | | | | \$277,623 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|-------------------|------|----------|------|----------|--------|
| Air Conditioning | | Window A/C Unit | Entire Building | 4 | 18 | EA | \$38,610 | |
| Air Conditioning | | Window A/C Unit | Entire Building | 6 | 11 | EA | \$2,360 | |
| Air Handling Systems | | Air Intake - Built Up Air Handling Unit | Ground floor Wall | 6 | 3 | EA | \$4,290 | |
| Air Handling Systems | | Multi Zone Built Up Air Handling Unit - Steam 15,001 to 25,000 cfm | Engine Room | 5 | 1 | EA | \$35,750 | |
| Air Handling Systems | | Multi Zone Built Up Air Handling Unit Auxiliaries - Steam 15,001 to 25,000 cfm | Engine Room | 6 | 1 | EA | \$2,860 | |
| Air Handling Systems | | Multi Zone Double Delivery Built Up Air Handling Unit - Steam 45,000 to 60,000 cfm | Engine Room | 5 | 1 | EA | \$82,940 | |
| Air Handling Systems | | Multi Zone Double Delivery Built Up Air Handling Unit Auxiliaries - Steam 45,001 to 60,000 cfm | Engine Room | 6 | 1 | EA | \$7,150 | |
| Air Handling Systems | | Return Duct Work - Indoor - Vertical Shaft and Ducts | Interior Shaft | 6 | 100 | LF | \$6,292 | |
| Air Handling Systems | | Return Duct Work - Indoor - Vertical Shaft and Ducts | Building Facade | 6 | 50 | LF | \$3,146 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|--------------------|------|----------|------|--------------------|----------------|
| Air Handling Systems | | Return Duct Work - Masonry and Ducts - Existing or Missing Exterior Shaft | Boiler Room | 4 | 100 | LF | \$264,550 | Missing System |
| Air Handling Systems | | Return Fans - Indoor greater than 20,000 CFM | Attic | 6 | 2 | EA | \$6,578 | |
| Boiler Systems | | Boiler Assembly - Steam - Low Pressure Scotch Marine Boiler 101-150 HP | Boiler Room | 5 | 1 | EA | \$62,920 | |
| Boiler Systems | | Boiler Assembly - Steam - Low Pressure Scotch Marine Boiler 101-150 HP | Boiler Room | 5 | 1 | EA | \$62,920 | |
| Boiler Systems | | Boiler Auxiliary - Steam Boiler 101-150 HP | Boiler Room | 5 | 2 | EA | \$22,880 | |
| Boiler Systems | | Chemical Feed System (Steam Boilers) | Boiler Room | 6 | 1 | EA | \$2,145 | |
| Boiler Systems | | Combustion Dampers | Boiler Room | 6 | 2 | EA | \$572 | |
| Boiler Systems | | Feed Water Pumps and Tank - Steam Boilers | Boiler Room | 6 | 1 | EA | \$8,437 | |
| Heating Devices | | Fin Tube Hot Water | Entire Building | 4 | 60 | LF | \$10,296 | |
| Heating Devices | | Radiators - Steam | Boiler Room | 4 | 1 | EA | \$1,401 | |
| Heating Devices | | Unit Heater - Electric | Entire Building | 6 | 6 | EA | \$8,580 | |
| Heating Devices | | Unit Heater - Electric | Boiler Room | 4 | 2 | EA | \$11,440 | |
| Heating Devices | | Wall Heater - Electric | Entire Building | 4 | 6 | EA | \$6,178 | |
| Mechanical Plumbing | | Piping - Condensate - Steel or Galvanized | Basement | 5 | 500 | LF | \$16,266 | |
| Mechanical Plumbing | | Piping - Steam - Steel or Galvanized | Basement | 5 | 500 | LF | \$24,739 | |
| Mechanical Plumbing | | Pumps - Vacuum | Pump and Tank Room | 6 | 1 | EA | \$2,860 | |
| Temperature Control | | Direct Digital Control (DDC) System | Entire Building | 5 | 74,800 | SF | \$374,374 | |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | Entire Building | 6 | 39 | EA | \$5,577 | |
| Temperature Control | | Zone Dampers | Entire Building | 6 | 38 | EA | \$5,434 | |
| Ventilation | | Exhaust Fan - Indoor | Kitchen | 6 | 1 | EA | \$501 | |
| Ventilation | | Exhaust Fan - Indoor | Attic | 6 | 2 | EA | \$1,001 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Lower Roof | 6 | 1 | EA | \$429 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Lower Roof | 6 | 1 | EA | \$229 | |
| MECHANICAL Sub Total | | | | | | | \$1,083,704 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------|-----------|--|-----------------|------|----------|------|----------|--------|
| Hot Water | | Hot Water Heater - Gas 150,000 -300,000 BTU/HR | Boiler Room | 4 | 1 | EA | \$22,880 | |
| Hot Water | | Hot Water Heater - Gas 150,000 -300,000 BTU/HR | Boiler Room | 6 | 1 | EA | \$4,147 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 6 | 74,800 | SF | \$8,557 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 4 | 74,800 | SF | \$48,134 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 6 | 74,800 | SF | \$11,766 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 4 | 74,800 | SF | \$34,228 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|---|--------------------|------|----------|------|------------------|--------|
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 4 | 74,800 | SF | \$40,646 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 4 | 74,800 | SF | \$178,630 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 4 | 74,800 | SF | \$147,610 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 4 | 74,800 | SF | \$85,571 | |
| Piping | | Sanitary Piping | Entire Building | 5 | 74,800 | SF | \$45,995 | |
| Piping | | Storm Piping | Entire Building | 5 | 74,800 | SF | \$35,298 | |
| Piping | | Vent Piping | Entire Building | 5 | 74,800 | SF | \$26,741 | |
| Pumps | | Domestic Booster Pump duplex | Pump and Tank Room | 6 | 1 | EA | \$3,146 | |
| Pumps | | Ejector Pump | Boiler Room | 6 | 1 | EA | \$3,003 | |
| PLUMBING Sub Total | | | | | | | \$696,353 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|---------------------------|---------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Engineer Office | 6 | 350 | SF | \$991 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | in Kitchen | 6 | 88 | SF | \$249 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 104 | 6 | 330 | SF | \$934 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 204 teachers lounge | 6 | 340 | SF | \$963 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | main office 105 | 6 | 395 | SF | \$1,118 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 105A | 6 | 160 | SF | \$453 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 108 | 6 | 860 | SF | \$2,435 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 108 | 6 | 860 | SF | \$1,230 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Engineer Office | 5 | 350 | SF | \$1,982 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 104 | 7 | 330 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 204 teachers lounge | 5 | 340 | SF | \$1,925 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | main office 105 | 7 | 395 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 105A | 7 | 160 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------------|-------------------------------|--------------------------------|---------------------|------|----------|------|-----------|--------|
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | in Kitchen | 6 | 88 | SF | \$126 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | main office 105 | 7 | 8 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | in Kitchen | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Engineer Office | 7 | 4 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 204 teachers lounge | 7 | 5 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 105A | 7 | 4 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 108 | 7 | 14 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 104 | 7 | 7 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Engineer Office | 7 | 140 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | in Kitchen | 6 | 205 | SF | \$586 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Engineer Office | 7 | 120 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | in Kitchen | 6 | 156 | SF | \$368 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 108 | 6 | 1,365 | SF | \$3,221 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 105A | 6 | 515 | SF | \$1,215 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | main office 105 | 6 | 955 | SF | \$2,253 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 204 teachers lounge | 6 | 875 | SF | \$2,065 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 104 | 6 | 955 | SF | \$2,253 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Engineer Office | 6 | 300 | SF | \$708 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Structural Glazed Tile | Engineer Office | 6 | 195 | SF | \$1,394 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Balcony Seating | 1st Floor | 7 | 110 | EA | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Main Floor Seating | 1st Floor | 7 | 245 | EA | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Sound System | 1st Floor | | | EA | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Stage Curtains | 1st Floor | 6 | 1 | EA | \$11,326 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Stage Lighting System | 1st Floor | 6 | 1 | EA | \$114,400 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------------|------------------------------|--------------------------------------|--------------------------|------|----------|------|-----------|--------|
| Corridor | | Stair Handrails | auditorium | 6 | 19 | LF | \$0 | |
| Corridor | | Stairs - Tile | auditorium | 6 | 6 | LF | \$45 | |
| Doors | | Interior Steel Doors incl hw | Entire Building | 7 | 10 | EA | \$0 | |
| Doors | | Interior Steel Doors incl hw | Entire Building | 6 | 6 | EA | \$1,699 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 5 | 36 | EA | \$16,988 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 6 | 24 | EA | \$6,795 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 7 | 7 | EA | \$0 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 4 | 39 | EA | \$125,148 | |
| Doors | | Side-lite | Entire Building | 6 | 60 | SF | \$1,115 | |
| Doors | | Transom Window | Entire Building | 6 | 630 | SF | \$11,712 | |
| Drinking Fountains | Corridors | Double Fountain | 2nd Floor | 5 | 1 | EA | \$3,289 | |
| Drinking Fountains | Corridors | Single Fountain | 2nd Floor | 6 | 1 | EA | \$386 | |
| Drinking Fountains | Corridors | Single Fountain | 3rd Floor | 7 | 1 | EA | \$0 | |
| Drinking Fountains | | Single Fountain | in 101 | 7 | 1 | EA | \$0 | |
| Drinking Fountains | Corridors | Triple Fountain | Basement | 6 | 1 | EA | \$972 | |
| Drinking Fountains | Corridors | Triple Fountain | 1st Floor | 7 | 1 | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Bleacher Seating | 3rd Floor | | | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Ceiling - Plaster/Drywall | 3rd Floor | 6 | 3,055 | SF | \$26,125 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Flooring - Tile/Sheet | 3rd Floor | 6 | 3,055 | SF | \$4,369 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Lighting - Metal Halide/Sodium Vapor | 3rd Floor | 6 | 24 | EA | \$4,290 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Scoreboards | 3rd Floor | 6 | 1 | EA | \$2,076 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Sound System | 3rd Floor | | | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Stage Curtain | 3rd Floor | | | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Walls - Plaster/Drywall | 3rd Floor | 6 | 4,320 | SF | \$37,066 | |
| Kitchen | Warming Kitchen | Ceiling - Plaster/Drywall | in lunchroom 2 | 6 | 312 | SF | \$1,178 | |
| Kitchen | Warming Kitchen | Flooring - Tile/Sheet | in lunchroom 2 | 6 | 312 | SF | \$446 | |
| Kitchen | Warming Kitchen | Lighting - Pendant/Surface | in lunchroom 2 | 7 | 5 | SF | \$0 | |
| Kitchen | Warming Kitchen | Wall - Concrete Block | in lunchroom 2 | 6 | 232 | SF | \$664 | |
| Kitchen | Warming Kitchen | Wall - Plaster/Drywall | in lunchroom 2 | 6 | 300 | SF | \$708 | |
| Kitchen | Warming Kitchen | Wall - Structural Glazed Tile | in lunchroom 2 | 5 | 162 | SF | \$7,645 | |
| Locker/Shower Room | Staff Restroom | Benches | in basement multipurpose | | | LF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------|--------------------------------------|---------|---------------------------------|------|----------|------|------|--------|
| Locker/Shower Room | Early Childhood Student Restroom | Benches | 109 | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Benches | in 101 | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | Engineers Toilet | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | 3rd floor unisex 2 | | | LF | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Benches | 1st floor unisex and accessible | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | 104 unisex | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | 204 womens | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | 204 mens | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Benches | 2nd floor girls | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Benches | 2nd floor boys | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | 3rd floor unisex 1 | | | LF | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Benches | Basement Boys | | | LF | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Benches | Basement Girls | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | in 101 | | | EA | \$0 | |
| Locker/Shower Room | Early Childhood Student Restroom | Lockers | 109 | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Lockers | Basement Girls | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | 204 womens | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | in basement multipurpose | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | 204 mens | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | 2nd floor girls | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | 2nd floor boys | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | 3rd floor unisex 1 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | 3rd floor unisex 2 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | Engineers Toilet | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Lockers | Basement Boys | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | 104 unisex | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Lockers | 1st floor unisex and accessible | | | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------|--------------------------------------|----------------------------|---------------------------------|------|----------|------|---------|--------|
| Locker/Shower Room | Staff Restroom | Showers | 104 unisex | | | EA | \$0 | |
| Locker/Shower Room | Early Childhood Student Restroom | Showers | 109 | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | in 101 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | Engineers Toilet | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 3rd floor unisex 2 | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Showers | Basement Boys | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 3rd floor unisex 1 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | in basement multipurpose | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | 2nd floor boys | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Showers | 1st floor unisex and accessible | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 204 womens | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 204 mens | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | 2nd floor girls | | | EA | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Showers | Basement Girls | | | EA | \$0 | |
| Lunchroom | Multipurpose Room | Ceiling - Plaster/Drywall | Basement- Multipurpose 1 | 6 | 313 | SF | \$886 | |
| Lunchroom | Lunchroom | Ceiling - Plaster/Drywall | Lunchroom 2- rm 002 | 6 | 677 | SF | \$1,917 | |
| Lunchroom | Multipurpose Room | Ceiling - Plaster/Drywall | Basement- Multipurpose 2 | 6 | 313 | SF | \$886 | |
| Lunchroom | Lunchroom | Ceiling - Plaster/Drywall | Lunchroom 1- rm 002 | 5 | 1,020 | SF | \$5,776 | |
| Lunchroom | Multipurpose Room | Flooring - Tile/Sheet | Basement- Multipurpose 1 | 6 | 313 | SF | \$448 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Lunchroom 1- rm 002 | 7 | 1,020 | SF | \$0 | |
| Lunchroom | Multipurpose Room | Flooring - Tile/Sheet | Basement- Multipurpose 2 | 6 | 313 | SF | \$448 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Lunchroom 2- rm 002 | 6 | 677 | SF | \$968 | |
| Lunchroom | Multipurpose Room | Lighting - Pendant/Surface | Basement- Multipurpose 2 | 4 | 1 | SF | \$7 | |
| Lunchroom | Multipurpose Room | Lighting - Pendant/Surface | Basement- Multipurpose 1 | 4 | 1 | SF | \$7 | |
| Lunchroom | Lunchroom | Lighting - Pendant/Surface | Lunchroom 1- rm 002 | 7 | 17 | SF | \$0 | |
| Lunchroom | Lunchroom | Lighting - Pendant/Surface | Lunchroom 2- rm 002 | 7 | 15 | SF | \$0 | |
| Lunchroom | Multipurpose Room | Serving Line | Basement- Multipurpose 2 | | | LF | \$0 | |
| Lunchroom | Multipurpose Room | Serving Line | Basement- Multipurpose 1 | | | LF | \$0 | |
| Lunchroom | Lunchroom | Serving Line | Lunchroom 1- rm 002 | | | LF | \$0 | |
| Lunchroom | Lunchroom | Serving Line | Lunchroom 2- rm 002 | | | LF | \$0 | |
| Lunchroom | Lunchroom | Wall - Concrete Block | Lunchroom 2- rm 002 | 6 | 727 | SF | \$2,079 | |
| Lunchroom | Multipurpose Room | Wall - Concrete Block | Basement- Multipurpose 2 | 6 | 745 | SF | \$2,131 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------------------------|--------------------------|---------------------------------|------|----------|------|---------|--------|
| Lunchroom | Multipurpose Room | Wall - Concrete Block | Basement- Multipurpose 1 | 6 | 745 | SF | \$2,131 | |
| Lunchroom | Lunchroom | Wall - Concrete Block | Lunchroom 1- rm 002 | 6 | 1,075 | SF | \$3,075 | |
| Lunchroom | Lunchroom | Wall - Plaster/Drywall | Lunchroom 2- rm 002 | 6 | 247 | SF | \$583 | |
| MDF/IDF | | Finishes | 2nd Floor | 5 | 155 | SF | \$1,738 | |
| MDF/IDF | | Ventilation and Cooling | 2nd Floor | 7 | 1 | EA | \$0 | |
| Mechanical/Service Rooms | | Janitor's Closet | Entire Building | 6 | 6 | SF | \$28 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement | 7 | 3,150 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Boiler Room | 6 | 1,180 | SF | \$5,568 | |
| Mechanical/Service Rooms | | Storage Room | 104 | 7 | 45 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | 105 main office | 6 | 22 | SF | \$104 | |
| Mechanical/Service Rooms | | Storage Room | in 101 | 7 | 105 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | 1st Floor | 6 | 800 | SF | \$3,775 | |
| Mechanical/Service Rooms | | Storage Room | 3rd Floor | 6 | 1,200 | SF | \$5,663 | |
| Mechanical/Service Rooms | | Storage Room | 108 | 6 | 80 | SF | \$378 | |
| Mechanical/Service Rooms | | Storage Room | 2nd Floor | 6 | 100 | SF | \$472 | |
| Mechanical/Service Rooms | | Storage Room | in Engineers Office | 6 | 90 | SF | \$425 | |
| Mechanical/Service Rooms | | Storage Room | in 100 | 7 | 175 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | in Science Classroom-basement | 7 | 160 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Basement under stairs | 6 | 200 | SF | \$944 | |
| Mechanical/Service Rooms | | Storage Room | in 009 | 7 | 160 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | 2nd Floor | 6 | 1,125 | SF | \$5,309 | |
| Mechanical/Service Rooms | | Vaults | main office 105 | 6 | 25 | SF | \$118 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | 109 | 7 | 125 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | 1st floor unisex and accessible | 7 | 45 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | in 101 | 7 | 44 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | Engineers Toilet | 7 | 85 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | Basement Boys | 7 | 680 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | Basement Girls | 6 | 593 | SF | \$4,579 | |
| Staff Restroom | Staff Restroom | Accessories | in basement multipurpose | 7 | 90 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 104 unisex | 7 | 35 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 204 womens | 7 | 55 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 204 mens | 7 | 50 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|---------------------------|---------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd floor girls | 7 | 215 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd floor boys | 7 | 215 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 3rd floor unisex 1 | 7 | 24 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 3rd floor unisex 2 | 7 | 24 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Lay-In | 1st floor unisex and accessible | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 104 unisex | 7 | 35 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd floor boys | 6 | 215 | SF | \$609 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | Basement Boys | 6 | 680 | SF | \$1,925 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 204 mens | 6 | 50 | SF | \$142 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 204 womens | 6 | 55 | SF | \$156 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | in basement multipurpose | 5 | 90 | SF | \$510 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Engineers Toilet | 6 | 85 | SF | \$241 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | in 101 | 7 | 44 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Plaster/Drywall | 109 | 6 | 125 | SF | \$354 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 3rd floor unisex 1 | 7 | 24 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 3rd floor unisex 2 | 7 | 24 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd floor girls | 6 | 215 | SF | \$609 | |
| Staff Restroom | Staff Restroom | Floor Drain | 3rd floor unisex 1 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 3rd floor unisex 2 | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 2nd floor boys | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 2nd floor girls | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 204 mens | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 204 womens | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | 1st floor unisex and accessible | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | in basement multipurpose | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | Basement Girls | 7 | 2 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | Basement Boys | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | Engineers Toilet | | | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|---------------------------------|------|----------|------|-------|--------|
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | in 101 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | 109 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 104 unisex | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement Boys | 7 | 680 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 3rd floor unisex 2 | 6 | 24 | SF | \$61 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement Girls | 7 | 593 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | in 101 | 7 | 44 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | 109 | 6 | 125 | SF | \$318 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 3rd floor unisex 1 | 6 | 24 | SF | \$61 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | in basement multipurpose | 6 | 90 | SF | \$129 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | 104 unisex | 7 | 35 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile/Sheet | 2nd floor boys | 6 | 215 | SF | \$307 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile/Sheet | 2nd floor girls | 6 | 215 | SF | \$307 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | 204 mens | 6 | 50 | SF | \$72 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | 204 womens | 6 | 55 | SF | \$79 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | Engineers Toilet | 6 | 85 | SF | \$122 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile/Sheet | 1st floor unisex and accessible | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | 3rd floor unisex 2 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | 104 unisex | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Hand Dryer | 109 | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | in 101 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | Engineers Toilet | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | Basement Boys | 5 | 1 | EA | \$716 | |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | Basement Girls | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | in basement multipurpose | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | 1st floor unisex and accessible | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | 204 womens | | | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------|---------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Staff Restroom | Hand Dryer | 204 mens | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 2nd floor girls | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 2nd floor boys | 6 | 1 | EA | \$217 | |
| Staff Restroom | Staff Restroom | Hand Dryer | 3rd floor unisex 1 | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | Basement Girls | 5 | 2 | EA | \$1,433 | |
| Staff Restroom | Staff Restroom | Lavatory | in basement multipurpose | 6 | 1 | EA | \$372 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | 109 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | in 101 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Engineers Toilet | 6 | 1 | EA | \$372 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | Basement Boys | 7 | 11 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | Basement Girls | 7 | 11 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 3rd floor unisex 2 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 3rd floor unisex 1 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd floor boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd floor girls | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 204 mens | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 204 womens | 6 | 2 | EA | \$744 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | 1st floor unisex and accessible | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 104 unisex | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 204 womens | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Pendant/ Surface | 109 | 7 | 2 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Engineers Toilet | 7 | 1 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Pendant/ Surface | Basement Boys | 6 | 11 | SF | \$8 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Pendant/ Surface | Basement Girls | 6 | 11 | SF | \$8 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | in basement multipurpose | 6 | 2 | SF | \$1 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Pendant/ Surface | 1st floor unisex and accessible | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 104 unisex | 7 | 1 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------|---------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd floor boys | 7 | 4 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | in 101 | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd floor girls | 7 | 4 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 204 mens | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | 104 unisex | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | 3rd floor unisex 2 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | 3rd floor unisex 1 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | Engineers Toilet | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | in 101 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 204 womens | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | Basement Boys | 7 | 4 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | Basement Girls | 7 | 16 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | in basement multipurpose | 6 | 1 | EA | \$179 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | 1st floor unisex and accessible | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 104 unisex | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 3rd floor unisex 2 | 6 | 1 | EA | \$179 | |
| Staff Restroom | Staff Restroom | Partitions | 3rd floor unisex 1 | 6 | 1 | EA | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd floor boys | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd floor girls | 6 | 6 | EA | \$1,076 | |
| Staff Restroom | Staff Restroom | Partitions | 204 mens | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Partitions | 109 | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | Basement Girls | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | 3rd floor unisex 1 | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Urinals | 109 | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | in 101 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | Engineers Toilet | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | Basement Boys | 7 | 12 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------------------------|---------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Staff Restroom | Urinals | in basement multipurpose | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | 204 womens | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | 204 mens | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 2nd floor girls | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | 1st floor unisex and accessible | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 2nd floor boys | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | 3rd floor unisex 2 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | 104 unisex | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Concrete Block | Basement Boys | 7 | 100 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Concrete Block | Basement Girls | 6 | 273 | SF | \$781 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | in basement multipurpose | 7 | 180 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 3rd floor unisex 1 | 6 | 175 | SF | \$413 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | in 101 | 7 | 365 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | 109 | 6 | 355 | SF | \$838 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Plaster/Drywall | Basement Boys | 7 | 325 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Engineers Toilet | 6 | 370 | SF | \$873 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 104 unisex | 6 | 195 | SF | \$460 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 3rd floor unisex 2 | 6 | 175 | SF | \$413 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | 2nd floor boys | 6 | 560 | SF | \$1,321 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 204 mens | 6 | 200 | SF | \$472 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 204 womens | 6 | 250 | SF | \$590 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Plaster/Drywall | 1st floor unisex and accessible | 7 | 260 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | 2nd floor girls | 6 | 560 | SF | \$1,321 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Plaster/Drywall | Basement Girls | 7 | 328 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | in basement multipurpose | 6 | 380 | SF | \$897 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Structural Glazed Tile | Basement Boys | 6 | 924 | SF | \$6,607 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Structural Glazed Tile | Basement Girls | 6 | 700 | SF | \$5,005 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|--------------------------------|---------------------------------|------|----------|------|----------|--------|
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | 204 womens | 6 | 200 | SF | \$509 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | 2nd floor boys | 7 | 445 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | 2nd floor girls | 7 | 445 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Basement Girls | 7 | 438 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | 204 mens | 6 | 170 | SF | \$433 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Basement Boys | 7 | 372 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 204 mens | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd floor girls | 6 | 6 | EA | \$2,231 | |
| Staff Restroom | Staff Restroom | Water Closet | 104 unisex | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Engineers Toilet | 6 | 1 | EA | \$372 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | 1st floor unisex and accessible | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | in basement multipurpose | 6 | 1 | EA | \$372 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | Basement Girls | 7 | 14 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | Basement Girls | 5 | 2 | EA | \$3,718 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | Basement Boys | 5 | 1 | EA | \$1,859 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | Basement Boys | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd floor boys | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | in 101 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | 109 | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 204 womens | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 3rd floor unisex 1 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 3rd floor unisex 2 | 7 | 1 | EA | \$0 | |
| Theater | Auditorium - Dedicated | Ceiling - Plaster/Drywall | 1st Floor | 6 | 3,735 | SF | \$31,939 | |
| Theater | Auditorium - Dedicated | Flooring - Tile/Sheet | 1st Floor | 6 | 845 | SF | \$1,208 | |
| Theater | Auditorium - Dedicated | Flooring - Wood | 1st Floor | 7 | 240 | SF | \$0 | |
| Theater | Auditorium - Dedicated | Flooring - Wood | 1st Floor | 6 | 3,735 | SF | \$28,201 | |
| Theater | Auditorium - Dedicated | Lighting - Pendant/ Surface | 1st Floor | 6 | 28 | SF | \$46 | |
| Theater | Auditorium - Dedicated | Lighting - Wall Mounted | 1st Floor | 6 | 10 | EA | \$286 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|------------------------|------------------------|-----------|------|----------|------|------------------|--------|
| Theater | Auditorium - Dedicated | Wall - Plaster/Drywall | 1st Floor | 6 | 5,960 | SF | \$51,137 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| INTERIOR Sub Total | | | | | | | \$611,368 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 5 | 14 | LF | \$2,503 | |
| Casework | Classroom | Casework | | 7 | 6 | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 5 | 8 | LF | \$1,430 | |
| Casework | Classroom | Casework | | 5 | 13 | LF | \$2,324 | |
| Casework | Classroom | Casework | | 5 | 27 | LF | \$4,826 | |
| Casework | Classroom | Casework | | 6 | 12 | LF | \$429 | |
| Casework | Classroom | Casework | | 5 | 8 | LF | \$1,430 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 5 | 11 | LF | \$1,966 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 5 | 8 | LF | \$1,430 | |
| Casework | Classroom | Casework | | 5 | 11 | LF | \$1,966 | |
| Casework | Classroom | Casework | | 5 | 12 | LF | \$2,145 | |
| Casework | Classroom | Casework | | 5 | 10 | LF | \$1,788 | |
| Casework | Classroom | Casework | | 5 | 8 | LF | \$1,430 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 5 | 12 | LF | \$2,145 | |
| Casework | Classroom | Casework | | 5 | 8 | LF | \$1,430 | |
| Casework | Classroom | Casework | | 5 | 11 | LF | \$1,966 | |
| Casework | Classroom | Casework | | 5 | 11 | LF | \$1,966 | |
| Casework | Classroom | Casework | | 5 | 13 | LF | \$2,324 | |
| Casework | Classroom | Casework | | 5 | 8 | LF | \$1,430 | |
| Casework | Classroom | Casework | | 5 | 13 | LF | \$2,324 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,982 | SF | \$5,612 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 930 | SF | \$2,633 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 883 | SF | \$2,500 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 883 | SF | \$2,500 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|-----------------|---------------------|------|----------|------|---------|--------|
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,073 | SF | \$3,038 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 785 | SF | \$2,223 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 905 | SF | \$2,562 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 905 | SF | \$5,125 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 905 | SF | \$2,562 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 905 | SF | \$2,562 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 905 | SF | \$2,562 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 905 | SF | \$2,562 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 905 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 905 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 905 | SF | \$2,562 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 785 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 810 | SF | \$2,293 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 3 | LF | \$365 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 2 | LF | \$243 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | 2 | LF | \$243 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | 11 | LF | \$1,337 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | 44 | LF | \$5,348 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Lunchroom | Chalk Board | Lunchroom 2- rm 002 | 4 | | LF | | |
| Chalk Board | Lunchroom | Chalk Board | Lunchroom 1- rm 002 | 4 | | LF | | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-------------------|------------------------|--------------------------|------|----------|------|----------|--------|
| Chalk Board | Multipurpose Room | Chalk Board | Basement- Multipurpose 1 | 4 | | LF | | |
| Chalk Board | Multipurpose Room | Chalk Board | Basement- Multipurpose 2 | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | 10 | LF | \$1,216 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Corridors | Corridors | Concrete Block | Basement | 6 | 1,496 | SF | \$4,279 | |
| Corridors | Corridors | Concrete Epoxy/Painted | 1st Floor | 5 | 2,400 | SF | \$11,326 | |
| Corridors | Corridors | Concrete Epoxy/Painted | 3rd Floor | 6 | 2,525 | SF | \$11,915 | |
| Corridors | Corridors | Concrete Epoxy/Painted | 2nd Floor | 6 | 2,525 | SF | \$11,915 | |
| Corridors | Corridors | Drinking Fountains | Center Stair | | | EA | \$0 | |
| Corridors | Corridors | Drinking Fountains | North and South Stairs | | | EA | \$0 | |
| Corridors | Corridors | Drinking Fountains | Grade Floor | | | EA | \$0 | |
| Corridors | Corridors | Metal Panel | Basement | 6 | 341 | SF | \$2,897 | |
| Corridors | Corridors | Pendant/Surface | North and South Stairs | 7 | 1,428 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 1st Floor | 7 | 2,525 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | Basement | 7 | 967 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 7 | 2,525 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | Grade Floor | 7 | 280 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 3rd Floor | 7 | 2,525 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | Grade Floor | 4 | 185 | EA | \$1,799 | |
| Corridors | Corridors | Pendant/Surface | Center Stair | 7 | 270 | EA | \$0 | |
| Corridors | Corridors | Plaster/Drywall | Basement | 6 | 315 | SF | \$743 | |
| Corridors | Corridors | Plaster/Drywall | Center Stair | 7 | 692 | SF | \$0 | |
| Corridors | Corridors | Plaster/Drywall | North and South Stairs | 6 | 6,756 | SF | \$15,941 | |
| Corridors | Corridors | Plaster/Drywall | 3rd Floor | 6 | 4,580 | SF | \$10,807 | |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 6 | 4,580 | SF | \$10,807 | |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 6 | 4,425 | SF | \$10,441 | |
| Corridors | Corridors | Plaster/Drywall | Grade Floor | 6 | 118 | SF | \$278 | |
| Corridors | Corridors | Single Water Cooler | 1st Floor | 7 | 4 | EA | \$0 | |
| Corridors | Corridors | Stair Handrails | Center Stair | 6 | 18 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | 2nd Floor | | | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | North and South Stairs | 6 | 266 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | Grade Floor | | | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | Basement | | | LF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|------------------------|------------------------|------|----------|------|----------|--------|
| Corridors | Corridors | Stair Handrails | 1st Floor | | | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | 3rd Floor | | | LF | \$0 | |
| Corridors | Corridors | Stairs | 2nd Floor | | | EA | \$0 | |
| Corridors | Corridors | Stairs | 3rd Floor | | | EA | \$0 | |
| Corridors | Corridors | Stairs | Grade Floor | | | EA | \$0 | |
| Corridors | Corridors | Stairs | 1st Floor | | | EA | \$0 | |
| Corridors | Corridors | Stairs | Basement | | | EA | \$0 | |
| Corridors | Corridors | Structural Glazed Tile | Grade Floor | 5 | 408 | SF | \$19,254 | |
| Corridors | Corridors | Structural Glazed Tile | Grade Floor | 6 | 378 | SF | \$2,703 | |
| Corridors | Corridors | Student Lockers | 2nd Floor | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | Center Stair | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | Grade Floor | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | Basement | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | 1st Floor | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | 3rd Floor | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | North and South Stairs | | | EA | \$0 | |
| Corridors | Corridors | Terrazzo | Basement | 7 | 130 | SF | \$0 | |
| Corridors | Corridors | Tile Ceramic/Porcelain | Center Stair | 7 | 78 | SF | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | Basement | 6 | 837 | SF | \$1,197 | |
| Corridors | Corridors | Tile/Sheet Flooring | Grade Floor | 6 | 280 | SF | \$400 | |
| Corridors | Corridors | Tile/Sheet Flooring | Grade Floor | 4 | 185 | SF | \$2,619 | |
| Corridors | Corridors | Tile/Sheet Flooring | North and South Stairs | 7 | 1,408 | SF | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | 1st Floor | 7 | 2,400 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 3rd Floor | 6 | 2,525 | SF | \$7,149 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | North and South Stairs | 7 | 1,428 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Basement | 6 | 967 | SF | \$2,738 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Grade Floor | 6 | 465 | SF | \$1,317 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Center Stair | 6 | 270 | SF | \$764 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 1st Floor | 7 | 2,400 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 2nd Floor | 7 | 2,525 | SF | \$0 | |
| Stairs | Corridors | Asphalt | Center Stair | 5 | 32 | SF | \$1,602 | |
| Stairs | Corridors | Asphalt | North and South Stairs | 6 | 432 | SF | \$3,089 | |
| Floor | Classroom | Tile/Sheet | | 6 | 930 | SF | \$1,330 | |
| Floor | Classroom | Tile/Sheet | | 6 | 810 | SF | \$1,158 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,982 | SF | \$2,834 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,073 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 810 | SF | \$1,158 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|-----------------|----------|------|----------|------|----------|--------|
| Floor | Classroom | Wood | | 6 | 810 | SF | \$6,116 | |
| Floor | Classroom | Wood | | 5 | 905 | SF | \$12,812 | |
| Floor | Classroom | Wood | | 6 | 905 | SF | \$6,833 | |
| Floor | Classroom | Wood | | 6 | 785 | SF | \$5,927 | |
| Floor | Classroom | Wood | | 6 | 905 | SF | \$6,833 | |
| Floor | Classroom | Wood | | 6 | 810 | SF | \$6,116 | |
| Floor | Classroom | Wood | | 6 | 810 | SF | \$6,116 | |
| Floor | Classroom | Wood | | 6 | 785 | SF | \$5,927 | |
| Floor | Classroom | Wood | | 6 | 810 | SF | \$6,116 | |
| Floor | Classroom | Wood | | 6 | 905 | SF | \$6,833 | |
| Floor | Classroom | Wood | | 6 | 905 | SF | \$6,833 | |
| Floor | Classroom | Wood | | 6 | 883 | SF | \$6,667 | |
| Floor | Classroom | Wood | | 6 | 905 | SF | \$6,833 | |
| Floor | Classroom | Wood | | 6 | 883 | SF | \$6,667 | |
| Floor | Classroom | Wood | | 6 | 810 | SF | \$6,116 | |
| Floor | Classroom | Wood | | 5 | 905 | SF | \$12,812 | |
| Floor | Classroom | Wood | | 6 | 810 | SF | \$6,116 | |
| Floor | Classroom | Wood | | 6 | 905 | SF | \$6,833 | |
| Floor | Classroom | Wood | | 6 | 810 | SF | \$6,116 | |
| Floor | Classroom | Wood | | 6 | 810 | SF | \$6,116 | |
| Floor | Classroom | Wood | | 6 | 810 | SF | \$6,116 | |
| Floor | Classroom | Wood | | 6 | 810 | SF | \$6,116 | |
| Floor | Classroom | Wood | | 6 | 905 | SF | \$6,833 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 17 | EA | \$6,685 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 39 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-------------------|-----------------|--------------------------|------|----------|------|---------|----------|
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 14 | EA | \$1,001 | bulb out |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 14 | EA | \$1,001 | bulb out |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 14 | EA | \$1,001 | bulb out |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 31 | LF | \$0 | |
| Marker Board | Multipurpose Room | Marker Board | Basement- Multipurpose 1 | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 50 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 36 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 26 | LF | \$744 | |
| Marker Board | Classroom | Marker Board | | 7 | 22 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 15 | LF | \$429 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 22 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 36 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 36 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 36 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 37 | LF | \$0 | |
| Marker Board | Multipurpose Room | Marker Board | Basement- Multipurpose 2 | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 34 | LF | \$0 | |
| Marker Board | Lunchroom | Marker Board | Lunchroom 1- rm 002 | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 30 | LF | \$858 | |
| Marker Board | Classroom | Marker Board | | 7 | 31 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 31 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 22 | LF | \$0 | |
| Marker Board | Lunchroom | Marker Board | Lunchroom 2- rm 002 | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 36 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 30 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 25 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------|---------------------------------|---------------------|----------------|------|----------|------|----------|--------|
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 41 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 17 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 31 | LF | \$0 | |
| RESTROOM_CEILING | Adult Standard Student Restroom | Restroom Ceiling | Basement Girls | | 593 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 222 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 220 | SF | \$0 | |
| Wall | Classroom | Masonry | | 6 | 1,113 | SF | \$14,324 | |
| Wall | Classroom | Metal/Folding Panel | | 7 | 971 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 940 | SF | \$2,218 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,235 | SF | \$2,914 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 900 | SF | \$2,124 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,465 | SF | \$3,457 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,235 | SF | \$2,914 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,545 | SF | \$3,645 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,405 | SF | \$3,315 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,545 | SF | \$3,645 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 900 | SF | \$2,124 | |
| Wall | Classroom | Plaster/Drywall | | 5 | 315 | SF | \$1,486 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,545 | SF | \$3,645 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,235 | SF | \$2,914 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,465 | SF | \$3,457 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 900 | SF | \$2,124 | |
| Wall | Classroom | Plaster/Drywall | | 5 | 315 | SF | \$1,486 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,215 | SF | \$2,867 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,175 | SF | \$2,772 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,545 | SF | \$3,645 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,215 | SF | \$2,867 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,215 | SF | \$2,867 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,215 | SF | \$2,867 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,215 | SF | \$2,867 | |
| Wall | Classroom | Plaster/Drywall | | 5 | 315 | SF | \$1,486 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,175 | SF | \$2,772 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,431 | SF | \$3,376 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,491 | SF | \$3,518 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 926 | SF | \$2,185 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|-----------------|----------|------|----------|------|------------------|--------|
| Wall | Classroom | Plaster/Drywall | | 6 | 1,405 | SF | \$3,315 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,405 | SF | \$3,315 | |
| ROOM Sub Total | | | | | | | \$516,801 | |

Building Main Sub Total \$4,931,917

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|---|------------------------------|------|----------|------|----------|--------|
| Athletic | | Basketball - Asphalt | South | 7 | 5,810 | SF | \$0 | |
| Athletic | | Football/Soccer - Synthetic including exc and retention | West | 7 | 12,104 | SF | \$0 | |
| Civil/Drainage | | Catch Basin | Entire Site | 7 | 2 | EA | \$0 | |
| Civil/Drainage | | Site Manhole | Entire Site | 7 | 10 | EA | \$0 | |
| Fencing | | Chain Link | South and North | 7 | 308 | LF | \$0 | |
| Fencing | | Chain Link | North | 4 | 193 | LF | \$20,699 | |
| Fencing | | Ornamental Iron | Entire Site | 7 | 1,369 | LF | \$0 | |
| Landscape | | Asphalt Play Area/Hardscape | South at Trash Enclosure | 7 | 1,400 | SF | \$0 | |
| Landscape | | Asphalt Play Area/Hardscape | West | 7 | 5,856 | SF | \$0 | |
| Landscape | | Asphalt Play Area/Hardscape | South/West | 6 | 2,200 | SF | \$1,888 | |
| Landscape | | Asphalt Play Area/Hardscape | South | 4 | 2,790 | SF | \$23,938 | |
| Landscape | | Grass | East/North | 7 | 3,070 | SF | \$0 | |
| Landscape | | Hardscape - Concrete | North | 7 | 1,376 | SF | \$0 | |
| Landscape | | Hardscape - Concrete | North and South | 4 | 2,393 | SF | \$45,170 | |
| Landscape | | Parkway trees | Entire Site | 7 | 31 | EA | \$0 | |
| Landscape | | Planting Beds/ Areas | South West | 7 | 2,960 | SF | \$0 | |
| Landscape | | Trash Receptacles | Entire Site | 4 | 2 | EA | \$3,289 | |
| Parking Lot | | Asphalt | Entire Site | 7 | 15,394 | SF | \$0 | |
| Parking Lot | | Concrete | West at North and South Ends | 4 | 3,234 | SF | \$61,045 | |
| Parking Lot | | Lights, Pole Mounted | Courtyard | 5 | 19 | EA | \$76,076 | |
| Parking Lot | | Trash Enclosure | South | 7 | 726 | SF | \$0 | |
| Playground | | Playground Equipment - Combo 3-12 | Entire Site | 6 | 1 | EA | \$0 | |
| Playground | | Playground Surfacing - Wood Chips | Entire Site | 4 | 2,500 | SF | \$16,088 | |
| Sidewalks | | Internal Walks | SouthWest | 7 | 370 | LF | \$0 | |
| Sidewalks | | Perimeter Sidewalks | Entire Site | 7 | 13,176 | SF | \$0 | |
| Signage | | Flag Pole | North | 7 | 1 | EA | \$0 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|--------------------------------------|----------|------|----------|------|------------------|--------|
| Signage | | Marquee - Free Standing Back Lighted | North | 6 | 1 | EA | \$0 | |
| SITE Sub Total | | | | | | | \$248,193 | |
| SITE Sub Total | | | | | | | \$248,193 | |

Total Campus Need ^{2 3} \$5,180,110

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-----------------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|---------------------|
| Building: Main | | | | | | | | | | | | | | |
| 002 | 1982 | | | | 40 | | | | N | N | N | Classroom | | |
| 009 | 1073 | 2 | 8 | 28 | 40 | 72 | 33 | | N | N | N | Classroom | | |
| 100 | 883 | 1 | 8 | 20 | 40 | 108 | 11 | 2 | N | N | N | Classroom | | |
| 101 | 883 | 1 | 7 | 20 | 40 | 149 | 19 | 2 | N | N | N | Classroom | | |
| 102 | 845 | 1 | 8 | 22 | 40 | 80 | 30 | 2 | N | N | Y | Classroom | | |
| 103 | 810 | 1 | 8 | 22 | 40 | 86 | | 2 | N | N | Y | Classroom | | |
| 106 | 845 | 1 | 8 | 18 | 40 | 80 | 30 | 2 | N | N | Y | Classroom | | |
| 107 | 785 | 1 | 8 | 22 | 40 | 86 | | 2 | N | N | Y | Classroom | | |
| 109 | 905 | 1 | 8 | 18 | 40 | 129 | | 3 | N | N | Y | Classroom | | |
| 200 | 905 | 1 | 8 | 24 | 40 | 116 | 25 | 1 | N | Y | Y | Classroom | | |
| 201 | 905 | 1 | 8 | 24 | 40 | 167 | 38 | 1 | N | N | Y | Classroom | | |
| 202 | 845 | | 30 | 38 | 40 | 80 | 30 | 2 | N | N | Y | Classroom | | |
| 203 | 810 | 1 | 8 | 22 | 40 | 86 | | 2 | N | N | Y | Classroom | | |
| 205 | 785 | 1 | 8 | 22 | 40 | 124 | 38 | | N | N | Y | Classroom | | |
| 207 | 810 | 1 | 7 | 18 | 40 | 124 | 38 | | N | N | Y | Classroom | | |
| 208 | 905 | 1 | 8 | 24 | 40 | 124 | 38 | | N | N | Y | Classroom | | |
| 209 | 905 | 1 | 8 | 24 | 40 | 186 | 57 | | N | N | N | Classroom | | |
| 300 | 905 | 2 | 34 | 66 | 40 | 86 | 36 | 1 | N | N | Y | Classroom | | |
| 301 | 905 | 1 | 8 | 18 | 40 | 78 | 36 | | N | N | N | Classroom | | |
| 302 | 845 | 1 | 8 | 18 | 40 | 100 | 50 | | N | N | Y | Classroom | | |
| 303 | 810 | 1 | 8 | 22 | 40 | 66 | 30 | 1 | N | N | Y | Classroom | | |
| 305 | 810 | 1 | 8 | 22 | 40 | 72 | 36 | | N | N | Y | Classroom | | |
| 306 | 845 | 1 | 8 | 18 | 40 | 100 | 50 | | N | N | Y | Classroom | | |
| 307 | 810 | 1 | 7 | 18 | 40 | 72 | 36 | | N | N | Y | Classroom | | |
| 308 | 905 | 1 | 8 | 24 | 40 | 72 | 30 | 1 | N | N | Y | Classroom | | |
| 309 | 905 | 1 | 8 | 24 | 40 | 72 | 30 | 1 | N | N | Y | Classroom | | |
| Basement | 930 | | | | 40 | | | | N | N | N | Classroom | | |
| Other | 2525 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | 2525 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 24 | | | | | | | | N | N | N | Restroom | Staff Restroom | 3rd floor unisex 2 |
| Other | 24 | | | | | | | | N | N | N | Restroom | Staff Restroom | 3rd floor unisex 1 |
| Other | 215 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd floor boys |
| Other | 50 | | | | | | | | N | N | N | Restroom | Staff Restroom | 204 mens |
| Other | 55 | | | | | | | | N | N | N | Restroom | Staff Restroom | 204 womens |
| Other | 340 | | | 13 | | | | | N | N | N | Administrative Suites/Offices | | 204 teachers lounge |
| Other | 215 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd floor girls |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|---------------------------------|
| Other | 88 | | | | | | | | N | N | N | Administrative Suites/Offices | | in Kitchen |
| Other | | | | | | | | | N | N | N | Corridors | | Center Stair |
| Other | 3735 | | | | | | | | N | N | N | Auditorium & Theater | Auditorium - Dedicated | 1st Floor |
| Other | 465 | | | | | | | | N | N | N | Corridors | | Grade Floor |
| Other | 967 | | | | | | | | N | N | N | Corridors | | Basement |
| Other | 313 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Multipurpose Room | Basement- Multipurpose 2 |
| Other | 313 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Multipurpose Room | Basement- Multipurpose 1 |
| Other | 90 | | | | | | | | N | N | N | Restroom | Staff Restroom | in basement multipurpose |
| Other | 593 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | Basement Girls |
| Other | 680 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | Basement Boys |
| Other | 85 | | | | | | | | N | N | N | Restroom | Staff Restroom | Engineers Toilet |
| Other | 330 | | | 10 | | | | | N | N | Y | Administrative Suites/Offices | | 104 |
| Other | 350 | | | | | | | | N | N | N | Administrative Suites/Offices | | Engineer Office |
| Other | 45 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | 1st floor unisex and accessible |
| Other | 3055 | | | | | | | | N | N | N | Gymnasia | Standard Dedicated Gymnasium | 3rd Floor |
| Other | 1020 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Lunchroom 1- rm 002 |
| Other | 677 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Lunchroom 2- rm 002 |
| Other | 312 | | | | | | | | N | N | N | Kitchen | Warming Kitchen | in lunchroom 2 |
| Other | 125 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | 109 |
| Other | 2400 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 860 | | | 22 | | | | | N | N | Y | Administrative Suites/Offices | | 108 |
| Other | 160 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | 105A |
| Other | 395 | | | 8 | | | | | N | N | Y | Administrative Suites/Offices | | main office 105 |
| Other | | | | | | | | | N | N | N | Corridors | | North and South Stairs |
| Other | 35 | | | | | | | | N | N | N | Restroom | Staff Restroom | 104 unisex |
| Other | 44 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | in 101 |