

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

- Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- Total Campus Need** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------|-----------|---|--------------------------------------|------|----------|------|----------|--------|
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | pool & laundry rm roofs | 7 | 4 | LF | \$0 | |
| Cornice | | Cornice - Masonry Projecting/Limestone | Entire Building | 7 | 2,448 | LF | \$0 | |
| Doors | | Exterior Steel Door | throughout | 7 | 3 | EA | \$0 | |
| Doors | | Exterior Wood Door | throughout | 7 | 29 | EA | \$0 | |
| Doors | | Transom Lite | throughout | 7 | 26 | EA | \$0 | |
| Entrance | | Concrete Exterior Stairs | throughout | 6 | 440 | LF | \$47,190 | |
| Entrance | | Concrete Exterior Stairs | throughout | 7 | 116 | LF | \$0 | |
| Entrance | | Entrance Controls - Audio and Video | Main Entrance | 7 | 1 | EA | \$0 | |
| Entrance | | Stair Handrails | throughout | 6 | 33 | LF | \$0 | |
| Foundation | | Masonry Foundation | Entire Building | 7 | 99,068 | SF | \$0 | |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Entire Building | 6 | 7 | EA | \$3,504 | |
| Lighting | | Exterior Lights - Wall Mounted | throughout | 6 | 4 | EA | \$858 | |
| Lintels | | Lintels - Brick | N elevation of band room - 4th floor | 7 | 60 | LF | \$0 | |
| Lintels | | Lintels - Steel | Courtyard | 6 | 672 | LF | \$25,369 | |

Building: Main
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|---|--------------------|------|----------|------|-----------|---------|
| Parapet | | Coping - Metal | auditorium roof | 7 | 487 | LF | \$0 | |
| Parapet | | Coping - Stone | Roofs | 6 | 1,556 | LF | \$0 | |
| Parapet | | Coping - Terra Cotta | Lower Roofs | 7 | 202 | LF | \$0 | |
| Parapet | | Parapet < 16" Height | Roofs | 7 | 689 | LF | \$0 | |
| Parapet | | Parapet 16" to 30" Height | Roofs | 7 | 1,556 | LF | \$0 | |
| Roof System | | Asphalt Shingle Roof | Roofs | 7 | 22,705 | SF | \$0 | |
| Roof System | | Exterior Downspouts | Roofs | 7 | 295 | LF | \$0 | |
| Roof System | | Interior Downspouts | Lower Roof | 6 | 30 | LF | \$0 | |
| Roof System | | Metal Roof | Roof | 7 | 8,279 | SF | \$0 | |
| Roof System | | Modified Bitumen Roof | Roofs | 6 | 78,611 | SF | \$556,448 | |
| Roof System | | Roof Structure: Steel with Clay Tile Arch | Roofs | 7 | 99,068 | SF | \$0 | |
| Superstructure | | Steel with Clay Tile Arch | Entire Building | 7 | 241,402 | SF | \$0 | |
| Walls | | Brick | Entire Building | 7 | 85,727 | SF | \$0 | |
| Walls | | Concrete Block | throughout | 6 | 1,000 | SF | \$6,607 | sealant |
| Walls | | Prefabricated Metal Panel Wall | Courtyard | 6 | 480 | SF | \$4,077 | |
| Walls | | Stone - Cast | Entire Building | 5 | 9,096 | SF | \$650,364 | |
| Windows | | Curtain wall - Insulated panel | Entire Building | 6 | 1,620 | SF | \$15,290 | |
| Windows | | Skylite - Glass Double-Pane | Roofs | 7 | 1,929 | SF | \$0 | |
| Windows | | Window - Guards perforated | throughout | 7 | 6,698 | SF | \$0 | |
| Windows | | Window - Guards wire guard | interior gymnasium | 7 | 1,152 | SF | \$0 | |
| Windows | | Windows - Decorative | throughout | 7 | 1,109 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum | 4th Floor | 7 | 420 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 7 | 23,460 | SF | \$0 | |

EXTERIOR Sub Total \$1,309,706

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------|-----------|---|-----------------|------|----------|------|----------|--------|
| Emergency System | | Automatic Transfer switch | 1st Floor | 4 | 1 | EA | \$8,866 | |
| Emergency System | | Emergency A/C power - Auditorium and aisle lighting | Entire Building | 4 | 10,541 | SF | \$73,107 | |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Entire Building | 4 | 16,071 | SF | \$49,410 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Entire Building | 4 | 26,552 | SF | \$47,462 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | 1st Floor | 6 | 5 | EA | \$536 | |
| Emergency System | | Exit Signs - Auditorium | Entire Building | 4 | 10 | EA | \$9,295 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Entire Building | 4 | 24 | EA | \$22,308 | |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | Entire Building | 4 | 16 | EA | \$14,872 | |

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|-----------------|------|----------|------|--------------------|--------|
| Emergency System | | Public Announcement System | Entire Building | 6 | 241,402 | SF | \$144,986 | |
| Emergency System | | Security System - Intrusion detection | Entire Building | 6 | 282,174 | SF | \$262,281 | |
| Main Service | | Main Electrical service 2000 to 3000 A 120/240/3PH | 1st Floor | 4 | 1 | EA | \$257,400 | |
| Main Service | | Main Electrical service above 3000 A 120/240/3PH | 1st Floor | 4 | 1 | EA | \$308,880 | |
| Power Distribution | | Lighting and power panels | Entire Building | 4 | 32 | EA | \$173,888 | |
| Power Distribution | | Main distribution panels 400-600 amp | Entire Building | 4 | 7 | EA | \$85,085 | |
| Power Distribution | | Main distribution panels above 600 amp | Entire Building | 4 | 2 | EA | \$37,180 | |
| Power Distribution | | Main distribution panels above 600 amp | Entire Building | 4 | 5 | EA | \$92,950 | |
| Power Distribution | | Main distribution panels less than 400 amp | Entire Building | 4 | 3 | EA | \$19,734 | |
| ELECTRICAL Sub Total | | | | | | | \$1,608,240 | |

Building: Main
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|--------------------------|-----------------|------|----------|------|--------------------|--|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 3 | 241,402 | SF | \$510,903 | Strobe lights are not provided or not located in all areas |
| Fire Alarm | | Fire Alarm System | 1st Floor | 4 | 241,402 | SF | \$852,656 | |
| FIRE PROTECTION Sub Total | | | | | | | \$1,363,559 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|---|------|----------|------|-----------|--|
| Air Conditioning | | Window A/C Unit | Entire Building | 5 | 27 | EA | \$28,958 | |
| Air Handling Systems | | Air Handling Unit Package - Single Zone - Steam 4,000 to 8,000 cfm | Attic | 6 | 1 | EA | \$5,005 | |
| Air Handling Systems | | Air Intake - Built Up Air Handling Unit | 1st Floor | 6 | 5 | EA | \$7,150 | |
| Air Handling Systems | | Multi Zone Double Delivery Built Up Air Handling Unit - Steam 15,000 to 30,000 cfm | 1st Floor | 4 | 4 | EA | \$457,600 | Unit is more than 40 years of age and the unit is operable |
| Air Handling Systems | | Multi Zone Double Delivery Built Up Air Handling Unit Auxiliaries - Steam 15,000 to 30,000 cfm | 1st Floor | 4 | 4 | EA | \$143,000 | |
| Air Handling Systems | | Single Zone Built Up Air Handling Unit - Steam 4,000 to 8,000 cfm | mezzanine over 1st Flr - North corridor | 4 | 3 | EA | \$77,220 | |
| Air Handling Systems | | Single Zone Built Up Air Handling Unit Auxiliaries - Steam 4,000 to 8,000 cfm | Mezzanine over 1st Flr - North corridor | 4 | 3 | EA | \$21,450 | |
| Heating Devices | | Unit Heater - Hot Water | Entire Building | 6 | 4 | EA | \$5,720 | |
| Heating Devices | | Wall Heater - Electric | Entire Building | 6 | 21 | EA | \$2,162 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|-----------------|------|----------|------|--------------------|--------|
| Mechanical Plumbing | | Piping - Condensate - Steel or Galvanized | 1st Floor | 4 | 2,000 | LF | \$195,910 | |
| Mechanical Plumbing | | Piping - Steam - Steel or Galvanized | Entire Building | 4 | 2,000 | LF | \$239,525 | |
| Temperature Control | | Thermostats - Pneumatic | 1st Floor | 4 | 89 | EA | \$58,544 | |
| Temperature Control | | Zone Dampers | 1st Floor | 6 | 89 | EA | \$12,727 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 4 | 9 | EA | \$38,610 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 4 | 9 | EA | \$20,592 | |
| Ventilation | | Exhaust Fans - Roof mounted less than 500 CFM | Roof | 4 | 1 | EA | \$1,573 | |
| Ventilation | | Type I Exhaust Hood - Kitchen or Culinary Arts | 2nd Floor | 4 | 1 | EA | \$26,884 | |
| MECHANICAL Sub Total | | | | | | | \$1,342,630 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|--|-----------------|------|----------|------|--------------------|--|
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 4 | 241,402 | SF | \$79,397 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 4 | 241,402 | SF | \$155,342 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 4 | 241,402 | SF | \$51,781 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 4 | 241,402 | SF | \$110,466 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 4 | 241,402 | SF | \$131,178 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 4 | 241,402 | SF | \$576,492 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 4 | 241,402 | SF | \$476,383 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 4 | 241,402 | SF | \$276,164 | |
| Piping | | Sanitary Piping | Entire Building | 5 | 241,402 | SF | \$148,438 | |
| Piping | | Storm Piping | Entire Building | 5 | 241,402 | SF | \$113,918 | |
| Piping | | Vent Piping | Entire Building | 5 | 241,402 | SF | \$86,301 | |
| Pool Systems | | Pool Drain Piping | 1st Floor | 4 | 200 | LF | \$34,320 | |
| Pool Systems | | Pool Filtration System | 1st Floor | 4 | 1 | EA | \$217,360 | |
| Pool Systems | | Pool Hot Water Heater - Steam Heat Exchanger | 1st Floor | 3 | 1 | EA | \$13,013 | Heat exchanger is more than 20 years of age and is leaking and is rusted |
| Pool Systems | | Pool Supply and Return Piping | 1st Floor | 4 | 200 | LF | \$31,460 | |
| Pumps | | Sump Pump | crawl space | 6 | 1 | EA | \$1,359 | |
| PLUMBING Sub Total | | | | | | | \$2,503,371 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------|----------|------|----------|------|------|--------|
|-------|-----------|------|----------|------|----------|------|------|--------|

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|---------------------------|-----------------------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Exposed | Teacher's Office in Room 130 | 7 | 95 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | PE Instructor's Office | 6 | 91 | SF | \$258 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 121 | 6 | 680 | SF | \$1,925 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Principal's Office (inaccessible) | 6 | 200 | SF | \$566 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 212 | 6 | 680 | SF | \$1,925 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Main Office | 6 | 1,600 | SF | \$4,530 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Additional Office in Pool Area | 6 | 136 | SF | \$385 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Gym Teacher's Office | 6 | 135 | SF | \$382 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 109 | 6 | 740 | SF | \$2,095 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Gym Teacher's Office | 7 | 128 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 305/309 Prep Room | 6 | 262 | SF | \$742 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Faculty Luncheon | 6 | 687 | SF | \$1,945 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office in Library Room 207 | 6 | 192 | SF | \$544 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 100 Asst. Principal's Office | 6 | 211 | SF | \$597 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 209, Faculty Lounge | 6 | 1,769 | SF | \$5,009 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 338 | 6 | 367 | SF | \$1,039 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | Room 117 | 6 | 680 | SF | \$1,459 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | Kitchen Manager's Office | 6 | 65 | SF | \$139 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Main Office | 6 | 1,600 | SF | \$2,288 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Principal's Office (inaccessible) | 6 | 200 | SF | \$286 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Terrazzo | PE Instructor's Office | 7 | 91 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Terrazzo | Additional Office in Pool Area | 7 | 136 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|----------------------------|-----------------------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Flooring - Terrazzo | Kitchen Manager's Office | 7 | 65 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 117 | 6 | 680 | SF | \$972 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Teacher's Office in Room 130 | 7 | 95 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 121 | 5 | 680 | SF | \$3,851 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 100 Asst. Principal's Office | 5 | 211 | SF | \$1,195 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office in Library Room 207 | 7 | 192 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 209, Faculty Lounge | 6 | 1,769 | SF | \$2,530 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Faculty Luncheon | 6 | 687 | SF | \$982 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 305/309 Prep Room | 6 | 262 | SF | \$375 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 109 | 6 | 740 | SF | \$1,058 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Wood | Room 338 | 6 | 367 | SF | \$2,771 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Wood | Gym Teacher's Office | 7 | 128 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Wood | Gym Teacher's Office | 7 | 135 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Wood | Room 212 | 6 | 680 | SF | \$5,134 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office in Library Room 207 | 4 | 4 | SF | \$26 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 109 | 4 | 10 | SF | \$66 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Principal's Office (inaccessible) | 4 | 4 | SF | \$26 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Main Office | 4 | 20 | SF | \$132 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 100 Asst. Principal's Office | 4 | 4 | SF | \$26 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Gym Teacher's Office | 4 | 2 | SF | \$13 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Additional Office in Pool Area | 4 | 2 | SF | \$13 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | PE Instructor's Office | 4 | 1 | SF | \$7 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|----------------------------|-----------------------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 121 | 4 | 10 | SF | \$66 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 209, Faculty Lounge | 4 | 30 | SF | \$197 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Teacher's Office in Room 130 | 4 | 1 | SF | \$7 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Faculty Luncheon | 4 | 12 | SF | \$79 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Kitchen Manager's Office | 4 | 1 | SF | \$7 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 305/309 Prep Room | 4 | 4 | SF | \$26 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 338 | 4 | 6 | SF | \$39 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 212 | 4 | 12 | SF | \$79 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Gym Teacher's Office | 4 | 2 | SF | \$13 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 117 | 4 | 12 | SF | \$79 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 121 | 6 | 1,230 | SF | \$2,902 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Main Office | 6 | 2,000 | SF | \$4,719 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 109 | 6 | 1,300 | SF | \$3,067 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Principal's Office (inaccessible) | 6 | 780 | SF | \$1,840 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 117 | 6 | 1,230 | SF | \$2,902 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 100 Asst. Principal's Office | 6 | 780 | SF | \$1,840 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Gym Teacher's Office | 7 | 325 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Additional Office in Pool Area | 6 | 523 | SF | \$1,234 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | PE Instructor's Office | 7 | 407 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Gym Teacher's Office | 6 | 462 | SF | \$1,090 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Teacher's Office in Room 130 | 7 | 229 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 209, Faculty Lounge | 6 | 1,784 | SF | \$4,209 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------------|-------------------------------|--------------------------------------|----------------------------|------|----------|------|----------|--------|
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office in Library Room 207 | 6 | 614 | SF | \$1,449 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 305/309 Prep Room | 7 | 721 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Kitchen Manager's Office | 6 | 223 | SF | \$526 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 338 | 6 | 955 | SF | \$2,253 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 212 | 6 | 1,204 | SF | \$2,841 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Faculty Luncheon | 7 | 1,784 | SF | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Balcony Seating | 1st Floor | 7 | 900 | EA | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Main Floor Seating | 1st Floor | 7 | 996 | EA | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Sound System | 1st Floor | 7 | 1 | EA | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Stage Curtains | 1st Floor | 7 | 8 | EA | \$0 | |
| Auditorium - Dedicated | Auditorium - Dedicated | Stage Lighting System | 1st Floor | 7 | 3 | EA | \$0 | |
| Band Room | Classroom | Instrument Storage Casework | | 6 | 120 | LF | \$6,864 | |
| Choral Room | | Risers | Room 212 | 7 | 240 | LF | \$0 | |
| Choral Room | Classroom | Risers | | 7 | 240 | LF | \$0 | |
| Corridor | | Stair Handrails | Entire Building | 7 | 1,860 | LF | \$0 | |
| Corridor | | Stairs - Terrazzo | Entire Building | 7 | 861 | LF | \$0 | |
| Corridor | | Student Lockers | Entire Building | 7 | 1,911 | EA | \$0 | |
| Doors | | Interior Steel Doors incl hw | throughout | 7 | 10 | EA | \$0 | |
| Doors | | Interior Wood Doors incl hw | throughout | 7 | 132 | EA | \$0 | |
| Doors | | Interior Wood Doors incl hw | throughout | 6 | 65 | EA | \$18,404 | |
| Doors | | Side-lite | throughout | 7 | 30 | SF | \$0 | |
| Doors | | Store Front Door | throughout | 7 | 9 | EA | \$0 | |
| Doors | | Transom Window | throughout | 7 | 338 | SF | \$0 | |
| Drinking Fountains | | Single Fountain | Entire Building | 7 | 15 | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Ceiling - Exposed | 1st Floor | 6 | 10,541 | SF | \$80,192 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Ceiling - Plaster/Drywall | 2nd Floor | 6 | 5,095 | SF | \$43,569 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Flooring - Wood | 1st Floor | 7 | 10,541 | SF | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Flooring - Wood | 2nd Floor | 7 | 5,095 | SF | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Lighting - Metal Halide/Sodium Vapor | 2nd Floor | 7 | 20 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|------------------------------|--------------------------------------|-------------------------------|------|----------|------|----------|--------|
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 7 | 24 | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Scoreboards | 1st Floor | 7 | 1 | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Sound System | 1st Floor | 7 | 1 | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Walls - Plaster/Drywall | 1st Floor | 7 | 6,109 | SF | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Walls - Structural Glazed Tile | 2nd Floor | 7 | 5,994 | SF | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Walls - Structural Glazed Tile | 1st Floor | 7 | 6,109 | SF | \$0 | |
| Kitchen | Cooking Kitchen | Ceiling - Splined | 2nd Floor | 6 | 1,139 | SF | \$3,258 | |
| Kitchen | Cooking Kitchen | Flooring - Tile Quarry | 2nd Floor | 7 | 1,139 | SF | \$0 | |
| Kitchen | Cooking Kitchen | Lighting - Pendant/Surface | 2nd Floor | 4 | 20 | SF | \$132 | |
| Kitchen | Cooking Kitchen | Wall - Plaster/Drywall | 2nd Floor | 7 | 1,786 | SF | \$0 | |
| Library | Library | Flooring Tile/ Sheet | Room 207 | 6 | 2,160 | SF | \$3,089 | |
| Library | Library | Lighting - Pendant/ Surface | Room 207 | 4 | 32 | SF | \$210 | |
| Locker/Shower Room | Locker/Shower Room | Benches | Girl's Locker Room, 1st Floor | 7 | 60 | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | In Kitchen Area | 6 | 18 | EA | \$883 | |
| Locker/Shower Room | Locker/Shower Room | Lockers | Girl's Locker Room, 1st Floor | 6 | 600 | EA | \$29,447 | |
| Locker/Shower Room | Locker/Shower Room | Showers | Girl's Locker Room, 1st Floor | 6 | 28 | EA | \$6,807 | |
| Lunchroom | Lunchroom | Ceiling - Splined | 2nd Floor | 6 | 10,916 | SF | \$23,415 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | 2nd Floor | 6 | 10,916 | SF | \$15,610 | |
| Lunchroom | Lunchroom | Lighting - Lay-In | 2nd Floor | 4 | 150 | SF | \$697 | |
| Lunchroom | Lunchroom | Serving Line | 2nd Floor | 7 | 164 | LF | \$0 | |
| Lunchroom | Lunchroom | Wall - Plaster/Drywall | 2nd Floor | 7 | 12,120 | SF | \$0 | |
| MDF/IDF | | Finishes | Room 210 | 6 | 125 | SF | \$425 | |
| MDF/IDF | | Ventilation and Cooling | Room 210 | 7 | 1 | EA | \$0 | |
| Mechanical/Service Rooms | | Crawl Space - Unfinished | Basement | 7 | 10,400 | SF | \$0 | |
| Mechanical/Service Rooms | | Janitor's Closet | Entire Building | 7 | 12 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Store Rooms next to Room 133 | 6 | 650 | SF | \$3,067 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Motors Room next to 214 | 7 | 100 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 2nd Floor | 7 | 467 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Engine Room 4 | 6 | 195 | SF | \$920 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Engine Room 3 | 6 | 195 | SF | \$920 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|---|--------------------------|--|------|----------|------|----------|--------|
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Fan Room above Room 133 | 6 | 100 | SF | \$472 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | In Girl's Locker Room | 7 | 279 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 1st Floor | 7 | 387 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 1st Floor | 7 | 387 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 1st Floor | 7 | 60 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Unit 3 East Chamber | 6 | 211 | SF | \$996 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 2nd Floor | 7 | 27 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | In Main Office | 7 | 100 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | 2nd Floor | 7 | 464 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | In Room 207, Library | 7 | 125 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Room 133 | 5 | 1,700 | SF | \$19,254 | |
| Mechanical/Service Rooms | | Storage Room | 1st Floor | 6 | 41 | SF | \$193 | |
| Mechanical/Service Rooms | | Storage Room | In the 1st Floor Gym | 7 | 708 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Room 216/220 Work Room | 6 | 155 | SF | \$731 | |
| Mechanical/Service Rooms | | Storage Room | Room 102 | 6 | 260 | SF | \$1,227 | |
| Mechanical/Service Rooms | | Storage Room | In the Girl's Locker Room | 7 | 197 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | In Room 100 | 6 | 80 | SF | \$378 | |
| Mechanical/Service Rooms | | Storage Room | Room 131 | 6 | 1,500 | SF | \$7,079 | |
| Mechanical/Service Rooms | | Storage Room | Room 129 | 6 | 1,700 | SF | \$8,022 | |
| Mechanical/Service Rooms | | Storage Room | In Room 130 | 7 | 203 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | 2nd Storage in Room 130 | 7 | 107 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Room 128B Formerly Women's Teacher's Toilet | 6 | 164 | SF | \$774 | |
| Mechanical/Service Rooms | | Storage Room | Room 128 | 6 | 164 | SF | \$774 | |
| Mechanical/Service Rooms | | Storage Room | 1st Floor | 6 | 1,293 | SF | \$6,102 | |
| Mechanical/Service Rooms | | Vaults | Room 222 | 7 | 105 | SF | \$0 | |
| Mechanical/Service Rooms | | Vaults | Main Office | 7 | 50 | SF | \$0 | |
| Music Room | Classroom | Sound Panels | | 6 | 1,000 | SF | \$2,431 | |
| Staff Restroom | Staff Restroom | Accessories | In Principal's Office | 6 | 38 | SF | \$293 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 1st Floor Southeast Boy's Room | 6 | 285 | SF | \$2,201 | |
| Staff Restroom | Locker/Shower Room | Accessories | Girl's Locker Room, 1st Floor | 7 | 4,818 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 3rd Floor Northeast Girl's Room | 7 | 292 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd Floor Northeast Girl's Room | 7 | 292 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd Floor Northwest Girl's Room | 7 | 292 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------|-------------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Staff Restroom | Accessories | In Main Office | 6 | 38 | SF | \$293 | |
| Staff Restroom | Staff Restroom | Accessories | 1st Floor Northeast Women's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | Room 130 | 7 | 33 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd Floor Southwest Boy's Room | 6 | 285 | SF | \$2,201 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 1st Floor Southwest Boy's Room | 6 | 285 | SF | \$2,201 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd Floor Northeast Women's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Staff Restroom | Accessories | In Kitchen Area | 6 | 241 | SF | \$1,861 | |
| Staff Restroom | Staff Restroom | Accessories | In Room 100 | 6 | 38 | SF | \$293 | |
| Staff Restroom | Staff Restroom | Accessories | 1st Floor Southeast Men's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 1st Floor Northwest Girl's Room | 7 | 292 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd Floor Southeast Boy's Room | 6 | 285 | SF | \$2,201 | |
| Staff Restroom | Staff Restroom | Accessories | 3rd Floor Southwest Men's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Staff Restroom | Accessories | Room 128C Women Janitor's Rest room | 6 | 164 | SF | \$1,266 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 3rd Floor Northwest Girl's Room | 7 | 292 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd Floor Southeast Men's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Staff Restroom | Accessories | 3rd Floor Southeast Men's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd Floor Southwest Men's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 3rd Floor Southwest Boy's Room | 6 | 285 | SF | \$2,201 | |
| Staff Restroom | Staff Restroom | Accessories | 3rd Floor Northeast Women's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Staff Restroom | Accessories | 1st Floor Northwest Women's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd Floor Northwest Women's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 1st Floor Northeast Girl's Room | 7 | 292 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 3rd Floor Southeast Boy's Room | 6 | 285 | SF | \$2,201 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|---------------------------|-------------------------------------|------|----------|------|----------|--------|
| Staff Restroom | Staff Restroom | Accessories | 3rd Floor Northwest Women's Room | 6 | 45 | SF | \$347 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Lay-In | Room 130 | 7 | 33 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 1st Floor Southeast Boy's Room | 6 | 285 | SF | \$807 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 3rd Floor Southwest Boy's Room | 6 | 285 | SF | \$807 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 3rd Floor Southeast Boy's Room | 6 | 285 | SF | \$807 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 1st Floor Northeast Girl's Room | 6 | 292 | SF | \$827 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 3rd Floor Northwest Girl's Room | 6 | 292 | SF | \$827 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Southwest Boy's Room | 6 | 285 | SF | \$807 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 1st Floor Southwest Boy's Room | 6 | 285 | SF | \$807 | |
| Staff Restroom | Locker/Shower Room | Ceiling - Plaster/Drywall | Girl's Locker Room, 1st Floor | 6 | 4,818 | SF | \$13,642 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 1st Floor Northwest Girl's Room | 6 | 292 | SF | \$827 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd Floor Southwest Men's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 3rd Floor Southeast Men's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 3rd Floor Northeast Girl's Room | 6 | 292 | SF | \$827 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Main Office | 6 | 38 | SF | \$108 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd Floor Southeast Men's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Room 128C Women Janitor's Rest room | 7 | 164 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Northeast Girl's Room | 6 | 292 | SF | \$827 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 1st Floor Southeast Men's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 3rd Floor Southwest Men's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Southeast Boy's Room | 6 | 285 | SF | \$807 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Kitchen Area | 6 | 241 | SF | \$682 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Principal's Office | 6 | 38 | SF | \$108 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|---------------------------|----------------------------------|------|----------|------|-------|--------|
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Room 100 | 6 | 38 | SF | \$108 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Northwest Girl's Room | 6 | 292 | SF | \$827 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd Floor Northwest Women's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 3rd Floor Northwest Women's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 1st Floor Northeast Women's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd Floor Northeast Women's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 3rd Floor Northeast Women's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 1st Floor Northwest Women's Room | 6 | 45 | SF | \$127 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 1st Floor Northwest Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 1st Floor Southwest Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 1st Floor Southeast Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 3rd Floor Northwest Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Locker/Shower Room | Floor Drain | Girl's Locker Room, 1st Floor | 7 | 12 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 2nd Floor Southwest Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 1st Floor Northeast Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 3rd Floor Southeast Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 3rd Floor Southwest Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 2nd Floor Southeast Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 2nd Floor Northwest Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 3rd Floor Northeast Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 2nd Floor Northeast Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 2nd Floor Northeast Women's Room | 7 | 45 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|---------------------|----------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 2nd Floor Southwest Boy's Room | 7 | 285 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 1st Floor Southwest Boy's Room | 7 | 285 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 1st Floor Northeast Women's Room | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 3rd Floor Northeast Women's Room | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 1st Floor Northwest Women's Room | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 2nd Floor Northwest Women's Room | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 3rd Floor Northwest Women's Room | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 2nd Floor Southeast Men's Room | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 3rd Floor Southeast Men's Room | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 1st Floor Southeast Men's Room | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | In Room 100 | 6 | 38 | SF | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 2nd Floor Northeast Girl's Room | 6 | 292 | SF | \$1,378 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | In Principal's Office | 6 | 38 | SF | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 2nd Floor Southeast Boy's Room | 7 | 285 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 2nd Floor Northwest Girl's Room | 6 | 292 | SF | \$1,378 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 2nd Floor Southwest Men's Room | 7 | 45 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | 3rd Floor Southwest Men's Room | 7 | 45 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 3rd Floor Southwest Boy's Room | 7 | 285 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 3rd Floor Southeast Boy's Room | 7 | 285 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 1st Floor Northwest Girl's Room | 6 | 292 | SF | \$1,378 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 3rd Floor Northwest Girl's Room | 6 | 292 | SF | \$1,378 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 1st Floor Northeast Girl's Room | 6 | 292 | SF | \$1,378 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 1st Floor Southeast Boy's Room | 7 | 285 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|-------------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | 3rd Floor Northeast Girl's Room | 6 | 292 | SF | \$1,378 | |
| Staff Restroom | Locker/Shower Room | Flooring - Concrete | Girl's Locker Room, 1st Floor | 7 | 4,818 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | Room 130 | 7 | 33 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Room 128C Women Janitor's Rest room | 6 | 164 | SF | \$417 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | In Main Office | 5 | 38 | SF | \$215 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | In Kitchen Area | 6 | 241 | SF | \$345 | |
| Staff Restroom | Locker/Shower Room | Hand Dryer | Girl's Locker Room, 1st Floor | 7 | 35 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | In Kitchen Area | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Main Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Principal's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | Room 130 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 3rd Floor Northeast Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Room 128C Women Janitor's Rest room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Room 100 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Locker/Shower Room | Lavatory | Girl's Locker Room, 1st Floor | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Kitchen Area | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 1st Floor Northeast Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 2nd Floor Northeast Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 1st Floor Northeast Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 3rd Floor Southwest Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 1st Floor Northwest Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 2nd Floor Southwest Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 3rd Floor Northwest Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 3rd Floor Southeast Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 3rd Floor Northeast Girl's Room | 7 | 1 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------|----------------------------------|------|----------|------|------|--------|
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd Floor Northeast Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd Floor Northwest Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 1st Floor Southeast Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 2nd Floor Southeast Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 3rd Floor Southwest Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 3rd Floor Southeast Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd Floor Southwest Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 2nd Floor Northwest Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd Floor Southeast Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 1st Floor Southwest Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 1st Floor Southeast Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 3rd Floor Northwest Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 1st Floor Northwest Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Lay-In | Room 130 | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 3rd Floor Southwest Boy's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 3rd Floor Northeast Women's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 3rd Floor Southeast Boy's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 2nd Floor Southeast Men's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 3rd Floor Southwest Men's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 1st Floor Southeast Men's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 1st Floor Northeast Girl's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Northeast Girl's Room | 4 | 7 | SF | \$30 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------|-------------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 3rd Floor Northeast Girl's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 3rd Floor Southeast Men's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Southeast Boy's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 3rd Floor Northwest Women's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 1st Floor Northwest Girl's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 1st Floor Northwest Women's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 2nd Floor Southwest Men's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 2nd Floor Northeast Women's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 1st Floor Northeast Women's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In Kitchen Area | 4 | 3 | SF | \$13 | |
| Staff Restroom | Locker/Shower Room | Lighting - Pendant/ Surface | Girl's Locker Room, 1st Floor | 4 | 70 | SF | \$300 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In Room 100 | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In Main Office | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In Principal's Office | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Room 128C Women Janitor's Rest room | 4 | 2 | SF | \$9 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 2nd Floor Northwest Women's Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 1st Floor Southeast Boy's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 1st Floor Southwest Boy's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Northwest Girl's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Southwest Boy's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 3rd Floor Northwest Girl's Room | 4 | 7 | SF | \$30 | |
| Staff Restroom | Locker/Shower Room | Partitions | Girl's Locker Room, 1st Floor | 6 | 20 | EA | \$3,586 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd Floor Southeast Boy's Room | 6 | 2 | EA | \$359 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------|-------------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Partitions | 1st Floor Southwest Boy's Room | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 1st Floor Southeast Boy's Room | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 3rd Floor Northwest Girl's Room | 6 | 8 | EA | \$1,435 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 1st Floor Northwest Girl's Room | 6 | 8 | EA | \$1,435 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 1st Floor Northeast Girl's Room | 6 | 8 | EA | \$1,435 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 3rd Floor Southeast Boy's Room | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 3rd Floor Southwest Boy's Room | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd Floor Northwest Girl's Room | 6 | 8 | EA | \$1,435 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd Floor Southwest Boy's Room | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 3rd Floor Northeast Girl's Room | 6 | 8 | EA | \$1,435 | |
| Staff Restroom | Staff Restroom | Partitions | In Room 100 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | In Main Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | Room 128C Women Janitor's Rest room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd Floor Northeast Girl's Room | 6 | 8 | EA | \$1,435 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 2nd Floor Southeast Boy's Room | 7 | 7 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 2nd Floor Southwest Boy's Room | 7 | 7 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 1st Floor Southwest Boy's Room | 7 | 7 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 1st Floor Southeast Boy's Room | 7 | 7 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 3rd Floor Southeast Boy's Room | 7 | 7 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 3rd Floor Southwest Boy's Room | 7 | 7 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 3rd Floor Northwest Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 1st Floor Northeast Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 1st Floor Southwest Boy's Room | 7 | 342 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|------------------------|-------------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 1st Floor Northeast Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 1st Floor Southeast Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 3rd Floor Northeast Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 3rd Floor Northwest Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 1st Floor Northwest Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 3rd Floor Southeast Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 3rd Floor Southwest Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 1st Floor Northwest Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 2nd Floor Southwest Men's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 2nd Floor Northwest Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 2nd Floor Southeast Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 2nd Floor Northwest Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 2nd Floor Northeast Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 3rd Floor Northeast Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 1st Floor Southeast Men's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 2nd Floor Southwest Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 3rd Floor Southeast Men's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 2nd Floor Southeast Men's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 3rd Floor Southwest Men's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 2nd Floor Northeast Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In Kitchen Area | 6 | 804 | SF | \$1,897 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Room 128C Women Janitor's Rest room | 6 | 327 | SF | \$772 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------------------------|----------------------------------|------|----------|------|-------|--------|
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | Room 130 | 7 | 216 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In Principal's Office | 6 | 240 | SF | \$566 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In Room 100 | 6 | 240 | SF | \$566 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In Main Office | 6 | 240 | SF | \$566 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 2nd Floor Southwest Men's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Locker/Shower Room | Wall - Structural Glazed Tile | Girl's Locker Room, 1st Floor | 7 | 5,604 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 1st Floor Northeast Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 2nd Floor Northeast Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 3rd Floor Northeast Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 1st Floor Northwest Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 2nd Floor Northwest Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 3rd Floor Northwest Women's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 2nd Floor Southeast Men's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 3rd Floor Southeast Men's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 3rd Floor Northeast Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Northwest Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 3rd Floor Southwest Men's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | 1st Floor Southeast Men's Room | 7 | 75 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 3rd Floor Southwest Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 3rd Floor Southeast Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 1st Floor Northeast Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 1st Floor Northwest Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 3rd Floor Northwest Girl's Room | 7 | 347 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------------------------|-------------------------------------|------|----------|------|------|--------|
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 1st Floor Southeast Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 1st Floor Southwest Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Southwest Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Southeast Boy's Room | 7 | 342 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Northeast Girl's Room | 7 | 347 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 3rd Floor Southwest Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Room 128C Women Janitor's Rest room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd Floor Southwest Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In Kitchen Area | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd Floor Southwest Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 1st Floor Southeast Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 3rd Floor Southwest Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 3rd Floor Southeast Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 1st Floor Northeast Girl's Room | 7 | 9 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In Main Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 1st Floor Northwest Girl's Room | 7 | 9 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In Room 100 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Locker/Shower Room | Water Closet | Girl's Locker Room, 1st Floor | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 3rd Floor Northwest Girl's Room | 7 | 9 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 1st Floor Southeast Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd Floor Northwest Girl's Room | 7 | 9 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 1st Floor Southwest Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 1st Floor Northwest Women's Room | 7 | 1 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------|--------------------------------------|---|----------------------------------|------|----------|------|-----------|--------|
| Staff Restroom | Staff Restroom | Water Closet | In Principal's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd Floor Southeast Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 1st Floor Northeast Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 3rd Floor Northeast Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd Floor Northwest Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 3rd Floor Northwest Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd Floor Southeast Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 3rd Floor Southeast Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 3rd Floor Northeast Girl's Room | 7 | 9 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd Floor Northeast Girl's Room | 7 | 9 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd Floor Northeast Women's Room | 7 | 1 | EA | \$0 | |
| Swimming Pool | | Accessories | 1st Floor | 7 | 3,548 | SF | \$0 | |
| Swimming Pool | | Bleacher Seating/Plank seating | 1st Floor | 7 | 95 | EA | \$0 | |
| Swimming Pool | | Lighting Pendant - Metal Halide/ High Pressure Sodium | 1st Floor | 7 | 36 | SF | \$0 | |
| Swimming Pool | | Pool Basin | 1st Floor | 6 | 1,515 | SF | \$42,896 | |
| Swimming Pool | | Pool Deck | 1st Floor | 7 | 2,024 | SF | \$0 | |
| Swimming Pool | | Pool deck drains | 1st Floor | 7 | 12 | EA | \$0 | |
| Swimming Pool | | Splined Ceiling including access | 1st Floor | 6 | 3,548 | SF | \$38,052 | |
| Swimming Pool | | Structural Glazed Tile | 1st Floor | 7 | 2,194 | SF | \$0 | |
| Theater | Auditorium - Dedicated | Ceiling - Plaster/Drywall | 1st Floor | 7 | 10,541 | SF | \$0 | |
| Theater | Auditorium - Dedicated | Flooring - Carpet | 1st Floor | 6 | 10,541 | SF | \$15,074 | |
| Theater | Auditorium - Dedicated | Lighting - Pendant/ Surface | 1st Floor | 7 | 56 | SF | \$0 | |
| Theater | | Stage Platform | 1st Floor | 7 | 1,152 | SF | \$0 | |
| Theater | Auditorium - Dedicated | Wall - Plaster/Drywall | 1st Floor | 6 | 13,456 | SF | \$115,452 | |
| Vertical Conveyance | | Elevator - Traction | Entire Building | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 5 | 1 | EA | \$1,931 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 4 | EA | \$1,544 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 2 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 2 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-----------|----------|------|----------|------|------------------|--------|
| Vocational Shop | Classroom | Work Sink | | 7 | 2 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 2 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 2 | EA | \$0 | |
| INTERIOR Sub Total | | | | | | | \$654,379 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|----------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 6 | 100 | LF | \$3,575 | |
| Casework | Classroom | Casework | | 6 | 100 | LF | \$3,575 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 6 | 100 | LF | \$3,575 | |
| Casework | Classroom | Casework | | 6 | 40 | LF | \$1,430 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 7 | 10 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 40 | LF | \$1,430 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 7 | 60 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 108 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 7 | 12 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 80 | LF | \$2,860 | |
| Casework | Classroom | Casework | | 7 | 12 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 6 | 40 | LF | \$1,430 | |
| Casework | Classroom | Casework | | 7 | 21 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 6 | 30 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 7 | 12 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 6 | 63 | LF | \$2,252 | |
| Casework | Classroom | Casework | | 7 | 60 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 60 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 6 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 60 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 7 | 36 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 80 | LF | \$2,860 | |
| Casework | Classroom | Casework | | 7 | 56 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 6 | 40 | LF | \$1,430 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 1,706 | SF | \$3,659 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 2,410 | SF | \$5,169 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 750 | SF | \$2,124 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 973 | SF | \$2,755 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Ceiling | Classroom | Plaster/Drywall | | 6 | 973 | SF | \$2,755 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,784 | SF | \$5,051 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,070 | SF | \$3,030 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 438 | SF | \$1,240 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,070 | SF | \$3,030 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,135 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,160 | SF | \$3,284 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,020 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,095 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,375 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,964 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 710 | SF | \$2,010 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 975 | SF | \$2,761 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,237 | SF | \$3,502 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 710 | SF | \$2,010 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,150 | SF | \$3,256 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,160 | SF | \$3,284 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,160 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,159 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 760 | SF | \$2,152 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,237 | SF | \$3,502 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 540 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 610 | SF | \$1,727 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,171 | SF | \$3,316 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 1,160 | SF | \$6,569 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,026 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 760 | SF | \$2,152 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 975 | SF | \$2,761 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 975 | SF | \$2,761 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 680 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 680 | SF | \$1,925 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 680 | SF | \$1,459 | |
| Ceiling | Classroom | Splined Ceiling | | 7 | 680 | SF | \$0 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 60 | LF | \$7,293 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 10 | LF | \$1,216 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 10 | LF | \$1,216 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 50 | LF | \$6,078 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 10 | LF | \$1,216 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 10 | LF | \$1,216 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|-------------------------|-----------------|------|----------|------|-----------|--------|
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 8 | LF | \$972 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 8 | LF | \$972 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 30 | LF | \$3,647 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 30 | LF | \$3,647 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 21 | LF | \$2,553 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 36 | LF | \$4,376 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 44 | LF | \$5,348 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 44 | LF | \$5,348 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 44 | LF | \$5,348 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 44 | LF | \$5,348 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 44 | LF | \$5,348 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 7 | 2 | EA | \$0 | |
| CLASSROOM | Classroom | Science Lab Elements | | 6 | 1,160 | SF | \$26,541 | |
| CLASSROOM | Classroom | Science Lab Elements | | 5 | 1,160 | SF | \$54,740 | |
| Corridors | Corridors | Pendant/Surface | Entire Building | 4 | 2,496 | EA | \$24,271 | |
| Corridors | Corridors | Plaster/Drywall | Entire Building | 6 | 51,282 | SF | \$121,000 | |
| Corridors | Corridors | Tile/Sheet Flooring | Entire Building | 6 | 16,071 | SF | \$22,982 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Entire Building | 6 | 16,071 | SF | \$45,503 | |
| Floor | Classroom | Carpet | | 6 | 610 | SF | \$872 | |
| Floor | Classroom | Tile/Sheet | | 6 | 973 | SF | \$1,391 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,070 | SF | \$1,530 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,135 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 5 | 1,160 | SF | \$6,569 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,159 | SF | \$1,657 | |
| Floor | Classroom | Tile/Sheet | | 6 | 540 | SF | \$772 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,160 | SF | \$1,659 | |
| Floor | Classroom | Tile/Sheet | | 6 | 680 | SF | \$972 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------------|----------|------|----------|------|----------|--------|
| Floor | Classroom | Tile/Sheet | | 7 | 1,095 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,964 | SF | \$2,809 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,375 | SF | \$1,966 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,706 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,160 | SF | \$1,659 | |
| Floor | Classroom | Tile/Sheet | | 7 | 750 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,150 | SF | \$1,645 | |
| Floor | Classroom | Tile/Sheet | | 6 | 973 | SF | \$1,391 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,160 | SF | \$1,659 | |
| Floor | Classroom | Tile/Sheet | | 6 | 680 | SF | \$972 | |
| Floor | Classroom | Tile/Sheet | | 6 | 975 | SF | \$1,394 | |
| Floor | Classroom | Tile/Sheet | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,171 | SF | \$1,675 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,070 | SF | \$1,530 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,237 | SF | \$1,769 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,237 | SF | \$1,769 | |
| Floor | Classroom | Tile/Sheet | | 6 | 680 | SF | \$972 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 6 | 1,784 | SF | \$13,470 | |
| Floor | Classroom | Wood | | 7 | 438 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 6 | 760 | SF | \$5,738 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 6 | 1,020 | SF | \$7,701 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 2,410 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 760 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------|-----------|-----------------|----------|------|----------|------|----------|--------|
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 6 | 680 | SF | \$5,134 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 975 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 710 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 680 | SF | \$0 | |
| Floor | Classroom | Wood | | 6 | 975 | SF | \$7,362 | |
| Floor | Classroom | Wood | | 6 | 680 | SF | \$5,134 | |
| Floor | Classroom | Wood | | 7 | 1,026 | SF | \$0 | |
| Floor | Classroom | Wood | | 6 | 680 | SF | \$5,134 | |
| Floor | Classroom | Wood | | 6 | 680 | SF | \$5,134 | |
| Floor | Classroom | Wood | | 7 | 710 | SF | \$0 | |
| LIBRARY_CEILING | Library | Plaster/Drywall | Room 207 | 6 | 2,160 | SF | \$6,116 | |
| LIBRARY_WALL | Library | Plaster/Drywall | Room 207 | 7 | 2,499 | | \$0 | |
| Lighting | Classroom | Lay-In | | 4 | 17 | EA | \$6,321 | |
| Lighting | Classroom | Lay-In | | 4 | 24 | EA | \$8,923 | |
| Lighting | Classroom | Lay-In | | 4 | 36 | EA | \$13,385 | |
| Lighting | Classroom | Lay-In | | 4 | 18 | EA | \$6,692 | |
| Lighting | Classroom | Lay-In | | 4 | 17 | EA | \$6,321 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 16 | EA | \$6,292 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 20 | EA | \$7,865 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 18 | EA | \$7,079 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 18 | EA | \$7,079 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 20 | EA | \$7,865 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 28 | EA | \$11,011 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 8 | EA | \$3,146 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|-----------------|----------|------|----------|------|----------|--------|
| Lighting | Classroom | Pendant/Surface | | 4 | 18 | EA | \$7,079 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 28 | EA | \$11,011 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 18 | EA | \$7,079 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 28 | EA | \$11,011 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 28 | EA | \$11,011 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 30 | EA | \$11,798 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 28 | EA | \$11,011 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 18 | EA | \$7,079 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 24 | EA | \$9,438 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 14 | EA | \$5,506 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 8 | EA | \$3,146 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 14 | EA | \$5,506 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 34 | EA | \$13,371 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 23 | EA | \$9,045 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 14 | EA | \$5,506 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 34 | EA | \$13,371 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 24 | EA | \$9,438 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 30 | EA | \$11,798 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 10 | EA | \$3,933 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 18 | EA | \$7,079 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|-----------------|----------|------|----------|------|----------|--------|
| Lighting | Classroom | Pendant/Surface | | 4 | 30 | EA | \$11,798 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 40 | EA | \$15,730 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 20 | EA | \$7,865 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 4 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 6 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 21 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Wall | Classroom | Masonry | | 7 | 3,026 | SF | \$0 | |
| Wall | Classroom | Masonry | | 7 | 2,534 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,280 | SF | \$3,020 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,280 | SF | \$3,020 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,714 | SF | \$4,044 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,714 | SF | \$4,044 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,280 | SF | \$3,020 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,530 | SF | \$3,610 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|-----------------|----------|------|----------|------|----------|--------|
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,952 | SF | \$4,606 | |
| Wall | Classroom | Plaster/Drywall | | 5 | 2,850 | SF | \$13,449 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,419 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,610 | SF | \$3,799 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,437 | SF | \$3,391 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,605 | SF | \$3,787 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,605 | SF | \$3,787 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,419 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,223 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 5 | 1,204 | SF | \$5,682 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,004 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 980 | SF | \$2,312 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,133 | SF | \$2,673 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,133 | SF | \$2,673 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,133 | SF | \$2,673 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,470 | SF | \$3,468 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,133 | SF | \$2,673 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,437 | SF | \$3,391 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,437 | SF | \$3,391 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,577 | SF | \$3,721 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,494 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,605 | SF | \$3,787 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,330 | SF | \$3,138 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,610 | SF | \$3,799 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,280 | SF | \$3,020 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,494 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,204 | SF | \$2,841 | |

Building: Telpochalli
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|---|-----------------|------|----------|------|------------------|----------------|
| Foundation | | Concrete Foundation | Entire Building | 7 | 763 | LF | \$0 | |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Entire Building | 6 | 6 | EA | \$3,003 | |
| Lighting | | Exterior Lights - Wall Mounted | throughout | 6 | 2 | EA | \$429 | |
| Parapet | | Coping - Stone | Roofs | 6 | 830 | LF | \$0 | |
| Parapet | | Parapet < 16" Height | Roofs | 7 | 80 | LF | \$0 | |
| Parapet | | Parapet > 30" Height | Roofs | 7 | 747 | LF | \$0 | |
| Parapet | | Parapet > 30" Height | SE elevation | 5 | 3 | LF | \$1,203 | |
| Roof System | | Interior Downspouts | Roofs | 6 | 350 | LF | \$0 | |
| Roof System | | Modified Bitumen Roof | Roofs | 6 | 20,386 | SF | \$144,302 | |
| Roof System | | Roof Structure: Steel with Clay Tile Arch | Roofs | 7 | 20,386 | SF | \$0 | |
| Superstructure | | Steel with Clay Tile Arch | Entire Building | 7 | 40,772 | SF | \$0 | |
| Walls | | Brick | East Façade | 4 | 2,345 | SF | \$177,057 | waves & bulges |
| Walls | | Brick | Entire Building | 7 | 18,472 | SF | \$0 | |
| Walls | | Concrete Block | throughout | 6 | 140 | SF | \$925 | |
| Walls | | Stone - Cast | Entire Building | 6 | 4,578 | SF | \$65,465 | |
| Windows | | Curtain wall - Insulated panel | Entire Building | 6 | 1,170 | SF | \$11,042 | |
| Windows | | Window - Guards perforated | throughout | 7 | 4,300 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 7 | 9,000 | SF | \$0 | |
| EXTERIOR Sub Total | | | | | | | \$456,094 | |

Building: Telpochalli
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|-----------------|------|----------|------|------------------|--------|
| Emergency System | | Emergency A/C power - Corridors and Stairs | Entire Building | 4 | 40,772 | SF | \$125,354 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Entire Building | 4 | 40 | EA | \$37,180 | |
| Emergency System | | Public Announcement System | Entire Building | 6 | 40,772 | SF | \$24,488 | |
| Power Distribution | | Lighting and power panels | Entire Building | 4 | 8 | EA | \$43,472 | |
| Power Distribution | | Main distribution panels less than 400 amp | Boiler Room | 4 | 2 | EA | \$13,156 | |
| ELECTRICAL Sub Total | | | | | | | \$243,649 | |

Building: Telpochalli
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|--------------------------|-----------------|------|----------|------|-----------------|--|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 3 | 40,772 | SF | \$86,290 | Strobe lights are not provided or not located in all areas |
| FIRE PROTECTION Sub Total | | | | | | | \$86,290 | |

Building: Telpochalli
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|---------------------------|------|----------|------|--------------------|--|
| Air Handling Systems | | Air Handling Unit Package - Multi Zone - Steam 6,000 to 10,000 cfm | 1st Floor | 4 | 1 | EA | \$55,770 | |
| Air Handling Systems | | Air Handling Unit Package - Multi Zone - Steam 10,001 to 15,000 cfm | 1st Floor | 4 | 1 | EA | \$74,360 | |
| Air Handling Systems | | Air Intake - Built Up Air Handling Unit | Roof | 4 | 2 | EA | \$52,338 | |
| Air Handling Systems | | Single Zone Built Up Air Handling Unit - Steam 4,000 to 8,000 cfm | 1st Floor | 4 | 1 | EA | \$25,740 | |
| Air Handling Systems | | Single Zone Built Up Air Handling Unit Auxiliaries - Steam 4,000 to 8,000 cfm | 1st Floor | 4 | 1 | EA | \$7,150 | |
| Boiler Systems | | Boiler Assembly - Steam - Low Pressure Scotch Marine Boiler greater than 200 HP | Boiler Room | 4 | 3 | EA | \$896,610 | |
| Boiler Systems | | Boiler Auxiliary - Steam Boiler greater than 200 HP | Boiler Room | 6 | 3 | EA | \$9,867 | |
| Boiler Systems | | Chemical Feed System (Steam Boilers) | Mechanical Room | 6 | 1 | EA | \$2,145 | |
| Boiler Systems | | Combustion Dampers | Boiler Room | 6 | 3 | EA | \$858 | |
| Boiler Systems | | Feed Water Pumps and Tank - Steam Boilers | Mechanical Room | 4 | 1 | EA | \$31,460 | |
| Heating Devices | | Radiators - Steam | Boiler Room | 2 | 1 | EA | \$1,401 | Radiator is more than 30 years of age and is not working. Unit is valved off due to leaks. |
| Heating Devices | | Unit Heater - Electric | Entire Building | 6 | 18 | EA | \$25,740 | |
| Mechanical Plumbing | | Piping - Condensate - Steel or Galvanized | Entire Building | 4 | 600 | LF | \$58,773 | |
| Mechanical Plumbing | | Piping - Steam - Steel or Galvanized | Entire Building | 4 | 600 | LF | \$71,858 | |
| Mechanical Plumbing | | Pumps - Vacuum | Pump Room off Boiler Room | 6 | 1 | EA | \$2,860 | |
| Temperature Control | | Pneumatic System | Mechanical Room | 4 | 282,174 | SF | \$2,017,544 | |
| Temperature Control | | Thermostats - Pneumatic | Entire Building | 4 | 18 | EA | \$11,840 | |
| Temperature Control | | Zone Dampers | 1st Floor | 4 | 18 | EA | \$15,187 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 4 | 1 | EA | \$2,288 | |
| MECHANICAL Sub Total | | | | | | | \$3,363,789 | |

Building: Telpochalli
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------|-----------|--|-----------------|------|----------|------|----------|--------|
| Hot Water | | Hot Water Heater - Gas more than 300,000 BTU/HR | Mechanical Room | 4 | 2 | EA | \$64,064 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 4 | 40,772 | SF | \$13,410 | |

Building: Telpochalli
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|--|-----------------|------|----------|------|------------------|--------|
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 4 | 40,772 | SF | \$26,237 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 4 | 40,772 | SF | \$8,746 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 4 | 40,772 | SF | \$18,657 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 4 | 40,772 | SF | \$22,156 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 4 | 40,772 | SF | \$97,368 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 4 | 40,772 | SF | \$80,459 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 4 | 40,772 | SF | \$46,643 | |
| Piping | | Sanitary Piping | Entire Building | 5 | 40,772 | SF | \$25,071 | |
| Piping | | Storm Piping | Entire Building | 5 | 40,772 | SF | \$19,240 | |
| Piping | | Vent Piping | Entire Building | 5 | 40,772 | SF | \$14,576 | |
| Pumps | | Domestic Booster Pump duplex | Mechanical Room | 4 | 1 | EA | \$31,460 | |
| PLUMBING Sub Total | | | | | | | \$468,086 | |

Building: Telpochalli
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|---------------------------|---------------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Janitor's Lounge | 6 | 344 | SF | \$738 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Engineer's Office | 6 | 230 | SF | \$651 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Maintenance Office | 7 | 112 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Chief Engineer's Office | 7 | 274 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Room 155 | 6 | 806 | SF | \$2,282 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | Nurse's Office, 1st Floor | 6 | 42 | SF | \$90 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | Room 168 Office | 6 | 342 | SF | \$734 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | Principal's Office | 6 | 205 | SF | \$440 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | Room 166 Copy Room | 6 | 312 | SF | \$669 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | Office #1 in Room 168 | 6 | 54 | SF | \$116 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | Office #2 in Room 168 | 6 | 95 | SF | \$204 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | Main Office | 6 | 249 | SF | \$534 | |

Building: Telpochalli
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|----------------------------|---------------------------|------|----------|------|-------|--------|
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 155 | 7 | 806 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Janitor's Lounge | 7 | 344 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office #1 in Room 168 | 7 | 54 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Engineer's Office | 6 | 230 | SF | \$329 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Maintenance Office | 6 | 112 | SF | \$160 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Nurse's Office, 1st Floor | 7 | 42 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Office #2 in Room 168 | 7 | 95 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 168 Office | 6 | 342 | SF | \$489 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Principal's Office | 7 | 205 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Main Office | 7 | 249 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 166 Copy Room | 7 | 312 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Chief Engineer's Office | 7 | 274 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Janitor's Lounge | 4 | 8 | SF | \$37 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Chief Engineer's Office | 4 | 5 | SF | \$33 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Principal's Office | 4 | 3 | SF | \$20 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Main Office | 4 | 4 | SF | \$26 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 166 Copy Room | 4 | 8 | SF | \$53 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office #1 in Room 168 | 4 | 1 | SF | \$7 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office #2 in Room 168 | 4 | 2 | SF | \$13 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 168 Office | 4 | 6 | SF | \$39 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Nurse's Office, 1st Floor | 4 | 1 | SF | \$7 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 155 | 4 | 18 | SF | \$118 | |

Building: Telpochalli
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|------------------------------|---------------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Maintenance Office | 4 | 2 | SF | \$13 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Engineer's Office | 4 | 5 | SF | \$33 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Janitor's Lounge | 6 | 750 | SF | \$1,770 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Chief Engineer's Office | 6 | 735 | SF | \$1,734 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Engineer's Office | 6 | 788 | SF | \$1,859 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Principal's Office | 7 | 580 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office #1 in Room 168 | 7 | 384 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 166 Copy Room | 7 | 809 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Main Office | 7 | 721 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office #2 in Room 168 | 7 | 525 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Maintenance Office | 6 | 559 | SF | \$1,319 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 155 | 6 | 1,480 | SF | \$3,492 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Nurse's Office, 1st Floor | 6 | 343 | SF | \$809 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 168 Office | 6 | 782 | SF | \$1,845 | |
| Classrooms | | Work Sink | Room 155 | 7 | 1 | EA | \$0 | |
| Corridor | | Stair Handrails | Entire Building | 7 | 272 | LF | \$0 | |
| Corridor | | Stairs - Terrazzo | Entire Building | 7 | 122 | LF | \$0 | |
| Corridor | | Student Lockers | Entire Building | 7 | 195 | EA | \$0 | |
| Doors | | Interior Steel Doors incl hw | throughout | 7 | 8 | EA | \$0 | |
| Doors | | Interior Wood Doors incl hw | throughout | 7 | 31 | EA | \$0 | |
| Doors | | Interior Wood Doors incl hw | throughout | 6 | 15 | EA | \$4,247 | |
| Doors | | Side-lite | throughout | 7 | 14 | SF | \$0 | |
| Doors | | Store Front Door | throughout | 7 | 2 | EA | \$0 | |
| Doors | | Transom Window | throughout | 7 | 71 | SF | \$0 | |
| Drinking Fountains | | Single Fountain | Entire Building | 7 | 4 | EA | \$0 | |
| Drinking Fountains | | Single Fountain | Room 162 | 7 | 1 | EA | \$0 | |
| Library | Library | Flooring Carpet | Room 258 | 7 | 1,031 | SF | \$0 | |

Building: Telpochalli
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------------------------|---------------------------|---|------|----------|------|---------|--------|
| Library | Library | Lighting - Lay-In | Room 258 | 4 | 18 | SF | \$84 | |
| Locker/Shower Room | Staff Restroom | Lockers | In Chief Engineer's Office | 7 | 1 | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | In Engineer's Office | 6 | 1 | EA | \$243 | |
| Locker/Shower Room | Staff Restroom | Showers | In the Employee Lounge | 6 | 1 | EA | \$243 | |
| Mechanical/Service Rooms | | Boiler Room | 1st Floor | 7 | 2,082 | SF | \$0 | |
| Mechanical/Service Rooms | | Janitor's Closet | Entire Building | 7 | 2 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 1st Floor | 7 | 1,211 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | In Principal's Office | 7 | 93 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | In the Boiler Room | 6 | 30 | SF | \$232 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | In Room 162 | 7 | 47 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | In Engineer's Office | 6 | 39 | SF | \$301 | |
| Staff Restroom | Staff Restroom | Accessories | In the Employee Lounge | 6 | 75 | SF | \$579 | |
| Staff Restroom | Staff Restroom | Accessories | Women's Room on 1st Floor | 6 | 21 | SF | \$162 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 1st Floor Girl's Room (Floor Plan Boy's Room) | 6 | 435 | SF | \$3,359 | |
| Staff Restroom | Staff Restroom | Accessories | Men's Room on 2nd Floor | 6 | 21 | SF | \$162 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Boy's Room (Floor Plan Girl's Room) | 6 | 474 | SF | \$3,660 | |
| Staff Restroom | Staff Restroom | Accessories | In Chief Engineer's Office | 6 | 39 | SF | \$301 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Chief Engineer's Office | 7 | 39 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In the Employee Lounge | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Engineer's Office | 7 | 39 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In the Boiler Room | 6 | 30 | SF | \$85 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Women's Room on 1st Floor | 6 | 21 | SF | \$59 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Men's Room on 2nd Floor | 6 | 21 | SF | \$59 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Boy's Room (Floor Plan Girl's Room) | 6 | 474 | SF | \$1,342 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Plaster/Drywall | In Room 162 | 7 | 47 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 1st Floor Girl's Room (Floor Plan Boy's Room) | 6 | 435 | SF | \$1,232 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Boy's Room (Floor Plan Girl's Room) | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | In the Employee Lounge | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | In Engineer's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 1st Floor Girl's Room (Floor Plan Boy's Room) | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | In the Boiler Room | 7 | 30 | SF | \$0 | |

Building: Telpochalli
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|---|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Boy's Room (Floor Plan Girl's Room) | 6 | 474 | SF | \$1,207 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 1st Floor Girl's Room (Floor Plan Boy's Room) | 7 | 435 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Women's Room on 1st Floor | 7 | 21 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Men's Room on 2nd Floor | 7 | 21 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | In Engineer's Office | 6 | 39 | SF | \$56 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | In Chief Engineer's Office | 7 | 39 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | In the Employee Lounge | 6 | 75 | SF | \$107 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile/Sheet | In Room 162 | 7 | 47 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 1st Floor Girl's Room (Floor Plan Boy's Room) | 6 | 2 | EA | \$434 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Boy's Room (Floor Plan Girl's Room) | 6 | 2 | EA | \$434 | |
| Staff Restroom | Staff Restroom | Lavatory | In the Employee Lounge | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Chief Engineer's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Engineer's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In the Boiler Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Women's Room on 1st Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 1st Floor Girl's Room (Floor Plan Boy's Room) | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Men's Room on 2nd Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Boy's Room (Floor Plan Girl's Room) | 7 | 4 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | In Room 162 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Pendant/ Surface | In Room 162 | 4 | 2 | SF | \$9 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Boy's Room (Floor Plan Girl's Room) | 4 | 9 | SF | \$39 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Men's Room on 2nd Floor | 4 | 1 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 1st Floor Girl's Room (Floor Plan Boy's Room) | 4 | 10 | SF | \$43 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Women's Room on 1st Floor | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In the Boiler Room | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In Engineer's Office | 4 | 2 | SF | \$9 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In Chief Engineer's Office | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In the Employee Lounge | 4 | 2 | SF | \$9 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | In Chief Engineer's Office | 6 | 1 | EA | \$29 | |
| Staff Restroom | Staff Restroom | Partitions | In the Employee Lounge | 6 | 2 | EA | \$359 | |

Building: Telpochalli
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------|--------------------------------------|-------------------------------|---|------|----------|------|-------|--------|
| Staff Restroom | Children's Standard Student Restroom | Partitions | 1st Floor Girl's Room (Floor Plan Boy's Room) | 7 | 8 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Boy's Room (Floor Plan Girl's Room) | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | In Engineer's Office | 6 | 1 | EA | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Boy's Room (Floor Plan Girl's Room) | 7 | 8 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In the Employee Lounge | 6 | 366 | SF | \$864 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In Engineer's Office | 6 | 351 | SF | \$828 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In Chief Engineer's Office | 6 | 325 | SF | \$767 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | In Room 162 | 7 | 225 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Men's Room on 2nd Floor | 7 | 149 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Women's Room on 1st Floor | 7 | 149 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In the Boiler Room | 6 | 168 | SF | \$396 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 1st Floor Girl's Room (Floor Plan Boy's Room) | 7 | 1,066 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Boy's Room (Floor Plan Girl's Room) | 7 | 1,455 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | In Room 162 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In the Employee Lounge | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Boy's Room (Floor Plan Girl's Room) | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Men's Room on 2nd Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 1st Floor Girl's Room (Floor Plan Boy's Room) | 7 | 10 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Women's Room on 1st Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In the Boiler Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In Engineer's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In Chief Engineer's Office | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 2 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |

INTERIOR Sub Total \$42,798

Building: Telpochalli
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------|----------|------|----------|------|------|--------|
|-------|-----------|------|----------|------|----------|------|------|--------|

Building: Telpochalli
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 7 | 38 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 10 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 16 | LF | \$572 | |
| Casework | Classroom | Casework | | 6 | 45 | LF | \$1,609 | |
| Casework | Classroom | Casework | | 7 | 8 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 7 | 30 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 7 | 20 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 7 | 30 | LF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 1,171 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 620 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 909 | SF | \$2,574 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 620 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 883 | SF | \$2,500 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 940 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 948 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 935 | SF | \$2,647 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 620 | SF | \$1,755 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 959 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 620 | SF | \$1,755 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 620 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 925 | SF | \$2,619 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 620 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 615 | SF | \$1,741 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 584 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 720 | SF | \$4,077 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 30 | LF | \$3,647 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 6 | LF | \$729 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |

Building: Telpochalli
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|-------------------------|-----------------|------|----------|------|----------|--------|
| Chalk Board | Classroom | Chalk Board | | 4 | 16 | LF | \$1,945 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 36 | LF | \$4,376 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 36 | LF | \$4,376 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 36 | LF | \$4,376 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 36 | LF | \$4,376 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 36 | LF | \$4,376 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 7 | 1 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | Entire Building | 4 | 448 | EA | \$4,356 | |
| Corridors | Corridors | Plaster/Drywall | Entire Building | 6 | 10,162 | SF | \$23,977 | |
| Corridors | Corridors | Tile/Sheet Flooring | Entire Building | 6 | 5,096 | SF | \$7,287 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Entire Building | 6 | 5,096 | SF | \$14,429 | |
| Floor | Classroom | Carpet | | 7 | 1,171 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 883 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 948 | SF | \$1,356 | |
| Floor | Classroom | Tile/Sheet | | 7 | 959 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 584 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 720 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 620 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 940 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 935 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 925 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 615 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 909 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 620 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 620 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 620 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 620 | SF | \$0 | |
| Floor | Classroom | Wood | | 7 | 620 | SF | \$0 | |
| LIBRARY_CEILING | Library | Drop/Lay-In | Room 258 | 6 | 1,031 | SF | \$2,211 | |
| LIBRARY_WALL | Library | Plaster/Drywall | Room 258 | 7 | 1,286 | | \$0 | |
| Lighting | Classroom | Lay-In | | 4 | 23 | EA | \$8,551 | |
| Lighting | Classroom | Lay-In | | 4 | 10 | EA | \$3,718 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 10 | EA | \$3,933 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 10 | EA | \$3,933 | |

Building: Telpochalli
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|-----------------|----------|------|----------|------|----------|--------|
| Lighting | Classroom | Pendant/Surface | | 4 | 10 | EA | \$3,933 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 10 | EA | \$3,933 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 10 | EA | \$3,933 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 22 | EA | \$8,652 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 18 | EA | \$7,079 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 23 | EA | \$9,045 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 27 | EA | \$10,618 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 24 | EA | \$9,438 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 16 | EA | \$6,292 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 18 | EA | \$7,079 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 10 | EA | \$3,933 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 18 | EA | \$7,079 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 16 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 40 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 16 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 5 | LF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,130 | SF | \$2,666 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,602 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,525 | SF | \$3,598 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,185 | SF | \$2,796 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,130 | SF | \$2,666 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,130 | SF | \$2,666 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,130 | SF | \$2,666 | |

Building: Telpochalli
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------------------|-----------|-----------------|----------|------|----------|------|--------------------|--------|
| Wall | Classroom | Plaster/Drywall | | 6 | 1,130 | SF | \$2,666 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,130 | SF | \$2,666 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,645 | SF | \$3,881 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,290 | SF | \$3,044 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,614 | SF | \$3,808 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,699 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,601 | SF | \$3,778 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,400 | SF | \$3,303 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,253 | SF | \$2,956 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,420 | SF | \$3,350 | |
| ROOM Sub Total | | | | | | | \$269,899 | |
| Building Telpochalli Sub Total | | | | | | | \$4,930,606 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|---------------------------------------|---------------------------|------|----------|------|----------|------------------|
| Civil/Drainage | | Catch Basin | throughout site | 7 | 9 | EA | \$0 | |
| Civil/Drainage | | Site Manhole | throughout site | 7 | 6 | EA | \$0 | |
| Fencing | | Chain Link | play area | 6 | 279 | LF | \$4,002 | |
| Fencing | | Ornamental Iron | throughout site | 7 | 720 | LF | \$0 | |
| Fencing | | Ornamental Iron | E site | 4 | 40 | LF | \$7,550 | bent/leaning |
| Landscape | | Asphalt Play Area/Hardscape | play area | 5 | 8,921 | SF | \$25,259 | cracks & ponding |
| Landscape | | Benches | throughout site | 7 | 4 | EA | \$0 | |
| Landscape | | Grass | throughout site | 7 | 19,191 | SF | \$0 | |
| Landscape | | Grass | NE site | 4 | 970 | SF | \$3,842 | mud |
| Landscape | | Hardscape - Pavers | Main Entrance | 7 | 320 | SF | \$0 | |
| Landscape | | Parkway trees | throughout site perimeter | 7 | 31 | EA | \$0 | |
| Landscape | | Planting Beds/ Areas | throughout site | 7 | 1,707 | SF | \$0 | |
| Landscape | | Trash Receptacles | S site | 7 | 2 | EA | \$0 | |
| Parking Lot | | Asphalt | E site | 7 | 88,057 | SF | \$0 | |
| Parking Lot | | Lights, Pole Mounted | E site | 6 | 2 | EA | \$2,288 | |
| Parking Lot | | Trash Compactor | NW site | 7 | 1 | EA | \$0 | |
| Parking Lot | | Vehicular Screening | SE site | 7 | 165 | LF | \$0 | |
| Playground | | Playground Equipment - Pre-K 3-5 | S site | 7 | 1 | EA | \$0 | |
| Playground | | Playground Surfacing - Poured Surface | S site | 7 | 2,526 | SF | \$0 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|--------------------------------------|---------------------------|------|----------|------|-----------------|--------|
| Sidewalks | | Internal Walks | throughout site | 6 | 611 | LF | \$5,767 | |
| Sidewalks | | Perimeter Sidewalks | throughout site perimeter | 7 | 26,563 | SF | \$0 | |
| Signage | | Flag Pole | S site | 6 | 1 | EA | \$0 | |
| Signage | | Marquee - Free Standing Back Lighted | Main Entrance | 7 | 1 | EA | \$0 | |
| SITE Sub Total | | | | | | | \$48,708 | |
| SITE Sub Total | | | | | | | \$48,708 | |

Total Campus Need ^{2 3} \$15,050,007

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

| Room Summary | | | | | | | | | | | | | Room Type | Room Sub Type | Location |
|-----------------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-----------|-----------|---------------|----------|
| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | | | | |
| Building: Main | | | | | | | | | | | | | | | |
| 104 | 1020 | 1 | 0 | 12 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | | |
| 106 | 1095 | 1 | 0 | 12 | 40 | 225 | 72 | 2 | N | N | Y | Classroom | | | |
| 119 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | | |
| 123 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | | |
| 125 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | | |
| 127 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | 1 | N | N | Y | Classroom | | | |
| 130 | 1706 | 1 | 2 | 8 | 40 | 375 | 120 | 0 | N | N | Y | Classroom | | | |
| 143 | 1375 | 1 | 2 | 6 | 40 | 0 | 0 | 0 | N | N | Y | Classroom | | | |
| 144 | 1964 | 1 | 3 | 8 | 40 | 0 | 0 | 0 | N | N | Y | Classroom | | | |
| 202 | 1160 | 1 | 0 | 24 | 40 | 300 | 96 | 2 | N | N | Y | Classroom | | | |
| 206 | 1160 | 1 | 0 | 24 | 40 | 225 | 72 | 2 | N | N | Y | Classroom | | | |
| 212 | 680 | 1 | 0 | 10 | 40 | 114 | 30 | 1 | N | N | Y | Classroom | | | |
| 213 | 680 | 1 | 0 | 10 | 40 | 114 | 30 | 0 | N | N | Y | Classroom | | | |
| 214 | 680 | 1 | 0 | 9 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | | |
| 215 | 680 | 1 | 0 | 8 | 40 | 114 | 30 | | N | N | Y | Classroom | | | |
| 216 | 1160 | 1 | 0 | 24 | 40 | 225 | 72 | 2 | N | N | Y | Classroom | | | |
| 217 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | 1 | N | N | Y | Classroom | | | |
| 219 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | | |
| 220 | 610 | 1 | 0 | 12 | 40 | 150 | 48 | 1 | N | N | Y | Classroom | | | |
| 221 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | | |
| 223 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | | |
| 224 | 1160 | 1 | 0 | 24 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | | |
| 225 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | 1 | N | N | Y | Classroom | | | |
| 226 | 680 | 1 | 0 | 9 | 40 | 150 | 48 | 1 | N | N | Y | Classroom | | | |
| 227 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | 1 | N | N | Y | Classroom | | | |
| 228 | 750 | 1 | 0 | 4 | 40 | 150 | 48 | 0 | N | N | N | Classroom | | | |
| 300 | 1784 | 1 | 2 | 6 | 40 | 0 | 0 | 0 | N | N | N | Classroom | | | |
| 302 | 973 | 1 | 0 | 6 | 40 | 225 | 72 | 0 | N | N | N | Classroom | | | |
| 304 | 973 | 1 | 0 | 6 | 40 | 225 | 72 | 0 | N | N | N | Classroom | | | |
| 305 | 1070 | 1 | 0 | 6 | 40 | 225 | 42 | 0 | N | Y | Y | Classroom | | | |
| 308 | 710 | 1 | 0 | 9 | 40 | 100 | 48 | 0 | N | N | Y | Classroom | | | |
| 309 | 1070 | 1 | 0 | 6 | 40 | 225 | 42 | 0 | N | Y | Y | Classroom | | | |
| 310 | 680 | 1 | 0 | 5 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | | |
| 311 | 710 | 1 | 0 | 9 | 40 | 100 | 48 | 0 | N | N | Y | Classroom | | | |
| 312 | 438 | 1 | 0 | 10 | 40 | 100 | 32 | 0 | N | N | Y | Classroom | | | |
| 313 | 1150 | 1 | 0 | 16 | 40 | 250 | 80 | 0 | N | N | Y | Classroom | | | |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-----------|--------------------------------------|----------------------------------|
| 314 | 680 | 1 | 0 | 20 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 315 | 680 | 1 | 0 | 9 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 316 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 317 | 1135 | 1 | 0 | 10 | 40 | 275 | 88 | 0 | N | N | Y | Classroom | | |
| 318 | 1026 | 1 | 0 | 8 | 40 | 225 | 72 | 0 | N | Y | Y | Classroom | | |
| 320 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | | N | N | Y | Classroom | | |
| 321 | 1159 | 1 | 0 | 8 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| 322 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | | N | N | Y | Classroom | | |
| 323 | 540 | 1 | 0 | 6 | 40 | 125 | 40 | 0 | N | N | Y | Classroom | | |
| 326 | 680 | 1 | 0 | 8 | 40 | 150 | 48 | | N | N | Y | Classroom | | |
| 327 | 1171 | 1 | 0 | 12 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| 328 | 760 | 1 | 0 | 12 | 40 | 100 | 32 | 0 | N | N | Y | Classroom | | |
| 329 | 760 | 1 | 0 | 12 | 40 | 100 | 32 | 0 | N | N | Y | Classroom | | |
| 331 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 332 | 1237 | 1 | 0 | 20 | 40 | 300 | 96 | 0 | N | N | Y | Classroom | | |
| 333 | 975 | 1 | 0 | 16 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| 334 | 1237 | 1 | 0 | 20 | 40 | 300 | 96 | 0 | N | N | Y | Classroom | | |
| 335 | 975 | 1 | 0 | 16 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| 336 | 975 | 1 | 0 | 16 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| 337 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 339 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 340 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 341 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 342 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 343 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 344 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 346 | 680 | 1 | 0 | 12 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 400 | 2410 | 1 | 0 | 16 | 40 | 450 | 104 | 0 | N | N | Y | Classroom | | |
| Other | 292 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 1st Floor Northeast Girl's Room |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 3rd Floor Northeast Women's Room |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 1st Floor Northwest Women's Room |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd Floor Northwest Women's Room |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 3rd Floor Northwest Women's Room |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd Floor Southeast Men's Room |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 3rd Floor Southeast Men's Room |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|-------------------------------------|
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 1st Floor Southeast Men's Room |
| Other | 680 | | | 10 | | | | | N | N | Y | Administrative Suites/Offices | | Room 212 |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd Floor Southwest Men's Room |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 3rd Floor Southwest Men's Room |
| Other | 292 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 3rd Floor Northeast Girl's Room |
| Other | 285 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 3rd Floor Southwest Boy's Room |
| Other | 292 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd Floor Northwest Girl's Room |
| Other | 285 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd Floor Southeast Boy's Room |
| Other | 292 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 1st Floor Northwest Girl's Room |
| Other | 292 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 3rd Floor Northwest Girl's Room |
| Other | 285 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 1st Floor Southeast Boy's Room |
| Other | 367 | | | 10 | | | | | N | N | Y | Administrative Suites/Offices | | Room 338 |
| Other | 5095 | | | | | | | | N | N | N | Gymnasia | Standard Dedicated Gymnasium | 2nd Floor |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd Floor Northeast Women's Room |
| Other | 285 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 1st Floor Southwest Boy's Room |
| Other | 285 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 3rd Floor Southeast Boy's Room |
| Other | 285 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd Floor Southwest Boy's Room |
| Other | 292 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd Floor Northeast Girl's Room |
| Other | 33 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | Room 130 |
| Other | 192 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Office in Library Room 207 |
| Other | 45 | | | | | | | | N | N | N | Restroom | Staff Restroom | 1st Floor Northeast Women's Room |
| Other | 164 | | | | | | | | N | N | N | Restroom | Staff Restroom | Room 128C Women Janitor's Rest room |
| Other | 680 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Room 121 |
| Other | 95 | | | 2 | | | | | N | N | Y | Administrative Suites/Offices | | Teacher's Office in Room 130 |
| Other | 680 | | | 10 | | | | | N | N | Y | Administrative Suites/Offices | | Room 117 |
| Other | 740 | | | 10 | | | | | N | N | Y | Administrative Suites/Offices | | Room 109 |
| Other | 200 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Principal's Office (inaccessible) |
| Other | 38 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Principal's Office |
| Other | 1600 | | | 20 | | | | | N | N | Y | Administrative Suites/Offices | | Main Office |
| Other | 38 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Main Office |
| Other | 38 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Room 100 |
| Other | 211 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Room 100 Asst. Principal's Office |
| Other | 10541 | | | | | | | | N | N | N | Auditorium & Theater | Auditorium - Dedicated | 1st Floor |
| Other | 10916 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | 2nd Floor |
| Other | 16071 | | | | | | | | N | N | N | Corridors | | Entire Building |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|------------------------------|--------------------------------|
| Other | 262 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Room 305/309 Prep Room |
| Other | 135 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Gym Teacher's Office |
| Other | 1139 | | | | | | | | N | N | N | Kitchen | Cooking Kitchen | 2nd Floor |
| Other | 241 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Kitchen Area |
| Other | 65 | | | 2 | | | | | N | N | Y | Administrative Suites/Offices | | Kitchen Manager's Office |
| Other | 687 | | | 6 | | | | | N | N | N | Administrative Suites/Offices | | Faculty Luncroom |
| Other | 1769 | | | 6 | | | | | N | N | N | Administrative Suites/Offices | | Room 209, Faculty Lounge |
| Other | 128 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Gym Teacher's Office |
| Other | 2160 | | | | | | | | N | N | N | Library | | Room 207 |
| Other | 4818 | | | | | | | | N | N | N | Restroom | Locker/Shower Room | Girl's Locker Room, 1st Floor |
| Other | 10541 | | | | | | | | N | N | N | Gymnasia | Standard Dedicated Gymnasium | 1st Floor |
| Other | 136 | | | 2 | | | | | N | N | N | Administrative Suites/Offices | | Additional Office in Pool Area |
| Other | 91 | | | 2 | | | | | N | N | Y | Administrative Suites/Offices | | PE Instructor's Office |

Building: Telpochalli

| | | | | | | | | | | | | | | |
|-------|------|---|---|----|----|-----|----|---|---|---|---|-------------------------------|----------------------------------|---------------------------|
| 151 | 909 | 1 | 0 | 8 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| 152 | 620 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 153 | 883 | 1 | 0 | 8 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| 156 | 720 | 1 | 0 | 12 | 40 | 175 | 56 | 0 | N | N | Y | Classroom | | |
| 159 | 584 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 162 | 940 | 1 | 0 | 6 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 251 | 948 | 1 | 0 | 12 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| 252 | 620 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 253 | 620 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 254 | 620 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 255 | 620 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 256 | 620 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | N | Y | Classroom | | |
| 257 | 1171 | 1 | 0 | 12 | 40 | 225 | 72 | 2 | N | N | Y | Classroom | | |
| 259 | 615 | 1 | 0 | 8 | 40 | 150 | 48 | 0 | N | Y | Y | Classroom | | |
| 260 | 925 | 1 | 0 | 8 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| 262 | 959 | 1 | 0 | 10 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| 264 | 935 | 1 | 0 | 10 | 40 | 225 | 72 | 0 | N | N | Y | Classroom | | |
| Other | 42 | | | 2 | | | | | N | N | N | Administrative Suites/Offices | | Nurse's Office, 1st Floor |
| Other | 312 | | | 10 | | | | | N | N | Y | Administrative Suites/Offices | | Room 166 Copy Room |
| Other | 95 | | | 20 | | | | | N | N | N | Administrative Suites/Offices | | Office #2 in Room 168 |
| Other | 47 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | In Room 162 |
| Other | 30 | | | | | | | | N | N | N | Restroom | Staff Restroom | In the Boiler Room |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|---|
| Other | 342 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Room 168 Office |
| Other | 205 | | | 12 | | | | | N | N | Y | Administrative Suites/Offices | | Principal's Office |
| Other | 249 | | | 8 | | | | | N | N | N | Administrative Suites/Offices | | Main Office |
| Other | 54 | | | 2 | | | | | N | N | Y | Administrative Suites/Offices | | Office #1 in Room 168 |
| Other | 806 | | | 806 | | | | | N | N | Y | Administrative Suites/Offices | | Room 155 |
| Other | 1031 | | | | | | | | N | N | N | Library | | Room 258 |
| Other | 112 | | | 2 | | | | | N | N | N | Administrative Suites/Offices | | Maintenance Office |
| Other | 75 | | | | | | | | N | N | N | Restroom | Staff Restroom | In the Employee Lounge |
| Other | 344 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Janitor's Lounge |
| Other | 39 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Chief Engineer's Office |
| Other | 274 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Chief Engineer's Office |
| Other | 230 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Engineer's Office |
| Other | 21 | | | | | | | | N | N | N | Restroom | Staff Restroom | Women's Room on 1st Floor |
| Other | 435 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 1st Floor Girl's Room (Floor Plan Boy's Room) |
| Other | 21 | | | | | | | | N | N | N | Restroom | Staff Restroom | Men's Room on 2nd Floor |
| Other | 474 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Boy's Room (Floor Plan Girl's Room) |
| Other | 5096 | | | | | | | | N | N | N | Corridors | | Entire Building |
| Other | 39 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Engineer's Office |