

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

- Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- Total Campus Need** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|--|---------------------|------|----------|------|-----------|--------|
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Southeast | 6 | 60 | LF | \$30,030 | |
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Northeast | 6 | 48 | LF | \$24,024 | |
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Top | 5 | 20 | LF | \$35,750 | |
| Chimney | | Metal Flue | NE | 6 | 5 | LF | \$322 | |
| Cornice | | Cornice - Metal Projecting | Entire Building | 6 | 1,182 | LF | \$105,979 | |
| Cornice | | Cornice - Metal Projecting | Courtyard | 5 | 120 | LF | \$35,506 | |
| Doors | | Exterior Steel Door | Entire Building | 6 | 16 | EA | \$5,285 | |
| Doors | | Exterior Steel Door | West | 5 | 1 | EA | \$1,090 | |
| Doors | | Exterior Wood Door | South roof level | 5 | 1 | EA | \$1,059 | |
| Doors | | Transom Lite | East, West | 6 | 8 | EA | \$2,265 | |
| Entrance | | Concrete Exterior Stairs | east,west | 6 | 27 | LF | \$2,896 | |
| Entrance | | Entrance Controls - Audio and Video | West, Main entrance | 6 | 1 | EA | \$1,430 | |
| Fire Escape | | Fire Escapes | West | 6 | 6 | LF | \$612 | |
| Foundation | | Masonry Foundation | Entire Building | 7 | 540 | SF | \$0 | |

Building: Main
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|--------------------------------|--|------|----------|------|-----------|--------|
| Foundation | | Masonry Foundation | Boiler House area | 4 | 105 | SF | \$104,054 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 7 | 8 | EA | \$0 | |
| Lintels | | Lintels - Brick | Along1 story | 6 | 107 | LF | \$0 | |
| Lintels | | Lintels - Steel | West | 6 | 94 | LF | \$3,549 | |
| Lintels | | Lintels - Stone | Entire Building | 6 | 434 | LF | \$0 | |
| Parapet | | Coping - Clay Tile | SW & NE | 6 | 38 | LF | \$0 | |
| Parapet | | Coping - Stone | North Building | 5 | 329 | LF | \$28,689 | |
| Parapet | | Coping - Stone | West entrance | 6 | 32 | LF | \$0 | |
| Parapet | | Coping - Terra Cotta | South Building & East | 6 | 563 | LF | \$0 | |
| Parapet | | Parapet < 16" Height | North Bldg. and SW | 6 | 405 | LF | \$63,069 | |
| Parapet | | Parapet < 16" Height | 1st Story Spalling | 5 | 20 | LF | \$4,813 | |
| Parapet | | Parapet 16" to 30" Height | South bldg. | 6 | 432 | LF | \$89,699 | |
| Parapet | | Parapet 16" to 30" Height | East lower roof | 4 | 105 | LF | \$74,324 | |
| Roof System | | Asphalt Gravel Ballast Roof | Entire Building | 6 | 16,117 | SF | \$102,791 | |
| Roof System | | Asphalt Gravel Ballast Roof | East lower Roof | 5 | 450 | SF | \$5,734 | |
| Roof System | | Asphalt Gravel Ballast Roof | West Center lower roof | 5 | 100 | SF | \$1,274 | |
| Roof System | | Exterior Downspouts | Entire Building | 6 | 402 | LF | \$7,473 | |
| Roof System | | Exterior Downspouts | Southeast | 4 | 25 | LF | \$4,469 | |
| Roof System | | Exterior Downspouts | North,West,East | 5 | 33 | LF | \$613 | |
| Roof System | | Metal Roof | West Oriel & South roof level | 6 | 30 | SF | \$227 | |
| Roof System | | Modified Bitumen Roof | West Entrances & on top of air intakes at roof level | 6 | 120 | SF | \$849 | |
| Roof System | | Roof Structure: Concrete | East 1 story | 7 | 2,553 | SF | \$0 | |
| Roof System | | Roof Structure: Heavy Timber | Entire Building | 7 | 16,817 | SF | \$0 | |
| Superstructure | | Concrete | East 1 story Boilerhouse | 7 | 2,553 | SF | \$0 | |
| Superstructure | | Heavy Timber | Entire Building | 7 | 60,290 | SF | \$0 | |
| Walls | | Brick | Roof | 5 | 32 | SF | \$725 | |
| Walls | | Brick | East near Chimney | 5 | 130 | SF | \$2,945 | |
| Walls | | Brick | South face | 5 | 600 | SF | \$13,591 | |
| Walls | | Brick | East corner near courtyard | 5 | 170 | SF | \$3,851 | |
| Walls | | Brick | South roof level | 5 | 50 | SF | \$1,133 | |
| Walls | | Brick | Entire Building | 6 | 34,630 | SF | \$228,787 | |
| Walls | | Brick | East Face1 Story | 5 | 593 | SF | \$13,432 | |
| Walls | | Precast Panel Wall | West face of North bldg | 6 | 87 | SF | \$575 | |
| Walls | | Stone - Cut | Entire Building | 6 | 1,080 | SF | \$15,444 | |
| Walls | | Stone - Cut | Door 2 | 5 | 6 | SF | \$644 | |
| Windows | | Skylite - Glass Single-Pane | North roof level | 6 | 28 | SF | \$264 | |
| Windows | | Window - Guards perforated | Entire Building | 7 | 2,281 | SF | \$0 | |

Building: Main
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-------------------------------------|-----------------|------|----------|------|--------------------|--------|
| Windows | | Window - Guards perforated | East | 6 | 31 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 6 | 5,477 | SF | \$46,993 | |
| EXTERIOR Sub Total | | | | | | | \$1,066,257 | |

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|-----------------|------|----------|------|------------------|--------|
| Emergency System | | Automatic Transfer switch | Electrical Room | 7 | 1 | EA | \$0 | |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Entire Building | 4 | 7,146 | SF | \$21,970 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Entire Building | 4 | 4,503 | SF | \$8,049 | |
| Emergency System | | Emergency A/C power - Students Toilets | Entire Building | 4 | 2,345 | SF | \$8,383 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | 2nd Floor | 7 | 2 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | 1st Floor | 7 | 1 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | 3rd Floor | 7 | 1 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | Basement | 4 | 1 | EA | \$541 | |
| Emergency System | | Emergency generator below 60 KW diesel - Outdoor | Site - East | 6 | 1 | EA | \$5,577 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Basement | 7 | 10 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | 1st Floor | 7 | 3 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | 2nd Floor | 7 | 2 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | 3rd Floor | 7 | 1 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | 3rd Floor | 6 | 2 | EA | \$466 | |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | 3rd Floor | 7 | 3 | EA | \$0 | |
| Emergency System | | Public Announcement System | Main Office | 7 | 62,843 | SF | \$0 | |
| Emergency System | | Security System - CCTV | Main Office | 5 | 62,843 | SF | \$179,731 | |
| Main Service | | Main Electrical service 2000 A 120/208/3PH | Electrical Room | 7 | 1 | EA | \$0 | |
| Power Distribution | | Lighting and power panels | Basement | 6 | 4 | EA | \$2,860 | |
| Power Distribution | | Lighting and power panels | 2nd Floor | 6 | 2 | EA | \$1,430 | |
| Power Distribution | | Lighting and power panels | Basement | 7 | 3 | EA | \$0 | |
| Power Distribution | | Lighting and power panels | 3rd Floor | 6 | 2 | EA | \$1,430 | |
| Power Distribution | | Lighting and power panels | 1st Floor | 6 | 2 | EA | \$1,430 | |
| Power Distribution | | Main distribution panels 400-600 amp | Electrical Room | 7 | 1 | EA | \$0 | |
| Power Distribution | | Main distribution panels above 600 amp | Electrical Room | 7 | 1 | EA | \$0 | |
| ELECTRICAL Sub Total | | | | | | | \$231,868 | |

Building: Main
Category: FIRE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------|----------|------|----------|------|------|--------|
|-------|-----------|------|----------|------|----------|------|------|--------|

Building: Main
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------|-----------|--------------------------|-------------------|------|----------|------|-----------|--------|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 7 | 62,843 | SF | \$0 | |
| Fire Alarm | | Fire Alarm System | Engineer's Office | 4 | 58,108 | SF | \$205,243 | |
| Fire Alarm | | Fire Pump Controller | Pump Room | 4 | 1 | EA | \$18,590 | |
| Pump Room Assembly | | Fire Pump 25-50hp | Pump Room | 5 | 1 | EA | \$15,015 | |
| Sprinkler System | | Dry Sprinkler System | Pump Room | 5 | 62,843 | SF | \$265,103 | |
| Sprinkler System | | Sprinkler Heads | Entire Building | 6 | 62,843 | SF | \$3,595 | |

FIRE PROTECTION Sub Total \$507,546

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|---------------------|------|----------|------|----------|--------|
| Air Conditioning | | Window A/C Unit | 1st Floor | 6 | 1 | EA | \$215 | |
| Air Handling Systems | | Air Intake - Built Up Air Handling Unit | 2nd Floor East Wall | 6 | 1 | EA | \$1,430 | |
| Air Handling Systems | | Multi Zone Built Up Air Handling Unit - Steam above 35,000 cfm | Basement | 6 | 1 | EA | \$17,160 | |
| Air Handling Systems | | Multi Zone Built Up Air Handling Unit Auxiliaries - Steam above 35,000 cfm | Basement | 6 | 1 | EA | \$4,290 | |
| Air Handling Systems | | Return Duct Work - Indoor - Vertical Shaft and Ducts | Entire Building | 7 | 100 | LF | \$0 | |
| Boiler Systems | | Boiler Assembly - Steam - Low Pressure Scotch Marine Boiler 50-75 HP | Boiler Room | 6 | 2 | EA | \$20,020 | |
| Boiler Systems | | Boiler Auxiliary - Steam Boiler 50-75 HP | Boiler Room | 7 | 2 | EA | \$0 | |
| Boiler Systems | | Chemical Feed System (Steam Boilers) | Boiler Room | 7 | 1 | EA | \$0 | |
| Boiler Systems | | Combustion Dampers | Boiler Room | 7 | 2 | EA | \$0 | |
| Boiler Systems | | Feed Water Pumps and Tank - Steam Boilers | Boiler Room | 6 | 1 | EA | \$8,437 | |
| Heating Devices | | Fin Tube Electric | 1st Floor | 6 | 8 | LF | \$114 | |
| Heating Devices | | Radiators - Steam | 2nd Floor | 5 | 1 | EA | \$658 | |
| Heating Devices | | Unit Heater - Gas | Boiler Room | 7 | 1 | EA | \$0 | |
| Heating Devices | | Wall Heater - Electric | Pump Room | 4 | 1 | EA | \$1,030 | |
| Heating Devices | | Wall Heater - Electric | 1st Floor | 4 | 1 | EA | \$1,030 | |
| Heating Devices | | Wall Heater - Electric | 2nd Floor | 4 | 5 | EA | \$5,148 | |
| Heating Devices | | Wall Heater - Electric | Basement | 4 | 7 | EA | \$7,207 | |
| Mechanical Plumbing | | Piping - Condensate - Steel or Galvanized | Entire Building | 4 | 400 | LF | \$39,182 | |
| Mechanical Plumbing | | Piping - Steam - Steel or Galvanized | Entire Building | 5 | 400 | LF | \$19,791 | |
| Temperature Control | | Direct Digital Control (DDC) System | Engineer's Office | 6 | 62,843 | SF | \$62,906 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|-----------------|------|----------|------|------------------|--------|
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | 3rd Floor | 6 | 8 | EA | \$1,144 | |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | Basement | 6 | 3 | EA | \$429 | |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | 2nd Floor | 6 | 8 | EA | \$1,144 | |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | 1st Floor | 6 | 10 | EA | \$1,430 | |
| Temperature Control | | Zone Dampers | Basement | 6 | 40 | EA | \$5,720 | |
| Ventilation | | Exhaust Fan - Indoor | 2nd Floor | 4 | 1 | EA | \$5,577 | |
| Ventilation | | Exhaust Fan - Indoor | Electrical Room | 5 | 1 | EA | \$1,859 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 6 | 1 | EA | \$429 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 6 | 2 | EA | \$458 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 5 | 1 | EA | \$1,287 | |
| Ventilation | | Type I Exhaust Hood - Kitchen or Culinary Arts | 2nd Floor | 6 | 1 | EA | \$1,716 | |
| MECHANICAL Sub Total | | | | | | | \$209,810 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|--|-----------------|------|----------|------|-----------------|--------|
| Hot Water | | Hot Water Heater - Gas 150,000 -300,000 BTU/HR | Boiler Room | 7 | 2 | EA | \$0 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 6 | 62,843 | SF | \$7,189 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 6 | 62,843 | SF | \$9,885 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 6 | 62,843 | SF | \$9,885 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 6 | 62,843 | SF | \$9,885 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 6 | 62,843 | SF | \$9,885 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 6 | 62,843 | SF | \$14,378 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 6 | 62,843 | SF | \$12,581 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 6 | 62,843 | SF | \$9,885 | |
| Piping | | Sanitary Piping | Entire Building | 7 | 62,843 | SF | \$0 | |
| Piping | | Storm Piping | Entire Building | 7 | 62,843 | SF | \$0 | |
| Piping | | Vent Piping | Entire Building | 7 | 62,843 | SF | \$0 | |
| Pumps | | Domestic Booster Pump simplex | Boiler Room | 6 | 1 | EA | \$1,716 | |
| Pumps | | Sump Pump | Boiler Room | 6 | 2 | EA | \$2,717 | |
| PLUMBING Sub Total | | | | | | | \$88,008 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------|----------|------|----------|------|------|--------|
|-------|-----------|------|----------|------|----------|------|------|--------|

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|----------------------------|------------------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Main Office 1st Floor | 6 | 529 | SF | \$1,498 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 1st Floor Faculty Lounge | 6 | 271 | SF | \$767 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Basement Engineer's Office | 6 | 155 | SF | \$439 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Principal's Office 1st Floor | 6 | 160 | SF | \$453 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Art Office | 4 | 596 | SF | \$7,875 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 2nd Floor Teachers Lounge | 6 | 139 | SF | \$394 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 1st Floor Conference Room | 6 | 194 | SF | \$549 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | 1st Floor Conference Room | 5 | 194 | SF | \$694 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Concrete | Art Office | 5 | 596 | SF | \$2,813 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 2nd Floor Teachers Lounge | 6 | 139 | SF | \$199 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Main Office 1st Floor | 6 | 529 | SF | \$756 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 1st Floor Faculty Lounge | 6 | 271 | SF | \$388 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement Engineer's Office | 6 | 155 | SF | \$222 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Wood | Principal's Office 1st Floor | 6 | 160 | SF | \$1,208 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 2nd Floor Teachers Lounge | 4 | 1 | SF | \$7 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 1st Floor Faculty Lounge | 4 | 3 | SF | \$20 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 1st Floor Conference Room | 4 | 3 | SF | \$20 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Main Office 1st Floor | 4 | 8 | SF | \$53 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Basement Engineer's Office | 4 | 2 | SF | \$13 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Art Office | 4 | 6 | SF | \$39 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Principal's Office 1st Floor | 4 | 2 | SF | \$13 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Art Office | 6 | 208 | SF | \$595 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------------|--------------------------------------|------------------------------|------------------------------|------|----------|------|----------|--------|
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Main Office 1st Floor | 6 | 775 | SF | \$1,829 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Principal's Office 1st Floor | 6 | 243 | SF | \$573 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 1st Floor Conference Room | 6 | 339 | SF | \$800 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 1st Floor Faculty Lounge | 6 | 637 | SF | \$1,503 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement Engineer's Office | 6 | 443 | SF | \$1,045 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 2nd Floor Teachers Lounge | 6 | 614 | SF | \$1,449 | |
| Doors | | Interior Steel Doors incl hw | Entire Building | 6 | 8 | EA | \$2,265 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 6 | 94 | EA | \$26,615 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 4 | 7 | EA | \$22,462 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 5 | 28 | EA | \$13,213 | |
| Doors | | Transom Window | Entire Building | 6 | 500 | SF | \$9,295 | |
| Drinking Fountains | Corridors | Double Fountain | 3rd Floor | 4 | 1 | EA | \$6,578 | |
| Drinking Fountains | Corridors | Single Fountain | 2nd Floor | 6 | 2 | EA | \$772 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Bleacher Seating | 3rd Floor | | | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Ceiling - Plaster/Drywall | 3rd Floor | 6 | 3,578 | SF | \$30,597 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Flooring - Wood | 3rd Floor | 6 | 352 | SF | \$2,658 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Flooring - Wood | 3rd Floor | 6 | 3,578 | SF | \$27,015 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Lighting - Pendant/Surface | 3rd Floor | 5 | 15 | EA | \$8,151 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Scoreboards | 3rd Floor | | | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Sound System | 3rd Floor | | | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Stage Curtain | 3rd Floor | 6 | 4 | EA | \$37,752 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Walls - Plaster/Drywall | 3rd Floor | 5 | 2,885 | SF | \$41,256 | |
| Locker/Shower Room | Early Childhood Student Restroom | Benches | In Room 108 | | | LF | \$0 | |
| Locker/Shower Room | Staff Restroom | Benches | 2nd Floor | | | LF | \$0 | |
| Locker/Shower Room | Early Childhood Student Restroom | Benches | In Room 104 | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Benches | Girls 1st Floor | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Benches | Boys Basement | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Benches | Girls Basement | | | LF | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Benches | Boys 1st Floor | | | LF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------------------------|----------------------------|----------------------------------|------|----------|------|-----------|--------|
| Locker/Shower Room | Children's Standard Student Restroom | Benches | Basement, Not Used | | | LF | \$0 | |
| Locker/Shower Room | Early Childhood Student Restroom | Lockers | In Room 108 | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | Boys Basement | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | Basement, Not Used | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | Girls Basement | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | Girls 1st Floor | | | EA | \$0 | |
| Locker/Shower Room | Early Childhood Student Restroom | Lockers | In Room 104 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Lockers | 2nd Floor | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Lockers | Boys 1st Floor | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | Basement, Not Used | 4 | 1 | EA | \$2,431 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | Boys Basement | | | EA | \$0 | |
| Locker/Shower Room | Early Childhood Student Restroom | Showers | In Room 104 | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | Girls Basement | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | Boys 1st Floor | | | EA | \$0 | |
| Locker/Shower Room | Early Childhood Student Restroom | Showers | In Room 108 | | | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | 2nd Floor | | | EA | \$0 | |
| Locker/Shower Room | Children's Standard Student Restroom | Showers | Girls 1st Floor | | | EA | \$0 | |
| Lunchroom | Lunchroom | Ceiling - Plaster/Drywall | Room 208 | 6 | 925 | SF | \$2,619 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Room 208 | 6 | 925 | SF | \$1,323 | |
| Lunchroom | Lunchroom | Lighting - Pendant/Surface | Room 208 | 4 | 16 | SF | \$105 | |
| Lunchroom | Lunchroom | Serving Line | Room 208 | 6 | 17 | LF | \$729 | |
| Lunchroom | Lunchroom | Wall - Plaster/Drywall | Room 208 | 6 | 1,376 | SF | \$3,247 | |
| MDF/IDF | | Finishes | Basement | 5 | 126 | SF | \$1,413 | |
| MDF/IDF | | Ventilation and Cooling | Basement | 6 | 126 | EA | \$176,576 | |
| Mechanical/Service Rooms | | Boiler Room | Basement | 5 | 2,472 | SF | \$27,997 | |
| Mechanical/Service Rooms | | Storage Room | Storage at Main Office 1st Floor | 6 | 178 | SF | \$840 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------------------------|---------------------------|------------------------------------|------|----------|------|----------|--------|
| Mechanical/Service Rooms | | Storage Room | Total Classroom Wardrobe Storage | 6 | 2,404 | SF | \$11,344 | |
| Mechanical/Service Rooms | | Storage Room | Basement Office Storage | 6 | 172 | SF | \$812 | |
| Mechanical/Service Rooms | | Storage Room | 2nd Floor Storage at Lunchroom | 6 | 178 | SF | \$840 | |
| Mechanical/Service Rooms | | Storage Room | Basement | 5 | 157 | SF | \$1,778 | |
| Mechanical/Service Rooms | | Storage Room | Basement Room 006 | 6 | 811 | SF | \$3,827 | |
| Mechanical/Service Rooms | | Storage Room | Basement Room 007 | 6 | 700 | SF | \$3,303 | |
| Mechanical/Service Rooms | | Storage Room | Wardrobe at 104 | 6 | 68 | SF | \$321 | |
| Mechanical/Service Rooms | | Storage Room | Basement Boys Playroom 008 Storage | 5 | 178 | SF | \$2,016 | |
| Mechanical/Service Rooms | | Storage Room | Basement Storage 003 | 5 | 45 | SF | \$510 | |
| Mechanical/Service Rooms | | Storage Room | Basement Fire Pump | 5 | 85 | SF | \$963 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | In Room 104 | 6 | 46 | SF | \$355 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Girls 1st Floor | 6 | 315 | SF | \$2,432 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Boys 1st Floor | 6 | 280 | SF | \$2,162 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Girls Basement | 6 | 600 | SF | \$4,633 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd Floor | 6 | 102 | SF | \$788 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Boys Basement | 6 | 918 | SF | \$7,089 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Basement, Not Used | 5 | 161 | SF | \$4,103 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | In Room 108 | 6 | 25 | SF | \$193 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Exposed | In Room 108 | 6 | 25 | SF | \$47 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Plaster/Drywall | In Room 104 | 6 | 46 | SF | \$130 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Boys 1st Floor | 5 | 280 | SF | \$1,586 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Girls 1st Floor | 6 | 315 | SF | \$892 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Basement, Not Used | 5 | 161 | SF | \$912 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Boys Basement | 5 | 918 | SF | \$5,198 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd Floor | 6 | 102 | SF | \$289 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|--------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Girls Basement | 5 | 600 | SF | \$3,398 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | In Room 108 | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Boys 1st Floor | 6 | 1 | EA | \$300 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Girls Basement | 6 | 2 | EA | \$601 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Boys Basement | 6 | 2 | EA | \$601 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Girls 1st Floor | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | In Room 104 | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Basement, Not Used | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 2nd Floor | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | Basement, Not Used | 6 | 161 | SF | \$760 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Concrete | Boys Basement | 5 | 918 | SF | \$4,332 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Girls Basement | 6 | 600 | SF | \$1,527 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Girls 1st Floor | 6 | 315 | SF | \$802 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Boys 1st Floor | 5 | 280 | SF | \$4,404 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | 2nd Floor | 6 | 102 | SF | \$146 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile/Sheet | In Room 104 | 5 | 46 | SF | \$260 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile/Sheet | In Room 108 | 6 | 25 | SF | \$36 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Basement, Not Used | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | 2nd Floor | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Hand Dryer | In Room 108 | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Hand Dryer | In Room 104 | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Girls 1st Floor | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Boys Basement | 6 | 1 | EA | \$217 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------|--------------------|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Boys Basement | 4 | 1 | EA | \$2,171 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Girls Basement | 6 | 1 | EA | \$217 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Boys 1st Floor | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | In Room 104 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Basement, Not Used | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | In Room 108 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Girls 1st Floor | 6 | 3 | EA | \$1,115 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Boys Basement | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Girls Basement | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Boys 1st Floor | 6 | 2 | EA | \$744 | |
| Staff Restroom | Staff Restroom | Lavatory | 2nd Floor | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Boys Basement | 5 | 6 | SF | \$9 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Boys 1st Floor | 5 | 7 | SF | \$10 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Girls Basement | 5 | 6 | SF | \$9 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Girls 1st Floor | 5 | 5 | SF | \$7 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 2nd Floor | 4 | 1 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Basement, Not Used | 4 | 3 | SF | \$13 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Pendant/ Surface | In Room 104 | 4 | 1 | SF | \$4 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Girls 1st Floor | 6 | 8 | EA | \$1,435 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Boys 1st Floor | 6 | 3 | EA | \$538 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Boys Basement | 6 | 4 | EA | \$717 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Basement, Not Used | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Partitions | In Room 104 | | | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|--------------------------------|--------------------|------|----------|------|---------|--------|
| Staff Restroom | Early Childhood Student Restroom | Partitions | In Room 108 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 2nd Floor | 6 | 2 | EA | \$359 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Girls Basement | 6 | 10 | EA | \$1,793 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Boys Basement | 5 | 1 | EA | \$1,859 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Boys 1st Floor | 6 | 5 | EA | \$1,859 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Girls Basement | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Boys Basement | 6 | 7 | EA | \$2,603 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Girls 1st Floor | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Urinals | In Room 104 | | | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Urinals | In Room 108 | | | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | 2nd Floor | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Basement, Not Used | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Basement, Not Used | 5 | 646 | SF | \$3,048 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 2nd Floor | 6 | 546 | SF | \$1,288 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | In Room 108 | 6 | 70 | SF | \$165 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Plaster/Drywall | In Room 104 | 6 | 211 | SF | \$498 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Girls 1st Floor | 6 | 534 | SF | \$1,260 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Girls Basement | 5 | 998 | SF | \$4,710 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Boys 1st Floor | 6 | 480 | SF | \$1,133 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Boys Basement | 7 | 204 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Girls Basement | 7 | 182 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Girls 1st Floor | 6 | 697 | SF | \$1,774 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Tile Ceramic/ Porcelain | Boys 1st Floor | 6 | 600 | SF | \$1,527 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|--------------------------------------|--------------------------------|--------------------|------|----------|------|------------------|--------|
| Staff Restroom | Early Childhood Student Restroom | Wall - Tile Ceramic/ Porcelain | In Room 108 | 6 | 70 | SF | \$178 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | In Room 104 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | In Room 108 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd Floor | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Basement, Not Used | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Girls 1st Floor | 6 | 8 | EA | \$2,974 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Boys Basement | 6 | 4 | EA | \$1,487 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Girls Basement | 6 | 10 | EA | \$3,718 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Boys 1st Floor | 6 | 3 | EA | \$1,115 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| INTERIOR Sub Total | | | | | | | \$590,845 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------|-------------------------------|-----------------------------|------------------------------|------|----------|------|---------|--------|
| ADMIN_WALL | Administrative Suites/Offices | Administrative Office Walls | Main Office 1st Floor | 6 | 376 | SF | \$887 | |
| ADMIN_WALL | Administrative Suites/Offices | Administrative Office Walls | Principal's Office 1st Floor | 6 | 397 | SF | \$937 | |
| ADMIN_WALL | Administrative Suites/Offices | Administrative Office Walls | 1st Floor Conference Room | 6 | 456 | SF | \$1,076 | |
| ADMIN_WALL | Administrative Suites/Offices | Administrative Office Walls | Art Office | 4 | 834 | SF | \$7,871 | |
| Casework | Classroom | Casework | | 6 | 4 | LF | \$143 | |
| Casework | Classroom | Casework | | 5 | 6 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 5 | 6 | LF | \$1,073 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 5 | 4 | LF | \$715 | |
| Casework | Classroom | Casework | | 5 | 4 | LF | \$715 | |
| Casework | Classroom | Casework | | 5 | 6 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 5 | 3 | LF | \$536 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|-----------------|----------|------|----------|------|----------|--------|
| Casework | Classroom | Casework | | 5 | 6 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 12 | LF | \$429 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 7 | LF | \$250 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 5 | 6 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 6 | 4 | LF | \$143 | |
| Casework | Classroom | Casework | | 4 | 28 | LF | \$13,013 | |
| Casework | Classroom | Casework | | 5 | 22 | LF | \$3,933 | |
| Casework | Classroom | Casework | | 5 | 4 | LF | \$715 | |
| Casework | Classroom | Casework | | 5 | 6 | LF | \$1,073 | |
| Casework | Classroom | Casework | | 5 | 12 | LF | \$2,145 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 5 | 8 | LF | \$1,430 | |
| Ceiling | Classroom | Lay-In/Drop | | 5 | 812 | SF | \$4,598 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 930 | SF | \$5,266 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 930 | SF | \$2,633 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 930 | SF | \$5,266 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 930 | SF | \$5,266 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 416 | SF | \$1,178 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 812 | SF | \$2,299 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 930 | SF | \$5,266 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 812 | SF | \$2,299 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 812 | SF | \$2,299 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 930 | SF | \$2,633 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 925 | SF | \$5,238 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 930 | SF | \$2,633 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 812 | SF | \$2,299 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 930 | SF | \$2,633 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 930 | SF | \$2,633 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 930 | SF | \$5,266 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 930 | SF | \$2,633 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 945 | SF | \$5,351 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,060 | SF | \$3,001 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 812 | SF | \$2,299 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 927 | SF | \$5,249 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|------------------------|------------------------|------|----------|------|---------|--------|
| Ceiling | Classroom | Plaster/Drywall | | 5 | 833 | SF | \$4,717 | |
| Ceiling | Classroom | Plaster/Drywall | | 5 | 815 | SF | \$4,615 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 34 | LF | \$4,133 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | 21 | LF | \$2,553 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 19 | LF | \$2,309 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 36 | LF | \$4,376 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 36 | LF | \$4,376 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 22 | LF | \$2,674 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 22 | LF | \$2,674 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | 38 | LF | \$4,619 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 34 | LF | \$4,133 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 32 | LF | \$3,890 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 46 | LF | \$5,591 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 25 | LF | \$3,039 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Lunchroom | Chalk Board | Room 208 | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | 58 | LF | \$7,050 | |
| Corridors | Corridors | Ceiling | South Stair | 6 | 84 | SF | \$238 | |
| Corridors | Corridors | Concrete Epoxy/Painted | Basement | 6 | 1,055 | SF | \$4,979 | |
| Corridors | Corridors | Concrete Epoxy/Painted | South Stair | 5 | 908 | SF | \$4,285 | |
| Corridors | Corridors | Concrete Epoxy/Painted | North Stair | 5 | 576 | SF | \$2,718 | |
| Corridors | Corridors | Concrete Epoxy/Painted | Vestibule Basement | 5 | 54 | SF | \$255 | |
| Corridors | Corridors | Drinking Fountains | Boys Bathroom Corridor | | | EA | \$0 | |
| Corridors | Corridors | Drinking Fountains | South Stair | | | EA | \$0 | |
| Corridors | Corridors | Drinking Fountains | North Stair | | | EA | \$0 | |
| Corridors | Corridors | Drinking Fountains | 1st Floor | | | EA | \$0 | |
| Corridors | Corridors | Drinking Fountains | Vestibule Basement | | | EA | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------|-----------|--------------------|------------------------|------|----------|------|-------------|--------|
| Corridors | Corridors | Drinking Fountains | Basement | | | EA | \$0 | |
| Corridors | Corridors | Floors | 2nd Floor | 6 | 2,451 | SF | \$18,506 | |
| Corridors | Corridors | Floors | 3rd Floor | 6 | 885 | SF | \$6,682 | |
| Corridors | Corridors | Lighting | 1st Floor | 4 | 2,527 | EA | \$1,535,784 | |
| Corridors | Corridors | Pendant/Surface | South Stair | 5 | 908 | EA | \$2,921 | |
| Corridors | Corridors | Pendant/Surface | 3rd Floor | 4 | 885 | EA | \$8,606 | |
| Corridors | Corridors | Pendant/Surface | Basement | 4 | 1,055 | EA | \$10,259 | |
| Corridors | Corridors | Pendant/Surface | Vestibule Basement | 5 | 1 | EA | \$3 | |
| Corridors | Corridors | Pendant/Surface | North Stair | 5 | 576 | EA | \$1,853 | |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 4 | 2,451 | EA | \$23,834 | |
| Corridors | Corridors | Pendant/Surface | Boys Bathroom Corridor | 5 | 136 | EA | \$438 | |
| Corridors | Corridors | Plaster/Drywall | North Stair | 5 | 3,388 | SF | \$15,988 | |
| Corridors | Corridors | Plaster/Drywall | South Stair | 6 | 228 | SF | \$538 | |
| Corridors | Corridors | Plaster/Drywall | Vestibule Basement | 4 | 518 | SF | \$4,889 | |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 6 | 3,218 | SF | \$7,593 | |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 6 | 3,121 | SF | \$7,364 | |
| Corridors | Corridors | Plaster/Drywall | Basement | 6 | 823 | SF | \$1,942 | |
| Corridors | Corridors | Plaster/Drywall | South Stair | 5 | 3,984 | SF | \$18,800 | |
| Corridors | Corridors | Plaster/Drywall | Boys Bathroom Corridor | 6 | 848 | SF | \$2,001 | |
| Corridors | Corridors | Plaster/Drywall | 3rd Floor | 6 | 1,598 | SF | \$3,770 | |
| Corridors | Corridors | Stair Handrails | North Stair | 6 | 164 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | 3rd Floor | | | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | Boys Bathroom Corridor | | | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | South Stair | 6 | 165 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | 1st Floor | 6 | 79 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | Vestibule Basement | 5 | 8 | LF | \$106 | |
| Corridors | Corridors | Stair Handrails | 2nd Floor | | | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | Basement | | | LF | \$0 | |
| Corridors | Corridors | Stairs | 1st Floor | 6 | 22 | EA | \$157 | |
| Corridors | Corridors | Stairs | Vestibule Basement | 6 | 8 | EA | \$57 | |
| Corridors | Corridors | Stairs | 2nd Floor | | | EA | \$0 | |
| Corridors | Corridors | Stairs | 3rd Floor | | | EA | \$0 | |
| Corridors | Corridors | Stairs | Basement | | | EA | \$0 | |
| Corridors | Corridors | Stairs | South Stair | 5 | 84 | EA | \$4,204 | |
| Corridors | Corridors | Stairs | Boys Bathroom Corridor | | | EA | \$0 | |
| Corridors | Corridors | Stairs | North Stair | 5 | 78 | EA | \$3,904 | |
| Corridors | Corridors | Student Lockers | 1st Floor | | | EA | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|------------------------|------------------------|------|----------|------|---------|--------|
| Corridors | Corridors | Student Lockers | 3rd Floor | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | Vestibule Basement | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | North Stair | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | 2nd Floor | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | Basement | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | South Stair | | | EA | \$0 | |
| Corridors | Corridors | Student Lockers | Boys Bathroom Corridor | | | EA | \$0 | |
| Corridors | Corridors | Tile Ceramic/Porcelain | Boys Bathroom Corridor | 6 | 136 | SF | \$346 | |
| Corridors | Corridors | Tile/Sheet Flooring | 1st Floor | 6 | 2,527 | SF | \$3,614 | |
| Corridors | Corridors | Walls | Basement | 6 | 69 | SF | \$163 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Boys Bathroom Corridor | 5 | 136 | SF | \$770 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | South Stair | 5 | 960 | SF | \$5,436 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 1st Floor | 6 | 2,527 | SF | \$7,155 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Vestibule Basement | 5 | 92 | SF | \$521 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 3rd Floor | 6 | 885 | SF | \$2,506 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Basement | 6 | 1,055 | SF | \$2,987 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 2nd Floor | 6 | 2,451 | SF | \$6,940 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | North Stair | 5 | 424 | SF | \$2,401 | |
| Floor | Classroom | Carpet | | 5 | 930 | SF | \$3,325 | |
| Floor | Classroom | Carpet | | 6 | 812 | SF | \$1,161 | |
| Floor | Classroom | Carpet | | 5 | 930 | SF | \$3,325 | |
| Floor | Classroom | Carpet | | 6 | 812 | SF | \$1,161 | |
| Floor | Classroom | Carpet | | 5 | 930 | SF | \$3,325 | |
| Floor | Classroom | Concrete | | 6 | 1,060 | SF | \$5,002 | |
| Floor | Classroom | Concrete | | 5 | 815 | SF | \$3,846 | |
| Floor | Classroom | Concrete | | 6 | 833 | SF | \$3,931 | |
| Floor | Classroom | Concrete | | 6 | 924 | SF | \$4,360 | |
| Floor | Classroom | Tile/Sheet | | 6 | 925 | SF | \$1,323 | |
| Floor | Classroom | Tile/Sheet | | 6 | 930 | SF | \$1,330 | |
| Floor | Classroom | Tile/Sheet | | 6 | 927 | SF | \$1,326 | |
| Floor | Classroom | Wood | | 6 | 930 | SF | \$7,022 | |
| Floor | Classroom | Wood | | 6 | 828 | SF | \$6,252 | |
| Floor | Classroom | Wood | | 6 | 812 | SF | \$6,131 | |
| Floor | Classroom | Wood | | 6 | 812 | SF | \$6,131 | |
| Floor | Classroom | Wood | | 6 | 828 | SF | \$6,252 | |
| Floor | Classroom | Wood | | 6 | 930 | SF | \$7,022 | |
| Floor | Classroom | Wood | | 6 | 930 | SF | \$7,022 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|----------------------|-----------------|-----------|------|----------|------|---------|--------|
| Floor | Classroom | Wood | | 6 | 416 | SF | \$3,141 | |
| Floor | Classroom | Wood | | 6 | 930 | SF | \$7,022 | |
| Floor | Classroom | Wood | | 6 | 930 | SF | \$7,022 | |
| Floor | Classroom | Wood | | 6 | 930 | SF | \$7,022 | |
| Floor | Classroom | Wood | | 6 | 930 | SF | \$7,022 | |
| GYM_WALL | Gymnasium.Auditorium | Gymnasia Walls | 3rd Floor | 6 | 962 | SF | \$8,254 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 4 | EA | \$1,573 | |
| Lighting | Classroom | Pendant/Surface | | 5 | 18 | EA | \$2,574 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 12 | EA | \$858 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 3 | EA | \$215 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 6 | EA | \$2,360 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 6 | EA | \$2,360 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 12 | EA | \$858 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 21 | EA | \$8,258 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 21 | EA | \$1,502 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 7 | EA | \$2,753 | |
| LUNCH_WALL | Lunchroom | Lunchroom Walls | Room 208 | 6 | 416 | SF | \$1,190 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 14 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Lunchroom | Marker Board | Room 208 | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------------|---------------|------|----------|------|----------|--------|
| Marker Board | Classroom | Marker Board | | 7 | 16 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 8 | LF | \$229 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 14 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 6 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 6 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 6 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| RESTROOM_LIGHT | Early Childhood Student Restroom | Restroom Lighting | In Room 108 | | | EA | \$0 | |
| RESTROOM_WALL | Early Childhood Student Restroom | Restroom Walls | In Room 104 | 6 | 141 | SF | \$359 | |
| RESTROOM_WALL | Children's Standard Student Restroom | Restroom Walls | Boys Basement | 5 | 1,190 | SF | \$18,719 | |
| Wall | Classroom | Concrete Block | | 6 | 95 | SF | \$272 | |
| Wall | Classroom | Masonry | | 4 | 1,056 | SF | \$67,954 | |
| Wall | Classroom | Masonry | | 5 | 762 | SF | \$28,767 | |
| Wall | Classroom | Masonry | | 5 | 720 | SF | \$27,181 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,422 | SF | \$3,355 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 327 | SF | \$772 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,457 | SF | \$3,438 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,422 | SF | \$3,355 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,457 | SF | \$3,438 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,447 | SF | \$3,414 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,411 | SF | \$3,329 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,411 | SF | \$3,329 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,100 | SF | \$2,595 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,302 | SF | \$3,072 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,445 | SF | \$3,409 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,269 | SF | \$2,994 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Wall | Classroom | Plaster/Drywall | | 6 | 1,445 | SF | \$3,409 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,447 | SF | \$3,414 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,411 | SF | \$3,329 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,269 | SF | \$2,994 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,290 | SF | \$3,044 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,245 | SF | \$2,938 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,245 | SF | \$2,938 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,156 | SF | \$2,728 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,263 | SF | \$2,980 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,140 | SF | \$2,690 | |
| Wall | Classroom | Wall | | 6 | 289 | SF | \$682 | |
| Wall | Classroom | Wall | | 6 | 330 | SF | \$779 | |

ROOM Sub Total \$2,291,096

Building Main Sub Total \$4,985,429

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|--------------------------------|----------------------|------|----------|------|----------|--------|
| Civil/Drainage | | Catch Basin | Entire Site | 7 | 4 | EA | \$0 | |
| Civil/Drainage | | Catch Basin | Parking Lot | 6 | 1 | EA | \$543 | |
| Civil/Drainage | | Site Manhole | Entire Site | 7 | 8 | EA | \$0 | |
| Fencing | | Chain Link | Entire Site | 6 | 510 | LF | \$7,315 | |
| Fencing | | Ornamental Iron | Entire Site | 7 | 835 | LF | \$0 | |
| Landscape | | Asphalt Play Area/Hardscape | North & South | 5 | 22,285 | SF | \$63,098 | |
| Landscape | | Grass | West | 7 | 261 | SF | \$0 | |
| Landscape | | Hardscape - Concrete | South | 5 | 814 | SF | \$5,075 | |
| Landscape | | Hardscape - Concrete | Entire Site | 6 | 540 | SF | \$1,019 | |
| Landscape | | Irrigation | west | 5 | 261 | SF | \$493 | |
| Landscape | | Parkway trees | Entire Site | 7 | 14 | EA | \$0 | |
| Landscape | | Planting Beds/ Areas | West | 7 | 32 | SF | \$0 | |
| Parking Lot | | Asphalt | East | 6 | 15,510 | SF | \$13,308 | |
| Parking Lot | | Concrete Curbs | East | 6 | 170 | LF | \$1,026 | |
| Parking Lot | | Parking lot interior plantings | East | 7 | 2 | LF | \$0 | |
| Parking Lot | | Vehicular Screening | North of parking lot | 7 | 135 | LF | \$0 | |
| Sidewalks | | Perimeter Sidewalks | Entire Site | 6 | 8,368 | SF | \$15,795 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|--------------------------------------|----------|------|----------|------|------------------|--------|
| Signage | | Flag Pole | NW | 7 | 1 | EA | \$0 | |
| Signage | | Marquee - Free Standing Back Lighted | NW | 7 | 1 | EA | \$0 | |
| SITE Sub Total | | | | | | | \$107,672 | |
| SITE Sub Total | | | | | | | \$107,672 | |

Total Campus Need ^{2 3} \$5,093,101

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

| Room Summary | | | | | | | | | | | | | | |
|-----------------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|--------------------------|
| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
| Building: Main | | | | | | | | | | | | | | |
| 001 | 1060 | | | 4 | 40 | 32 | 14 | | N | N | Y | Classroom | | |
| 003 | 815 | | | | 40 | | | | N | N | N | Classroom | | |
| 008 | 945 | | | 4 | 40 | 45 | 15 | | N | N | Y | Classroom | | |
| 011 | 833 | | | | 40 | | | | N | N | N | Classroom | | |
| 101 | 828 | 1 | 2 | 8 | 40 | 104 | 48 | | N | N | Y | Classroom | | |
| 102 | 930 | 1 | 2 | 6 | 40 | 118 | 54 | | N | N | Y | Classroom | | |
| 103 | 930 | 1 | 2 | 6 | 40 | 80 | 36 | | N | N | Y | Classroom | | |
| 104 | 927 | 1 | 1 | 10 | 40 | 130 | 60 | | N | N | Y | Classroom | | |
| 105 | 812 | | | 8 | 40 | 104 | 48 | | N | N | Y | Classroom | | |
| 106 | 812 | 1 | 2 | 8 | 40 | 104 | 48 | | N | N | Y | Classroom | | |
| 108 | 925 | 1 | 1 | 10 | 40 | 156 | 72 | | N | N | Y | Classroom | | |
| 202 | 930 | 1 | 2 | 10 | 40 | 118 | 54 | | N | N | Y | Classroom | | |
| 203 | 930 | 1 | 2 | 6 | 40 | 80 | 36 | | N | N | Y | Classroom | | |
| 204 | 930 | 1 | 2 | 4 | 40 | 118 | 54 | | N | N | Y | Classroom | | |
| 205 | 812 | 1 | 2 | 3 | 40 | 104 | 48 | | N | N | Y | Classroom | | |
| 206 | 812 | | | 8 | 40 | 104 | 48 | | N | N | Y | Classroom | | |
| 207 | 930 | 1 | 2 | 4 | 40 | 70 | 27 | | N | N | Y | Classroom | | |
| 301 | 828 | 1 | 34 | 72 | 40 | 104 | 48 | | N | N | Y | Classroom | | |
| 302 | 930 | 1 | 2 | 10 | 40 | 118 | 54 | | N | N | Y | Classroom | | |
| 303 | 930 | 1 | 2 | 6 | 40 | 80 | 36 | | N | N | Y | Classroom | | |
| 304 | 930 | 1 | 2 | 4 | 40 | 118 | 54 | | N | N | Y | Classroom | | |
| 306 | 416 | 1 | 2 | 2 | 40 | 20 | 9 | | N | N | Y | Classroom | | |
| 307 | 930 | 1 | 2 | 4 | 40 | 70 | 27 | | N | N | Y | Classroom | | |
| 308 | 930 | 1 | 2 | 4 | 40 | 80 | 36 | | N | N | Y | Classroom | | |
| Other | | | | | | | | | N | N | N | Corridors | | South Stair |
| Other | 2451 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 280 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Boys 1st Floor |
| Other | 136 | | | | | | | | N | N | N | Corridors | | Boys Bathroom Corridor |
| Other | 600 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Girls Basement |
| Other | 885 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | 925 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Room 208 |
| Other | 161 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Basement, Not Used |
| Other | 102 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd Floor |
| Other | 25 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | In Room 108 |
| Other | 46 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | In Room 104 |
| Other | 271 | | | | | | | | N | N | N | Administrative Suites/Offices | | 1st Floor Faculty Lounge |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|------------------------------|
| Other | 194 | | | 2 | | | | | N | N | Y | Administrative Suites/Offices | | 1st Floor Conference Room |
| Other | 160 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Principal's Office 1st Floor |
| Other | 918 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Boys Basement |
| Other | 139 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | 2nd Floor Teachers Lounge |
| Other | 315 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Girls 1st Floor |
| Other | 3578 | | | | | | | | N | N | N | Gymnasia | Gymnasium.Auditorium | 3rd Floor |
| Other | 596 | | | 4 | | | | | N | N | Y | Administrative Suites/Offices | | Art Office |
| Other | 92 | | | | | | | | N | N | N | Corridors | | Vestibule Basement |
| Other | 1055 | | | | | | | | N | N | N | Corridors | | Basement |
| Other | 2527 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | | | | | | | | | N | N | N | Corridors | | North Stair |
| Other | 155 | | | 10 | | | | | N | N | N | Administrative Suites/Offices | | Basement Engineer's Office |
| Other | 529 | | | 8 | | | | | N | N | Y | Administrative Suites/Offices | | Main Office 1st Floor |