

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

Rank 7: The item/system is new or in good condition and no work is required.

Rank 6: The item/system requires general cleaning and/or routine maintenance.

Rank 5: The item/system requires repairs and has not reached the end of its serviceable life.

Rank 4: The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.

Rank 3: The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.

Rank 2: The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.

Rank 1: The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.

Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.

For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.

Total Campus Need also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|--|-----------------------|------|----------|------|-----------|---------------------|
| Canopy | | Metal Canopy | South, west entrances | 4 | 84 | SF | \$13,477 | Damaged and rusted |
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Roof | 6 | 21 | LF | \$10,511 | |
| Doors | | Exterior FRP Door | Entire Building | 6 | 6 | EA | \$3,341 | |
| Doors | | Exterior Steel Door | Entire Building | 6 | 15 | EA | \$4,955 | |
| Doors | | Transom Lite | Entire Building | 6 | 4 | EA | \$1,133 | |
| Entrance | | Entrance Controls - Audio and Video | Main Entrance | 6 | 1 | EA | \$1,430 | |
| Foundation | | Concrete Foundation | Entire Building | 7 | 956 | LF | \$0 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 9 | EA | \$1,931 | Replace dead lamps |
| Lighting | | Exterior Lights - Wall Mounted | Main Entrance | 6 | 9 | EA | \$1,931 | Replace dead lamps |
| Lintels | | Lintels - Steel | Entire Building | 5 | 931 | LF | \$266,266 | Rusted |
| Parapet | | Coping - Metal | South main roof | 7 | 124 | LF | \$0 | |
| Parapet | | Parapet < 16" Height | South main roof | 6 | 124 | LF | \$19,310 | |
| Roof System | | Asphalt Gravel Ballast Roof | Roof | 4 | 30,816 | SF | \$785,272 | Blisters throughout |
| Roof System | | Exterior Downspouts | South low roof | 6 | 16 | LF | \$297 | |

Building: Main
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|---|---------------------------|------|----------|------|-----------|--------|
| Roof System | | Interior Downspouts | Roof | 6 | 368 | LF | \$0 | |
| Roof System | | Roof Structure: Steel/Metal Deck/Concrete Topping | Roof | 7 | 30,816 | SF | \$0 | |
| Superstructure | | Steel | Entire Building | 7 | 45,926 | SF | \$0 | |
| Walls | | Brick | Entire Building | 6 | 18,247 | SF | \$120,551 | |
| Walls | | Prefabricated Metal Panel Wall | East elevation, south end | 6 | 216 | SF | \$1,835 | |
| Windows | | Curtain wall - Glazed Double Pane | Entire Building | 6 | 2,323 | SF | \$21,924 | |
| Windows | | Curtain wall - Insulated panel | Entire Building | 6 | 886 | SF | \$8,362 | |
| Windows | | Window - Guards perforated | Entire Building | 5 | 2,946 | SF | \$74,313 | |
| Windows | | Windows - Casement Aluminum Double-pane | Entire Building | 6 | 2,474 | SF | \$14,151 | |

EXTERIOR Sub Total \$1,350,990

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------|-----------|---|----------------------|------|----------|------|----------|--------|
| Emergency System | | Automatic Transfer switch | Electrical Room | 6 | 1 | EA | \$1,430 | |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Corridors and Stairs | 6 | 6,752 | SF | \$2,897 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Gym | 6 | 3,000 | SF | \$1,587 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Lunch Room | 6 | 2,132 | SF | \$1,128 | |
| Emergency System | | Emergency A/C power - Students Toilets | Student Toilets | 6 | 1,454 | SF | \$624 | |
| Emergency System | | Emergency Battery Packs - Corridors and Stairs | Corridors and Stairs | 7 | 19 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Lunchroom and Gym | Gym | 7 | 10 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Lunchroom and Gym | Lunch Room | 7 | 5 | EA | \$0 | |
| Emergency System | | Emergency Battery Packs - Toilets | Student Toilets | 7 | 4 | EA | \$0 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Corridors and Stairs | 7 | 9 | EA | \$0 | |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | Lunch Room | 7 | 3 | EA | \$0 | |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | Gym | 7 | 6 | EA | \$0 | |
| Emergency System | | Independent Electrical Service for emergency power | Entire Building | 6 | 1 | EA | \$1,430 | |
| Emergency System | | Public Announcement System | Entire Building | 4 | 1 | SF | \$4 | |
| Emergency System | | Security System - CCTV | Entire Building | 6 | 45,926 | SF | \$65,674 | |
| Emergency System | | Security System - Intrusion detection | Electrical Room | 6 | 45,926 | SF | \$42,688 | |
| Main Service | | Main Electrical service - Live Front - 1500 A 120/208/3PH | Electrical Room | 6 | 1 | EA | \$9,295 | |
| Power Distribution | | Lighting and power panels | Entire Building | 4 | 8 | EA | \$43,472 | |
| Power Distribution | | Lighting and power panels | Entire Building | 6 | 19 | EA | \$13,585 | |
| Power Distribution | | Main distribution panels above 600 amp | Electrical Room | 6 | 1 | EA | \$2,145 | |

ELECTRICAL Sub Total \$185,959

Building: Main
Category: FIRE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------|----------|------|----------|------|------|--------|
|-------|-----------|------|----------|------|----------|------|------|--------|

Building: Main
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|--------------------------|-----------------|------|----------|------|------------------|--------|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 6 | 45,926 | SF | \$16,419 | |
| Fire Alarm | | Fire Alarm System | Boiler Room | 4 | 45,926 | SF | \$162,215 | |
| FIRE PROTECTION Sub Total | | | | | | | \$178,634 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|----------------------|------|----------|------|----------|--|
| Air Conditioning | | Condensing Unit - Roof Mounted less than 5 tons | Roof | 7 | 1 | EA | \$0 | |
| Air Conditioning | | Window A/C Unit | Entire Building | 5 | 34 | EA | \$36,465 | |
| Air Handling Systems | | Air Handling Unit Package - Single Zone - Hot Water less than 4,000 cfm | Mechanical Room | 4 | 1 | EA | \$35,750 | No Temperature Control - unit runs wild. |
| Air Handling Systems | | Air Handling Unit Package - Single Zone - Steam 4,000 to 8,000 cfm | Mechanical Room | 4 | 1 | EA | \$50,050 | No Temperature Control - unit runs wild. |
| Air Handling Systems | | Air intake for all Air Handling Units except built up AHU | West Façade | 4 | 1 | EA | \$7,436 | Motorized Damper removed and Louver Blanked off with Sheet Metal - Unit Starved for air. |
| Air Handling Systems | | Air intake for all Air Handling Units except built up AHU | Roof and West Facade | 5 | 2 | EA | \$11,440 | Louver is damaged and needs repair- Intake is rusted on roof |
| Air Handling Systems | | Make Up Air Unit - Indoor Mounted - Hot Water less than 6000 cfm | Mechanical Room | 4 | 1 | EA | \$20,020 | OA Damper Blanked off and Unit Starved for air. No Temperature Control - unit runs wild. |
| Air Handling Systems | | Return Duct Work - Sheet Metal - Exterior Vertical Shaft and Ducts | Entire Building | 7 | 200 | LF | \$0 | |
| Boiler Systems | | Boiler Assembly - Non-Condensing Flexible Tube Hot Water Boiler 2,001MBH-3,000 MBH | Boiler Room | 6 | 2 | EA | \$20,592 | |
| Boiler Systems | | Boiler Auxiliary Non-Condensing Hot Water Boiler 2,001MBH-3,000 MBH | Boiler Room | 6 | 2 | EA | \$11,154 | |
| Boiler Systems | | Combustion Dampers | Boiler Room | 3 | 2 | EA | \$11,154 | Combustion intake damper is inoperable and has failed in the open position. |
| Boiler Systems | | Glycol Feed System | Boiler Room | 3 | 1 | EA | \$3,861 | Glycol feed systems proper glycol levels cannot be maintained. |
| Heating Devices | | Radiators - Hot Water | 3rd Floor | 6 | 58 | EA | \$7,299 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------|-----------|---|--------------------|------|----------|------|-----------|---|
| Mechanical Plumbing | | Piping - Hydronic Supply and Return - Steel or Galvanized | Entire Building | 6 | 1,000 | LF | \$8,866 | |
| Mechanical Plumbing | | Pumps - Hot Water 5 to 10 HP | Boiler Room | 6 | 2 | EA | \$4,004 | |
| Temperature Control | | Direct Digital Control (DDC) System | Entire Building | 2 | 45,926 | SF | \$459,719 | System disconnected |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | Entire Building | 4 | 3 | EA | \$2,789 | |
| Unit Ventilation | | Unit Ventilators - Hot Water-Heating | Entire Building | 6 | 35 | EA | \$50,050 | |
| Ventilation | | Exhaust Fan - Indoor | Entire Building | 6 | 8 | EA | \$4,004 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | South Courtyard | 5 | 1 | EA | \$1,502 | Unit functional but not used due to space allocation. |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 6 | 9 | EA | \$3,861 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 5 | 1 | EA | \$1,502 | Possible Bearing Issues |
| Ventilation | | Exhaust Fans - Roof mounted less than 500 CFM | Roof and Side Wall | 6 | 6 | EA | \$944 | |
| Ventilation | | Type I Exhaust Hood - Kitchen or Culinary Arts | Kitchen | 2 | 1 | EA | \$26,884 | Fire suppressionr does not exist. |

MECHANICAL Sub Total \$779,344

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------|-----------|--|-----------------|------|----------|------|----------|--------|
| Hot Water | | Hot Water Heater - Gas 150,000 -300,000 BTU/HR | Boiler Room | 4 | 1 | EA | \$22,880 | |
| Hot Water | | Hot Water Heater - Gas more than 300,000 BTU/HR | Boiler Room | 4 | 1 | EA | \$32,032 | |
| Hot Water | | Storage Tank more than 500 gallons | Boiler Room | 4 | 1 | EA | \$28,600 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 5 | 22,963 | SF | \$3,940 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 7 | 22,963 | SF | \$0 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 5 | 22,963 | SF | \$7,553 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 7 | 22,963 | SF | \$0 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 5 | 22,963 | SF | \$26,270 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 5 | 45,926 | SF | \$9,851 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 5 | 45,926 | SF | \$11,821 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 5 | 22,963 | SF | \$20,359 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 7 | 22,963 | SF | \$0 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 7 | 22,963 | SF | \$0 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 5 | 22,963 | SF | \$12,150 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 5 | 45,926 | SF | \$24,956 | |
| Piping | | Sanitary Piping | Entire Building | 7 | 22,963 | SF | \$0 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-----------------|-----------------|------|----------|------|------------------|--------|
| Piping | | Sanitary Piping | Entire Building | 5 | 22,963 | SF | \$14,120 | |
| Piping | | Storm Piping | Entire Building | 5 | 45,926 | SF | \$21,672 | |
| Piping | | Vent Piping | Entire Building | 5 | 45,926 | SF | \$16,419 | |
| PLUMBING Sub Total | | | | | | | \$252,623 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|---------------------------|--|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Exposed | First floor, Engineer office | 6 | 94 | SF | \$177 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Main Office 135 | 7 | 448 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Principal's Office | 7 | 180 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 1st floor PE Office | 6 | 90 | SF | \$255 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | First floor, Nurses office | 6 | 255 | SF | \$547 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | First floor, Northwest, Lounge room next to room 101 | 6 | 180 | SF | \$386 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | First floor, doctors office | 6 | 164 | SF | \$352 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | First floor, dentist office | 6 | 132 | SF | \$283 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | First floor, Copy room next to doctors office | 7 | 178 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | Room 215 Faculty Lounge | 6 | 195 | SF | \$418 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | First floor, counselor office suite | 6 | 1,239 | SF | \$2,658 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | First floor, Nurses office | 6 | 255 | SF | \$365 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Main Office 135 | 7 | 302 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Principal's Office | 7 | 180 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Main Office 135 | 6 | 146 | SF | \$209 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Room 215 Faculty Lounge | 6 | 195 | SF | \$279 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|----------------------------|--|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, Northwest, Lounge room next to room 101 | 6 | 180 | SF | \$257 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, doctors office | 6 | 164 | SF | \$235 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, dentist office | 6 | 132 | SF | \$189 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, Copy room next to doctors office | 6 | 178 | SF | \$255 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, counselor office suite | 6 | 1,239 | SF | \$1,772 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, Engineer office | 6 | 94 | SF | \$134 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 1st floor PE Office | 6 | 90 | SF | \$129 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Main Office 135 | 7 | 10 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Principal's Office | 7 | 4 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | First floor, doctors office | 4 | 6 | SF | \$39 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | First floor, dentist office | 4 | 6 | SF | \$39 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 1st floor PE Office | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | First floor, Engineer office | 7 | 1 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | First floor, Copy room next to doctors office | 4 | 6 | SF | \$39 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | First floor, Northwest, Lounge room next to room 101 | 4 | 3 | SF | \$20 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Room 215 Faculty Lounge | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | First floor, counselor office suite | 4 | 24 | SF | \$158 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | First floor, Nurses office | 7 | 6 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | 1st floor PE Office | 6 | 720 | SF | \$2,059 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, Northwest, Lounge room next to room 101 | 6 | 550 | SF | \$1,298 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------------|-------------------------------|--------------------------------------|---|------|----------|------|----------|--------|
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Room 215 Faculty Lounge | 6 | 427 | SF | \$1,008 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, Nurses office | 6 | 395 | SF | \$932 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, doctors office | 6 | 524 | SF | \$1,236 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, dentist office | 6 | 488 | SF | \$1,151 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, Copy room next to doctors office | 6 | 536 | SF | \$1,265 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, counselor office suite | 6 | 2,306 | SF | \$5,441 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, Engineer office | 6 | 352 | SF | \$831 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Main Office 135 | 7 | 830 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Principal's Office | 7 | 630 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Structural Glazed Tile | First floor, counselor office suite | 6 | 373 | SF | \$2,667 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Structural Glazed Tile | First floor, Nurses office | 6 | 133 | SF | \$951 | |
| Doors | | Interior Steel Doors incl hw | Entire Building | 6 | 18 | EA | \$5,097 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 6 | 82 | EA | \$23,217 | |
| Doors | | Side-lite | Entire Building | 6 | 345 | SF | \$6,414 | |
| Doors | | Transom Window | Entire Building | 7 | 10 | SF | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 1st Floor | 6 | 3 | EA | \$1,158 | |
| Drinking Fountains | Corridors | Single Fountain | 2nd Floor | 7 | 3 | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Ceiling - Exposed | 1st Floor | 6 | 3,000 | SF | \$22,823 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Flooring - Wood | 1st Floor | 6 | 3,000 | SF | \$22,651 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 7 | 13 | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Scoreboards | 1st Floor | 7 | 1 | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Sound System | 1st Floor | 7 | 1 | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Stage Curtain | 1st Floor | 7 | 2 | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Walls - Concrete Block | 1st Floor | 6 | 3,700 | SF | \$31,746 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Walls - Structural Glazed Tile | 1st Floor | 6 | 1,590 | SF | \$11,369 | |
| Kitchen | Cooking Kitchen | Ceiling - Plaster/Drywall | 1st Floor | 6 | 876 | SF | \$3,307 | |
| Kitchen | Cooking Kitchen | Flooring - Tile/Sheet | 1st Floor | 6 | 876 | SF | \$1,253 | |
| Kitchen | Cooking Kitchen | Lighting - Pendant/Surface | 1st Floor | 7 | 12 | SF | \$0 | |
| Kitchen | Cooking Kitchen | Wall - Structural Glazed Tile | 1st Floor | 6 | 1,438 | SF | \$10,282 | |
| Library | Library | Flooring Carpet | 1st Floor | 7 | 886 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------|-------------------------------|-------------------------------------|------|----------|------|---------|--------|
| Library | Library | Lighting - Lay-In | 1st Floor | 7 | 14 | SF | \$0 | |
| Locker/Shower Room | Locker/Shower Room | Benches | 1st floor Women's Locker Room | 7 | 10 | LF | \$0 | |
| Locker/Shower Room | Locker/Shower Room | Benches | 1st floor Men's Locker Room | 7 | 10 | LF | \$0 | |
| Locker/Shower Room | Locker/Shower Room | Lockers | 1st floor Women's Locker Room | 7 | 39 | EA | \$0 | |
| Locker/Shower Room | Locker/Shower Room | Lockers | 1st floor Men's Locker Room | 7 | 39 | EA | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | First floor, Janitor staff bathroom | 6 | 1 | EA | \$243 | |
| Locker/Shower Room | Staff Restroom | Showers | First floor, kitchen bathroom | 6 | 1 | EA | \$243 | |
| Lunchroom | Lunchroom | Ceiling - Splined | 1st Floor | 6 | 2,132 | SF | \$4,573 | |
| Lunchroom | Lunchroom | Ceiling - Splined | First floor, staff lunch room | 6 | 487 | SF | \$1,045 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | 1st Floor | 6 | 2,132 | SF | \$3,049 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | First floor, staff lunch room | 6 | 487 | SF | \$696 | |
| Lunchroom | Lunchroom | Lighting - Pendant/Surface | First floor, staff lunch room | 4 | 8 | SF | \$53 | |
| Lunchroom | Lunchroom | Lighting - Pendant/Surface | 1st Floor | 4 | 40 | SF | \$263 | |
| Lunchroom | Cooking Kitchen | Serving Line | 1st Floor | 7 | 18 | LF | \$0 | |
| Lunchroom | Lunchroom | Wall - Concrete Block | 1st Floor | 6 | 1,402 | SF | \$4,010 | |
| Lunchroom | Lunchroom | Wall - Structural Glazed Tile | First floor, staff lunch room | 6 | 1,290 | SF | \$9,224 | |
| Lunchroom | Lunchroom | Wall - Structural Glazed Tile | 1st Floor | 6 | 1,238 | SF | \$8,852 | |
| MDF/IDF | | Finishes | Inside library | 7 | 173 | SF | \$0 | |
| MDF/IDF | | Ventilation and Cooling | Inside library | 7 | 1 | EA | \$0 | |
| Mechanical/Service Rooms | | Boiler Room | 1st Floor | 6 | 783 | SF | \$3,695 | |
| Mechanical/Service Rooms | | Janitor's Closet | Entire Building | 6 | 3 | SF | \$14 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Switchgear Room next to ComED Vault | 6 | 80 | SF | \$378 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 2nd floor Fan Room 223 | 6 | 302 | SF | \$1,425 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Electrical Vault 152 | 6 | 80 | SF | \$378 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | ComEd Vault next to 152 | 7 | 160 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Room 201A | 6 | 70 | SF | \$330 | |
| Mechanical/Service Rooms | | Storage Room | Gym Storage | 6 | 100 | SF | \$472 | |
| Mechanical/Service Rooms | | Storage Room | Main Office Book Room | 6 | 60 | SF | \$283 | |
| Mechanical/Service Rooms | | Storage Room | 2nd floor Book Room 213 | 6 | 232 | SF | \$1,095 | |
| Mechanical/Service Rooms | | Storage Room | In Room 200 | 6 | 160 | SF | \$755 | |
| Mechanical/Service Rooms | | Storage Room | Prep Room 207A | 7 | 205 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, Engineer storage | 6 | 80 | SF | \$378 | |
| Mechanical/Service Rooms | | Storage Room | First floor, kitchen storage | 6 | 185 | SF | \$873 | |
| Mechanical/Service Rooms | | Storage Room | First floor, lunch room storage | 6 | 580 | SF | \$2,737 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|---------------------------------|---------------------------|---|------|----------|------|---------|--------|
| Mechanical/Service Rooms | | Storage Room | First floor, counselor office storage | 6 | 120 | SF | \$566 | |
| Mechanical/Service Rooms | | Storage Room | First floor, nurses storage | 6 | 35 | SF | \$165 | |
| Mechanical/Service Rooms | | Storage Room | First floor, room 101 Storage | 6 | 53 | SF | \$250 | |
| Mechanical/Service Rooms | | Storage Room | First floor, storage room between class 107 and 105 | 6 | 451 | SF | \$2,128 | |
| Mechanical/Service Rooms | | Storage Room | First floor, store room in room 109 | 6 | 99 | SF | \$467 | |
| Mechanical/Service Rooms | | Storage Room | In Room 216 | 6 | 150 | SF | \$708 | |
| Mechanical/Service Rooms | | Vaults | In Main Office | 6 | 266 | SF | \$1,255 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | First floor Women | 7 | 205 | SF | \$0 | |
| Staff Restroom | Locker/Shower Room | Accessories | 1st floor Men's Locker Room | 7 | 310 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | Firs floor, unisex next to library | 6 | 106 | SF | \$819 | |
| Staff Restroom | Staff Restroom | Accessories | In Faculty Lounge 215 | 6 | 58 | SF | \$448 | |
| Staff Restroom | Staff Restroom | Accessories | Firs floor, northwest side | 6 | 58 | SF | \$448 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | 2nd floor Women | 7 | 212 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | Firs floor, Nurses bathroom | 6 | 30 | SF | \$232 | |
| Staff Restroom | Staff Restroom | Accessories | First floor, Guidance counselor office bathroom | 6 | 30 | SF | \$232 | |
| Staff Restroom | Staff Restroom | Accessories | First floor, Janitor staff bathroom | 6 | 133 | SF | \$1,027 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | 2nd floor Men | 7 | 212 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | In Principal's Office | 7 | 22 | SF | \$0 | |
| Staff Restroom | Locker/Shower Room | Accessories | 1st floor Women's Locker Room | 7 | 310 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | First floor Men | 7 | 205 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | First floor, kitchen bathroom | 6 | 146 | SF | \$1,127 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | First floor, Janitor staff bathroom | 6 | 86 | SF | \$184 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | First floor, Janitor staff bathroom | 6 | 47 | SF | \$133 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Principal's Office | 7 | 22 | SF | \$0 | |
| Staff Restroom | Locker/Shower Room | Ceiling - Plaster/Drywall | 1st floor Men's Locker Room | 7 | 310 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Firs floor, Nurses bathroom | 6 | 30 | SF | \$85 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | First floor Women | 7 | 205 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|---------------------------------|-----------------------------------|---|------|----------|------|-------|--------|
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | First floor, kitchen bathroom | 6 | 146 | SF | \$413 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Firs floor, northwest side | 6 | 58 | SF | \$164 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Firs floor, unisex next to library | 6 | 106 | SF | \$300 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | First floor Men | 7 | 205 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | First floor, Guidance counselor office bathroom | 6 | 30 | SF | \$85 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd floor Women | 7 | 212 | SF | \$0 | |
| Staff Restroom | Locker/Shower Room | Ceiling - Plaster/Drywall | 1st floor Women's Locker Room | 7 | 310 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd floor Men | 7 | 212 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In Faculty Lounge 215 | 6 | 58 | SF | \$164 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | 2nd floor Men | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | Firs floor, unisex next to library | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | First floor, Janitor staff bathroom | 6 | 1 | EA | \$300 | |
| Staff Restroom | Staff Restroom | Floor Drain | First floor, kitchen bathroom | 6 | 1 | EA | \$300 | |
| Staff Restroom | Locker/Shower Room | Floor Drain | 1st floor Men's Locker Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | In Faculty Lounge 215 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | 2nd floor Women | 7 | 1 | EA | \$0 | |
| Staff Restroom | Locker/Shower Room | Floor Drain | 1st floor Women's Locker Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | First floor Men | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | First floor Women | 7 | 1 | EA | \$0 | |
| Staff Restroom | Locker/Shower Room | Flooring - Concrete | 1st floor Women's Locker Room | 7 | 180 | SF | \$0 | |
| Staff Restroom | Locker/Shower Room | Flooring - Concrete | 1st floor Men's Locker Room | 7 | 180 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, Guidance counselor office bathroom | 6 | 30 | SF | \$76 | |
| Staff Restroom | Locker/Shower Room | Flooring - Tile Ceramic/Porcelain | 1st floor Men's Locker Room | 7 | 130 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Firs floor, northwest side | 6 | 58 | SF | \$148 | |
| Staff Restroom | Locker/Shower Room | Flooring - Tile Ceramic/Porcelain | 1st floor Women's Locker Room | 7 | 130 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | In Principal's Office | 7 | 22 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|---------------------------------|-----------------------------------|---|------|----------|------|-------|--------|
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, Janitor staff bathroom | 6 | 47 | SF | \$120 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, kitchen bathroom | 6 | 50 | SF | \$127 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Firs floor, unisex next to library | 6 | 106 | SF | \$270 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | First floor Men | 7 | 205 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | First floor Women | 7 | 205 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Firs floor, Nurses bathroom | 6 | 30 | SF | \$76 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd floor Men | 7 | 212 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd floor Women | 7 | 212 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | In Faculty Lounge 215 | 6 | 58 | SF | \$148 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | First floor, Janitor staff bathroom | 6 | 86 | SF | \$123 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | First floor, kitchen bathroom | 6 | 96 | SF | \$137 | |
| Staff Restroom | Locker/Shower Room | Hand Dryer | 1st floor Men's Locker Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | Firs floor, unisex next to library | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | First floor Women | 7 | 1 | EA | \$0 | |
| Staff Restroom | Locker/Shower Room | Hand Dryer | 1st floor Women's Locker Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | First floor Men | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | 2nd floor Women | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Faculty Lounge 215 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | 2nd floor Men | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Firs floor, northwest side | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, Janitor staff bathroom | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Lavatory | Firs floor, Nurses bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, Guidance counselor office bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | First floor Women | 7 | 2 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | First floor Men | 7 | 2 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|---------------------------------|-----------------------------|---|------|----------|------|-------|--------|
| Staff Restroom | Locker/Shower Room | Lavatory | 1st floor Women's Locker Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Firs floor, unisex next to library | 7 | 1 | EA | \$0 | |
| Staff Restroom | Locker/Shower Room | Lavatory | 1st floor Men's Locker Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In Principal's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, kitchen bathroom | 6 | 1 | EA | \$372 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Lay-In | 2nd floor Women | 7 | 4 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Lay-In | 2nd floor Men | 7 | 4 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Lay-In | First floor Men | 7 | 4 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Lay-In | First floor Women | 7 | 4 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | First floor, Janitor staff bathroom | 6 | 2 | SF | \$1 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | In Faculty Lounge 215 | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Firs floor, northwest side | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Firs floor, unisex next to library | 4 | 1 | SF | \$4 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | First floor, kitchen bathroom | 6 | 2 | SF | \$1 | |
| Staff Restroom | Locker/Shower Room | Lighting - Pendant/ Surface | 1st floor Men's Locker Room | 7 | 5 | SF | \$0 | |
| Staff Restroom | Locker/Shower Room | Lighting - Pendant/ Surface | 1st floor Women's Locker Room | 7 | 5 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | In Principal's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | Firs floor, unisex next to library | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | First floor, Guidance counselor office bathroom | 4 | 1 | EA | \$322 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | Firs floor, Nurses bathroom | 4 | 1 | EA | \$322 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | In Faculty Lounge 215 | 4 | 1 | EA | \$322 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | 2nd floor Men | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | 2nd floor Women | 7 | 3 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | First floor Men | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | Firs floor, northwest side | 6 | 1 | EA | \$179 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | First floor Women | 7 | 3 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|---------------------------------|-------------------------------|---|------|----------|------|---------|--------|
| Staff Restroom | Locker/Shower Room | Partitions | 1st floor Women's Locker Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Locker/Shower Room | Partitions | 1st floor Men's Locker Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | In Principal's Office | 6 | 2 | EA | \$359 | |
| Staff Restroom | Staff Restroom | Partitions | First floor, kitchen bathroom | 6 | 1 | EA | \$179 | |
| Staff Restroom | Staff Restroom | Partitions | First floor, Janitor staff bathroom | 6 | 1 | EA | \$179 | |
| Staff Restroom | Staff Restroom | Partitions | In Faculty Lounge 215 | 6 | 2 | EA | \$359 | |
| Staff Restroom | Locker/Shower Room | Urinals | 1st floor Men's Locker Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | First floor Men | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | Firs floor, northwest side | 6 | 1 | EA | \$372 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | 2nd floor Men | 7 | 2 | EA | \$0 | |
| Staff Restroom | Locker/Shower Room | Wall - Concrete Block | 1st floor Women's Locker Room | 7 | 345 | SF | \$0 | |
| Staff Restroom | Locker/Shower Room | Wall - Concrete Block | 1st floor Men's Locker Room | 7 | 345 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | First floor, Janitor staff bathroom | 6 | 308 | SF | \$881 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | Firs floor, unisex next to library | 6 | 164 | SF | \$469 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Concrete Block | 2nd floor Men | 7 | 500 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Concrete Block | 2nd floor Women | 7 | 500 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | First floor, Guidance counselor office bathroom | 6 | 130 | SF | \$307 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In Principal's Office | 6 | 160 | SF | \$378 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Firs floor, Nurses bathroom | 6 | 130 | SF | \$307 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | Firs floor, unisex next to library | 6 | 164 | SF | \$1,173 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | In Faculty Lounge 215 | 6 | 250 | SF | \$1,788 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Structural Glazed Tile | 2nd floor Women | 7 | 75 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Structural Glazed Tile | 2nd floor Men | 7 | 75 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | Firs floor, northwest side | 6 | 250 | SF | \$1,788 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | Firs floor, Nurses bathroom | 6 | 48 | SF | \$343 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | First floor, Guidance counselor office bathroom | 6 | 48 | SF | \$343 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Structural Glazed Tile | First floor Men | 7 | 484 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------|---------------------------------|-------------------------------|---|------|----------|------|---------|--------|
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | First floor, Janitor staff bathroom | 6 | 228 | SF | \$1,630 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | First floor, kitchen bathroom | 6 | 410 | SF | \$2,932 | |
| Staff Restroom | Locker/Shower Room | Wall - Structural Glazed Tile | 1st floor Women's Locker Room | 7 | 380 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Structural Glazed Tile | First floor Women | 7 | 484 | SF | \$0 | |
| Staff Restroom | Locker/Shower Room | Wall - Structural Glazed Tile | 1st floor Men's Locker Room | 7 | 380 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | First floor, kitchen bathroom | 6 | 1 | EA | \$372 | |
| Staff Restroom | Locker/Shower Room | Water Closet | 1st floor Women's Locker Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Locker/Shower Room | Water Closet | 1st floor Men's Locker Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In Principal's Office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | First floor, Janitor staff bathroom | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | Firs floor, unisex next to library | 6 | 1 | EA | \$372 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | First floor Men | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | First floor Women | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | First floor, Guidance counselor office bathroom | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | Firs floor, Nurses bathroom | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | Firs floor, northwest side | 6 | 1 | EA | \$372 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | 2nd floor Men | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | In Faculty Lounge 215 | 7 | 2 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | 2nd floor Women | 7 | 3 | EA | \$0 | |
| Theater | | Stage | 1st floor Gym/Assembly | 6 | 470 | SF | \$1,996 | |
| Theater | | Stage Lighting System | 1st floor Gym/Assembly | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 2 | EA | \$772 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|------|----------|------|----------|------|------------------|--------|
| INTERIOR Sub Total | | | | | | | \$249,028 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 6 | 12 | LF | \$429 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 5 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 10 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 6 | 50 | LF | \$1,788 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 6 | 50 | LF | \$1,788 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 819 | SF | \$1,757 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 812 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 700 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 812 | SF | \$0 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 812 | SF | \$1,742 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 734 | SF | \$1,574 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 848 | SF | \$1,819 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 545 | SF | \$1,169 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 545 | SF | \$1,169 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 545 | SF | \$1,169 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 545 | SF | \$1,169 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 545 | SF | \$1,169 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 812 | SF | \$1,742 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 545 | SF | \$1,169 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 855 | SF | \$1,834 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 550 | SF | \$1,180 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|------------------------|-------------------------|------|----------|------|---------|--------|
| Ceiling | Classroom | Splined Ceiling | | 6 | 855 | SF | \$1,834 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 550 | SF | \$1,180 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 550 | SF | \$1,180 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 852 | SF | \$1,828 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 545 | SF | \$1,169 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 812 | SF | \$1,742 | |
| Ceiling | Classroom | Splined Ceiling | | 6 | 545 | SF | \$1,169 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 9 | LF | \$1,094 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 8 | LF | \$972 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 16 | LF | \$1,945 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 4 | LF | \$486 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 10 | LF | \$1,216 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 10 | LF | \$1,216 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 10 | LF | \$1,216 | |
| CLASSROOM | Classroom | Eye Wash Station | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Science Lab Elements | | 7 | 812 | SF | \$0 | |
| CLASSROOM | Classroom | Science Lab Shower | | 7 | 1 | EA | \$0 | |
| Corridors | Corridors | Concrete Epoxy/Painted | Entire Building, Stairs | 6 | 88 | SF | \$415 | |
| Corridors | Corridors | Drop/Lay-In | 1st Floor | 6 | 4,275 | SF | \$9,170 | |
| Corridors | Corridors | Drop/Lay-In | Entire Building, Stairs | 6 | 270 | SF | \$579 | |
| Corridors | Corridors | Drop/Lay-In | 2nd Floor | 6 | 2,207 | SF | \$4,734 | |
| Corridors | Corridors | Lay-In | Entire Building, Stairs | 7 | 270 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 1st Floor | 6 | 4,275 | EA | \$3,057 | |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 7 | 2,207 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | Entire Building, Stairs | 7 | 240 | EA | \$0 | |
| Corridors | Corridors | Single Water Cooler | 1st Floor | 6 | 1 | EA | \$615 | |
| Corridors | Corridors | Single Water Cooler | 2nd Floor | 6 | 1 | EA | \$615 | |
| Corridors | Corridors | Stair Handrails | Entire Building, Stairs | 6 | 90 | LF | \$0 | |
| Corridors | Corridors | Stair Handrails | Stage Stairs | 6 | 20 | LF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|------------------------|-------------------------|------|----------|------|-----------|-----------------|
| Corridors | Corridors | Structural Glazed Tile | 1st Floor | 6 | 6,658 | SF | \$47,605 | |
| Corridors | Corridors | Structural Glazed Tile | 2nd Floor | 6 | 3,480 | SF | \$24,882 | |
| Corridors | Corridors | Structural Glazed Tile | Entire Building, Stairs | 6 | 1,500 | SF | \$10,725 | |
| Corridors | Corridors | Student Lockers | 2nd Floor | 7 | 107 | EA | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | Entire Building, Stairs | 6 | 240 | SF | \$343 | |
| Corridors | Corridors | Tile/Sheet Flooring | 2nd Floor | 6 | 2,207 | SF | \$3,156 | |
| Corridors | Corridors | Tile/Sheet Flooring | 1st Floor | 6 | 4,275 | SF | \$6,113 | |
| Corridors | Corridors | Wall Mounted | Entire Building, Stairs | 4 | 88 | EA | \$339,768 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Entire Building, Stairs | 6 | 154 | SF | \$436 | |
| Stairs | Corridors | Asphalt | Entire Building, Stairs | 6 | 40 | SF | \$286 | |
| Stairs | Corridors | Tile | Stage Stairs | 6 | 10 | SF | \$76 | |
| Floor | Classroom | Tile/Sheet | | 6 | 545 | SF | \$779 | |
| Floor | Classroom | Tile/Sheet | | 6 | 852 | SF | \$1,218 | |
| Floor | Classroom | Tile/Sheet | | 6 | 812 | SF | \$1,161 | |
| Floor | Classroom | Tile/Sheet | | 6 | 545 | SF | \$779 | |
| Floor | Classroom | Tile/Sheet | | 6 | 545 | SF | \$779 | |
| Floor | Classroom | Tile/Sheet | | 7 | 812 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 545 | SF | \$779 | |
| Floor | Classroom | Tile/Sheet | | 6 | 812 | SF | \$1,161 | |
| Floor | Classroom | Tile/Sheet | | 6 | 550 | SF | \$787 | |
| Floor | Classroom | Tile/Sheet | | 6 | 550 | SF | \$787 | |
| Floor | Classroom | Tile/Sheet | | 6 | 550 | SF | \$787 | |
| Floor | Classroom | Tile/Sheet | | 6 | 700 | SF | \$1,001 | |
| Floor | Classroom | Tile/Sheet | | 6 | 812 | SF | \$1,161 | |
| Floor | Classroom | Tile/Sheet | | 6 | 545 | SF | \$779 | |
| Floor | Classroom | Tile/Sheet | | 6 | 855 | SF | \$1,223 | |
| Floor | Classroom | Tile/Sheet | | 6 | 545 | SF | \$779 | |
| Floor | Classroom | Tile/Sheet | | 7 | 812 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 855 | SF | \$1,223 | |
| Floor | Classroom | Tile/Sheet | | 6 | 545 | SF | \$779 | |
| Floor | Classroom | Tile/Sheet | | 4 | 734 | SF | \$10,391 | Dmaged and worn |
| Floor | Classroom | Tile/Sheet | | 6 | 848 | SF | \$1,213 | |
| Floor | Classroom | Tile/Sheet | | 6 | 819 | SF | \$1,171 | |
| Floor | Classroom | Tile/Sheet | | 6 | 545 | SF | \$779 | |
| LIBRARY_CEILING | Library | Drop/Lay-In | 1st Floor | 7 | 886 | SF | \$0 | |
| LIBRARY_WALL | Library | Plaster/Drywall | 1st Floor | 6 | 1,182 | | \$2,789 | |
| Lighting | Classroom | Lay-In | | 7 | 13 | EA | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Lighting | Classroom | Lay-In | | 7 | 12 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 12 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 20 | EA | \$7,865 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 20 | EA | \$7,865 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 15 | EA | \$5,899 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 12 | EA | \$4,719 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 20 | EA | \$7,865 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 21 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 15 | EA | \$5,899 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 20 | EA | \$7,865 | |
| Lighting | Classroom | Pendant/Surface | | 4 | 18 | EA | \$7,079 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 15 | EA | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 4 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 16 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 16 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 28 | LF | \$801 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 10 | LF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 960 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 960 | SF | \$2,265 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 732 | SF | \$1,727 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 820 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,012 | SF | \$2,388 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 782 | SF | \$1,845 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Wall | Classroom | Plaster/Drywall | | 6 | 782 | SF | \$1,845 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 732 | SF | \$1,727 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,022 | SF | \$2,411 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 782 | SF | \$1,845 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,028 | SF | \$2,426 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 960 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,061 | SF | \$2,503 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,002 | SF | \$2,364 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 849 | SF | \$2,003 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 732 | SF | \$1,727 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 732 | SF | \$1,727 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 732 | SF | \$1,727 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 732 | SF | \$1,727 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 732 | SF | \$1,727 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 960 | SF | \$2,265 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 732 | SF | \$1,727 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 960 | SF | \$2,265 | |

ROOM Sub Total \$644,556

Building Main Sub Total \$3,641,133

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|-----------------------------|------------------------|------|----------|------|----------|--------|
| Civil/Drainage | | Catch Basin | Entire Site | 6 | 3 | EA | \$1,630 | |
| Civil/Drainage | | Site Manhole | Entire Site | 7 | 3 | EA | \$0 | |
| Fencing | | Chain Link | North, east perimeters | 4 | 618 | LF | \$66,281 | |
| Fencing | | Chain Link | South, west perimeters | 6 | 324 | LF | \$4,647 | |
| Fencing | | Ornamental Iron | Site ζ North | 7 | 58 | LF | \$0 | |
| Landscape | | Asphalt Play Area/Hardscape | Playground | 6 | 25,093 | SF | \$21,530 | |
| Landscape | | Grass | Entire Site | 6 | 8,236 | SF | \$3,298 | |
| Landscape | | Hardscape - Concrete | Entire Site | 6 | 2,414 | SF | \$4,557 | |
| Landscape | | Hardscape - Pavers | Parking Lot | 7 | 5,104 | SF | \$0 | |
| Landscape | | Parkway trees | North, East and South | 6 | 19 | EA | \$5,434 | |
| Landscape | | Planting Beds/ Areas | Entire Site | 6 | 716 | SF | \$0 | |
| Parking Lot | | Asphalt | Site ζ South | 6 | 6,288 | SF | \$5,395 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|---|-----------------------|------|----------|------|------------------|--------|
| Parking Lot | | Concrete | Site ζ South | 7 | 1,378 | SF | \$0 | |
| Parking Lot | | Concrete Curbs | Parking Lot | 7 | 255 | LF | \$0 | |
| Parking Lot | | Trash Enclosure | Site ζ South | 7 | 996 | SF | \$0 | |
| Sidewalks | | Perimeter Sidewalks | North, East and South | 6 | 6,916 | SF | \$13,055 | |
| Signage | | Flag Pole | Main Entrance | 6 | 1 | EA | \$0 | |
| Signage | | Marquee - Building Mounted Back Lighted | Main Entrance | 6 | 1 | EA | \$0 | |
| SITE Sub Total | | | | | | | \$125,826 | |
| SITE Sub Total | | | | | | | \$125,826 | |

Total Campus Need ^{2 3} \$3,766,959

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-----------------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|---------------------------------|--|
| Building: Main | | | | | | | | | | | | | | |
| 101 | 855 | 1 | 8 | 26 | 40 | 55 | 35 | 1 | Y | N | N | Classroom | | |
| 102 | 550 | 1 | 5 | 16 | 40 | 55 | 35 | 1 | Y | Y | N | Classroom | | |
| 103 | 855 | 1 | 8 | 26 | 40 | 55 | 35 | 1 | Y | N | N | Classroom | | |
| 104 | 550 | 1 | 5 | 16 | 40 | 55 | 35 | 1 | Y | Y | N | Classroom | | |
| 105 | 852 | 1 | 2 | 14 | 40 | 45 | 21 | 1 | Y | N | N | Classroom | | |
| 106 | 550 | 1 | 5 | 16 | 40 | 55 | 35 | 1 | Y | Y | N | Classroom | | |
| 107 | 848 | 1 | 8 | 22 | 40 | 50 | 28 | 1 | Y | N | N | Classroom | | |
| 108 | 819 | 1 | 8 | 24 | 40 | 80 | 49 | 1 | Y | Y | N | Classroom | | |
| 109 | 734 | 1 | 8 | 18 | 40 | 30 | 14 | 1 | Y | Y | N | Classroom | | |
| 200 | 545 | 1 | 6 | 20 | 40 | 120 | 24 | 1 | Y | N | N | Classroom | | |
| 201 | 812 | 1 | 8 | 30 | 40 | 120 | 24 | 1 | Y | N | N | Classroom | | |
| 202 | 545 | 0 | 5 | 16 | 40 | 120 | 24 | 1 | Y | Y | Y | Classroom | | |
| 203 | 812 | 1 | 8 | 30 | 40 | 120 | 24 | 1 | Y | N | N | Classroom | | |
| 204 | 545 | 0 | 5 | 16 | 40 | 120 | 24 | 1 | Y | N | Y | Classroom | | |
| 205 | 812 | 1 | 2 | 20 | 40 | 120 | 24 | 1 | Y | Y | N | Classroom | | |
| 206 | 545 | 0 | 5 | 16 | 40 | 120 | 24 | 1 | Y | N | Y | Classroom | | |
| 207 | 812 | 1 | 10 | 40 | 40 | 120 | 24 | 1 | Y | N | Y | Classroom | | |
| 208 | 545 | 0 | 5 | 16 | 40 | 120 | 24 | 1 | Y | N | Y | Classroom | | |
| 209 | 812 | 1 | 18 | 40 | 40 | 120 | 24 | 1 | Y | N | Y | Classroom | | |
| 210 | 545 | 0 | 5 | 16 | 40 | 120 | 24 | 1 | Y | N | N | Classroom | | |
| 212 | 545 | 0 | 5 | 16 | 40 | 120 | 24 | 1 | Y | N | N | Classroom | | |
| 214 | 545 | 0 | 5 | 16 | 40 | 120 | 24 | 1 | Y | N | N | Classroom | | |
| 216 | 700 | 1 | 6 | 20 | 40 | 180 | 36 | 1 | Y | N | Y | Classroom | | |
| Other | 195 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Room 215 Faculty Lounge |
| Other | 58 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Faculty Lounge 215 |
| Other | 212 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | 2nd floor Women |
| Other | 58 | | | | | | | | N | N | N | Restroom | Staff Restroom | Firs floor, northwest side |
| Other | 212 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | 2nd floor Men |
| Other | 180 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | First floor, Northwest, Lounge room next to room 101 |
| Other | 255 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | First floor, Nurses office |
| Other | 886 | | | | | | | | N | N | N | Library | | 1st Floor |
| Other | 4275 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 133 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, Janitor staff bathroom |
| Other | 0 | | | | | | | | N | N | N | Corridors | | Stage Stairs |
| Other | 94 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | First floor, Engineer office |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|---------------------------------|---|
| Other | 487 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | First floor, staff lunch room |
| Other | 146 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, kitchen bathroom |
| Other | 2207 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 876 | | | | | | | | N | N | N | Kitchen | Cooking Kitchen | 1st Floor |
| Other | 90 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | 1st floor PE Office |
| Other | 310 | | | | | | | | N | N | N | Restroom | Locker/Shower Room | 1st floor Women's Locker Room |
| Other | 2132 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | 1st Floor |
| Other | 30 | | | | | | | | N | N | N | Restroom | Staff Restroom | Firs floor, Nurses bathroom |
| Other | 310 | | | | | | | | N | N | N | Restroom | Locker/Shower Room | 1st floor Men's Locker Room |
| Other | 164 | | | 6 | | | | | N | N | N | Administrative Suites/Offices | | First floor, doctors office |
| Other | 205 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | First floor Men |
| Other | 205 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | First floor Women |
| Other | 3000 | | | | | | | | N | N | N | Gymnasia | Gymnasium.Auditorium | 1st Floor |
| Other | 1239 | | | 28 | | | | | N | N | N | Administrative Suites/Offices | | First floor, counselor office suite |
| Other | 22 | | | | | | | | N | N | N | Restroom | Staff Restroom | In Principal's Office |
| Other | 180 | | | 8 | | | | | N | N | Y | Administrative Suites/Offices | | Principal's Office |
| Other | 30 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, Guidance counselor office bathroom |
| Other | 448 | | | 12 | | | | | N | N | Y | Administrative Suites/Offices | | Main Office 135 |
| Other | 178 | | | 8 | | | | | N | N | N | Administrative Suites/Offices | | First floor, Copy room next to doctors office |
| Other | 132 | | | 6 | | | | | N | N | N | Administrative Suites/Offices | | First floor, dentist office |
| Other | 270 | | | | | | | | N | N | N | Corridors | | Entire Building, Stairs |
| Other | 106 | | | | | | | | N | N | N | Restroom | Staff Restroom | Firs floor, unisex next to library |