

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

- Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- Total Campus Need** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: William B. Ogden School
Category: EXTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Canopy		Concrete/ Stucco Canopy	Main Entrance	7	336	SF	\$0	
Chimney		Metal Flue	Roof	7	3	LF	\$0	
Chimney		Metal Flue	Roof	7	3	LF	\$0	
Chimney		Metal Flue	Roof	7	4	LF	\$0	
Chimney		Metal Flue	Roof	7	4	LF	\$0	
Doors		Exterior Steel Door	throughout	7	7	EA	\$0	
Doors		Overhead Rolling / Garage Door	throughout	7	1	EA	\$0	
Doors		Overhead Rolling / Garage Door	Parking Garage Entrance/Exit	7	2	EA	\$0	
Doors		Side Lite	throughout	7	5	EA	\$0	
Doors		Side Lite	Main Entrance	7	2	EA	\$0	
Doors		Side Lite	Roof	7	1	EA	\$0	
Doors		Store Front Door	Roof	7	7	EA	\$0	
Doors		Store Front Door	throughout	7	13	EA	\$0	
Doors		Store Front Door	Main Entrance	7	4	EA	\$0	

Building: William B. Ogden School
Category: EXTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Doors		Transom Lite	throughout	7	14	EA	\$0	
Doors		Transom Lite	Main Entrance	7	4	EA	\$0	
Doors		Transom Lite	Roof	7	6	EA	\$0	
Entrance		Concrete Exterior Stairs	West Entrances	7	48	LF	\$0	
Entrance		Concrete Exterior Stairs	Main Entrance	7	72	LF	\$0	
Entrance		Concrete Ramp	Main Entrance	7	65	LF	\$0	
Entrance		Concrete Ramp	Loading Dock Ramp	7	35	LF	\$0	
Entrance		Entrance Controls - Audio and Video	Entrance next to parking garage	7	1	EA	\$0	
Entrance		Entrance Controls - Audio and Video	West Entrances	7	1	EA	\$0	
Entrance		Entrance Controls - Audio and Video	Main Entrance	7	1	EA	\$0	
Entrance		Entrance Controls - Audio and Video	Vestibule 1067	7	1	EA	\$0	
Entrance		Entrance Controls - Audio and Video	Loading Dock	7	1	EA	\$0	
Entrance		Entrance Controls - Audio and Video	Parking Garage Entrance	7	1	EA	\$0	
Entrance		Entrance Controls - Audio and Video	East Entrances	7	1	EA	\$0	
Entrance		Entrance Controls - Audio and Video	Northeast Entrance	7	1	EA	\$0	
Entrance		Entrance Controls - Audio and Video	Northwest Entrance	7	1	EA	\$0	
Entrance		Entrance Controls - Audio and Video	East Parking Garage Entrance on Mechanical Room 0020	7	1	EA	\$0	
Entrance		Entrance Controls - Audio and Video	Parking Garage Exit	7	1	EA	\$0	
Entrance		Power Door Operator and Controls	Main Entrance	7	2	EA	\$0	
Entrance		Power Door Operator and Controls	Vestibule 1067	7	2	EA	\$0	
Entrance		Ramp Handrails	Main Entrance	7	130	LF	\$0	
Entrance		Stair Handrails	Main Entrance	7	70	LF	\$0	
Entrance		Stair Handrails	West Entrances	7	20	LF	\$0	
Foundation		Concrete Foundation	Entire Building	7	994	LF	\$0	
Lighting		Exterior Lights - Parapet or Roof Mounted	Roof	7	4	EA	\$0	
Lighting		Exterior Lights - Wall Mounted	South Courtyard	7	24	EA	\$0	
Lighting		Exterior Lights - Wall Mounted	Roof	7	2	EA	\$0	
Lighting		Exterior Lights - Wall Mounted	Entire Building	6	4	EA	\$858	
Lighting		Exterior Lights - Wall Mounted	Entire Building	7	15	EA	\$0	
Lighting		Exterior Lights - Wall Mounted	Main Entrance	7	16	EA	\$0	
Lighting		Exterior Lights - Wall Mounted	North Entrances	7	9	EA	\$0	
Lighting		Exterior Lights - Wall Mounted	South Courtyard	7	4	EA	\$0	
Lintels		Lintels - Steel	Entire Building	7	528	LF	\$0	
Parapet		Coping - Metal	Roofs	7	100	LF	\$0	
Parapet		Coping - Stone	Roofs	7	1,442	LF	\$0	

Building: William B. Ogden School
Category: EXTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Parapet		Parapet > 30" Height	Roofs	7	1,198	LF	\$0	
Parapet		Parapet 16" to 30" Height	Penthouse	7	344	LF	\$0	
Roof System		Asphalt Gravel Ballast Roof	Roofs	7	1,522	SF	\$0	
Roof System		EPDM/ Synthetic Rubber Roof	Lower Roofs	7	2,035	SF	\$0	
Roof System		EPDM/ Synthetic Rubber Roof	Roofs	7	21,299	SF	\$0	
Roof System		EPDM/ Synthetic Rubber Roof	SW roof, above library	5	100	SF	\$858	
Roof System		Interior Downspouts	Roofs	7	1,838	LF	\$0	
Roof System		Roof Structure: Steel/Metal Deck/Concrete Topping	Roofs	7	40,960	SF	\$0	
Superstructure		Steel	Entire Building	7	157,466	SF	\$0	
Walls		Brick	Entire Building	7	54,952	SF	\$0	
Walls		Stone - Cast	Entire Building	7	2,284	SF	\$0	
Windows		Curtain wall - Glazed Double Pane	Main Entrance	7	936	SF	\$0	
Windows		Curtain wall - Glazed Double Pane	throughout	7	4,099	SF	\$0	
Windows		Curtain wall - Glazed Double Pane	southwest elevation	7	746	SF	\$0	
Windows		Window - Guards wire guard	gymnasium interior at south wall	7	240	SF	\$0	
Windows		Windows - Casement Aluminum Double-pane	throughout	7	856	SF	\$0	
Windows		Windows - Sash Aluminum Double-pane	throughout	7	5,168	SF	\$0	
EXTERIOR Sub Total							\$1,716	

Building: William B. Ogden School
Category: ELECTRICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Emergency System		Automatic Transfer switch	Mechanical Room	7	4	EA	\$0	
Emergency System		Emergency A/C power - Corridors and Stairs	Entire Building	7	21,070	SF	\$0	
Emergency System		Emergency A/C power - Gym and Lunch rooms	Entire Building	7	7,762	SF	\$0	
Emergency System		Emergency A/C power - Students Toilets	Entire Building	7	3,716	SF	\$0	
Emergency System		Emergency generator 100 to 150 KW natural gas - Outdoor	Entire Building	7	1	EA	\$0	
Emergency System		Exit Signs - Corridors and Stairs	Entire Building	7	28	EA	\$0	
Emergency System		Exit Signs - Lunchroom - Gym - multipurpose rooms	Entire Building	7	8	EA	\$0	
Emergency System		Independent Electrical Service for emergency power	Mechanical Room	7	1	EA	\$0	
Emergency System		Public Announcement System	Entire Building	7	157,466	SF	\$0	
Emergency System		Security System - Intrusion detection	Entire Building	7	157,466	SF	\$0	
Emergency System		System 1 emergency service configuration	Entire Building	7	157,466	SF	\$0	
Main Service		Main Electrical service 2000 to 3000 A 277/480/3PH	Mechanical Room	7	1	EA	\$0	

Building: William B. Ogden School
Category: ELECTRICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Power Distribution		Lighting and power panels	Mechanical Room	7	33	EA	\$0	
Power Distribution		Main distribution panels 400-600 amp	Mechanical Room	7	2	EA	\$0	
Power Distribution		Main distribution panels 400-600 amp	Mechanical Room	7	5	EA	\$0	
Power Distribution		Transformers 277/480-120/208	Mechanical Room	7	6	EA	\$0	
ELECTRICAL Sub Total							\$0	

Building: William B. Ogden School
Category: FIRE PROTECTION

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Fire Alarm		Fire Alarm Strobe Lights	Entire Building	7	157,466	SF	\$0	
Fire Alarm		Fire Alarm System	Mechanical Room	7	157,466	SF	\$0	
Fire Alarm		Fire Pump Controller	Mechanical Room	7	1	EA	\$0	
Pump Room Assembly		Fire Pump 50-75hp	Mechanical Room	7	1	EA	\$0	
Sprinkler System		Combination Wet and Dry Sprinkler System	Entire Building	7	157,766	SF	\$0	
FIRE PROTECTION Sub Total							\$0	

Building: William B. Ogden School
Category: MECHANICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Air Conditioning		Chillers - Air Cooled - Scroll type - Roof Mounted 101 to 150 tons	Chiller Well - 2nd Fl Roof	7	1	EA	\$0	
Air Conditioning		Condensing Unit - Roof Mounted less than 5 tons	Lower Parking Garage	7	1	EA	\$0	
Air Conditioning		Condensing Unit - Roof Mounted less than 5 tons	Main Roof	7	1	EA	\$0	
Air Handling Systems		Air Handling Unit Package - Multi Zone - Hot Water 15,001 - 20,000 cfm	2nd Fl Mech Rm	7	2	EA	\$0	
Air Handling Systems		Air Handling Unit Package - Single Zone - Hot Water 12,001 to 20,000 cfm	3rd Fl Mech Rm	7	3	EA	\$0	
Air Handling Systems		Return Fans - Indoor 10,001 to 20,000 CFM	TBD	7	3	EA	\$0	
Air Handling Systems		Return Fans - Indoor greater than 20,000 CFM	Mechanical Room	7	2	EA	\$0	
Air Handling Systems		Variable Air Volume (VAV) Box With Hot Water Coil	Entire Building	7	74	EA	\$0	
Boiler Systems		Boiler Assembly - Condensing Hot Water Boiler 1,001MBH-2,000 MBH	Boiler Room	7	2	EA	\$0	
Boiler Systems		Boiler Auxiliary - Condensing Hot Water Boiler 1,001MBH-2,000 MBH	Boiler Room	7	2	EA	\$0	
Boiler Systems		Chemical Pot Feeder - Hot Water	3rd Fl. Mech Rm	7	2	EA	\$0	
Boiler Systems		Glycol Feed System	Mechanical Room	7	1	EA	\$0	
Boiler Systems		Glycol Feed System	3rd Fl Mech Rm	7	2	EA	\$0	
Heat Exchangers		Heat Exchanger - Steam to Hot Water Shell Type	Mechanical Room	7	2	EA	\$0	

Building: William B. Ogden School
Category: MECHANICAL

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Heat Exchangers		Heat Exchanger - Water to Water Plate Type	Mechanical Room	7	1	EA	\$0	
Heating Devices		Cabinet Heaters With Hot Water Coils	Entire Building	7	46	EA	\$0	
Heating Devices		Radiators - Hot Water	Entire Building	7	6	EA	\$0	
Heating Devices		Unit Heater - Electric	Entire Building	7	13	EA	\$0	
Mechanical Plumbing		Piping - Hydronic Supply and Return - Steel or Galvanized	Entire Building	7	1,500	LF	\$0	
Mechanical Plumbing		Pumps - Chilled Water 10 to 20 HP	3rd Fl Mech Rm	7	2	EA	\$0	
Mechanical Plumbing		Pumps - Hot Water 11 to 20 HP	Mech Rm	7	7	EA	\$0	
Temperature Control		Direct Digital Control (DDC) System	Entire Building	7	157,466	SF	\$0	
Temperature Control		Thermostats - Direct Digital Control (DDC)	Entire Building	7	126	EA	\$0	
Ventilation		Exhaust Fan - Indoor	Kiln - Art Room	7	1	EA	\$0	
Ventilation		Exhaust Fan - Indoor	Loading Dock	7	1	EA	\$0	
Ventilation		Exhaust Fan - Indoor	MDF Room	7	1	EA	\$0	
Ventilation		Exhaust Fan - Indoor	Mechanical Room	7	3	EA	\$0	
Ventilation		Exhaust Fan - Indoor	Toilets	7	2	EA	\$0	
Ventilation		Exhaust Fan - Indoor	Kitchen	7	1	EA	\$0	
Ventilation		Exhaust Fan - Indoor	Garage	7	2	EA	\$0	
Ventilation		Exhaust Fan - Indoor	Gym	7	1	EA	\$0	
Ventilation		Type II Exhaust Hood - Warming Kitchen	Kitchen	7	1	EA	\$0	
MECHANICAL Sub Total							\$0	

Building: William B. Ogden School
Category: PLUMBING

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Hot Water		Hot Water Heater - Gas 150,000 -300,000 BTU/HR	Mechanical Room	7	2	EA	\$0	
Piping		Domestic Piping - Cold Water from Risers to Fixtures	Entire Building	7	157,466	SF	\$0	
Piping		Domestic Piping - Cold Water Risers	Entire Building	7	157,466	SF	\$0	
Piping		Domestic Piping - Hot Water from Riser to fixtures	Entire Building	7	157,466	SF	\$0	
Piping		Domestic Piping - Hot Water Return Risers	Entire Building	7	157,466	SF	\$0	
Piping		Domestic Piping - Hot Water Risers	Entire Building	7	157,466	SF	\$0	
Piping		Domestic Piping Cold Water Horizontal lines	Entire Building	7	157,466	SF	\$0	
Piping		Domestic Piping Hot Water Horizontal lines	Entire Building	7	157,466	SF	\$0	
Piping		Domestic Piping Hot Water Return Lines	Entire Building	7	157,466	SF	\$0	
Piping		Sanitary Piping	Entire Building	7	157,466	SF	\$0	
Piping		Storm Piping	Entire Building	7	157,466	SF	\$0	
Piping		Vent Piping	Entire Building	7	157,466	SF	\$0	
Pumps		Domestic Booster Pump duplex	Mechanical Room	7	1	EA	\$0	

Building: William B. Ogden School
Category: PLUMBING

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Pumps		Ejector Pump	Mechanical Room	7	4	EA	\$0	
Pumps		Sump Pump	Mechanical Room	7	2	EA	\$0	
PLUMBING Sub Total							\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 320 Faculty Lounge	7	749	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Teacher's Lounge/Kitchen	7	152	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Office Room 106	7	172	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 108 Speech Pathology Office	7	172	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 114A-1 in Kitchen	7	147	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 319A (AV Storage 3021)	7	122	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 300A Work Room in Library	7	187	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 104B Social Workers Office	7	100	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Operations Manager's Ofc Room 100B	7	281	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 224B Gym Office	7	99	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Main Office	7	728	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 104D Counselor's Office	7	178	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 104E PYP Curriculum Co-Ord	7	182	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 100A Conference Room	7	278	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Janitor's Break Room	7	192	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Principal's Office Room 100C	7	280	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 100E Office	7	164	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Conference Room 104F	7	183	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Ceiling - Lay-In	Room 104 Waiting Area	7	273	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	Operations Manager's Ofc Room 100B	7	281	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	Room 300A Work Room in Library	7	187	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	Room 108 Speech Pathology Office	7	172	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	Main Office	7	728	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	Room 100A Conference Room	7	278	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	Conference Room 104F	7	183	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	Office Room 106	7	172	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	Principal's Office Room 100C	7	280	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Carpet	Room 104E PYP Curriculum Co-Ord	7	182	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Room 320 Faculty Lounge	7	749	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Janitor's Break Room	7	192	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Room 100E Office	7	164	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Room 104D Counselor's Office	7	178	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Room 104B Social Workers Office	7	100	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Teacher's Lounge/Kitchen	7	152	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Room 104 Waiting Area	7	273	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Room 114A-1 in Kitchen	7	147	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Room 319A (AV Storage 3021)	7	122	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Flooring - Tile/Sheet	Room 224B Gym Office	7	99	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Room 104E PYP Curriculum Co-Ord	7	3	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Teacher's Lounge/Kitchen	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Principal's Office Room 100C	7	6	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Room 100E Office	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Room 104D Counselor's Office	7	4	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Conference Room 104F	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Room 104B Social Workers Office	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Operations Manager's Ofc Room 100B	7	6	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Room 108 Speech Pathology Office	7	4	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Room 114A-1 in Kitchen	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Room 224B Gym Office	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Janitor's Break Room	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Room 300A Work Room in Library	7	6	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Room 100A Conference Room	7	6	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Room 320 Faculty Lounge	7	10	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Lay-In	Office Room 106	7	4	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Main Office	7	12	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Room 319A (AV Storage 3021)	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Lighting - Pendant/Surface	Room 104 Waiting Area	7	2	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Office Room 106	7	250	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Conference Room 104F	7	245	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Operations Manager's Ofc Room 100B	7	400	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 104B Social Workers Office	7	100	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 104D Counselor's Office	7	300	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Teacher's Lounge/Kitchen	7	150	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 104 Waiting Area	7	300	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 108 Speech Pathology Office	7	200	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 114A-1 in Kitchen	7	150	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 319A (AV Storage 3021)	7	410	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 224B Gym Office	7	150	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 320 Faculty Lounge	7	628	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Janitor's Break Room	7	300	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 100E Office	7	175	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Main Office	7	945	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 300A Work Room in Library	7	325	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Principal's Office Room 100C	7	400	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 104E PYP Curriculum Co-Ord	7	300	SF	\$0	
Administrative Suites	Administrative Suites/Offices	Walls - Concrete Block	Room 100A Conference Room	7	400	SF	\$0	
Corridor		Ceiling - Exposed	Entire Building	7	1,422	SF	\$0	
Corridor		Ceiling - Lay-In	Entire Building	7	17,323	SF	\$0	
Corridor		Ceiling - Plaster/Drywall	Entire Building	7	3,369	SF	\$0	
Corridor		Flooring Terrazzo	Entire Building	7	20,712	SF	\$0	
Corridor		Flooring Tile/ Sheet	Back corridor	7	358	SF	\$0	
Corridor		Stair Handrails	Entire Building	7	573	LF	\$0	
Corridor		Stair Handrails	Loading Dock	7	12	LF	\$0	
Corridor		Stairs - Asphalt	Loading Dock	7	6	LF	\$0	
Corridor		Stairs - Terrazzo	Entire Building	7	246	LF	\$0	
Corridor		Student Lockers	Entire Building	7	724	EA	\$0	
Corridor		Walls - Concrete Block	Back corridor	7	895	SF	\$0	
Corridor		Walls - Masonry	Entire Building	7	2,829	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Corridor		Walls - Plaster/Drywall	Entire Building	7	6,524	SF	\$0	
Corridor		Walls - Structural Glazed Tile	Entire Building	7	22,901	SF	\$0	
Doors		Interior Steel Doors incl hw	throughout	7	124	EA	\$0	
Doors		Interior Wood Doors incl hw	throughout	7	81	EA	\$0	
Doors		Side-lite	Main Entrance	7	2	SF	\$0	
Doors		Side-lite	Vestibule 1067	7	1	SF	\$0	
Doors		Side-lite	throughout	7	59	SF	\$0	
Doors		Store Front Door	Vestibule 1067	7	2	EA	\$0	
Doors		Store Front Door	Main Entrance	7	4	EA	\$0	
Doors		Transom Window	Main Entrance	7	4	SF	\$0	
Drinking Fountains		Single Fountain	Entire Building	7	18	EA	\$0	
Drinking Fountains		Single Fountain	1st Floor	7	1	EA	\$0	
Drinking Fountains		Single Fountain	Rooms 107, 109, 111, 113 & 115	7	5	EA	\$0	
Fine Art Room		Work Sink	Science Room 219	7	2	EA	\$0	
Fine Art Room		Work Sink	Room 104C	7	1	EA	\$0	
Fine Art Room		Work Sink	1st Floor	7	1	EA	\$0	
Fine Art Room		Work Sink	Music Room 319	7	1	EA	\$0	
Fine Art Room		Work Sink	Art Rooms 103 & 105 (1025 & 1026)	7	1	EA	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Bleacher Seating	2nd Floor	7	107	EA	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Ceiling - Exposed	2nd Floor	7	4,264	SF	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Flooring - Wood	2nd Floor	7	4,264	SF	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Lighting - Pendant/Surface	2nd Floor	6	42	EA	\$5,105	
Gymnasium / Auditorium	Gymnasium.Auditorium	Scoreboards	2nd Floor	7	1	EA	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Sound System	2nd Floor	7	1	EA	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Stage Curtain	2nd Floor	7	10	EA	\$0	
Gymnasium / Auditorium	Gymnasium.Auditorium	Walls - Concrete Block	2nd Floor	7	3,735	SF	\$0	
Kitchen	Warming Kitchen	Ceiling - Lay-In	1st Floor	7	1,449	SF	\$0	
Kitchen	Warming Kitchen	Flooring - Tile Quarry	1st Floor	7	1,449	SF	\$0	
Kitchen	Warming Kitchen	Lighting - Lay-In	1st Floor	7	14	SF	\$0	
Kitchen	Warming Kitchen	Wall - Concrete Block	1st Floor	7	1,620	SF	\$0	
Library		Casework	3rd Floor	7	54	LF	\$0	
Library		Flooring Carpet	3rd Floor	7	3,698	SF	\$0	
Library		Lighting - Lay-In	3rd Floor	7	20	SF	\$0	Recessed Can Lights
Library		Lighting - Pendant/ Surface	3rd Floor	7	200	SF	\$0	
Locker/Shower Room	Staff Restroom	Showers	In the Main Office area	7	1	EA	\$0	
Lunchroom	Multipurpose Room	Ceiling - Lay-In	1st Floor	7	3,498	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Lunchroom	Multipurpose Room	Flooring - Tile/Sheet	1st Floor	7	3,498	SF	\$0	
Lunchroom	Multipurpose Room	Lighting - Lay-In	1st Floor	7	82	SF	\$0	
Lunchroom	Multipurpose Room	Lighting - Pendant/Surface	1st Floor	7	15	SF	\$0	
Lunchroom	Multipurpose Room	Serving Line	1st Floor	7	30	LF	\$0	
Lunchroom	Multipurpose Room	Wall - Concrete Block	1st Floor	7	3,000	SF	\$0	
MDF/IDF		Finishes	1st Floor	7	263	SF	\$0	
MDF/IDF		Ventilation and Cooling	1st Floor	7	1	EA	\$0	
Mechanical/Service Rooms		Boiler Room	3rd Floor	7	1,754	SF	\$0	
Mechanical/Service Rooms		Janitor's Closet	3rd Floor	7	2	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Room 224A-2 Dimmer	7	107	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Basement	7	663	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Basement	7	637	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Basement	7	277	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Basement	7	1,385	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	3rd Floor	7	164	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	3rd Floor	7	325	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Basement	7	541	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	2nd Floor	7	95	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	2nd Floor	7	1,827	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	2nd Floor	7	139	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Basement	7	208	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	Basement	7	414	SF	\$0	
Mechanical/Service Rooms		Mechanical/Service Rooms	3rd Floor	7	232	SF	\$0	
Mechanical/Service Rooms		Storage Room	Room 219A (Art Storage 2022)	7	194	SF	\$0	
Mechanical/Service Rooms		Storage Room	1st Floor	7	69	SF	\$0	
Mechanical/Service Rooms		Storage Room	Basement	7	231	SF	\$0	
Mechanical/Service Rooms		Storage Room	2nd Floor	7	401	SF	\$0	
Mechanical/Service Rooms		Storage Room	Basement	7	406	SF	\$0	
Mechanical/Service Rooms		Storage Room	3rd Floor	7	337	SF	\$0	
Mechanical/Service Rooms		Storage Room	Basement	7	587	SF	\$0	
Mechanical/Service Rooms		Storage Room	Room 319B (Music Rm. Storage 3019)	7	138	SF	\$0	
Mechanical/Service Rooms		Storage Room	Room 219A (Kiln Room 2024)	7	66	SF	\$0	
Mechanical/Service Rooms		Storage Room	2nd Floor	7	337	SF	\$0	
Mechanical/Service Rooms		Storage Room	3rd Floor	7	59	SF	\$0	
Mechanical/Service Rooms		Storage Room	Basement	7	445	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Mechanical/Service Rooms		Storage Room	Rooms 107, 109, 111, 113 & 115 (1029, 1032, 1035, 1038 & 1041)	7	340	SF	\$0	
Mechanical/Service Rooms		Storage Room	Rooms 103 & 105 (1025A & 1026A)	7	25	SF	\$0	
Mechanical/Service Rooms		Storage Room	Room 100D	7	69	SF	\$0	
Mechanical/Service Rooms		Storage Room	Pre-K Room 110	7	66	SF	\$0	
Mechanical/Service Rooms		Storage Room	1st Floor	7	135	SF	\$0	
Mechanical/Service Rooms		Storage Room	Room 224A-1 Gym Storage Room	7	107	SF	\$0	
Music Room		Sound Panels	Room 319	7	256	SF	\$0	
Music Room		Sound System	Room 319	7	1	EA	\$0	
Pre-Kindergarten		Work Sink	Rooms 107, 109, 110, 111, 113 & 115	7	6	EA	\$0	
Staff Restroom	Staff Restroom	Accessories	Room 301BD NW Corner	7	51	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	Women's Room 1st Floor next to Kitchen	7	70	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	2nd Floor NW Corner	7	51	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	2nd Flr Girl's Room SE corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	2nd Flr Girl's Room 201C NW corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	1st Flr SE Boy's Room	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	1st Flr NW Boy's Room	7	293	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	In the Main Office area	7	82	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	2nd Flr SE Boy's Room 218C	7	293	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	Men's Room 1st Floor next to Kitchen	7	70	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	Room 316D SE Corner	7	51	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	3rd Flr Girl's Room 316A SE corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	3rd Flr Girl's Room 301C NW corner	7	301	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Accessories	Pre-School 107, 109, 110, 111, 113 & 115 (1028, 1031, 1034, 1037 & 1040)	7	79	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	3rd Flr NW Boy's Room 301A	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	3rd Flr SE Boy's Room 316C	7	293	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Staff Restroom	Accessories	Room 100G	7	61	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Accessories	Room 110	7	73	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	2nd Flr NW Boy's Room 201A	7	293	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	1st Floor NW Corner	7	51	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	1st Flr Girl's Room SE corner	7	301	SF	\$0	
Staff Restroom	Staff Restroom	Accessories	1st Floor NW Corner	7	51	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Accessories	1st Flr Girl's Room NW corner	7	301	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Lay-In	Room 100G	7	61	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Lay-In	2nd Floor NW Corner	7	51	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Lay-In	1st Floor NW Corner	7	51	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Ceiling - Lay-In	Room 110	7	73	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Ceiling - Lay-In	Pre-School 107, 109, 110, 111, 113 & 115 (1028, 1031, 1034, 1037 & 1040)	7	95	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Lay-In	Room 316D SE Corner	7	51	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Lay-In	Women's Room 1st Floor next to Kitchen	7	70	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Lay-In	Men's Room 1st Floor next to Kitchen	7	70	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Lay-In	In the Main Office area	7	82	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Lay-In	Room 301BD NW Corner	7	51	SF	\$0	
Staff Restroom	Staff Restroom	Ceiling - Lay-In	1st Floor NW Corner	7	51	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	2nd Flr SE Boy's Room 218C	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	1st Flr Girl's Room SE corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	1st Flr Girl's Room NW corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	2nd Flr Girl's Room SE corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	2nd Flr Girl's Room 201C NW corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	1st Flr SE Boy's Room	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	1st Flr NW Boy's Room	7	293	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	2nd Flr NW Boy's Room 201A	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	3rd Flr Girl's Room 316A SE corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	3rd Flr Girl's Room 301C NW corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	3rd Flr NW Boy's Room 301A	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Ceiling - Plaster/Drywall	3rd Flr SE Boy's Room 316C	7	293	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Floor Drain	Pre-School 107, 109, 110, 111, 113 & 115 (1028, 1031, 1034, 1037 & 1040)	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	2nd Flr SE Boy's Room 218C	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	1st Flr Girl's Room NW corner	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	In the Main Office area	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	Women's Room 1st Floor next to Kitchen	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	Men's Room 1st Floor next to Kitchen	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	2nd Flr Girl's Room SE corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	1st Flr Girl's Room SE corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	2nd Flr Girl's Room 201C NW corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	1st Flr SE Boy's Room	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	3rd Flr SE Boy's Room 316C	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	2nd Flr NW Boy's Room 201A	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	1st Floor NW Corner	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	Room 301BD NW Corner	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	Room 316D SE Corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	3rd Flr Girl's Room 316A SE corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	3rd Flr Girl's Room 301C NW corner	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	2nd Floor NW Corner	7	1	EA	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Floor Drain	3rd Flr NW Boy's Room 301A	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	Room 100G	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Floor Drain	Room 110	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Floor Drain	1st Flr NW Boy's Room	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Floor Drain	1st Floor NW Corner	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile Ceramic/Porcelain	In the Main Office area	7	82	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Flooring - Tile Ceramic/Porcelain	Room 110	7	73	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	2nd Flr Girl's Room 201C NW corner	7	301	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile Ceramic/Porcelain	Women's Room 1st Floor next to Kitchen	7	70	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile Ceramic/Porcelain	Men's Room 1st Floor next to Kitchen	7	70	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	2nd Flr Girl's Room SE corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	1st Flr Girl's Room SE corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	1st Flr SE Boy's Room	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	2nd Flr NW Boy's Room 201A	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	2nd Flr SE Boy's Room 218C	7	293	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Flooring - Tile Ceramic/Porcelain	Pre-School 107, 109, 110, 111, 113 & 115 (1028, 1031, 1034, 1037 & 1040)	7	95	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	3rd Flr Girl's Room 316A SE corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	3rd Flr SE Boy's Room 316C	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	3rd Flr Girl's Room 301C NW corner	7	301	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	3rd Flr NW Boy's Room 301A	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	1st Flr NW Boy's Room	7	293	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Flooring - Tile Ceramic/Porcelain	1st Flr Girl's Room NW corner	7	301	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile/Sheet	1st Floor NW Corner	7	51	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Staff Restroom	Flooring - Tile/Sheet	1st Floor NW Corner	7	51	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile/Sheet	Room 301BD NW Corner	7	51	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile/Sheet	Room 100G	7	61	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile/Sheet	2nd Floor NW Corner	7	51	SF	\$0	
Staff Restroom	Staff Restroom	Flooring - Tile/Sheet	Room 316D SE Corner	7	51	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Hand Dryer	Room 110	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Hand Dryer	Room 100G	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	3rd Flr SE Boy's Room 316C	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	3rd Flr Girl's Room 301C NW corner	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	3rd Flr NW Boy's Room 301A	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Hand Dryer	Men's Room 1st Floor next to Kitchen	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	3rd Flr Girl's Room 316A SE corner	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	2nd Flr SE Boy's Room 218C	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	2nd Flr NW Boy's Room 201A	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	1st Flr NW Boy's Room	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	1st Flr SE Boy's Room	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	2nd Flr Girl's Room 201C NW corner	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	2nd Flr Girl's Room SE corner	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Hand Dryer	Women's Room 1st Floor next to Kitchen	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Hand Dryer	In the Main Office area	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	1st Flr Girl's Room NW corner	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Hand Dryer	1st Flr Girl's Room SE corner	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	2nd Flr SE Boy's Room 218C	7	1	EA	\$0	4 compartment sink
Staff Restroom	Children's Standard Student Restroom	Lavatory	2nd Flr NW Boy's Room 201A	7	1	EA	\$0	4 compartment sink
Staff Restroom	Children's Standard Student Restroom	Lavatory	1st Flr Girl's Room NW corner	7	1	EA	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Staff Restroom	Lavatory	In the Main Office area	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	Women's Room 1st Floor next to Kitchen	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	Men's Room 1st Floor next to Kitchen	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	2nd Flr Girl's Room SE corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	1st Flr Girl's Room SE corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	2nd Flr Girl's Room 201C NW corner	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	Room 316D SE Corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	1st Flr NW Boy's Room	7	1	EA	\$0	4 compartment sink
Staff Restroom	Staff Restroom	Lavatory	Room 100G	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Lavatory	Room 110	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	Room 301BD NW Corner	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Lavatory	1st Floor NW Corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	3rd Flr NW Boy's Room 301A	7	1	EA	\$0	4 compartment sink
Staff Restroom	Children's Standard Student Restroom	Lavatory	3rd Flr Girl's Room 316A SE corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	3rd Flr Girl's Room 301C NW corner	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Lavatory	Pre-School 107, 109, 110, 111, 113 & 115 (1028, 1031, 1034, 1037 & 1040)	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	1st Flr SE Boy's Room	7	1	EA	\$0	4 compartment sink
Staff Restroom	Staff Restroom	Lavatory	2nd Floor NW Corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Lavatory	3rd Flr SE Boy's Room 316C	7	1	EA	\$0	4 compartment sink
Staff Restroom	Staff Restroom	Lavatory	1st Floor NW Corner	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	Room 301BD NW Corner	7	1	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	Men's Room 1st Floor next to Kitchen	7	1	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	Room 316D SE Corner	7	1	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	Room 100G	7	1	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Lighting - Lay-In	Room 110	7	1	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	1st Floor NW Corner	7	1	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Staff Restroom	Lighting - Lay-In	1st Floor NW Corner	7	1	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	2nd Floor NW Corner	7	1	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	In the Main Office area	7	2	SF	\$0	
Staff Restroom	Staff Restroom	Lighting - Lay-In	Women's Room 1st Floor next to Kitchen	7	1	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	1st Flr SE Boy's Room	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	2nd Flr Girl's Room SE corner	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	2nd Flr Girl's Room 201C NW corner	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	1st Flr Girl's Room NW corner	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	1st Flr NW Boy's Room	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	2nd Flr NW Boy's Room 201A	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	2nd Flr SE Boy's Room 218C	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	3rd Flr Girl's Room 316A SE corner	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	3rd Flr Girl's Room 301C NW corner	7	9	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Lighting - Pendant/ Surface	Pre-School 107, 109, 110, 111, 113 & 115 (1028, 1031, 1034, 1037 & 1040)	7	1	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	3rd Flr NW Boy's Room 301A	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	3rd Flr SE Boy's Room 316C	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Lighting - Pendant/ Surface	1st Flr Girl's Room SE corner	7	9	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	1st Flr SE Boy's Room	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	1st Flr Girl's Room NW corner	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	2nd Flr Girl's Room 201C NW corner	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	2nd Flr Girl's Room SE corner	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	1st Flr Girl's Room SE corner	7	3	EA	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Children's Standard Student Restroom	Partitions	1st Flr NW Boy's Room	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	2nd Flr NW Boy's Room 201A	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	2nd Flr SE Boy's Room 218C	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	3rd Flr Girl's Room 316A SE corner	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	3rd Flr Girl's Room 301C NW corner	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	3rd Flr SE Boy's Room 316C	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Partitions	3rd Flr NW Boy's Room 301A	7	3	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Urinals	2nd Flr NW Boy's Room 201A	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Urinals	3rd Flr SE Boy's Room 316C	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Urinals	3rd Flr NW Boy's Room 301A	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Urinals	1st Flr NW Boy's Room	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Urinals	1st Flr SE Boy's Room	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Urinals	2nd Flr SE Boy's Room 218C	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	Room 100G	7	80	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	2nd Floor NW Corner	7	168	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	1st Floor NW Corner	7	168	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Wall - Concrete Block	Pre-School 107, 109, 110, 111, 113 & 115 (1028, 1031, 1034, 1037 & 1040)	7	320	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	Room 316D SE Corner	7	168	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	Room 301BD NW Corner	7	168	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Concrete Block	1st Floor NW Corner	7	168	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	3rd Flr SE Boy's Room 316C	7	300	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	1st Flr SE Boy's Room	7	300	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Structural Glazed Tile	Women's Room 1st Floor next to Kitchen	7	90	SF	\$0	
Staff Restroom	Staff Restroom	Wall - Structural Glazed Tile	In the Main Office area	7	100	SF	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Staff Restroom	Wall - Structural Glazed Tile	Men's Room 1st Floor next to Kitchen	7	90	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	2nd Flr Girl's Room 201C NW corner	7	350	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	2nd Flr Girl's Room SE corner	7	350	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	1st Flr Girl's Room SE corner	7	350	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	1st Flr NW Boy's Room	7	300	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	2nd Flr NW Boy's Room 201A	7	300	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	2nd Flr SE Boy's Room 218C	7	300	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	3rd Flr Girl's Room 316A SE corner	7	350	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	3rd Flr NW Boy's Room 301A	7	300	SF	\$0	
Staff Restroom	Early Childhood Student Restroom	Wall - Structural Glazed Tile	Room 110	7	100	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	1st Flr Girl's Room NW corner	7	350	SF	\$0	
Staff Restroom	Children's Standard Student Restroom	Wall - Structural Glazed Tile	3rd Flr Girl's Room 301C NW corner	7	350	SF	\$0	
Staff Restroom	Staff Restroom	Water Closet	In the Main Office area	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	2nd Flr SE Boy's Room 218C	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	1st Flr Girl's Room NW corner	7	4	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	2nd Flr Girl's Room 201C NW corner	7	4	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	Women's Room 1st Floor next to Kitchen	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	2nd Flr Girl's Room SE corner	7	4	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	1st Flr Girl's Room SE corner	7	4	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	1st Flr SE Boy's Room	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	Men's Room 1st Floor next to Kitchen	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	2nd Flr NW Boy's Room 201A	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	2nd Floor NW Corner	7	1	EA	\$0	

Building: William B. Ogden School
Category: INTERIOR

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Staff Restroom	Staff Restroom	Water Closet	Room 316D SE Corner	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	Room 301BD NW Corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	3rd Flr Girl's Room 316A SE corner	7	4	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	3rd Flr Girl's Room 301C NW corner	7	4	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Water Closet	Pre-School 107, 109, 110, 111, 113 & 115 (1028, 1031, 1034, 1037 & 1040)	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	3rd Flr NW Boy's Room 301A	7	2	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	3rd Flr SE Boy's Room 316C	7	2	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	Room 100G	7	1	EA	\$0	
Staff Restroom	Early Childhood Student Restroom	Water Closet	Room 110	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	1st Floor NW Corner	7	1	EA	\$0	
Staff Restroom	Staff Restroom	Water Closet	1st Floor NW Corner	7	1	EA	\$0	
Staff Restroom	Children's Standard Student Restroom	Water Closet	1st Flr NW Boy's Room	7	2	EA	\$0	
Theater		Stage Platform	2nd Floor	7	1,078	SF	\$0	
Vertical Conveyance		Elevator - Traction	southwest corridors	7	1	EA	\$0	
Vertical Conveyance		Elevator - Traction	1st Floor	7	1	EA	\$0	

INTERIOR Sub Total \$5,105

Building: William B. Ogden School
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Casework	Classroom	Casework		7	30	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	

Building: William B. Ogden School
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Casework	Classroom	Casework		7	27	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	21	LF	\$0	
Casework	Classroom	Casework		7	12	LF	\$0	
Casework	Classroom	Casework		7	45	LF	\$0	
Casework	Classroom	Casework		7	30	LF	\$0	
Casework	Classroom	Casework		7	30	LF	\$0	
Casework	Classroom	Casework		7	29	LF	\$0	
Casework	Classroom	Casework		7	30	LF	\$0	
Casework	Classroom	Casework		7	35	LF	\$0	
Casework	Classroom	Casework		7	30	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	35	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Casework	Classroom	Casework		7	49	LF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,037	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	790	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	979	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,140	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,140	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,140	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,140	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,140	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,140	SF	\$0	

Building: William B. Ogden School
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	790	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,200	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	890	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,200	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	890	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,339	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	241	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	1,683	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	890	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	897	SF	\$0	
Ceiling	Classroom	Lay-In/Drop		7	890	SF	\$0	
Chalk Board	Classroom	Chalk Board		4		LF		
Chalk Board	Classroom	Chalk Board		4		LF		
Chalk Board	Classroom	Chalk Board		4		LF		
Chalk Board	Classroom	Chalk Board		4		LF		
Chalk Board	Classroom	Chalk Board		4		LF		
Chalk Board	Classroom	Chalk Board		4		LF		
Chalk Board	Classroom	Chalk Board		4		LF		
Floor	Classroom	Carpet		7	241	SF	\$0	
Floor	Classroom	Tile/Sheet		7	1,140	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	1,140	SF	\$0	
Floor	Classroom	Tile/Sheet		7	1,037	SF	\$0	

Building: William B. Ogden School
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Floor	Classroom	Tile/Sheet		7	1,140	SF	\$0	
Floor	Classroom	Tile/Sheet		7	1,140	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	1,200	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	1,200	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	790	SF	\$0	
Floor	Classroom	Tile/Sheet		7	1,140	SF	\$0	
Floor	Classroom	Tile/Sheet		7	790	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	1,339	SF	\$0	
Floor	Classroom	Tile/Sheet		7	1,683	SF	\$0	
Floor	Classroom	Tile/Sheet		7	890	SF	\$0	
Floor	Classroom	Tile/Sheet		7	890	SF	\$0	
Floor	Classroom	Tile/Sheet		7	890	SF	\$0	
Floor	Classroom	Tile/Sheet		7	890	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	897	SF	\$0	
Floor	Classroom	Tile/Sheet		7	979	SF	\$0	
Lighting	Classroom	Lay-In		7	14	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	7	EA	\$0	
Lighting	Classroom	Lay-In		7	3	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	6	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	

Building: William B. Ogden School
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	6	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	Recessed Lights
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Lay-In		7	8	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	10	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	15	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	20	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	10	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	10	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	24	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	15	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	15	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	15	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	10	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	24	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	10	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	10	EA	\$0	
Lighting	Classroom	Pendant/Surface		7	10	EA	\$0	

Building: William B. Ogden School
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Marker Board	Classroom	Marker Board		7	18	LF	\$0	
Marker Board	Classroom	Marker Board		7	18	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	6	LF	\$0	
Marker Board	Classroom	Marker Board		7	16	LF	\$0	
Marker Board	Classroom	Marker Board		7	4	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	8	LF	\$0	
Marker Board	Classroom	Marker Board		7	18	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	24	LF	\$0	
Marker Board	Classroom	Marker Board		7	6	LF	\$0	
Marker Board	Classroom	Marker Board		7	12	LF	\$0	
Marker Board	Classroom	Marker Board		7	24	LF	\$0	
Marker Board	Classroom	Marker Board		7	18	LF	\$0	
Wall	Classroom	Concrete Block		7	243	SF	\$0	
Wall	Classroom	Concrete Block		7	909	SF	\$0	
Wall	Classroom	Concrete Block		7	243	SF	\$0	
Wall	Classroom	Concrete Block		7	1,070	SF	\$0	
Wall	Classroom	Concrete Block		7	1,070	SF	\$0	
Wall	Classroom	Concrete Block		7	1,070	SF	\$0	
Wall	Classroom	Concrete Block		7	243	SF	\$0	
Wall	Classroom	Concrete Block		7	243	SF	\$0	
Wall	Classroom	Concrete Block		7	243	SF	\$0	
Wall	Classroom	Concrete Block		7	243	SF	\$0	
Wall	Classroom	Concrete Block		7	1,070	SF	\$0	
Wall	Classroom	Concrete Block		7	243	SF	\$0	
Wall	Classroom	Concrete Block		7	550	SF	\$0	
Wall	Classroom	Concrete Block		7	243	SF	\$0	
Wall	Classroom	Concrete Block		7	450	SF	\$0	
Wall	Classroom	Concrete Block		7	757	SF	\$0	
Wall	Classroom	Concrete Block		7	243	SF	\$0	

Building: William B. Ogden School
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Wall	Classroom	Concrete Block		7	243	SF	\$0	
Wall	Classroom	Concrete Block		7	1,240	SF	\$0	
Wall	Classroom	Concrete Block		7	550	SF	\$0	
Wall	Classroom	Concrete Block		7	450	SF	\$0	
Wall	Classroom	Concrete Block		7	1,240	SF	\$0	
Wall	Classroom	Concrete Block		7	1,070	SF	\$0	
Wall	Classroom	Concrete Block		7	550	SF	\$0	
Wall	Classroom	Concrete Block		7	490	SF	\$0	
Wall	Classroom	Concrete Block		7	450	SF	\$0	
Wall	Classroom	Concrete Block		7	450	SF	\$0	
Wall	Classroom	Concrete Block		7	1,522	SF	\$0	
Wall	Classroom	Concrete Block		7	265	SF	\$0	
Wall	Classroom	Concrete Block		7	750	SF	\$0	
Wall	Classroom	Concrete Block		7	750	SF	\$0	
Wall	Classroom	Concrete Block		7	750	SF	\$0	
Wall	Classroom	Concrete Block		7	968	SF	\$0	
Wall	Classroom	Concrete Block		7	1,746	SF	\$0	
Wall	Classroom	Concrete Block		7	750	SF	\$0	
Wall	Classroom	Concrete Block		7	757	SF	\$0	
Wall	Classroom	Concrete Block		7	450	SF	\$0	
Wall	Classroom	Metal/Folding Panel		7	430	SF	\$0	
Wall	Classroom	Metal/Folding Panel		7	430	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	260	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	757	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	757	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	757	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	757	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	260	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	260	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	260	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	260	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	450	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	757	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	260	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	550	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	260	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	243	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	550	SF	\$0	

Building: William B. Ogden School
Category: ROOM

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Wall	Classroom	Plaster/Drywall		7	550	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	450	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	550	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	450	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	243	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	757	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	757	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	757	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	757	SF	\$0	
Wall	Classroom	Plaster/Drywall		7	550	SF	\$0	
ROOM Sub Total							\$0	

Building William B. Ogden School Sub Total \$6,821

Building: SITE
Category: SITE

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Civil/Drainage		Catch Basin	Entire site	7	1	EA	\$0	
Civil/Drainage		Catch Basin	Entire site	7	3	EA	\$0	
Civil/Drainage		Site Manhole	Entire site	7	4	EA	\$0	
Fencing		Ornamental Iron	Entire site	7	606	LF	\$0	
Fencing		Ornamental Iron	Roof	7	729	LF	\$0	
Landscape		Benches	South Courtyard	7	4	EA	\$0	
Landscape		Benches	Roof	7	4	EA	\$0	
Landscape		Grass	Roof	7	5,535	SF	\$0	
Landscape		Hardscape - Concrete	Entire site	7	1,305	SF	\$0	
Landscape		Hardscape - Concrete	Roof	7	265	SF	\$0	
Landscape		Hardscape - Pavers	West Entrances	7	8,958	SF	\$0	
Landscape		Hardscape - Pavers	Roof	7	4,072	SF	\$0	
Landscape		Parkway trees	Entire Building	7	34	EA	\$0	
Landscape		Planting Beds/ Areas	Entire site	7	5,521	SF	\$0	
Landscape		Retaining Wall - Concrete	West Entrances	7	98	SF	\$0	
Landscape		Trash Receptacles	Roof	7	2	EA	\$0	
Landscape		Trash Receptacles	South Courtyard	7	2	EA	\$0	
Parking Lot		Concrete	North Entrances	7	4,603	SF	\$0	
Parking Lot		Concrete Curbs	North Entrances	7	211	LF	\$0	

Building: SITE
Category: SITE

Group	Sub Group	Item	Location	Rank	Quantity	Unit	Cost	Reason
Parking Lot		Concrete Curbs	Entire Building	7	1,065	LF	\$0	
Playground		Playground Equipment - School Age 5-12	South Courtyard	7	1	EA	\$0	
Playground		Playground Surfacing - Poured Surface	South Courtyard	7	1,538	SF	\$0	
Playground		Playground Surfacing - Poured Surface	Roof	7	4,610	SF	\$0	
Sidewalks		Perimeter Sidewalks	Entire Building	7	11,200	SF	\$0	
Signage		Flag Pole	South Courtyard	7	2	EA	\$0	
Signage		Flag Pole	West Façade	6	1	EA	\$0	
Signage		Marquee - Free Standing Back Lighted	Southwest corner	6	1	EA	\$0	
SITE Sub Total							\$0	
SITE Sub Total							\$0	

Total Campus Need ^{2 3} \$6,821

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Room Summary

Room Number	Room Size	Voice Outlet	Data Outlet	Elect Outlet	Noise Level	Glaze Window Area	Operable Window Area	No. of Window AC	Window Stop	Smart Board	Power Strip	Room Type	Room Sub Type	Location
Building: William B. Ogden School														
103	790	2	7	20	40	150	6	0	Y	N	N	Classroom		
105	790	2	7	20	40	150	6	0	Y	N	N	Classroom		
107	1140	2	12	30	40	200	8	0	Y	Y	N	Classroom		
109	1140	2	12	30	40	200	8	0	Y	Y	N	Classroom		
110	1339	1	4	10	40	150	6		Y	N	Y	Classroom		
111	1140	2	12	30	40	200	8	0	Y	Y	N	Classroom		
113	1140	2	12	30	40	200	8	0	Y	Y	N	Classroom		
115	1140	2	12	30	40	200	8	0	Y	Y	N	Classroom		
203	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
205	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
206	241	1	2	2	40	0	0		Y	Y	N	Classroom		
207	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
208	1683	1	40	48	40	150	6		Y	Y	N	Classroom		
209	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
210	890	1	9	24	40	50	2		Y	Y	N	Classroom		
211	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
212	890	1	9	24	40	50	2		Y	Y	N	Classroom		
213	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
214	890	1	9	24	40	50	2		Y	Y	N	Classroom		
215	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
217	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
219	1200	1	10	38	40	230	4	0	Y	N	N	Classroom		
226	1037	1	9	24	40	150	6		Y	Y	N	Classroom		
303	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
305	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
307	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
308	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
309	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
310	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
311	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
312	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
313	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
315	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
317	897	1	9	26	40	150	6	0	Y	Y	N	Classroom		
319	1200	1	9	26	40	230	4	0	Y	Y	N	Classroom		
324	979	1	9	26	40	150	6		Y	Y	N	Classroom		

Room Summary

Room Number	Room Size	Voice Outlet	Data Outlet	Elect Outlet	Noise Level	Glaze Window Area	Operable Window Area	No. of Window AC	Window Stop	Smart Board	Power Strip	Room Type	Room Sub Type	Location
Other	293								N	N	N	Restroom	Children's Standard Student Restroom	2nd Flr SE Boy's Room 218C
Other	301								N	N	N	Restroom	Children's Standard Student Restroom	3rd Flr Girl's Room 316A SE corner
Other	51								N	N	N	Restroom	Staff Restroom	Room 301BD NW Corner
Other	51								N	N	N	Restroom	Staff Restroom	Room 316D SE Corner
Other	749			34					N	N	N	Administrative Suites/Offices		Room 320 Faculty Lounge
Other	122			8					N	N	N	Administrative Suites/Offices		Room 319A (AV Storage 3021)
Other	187			12					N	N	N	Administrative Suites/Offices		Room 300A Work Room in Library
Other	293								N	N	N	Restroom	Children's Standard Student Restroom	3rd Flr SE Boy's Room 316C
Other	293								N	N	N	Restroom	Children's Standard Student Restroom	3rd Flr NW Boy's Room 301A
Other	301								N	N	N	Restroom	Children's Standard Student Restroom	3rd Flr Girl's Room 301C NW corner
Other	178			10					N	N	N	Administrative Suites/Offices		Room 104D Counselor's Office
Other	3498								N	N	N	Lunch & Multipurpose Room	Multipurpose Room	1st Floor
Other	172			10					N	N	N	Administrative Suites/Offices		Room 108 Speech Pathology Office
Other	172			10					N	N	N	Administrative Suites/Offices		Office Room 106
Other	273			4					N	N	N	Administrative Suites/Offices		Room 104 Waiting Area
Other	152			4					N	N	N	Administrative Suites/Offices		Teacher's Lounge/Kitchen
Other	82								N	N	N	Restroom	Staff Restroom	In the Main Office area
Other	4264								N	N	N	Gymnasia	Gymnasium.Auditorium	2nd Floor
Other	183			6					N	N	N	Administrative Suites/Offices		Conference Room 104F
Other	70								N	N	N	Restroom	Staff Restroom	Women's Room 1st Floor next to Kitchen
Other	182			4					N	N	N	Administrative Suites/Offices		Room 104E PYP Curriculum Co-Ord
Other	164			14					N	N	N	Administrative Suites/Offices		Room 100E Office
Other	280			6					N	N	N	Administrative Suites/Offices		Principal's Office Room 100C
Other	281			4					N	N	N	Administrative Suites/Offices		Operations Manager's Ofc Room 100B
Other	61								N	N	N	Restroom	Staff Restroom	Room 100G
Other	278			6					N	N	N	Administrative Suites/Offices		Room 100A Conference Room
Other	100			6					N	N	N	Administrative Suites/Offices		Room 104B Social Workers Office
Other	51								N	N	N	Restroom	Staff Restroom	2nd Floor NW Corner
Other	728			24					N	N	N	Administrative Suites/Offices		Main Office
Other	293								N	N	N	Restroom	Children's Standard Student Restroom	2nd Flr NW Boy's Room 201A
Other	293								N	N	N	Restroom	Children's Standard Student Restroom	1st Flr NW Boy's Room
Other	293								N	N	N	Restroom	Children's Standard Student Restroom	1st Flr SE Boy's Room
Other	301								N	N	N	Restroom	Children's Standard Student Restroom	2nd Flr Girl's Room 201C NW corner

Room Summary

Room Number	Room Size	Voice Outlet	Data Outlet	Elect Outlet	Noise Level	Glaze Window Area	Operable Window Area	No. of Window AC	Window Stop	Smart Board	Power Strip	Room Type	Room Sub Type	Location
Other	301								N	N	N	Restroom	Children's Standard Student Restroom	1st Flr Girl's Room NW corner
Other	147			6					N	N	N	Administrative Suites/Offices		Room 114A-1 in Kitchen
Other	301								N	N	N	Restroom	Children's Standard Student Restroom	2nd Flr Girl's Room SE corner
Other	1449								N	N	N	Kitchen	Warming Kitchen	1st Floor
Other	51								N	N	N	Restroom	Staff Restroom	1st Floor NW Corner
Other	51								N	N	N	Restroom	Staff Restroom	1st Floor NW Corner
Other	73								N	N	N	Restroom	Early Childhood Student Restroom	Room 110
Other	192			4					N	N	N	Administrative Suites/Offices		Janitor's Break Room
Other	70								N	N	N	Restroom	Staff Restroom	Men's Room 1st Floor next to Kitchen
Other	95								N	N	N	Restroom	Early Childhood Student Restroom	Pre-School 107, 109, 110, 111, 113 & 115 (1028, 1031, 1034, 1037 & 1040)
Other	99			6					N	N	N	Administrative Suites/Offices		Room 224B Gym Office
Other	301								N	N	N	Restroom	Children's Standard Student Restroom	1st Flr Girl's Room SE corner