

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

- Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated.
- Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
- Cost** means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.
- For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.**
- Total Campus Need** also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------|-----------|---|-----------------|------|----------|------|----------|---------------|
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | top of chimney | 5 | 15 | LF | \$26,813 | |
| Chimney | | Brick Chimney - Concrete/ Mortar Liner | Boiler Room | 6 | 62 | LF | \$31,031 | mortar |
| Chimney | | Metal Flue | Lower Roof | 7 | 35 | LF | \$0 | |
| Cornice | | Cornice - Cast Stone | East Façade | 6 | 242 | LF | \$13,019 | |
| Cornice | | Cornice - Metal Projecting | Entire Building | 6 | 161 | LF | \$14,435 | |
| Doors | | Exterior FRP Door | 1st Floor | 6 | 6 | EA | \$3,341 | |
| Doors | | Exterior Steel Door | 1st Floor | 6 | 1 | EA | \$330 | |
| Doors | | Transom Lite | 1st Floor | 6 | 8 | EA | \$2,265 | |
| Entrance | | Entrance Controls - Audio and Video | 1st Floor | 6 | 2 | EA | \$2,860 | |
| Entrance | | Power Door Operator and Controls | 1st Floor | 6 | 2 | EA | \$0 | |
| Foundation | | Masonry Foundation | Entire Building | 7 | 290 | SF | \$0 | |
| Foundation | | Masonry Foundation | Boiler Room | 5 | 30 | SF | \$9,811 | efflorescence |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Roof | 6 | 1 | EA | \$501 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 8 | EA | \$1,716 | |

Building: Main
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|-------------------------------------|------------------------------|------|----------|------|-----------|---|
| Lintels | | Lintels - Brick | Courtyard | 6 | 30 | LF | \$0 | |
| Lintels | | Lintels - Steel | Entire Building | 6 | 290 | LF | \$10,948 | |
| Lintels | | Lintels - Stone | East Façade | 7 | 155 | LF | \$0 | |
| Parapet | | Coping - Stone | main roof, E elevation | 6 | 121 | LF | \$0 | |
| Parapet | | Coping - Terra Cotta | low W roof, N & S elevations | 3 | 40 | LF | \$10,571 | deteriorated and allowing water intrusion |
| Parapet | | Coping - Terra Cotta | Roofs | 6 | 352 | LF | \$0 | |
| Parapet | | Coping - Terra Cotta | Main Roof | 4 | 207 | LF | \$54,703 | |
| Parapet | | Parapet < 16" Height | Roofs | 6 | 278 | LF | \$43,292 | |
| Parapet | | Parapet > 30" Height | Upper roof, W elevation | 6 | 25 | LF | \$6,489 | |
| Parapet | | Parapet 16" to 30" Height | Roofs | 6 | 336 | LF | \$69,766 | |
| Parapet | | Parapet 16" to 30" Height | upper roof, N elevation | 4 | 81 | LF | \$57,336 | spalling |
| Roof System | | Exterior Downspouts | North Courtyard | 7 | 13 | LF | \$0 | |
| Roof System | | Exterior Downspouts | South Courtyard | 5 | 13 | LF | \$242 | vegetation growth |
| Roof System | | Interior Downspouts | Main Roof | 6 | 111 | LF | \$0 | |
| Roof System | | Interior Downspouts | boiler room - bathroom | 5 | 13 | LF | \$1,394 | leaks during heavy rains |
| Roof System | | Metal Roof | mid roof, W elevation | 6 | 189 | SF | \$1,427 | |
| Roof System | | Modified Bitumen Roof | Roofs | 5 | 12,219 | SF | \$144,154 | bubbles |
| Roof System | | Modified Bitumen Roof | low W roof | 3 | 100 | SF | \$2,360 | deterioration and water intrusion |
| Roof System | | Roof Structure: Heavy Timber | Roofs | 7 | 12,500 | SF | \$0 | |
| Roof System | | Roof Structure: Heavy Timber | at roof hatch | 5 | 8 | SF | \$287 | split at bottom of joist |
| Superstructure | | Heavy Timber | Entire Building | 7 | 39,496 | SF | \$0 | |
| Walls | | Brick | Entire Building | 6 | 14,787 | SF | \$97,692 | |
| Walls | | Brick | lower W elevation | 5 | 2,340 | SF | \$53,004 | |
| Walls | | Stone - Cast | East Façade | 6 | 968 | SF | \$13,842 | |
| Windows | | Window - Guards perforated | 1st Floor | 6 | 1,260 | SF | \$0 | |
| Windows | | Windows - Decorative | stairwells | 7 | 112 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 7 | 3,675 | SF | \$0 | |

EXTERIOR Sub Total \$673,626

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------|-----------|--|----------------------|------|----------|------|----------|--------|
| Emergency System | | Automatic Transfer switch | Electrical Room | 6 | 2 | EA | \$2,860 | |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Corridors and Stairs | 6 | 5,318 | SF | \$2,281 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Entire Building | 4 | 15 | EA | \$13,943 | |
| Emergency System | | Public Announcement System | Main Office | 6 | 39,496 | SF | \$23,721 | |

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|-----------------|------|----------|------|------------------|--------|
| Emergency System | | Security System - CCTV | Entire Building | 6 | 39,496 | SF | \$56,479 | |
| Emergency System | | Security System - Intrusion detection | Mechanical Room | 6 | 39,496 | SF | \$36,712 | |
| Emergency System | | UPS 30 KW and below | Electrical Room | 5 | 1 | EA | \$28,600 | |
| Main Service | | Main Electrical service - Live Front - 2000 A 120/240/3PH | Electrical Room | 6 | 1 | EA | \$12,155 | |
| Power Distribution | | Lighting and power panels | Entire Building | 4 | 6 | EA | \$32,604 | |
| Power Distribution | | Main distribution panels above 600 amp | Electrical Room | 7 | 1 | EA | \$0 | |
| Power Distribution | | Main distribution panels less than 400 amp | Electrical Room | 7 | 1 | EA | \$0 | |
| ELECTRICAL Sub Total | | | | | | | \$209,355 | |

Building: Main
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|--------------------------|-----------------|------|----------|------|------------------|--|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 3 | 39,496 | SF | \$83,589 | Strobe lights are not located in all areas |
| Fire Alarm | | Fire Alarm System | Electrical Room | 6 | 39,496 | SF | \$48,007 | |
| Fire Alarm | | Fire Pump Controller | Basement | 6 | 1 | EA | \$2,145 | |
| Pump Room Assembly | | Fire Pump 25-50hp | Basement | 6 | 1 | EA | \$3,718 | |
| Pump Room Assembly | | Jockey Pump | Basement | 6 | 1 | EA | \$744 | |
| Sprinkler System | | Dry Sprinkler System | Entire Building | 6 | 39,496 | SF | \$28,240 | |
| Sprinkler System | | Sprinkler Heads | Entire Building | 6 | 39,496 | SF | \$2,259 | |
| FIRE PROTECTION Sub Total | | | | | | | \$168,702 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|-----------------|------|----------|------|----------|--------|
| Air Conditioning | | Window A/C Unit | Entire Building | 6 | 6 | EA | \$1,287 | |
| Air Handling Systems | | Air Intake - Built Up Air Handling Unit | East Façade | 5 | 1 | EA | \$16,016 | |
| Air Handling Systems | | Multi Zone Double Delivery Built Up Air Handling Unit - Hot Water or Dual Temperature Water 30,001 to 45,000 cfm | Mechanical Room | 6 | 1 | EA | \$17,303 | |
| Air Handling Systems | | Multi Zone Double Delivery Built Up Air Handling Unit Auxiliaries - Hot Water or Dual Temperature Water 30,001 to 45,000 cfm | Mechanical Room | 6 | 1 | EA | \$6,578 | |
| Air Handling Systems | | Return Duct Work - Indoor - Vertical Shaft and Ducts | Attic | 6 | 100 | LF | \$6,292 | |
| Air Handling Systems | | Return Fans - Indoor 10,001 to 20,000 CFM | Attic | 6 | 2 | EA | \$4,862 | |
| Boiler Systems | | Boiler Assembly - Non-Condensing Scotch Marine Hot Water Boiler greater than 4,000 MBH | Boiler Room | 6 | 2 | EA | \$62,062 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|-------------------|------|----------|------|------------------|---|
| Boiler Systems | | Boiler Auxiliary Non-Condensing Hot Water Boiler greater than 4,000MBH | Boiler Room | 6 | 2 | EA | \$13,156 | |
| Boiler Systems | | Chemical Pot Feeder - Hot Water | Mechanical Room | 6 | 1 | EA | \$300 | |
| Boiler Systems | | Glycol Feed System | Mechanical Room | 3 | 1 | EA | \$3,861 | Glycol feed system is working, however the glycol levels in the system are non-existent |
| Heating Devices | | Unit Heater - Gas | Boiler Room | 6 | 1 | EA | \$2,145 | |
| Mechanical Plumbing | | Piping - Hydronic Supply and Return - Steel or Galvanized | Mechanical Room | 6 | 400 | LF | \$3,546 | |
| Mechanical Plumbing | | Pumps - Hot Water 11 to 20 HP | Mechanical Room | 6 | 2 | EA | \$5,148 | |
| Mechanical Plumbing | | Pumps - Hot Water 21 - 50 HP | Mechanical Room | 6 | 2 | EA | \$11,440 | |
| Temperature Control | | Direct Digital Control (DDC) System | Engineer's Office | 6 | 99,227 | SF | \$99,326 | |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | Entire Building | 6 | 19 | EA | \$2,717 | |
| Temperature Control | | Zone Dampers | Plenum | 6 | 19 | EA | \$2,717 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 6 | 2 | EA | \$858 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Lower Roof | 3 | 1 | EA | \$2,288 | Unit is not working - Bad Motor |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 6 | 1 | EA | \$229 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Lower Roof | 6 | 1 | EA | \$229 | |
| Ventilation | | Exhaust Fans - Roof mounted less than 500 CFM | Roof | 6 | 1 | EA | \$157 | |
| MECHANICAL Sub Total | | | | | | | \$262,518 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------|-----------|--|-----------------|------|----------|------|----------|--------|
| Hot Water | | Hot Water Heater - Gas 150,000 -300,000 BTU/HR | Boiler Room | 6 | 2 | EA | \$8,294 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 7 | 39,496 | SF | \$0 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 4 | 39,496 | SF | \$25,416 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 7 | 39,496 | SF | \$0 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 4 | 39,496 | SF | \$18,073 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 4 | 39,496 | SF | \$21,462 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 7 | 39,496 | SF | \$0 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 7 | 39,496 | SF | \$0 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 7 | 39,496 | SF | \$0 | |
| Piping | | Sanitary Piping | Entire Building | 5 | 39,496 | SF | \$24,286 | |
| Piping | | Storm Piping | Entire Building | 5 | 39,496 | SF | \$18,638 | |
| Piping | | Vent Piping | Entire Building | 5 | 39,496 | SF | \$14,120 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-------------------------------|-----------------|------|----------|------|------------------|--------|
| Pumps | | Domestic Booster Pump simplex | Mechanical Room | 6 | 1 | EA | \$1,716 | |
| PLUMBING Sub Total | | | | | | | \$132,005 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|----------------------------|------------------------------|------|----------|------|-------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Principals' Office | 7 | 211 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Assistant Principals Office | 7 | 865 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Main Office | 7 | 490 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Basement east of boiler room | 6 | 175 | SF | \$495 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Staff Lounge in Room 102A | 7 | 210 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Principals' Office | 7 | 211 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | Main Office | 7 | 575 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Staff Lounge in Room 102A | 6 | 210 | SF | \$300 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement east of boiler room | 6 | 175 | SF | \$250 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Assistant Principals Office | 7 | 865 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Main Office | 7 | 575 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Staff Lounge in Room 102A | 7 | 5 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Principals' Office | 7 | 3 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Assistant Principals Office | 7 | 12 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Main Office | 7 | 9 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Basement east of boiler room | 6 | 2 | SF | \$1 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Basement east of boiler room | 6 | 258 | SF | \$738 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Main Office | 7 | 1,150 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|-------------------------------|------------------------------|---|------|----------|------|----------|--------|
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement east of boiler room | 6 | 258 | SF | \$609 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Assistant Principals Office | 7 | 1,521 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Staff Lounge in Room 102A | 6 | 640 | SF | \$1,510 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Principals' Office | 7 | 767 | SF | \$0 | |
| Doors | | Interior Steel Doors incl hw | Basement | 6 | 14 | EA | \$3,964 | |
| Doors | | Interior Steel Doors incl hw | 1st Floor | 6 | 2 | EA | \$566 | |
| Doors | | Interior Wood Doors incl hw | 3rd Floor | 6 | 8 | EA | \$2,265 | |
| Doors | | Interior Wood Doors incl hw | 2nd Floor | 6 | 9 | EA | \$2,548 | |
| Doors | | Interior Wood Doors incl hw | 1st Floor | 6 | 12 | EA | \$3,398 | |
| Doors | | Interior Wood Doors incl hw | Basement | 6 | 23 | EA | \$6,512 | |
| Doors | | Side-lite | 1st Floor | 6 | 15 | SF | \$279 | |
| Doors | | Side-lite | Basement | 6 | 20 | SF | \$372 | |
| Doors | | Transom Window | 3rd Floor | 6 | 70 | SF | \$1,301 | |
| Doors | | Transom Window | 2nd Floor | 6 | 60 | SF | \$1,115 | |
| Doors | | Transom Window | 1st Floor | 6 | 70 | SF | \$1,301 | |
| Doors | | Transom Window | Basement | 6 | 60 | SF | \$1,115 | |
| Drinking Fountains | Corridors | Double Fountain | 1st Floor | 7 | 1 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | Basement | 7 | 2 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 3rd Floor | 7 | 2 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 2nd Floor | 7 | 2 | EA | \$0 | |
| Mechanical/Service Rooms | | Boiler Room | Basement | 6 | 1,252 | SF | \$5,908 | |
| Mechanical/Service Rooms | | Janitor's Closet | Entire Building | 6 | 3 | SF | \$14 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement east of boiler room | 6 | 2,880 | SF | \$13,591 | |
| Mechanical/Service Rooms | | Storage Room | 2nd floor between Rms 201 & 203 | 6 | 382 | SF | \$1,803 | |
| Mechanical/Service Rooms | | Storage Room | Basement three storages next to boiler room | 6 | 1,751 | SF | \$8,263 | |
| Mechanical/Service Rooms | | Storage Room | 3rd Floor | 7 | 155 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | Sub-Basement east of boiler room | 5 | 16 | SF | \$408 | |
| Staff Restroom | Staff Restroom | Accessories | 1st Floor | 6 | 142 | SF | \$1,097 | |
| Staff Restroom | Staff Restroom | Accessories | In the Main Office Area | 7 | 36 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 1st Floor | 7 | 142 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Sub-Basement east of boiler room | 6 | 16 | SF | \$45 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|----------------|-----------------------------------|----------------------------------|------|----------|------|---------|--------|
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | In the Main Office Area | 7 | 36 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Concrete | Sub-Basement east of boiler room | 6 | 16 | SF | \$76 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 1st Floor | 5 | 142 | SF | \$2,234 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | In the Main Office Area | 7 | 36 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 1st Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | In the Main Office Area | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Sub-Basement east of boiler room | 6 | 1 | SF | \$1 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | 1st Floor | 7 | 3 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | In the Main Office Area | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 1st Floor | 5 | 3 | EA | \$1,716 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | Sub-Basement east of boiler room | 5 | 234 | SF | \$1,767 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | 1st Floor | 7 | 419 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | In the Main Office Area | 7 | 160 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 1st Floor | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Sub-Basement east of boiler room | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | In the Main Office Area | 7 | 1 | EA | \$0 | |

INTERIOR Sub Total \$65,934

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 7 | 2 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 11 | LF | \$393 | |
| Casework | Classroom | Casework | | 6 | 11 | LF | \$393 | |
| Casework | Classroom | Casework | | 6 | 15 | LF | \$536 | |
| Casework | Classroom | Casework | | 6 | 11 | LF | \$393 | |
| Casework | Classroom | Casework | | 6 | 11 | LF | \$393 | |
| Casework | Classroom | Casework | | 6 | 7 | LF | \$250 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 1,342 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,091 | SF | \$3,089 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,091 | SF | \$3,089 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 878 | SF | \$2,486 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 878 | SF | \$2,486 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 880 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|-------------------------|----------------------------|------|----------|------|----------|--------|
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,091 | SF | \$3,089 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 1,091 | SF | \$3,089 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 880 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 862 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 880 | SF | \$0 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 8 | LF | \$972 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 24 | LF | \$2,917 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 7 | 1 | EA | \$0 | |
| Corridors | Corridors | Concrete Epoxy/Painted | 1st Floor | 6 | 1,103 | SF | \$5,205 | |
| Corridors | Corridors | Concrete Epoxy/Painted | Basement | 6 | 1,103 | SF | \$5,205 | |
| Corridors | Corridors | Concrete Epoxy/Painted | 3rd Floor | 6 | 1,103 | SF | \$5,205 | |
| Corridors | Corridors | Concrete Epoxy/Painted | 2nd Floor | 6 | 1,103 | SF | \$5,205 | |
| Corridors | Corridors | Pendant/Surface | Basement | 7 | 1,103 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 3rd Floor | 7 | 1,103 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 7 | 1,103 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | Entire building stairwells | 6 | 1,922 | EA | \$1,374 | |
| Corridors | Corridors | Pendant/Surface | 1st Floor | 7 | 1,103 | EA | \$0 | |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 6 | 2,433 | SF | \$5,741 | |
| Corridors | Corridors | Plaster/Drywall | Basement | 6 | 2,433 | SF | \$5,741 | |
| Corridors | Corridors | Plaster/Drywall | Entire building stairwells | 6 | 7,320 | SF | \$17,272 | |
| Corridors | Corridors | Plaster/Drywall | 3rd Floor | 6 | 2,433 | SF | \$5,741 | |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 6 | 2,433 | SF | \$5,741 | |
| Corridors | Corridors | Stair Handrails | Entire building stairwells | 6 | 372 | LF | \$0 | |
| Corridors | Corridors | Student Lockers | 3rd Floor | 7 | 78 | EA | \$0 | |
| Corridors | Corridors | Student Lockers | 2nd Floor | 7 | 78 | EA | \$0 | |
| Corridors | Corridors | Student Lockers | 1st Floor | 7 | 78 | EA | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | Entire building stairwells | 6 | 1,180 | SF | \$1,687 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Entire building stairwells | 6 | 1,922 | SF | \$5,442 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 2nd Floor | 7 | 1,103 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 1st Floor | 7 | 1,103 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Basement | 7 | 1,103 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 3rd Floor | 7 | 1,103 | SF | \$0 | |
| Stairs | Corridors | Tile | Entire building stairwells | 6 | 178 | SF | \$1,344 | |
| Floor | Classroom | Carpet | | 6 | 878 | SF | \$1,256 | |
| Floor | Classroom | Carpet | | 6 | 878 | SF | \$1,256 | |
| Floor | Classroom | Carpet | | 7 | 880 | SF | \$0 | |
| Floor | Classroom | Carpet | | 7 | 880 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Floor | Classroom | Carpet | | 7 | 880 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,091 | SF | \$1,560 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,091 | SF | \$1,560 | |
| Floor | Classroom | Tile/Sheet | | 7 | 862 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,091 | SF | \$1,560 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,342 | SF | \$1,919 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,091 | SF | \$1,560 | |
| Lighting | Classroom | Lay-In | | 7 | 23 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 14 | EA | \$1,001 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 14 | EA | \$1,001 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 16 | EA | \$1,144 | |
| Marker Board | Classroom | Marker Board | | 6 | 13 | LF | \$372 | |
| Marker Board | Classroom | Marker Board | | 6 | 13 | LF | \$372 | |
| Marker Board | Classroom | Marker Board | | 6 | 13 | LF | \$372 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 8 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 53 | LF | \$1,516 | |
| Marker Board | Classroom | Marker Board | | 7 | 36 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 24 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 53 | LF | \$1,516 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 13 | LF | \$372 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,529 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,529 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,529 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 2,004 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 934 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 2,151 | SF | \$5,075 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 2,151 | SF | \$5,075 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 2,151 | SF | \$5,075 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------------|-----------|-----------------|----------|------|----------|------|--------------------|--------|
| Wall | Classroom | Plaster/Drywall | | 6 | 2,151 | SF | \$5,075 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,316 | SF | \$3,105 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,316 | SF | \$3,105 | |
| ROOM Sub Total | | | | | | | \$142,758 | |
| Building Main Sub Total | | | | | | | \$1,654,899 | |

Building: Addition 1
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|---|-----------------------|------|----------|------|-----------|--|
| Cornice | | Cornice - Masonry Projecting/Limestone | Entire Building | 6 | 324 | LF | \$9,938 | |
| Cornice | | Cornice - Metal Projecting | Entire Building | 6 | 324 | LF | \$29,050 | |
| Doors | | Exterior FRP Door | 1st Floor | 6 | 3 | EA | \$1,671 | |
| Doors | | Exterior Steel Door | 1st Floor | 6 | 11 | EA | \$3,634 | |
| Fire Escape | | Fire Escapes | West Façade | 6 | 78 | LF | \$7,951 | locked and blocked egress at 3rd & 2nd floors; debris & vegetation growth at bottom door |
| Foundation | | Concrete Foundation | Entire Building | 7 | 345 | LF | \$0 | |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Roofs | 6 | 3 | EA | \$1,502 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 3 | EA | \$644 | |
| Lintels | | Lintels - Steel | Entire Building | 6 | 154 | LF | \$5,814 | |
| Lintels | | Lintels - Stone | Entire Building | 7 | 176 | LF | \$0 | |
| Parapet | | Coping - Stone | Roofs | 6 | 448 | LF | \$0 | |
| Parapet | | Parapet > 30" Height | N & S roof elevations | 5 | 164 | LF | \$65,783 | |
| Parapet | | Parapet > 30" Height | NE roof | 4 | 5 | LF | \$4,969 | |
| Parapet | | Parapet > 30" Height | Roofs | 6 | 279 | LF | \$72,413 | |
| Roof System | | Interior Downspouts | Roofs | 6 | 186 | LF | \$0 | |
| Roof System | | Modified Bitumen Roof | Roofs | 6 | 9,247 | SF | \$65,455 | |
| Roof System | | Roof Structure: Concrete | S roof | 7 | 4,689 | SF | \$0 | |
| Roof System | | Roof Structure: Concrete | N roof | 7 | 4,371 | SF | \$0 | |
| Superstructure | | Concrete | N structure | 7 | 15,908 | SF | \$0 | |
| Superstructure | | Steel with Clay Tile Arch | S structure | 7 | 17,484 | SF | \$0 | |
| Walls | | Brick | Entire Building | 6 | 19,820 | SF | \$130,943 | |
| Walls | | Stone - Cast | Entire Building | 6 | 1,856 | SF | \$26,541 | |
| Windows | | Window - Guards perforated | Entire Building | 6 | 84 | SF | \$0 | |

Building: Addition 1
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-------------------------------------|-----------------|------|----------|------|------------------|--------|
| Windows | | Windows - Sash Aluminum | fire escape | 7 | 120 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 7 | 2,328 | SF | \$0 | |
| EXTERIOR Sub Total | | | | | | | \$426,306 | |

Building: Addition 1
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|----------------------|------|----------|------|------------------|--|
| Emergency System | | Emergency A/C power - Auditorium and aisle lighting | Auditorium | 3 | 2,502 | SF | \$17,353 | A number of the emergency lights do not work and/or lights are not provided in all areas |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Corridors and Stairs | 6 | 8,046 | SF | \$3,452 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Gym - 3rd Floor | 6 | 2,976 | SF | \$1,575 | |
| Emergency System | | Emergency A/C power - Students Toilets | Student Toilets | 6 | 822 | SF | \$353 | |
| Emergency System | | Exit Signs - Auditorium | Auditorium | 2 | 11 | EA | \$10,225 | Exit signs are more than 20 years old and they are not provided with battery backup and the appearance is poor |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms Gym | | 2 | 3 | EA | \$2,789 | Exit signs are more than 20 years old and they are not provided with battery backup and the appearance is poor |
| Emergency System | | Public Announcement System | Entire Building | 4 | 33,579 | SF | \$119,085 | |
| Emergency System | | Security System - CCTV | Entire Building | 4 | 33,579 | SF | \$240,090 | |
| Emergency System | | Security System - Intrusion detection | Entire Building | 6 | 33,579 | SF | \$31,212 | |
| Power Distribution | | Lighting and power panels | Entire Building | 4 | 3 | EA | \$16,302 | |
| Power Distribution | | Main distribution panels 400-600 amp | Mechanical Room | 7 | 1 | EA | \$0 | |
| ELECTRICAL Sub Total | | | | | | | \$442,433 | |

Building: Addition 1
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|--------------------------|-----------------|------|----------|------|-----------------|--|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 3 | 33,579 | SF | \$71,067 | Strobe lights are not located in all areas |
| Sprinkler System | | Dry Sprinkler System | Entire Building | 6 | 33,579 | SF | \$24,009 | |
| Sprinkler System | | Sprinkler Heads | Entire Building | 6 | 33,579 | SF | \$1,921 | |
| FIRE PROTECTION Sub Total | | | | | | | \$96,996 | |

Building: Addition 1
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|------|----------|------|----------|------|------|--------|
|-------|-----------|------|----------|------|----------|------|------|--------|

Building: Addition 1
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|-----------------|------|----------|------|-----------------|---|
| Air Handling Systems | | Air Intake - Built Up Air Handling Unit | West Façade | 5 | 1 | EA | \$16,016 | |
| Air Handling Systems | | Multi Zone Built Up Air Handling Unit - Hot Water or Dual Temperature Water 15,001 to 25,000 cfm | Mechanical Room | 6 | 1 | EA | \$11,297 | |
| Air Handling Systems | | Multi Zone Built Up Air Handling Unit Auxiliaries - Hot Water 15,000 to 25,000 cfm | Mechanical Room | 6 | 1 | EA | \$3,289 | |
| Air Handling Systems | | Return Duct Work - Indoor - Vertical Shaft and Ducts | Attic | 6 | 100 | LF | \$6,292 | |
| Air Handling Systems | | Return Fans - Indoor 10,001 to 20,000 CFM | Attic | 6 | 1 | EA | \$2,431 | |
| Heating Devices | | Wall Heater - Electric | Entire Building | 6 | 2 | EA | \$206 | |
| Heating Devices | | Wall Heater - Electric | Entire Building | 3 | 2 | EA | \$2,059 | Wall heater is more than 10 years of age and is working, however the heater cannot maintain the proper heat in the area |
| Mechanical Plumbing | | Piping - Hydronic Supply and Return - Steel or Galvanized | Entire Building | 6 | 200 | LF | \$1,773 | |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | Entire Building | 6 | 14 | EA | \$2,002 | |
| Temperature Control | | Zone Dampers | Plenum | 6 | 14 | EA | \$2,002 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 6 | 1 | EA | \$429 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 4 | 1 | EA | \$2,288 | Severe Vibration |
| Ventilation | | Exhaust Fans - Roof mounted less than 500 CFM | Roof | 6 | 1 | EA | \$157 | |
| MECHANICAL Sub Total | | | | | | | \$50,242 | |

Building: Addition 1
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------|-----------|--|-----------------|------|----------|------|----------|--------|
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 7 | 33,579 | SF | \$0 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 4 | 33,579 | SF | \$21,608 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 7 | 33,579 | SF | \$0 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 4 | 33,579 | SF | \$15,366 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 4 | 33,579 | SF | \$18,247 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 7 | 33,579 | SF | \$0 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 7 | 33,579 | SF | \$0 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 7 | 33,579 | SF | \$0 | |

Building: Addition 1
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-----------------|-----------------|------|----------|------|------------------|--------|
| Piping | | Sanitary Piping | Entire Building | 5 | 33,579 | SF | \$20,648 | |
| Piping | | Storm Piping | Entire Building | 5 | 33,579 | SF | \$15,846 | |
| Piping | | Vent Piping | Entire Building | 5 | 33,579 | SF | \$12,004 | |
| PLUMBING Sub Total | | | | | | | \$103,719 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|-----------------------------------|--|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Office is former Women's Room next to Auditorium | 7 | 103 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Faculty Lounge in Basement | 7 | 434 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Gym Teacher's Office | 6 | 701 | SF | \$1,985 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 1st floor NE room #107 | 6 | 879 | SF | \$2,489 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 1st floor offices #105 & 107A | 6 | 586 | SF | \$1,659 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | 1st floor NE room #107 | 6 | 879 | SF | \$1,257 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Concrete | Gym Teacher's Office | 7 | 351 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile Ceramic/Porcelain | Gym Teacher's Office | 6 | 351 | SF | \$893 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile Ceramic/Porcelain | Office is former Women's Room next to Auditorium | 6 | 103 | SF | \$262 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 1st floor offices #105 & 107A | 6 | 586 | SF | \$838 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Faculty Lounge in Basement | 6 | 434 | SF | \$621 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 1st floor offices #105 & 107A | 6 | 6 | SF | \$4 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Gym Teacher's Office | 7 | 16 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Faculty Lounge in Basement | 7 | 8 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Office is former Women's Room next to Auditorium | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 1st floor NE room #107 | 6 | 8 | SF | \$6 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Faculty Lounge in Basement | 7 | 686 | SF | \$0 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------------|---------------------------------|--------------------------------------|--|------|----------|------|----------|--------|
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 1st floor offices #105 & 107A | 6 | 1,623 | SF | \$3,829 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 1st floor NE room #107 | 6 | 1,424 | SF | \$3,360 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Office is former Women's Room next to Auditorium | 7 | 360 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Gym Teacher's Office | 7 | 921 | SF | \$0 | |
| Auditorium - Dedicated | Theater | Balcony Seating | 1st Floor | 6 | 90 | EA | \$3,313 | |
| Auditorium - Dedicated | Theater | Main Floor Seating | 1st Floor | 6 | 330 | EA | \$12,147 | |
| Auditorium - Dedicated | Theater | Sound System | 1st Floor | 7 | 1 | EA | \$0 | |
| Auditorium - Dedicated | Theater | Stage Curtains | 1st Floor | 6 | 6 | EA | \$67,954 | |
| Auditorium - Dedicated | Theater | Stage Lighting System | 1st Floor | 7 | 1 | EA | \$0 | |
| Doors | | Interior Steel Doors incl hw | Basement | 6 | 5 | EA | \$1,416 | |
| Doors | | Interior Wood Doors incl hw | 1st Floor | 6 | 12 | EA | \$3,398 | |
| Doors | | Interior Wood Doors incl hw | Basement | 6 | 24 | EA | \$6,795 | |
| Doors | | Interior Wood Doors incl hw | 3rd Floor | 6 | 6 | EA | \$1,699 | |
| Doors | | Interior Wood Doors incl hw | 2nd Floor | 6 | 6 | EA | \$1,699 | |
| Doors | | Transom Window | 2nd Floor | 6 | 40 | SF | \$744 | |
| Doors | | Transom Window | 1st Floor | 6 | 40 | SF | \$744 | |
| Doors | | Transom Window | 3rd Floor | 6 | 40 | SF | \$744 | |
| Drinking Fountains | Corridors | Single Fountain | Basement | 7 | 2 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 1st Floor | 7 | 3 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 2nd Floor | 7 | 2 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 3rd Floor | 7 | 2 | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Ceiling - Plaster/Drywall | 3rd Floor | 7 | 2,976 | SF | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Flooring - Wood | 3rd Floor | 7 | 2,976 | SF | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Lighting - Metal Halide/Sodium Vapor | 3rd Floor | 7 | 16 | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Scoreboards | 3rd Floor | 7 | 1 | EA | \$0 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Walls - Plaster/Drywall | 3rd Floor | 6 | 2,241 | SF | \$19,228 | |
| Gymnasium / Auditorium | Standard Dedicated Gymnasium | Walls - Structural Glazed Tile | 3rd Floor | 6 | 2,244 | SF | \$16,045 | |
| Locker/Shower Room | Adult Standard Student Restroom | Benches | women's restroom in auditorium foyer | | | LF | \$0 | |
| Locker/Shower Room | Adult Standard Student Restroom | Lockers | women's restroom in auditorium foyer | | | EA | \$0 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------------------------|-----------------------------------|--|------|----------|------|---------|--------|
| Locker/Shower Room | Adult Standard Student Restroom | Showers | women's restroom in auditorium foyer | | | EA | \$0 | |
| Mechanical/Service Rooms | | Air Handling/ Mechanical Room | Basement | 7 | 210 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement | 7 | 65 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Basement | 7 | 448 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Rooms 302,304,202,102 | 7 | 680 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Room 300 | 7 | 710 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Former Boy's Restroom and locker room per the plan | 6 | 345 | SF | \$1,628 | |
| Physical Education Rooms | | Flooring Tile/ Sheet | Room 200, Boxing Gym | 7 | 564 | SF | \$0 | |
| Physical Education Rooms | | Lighting - Pendant/ Surface | Room 200, Boxing Gym | 7 | 564 | SF | \$0 | |
| Physical Education Rooms | | Paint | Room 200, Boxing Gym | 7 | 798 | SF | \$0 | |
| Physical Education Rooms | | Splined Ceiling | Room 200, Boxing Gym | 7 | 564 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | Men's Room in the Lobby of the Auditorium | 6 | 360 | SF | \$2,780 | |
| Staff Restroom | Adult Standard Student Restroom | Accessories | women's restroom in auditorium foyer | | | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd floor Boy's Room | 6 | 346 | SF | \$2,672 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd Floor Girl's Room | 6 | 373 | SF | \$2,880 | |
| Staff Restroom | Adult Standard Student Restroom | Ceiling - Plaster/Drywall | Men's Room in the Lobby of the Auditorium | 7 | 103 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Girl's Room | 7 | 373 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd floor Boy's Room | 6 | 346 | SF | \$980 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 2nd Floor Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 2nd floor Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Floor Drain | women's restroom in auditorium foyer | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Men's Room in the Lobby of the Auditorium | 6 | 103 | SF | \$262 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd floor Boy's Room | 7 | 346 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor Girl's Room | 7 | 373 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Hand Dryer | women's restroom in auditorium foyer | | | EA | \$0 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------------------------|---|------|----------|------|-------|--------|
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 2nd Floor Girl's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 2nd floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | Men's Room in the Lobby of the Auditorium | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd Floor Girl's Room | 7 | 4 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lavatory | women's restroom in auditorium foyer | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd floor Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Lighting - Pendant/ Surface | Men's Room in the Lobby of the Auditorium | 7 | 2 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Girl's Room | 7 | 5 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd floor Boy's Room | 7 | 5 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | women's restroom in auditorium foyer | | | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Partitions | Men's Room in the Lobby of the Auditorium | 6 | 1 | EA | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd Floor Girl's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd floor Boy's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Urinals | women's restroom in auditorium foyer | | | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 2nd floor Boy's Room | 7 | 9 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 2nd Floor Girl's Room | 7 | 257 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 2nd floor Boy's Room | 7 | 552 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Plaster/Drywall | Men's Room in the Lobby of the Auditorium | 6 | 180 | SF | \$425 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | 2nd Floor Girl's Room | 7 | 514 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Girl's Room | 7 | 257 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Wall - Structural Glazed Tile | Men's Room in the Lobby of the Auditorium | 7 | 180 | SF | \$0 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | Men's Room in the Lobby of the Auditorium | 7 | 1 | EA | \$0 | |

Building: Addition 1
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|--------------------------------------|-------------------------------------|--------------------------------------|------|----------|------|------------------|--------|
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd Floor Girl's Room | 6 | 6 | EA | \$2,231 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd floor Boy's Room | 6 | 6 | EA | \$2,231 | |
| Staff Restroom | Adult Standard Student Restroom | Water Closet | women's restroom in auditorium foyer | | | EA | \$0 | |
| Theater | Theater | Ceiling - Plaster/Drywall | 1st Floor | 7 | 2,502 | SF | \$0 | |
| Theater | Theater | Flooring - Concrete | 1st Floor | 6 | 2,502 | SF | \$11,807 | |
| Theater | Theater | Lighting - Pendant/ Surface | 1st Floor | 7 | 48 | SF | \$0 | |
| Theater | Theater | Stage | 1st Floor | 7 | 618 | SF | \$0 | |
| Theater | Theater | Wall - Plaster/Drywall | 1st Floor | 7 | 5,628 | SF | \$0 | |
| Vertical Conveyance | | Elevator - Roped Holeless Hydraulic | Entire Building | 7 | 1 | EA | \$0 | |
| Vertical Conveyance | | Stage Lift | In the Auditorium | 7 | 1 | EA | \$0 | |
| INTERIOR Sub Total | | | | | | | \$181,201 | |

Building: Addition 1
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 6 | 9 | LF | \$322 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 7 | 6 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 6 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 9 | LF | \$322 | |
| Casework | Classroom | Casework | | | | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 9 | LF | \$322 | |
| Casework | Classroom | Casework | | 6 | 9 | LF | \$322 | |
| Ceiling | Classroom | Ceiling | | | | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 724 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 721 | SF | \$2,041 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 721 | SF | \$2,041 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 721 | SF | \$2,041 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 739 | SF | \$2,092 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 722 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 724 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 722 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 724 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 724 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 724 | SF | \$0 | |

Building: Addition 1
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|---------------------|----------------------------|------|----------|------|----------|--------|
| Chalk Board | Classroom | Chalk Board | | 4 | 24 | LF | \$2,917 | |
| Chalk Board | Classroom | Chalk Board | | 4 | | LF | | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Corridors | Corridors | Pendant/Surface | Entire building stairwells | 6 | 210 | EA | \$150 | |
| Corridors | Corridors | Pendant/Surface | Basement | 7 | 1,959 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 1st Floor | 7 | 1,959 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 7 | 1,959 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 3rd Floor | 7 | 1,959 | EA | \$0 | |
| Corridors | Corridors | Plaster/Drywall | 1st Floor | 7 | 4,276 | SF | \$0 | |
| Corridors | Corridors | Plaster/Drywall | 3rd Floor | 7 | 4,276 | SF | \$0 | |
| Corridors | Corridors | Plaster/Drywall | 2nd Floor | 7 | 4,276 | SF | \$0 | |
| Corridors | Corridors | Plaster/Drywall | Entire building stairwells | 6 | 2,645 | SF | \$6,241 | |
| Corridors | Corridors | Plaster/Drywall | Basement | 7 | 4,276 | SF | \$0 | |
| Corridors | Corridors | Stair Handrails | Entire building stairwells | 6 | 132 | LF | \$0 | |
| Corridors | Corridors | Terrazzo | Basement | 6 | 729 | SF | \$4,128 | |
| Corridors | Corridors | Terrazzo | 1st Floor | 6 | 729 | SF | \$4,128 | |
| Corridors | Corridors | Terrazzo | Entire building stairwells | 6 | 120 | SF | \$680 | |
| Corridors | Corridors | Terrazzo | 2nd Floor | 6 | 729 | SF | \$4,128 | |
| Corridors | Corridors | Terrazzo | 3rd Floor | 6 | 729 | SF | \$4,128 | |
| Corridors | Corridors | Tile/Sheet Flooring | Basement | 6 | 1,200 | SF | \$1,716 | |
| Corridors | Corridors | Tile/Sheet Flooring | 1st Floor | 6 | 1,200 | SF | \$1,716 | |
| Corridors | Corridors | Tile/Sheet Flooring | 2nd Floor | 6 | 1,200 | SF | \$1,716 | |
| Corridors | Corridors | Tile/Sheet Flooring | 3rd Floor | 6 | 1,200 | SF | \$1,716 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Entire building stairwells | 6 | 210 | SF | \$595 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 1st Floor | 7 | 1,959 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 2nd Floor | 7 | 1,959 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 3rd Floor | 7 | 1,959 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Basement | 7 | 1,959 | SF | \$0 | |
| Stairs | Corridors | Terrazzo | Entire building stairwells | 6 | 56 | SF | \$634 | |
| Floor | Classroom | Carpet | | 6 | 721 | SF | \$1,031 | |
| Floor | Classroom | Carpet | | 6 | 721 | SF | \$1,031 | |
| Floor | Classroom | Floor | | | | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 4 | 739 | SF | \$10,462 | |
| Floor | Classroom | Tile/Sheet | | 4 | 721 | SF | \$10,207 | |
| Floor | Classroom | Tile/Sheet | | 5 | 724 | SF | \$4,100 | |

Building: Addition 1
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------|---------------------------------|-------------------|--------------------------------------|------|----------|------|---------|--------|
| Floor | Classroom | Tile/Sheet | | 5 | 724 | SF | \$4,100 | |
| Floor | Classroom | Tile/Sheet | | 5 | 724 | SF | \$4,100 | |
| Floor | Classroom | Wood | | 6 | 722 | SF | \$5,451 | |
| Floor | Classroom | Wood | | 6 | 722 | SF | \$5,451 | |
| Floor | Classroom | Wood | | 7 | 724 | SF | \$0 | |
| Lighting | Classroom | Lighting | | | | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 14 | EA | \$1,001 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 14 | EA | \$1,001 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 14 | EA | \$1,001 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 14 | EA | \$1,001 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |
| Marker Board | Classroom | Marker Board | | | | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 32 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |
| RESTROOM_CEILING | Adult Standard Student Restroom | Restroom Ceiling | women's restroom in auditorium foyer | | | SF | \$0 | |
| RESTROOM_FLOOR | Adult Standard Student Restroom | Restroom Floor | women's restroom in auditorium foyer | | | SF | \$0 | |
| RESTROOM_LIGHT | Adult Standard Student Restroom | Restroom Lighting | women's restroom in auditorium foyer | | | EA | \$0 | |
| RESTROOM_WALL | Adult Standard Student Restroom | Restroom Walls | women's restroom in auditorium foyer | | | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,160 | SF | \$2,737 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,160 | SF | \$2,737 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,386 | SF | \$0 | |

Building: Addition 1
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------------------|-----------|-----------------|----------|------|----------|------|--------------------|--------|
| Wall | Classroom | Plaster/Drywall | | 7 | 1,386 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 867 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,160 | SF | \$2,737 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 867 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,386 | SF | \$3,270 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,160 | SF | \$2,737 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 1,386 | SF | \$3,270 | |
| Wall | Classroom | Wall | | | | SF | \$0 | |
| ROOM Sub Total | | | | | | | \$119,345 | |
| Building Addition 1 Sub Total | | | | | | | \$1,420,241 | |

Building: Addition 2
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|---|------------------|------|----------|------|------------------|--------------------|
| Canopy | | Metal Canopy | N & E elevations | 6 | 110 | SF | \$2,647 | |
| Doors | | Exterior FRP Door | 1st Floor | 6 | 3 | EA | \$1,671 | |
| Doors | | Exterior Steel Door | 1st Floor | 6 | 1 | EA | \$330 | |
| Foundation | | Concrete Foundation | Entire Building | 7 | 369 | LF | \$0 | |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Roofs | 6 | 7 | EA | \$3,504 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 4 | EA | \$858 | |
| Lintels | | Lintels - Steel | Entire Building | 6 | 597 | LF | \$22,538 | |
| Roof System | | Asphalt Gravel Ballast Roof | Roofs | 4 | 9,036 | SF | \$230,261 | excessive blisters |
| Roof System | | Interior Downspouts | Roofs | 6 | 180 | LF | \$0 | |
| Roof System | | Modified Bitumen Roof | upper roof | 6 | 591 | SF | \$4,183 | |
| Roof System | | Roof Structure: Concrete | Roofs | 7 | 9,627 | SF | \$0 | |
| Superstructure | | Concrete | Entire Building | 7 | 26,152 | SF | \$0 | |
| Walls | | Brick | Entire Building | 6 | 12,753 | SF | \$84,254 | |
| Windows | | Window - Guards perforated | 1st Floor | 6 | 1,092 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 7 | 3,898 | SF | \$0 | |
| EXTERIOR Sub Total | | | | | | | \$350,246 | |

Building: Addition 2
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------|-----------|--|----------------------|------|----------|------|---------|--------|
| Emergency System | | Emergency A/C power - Corridors and Stairs | Corridors and Stairs | 6 | 4,454 | SF | \$1,911 | |

Building: Addition 2
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|----------------------|------|----------|------|------------------|--|
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Lunch Room | 6 | 2,805 | SF | \$1,484 | |
| Emergency System | | Emergency A/C power - Students Toilets | Student Toilets | 6 | 1,721 | SF | \$738 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Corridors and Stairs | 2 | 9 | EA | \$8,366 | Exit signs are more than 20 years old and they are not provided with battery backup and the appearance is poor |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | Lunch Room | 2 | 6 | EA | \$5,577 | Exit signs are more than 20 years old and they are not provided with battery backup and the appearance is poor |
| Emergency System | | Public Announcement System | Entire Building | 6 | 26,152 | SF | \$15,707 | |
| Emergency System | | Security System - CCTV | MDF Room 210 | 4 | 26,152 | SF | \$186,987 | |
| Emergency System | | Security System - Intrusion detection | Entire Building | 6 | 26,152 | SF | \$24,308 | |
| Power Distribution | | Lighting and power panels | Entire Building | 7 | 4 | EA | \$0 | |
| Power Distribution | | Lighting and power panels | Entire Building | 4 | 3 | EA | \$16,302 | |
| ELECTRICAL Sub Total | | | | | | | \$261,380 | |

Building: Addition 2
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|--------------------------|-----------------|------|----------|------|-----------------|--|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 3 | 26,152 | SF | \$55,348 | Strobe lights are not located in all areas |
| Sprinkler System | | Dry Sprinkler System | Entire Building | 6 | 26,152 | SF | \$18,699 | |
| Sprinkler System | | Sprinkler Heads | Entire Building | 6 | 26,152 | SF | \$1,496 | |
| FIRE PROTECTION Sub Total | | | | | | | \$75,543 | |

Building: Addition 2
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|-----------------|------|----------|------|----------|--------|
| Air Conditioning | | Window A/C Unit | Entire Building | 6 | 21 | EA | \$4,505 | |
| Air Handling Systems | | Fan Coil Unit - Hot Water-Heating | Entire Building | 6 | 6 | EA | \$8,065 | |
| Heating Devices | | Wall Heater - Electric | Electrical Room | 6 | 4 | EA | \$412 | |
| Unit Ventilation | | Unit Ventilators - Hot Water-Heating | Entire Building | 6 | 14 | EA | \$20,020 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Lower Roof | 6 | 2 | EA | \$858 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Lower Roof | 6 | 2 | EA | \$458 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 4 | 1 | EA | \$2,288 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 6 | 1 | EA | \$229 | |

Building: Addition 2
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|--|------------|------|----------|------|-----------------|---|
| Ventilation | | Exhaust Fans - Roof mounted less than 500 CFM | Roof | 6 | 1 | EA | \$157 | |
| Ventilation | | Exhaust Fans - Roof mounted less than 500 CFM | Lower Roof | 2 | 1 | EA | \$1,573 | Unit is not working - Bad Motor |
| Ventilation | | Type I Exhaust Hood - Kitchen or Culinary Arts | 1st Floor | 2 | 1 | EA | \$26,884 | Fire suppression does not exist. Kitchen equipment located outside the hood |
| MECHANICAL Sub Total | | | | | | | \$65,448 | |

Building: Addition 2
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|--|-----------------|------|----------|------|-----------------|--------|
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 7 | 26,152 | SF | \$0 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 4 | 26,152 | SF | \$16,829 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 7 | 26,152 | SF | \$0 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 4 | 26,152 | SF | \$11,967 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 4 | 26,152 | SF | \$14,211 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 7 | 26,152 | SF | \$0 | |
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 7 | 26,152 | SF | \$0 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 7 | 26,152 | SF | \$0 | |
| Piping | | Sanitary Piping | Entire Building | 5 | 26,152 | SF | \$16,081 | |
| Piping | | Storm Piping | Entire Building | 5 | 26,152 | SF | \$12,341 | |
| Piping | | Vent Piping | Entire Building | 5 | 26,152 | SF | \$9,349 | |
| PLUMBING Sub Total | | | | | | | \$80,778 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|-----------------------------------|---|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 1st floor Teacher's Lounge | 6 | 173 | SF | \$490 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | 2nd floor Teacher's Lounge | 6 | 173 | SF | \$490 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Plaster/Drywall | Basement #009 & 009A (Former classrooms per plan) | 6 | 795 | SF | \$2,251 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Splined | basement floor inside kitchen | 6 | 158 | SF | \$339 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile Ceramic/Porcelain | basement floor inside kitchen | 6 | 158 | SF | \$402 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|-----------------------------------|---|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 2nd floor Teacher's Lounge | 6 | 173 | SF | \$247 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | 1st floor Teacher's Lounge | 6 | 173 | SF | \$247 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Basement #009 & 009A (Former classrooms per plan) | 6 | 795 | SF | \$1,137 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | basement floor inside kitchen | 6 | 2 | SF | \$1 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | Basement #009 & 009A (Former classrooms per plan) | 6 | 8 | SF | \$6 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 1st floor Teacher's Lounge | 6 | 2 | SF | \$1 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | 2nd floor Teacher's Lounge | 6 | 2 | SF | \$1 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | basement floor inside kitchen | 6 | 518 | SF | \$1,481 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Basement #009 & 009A (Former classrooms per plan) | 6 | 2,233 | SF | \$5,269 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 2nd floor Teacher's Lounge | 6 | 528 | SF | \$1,246 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | 1st floor Teacher's Lounge | 6 | 528 | SF | \$1,246 | |
| Doors | | Interior Steel Doors incl hw | Basement | 6 | 1 | EA | \$283 | |
| Doors | | Interior Wood Doors incl hw | 2nd Floor | 6 | 9 | EA | \$2,548 | |
| Doors | | Interior Wood Doors incl hw | 1st Floor | 6 | 10 | EA | \$2,831 | |
| Doors | | Interior Wood Doors incl hw | Basement | 6 | 22 | EA | \$6,229 | |
| Doors | | Side-lite | Basement | 6 | 20 | SF | \$372 | |
| Drinking Fountains | Corridors | Single Fountain | Basement | 7 | 2 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 2nd Floor | 7 | 2 | EA | \$0 | |
| Drinking Fountains | Corridors | Single Fountain | 1st Floor | 7 | 2 | EA | \$0 | |
| Kitchen | Cooking Kitchen | Ceiling - Plaster/Drywall | Basement | 6 | 972 | SF | \$3,669 | |
| Kitchen | Cooking Kitchen | Flooring - Tile Ceramic/Porcelain | Basement | 6 | 972 | SF | \$2,474 | |
| Kitchen | Cooking Kitchen | Lighting - Pendant/Surface | Basement | 6 | 18 | SF | \$13 | |
| Kitchen | Cooking Kitchen | Wall - Structural Glazed Tile | Basement | 6 | 1,203 | SF | \$8,601 | |
| Lunchroom | Lunchroom | Ceiling - Plaster/Drywall | Lunch Room #2, in Basement(former Pre-K Room) | 7 | 1,048 | SF | \$0 | |
| Lunchroom | Lunchroom | Ceiling - Splined | Basement | 6 | 1,757 | SF | \$3,769 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Basement | 6 | 1,757 | SF | \$2,513 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------------------------|----------------------------|---|------|----------|------|----------|--------|
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Lunch Room #2, in Basement(former Pre-K Room) | 6 | 1,048 | SF | \$1,499 | |
| Lunchroom | Lunchroom | Lighting - Pendant/Surface | Lunch Room #2, in Basement(former Pre-K Room) | 7 | 27 | SF | \$0 | |
| Lunchroom | Lunchroom | Lighting - Pendant/Surface | Basement | 6 | 46 | SF | \$33 | |
| Lunchroom | Cooking Kitchen | Serving Line | Basement | 6 | 25 | LF | \$1,073 | |
| Lunchroom | Lunchroom | Wall - Concrete Block | Basement | 6 | 1,956 | SF | \$5,594 | |
| Lunchroom | Lunchroom | Wall - Concrete Block | Lunch Room #2, in Basement(former Pre-K Room) | 6 | 1,752 | SF | \$5,011 | |
| MDF/IDF | | Finishes | Room 210C | 7 | 70 | SF | \$0 | |
| MDF/IDF | | Ventilation and Cooling | Room 210C | 6 | 1 | EA | \$1,401 | |
| Mechanical/Service Rooms | | Crawl Space - Unfinished | Basement | 6 | 7,490 | SF | \$14,138 | |
| Mechanical/Service Rooms | | Janitor's Closet | Entire Building | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Basement Boy's Room | 6 | 212 | SF | \$1,637 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 81 | SF | \$625 | |
| Staff Restroom | Staff Restroom | Accessories | 1st Floor | 6 | 47 | SF | \$363 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd Floor Girl's Room | 6 | 212 | SF | \$1,637 | |
| Staff Restroom | Staff Restroom | Accessories | Basement | 6 | 47 | SF | \$363 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | In Room 010 | 7 | 25 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Basement Girl's Room | 6 | 212 | SF | \$1,637 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 1st Floor Boy's Room | 6 | 212 | SF | \$1,637 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 2nd Floor Boy's Room | 6 | 212 | SF | \$1,637 | |
| Staff Restroom | Staff Restroom | Accessories | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 81 | SF | \$625 | |
| Staff Restroom | Staff Restroom | Accessories | Room 008B, Women's Room in Basement | 7 | 38 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 1st Floor Girl's Room | 6 | 212 | SF | \$1,637 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 3rd Floor Boy's Room | 6 | 212 | SF | \$1,637 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 3rd Floor Girl's Room | 6 | 212 | SF | \$1,637 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|---------------------------|--|------|----------|------|-------|--------|
| Staff Restroom | Staff Restroom | Accessories | 2nd Floor | 6 | 47 | SF | \$363 | |
| Staff Restroom | Staff Restroom | Accessories | Basement inside Rm 009 | 6 | 43 | SF | \$332 | |
| Staff Restroom | Staff Restroom | Accessories | Room 008A, Unisex Room in Basement | 7 | 38 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Basement Boy's Room | 6 | 212 | SF | \$600 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 3rd Floor Boy's Room | 6 | 212 | SF | \$600 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Basement inside Rm 009 | 6 | 43 | SF | \$122 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Room 008A, Unisex Room in Basement | 7 | 38 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 81 | SF | \$229 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Boy's Room | 6 | 212 | SF | \$600 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 2nd Floor Girl's Room | 6 | 212 | SF | \$600 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Plaster/Drywall | In Room 010 | 7 | 25 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Room 008B, Women's Room in Basement | 7 | 38 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 1st Floor | 7 | 47 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 1st Floor Girl's Room | 6 | 212 | SF | \$600 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 81 | SF | \$229 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 3rd Floor Girl's Room | 6 | 212 | SF | \$600 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | Basement | 7 | 47 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | Basement Girl's Room | 6 | 212 | SF | \$600 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | 2nd Floor | 7 | 47 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Plaster/Drywall | 1st Floor Boy's Room | 6 | 212 | SF | \$600 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Basement Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | Room 008B, Women's Room in Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 3rd Floor Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Basement Girl's Room | 7 | 1 | EA | \$0 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|--|------|----------|------|---------|--------|
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 2nd Floor Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 1st Floor Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 2nd Floor Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | Room 008A, Unisex Room in Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 3rd Floor Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 1st Floor Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 1st Floor Girl's Room | 7 | 212 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 1st Floor | 7 | 47 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Room 008B, Women's Room in Basement | 7 | 38 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor Boy's Room | 7 | 212 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor | 7 | 47 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Basement | 7 | 47 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | In Room 010 | 7 | 25 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement Girl's Room | 7 | 212 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Basement Boy's Room | 7 | 212 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 3rd Floor Boy's Room | 7 | 212 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 3rd Floor Girl's Room | 7 | 212 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 2nd Floor Girl's Room | 7 | 212 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 1st Floor Boy's Room | 7 | 212 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Room 008A, Unisex Room in Basement | 7 | 38 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | Basement inside Rm 009 | 6 | 43 | SF | \$61 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | 2nd floor inside Rm 209A, Teacher's Lounge | 4 | 81 | SF | \$1,147 | |
| Staff Restroom | Staff Restroom | Flooring - Tile/Sheet | 2nd floor inside Rm 209A, Teacher's Lounge | 4 | 81 | SF | \$1,147 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|------------|--|------|----------|------|-------|--------|
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Basement Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | Room 008A, Unisex Room in Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 1st Floor Girl's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 3rd Floor Girl's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Hand Dryer | Room 008B, Women's Room in Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 3rd Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 2nd Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 1st Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 2nd Floor Girl's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | Basement Girl's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 3rd Floor Girl's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 3rd Floor Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Basement Girl's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 1 | EA | \$372 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | In Room 010 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Basement inside Rm 009 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Basement Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 1st Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 1st Floor Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd Floor Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 1st Floor Girl's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 1 | EA | \$372 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------|--|------|----------|------|------|--------|
| Staff Restroom | Staff Restroom | Lavatory | 2nd Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Room 008A, Unisex Room in Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Room 008B, Women's Room in Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 2nd Floor Girl's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | 2nd Floor | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | 1st Floor | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Lay-In | In Room 010 | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Basement inside Rm 009 | 6 | 1 | SF | \$1 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 1 | SF | \$1 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Basement | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 1 | SF | \$1 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Room 008B, Women's Room in Basement | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Pendant/ Surface | Room 008A, Unisex Room in Basement | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 1st Floor Girl's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Boy's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 1st Floor Boy's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 2nd Floor Girl's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Basement Girl's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 3rd Floor Boy's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | 3rd Floor Girl's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Pendant/ Surface | Basement Boy's Room | 7 | 3 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | 2nd Floor | 6 | 1 | EA | \$29 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | Basement inside Rm 009 | 6 | 1 | EA | \$29 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | Basement | 6 | 1 | EA | \$29 | |
| Staff Restroom | Staff Restroom | Lighting - Wall Mounted | 1st Floor | 6 | 1 | EA | \$29 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|------------------------|--|------|----------|------|-------|--------|
| Staff Restroom | Staff Restroom | Partitions | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 1 | EA | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 3rd Floor Girl's Room | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 3rd Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Basement Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Basement Girl's Room | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Partitions | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 1 | EA | \$179 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd Floor Girl's Room | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 1st Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 2nd Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 1st Floor Girl's Room | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 3rd Floor Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Basement Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Urinals | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 1st Floor Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 2nd Floor Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | Basement inside Rm 009 | 6 | 225 | SF | \$644 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | Basement | 7 | 193 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 308 | SF | \$881 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Concrete Block | In Room 010 | 7 | 43 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 308 | SF | \$881 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 1st Floor | 7 | 193 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 2nd Floor | 7 | 193 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Room 008B, Women's Room in Basement | 7 | 50 | SF | \$0 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------------------------|--|------|----------|------|-------|--------|
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Room 008A, Unisex Room in Basement | 7 | 50 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Structural Glazed Tile | In Room 010 | 7 | 43 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Boy's Room | 7 | 475 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 1st Floor Boy's Room | 7 | 475 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | Room 008B, Women's Room in Basement | 7 | 151 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 2nd Floor Girl's Room | 7 | 475 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Basement Girl's Room | 7 | 475 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | Basement Boy's Room | 7 | 475 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 3rd Floor Boy's Room | 7 | 475 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 3rd Floor Girl's Room | 7 | 475 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Structural Glazed Tile | Room 008A, Unisex Room in Basement | 7 | 151 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Structural Glazed Tile | 1st Floor Girl's Room | 7 | 475 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Basement Girl's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Basement Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 3rd Floor Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Room 008A, Unisex Room in Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 1 | EA | \$372 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | In Room 010 | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 3rd Floor Girl's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 1st Floor Boy's Room | 7 | 2 | EA | \$0 | |

Building: Addition 2
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|--------------------------------------|--------------|--|------|----------|------|------------------|--------|
| Staff Restroom | Staff Restroom | Water Closet | 2nd floor inside Rm 209A, Teacher's Lounge | 6 | 1 | EA | \$372 | |
| Staff Restroom | Staff Restroom | Water Closet | Room 008B, Women's Room in Basement | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 2nd Floor Girl's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Basement inside Rm 009 | 6 | 1 | EA | \$372 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 1st Floor Girl's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 1st Floor | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 2nd Floor | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 6 | 1 | EA | \$386 | |
| INTERIOR Sub Total | | | | | | | \$106,281 | |

Building: Addition 2
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|-----------------|----------|------|----------|------|---------|--------|
| Casework | Classroom | Casework | | 7 | 36 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 60 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 6 | LF | \$215 | |
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Casework | Classroom | Casework | | 7 | 30 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 8 | LF | \$286 | |
| Casework | Classroom | Casework | | 7 | 30 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 30 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 6 | 20 | LF | \$715 | |
| Casework | Classroom | Casework | | 7 | 30 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 30 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 738 | SF | \$2,090 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 786 | SF | \$2,225 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 738 | SF | \$2,090 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 806 | SF | \$2,282 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 738 | SF | \$2,090 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 738 | SF | \$2,090 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 368 | SF | \$1,042 | |

Building: Addition 2
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|------------------------|----------------------------|------|----------|------|----------|--------|
| Ceiling | Classroom | Plaster/Drywall | | 6 | 738 | SF | \$2,090 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 738 | SF | \$2,090 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 738 | SF | \$2,090 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 738 | SF | \$2,090 | |
| Ceiling | Classroom | Plaster/Drywall | | 7 | 1,103 | SF | \$0 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 806 | SF | \$2,282 | |
| Ceiling | Classroom | Plaster/Drywall | | 6 | 724 | SF | \$2,050 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 18 | LF | \$2,188 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 24 | LF | \$2,917 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 40 | LF | \$4,862 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 20 | LF | \$2,431 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 24 | LF | \$2,917 | |
| Corridors | Corridors | Concrete Block | Entire building stairwells | 6 | 4,226 | SF | \$12,086 | |
| Corridors | Corridors | Concrete Block | 1st Floor | 7 | 1,025 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | 2nd Floor | 7 | 1,025 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | Basement | 7 | 1,025 | SF | \$0 | |
| Corridors | Corridors | Lay-In | Entire building stairwells | 6 | 1,247 | EA | \$892 | |
| Corridors | Corridors | Lay-In | 2nd Floor | 7 | 1,280 | EA | \$0 | |
| Corridors | Corridors | Lay-In | 1st Floor | 7 | 1,280 | EA | \$0 | |
| Corridors | Corridors | Lay-In | Basement | 7 | 1,280 | EA | \$0 | |
| Corridors | Corridors | Stair Handrails | Entire building stairwells | 6 | 312 | LF | \$0 | |
| Corridors | Corridors | Structural Glazed Tile | Basement | 7 | 1,025 | SF | \$0 | |
| Corridors | Corridors | Structural Glazed Tile | 1st Floor | 7 | 1,025 | SF | \$0 | |
| Corridors | Corridors | Structural Glazed Tile | Entire building stairwells | 6 | 4,226 | SF | \$30,216 | |
| Corridors | Corridors | Structural Glazed Tile | 2nd Floor | 7 | 1,025 | SF | \$0 | |
| Corridors | Corridors | Terrazzo | Entire building stairwells | 6 | 1,105 | SF | \$6,257 | |
| Corridors | Corridors | Tile/Sheet Flooring | Basement | 7 | 1,280 | SF | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | 2nd Floor | 7 | 1,280 | SF | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | 1st Floor | 7 | 1,280 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | 2nd Floor | 7 | 1,280 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Basement | 7 | 1,280 | SF | \$0 | |

Building: Addition 2
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|-----------------|----------------------------|------|----------|------|----------|--------|
| Corridors Ceiling | Corridors | Plaster/Drywall | 1st Floor | 7 | 1,280 | SF | \$0 | |
| Corridors Ceiling | Corridors | Plaster/Drywall | Entire building stairwells | 6 | 1,247 | SF | \$3,531 | |
| Stairs | Corridors | Terrazzo | Entire building stairwells | 6 | 146 | SF | \$1,654 | |
| Floor | Classroom | Tile/Sheet | | 6 | 724 | SF | \$1,035 | |
| Floor | Classroom | Tile/Sheet | | 6 | 806 | SF | \$1,153 | |
| Floor | Classroom | Tile/Sheet | | 4 | 786 | SF | \$11,127 | |
| Floor | Classroom | Tile/Sheet | | 4 | 806 | SF | \$11,411 | |
| Floor | Classroom | Tile/Sheet | | 4 | 738 | SF | \$10,448 | |
| Floor | Classroom | Tile/Sheet | | 4 | 738 | SF | \$10,448 | |
| Floor | Classroom | Tile/Sheet | | 6 | 1,103 | SF | \$1,577 | |
| Floor | Classroom | Tile/Sheet | | 4 | 738 | SF | \$10,448 | |
| Floor | Classroom | Tile/Sheet | | 6 | 738 | SF | \$1,055 | |
| Floor | Classroom | Tile/Sheet | | 4 | 738 | SF | \$10,448 | |
| Floor | Classroom | Tile/Sheet | | 4 | 738 | SF | \$10,448 | |
| Floor | Classroom | Tile/Sheet | | 4 | 738 | SF | \$10,448 | |
| Floor | Classroom | Tile/Sheet | | 4 | 738 | SF | \$10,448 | |
| Floor | Classroom | Tile/Sheet | | 4 | 738 | SF | \$10,448 | |
| Floor | Classroom | Tile/Sheet | | 6 | 368 | SF | \$526 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 18 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 18 | EA | \$1,287 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 25 | EA | \$0 | |
| Lighting | Classroom | Pendant/Surface | | 6 | 10 | EA | \$715 | |
| Lighting | Classroom | Pendant/Surface | | 7 | 14 | EA | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 12 | LF | \$343 | |

Building: Addition 2
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|----------------|----------|------|----------|------|------------------|--------|
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 20 | LF | \$572 | |
| Marker Board | Classroom | Marker Board | | 7 | 18 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 1,252 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 6 | 875 | SF | \$2,503 | |
| Wall | Classroom | Concrete Block | | 6 | 875 | SF | \$2,503 | |
| Wall | Classroom | Concrete Block | | 6 | 875 | SF | \$2,503 | |
| Wall | Classroom | Concrete Block | | 6 | 875 | SF | \$2,503 | |
| Wall | Classroom | Concrete Block | | 6 | 887 | SF | \$2,537 | |
| Wall | Classroom | Concrete Block | | 6 | 875 | SF | \$2,503 | |
| Wall | Classroom | Concrete Block | | 6 | 875 | SF | \$2,503 | |
| Wall | Classroom | Concrete Block | | 6 | 887 | SF | \$2,537 | |
| Wall | Classroom | Concrete Block | | 6 | 855 | SF | \$2,445 | |
| Wall | Classroom | Concrete Block | | 6 | 897 | SF | \$2,565 | |
| Wall | Classroom | Concrete Block | | 6 | 875 | SF | \$2,503 | |
| Wall | Classroom | Concrete Block | | 6 | 758 | SF | \$2,168 | |
| Wall | Classroom | Concrete Block | | 6 | 875 | SF | \$2,503 | |
| ROOM Sub Total | | | | | | | \$250,726 | |

Building Addition 2 Sub Total \$1,190,402

Building: Annex
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|---|-----------------|------|----------|------|-----------|--------------------------------------|
| Doors | | Exterior FRP Door | 1st Floor | 6 | 8 | EA | \$4,455 | |
| Entrance | | Entrance Controls - Audio and Video | 1st Floor | 6 | 1 | EA | \$1,430 | |
| Foundation | | Concrete Foundation | Entire Building | 7 | 867 | LF | \$0 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 8 | EA | \$1,716 | |
| Roof System | | Asphalt Gravel Ballast Roof | Roofs | 4 | 22,866 | SF | \$582,685 | excessive blisters |
| Roof System | | Interior Downspouts | Roofs | 5 | 230 | LF | \$24,668 | missing covers and vegetative growth |
| Roof System | | Roof Structure: Steel/Metal Deck/Concrete Topping | Roofs | 7 | 22,866 | SF | \$0 | |
| Superstructure | | Steel | Entire Building | 7 | 22,866 | SF | \$0 | |
| Walls | | Prefabricated Metal Panel Wall | Entire Building | 6 | 11,119 | SF | \$94,447 | |

Building: Annex
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-------------------------------------|-------------------|------|----------|------|------------------|----------------|
| Walls | | Prefabricated Metal Panel Wall | S & SE elevations | 5 | 585 | SF | \$16,731 | holes |
| Windows | | Curtain wall - Louver | Entire Building | 6 | 418 | SF | \$3,945 | |
| Windows | | Window - Guards perforated | South Façade | 5 | 46 | SF | \$1,160 | repair screens |
| Windows | | Window - Guards perforated | Entire Building | 6 | 2,576 | SF | \$0 | |
| Windows | | Windows - Sash Aluminum Double-pane | Entire Building | 7 | 2,622 | SF | \$0 | |
| EXTERIOR Sub Total | | | | | | | \$731,237 | |

Building: Annex
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|----------------------|------|----------|------|------------------|--|
| Emergency System | | Automatic Transfer switch | Electrical Room | 2 | 1 | EA | \$8,866 | ATS does not work - Electrical Failure at Operator |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Corridors and Stairs | 6 | 4,447 | SF | \$1,908 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Lunchroom | 6 | 747 | SF | \$395 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Corridors and Stairs | 3 | 5 | EA | \$4,648 | Exit signs are more than 20 years old and they are not provided with battery backup and the appearance is poor |
| Emergency System | | Independent Electrical Service for emergency power | Entire Building | 5 | 1 | EA | \$5,005 | |
| Emergency System | | Public Announcement System | Entire Building | 4 | 22,866 | SF | \$81,092 | |
| Emergency System | | Security System - Intrusion detection | IDF Room | 6 | 22,866 | SF | \$21,254 | |
| Main Service | | Main Electrical service - Live Front - 1500 A 120/208/3PH | Electrical Room | 3 | 1 | EA | \$130,416 | Switch gear is live front and significantly deteriorated. |
| Power Distribution | | Lighting and power panels | Entire Building | 4 | 5 | EA | \$27,170 | |
| Power Distribution | | Main distribution panels above 600 amp | Electrical Room | 3 | 3 | EA | \$55,770 | Panel is a part of the live front |
| ELECTRICAL Sub Total | | | | | | | \$336,523 | |

Building: Annex
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------|-----------|--|-----------------|------|----------|------|-----------|--------|
| Heating Devices | | Wall Heater - Electric | Entire Building | 6 | 4 | EA | \$412 | |
| Unit Ventilation | | Packaged Terminal Air Conditioner (PTAC) | Main Office | 6 | 2 | EA | \$2,860 | |
| Unit Ventilation | | Unit Ventilators - Electric | Entire Building | 4 | 21 | EA | \$294,294 | |
| Ventilation | | Exhaust Fans - Roof Mounted 500 to 1,500 cfm | Roof | 5 | 2 | EA | \$2,574 | |

Building: Annex
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|------|----------|------|----------|------|------------------|--------|
| MECHANICAL Sub Total | | | | | | | \$300,140 | |

Building: Annex
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|---|-----------------|------|----------|------|------------------|--------|
| | | Hot Water Heater - Electric less than 50 KW | Mechanical Room | 5 | 1 | EA | \$5,606 | |
| | | Domestic Piping Cold Water Horizontal lines | Entire Building | 4 | 22,866 | SF | \$54,606 | |
| | | Domestic Piping Hot Water Horizontal lines | Entire Building | 4 | 22,866 | SF | \$45,124 | |
| | | Sanitary Piping | Entire Building | 5 | 22,866 | SF | \$14,060 | |
| | | Storm Piping | Entire Building | 5 | 22,866 | SF | \$10,790 | |
| | | Vent Piping | Entire Building | 5 | 22,866 | SF | \$8,175 | |
| PLUMBING Sub Total | | | | | | | \$138,361 | |

Building: Annex
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|-------------------------|--------------------|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Main Office | 6 | 319 | SF | \$684 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Principal's Office | 7 | 147 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Teacher's Lounge | 6 | 170 | SF | \$365 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Principal's Office | 6 | 147 | SF | \$210 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Teacher's Lounge | 6 | 170 | SF | \$243 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Main Office | 6 | 319 | SF | \$456 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Principal's Office | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Main Office | 7 | 10 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Teacher's Lounge | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Principal's Office | 6 | 388 | SF | \$915 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Main Office | 6 | 598 | SF | \$1,411 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | Teacher's Lounge | 6 | 406 | SF | \$958 | |

Building: Annex
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------------------------|------------------------------|-----------------------|------|----------|------|----------|--------|
| Doors | | Interior Steel Doors incl hw | 1st Floor | 6 | 32 | EA | \$9,060 | |
| Drinking Fountains | Corridors | Single Fountain | 1st Floor | 7 | 4 | EA | \$0 | |
| Kitchen | Cooking Kitchen | Ceiling - Lay-In | 1st Floor | 6 | 683 | SF | \$1,953 | |
| Kitchen | Cooking Kitchen | Flooring - Tile/Sheet | 1st Floor | 5 | 683 | SF | \$3,868 | |
| Kitchen | Cooking Kitchen | Lighting - Lay-In | 1st Floor | 7 | 10 | SF | \$0 | |
| Kitchen | Cooking Kitchen | Wall - Plaster/Drywall | 1st Floor | 6 | 830 | SF | \$1,958 | |
| Lunchroom | Lunchroom | Ceiling - Lay-In | Room 403 | 6 | 747 | SF | \$1,602 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | Room 403 | 6 | 747 | SF | \$1,068 | |
| Lunchroom | Lunchroom | Lighting - Lay-In | Room 403 | 7 | 10 | SF | \$0 | |
| Lunchroom | Cooking Kitchen | Serving Line | 1st Floor | 7 | 24 | LF | \$0 | |
| Lunchroom | Lunchroom | Wall - Plaster/Drywall | Room 403 | 6 | 869 | SF | \$2,050 | |
| MDF/IDF | | Finishes | 1st Floor | 6 | 175 | SF | \$596 | |
| MDF/IDF | | Ventilation and Cooling | 1st Floor | 4 | 1 | EA | \$14,014 | |
| Mechanical/Service Rooms | | Janitor's Closet | 1st Floor | 6 | 2 | SF | \$9 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | 1st Floor | 6 | 133 | SF | \$628 | |
| Mechanical/Service Rooms | | Storage Room | 1st Floor | 7 | 39 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Northeast Boy's Room | 6 | 264 | SF | \$2,039 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Southeast Boy's Room | 6 | 264 | SF | \$2,039 | |
| Staff Restroom | Staff Restroom | Accessories | Men's Room | 6 | 62 | SF | \$479 | |
| Staff Restroom | Staff Restroom | Accessories | Women's Room | 6 | 55 | SF | \$425 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Southeast Girl's Room | 6 | 264 | SF | \$2,039 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | Northeast Girl's Room | 6 | 264 | SF | \$2,039 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Southeast Girl's Room | 6 | 264 | SF | \$566 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | Women's Room | 6 | 55 | SF | \$118 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Northeast Girl's Room | 6 | 264 | SF | \$566 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Southeast Boy's Room | 6 | 264 | SF | \$566 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | Northeast Boy's Room | 6 | 264 | SF | \$566 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | Men's Room | 7 | 62 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Southeast Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Northeast Girl's Room | 7 | 1 | EA | \$0 | |

Building: Annex
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|-----------------------|------|----------|------|-------|--------|
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Southeast Girl's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | Northeast Boy's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Southeast Girl's Room | 6 | 264 | SF | \$672 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Northeast Girl's Room | 6 | 264 | SF | \$672 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Men's Room | 7 | 62 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Southeast Boy's Room | 6 | 264 | SF | \$672 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | Northeast Boy's Room | 6 | 264 | SF | \$672 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | Women's Room | 6 | 55 | SF | \$140 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Northeast Girl's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Southeast Girl's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | Men's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Northeast Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | Southeast Boy's Room | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Southeast Boy's Room | 7 | 2 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Men's Room | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Northeast Girl's Room | 7 | 2 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | Women's Room | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Northeast Boy's Room | 7 | 2 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | Southeast Girl's Room | 7 | 2 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Southeast Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Southeast Girl's Room | 7 | 6 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Northeast Girl's Room | 7 | 6 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | Northeast Boy's Room | 7 | 2 | EA | \$0 | |

Building: Annex
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|--------------------------------------|------------------------|-----------------------|------|----------|------|-----------------|--------|
| Staff Restroom | Children's Standard Student Restroom | Urinals | Southeast Boy's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | Northeast Boy's Room | 7 | 5 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Southeast Boy's Room | 6 | 547 | SF | \$1,291 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Northeast Boy's Room | 6 | 547 | SF | \$1,291 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Northeast Girl's Room | 6 | 547 | SF | \$1,291 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Plaster/Drywall | Southeast Girl's Room | 6 | 547 | SF | \$1,291 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Women's Room | 6 | 243 | SF | \$573 | |
| Staff Restroom | Staff Restroom | Wall - Plaster/Drywall | Men's Room | 6 | 259 | SF | \$611 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Northeast Girl's Room | 7 | 7 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Southeast Girl's Room | 7 | 7 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Northeast Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | Southeast Boy's Room | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Women's Room | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | Men's Room | 7 | 1 | EA | \$0 | |
| INTERIOR Sub Total | | | | | | | \$62,666 | |

Building: Annex
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|----------|----------|------|----------|------|-------|--------|
| Casework | Classroom | Casework | | 7 | 12 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Casework | Classroom | Casework | | 6 | 12 | LF | \$429 | |
| Casework | Classroom | Casework | | 7 | 12 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 12 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 12 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Casework | Classroom | Casework | | 6 | 12 | LF | \$429 | |
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Casework | Classroom | Casework | | 6 | 10 | LF | \$358 | |

Building: Annex
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------|-----------|---------------------|-----------|------|----------|------|----------|--------|
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Casework | Classroom | Casework | | 6 | 12 | LF | \$429 | |
| Casework | Classroom | Casework | | 7 | 12 | LF | \$0 | |
| Casework | Classroom | Casework | | 6 | 5 | LF | \$179 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 792 | SF | \$1,699 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 763 | SF | \$1,637 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 731 | SF | \$1,568 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 775 | SF | \$1,662 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 838 | SF | \$1,798 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 765 | SF | \$1,641 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 731 | SF | \$1,568 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 838 | SF | \$1,798 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 705 | SF | \$1,512 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 792 | SF | \$1,699 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 792 | SF | \$1,699 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 731 | SF | \$1,568 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 763 | SF | \$1,637 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 763 | SF | \$1,637 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 763 | SF | \$1,637 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 763 | SF | \$1,637 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 763 | SF | \$1,637 | |
| Ceiling | Classroom | Lay-In/Drop | | 6 | 838 | SF | \$1,798 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Chalk Board | Classroom | Chalk Board | | 4 | 12 | LF | \$1,459 | |
| Corridors | Corridors | Drop/Lay-In | 1st Floor | 6 | 4,447 | SF | \$9,539 | |
| Corridors | Corridors | Lay-In | 1st Floor | 7 | 4,447 | EA | \$0 | |
| Corridors | Corridors | Metal Panel | 1st Floor | 6 | 7,665 | SF | \$65,108 | |
| Corridors | Corridors | Tile/Sheet Flooring | 1st Floor | 6 | 4,447 | SF | \$6,359 | |
| Floor | Classroom | Tile/Sheet | | 6 | 838 | SF | \$1,198 | |
| Floor | Classroom | Tile/Sheet | | 6 | 838 | SF | \$1,198 | |
| Floor | Classroom | Tile/Sheet | | 6 | 763 | SF | \$1,091 | |
| Floor | Classroom | Tile/Sheet | | 6 | 763 | SF | \$1,091 | |
| Floor | Classroom | Tile/Sheet | | 6 | 763 | SF | \$1,091 | |
| Floor | Classroom | Tile/Sheet | | 6 | 763 | SF | \$1,091 | |

Building: Annex
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|--------------|----------|------|----------|------|---------|--------|
| Floor | Classroom | Tile/Sheet | | 6 | 763 | SF | \$1,091 | |
| Floor | Classroom | Tile/Sheet | | 6 | 765 | SF | \$1,094 | |
| Floor | Classroom | Tile/Sheet | | 6 | 838 | SF | \$1,198 | |
| Floor | Classroom | Tile/Sheet | | 6 | 792 | SF | \$1,133 | |
| Floor | Classroom | Tile/Sheet | | 6 | 731 | SF | \$1,045 | |
| Floor | Classroom | Tile/Sheet | | 6 | 705 | SF | \$1,008 | |
| Floor | Classroom | Tile/Sheet | | 6 | 792 | SF | \$1,133 | |
| Floor | Classroom | Tile/Sheet | | 6 | 792 | SF | \$1,133 | |
| Floor | Classroom | Tile/Sheet | | 6 | 731 | SF | \$1,045 | |
| Floor | Classroom | Tile/Sheet | | 6 | 731 | SF | \$1,045 | |
| Floor | Classroom | Tile/Sheet | | 6 | 775 | SF | \$1,108 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 6 | 10 | EA | \$715 | |
| Lighting | Classroom | Lay-In | | 6 | 10 | EA | \$715 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 6 | 10 | EA | \$715 | |
| Lighting | Classroom | Lay-In | | 6 | 10 | EA | \$715 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Lighting | Classroom | Lay-In | | 7 | 10 | EA | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |

Building: Annex
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------------|-----------|---------------------|----------|------|----------|------|--------------------|--------|
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 6 | 16 | LF | \$458 | |
| Marker Board | Classroom | Marker Board | | 7 | 12 | LF | \$0 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 819 | SF | \$1,932 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 882 | SF | \$2,081 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 896 | SF | \$2,114 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 896 | SF | \$2,114 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 882 | SF | \$2,081 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 819 | SF | \$1,932 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 879 | SF | \$2,074 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 819 | SF | \$1,932 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 882 | SF | \$2,081 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 882 | SF | \$2,081 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 819 | SF | \$1,932 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 882 | SF | \$2,081 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 882 | SF | \$2,081 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 819 | SF | \$1,932 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 882 | SF | \$2,081 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 882 | SF | \$2,081 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 896 | SF | \$2,114 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 882 | SF | \$2,081 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 882 | SF | \$2,081 | |
| Wall | Classroom | Metal/Folding Panel | | 6 | 794 | SF | \$1,873 | |
| ROOM Sub Total | | | | | | | \$179,921 | |
| Building Annex Sub Total | | | | | | | \$1,748,848 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|-----------|-----------------|-----------------|------|----------|------|----------|--------|
| Civil/Drainage | | Catch Basin | Entire Site | 7 | 2 | EA | \$0 | |
| Civil/Drainage | | Site Manhole | Entire Site | 7 | 8 | EA | \$0 | |
| Fencing | | Chain Link | annex courtyard | 6 | 45 | LF | \$645 | |
| Fencing | | Ornamental Iron | Entire Site | 6 | 1,786 | LF | \$33,713 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|---|-----------------------|------|----------|------|------------------|---------------|
| Landscape | | Asphalt Play Area/Hardscape | Entire Site | 6 | 26,996 | SF | \$23,163 | |
| Landscape | | Benches | Site ζ North | 5 | 1 | EA | \$779 | |
| Landscape | | Benches | Site ζ South | 7 | 1 | EA | \$0 | |
| Landscape | | Grass | Entire Site | 6 | 7,524 | SF | \$3,013 | |
| Landscape | | Hardscape - Concrete | entrance 4 | 4 | 591 | SF | \$11,156 | |
| Landscape | | Parkway trees | Entire Site | 7 | 32 | EA | \$0 | |
| Landscape | | Planting Beds/ Areas | Entire Site | 6 | 6,406 | SF | \$0 | |
| Landscape | | Trash Receptacles | Entire Site | 7 | 2 | EA | \$0 | |
| Parking Lot | | Asphalt | S parking lot | 5 | 1,804 | SF | \$5,108 | |
| Parking Lot | | Asphalt | W parking lot | 6 | 19,571 | SF | \$16,792 | |
| Parking Lot | | Concrete | driveway | 6 | 3,254 | SF | \$0 | |
| Parking Lot | | Trash Enclosure | Annex W alley | 5 | 225 | SF | \$4,826 | missing gates |
| Parking Lot | | Trash Enclosure | Parking Lot | 6 | 360 | SF | \$3,861 | |
| Playground | | Playground - Swingset | Playground | 5 | 1 | EA | \$0 | |
| Playground | | Playground Equipment - Pre-K 3-5 | Playground | 5 | 1 | EA | \$0 | broken slide |
| Playground | | Playground Equipment - School Age 5-12 | Playground | 6 | 1 | EA | \$0 | |
| Playground | | Playground Surfacing - Square Rubber Mats | Playground | 4 | 4,572 | SF | \$101,338 | |
| Sidewalks | | Internal Walks | Annex door 9 & door 3 | 5 | 42 | LF | \$1,308 | |
| Sidewalks | | Internal Walks | doors 1 & 2 | 7 | 70 | LF | \$0 | |
| Sidewalks | | Internal Walks | Entire Site | 6 | 75 | LF | \$708 | |
| Sidewalks | | Perimeter Sidewalks | Entire Site | 6 | 16,750 | SF | \$31,617 | |
| Sidewalks | | Perimeter Sidewalks | Site - East | 5 | 300 | SF | \$1,870 | |
| Signage | | Flag Pole | East Façade | 7 | 1 | EA | \$0 | |
| Signage | | Marquee - Free Standing Back Lighted w/ LED | SE site | 7 | 1 | EA | \$0 | |
| SITE Sub Total | | | | | | | \$239,897 | |
| SITE Sub Total | | | | | | | \$239,897 | |

Building: SITE

Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--|-----------|------|----------|------|----------|------|--------------------|--------|
| Total Campus Need ² ³ | | | | | | | \$6,254,287 | |

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-----------------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|----------------|----------------------------------|
| Building: Main | | | | | | | | | | | | | | |
| 101 | 1091 | 1 | 10 | 25 | 40 | 150 | 75 | | N | Y | Y | Classroom | | |
| 102 | 862 | 2 | 10 | 12 | 40 | 160 | 80 | 0 | N | N | Y | Classroom | | |
| 103 | 1091 | 1 | 10 | 25 | 40 | 150 | 75 | | N | Y | Y | Classroom | | |
| 201 | 878 | 2 | 25 | 50 | 40 | 120 | 60 | 2 | N | Y | Y | Classroom | | |
| 202 | 880 | 0 | 28 | 50 | 40 | 160 | 80 | 2 | N | N | N | Classroom | | |
| 203 | 878 | 2 | 25 | 50 | 40 | 120 | 60 | 2 | N | Y | Y | Classroom | | |
| 204 | 880 | 0 | 14 | 20 | 40 | 160 | 80 | 0 | N | N | N | Classroom | | |
| 301 | 1091 | 1 | 10 | 25 | 40 | 150 | 75 | | N | Y | Y | Classroom | | |
| 302 | 880 | 0 | 6 | 14 | 40 | 160 | 80 | 0 | N | N | Y | Classroom | | |
| 303 | 1091 | 1 | 20 | 40 | 40 | 150 | 75 | | N | Y | Y | Classroom | | |
| 304 | 1342 | 1 | 16 | 38 | 40 | 280 | 140 | 0 | N | N | Y | Classroom | | |
| Other | 211 | | | 6 | | | | | N | N | N | Administrative Suites/Offices | | Principals' Office |
| Other | 1103 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 1103 | | | | | | | | N | N | N | Corridors | | Basement |
| Other | 906 | | | | | | | | N | N | N | Corridors | | Entire building stairwells |
| Other | 175 | | | 8 | | | | | N | N | Y | Administrative Suites/Offices | | Basement east of boiler room |
| Other | 16 | | | | | | | | N | N | N | Restroom | Staff Restroom | Sub-Basement east of boiler room |
| Other | 36 | | | | | | | | N | N | N | Restroom | Staff Restroom | In the Main Office Area |
| Other | 865 | | | 12 | | | | | N | N | Y | Administrative Suites/Offices | | Assistant Principals Office |
| Other | 1103 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | 490 | | | 8 | | | | | N | N | Y | Administrative Suites/Offices | | Main Office |
| Other | 1103 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 142 | | | | | | | | N | N | N | Restroom | Staff Restroom | 1st Floor |
| Other | 210 | | | 4 | | | | | N | N | N | Administrative Suites/Offices | | Staff Lounge in Room 102A |

Building: Addition 1

| | | | | | | | | | | | | | | |
|-----|-----|---|----|----|----|-----|----|---|---|---|---|-----------|--|--|
| 106 | 722 | 1 | 12 | 18 | 50 | 144 | 72 | 0 | N | N | Y | Classroom | | |
| 108 | 722 | 1 | 24 | 40 | 40 | 96 | 48 | | N | Y | Y | Classroom | | |
| 205 | 721 | 0 | 8 | 26 | 40 | 120 | 60 | | N | N | Y | Classroom | | |
| 206 | 724 | 0 | 8 | 12 | 40 | 160 | 80 | 0 | N | N | N | Classroom | | |
| 207 | 721 | 0 | 8 | 26 | 40 | 120 | 60 | | N | N | Y | Classroom | | |
| 208 | 724 | 0 | 6 | 12 | 40 | 160 | 80 | 0 | N | N | N | Classroom | | |
| 300 | | | | | | | | | N | N | N | Classroom | | |
| 305 | 739 | 0 | 8 | 26 | 40 | 120 | 60 | | N | N | Y | Classroom | | |
| 306 | 724 | 0 | 4 | 12 | 40 | 160 | 80 | 0 | N | N | N | Classroom | | |
| 307 | 721 | 0 | 8 | 26 | 40 | 120 | 60 | | N | N | Y | Classroom | | |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|--|
| 308 | 724 | 0 | 8 | 22 | 40 | 160 | 80 | 0 | N | N | N | Classroom | | |
| Other | 1959 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 1959 | | | | | | | | N | N | N | Corridors | | Basement |
| Other | 2976 | | | | | | | | N | N | N | Gymnasia | Standard Dedicated Gymnasium | 3rd Floor |
| Other | 701 | | | 10 | | | | | N | N | N | Administrative Suites/Offices | | Gym Teacher's Office |
| Other | 586 | | | 12 | | | | | N | N | Y | Administrative Suites/Offices | | 1st floor offices #105 & 107A |
| Other | 1959 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 1959 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | 373 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd Floor Girl's Room |
| Other | 346 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd floor Boy's Room |
| Other | 2502 | | | | | | | | N | N | N | Auditorium & Theater | Theater | 1st Floor |
| Other | 103 | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | Men's Room in the Lobby of the Auditorium |
| Other | 103 | | | 6 | | | | | N | N | N | Administrative Suites/Offices | | Office is former Women's Room next to Auditorium |
| Other | 434 | | | 14 | | | | | N | N | N | Administrative Suites/Offices | | Faculty Lounge in Basement |
| Other | 879 | | | 12 | | | | | N | N | Y | Administrative Suites/Offices | | 1st floor NE room #107 |
| Other | | | | | | | | | N | N | N | Restroom | Adult Standard Student Restroom | women's restroom in auditorium foyer |
| Other | 210 | | | | | | | | N | N | N | Corridors | | Entire building stairwells |

Building: Addition 2

| | | | | | | | | | | | | | | |
|-------|------|---|----|-----|----|-----|-----|---|---|---|---|-----------|----------------|--|
| 010 | 1103 | 1 | 6 | 18 | 50 | 288 | 144 | 0 | N | N | Y | Classroom | | |
| 011 | 368 | 1 | 8 | 16 | 40 | 80 | 40 | | N | N | Y | Classroom | | |
| 109 | 786 | 1 | 6 | 18 | 40 | 160 | 80 | 2 | N | N | Y | Classroom | | |
| 110 | 738 | 1 | 6 | 18 | 50 | 144 | 72 | 2 | N | N | Y | Classroom | | |
| 111 | 806 | 1 | 6 | 18 | 40 | 160 | 80 | 2 | N | N | Y | Classroom | | |
| 112 | 738 | 1 | 6 | 18 | 50 | 144 | 72 | 2 | N | N | Y | Classroom | | |
| 113 | 738 | 1 | 6 | 18 | 40 | 160 | 80 | 2 | N | N | Y | Classroom | | |
| 114 | 738 | 1 | 6 | 18 | 50 | 144 | 72 | 2 | N | N | Y | Classroom | | |
| 209 | 724 | 1 | 6 | 18 | 40 | 160 | 80 | 2 | N | N | Y | Classroom | | |
| 210 | 738 | 0 | 12 | 20 | 50 | 144 | 72 | 2 | N | N | Y | Classroom | | |
| 211 | 806 | 1 | 6 | 18 | 40 | 160 | 80 | 2 | N | N | Y | Classroom | | |
| 212 | 738 | 1 | 30 | 114 | 50 | 144 | 72 | 2 | N | N | Y | Classroom | | |
| 213 | 738 | 1 | 6 | 18 | 40 | 160 | 80 | 2 | N | N | Y | Classroom | | |
| 214 | 738 | 1 | 6 | 18 | 50 | 144 | 72 | 2 | N | N | Y | Classroom | | |
| Other | 614 | | | | | | | | N | N | N | Corridors | | Entire building stairwells |
| Other | 81 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd floor inside Rm 209A, Teacher's Lounge |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|---|
| Other | 1280 | | | | | | | | N | N | N | Corridors | | Basement |
| Other | 1280 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 212 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 3rd Floor Girl's Room |
| Other | 212 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 3rd Floor Boy's Room |
| Other | 173 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | 2nd floor Teacher's Lounge |
| Other | 212 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Basement Boy's Room |
| Other | 212 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Basement Girl's Room |
| Other | 173 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | 1st floor Teacher's Lounge |
| Other | 25 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | In Room 010 |
| Other | 81 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd floor inside Rm 209A, Teacher's Lounge |
| Other | 38 | | | | | | | | N | N | N | Restroom | Staff Restroom | Room 008A, Unisex Room in Basement |
| Other | 38 | | | | | | | | N | N | N | Restroom | Staff Restroom | Room 008B, Women's Room in Basement |
| Other | 1048 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Lunch Room #2, in Basement(former Pre-K Room) |
| Other | 212 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd Floor Boy's Room |
| Other | 47 | | | | | | | | N | N | N | Restroom | Staff Restroom | 2nd Floor |
| Other | 212 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 1st Floor Girl's Room |
| Other | 43 | | | | | | | | N | N | N | Restroom | Staff Restroom | Basement inside Rm 009 |
| Other | 212 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 2nd Floor Girl's Room |
| Other | 212 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 1st Floor Boy's Room |
| Other | 1280 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 795 | | | 12 | | | | | N | N | Y | Administrative Suites/Offices | | Basement #009 & 009A (Former classrooms per plan) |
| Other | 1757 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Basement |
| Other | 158 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | basement floor inside kitchen |
| Other | 972 | | | | | | | | N | N | N | Kitchen | Cooking Kitchen | Basement |
| Other | 47 | | | | | | | | N | N | N | Restroom | Staff Restroom | 1st Floor |
| Other | 47 | | | | | | | | N | N | N | Restroom | Staff Restroom | Basement |

Building: Annex

| | | | | | | | | | | | | | | |
|-----|-----|---|---|----|----|-----|----|---|---|---|---|-----------|--|--|
| 401 | 763 | 1 | 4 | 16 | 50 | 126 | 63 | 0 | N | N | N | Classroom | | |
| 402 | 763 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| 404 | 731 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| 406 | 775 | 1 | 4 | 16 | 40 | 100 | 50 | 0 | N | N | Y | Classroom | | |
| 407 | 760 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| 408 | 838 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|-----------------------|
| 409 | 765 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| 410 | 838 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| 411 | 838 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| 412 | 705 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| 413 | 760 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| 414 | 763 | 1 | 4 | 16 | 50 | 126 | 63 | 0 | N | N | Y | Classroom | | |
| 415 | 792 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| 416 | 763 | 1 | 4 | 16 | 50 | 126 | 63 | 0 | N | N | Y | Classroom | | |
| 417 | 731 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| 418 | 763 | 1 | 4 | 16 | 50 | 126 | 63 | 0 | N | N | Y | Classroom | | |
| 419 | 731 | 1 | 4 | 16 | 40 | 120 | 60 | 0 | N | N | Y | Classroom | | |
| Other | 4447 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 264 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Northeast Girl's Room |
| Other | 264 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Southeast Girl's Room |
| Other | 264 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Northeast Boy's Room |
| Other | 319 | | | 10 | | | | | N | N | Y | Administrative Suites/Offices | | Main Office |
| Other | 62 | | | | | | | | N | N | N | Restroom | Staff Restroom | Men's Room |
| Other | 147 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | Principal's Office |
| Other | 170 | | | 6 | | | | | N | N | N | Administrative Suites/Offices | | Teacher's Lounge |
| Other | 55 | | | | | | | | N | N | N | Restroom | Staff Restroom | Women's Room |
| Other | 683 | | | | | | | | N | N | N | Kitchen | Cooking Kitchen | 1st Floor |
| Other | 747 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | Room 403 |
| Other | 264 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | Southeast Boy's Room |