

Facility Assessment Detail

This report contains the findings of a facility assessment completed on the date noted in the document footer below. Assessors rate each facility feature and system by visual observation only; they do not test operability or perform destructive testing inside walls, ceilings or floors. The rankings below reflect the assessors' visual evaluations of the property condition as of that date. For additional information, you may visit the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/About_CPS/Policies_and_guidelines/Pages/facilitystandards.aspx.

Condition Rankings and Descriptions

- Rank 7:** The item/system is new or in good condition and no work is required.
- Rank 6:** The item/system requires general cleaning and/or routine maintenance.
- Rank 5:** The item/system requires repairs and has not reached the end of its serviceable life.
- Rank 4:** The item/system has reached its expected useful life, but is still fully operational. CPS will maintain until replacement occurs.
- Rank 3:** The item/system has surpassed its expected useful life and has limited operability. CPS will maintain until replacement occurs.
- Rank 2:** The item/system has surpassed its expected useful life and has low operability. CPS will maintain until replacement occurs.
- Rank 1:** The item's/system's failure leads to an immediate life safety condition for occupants or to the potential of an uninhabitable facility.¹

Definitions

Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated.

Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Cost means a basic estimate for each item needing some level of repair or replacement. Cost does not include all expenses that would be necessary to complete a repair or replacement project. This is because, depending on the item and on the overall scope of a construction project, repair/replacement projects can include additional costs such as destructive testing, environmental needs, discovered conditions, and additional work triggered by building codes.

For the same reason, the Total Campus Need listed at the end of this report reflects only a portion of what it would actually cost to repair/replace all of the listed features.

Total Campus Need also does not reflect features that do not yet exist at a particular facility, such as: programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration, or construction to alleviate overcrowding; these are viewed as separate capital needs.

Building: Main Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------|-----------|---|-------------------|------|----------|------|----------|----------------|
| Canopy | | Metal Canopy | Main Entrance | 6 | 1,112 | SF | \$26,762 | |
| Chimney | | Metal Flue | Roof | 7 | 16 | LF | \$0 | |
| Doors | | Exterior Steel Door | Entire Building | 6 | 9 | EA | \$2,973 | |
| Doors | | Overhead Rolling / Garage Door | Landscape storage | 7 | 1 | EA | \$0 | |
| Doors | | Store Front Door | Entire Building | 7 | 15 | EA | \$0 | |
| Entrance | | Entrance Controls - Audio and Video | Entire Building | 7 | 3 | EA | \$0 | |
| Entrance | | Power Door Operator and Controls | Entire Building | 7 | 6 | EA | \$0 | |
| Foundation | | Concrete Foundation | Trash enclosure | 7 | 140 | LF | \$0 | |
| Foundation | | Concrete Foundation | Entire Building | 7 | 1,158 | LF | \$0 | |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Roof - north end | 4 | 1 | EA | \$3,718 | Support broken |
| Lighting | | Exterior Lights - Parapet or Roof Mounted | Roof | 6 | 5 | EA | \$2,503 | |
| Lighting | | Exterior Lights - Wall Mounted | Entire Building | 6 | 24 | EA | \$5,148 | |
| Lighting | | Exterior Lights - Wall Mounted | Main Entrance | 7 | 7 | EA | \$0 | |
| Lintels | | Lintels - Steel | Entire Building | 7 | 1,134 | LF | \$0 | |

Building: Main
Category: EXTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|---|-----------------|------|----------|------|-----------------|--------|
| Parapet | | Coping - Metal | Roof | 7 | 1,250 | LF | \$0 | |
| Parapet | | Coping - Metal | Trash enclosure | 7 | 140 | LF | \$0 | |
| Parapet | | Coping - Stone | Gym roof | 7 | 160 | LF | \$0 | |
| Parapet | | Parapet < 16" Height | Roof | 7 | 165 | LF | \$0 | |
| Parapet | | Parapet > 30" Height | Gym roof | 7 | 160 | LF | \$0 | |
| Parapet | | Parapet 16" to 30" Height | Roof | 7 | 1,085 | LF | \$0 | |
| Roof System | | PVC Membrane Roof | Roof | 7 | 27,591 | SF | \$0 | |
| Roof System | | PVC Membrane Roof | Roof | 7 | 13,018 | SF | \$0 | |
| Roof System | | Roof Structure: Steel/Metal Deck/Concrete Topping | Roof | 7 | 40,609 | SF | \$0 | |
| Superstructure | | Steel | Entire Building | 7 | 108,624 | SF | \$0 | |
| Walls | | Brick | Entire Building | 7 | 43,507 | SF | \$0 | |
| Walls | | Brick | Trash enclosure | 7 | 1,147 | SF | \$0 | |
| Walls | | Prefabricated Metal Panel Wall | Chiller | 6 | 1,330 | SF | \$11,297 | |
| Walls | | Prefabricated Metal Panel Wall | Entire Building | 7 | 6,979 | SF | \$0 | |
| Walls | | Stone - Cast | Entire Building | 7 | 1,449 | SF | \$0 | |
| Windows | | Curtain wall - Glazed Double Pane | Entire Building | 7 | 6,105 | SF | \$0 | |
| Windows | | Window - Guards perforated | 1st Floor | 6 | 2,408 | SF | \$0 | |
| Windows | | Window - Guards wire guard | Gym | 7 | 233 | SF | \$0 | |
| Windows | | Windows - Casement Aluminum Double-pane | Entire Building | 7 | 7,827 | SF | \$0 | |
| EXTERIOR Sub Total | | | | | | | \$52,401 | |

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------|-----------|---|----------------------|------|----------|------|-----------|---|
| Emergency System | | Automatic Transfer switch | Entire Building | 7 | 3 | EA | \$0 | |
| Emergency System | | Emergency A/C power - Corridors and Stairs | Corridors and Stairs | 7 | 17,152 | SF | \$0 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Gym/Multi Purpose | 7 | 4,397 | SF | \$0 | |
| Emergency System | | Emergency A/C power - Gym and Lunch rooms | Lunch Room | 7 | 4,208 | SF | \$0 | |
| Emergency System | | Emergency A/C power - Students Toilets | Student Toilets | 7 | 2,621 | SF | \$0 | |
| Emergency System | | Emergency generator 150 KW -200 KW natural gas - Indoor | Electrical Room | 6 | 1 | EA | \$14,372 | |
| Emergency System | | Exit Signs - Corridors and Stairs | Corridors and Stairs | 6 | 47 | EA | \$10,955 | One Light on 2nd Floor Inoperative |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | Gym | 6 | 7 | EA | \$1,632 | |
| Emergency System | | Exit Signs - Lunchroom - Gym - multipurpose rooms | Lunch Room | 7 | 5 | EA | \$0 | |
| Emergency System | | Public Announcement System | Entire Building | 7 | 108,624 | SF | \$0 | |
| Emergency System | | Security System - CCTV | Entire Building | 5 | 108,624 | SF | \$310,665 | 6 DVR's 1- is down 18 Cameras are inoperative |

Building: Main
Category: ELECTRICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|-----------------|------|----------|------|------------------|--------|
| Emergency System | | Security System - Intrusion detection | MDF Room | 7 | 108,624 | SF | \$0 | |
| Main Service | | Main Electrical service - Live Front - 2000 to 3000 A 277/480/3PH | Electrical Room | 6 | 1 | EA | \$30,388 | |
| Power Distribution | | Lighting and power panels | Electrical Room | 6 | 27 | EA | \$19,305 | |
| Power Distribution | | Main distribution panels 400-600 amp | Electrical Room | 6 | 3 | EA | \$4,290 | |
| Power Distribution | | Main distribution panels above 600 amp | Electrical Room | 6 | 11 | EA | \$23,595 | |
| Power Distribution | | Main distribution panels less than 400 amp | Electrical Room | 6 | 1 | EA | \$1,216 | |
| Power Distribution | | Transformers 277/480-120/208 | Electrical Room | 6 | 4 | EA | \$4,576 | |
| ELECTRICAL Sub Total | | | | | | | \$420,992 | |

Building: Main
Category: FIRE PROTECTION

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------------------|-----------|--|-----------------|------|----------|------|------------|--------|
| Fire Alarm | | Fire Alarm Strobe Lights | Entire Building | 7 | 108,624 | SF | \$0 | |
| Fire Alarm | | Fire Alarm System | Electrical Room | 7 | 108,624 | SF | \$0 | |
| Fire Alarm | | Fire Pump Controller | Mechanical Room | 7 | 1 | EA | \$0 | |
| Pump Room Assembly | | Fire Pump 50-75hp | Mechanical Room | 7 | 1 | EA | \$0 | |
| Pump Room Assembly | | Jockey Pump | Mechanical Room | 7 | 1 | EA | \$0 | |
| Sprinkler System | | Combination Wet and Dry Sprinkler System | Entire Building | 7 | 108,624 | SF | \$0 | |
| Sprinkler System | | Sprinkler Heads | Entire Building | 7 | 108,624 | SF | \$0 | |
| FIRE PROTECTION Sub Total | | | | | | | \$0 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------------|-----------|--|-----------------|------|----------|------|----------|----------------------------|
| Air Conditioning | | Chillers - Air Cooled - Rotary/Screw type - Roof Mounted 100 to 200 tons | Roof | 7 | 2 | EA | \$0 | |
| Air Conditioning | | Condensing Unit - Roof Mounted less than 5 tons | Roof | 7 | 1 | EA | \$0 | |
| Air Handling Systems | | Air Handling Unit Package - Single Zone - Hot Water 12,001 to 20,000 cfm | Mechanical Room | 6 | 1 | EA | \$7,579 | AH-1. Filters Clogged |
| Air Handling Systems | | Air Handling Unit Package - Single Zone - Hot Water 8,001 to 12,000 cfm | Mechanical Room | 6 | 2 | EA | \$12,584 | AH-2 AH-3. Filters Clogged |
| Air Handling Systems | | Air Handling Unit Package - Single Zone - Hot Water above 30,000 cfm | Boiler Room | 6 | 1 | EA | \$21,450 | AH-4. Filters Clogged |
| Air Handling Systems | | Air intake for all Air Handling Units except built up AHU | North Façade | 7 | 2 | EA | \$0 | |
| Air Handling Systems | | Return Duct Work - Sheet Metal - Exterior Vertical Shaft and Ducts | Entire Building | 7 | 400 | LF | \$0 | |
| Air Handling Systems | | Return Fans - Indoor 10,001 to 20,000 CFM | Mechanical Room | 7 | 2 | EA | \$0 | |

Building: Main
Category: MECHANICAL

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------------|-----------|---|-----------------|------|----------|------|------------------|---|
| Air Handling Systems | | Return Fans - Indoor greater than 20,000 CFM | Mechanical Room | 7 | 1 | EA | \$0 | |
| Air Handling Systems | | Variable Air Volume (VAV) Box With Hot Water Coil | Entire Building | 7 | 61 | EA | \$0 | |
| Boiler Systems | | Boiler Assembly - Condensing Hot Water Boiler 1,001MBH-2,000 MBH | Boiler Room | 7 | 2 | EA | \$0 | |
| Boiler Systems | | Boiler Auxiliary - Condensing Hot Water Boiler 1,001MBH-2,000 MBH | Boiler Room | 7 | 2 | EA | \$0 | |
| Boiler Systems | | Chemical Pot Feeder - Hot Water | Boiler Room | 7 | 2 | EA | \$0 | |
| Boiler Systems | | Glycol Feed System | Boiler Room | 7 | 1 | EA | \$0 | |
| Heating Devices | | Cabinet Heaters With Hot Water Coils | West Courtyard | 7 | 8 | EA | \$0 | |
| Heating Devices | | Radiators - Hot Water | Entire Building | 7 | 6 | EA | \$0 | |
| Heating Devices | | Unit Heater - Electric | Entire Building | 7 | 2 | EA | \$0 | |
| Heating Devices | | Unit Heater - Hot Water | Entire Building | 7 | 7 | EA | \$0 | |
| Mechanical Plumbing | | Piping - Hydronic Supply and Return - Steel or Galvanized | Entire Building | 7 | 1,000 | LF | \$0 | |
| Mechanical Plumbing | | Pumps - Chilled Water 10 to 20 HP | Boiler Room | 7 | 2 | EA | \$0 | |
| Mechanical Plumbing | | Pumps - Hot Water 5 to 10 HP | Boiler Room | 7 | 2 | EA | \$0 | |
| Mechanical Plumbing | | Pumps - Hot Water less than 5 HP | Mechanical Room | 7 | 4 | EA | \$0 | |
| Temperature Control | | Direct Digital Control (DDC) System | Entire Building | 6 | 108,624 | SF | \$108,733 | OA Sensor Failed - Boilers on Manual Operaton |
| Temperature Control | | Thermostats - Direct Digital Control (DDC) | Entire Building | 7 | 75 | EA | \$0 | |
| Ventilation | | Exhaust Fan - Indoor | Entire Building | 7 | 7 | EA | \$0 | |
| Ventilation | | Exhaust Fans - Roof Mounted 1,501 to 8,000 cfm | Roof | 7 | 3 | EA | \$0 | |
| Ventilation | | Exhaust Fans - Roof mounted less than 500 CFM | Roof | 7 | 2 | EA | \$0 | |
| Ventilation | | Type II Exhaust Hood - Warming Kitchen | Kitchen | 7 | 1 | EA | \$0 | |
| MECHANICAL Sub Total | | | | | | | \$150,346 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------|-----------|--|-----------------|------|----------|------|------|--------|
| Hot Water | | Hot Water Heater - Gas more than 300,000 BTU/HR | Boiler Room | 7 | 2 | EA | \$0 | |
| Piping | | Domestic Piping - Cold Water from Risers to Fixtures | Entire Building | 7 | 108,624 | SF | \$0 | |
| Piping | | Domestic Piping - Cold Water Risers | Entire Building | 7 | 108,624 | SF | \$0 | |
| Piping | | Domestic Piping - Hot Water from Riser to fixtures | Entire Building | 7 | 108,624 | SF | \$0 | |
| Piping | | Domestic Piping - Hot Water Return Risers | Entire Building | 7 | 108,624 | SF | \$0 | |
| Piping | | Domestic Piping - Hot Water Risers | Entire Building | 7 | 108,624 | SF | \$0 | |
| Piping | | Domestic Piping Cold Water Horizontal lines | Entire Building | 7 | 108,624 | SF | \$0 | |

Building: Main
Category: PLUMBING

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|--|-----------------|------|----------|------|----------------|----------|
| Piping | | Domestic Piping Hot Water Horizontal lines | Entire Building | 7 | 108,624 | SF | \$0 | |
| Piping | | Domestic Piping Hot Water Return Lines | Entire Building | 7 | 108,624 | SF | \$0 | |
| Piping | | Sanitary Piping | Entire Building | 7 | 108,624 | SF | \$0 | |
| Piping | | Storm Piping | Entire Building | 7 | 108,624 | SF | \$0 | |
| Piping | | Vent Piping | Entire Building | 7 | 108,624 | SF | \$0 | |
| Pumps | | Domestic Booster Pump duplex | Mechanical Room | 7 | 1 | EA | \$0 | |
| Pumps | | Sump Pump | Elevator Pit | 6 | 1 | EA | \$1,359 | Sump Dry |
| PLUMBING Sub Total | | | | | | | \$1,359 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|-------------------|--|------|----------|------|------|--------|
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, Room 110, student services office suite | 7 | 458 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, Nurses office suite | 7 | 997 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | Faculty Lounge 217 | 7 | 575 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, Main office, conference room 100C | 7 | 221 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, engineers office | 7 | 160 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, Main office | 7 | 1,224 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, Room 100A, principal office | 7 | 223 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, gym office | 7 | 148 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, Room 100B, Asst principal office | 7 | 220 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Ceiling - Lay-In | First floor, Kitchen office | 7 | 95 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | First floor, Room 100A, principal office | 7 | 223 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | First floor, Main office | 7 | 879 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | First floor, Room 100B, Asst principal office | 7 | 220 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | First floor, Main office, conference room 100C | 7 | 221 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Carpet | First floor, Room 110, student services office suite | 7 | 458 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-------------------------------|----------------------------|--|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Flooring - Terrazzo | First floor, Main office | 7 | 345 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, engineers office | 7 | 160 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, Kitchen office | 7 | 95 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | Faculty Lounge 217 | 7 | 575 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, Nurses office suite | 7 | 997 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Flooring - Tile/Sheet | First floor, gym office | 7 | 148 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | Faculty Lounge 217 | 7 | 6 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, engineers office | 7 | 3 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, Main office | 7 | 12 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, Room 110, student services office suite | 7 | 8 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, gym office | 7 | 2 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, Nurses office suite | 7 | 13 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, Main office, conference room 100C | 7 | 3 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, Room 100B, Asst principal office | 7 | 3 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, Room 100A, principal office | 7 | 3 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Lay-In | First floor, Kitchen office | 7 | 1 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Lighting - Pendant/Surface | First floor, Main office | 7 | 12 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | First floor, engineers office | 6 | 474 | SF | \$1,356 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | First floor, Room 110, student services office suite | 6 | 846 | SF | \$2,420 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | First floor, Kitchen office | 6 | 354 | SF | \$1,012 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | Faculty Lounge 217 | 7 | 930 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | First floor, gym office | 7 | 460 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|------------------------|-------------------------------|--------------------------------------|--|------|----------|------|---------|--------|
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | First floor, Main office, conference room 100C | 6 | 280 | SF | \$801 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | First floor, Room 100B, Asst principal office | 6 | 120 | SF | \$343 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | First floor, Room 100A, principal office | 6 | 280 | SF | \$801 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | First floor, Nurses office suite | 6 | 2,135 | SF | \$6,106 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Concrete Block | First floor, Main office | 6 | 1,488 | SF | \$4,256 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, Room 100B, Asst principal office | 7 | 438 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, Room 100A, principal office | 7 | 280 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, Main office | 7 | 788 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, Room 110, student services office suite | 7 | 189 | SF | \$0 | |
| Administrative Suites | Administrative Suites/Offices | Walls - Plaster/Drywall | First floor, Main office, conference room 100C | 7 | 280 | SF | \$0 | |
| Auditorium - Dedicated | | Stage Platform | First floor, gym | 6 | 993 | SF | \$4,217 | |
| Doors | | Interior Steel Doors incl hw | Entire Building | 7 | 97 | EA | \$0 | |
| Doors | | Interior Wood Doors incl hw | Entire Building | 7 | 77 | EA | \$0 | |
| Doors | | Side-lite | Entire Building | 7 | 350 | SF | \$0 | |
| Doors | | Store Front Door | 1st Floor | 7 | 9 | EA | \$0 | |
| Drinking Fountains | Corridors | Triple Fountain | 2nd Floor | 7 | 2 | EA | \$0 | |
| Drinking Fountains | Corridors | Triple Fountain | 3rd Floor | 7 | 2 | EA | \$0 | |
| Drinking Fountains | Corridors | Triple Fountain | 1st Floor | 7 | 2 | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Bleacher Seating | 1st Floor | 7 | 75 | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Ceiling - Exposed | 1st Floor | 7 | 4,120 | SF | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Ceiling - Lay-In | 1st Floor | 7 | 277 | SF | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Flooring - Wood | 1st Floor | 7 | 4,397 | SF | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Lighting - Metal Halide/Sodium Vapor | 1st Floor | 6 | 20 | EA | \$3,575 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Scoreboards | 1st Floor | 7 | 1 | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Stage Curtain | 1st Floor | 7 | 10 | EA | \$0 | |
| Gymnasium / Auditorium | Gymnasium.Auditorium | Walls - Concrete Block | 1st Floor | 7 | 8,356 | SF | \$0 | |
| Kitchen | Cooking Kitchen | Ceiling - Lay-In | 1st Floor | 6 | 1,030 | SF | \$2,946 | |
| Kitchen | Cooking Kitchen | Flooring - Concrete | 1st Floor | 6 | 1,030 | SF | \$4,861 | |
| Kitchen | Cooking Kitchen | Lighting - Lay-In | 1st Floor | 7 | 12 | SF | \$0 | |
| Kitchen | Cooking Kitchen | Wall - Concrete Block | 1st Floor | 6 | 1,204 | SF | \$3,443 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|----------------|-------------------------------|--|------|----------|------|-------|--------|
| Library | Library | Casework | Room 300 | 7 | 200 | LF | \$0 | |
| Library | Library | Flooring Carpet | Room 300 | 7 | 3,760 | SF | \$0 | |
| Library | Library | Lighting - Lay-In | Room 300 | 7 | 4 | SF | \$0 | |
| Library | Library | Lighting - Pendant/ Surface | Room 300 | 7 | 48 | SF | \$0 | |
| Locker/Shower Room | Staff Restroom | Showers | First floor, nurses bathroom | 7 | 1 | EA | \$0 | |
| Lunchroom | Lunchroom | Ceiling - Lay-In | 1st Floor | 7 | 4,208 | SF | \$0 | |
| Lunchroom | Lunchroom | Flooring - Tile/Sheet | 1st Floor | 7 | 4,208 | SF | \$0 | |
| Lunchroom | Lunchroom | Lighting - Lay-In | 1st Floor | 7 | 56 | SF | \$0 | |
| Lunchroom | Lunchroom | Lighting - Pendant/Surface | 1st Floor | 7 | 18 | SF | \$0 | |
| Lunchroom | Lunchroom | Serving Line | 1st Floor | 7 | 30 | LF | \$0 | |
| Lunchroom | Lunchroom | Wall - Concrete Block | 1st Floor | 7 | 1,786 | SF | \$0 | |
| Lunchroom | Lunchroom | Wall - Structural Glazed Tile | 1st Floor | 7 | 1,283 | SF | \$0 | |
| MDF/IDF | | Finishes | MDF Room 209 | 7 | 330 | SF | \$0 | |
| MDF/IDF | | Ventilation and Cooling | MDF Room 209 | 7 | 1 | EA | \$0 | |
| Mechanical/Service Rooms | | Boiler Room | Boiler Room 307 | 7 | 3,000 | SF | \$0 | |
| Mechanical/Service Rooms | | Janitor's Closet | Entire Building | 7 | 7 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | First floor, room 116, pump room | 7 | 390 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Electrical Closet 215A | 7 | 160 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Electical Room 328 | 7 | 100 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Fan Room 211 | 7 | 3,112 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Automatic Transfer Switch 211B | 7 | 55 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | Emergency Generator 211A | 7 | 690 | SF | \$0 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | First floor, elevator machine room | 6 | 58 | SF | \$274 | |
| Mechanical/Service Rooms | | Mechanical/Service Rooms | First floor, room 117, electrical room | 7 | 508 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, Kitchen Storage | 7 | 100 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, room 123 storage | 7 | 50 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, next to engineer office | 6 | 132 | SF | \$623 | |
| Mechanical/Service Rooms | | Storage Room | Storage 203 | 7 | 200 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Rooms 200A & 201A | 7 | 310 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Storage 215B | 7 | 62 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Storage 326 | 7 | 106 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Storage 303 | 7 | 200 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, store room, inside room 122 | 7 | 50 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------|--------------------------------------|--------------|-----------------------------------|------|----------|------|------|--------|
| Mechanical/Service Rooms | | Storage Room | Storage 205 | 7 | 103 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, room 121 storage | 7 | 50 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, room 120 storage | 7 | 50 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, room 119 storage | 7 | 50 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, room 118 storage | 7 | 50 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, gym storage | 7 | 274 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | First floor, Main office | 7 | 224 | SF | \$0 | |
| Mechanical/Service Rooms | | Storage Room | Storage 300A | 7 | 245 | SF | \$0 | |
| Music Room | Classroom | Sound Panels | | 7 | 560 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | Room 118 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 129D Men's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 129A Boy's, north | 7 | 252 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | Room 122 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | Room 123 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | Room 121 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 129C Girl's, north | 7 | 252 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | Room 119 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 113D Women's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 113C Boy's, South | 7 | 252 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | First floor, main office | 7 | 70 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | First floor, nurses bathroom | 7 | 90 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | First floor, Kitchen staff, Men's | 7 | 62 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 229C Girl's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Accessories | Room 120 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 229D Men's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 329C Girl's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 329A Boy's, north | 7 | 253 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|------------------|-------------------------------------|------|----------|------|------|--------|
| Staff Restroom | Children's Standard Student Restroom | Accessories | 313A Girl's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 113A Girl's, South | 7 | 252 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 229A Boy's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 213C Boy's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | First floor, Kitchen staff, Women's | 7 | 62 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 329D Men's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 213D Unisex, south | 7 | 67 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Accessories | 313D Women's, south | 7 | 67 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 213A Girl's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Accessories | 313C Boy's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Lay-In | Room 123 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 129A Boy's, north | 7 | 252 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Lay-In | Room 122 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | 129D Men's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 129C Girl's, north | 7 | 252 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | 313D Women's, south | 7 | 67 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Lay-In | Room 121 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | 213D Unisex, south | 7 | 67 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Lay-In | Room 119 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 329C Girl's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Lay-In | Room 118 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | 113D Women's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 113C Boy's, South | 7 | 252 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 113A Girl's, South | 7 | 252 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Ceiling - Lay-In | Room 120 bathroom | 7 | 58 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|---------------------------|-------------------------------------|------|----------|------|------|--------|
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 213A Girl's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | First floor, Kitchen staff, Men's | 7 | 62 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | First floor, Kitchen staff, Women's | 7 | 62 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 229C Girl's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 229A Boy's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | First floor, main office | 7 | 70 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | 329D Men's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 313A Girl's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 329A Boy's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 313C Boy's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Ceiling - Lay-In | 213C Boy's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Lay-In | 229D Men's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Ceiling - Plaster/Drywall | First floor, nurses bathroom | 7 | 90 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | Room 118 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | First floor, main office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | First floor, nurses bathroom | 7 | 2 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | Room 123 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 329C Girl's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 113D Women's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | Room 120 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | Room 119 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | First floor, Kitchen staff, Men's | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | First floor, Kitchen staff, Women's | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 229C Girl's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 313A Girl's, south | 7 | 2 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|---------------------|------|----------|------|------|--------|
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 113A Girl's, South | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 329A Boy's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 229A Boy's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 313C Boy's, south | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 129C Girl's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 113C Boy's, South | 7 | 2 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | Room 121 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 213A Girl's, south | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 129D Men's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Floor Drain | Room 122 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 313D Women's, south | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 213D Unisex, south | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 329D Men's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Floor Drain | 229D Men's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 213C Boy's, south | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Floor Drain | 129A Boy's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 129A Boy's, north | 7 | 252 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 129D Men's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | Room 121 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | Room 122 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | Room 119 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | Room 123 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | Room 120 bathroom | 7 | 58 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Flooring - Tile Ceramic/Porcelain | Room 118 bathroom | 7 | 58 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------------------|-------------------------------------|------|----------|------|------|--------|
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 113C Boy's, South | 7 | 252 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, main office | 7 | 70 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 129C Girl's, north | 7 | 252 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 313A Girl's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 113D Women's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 313D Women's, south | 7 | 67 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 213D Unisex, south | 7 | 67 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 229D Men's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | 329D Men's, north | 7 | 67 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 213C Boy's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 313C Boy's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 229A Boy's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 329A Boy's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, Kitchen staff, Women's | 7 | 62 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 213A Girl's, south | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 329C Girl's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, nurses bathroom | 7 | 90 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Flooring - Tile Ceramic/Porcelain | First floor, Kitchen staff, Men's | 7 | 62 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 229C Girl's, north | 7 | 253 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Flooring - Tile Ceramic/Porcelain | 113A Girl's, South | 7 | 252 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 113A Girl's, South | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 113C Boy's, South | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 129A Boy's, north | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 129C Girl's, north | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 213C Boy's, south | 7 | 3 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|------------|-------------------------------------|------|----------|------|------|--------|
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 313C Boy's, south | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 329A Boy's, north | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 329C Girl's, north | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 313A Girl's, south | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 213A Girl's, south | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 229C Girl's, north | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Hand Dryer | 229A Boy's, north | 7 | 3 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 113A Girl's, South | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 129A Boy's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | Room 122 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | Room 123 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | Room 121 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | Room 120 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | Room 119 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lavatory | Room 118 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, nurses bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 113C Boy's, South | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, main office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 129C Girl's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 313D Women's, south | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 113D Women's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, Kitchen staff, Women's | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 129D Men's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | First floor, Kitchen staff, Men's | 7 | 1 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------------|-------------------------------------|------|----------|------|------|--------|
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 229C Girl's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 213A Girl's, south | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 313A Girl's, south | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 329C Girl's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 329A Boy's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 313C Boy's, south | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 213C Boy's, south | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 229D Men's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 329D Men's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Lavatory | 213D Unisex, south | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lavatory | 229A Boy's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 113A Girl's, South | 7 | 12 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 129A Boy's, north | 7 | 12 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Lay-In | Room 122 bathroom | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Lay-In | Room 123 bathroom | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Lay-In | Room 121 bathroom | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Lay-In | Room 120 bathroom | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Lay-In | Room 119 bathroom | 7 | 1 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Lighting - Lay-In | Room 118 bathroom | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | First floor, nurses bathroom | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 113C Boy's, South | 7 | 12 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | First floor, main office | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | 129D Men's, north | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | First floor, Kitchen staff, Women's | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | 113D Women's, north | 7 | 1 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-------------------|-----------------------------------|------|----------|------|------|--------|
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 329C Girl's, north | 7 | 12 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 213A Girl's, south | 7 | 12 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 129C Girl's, north | 7 | 12 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 229C Girl's, north | 7 | 12 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 313A Girl's, south | 7 | 12 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 329A Boy's, north | 7 | 12 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 229A Boy's, north | 7 | 12 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 313C Boy's, south | 7 | 12 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Lighting - Lay-In | 213C Boy's, south | 7 | 12 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | 229D Men's, north | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | 329D Men's, north | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | 213D Unisex, south | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | 313D Women's, south | 7 | 1 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Lighting - Lay-In | First floor, Kitchen staff, Men's | 7 | 1 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 229C Girl's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 213C Boy's, south | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 113A Girl's, South | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 113C Boy's, South | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 129A Boy's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 129C Girl's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 313C Boy's, south | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 229A Boy's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 329A Boy's, north | 7 | 2 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|-----------------------|-------------------------------------|------|----------|------|-------|--------|
| Staff Restroom | Children's Standard Student Restroom | Partitions | 329C Girl's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 213A Girl's, south | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Partitions | 313A Girl's, south | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 113C Boy's, South | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 329A Boy's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 229A Boy's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 313C Boy's, south | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 129A Boy's, north | 6 | 2 | EA | \$744 | |
| Staff Restroom | Children's Standard Student Restroom | Urinals | 213C Boy's, south | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 329D Men's, north | 7 | 270 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 313A Girl's, south | 7 | 600 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 213A Girl's, south | 7 | 600 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 229C Girl's, north | 7 | 600 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | First floor, Kitchen staff, Women's | 7 | 270 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | First floor, Kitchen staff, Men's | 7 | 270 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 329A Boy's, north | 7 | 600 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 229A Boy's, north | 7 | 600 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 313C Boy's, south | 7 | 600 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 329C Girl's, north | 7 | 600 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 229D Men's, north | 7 | 270 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 213D Unisex, south | 7 | 270 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 313D Women's, south | 7 | 270 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 129C Girl's, north | 7 | 594 | SF | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------------|--------------------------------------|--------------------------------|------------------------------|------|----------|------|-------|--------|
| Staff Restroom | Early Childhood Student Restroom | Wall - Concrete Block | Room 118 bathroom | 6 | 232 | SF | \$664 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | First floor, nurses bathroom | 7 | 304 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | First floor, main office | 7 | 270 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 113A Girl's, South | 7 | 594 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 213C Boy's, south | 7 | 600 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 113D Women's, north | 7 | 270 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Concrete Block | 129D Men's, north | 7 | 270 | SF | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Concrete Block | Room 119 bathroom | 6 | 232 | SF | \$664 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Concrete Block | Room 120 bathroom | 6 | 232 | SF | \$664 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Concrete Block | Room 121 bathroom | 6 | 232 | SF | \$664 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Concrete Block | Room 123 bathroom | 6 | 232 | SF | \$664 | |
| Staff Restroom | Early Childhood Student Restroom | Wall - Concrete Block | Room 122 bathroom | 6 | 232 | SF | \$664 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 129A Boy's, north | 7 | 594 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Wall - Concrete Block | 113C Boy's, South | 7 | 594 | SF | \$0 | |
| Staff Restroom | Staff Restroom | Wall - Tile Ceramic/ Porcelain | First floor, nurses bathroom | 7 | 102 | SF | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 129A Boy's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 313A Girl's, south | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 113D Women's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | Room 119 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | Room 120 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | Room 121 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | Room 123 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | Room 122 bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 313C Boy's, south | 7 | 2 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------|--------------------------------------|-------------------------------------|-------------------------------------|------|----------|------|------|--------|
| Staff Restroom | Staff Restroom | Water Closet | First floor, Kitchen staff, Men's | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | First floor, Kitchen staff, Women's | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 229C Girl's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 213A Girl's, south | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 113C Boy's, South | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 329C Girl's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 329A Boy's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 229A Boy's, north | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 129D Men's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 213C Boy's, south | 7 | 2 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 229D Men's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 329D Men's, north | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 213D Unisex, south | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | 313D Women's, south | 7 | 1 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 129C Girl's, north | 7 | 4 | EA | \$0 | |
| Staff Restroom | Children's Standard Student Restroom | Water Closet | 113A Girl's, South | 7 | 4 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | First floor, nurses bathroom | 7 | 1 | EA | \$0 | |
| Staff Restroom | Staff Restroom | Water Closet | First floor, main office | 7 | 1 | EA | \$0 | |
| Staff Restroom | Early Childhood Student Restroom | Water Closet | Room 118 bathroom | 7 | 1 | EA | \$0 | |
| Vertical Conveyance | | Elevator - Roped Holeless Hydraulic | Entire Building | 7 | 1 | EA | \$0 | |
| Vertical Conveyance | | Stage Lift | First floor, gym | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 2 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |

Building: Main
Category: INTERIOR

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---------------------------|-----------|-----------|----------|------|----------|------|-----------------|--------|
| Vocational Shop | Classroom | Work Sink | | 7 | 1 | EA | \$0 | |
| INTERIOR Sub Total | | | | | | | \$42,501 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|----------|-----------|----------|----------|------|----------|------|------|--------|
| Casework | Classroom | Casework | | 7 | 28 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 20 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 48 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 28 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 28 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 28 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 28 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 28 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 28 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 28 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 28 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 50 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 40 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 40 | LF | \$0 | |
| Casework | Classroom | Casework | | 7 | 10 | LF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------|-----------|-------------------------|-------------------------|------|----------|------|------|--------|
| Ceiling | Classroom | Lay-In/Drop | | 7 | 900 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 1,200 | SF | \$0 | |
| Ceiling | Classroom | Lay-In/Drop | | 7 | 900 | SF | \$0 | |
| CLASSROOM | Classroom | Eye Wash Station | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Laptop Charging Station | | 7 | 1 | EA | \$0 | |
| CLASSROOM | Classroom | Science Lab Elements | | 7 | 1,360 | SF | \$0 | |
| Corridors | Corridors | Ceiling | 1st Floor | | 5,640 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | 2nd Floor | 7 | 8,690 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | 1st Floor | 7 | 7,084 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | Entire building, stairs | 7 | 7,612 | SF | \$0 | |
| Corridors | Corridors | Concrete Block | 3rd Floor | 7 | 8,690 | SF | \$0 | |
| Corridors | Corridors | Drop/Lay-In | 2nd Floor | 7 | 4,678 | SF | \$0 | |
| Corridors | Corridors | Drop/Lay-In | 3rd Floor | 7 | 4,678 | SF | \$0 | |
| Corridors | Corridors | Drop/Lay-In | Entire building, stairs | 7 | 1,560 | SF | \$0 | |
| Corridors | Corridors | Exposed | 3rd Floor | 7 | 663 | SF | \$0 | |
| Corridors | Corridors | Exposed | 2nd Floor | 7 | 663 | SF | \$0 | |
| Corridors | Corridors | Lay-In | 1st Floor | 7 | 5,640 | EA | \$0 | |
| Corridors | Corridors | Lay-In | 2nd Floor | 7 | 4,678 | EA | \$0 | |
| Corridors | Corridors | Lay-In | Entire building, stairs | 7 | 1,560 | EA | \$0 | |
| Corridors | Corridors | Lay-In | 3rd Floor | 7 | 4,678 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 3rd Floor | 7 | 663 | EA | \$0 | |
| Corridors | Corridors | Pendant/Surface | 2nd Floor | 7 | 663 | EA | \$0 | |
| Corridors | Corridors | Stair Handrails | Entire building, stairs | 7 | 148 | LF | \$0 | |
| Corridors | Corridors | Student Lockers | 1st Floor | 7 | 173 | EA | \$0 | |
| Corridors | Corridors | Student Lockers | 2nd Floor | 7 | 290 | EA | \$0 | |
| Corridors | Corridors | Student Lockers | 3rd Floor | 7 | 288 | EA | \$0 | |
| Corridors | Corridors | Terrazzo | Entire building, stairs | 7 | 1,560 | SF | \$0 | |
| Corridors | Corridors | Terrazzo | 3rd Floor | 7 | 4,678 | SF | \$0 | |
| Corridors | Corridors | Terrazzo | 2nd Floor | 7 | 4,678 | SF | \$0 | |
| Corridors | Corridors | Terrazzo | 1st Floor | 7 | 5,640 | SF | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | 2nd Floor | 7 | 663 | SF | \$0 | |
| Corridors | Corridors | Tile/Sheet Flooring | 3rd Floor | 7 | 663 | SF | \$0 | |
| Corridors | Corridors | Wall Mounted | Entire building, stairs | 7 | 418 | EA | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------------------|-----------|-----------------|-------------------------|------|----------|------|------|--------|
| Corridors Ceiling | Corridors | Plaster/Drywall | Entire building, stairs | 7 | 210 | SF | \$0 | |
| Stairs | Corridors | Terrazzo | Entire building, stairs | 7 | 96 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,200 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,290 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,360 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,280 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 937 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,112 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,112 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,112 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,112 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,112 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 1,112 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |
| Floor | Classroom | Tile/Sheet | | 7 | 900 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------|-----------|----------------|----------|------|----------|------|---------|--------|
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Marker Board | Classroom | Marker Board | | 7 | 20 | LF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 460 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 530 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 460 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 460 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 6 | 578 | SF | \$1,653 | |
| Wall | Classroom | Concrete Block | | 6 | 675 | SF | \$1,931 | |
| Wall | Classroom | Concrete Block | | 6 | 675 | SF | \$1,931 | |
| Wall | Classroom | Concrete Block | | 6 | 675 | SF | \$1,931 | |
| Wall | Classroom | Concrete Block | | 6 | 675 | SF | \$1,931 | |
| Wall | Classroom | Concrete Block | | 6 | 675 | SF | \$1,931 | |
| Wall | Classroom | Concrete Block | | 7 | 500 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 6 | 675 | SF | \$1,931 | |
| Wall | Classroom | Concrete Block | | 6 | 675 | SF | \$1,931 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 1,100 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 460 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 460 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 500 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 460 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 400 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 400 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 400 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 430 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-------|-----------|---------------------|----------|------|----------|------|---------|--------|
| Wall | Classroom | Concrete Block | | 7 | 1,565 | SF | \$0 | |
| Wall | Classroom | Concrete Block | | 7 | 195 | SF | \$0 | |
| Wall | Classroom | Metal/Folding Panel | | 7 | 265 | SF | \$0 | |
| Wall | Classroom | Metal/Folding Panel | | 7 | 265 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 450 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 450 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 350 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 449 | SF | \$1,059 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 500 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 424 | SF | \$1,000 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 449 | SF | \$1,059 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 449 | SF | \$1,059 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 449 | SF | \$1,059 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 449 | SF | \$1,059 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 449 | SF | \$1,059 | |
| Wall | Classroom | Plaster/Drywall | | 6 | 449 | SF | \$1,059 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 450 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 450 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 450 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 450 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 450 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 265 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 265 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 830 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 1,050 | SF | \$0 | |

Building: Main
Category: ROOM

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|--------------------------------|-----------|-----------------|----------|------|----------|------|------------------|--------|
| Wall | Classroom | Plaster/Drywall | | 7 | 450 | SF | \$0 | |
| Wall | Classroom | Plaster/Drywall | | 7 | 715 | SF | \$0 | |
| ROOM Sub Total | | | | | | | \$20,593 | |
| Building Main Sub Total | | | | | | | \$688,192 | |

Building: SITE
Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|-----------------------|-----------|--|------------------|------|----------|------|------------------|--------|
| Civil/Drainage | | Catch Basin | Entire Site | 6 | 9 | EA | \$4,891 | |
| Fencing | | Ornamental Iron | Entire Site | 7 | 904 | LF | \$0 | |
| Fencing | | Ornamental Iron | Entire Site | 7 | 917 | LF | \$0 | |
| Landscape | | Benches | Entire Site | 7 | 13 | EA | \$0 | |
| Landscape | | Grass | Entire Site | 6 | 80,809 | SF | \$32,356 | |
| Landscape | | Hardscape - Concrete | Entire Site | 7 | 1,357 | SF | \$0 | |
| Landscape | | Hardscape - Pavers | Main Entrance | 7 | 4,663 | SF | \$0 | |
| Landscape | | Parkway trees | Entire Site | 6 | 11 | EA | \$3,146 | |
| Landscape | | Planting Beds/ Areas | Entire Site | 6 | 8,641 | SF | \$0 | |
| Landscape | | Planting Beds/ Areas | Northeast corner | 7 | 22,159 | SF | \$0 | |
| Landscape | | Trash Receptacles | Entire Site | 6 | 8 | EA | \$1,661 | |
| Parking Lot | | Concrete | Compactor/drive | 6 | 3,731 | SF | \$0 | |
| Parking Lot | | Concrete Curbs | Parking Lot | 6 | 469 | LF | \$2,830 | |
| Parking Lot | | Lights, Pole Mounted | Entire Site | 6 | 41 | EA | \$46,904 | |
| Parking Lot | | Pavers | Parking Lot | 6 | 8,526 | SF | \$0 | |
| Parking Lot | | Trash Compactor | Site - East | 6 | 1 | EA | \$3,575 | |
| Playground | | Playground Equipment - School Age 5-12 | Playground | 7 | 1 | EA | \$0 | |
| Playground | | Playground Surfacing - Poured Surface | Playground | 7 | 2,941 | SF | \$0 | |
| Sidewalks | | Internal Walks | Entire Site | 7 | 2,405 | LF | \$0 | |
| Sidewalks | | Perimeter Sidewalks | Entire Site | 6 | 7,654 | SF | \$14,448 | |
| Signage | | Flag Pole | Main Entrance | 7 | 1 | EA | \$0 | |
| SITE Sub Total | | | | | | | \$109,811 | |
| SITE Sub Total | | | | | | | \$109,811 | |

Building: SITE

Category: SITE

| Group | Sub Group | Item | Location | Rank | Quantity | Unit | Cost | Reason |
|---|-----------|------|----------|------|----------|------|------------------|--------|
| Total Campus Need ^{2 3} | | | | | | | \$798,002 | |

¹ It is very rare for an assessor to find a feature in this condition. If they do, they are required to report it immediately to CPS, and CPS addresses it immediately. Thus, no features will be ranked "1" in summary reports; by the time the report is compiled, they have been resolved.

² As stated above, Total Assessed Campus Need does not include the addition of features not already in a particular facility, such as programmatic improvements, school-wide ADA compliance, air conditioning, space reconfiguration or construction to alleviate overcrowding; these items are treated as separate capital needs. The Total Assessed Campus Need includes current deficiencies and is based on current unit cost estimates; it does not reflect a complete project cost.

³ The overall condition of different items can change after an assessment date due to many variables, including newly occurring deficiencies, renovation or repairs and cost changes. These dollar figures in this report are estimates only and are based solely on the data that was collected as of the assessment date in the footer below.

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-----------------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-----------|---------------|----------|
| Building: Main | | | | | | | | | | | | | | |
| 118 | 1112 | 1 | 4 | 18 | 40 | 196 | 52 | 0 | N | N | N | Classroom | | |
| 119 | 1112 | 1 | 4 | 18 | 40 | 196 | 52 | 0 | N | N | N | Classroom | | |
| 120 | 1112 | 1 | 4 | 18 | 40 | 196 | 52 | 0 | N | N | N | Classroom | | |
| 121 | 1112 | 1 | 4 | 18 | 40 | 196 | 52 | 0 | N | N | N | Classroom | | |
| 122 | 1112 | 1 | 4 | 18 | 40 | 196 | 52 | 0 | N | N | N | Classroom | | |
| 123 | 1112 | 1 | 4 | 18 | 40 | 196 | 52 | 0 | N | N | N | Classroom | | |
| 126 | 920 | 1 | 8 | 24 | 40 | 147 | 49 | 0 | N | N | N | Classroom | | |
| 200 | 1290 | 1 | 10 | 34 | 40 | 244 | 0 | 0 | N | N | N | Classroom | | |
| 201 | 1360 | 1 | 10 | 34 | 40 | 144 | 0 | 0 | N | N | N | Classroom | | |
| 214 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 216 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 218 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 219 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | Y | N | Classroom | | |
| 220 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 221 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 222 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 223 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 224 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 225 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 226 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 227 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 228 | 937 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | Y | N | Classroom | | |
| 300 | 1280 | 1 | 6 | 24 | 40 | 420 | 10 | 0 | N | N | N | Classroom | | |
| 309 | 1200 | 1 | 40 | 80 | 40 | 150 | 30 | 0 | N | N | N | Classroom | | |
| 314 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 316 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 317 | 900 | 1 | 4 | 20 | 40 | 70 | 10 | 0 | N | Y | N | Classroom | | |
| 318 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 319 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | Y | N | Classroom | | |
| 320 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 321 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 322 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 323 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | Y | N | Classroom | | |
| 324 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 325 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |
| 327 | 900 | 1 | 4 | 20 | 40 | 195 | 30 | 0 | N | N | N | Classroom | | |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|--------------------------------------|--|
| Other | 5341 | | | | | | | | N | N | N | Corridors | | 3rd Floor |
| Other | 830 | | | | | | | | N | N | N | Corridors | | Entire building, stairs |
| Other | 160 | | | 12 | | | | | N | N | Y | Administrative Suites/Offices | | First floor, engineers office |
| Other | 62 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, Kitchen staff, Women's |
| Other | 62 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, Kitchen staff, Men's |
| Other | 5341 | | | | | | | | N | N | N | Corridors | | 2nd Floor |
| Other | 1030 | | | | | | | | N | N | N | Kitchen | Cooking Kitchen | 1st Floor |
| Other | 252 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 129C Girl's, north |
| Other | 67 | | | | | | | | N | N | N | Restroom | Staff Restroom | 129D Men's, north |
| Other | 95 | | | 6 | | | | | N | N | Y | Administrative Suites/Offices | | First floor, Kitchen office |
| Other | 67 | | | | | | | | N | N | N | Restroom | Staff Restroom | 313D Women's, south |
| Other | 67 | | | | | | | | N | N | N | Restroom | Staff Restroom | 213D Unisex, south |
| Other | 67 | | | | | | | | N | N | N | Restroom | Staff Restroom | 329D Men's, north |
| Other | 67 | | | | | | | | N | N | N | Restroom | Staff Restroom | 229D Men's, north |
| Other | 252 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 129A Boy's, north |
| Other | 253 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 313C Boy's, south |
| Other | 221 | | | 10 | | | | | N | N | Y | Administrative Suites/Offices | | First floor, Main office, conference room 100C |
| Other | 253 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 229A Boy's, north |
| Other | 253 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 329A Boy's, north |
| Other | 253 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 329C Girl's, north |
| Other | 253 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 313A Girl's, south |
| Other | 253 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 213A Girl's, south |
| Other | 253 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 213C Boy's, south |
| Other | 58 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | Room 123 bathroom |
| Other | 252 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 113C Boy's, South |
| Other | 67 | | | | | | | | N | N | N | Restroom | Staff Restroom | 113D Women's, north |
| Other | 4208 | | | | | | | | N | N | N | Lunch & Multipurpose Room | Lunchroom | 1st Floor |
| Other | 252 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 113A Girl's, South |
| Other | 4397 | | | | | | | | N | N | N | Gymnasia | Gymnasium.Auditorium | 1st Floor |
| Other | 5640 | | | | | | | | N | N | N | Corridors | | 1st Floor |
| Other | 253 | | | | | | | | N | N | N | Restroom | Children's Standard Student Restroom | 229C Girl's, north |
| Other | 3760 | | | | | | | | N | N | N | Library | | Room 300 |
| Other | 58 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | Room 119 bathroom |
| Other | 223 | | | 10 | | | | | N | N | Y | Administrative Suites/Offices | | First floor, Room 100A, principal office |
| Other | 58 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | Room 121 bathroom |
| Other | 90 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, nurses bathroom |

Room Summary

| Room Number | Room Size | Voice Outlet | Data Outlet | Elect Outlet | Noise Level | Glaze Window Area | Operable Window Area | No. of Window AC | Window Stop | Smart Board | Power Strip | Room Type | Room Sub Type | Location |
|-------------|-----------|--------------|-------------|--------------|-------------|-------------------|----------------------|------------------|-------------|-------------|-------------|-------------------------------|----------------------------------|--|
| Other | 575 | | | 20 | | | | | N | N | Y | Administrative Suites/Offices | | Faculty Lounge 217 |
| Other | 148 | | | 8 | | | | | N | N | Y | Administrative Suites/Offices | | First floor, gym office |
| Other | 58 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | Room 122 bathroom |
| Other | 70 | | | | | | | | N | N | N | Restroom | Staff Restroom | First floor, main office |
| Other | 220 | | | 8 | | | | | N | N | Y | Administrative Suites/Offices | | First floor, Room 100B, Asst principal office |
| Other | 58 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | Room 118 bathroom |
| Other | 1224 | | | 28 | | | | | N | N | Y | Administrative Suites/Offices | | First floor, Main office |
| Other | 458 | | | 14 | | | | | N | N | Y | Administrative Suites/Offices | | First floor, Room 110, student services office suite |
| Other | 997 | | | 16 | | | | | N | N | Y | Administrative Suites/Offices | | First floor, Nurses office suite |
| Other | 58 | | | | | | | | N | N | N | Restroom | Early Childhood Student Restroom | Room 120 bathroom |