





Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1916	3	93,084
Addition	2013	2	19,000
Campus Total			112,084

Catego	ry : Exterior	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	Chimney	1	EA	7	10+ years	
	Cell Equipment - Cabinets	Chimney	1	EA	7	10+ years	
	Cell Equipment - Generator	Chimney	1	EA	7	10+ years	
Entrance	1						
	Entrance Control - Audio and Video	1-Main	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	1-Main	3	EA	6	10+ years	
	Power Door Operator and Controls	1-Main	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	10	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	10	3	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	2	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	2	4	EA	6	10+ years	
	Exterior Stairs - Concrete	2	40	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	2	120	LF	5	10+ years	
	Ramps - Concrete	2	60	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	2	10	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	3	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	3	3	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	3	30	LF	5	1-2 years	Leaning
	Ramps - Concrete	3	30	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	4	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	4	3	EA	6	10+ years	
	Exterior Stairs - Concrete	4	72	LF	6	10+ years	

Campus Name: Bell Page : 1 of 44 Assessment Date: 07/27/2021



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramps - Concrete	4	72	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	4	50	LF	7	10+ years	Quantity changed to update/correct to match current observations.
	Exterior Doors - Exterior Steel Door	8	1	EA	5	2-5 years	
	Exterior Stairs - Concrete	8	32	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	8.1 - West mechanical doors	2	EA	5	2-5 years	
	Entrance Control - Audio	9	1	EA	5	2-5 years	Quantity changed to update/correct to match current observations.
	Exterior Doors - Exterior Steel Door	9	1	EA	6	10+ years	
Foundati							
	Foundation - Concrete	Entire Building	1,077	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	92,112	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	21	EA	6	6-10 years	
Roof Sys							
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Boiler Room Roof	90	LF	6	10+ years	
	Coping - Stone	Boiler Room Roof	143	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Boiler Room Roof	30	LF	5	0-1 year	Downspout disconnected
	Downspouts - Interior Downspouts	Boiler Room Roof	33	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Boiler Room Roof	143	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Boiler Room Roof	3,780	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Boiler Room Roof	3,780	SF	7	10+ years	
	Downspouts - Exterior Downspouts	Center Lower	34	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Center Lower	860	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Center Lower	860	SF	7	10+ years	
	Access Ladder - Metal	High	4	EA	7	10+ years	
	Coping - Stone	High	840	LF	6	10+ years	
	Coping - Terra Cotta	High	273	LF	6	10+ years	
	Downspouts - Interior Downspouts	High	435	LF	7	10+ years	
	Parapet - 16" - 30" Height	High	993	LF	6	10+ years	
	Parapet - Parapet > 30"	High	120	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	High	27,688	SF	6	6-10 years	
	Roof Hatch - Metal	High	4	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	High	27,688	SF	7	10+ years	
	Coping - Stone	Lower - Over Entrance #2	80	LF	6	10+ years	
	Downspouts - Interior Downspouts	Lower - Over Entrance #2	66	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Lower - Over Entrance #2	80	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Lower - Over Entrance #2	750	SF	6	6-10 years	

Campus Name: Bell Page : 2 of 44 Assessment Date: 07/27/2021



Outcgo	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Steel with Clay Tile Arch	Lower - Over Entrance #2	750	SF	7	10+ years	
<i>N</i> alls	0 1 1 1 1 1 0		400				
	Cheek-Wall - Concrete	Entire Building	188	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	10	SF	4	0-1 year	Loose safety issue
	Cheek-Wall - Concrete	Entire Building	60	SF	4	1-2 years	Displacement/spalling
	Cornice - Cast Stone	Entire Building	1,077	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	14,301	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	6,661	SF	6	10+ years	
Windows	<u>, </u>						
· viiiuovs	Guard - Guards perforated	Entire Building	4,940	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,641	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	100	SF	4	0-1 year	Cracked glazing throughout
	Windows - Sash Aluminum Double-pane	Entire Building	14,183	SF	3	0-1 year	Issues with balancers throughout
	Windows - Sash Aluminum Double-pane	Entire Building	570	SF	3	0-1 year	Issues with balancers throughout
	Willdows - Sasii Aldillilldill Double-parle	Entire Building	370	SI	3	0-1 year	issues with balancers throughout
Catego	ry : Electrical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	1st Floor	4	EA	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	7	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	19	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EΑ	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	92,112	SF	7	6-10 years	
			~_ , _				
	Security System - Intrusion Detection	Entire Building	92 112	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	92,112	SF EA	6 7	6-10 years	
	Security System - Intrusion Detection Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW	Site South	92,112 1	SF EA	6 7	6-10 years 6-10 years	
Main Co	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW					•	
Main Se	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW	Site South		EA	7	6-10 years	
Main Se	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW rvice Main Electrical Service - 2000 A		1			•	
Main Se	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW rvice Main Electrical Service - 2000 A 120/208/3PH	Site South Electrical Room	1	EA	6	6-10 years 10+ years	New
Main Se	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW rvice Main Electrical Service - 2000 A 120/208/3PH Independent Electrical Service for	Site South	1	EA	7	6-10 years	New
Main Se	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW rvice Main Electrical Service - 2000 A 120/208/3PH Independent Electrical Service for emergency power	Site South Electrical Room Electrical Room	1 1	EA EA EA	7 6 7	6-10 years 10+ years 10+ years	New
Main Se	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW rvice Main Electrical Service - 2000 A 120/208/3PH Independent Electrical Service for	Site South Electrical Room	1	EA	6	6-10 years 10+ years	New
	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW rvice Main Electrical Service - 2000 A 120/208/3PH Independent Electrical Service for emergency power PA System	Site South Electrical Room Electrical Room Entire Building	1 1	EA EA SF	7 6 7	6-10 years 10+ years 10+ years	New
	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW rvice Main Electrical Service - 2000 A 120/208/3PH Independent Electrical Service for emergency power PA System	Site South Electrical Room Electrical Room	1 1	EA EA EA	7 6 7	6-10 years 10+ years 10+ years	New
	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW rvice Main Electrical Service - 2000 A 120/208/3PH Independent Electrical Service for emergency power PA System istribution Lighting and Power Panels - 100 A	Site South Electrical Room Electrical Room Entire Building Entire Building	1 1 1 92,112	EA EA SF	7 6 7 7	6-10 years 10+ years 10+ years 6-10 years	New
	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW rvice Main Electrical Service - 2000 A 120/208/3PH Independent Electrical Service for emergency power PA System	Site South Electrical Room Electrical Room Entire Building	1 1 1 92,112	EA EA SF	7 6 7	6-10 years 10+ years 10+ years 6-10 years	New

Campus Name: Bell Page : 3 of 44 Assessment Date: 07/27/2021



amp

Alexander Graham Bell Elementary School 3730 N Oakley AVENUE, Chicago, IL 60618

Category : Electrical	Building : Main						
					Recommend		
Group Item - Type	Location	Quantity	UOM	Rank	Replacement Comments		

Building: Main Category: Fire Protection

Group Item - Type Fire Alarm	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarm Panel	Entire Building	1 92.112	EA SF	6	6-10 years 6-10 years	
Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	111,994	SF	6	6-10 years	

Category : Mechanical **Building: Main**

Guicgo	ategory: meenamear			unung			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Cond	ditionina						
	Condensing Unit- Roof Mounted - Less than 5 tons	Main Roof	1	EA	6	6-10 years	Quantity changed to update/correct to match current observations.
Air Hand	Iling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	1st Floor	1	EA	6	6-10 years	This unit has no temperature controls- it is just a fan. Quantity changed to update/correct to match current observations.
	Air Intake	1st Floor	1	EA	6	6-10 years	North air intake . Serves the gym and auditorium
	Auxiliaries - 25001 - 35000 cfm	1st Floor	1	EA	5	2-5 years	Quantity changed to update/correct to match current observations.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	1st Floor	200	LF	6	10+ years	
	Zone Dampers	1st Floor	24	EA	6	6-10 years	Quantity changed to update/correct to match current observations.
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm	1st Floor	1	EA	6	6-10 years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations.
	Air Intake	1st Floor	1	EA	6	6-10 years	South air intake. Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations.
	Auxiliaries - 15001 - 25000 cfm	1st Floor	1	EA	6	6-10 years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations.
	Return Duct Work - Indoor- Vertical Shaft	1st Floor	100	LF	6	10+ years	Rank and/or Priority Replacement

Campus Name: Bell Page : 4 of 44 Assessment Date: 07/27/2021



Catego	ry : Mechanical		В	uilding	: Main		, <u>, , , , , , , , , , , , , , , , , , </u>
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	and Ducts						(AKA RUL) changed to update/correct to match current observations.
	Zone Dampers	1st Floor	54	EA	6	6-10 years	Quantity changed to update/correct to match current observations.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	6	6-10 years	Serves the North part of the building. Quantity changed to update/correct to match current observations.
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EΑ	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room	100	LF	6	10+ years	
	and Ducts				•	.o. youro	
	Zone Dampers	Mechanical Room	38	EA	6	6-10 years	
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	6	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	7	6-10 years	Quantity changed to update/correct to match current observations.
	Combustion Dampers	Boiler Room	2	EA	6	2-5 years	
	Condensate Pump	Boiler Room	2	EA	6	2-5 years	As per POC the pumps are working fine by they're installed in a crawl space with difficult access
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	·
	Non Condensing - Fire Tube - Scotch Marine- Steam - Low Pressure Boiler - 151 - 200 HP	Boiler Room	2	EA	6	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	300	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	300	LF	6	6-10 years	
	Steam Traps	Boiler Room	1	EA	7	6-10 years	
_Heat Exc							
	Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	1	EA	7	6-10 years	
Heating	Devices						
	Unit Heater - Gas	1st Floor	1	EA	5	2-5 years	
	Wall Heater - Electric	Entire Building	24	EA	5	6-10 years	
	Radiators - Steam	Entire Building	28	EA	6	6-10 years	Most of them have new regulator valves -
	Unit Heater - Steam	Entire Building	2	EA	5	2-5 years	
	Fin Tube - Steam	Entire Building	20	LF	5	6-10 years	Needs to be cleaned
		g	20	 •	٠	,	

Campus Name: Bell Page : 5 of 44 Assessment Date: 07/27/2021



Catego	ry : Mechanical		В	uilding	: Main		WISO N Cakey AVENCE, Chicago, IE 60010
	· _					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Tempera	ature Control						
	Hybrid Pneumatic/DDC System	Entire Building	92,112	SF	7	6-10 years	
	Thermostats - Pneumatic	Entire Building	55	EA	6	6-10 years	
\							
_Ventilati		Fatire Duilding	4	EA		2.5.42.272	Overetity above and to variety/serve at to
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	4	EA	5	2-5 years	Quantity changed to update/correct to match current observations.
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	7	6-10 years	Quantity changed to update/correct to
	CFM	g				5 15 , 555	match current observations.
	Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	5	2-5 years	Quantity changed to update/correct to
	500 CFM						match current observations.
0-1	mar Diametrica		ь.				
Catego	ry : Plumbing		<u> </u>	uilding	: Main	Decembered	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wat	-	Location	Quantity	OOW	IVALIK	Replacement	Comments
_HOL Wat	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	10+ years	
	Gas rieater - 130000 - 300000 B10/1110	Bollet Room	•	LA	O	10+ years	
Piping							
<u> </u>	Domestic Piping-Hot Water Return Lines	Entire Building	92,112	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	92,112	SF	6	6-10 years	Rank and/or Priority Replacement
							(AKA RUL) changed to
							update/correct to match current
	Domestic Piping-Hot Water from Risers to	Entire Building	92,112	SF	6	6-10 years	observations. Rank and/or Priority Replacement
	Fixtures	Entire Building	92,112	SF	O	0-10 years	(AKA RUL) changed to
	Tixtures						update/correct to match current
							observations.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	92,112	SF	6	10+ years	Rank and/or Priority Replacement
	(Horizontal Lines)						(AKA RUL) changed to
							update/correct to match current
	Domestic Piping-Hot/Cold Water Supply	Entire Building	92,112	SF	6	6-10 years	observations. Rank and/or Priority Replacement
	(Risers)	Littile Ballaling	92,112	OI.	O	0-10 years	(AKA RUL) changed to
	(1110010)						update/correct to match current
							observations.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	92,112	SF	6	10+ years	Rank and/or Priority Replacement
	(from Risers to Fixtures)						(AKA RUL) changed to
							update/correct to match current
	Sanitary Piping	Entire Building	92,112	SF	6	6-10 years	observations.
	Storm Piping Storm Piping	Entire Building	92,112	SF SF	6	10+ years	
	Vent Piping	Entire Building	92,112	SF	6	10+ years	
	···- g	9	02,112	٥.	Ŭ	.o. youro	

Campus Name: Bell Page : 6 of 44 Assessment Date: 07/27/2021



Building: Main Category: Plumbing

Recommend Item - Type Location Quantity UOM Rank Replacement Comments Group

Pumps

Pumps - Domestic Booster Pump-Simplex EΑ 6-10 years Boiler Room 1 6

Category: Room **Building: Main**

icgo	y . Room			unung	· Wall	Recommend	
aa	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
oup	<u> </u>	Location	Quantity	UOW	Kank	Replacement	Comments
minist	rative Suites/Offices						
	AC Unit	105 Office	1	EA	7	6-10 years	
	Ceiling - Splined	105 Office	480	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105 Office	1	EA	7	10+ years	
	Floor - Carpet	105 Office	460	SF	7	6-10 years	
	Floor - Tile	105 Office	20	SF	7	10+ years	
	Lighting - Pendent/Surface	105 Office	10	EA	7	6-10 years	
	Power Distribution	105 Office	18	EA	7	10+ years	
	Walls - Plaster/Drywall	105 Office	1,123	SF	7	10+ years	
	Work SInk	105 Office	1	EA	7	10+ years	
	AC Unit	116 Nurse's Suite	1	EA	7	6-10 years	
	Ceiling - Lay-in	116 Nurse's Suite	403	SF	7	10+ years	
	Doors - Steel Doors incl hw	116 Nurse's Suite	4	EA	7	10+ years	
	Floor - Tile	116 Nurse's Suite	403	SF	7	10+ years	
	Lighting - Lay-in	116 Nurse's Suite	8	EA	7	6-10 years	
	Power Distribution	116 Nurse's Suite	12	EA	7	10+ years	
	Storage/ Closet	116 Nurse's Suite	15	SF	7	10+ years	
	Walls - Plaster/Drywall	116 Nurse's Suite	930	SF	7	10+ years	
	Work SInk	116 Nurse's Suite	1	EA	7	10+ years	
	Ceiling - Lay-in	116A Exam Room	75	SF	7	10+ years	
	Doors - Steel Doors incl hw	116A Exam Room	1	EA	7	10+ years	
	Floor - Tile	116A Exam Room	75	SF	7	10+ years	
	Lighting - Lay-in	116A Exam Room	1	EA	7	6-10 years	
	Power Distribution	116A Exam Room	4	EA	7	10+ years	
	Walls - Plaster/Drywall	116A Exam Room	315	SF	7	10+ years	
	Work SInk	116A Exam Room	1	EA	7	10+ years	Rank and/or Priority Replacemer
							(AKA RUL) changed to
							update/correct to match current
							observations.
	AC Unit	300 (at stair landing)	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	300 (at stair landing)	357	SF	6	10+ years	
	Doors - Transom Window	300 (at stair landing)	24	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	300 (at stair landing)	1	EA	6	6-10 years	
	Floor - Carpet	300 (at stair landing)	357	SF	6	6-10 years	
	Lighting - Pendent/Surface	300 (at stair landing)	6	EA	6	6-10 years	
	Power Distribution	300 (at stair landing)	4	EA	6	6-10 years	
	Walls - Metal Panel	300 (at stair landing)	442	SF	6	10+ years	

Campus Name: Bell Page: 7 of 44 Assessment Date: 07/27/2021



Category : Room			В	Building : Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	300 (at stair landing)	442	SF	6	10+ years		
	Ceiling - Lay-in	301A	250	SF	6	6-10 years		
	Doors - Steel Doors incl hw	301A	1	EA	6	6-10 years		
	Floor - Carpet	301A	250	SF	7	6-10 years		
	Lighting - Pendent/Surface	301A	4	EA	6	6-10 years		
	Power Distribution	301A	6	EA	6	6-10 years		
	Walls - Metal Panel	301A	575	SF	6	10+ years		
	Walls - Plaster/Drywall	301A	178	SF	6	10+ years		
	Ceiling - Lay-in	305A	169	SF	6	10+ years		
	Doors - Steel Doors incl hw	305A	1	EA	6	6-10 years		
	Floor - Carpet	305A	169	SF	6	6-10 years		
	Lighting - Pendent/Surface	305A	2	EA	6	6-10 years		
	Power Distribution	305A	4	EA	6	6-10 years		
	Walls - Metal Panel	305A	178	SF	6	10+ years		
	Walls - Plaster/Drywall	305A	425	SF	6	10+ years		
	Ceiling - Lay-in	320	250	SF	7	10+ years		
	Doors - Side-lite	320	15	SF	7	6-10 years		
	Doors - Steel Doors incl hw	320	1	ĒΑ	7	6-10 years		
	Floor - Carpet	320	250	SF	7	6-10 years		
	Lighting - Pendent/Surface	320	4	ĒΑ	7	6-10 years		
	Power Distribution	320	4	EA	7	6-10 years		
	Walls - Metal Panel	320	575	SF	7	10+ years		
	Walls - Plaster/Drywall	320	178	SF	7	10+ years		
	Ceiling - Lay-in	Engineer Office, 1st Flr.	281	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Engineer Office, 1st Flr.	2	ĒΑ	7	10+ years		
	Floor - Tile	Engineer Office, 1st Flr.	108	SF	7	10+ years		
	Lighting - Pendent/Surface	Engineer Office, 1st Flr.	1	ĒΑ	7	6-10 years		
	Power Distribution	Engineer Office, 1st Flr.	4	EA	7	10+ years		
	Storage/ Closet	Engineer Office, 1st Flr.	173	SF	7	10+ years		
	Walls - Plaster/Drywall	Engineer Office, 1st Flr.	322	SF	6	10+ years		
	Ceiling - Plaster/Drywall	Interpreter's Office/Staff Lounge	342	SF	6	10+ years	Paint cracking and peeling	
		(Balcony)	J		-	,	throughout.	
	Doors - Wood Doors inclu hw	Interpreter's Office/Staff Lounge	3	EA	6	6-10 years	o a g o a	
	Boold Wood Boold Mold III	(Balcony)	Ü	_, ,	Ū	o io jouio		
	Floor - Tile	Interpreter's Office/Staff Lounge	332	SF	6	10+ years		
	. 1.00.	(Balcony)		О.	•	,		
	Floor - Tile	Interpreter's Office/Staff Lounge	10	SF	4	1-2 years	Damaged tile	
	11001 1110	(Balcony)		O.	•	. <i>-</i> you.o	Damagod mo	
	Lighting - Pendent/Surface	Interpreter's Office/Staff Lounge	5	EA	7	2-5 years		
	gg	(Balcony)	· ·		•	_ 0 ,00.0		
	Power Distribution	Interpreter's Office/Staff Lounge	8	EA	7	6-10 years		
	. C. C. Diodiodion	(Balcony)	J		•	5 10 Jouro		
	Storage/ Closet	Interpreter's Office/Staff Lounge	43	SF	7	6-10 years		
	213.333, 010000	(Balcony)	10	٥.	•	5 10 Jouro		
		(= 3)						



Catego	ry : Room		Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	Interpreter's Office/Staff Lounge	558	SF	7	10+ years			
		(Balcony)							
	AC Unit	Main Office	1	EΑ	7	6-10 years			
	Ceiling - Lay-in	Main Office	624	SF	6	10+ years			
	Doors - Steel Doors incl hw	Main Office	1	EA	7	10+ years			
	Doors - Wood Doors inclu hw	Main Office	3	EA	7	10+ years			
	Floor - Carpet	Main Office	624	SF	7	6-10 years			
	Lighting - Pendent/Surface	Main Office	12	EΑ	7	6-10 years			
	Power Distribution	Main Office	14	EA	7	10+ years			
	Storage/ Closet	Main Office	85	SF	7	10+ years			
	Walls - Plaster/Drywall	Main Office	1,258	SF	7	10+ years			
	AC Unit	Office 113B	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Office 113B	512	SF	7	10+ years			
	Doors - Transom Window	Office 113B	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Office 113B	1	EA	7	10+ years			
	Floor - Carpet	Office 113B	512	SF	7	6-10 years			
	Lighting - Pendent/Surface	Office 113B	9	EA	7	6-10 years			
	Power Distribution	Office 113B	8	EA	7	10+ years			
	Storage/ Closet	Office 113B	108	SF	7	10+ years			
	Walls - Plaster/Drywall	Office 113B	1,020	SF	7	10+ years			
	AC Unit	Principal's Office	1	EA	7	6-10 years			
	Ceiling - Lay-in	Principal's Office	370	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Principal's Office	3	EA	7	10+ years			
	Floor - Carpet	Principal's Office	370	SF	7	6-10 years			
	Lighting - Pendent/Surface	Principal's Office	12	EA	7	6-10 years			
	Power Distribution	Principal's Office	10	EΑ	7	10+ years			
	Walls - Plaster/Drywall	Principal's Office	977	SF	7	10+ years			
Auditoriu	ım & Theater								
	Balcony Seating	1st Floor	10	EA	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	6,846	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years			
	Doors - Transom Window	1st Floor	120	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	6	ĒΑ	7	10+ years			
	Floor - Carpet	1st Floor	2,664	SF	7	6-10 years			
	Floor - Wood	1st Floor	4,237	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	109	ĒΑ	7	6-10 years			
	Main Floor Seating	1st Floor	656	EA	7	10+ years			
	Sound System	1st Floor	1	EA	7	6-10 years			
	Stage	1st Floor	875	SF	7	10+ years			
	Stage Curtain	1st Floor	8	ĒΑ	7	6-10 years			
	Stage Lift	1st Floor	1	EA	7	6-10 years			
	Stage Lighting System	1st Floor	1	EA	7	6-10 years			
	Stage-Stairs - Wood	1st Floor	32	LF	7	10+ years			
	-					•			



Catego	Category : Room		В	uilding	: Main		730 N Garley Avenue, Gilleage, 12 000 To
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	8,777	SF	6	10+ years	
_Gymnas	sia						
	Bleacher Seating	3rd Floor	80	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	3,784	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	30	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	6-10 years	
	Floor - Wood	3rd Floor	3,782	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	10	EΑ	7	6-10 years	
	Lighting - Wall Mounted	3rd Floor	2	EΑ	7	6-10 years	
	Scoreboards	3rd Floor	1	EΑ	7	2-5 years	
	Walls - Plaster/Drywall	3rd Floor	3,642	SF	6	10+ years	
Library							
	AC Unit	114 Library	2	EA	7	6-10 years	
	Ceiling - Lay-in	114 Library	1,366	SF	7	10+ years	
	Doors - Steel Doors incl hw	114 Library	4	EA	7	10+ years	
	Floor - Carpet	114 Library	1,366	SF	7	6-10 years	
	Lighting - Lay-in	114 Library	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	114 Library	30	EA	7	6-10 years	
	Storage/ Closet	114 Library	46	SF	7	10+ years	
	Walls - Plaster/Drywall	114 Library	1,295	SF	7	10+ years	
MDF_ID)F						
	Doors - Steel Doors incl hw	Room 118	1	EA	7	6-10 years	
	Finishes	Room 118	106	SF	5	6-10 years	
	Window AC Unit	Room 118	1	EA	7	2-5 years	
Mechan	ical/ Service Rooms						
INICCITATI	Janitor's Closet	1st Floor	25	SF	7	10+ years	
	Janitor's Closet	1st Floor	35	SF	7	10+ years	
	Storage Room	1st Floor	100	SF	7	10+ years	
	Vaults	1st Floor	50	SF	7	10+ years	
	Janitor's Closet	Entire Building	150	SF	7	6-10 years	
	Janitor's Closet	Entire Building	20	SF	7	6-10 years	Quantity changed to update/correct to
		_		-	-	-	match current observations.
	Boiler Room	Mechanical Room	1,413	SF	7	10+ years	
	Mechanical/ Service Rooms	Mechanical Room	2,986	SF	7	10+ years	
	Storage Room	Mechanical Room	140	SF	7	10+ years	
	Storage Room	Room 113A	50	SF	7	6-10 years	
Restroo	m						
	Accessories	101A	42	SF	7	6-10 years	

Campus Name: Bell Page : 10 of 44 Assessment Date: 07/27/2021



ategory : Room			В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	101A	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	101A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	101A	42	SF	7	10+ years	
	Lavatory	101A	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	101A	1	EA	7	6-10 years	
	Partitions	101A	1	EA	7	10+ years	
	Walls - Plaster/Drywall	101A	277	SF	7	10+ years	
	Walls - Plaster/Drywall	101A	100	SF	4	0-1 year	Cracking
	Water Closet	101A	1	EA	7	10+ years	•
	Accessories	116 Nurse Suite	46	SF	7	6-10 years	
	Ceiling - Lay-in	116 Nurse Suite	46	SF	7	10+ vears	
	Doors - Steel Doors incl hw	116 Nurse Suite	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	116 Nurse Suite	46	SF	7	10+ years	
	Floor Drain	116 Nurse Suite	1	ĒΑ	7	10+ years	
	Lavatory	116 Nurse Suite	1	EA	7	10+ years	
	Lighting - Lay-in	116 Nurse Suite	1	EA	7	6-10 years	Rank and/or Priority Replacemen
	Lighting Lay III	TTO Naise Galle	·	Lit	,	o to years	(AKA RUL) changed to update/correct to match current observations.
	Walls - Plaster/Drywall	116 Nurse Suite	124	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	116 Nurse Suite	124	SF	7	10+ years	
	Water Closet	116 Nurse Suite	1	EA	7	10+ years	
	Accessories	1st Floor	410	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	410	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	6	10+ years	
	Doors - Transom Window	1st Floor	15	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	410	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Partitions	1st Floor	8	EA	7	10+ years	
	Walls - Masonry	1st Floor	280	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	560	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	280	SF	7	10+ years	
	Water Closet	1st Floor	8	EA	7	10+ years	
	Accessories	1st Floor	410	SF	7	6-10 years	
	Ceiling - Plaster/Drywall			SF	6	•	
	Doors - Steel Doors incl hw	1st Floor 1st Floor	410 1	SF EA	6	10+ years	
			15	SF	6 7	10+ years	
	Doors - Transom Window	1st Floor		SF SF	-	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	410		6	10+ years	
	Floor Drain	1st Floor	1	EΑ	7	10+ years	
	Hand Dryer	1st Floor	1	EΑ	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	10+ years	

Campus Name: Bell Page : 11 of 44 Assessment Date: 07/27/2021



Catego	Category : Room		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years		
	Partitions	1st Floor	3	EA	7	10+ years		
	Urinals	1st Floor	6	EA	7	10+ years		
	Walls - Masonry	1st Floor	280	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	560	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor	280	SF	6	10+ years		
	Water Closet	1st Floor	3	EA	7	10+ years		
	Accessories	1st Floor East Unisex	190	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor East Unisex	190	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor East Unisex	1	EA	5	10+ years		
	Floor - Tile	1st Floor East Unisex	190	SF	6	10+ years		
	Lavatory	1st Floor East Unisex	1	ĒA	6	10+ years		
	Lighting - Pendent/Surface	1st Floor East Unisex	2	EA	7	6-10 years		
	Partitions	1st Floor East Unisex	2	EA	7	10+ years		
	Student Lockers - Two Tiers	1st Floor East Unisex	20	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor East Unisex	885	SF	6	10+ years		
	Water Closet	1st Floor East Unisex	2	EA	7	10+ years		
	Accessories	2nd Floor	410	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	410	SF	6	10+ years		
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years		
	Doors - Transom Window	2nd Floor	15	SF	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	410	SF	6	10+ years		
	Floor Drain	2nd Floor	1	EA	7	6-10 years		
	Hand Dryer	2nd Floor	1	EA	7	2-5 years		
	Lavatory	2nd Floor	3	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years		
	Partitions	2nd Floor	8	EA	7	6-10 years		
	Walls - Masonry	2nd Floor	280	SF	6	10+ years		
	Walls - Masority Walls - Plaster/Drywall	2nd Floor	560	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd Floor	280	SF	7	10+ years		
	Water Closet	2nd Floor 2nd Floor	8	EA	7	6-10 years		
	Accessories	2nd Floor	410	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	410	SF	7	10+ years		
	Doors - Steel Doors incl hw	2nd Floor 2nd Floor	1	EA	7	6-10 years		
	Doors - Transom Window	2nd Floor 2nd Floor	15	SF	7	6-10 years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor 2nd Floor	410	SF	7	6-10 years		
	Floor Drain	2nd Floor 2nd Floor	410	EA	7			
	Hand Dryer	2nd Floor 2nd Floor	1	EA	7	10+ years		
	•		-	EA	7	10+ years		
	Lavatory	2nd Floor	3			6-10 years		
	Lighting - Pendent/Surface	2nd Floor	4	EΑ	7	2-5 years		
	Partitions	2nd Floor	3	EΑ	7	6-10 years		
	Urinals	2nd Floor	6	EA	7	6-10 years		
	Walls - Masonry	2nd Floor	280	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	560	SF	7	10+ years		

Campus Name: Bell Page : 12 of 44 Assessment Date: 07/27/2021



Catego	ry : Room		В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	2nd Floor	280	SF	7	10+ years	
	Water Closet	2nd Floor	3	EΑ	7	6-10 years	
	Accessories	2nd Floor Central Unisex	160	SF	7	2-5 years	
	Ceiling - Plaster/Drywall	2nd Floor Central Unisex	160	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Central Unisex	2	EΑ	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor Central Unisex	160	SF	7	10+ years	
	Hand Dryer	2nd Floor Central Unisex	1	EA	7	6-10 years	
	Lavatory	2nd Floor Central Unisex	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Central Unisex	2	EA	7	6-10 years	
	Partitions	2nd Floor Central Unisex	2	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor Central Unisex	820	SF	7	10+ years	
	Water Closet	2nd Floor Central Unisex	2	EA	7	6-10 years	
	Accessories	3rd Floor	410	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	410	SF	6	6-10 years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	6-10 years	
	Doors - Transom Window	3rd Floor	15	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	410	SF	6	6-10 years	
	Floor Drain	3rd Floor	1	EA	7	6-10 years	
			1	EA	7		
	Hand Dryer	3rd Floor	· · · · · · · · · · · · · · · · · · ·	EA		6-10 years	
	Lavatory	3rd Floor	3		6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	5	EA	6	6-10 years	
	Partitions	3rd Floor	8	EA	7	6-10 years	
	Walls - Masonry	3rd Floor	280	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	560	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	280	SF	7	10+ years	
	Water Closet	3rd Floor	8	EA	7	6-10 years	
	Accessories	3rd Floor	410	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	410	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	6-10 years	
	Doors - Transom Window	3rd Floor	15	SF	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	410	SF	7	6-10 years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	1	EA	7	2-5 years	
	Lavatory	3rd Floor	3	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	4	EΑ	7	6-10 years	
	Partitions	3rd Floor	3	EΑ	7	6-10 years	
	Urinals	3rd Floor	6	EΑ	7	6-10 years	
	Walls - Masonry	3rd Floor	280	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	560	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor	280	SF	7	10+ years	
	Water Closet	3rd Floor	3	ĒΑ	7	6-10 years	
	Accessories	3rd Floor Central Unisex	160	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Central Unisex	160	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Central Unisex	1	EA	7	6-10 years	
	200.0 11000 20010 11010 1110	ora i issi esimai emoox	,	_, .	•	o lo youlo	

Campus Name: Bell Page : 13 of 44 Assessment Date: 07/27/2021



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	3rd Floor Central Unisex	160	SF	7	6-10 years	
	Lavatory	3rd Floor Central Unisex	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor Central Unisex	2	EA	7	6-10 years	
	Partitions	3rd Floor Central Unisex	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor Central Unisex	820	SF	7	10+ years	
	Water Closet	3rd Floor Central Unisex	2	EA	7	6-10 years	
	Accessories	Boiler Room Unisex	30	SF	7	6-10 years	
	Ceiling - Lay-in	Boiler Room Unisex	25	SF	7	10+ years	
	Ceiling - Lay-in	Boiler Room Unisex	5	SF	4	0-1 year	Water Stains
	Doors - Wood Doors inclu hw	Boiler Room Unisex	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Boiler Room Unisex	30	SF	7	10+ years	
	Lavatory	Boiler Room Unisex	1	ĒΑ	7	10+ years	
	Lighting - Wall Mounted	Boiler Room Unisex	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	Boiler Room Unisex	198	SF	7	10+ years	
	Water Closet	Boiler Room Unisex	1	EA	7	10+ years	
	Accessories	Engineer's Toilet	32	SF	5	6-10 years	
	Ceiling - Lay-in	Engineer's Toilet	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Toilet	1	EA	5	10+ years	
	Floor - Tile	Engineer's Toilet	32	SF	5	10+ years	
	Lavatory	Engineer's Toilet Engineer's Toilet	32 1	EA	5 5	10+ years	Rank and/or Priority Replacement
	Lavatory	Lingingor o Tonot	·	273	O	To Tyouro	(AKA RUL) changed to update/correct to match current observations.
	Lighting - Pendent/Surface	Engineer's Toilet	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Engineer's Toilet	180	SF	6	10+ years	
	Water Closet	Engineer's Toilet	1	EA	6	10+ years	
	Accessories	Inside 112	60	SF	7	6-10 years	Added missing restroom
	Ceiling - Plaster/Drywall	Inside 112	60	SF	6	10+ years	3
	Doors - Wood Doors inclu hw	Inside 112	1	ĒΑ	6	10+ years	
	Floor - Tile	Inside 112	60	SF	6	10+ years	
	Lavatory	Inside 112	1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	Inside 112	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Inside 112	250	SF	6	10+ years	
	Water Closet	Inside 112	1	EA	6	10+ years	
	Accessories	Main Office	48	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years	
	Floor - Tile	Main Office	48	SF	7	10+ years	
	Lavatory	Main Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Main Office	1	EA	7	6-10 years	
	Lighting - Pendeni/Surface Lighting - Wall Mounted	Main Office	1	EA	7	6-10 years	
		Main Office	· ·	SF	7		
	Walls - Plaster/Drywall	Main Office Main Office	265	_		10+ years	
	Water Closet		1	EA	7 7	10+ years	
	Accessories	North side of Aud. Stairs/Vest.	58	SF	1	6-10 years	

Campus Name: Bell Page : 14 of 44 Assessment Date: 07/27/2021



Catego	ry : Room		В	uilding	: Main		•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	North side of Aud. Stairs/Vest.	58	SF	7	10+ years	
	Doors - Wood Doors inclu hw	North side of Aud. Stairs/Vest.	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North side of Aud. Stairs/Vest.	58	SF	7	10+ years	
	Lavatory	North side of Aud. Stairs/Vest.	1	EA	7	10+ years	
	Lighting - Pendent/Surface	North side of Aud. Stairs/Vest.	2	EA	7	6-10 years	
	Partitions	North side of Aud. Stairs/Vest.	1	EA	7	10+ years	
	Walls - Plaster/Drywall	North side of Aud. Stairs/Vest.	315	SF	6	10+ years	
	Water Closet	North side of Aud. Stairs/Vest.	1	EA	7	6-10 years	
	Accessories	Room 118	46	SF	7	6-10 years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations.
	Benches	Room 118	5	LF	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations.
	Ceiling - Exposed	Room 118	46	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 118	1	EA	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations.
	Floor - Tile Ceramic/ Porcelain	Room 118	46	SF	7	10+ years	
	Lavatory	Room 118	1	EA	7	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations.
	Lighting - Pendent/Surface	Room 118	1	EA	7	6-10 years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations.
	Walls - Plaster/Drywall	Room 118	175	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Room 118	100	SF	7	10+ years	
	Water Closet	Room 118	1	EA	7	10+ years	
	Accessories	South side of Aud. Stairs/Vest,	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	South side of Aud. Stairs/Vest,	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	South side of Aud. Stairs/Vest,	1	EΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	South side of Aud. Stairs/Vest,	45	SF	7	10+ years	
	Floor Drain	South side of Aud. Stairs/Vest,	1	EA	7	10+ years	
	Lavatory	South side of Aud. Stairs/Vest,	1	EA	7	10+ years	
	Lighting - Pendent/Surface	South side of Aud. Stairs/Vest,	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	South side of Aud. Stairs/Vest,	252	SF	5	10+ years	
	Water Closet	South side of Aud. Stairs/Vest,	1	EA	4	0-1 year	Not in use

Campus Name: Bell Page : 15 of 44 Assessment Date: 07/27/2021



Catego	Category : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	743	SF	5	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Carpet	1st Floor	743	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	26	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	16	LF	6	6-10 years	
	Storage/ Closet	1st Floor	18	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,098	SF	5	10+ years	Rank and/or Priority Replacement
	Traile Tractor/21/Trail	1001	1,000	٥.	Ū	ioi youro	(AKA RUL) changed to
							update/correct to match current
							observations.
							observations.
Classics	om #102 (Kindergarten)						
Classion	` ,	1st Floor	1	ГΛ	7	6.10 vooro	
	AC Units		1	EA LF	7	6-10 years	
	Casework	1st Floor	9		5	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	895	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	895	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,246	SF	6	10+ years	
Classroo	om #104 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	895	SF	5	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Carpet	1st Floor	895	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	25	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Storage/ Closet	1st Floor	75	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,213	SF	6	10+ years	
	vvalis - Flastel/Drywall	151 -1001	1,213	ЗF	O	10+ years	
Classroo	om #106 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	Library turned into classroom
	Ceiling - Lay-in	1st Floor	1,121	SF	7	10+ years	. ,
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
					-	,	

Campus Name: Bell Page : 16 of 44 Assessment Date: 07/27/2021



Catego	Category : Classroom		В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Carpet	1st Floor	1,121	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	6-10 years	
	Marker Board	1st Floor	25	LF	7	6-10 years	
	Storage/ Closet	1st Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,416	SF	7	10+ years	
Classroo	om #112 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	35	LF	5	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,024	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	1,024	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	28	ĒΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,446	SF	7	10+ years	
Classroo	om #115 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	23	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	700	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	700	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	11	EA	6	6-10 years	
	Marker Board	1st Floor	23	LF	7	6-10 years	
	Storage/ Closet	1st Floor	64	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,045	SF	7	10+ years	
Classroo	om #117 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	21	LF	5	10+ years	
	Ceiling - Lay-in	1st Floor	700	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	700	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	15	EA	6	6-10 years	
	Marker Board	1st Floor	23	LF	7	6-10 years	
	Storage/ Closet	1st Floor	64	SF	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,045	SF	6	10+ years	
_Classroo	m #118 (Special Education)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	5	10+ years	
	222310111	1001	10		J	.o. youro	



Catego	ry : Classroom		В	uilding	: Main		7730 N Oakley AVENUE, Chicago, IL 60616
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Ceiling - Lay-in	1st Floor	505	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	505	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	11	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	55	SF	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,008	SF	6	10+ years	
Classroo	om #119 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	. 21	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	700	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Carpet	1st Floor	700	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	15	EA	6	6-10 years	
	Marker Board	1st Floor	23	LF	7	6-10 years	
	Storage/ Closet	1st Floor	64	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,045	SF	6	10+ years	
Classroo	om #200 (at stair) (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	358	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	6-10 years	
	Floor - Tile	2nd Floor	358	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	ĒA	6	6-10 years	
	Marker Board	2nd Floor	13	LF	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	4	EA	6	6-10 years	
	Walls - Metal Panel	2nd Floor	442	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	434	SF	7	10+ years	
Classroo	om #200 North (Special Program)						
	AC Units	Balcony	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Balcony	233	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Balcony	1	ĒΑ	6	6-10 years	
	Floor - Carpet	Balcony	233	SF	6	6-10 years	
	Lighting - Pendent/Surface	Balcony	6	ĒΑ	7	6-10 years	
	Marker Board	Balcony	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	Balcony	740	SF	6	10+ years	
Classroo	om #200 South (Special Program)						
	· · · · · · · · · · · · · · · · · · ·						

Campus Name: Bell Page : 18 of 44 Assessment Date: 07/27/2021



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	Balcony	1	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	Balcony	233	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Balcony	1	EA	6	6-10 years	
	Floor - Tile/Sheet	Balcony	233	SF	7	6-10 years	
	Lighting - Pendent/Surface	Balcony	4	EΑ	7	6-10 years	
	Marker Board	Balcony	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	Balcony	740	SF	6	10+ years	
Classroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	10+ years	
				LF			
	Chalk Board Doors - Transom Window	2nd Floor 2nd Floor	12 9	SF	4 6	2-5 years	
					_	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	34	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,153	SF	7	10+ years	
Classroc	om #202 (Other Instructional Use)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Carpet	3rd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	26	EΑ	6	6-10 years	
	Marker Board	3rd Floor	34	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,131	SF	6	10+ years	
Classroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	820	SF	6	•	
	Doors - Transom Window			SF SF	6	10+ years	
		2nd Floor	9		_	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	37	LF SF	7	6-10 years	
	Storage/ Closet	2nd Floor	72		7	6-10 years	

Campus Name: Bell Page : 19 of 44 Assessment Date: 07/27/2021



Catego	ry : Classroom		В	uilding	: Main	_		
_						Recommend	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	2nd Floor	1,131	SF	6	10+ years		
Classroc	m #204A &204B (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	6	6-10 years		
	Ceiling - Lay-in	2nd Floor	820	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years		
	Floor - Carpet	2nd Floor	820	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years		
	Marker Board	2nd Floor	37	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	72	SF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,131	SF	6	10+ years		
Classroo	nm #205 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Carpet	2nd Floor	820	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	2-5 years		
	Marker Board	2nd Floor	37	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	75	SF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,131	SF	7	10+ years		
Classroo	om #206 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years		
	Floor - Carpet	2nd Floor	820	SF	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years		
	Marker Board	2nd Floor	22	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	75	SF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,131	SF	6	10+ years		
Classron	nm #208 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor 2nd Floor	9	LF	6	6-10 years		
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	820	SF	6	10+ years		
					_	•		
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years		

Campus Name: Bell Page : 20 of 44 Assessment Date: 07/27/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	2-5 years	
	Marker Board	2nd Floor	37	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,259	SF	6	10+ years	
Classroo	m #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	622	SF	5	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor 2nd Floor	37	LF	7	6-10 years	
		2nd Floor 2nd Floor	75	SF	7		
	Storage/ Closet			SF SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,457	SF	,	10+ years	
Classroo	m #211 (at stair) (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	358	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Carpet	2nd Floor	358	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Metal Panel	2nd Floor	441	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	441	SF	7	10+ years	
Classroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor 2nd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	2-5 years	
	Marker Board	2nd Floor 2nd Floor	37	LF	7	•	
				SF		6-10 years	
	Storage/ Closet	2nd Floor	75		7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,259	SF	6	10+ years	
	m #213 (Regular Classroom)						

Campus Name: Bell Page : 21 of 44 Assessment Date: 07/27/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	21	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	636	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	6-10 years	
	Floor - Carpet	2nd Floor	636	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	6-10 years	
	Marker Board	2nd Floor	23	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	64	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,045	SF	7	6-10 years	
Classroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	820	SF	6	•	
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	21	EA	6	6-10 years	
						6-10 years	
	Marker Board	2nd Floor	37 75	LF	7	6-10 years	
	Storage/ Closet	2nd Floor		SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,131	SF	7	10+ years	
lassroc	om #215 (Computer Lab)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	21	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,275	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	1,275	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	46	EA	6	6-10 years	
	Marker Board	2nd Floor	23	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	150	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,495	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
lassroo	om #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	820	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor 2nd Floor	820	SF	6	•	
	Floor - Carper	211U F1001	620	SF	O	6-10 years	

Page : 22 of 44 Campus Name: Bell Assessment Date: 07/27/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	6-10 years	
	Marker Board	2nd Floor	37	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,131	SF	7	10+ years	
Classroo	m #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	2-5 years	
	Ceiling - Lay-in	2nd Floor	626	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	5	1-2 years	Water stain
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	6-10 years	
	Floor - Carpet	2nd Floor	636	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	6	2-5 years	
	Marker Board	2nd Floor	37	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,259	SF	6	10+ years	
	walle I lactor, 21, wall	2110 1 1001	1,200	O.	Ü	101 yours	
Classroo	m #219 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	636	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	636	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	2-5 years	
	Marker Board	2nd Floor	34	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	64	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,045	SF	6	6-10 years	
Classroo	m #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Carpet	3rd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	6-10 years	
	Marker Board	3rd Floor	37	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,131	SF	7	10+ years	
	Hadion Diff Wall	0.0.1001	1,101	٥.	•	.o. youro	
Classroo	m #302 (Regular Classroom)						

Campus Name: Bell Page : 23 of 44 Assessment Date: 07/27/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	820	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	6-10 years	
	Marker Board	3rd Floor	37	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,131	SF	7	10+ years	
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Quantity changed to update/correct to match current observations.
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	observations. Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations.
	Floor - Carpet	3rd Floor	820	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	21	ĒΑ	6	2-5 years	
	Marker Board	3rd Floor	37	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,131	SF	7	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	820	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	2-5 years	
	Marker Board	3rd Floor	37	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,131	SF	6	10+ years	
Classroo	om #305 (Regular Classroom)						

Page : 24 of 44 Campus Name: Bell Assessment Date: 07/27/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	6-10 years	
	Floor - Carpet	3rd Floor	800	SF	7	6-10 years	
	Floor - Carpet	3rd Floor	20	SF	5	2-5 years	Torn carpet
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	6-10 years	Tom carpor
	Marker Board	3rd Floor	37	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,131	SF	6		
	walls - Plaster/Drywall	31d F1001	1,131	SF	б	10+ years	
Classroo	om #306A & 306B (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	820	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	6-10 years	
	Floor - Carpet	3rd Floor	820	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	9	EA	6	6-10 years	
	Marker Board	3rd Floor	37	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7		
				SF SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,131	SF	,	10+ years	
Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	358	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	6	6-10 years	
	Floor - Carpet	3rd Floor	358	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	6	6-10 years	
	Marker Board	3rd Floor	13	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	822	SF	7	6-10 years	
Ol	// // // // // // // // // // // // //						
Classroo	om #308 (Regular Classroom)	0.15				0.40	
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Carpet	3rd Floor	820	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	2-5 years	
				LF			

Campus Name: Bell Page : 25 of 44 Assessment Date: 07/27/2021



Catego	ry : Classroom		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	3rd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,259	SF	7	10+ years	
Classroo	m #309 (Multi Purpose Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Room was not found in existing data
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	395	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Floor - Carpet	3rd Floor	395	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	10	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	975	SF	7	10+ years	
Classroo	m #310 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	39	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	7	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	Rank and/or Priority Replacement
					·	2 o youro	(AKA RUL) changed to update/correct to match current observations.
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	820	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	2-5 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,259	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	6-10 years	
Classroo	m #311 (at stair) (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	357	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Carpet	3rd Floor	357	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	6	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	808	SF	6	10+ years	
Classroo	m #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	

Campus Name: Bell Page : 26 of 44 Assessment Date: 07/27/2021



Catego	ry : Classroom		В	uilding	: Main		730 N Gandy AVENGE, Officago, 12 00010
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	820	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	815	SF	7	10+ years	
	Floor - Tile	3rd Floor	5	SF	5	1-2 years	Chipped tile
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	6-10 years	• •
	Marker Board	3rd Floor	37	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,289	SF	7	10+ years	
_Classroo	om #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	636	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Carpet	3rd Floor	636	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	23	EA	6	6-10 years	
	Marker Board	3rd Floor	23	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	64	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,070	SF SF	7 7	•	
	Walls - Flastel/Drywall	31d F1001	1,070	SI	,	10+ years	
_Classroo	om #313A (Special Education)						
	Ceiling - Lay-in	3rd Floor	169	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Carpet	3rd Floor	169	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	4	EA	6	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Walls - Metal Panel	3rd Floor	603	SF	6	6-10 years	
_Classroo	om #314A (Special Program)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	400	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Carpet	3rd Floor	400	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	11	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	550	SF	7	10+ years	
Classroo	om #314B (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	2-5 years	
	AC Office	014 1 1001	ı	LA	,	2 0 years	

Campus Name: Bell Page : 27 of 44 Assessment Date: 07/27/2021



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	40	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	944	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	944	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	6-10 years	
	Student Lockers - Two Tiers	3rd Floor	15	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	946	SF	6	10+ years	
	Work Sink	3rd Floor	4	EA	7	6-10 years	
lassroc	om #315 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	2-5 years	
	Casework	3rd Floor	21	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	636	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Carpet	3rd Floor	616	SF	7	6-10 years	
	Floor - Carpet	3rd Floor	20	SF	5	1-2 years	Torn carpet
	Lighting - Pendent/Surface	3rd Floor	23	EA	6	6-10 years	Tom carpet
			23	LF	7	6-10 years	
	Marker Board Storage/ Closet	3rd Floor 3rd Floor	64	SF	, 5	6-10 years	
		3rd Floor	_	SF SF	5 6		
	Walls - Plaster/Drywall	310 F1001	1,045	SF	b	10+ years	
lassroc	om #316 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	2-5 years	
	Casework	3rd Floor	21	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	636	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Carpet	3rd Floor	616	SF	7	6-10 years	
	Floor - Carpet	3rd Floor	20	SF	5	1-2 years	Torn carpet
	Lighting - Pendent/Surface	3rd Floor	15	EA	6	6-10 years	•
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	64	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,045	SF	6	10+ years	
lassroc	om #317 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	21	LF	6	6-10 years	
	Ceiling - Splined	3rd Floor	636	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Carpet	3rd Floor	616	SF	7	•	
	rioui - Gaipet	314 F1001	010	SF	,	6-10 years	

Campus Name: Bell Page : 28 of 44 Assessment Date: 07/27/2021



Catogo	ry : Classroom		R	uilding	· Main		730 N Carley AVENUE, Officago, IE 000 To
Catego	iy . Classiooni		<u> </u>	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Floor - Carpet	3rd Floor	20	SF	5	1-2 years	Torn carpet
	Lighting - Pendent/Surface	3rd Floor	23	EA	6	6-10 years	Tom carpet
	Marker Board	3rd Floor	23	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	64	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,045	SF	7	•	
	Walls - Plastel/Drywall	310 F1001	1,045	SF	,	10+ years	
lassroo	m #318 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	636	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
		3rd Floor		SF	7		
	Floor - Carpet		636	Sr EA		6-10 years	
	Lighting - Pendent/Surface	3rd Floor	15		6	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	64	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,045	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
lassroo	m #319 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	21	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	636	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Wood	3rd Floor	636	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	6	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	64	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,045	SF	6	10+ years	
	Work Sink	3rd Floor	1,045	EA	7	6-10 years	
						- · · · · · · · · · · · · · · · · · · ·	
atego	ry : Interior		В	uilding	: Main	Dagammand	
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor						•	
	Ceiling - Lay-in	1st Fl Main Corridor	2,900	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Fl Main Corridor	2,000	SF	7	10+ years	
	Doors - Transom Window	1st Fl Main Corridor	630	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Fl Main Corridor	24	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Fl Main Corridor	2	EA	7	6-10 years	
	Floor - Carpet	1st Fl Main Corridor	4,900	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Fl Main Corridor	4,900	EA	7	6-10 years	
	Lighting - Fendent/Surface	151 FT MAIN CONTON	30	EA	1	o- to years	

Campus Name: Bell Page : 29 of 44 Assessment Date: 07/27/2021



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Fl Main Corridor	7,804	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st flr Auditorium Entries	360	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr Auditorium Entries	260	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st flr Auditorium Entries	2	EA	7	2-5 years	
	Walls - Plaster/Drywall	1st flr Auditorium Entries	847	SF	7	10+ years	
	Ceiling - Lay-in	2nd Fl Main Corridor	4,358	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Fl Main Corridor	500	SF	7	10+ years	
	Floor - Carpet	2nd Fl Main Corridor	4,858	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Fl Main Corridor	36	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Fl Main Corridor	7,782	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd flr Aud. Balcony Entries	332	SF	7	10+ years	
	Floor - Carpet	2nd flr Aud. Balcony Entries	332	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd flr Aud. Balcony Entries	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd flr Aud. Balcony Entries	1,016	SF	7	10+ years	
	Ceiling - Lay-in	3rd flr Gym Entries & Vestibules	218	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd flr Gym Entries & Vestibules	332	SF	6	10+ years	
	Doors - Transom Window	3rd flr Gym Entries & Vestibules	90	SF	7	6-10 years	
	Floor - Carpet	3rd flr Gym Entries & Vestibules	550	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd flr Gym Entries & Vestibules	10	EA	7	10+ years	
	Student Lockers - One Tier	3rd flr Gym Entries & Vestibules	23	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd flr Gym Entries & Vestibules	1,632	SF	7	10+ years	
	Ceiling - Lay-in	Main 3rd Floor Corridor	4,858	SF	7	10+ years	
	Floor - Carpet	Main 3rd Floor Corridor	4,858	SF	7	6-10 years	
	Lighting - Pendent/Surface	Main 3rd Floor Corridor	36	EA	7	2-5 years	
	Walls - Plaster/Drywall	Main 3rd Floor Corridor	7,782	SF	7	10+ years	
	Doors - Steel Doors incl hw	Mechanical/Service Room Doors	4	EA	7	6-10 years	
	Doors - Wood Doors include hw	Mechanical/Service Room Doors	9	EA	7	6-10 years	
afety							
	Security Cameras	1st Floor	10	EA	7	6-10 years	Quantity changed to update/correct t
							match current observations.
airs							
	Ceiling - Lay-in	Central North Stair	340	SF	7	10+ years	
	Ceiling - Lay-in	Central North Stair	10	SF	4	1-2 years	Water stain
	Ceiling - Plaster/Drywall	Central North Stair	450	SF	7	10+ years	
	Floor - Carpet	Central North Stair	175	SF	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	Central North Stair	180	SF	7	10+ years	
	Floor - Tile Quarry	Central North Stair	175	SF	7	10+ years	
	Handrails	Central North Stair	204	LF	7	6-10 years	
	Lighting - Pendent/Surface	Central North Stair	8	EA	7	6-10 years	
	Stairs - Concrete	Central North Stair	528	LF	7	10+ years	
	Walls - Plaster/Drywall	Central North Stair	2,925	SF	7	10+ years	
	Ceiling - Lay-in	Central South Stair	350	SF	7	10+ years	



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Central South Stair	450	SF	7	10+ years	
	Floor - Carpet	Central South Stair	175	SF	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	Central South Stair	180	SF	7	10+ years	
	Floor - Tile Quarry	Central South Stair	175	SF	7	10+ years	
	Handrails	Central South Stair	204	LF	7	6-10 years	
	Lighting - Pendent/Surface	Central South Stair	10	EA	7	6-10 years	
	Stairs - Concrete	Central South Stair	528	LF	7	6-10 years	
	Walls - Plaster/Drywall	Central South Stair	2,761	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North & South Auditorium Vestibule Stairs	523	SF	7	10+ years	
	Floor - Asphalt	North & South Auditorium Vestibule Stairs	32	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	North & South Auditorium Vestibule Stairs	289	SF	7	10+ years	
	Handrails	North & South Auditorium Vestibule Stairs	70	LF	7	10+ years	
	Lighting - Pendent/Surface	North & South Auditorium Vestibule Stairs	3	EA	7	6-10 years	
	Lighting - Wall Mounted	North & South Auditorium Vestibule Stairs	2	EA	7	6-10 years	
	Stairs - Asphalt	North & South Auditorium Vestibule Stairs	203	LF	7	10+ years	
	Walls - Plaster/Drywall	North & South Auditorium Vestibule Stairs	2,113	SF	7	10+ years	
	Walls - Plaster/Drywall	North & South Auditorium Vestibule Stairs	100	SF	4	0-1 year	Peeling
	Ceiling - Lay-in	North Stair	100	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North Stair	350	SF	7	10+ years	
	Floor - Carpet	North Stair	175	SF	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	North Stair	180	SF	7	10+ years	
	Floor - Tile Quarry	North Stair	175	SF	7	10+ years	
	Handrails	North Stair	204	LF	7	6-10 years	
	Lighting - Pendent/Surface	North Stair	9	EA	7	6-10 years	
	Stairs - Concrete	North Stair	528	LF	7	10+ years	
	Walls - Plaster/Drywall	North Stair	2,761	SF	7	10+ years	
	Ceiling - Lay-in	South Stair	200	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South Stair	600	SF	7	10+ years	
	Floor - Carpet	South Stair	175	SF	7	6-10 years	
	Floor - Concrete Epoxy/ Painted	South Stair	180	SF	7	10+ years	
	Floor - Tile Quarry	South Stair	175	SF	7	10+ years	
	Handrails	South Stair	204	LF	7	6-10 years	
	Lighting - Pendent/Surface	South Stair	8	EA	7	6-10 years	
	Stairs - Concrete	South Stair	528	LF	7 7	10+ years	
	Walls - Plaster/Drywall	South Stair	2,761	SF	7	10+ years	
	vvalis - Mastel/Drywali	Jouin Stail	2,701	SF.	,	10+ years	



Category : Interior		Building : Main
		Recommend
Group Item - Type	Location	Quantity UOM Rank Replacement Comments
Vertical Conveyance		
Elevator - Hydraulic Elevator	1st Floor	1 EA 7 6-10 years







Category : Exterior **Building: Addition**

alegui	y . Exterior		Building . Addition					
0	V T	Lagation	0	LIONA	Danis	Recommend	0	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance								
	Exterior Doors - Store Front	5	2	EA	7	10+ years		
	Exterior Doors - Store Front	6	2	EA	7	10+ years		
	Entrance Control - Audio and Video	7	1	EA	7	10+ years		
	Exterior Doors - Exterior Steel Door	7	2	EA	7	10+ years		
oundatio	on.							
oundan	Foundation - Concrete	Entire Building	436	LF	7	10+ years		
	Superstructure - Metal Deck/ Concrete	Entire Building	19,882	SF	7	10+ years		
	Topping	Little Ballaling	13,002	Oi	,	10+ years		
	Topping							
ghting								
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	6	10+ years		
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	6	10+ years		
oof Sys	tom							
JUI UYS	Access Ladder - Metal	High	1	EA	7	10+ years		
	Chimney - Metal Flue	High	5	LF	7	10+ years		
	Coping - Metal	High	241	LF	7	10+ years		
	Downspouts - Interior Downspouts	High	73	LF	7	10+ years		
	Parapet - 16" - 30" Height		73 241	LF	7			
	Roof - Modified Bitumen	High		SF	7	10+ years		
		High	11,985			10+ years		
	Roof Hatch - Metal	High	1	EA	7	10+ years		
	Roof Structure - Steel / Metal Deck/	High	11,985	SF	7	10+ years		
	Concrete Topping		101		_	4.0		
	Coping - Metal	Lower	134	LF . –	7	10+ years		
	Downspouts - Interior Downspouts	Lower	17	LF	7	10+ years		
	Roof - Modified Bitumen	Lower	1,092	SF	7	10+ years		
	Roof Structure - Steel / Metal Deck/	Lower	1,092	SF	7	10+ years		
	Concrete Topping							
alls								
	Exterior Walls - Brick	Entire Building	6,517	SF	7	10+ years		
	Exterior Walls - Prefabricated Metal Panel	Entire Building	3,721	SF	7	10+ years		
	Wall	-				-		
/indows								
	Curtain wall - Glazed Double Pane	Entire Building	465	SF	7	10+ years		
	Curtain wall - Louver	Entire Building	79	SF	7	10+ years		
	Lintels - Steel	Entire Building	329	ĹF	7	10+ years		
	Storefront Windows	Entire Building	1,601	SF	7	10+ years		
		3	,			,		



Category : Exterior			В	Building : Addition					
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Windows - Casement Aluminum Double- pane	Entire Building	216	SF	7	10+ years			
Catego	ry : Electrical		В	uilding	: Additio	on			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Emerger	ncy System								
· ·	Exit Signs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years			
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years			
	Security System - CCTV	Entire Building	19,882	SF	6	6-10 years			
	Security System - Intrusion Detection	Entire Building	19,882	SF	6	6-10 years			
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,806	SF	6	6-10 years			
	Emergency A/C Power - Multipurpose Room	Entire Building	3,927	SF	7	6-10 years			
Main Se	rvice								
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	7	10+ years			
	PA System	Entire Building	19,882	SF	6	6-10 years			
Power D	istribution								
	Lighting and Power Panels - 100 A	Entire Building	5	EA	7	6-10 years			
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	6-10 years			
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years			
	Main Distribution Panels - Less than 400 amp	Entire Building	2	EA	7	6-10 years			

Category: Fire Protection Building: Addition

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Fire Alar	m						
	Fire Alarm_System Fire Pump Controller	Entire Building Entire Building	19,882 1	SF EA	7 7	6-10 years 6-10 years	
Pump Ro	oom Assembly						
•	Fire Pump - Less than 25hp	1st Floor	1	EA	7	6-10 years	
	Jockey Pump	1st Floor	1	EA	7	6-10 years	
_Sprinkler	System						
	Dry Sprinkler System	1st Floor	19,882	SF	7	6-10 years	

Campus Name: Bell Page : 34 of 44 Assessment Date: 07/27/2021



Category : Mechanical		Building : Addition						
	_					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Air Cond								
	Heat Pump- Floor Mounted- Electric Heating & DX Cooling- Self Contained Air Cooled Compressor - Less than 3 tons	Roof	1	EA	7	6-10 years		
	Chiller-Air Cooled-Scroll Type-Roof Mounted - 50 - 100 tons	Roof	1	EA	7	10+ years		
Air Hand	ling Systems							
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 6000- 10000 cfm	Entire Building	1	EA	7	10+ years	Serves the entire 2nd floor	
	Air Intake	Entire Building	1	EA	7	10+ years		
	VAV Box	Entire Building	5	EA	7	6-10 years		
	Fan Coil Unit- Celing Mounted - Electric	MDF Room	1	EA	7	6-10 years		
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 10001- 15000 cfm	Mechanical Room	1	EA	7	10+ years	Serves the multipurpose room and the first floor	
	Air Intake	Mechanical Room	1	EA	7	10+ years		
	VAV Box	Mechanical Room	4	EA	7	10+ years		
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	7	6-10 years	Serves ahu 2	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Room	1	EA	7	6-10 years	Serves ahu 1	
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Roof	1	EA	7	10+ years		
Boiler Sy	estems							
,	Chemical Pot Feeder	Mechanical Room	1	EA	7	10+ years		
	Glycol Feed System	Mechanical Room	1	EA	7	10+ years		
Heating	Devices							
	Radiator Panels - Hot Water	Entire Building	17	EA	7	10+ years		
	Cabinet Heaters - With Hot Water Coil	Entire Building	7	EA	7	10+ years		
	Unit Heater - Electric	Entire Building	1	EA	7	6-10 years		
	Unit Heater - Hot Water	Mechanical Room	1	EA	7	6-10 years		
Mechani	cal Plumbing							
	Hydronic Supply and Return - Steel	Entire Building	300	LF	7	10+ years		
	Hot Water Pump - Less than 10	Mechanical Room	2	EA	7	6-10 years		
	Dual Temperature Pump - Less than 10	Mechanical Room	2	EA	7	6-10 years		

Page : 35 of 44 Campus Name: Bell Assessment Date: 07/27/2021



Catego	ry : Mechanical		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	DDC System	Entire Building	19,882	SF	7	10+ years	
	Electric Thermostat	Entire Building	8	EA	6	6-10 years	Quantity changed to update/correct to match current observations.
	Thermostats - DDC	Entire Building	19	EA	7	6-10 years	
_Ventilati	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EΑ	7	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	6-10 years	Rank and/or Priority Replacement (AKA RUL) changed to update/correct to match current observations.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	7	6-10 years	Quantity changed to update/correct to match current observations.
	Roof Mounted Duct Work	Entire Building	50	LF	7	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	7	6-10 years	No Ansul system in place. Quantity changed to update/correct to match current observations.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	7	10+ years	Quantity changed to update/correct to match current observations.

Building: Addition

Category: Plumbing

Croun	Itom Tuno	Lagatian	Quantitu	HOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Pump Room	2	EA	7	10+ years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	19,882	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	19,882	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	19,882	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	19,882	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	19,882	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	19,882	SF	7	10+ years	
	Sanitary Piping	Entire Building	19,882	SF	7	10+ years	
	Storm Piping	Entire Building	19,882	SF	7	10+ years	
	Vent Piping	Entire Building	19,882	SF	7	10+ years	
Pumps							
·	Pumps - Domestic Booster Pump-Duplex	Pump Room	1	EA	7	6-10 years	Rank and/or Priority Replacement

Campus Name: Bell Page : 36 of 44 Assessment Date: 07/27/2021



Alexander Graham Bell Elementary School

3730 N Oakley AVENUE, Chicago, IL 60618

Category : Plumbing Building : Addition

Recommend

Group Item - Type Location Quantity UOM Rank Replacement Comments

(AKA RUL) changed to

update/correct to match current

observations.

Category : Room Building : Addition

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	trative Suites/Offices						
	Ceiling - Lay-in	1st flr rm #125 - Kitchen Office	90	SF	7	10+ years	
	Doors - Side-lite	1st flr rm #125 - Kitchen Office	15	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st flr rm #125 - Kitchen Office	1	EA	7	6-10 years	
	Floor - Tile/Sheet	1st flr rm #125 - Kitchen Office	90	SF	7	6-10 years	
	Lighting - Lay-in	1st flr rm #125 - Kitchen Office	1	EA	7	2-5 years	
	Power Distribution	1st flr rm #125 - Kitchen Office	8	EA	7	6-10 years	
	Walls - Concrete Block	1st flr rm #125 - Kitchen Office	292	SF	7	10+ years	
_Gvmnas	ia						
-	Ceiling - Exposed	1st flr rm #123	3,927	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st flr rm #123	4	EA	7	6-10 years	
	Floor - Sport Flooring	1st flr rm #123	3,927	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st flr rm #123	12	EA	7	2-5 years	
	Scoreboards	1st flr rm #123	1	EA	7	2-5 years	
	Storage/ Closet	1st flr rm #123	420	SF	7	6-10 years	
	Walls - Concrete Block	1st flr rm #123	4,263	SF	7	10+ years	
	Walls - Plaster/Drywall	1st flr rm #123	1,284	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	1st flr rm #123C	940	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st flr rm #123C	3	EA	7	6-10 years	
	Floor - Tile Quarry	1st flr rm #123C	940	SF	7	6-10 years	
	Lighting - Lay-in	1st flr rm #123C	10	EA	7	6-10 years	
	Storage/ Closet	1st flr rm #123C	172	SF	7	6-10 years	
	Walls - Concrete Block	1st flr rm #123C	1,467	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st flr rm 123B - Servery	688	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st flr rm 123B - Servery	2	ĒΑ	7	6-10 years	
	Floor - Tile/Sheet	1st flr rm 123B - Servery	688	SF	7	6-10 years	
	Lighting - Lay-in	1st flr rm 123B - Servery	12	EA	7	6-10 years	
	Serving Line	1st flr rm 123B - Servery	35	LF	7	6-10 years	
	Walls - Concrete Block	1st flr rm 123B - Servery	1,012	SF	7	10+ years	
MDF ID	F						

Campus Name: Bell Page: 37 of 44 Assessment Date: 07/27/2021



Category : Room			B	on			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	6-10 years	
	Finishes	2nd Floor	340	SF	7	6-10 years	
	Other Cooling Unit	2nd Floor	1	EA	7	10+ years	Fan coil unit
4 l :- i	ant/ Comiting December						
<u>lecnani</u>	cal/ Service Rooms	4 (5)		05		40	
	Janitor's Closet	1st Floor	30	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	1,736	SF	7	10+ years	
	Storage Room	1st Floor	168	SF	7	10+ years	
Restroor	n						
	Accessories	1st Flr Mens	60	SF	7	6-10 years	
	Ceiling - Lay-in	1st Flr Mens	60	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Flr Mens	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Flr Mens	60	SF	7	10+ years	
	Floor Drain	1st Flr Mens	1	EA	7	10+ years	
	Hand Dryer	1st Flr Mens	1	EA	7	6-10 years	
	Lavatory	1st Flr Mens	1	EA	7	6-10 years	
	Lighting - Lay-in	1st Fir Mens	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Fir Mens	282	SF	7	10+ years	
	Water Closet	1st Fir Mens	1	EA	7	6-10 years	
	Accessories	1st Flr Womens	60	SF	7	6-10 years	
	Ceiling - Lay-in	1st Flr Womens	60	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Flr Womens	1	ĒΑ	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Flr Womens	60	SF	7	6-10 years	
	Floor Drain	1st FIr Womens	1	EΑ	7	10+ years	
	Hand Dryer	1st Flr Womens	1	EΑ	7	6-10 years	
	Lavatory	1st Flr Womens	1	EA	7	6-10 years	
	Lighting - Lay-in	1st Fir Womens	1	EΑ	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Fir Womens	282	SF	7	10+ years	
	Water Closet	1st Fir Womens	1	EA	7	6-10 years	
	Accessories	Unisex Accessible A - 2nd flr North	55	SF	7	6-10 years	
	Ceiling - Lay-in	Unisex Accessible A - 2nd fir North	55	SF	7	10+ years	
	Doors - Steel Doors incl hw	Unisex Accessible A - 2nd fir North	1	EA	7	6-10 years	
			55	SF	7	,	
	Floor - Tile Ceramic/ Porcelain Floor Drain	Unisex Accessible A - 2nd flr North Unisex Accessible A - 2nd flr North	55 1	SF EA	7 7	6-10 years	
			1	EA EA	7	10+ years	
	Hand Dryer	Unisex Accessible A - 2nd flr North				2-5 years	
	Lavatory	Unisex Accessible A - 2nd flr North	1	EΑ	7	6-10 years	
	Lighting - Lay-in	Unisex Accessible A - 2nd flr North	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Unisex Accessible A - 2nd flr North	235	SF	7	10+ years	
	Water Closet	Unisex Accessible A - 2nd flr North	1	EA	7	6-10 years	
	Accessories	Unisex Accessible B - 2nd Flr South	55	SF	7	6-10 years	
	Ceiling - Lay-in	Unisex Accessible B - 2nd Flr South	55	SF	7	10+ years	
	Doors - Steel Doors incl hw	Unisex Accessible B - 2nd Flr South	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Unisex Accessible B - 2nd Flr South	55	SF	7	6-10 years	

Page : 38 of 44 Campus Name: Bell Assessment Date: 07/27/2021



Category : Room			Building : Addition				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	Unisex Accessible B - 2nd Flr South	1	EA	7	10+ years	
	Hand Dryer	Unisex Accessible B - 2nd Flr South	1	EA	7	2-5 years	
	Lavatory	Unisex Accessible B - 2nd Flr South	1	EA	7	6-10 years	
	Lighting - Lay-in	Unisex Accessible B - 2nd Flr South	1	ΕA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Unisex Accessible B - 2nd Flr South	235	SF	7	10+ years	
	Water Closet	Unisex Accessible B - 2nd Flr South	1	EA	7	6-10 years	
Catego	ry : Classroom		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	OOW	Naiik	Replacement	Comments
Jassroc	om #223 (Music Room)	0.151				0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	6-10 years	
	Ceiling - Exposed	2nd Floor	326	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	980	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	30	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	6-10 years	
	Floor - Tile Quarry	2nd Floor	1,306	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Sound Panels	2nd Floor	22	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	170	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	570	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,672	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroc	om #224 (Art Room)						
	AC Units	2nd Floor	1	EA	7	2-5 years	
	Casework	2nd Floor	27	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,010	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	15	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	1,010	SF	7	6-10 years	
	Kiln	2nd Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	2-5 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	250	SF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	175	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,010	SF	7	10+ years	
	Work Sink	2nd Floor	1,010	EA	7	6-10 years	
						,	
Classroc	om #225 (Science)						
	AC Units	2nd Floor	1	EA	7	6-10 years	

Campus Name: Bell Page : 39 of 44 Assessment Date: 07/27/2021



Catego	Category : Classroom			Building : Addition				
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Casework	2nd Floor	30	LF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	1,208	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	15	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	6-10 years		
	Eye Wash Station	2nd Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	1,208	SF	7	10+ years		
	Gas Line	2nd Floor	1	EΑ	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	2-5 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	190	SF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	850	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	688	SF	7	10+ years		
	Work Sink	2nd Floor	3	EA	7	6-10 years		

Building: Addition Category : Interior

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	820	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	12	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	6-10 years	
	Floor - Tile Quarry	1st Floor	428	SF	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	392	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	9	EA	7	2-5 years	
	Walls - Concrete Block	1st Floor	2,256	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	866	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	6	EA	7	6-10 years	
	Floor - Carpet	2nd Floor	866	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	4	EA	7	2-5 years	
	Student Lockers - One Tier	2nd Floor	32	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,598	SF	7	10+ years	
Stairs							
	Ceiling - Lay-in	North and South Stairs	730	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	North and South Stairs	330	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	North and South Stairs	580	SF	7	10+ years	
	Floor - Tile/Sheet	North and South Stairs	210	SF	5	6-10 years	
	Handrails	North and South Stairs	66	LF	7	6-10 years	
	Lighting - Lay-in	North and South Stairs	6	EA	7	2-5 years	
	Lighting - Wall Mounted	North and South Stairs	14	EA	7	6-10 years	
	Stairs - Rubber	North and South Stairs	354	LF	7	6-10 years	
	Walls - Concrete Block	North and South Stairs	4,192	SF	7	10+ years	







Category : Site **Building: Site**

Catego	ry : Site		В	ullaing	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Synthetic	North East	10,868	SF	7	10+ years	
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	7	10+ years	
_Fencing							
	Fencing - Chain Link	Entire Site	118	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	36	LF	5	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	1,027	LF	7	10+ years	
	Fencing - Old Standard Ornamental	Entire Site	726	LF	7	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	120	LF	7	6-10 years	Quantity changed to update/correct to
							match current observations.
Landsca	no						
Lanusca	Benches	Entire Site	31	EA	7	6-10 years	
	Landscape - Grass	Entire Site	5,074	SF	6	6-10 years	
	Landscape - Grass Landscape - Hardscape- Concrete	Entire Site	16,577	SF	7	10+ years	
	Landscape - Mulch	Entire Site	11,200	SF	6	6-10 years	
	Parkway trees	Entire Site	32	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	18,923	SF	7	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	31,910	SF	6	6-10 years	
	Trash Receptacles	Entire Site	12	EA	7	6-10 years	
	Hasii Neceptacies	Littile Site	12	LA	,	0-10 years	
Parking	Lot						
J	Surface - Concrete	West	6,200	SF	7	10+ years	Quantity changed to update/correct to
							match current observations.
	Trash Compactor	West	1	EA	7	10+ years	
	Trash Enclosure - Masonry	West	800	SF	7	10+ years	
Playgrou	und						
aygrot	Equipment - Pre K 3-5	Site Northwest	1	EA	7	6-10 years	
	Equipment - School Age 5-12	Site Northwest	. 1	EA	7	6-10 years	
	Surface - Poured Surface	Site Northwest	3,960	SF	7	6-10 years	
	Equipment - Pre K 3-5	West	3,300	EA	6	6-10 years	
	Surface - Square Rubber Mats	West	1,260	SF	4	0-1 year	Gaps
	Canado Oqualo Madol Mato	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1,200	51	7	o i youi	
Sidewall	KS						
	Sidewalks - Internal Walks	Entire Site	275	LF	7	10+ years	Quantity changed to update/correct to
						-	match current observations.



Alexander Graham Bell Elementary School

3730 N Oakley AVENUE, Chicago, IL 60618

Category : Site			В	uilding			
					_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	15,672	SF	6	10+ years	
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	Quantity changed to update/correct to match current observations.
	Marquee - Building Mounted Back Lighted	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	Quantity changed to update/correct to match current observations.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Bell Page : 42 of 44 Assessment Date: 07/27/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classicom Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		1	.	•	1	•	T	•	1
Computer Lab	Regular Classroom	2nd Floor	215	E215	1,425	320	160	Y	N
Kindergarten	Kindergarten	1st Floor	101	101	743	160	80	N	Υ
Kindergarten	Regular Classroom	1st Floor	102	102	895	197	99	N	N
Kindergarten	Regular Classroom	1st Floor	104	104	895	280	140	N	Υ
Kindergarten	Regular Classroom	1st Floor	112	112	1,024	240	120	N	Υ
Multi Purpose Room	Vacant	3rd Floor	309	309	395	62	31	Υ	N
Office	Vacant	2nd Floor	211 (at stair)	211	358	128	64	Y	Y
Other Instructional Use	Art Room	3rd Floor	202	202	895	197	99	Y	N
Regular Classroom	Regular Classroom	1st Floor	106	106 Library	1,121	280	140		
Regular Classroom	Regular Classroom	1st Floor	115	115	700	180	90	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	117	117	700	180	90	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	119	119	700	120	60	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	895	197	99	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	892	240	120	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204A &204B	204	892	240	120	Y	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	895	240	120	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	895	200	100	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	895	160	80	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	895	200	100	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	895	160	80	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	700	160	80	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	895	200	100	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	895	240	120	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	700	200	100	Y	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	700	160	80	Y	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	895	197	99	Y	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	895	197	99	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	895	240	120	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	895	240	120	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	895	197	99	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	306A & 306B	306	895	197	99	Y	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	358	64	32	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	308	308	895	160	80	Y	N
Regular Classroom	Regular Classroom	3rd Floor	312	312	895	160	80	Y	N
Regular Classroom	Regular Classroom	3rd Floor	313	313	700	140	70	Y	N



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	3rd Floor	315	315	700	160	80	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	316	316	700	160	80	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	317	317	700	160	80	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	318	318	700	160	80	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	319	319	700	160	80	Υ	N
Regular Classroom	Vacant	2nd Floor	200 (at stair)	200	358	128	64	N	N
Regular Classroom	Vacant	3rd Floor	311 (at stair)	311	357	56	29	Y	N
Science Classroom	Other Instructional Use	3rd Floor	314B	314B	944	240	120	Υ	N
Science Classroom	Regular Classroom	3rd Floor	310	310	895	200	100	Υ	N
Special Education	Special Education	1st Floor	118	118	505	120	60	Υ	Υ
Special Education	Store Room	3rd Floor	313A	N/A	169	0	0	N	N
Special Program	Regular Classroom	3rd Floor	314A	314A	400	56	29	Υ	N
Special Program	Special Program	Balcony	200 North	Aud. Balcony	233	12	6	N	N
Special Program	Special Program	Balcony	200 South	Aud. Balcony	233	12	6	N	N

Building : Addition										
Art Room	Art Room	2nd Floor	224	206	1,260	144	6	Υ	N	
Music Room	Music Room	2nd Floor	223	210	1,476	144	5	Υ	N	
Science	Science Lab Level 3	2nd Floor	225	204	1,398	180	5	Υ	N	