

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1960	2	63,929
Campus Total			63,929

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	Entrance 10.1 - North	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 5/D-North / Kitchen	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 6/E-North	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Entrance 6/E-North	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Entrance 6a	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 7/F-North	2	EA	7	10+ years	
	Entrance Control - Audio and Video	Entrance 8/G-West	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Entrance 8/G-West	2	EA	7	10+ years	
	Power Door Operator and Controls	Entrance 8/G-West	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 9A-NW	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Entrance 9A-NW	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 10/J-North	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	Exit 10/J-North	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	Exit 2/B-South / Gym	2	EA	7	10+ years	
	Exterior Stairs - Concrete	Exit 2/B-South / Gym	40	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Exit 2/B-South / Gym	28	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 3/B-South / Gym	2	EA	7	10+ years	
	Exterior Stairs - Concrete	Exit 3/B-South / Gym	40	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Exit 3/B-South / Gym	28	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Exit 4/C-West / Lunchroom	1	EA	6	6-10 years	
	Exterior Stairs - Stone	Exit 4/C-West / Lunchroom	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 9/H-NW	1	EA	7	10+ years	
	Entrance Control - Audio and Video	Main Entrance 1/A-SE	1	EA	6	6-10 years	
	Exterior Doors - Side lite	Main Entrance 1/A-SE	2	EA	6	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Doors - Store Front	Main Entrance 1/A-SE	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Main Entrance 1/A-SE	3	EA	7	10+ years	
	Power Door Operator and Controls	Main Entrance 1/A-SE	1	EA	7	10+ years	
Foundation							
	Foundation - Concrete	Entire Building	1,139	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	63,929	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	27	EA	7	10+ years	
Roof System							
	Access Ladder - Metal	Roof 1 - Main	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1 - Main	35	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1 - Main	5	LF	5	6-10 years	
	Coping - Metal	Roof 1 - Main	80	LF	6	6-10 years	
	Coping - Metal	Roof 1 - Main	755	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof 1 - Main	120	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof 1 - Main	80	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 1 - Main	23,715	SF	6	6-10 years	
	Roof Hatch - Metal	Roof 1 - Main	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 1 - Main	23,715	SF	7	10+ years	
	Access Ladder - Metal	Roof 2 - South	2	EA	7	10+ years	
	Coping - Metal	Roof 2 - South	420	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2 - South	65	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof 2 - South	8,100	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 2 - South	8,100	SF	7	10+ years	
	Access Ladder - Metal	Roof 3 - West	1	EA	7	10+ years	
	Chimney - Metal Flue	Roof 3 - West	20	LF	6	6-10 years	
	Coping - Metal	Roof 3 - West	275	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof 3 - West	30	LF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof 3 - West	8,480	SF	6	6-10 years	Patched roof
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 3 - West	8,480	SF	7	10+ years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	44	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	22,566	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,000	SF	6	10+ years	

Category : Exterior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	1,429	SF	7	10+ years	
	Exterior Walls - Stucco	Entire Building	2,300	SF	6	10+ years	
	Exterior Walls - Stucco	Entire Building	30	SF	6	10+ years	

Windows

	Guard - Guards perforated	Entire Building	1,000	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	5,900	SF	6	6-10 years	
	Lintels - Steel	Entire Building	1,140	LF	6	10+ years	
	Skylite - Lexan	Entire Building	80	SF	6	6-10 years	
	Windows - Louver	Entire Building	200	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	8,468	SF	6	6-10 years	

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Emergency System</u>							
	Emergency A/C Power - Corridors and Stairs	Entire Building	9,669	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,258	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	Entire Building	3,492	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,984	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	18	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	7	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	13	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Security System - CCTV	Entire Building	63,929	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	63,929	SF	5	6-10 years	

Main Service

	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	63,929	SF	7	6-10 years	New unit

Category : Electrical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Power Distribution</u>							
	Lighting and Power Panels - 100 A	Entire Building	10	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	

Category : Fire Protection
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Fire Alarm</u>							
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	16,961	SF	6	10+ years	
	Fire Alarm_System	Entire Building	63,929	SF	6	6-10 years	

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Air Conditioning</u>							
	Chemical Pot Feeder	Grade Mounted outside Mechanical Room	1	EA	6	10+ years	
	Chiller-Air Cooled-Scroll Type-Ground Mounted - 50 - 100 tons	Grade Mounted outside Mechanical Room	1	EA	5	6-10 years	
	Glycol Feed	Grade Mounted outside Mechanical Room	1	EA	6	10+ years	
	Pipes - Chilled Water Pipe- Galvanized	Grade Mounted outside Mechanical Room	200	LF	6	10+ years	
	Pressure Fill System	Grade Mounted outside Mechanical Room	1	EA	6	10+ years	The same with the one used for the boilers

Air Handling Systems

	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 10001-15000 cfm	Boiler Room	1	EA	6	6-10 years	One unit
	Air Intake	Boiler Room	1	EA	6	6-10 years	
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	2	EA	6	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 4000-8000 cfm	Gym	2	EA	7	10+ years	Units installed in 2015
	Air Intake	Gym	2	EA	6	10+ years	
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - Less than 6000 cfm	Mechanical Room	1	EA	6	6-10 years	One unit
	Air Intake	Mechanical Room	1	EA	6	10+ years	

Category : Mechanical
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Boiler Systems							
	Boiler Auxiliary- Condensing Hot Water - Less than 500 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	5	10+ years	Rusted and leaking
	Condensing- Hot Water Boiler - Less than 500 MBH	Boiler Room	2	EA	6	10+ years	No data plates available . Boiler #1 is under repair, the heat exchanger is cra
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	
	Water Fill System	Boiler Room	1	EA	6	10+ years	
Heating Devices							
	Cabinet Heaters - With Hot Water Coil	Corridor	14	EA	7	10+ years	
	Fin Tube - Hot Water	Entire Building	500	LF	6	10+ years	
	PTAC - Hot Water Heating and Self Contained Cooling	Entire Building	6	EA	6	6-10 years	
Mechanical Plumbing							
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	2	EA	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	600	LF	6	10+ years	
Temperature Control							
	DDC System	Entire Building	63,929	SF	6	10+ years	
	Electric Thermostat	Entire Building	5	EA	5	6-10 years	
	Thermostats - DDC	Entire Building	38	EA	6	10+ years	
Unit Ventilation							
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	8	EA	6	6-10 years	
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	25	EA	6	10+ years	
Ventilation							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	6	EA	7	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	3	EA	7	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	Type II , no cooking range underneath

Category : Plumbing
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Hot Water</u>							
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
	Hot Water Storage Tank_Gas - Less than 200 Gallons	Boiler Room	1	EA	7	10+ years	
<u>Piping</u>							
	Domestic Piping-Hot Water Return Lines	Entire Building	63,929	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	63,929	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	63,929	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	63,929	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	63,929	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	63,929	SF	6	10+ years	
	Sanitary Piping	Entire Building	63,929	SF	6	10+ years	
	Storm Piping	Entire Building	63,929	SF	6	10+ years	
	Vent Piping	Entire Building	63,929	SF	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Administrative Suites/Offices</u>							
	Ceiling - Splined	100 Teachers work room	558	SF	6	10+ years	
	Doors - Wood Doors inclu hw	100 Teachers work room	1	EA	6	10+ years	
	Floor - Tile/Sheet	100 Teachers work room	558	SF	7	10+ years	
	Lighting - Pendent/Surface	100 Teachers work room	13	EA	7	6-10 years	
	Power Distribution	100 Teachers work room	16	EA	7	10+ years	
	Storage/ Closet	100 Teachers work room	79	SF	7	10+ years	
	Walls - Plaster/Drywall	100 Teachers work room	1,067	SF	6	10+ years	
	Ceiling - Plaster/Drywall	103 office	197	SF	6	10+ years	
	Doors - Transom Window	103 office	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	103 office	1	EA	6	10+ years	
	Floor - Tile/Sheet	103 office	197	SF	7	10+ years	
	Lighting - Pendent/Surface	103 office	3	EA	7	6-10 years	
	Power Distribution	103 office	8	EA	7	10+ years	
	Storage/ Closet	103 office	7	SF	7	10+ years	
	Walls - Plaster/Drywall	103 office	884	SF	6	10+ years	
	Ceiling - Splined	103D office in 103 - 103E Nurse Office	159	SF	6	10+ years	
	Doors - Wood Doors inclu hw	103D office in 103 - 103E Nurse Office	1	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile/Sheet	103D office in 103 - 103E Nurse Office	159	SF	7	10+ years	
	Lighting - Pendent/Surface	103D office in 103 - 103E Nurse Office	4	EA	7	6-10 years	
	Power Distribution	103D office in 103 - 103E Nurse Office	8	EA	7	10+ years	
	Storage/ Closet	103D office in 103 - 103E Nurse Office	9	SF	7	10+ years	
	Walls - Plaster/Drywall	103D office in 103 - 103E Nurse Office	550	SF	6	10+ years	
	Work Slnk	103D office in 103 - 103E Nurse Office	1	EA	7	10+ years	
	Ceiling - Splined	103H office in 103 -103C Counseling Office	140	SF	6	10+ years	
	Doors - Wood Doors inclu hw	103H office in 103 -103C Counseling Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	103H office in 103 -103C Counseling Office	140	SF	7	10+ years	
	Lighting - Pendent/Surface	103H office in 103 -103C Counseling Office	2	EA	7	6-10 years	
	Power Distribution	103H office in 103 -103C Counseling Office	6	EA	7	10+ years	
	Storage/ Closet	103H office in 103 -103C Counseling Office	9	SF	7	10+ years	
	Walls - Plaster/Drywall	103H office in 103 -103C Counseling Office	473	SF	6	10+ years	
	Ceiling - Splined	121 Faculty lounge	635	SF	7	10+ years	
	Doors - Wood Doors inclu hw	121 Faculty lounge	1	EA	7	10+ years	
	Floor - Tile	121 Faculty lounge	635	SF	7	10+ years	
	Lighting - Pendent/Surface	121 Faculty lounge	6	EA	7	6-10 years	
	Power Distribution	121 Faculty lounge	12	EA	7	10+ years	
	Storage/ Closet	121 Faculty lounge	11	SF	7	10+ years	
	Walls - Plaster/Drywall	121 Faculty lounge	1,281	SF	7	10+ years	
	Work Slnk	121 Faculty lounge	1	EA	7	10+ years	
	Ceiling - Lay-in	130 Main office	565	SF	7	10+ years	
	Doors - Side-lite	130 Main office	60	SF	7	10+ years	
	Doors - Store Front	130 Main office	1	EA	7	10+ years	
	Doors - Transom Window	130 Main office	4	SF	7	10+ years	
	Floor - Carpet	130 Main office	408	SF	7	6-10 years	
	Floor - Tile	130 Main office	157	SF	7	10+ years	
	Lighting - Pendent/Surface	130 Main office	23	EA	7	6-10 years	
	Power Distribution	130 Main office	18	EA	7	10+ years	
	Storage/ Closet	130 Main office	122	SF	7	10+ years	
	Walls - Plaster/Drywall	130 Main office	1,015	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Ceiling - Lay-in	130A, principal office	101	SF	7	10+ years	
	Doors - Wood Doors inclu hw	130A, principal office	1	EA	7	10+ years	
	Floor - Carpet	130A, principal office	101	SF	7	6-10 years	
	Lighting - Lay-in	130A, principal office	2	EA	7	6-10 years	
	Power Distribution	130A, principal office	14	EA	7	10+ years	
	Walls - Plaster/Drywall	130A, principal office	388	SF	7	10+ years	
	Ceiling - Lay-in	130C Asst principals office in main office	154	SF	7	10+ years	
	Doors - Wood Doors inclu hw	130C Asst principals office in main office	1	EA	7	10+ years	
	Floor - Carpet	130C Asst principals office in main office	154	SF	7	6-10 years	
	Lighting - Pendent/Surface	130C Asst principals office in main office	3	EA	7	6-10 years	
	Power Distribution	130C Asst principals office in main office	6	EA	7	10+ years	
	Storage/ Closet	130C Asst principals office in main office	9	SF	7	10+ years	
	Walls - Plaster/Drywall	130C Asst principals office in main office	422	SF	7	10+ years	
	Ceiling - Lay-in	130E Conference room	188	SF	7	10+ years	
	Doors - Steel Doors incl hw	130E Conference room	1	EA	7	10+ years	
	Floor - Carpet	130E Conference room	188	SF	7	6-10 years	
	Lighting - Lay-in	130E Conference room	2	EA	7	6-10 years	
	Power Distribution	130E Conference room	16	EA	7	10+ years	
	Walls - Plaster/Drywall	130E Conference room	440	SF	7	10+ years	
	Ceiling - Plaster/Drywall	219 Office - 217a	220	SF	6	10+ years	
	Doors - Wood Doors inclu hw	219 Office - 217a	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	219 Office - 217a	220	SF	6	10+ years	
	Lighting - Pendent/Surface	219 Office - 217a	3	EA	7	6-10 years	
	Power Distribution	219 Office - 217a	12	EA	7	10+ years	
	Walls - Plaster/Drywall	219 Office - 217a	343	SF	6	10+ years	
	Walls - Structural Glazed Tile	219 Office - 217a	391	SF	6	10+ years	
	Ceiling - Lay-in	Engineers office in boiler room	75	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineers office in boiler room	1	EA	6	10+ years	
	Floor - Tile	Engineers office in boiler room	75	SF	7	10+ years	
	Lighting - Lay-in	Engineers office in boiler room	1	EA	7	6-10 years	
	Power Distribution	Engineers office in boiler room	12	EA	7	10+ years	
	Walls - Plaster/Drywall	Engineers office in boiler room	293	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Kitchen office	91	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen office	1	EA	7	10+ years	
	Floor - Tile Quarry	Kitchen office	91	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen office	2	EA	7	6-10 years	
	Power Distribution	Kitchen office	6	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage/ Closet	Kitchen office	59	SF	7	10+ years	
	Walls - Structural Glazed Tile	Kitchen office	512	SF	7	10+ years	
	Ceiling - Splined	Operations office	127	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Operations office	1	EA	7	10+ years	
	Floor - Tile	Operations office	127	SF	7	10+ years	
	Lighting - Pendent/Surface	Operations office	3	EA	7	6-10 years	
	Power Distribution	Operations office	8	EA	7	10+ years	
	Storage/ Closet	Operations office	9	SF	7	10+ years	
	Walls - Plaster/Drywall	Operations office	393	SF	7	10+ years	
	Ceiling - Lay-in	Security office, across from 100	273	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Security office, across from 100	1	EA	7	10+ years	
	Floor - Tile	Security office, across from 100	273	SF	7	10+ years	
	Lighting - Pendent/Surface	Security office, across from 100	2	EA	7	6-10 years	
	Power Distribution	Security office, across from 100	6	EA	7	10+ years	
	Walls - Concrete Block	Security office, across from 100	286	SF	7	10+ years	
	Walls - Masonry	Security office, across from 100	148	SF	6	10+ years	
	Walls - Plaster/Drywall	Security office, across from 100	139	SF	7	10+ years	

Gymnasia

	Ceiling - Lay-in	025 gym	3,492	SF	7	10+ years	
	Doors - Wood Doors inclu hw	025 gym	5	EA	7	10+ years	
	Floor - Wood	025 gym	3,492	SF	7	10+ years	
	Lighting - Lay-in	025 gym	20	EA	7	6-10 years	
	Scoreboards	025 gym	1	EA	7	10+ years	
	Sound System	025 gym	1	EA	7	10+ years	
	Stage	025 gym	862	SF	7	10+ years	
	Stage Curtain	025 gym	2	EA	7	10+ years	
	Stage Lift	025 gym	1	EA	7	10+ years	
	Stage Lighting System	025 gym	1	EA	7	10+ years	
	Stage-Stairs - Tile	025 gym	5	LF	7	10+ years	
	Stage-Stairs - Wood	025 gym	12	LF	7	10+ years	
	Storage/ Closet	025 gym	268	SF	7	10+ years	
	Walls - Plaster/Drywall	025 gym	2,676	SF	7	10+ years	
	Walls - Structural Glazed Tile	025 gym	1,750	SF	7	10+ years	

Kitchen

	Ceiling - Lay-in	Kitchen, rooms 016/017	165	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Kitchen, rooms 016/017	832	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen, rooms 016/017	3	EA	7	10+ years	
	Floor - Tile Quarry	Kitchen, rooms 016/017	997	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen, rooms 016/017	13	EA	7	6-10 years	
	Storage/ Closet	Kitchen, rooms 016/017	110	SF	7	10+ years	
	Walls - Plaster/Drywall	Kitchen, rooms 016/017	651	SF	7	10+ years	
	Walls - Structural Glazed Tile	Kitchen, rooms 016/017	1,340	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Lunch & Multipurpose Room							
	Ceiling - Lay-in	010 lunchroom	2,258	SF	7	10+ years	
	Doors - Wood Doors inclu hw	010 lunchroom	2	EA	7	10+ years	
	Floor - Tile/Sheet	010 lunchroom	2,258	SF	7	10+ years	
	Lighting - Lay-in	010 lunchroom	30	EA	7	6-10 years	
	Storage/ Closet	010 lunchroom	218	SF	7	10+ years	
	Walls - Plaster/Drywall	010 lunchroom	758	SF	7	10+ years	
	Walls - Structural Glazed Tile	010 lunchroom	1,578	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Serving room in kitchen	91	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Serving room in kitchen	1	EA	7	10+ years	
	Floor - Tile Quarry	Serving room in kitchen	91	SF	7	10+ years	
	Lighting - Pendent/Surface	Serving room in kitchen	2	EA	7	6-10 years	
	Serving Line	Serving room in kitchen	18	LF	7	10+ years	
	Walls - Plaster/Drywall	Serving room in kitchen	130	SF	7	10+ years	
	Walls - Structural Glazed Tile	Serving room in kitchen	281	SF	7	10+ years	
MDF_IDF							
	Doors - Wood Doors inclu hw	103C in room 103 - 103G	1	EA	6	10+ years	
	Finishes	103C in room 103 - 103G	118	SF	7	10+ years	
	Other Cooling Unit	103C in room 103 - 103G	1	EA	7	10+ years	
	Window AC Unit	103C in room 103 - 103G	1	EA	7	10+ years	
Mechanical/ Service Rooms							
	Boiler Room	1st Floor	1,550	SF	7	10+ years	
	Janitor's Closet	1st Floor	72	SF	7	10+ years	
	Janitor's Closet	1st Floor	69	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	20	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	151	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	230	SF	7	10+ years	
	Storage Room	1st Floor	161	SF	7	10+ years	
	Storage Room	1st Floor	21	SF	7	10+ years	
	Storage Room	1st Floor	57	SF	7	10+ years	
	Storage Room	1st Floor	113	SF	7	10+ years	
	Storage Room	1st Floor	60	SF	7	10+ years	
	Storage Room	1st Floor	158	SF	7	10+ years	
	Storage Room	1st Floor	47	SF	7	10+ years	
	Storage Room	1st Floor	167	SF	7	10+ years	
	Vaults	1st Floor	188	SF	7	10+ years	
	Janitor's Closet	2nd Floor	40	SF	7	10+ years	
	Storage Room	2nd Floor	160	SF	5	10+ years	Light fixture not working
Restroom							

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Accessories	113A restroom	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	113A restroom	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	113A restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	113A restroom	70	SF	7	10+ years	
	Hand Dryer	113A restroom	1	EA	7	6-10 years	
	Lavatory	113A restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	113A restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	113A restroom	300	SF	7	10+ years	
	Water Closet	113A restroom	1	EA	7	10+ years	
	Accessories	115A restroom	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	115A restroom	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	115A restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	115A restroom	70	SF	7	10+ years	
	Hand Dryer	115A restroom	1	EA	7	6-10 years	
	Lavatory	115A restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	115A restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	115A restroom	300	SF	7	10+ years	
	Water Closet	115A restroom	1	EA	7	10+ years	
	Accessories	2nd Floor Boys Toilet	302	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Boys Toilet	302	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Boys Toilet	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Boys Toilet	302	SF	6	10+ years	
	Floor Drain	2nd Floor Boys Toilet	1	EA	7	10+ years	
	Lavatory	2nd Floor Boys Toilet	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Boys Toilet	3	EA	7	6-10 years	
	Partitions	2nd Floor Boys Toilet	2	EA	7	10+ years	
	Urinals	2nd Floor Boys Toilet	5	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor Boys Toilet	616	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor Boys Toilet	525	SF	6	10+ years	
	Water Closet	2nd Floor Boys Toilet	2	EA	6	10+ years	
	Accessories	2nd Floor Girls toilet next to 207	488	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls toilet next to 207	488	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girls toilet next to 207	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls toilet next to 207	488	SF	6	10+ years	
	Floor Drain	2nd Floor Girls toilet next to 207	1	EA	7	10+ years	
	Lavatory	2nd Floor Girls toilet next to 207	4	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls toilet next to 207	3	EA	7	6-10 years	
	Partitions	2nd Floor Girls toilet next to 207	8	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Girls toilet next to 207	419	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Girls toilet next to 207	592	SF	6	10+ years	
	Water Closet	2nd Floor Girls toilet next to 207	8	EA	6	10+ years	
	Accessories	2nd Floor Men's Toilet	68	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Men's Toilet	68	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Men's Toilet	1	EA	6	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile/Sheet	2nd Floor Men's Toilet	68	SF	7	10+ years	
	Lavatory	2nd Floor Men's Toilet	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Men's Toilet	1	EA	7	6-10 years	
	Partitions	2nd Floor Men's Toilet	1	EA	7	10+ years	
	Urinals	2nd Floor Men's Toilet	2	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor Men's Toilet	376	SF	6	10+ years	
	Water Closet	2nd Floor Men's Toilet	1	EA	6	10+ years	
	Accessories	2nd Floor Women's Toilet - unisex	126	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Women's Toilet - unisex	126	SF	6	10+ years	
	Doors - Hardware	2nd Floor Women's Toilet - unisex	1	EA	6	1-2 years	Lock missing
	Doors - Wood Doors inclu hw	2nd Floor Women's Toilet - unisex	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor Women's Toilet - unisex	126	SF	7	10+ years	
	Lavatory	2nd Floor Women's Toilet - unisex	2	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Women's Toilet - unisex	2	EA	7	6-10 years	
	Partitions	2nd Floor Women's Toilet - unisex	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Women's Toilet - unisex	678	SF	6	10+ years	
	Water Closet	2nd Floor Women's Toilet - unisex	2	EA	6	10+ years	
	Accessories	2nd floor Girls Toilet next to 201	209	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor Girls Toilet next to 201	209	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor Girls Toilet next to 201	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor Girls Toilet next to 201	209	SF	6	10+ years	
	Floor Drain	2nd floor Girls Toilet next to 201	1	EA	7	10+ years	
	Lavatory	2nd floor Girls Toilet next to 201	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor Girls Toilet next to 201	2	EA	7	6-10 years	
	Partitions	2nd floor Girls Toilet next to 201	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor Girls Toilet next to 201	344	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor Girls Toilet next to 201	382	SF	6	10+ years	
	Water Closet	2nd floor Girls Toilet next to 201	4	EA	6	10+ years	
	Accessories	Boiler room restroom	100	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boiler room restroom	100	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boiler room restroom	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boiler room restroom	100	SF	7	10+ years	
	Floor Drain	Boiler room restroom	1	EA	7	10+ years	
	Lavatory	Boiler room restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Boiler room restroom	3	EA	7	6-10 years	
	Lighting - Wall Mounted	Boiler room restroom	1	EA	7	6-10 years	
	Showers	Boiler room restroom	1	EA	7	10+ years	
	Walls - Concrete Block	Boiler room restroom	200	SF	7	10+ years	
	Walls - Plaster/Drywall	Boiler room restroom	213	SF	7	10+ years	
	Walls - Plaster/Drywall	Boiler room restroom	20	SF	6	10+ years	
	Water Closet	Boiler room restroom	1	EA	6	10+ years	
	Accessories	Boys restroom, across from room 110	230	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys restroom, across from room 110	230	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	110 Boys restroom, across from room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	110 Boys restroom, across from room	230	SF	7	10+ years	
	Floor Drain	110 Boys restroom, across from room	1	EA	7	10+ years	
	Hand Dryer	110 Boys restroom, across from room	2	EA	7	6-10 years	
	Lavatory	110 Boys restroom, across from room	3	EA	7	10+ years	
	Lighting - Pendent/Surface	110 Boys restroom, across from room	3	EA	7	6-10 years	
	Partitions	110 Boys restroom, across from room	2	EA	7	10+ years	
	Urinals	110 Boys restroom, across from room	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	110 Boys restroom, across from room	495	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	110 Boys restroom, across from room	406	SF	7	10+ years	
	Water Closet	110 Boys restroom, across from room	2	EA	7	10+ years	
	Accessories	108 Girls restroom, across from room	313	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	108 Girls restroom, across from room	313	SF	7	10+ years	
	Doors - Wood Doors inclu hw	108 Girls restroom, across from room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	108 Girls restroom, across from room	313	SF	7	10+ years	
	Floor Drain	108 Girls restroom, across from room	1	EA	7	10+ years	
	Hand Dryer	108 Girls restroom, across from room	1	EA	7	6-10 years	
	Lavatory	108 Girls restroom, across from room	5	EA	7	10+ years	
	Lighting - Pendent/Surface	108 Girls restroom, across from room	3	EA	7	6-10 years	
	Partitions	108 Girls restroom, across from room	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	108 Girls restroom, across from room	600	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	108 Girls restroom, across from room	500	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Water Closet	108 Girls restroom, across from room	4	EA	7	10+ years	
	Water Closet	108 Girls restroom, across from room	1	EA	7	10+ years	
	Accessories	108 Mens staff restroom across from Gym	143	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Mens staff restroom across from Gym	143	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Mens staff restroom across from Gym	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Mens staff restroom across from Gym	143	SF	7	10+ years	
	Floor Drain	Mens staff restroom across from Gym	1	EA	7	10+ years	
	Hand Dryer	Mens staff restroom across from Gym	1	EA	7	6-10 years	
	Lavatory	Mens staff restroom across from Gym	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Mens staff restroom across from Gym	2	EA	7	6-10 years	
	Partitions	Mens staff restroom across from Gym	1	EA	7	10+ years	
	Urinals	Mens staff restroom across from Gym	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	Mens staff restroom across from Gym	337	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Mens staff restroom across from Gym	179	SF	7	10+ years	
	Water Closet	Mens staff restroom across from Gym	1	EA	7	10+ years	
	Accessories	Restroom in Principals office	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in Principals office	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Restroom in Principals office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Restroom in Principals office	40	SF	7	10+ years	
	Lavatory	Restroom in Principals office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Restroom in Principals office	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Restroom in Principals office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Restroom in Principals office	230	SF	7	10+ years	
	Water Closet	Restroom in Principals office	1	EA	7	10+ years	
	Accessories	Restroom in kitchen	27	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in kitchen	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Restroom in kitchen	1	EA	7	10+ years	
	Floor - Tile/Sheet	Restroom in kitchen	27	SF	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lavatory	Restroom in kitchen	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Restroom in kitchen	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Restroom in kitchen	188	SF	7	10+ years	
	Water Closet	Restroom in kitchen	1	EA	7	10+ years	
	Accessories	Staff restroom 103B	27	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff restroom 103B	27	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Staff restroom 103B	1	EA	6	10+ years	
	Floor - Tile/Sheet	Staff restroom 103B	27	SF	7	10+ years	
	Lavatory	Staff restroom 103B	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Staff restroom 103B	1	EA	7	6-10 years	
	Lighting - Wall Mounted	Staff restroom 103B	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Staff restroom 103B	228	SF	6	10+ years	
	Water Closet	Staff restroom 103B	1	EA	6	10+ years	
	Accessories	Staff restroom across fro lunch room	82	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff restroom across fro lunch room	82	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff restroom across fro lunch room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Staff restroom across fro lunch room	82	SF	6	10+ years	
	Lavatory	Staff restroom across fro lunch room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Staff restroom across fro lunch room	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Staff restroom across fro lunch room	360	SF	7	10+ years	
	Water Closet	Staff restroom across fro lunch room	1	EA	7	10+ years	
	Accessories	Women's staff restroom across from Gym	142	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's staff restroom across from Gym	142	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Women's staff restroom across from Gym	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's staff restroom across from Gym	142	SF	7	10+ years	
	Floor Drain	Women's staff restroom across from Gym	1	EA	7	10+ years	
	Hand Dryer	Women's staff restroom across from Gym	2	EA	7	6-10 years	
	Lavatory	Women's staff restroom across from Gym	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Women's staff restroom across from Gym	2	EA	7	6-10 years	
	Partitions	Women's staff restroom across from Gym	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	Women's staff restroom across from Gym	335	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Women's staff restroom across from Gym	209	SF	7	10+ years	
	Water Closet	Women's staff restroom across from Gym	3	EA	7	10+ years	

Category : Room
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
		Gym					

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-------	-------------	----------	----------	-----	------	-----------------------	----------

Classroom #102 (Faculty Lounge)

	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	935	SF	6	10+ years	

Classroom #104 (Regular Classroom)

	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	935	SF	6	10+ years	

Classroom #105 (Regular Classroom)

	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	Updated to match current observations
	Floor - Tile/Sheet	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	995	SF	6	10+ years	

Classroom #106 (Regular Classroom)

	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	Updated to match current observations

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	935	SF	7	10+ years	
<hr/>							
Classroom #107 (Regular Classroom)							
	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	995	SF	6	10+ years	
<hr/>							
Classroom #108 (Regular Classroom)							
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	935	SF	7	10+ years	
<hr/>							
Classroom #110 (Regular Classroom)							
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	935	SF	7	10+ years	
<hr/>							
Classroom #111 (Art Room)							
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	45	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	32	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,272	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,304	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	69	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,575	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #112 (Regular Classroom)							
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	935	SF	7	10+ years	
Classroom #113 (Kindergarten)							
	Casework	1st Floor	47	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,304	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,304	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,350	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #114 (Regular Classroom)							
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	935	SF	6	10+ years	
Classroom #115 (Kindergarten)							
	Casework	1st Floor	43	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	1,304	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Tile	1st Floor	1,304	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	23	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,350	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroom #116 (Regular Classroom)							
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	935	SF	7	10+ years	
Classroom #118 (Regular Classroom)							
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	793	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Storage/ Closet	1st Floor	185	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	935	SF	6	10+ years	
Classroom #202 (Library)							
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	60	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2,379	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	3	EA	7	10+ years	Updated to match current observations
	Floor - Carpet	2nd Floor	2,379	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	27	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,560	SF	7	10+ years	
Classroom #203 (Music Room)							
	Ceiling - Lay-in	2nd Floor	1,586	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years	Updated to match current observations

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Floor - Carpet	2nd Floor	1,586	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	7	10+ years	
Classroom #205 (Regular Classroom)							
	Casework	2nd Floor	18	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	793	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	Updated to match current observations
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	6	10+ years	
Classroom #206 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	2-5 years	Lock missing
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	6	10+ years	
Classroom #207 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	Updated to match current observations
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	7	10+ years	Updated to match current observations
Classroom #208 (Store Room)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	Updated to match current observations
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	7	10+ years	
Classroom #209 (Art Room)							
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	281	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Quarry	2nd Floor	281	SF	6	10+ years	
	Kiln	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	786	SF	7	10+ years	
Classroom #210 (Vacant)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	Updated to match current observations
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	7	10+ years	Updated to match current observations
Classroom #211 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Hardware	2nd Floor	1	EA	6	2-5 years	Door handle loose
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	7	10+ years	Updated to match current observations
Classroom #212 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	6	10+ years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #213 (Regular Classroom)							
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	793	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	6	10+ years	
Classroom #214 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	6	10+ years	
Classroom #215 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	6	10+ years	
Classroom #216 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	6	10+ years	
Classroom #217 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	

Category : Classroom
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storage/ Closet	2nd Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,260	SF	6	10+ years	
Classroom #218 (Music Room)							
	Ceiling - Lay-in	2nd Floor	793	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	Updated to match current observations
	Floor - Tile/Sheet	2nd Floor	793	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	129	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,261	SF	6	10+ years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	1,093	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	5,439	SF	7	10+ years	
	Doors - Side-lite	1st Floor	44	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	5	EA	7	10+ years	
	Doors - Store Front	1st Floor	10	EA	7	10+ years	
	Doors - Transom Window	1st Floor	37	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	6,532	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	37	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	300	EA	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	150	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	5,195	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	4,128	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	1,150	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2,936	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,936	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	24	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor	150	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,993	SF	7	10+ years	
Safety							
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	17	EA	7	6-10 years	

Category : Interior
Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Stairs</u>							
	Ceiling - Lay-in	Stairwell #1	136	SF	6	10+ years	
	Floor - Terrazzo	Stairwell #1	52	SF	6	10+ years	
	Handrails	Stairwell #1	45	LF	7	10+ years	
	Lighting - Lay-in	Stairwell #1	1	EA	7	6-10 years	
	Stairs - Terrazzo	Stairwell #1	20	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell #1	400	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stairwell #1	200	SF	6	10+ years	
	Ceiling - Lay-in	Stairwell #2	200	SF	6	10+ years	
	Floor - Terrazzo	Stairwell #2	92	SF	6	10+ years	
	Handrails	Stairwell #2	48	LF	7	10+ years	
	Lighting - Lay-in	Stairwell #2	1	EA	6	6-10 years	
	Stairs - Terrazzo	Stairwell #2	20	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell #2	210	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stairwell #2	145	SF	6	10+ years	
	Ceiling - Lay-in	Stairwell #3	158	SF	6	10+ years	
	Floor - Terrazzo	Stairwell #3	57	SF	6	10+ years	
	Handrails	Stairwell #3	48	LF	7	10+ years	
	Lighting - Lay-in	Stairwell #3	1	EA	7	6-10 years	
	Stairs - Terrazzo	Stairwell #3	20	LF	6	10+ years	
	Walls - Plaster/Drywall	Stairwell #3	180	SF	6	10+ years	
	Walls - Structural Glazed Tile	Stairwell #3	140	SF	6	10+ years	
<u>Vertical Conveyance</u>							
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	

Category : Site
Building : Site

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
<u>Civil/Drainage</u>							
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	6	10+ years	
<u>Fencing</u>							
	Fencing - New Standard Ornamental	Entire Site	550	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	460	LF	6	6-10 years	
<u>Landscape</u>							
	Landscape - Grass	Entire Site	25,690	SF	6	10+ years	
	Landscape - Grass	Entire Site	5,000	SF	4	0-1 year	Muddy, no grass
	Landscape - Hardscape- Asphalt	Entire Site	1,470	SF	6	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	1,250	SF	6	10+ years	
	Parkway trees	Entire Site	7	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	3,000	SF	6	6-10 years	
	Play Area - Synthetic Turf	Entire Site	1,800	SF	7	10+ years	
	Trash Receptacles	Entire Site	1	EA	6	6-10 years	
<u>Parking Lot</u>							
	Concrete Curbs	West	675	LF	7	10+ years	
	Interior Plantings	West	80	LF	7	10+ years	
	Surface - Asphalt	West	12,415	SF	6	6-10 years	
	Trash Enclosure - Masonry	West	350	SF	6	10+ years	
	Vehicular Screening	West	120	LF	6	10+ years	
<u>Playground</u>							
	Equipment - Combo 3-12	West	1	EA	6	6-10 years	
	Surface - Poured Surface	West	1,630	SF	6	6-10 years	
<u>Sidewalks</u>							
	Sidewalks - Internal Walks	Entire Site	560	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	10	LF	5	0-1 year	Spalled, uneven
	Sidewalks - Perimeter Sidewalks	Entire Site	11,865	SF	6	10+ years	
<u>Signage</u>							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	6-10 years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	6-10 years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
 - **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").
-

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart-Board
Building : Main									
Art Room	Art Room	2nd Floor	209	209	281	48	48	N	N
Art Room	Kindergarten	1st Floor	111	111	1,304	225	135	N	N
Faculty Lounge	Regular Classroom	1st Floor	102	102	793	238	119	N	N
Kindergarten	Kindergarten	1st Floor	113	113	1,304	225	135	N	Y
Kindergarten	Kindergarten	1st Floor	115	115	1,304	225	135	N	Y
Library	Library	2nd Floor	202	202	2,379	525	315	N	N
Music Room	Music Room	2nd Floor	203	203	1,586	476	238	N	N
Music Room	Regular Classroom	2nd Floor	218	218	793	175	105	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	793	238	119	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	793	175	105	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	793	238	119	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	793	175	105	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	793	238	119	N	N
Regular Classroom	Regular Classroom	1st Floor	110	110	793	238	119	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	793	238	119	N	Y
Regular Classroom	Regular Classroom	1st Floor	114	114	793	238	119	N	Y
Regular Classroom	Regular Classroom	1st Floor	116	116	793	238	119	N	Y
Regular Classroom	Regular Classroom	1st Floor	118	118	793	238	119	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	793	238	119	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	793	175	105	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	793	238	119	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	793	238	119	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	793	175	105	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	793	238	119	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	793	175	105	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	793	238	119	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	793	175	105	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	793	238	119	N	N
Store Room	Regular Classroom	2nd Floor	208	208	793	175	105	N	N
Vacant	Regular Classroom	2nd Floor	210	210	793	175	105	N	N