

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1946	3	98,604
Addition	1956	3	26,826
Campus Total			125,430

Category : Exterior Building : Main

	y : Exterior	Danaing . main					
Craun	Hom Type	Lagation	Quantity	ПОМ	Donk	Recommend	Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance							
	Entrance Control - Audio and Video	1	1	EA	7	10+ years	
	Exterior Doors - Store Front	1	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	1	2	EA	6	10+ years	Scrape/Paint Frame at Door and Transom
	Power Door Operator and Controls	1	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	11	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	11	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	2	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	2	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	3	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	3	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	3	36	LF	7	10+ years	
	Exterior Stairs - Stone	3	7	LF	7	10+ years	
	Exterior Doors - Store Front	4 & 5	6	EA	7	10+ years	
	Exterior Doors - Transom Lite	4 & 5	3	EA	7	10+ years	
	Exterior Stairs - Concrete	4 & 5	126	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	4 & 5	20	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	5.5	1	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	5.5	58	LF	7	10+ years	
	Ramps - Steel or Aluminum	5.5	24	LF	7	10+ years	
	Entrance Control - Audio and Video	6	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	6	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	6	2	EA	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Concrete	6	7	LF	7	10+ years	
	Entrance Control - Audio and Video	7	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	7	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	7	2	EA	5	2-5 years	Scrape/Paint
	Exterior Stairs - Concrete	7	32	LF	7	10+ years	
	Exterior Stairs - Stone	7	7	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	8	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	8	28	LF	6	10+ years	Flooding at Door - Drain in Disrepa
	Stair Handrail - Steel_Stair Handrail	8	6	LF	5	2-5 years	
oundat	ion						
	Foundation - Concrete	Entire Building	962	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	98,604	SF	7	10+ years	
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	7	10+ years	
oof Sys	stem						
	Access Ladder - Metal	A-Main Roof	1	EA	7	10+ years	
	Access Ladder - Metal	A-Main Roof	1	EA	3	2-5 years	Unused
	Chimney - Brick Chimney- Concrete/ Mortar Liner	A-Main Roof	50	LF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	A-Main Roof	10	LF	5	2-5 years	Deteriorated Mortar at Brick Joints.
	Coping - Stone	A-Main Roof	1,095	LF	6	10+ years	
	Downspouts - Exterior Downspouts	A-Main Roof	867	LF	6	10+ years	
	Parapet - 16" - 30" Height	A-Main Roof	469	LF	7	10+ years	
	Parapet - Parapet < 16" Height	A-Main Roof	460	LF	7	10+ years	Parapet Less Than 16" is on North Roof
	Parapet - Parapet > 30"	A-Main Roof	166	LF	7	10+ years	11001
	Roof - Modified Bitumen	A-Main Roof	28,264	SF	6	6-10 years	
	Roof Hatch - Metal	A-Main Roof	1	EA	7	10+ years	Only 1 Roof Hatch/Roof Access.
	Roof Hatch - Metal	A-Main Roof	1	EA	3	2-5 years	Unused
	Roof Structure - Concrete	A-Main Roof	28,264	SF	7	10+ years	Chaoda
	Coping - Stone	B	28	LF	6	10+ years	
	Downspouts - Exterior Downspouts	В	8	LF	6	10+ years	
	Parapet - Parapet < 16" Height	В	28	LF	6	10+ years	
	Roof - Modified Bitumen	В	180	SF	6	10+ years	
	Roof Structure - Concrete	В	180	SF SF	7	10+ years 10+ years	
		С	28	LF			
	Coping - Stone			LF LF	6	10+ years	
	Downspouts - Exterior Downspouts	C	8	LF LF	6	10+ years	
	Parapet - Parapet < 16" Height	С	28	LF	6	10+ years	

Campus Name: Camras Page : 2 of 43 Assessment Date: 10/12/2021



Category : Exterior

Marvin Camras Elementary School 3000 N Mango AVENUE, Chicago, IL 60634

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	C	180	SF	7	10+ years	
	Roof Structure - Concrete	С	180	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	14,991	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	20,705	SF	6	10+ years	
Windows							
	Lintels - Steel	Entire Building	936	LF	7	10+ years	
	Lintels - Stone	Entire Building	715	LF	7	10+ years	
	Windows - Decorative	Entire Building	48	SF	6	10+ years	
	Windows - Louver	Entire Building	28	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	14,182	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	· Main		
Guiogo				unung	· waiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncv System		•			•	
	Emergency A/C Power - Corridors and Stairs	1st Floor	13,000	SF	6	10+ years	
	Emergency A/C Power - Gym	1st Floor	1,100	SF	6	10+ years	
	Automatic Transfer Switch	Boiler Room	1	EA	4	2-5 years	Older technology, more than 40 years old, also serves addition
	Security System - CCTV	Entire Building	98,604	SF	6	6-10 years	old, also serves addition
	Security System - Intrusion Detection	Entire Building	98,604	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	63	EA	6	6-10 years	
	Stairs	· ·				-	
	Emergency Battery Packs - Gym	Entire Building	8	EA	6	10+ years	
	Emergency Battery Packs - Lunchrooms	Entire Building	9	EA	6	10+ years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	3	EA	6	10+ years	
	Emergency Battery Packs - Students Toilets	Entire Building	7	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	39	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	8	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	8	ΕA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	2	EA	6	6-10 years	
Main Se	rvice						
_wan oc	Main Electrical Service - 2000 A	Boiler Room	1	EA	4	2-5 years	Corroded, not reliable, also serves
	120/240/3PH					<u>,</u>	addition. No nameplate
	Independent Electrical Service for	Boiler Room	1	EA	6	6-10 years	Served by ATS, 2 electric meters
	emergency power		·		-		·, · · · · · · · · · · · · · · · · · ·
	PA System	Entire Building	98,604	SF	6	6-10 years	Also serves addition

Building: Main

Campus Name: Camras Page : 3 of 43 Assessment Date: 10/12/2021



	ry : Electrical		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Dower D	istribution						
Powel D	Lighting and Power Panels - 100 A	Entire Building	5	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - 100 A	Entire Building	23	EA	7	10+ years	Functional panels rated 7
	Lighting and Power Panels - Above 100 A	Entire Building	23 5	EA	7	•	
						10+ years	Functional panels rated 7, 5 found
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EΑ	7	10+ years	3 found, functional panels rated 7
	Main Distribution Panels - Less than 400	Entire Building	1	EA	7	10+ years	Functional panels rated 7
	amp	E (4	_ ^	•	40	
	Transformers - 120/240 - 120/208	Entire Building	1	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	Serves main and addition buildings
	Fire Alarm Strobe Lights	Entire Building	98,604	SF	6	10+ years	· ·
	Fire Alarm_System	Entire Building	98,604	SF	6	10+ years	Also serves sddition
	- •	3	,			,	
Catego	ry : Mechanical		В	uilding	: Main		
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	Serves MDF room, split system
	than 5 tons						
۸: بر ا ا م. بر ما	llin a Cuatama						
Air Hand	ling Systems Air Handling Unit- Package Single Zone-						
		Machaniaal Daam	4	Ε.Δ	_	C 10	Cam
		Mechanical Room	1	EA	5	6-10 years	Serves gym
	Indoor- Steam Coils - 4000-8000 cfm					·	Serves gym
		Mechanical Room Mechanical Room	1	EA EA	5 5	6-10 years 6-10 years	Serves gym
Boiler Sv	Indoor- Steam Coils - 4000-8000 cfm Air Intake					·	Serves gym
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake		1			6-10 years	Serves gym
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake	Mechanical Room		EA	5	·	Serves gym
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake vstems Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Mechanical Room	1	EA	5	6-10 years	Serves gym
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake vistems Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP Chemical Feed System	Mechanical Room Boiler Room	2	EA EA	5 6 6	6-10 years 6-10 years 6-10 years	Serves gym
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake **stems** Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP Chemical Feed System Combustion Dampers	Mechanical Room Boiler Room Boiler Room Boiler Room	1 2 1 2	EA EA EA EA	5 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	Serves gym
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake **stems** Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP Chemical Feed System Combustion Dampers Condensate Pump	Mechanical Room Boiler Room Boiler Room Boiler Room Boiler Room	1 2 1 2 2 2	EA EA EA EA EA	5 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Serves gym
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake **stems** Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP Chemical Feed System Combustion Dampers Condensate Pump Feed Water Pumps and Tank	Mechanical Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room	1 2 1 2 2 2	EA EA EA EA EA EA	5 6 6 6 6	6-10 years	
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake **Stems** Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP Chemical Feed System Combustion Dampers Condensate Pump Feed Water Pumps and Tank Non Condensing- Fire Tube- Scotch Marine-	Mechanical Room Boiler Room Boiler Room Boiler Room Boiler Room	1 2 1 2 2 2	EA EA EA EA EA	5 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Serves gym Also serves addition
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake **Stems** Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP Chemical Feed System Combustion Dampers Condensate Pump Feed Water Pumps and Tank Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Mechanical Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room	1 2 1 2 2 1 2	EA EA EA EA EA EA	5 6 6 6 6 6	6-10 years	Also serves addition
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake **Stems** Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP Chemical Feed System Combustion Dampers Condensate Pump Feed Water Pumps and Tank Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP Piping - Condensate Pipe- Steel	Mechanical Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room	1 2 1 2 2 1 2 200	EA EA EA EA EA EA EA	5 6 6 6 6 6 5	6-10 years	Also serves addition Leaks repaired
Boiler Sy	Indoor- Steam Coils - 4000-8000 cfm Air Intake **Stems** Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP Chemical Feed System Combustion Dampers Condensate Pump Feed Water Pumps and Tank Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Mechanical Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room Boiler Room	1 2 1 2 2 1 2	EA EA EA EA EA EA	5 6 6 6 6 6	6-10 years	Also serves addition

Campus Name: Camras Page : 4 of 43 Assessment Date: 10/12/2021



Catego	ry : Mechanical		В	uilding	: Main		-
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Heat Exc	changers						
	Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	2	EA	6	6-10 years	Serves main and addition buildings
Heating	Devices						
J	Unit Heater - Electric	Basement	1	EA	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	7	EA	5	6-10 years	Cleaned, reconditioned, cleaned
	Cabinet Heaters - With Hot Water Coil	Entire Building	24	EΑ	5	6-10 years	,
	Cabinet Heaters - With Hot Water Coil	Entire Building	3	EA	5	6-10 years	
	Fin Tube - Hot Water	Entire Building	910	LF	6	10+ years	Recently cleaned
	Fin Tube - Hot Water	Entire Building	130	LF	5	6-10 years	,,
	Radiators - Steam	Entire Building	19	ĒA	5	6-10 years	Recently painted, temperature control added. Leak repaired
	Radiators - Steam	Entire Building	22	EA	5	6-10 years	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
	Wall Heater - Electric	Entire Building	7	EA	6	10+ years	
	Wall Heater - Electric	Entire Building	3	EA	5	6-10 years	
Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	2	EA	6	6-10 years	Serve main and addition buildings
	Hydronic Supply and Return - Steel	Entire Building	500	LF	6	10+ years	Served by heat exchanger
Tempera	ture Control						
	DDC System	Gymnasium	98,600	SF	2	0-1 year	Per engineer, not hooked up, waiting for completion of DDC installation
	Electric Thermostat	Gymnasium	1	EA	4	2-5 years	Difficult to control temperatures, not calibrated, serves single zone unit
	Thermostats - Pneumatic	Gymnasium	41	EA	5	6-10 years	Control temperature of radiators and fin tubes
Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	2 found
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Main		
Group	· · · · · · · · · · · · · · · · · · ·	Location	Quantity	UOM	Rank	Recommend	Comments



						Replacement	
Hot Wat	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	5	6-10 years	Serves main and addition building
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	Serves kitchen area
Piping							
_, ,	Domestic Piping-Hot Water Return Lines	Entire Building	98,604	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	98,604	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	98,604	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	98,604	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	98,604	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	98,604	SF	6	6-10 years	
	Sanitary Piping	Entire Building	98,604	SF	6	6-10 years	
	Storm Piping	Entire Building	98,604	SF	5	6-10 years	
	Vent Piping	Entire Building	98,604	SF	6	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Boiler Room	1	EA	6	10+ years	Serves main and addition buildings
	Pumps - Ejector-Duplex	Boiler Room	2	EA	5	6-10 years	2 in building, well recently cleaned and serviced
	Pumps - Sump-Simplex	Boiler Room	1	EA	6	10+ years	Under elevator

Category: Room **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	AC Unit	009B	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	009B	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	009B	1	EΑ	6	10+ years	
	Floor - Terrazzo	009B	80	SF	7	10+ years	
	Lighting - Lay-in	009B	1	EΑ	7	10+ years	
	Power Distribution	009B	1	EΑ	6	10+ years	
	Walls - Plaster/Drywall	009B	400	SF	7	10+ years	
	Ceiling - Lay-in	009C	80	SF	6	10+ years	
	Doors - Wood Doors inclu hw	009C	1	EA	6	10+ years	
	Floor - Terrazzo	009C	80	SF	7	10+ years	
	Lighting - Lay-in	009C	1	EA	7	10+ years	
	Power Distribution	009C	1	EA	6	10+ years	
	Walls - Plaster/Drywall	009C	400	SF	7	10+ years	
	Ceiling - Splined	009D	70	SF	6	10+ years	
	Ceiling - Splined	009D	10	SF	5	1-2 years	Damaged
	Doors - Wood Doors inclu hw	009D	1	EA	6	10+ years	-

Campus Name: Camras Page : 6 of 43 Assessment Date: 10/12/2021



Category : Room		B	uilding	: Main			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	009D	80	SF	6	10+ years	
	Lighting - Lay-in	009D	1	EA	7	10+ years	
	Power Distribution	009D	1	EA	6	10+ years	
	Walls - Plaster/Drywall	009D	400	SF	6	10+ years	
	AC Unit	009E	1	EA	7	6-10 years	
	Ceiling - Lay-in	009E	70	SF	7	10+ years	
	Ceiling - Lay-in	009E	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	009E	1	EA	6	10+ years	
	Floor - Terrazzo	009E	80	SF	7	10+ years	
	Lighting - Lay-in	009E	1	EA	7	10+ years	
	Power Distribution	009E	1	EA	7	10+ years	
	Walls - Plaster/Drywall	009E	400	SF	7	10+ years	
	AC Unit	009F	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	009F	80	SF	6	10+ years	
	Doors - Wood Doors inclu hw	009F	1	EA	6	10+ years	
	Floor - Terrazzo	009F	80	SF	7	10+ years	
	Lighting - Lay-in	009F	1	EA	7	10+ years	
	Power Distribution	009F	1	EA	7	10+ years	
	Walls - Plaster/Drywall	009F	400	SF	7	10+ years	
	Ceiling - Lay-in	013-Guidance Center	42	SF	7	10+ years	
	Ceiling - Lay-in	013-Guidance Center	6	SF	5	1-2 years	Damaged tile
	Doors - Wood Doors inclu hw	013-Guidance Center	1	EA	6	10+ years	ŭ
	Floor - Terrazzo	013-Guidance Center	48	SF	7	10+ years	
	Lighting - Lay-in	013-Guidance Center	5	EA	7	10+ years	
	Power Distribution	013-Guidance Center	6	EA	7	10+ years	
	Walls - Plaster/Drywall	013-Guidance Center	228	SF	7	10+ years	
	Ceiling - Lay-in	013B	77	SF	6	10+ years	
	Ceiling - Lay-in	013B	8	SF	5	1-2 years	Damaged tile
	Doors - Wood Doors inclu hw	013B	1	ĒA	6	10+ years	3.1.1
	Floor - Terrazzo	013B	85	SF	6	10+ years	
	Lighting - Lay-in	013B	1	ĒΑ	7	10+ years	
	Power Distribution	013B	6	EA	6	10+ years	
	Walls - Plaster/Drywall	013B	281	SF	7	10+ years	
	Ceiling - Lay-in	013C	75	SF	7	10+ years	
	Ceiling - Lay-in	013C	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	013C	1	EA	6	10+ years	
	Floor - Terrazzo	013C	85	SF	7	10+ years	
	Lighting - Lay-in	013C	1	EA	7	10+ years	
	Power Distribution	013C	6	EA	6	10+ years	
	Walls - Plaster/Drywall	013C	281	SF	7	10+ years	
	Ceiling - Lay-in	013D	84	SF	7	10+ years	
	Doors - Wood Doors inclu hw	013D 013D	1	EA	6	10+ years	
	Floor - Terrazzo	013D 013D	84	SF	7	10+ years	
		013D 013D	1	EA	7	•	
	Lighting - Lay-in	UISD	I	EA	′	10+ years	

Page: 7 of 43 Campus Name: Camras Assessment Date: 10/12/2021



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	013D	6	EA	6	10+ years	
	Walls - Plaster/Drywall	013D	281	SF	7	10+ years	
	Ceiling - Lay-in	013E	84	SF	7	10+ years	
	Doors - Wood Doors inclu hw	013E	1	EA	6	10+ years	
	Floor - Terrazzo	013E	84	SF	7	10+ years	
	Lighting - Lay-in	013E	1	EA	7	10+ years	
	Power Distribution	013E	6	EA	6	10+ years	
	Walls - Plaster/Drywall	013E	356	SF	7	10+ years	
	Ceiling - Plaster/Drywall	101	150	SF	6	10+ years	
	Doors - Wood Doors inclu hw	101	1	EA	6	10+ years	
	Floor - Tile/Sheet	101	150	SF	7	10+ years	
	Lighting - Pendent/Surface	101	2	ĒA	6	10+ years	
	Power Distribution	101	2	EA	6	10+ years	
	Walls - Masonry	101	626	SF	6	10+ years	
	Ceiling - Plaster/Drywall	112	250	SF	6	10+ years	
	Doors - Wood Doors inclu hw	112	2	EA	6	10+ years	
	Floor - Terrazzo	112	250	SF	6	10+ years	
	Lighting - Lay-in	112	4	EA	6	10+ years	
	Power Distribution	112	2	EA	6	10+ years	
	Walls - Plaster/Drywall	112	820	SF	6	10+ years	
	Ceiling - Plaster/Drywall	112A	150	SF	6	10+ years	
	Doors - Wood Doors inclu hw	112A	130	EA	7	10+ years	
	Floor - Terrazzo	112A 112A	150	SF	7	•	
	Lighting - Lay-in	112A 112A	150	EA	6	10+ years	
				SF		10+ years	
	Walls - Plaster/Drywall Ceiling - Plaster/Drywall	112A	510 180	SF	6	10+ years	
	Doors - Wood Doors inclu hw	115A 115A		SF EA	6 6	10+ years	
			1	SF		10+ years	
	Floor - Tile/Sheet	115A	180		7	10+ years	
	Lighting - Pendent/Surface	115A	2	EΑ	6	10+ years	
	Power Distribution	115A	4	EA	6	10+ years	
	Walls - Plaster/Drywall	115A	596	SF	6	10+ years	
	Ceiling - Plaster/Drywall	201 - Storage	250	SF	6	10+ years	
	Doors - Wood Doors inclu hw	201 - Storage	1	EA	6	10+ years	
	Floor - Tile/Sheet	201 - Storage	250	SF	7	10+ years	
	Lighting - Pendent/Surface	201 - Storage	3	EA	7	10+ years	
	Power Distribution	201 - Storage	2	EA	6	10+ years	
	Walls - Plaster/Drywall	201 - Storage	20	SF	6	1-2 years	Hole in wall
	Walls - Plaster/Drywall	201 - Storage	985	SF	6	10+ years	
	Ceiling - Lay-in	211A Storage	215	SF	7	10+ years	
	Doors - Wood Doors inclu hw	211A Storage	1	EA	7	10+ years	
	Floor - Tile	211A Storage	215	SF	7	10+ years	
	Lighting - Lay-in	211A Storage	3	EA	7	10+ years	
	Power Distribution	211A Storage	1	EA	7	10+ years	
	Walls - Plaster/Drywall	211A Storage	700	SF	7	10+ years	



Catego	Category : Room		Building : Main					
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	300C-Kitchen Office	120	SF	6	10+ years		
	Doors - Wood Doors inclu hw	300C-Kitchen Office	1	EA	6	10+ years		
	Floor - Tile/Sheet	300C-Kitchen Office	120	SF	7	10+ years		
	Lighting - Pendent/Surface	300C-Kitchen Office	1	EA	7	10+ years		
	Power Distribution	300C-Kitchen Office	2	EA	7	10+ years		
	Walls - Plaster/Drywall	300C-Kitchen Office	526	SF	7	10+ years		
	Ceiling - Plaster/Drywall	301	254	SF	7	10+ years		
	Doors - Wood Doors inclu hw	301	1	EA	7	10+ years		
	Floor - Tile/Sheet	301	254	SF	7	10+ years		
	Lighting - Pendent/Surface	301	3	EA	7	10+ years		
	Power Distribution	301	2	EA	7	10+ years		
	Walls - Plaster/Drywall	301	1,014	SF	7	10+ years		
	AC Unit	Engineer's Office 005	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Engineer's Office 005	250	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Engineer's Office 005	1	EA	6	10+ years		
	Floor - Tile	Engineer's Office 005	250	SF	6	10+ years		
	Lighting - Pendent/Surface	Engineer's Office 005	4	EA	7	10+ years		
	Power Distribution	Engineer's Office 005	2	EA	6	10+ years		
	Walls - Plaster/Drywall	Engineer's Office 005	620	SF	7	10+ years		
	AC Unit	Main Office 114	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	Main Office 114	410	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Main Office 114	1	EA	6	10+ years		
	Floor - Terrazzo	Main Office 114	410	SF	6	10+ years		
	Lighting - Lay-in	Main Office 114	6	EA	6	10+ years		
	Power Distribution	Main Office 114	3	EA	6	10+ years		
	Storage/ Closet	Main Office 114	32	SF	7	10+ years		
	Walls - Plaster/Drywall	Main Office 114	814	SF	6	10+ years		
0								
Gymnas	Ceiling - Plaster/Drywall	Gym 100 Level .5	6,900	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Gym 100 Level .5	12	EA	6	10+ years		
	Floor - Wood	Gym 100 Level .5	6,900	SF	6	10+ years	Edited to match room size	
	Lighting - Pendent/Surface	Gym 100 Level .5	18	EA	7	10+ years	Edited to mater room size	
	Lighting - Pendent/Surface	Gym 100 Level .5	5	EA	6	10+ years		
	Scoreboards	Gym 100 Level .5	2	EA	7	10+ years		
	Sound System	Gym 100 Level .5	1	EA	7	10+ years		
	Stage	Gym 100 Level .5	780	SF	6	10+ years		
	Stage Curtain	Gym 100 Level .5	2	EA	7	10+ years		
	Stage Curtain Stage Lighting System	Gym 100 Level .5	1	EA	7	•		
	Stage-Stairs - Wood	Gym 100 Level .5	50	LF	7	10+ years		
				SF		10+ years		
	Storage/ Closet	Gym 100 Level .5	600	SF	5	10+ years		
	Walls - Metal Panel	Gym 100 Level .5	7,920	SF SF	6	10+ years		
	Walls - Plaster/Drywall	Gym 100 Level .5	1,050	5 F	7	10+ years		



Categor	ry : Room		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	item - Type	Location	Qualitity	OOW	Naiik	Replacement	Comments
itchen	A C. I. Incit	Ord Floor	4	ΓΛ	7	C 10	
	AC Unit	3rd Floor 3rd Floor	1	EA SF	7	6-10 years	Overtity above and to undetection
	Ceiling - Plaster/Drywall		780		6	10+ years	Quantity changed to update currer observation
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	24	EA	7	10+ years	
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,513	SF	6	10+ years	
ibrary							
	AC Unit	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	195	LF	6	10+ years	
	Ceiling - Splined	1st Floor	3,608	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	3,608	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	63	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,323	SF	6	10+ years	
unch &	Multipurpose Room						
	AC Unit	020-Multipurpose Room	2	EA	7	6-10 years	
	Ceiling - Splined	020-Multipurpose Room	2,565	SF	6	10+ years	
	Doors - Steel Doors incl hw	020-Multipurpose Room	3	EA	6	10+ years	
	Floor - Tile/Sheet	020-Multipurpose Room	2,565	SF	7	10+ years	
	Lighting - Pendent/Surface	020-Multipurpose Room	46	EA	7	10+ years	
	Walls - Concrete Block	020-Multipurpose Room	439	SF	6	10+ years	
	Walls - Plaster/Drywall	020-Multipurpose Room	439	SF	6	10+ years	
	Walls - Structural Glazed Tile	020-Multipurpose Room	879	SF	6	10+ years	
	Ceiling - Plaster/Drywall	300A Teacher's Lunchroom	720	SF	7	10+ years	
	Doors - Wood Doors inclu hw	300A Teacher's Lunchroom	4	ĒΑ	6	10+ years	
	Floor - Tile/Sheet	300A Teacher's Lunchroom	720	SF	7	10+ years	
	Lighting - Lay-in	300A Teacher's Lunchroom	20	ĒΑ	7	10+ years	
	Walls - Plaster/Drywall	300A Teacher's Lunchroom	1,280	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,460	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	2,460	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2,400	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	4,920	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	4,920 120	EA	6	10+ years	
	Serving Line	3rd Floor		LF			
	SELVITO LITTE	310 F1001	40 3,000	SF	6 6	10+ years 10+ years	

Campus Name: Camras Page: 10 of 43 Assessment Date: 10/12/2021



Categor	ry : Room		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Finishes	1st Floor	341	SF	5	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	6-10 years	Split unit
Mechanio	cal/ Service Rooms						
	Storage Room	000A Storage	100	SF	7	10+ years	
	Storage Room	000B Storage	445	SF	7	10+ years	
	Mechanical/ Service Rooms	001A Elevator Machine Room	100	SF	7	10+ years	
	Storage Room	002 Storage	1,000	SF	7	10+ years	
	Storage Room	003 Storage	250	SF	5	10+ years	
	Storage Room	007 Storage	450	SF	5	10+ years	
	Storage Room	009 - Storage	540	SF	7	10+ years	
	Storage Room	009A Storage	200	SF	7	10+ years	
	Storage Room	100F Laptop Charging/Storage	100	SF	5	10+ years	
	Vaults	112B Vault /Safe	50	SF	7	10+ years	Not accessible
	Janitor's Closet	1st Floor	16	SF	5	10+ years	Not accessible
	Storage Room	200F - Laptop Charging	1,000	SF	5	10+ years	
	Storage Room	Room/Storage	1,000		3	10+ years	
	Janitor's Closet	2nd Floor	7	SF	7	10+ years	
	Janitor's Closet	2nd Floor	15	SF	5	10+ years	
	Storage Room	300F Storage	100	SF	5	10+ years	Light does not work
	Storage Room	300G Storage	50	SF	5	10+ years	
	Storage Room	300H - Laptop Charging Room /Storage	100	SF	5	10+ years	
	Janitor's Closet	3rd Floor	6	SF	5	10+ years	
	Janitor's Closet	3rd Floor	15	SF	7	10+ years	
	Boiler Room	Basement	2,101	SF	5	10+ years	
	Janitor's Closet	Basement	25	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	96	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	61	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	113	SF	5	10+ years	
	Janitor's Closet	Basement	15	SF	5	6-10 years	
	Janitor's Closet	Dasement	10	OI.	3	0-10 years	
Restroom		0054				0.40	
	Accessories	005A	50	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	005A	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	005A	1	EA	6	10+ years	
	Floor - Terrazzo	005A	50	SF	6	10+ years	
	Lavatory	005A	1	EA	6	10+ years	
	Lighting - Lay-in	005A	1	EA	6	10+ years	
	Partitions	005A	1	EA	5	10+ years	
	Walls - Plaster/Drywall	005A	75	SF	6	10+ years	
	Walls - Structural Glazed Tile	005A	125	SF	6	10+ years	
	Water Closet	005A	1	EA	6	10+ years	



Catego	Category : Room		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	009A-1	50	SF	7	6-10 years	Observed- in good condition
	Ceiling - Plaster/Drywall	009A-1	50	SF	7	10+ years	Observed- in good condition
	Doors - Wood Doors inclu hw	009A-1	1	EA	6	10+ years	
	Floor - Terrazzo	009A-1	50	SF	7	10+ years	Observed- in good condition
	Lavatory	009A-1	1	EA	6	10+ years	
	Lighting - Lay-in	009A-1	1	EA	6	10+ years	
	Partitions	009A-1	1	EA	7	6-10 years	Observed- in good condition
	Walls - Plaster/Drywall	009A-1	200	SF	6	10+ years	ŭ
	Water Closet	009A-1	1	EA	6	10+ years	
	Accessories	018-Boys	174	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	018-Boys	174	SF	7	10+ years	
	Doors - Steel Doors incl hw	018-Boys	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	018-Boys	174	SF	6	10+ years	
	Floor Drain	018-Boys	1	EA	7	10+ years	
	Lavatory	018-Boys	2	EA	6	10+ years	
	Lighting - Pendent/Surface	018-Boys	2	EA	7	10+ years	
	Partitions	018-Boys	3	EA	7	10+ years	
	Urinals	018-Boys	2	EA	6	10+ years	
	Walls - Plaster/Drywall	018-Boys	158	SF	7	10+ years	
	Walls - Flaster/Drywall Walls - Tile Ceramic/ Porcelain	018-Boys	318	SF	7	10+ years	
	Water Closet	018-Boys	310	EA	7	•	
		•	80	SF	7	10+ years	
	Accessories	111A - In 111		SF SF		6-10 years	
	Ceiling - Lay-in	111A - In 111	64	SF SF	6	10+ years	Matan dama ara
	Ceiling - Lay-in	111A - In 111	16		5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	111A - In 111	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	111A - In 111	80	SF	6	10+ years	
	Lavatory	111A - In 111	1	EA	6	10+ years	
	Lighting - Pendent/Surface	111A - In 111	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	111A - In 111	315	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	111A - In 111	5	SF	4	1-2 years	Damaged behind toilet
	Water Closet	111A - In 111	1	EA	7	10+ years	
	Accessories	115 A	83	SF	7	10+ years	
	Ceiling - Plaster/Drywall	115 A	83	SF	6	10+ years	
	Doors - Steel Doors incl hw	115 A	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	115 A	83	SF	6	10+ years	
	Floor Drain	115 A	1	EA	7	10+ years	
	Lavatory	115 A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	115 A	1	EA	7	10+ years	
	Walls - Concrete Block	115 A	46	SF	6	10+ years	
	Walls - Plaster/Drywall	115 A	137	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	115 A	234	SF	7	10+ years	
	Water Closet	115 A	1	EA	6	10+ years	
	Accessories	1st Floor Girls	245	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Girls	245	SF	6	10+ years	

Campus Name: Camras Page: 12 of 43 Assessment Date: 10/12/2021



Catego	ry : Room	Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor Girls	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls	245	SF	6	10+ years	
	Floor Drain	1st Floor Girls	1	EA	7	10+ years	
	Hand Dryer	1st Floor Girls	1	EA	7	10+ years	
	Lavatory	1st Floor Girls	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Girls	3	EA	6	10+ years	
	Partitions	1st Floor Girls	5	EA	5	10+ years	
	Walls - Concrete Block	1st Floor Girls	200	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Girls	600	SF	6	10+ years	
	Water Closet	1st Floor Girls	5	ĒΑ	6	10+ years	
	Accessories	2nd Floor Girls	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls	225	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Girls	20	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girls	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls	245	SF	6	10+ years	
	Floor Drain	2nd Floor Girls 2nd Floor Girls	1	EA	7	10+ years	
	Hand Dryer	2nd Floor Girls 2nd Floor Girls	1	EA	7	10+ years	
	Lavatory	2nd Floor Girls 2nd Floor Girls	3	EA	6	10+ years	
						,	
	Lighting - Lay-in	2nd Floor Girls	3	EΑ	7	10+ years	
	Partitions	2nd Floor Girls	5	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Girls	200	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Girls	600	SF	7	10+ years	
	Water Closet	2nd Floor Girls	5	EA	7	10+ years	
	Accessories	2nd Floor North Girls	352	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor North Girls	352	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor North Girls	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor North Girls	352	SF	6	10+ years	
	Floor Drain	2nd Floor North Girls	1	EA	7	10+ years	
	Hand Dryer	2nd Floor North Girls	1	EA	7	10+ years	
	Lavatory	2nd Floor North Girls	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor North Girls	4	EA	7	10+ years	
	Partitions	2nd Floor North Girls	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor North Girls	196	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor North Girls	588	SF	7	10+ years	
	Water Closet	2nd Floor North Girls	5	EA	7	10+ years	
	Accessories	3rd Floor Girls	245	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor Girls	245	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Girls	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Girls	245	SF	6	10+ years	
	Floor Drain	3rd Floor Girls	1	ĒΑ	7	10+ years	
	Hand Dryer	3rd Floor Girls	1	EΑ	7	10+ years	
	Lavatory	3rd Floor Girls	3	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor Girls	5	EA	7	10+ years	
	Partitions	3rd Floor Girls	5	EA	7	10+ years	
	- Gradiono	014 1 1001 01110	3	_/\	,	ioi youis	

Campus Name: Camras Page: 13 of 43 Assessment Date: 10/12/2021



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor Girls	202	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor Girls	610	SF	7	10+ years	
	Water Closet	3rd Floor Girls	5	EA	7	10+ years	
	Accessories	3rd Floor Girls North	358	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor Girls North	358	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor Girls North	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Girls North	358	SF	6	10+ years	
	Floor Drain	3rd Floor Girls North	1	EA	7	10+ years	
	Lavatory	3rd Floor Girls North	3	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor Girls North	3	EA	7	10+ years	
	Partitions	3rd Floor Girls North	5	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor Girls North	357	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor Girls North	509	SF	6	10+ years	
	Water Closet	3rd Floor Girls North	6	ĒΑ	6	10+ years	
	Accessories	Boys 1st Fl	200	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Boys 1st Fl	200	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boys 1st Fl	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys 1st Fl	200	SF	6	10+ years	
	Floor Drain	Boys 1st Fl	1	ĒΑ	7	10+ years	
	Hand Dryer	Boys 1st Fl	1	ĒΑ	7	10+ years	
	Lavatory	Boys 1st Fl	2	EA	6	10+ years	
	Lighting - Lay-in	Boys 1st Fl	2	EA	6	10+ years	
	Partitions	Boys 1st Fl	2	EA	7	10+ years	
	Urinals	Boys 1st Fl	2	ĒΑ	6	10+ years	
	Walls - Concrete Block	Boys 1st Fl	120	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boys 1st Fl	400	SF	6	10+ years	
	Water Closet	Boys 1st Fl	2	ĒΑ	6	10+ years	
	Accessories	Boys 2nd Fl	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys 2nd Fl	145	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Boys 2nd Fl	100	SF	5	2-5 years	
	Doors - Wood Doors inclu hw	Boys 2nd Fl	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys 2nd Fl	245	SF	6	10+ years	
	Floor Drain	Boys 2nd Fl	1	ĒΑ	7	10+ years	
	Hand Dryer	Boys 2nd Fl	1	EA	7	10+ years	
	Lavatory	Boys 2nd Fl	3	EA	6	10+ years	
	Lighting - Lay-in	Boys 2nd Fl	3	EA	7	10+ years	
	Partitions	Boys 2nd Fl	2	EA	7	10+ years	
	Urinals	Boys 2nd Fl	3	EA	6	10+ years	
	Walls - Plaster/Drywall	Boys 2nd Fl	200	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boys 2nd Fl	600	SF	7	10+ years	
	Water Closet	Boys 2nd Fl	2	EA	6	10+ years	
	Accessories	Boys 3rd Fl	245	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Boys 3rd Fl	245	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boys 3rd Fl	1	EA	7	10+ years	
		,	·		•	,	

Campus Name: Camras Page: 14 of 43 Assessment Date: 10/12/2021



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Boys 3rd Fl	245	SF	6	10+ years	
	Floor Drain	Boys 3rd Fl	1	EA	7	10+ years	
	Hand Dryer	Boys 3rd Fl	1	EA	7	10+ years	
	Lavatory	Boys 3rd Fl	3	EA	7	10+ years	
	Lighting - Chandelier, Incandescent	Boys 3rd Fl	1	EA	7	6-10 years	Quantity changed to update current observation
	Lighting - Lay-in	Boys 3rd Fl	3	EA	7	10+ years	Quantity changed to update current observation
	Partitions	Boys 3rd Fl	2	EA	7	10+ years	
	Urinals	Boys 3rd Fl	3	EA	6	10+ years	
	Walls - Plaster/Drywall	Boys 3rd Fl	200	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boys 3rd Fl	610	SF	6	10+ years	
	Water Closet	Boys 3rd Fl	2	EA	6	10+ years	
	Accessories	Girls Basement	250	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls Basement	250	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Girls Basement	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls Basement	250	SF	6	10+ years	
	Floor Drain	Girls Basement	1	EA	7	10+ years	
	Lavatory	Girls Basement	3	EΑ	6	10+ years	
	Lighting - Lay-in	Girls Basement	3	EA	7	10+ years	
	Partitions	Girls Basement	5	EΑ	7	10+ years	
	Walls - Concrete Block	Girls Basement	200	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girls Basement	600	SF	7	10+ years	
	Water Closet	Girls Basement	6	EΑ	7	10+ years	
	Accessories	Unisex 1st FL	80	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex 1st FL	80	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Unisex 1st FL	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex 1st FL	80	SF	6	10+ years	
	Lavatory	Unisex 1st FL	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Unisex 1st FL	1	EΑ	6	10+ years	
	Walls - Plaster/Drywall	Unisex 1st FL	400	SF	6	10+ years	
	Water Closet	Unisex 1st FL	1	EA	7	10+ years	
	Accessories	Unisex Staff 3rd FI	80	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Unisex Staff 3rd FI	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex Staff 3rd FI	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Staff 3rd FI	80	SF	6	10+ years	
	Lavatory	Unisex Staff 3rd FI	1	EA	6	10+ years	
	Lighting - Lay-in	Unisex Staff 3rd FI	1	EA	6	10+ years	
	Walls - Concrete Block	Unisex Staff 3rd FI	108	SF	7	10+ years	
	Walls - Plaster/Drywall	Unisex Staff 3rd FI	44	SF	7	10+ years	
	Walls - Plaster/Drywall	Unisex Staff 3rd Fl	400	SF	7	10+ years	
	Water Closet	Unisex Staff 3rd FI	1	EA	7	10+ years	
						•	

Campus Name: Camras Page : 15 of 43 Assessment Date: 10/12/2021



Category : Classroom		В	uilding	: Main		
5 /			J		Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroom #008 (Art Room)						
AC Units	Basement	1	EA	7	6-10 years	
Casework	Basement	12	LF	6	10+ years	
Ceiling - Plaster/Drywall	Basement	1,000	SF	6	10+ years	
Doors - Wood Doors inclu hw		2	ĒΑ	6	10+ years	
Floor - Tile	Basement	1,000	SF	6	10+ years	
Lighting - Lay-in	Basement	8	ĒΑ	6	10+ years	
Lighting - Pendent/Surface	Basement	12	EA	6	10+ years	
Walls - Plaster/Drywall	Basement	1,325	SF	6	10+ years	
Work Sink	Basement	2	EA	7	6-10 years	2 work sinks
Classroom #014 (Art Room)						
AC Units	Basement	1	EA	7	6-10 years	
Casework	Basement	16	LF	6	10+ years	
Ceiling - Plaster/Drywall	Basement	840	SF	7	10+ years	
Chalk Board	Basement	12	LF	4	2-5 years	
Doors - Wood Doors inclu hw		2	EΑ	6	10+ years	
Floor - Tile	Basement	840	SF	6	10+ years	
Lighting - Pendent/Surface	Basement	16	ĒΑ	7	10+ years	
Walls - Plaster/Drywall	Basement	973	SF	6	10+ years	
Work Sink	Basement	2	EA	7	10+ years	
Classroom #102 (Kindergarten)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	8	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
Doors - Wood Doors inclu hw		1	EA	7	10+ years	
Floor - Tile	1st Floor	730	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	12	EA	6	10+ years	
Marker Board	1st Floor	24	LF	6	10+ years	
Walls - Plaster/Drywall	1st Floor	1,130	SF	7	10+ years	
Classroom #104 (Kindergarten)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	8	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	730	SF	6	10+ years	
Doors - Wood Doors inclu hw		1	EA	6	10+ years	
Floor - Tile	1st Floor	730	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
Marker Board	1st Floor	24	LF	6	10+ years	
Walls - Plaster/Drywall	1st Floor	1,130	SF	7	10+ years	
Classroom #111 (Pre School)						

Campus Name: Camras Page : 16 of 43 Assessment Date: 10/12/2021



Units sework Iling - Plaster/Drywall ors - Wood Doors inclu hw or - Tile hting - Pendent/Surface rker Board Ills - Plaster/Drywall 13 (Kindergarten) Units sework Iling - Plaster/Drywall ors - Wood Doors inclu hw	Location 1st Floor	Quantity 1 24 1,008 1 1,008 14 20 1,380	UOM EA LF SF EA SF EA LF SF	Rank 7 6 6 6 6 6 7	Recommend Replacement 6-10 years 10+ years	Comments
Units sework iling - Plaster/Drywall ors - Wood Doors inclu hw or - Tile hting - Pendent/Surface rker Board ills - Plaster/Drywall 13 (Kindergarten) Units sework iling - Plaster/Drywall	1st Floor	1 24 1,008 1 1,008 14 20 1,380	EA LF SF EA SF EA LF	7 6 6 6 6 6	6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
sework lling - Plaster/Drywall ors - Wood Doors inclu hw or - Tile hting - Pendent/Surface rker Board ills - Plaster/Drywall 13 (Kindergarten) Units sework lling - Plaster/Drywall	1st Floor	24 1,008 1 1,008 14 20 1,380	LF SF EA SF EA LF	6 6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
lling - Plaster/Drywall ors - Wood Doors inclu hw or - Tile hting - Pendent/Surface rker Board ills - Plaster/Drywall 13 (Kindergarten) Units sework iling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1,008 1 1,008 14 20 1,380	SF EA SF EA LF	6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years	
ors - Wood Doors inclu hw or - Tile hting - Pendent/Surface rker Board ills - Plaster/Drywall 13 (Kindergarten) Units sework iling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 1,008 14 20 1,380	EA SF EA LF	6 6 6	10+ years 10+ years 10+ years 10+ years	
ors - Wood Doors inclu hw or - Tile hting - Pendent/Surface rker Board ills - Plaster/Drywall 13 (Kindergarten) Units sework iling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor	1,008 14 20 1,380	SF EA LF	6 6 6	10+ years 10+ years 10+ years 10+ years	
or - Tile hting - Pendent/Surface rker Board ills - Plaster/Drywall 13 (Kindergarten) Units sework iling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor	14 20 1,380	EA LF	6 6 6	10+ years 10+ years 10+ years	
rker Board Ills - Plaster/Drywall 13 (Kindergarten) Units sework Iling - Plaster/Drywall	1st Floor 1st Floor 1st Floor	14 20 1,380	EA LF	6	10+ years 10+ years	
rker Board Ills - Plaster/Drywall 13 (Kindergarten) Units sework Iling - Plaster/Drywall	1st Floor 1st Floor 1st Floor	20 1,380	LF	6	10+ years	
Ills - Plaster/Drywall 13 (Kindergarten) Units sework iling - Plaster/Drywall	1st Floor 1st Floor	1,380		-		
Units sework lling - Plaster/Drywall		1				
Units sework lling - Plaster/Drywall		1				
sework iling - Plaster/Drywall			EA	7	6-10 years	
iling - Plaster/Drywall	13111001	20	LF	6	10+ years	
ors - Wood Doors inclu hw	1st Floor	780	SF	6	10+ years	
015 - WOOG DOOLS HICK HW	1st Floor	1	EA	6	10+ years	
or - Tile	1st Floor	780	SF		-	
				6	10+ years	
				_		
ilis - Plaster/Drywali	1st Floor	1,200	SF	6	10+ years	
15 (Kindergarten)						
Units	1st Floor	1		7	6-10 years	
sework	1st Floor	3		6	10+ years	
iling - Plaster/Drywall	1st Floor	960		6	10+ years	
ors - Wood Doors inclu hw	1st Floor	2		6	10+ years	
or - Tile	1st Floor	960	SF	6	10+ years	
hting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
ills - Plaster/Drywall	1st Floor	1,274	SF	6	10+ years	
rk Sink	1st Floor	1	EA	7	10+ years	
16 (Regular Classroom)						
,	1st Floor	1	FA	7	6-10 years	
ors - Wood Doors inclu hw						
					•	
ills - Plaster/Drywall	1st Floor	1,324	SF	6	10+ years	
10 (Kindorgarton)						
	1ot Floor	4	Γ^	7	2 5 112272	
					-	
ors - vvood Doors Inclu hw	1st Floor	2	ΕA	6	10+ years	
tri cotto	Inting - Pendent/Surface Irker Board Ills - Plaster/Drywall 15 (Kindergarten) Units Isework Iling - Plaster/Drywall Iors - Wood Doors inclu hw Ior - Tile Inting - Pendent/Surface Ills - Plaster/Drywall Irk Sink 16 (Regular Classroom) Units Iling - Plaster/Drywall Iors - Wood Doors inclu hw Ior - Tile Iors - Wood Doors inclu hw Ior - Tile Inting - Pendent/Surface Inting - Pendent/Surface Irker Board	Inting - Pendent/Surface Incker Board Its - Plaster/Drywall Ist Floor Its (Kindergarten) Units Ist Floor	1st Floor 12 1st Floor 20 1st Floor 20 1st Floor 2st Floor 1st Floor 1	1st Floor 1st	1st Floor 12	1st Floor 12



Catego	ry : Classroom		В	uilding	: Main		•
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	1,204	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	10+ years	
	Marker Board	1st Floor	14	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,423	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	10+ years	
	Marker Board	2nd Floor	18	LF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,329	SF	6	10+ years	
Classroc	om #204 (Regular Classroom)						
Oldooroo	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	10+ years	
	Marker Board	2nd Floor	18	LF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,325	SF	6	10+ years	
Classroc	om #211 (Science Lab Level 3)						
Oldooroo	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,071	SF	6	10+ years	Edited to match room size
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	Edited to mater room size
	Floor - Tile	2nd Floor	1,071	SF	7	10+ years	Edited to match room size
	Gas Line	2nd Floor	2	EA	6	10+ years	Luited to mater room size
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	10+ years	
	Marker Board	2nd Floor	20	LF	6	10+ years	
		2nd Floor	85	SF	7		
	Storage/ Closet Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,350	SF	6	10+ years 10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years 10+ years	
Classroo	om #212 (Regular Classroom)						
<u> </u>	AC Units	2nd Floor	4	ΕΛ	7	6 10 years	
		2nd Floor 2nd Floor	1 8	EA LF	7	6-10 years	
	Casework			SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	5 F	6	10+ years	

Campus Name: Camras Page: 18 of 43 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,176	SF	6	10+ years	
Classroo	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	885	SF	7	10+ years	Edited to match room size
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Editod to materi room size
	Floor - Tile	2nd Floor	885	SF	7	10+ years	Edited to match room size
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	10+ years	Luited to mater room size
	Marker Board	2nd Floor	18	LF	6	10+ years	
	Storage/ Closet	2nd Floor	85	SF	7	•	
	Malla Diagtar/Drawall			SF SF		10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,300	5F	7	10+ years	
lassroc	nm #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	24	LF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,176	SF	6	10+ years	
Classroo	om #215 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	3	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	964	SF	6	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	964	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	6	1-2 years	Light switch broken
	Marker Board	2nd Floor	27	LF	6	10+ years	Light ownor broken
	Walls - Plaster/Drywall	2nd Floor	1,295	SF	6	10+ years	
:lassroo	nm #216 (Regular Classroom)						
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	AC Units	2nd Floor	4	EA	7	6-10 years	
		2nd Floor 2nd Floor	1 7	LF	7		
	Casework				6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	6	10+ years	

Campus Name: Camras Page: 19 of 43 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	6	10+ years	
	Marker Board	2nd Floor	14	LF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,090	SF	6	10+ years	
Classroo	m #217 (Regular Classroom)						
0,000,00	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	734	SF		•	
					6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	743	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Marker Board	2nd Floor	20	LF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,113	SF	6	10+ years	
Classroo	m #218C (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	732	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Marker Board	2nd Floor	38	LF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,050	SF	6	10+ years 10+ years	
Classroo	m #218D (Regular Classroom)						
Classico	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	732	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	732	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	38	LF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,050	SF	6	10+ years	
Classroo	m #218E (Regular Classroom)						_
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	14	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,041	SF	6	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	1,041	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	28	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,556	SF	7	10+ years	
lassroc	om #219 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	733	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	733	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
	Marker Board	2nd Floor	34	LF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,159	SF	6	•	
	walls - Flastel/Drywall	2110 11001	1,159	SF	b	10+ years	
lassroc	m #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	6	10+ years	
	Marker Board	3rd Floor	18	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	6	10+ years	
lassroc	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EΑ	6	10+ years	
	Floor - Tile	3rd Floor	740	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6		
						10+ years	
	Marker Board	3rd Floor	18	LF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,305	SF	6	10+ years	
lassroc	om #309 (Science Lab Level 3)						
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Casework	3rd Floor	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,090	SF	6	10+ years	Edited to match room size
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	-
	Floor - Tile	3rd Floor	1,090	SF	7	10+ years	Edited to match room size



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	10+ years	
	Marker Board	3rd Floor	6	LF	6	10+ years	
	Storage/ Closet	3rd Floor	160	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,395	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
Classroo	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	830	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years 10+ years	
	Marker Board	3rd Floor		LF	7		
			10			6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	6	10+ years	
Classroo	nm #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	18	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,180	SF	7	10+ years	
Classroo	om #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	750	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	10+ years	
	Marker Board	3rd Floor	18	LF	6	10+ years	
	Walls - Concrete Block	3rd Floor	1,175	SF	7	10+ years 10+ years	
Classes -	om #245 (Computer Lab)						
Ciassi00	om #315 (Computer Lab)	01 []				0.40	
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Splined	3rd Floor	980	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	980	SF	7	10+ years	

Campus Name: Camras Page : 22 of 43 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	10+ years	
	Marker Board	3rd Floor	34	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,248	SF	6	10+ years	
Classroo	om #316 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	780	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Tile	3rd Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	6	10+ years	
	Marker Board	3rd Floor	16	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,090	SF	6	10+ years	
Classroo	om #317 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	742	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	742	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	10+ years	
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,058	SF	6	10+ years	
Classro	om #318C (Regular Classroom)						
Ciassion	AC Units	3rd Floor	1	EA	7	6.10 years	
			1 7	LF		6-10 years	
	Casework	3rd Floor		SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	744		7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA SF	6	10+ years	
	Floor - Tile	3rd Floor	744		7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,060	SF	6	10+ years	
Classroo	om #318D (Regular Classroom)	. —					
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	743	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	743	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,015	SF	6	10+ years	

Campus Name: Camras Page : 23 of 43 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Main		7000 N Marigo AVENOE, Officago, IE 00034
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #318E (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	380	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	380	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	10+ years	
	Marker Board	3rd Floor	14	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	915	SF	6	10+ years	
Classroo	om #318F (Store Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	692	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	692	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	10+ years	
	Marker Board	3rd Floor	12	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,015	SF	6	10+ years	
	walls - Flaster/Drywall	314 1 1001	1,013	OI.	O	10+ years	
Classroo	om #319 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	740	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	740	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	40	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,056	SF	6	10+ years	
Catego	ry : Interior		R	uilding	· Main		
Jalogo	. ,			uiig		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Corridor							
	Ceiling - Lay-in	1st Floor - North Corridor	135	SF	6	10+ years	
	Ceiling - Splined	1st Floor - North Corridor	1,017	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor - North Corridor	2	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor - North Corridor	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor - North Corridor	1,152	SF	6	10+ years	
	Lighting - Lay-in	1st Floor - North Corridor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - North Corridor	1,474	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - North Corridor	870	SF	7	10+ years	
	Ceiling - Splined	1st Floor - South	2,800	SF	6	10+ years	



Catego	Category : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors include hw	1st Floor - South	6	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor - South	3	EA	7	10+ years	
	Floor - Terrazzo	1st Floor - South	2,800	SF	6	10+ years	
	Lighting - Lay-in	1st Floor - South	22	EA	6	10+ years	
	Stairs - Terrazzo	1st Floor - South	180	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - South	2,275	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - South	2,275	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor - North Corridor	279	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - North Corridor	131	SF	7	10+ years	
	Ceiling - Splined	2nd Floor - North Corridor	872	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor - North Corridor	2	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor - North Corridor	1,282	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor - North Corridor	22	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor - North Corridor	85	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - North Corridor	1,484	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - North Corridor	985	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor - South	1,907	SF	6	10+ years	
	Ceiling - Splined	2nd Floor - South	818	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor - South	4	EA	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor - South	3	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor - South	2,725	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor - South	20	EA	6	10+ years	
	Student Lockers - One Tier	2nd Floor - South	72	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - South	2,100	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - South	2,200	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor - North Corridor	279	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor - North Corridor	131	SF	6	10+ years	
	Ceiling - Splined	3rd Floor - North Corridor	872	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor - North Corridor	2	EΑ	7	10+ years	
	Floor - Terrazzo	3rd Floor - North Corridor	1,282	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor - North Corridor	22	EA	7	10+ years	
	Student Lockers - One Tier	3rd Floor - North Corridor	85	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor - North Corridor	1,484	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor - North Corridor	985	SF	6	10+ years	
	Ceiling - Splined	3rd Floor - South	2,725	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor - South	2	EA	6	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor - South	3	EΑ	7	10+ years	
	Floor - Terrazzo	3rd Floor - South	2,725	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor - South	20	EA	7	10+ years	
	Student Lockers - One Tier	3rd Floor - South	80	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor - South	2,300	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor - South	2,300	SF	7	10+ years	
	Ceiling - Lay-in	Basement - North Corridor	423	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - North Corridor	209	SF	7	10+ years	
						•	

Campus Name: Camras Page : 25 of 43 Assessment Date: 10/12/2021



Catego	ory : Interior		В	uilding	: Main				
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Splined	Basement - North Corridor	534	SF	6	10+ years			
	Floor - Terrazzo	Basement - North Corridor	423	SF	6	10+ years			
	Floor - Tile/Sheet	Basement - North Corridor	743	SF	7	10+ years			
	Lighting - Pendent/Surface	Basement - North Corridor	10	EΑ	7	10+ years			
	Walls - Concrete Block	Basement - North Corridor	534	SF	6	10+ years			
	Walls - Plaster/Drywall	Basement - North Corridor	913	SF	6	10+ years			
	Walls - Structural Glazed Tile	Basement - North Corridor	1,052	SF	6	10+ years			
	Ceiling - Lay-in	Basement South	1,000	SF	6	10+ years			
	Ceiling - Splined	Basement South	1,550	SF	6	10+ years			
	Doors - Wood Doors include hw	Basement South	4	EA	6	10+ years			
	Drinking Fountains - Single Fountain	Basement South	3	EΑ	7	10+ years			
	Floor - Terrazzo	Basement South	2,550	SF	6	10+ years			
	Lighting - Lay-in	Basement South	20	EA	7	10+ years			
	Walls - Plaster/Drywall	Basement South	2,200	SF	6	10+ years			
	Walls - Structural Glazed Tile	Basement South	2,200	SF	6	10+ years			
Safety									
Calety	Camera Viewing Station	Throughout Building	1	EA	7	10+ years			
	Security Cameras	Throughout Building	24	EΑ	7	6-10 years			
	•	3 3				,			
Stairs									
	Ceiling - Plaster/Drywall	Center Stairs	920	SF	6	10+ years			
	Floor - Terrazzo	Center Stairs	816	SF	6	10+ years			
	Handrails	Center Stairs	230	LF	7	10+ years			
	Lighting - Wall Mounted	Center Stairs	5	EA	6	10+ years			
	Stairs - Terrazzo	Center Stairs	1,015	LF	6	10+ years			
	Walls - Plaster/Drywall	Center Stairs	2,160	SF	7	10+ years			
	Walls - Structural Glazed Tile	Center Stairs	2,275	SF	7	10+ years			
	Ceiling - Plaster/Drywall	North East	513	SF	6	10+ years			
	Floor - Terrazzo	North East	408	SF	6	10+ years			
	Handrails	North East	164	LF	7	10+ years			
	Lighting - Pendent/Surface	North East	4	EA	7	10+ years			
	Lighting - Wall Mounted	North East	1	EA	7	10+ years			
	Stairs - Terrazzo	North East	338	LF	6	10+ years			
	Walls - Plaster/Drywall	North East	1,917	SF	6	10+ years			
	Walls - Structural Glazed Tile	North East	639	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Stair G-North/East	513	SF	6	10+ years			
	Floor - Terrazzo	Stair G-North/East	408	SF	6	10+ years			
	Handrails	Stair G-North/East	164	LF	7	10+ years			
	Lighting - Pendent/Surface	Stair G-North/East	4	EA	7	10+ years			
	Lighting - Wall Mounted	Stair G-North/East	1	EA	7	10+ years			
	Stairs - Terrazzo	Stair G-North/East	338	LF	6	10+ years			
	Walls - Plaster/Drywall	Stair G-North/East	1,917	SF	6	10+ years			
	Walls - Structural Glazed Tile	Stair G-North/East	639	SF	6	10+ years			

Campus Name: Camras Page : 26 of 43 Assessment Date: 10/12/2021



Category : Interior		Building : Main
Group Item - Type	Location	Recommend Quantity UOM Rank Replacement Comments
Vertical Conveyance		
Elevator - Hydraulic Elevator Elevator - Hydraulic Elevator	1st Floor 1st Floor	1 EA 7 10+ years 1 EA 7 10+ years

Campus Name: Camras Page : 27 of 43 Assessment Date: 10/12/2021



Catego	ry : Exterior		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	9						
	Exterior Doors - Exterior FRP Door	10	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	10	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	9	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	9	1	EA	6	10+ years	
	Exterior Stairs - Stone	9	7	LF	7	10+ years	
_Foundat	on						
	Foundation - Concrete	Entire Building	294	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	26,826	SF	7	10+ years	
	•	Ğ				·	
_Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	7	10+ years	Non-Present on this Addition Roof/Parapet
	Exterior Lighting - Wall Mounted	Entire Building	7	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	4	1-2 years	Weathered
_Roof Sys							
	Chimney - Metal Flue	F	5	LF	6	10+ years	
	Coping - Metal	F	304	LF	6	10+ years	
	Downspouts - Interior Downspouts	F	196	LF	6	10+ years	
	Roof - Modified Bitumen	F	6,644	SF	6	6-10 years	
	Roof Structure - Concrete	F	6,644	SF	7	10+ years	
	Coping - Metal	G	10	LF	7	10+ years	5
	Downspouts - Interior Downspouts	G	15	LF	6	10+ years	Drain is Clogged - Water Puddled on Roof.
	Roof - Modified Bitumen	G	250	SF	5	2-5 years	Monitor Roof.
	Roof Structure - Concrete	G	250	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Entire Building	11,250	SF	7	10+ years	Cleaned - Per "POC"
_Windows							
	Curtain wall - Glazed Single Pane	Entire Building	65	SF	6	10+ years	Windows in Main Building
	Curtain wall - Insulated Panel	Entire Building	58	SF	6	10+ years	Times in the Danding
	Curtain wall - Windows	Entire Building	22	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	235	SF	6	10+ years	Scrape/Paint - Modified ornamental
		g			-	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Fence, made burglar Bars/Window Guards.
	Lintels - Steel	Entire Building	487	LF	7	10+ years	
	Windows - Louver	Entire Building	30	SF	6	10+ years	
		3			-	,	

Campus Name: Camras Page : 28 of 43 Assessment Date: 10/12/2021



Categor	y : Exterior		R	uildina	: Addition		000 N Mango Avenue, Chicago, IL 80
categor	y . Lxterior		January 1	unung	. Additio	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Windows - Sash Aluminum Double-pane	Entire Building	3,667	SF	6	10+ years	Comments
	-		_		A 1 1141		
Categor	y : Electrical		В	uilding	: Addition		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	cy System		4.0.0		110		
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	17	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Security System - CCTV	Entire Building	26,826	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	26,826	SF	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	20,020	EA	6	6-10 years	
			 			•	
	Exit Signs - Corridors and Stairs	Entire Building	11	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,200	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,600	SF	6	6-10 years	
Main Sen	vice						
	PA System	Entire Building	26,826	SF	6	6-10 years	Connected to main building
Power Di	stribution						
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	
Categor	y : Fire Protection		В	uilding	: Additio	on	
Ĭ.						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarn	n						
	Fire Alarm Strobe Lights	Entire Building	26,826	SF	6	10+ years	
	Fire Alarm_System	Entire Building	26,826	SF	5	6-10 years	Connected to main building
	=-,						
Categor	y : Mechanical		В	uilding	: Additio		
_	•	Location	B	uilding UOM	: Addition	Recommend	Comments
Group	y : Mechanical Item - Type	Location				Recommend	Comments
Group	y : Mechanical	Location 3rd Floor				Recommend	Comments Serves third floor and second floor

Assessment Date: 10/12/2021 Page : 29 of 43 Campus Name: Camras



Catego	ry : Mechanical		В	uilding	: Additi	on	•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Indoor- Hot Water Coils - Less than 4000						
	cfm	0.151	2	^	-	0.40	
	Air Intake	3rd Floor	3	EA	5	6-10 years	
Boiler Sy	ystems						
	Piping - Condensate Pipe- Steel	Entire Building	200	LF	5	6-10 years	Connects to main building
	Piping - Steam Pipe- Steel	Entire Building	200	LF	5	6-10 years	Connects to main building
	Steam Traps	Entire Building	15	EA	5	6-10 years	Serve steam radiators
Heating	Devices						
	Fin Tube - Hot Water	Entire Building	690	LF	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	3	EA	5	6-10 years	Recently cleaned, hot water, served
		·				·	by heat exchanger, 3 found. Recently serviced
	Wall Heater - Electric	Entire Building	4	EA	6	6-10 years	
	Radiators - Steam	Entire Building	15	EA	5	6-10 years	
_Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	600	LF	6	10+ years	Served by heat exchanger from main building
Tempera	ature Control						
	Electric Thermostat	Entire Building	3	EA	5	6-10 years	Serve single zone air handlers
	Thermostats - Pneumatic	Entire Building	15	EA	5	6-10 years	Control temperatures of radiators and fin tube heaters
Ventilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping	1,000	- COULIVII	Qualitity	00141	Italik	Nopidocinicit	Commonts
— Біпд							

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	26,826	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	26,826	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	26,826	SF	6	10+ years	
	Fixtures						

Campus Name: Camras Page : 30 of 43 Assessment Date: 10/12/2021



Catego	Category : Plumbing			uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	26,826	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	26,826	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	26,826	SF	6	10+ years	
	Sanitary Piping	Entire Building	26,826	SF	5	10+ years	
	Storm Piping	Entire Building	26,826	SF	5	6-10 years	
	Vent Piping	Entire Building	26,826	SF	6	10+ years	

Category: Room **Building: Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Splined	126	138	SF	7	10+ years	
	Doors - Wood Doors inclu hw	126	1	ĒΑ	6	10+ years	
	Floor - Tile	126	138	SF	6	10+ years	
	Lighting - Pendent/Surface	126	1	EA	7	10+ years	
	Power Distribution	126	8	EA	7	10+ years	
	Walls - Plaster/Drywall	126	434	SF	7	10+ years	
	Ceiling - Splined	128	138	SF	6	10+ years	
	Doors - Wood Doors inclu hw	128	1	EΑ	6	10+ years	
	Floor - Tile/Sheet	128	138	SF	7	10+ years	
	Lighting - Pendent/Surface	128	1	EA	7	10+ years	
	Power Distribution	128	8	EA	7	10+ years	
	Walls - Plaster/Drywall	128	434	SF	7	10+ years	
	Ceiling - Splined	130	138	SF	6	10+ years	
	Doors - Wood Doors inclu hw	130	1	EA	7	10+ years	
	Floor - Tile/Sheet	130	138	SF	7	10+ years	
	Lighting - Pendent/Surface	130	2	EA	7	10+ years	
	Power Distribution	130	8	EA	6	10+ years	
	Walls - Plaster/Drywall	130	449	SF	7	10+ years	
	Ceiling - Splined	132	137	SF	7	10+ years	
	Doors - Wood Doors inclu hw	132	1	EA	6	10+ years	
	Floor - Tile/Sheet	132	137	SF	7	10+ years	
	Lighting - Pendent/Surface	132	2	EA	7	10+ years	
	Power Distribution	132	8	EA	6	10+ years	
	Walls - Plaster/Drywall	132	434	SF	7	10+ years	
	Ceiling - Plaster/Drywall	134 Nurse Office	255	SF	6	10+ years	
	Doors - Wood Doors inclu hw	134 Nurse Office	1	EA	6	10+ years	
	Floor - Tile/Sheet	134 Nurse Office	255	SF	7	10+ years	
	Lighting - Pendent/Surface	134 Nurse Office	2	EA	7	10+ years	
	Power Distribution	134 Nurse Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	134 Nurse Office	598	SF	7	10+ years	

Campus Name: Camras Page : 31 of 43 Assessment Date: 10/12/2021



Catego	ategory : Room			uilding	: Additi		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
uditoriu	ım & Theater						
	Ceiling - Lay-in	023-Lecture Room	538	SF	7	10+ years	
	Ceiling - Splined	023-Lecture Room	2,437	SF	7	10+ years	
	Doors - Steel Doors incl hw	023-Lecture Room	4	EA	6	10+ years	
	Floor - Tile/Sheet	023-Lecture Room	2,975	SF	7	10+ years	
	Lighting - Pendent/Surface	023-Lecture Room	34	EA	7	10+ years	
	Main Floor Seating	023-Lecture Room	275	EA	7	10+ years	
	Stage	023-Lecture Room	590	SF	6	10+ years	
	Walls - Concrete Block	023-Lecture Room	738	SF	7	10+ years	
	Walls - Structural Glazed Tile	023-Lecture Room	1,722	SF	7	10+ years	
1echani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	19	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	149	SF	5	10+ years	
	Janitor's Closet	2nd Floor	54	SF	5	10+ years	
	Mechanical/ Service Rooms	2nd Floor	149	SF	5	10+ years	
	Janitor's Closet	3rd Floor	53	SF	5	10+ years	
	Mechanical/ Service Rooms	3rd Floor	269	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	148	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement	247	SF	5	6-10 years	
	Wednamaay Corvice Recome	Bacomoni		O.	Ū	o io jouio	
Restroor	m						
	Accessories	134A	74	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	134A	74	SF	6	10+ years	
	Doors - Wood Doors inclu hw	134A	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	134A	74	SF	6	10+ years	
	Floor Drain	134A	1	ĒΑ	7	10+ years	
	Lavatory	134A	1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	134A	1	EΑ	7	10+ years	
	Showers	134A	1	EΑ	5	10+ years	
	Walls - Concrete Block	134A	26	SF	7	10+ years	
	Walls - Plaster/Drywall	134A	77	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	134A	220	SF	7	10+ years	
	Water Closet	134A	1	EA	7	10+ years	
	Accessories	1st Floor Boys	106	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Boys	106	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Boys	100	EA	6	-	
	Floor - Tile Ceramic/ Porcelain	1st Floor Boys 1st Floor Boys	106	SF	6	10+ years	
						10+ years	
	Floor Drain	1st Floor Boys	1	EΑ	7	10+ years	
	Hand Dryer	1st Floor Boys	1	EΑ	7	10+ years	
	Lavatory	1st Floor Boys	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Boys	2	EA	7	10+ years	

Campus Name: Camras Page : 32 of 43 Assessment Date: 10/12/2021



Catego	ry : Room	-	В	uilding	: Additi	on	-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	1st Floor Boys	1	EA	7	10+ years	
	Urinals	1st Floor Boys	1	EA	6	10+ years	
	Walls - Concrete Block	1st Floor Boys	82	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Boys	134	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Boys	134	SF	6	10+ years	
	Water Closet	1st Floor Boys	1	EA	7	10+ years	
	Accessories	1st Floor Girls	106	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Girls	106	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Girls	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Girls	106	SF	6	10+ years	
	Floor Drain	1st Floor Girls	1	EA	7	10+ years	
	Hand Dryer	1st Floor Girls	1	EA	7	10+ years	
	Lavatory	1st Floor Girls	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Girls	2	EA	7	10+ years	
	Partitions	1st Floor Girls	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Girls	82	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Girls	134	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Girls	134	SF	7	10+ years	
	Water Closet	1st Floor Girls	2	EA	6	10+ years	
	Accessories	2nd Floor North Boys	338	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor North Boys	338	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor North Boys	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor North Boys	338	SF	7	10+ years	
	Floor Drain	2nd Floor North Boys	1	EA	7	10+ years	
	Hand Dryer	2nd Floor North Boys	1	EA	7	10+ years	
	Lavatory	2nd Floor North Boys	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor North Boys	6	EA	7	10+ years	
	Partitions	2nd Floor North Boys	3	EA	7	10+ years	
	Urinals	2nd Floor North Boys	3	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor North Boys	301	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor North Boys	186	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor North Boys	298	SF	7	10+ years	
	Water Closet	2nd Floor North Boys	3	EA	7	10+ years	
	Accessories	3rd Floor Boys	340	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Boys	340	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor Boys	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor Boys	340	SF	6	10+ years	
	Floor Drain	3rd Floor Boys	3 4 0	EA	7	,	
	Lavatory	3rd Floor Boys	3	EA	6	10+ years 10+ years	
	Lighting - Pendent/Surface	3rd Floor Boys	4	EA	7	-	
	Partitions			EA		10+ years	
		3rd Floor Boys	4		7	10+ years	
	Urinals	3rd Floor Boys	3	EA SF	6	10+ years	
	Walls - Concrete Block	3rd Floor Boys	285	SF SF	7 7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Boys	495	ЭF	1	10+ years	

Campus Name: Camras Page: 33 of 43 Assessment Date: 10/12/2021



Stoup Item - Type
Walls - Tile Ceramic/ Porcelain 3rd Floor Boys 180 SF 7 10+ years
Water Closet
Accessories
Ceiling - Plaster/Drywall Basement - 024-Girls 143 SF 6 10+ years
Doors - Steel Doors inch W Basement - 024-Girls 1 EA 6 10+ years Floor - Tile Ceramic/ Porcelain Basement - 024-Girls 143 SF 6 10+ years Floor Drain Basement - 024-Girls 1 EA 7 10+ years Floor Drain Basement - 024-Girls 1 EA 7 10+ years Floor Drain Basement - 024-Girls 2 EA 6 10+ years Floor Drain Floor Drain Floor Drain Basement - 024-Girls 2 EA 6 10+ years Floor Drain Floor F
Floor - Tile Ceramic/ Porcelain Basement - 024-Girls 143 SF 6 10+ years
Floor Drain
Lavatory
Lighting - Pendent/Surface
Lighting - Pendent/Surface Basement - 024-Girls 1 EA 7 10+ years Partitions Basement - 024-Girls 3 EA 7 10+ years Partitions Basement - 024-Girls 3 EA 7 10+ years Partitions Partitions Pasement - 024-Girls 96 SF 6 10+ years Partitions Pasement - 024-Girls 96 SF 6 10+ years Partitions Pasement - 024-Girls
Partitions
Walls - Concrete Block Basement - 024-Girls 96 SF 6 10+ years Walls - Structural Glazed Tile Basement - 024-Girls 94 SF 6 10+ years Walls - Tile Ceramic/ Porcelain Basement - 024-Girls 117 SF 6 10+ years Water Closet Basement - 024-Girls 3 EA 6 10+ years Category : Classroom Building : Addition Recommend Replacement Comments Category : Classroom Addition Recommend Replacement Comments Category : Classroom Addition Recommend Replacement Comments Classroom #026 (Music Room) AC Units Basement 4 EA 7 6-10 years Celling - Splined Basement 1,862 SF 6 10+ years Doors - Steel Doors incl hw Basement 1,862 SF 6 10+ years Lighting - Pendent/Surface Basement<
Walls - Structural Glazed Tile Basement - 024-Girls 94 SF 6 10+ years Walls - Tile Ceramic/ Porcelain Basement - 024-Girls 117 SF 6 10+ years Water Closet Basement - 024-Girls 117 SF 6 10+ years Basement - 024-Girls 3 EA 6 10+ years Category: Classroom Building: Addition Group Item - Type Location Quantity UOM Rank Replacement Comments Classroom #026 (Music Room) AC Units Basement 4 EA 7 6-10 years Ceiling - Splined Basement 1,862 SF 6 10+ years Ploors - Steel Doors incl hw Basement 4 EA 6 10+ years Floor - Tile Basement 1,862 SF 6 10+ years Lighting - Pendent/Surface Basement 15 EA 7 10+ years Walls - Concrete Block Basement 819 SF 6 10+ years Walls - Structural Glazed Tile Basement 819 SF 6 10+ years Walls - Structural Glazed Tile Basement 819 SF 6 10+ years
Walls - Tile Ceramic/ Porcelain Water Closet Basement - 024-Girls 117 SF 6 10+ years 6 10+ years Category : Classroom Building : Addition Recommend Recommend Recommend Recommend Recommend Recommend Replacement Classroom #026 (Music Room) AC Units Basement 4 EA 7 6-10 years Ceiling - Splined Basement 1,862 SF 6 10+ years Doors - Steel Doors incl hw Basement 4 EA 6 10+ years Floor - Tile Basement 1,862 SF 6 10+ years Lighting - Pendent/Surface Basement 1,862 SF 6 10+ years Walls - Concrete Block Basement 819 SF 6 10+ years Walls - Structural Glazed Tile Basement 819 SF 6 10+ years
Water Closet Basement - 024-Girls 3 EA 6 10+ years
Category : Classroom Classroom Classroom Location Quantity UOM Rank Recommend Recommend Recommend Recommend Replacement Comments Recommend Replacement Replacement Replacement Replacement Replacement Replacement Comments Recommend Replacement Replac
Group Item - Type Location Quantity UOM Rank Replacement Comments Classroom #026 (Music Room) AC Units Basement 1,862 SF 6 10+ years Doors - Steel Doors incl hw Basement 1,862 SF 6 10+ years Floor - Tile Basement 1,862 SF 6 10+ years Lighting - Pendent/Surface Basement 15 EA 7 10+ years Walls - Concrete Block Basement 819 SF 6 10+ years Walls - Structural Glazed Tile Basement 819 SF 6 10+ years Walls - Structural Glazed Tile Basement 819 SF 6 10+ years
Group Item - Type Location Quantity UOM Rank Replacement Comments Classroom #026 (Music Room) AC Units Basement 1,862 SF 6 10+ years Doors - Steel Doors incl hw Basement 1,862 SF 6 10+ years Floor - Tile Basement 1,862 SF 6 10+ years Lighting - Pendent/Surface Basement 15 EA 7 10+ years Walls - Concrete Block Basement 819 SF 6 10+ years Walls - Structural Glazed Tile Basement 819 SF 6 10+ years Walls - Structural Glazed Tile Basement 819 SF 6 10+ years
AC Units AC Units Basement AC Units Ceiling - Splined Basement Doors - Steel Doors incl hw Basement Floor - Tile Basement Base
AC Units Ceiling - Splined Basement Bas
AC Units Ceiling - Splined Basement Bas
Ceiling - Splined Basement Doors - Steel Doors incl hw Basement Floor - Tile Basement Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Basement Basemen
Doors - Steel Doors incl hw Floor - Tile Basement Lighting - Pendent/Surface Walls - Concrete Block Walls - Structural Glazed Tile Basement Basemen
Floor - Tile Lighting - Pendent/Surface Basement Walls - Concrete Block Walls - Structural Glazed Tile Basement
Lighting - Pendent/Surface Basement 15 EA 7 10+ years Walls - Concrete Block Basement 819 SF 6 10+ years Walls - Structural Glazed Tile Basement 819 SF 6 10+ years Classroom #125 (Kindergarten)
Walls - Concrete Block Basement 819 SF 6 10+ years Walls - Structural Glazed Tile Basement 819 SF 6 10+ years Classroom #125 (Kindergarten)
Walls - Structural Glazed Tile Basement 819 SF 6 10+ years Classroom #125 (Kindergarten)
AC Units 1st Floor 1 EA 7 6-10 years
Ceiling - Splined 1st Floor 895 SF 7 10+ years
Doors - Steel Doors incl hw 1st Floor 1 EA 6 10+ years
Floor - Tile 1st Floor 895 SF 7 10+ years
Lighting - Pendent/Surface 1st Floor 16 EA 7 6-10 years
Marker Board 1st Floor 10 LF 7 6-10 years
Walls - Concrete Block 1st Floor 381 SF 7 10+ years
Walls - Plaster/Drywall 1st Floor 744 SF 6 10+ years
Walls - Structural Glazed Tile 1st Floor 120 SF 7 10+ years
Classroom #127 (Pagular Classroom)
Classroom #127 (Regular Classroom)
AC Units 1st Floor 1 EA 7 6-10 years
AC Units 1st Floor 1 EA 7 6-10 years Ceiling - Splined 1st Floor 985 SF 5 6-10 years
AC Units 1st Floor 1 EA 7 6-10 years

Campus Name: Camras Page: 34 of 43 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	1st Floor	985	SF	5	6-10 years	
	Lighting - Pendent/Surface	1st Floor	7	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	553	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	744	SF	6	10+ years	
Classroc	om #129 (Kindergarten)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	985	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	6-10 years	
	Floor - Tile/Sheet	1st Floor	985	SF	5	6-10 years	
	Lighting - Pendent/Surface	1st Floor	17	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,297	SF	7	10+ years	
Classroc	om #223 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	707	SF	6	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	707	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	6	10+ years	
	Walls - Concrete Block	2nd Floor	1,013	SF	6	10+ years	
Classroc	om #224 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	517	SF	6	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	10+ years	
	Floor - Tile	2nd Floor	517	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	10+ years	
	Marker Board	2nd Floor	14	LF	6		
	Walls - Concrete Block	2nd Floor	911	SF	6	10+ years 10+ years	
Clacaraa	om #225 (Regular Classroom)						
CIASSIUC	, ,	2nd Floor	4		7	6 10 2000	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF CF	6	10+ years	
	Ceiling - Splined	2nd Floor	700	SF	7	10+ years	Water damage
	Ceiling - Splined	2nd Floor	5	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	705	SF	6	10+ years	

Campus Name: Camras Page : 35 of 43 Assessment Date: 10/12/2021



Catego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	28	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,139	SF	7	10+ years	
Classroo	m #226 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	504	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	10	SF	5	2-5 years	Water damage
	Chalk Board	2nd Floor	10	LF	4	2-5 years 2-5 years	water damage
						-	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	514	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	10+ years	
	Marker Board	2nd Floor	14	LF	6	6-10 years	
	Walls - Concrete Block	2nd Floor	908	SF	7	10+ years	
Classroo	m #227 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	705	SF	6	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	705	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	10+ years	
					7		
	Marker Board	2nd Floor	14	LF		6-10 years	
	Walls - Concrete Block	2nd Floor	1,139	SF	7	10+ years	
Classroo	m #228 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	508	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	508	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	10+ years	
	Marker Board		14	LF	7	•	
		2nd Floor		SF		6-10 years	
	Walls - Concrete Block	2nd Floor	902	5 F	7	10+ years	
lassroo	m #323 (Regular Classroom)						
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Casework	3rd Floor	7	LF	6	6-10 years	
	Ceiling - Splined	3rd Floor	697	SF	5	6-10 years	Observed- in good condition
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	6-10 years	-

Campus Name: Camras Page : 36 of 43 Assessment Date: 10/12/2021



Catego	ategory : Classroom		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	3rd Floor	697	SF	5	6-10 years	Observed in good codition
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	· ·
	Marker Board	3rd Floor	34	LF	6	2-5 years	
	Walls - Concrete Block	3rd Floor	1,015	SF	7	10+ years	
lassroc	om #324 (Regular Classroom)						
211400101	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Splined	3rd Floor	518	SF	7	10+ years	Observed- in good condition
				LF			Observed- in good condition
	Chalk Board	3rd Floor	14		4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	_ 1	EA	6	6-10 years	
	Floor - Tile/Sheet	3rd Floor	518	SF	7	10+ years	Observed- in good condition
	Lighting - Pendent/Surface	3rd Floor	11	EA	6	6-10 years	
	Marker Board	3rd Floor	14	LF	6	2-5 years	
	Walls - Concrete Block	3rd Floor	957	SF	6	10+ years	
Classroc	om #325 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	No counter observed
	Ceiling - Splined	3rd Floor	702	SF	5	6-10 years	Observed- in good condition
	Chalk Board	3rd Floor	20	LF	4	2-5 years	Cocorda in good condition
	Doors - Wood Doors inclu hw	3rd Floor	20	EA	7		Pank shanged as asset has been
	Doors - Wood Doors Inclu IIW	314 F1001	2		,	10+ years	Rank changed as asset has been replaced/ refurbished
	Floor - Tile/Sheet	3rd Floor	702	SF	7	10+ years	Observed- in good condition
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	10+ years	Observed- in good condition
	Marker Board	3rd Floor	14	LF	6	6-10 years	3
	Walls - Concrete Block	3rd Floor	1,065	SF	7	10+ years	
Classroc	om #326 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	2-5 years	Observed- working
	Casework	3rd Floor	7	LF	7	6-10 years	Ranked changed as asset has been
	Casework	314 1 1001	,	Li	,	0-10 years	replaced
	Ceiling - Splined	3rd Floor	518	SF	5	6-10 years	Observed- ceiling ok
					_		Observed- ceiling ok
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile/Sheet	3rd Floor	518	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	11	EA	6	6-10 years	
	Marker Board	3rd Floor	28	LF	6	2-5 years	
	Walls - Concrete Block	3rd Floor	957	SF	7	10+ years	
lassroc	om #327 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	5	2-5 years	
	Ceiling - Splined	3rd Floor	702	SF	7	10+ years	Observed-in good condition
	Chalk Board	3rd Floor	14	LF	4	2-5 years	2233. Tad in good containon
	Chair Dourd	014 1 1001	14		7	2 o years	

Campus Name: Camras Page : 37 of 43 Assessment Date: 10/12/2021



Catego	ry : Classroom	В	uilding	: Addition	on		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	6-10 years	Observed frame to be in good condition
	Floor - Tile/Sheet	3rd Floor	702	SF	5	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	6	6-10 years	
	Marker Board	3rd Floor	14	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	1,065	SF	7	10+ years	
Classroo	om #328 (Special Education)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Splined	3rd Floor	515	SF	5	6-10 years	
	Chalk Board	3rd Floor	7	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	515	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	11	EA	6	6-10 years	
	Marker Board	3rd Floor	21	LF	6	6-10 years	
	Walls - Concrete Block	3rd Floor	909	SF	7	10+ years	

Category: Interior Building: Addition

Jaicgo	iy. iiiterioi		<u> </u>	unung	. Additi	Oli	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Splined	1st Floor Corridor	1,024	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor Corridor	6	EA	5	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor Corridor	3	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor Corridor	1,024	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor Corridor	8	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor Corridor	533	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Corridor	818	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor Corridor	818	SF	7	10+ years	
	Ceiling - Splined	2nd Floor	1,100	SF	6	6-10 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	5	6-10 years	
	Doors - Wood Doors include hw	2nd Floor	4	EA	6	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	1,100	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	100	EA	5	6-10 years	
	Walls - Concrete Block	2nd Floor	1,004	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	860	SF	7	10+ years	
	Ceiling - Splined	3rd Floor Corridor	1,100	SF	5	6-10 years	Observed- in good condition
	Doors - Steel Doors incl hw	3rd Floor Corridor	1	EA	7	10+ years	Observed- in good condition
	Doors - Wood Doors include hw	3rd Floor Corridor	4	EA	6	10+ years	· ·
	Drinking Fountains - Single Fountain	3rd Floor Corridor	3	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor Corridor	1,100	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor Corridor	8	EA	7	6-10 years	

Campus Name: Camras Page : 38 of 43 Assessment Date: 10/12/2021



Catego	ry : Interior		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	3rd Floor Corridor	100	EA	6	6-10 years	
	Walls - Concrete Block	3rd Floor Corridor	1,040	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Corridor	860	SF	7	10+ years	
	Ceiling - Splined	Basement Corridor	262	SF	5	6-10 years	
	Floor - Terrazzo	Basement Corridor	262	SF	6	6-10 years	No
	Lighting - Pendent/Surface	Basement Corridor	2	EA	5	10+ years	No
	Walls - Concrete Block	Basement Corridor	377	SF	5	10+ years	No
	Walls - Structural Glazed Tile	Basement Corridor	377	SF	5	10+ years	No
Stairs							
	Ceiling - Splined	Stair E-North West	20	SF	5	1-2 years	At level 02
	Ceiling - Splined	Stair E-North West	8	SF	5	1-2 years	Ceiling at basement level
	Ceiling - Splined	Stair E-North West	353	SF	5	6-10 years	•
	Floor - Terrazzo	Stair E-North West	434	SF	5	6-10 years	
	Handrails	Stair E-North West	164	LF	5	6-10 years	
	Lighting - Pendent/Surface	Stair E-North West	4	EΑ	6	6-10 years	
	Lighting - Wall Mounted	Stair E-North West	2	EA	6	6-10 years	
	Stairs - Terrazzo	Stair E-North West	350	LF	6	10+ years	
	Walls - Concrete Block	Stair E-North West	3,190	SF	7	10+ years	
	Walls - Structural Glazed Tile	Stair E-North West	1,595	SF	7	10+ years	
	Ceiling - Splined	Stair F-North	673	SF	5	6-10 years	
	Floor - Terrazzo	Stair F-North	933	SF	6	6-10 years	
	Handrails	Stair F-North	164	LF	5	6-10 years	
	Lighting - Pendent/Surface	Stair F-North	4	EA	6	6-10 years	
	Lighting - Wall Mounted	Stair F-North	5	EA	6	6-10 years	
	Stairs - Terrazzo	Stair F-North	340	LF	5	6-10 years	
	Walls - Concrete Block	Stair F-North	3,232	SF	7	10+ years	

Campus Name: Camras Page: 39 of 43 Assessment Date: 10/12/2021



Catego	ry : Site		В	uilding	: Site		
	•			, i		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	7	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	7	EA	7	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	7	10+ years	
_Fencing							
	Fencing - Chain Link	Entire Site	60	LF	6	10+ years	
	Fencing - Guard Rail	Entire Site	109	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	372	LF	7	10+ years	
	Fencing - Old Standard Ornamental	Entire Site	190	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	109	LF	7	10+ years	
_Landsca	pe						
,	Benches	Entire Site	2	EA	7	10+ years	
	Landscape - Grass	Entire Site	6,716	SF	7	10+ years	
	Landscape - Grass	Entire Site	3,344	SF	4	1-2 years	Do Grass Removed/Substituted
	Landscape - Hardscape- Pavers	Entire Site	2,025	SF	7	10+ years	
	Parkway trees	Entire Site	19	EA	7	10+ years	19 Parkway Trees Counted
	Parkway trees	Entire Site	2	EA	4	1-2 years	2 Trees on North Perimeter Appear Removed/abandoned.
	Planting Beds/ Area	Entire Site	6,623	SF	7	6-10 years	rtomovod/abandomod.
	Retaining Wall - Concrete	Entire Site	489	SF	7	10+ years	
	Retaining Wall - Concrete	Entire Site	238	SF	5	2-5 years	Significant Damage.
	Retaining Wall - Masonry	Entire Site	136	SF	7	10+ years	- 9
	Trash Receptacles	Entire Site	3	EA	7	10+ years	
Parking I	ot						
Ū	Concrete Curbs	Entire Site	395	LF	7	10+ years	
	Lighting - Pole Mounted	Entire Site	4	EA	7	10+ years	
	Pavers	Entire Site	9,312	SF	7	10+ years	
	Surface - Concrete	Entire Site	1,860	SF	7	10+ years	
	Trash Compactor	Entire Site	1	EA	6	10+ years	
	Trash Enclosure - Chain Links	Entire Site	1	SF	7	10+ years	
	Vehicular Screening	Entire Site	39	LF	7	10+ years	
_Playgrou	nd						
	Equipment - Pre K 3-5	North	1	EA	7	10+ years	
	Equipment - School Age 5-12	North	1	EA	7	10+ years	
	Surface - Poured Surface	North	3,741	SF	6	6-10 years	



Catego	ry : Site		В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Sidewall							
	Sidewalks - Internal Walks	Entire Site	170	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	6,335	SF	7	10+ years	
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	7	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Camras Page: 41 of 43 Assessment Date: 10/12/2021

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main				1					
Art Room	Art Room	Basement	800	800	1,000	200	40	Υ	N
Art Room	Art Room	Basement	014	014	840	144	38	Υ	N
Computer Lab	Computer Lab	2nd Floor	215	NA	964	174	96	Υ	N
Computer Lab	Computer Lab	3rd Floor	315	NA	980	174	96	Υ	N
Kindergarten	Kindergarten	1st Floor	102	102	730	220	60	Y	N
Kindergarten	Kindergarten	1st Floor	104	104	760	200	60	Υ	N
Kindergarten	Kindergarten	1st Floor	113	NA	780	220	60	Υ	N
Kindergarten	Kindergarten	1st Floor	115	NA	960	94	48	Υ	N
Kindergarten	Kindergarten	1st Floor	119	NA	1,204	242	54	Υ	N
Office	Special Education	3rd Floor	318E	NA	380	102	27	Υ	N
Pre School	Pre School	1st Floor	111	NA	1,008	220	60	Υ	N
Regular Classroom	Regular Classroom	1st Floor	116	116	968	86	43	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	NA	740	200	55	Y	N
Regular Classroom	Regular Classroom	2nd Floor	204	NA	740	200	50	Y	N
Regular Classroom	Regular Classroom	2nd Floor	212	NA	750	200	60	Y	N
Regular Classroom	Regular Classroom	2nd Floor	213	NA	885	160	50	Y	N
Regular Classroom	Regular Classroom	2nd Floor	214	NA	750	200	60	Y	N
Regular Classroom	Regular Classroom	2nd Floor	216	NA	780	174	46	Y	N
Regular Classroom	Regular Classroom	2nd Floor	217	NA	743	174	46	Y	N
Regular Classroom	Regular Classroom	2nd Floor	218C	NA	732	174	46	Y	N
Regular Classroom	Regular Classroom	2nd Floor	218D	NA	732	174	46	Y	N
Regular Classroom	Regular Classroom	2nd Floor	218E	NA	1,041	136	36	Y	N
Regular Classroom	Regular Classroom	2nd Floor	219	NA	733	174	46	Y	N
Regular Classroom	Regular Classroom	3rd Floor	302	NA	730	200	50	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	NA	740	200	52	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	311	NA	830	112	45	Y	N
Regular Classroom	Regular Classroom	3rd Floor	312	NA	750	200	50	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	314	NA	750	200	50	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	316	NA	780	174	46	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	317	NA	742	174	46	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	318C	NA	744	174	46	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	318D	NA	743	174	46	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	319	NA	740	174	46	Υ	N
Science Lab Level 3	Science Classroom	3rd Floor	309	NA	1,090	228	150	Υ	N
Science Lab Level 3	Science Lab Level 3	2nd Floor	211	NA	1,071	220	65	Υ	N
Store Room	Regular Classroom	3rd Floor	318F	NA	692	170	45	Υ	N

Building : Addition



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Kindergarten	Kindergarten	1st Floor	125	N/A	895	110	30	Υ	N
Kindergarten	Kindergarten	1st Floor	129	04	985	126	42	Υ	N
Music Room	Music Room	Basement	026	N/A	1,862	48	8	Υ	N
Regular Classroom	Regular Classroom	1st Floor	127	03	985	126	42	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	223	14	707	168	35	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	225	015	705	168	49	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	227	016	705	168	49	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	323	27	697	168	35	N	N
Regular Classroom	Regular Classroom	3rd Floor	324	030	518	114	30	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	325	28	702	133	35	Y	N
Regular Classroom	Regular Classroom	3rd Floor	327	29	702	133	35	Υ	N
Regular Classroom	Special Education	2nd Floor	224	03	517	114	30	Υ	N
Regular Classroom	Special Education	2nd Floor	226	02	514	114	30	Υ	N
Regular Classroom	Special Education	3rd Floor	326	06	518	114	30	Y	N
Regular Classroom	Special Program	2nd Floor	228	2041	508	114	30	N	N
Special Education	Special Education	3rd Floor	328	05	515	114	30	Υ	N