

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1935	3	38,530
Addition	1955	3	6,255
Annex	2020	1	17,340
Campus Total			62,125

Category : Exterior Building : Main

	,					Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance			·			·	
	Entrance Control - Audio and Video	#1 Main - East	1	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#1 Main - East	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 Main - East	1	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	#1 Main - East	195	LF	6	10+ years	
	Exterior Stairs - Concrete	#1 Main - East	15	LF	5	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#1 Main - East	6	LF	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#2 - E	2	EΑ	5	2-5 years	Delaminating
	Exterior Doors - Transom Lite	#2 - E	1	EΑ	6	6-10 years	•
	Exterior Stairs - Concrete	#2 - E	70	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#2a - N	2	EΑ	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#3 - W	2	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	#3 - W	1	EΑ	5	2-5 years	
	Exterior Stairs - Concrete	#3 - W	72	LF	5	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#3 - W	16	LF	6	6-10 years	
	Entrance Control - Audio and Video	#4 - E	1	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#4 - E	2	EΑ	4	1-2 years	Delaminating
	Exterior Doors - Transom Lite	#4 - E	1	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	#4 - E	80	LF	6	10+ years	
	Power Door Operator and Controls	#4 - E	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	#4 - E	150	LF	6	6-10 years	
	Ramps - Concrete	#4 - E	75	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#4 - E	16	LF	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	#5 - W	2	EA	4	1-2 years	Damaged, delaminating
	Exterior Doors - Transom Lite	#5 - W	1	EA	4	1-2 years	Warped, deteriorated
	Exterior Stairs - Concrete	#5 - W	72	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#5 - W	16	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6 - W lowdoors	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#7 - W basement	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#7 - W basement	30	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#7 - W basement	8	LF	6	6-10 years	
Foundati	on						
	Foundation - Concrete	Entire Building	629	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	38,530	SF	7	10+ years	
Lighting							
- 5 - 5	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	12	EA	6	10+ years	
Roof Sys	stem						
	Access Ladder - Metal	Main Roof	2	EA	7	6-10 years	
	Coping - Stone	Main Roof	507	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	168	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	507	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	13,227	SF	6	6-10 years	
	Roof Hatch - Metal	Main Roof	2	ĒΑ	7	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	13,227	SF	7	10+ years	
	Coping - Stone	NW Roof	37	LF	6	10+ years	
	Downspouts - Interior Downspouts	NW Roof	26	LF	6	6-10 years	
	Parapet - 16" - 30" Height	NW Roof	37	LF	6	10+ years	
	Roof - Modified Bitumen	NW Roof	242	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	NW Roof	242	SF	6	10+ years	
	Coping - Stone	SW Roofs	55	LF	6	10+ years	
	Downspouts - Interior Downspouts	SW Roofs	38	LF	6	6-10 years	
	Parapet - 16" - 30" Height	SW Roofs	55	LF	6	10+ years	
	Roof - Modified Bitumen	SW Roofs	314	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	SW Roofs	314	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	West Low Roof	65	LF	6	10+ years	
	Coping - Stone	West Low Roof	187	LF	6	10+ years	
	Downspouts - Interior Downspouts	West Low Roof	62	LF	6	6-10 years	
	Parapet - Parapet > 30"	West Low Roof	187	LF	6	10+ years	
	Roof - Modified Bitumen	West Low Roof	3,857	SF	6	6-10 years	Patched
	Roof Structure - Steel with Clay Tile Arch	West Low Roof	3,857	SF	7	10+ years	



Catego	ry : Exterior	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Nalls							
	Cheek-Wall - Concrete	Entire Building	86	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	3,600	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	24,250	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	1,455	SF	6	10+ years	
Vindows							
VIIIGOWS	Guard - Guards perforated	Entire Building	2,280	SF	6	6-10 years	
	Lintels - Steel	Entire Building	465	LF	6		
					_	10+ years	
	Lintels - Stone	Entire Building	273	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,122	SF	6	6-10 years	
atego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>-mergen</u>	cy System						
	Automatic Transfer Switch	Electrical Room	2	EA	6	10+ years	
	UPS - Less than 30 KW	Electrical Room	1	EA	4	2-5 years	The system has been decommissioned, no batteries
	Security System - CCTV	Entire Building	38,350	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	38,530	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	14	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and	Entire Building	8	EA	6	6-10 years	
	Stairs				_		
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	10,044	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,860	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	2,716	SF	6	10+ years	
∕lain Ser	vice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	



Calego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	PA System	Entire Building	38,530	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	9	EΑ	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	9	EΑ	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	4	2-5 years	Fuses with live, exposed electric
	M : B: ( ) ( ) B   1   400   000	F (		_ ^	•	40	contacts
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	10+ years	
	amp Main Distribution Panels - Less than 400	Entire Building	1	EA	6	10+ years	
	amp	Entire Ballating	•		Ü	101 youro	
Catego	ry : Fire Protection		В	uilding	: Main		
, i						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						
	Fire Alarm Panel	Electrical Room	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Electrical Room	38,530	SF	6	10+ years	
	Fire Alarm_System	Electrical Room	38,530	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
Jaiogo	. y . moonamou.		_	u	1 1114111	Recommend	
<b>3roup</b>	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc	itioning						
	Condensing Unit- Ground Mounted - Less	1st Floor	1	EA	6	10+ years	
	than 5 tons				_		
	Chemical Pot Feeder	Site North	1	EA	5	6-10 years	
	Chiller-Air Cooled-Screw Type-Ground	Site North	2	EA	5	6-10 years	One unit runs low in refrigerant,
	Mounted - 101 - 200 tons						second unit has communication
					_	0.40	issues
	Chical Food	Cita Nauth	4	_ ^		h-III VAare	
	Glycol Feed	Site North	1	EA	5	6-10 years	
	Pipes - Dual Temperature Pipe- Galvanized	Site North	600	LF	6	10+ years	
			· · · · · · · · · · · · · · · · · · ·				
Air Hand	Pipes - Dual Temperature Pipe- Galvanized	Site North	600	LF	6	10+ years	
Air Hand	Pipes - Dual Temperature Pipe- Galvanized Pressure Fill System  lling Systems Fan Coil Unit- Celing Mounted - Hot Water	Site North	600	LF	6	10+ years	
Air Hanc	Pipes - Dual Temperature Pipe- Galvanized Pressure Fill System	Site North Site North	600	LF EA	6 6	10+ years 10+ years	



Catego	ry : Mechanical		В	uilding	: Main		NO IN OSCODIA AVENOE, Officago, in 00004
J				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fan Coil Unit- Celing Mounted - Hot Water and Chilled Water	Entire Building	1	EA	6	6-10 years	
	Fan Coil Unit- Floor Mounted - Hot Water and Chilled Water	Entire Building	32	EA	6	6-10 years	For cooling only
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coil and Chilled Water Coils - 10001-15000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Zone Dampers	Mechanical Room	5	EA	5	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils and Chilled Water Coils - Greater than 35000 cfm	Mechanical Room	1	EA	5	6-10 years	
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - Greater than 35000 cfm	Mechanical Room	1	EA	6	6-10 years	The cooling coils has been recently replaced
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	9	EA	5	6-10 years	·
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	10+ years	
	Zone Dampers	Mechanical Room	35	EA	5	6-10 years	
Boiler S	vstems vstems						
·	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Condensate Pump	Boiler Room	2	EA	6	10+ years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	5	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	6	10+ years	
	Steam Traps	Boiler Room	56	ĒΑ	5	6-10 years	
_Heating_	Devices						
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Unit Heater - Electric	Electrical Room	3	EΑ	6	6-10 years	
	Unit Heater - Electric	Electrical Room	1	EΑ	5	6-10 years	
	Radiators - Steam	Entire Building	1	EA	6	6-10 years	
	Radiators - Steam	Entire Building	3	EA	6	6-10 years	
	Radiators - Steam	Entire Building	1	EA	6	2-5 years	Units have been repaired
	Radiators - Steam	Entire Building	7	EA	6	6-10 years	Units are functional
	Fin Tube - Steam	Entire Building	20	LF	6	10+ years	Onits are functional

Campus Name: Dever Page : 5 of 37 Assessment Date: 12/13/2021



Catego	ry : Mechanical		В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Mechani	cal Plumbing						
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	5	EA	5	6-10 years	
Tempera	ature Control						
	Hybrid Pneumatic/DDC System	Entire Building	38,530	SF	5	6-10 years	
	Thermostats - Pneumatic	Entire Building	54	EA	6	10+ years	
	Thermostats - Pneumatic	Entire Building	32	EA	6	10+ years	The cooling fan boxes have digital thermostats
Ventilation	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	10+ years	Non existent
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	7	10+ years	

**Category: Plumbing Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Boiler Room	1	EA	6	6-10 years	
_Piping_							
	Domestic Piping-Hot Water Return Lines	Entire Building	38,530	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	38,530	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	38,530	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	38,530	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	38,530	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	38,530	SF	6	10+ years	
	Sanitary Piping	Entire Building	38,530	SF	6	10+ years	
	Storm Piping	Entire Building	38,530	SF	6	10+ years	
	Vent Piping	Entire Building	38,530	SF	6	10+ years	

Campus Name: Dever Page : 6 of 37 Assessment Date: 12/13/2021



Catego	ry : Plumbing	В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Pumps							
•	Pumps - Domestic Booster Pump-Duplex	Boiler Room	1	EA	6	10+ years	
	Pumps - Sump-Duplex	Boiler Room	1	EA	5	1-2 years	One pump doesn't work
			1 1		6 5	,	One pump doesn't work

Category: Room **Building: Main** 

Salego	ry . Room		D	unamg	. IVIAIII		
<b>0</b>	Name Time	Location	0	LIOM	Danila	Recommend	0
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	Ceiling - Plaster/Drywall	311A	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	311A	1	EA	7	10+ years	
	Floor - Wood	311A	150	SF	7	10+ years	
	Lighting - Pendent/Surface	311A	3	EA	7	6-10 years	
	Power Distribution	311A	6	EA	7	10+ years	
	Walls - Plaster/Drywall	311A	500	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Ass't Principal office	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Ass't Principal office	1	EA	7	10+ years	
	Floor - Wood	Ass't Principal office	100	SF	7	10+ years	
	Lighting - Pendent/Surface	Ass't Principal office	1	EA	7	6-10 years	
	Power Distribution	Ass't Principal office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Ass't Principal office	350	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Counselor Rm 109	210	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Counselor Rm 109	1	EA	7	10+ years	
	Floor - Carpet	Counselor Rm 109	210	SF	6	6-10 years	
	Lighting - Pendent/Surface	Counselor Rm 109	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	Counselor Rm 109	797	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office	105	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	ĒΑ	6	10+ years	
	Floor - Tile	Engineer's Office	105	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	2	ĒΑ	7	6-10 years	
	Power Distribution	Engineer's Office	6	EA	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	123	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Kitchen manager office	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen manager office	1	ĒΑ	7	10+ years	
	Floor - Tile	Kitchen manager office	120	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen manager office	3	ĒΑ	7	6-10 years	
	Power Distribution	Kitchen manager office	4	ĒΑ	7	10+ years	
	Storage/ Closet	Kitchen manager office	30	SF	7	10+ years	
	Walls - Plaster/Drywall	Kitchen manager office	440	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Main Office 1st Floor	453	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office 1st Floor	1	EA	7	10+ years	
	Floor - Carpet	Main Office 1st Floor	453	SF	7	6-10 years	Quantity changed to match curre observation
	Lighting - Pendent/Surface	Main Office 1st Floor	4	EA	7	6-10 years	ODGGI VALIGIT

Campus Name: Dever Page : 7 of 37 Assessment Date: 12/13/2021



Categor	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Main Office 1st Floor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office 1st Floor	600	SF	7	10+ years	Quantity changed to match current observation
	Ceiling - Plaster/Drywall	Nurse	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Nurse	1	EA	7	10+ years	
	Floor - Wood	Nurse	150	SF	7	10+ years	
	Lighting - Pendent/Surface	Nurse	3	EA	7	6-10 years	
	Power Distribution	Nurse	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Nurse	500	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Office A in main office suite	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office A in main office suite	1	EA	7	10+ years	
	Floor - Carpet	Office A in main office suite	100	SF	7	6-10 years	
	Lighting - Pendent/Surface	Office A in main office suite	1	EA	7	6-10 years	
	Power Distribution	Office A in main office suite	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Office A in main office suite	400	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Principal office	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal office	2	ĒΑ	7	10+ years	
	Floor - Carpet	Principal office	150	SF	7	6-10 years	
	Lighting - Pendent/Surface	Principal office	2	EA	7	6-10 years	
	Power Distribution	Principal office	6	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Principal office	500	SF	7	10+ years	
Gymnasi	a						
,	Ceiling - Plaster/Drywall	1st Floor	2,506	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Floor - Wood	1st Floor	2,506	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	8	ĒΑ	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Walls - Masonry	1st Floor	3,007	SF	7	10+ years	
1.50							
Kitchen	Ceiling - Plaster/Drywall	1st Floor	310	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	310	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	366	SF	7	10+ years	
	M. Kr.						
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	1st Floor	2,683	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile	1st Floor	2,683	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7 7	6-10 years 6-10 years	
	Lighting - Wall Mounted	1st Floor	8	EΑ			

Campus Name: Dever Page: 8 of 37 Assessment Date: 12/13/2021



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stage	1st Floor	172	SF	7	10+ years	
	Walls - Masonry	1st Floor	3,165	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Servery	177	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Servery	1	EA	7	10+ years	
	Floor - Tile Quarry	Servery	177	SF	7	10+ years	
	Lighting - Pendent/Surface	Servery	4	EA	7	6-10 years	
	Serving Line	Servery	12	LF	7	10+ years	
	Walls - Structural Glazed Tile	Servery	209	SF	7	10+ years	
MDF ID	F						
_	Doors - Steel Doors incl hw	311	1	EA	7	10+ years	
	Finishes	311	100	SF	7	6-10 years	
	Other Cooling Unit	311	1	ĒΑ	7	6-10 years	Ducted AC
	3 3 3		·	_, .	·	0 .0 yea.e	
Mechani	ical/ Service Rooms	1.0.10.5					
	Janitor's Closet	1st 2nd & 3rd	60	SF	7	10+ years	
	Storage Room	1st 2nd & 3rd	150	SF	7	10+ years	
	Boiler Room	Basement	1,011	SF	7	10+ years	
	Coal Room	Basement	423	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	4,470	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,119	SF	7	10+ years	
	Storage Room	Basement	183	SF	7	10+ years	
Restroor	m						
	Accessories	1st Floor	24	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	24	SF	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	57	SF	7	10+ years	
	Water Closet	1st Floor	1	ĒΑ	7	10+ years	
	Accessories	1st Floor	206	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	206	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	206	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor		EA			
			2		7	10+ years	
	Urinals	1st Floor	4	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	49	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	500	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor	280	SF	7	6-10 years	Corrected quantities
	Ceiling - Plaster/Drywall	1st Floor	280	SF	7	10+ years	Corrected quantities
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	·
	Floor - Tile Ceramic/ Porcelain	1st Floor	280	SF	6	10+ years	Corrected quantities
	Floor Drain	1st Floor	1	EA	7	10+ years	·
	Lavatory	1st Floor	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	Corrected quantities
	Partitions	1st Floor	7	EA	7	10+ years	Corrected quantities
	Walls - Plaster/Drywall	1st Floor	121	SF	7	10+ years	•
	Walls - Structural Glazed Tile	1st Floor	484	SF	7	10+ years	Corrected quantities
	Water Closet	1st Floor	7	ĒΑ	7	10+ years	Corrected quantities
	Accessories	2nd Floor	513	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	513	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	513	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	7	EΑ	7	6-10 years	
	Partitions	2nd Floor	16	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	121	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	800	SF	7	10+ years	
	Water Closet	2nd Floor	16	EA	7	10+ years	
	Accessories	2nd Floor	92	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	90	SF	7	10+ years	Quantity changed to match current observation
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	oboot valion
	Floor - Tile Ceramic/ Porcelain	2nd Floor	90	SF	7	10+ years	Quantity changed to match current observation
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EΑ	7	6-10 years	
	Urinals	2nd Floor	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	300	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor	206	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	206	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	206	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	1	EA	6	10+ years	
	Lavaio. j	2110 1 1001		_, .	J	ioi youis	

Campus Name: Dever Page : 10 of 37 Assessment Date: 12/13/2021



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor	4	EA	7	10+ years	
	Urinals	2nd Floor	8	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	49	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	500	SF	7	10+ years	
	Water Closet	2nd Floor	4	EA	7	10+ years	
	Accessories	3rd Floor	24	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	24	SF	7	10+ years	
	Lavatory	3rd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	55	SF	7	10+ years	
	Water Closet	3rd Floor	1	EΑ	7	10+ years	
	Accessories	In Engineer's Office	47	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Engineer's Office	47	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Engineer's Office	1	EA	7	10+ years	
	Floor - Tile	In Engineer's Office	47	SF	6	10+ years	
	Lavatory	In Engineer's Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Engineer's Office	2	EA	7	6-10 years	
				SF	7	-	
	Walls - Plaster/Drywall	In Engineer's Office	61			10+ years	
	Water Closet	In Engineer's Office	1	EA	7	10+ years	
	Accessories	In the Boiler Room area	19	SF	7	6-10 years	
	Ceiling - Exposed	In the Boiler Room area	19	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In the Boiler Room area	1	EA	6	10+ years	
	Floor - Concrete	In the Boiler Room area	19	SF	7	10+ years	
	Lighting - Pendent/Surface	In the Boiler Room area	1	EA	6	6-10 years	
	Walls - Masonry	In the Boiler Room area	100	SF	7	10+ years	
	Walls - Plaster/Drywall	In the Boiler Room area	100	SF	7	10+ years	Quantity changed to match current observation
	Water Closet	In the Boiler Room area	1	EA	7	10+ years	
	Accessories	Staff Toilet in Main Office	21	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff Toilet in Main Office	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff Toilet in Main Office	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Staff Toilet in Main Office	21	SF	7	10+ years	
	Lavatory	Staff Toilet in Main Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Staff Toilet in Main Office	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Staff Toilet in Main Office	171	SF	7	10+ years	
	Water Closet	Staff Toilet in Main Office	1	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	· / / ·						



Catego	ry : Classroom		В	uilding	: Main	-	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,000	SF	7	10+ years	
	Walls - Flastel/Drywall	1St Floor	1,000	SI	,	10+ years	
Classroo	om #106 (Special Education)						
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	368	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	368	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Storage/ Closet	1st Floor	6	SF			
				SF SF	7	10+ years	Overetity, above and to recetable assument
	Walls - Plaster/Drywall	1st Floor	700	SF	7	10+ years	Quantity changed to match current observation
Classro	om #107 (Computer Lab)						
Ciassio	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor		EA			
			1		6	10+ years	
	Floor - Wood	1st Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,141	SF	6	10+ years	
Classroo	om #108 (Library)						
	Ceiling - Plaster/Drywall	1st Floor	897	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	897	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	•	
				SF		6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,141	SF	6	10+ years	
Classroo	om #111 (Faculty Lounge)						
	Ceiling - Plaster/Drywall	1st Floor	670	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
					_	•	
	Floor - Tile	1st Floor	670	SF	6	10+ years	

Campus Name: Dever Page : 12 of 37 Assessment Date: 12/13/2021



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,141	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	690	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Carpet	2nd Floor	690	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	828	SF	6	10+ years	
Classroo	om #205 (Special Program)						
	Ceiling - Plaster/Drywall	2nd Floor	345	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	320	SF	6	10+ years	
	Floor - Tile	2nd Floor	25	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	Broken tiloo
	Walls - Plaster/Drywall	2nd Floor	700	SF	7	10+ years	
Classroo	om #206 (Regular Classroom)						
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	690	SF	7	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	828	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	690	SF	6	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	11	LF	6	6-10 years	
	IVIAINEI DUAIU	2110 11001	11	LF	O	0-10 years	

Campus Name: Dever Page : 13 of 37 Assessment Date: 12/13/2021



Catego	ory : Classroom		В	uilding	: Main	-	NO IN OSCIONA AVENUE, Officago, IE 00004
Cuiogo	ny i Giacorcom		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	2nd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,141	SF	7	10+ years	
	•					-	
Classro	om #208 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	690	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,141	SF	7	10+ years	
Classra	om #200 (Bogular Classroom)						
Classio	om #209 (Regular Classroom)  Ceiling - Plaster/Drywall	2nd Floor	690	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,141	SF	7	10+ years	
	Traile Tracton 21 y trail	2110 1 1001	.,	O.	•	io. youro	
Classro	om #210 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	690	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	690	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,141	SF	7	10+ years	
Classra	om #211 (Regular Classroom)						
Classio	Coiling Planter/Drawell	2nd Floor	222	C.E.	7	10	
	Ceiling - Plaster/Drywall		690	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,141	SF	7	10+ years	

Campus Name: Dever Page : 14 of 37 Assessment Date: 12/13/2021



Catego	ry : Classroom		В	uilding	: Main		
0	И Т	Laadlaa	0	HOM	D/	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroc	om #301 (Regular Classroom)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	7	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	828	SF	7	10+ years	
_Classroo	om #302 (Regular Classroom)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	690	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	828	SF	7	10+ years	
Classroo	om #303 (Regular Classroom)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	690	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	828	SF	7	10+ years	
Classroo	om #304 (Regular Classroom)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	7	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Wood	3rd Floor	690	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
						-	



Catego	ry : Classroom		В	uilding	: Main		
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	828	SF	7	10+ years	
Classroc	om #305 (Regular Classroom)						
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	7	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Wood	3rd Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	828	SF	7	10+ years	
Classroo	om #306 (Regular Classroom)						
21455100	Casework	3rd Floor	6	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	690	SF	7	•	
	Doors - Transom Window	3rd Floor		SF		10+ years	
			9		7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA SF	6	10+ years	
	Floor - Wood	3rd Floor	690		7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	828	SF	7	10+ years	
Classroc	om #307 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	7	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	690	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	11	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,141	SF	7	10+ years	
Classroo	om #308 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	7	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
			1	EA	6	•	
	Doors - Wood Doors inclu hw	3rd Floor	690	SF		10+ years	
	Floor - Wood	3rd Floor			7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	

Campus Name: Dever Page : 16 of 37 Assessment Date: 12/13/2021



Catego	ry : Classroom		В	uilding	: Main		
_							
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	11	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,041	SF	7	10+ years	
Classroo	om #309 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	6	10+ years	
	Chalk Board	3rd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	690	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	11	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1.161	SF	7	10+ years	
	Traile Tractor/21y trail	0.0.1.00.	1,101	O.	•	ioi youlo	
Classroo	om #310 (Regular Classroom)						
	Ceiling - Plaster/Drywall	3rd Floor	90	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	600	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	690	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	11	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,141	SF	7	10+ years	
Classros	om #311 (Special Program)						
SIASSIUC	· · · · · · · · · · · · · · · · · · ·	2rd Floor	492	C.E.	7	10	Corrected quantities
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	3rd Floor	482	SF EA	7	10+ years	Corrected quantities
		3rd Floor	1		7	10+ years	Corrected guestitics
	Floor - Wood	3rd Floor	482	SF	7	10+ years	Corrected quantities
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF CF	6	6-10 years	Composted account() = =
	Walls - Plaster/Drywall	3rd Floor	670	SF	7	10+ years	Corrected quantities
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	2,764	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	10	ĒΑ	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	6	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	2,714	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	50	SF	4	1-2 years	Broken tiles



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	28	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	88	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,658	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,658	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,764	SF	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	2,614	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	150	SF	4	1-2 years	Broken tiles
	Lighting - Pendent/Surface	2nd Floor	28	EA	6	6-10 years	
	Student Lockers - One Tier	2nd Floor	177	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,658	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,658	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,764	SF	7	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	1	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	3rd Floor	4	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,764	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	150	SF	4	1-2 years	Broken tiles
	Lighting - Pendent/Surface	3rd Floor	28	EA	6	6-10 years	
	Student Lockers - One Tier	3rd Floor	177	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,658	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,658	SF	7	10+ years	
Safety							
-	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	3	EA	7	6-10 years	
_Stairs							
	Ceiling - Plaster/Drywall	North	876	SF	7	10+ years	
	Floor - Terrazzo	North	876	SF	7	10+ years	
	Handrails	North	150	LF	7	10+ years	
	Lighting - Pendent/Surface	North	6	ĒΑ	7	6-10 years	
	Stairs - Terrazzo	North	90	LF	7	10+ years	
	Walls - Plaster/Drywall	North	534	SF	7	10+ years	
	Walls - Structural Glazed Tile	North	534	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	876	SF	7	10+ years	
	Floor - Terrazzo	South	876	SF	7	10+ years	
	Handrails	South	150	LF	7	10+ years	
	Lighting - Pendent/Surface	South	6	ĒΑ	7	6-10 years	
	Stairs - Terrazzo	South	90	LF	7	10+ years	
	Walls - Plaster/Drywall	South	534	SF	7	10+ years	
	Walls - Structural Glazed Tile	South	534	SF	7	10+ years	

Campus Name: Dever Page : 18 of 37 Assessment Date: 12/13/2021



Catego	ry : Exterior		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Foundati	on						
	Foundation - Concrete Superstructure - Metal Deck/ Concrete Topping	Entire Building Entire Building	197 6,255	LF SF	7 7	10+ years 10+ years	
Lighting							
0 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	6	6-10 years	
Roof Sys							
	Chimney - Metal Flue	Main Roof	7	LF	6	6-10 years	
	Coping - Stone	Main Roof	133	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	78	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	133	LF SF	6	10+ years	
	Roof - Modified Bitumen Roof Structure - Steel / Metal Deck/	Main Roof Main Roof	2,066 2,066	SF SF	6 7	6-10 years	
	Concrete Topping	Main Roor	2,000	SF	/	10+ years	
_Walls							
	Exterior Walls - Brick	Entire Building	3,468	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	216	SF	6	10+ years	
Windows							
	Guard - Guards perforated	Entire Building	315	SF	6	6-10 years	
	Lintels - Steel	Entire Building	66	LF	6	10+ years	
	Lintels - Stone	Entire Building	40	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	739	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Emerger	ncy System						
- 0	Security System - Intrusion Detection	Entire Building	6,255	SF	5	6-10 years	
Main Se	rvice						
	PA System	Entire Building	6,255	SF	6	6-10 years	
_Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	10+ years	



#### William E Dever Elementary School

Catego	ry : Fire Protection		В	uilding	: Additi	on	
_				_		Recommend	
≩roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	6,255	SF	6	10+ years	
	Fire Alarm_System	Entire Building	6,255	SF	5	6-10 years	
atego	ry : Mechanical		В	uilding	: Additi		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ling Systems	Location	Quantity	OOM	IXAIIK	Replacement	Comments
штапи	Return Duct Work - Indoor- Vertical Shaft	Entire Building	100	LF	6	10+ years	
	and Ducts	Little Ballaling	100	LI	O	10+ years	
	Zone Dampers	Entire Building	6	EA	6	10+ years	
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	5	2-5 years	
	Electric and DX Cooling with Self Contained				_	7	
	Compressor - 5 - 10 tons						
[empera	ture Control						
'	Hybrid Pneumatic/DDC System	Entire Building	6,255	SF	6	10+ years	
	Thermostats - DDC	Entire Building	6	ĒΑ	6	10+ years	
		Ü				•	
Catego	ry : Plumbing		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	6,255	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	6,255	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	6,255	SF	6	10+ years	
	Fixtures	J				•	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	6,255	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	6,255	SF	6	10+ years	
	(Risers)	Entire Ballating	0,200	O.	Ü	101 youro	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	6,255	SF	6	10+ years	
	(from Risers to Fixtures)	9	2,	-		, , , , , , , , , , , , , , , , , , , ,	
	Sanitary Piping	Entire Building	6,255	SF	6	10+ years	
	Storm Piping	Entire Building	6,255	SF	6	10+ years	
	. •	Ü	,			,	
Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	Room 313	215	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 313	1	EA	7	10+ years	

Campus Name: Dever Page : 20 of 37 Assessment Date: 12/13/2021



Catego	ry : Room		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Room 313	215	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 313	7	EA	7	6-10 years	
	Power Distribution	Room 313	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 313	253	SF	7	10+ years	
	Ceiling - Plaster/Drywall	SPED Room 213	161	SF	6	10+ years	
	Ceiling - Splined	SPED Room 213	161	SF	6	10+ years	
	Doors - Transom Window	SPED Room 213	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	SPED Room 213	1	EA	6	10+ years	
	Floor - Tile	SPED Room 213	323	SF	7	10+ years	
	Lighting - Pendent/Surface	SPED Room 213	6	EA	7	6-10 years	
	Power Distribution	SPED Room 213	6	EA	6	10+ years	
	Walls - Plaster/Drywall	SPED Room 213	371	SF	7	10+ years	
	Work Sink	SPED Room 213	1	EΑ	7	10+ years	
	Ceiling - Plaster/Drywall	Speech and Music Room 113	215	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Speech and Music Room 113	1	EΑ	6	10+ years	
	Floor - Tile	Speech and Music Room 113	215	SF	7	10+ years	
	Lighting - Pendent/Surface	Speech and Music Room 113	7	EΑ	7	6-10 years	
	Power Distribution	Speech and Music Room 113	4	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Speech and Music Room 113	215	SF	7	10+ years	

Category : Classroom **Building: Addition** 

	.,							
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	om #100 (Regular Classroom)	Location	Quantity	00111	Italik	Replacement	Comments	
123310	Casework	1st Floor	6	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	690	SF	7	10+ years		
	Chalk Board	1st Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	690	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years		
	Marker Board	1st Floor	12	LF	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor	828	SF	7	10+ years		
lassro	om #112 (Regular Classroom)							
	Ceiling - Plaster/Drywall	1st Floor	690	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	25	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	680	SF	7	10+ years	<b>5</b> 1 40	
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Broken tiles	
		<del>_</del> .						
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years		
	Marker Board	1st Floor	20	LF	6 6	6-10 years		
						•		

Campus Name: Dever Page : 21 of 37 Assessment Date: 12/13/2021



Catego	ry : Classroom		В	uilding	: Additi		30 N Oscola AVENCE, Onicago, IE 30004
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #200 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	690	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	690	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	40	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	828	SF	7	10+ years	
Classroo	om #212 (Regular Classroom)						
	Ceiling - Splined	2nd Floor	690	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	690	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,141	SF	6	10+ years	
Classroo	om #300 (Regular Classroom)						
Oldobioc	Casework	3rd Floor	19	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	680	SF	7	10+ years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	680	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	828	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #312 (Special Program)						
	Ceiling - Plaster/Drywall	3rd Floor	600	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	90	SF	7	10+ years	
	Chalk Board	3rd Floor	21	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	688	SF	6	10+ years	
	Floor - Tile	3rd Floor	2	SF	5	1-2 years	Broken tiles
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	21	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,101	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	40	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Additi	on	
	Item - Type	Location	Quantity	UOM	Rank		Comments
J. Cup		Location	Quantity	00111	Rain	Noodiminona	Comonto



			Replacement						
Corridor									
Ceiling - Plaster/Dryv	wall	1st Floor	145	SF	7	10+ years			
Floor - Tile/Sheet		1st Floor	130	SF	7	10+ years			
Floor - Tile/Sheet		1st Floor	15	SF	4	1-2 years	Broken tiles		
Lighting - Pendent/S	urface	1st Floor	2	EA	7	6-10 years			
Walls - Plaster/Drywa	all .	1st Floor	72	SF	7	10+ years			
Walls - Structural Gla	zed Tile	1st Floor	72	SF	7	10+ years			
Ceiling - Plaster/Dryv	wall 2	2nd Floor	145	SF	7	10+ years			
Floor - Tile/Sheet	2	2nd Floor	145	SF	7	10+ years			
Lighting - Pendent/S	urface 2	2nd Floor	2	EA	7	6-10 years			
Student Lockers - On	ne Tier	2nd Floor	20	EA	7	10+ years			
Walls - Plaster/Drywa	all :	2nd Floor	72	SF	7	10+ years			
Walls - Structural Gla	zed Tile	2nd Floor	72	SF	7	10+ years			
Ceiling - Plaster/Dryv	wall :	3rd Floor	145	SF	7	10+ years			
Floor - Tile/Sheet	;	3rd Floor	145	SF	7	10+ years			
Lighting - Pendent/S	urface :	3rd Floor	2	EA	7	6-10 years			
Student Lockers - On	ne Tier	3rd Floor	20	EA	7	10+ years			
Walls - Plaster/Drywa	all :	3rd Floor	72	SF	7	10+ years			
Walls - Structural Gla	zed Tile	3rd Floor	72	SF	7	10+ years			



Category : Exterior Building : Annex

Catego	ry : Exterior	В					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1 - Main East	1	EA	7	10+ years	
	Exterior Doors - Side lite	1 - Main East	2	EA	7	10+ years	
	Exterior Doors - Store Front	1 - Main East	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	1 - Main East	1	EA	7	10+ years	
	Power Door Operator and Controls	1 - Main East	1	EA	7	10+ years	
	Exterior Doors - Store Front	2 - South	2	EA	7	10+ years	
	Exterior Doors - Transom Lite	2 - South	2	EA	7	10+ years	
	Entrance Control - Audio and Video	3 - West	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	3 - West	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	3A - West	2	EA	7	10+ years	
						, , , , , , , , , , , , , , , , , , , ,	
Foundati	on						
	Foundation - Concrete	Entire Building	575	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	16,800	SF	7	10+ years	
	Topping	3	-,			, , , , ,	
	11 3						
Lighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	6	EA	7	10+ years	
	3 3 3 4 4	3	-			, , , , ,	
Roof Sys	stem						
<b>,</b>	Access Ladder - Metal	Entire Building	1	EA	7	10+ years	
	Coping - Metal	Entire Building	575	LF	7	10+ years	
	Downspouts - Interior Downspouts	Entire Building	8	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Entire Building	575	LF	7	10+ years	
	Roof - Modified Bitumen	Entire Building	16,800	SF	7	10+ years	
	Roof Hatch - Metal	Entire Building	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Entire Building	16,800	SF	7	10+ years	
	Concrete Topping	g	. 0,000	О.	•	. o . y ca. c	
Walls							
	Exterior Walls - Precast Panel Wall	Entire Building	6,400	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	1,150	SF	7	10+ years	
			.,		-	,	
Windows							
	Guard - Guards perforated	Entire Building	1,484	SF	7	10+ years	
	Lintels - Steel	Entire Building	190	LF	7	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	1,484	SF	7	10+ years	
	pane	·········· <del>9</del>	., 10 1	٥.	•	,	
	L						

Campus Name: Dever Page : 24 of 37 Assessment Date: 12/13/2021



Calcyc	ory : Electrical	Building : Annex					
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
- meraei	ncy System		·			_	
J	Exit Signs - Corridors and Stairs	1st Floor	8	EA	7	10+ years	
	Security System - CCTV	1st Floor	17,340	SF	7	10+ years	
	Security System - Intrusion Detection	1st Floor	17,340	SF	7	10+ years	
	Emergency A/C Power - Corridors and	Entire Building	17,340	SF	7	6-10 years	
	Stairs	Zittiro Ballaling	17,010	O.	•	o ro youro	
	Emergency A/C Power - Students Toilets	Entire Building	4	SF	7	6-10 years	
	Emergency Battery Packs - Multipurpose	Entire Building	1	ĒΑ	7	6-10 years	
	Room	g	•		•	o .o you.o	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	7	6-10 years	
	g,,	g	·		-	,	
Main Se	ervice						
	PA System	1st Floor	17,340	SF	7	10+ years	Served from the main building
Power D	Distribution						
	Lighting and Power Panels - Above 100 A	1st Floor	5	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	1st Floor	2	EA	7	10+ years	
Catego	ory : Fire Protection		В	uilding	: Annex		
	, , , , , , , , , , , , , , , , , , , ,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar						<u> </u>	
		Fatire Duilding		EA	7	10+ years	
	Fire Alarm Panel	Entire Building	1				
	Fire Alarm Panel	Entire Building	1 17 3/0				
	Fire Alarm Strobe Lights	Entire Building	17,340	SF	7	10+ years	
Catego	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building	17,340 17,340	SF SF	7 7	10+ years 10+ years	
Catego	Fire Alarm Strobe Lights	Entire Building	17,340 17,340	SF	7 7	10+ years 10+ years	
J	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building	17,340 17,340	SF SF	7 7	10+ years 10+ years	Comments
Group	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type	Entire Building Entire Building	17,340 17,340 <b>B</b>	SF SF uilding	7 7 : <b>Annex</b>	10+ years 10+ years	Comments
Group	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type  ditioning	Entire Building Entire Building	17,340 17,340 <b>B</b>	SF SF uilding	7 7 : <b>Annex</b>	10+ years 10+ years Recommend Replacement	Comments
Group	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type	Entire Building Entire Building  Location	17,340 17,340 B Quantity	SF SF uilding UOM	7 7 : Annex Rank	10+ years 10+ years	Comments
Group	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less	Entire Building Entire Building  Location	17,340 17,340 B Quantity	SF SF uilding UOM	7 7 : Annex Rank	10+ years 10+ years Recommend Replacement	Comments
<b>Group</b> Air Conc	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less	Entire Building Entire Building  Location  Roof	17,340 17,340 <b>B</b> <b>Quantity</b>	SF SF uilding UOM EA	7 7 : Annex Rank	10+ years 10+ years Recommend Replacement	Comments
<b>Group</b> Air Conc	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less than 5 tons  Uling Systems VAV Box	Entire Building Entire Building  Location	17,340 17,340 B Quantity	SF SF uilding UOM EA	7 7 : Annex Rank 7	10+ years 10+ years  Recommend Replacement  10+ years	Comments
<b>Group</b> Air Conc	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less than 5 tons  Uling Systems VAV Box Roof Top Unit-Multi Zone-Roof Mounted-	Entire Building Entire Building  Location  Roof	17,340 17,340 <b>B</b> <b>Quantity</b>	SF SF uilding UOM EA	7 7 : Annex Rank	10+ years 10+ years Recommend Replacement	Comments
<b>Group</b> Air Conc	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less than 5 tons  VAV Box Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 10 - 20 tons	Entire Building Entire Building  Location  Roof  Entire Building Main Roof	17,340 17,340 <b>B</b> Quantity 1	SF SF uilding UOM EA	7 7 : Annex Rank 7	10+ years 10+ years  Recommend Replacement  10+ years	Comments
Group Air Cond	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less than 5 tons  dling Systems  VAV Box Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 10 - 20 tons Roof Top Unit-Multi Zone-Roof Mounted-	Entire Building Entire Building  Location  Roof  Entire Building	17,340 17,340 <b>B</b> Quantity 1	SF SF uilding UOM EA	7 7 : Annex Rank 7	10+ years 10+ years  Recommend Replacement  10+ years	Comments
<b>Group</b> Air Conc	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less than 5 tons  VAV Box Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 10 - 20 tons	Entire Building Entire Building  Location  Roof  Entire Building Main Roof	17,340 17,340 <b>B</b> Quantity 1 16 1	SF SF uilding UOM EA EA	7 7 <b>: Annex</b> <b>Rank</b> 7	10+ years 10+ years  Recommend Replacement  10+ years  10+ years 10+ years	Comments
<b>Group</b> Air Conc	Fire Alarm Strobe Lights Fire Alarm_System  ory: Mechanical  Item - Type  ditioning  Condensing Unit- Roof Mounted - Less than 5 tons  dling Systems  VAV Box Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling - 10 - 20 tons Roof Top Unit-Multi Zone-Roof Mounted-	Entire Building Entire Building  Location  Roof  Entire Building Main Roof	17,340 17,340 <b>B</b> Quantity 1 16 1	SF SF uilding UOM EA EA	7 7 <b>: Annex</b> <b>Rank</b> 7	10+ years 10+ years  Recommend Replacement  10+ years  10+ years 10+ years	Comments



Catego	ry : Mechanical	В	uilding	: Annex	,	-	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy	ystems						
	Boiler Auxiliary- Condensing Hot Water - Less than 500 HP	Boiler Room	2	EA	7	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	7	10+ years	
	Condensing- Hot Water Boiler - Less than 500 MBH	Boiler Room	2	EA	7	10+ years	
	Hot Water Pump	Boiler Room	2	EA	7	6-10 years	
	Piping - Dual Temperature Pipes- Copper	Boiler Room	300	LF	7	10+ years	
	Water Fill System	Boiler Room	1	EA	7	6-10 years	
Gas Boo	oster						
	Gas Booster	Boiler Room	2	EA	7	10+ years	
_Heating	Devices						
•	Unit Heater - Hot Water	1st Floor	1	EA	7	10+ years	
	Wall Heater - Electric	Entire Building	1	EA	7	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	7	10+ years	
Tempera	ature Control						
•	DDC System	Entire Building	17,340	SF	7	10+ years	
	Electric Thermostat	Entire Building	2	ĒΑ	7	10+ years	
	Thermostats - DDC	Entire Building	16	EA	7	10+ years	
Ventilati	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	7	10+ years	

**Category: Plumbing Building: Annex** 

	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	7	10+ years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	17,340	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	17,340	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	17,340	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	17,340	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	17,340	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	17,340	SF	7	10+ years	

Campus Name: Dever Page : 26 of 37 Assessment Date: 12/13/2021



Category : Plumbing

# William E Dever Elementary School 3436 N Osceola AVENUE, Chicago, IL 60634

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	(from Risers to Fixtures)						
	Sanitary Piping	Entire Building	17,340	SF	7	10+ years	
	Storm Piping	Entire Building	17,340	SF	7	10+ years	
	Vent Piping	Entire Building	17,340	SF	7	10+ years	
Catego	ry : Room		В	uilding	: Annex		
0	Name Tame	Lagathan	0	LIOM	Danila	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	trative Suites/Offices	4 . =	170				
	Ceiling - Lay-in	1st Floor	170	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	170	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	416	SF	7	10+ years	
	Ceiling - Lay-in Doors - Wood Doors inclu hw	1st Floor	154	SF EA	7 7	10+ years	
	Floor - Tile	1st Floor 1st Floor	1 154	SF	7	10+ years	
						10+ years	
	Lighting - Lay-in	1st Floor	2	EA	7 7	10+ years	
	Walls - Plaster/Drywall	1st Floor	147	SF	/	10+ years	
_Kitchen							
	Ceiling - Lay-in	1st Floor	441	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Epoxy/ Painted	1st Floor	441	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	7	EA	7	10+ years	
	Storage/ Closet	1st Floor	100	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	680	SF	7	10+ years	
_Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	1,502	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,502	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Market Board	1st Floor	40	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,520	SF	7	10+ years	
_MDF_ID	F						
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	134	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	10+ years	
Ma-1	isol/ Comiso Doorse						
_iviecnani	ical/ Service Rooms	1st Floor		SF	7	10	Vitaban Carridar Starrage
	Janitor's Closet	1St F100f	68	5F	/	10+ years	Kitchen Corridor Storage
Campus	Name: Dever	Page	27 of 37				Assessment Date: 12/13/2021

**Building: Annex** 

Recommend

Campus Name: Dever Page : 27 of 37 Assessment Date: 12/13/2021



Catego	ategory : Room			Building : Annex				
						Recommend		
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Mechanical/ Service Rooms	1st Floor	119	SF	7	10+ years	Electrical Room	
	Mechanical/ Service Rooms	1st Floor	142	SF	7	10+ years	Storage	
	Mechanical/ Service Rooms	1st Floor	388	SF	7	10+ years	Mechanical Room	
	Mechanical/ Service Rooms	1st Floor	52	SF	7	10+ years	Water Room	
	Storage Room	1st Floor	199	SF	7	10+ years	Main Corridor Storage	
estroor	n							
	Accessories	1st Floor	10	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	55	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	55	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	•		
			1			10+ years		
	Hand Dryer	1st Floor	1	EΑ	7	10+ years		
	Lavatory	1st Floor	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	89	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	149	SF	7	10+ years		
	Water Closet	1st Floor	1	EA	7	10+ years		
	Accessories	1st Floor	10	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	66	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years		
	Floor - Tile	1st Floor	66	SF	7	10+ years		
	Floor Drain	1st Floor	1	EΑ	7	10+ years		
	Hand Dryer	1st Floor	1	EΑ	7	10+ years		
	Lavatory	1st Floor	1	EΑ	7	10+ years		
	Lighting - Lay-in	1st Floor	1	EΑ	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	96	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	160	SF	7	10+ years		
	Water Closet	1st Floor	1	EA	7	10+ years		
	Accessories	1st Floor	10	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	104	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	104	EA	7	10+ years		
	Floor - Tile	1st Floor	104	SF	7	-		
				EA	7	10+ years		
	Floor Drain	1st Floor	1			10+ years		
	Hand Dryer	1st Floor	1	EΑ	7	10+ years		
	Lavatory	1st Floor	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	120	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	200	SF	7	10+ years		
	Water Closet	1st Floor	1	EA	7	10+ years		
	Accessories	1st Floor	5	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	56	SF	7	10+ years		

Campus Name: Dever Page : 28 of 37 Assessment Date: 12/13/2021



Catego	ry : Room	Building : Annex					
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st Floor	1	EΑ	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EΑ	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	90	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	150	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	5	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	56	SF	7	10+ years	
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	1st Floor	1	EΑ	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	90	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	150	SF	7	10+ years	
	Water Closet	1st Floor	130	EA	7	10+ years	
	Accessories	1st Floor	10	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw		1	EA	7	•	
		1st Floor		SF		10+ years	
	Floor - Tile	1st Floor	56		7	10+ years	
	Floor Drain	1st Floor	1	EΑ	7	10+ years	
	Hand Dryer	1st Floor	1	EΑ	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	90	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	150	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	10	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	56	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	90	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	150	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	10	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	164	SF	7	10+ years	
	Floor - Tile	1st Floor	164	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
						•	

Campus Name: Dever Page : 29 of 37 Assessment Date: 12/13/2021



Catego	Category : Room			Building : Annex				
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Hand Dryer	1st Floor	1	EA	7	10+ years		
	Lavatory	1st Floor	2	EA	7	10+ years		
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years		
	Partitions	1st Floor	2	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	195	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	325	SF	7	10+ years		
	Water Closet	1st Floor	2	EA	7	10+ years		
	Accessories	1st Floor	5	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	54	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	54	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Hand Dryer	1st Floor	1	EA	7	10+ years		
	Lavatory	1st Floor	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor	1	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	87	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	145	SF	7	10+ years		
	Water Closet	1st Floor	1	EA	7	10+ years		
	Accessories	1st Floor	10	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	164	SF	7	10+ years		
	Floor - Tile	1st Floor	164	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Hand Dryer	1st Floor	1	EA	7	10+ years		
	Lavatory	1st Floor	2	EA	7	10+ years		
	Lighting - Lay-in	1st Floor	2	EA	7	10+ years		
	Partitions	1st Floor	2	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	195	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	325	SF	7	10+ years		
	Water Closet	1st Floor	2	EA	7	10+ years		
	Accessories	1st Floor	10	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	56	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	56	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Hand Dryer	1st Floor	1	EA	7	10+ years		
	Lavatory	1st Floor	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	90	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	150	SF	7	10+ years		
	Water Closet	1st Floor	1	EA	7	10+ years		



Category : Classroom				Building : Annex				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroc	om #11 (Multi Purpose Room)					-		
	Ceiling - Lay-in	1st Floor	457	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years		
	Floor - Tile/Sheet	1st Floor	457	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	5	ĒΑ	7	6-10 years		
	Marker Board	1st Floor	10	LF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	784	SF	7	10+ years		
	,					, , , , , ,		
Classroc	om #14 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	762	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years		
	Floor - Tile/Sheet	1st Floor	762	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years		
	Marker Board	1st Floor	20	LF	7	10+ years		
	Storage/ Closet	1st Floor	67	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	960	SF	7	10+ years		
Classroc	om #15 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	762	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	762	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years		
	Marker Board	1st Floor	20	LF	7	10+ years		
	Storage/ Closet	1st Floor	70	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	960	SF	7	10+ years		
Classroc	om #16 (Regular Classroom)							
	Ceiling - Lay-in	1st Floor	791	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	791	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	9	EA	7	10+ years		
	Marker Board	1st Floor	20	LF	7	10+ years		
	Storage/ Closet	1st Floor	68	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	960	SF	7	10+ years		
laceroo	om #17 (Kindergarten)							
CIGOSIUL	Ceiling - Lay-in	1st Floor	818	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor	818	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years		
	Marker Board	1st Floor	15	LF	7	10+ years		
	Storage/ Closet	1st Floor	59	SF	7 7			
	Walls - Plaster/Drywall		1,016	SF SF	7	10+ years		
	vvalis - Flastei/DryWall	1st Floor	1,016	SF	′	10+ years		



Category : Classroom			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #18 (Kindergarten)						
	Ceiling - Lay-in	1st Floor	816	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	816	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	10+ years	
	Storage/ Closet	1st Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,016	SF	7	10+ years	
Classroo	om #19 (Kindergarten)						
	Ceiling - Lay-in	1st Floor	816	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	816	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	ĒΑ	7	10+ years	
	Marker Board	1st Floor	20	LF	7	10+ years	
	Storage/ Closet	1st Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,016	SF	7	10+ years	
Classroo	om #20 (Pre School)						
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	819	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	819	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	8	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	10+ years	
	Storage/ Closet	2nd Floor	57	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,010	SF	7	10+ years	
	Work Sink	2nd Floor	1,010	EA	7	10+ years	
laceroo	om #21 (Pre School)						
21433100	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	816	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	816	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure	2nd Floor	8	EA	7	10+ years	
	Sodium				ı	TOT years	
	Marker Board	2nd Floor	20	LF	7	10+ years	
	Storage/ Closet	2nd Floor	57	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,008	SF	7	10+ years	
	Work Sink	2nd Floor	1	ĒΑ	7	10+ years	

Campus Name: Dever Page : 32 of 37 Assessment Date: 12/13/2021



Category : Classroom			Building : Annex				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #22 (Pre School)						
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	786	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	786	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	8	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	10+ years	
	Storage/ Closet	2nd Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	992	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
lassroo	om #23 (Pre School)						
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	782	SF	7	10+ years	New, less than 2 years
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	782	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	10+ years	
	Storage/ Closet	1st Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	992	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Catego	ry : Interior		В	uilding	: Annex		
						Recommend	
iroup Corridor	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
OHIGOL							
		1et Floor	1 700		7	10+ years	
	Ceiling - Lay-in	1st Floor	1,709	SF EA	7	10+ years	
	Ceiling - Lay-in Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain	1st Floor 1st Floor	1 2	EA EA	7 7	10+ years 10+ years	
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor	1 2 1,709	EA EA SF	7 7 7	10+ years 10+ years 10+ years	
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor	1 2 1,709 19	EA EA SF EA	7 7 7 7	10+ years 10+ years 10+ years 10+ years	
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 2 1,709 19 4,347	EA EA SF EA SF	7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years	
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 2 1,709 19 4,347 234	EA EA SF EA SF SF	7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Doors - Wood Doors include hw	1st Floor	1 2 1,709 19 4,347 234	EA EA SF EA SF SF	7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Doors - Wood Doors include hw Floor - Tile/Sheet	1st Floor	1 2 1,709 19 4,347 234 1 235	EA SF EA SF SF EA SF	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Doors - Wood Doors include hw Floor - Tile/Sheet Lighting - Lay-in	1st Floor	1 2 1,709 19 4,347 234 1 235	EA SF EA SF SF EA SF EA	7 7 7 7 7 7 7 7	10+ years	
	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Doors - Wood Doors include hw Floor - Tile/Sheet	1st Floor	1 2 1,709 19 4,347 234 1 235	EA SF EA SF SF EA SF	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	
safety	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Doors - Wood Doors include hw Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall	1st Floor	1 2 1,709 19 4,347 234 1 235 4 774	EA EA SF SF EA SF EA SF	7 7 7 7 7 7 7 7	10+ years	
afety	Ceiling - Lay-in Doors - Steel Doors incl hw Drinking Fountains - Double Fountain Floor - Tile/Sheet Lighting - Lay-in Walls - Plaster/Drywall Ceiling - Lay-in Doors - Wood Doors include hw Floor - Tile/Sheet Lighting - Lay-in	1st Floor	1 2 1,709 19 4,347 234 1 235	EA SF EA SF SF EA SF EA	7 7 7 7 7 7 7 7	10+ years	

Campus Name: Dever Page : 33 of 37 Assessment Date: 12/13/2021



Category : Site	Building : Site

Juitge.	y . Site			unanig	. Oite		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	6	6-10 years	
encing							
	Fencing - Chain Link	Entire Site	105	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	1,150	LF	6	6-10 years	
andscar							
	Benches	Entire Site	4	EA	6	6-10 years	
	Landscape - Grass	Entire Site	37,225	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	15,225	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	4,000	SF	4	0-1 year	Cracking throughout
	Parkway trees	Entire Site	35	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	1,575	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	21,050	SF	6	6-10 years	
	Retaining Wall - Concrete	Entire Site	102	SF	6	10+ years	
	Trash Receptacles	Entire Site	3	EA	6	6-10 years	
arking L	Concrete Curbs	O - vitle O - vinte - mil	404	LF		40	
		South Courtyard	464		7	10+ years	
	Interior Plantings	South Courtyard	160	LF	7	10+ years	
	Lighting - Pole Mounted	South Courtyard	2	EA	7	10+ years	
	Surface - Asphalt	South Courtyard	14,000	SF	7	10+ years	
	Trash Enclosure - Chain Links	South Courtyard	1,206	SF	6	6-10 years	
	Vehicular Screening	South Courtyard	420	LF	7	10+ years	
laygrou	nd						
, ,	Equipment - Pre K 3-5	NW courtyard	1	EA	6	6-10 years	
	Equipment - School Age 5-12	NW courtyard	1	EA	6	6-10 years	
	Equipment - Swingset	NW courtyard	1	EA	6	6-10 years	
	Surface - Poured Surface	NW courtyard	5,025	SF	6	6-10 years	
idewalk							
	Sidewalks - Internal Walks	Entire Site	600	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	12,987	SF	6	10+ years	
Signage							
<del>3 -9-</del>	Flag Pole - Flag Pole	East	1	EA	6	6-10 years	
	Marquee - Building Mounted Back Lighted	East	1	EA	6	10+ years	

Campus Name: Dever Page : 34 of 37 Assessment Date: 12/13/2021



#### William E Dever Elementary School

3436 N Osceola AVENUE, Chicago, IL 60634

Category : Site Building : Site

Recommend
Group Item - Type Location Quantity UOM Rank Replacement Comments

Sign

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Dever Page : 35 of 37 Assessment Date: 12/13/2021

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				I -: -:					
				Floor Plan		Glazed	Operable	140	01
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main		T	1	1					
Computer Lab	Regular Classroom	1st Floor	107	107	690	172	60	Y	N
Faculty Lounge	Regular Classroom	1st Floor	111	111	670	172	60	Υ	N
Library	Regular Classroom	1st Floor	108	108	897	172	60	Υ	N
Regular Classroom	Regular Classroom	1st Floor	101	101	780	128	18	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	690	107	15	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	690	128	18	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	690	172	60	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	690	172	60	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	690	172	60	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	690	172	60	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	211	211	690	172	60	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	690	128	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	690	128	18	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	303	690	128	18	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	690	128	18	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	305	305	690	128	18	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	306	690	128	18	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	690	192	60	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	690	192	60	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	309	309	690	172	52	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	310	310	690	192	60	Υ	Υ
Special Education	Special Education	1st Floor	106	106	368	64	9	Υ	Υ
Special Program	Faculty Lounge	2nd Floor	205	205	345	64	9	N	N
Special Program	Regular Classroom	3rd Floor	311	311	482	172	60	Υ	N
op com r regression						1		ļ	
Building : Annex									
Kindergarten	Kindergarten	1st Floor	17	117	818				
Kindergarten	Kindergarten	1st Floor	18	118	816				
Kindergarten	Kindergarten	1st Floor	19	119	816				
Multi Purpose Room	Multi Purpose Room	1st Floor	11	111	457				
Pre School	Pre School	1st Floor	23	123	782			1	
Pre School	Pre School	2nd Floor	20	120	821			1	
Pre School	Pre School	2nd Floor	21	121	816				
Pre School	Pre School	2nd Floor	22	122	786				
Regular Classroom	Regular Classroom	1st Floor	14	114	762				
Regular Classroom	Regular Classroom	1st Floor	15	115	762				
Regular Classroom	Regular Classroom	1st Floor	16	116	791	1		1	$\vdash$
Regular Classiform	Regular Classroom	181 1001	10	110	791			1	<u> </u>



**Classroom Summary** 

Current Usage Building : Addition	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	1st Floor	100	100	690	128	18	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	112	112	690	172	60	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	690	128	18	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	690	172	60	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	300	300	680	128	18	Y	N
Special Program	Regular Classroom	3rd Floor	312	312	690	172	60	Υ	Y

Campus Name: Dever Page : 37 of 37 Assessment Date: 12/13/2021