

the end of this report.

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1903	3	47,850
Modular 1 (6-Classroom )	2003	1	5,645
Campus Total			53,495

Category : Exterior Building : Main

				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	1						
	Exterior Doors - Exterior Steel Door	Courtyard	1	EA	4	2-5 years	
	Exterior Stairs - Wood	Courtyard	9	LF	3	2-5 years	
	Stair Handrail - Steel_Stair Handrail	Courtyard	9	LF	4	2-5 years	Old rusted railing
	Entrance Control - Audio and Video	Door 3 - South	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 3 - South	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 3 - South	2	EA	6	10+ years	
	Entrance Control - Audio and Video	Door 4 - West	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 4 - West	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 4 - West	3	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 4 - West	20	LF	5	1-2 years	Spalled concrete, deteriorated repairs
	Exterior Doors - Exterior FRP Door	Door 5 - North	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 5 - North	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	Door 5 - North	10	LF	7	10+ years	New Ramp
	Exterior Doors - Exterior Steel Door	Door 6 - North	1	EΑ	6	10+ years	·
	Exterior Doors - Transom Lite	Door 6 - North	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 6 - North	3	LF	6	10+ years	Repaired
	Exterior Doors - Exterior Steel Door	Door 6.5 - East	2	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 7 - East	1	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	Door 8 - South	1	EΑ	5	2-5 years	
	Exterior Doors - Transom Lite	Door 8 - South	1	EΑ	5	2-5 years	
	Exterior Stairs - Concrete	Door 8 - South	3	LF	5	1-2 years	
	Exterior Doors - Exterior AMP Door	E Fire Escape 2nd & 3rd Floor	2	EA	6	10+ years	
	Exterior Doors - Side lite	E Fire Escape 2nd & 3rd Floor	2	EA	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	E Fire Escape 2nd & 3rd Floor	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	NW Fire Escape	1	EA	6	10+ years	
Fire Esc	ape						
	Fire Escape	East Façade	120	LF	6	10+ years	
	Fire Escape	Façade- NW	20	LF	6	10+ years	
Foundat	ion						
	Foundation - Concrete	Entire Building	490	LF	7	10+ years	
	Superstructure - Heavy Timber	Entire Building	47,850	SF	7	10+ years	
Lighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	1-2 years	Broken light fixture outside of second floor fire escape exit
Roof Svs	stem						
	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Coping - Clay Tile	Roof 1	180	LF	6	10+ years	
	Coping - Stone	Roof 1	180	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	152	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	40	LF	4	1-2 years	Old the downspout running on top of
							roof in several sections. It is disconnected from the new downspout
	Parapet - 16" - 30" Height	Roof 1	360	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	4,730	SF	6	10+ years	
	Roof Structure - Heavy Timber	Roof 1	4,730	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years	
	Coping - Metal	Roof 2	97	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 2	65	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 2	52	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 2	20	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 2	25	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2	2,650	SF	6	6-10 years	
	Roof Structure - Heavy Timber	Roof 2	2,650	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	1	EA	7	10+ years	
	Coping - Metal	Roof 3	101	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	80	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 3	55	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 3	20	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 3	26	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	2,480	SF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		, <b>3</b> ,
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Hatch - Metal	Roof 3	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	Roof 3	2,480	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 4	63	LF	6	10+ years	
	Liner						
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 4	13	LF	5	10+ years	
	Liner						
	Chimney - Metal Flue	Roof 4	73	LF	6	10+ years	
	Coping - Clay Tile	Roof 4	162	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 4	90	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 4	162	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 4	2,650	SF	6	10+ years	
	Roof Structure - Heavy Timber	Roof 4	2,650	SF	7	10+ years	
	Coping - Metal	Roof 5	75	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 5	4	LF	7	10+ years	
	Roof - Asphalt Shingle	Roof 5	362	SF	7	10+ years	
	Roof Structure - Heavy Timber	Roof 5	362	SF	7	10+ years	
	Coping - Metal	Roof 6	75	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 6	4	LF	6	10+ years	
	Roof - Asphalt Shingle	Roof 6	362	SF	7	10+ years	
	Roof Structure - Heavy Timber	Roof 6	362	SF	7	10+ years	
	Coping - Metal	Roof 7	75	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 7	4	LF	6	10+ years	
	Roof - Asphalt Shingle	Roof 7	360	SF	7	10+ years	
	Roof - Asphalt Shingle	Roof 7	2	SF	4	0-1 year	Missing asphalt shingle
	Roof Hatch - Metal	Roof 7	1	EA	3	10+ years	Hatch is screwed shut
	Roof Structure - Heavy Timber	Roof 7	362	SF	7	10+ years	
	Coping - Metal	Roof 8	75	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 8	4	LF	6	10+ years	
	Roof - Asphalt Shingle	Roof 8	362	SF	7	10+ years	
	Roof Structure - Heavy Timber	Roof 8	362	SF	7	10+ years	
\\/=!!=	•					•	
Walls	Cheek-Wall - Stone	Entire Building	20	SF	6	10+ years	Deteriorated mortar
	Cornice - Metal Projecting	Entire Building  Entire Building	550	SF LF	6	10+ years 10+ years	Needs sealant
	Exterior Walls - Brick	Entire Building Entire Building	16,095	SF	6	10+ years 10+ years	NECUS SEGIGITI
				SF SF	6 4		Open joints, deteriorated applicat
	Exterior Walls - Brick	Entire Building	80	SF	4	1-2 years	Open joints, deteriorated sealant scattered throughout building
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	360	SF	6	10+ years	Southered throughout building
	Exterior Walls - Stone-Cut	Entiro Buildina	E 27E	SF	6	10 L VOOTO	
	Exterior Walls - Stone-Cut  Exterior Walls - Stone-Cut	Entire Building	5,375	SF SF	6 5	10+ years	
	Exterior Walls - Stone-Cut  Exterior Walls - Stone-Cut	Entire Building Entire Building	160 20	SF SF		10+ years 1-2 years	Cracked sills
			400	SF SF	4 6	•	Cracked Sills
	Exterior Walls - Terra Cotta	Entire Building	400	ЭF	О	10+ years	

Campus Name: Everett Page : 3 of 26 Assessment Date: 11/10/2021



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Windows							
	Guard - Guards wire guard	Entire Building	1,410	SF	6	10+ years	
	Lintels - Brick	Entire Building	525	LF	6	10+ years	
	Lintels - Steel	Entire Building	44	LF	6	10+ years	
	Lintels - Stone	Entire Building	110	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	20	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	64	SF	7	10+ years	Cracked glass has been sealed
	Windows - Louver	Entire Building	2	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	390	SF	4	2-5 years	Obsolete single pane glass metal windows
	Windows - Sash Aluminum Double-pane	Entire Building	6,050	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System						
	Security System - CCTV	1st Floor	47,850	SF	4	2-5 years	
	Security System - Intrusion Detection	1st Floor	47,850	SF	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	3rd Floor	2	EA	2	0-1 year	
	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	17	EA	2	0-1 year	
	Exit Signs - Lunchroom	Entire Building	2	EA	2	0-1 year	
	Exit Signs - Multipurpose Room	Entire Building	6	EA	2	0-1 year	
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,023	SF	6	6-10 years	
Main Se	rvice						
	PA System	1st Floor	47,850	SF	7	10+ years	Installed in 2020 Fall
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	6-10 years	
	Main Electrical Service - 1200 A 120/208/3PH	Mechanical Room	1	EA	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	Boiler room
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	MDF room
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	3	1-2 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	2	1-2 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	



ALL A	SCHOOIS						3419 S Bell AVENUE, Chicago, IL 60608
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Croup	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	6-10 years	Comments
	amp	Entire ballaring		LA	U	0-10 years	
	апр						
Cotomo	m Fine Ductaction		D	به مداله الدي			
Catego	ry : Fire Protection		Б	uilding	: wain	_	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Fire Alar	m						
	Fire Alarm Panel	Entire Building	1	EA	3	1-2 years	
	Fire Alarm_System	Entire Building	47,850	SF	5	6-10 years	
	Fire Pump Controller	Entire Building	1	ĒΑ	5	6-10 years	
	o . dp dooo.	g	·		· ·	o .o you.o	
Dumn D	oom Assembly						
_Fullp K		Decement		Г^		0.40	
	Fire Pump - 25-50 hp	Basement	1	EA	5	6-10 years	
_Sprinkler	System System						
	Dry Sprinkler System	Entire Building	47,850	SF	6	6-10 years	
	Sprinkler Heads	Entire Building	47,850	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	47,850	SF	6	6-10 years	
	-ka	g	,	-	•	- · · · · · · · · · · · · · · · · · · ·	
Catego	ry : Mechanical		В	uilding	· Main		
	. ,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-			<u> </u>	00	rtuint	rtopiacomoni	
_Air Hano	ling Systems	4 . 🗖				0.40	D 1 1111
	Fan Coil Unit- Celing Mounted - Steam	1st Floor	4	EA	6	6-10 years	Per building engineer- not exist
	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room	1	EA	5	2-5 years	
	Steam Coils - 25001 - 35000 cfm						
	Air Intake	Mechanical Room	1	EA	6	2-5 years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	2-5 years	
	Return Duct Work - Masonry and Ducts-	Mechanical Room	100	LF	5	2-5 years	
	Missing or Existing Shaft						
	Zone Dampers	Mechanical Room	15	EA	5	2-5 years	
	Zone Dampers	Mechanical Room	8	EA	3	0-1 year	
Boiler Sy	vstems						
,	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	1	EA	5	6-10 years	
	Pressure Boiler - 101 - 150 HP	Bollot Room	•		Ü	o ro youro	
	Chemical Feeder	Boiler Room	1	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	5	6-10 years	Corroded
	•	Boiler Room	2	EA	5 5		Conduct
	Condensate Pump				_	6-10 years	Tanka carradad
	Feed Water Pumps and Tank	Boiler Room	1	EΑ	5	6-10 years	Tanks corroded
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	5	6-10 years	
	Steam- Low Pressure Boiler - 101 - 150 HP						

Campus Name: Everett Page : 5 of 26 Assessment Date: 11/10/2021



$\overline{}$	ry : Mechanical		D	uilding	· Main		3419 S Bell AVENUE, Chicago, IL 60606
Calego	ı y . Mechanicai		В	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Croup	Piping - Condensate Pipe- Steel	Boiler Room	100	LF	6	6-10 years	Comments
	Piping - Steam Pipe- Steel	Boiler Room	100	LF	5	6-10 years	
	Steam Traps	Boiler Room	20	EA	5	6-10 years	
	Vacuum Pump	Boiler Room	1	EA	5	6-10 years	
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	1	EA	5	6-10 years	
	Pressure Boiler - 76 - 100 HP	Boller Room	1	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Non Condensing - Fire Tube - Scotch Marine- Steam - Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	100	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	100	LF	6	6-10 years	
	Steam Traps	Boiler Room	18	EA	5	6-10 years	
	Steam Traps	Boller Room	10	EA	5	6-10 years	
_Gas Boo	ster						
	Gas Booster	Boiler Room	2	EA	6	6-10 years	
_Heating_							
	Cabinet Heaters - With Steam Coil	Basement	6	EA	6	6-10 years	
	Radiators - Steam	Entire Building	2	EA	6	6-10 years	
	Radiators - Steam	Entire Building	4	EA	5	6-10 years	
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Gas	Entire Building	1	EA	6	6-10 years	
	Unit Heater - Steam	Entire Building	1	EA	7	6-10 years	
	Wall Heater - Electric	Entire Building	8	EA	2	0-1 year	
Tempera	ature Control						
_теттрета	Pneumatic System	Entire Building	47,850	SF	5	6-10 years	
	Thermostats - Pneumatic	Entire Building	20	EA	5	6-10 years	
	Thermostats - Pheumatic	Entire Building  Entire Building	6	EA	4	0-10 years 0-1 year	
_Ventilatio	on.						
vorman	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Not exist
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	7	10+ years	Installed new exhaust fan in 2020 Fall- room 102
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	1 dii 100iii 102
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	7	10+ years	Installed new exhaust fan in 2020 Fall
	CFM	· ·				·	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	Installed new exhaust fan in 2020 Fall
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	3	0-1 year	
	Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	7	10+ years	Installed new exhaust fan in 2020 Fall



Catego	ry : Mechanical		В	uilding	: Main		
_			0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	500 CFM Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	47,850	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	47,850	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	47,850	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	47,850	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	47,850	SF	6	6-10 years	

SF

SF

SF

SF

6

6

6

6

47,850

47,850

47,850

47,850

6-10 years

6-10 years

6-10 years

6-10 years

\_Pumps\_

Domestic Piping-Hot/Cold Water Supply

(from Risers to Fixtures)

Sanitary Piping

Storm Piping

Vent Piping

Pumps - Domestic Booster Pump-Simplex **Entire Building** EΑ 2-5 years 1 5

Category: Room **Building: Main** 

**Entire Building** 

**Entire Building** 

Entire Building

Entire Building

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	1st Floor - Office (Main)	338	SF	6	10+ years	
	Doors - Side-lite	1st Floor - Office (Main)	90	SF	6	10+ years	
	Doors - Transom Window	1st Floor - Office (Main)	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Office (Main)	1	EΑ	6	10+ years	
	Floor - Wood	1st Floor - Office (Main)	338	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor - Office (Main)	6	EΑ	6	6-10 years	
	Power Distribution	1st Floor - Office (Main)	14	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor - Office (Main)	916	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Office (Main)	5	SF	4	1-2 years	Peeling
	AC Unit	1st Floor - Principal's Office (In Main	1	EA	5	6-10 years	3
		Office)				•	
	Ceiling - Plaster/Drywall	1st Floor - Principal's Office (In Main	180	SF	6	10+ years	

Assessment Date: 11/10/2021 Campus Name: Everett Page: 7 of 26



Catego	ry : Room		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Doors - Wood Doors inclu hw	Office) 1st Floor - Principal's Office (In Main	1	EA	6	10+ years	
	Floor - Tile/Sheet	Office) 1st Floor - Principal's Office (In Main	180	SF	5	6-10 years	
	Lighting - Chandelier, Incandescent	Office) 1st Floor - Principal's Office (In Main Office)	3	EA	6	6-10 years	
	Power Distribution	1st Floor - Principal's Office (In Main Office)	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor - Principal's Office (In Main Office)	328	SF	6	1-2 years	Peeling paint. Patch and repaint
	Ceiling - Plaster/Drywall	1st Floor Teacher's Lounge	400	SF	6	10+ years	
	Doors - Transom Window	1st Floor Teacher's Lounge	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Teacher's Lounge	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor Teacher's Lounge	390	SF	5	10+ years	
	Floor - Tile	1st Floor Teacher's Lounge	10	SF	4	1-2 years	Cracked tiles
	Lighting - Lay-in	1st Floor Teacher's Lounge	6	EA	6	6-10 years	
	Power Distribution	1st Floor Teacher's Lounge	30	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor Teacher's Lounge	730	SF	6	10+ years	
	Work Sink	1st Floor Teacher's Lounge	1	ĒA	5	6-10 years	
	AC Unit	204A	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	204A	920	SF	6	6-10 years	
	Doors - Side-lite	204A	256	SF	6	10+ years	
	Doors - Transom Window	204A	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	204A	1	ĒA	6	10+ years	
	Floor - Tile	204A	920	SF	6	6-10 years	
	Lighting - Pendent/Surface	204A	10	ĒΑ	7	6-10 years	
	Power Distribution	204A	5	EA	7	10+ years	
	Walls - Plaster/Drywall	204A	1,530	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Basement - 007	90	SF	6	10+ years	
	Doors - Side-lite	Basement - 007	3	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - 007	1	ĒΑ	6	10+ years	
	Floor - Tile	Basement - 007	90	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	Basement - 007	2	ĒΑ	6	6-10 years	
	Power Distribution	Basement - 007	4	ĒΑ	6	6-10 years	
	Walls - Plaster/Drywall	Basement - 007	144	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - 007	144	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - Engineer's Office	280	SF	5	0-1 year	
	Floor - Concrete	Basement - Engineer's Office	280	SF	5	2-5 years	
	Lighting - Pendent/Surface	Basement - Engineer's Office	7	EΑ	6	6-10 years	
	Power Distribution	Basement - Engineer's Office	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement - Engineer's Office	256	SF	6	10+ years	
Gymnas	·	<b>y</b>			-	<b>,</b>	

\_Gymnasia



Catego	ory : Room		В	uilding	: Main		. 5
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Exposed	3rd Floor	4,345	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	196	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Wood	3rd Floor	4,345	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	10+ years	
	Sound System	3rd Floor	1	EA	7	6-10 years	
	Stage	3rd Floor	512	SF	6	10+ years	
	Stage Curtain	3rd Floor	9	EA	7	6-10 years	
	Stage Lighting System	3rd Floor	1	EA	7	10+ years	
	Stage-Stairs - Tile	3rd Floor	10	LF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,690	SF	6	10+ years	
Kitchen							
	AC Unit	1st Floor - Kitchen - 106	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Kitchen - 106	825	SF	6	10+ years	
	Doors - Transom Window	1st Floor - Kitchen - 106	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Kitchen - 106	1	EA	6	10+ years	
	Floor - Tile	1st Floor - Kitchen - 106	625	SF	6	10+ years	
	Floor - Tile Quarry	1st Floor - Kitchen - 106	200	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor - Kitchen - 106	12	EA	6	6-10 years	
	Serving Line	1st Floor - Kitchen - 106	16	LF	6	10+ years	
	Storage/ Closet	1st Floor - Kitchen - 106	266	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor - Kitchen - 106	1,624	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	1st Floor - Lunch Room 105	945	SF	6	10+ years	
	Doors - Transom Window	1st Floor - Lunch Room 105	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Lunch Room 105	1	EA	6	10+ years	
	Floor - Tile	1st Floor - Lunch Room 105	943	SF	6	10+ years	
	Floor - Tile	1st Floor - Lunch Room 105	2	SF	4	1-2 years	Damaged tiles
	Lighting - Chandelier, Incandescent	1st Floor - Lunch Room 105	14	EA	6	6-10 years	ŭ
	Storage/ Closet	1st Floor - Lunch Room 105	50	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor - Lunch Room 105	1,181	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - Boys' Playroom South	1,025	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Boys' Playroom South	5	ĒΑ	6	10+ years	
	Floor - Concrete	Basement - Boys' Playroom South	1,025	SF	5	6-10 years	
	Lighting - Pendent/Surface	Basement - Boys' Playroom South	13	ĒΑ	6	6-10 years	
	Walls - Masonry	Basement - Boys' Playroom South	512	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Boys' Playroom South	512	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - Girls' Playroom North	945	SF	6	10+ years	
	Chalk Board	Basement - Girls' Playroom North	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement - Girls' Playroom North	4	ĒΑ	6	10+ years	
	Floor - Concrete	Basement - Girls' Playroom North	935	SF	7	6-10 years	
				=: =	-	- , , J	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Basement - Girls' Playroom North	10	SF	5	1-2 years	
	Lighting - Pendent/Surface	Basement - Girls' Playroom North	14	EA	6	6-10 years	
	Walls - Masonry	Basement - Girls' Playroom North	620	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Girls' Playroom North	620	SF	6	10+ years	
_MDF_IDI	E						
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Finishes	3rd Floor	249	SF	7	6-10 years	
	Window AC Unit	3rd Floor	1	EΑ	7	6-10 years	
Maahani	cal/ Service Rooms						
_wecnam	Janitor's Closet	1st Floor	6	SF	5	10+ years	
	Storage Room	1st Floor	330	SF	5 5	10+ years	
		2nd Floor	6	SF	5 7		
	Janitor's Closet	2nd Floor 2nd Floor	566	SF SF	7 7	10+ years	
	Storage Room				-	10+ years	
	Storage Room	3rd Floor	354	SF	7	10+ years	
	AC Unit	Basement	1	EA	5	2-5 years	
	Air Intake Plenums	Basement	440	SF	5	10+ years	
	Air Tunnel	Basement	400	SF	5	10+ years	
	Boiler Room	Basement	1,440	SF	5	10+ years	
	Coal Room	Basement	720	SF	5	10+ years	
	Crawl Space - Unfinished	Basement	800	SF	5	10+ years	
	Janitor's Closet	Basement	72	SF	5	10+ years	
	Janitor's Closet	Basement	150	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	960	SF	5	6-10 years	
	Storage Room	Basement	150	SF	5	10+ years	
	Storage Room	Basement	150	SF	5	10+ years	
	Storage Room	Basement	150	SF	5	10+ years	
	Storage Room	Basement	825	SF	5	10+ years	
Restroon	m						
	Accessories	105	23	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	105	23	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105	1	EA	6	10+ years	
	Floor - Tile	105	23	SF	5	10+ years	
	Floor Drain	105	1	EA	7	6-10 years	
	Lavatory	105	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	105	1	EA	6	6-10 years	
	Walls - Plaster/Drywall		177	SF	6		
		105			_	10+ years	
	Water Closet	105	1	EA	6	6-10 years	
	Accessories	1st Floor - Principal's Office	25	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal's Office	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal's Office	1	EA	6	10+ years	



Category : Room			Building : Main					
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	1st Floor - Principal's Office	25	SF	6	10+ years		
	Floor Drain	1st Floor - Principal's Office	1	EA	7	6-10 years		
	Lavatory	1st Floor - Principal's Office	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor - Principal's Office	1	EA	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor - Principal's Office	195	SF	6	1-2 years	Peeling paint	
	Water Closet	1st Floor - Principal's Office	1	EA	6	6-10 years	01	
	Accessories	1st Floor - Women Staff (Teacher's	65	SF	5	6-10 years		
		Lounge)		-	-	5 15 J 22 2		
	Ceiling - Plaster/Drywall	1st Floor - Women Staff (Teacher's	65	SF	6	10+ years		
		Lounge)		-	-	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
	Doors - Wood Doors inclu hw	1st Floor - Women Staff (Teacher's	1	EA	6	10+ years		
	Boole Wood Boole Illoid III	Lounge)	·	_, `	Ū	io. youro		
	Floor - Tile Ceramic/ Porcelain	1st Floor - Women Staff (Teacher's	65	SF	6	10+ years		
	The Column, Tolecham	Lounge)	00	O.	Ü	ioi youio		
	Floor Drain	1st Floor - Women Staff (Teacher's	2	EA	7	6-10 years		
	1 Ioor Brain	Lounge)	2	LA	,	0-10 years		
	Lavatory	1st Floor - Women Staff (Teacher's	1	EA	6	6-10 years		
	Lavatory	Lounge)	'	LA	U	0-10 years		
	Lighting - Pendent/Surface	1st Floor - Women Staff (Teacher's	2	EA	6	6-10 years		
	Lighting - Ferident/Surface	Lounge)	2	LA	O	0-10 years		
	Partitions	1st Floor - Women Staff (Teacher's	2	EA	5	6-10 years		
	Partitions		2	EA	5	0-10 years		
	Wells Disstar/Drawell	Lounge) 1st Floor - Women Staff (Teacher's	215	SF	6	10		
	Walls - Plaster/Drywall	· ·	215	SF	О	10+ years		
	Water Closet	Lounge) 1st Floor - Women Staff (Teacher's	2	EA	6	6 10 years		
	Water Closet		2	EA	О	6-10 years		
	A	Lounge)	00	C.E.	7	0.40		
	Accessories	2nd Floor - Boys	90	SF SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor - Boys	90		6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor - Boys	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Boys	90	SF	6	10+ years		
	Floor Drain	2nd Floor - Boys	2	EΑ	7	6-10 years		
	Lavatory	2nd Floor - Boys	2	EA	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor - Boys	2	EA	7	10+ years		
	Partitions	2nd Floor - Boys	2	EA	7	6-10 years		
	Urinals	2nd Floor - Boys	2	EA	6	6-10 years		
	Walls - Plaster/Drywall	2nd Floor - Boys	300	SF	6	10+ years		
	Water Closet	2nd Floor - Boys	2	EΑ	6	6-10 years		
	Accessories	2nd Floor - Girls	265	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor - Girls	265	SF	6	10+ years		
	Doors - Transom Window	2nd Floor - Girls	9	SF	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Girls	265	SF	6	10+ years		
	Floor Drain	2nd Floor - Girls	2	EA	7	6-10 years		
	Lavatory	2nd Floor - Girls	2	EA	6	6-10 years		
	Lighting - Pendent/Surface	2nd Floor - Girls	4	EA	6	10+ years		



Catego	ry : Room		В	uilding	: Main		· • • ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	2nd Floor - Girls	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor - Girls	640	SF	6	10+ years	
	Water Closet	2nd Floor - Girls	3	EA	6	6-10 years	
	Accessories	2nd Floor - Mens	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Mens	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Mens	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor - Mens	32	SF	7	10+ years	
	Floor Drain	2nd Floor - Mens	1	EA	7	6-10 years	
	Lavatory	2nd Floor - Mens	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - Mens	1	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Mens	165	SF	6	10+ years	
	Water Closet	2nd Floor - Mens	1	ĒΑ	6	6-10 years	
	Accessories	Basement	5	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	80	SF	7	10+ years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Lavatory	Basement	1	EΑ	7	10+ years	
	Lighting - Lay-in	Basement	2	EΑ	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	360	SF	7	10+ years	
	Water Closet	Basement	1	EA	7	10+ years	
	Accessories	Basement - Engineer's Toilet	80	SF	5	6-10 years	
		(Janitor's Closet South)	00		J	•	
	Ceiling - Exposed	Basement - Engineer's Toilet (Janitor's Closet South)	80	SF	4	1-2 years	
	Doors - Wood Doors inclu hw	Basement - Engineer's Toilet (Janitor's Closet South)	1	EA	6	10+ years	
	Floor - Tile	Basement - Engineer's Toilet (Janitor's Closet South)	80	SF	6	10+ years	
	Floor Drain	Basement - Engineer's Toilet (Janitor's Closet South)	1	EA	7	6-10 years	
	Lavatory	Basement - Engineer's Toilet (Janitor's Closet South)	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement - Engineer's Toilet (Janitor's Closet South)	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement - Engineer's Toilet (Janitor's Closet South)	246	SF	6	2-5 years	
	Walls - Plaster/Drywall	Basement - Engineer's Toilet (Janitor's Closet South)	10	SF	5	0-1 year	
	Water Closet	Basement - Engineer's Toilet (Janitor's Closet South)	1	EA	6	10+ years	
	Accessories	Basement - North Girls Toilet	560	SF	7	6-10 years	Repaired
	Ceiling - Plaster/Drywall	Basement - North Girls Toilet	560	SF	7	10+ years	Repaired
	Floor - Tile	Basement - North Girls Toilet	560	SF	7	10+ years	Repaired

Campus Name: Everett Page : 12 of 26 Assessment Date: 11/10/2021



Catego	Category : Room			uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	Basement - North Girls Toilet	1	EΑ	7	6-10 years	
	Lavatory	Basement - North Girls Toilet	4	EA	7	10+ years	Repaired
	Lighting - Pendent/Surface	Basement - North Girls Toilet	8	EA	7	10+ years	Repaired
	Partitions	Basement - North Girls Toilet	12	EA	7	10+ years	Repaired
	Walls - Plaster/Drywall	Basement - North Girls Toilet	1,208	SF	7	10+ years	Repaired
	Walls - Plaster/Drywall	Basement - North Girls Toilet	25	SF	7	10+ years	Repaired
	Water Closet	Basement - North Girls Toilet	12	EA	7	10+ years	Repaired
	Accessories	Basement - South Boys Toilet	585	SF	7	10+ years	Repaired
	Ceiling - Plaster/Drywall	Basement - South Boys Toilet	585	SF	7	10+ years	
	Floor - Epoxy/ Painted	Basement - South Boys Toilet	585	SF	7	10+ years	
	Floor Drain	Basement - South Boys Toilet	1	EA	7	10+ years	Repaired
	Lavatory	Basement - South Boys Toilet	4	EA	7	10+ years	Repaired
	Lighting - Pendent/Surface	Basement - South Boys Toilet	10	EA	7	10+ years	Repaired
	Partitions	Basement - South Boys Toilet	4	EA	7	10+ years	Repaired
	Urinals	Basement - South Boys Toilet	10	EA	7	10+ years	Repaired
	Walls - Plaster/Drywall	Basement - South Boys Toilet	1,417	SF	7	10+ years	Repaired
	Water Closet	Basement - South Boys Toilet	4	EA	7	6-10 years	Repaired
	Accessories	Toilet 101A - In room 101	21	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Toilet 101A - In room 101	21	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Toilet 101A - In room 101	1	EA	6	10+ years	
	Floor - Tile/Sheet	Toilet 101A - In room 101	21	SF	5	10+ years	
	Lavatory	Toilet 101A - In room 101	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Toilet 101A - In room 101	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Toilet 101A - In room 101	140	SF	6	10+ years	
	Water Closet	Toilet 101A - In room 101	1	EA	6	6-10 years	

Category : Classroom

						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Casework	1st Floor	20	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	930	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	4	1-2 years	Peeling
	Chalk Board	1st Floor	8	LF	4	2-5 years	-
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	305	SF	6	6-10 years	
	Floor - Tile	1st Floor	635	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	23	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,513	SF	6	10+ years	

**Building: Main** 

Campus Name: Everett Page : 13 of 26 Assessment Date: 11/10/2021



Catego	ry : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	980	SF	6	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	980	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	8	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,513	SF	6	10+ years	
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	940	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	940	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	6	6-10 years	
	Storage/ Closet	1st Floor	4	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,524	SF	6	10+ years	
Classroo	om #104 (Art Room)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	968	SF	6	10+ years	
	Chalk Board	1st Floor	63	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	968	SF	5	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	
	Storage/ Closet	1st Floor	164	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,535	SF	6	10+ years	
	vvalis - Flastei/Drywali	151 11001	1,555	SF	O	10+ years	
_Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	980	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	950	SF	6	6-10 years	
	Floor - Tile	2nd Floor	30	SF	5	1-2 years	Crack tile
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,513	SF	6	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	



Ceiling - Plaster/Dywall	Category : Classroom		В	uilding	: Main			
Ceiling - Plaster/Drywall	_				_			
Doors - Transom Window	Group	Item - Type		Quantity		Rank		Comments
Doors - Wood Doors inclu hw		Ceiling - Plaster/Drywall	2nd Floor	980		6	10+ years	
Floor - Tile		Doors - Transom Window	2nd Floor	9		6	10+ years	
Floor - Tile		Doors - Wood Doors inclu hw	2nd Floor	1		6	10+ years	
Lighting - Pendent/Surface   2nd Floor   14 EA 6 10+ years		Floor - Tile	2nd Floor	2		6	6-10 years	Repaired
Storage Closet   2nd Floor   90   SF   5   1-2 years		Floor - Tile	2nd Floor	980	SF	6	10+ years	
Storage Closet   2nd Floor   90   SF   5   1-2 years		Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
Classroom #201 (Regular Classroom)			2nd Floor	90	SF	5		
AC Units					SF	6		
AC Units	Classroo	m #203 (Regular Classroom)						
Casework			2nd Floor	1	FA	7	6-10 years	
Calling - Plaster/Drywall								
Chalk Board							<u>-</u>	
Doors - Transom Window   2nd Floor   9 SF 6 10+ years   Door knob missing		Chalk Board						
Doors - Wood Doors inclu hw   End Floor   1							-	
Floor - Tile								Door knob missing
Lighting - Pendent/Surface   2nd Floor   14   EA   7   10+ years								Door knob missing
Storage/ Closet   2nd Floor   120   SF   7   10+ years					_	_		
Walls - Plaster/Drywall   2nd Floor   1,513 SF 6 10+ years		Storage/ Closet						
AC Units 2nd Floor 680 SF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 680 SF 6 10+ years Doors - Side-lite 2nd Floor 64 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 10+ years Floor - Tile 2nd Floor 680 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 14 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor 832 SF 6 10+ years Classroom #205 (Regular Classroom)  AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 4 LF 6 6-10 years Ceiling - Plaster/Drywall 2nd Floor 940 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 9 SF 6 10+ years Floor - Tile 2nd Floor 9 SF 6 10+ years Floor - Tile 2nd Floor 9 SF 6 10+ years Floor - Tile 2nd Floor 1 EA 6 10+ years Floor - Tile 2nd Floor 940 SF 6 6-10 years Floor - Tile 2nd Floor 940 SF 6 6-10 years Storage/ Closet 2nd Floor 8 SF 7 10+ years Storage/ Closet 2nd Floor 8 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,513 SF 6 10+ years Walls - Plaster/Drywall 2nd Floor 1,513 SF 6 10+ years							•	
AC Units 2nd Floor 680 SF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 680 SF 6 10+ years Doors - Side-lite 2nd Floor 64 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EA 6 10+ years Floor - Tile 2nd Floor 680 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 14 EA 7 10+ years Walls - Plaster/Drywall 2nd Floor 832 SF 6 10+ years Classroom #205 (Regular Classroom)  AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 4 LF 6 6-10 years Ceiling - Plaster/Drywall 2nd Floor 940 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 9 SF 6 10+ years Floor - Tile 2nd Floor 9 SF 6 10+ years Floor - Tile 2nd Floor 9 SF 6 10+ years Floor - Tile 2nd Floor 1 EA 6 10+ years Floor - Tile 2nd Floor 940 SF 6 6-10 years Floor - Tile 2nd Floor 940 SF 6 6-10 years Storage/ Closet 2nd Floor 8 SF 7 10+ years Storage/ Closet 2nd Floor 8 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,513 SF 6 10+ years Walls - Plaster/Drywall 2nd Floor 1,513 SF 6 10+ years	Classroo	m #204B (Regular Classroom)						
Ceiling - Plaster/Drywall	Oldooroo		2nd Floor	1	FΔ	7	6-10 years	
Doors - Side-lite								
Doors - Transom Window								
Doors - Wood Doors inclu hw   2nd Floor   1								
Floor - Tile								
Lighting - Pendent/Surface Walls - Plaster/Drywall       2nd Floor       14 EA 7 10+ years         Classroom #205 (Regular Classroom)       2nd Floor       1 EA 7 6-10 years         Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Doors - Wood Doors inclu hw Ploor - Tile Doors - Tile Tile Tile Tile Tile Tile Tile Tile				•		_		
Walls - Plaster/Drywall         2nd Floor         832         SF         6         10+ years           Classroom #205 (Regular Classroom)         AC Units         2nd Floor         1         EA         7         6-10 years           Casework         2nd Floor         4         LF         6         6-10 years           Ceiling - Plaster/Drywall         2nd Floor         940         SF         6         10+ years           Doors - Transom Window         2nd Floor         9         SF         6         10+ years           Doors - Wood Doors inclu hw         2nd Floor         1         EA         6         10+ years           Floor - Tile         2nd Floor         940         SF         6         6-10 years           Lighting - Pendent/Surface         2nd Floor         14         EA         7         10+ years           Storage/ Closet         2nd Floor         8         SF         7         10+ years           Walls - Plaster/Drywall         2nd Floor         1,513         SF         6         10+ years					_			
AC Units   2nd Floor   1								
AC Units  Casework  Casework  Ceiling - Plaster/Drywall  Doors - Transom Window  Doors - Wood Doors inclu hw  Floor - Tile  Lighting - Pendent/Surface  Storage/ Closet  Walls - Plaster/Drywall  2nd Floor  3nd		walls - Plaster/Drywall	2110 F1001	032	SF	0	10+ years	
Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Storage/ Closet Walls - Plaster/Drywall  2nd Floor 3nd Floor	Classroo	, ,						
Ceiling - Plaster/Drywall2nd Floor940SF610+ yearsDoors - Transom Window2nd Floor9SF610+ yearsDoors - Wood Doors inclu hw2nd Floor1EA610+ yearsFloor - Tile2nd Floor940SF66-10 yearsLighting - Pendent/Surface2nd Floor14EA710+ yearsStorage/ Closet2nd Floor8SF710+ yearsWalls - Plaster/Drywall2nd Floor1,513SF610+ years								
Doors - Transom Window2nd Floor9SF610+ yearsDoors - Wood Doors inclu hw2nd Floor1EA610+ yearsFloor - Tile2nd Floor940SF66-10 yearsLighting - Pendent/Surface2nd Floor14EA710+ yearsStorage/ Closet2nd Floor8SF710+ yearsWalls - Plaster/Drywall2nd Floor1,513SF610+ years				=				
Doors - Wood Doors inclu hw2nd Floor1EA610+ yearsFloor - Tile2nd Floor940SF66-10 yearsLighting - Pendent/Surface2nd Floor14EA710+ yearsStorage/ Closet2nd Floor8SF710+ yearsWalls - Plaster/Drywall2nd Floor1,513SF610+ years								
Floor - Tile 2nd Floor 940 SF 6 6-10 years Lighting - Pendent/Surface 2nd Floor 14 EA 7 10+ years Storage/ Closet 2nd Floor 8 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,513 SF 6 10+ years							•	
Lighting - Pendent/Surface  2nd Floor  Storage/ Closet  2nd Floor  8 SF 7 10+ years  Walls - Plaster/Drywall  2nd Floor  1,513 SF 6 10+ years						_		
Storage/ Closet 2nd Floor 8 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor 1,513 SF 6 10+ years						_		
Walls - Plaster/Drywall 2nd Floor 1,513 SF 6 10+ years							•	
							10+ years	
Spectoom #206 (Pagular Classroom)		Walls - Plaster/Drywall	2nd Floor	1,513	SF	6	10+ years	
aassiuuiii #200 (Neguiai Giassiuuiii)	Classroo	m #206 (Regular Classroom)						

Campus Name: Everett Page : 15 of 26 Assessment Date: 11/10/2021



Catego	ry : Classroom		В	uilding	: Main		5413 & Bell AVENGE, Officago, IE 00000
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,005	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,005	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	100	SF	5	1-2 years	Paint peeling in Closet
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw		9	EA	6		
		3rd Floor				10+ years	
	Floor - Tile	3rd Floor	940	SF	6	6-10 years	0 1 1
	Floor - Tile	3rd Floor	40	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	10+ years	
	Marker Board	3rd Floor	3	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,513	SF	6	10+ years	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	980	SF	6	6-10 years	
	Floor - Tile	3rd Floor	5	SF	4	1-2 years	Missing tiles
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	6	10+ years	gg
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,513	SF	6	10+ years	
Classroo	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor		SF			
			940	SF SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	5F	6	10+ years	

Campus Name: Everett Page : 16 of 26 Assessment Date: 11/10/2021



, LE	3C1 10013						3419 S Bell AVENUE, Chicago, IL 6060			
Catego	ry : Classroom		В	Building : Main						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years				
	Floor - Tile	3rd Floor	940	SF	6	6-10 years				
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years				
	Marker Board	3rd Floor	12	LF	6	6-10 years				
	Storage/ Closet	3rd Floor	8	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor	1,513	SF	6	10+ years				
Classroo	om #306 (Computer Lab)									
	AC Units	3rd Floor	2	EA	7	6-10 years				
	Casework	3rd Floor	9	LF	6	6-10 years				
	Ceiling - Plaster/Drywall	3rd Floor	1,005	SF	6	10+ years				
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years				
	Floor - Tile	3rd Floor	1,005	SF	6	6-10 years				
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years				
	Storage/ Closet	3rd Floor	4	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor	1,575	SF	6	10+ years				
Catego	ry : Interior		В	uilding	: Main					
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Corridor										
	Ceiling - Plaster/Drywall	1st Floor	1,299	SF	6	10+ years				
	Drinking Fountains - Double Fountain	1st Floor	1	EA	5	10+ years				
	Floor - Tile/Sheet	1st Floor	1,299	SF	5	10+ years				
	Lighting - Chandelier, Incandescent	1st Floor	16	EA	6	6-10 years				
	Walls - Plaster/Drywall	1st Floor	2,348	SF	6	10+ years				
	O '1'   DI + /D   11	0 1 51	4 000	~=	•	4.0				

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	1,299	SF	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	5	10+ years	
	Floor - Tile/Sheet	1st Floor	1,299	SF	5	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor	16	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,348	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,299	SF	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,299	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	2nd Floor	17	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,348	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	425	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	425	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	3rd Floor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	955	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,371	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	8	EA	6	10+ years	
	Drinking Fountains - Double Fountain	Basement	2	EA	5	6-10 years	
	Floor - Asphalt Floor	Basement	1,371	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	16	EA	6	6-10 years	
	Stairs - Terrazzo	Basement	14	LF	6	10+ years	
	Walls - Plaster/Drywall	Basement	3,722	SF	6	10+ years	

Campus Name: Everett Page : 17 of 26 Assessment Date: 11/10/2021



ALL A	3CHOOIS						3419 S Bell AVENUE, Chicago, IL 60608
Catego	ry : Interior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Safety			-			•	
,	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	4	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North	588	SF	6	10+ years	
	Floor - Asphalt	North	288	SF	6	10+ years	
	Handrails	North	186	LF	5	10+ years	
	Lighting - Pendent/Surface	North	6	EA	6	6-10 years	
	Stairs - Asphalt	North	93	LF	6	10+ years	
	Walls - Plaster/Drywall	North	4,222	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	588	SF	6	10+ years	
	Floor - Asphalt	South	288	SF	6	10+ years	
	Handrails	South	186	LF	5	10+ years	
	Lighting - Pendent/Surface	South	6	EA	6	6-10 years	
	Stairs - Asphalt	South	93	LF	6	10+ years	
	Stairs - Asphalt	South	25	LF	6	10+ years	
	Walls - Plaster/Drywall	South	4,222	SF	6	10+ years	
	Ceiling - Plaster/Drywall	West	120	SF	6	10+ years	
	Floor - Asphalt	West	50	SF	6	10+ years	
	Handrails	West	36	LF	5	6-10 years	
	Lighting - Chandelier, Incandescent	West	2	EA	6	6-10 years	
	Stairs - Asphalt	West	18	LF	6	10+ years	
	Walls - Plaster/Drywall	West	1,392	SF	6	10+ years	





Category: Exterior Building: Modular 1 (6-Classroom) Recommend Location Replacement Comments Item - Type Quantity **UOM** Group Rank Entrance Exterior Doors - Exterior Steel Door 2 FΑ Door 1 - West 6 10+ years Door 1 - West 7 LF 5 Exterior Stairs - Concrete 1-2 years Broken concrete around post bases LF 5 Stair Handrail - Steel Stair Handrail Door 1 - West 17 1-2 years Broken concrete around post bases Exterior Doors - Exterior Steel Door Door 2 - East 2 EΑ 6 10+ years Foundation LF Foundation - Masonry Entire Building 310 6 10+ years Foundation needs Tuckpointing Superstructure - Steel **Entire Building** 5.645 SF 7 10+ years \_Liahtina Exterior Lighting - Wall Mounted EΑ 7 **Entire Building** 4 10+ years Roof System Coping - Metal **Entire Building** LF 6 310 10+ years LF Downspouts - Exterior Downspouts **Entire Building** 60 5 1-2 years downspout connections need sealing Roof - EPDM/ Synthetic Rubber Entire Building 5.445 SF 6 6-10 years Roof - EPDM/ Synthetic Rubber SF **Entire Building** 200 4 1-2 years Roof is leaking water onto room 401 Roof Structure - Steel / Metal Deck/ SF 10+ vears Entire Building 5.645 Concrete Topping Walls Exterior Walls - Hardie Board SF 6 Entire Building 2.650 10+ years SF Exterior Walls - Hardie Board **Entire Building** 20 4 1-2 years Minor issues around the building. Torn flashing, missing surface, detached trim, deteriorated sealant Windows Guard - Guards perforated SF **Entire Building** 400 6 10+ years Windows - Sash Aluminum **Entire Building** 400 SF 6 10+ years Category : Electrical Building: Modular 1 (6-Classroom) Recommend Location **UOM** Replacement Comments Item - Type Quantity Emergency System Security System - CCTV 1st Floor SF 7 5.645 10+ vears Security System - Intrusion Detection 1st Floor 5.645 SF 6 6-10 years Exit Signs - Corridors and Stairs EΑ 0-1 year 1st Floor Need bulb Exit Signs - Corridors and Stairs 1st Floor 1 EΑ 6 6-10 years Exit Signs - Multipurpose Room 1st Floor 6 EΑ 6 6-10 years Class rooms Emergency Battery Packs - Corridors and 1st Floor 3 FΑ 6-10 years

Campus Name: Everett Page: 19 of 26 Assessment Date: 11/10/2021



Catego	Category : Electrical			uilding	: Modul	ar 1 (6-Classro	om )	
						Recommend		
Group	Item - Type Stairs	Location	Quantity	UOM	Rank	Replacement	Comments	
	Emergency Battery Packs - Multipurpose Room	1st Floor	6	EA	6	6-10 years	Classrooms	
Main Ser	vice							
	PA System	1st Floor	5,645	SF	6	6-10 years		
	Main Electrical Service - 800 A and 120/208/3PH	exterior cabinet	1	EA	6	6-10 years		
Power Di	istribution							
	Lighting and Power Panels - 100 A	1st Floor	3	EA	6	6-10 years		
	Main Distribution Panels - Less than 400 amp	1st Floor	1	EA	6	6-10 years	No electrical room	
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (6-Classro	oom )	
<b>0</b>	Name Tama	Lagation	0	HOM	DI-	Recommend	0	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Aları	Fire Alarm_System	1st Floor	5,645	SF	6	6-10 years		
Sprinkler	System							
1	Sprinkler Heads	1st Floor	5,645	SF	7	6-10 years		
	Sprinkler Piping	1st Floor	5,645	SF	6	6-10 years		
	Wet Sprinkler System	1st Floor	5,645	SF	6	6-10 years		
Catego	ry : Mechanical		Building : Modular 1 (6-Classroom )					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	ture Control	Location	Quantity	JOIN	Runk	Ropidocinont	Comments	
•	Electric Thermostat	1st Floor	6	EA	6	6-10 years	Typical	
Unit Ven	tilation							
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	exterior surface	6	EA	6	6-10 years		
Ventilatio	on							
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	6	EA	6	6-10 years		
Catego	ry : Plumbing		В	uilding	: Modul	ar 1 (6-Classro	oom )	
outogo.								



						Replacement	
Hot Wat	er						
	Electric Heater - Less than 20 KW	1st Floor	1	EA	5	2-5 years	
						•	
_Piping_							
	Domestic Piping-Hot Water Return Lines	Entire Building	5,645	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	5,645	SF	7	6-10 years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	5,645	SF	6	6-10 years	
	(Horizontal Lines)						
	Sanitary Piping	Entire Building	5,645	SF	6	6-10 years	
	Storm Piping	Entire Building	5,645	SF	6	6-10 years	
	Vent Piping	Entire Building	5,645	SF	6	6-10 years	
Catago	w. Classram		ь	الم ما أمان	. Madul	or 1 /6 Classes	am \
Calego	ry : Classroom		D	unung	. Wodui	ar 1 (6-Classro Recommend	om )
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	om #401 (Kindergarten)	Location	Quantity	OOW	IVALIK	Replacement	Comments
Classion	Ceiling - Lay-in	1st Floor	660	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	660	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	6	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	SF	6	10+ years	
	walls willy coaled cypoull' all all a	13(1100)	745	0.	O	101 years	
Classro	om #402 (Kindergarten)						_
	Ceiling - Lay-in	1st Floor	660	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	5	1-2 years	Missing tiles
	Chalk Board	1st Floor	12	LF	4	2-5 years	3
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	660	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor	29	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	SF	6	10+ years	
_Classroo	om #403 (Physical Education Room)		_				
	Ceiling - Lay-in	1st Floor	660	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	660	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Storage/ Closet	1st Floor	35	SF SF	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	5F	6	10+ years	



Catego	ry : Classroom	Building : Modular 1 (6-Classroom )							
_				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classro	om #404 (Office)								
	Ceiling - Lay-in	1st Floor	660	SF	7	10+ years			
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile/Sheet	1st Floor	660	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	12	EΑ	7	10+ years			
	Storage/ Closet	1st Floor	21	SF	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	SF	7	10+ years			
Classroo	om #405 (Kindergarten)								
	Ceiling - Lay-in	1st Floor	660	SF	7	10+ years			
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile/Sheet	1st Floor	660	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	12	EΑ	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	SF	6	10+ years			
Classroo	om #406 (Kindergarten)								
	Ceiling - Lay-in	1st Floor	660	SF	7	10+ years			
	Chalk Board	1st Floor	12	LF	4	2-5 years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	660	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	SF	6	10+ years			

Category : Room **Building: Modular 1 (6-Classroom)** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Mechan	ical/ Service Rooms						
	Mechanical/ Service Rooms	Mechanical room in 402	52	SF	7	10+ years	
Restroo	m						
	Accessories	Boys	176	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys	176	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boys	1	EΑ	6	10+ years	
	Floor - Tile/Sheet	Boys	176	SF	7	10+ years	
	Floor Drain	Boys	1	EA	7	6-10 years	
	Lavatory	Boys	1	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	Boys	1	EΑ	7	10+ years	
	Partitions	Boys	2	EΑ	7	6-10 years	
	Urinals	Boys	2	EΑ	6	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	Boys	432	SF	7	10+ years	
	Water Closet	Boys	2	EA	7	6-10 years	

Campus Name: Everett Page : 22 of 26 Assessment Date: 11/10/2021



Category : Room			Building : Modular 1 (6-Classroom )					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Accessories	Girls	176	SF	7	6-10 years		
	Ceiling - Lay-in	Girls	176	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Girls	1	EA	6	10+ years		
	Floor - Tile/Sheet	Girls	176	SF	7	10+ years		
	Floor Drain	Girls	1	EA	7	6-10 years		
	Lavatory	Girls	2	EA	6	6-10 years		
	Lighting - Pendent/Surface	Girls	2	EA	7	10+ years		
	Partitions	Girls	4	EA	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	Girls	432	SF	6	10+ years		
	Water Closet	Girls	4	EA	6	6-10 years		

**Building: Modular 1 (6-Classroom) Category: Interior** 

Cutogo.	· , · · · · · · · · · · · · · · · · · ·	zanang i medalar i (e elacoreem )							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Lay-in	1st Floor	648	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years			
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years			
	Floor - Tile/Sheet	1st Floor	648	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	10	EA	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,424	SF	6	10+ years			





Category: Site **Building: Site** 

alego	iy. Oile		Building . Site						
	_					Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
vil/Dra	inage								
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	6	10+ years			
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years			
	Civil/ Drainage - Site Manhole	Entire Site	2	EA	6	10+ years			
ncing									
Ū	Fencing - Chain Link	Entire Site	255	LF	6	10+ years			
	Fencing - Guard Rail	Entire Site	10	LF	7	10+ years			
	Fencing - Iron and Concrete Post	Entire Site	390	LF	6	10+ years			
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	135	LF	6	10+ years			
andsca	pe								
	Landscape - Grass	Entire Site	2,900	SF	6	10+ years			
	Landscape - Hardscape- Concrete	Entire Site	3,510	SF	6	10+ years			
	Landscape - Hardscape- Pavers	Entire Site	400	SF	6	10+ years			
	Parkway trees	Entire Site	9	EA	6	10+ years			
	Parkway trees	Entire Site	10	EA	4	1-2 years	10 dead pine shrubs		
	Parkway trees	Entire Site	1	EA	4	1-2 years	Missing three		
	Trash Receptacles	Entire Site	1	EA	7	10+ years			
rking l	ot								
	Surface - Asphalt	N Parking Lot	7,000	SF	6	10+ years			
	Surface - Asphalt	N Parking Lot	500	SF	4	2-5 years	Alligatored surfacepotholes		
	Surface - Concrete	N Parking Lot	465	SF	6	10+ years			
	Trash Enclosure - Chain Links	N Parking Lot	315	SF	5	10+ years			
	Trash Enclosure - Wood	N Parking Lot	150	SF	5	10+ years			
dewalk	KS .								
	Sidewalks - Perimeter Sidewalks	Entire Site	8,620	SF	7	10+ years	New sidewalks		
gnage									
,	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years			
	Marquee - Building Mounted Back Lighted	Entire Site	1	EA	6	10+ years			
	w/ LED					•			

Campus Name: Everett Page: 24 of 26 Assessment Date: 11/10/2021

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Everett Page: 25 of 26 Assessment Date: 11/10/2021





**Classroom Summary** 

Oldssi Odii Odiiiiidiy			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	1st Floor	104	104	968	240	72	N	N
Computer Lab	Regular Classroom	3rd Floor	306	306	1,005	240	72	N	N
Regular Classroom	Kindergarten	1st Floor	101	101	940	240	72	N	N
Regular Classroom	Library	2nd Floor	203	203	940	175	68	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	980	240	72	N	Y
Regular Classroom	Regular Classroom	1st Floor	103	103	940	200	45	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	980	240	72	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	980	240	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	204B	204A	680	120	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	940	240	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	1,005	240	72	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	980	240	72	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	980	240	72	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	940	240	72	N	Υ
Building : Modular 1 (6-Classi	room )								
Kindergarten	Regular Classroom	1st Floor	401	401	660	60	26	N	N
Kindergarten	Regular Classroom	1st Floor	402	402	660	60	26	N	N
Kindergarten	Regular Classroom	1st Floor	405	405	660	60	26	N	N
Kindergarten	Regular Classroom	1st Floor	406	406	660	60	26	N	N
Office	Regular Classroom	1st Floor	404	404	660	60	26	N	N
Physical Education Room	Regular Classroom	1st Floor	403	403	660	60	26	N	N